

# Chicago Public Schools

## 6 Month Asbestos Surveillance

### 2018 - Fall

**School:** Hannah G Solomon Elementary School  
**Address:** 6206 N Hamlin Avenue

**Oracle Unit:** 25431  
**Region:** 01

**Building ID:** 5980  
**Mail Room:** 31

**CHECK HERE IF NO CHANGE TO ASBESTOS**

**Asbestos Surveyor:** Sanchez, Alexander  
**Survey Date:** 12/17/2018  
**Email Address:** sanchez-alexander@aramark.com

A copy of the 2016/2017 notice to parents and staff regarding the asbestos management plan notifications was distributed via:

*Each child's backpack*     
 *Notice printed in school's newsletter*     
 *Notice printed in school's calendar*     
 *Other*

| HA No | Material Description      | Material Quantity | Material Units | Material Location            | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|---------------------------|-------------------|----------------|------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 01    | 12"x12" Blue and Grey VFT | 60                | SF             | Teachers Toilet - 1953 Bldg. |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description               | Material Quantity | Material Units | Material Location                        | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|------------------------------------|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 02    | 12"x12" Brown w/ Brown Streaks VFT | 300               | SF             | Rooms 111 (Under New VFT) and 113 - 1956 |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |

| HA No | Material Description | Material Quantity | Material Units | Material Location   | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 08    | 12"x12" Grey VFT     | 2250              | SF             | Room 115 (Under New VFT), 117, 119 (Under New VFT) - 1956 |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description         | Material Quantity | Material Units | Material Location               | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|------------------------------|-------------------|----------------|---------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 10    | 12"x12" Yellow and White VFT | 750               | SF             | Room 112 (Under New VFT) - 1956 |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |

| HA No | Material Description             | Material Quantity | Material Units | Material Location      | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------------------|-------------------|----------------|------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 16    | 12"x12" Blue and Grey VFT Mastic | 60                | SF             | Teachers Toliet - 1953 |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description                      | Material Quantity | Material Units | Material Location                      | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|---|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 17    | 12"x12" Brown w/ Brown Streaks VFT Mastic | 1500              | SF             | Rooms 111 (Under New VFT) , 113 - 1956 |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |

| HA No | Material Description    | Material Quantity | Material Units | Material Location   | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|-------------------------|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 20    | 12"x12" Grey VFT Mastic | 2250              | SF             | Room 115 (Under New VFT), 117, 119 & Library (Under New VFT) - 1956 |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description                | Material Quantity | Material Units | Material Location               | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|-------------------------------------|-------------------|----------------|---------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 22    | 12"x12" Yellow and White VFT Mastic | 750               | SF             | Room 112 (Under New VFT) - 1956 |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |

| HA No | Material Description   | Material Quantity | Material Units | Material Location                  | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|------------------------|-------------------|----------------|------------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 25    | Linoleum--NOT OBSERVED | 0                 |                | Rooms 101, 103, 107 - NOT OBSERVED |               |                   |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description          | Material Quantity | Material Units | Material Location                        | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|-------------------------------|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 25A   | Linoleum Mastic--NOT OBSERVED | 0                 |                | Rooms 101, 103, 107 - 1953--NOT OBSERVED |               |                   |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |

| HA No | Material Description          | Material Quantity | Material Units | Material Location             | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|-------------------------------|-------------------|----------------|-------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 26    | 12"x12" Tan VFT--NOT OBSERVED | 0                 |                | Room 103 - 1953--NOT OBSERVED |               |                   |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description                     | Material Quantity | Material Units | Material Location                     | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|--|-------------------|----------------|---------------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 26A   | 12"x12" Tan VFT Mastic--<br>NOT OBSERVED | 850               | SF             | Room 103, 107 - 195--<br>NOT OBSERVED |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |

| HA No | Material Description | Material Quantity | Material Units | Material Location      | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------|-------------------|----------------|------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 27    | 12"x12" White VFT    | 1650              | SF             | Room 108, & 103 - 1953 |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description     | Material Quantity | Material Units | Material Location      | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|--------------------------|-------------------|----------------|------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 27A   | 12"x12" White VFT Mastic | 1650              | SF             | Room 108, & 103 - 1953 |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |

| HA No | Material Description         | Material Quantity | Material Units | Material Location    | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|------------------------------|-------------------|----------------|----------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 28    | 9"x9" Brown VFT (Under HA32) | 50                | SF             | Gym Vestibule - 1956 |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**



| HA No | Material Description                | Material Quantity | Material Units | Material Location    | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|-------------------------------------|-------------------|----------------|----------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 28A   | 9"x9" Brown VFT Mastic (Under HA32) | 50                | SF             | Gym Vestibule - 1956 |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |

| HA No | Material Description       | Material Quantity | Material Units | Material Location    | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------------|-------------------|----------------|----------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 29    | 12"x12" Brown w/ Beige VFT | 50                | SF             | Gym Vestibule - 1956 |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description              | Material Quantity | Material Units | Material Location    | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|-----------------------------------|-------------------|----------------|----------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 29A   | 12"x12" Brown w/ Beige VFT Mastic | 50                | SF             | Gym Vestibule - 1956 |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |

| HA No | Material Description             | Material Quantity | Material Units | Material Location              | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------------------|-------------------|----------------|--------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 30    | 12"x12" Tan w/ White Streaks VFT | 800               | SF             | Library (Under New VFT) - 1956 |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description                    | Material Quantity | Material Units | Material Location              | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|---|-------------------|----------------|--------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 30A   | 12"x12" Tan w/ White Streaks VFT Mastic | 800               | SF             | Library (Under New VFT) - 1956 |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |

| HA No | Material Description | Material Quantity | Material Units | Material Location                                 | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 31    | 12"x12" White VFT    | 0                 | SF             | Corridor, Eng. Office and Cust. Lockerroom - 1956 |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description     | Material Quantity | Material Units | Material Location                                 | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|--------------------------|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 31A   | 12"x12" White VFT Mastic | 3500              | SF             | Corridor, Eng. Office and Cust. Lockerroom - 1956 |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |

| HA No | Material Description                                    | Material Quantity | Material Units | Material Location    | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|---|-------------------|----------------|----------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 32    | 12"x12" Beige w/ Brown & White Streaks VFT (Over HA 28) | 50                | SF             | Gym Vestibule - 1956 |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description   | Material Quantity | Material Units | Material Location    | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|--|-------------------|----------------|----------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 32A   | 12"x12" Beige w/ Brown & White Streaks VFT Mastic (Over HA 28) | 50                | SF             | Gym Vestibule - 1956 |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |

| HA No | Material Description                           | Material Quantity | Material Units | Material Location                 | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|--|-------------------|----------------|-----------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 33    | 12"x12" Beige w/ Red Streaks VFT(under carpet) | 300               | SF             | Main Office (Under Carpet) - 1956 |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description                                 | Material Quantity | Material Units | Material Location  | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|--|-------------------|----------------|--------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 33A   | 12"x12" Beige w/ Red Streaks VFT Mastic UNDER CARPET | 300               | SF             | Main Office - 1956 |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |

| HA No | Material Description                               | Material Quantity | Material Units | Material Location                    | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|--|-------------------|----------------|--------------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 35    | 12"x12" Grey w/ Black, White, & Orange Streaks VFT | 1500              | SF             | Room 114, 116 (Under New VFT) - 1956 |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description                              | Material Quantity | Material Units | Material Location                    | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|---|-------------------|----------------|--------------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 35A   | 12"x12" Grey w/ Blk, Wht & Orange Stks VFT Mastic | 1500              | SF             | Room 114, 116 (Under New VFT) - 1956 |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 36    | 12"x12" Brown VFT    | 2500              | SF             | Corridor - 1953   |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description     | Material Quantity | Material Units | Material Location                | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|--------------------------|-------------------|----------------|----------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 36A   | 12"x12" Brown VFT Mastic | 2500              | SF             | Corridor, Room 108 Toilet - 1953 |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 37    | 12"x12" Brown VFT    | 1500              | SF             | Corridor - 1956   |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**



| HA No | Material Description     | Material Quantity | Material Units | Material Location  | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|--------------------------|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 37A   | 12"x12" Brown VFT Mastic | 3500              | SF             | Corridor, Rooms 110, 121, Eng. Office & Cust. Locker Room - 1956 |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |

| HA No | Material Description   | Material Quantity | Material Units | Material Location            | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|------------------------|-------------------|----------------|------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 38    | Linoleum--NOT OBSERVED | 0                 |                | Library - 1956--NOT OBSERVED |               |                   |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description          | Material Quantity | Material Units | Material Location            | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|-------------------------------|-------------------|----------------|------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 38A   | Linoleum Mastic--NOT OBSERVED | 0                 |                | Library - 1956--NOT OBSERVED |               |                   |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |

| HA No | Material Description              | Material Quantity | Material Units | Material Location                                  | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|-----------------------------------|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 39    | 12"x12" White w/ Gray Streaks VFT | 2800              | SF             | Rooms 100, 101, 102, 104, Teachers Restroom - 1953 |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description                     | Material Quantity | Material Units | Material Location                                  | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|--|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 39A   | 12"x12" White w/ Grey Streaks VFT Mastic | 2800              | SF             | Rooms 100, 101, 102, 104, Teachers Restroom - 1953 |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |

| HA No | Material Description                          | Material Quantity | Material Units | Material Location                     | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|---|-------------------|----------------|---------------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 40    | 12"x12" White w/ Beige Streaks --NOT OBSERVED | 0                 | SF             | Room 107, & Corridor --- NOT OBSERVED |               | Miscellaneous     |         | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description                              | Material Quantity | Material Units | Material Location                      | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|---|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 40A   | 12"x12" White w/ Beige Streaks VFT --NOT OBSERVED | 0                 |                | Room 107, & Corridor - -- NOT OBSERVED |               |                   |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |

| HA No | Material Description             | Material Quantity | Material Units | Material Location          | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------------------|-------------------|----------------|----------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 41    | 12"x12" Grey w/ Blue Streaks VFT | 2100              | SF             | Rooms 118, 120, 122 - 1956 |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description                    | Material Quantity | Material Units | Material Location          | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|---|-------------------|----------------|----------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 41A   | 12"x12" Grey w/ Blue Streaks VFT Mastic | 2100              | SF             | Rooms 118, 120, 122 - 1956 |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 42    | 12"x12" Tan VFT      | 350               | SF             | Room 110 - 1956   |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description   | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 42A   | 12"x12" Tan VFT Mastic | 350               | SF             | Room 110 - 1956   |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |

| HA No | Material Description              | Material Quantity | Material Units | Material Location  | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|-----------------------------------|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 43    | 12"x12" White w/ Grey Streaks VFT | 0                 | SF             | Rooms 111, 112, 113, 114, 115, 116, 117, 119, Principal Office (over ha's 2, 10, 35, 8, 33) & Main Office - 1956 |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description                     | Material Quantity | Material Units | Material Location  | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|--|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 43A   | 12"x12" White w/ Grey Streaks VFT Mastic | 0                 | SF             | Rooms 111, 112, 113, 114, 115, 116, 117, 119, Principal Office (over ha's 2, 10, 35, 8, 33) & Main Office - 1956 |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description                             | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|--|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 44    | 12 x 12 inch Lt Brown w/white & Dark Streaks VFT | 1000              | SF             | Room 105          |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |

| HA No | Material Description                               | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|--|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 44 A  | 12 x 12 inch Lt Brn w/White & Drk Strks VFT Mastic | 1000              | SF             | Room 105          |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**



| HA No | Material Description          | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|-------------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 45    | 12 x 12 inch White w/Grey VFT | 2000              | SF             | Rooms             |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |

| HA No | Material Description                 | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|--------------------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 45 A  | 12 x 12 inch White w/Grey VFT Mastic | 2000              | SF             | Class Rooms       |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description                            | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|---|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 46    | 12 x 12 inch White w/Blue Red & Brn Streaks VFT | 800               | SF             | Library           |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |

| HA No | Material Description                               | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|--|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 46 A  | 12 x 12 in White w/Blue Red & Brn Strks VFT Mastic | 800               | SF             | Library           |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description                | Material Quantity | Material Units | Material Location       | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|-------------------------------------|-------------------|----------------|-------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 47    | 1 x 1 ft Ceiling Tiles with Grooves | 25000             | SF             | Throughout - 1956 Bldg. |               | Miscellaneous     | Yes     | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |

| HA No | Material Description | Material Quantity | Material Units | Material Location     | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------|-------------------|----------------|-----------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 48    | 1'x1' Ceiling tile   | 7500              | SF             | Throughout 1953 Bldg. |               | Miscellaneous     | Yes     | Dist        | 6               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description        | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|-----------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 48A   | 1'x1' Ceiling tile (MASTIC) | 7500              | SF             | Throughout        |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |

| HA No | Material Description              | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|-----------------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 49    | 12"x12" white w/ gray streaks VFT | 700               | SF             | Main office       |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description                     | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|--|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 49A   | 12"x12" white w/ gray streaks VFT MASTIC | 700               | SF             | Main Office       |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |

| HA No | Material Description | Material Quantity | Material Units | Material Location  | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------|-------------------|----------------|--------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 50    | Carpet MASTIC        | 200               | SF             | Principal's office |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 51    | Fire door            | 6                 | EA             |                   |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |

| HA No | Material Description               | Material Quantity | Material Units | Material Location        | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|------------------------------------|-------------------|----------------|--------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 52    | 12"x12" white w/ beige streaks VFT | 4000              | SF             | room 103,110,107,121,108 |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description                     | Material Quantity | Material Units | Material Location        | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|--|-------------------|----------------|--------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 52A   | 12"x12" white w/beige streaks VFT MASTIC | 4000              | SF             | room 103,110,107,121,108 |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |

| HA No | Material Description               | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|------------------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 53    | 12"x12" brown w/ beige streaks VFT | 1000              | SF             | rm 107, 121       |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description                      | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|---|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 53A   | 12"x12" brown w/ beige streaks VFT MASTIC | 1000              | SF             | rm 107, 121       |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |

| HA No | Material Description    | Material Quantity | Material Units | Material Location  | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|-------------------------|-------------------|----------------|--------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| A     | Aircell Pipe Insulation | 600               | LF             | Pipe Chases - 1953 |               | TSI               | Yes     | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**



| HA No | Material Description      | Material Quantity | Material Units | Material Location  | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|---------------------------|-------------------|----------------|--------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| B     | Mag Block Pipe Insulation | 0                 |                | Boiler Room - 1953 |               | TSI               | Yes     | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |

| HA No | Material Description      | Material Quantity | Material Units | Material Location  | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|---------------------------|-------------------|----------------|--------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| C     | Cardboard Pipe Insulation | 200               | LF             | Pipe Chases - 1953 |               | TSI               | Yes     | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description           | Material Quantity | Material Units | Material Location  | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|--------------------------------|-------------------|----------------|--------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| D     | MJP on Aircell Pipe Insulation | 30                | LF             | Pipe Chases - 1953 |               | TSI               | Yes     | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |

| HA No | Material Description             | Material Quantity | Material Units | Material Location  | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------------------|-------------------|----------------|--------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| E     | MJP on Cardboard Pipe Insulation | 25                | LF             | Pipe Chases - 1953 |               | TSI               | Yes     | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description            | Material Quantity | Material Units | Material Location  | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|---------------------------------|-------------------|----------------|--------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| G     | Boiler Insulation (Abated 2002) |                   |                | Boiler Room - 1953 |               | Miscellaneous     |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |

| HA No | Material Description          | Material Quantity | Material Units | Material Location                                  | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|-------------------------------|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| H     | Transite Panels (Abated 2002) | 1000              | SF             | Room 101, 102, 103, 104, 105, 106, 107, 108 - 1953 |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description              | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|-----------------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| K     | MJP on Fiberglass Pipe Insulation | 0                 | LF             | Crawlspace - 1953 |               | TSI               | Yes     | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| L     | Hard Coat Plaster    | 0                 | SF             | Throughout - 1953 |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| M     | Hard Coat Plaster    | 0                 | SF             | Throughout - 1956 |               | Miscellaneous     | No      | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |

| HA No | Material Description    | Material Quantity | Material Units | Material Location  | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|-------------------------|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| N     | Aircell Pipe Insulation | 1000              | LF             | Mens Toliet, Womens Toliet, Mens Toliet Chase, Girls Toliet Chase, Boys Toliet, Cust. Locker Ro 1956 |               | TSI               | Yes     | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description           | Material Quantity | Material Units | Material Location  | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|--------------------------------|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| O     | MJP on Aircell Pipe Insulation | 100               | LF             | Mens Toliet, Womens Toliet, Mens Toliet Chase, Girls Toliet Chase, Boys Toliet, Cust Locker Roo 1956 |               | TSI               | Yes     | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description      | Material Quantity | Material Units | Material Location                       | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|---------------------------|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| P     | Cardboard Pipe Insulation | 30                | LF             | Girls Toilet Chase, Cust. Locker - 1956 |               | TSI               | Yes     | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |

| HA No | Material Description             | Material Quantity | Material Units | Material Location                            | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|----------------------------------|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| Q     | MJP on Cardboard Pipe Insulation | 30                | LF             | Girls Toilet Chase, Cust. Locker Room - 1956 |               | TSI               | Yes     | None        | 0               |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

| HA No | Material Description                            | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category   |
|-------|---|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| R     | MJP on Fiberglass Pipe Insulation (Abated 2002) |                   |                | Crawlspace - 1956 |               | TSI               |         |             |                 |              | <input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO |

|                           |
|---------------------------|
| 2016 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Fall: No Change    |
| Comments:                 |
|                           |
| 2017 - Spring: No Change  |
| Comments:                 |
|                           |
| 2018 - Fall: No Change    |
| Comments:                 |
|                           |
| 2018 - Spring : No Change |
| Comments:                 |
|                           |

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**



*ALL LEA Responsibilities, for this school, will be met.*



---

Robert Christlieb

***VFT = Vinyl Floor Tile***

***Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.***

NOTICE TO PARENTS AND STAFF REGARDING THE  
ASBESTOS MANAGEMENT PLAN NOTIFICATION

School: Hannah G Solomon Elementary School

Date: 1/7/2019

---

This is to notify you in accordance with Illinois and Federal Asbestos Regulations, that a copy of the Asbestos Management Plan is available at each school during school hours by appointment. Requests to review the Asbestos Management Plan must be made at least 24 hours in advance.

Also please be advised that CPS conducts asbestos inspections of all Schools every three years. The last inspection was completed in 2016. Asbestos surveillances are conducted every six months.

CHECK ONE

- A copy of this notice was sent home in each child's backpack.
- A copy of this notice was printed in the school's newsletter and sent home with each child
- A copy of this notice was printed in the school's calendar and sent home with each child
- Other.
- 

A COPY OF THIS NOTICE MUST BE PLACED IN THE  
SCHOOL'S ASBESTOS MANAGEMENT PLAN.

***VFT = Vinyl Floor Tile***

***Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.***