Chicago Public Schools

6 Month Asbestos Surveillance 2018 - Fall

Stephen F Gale Elementary Community Academy 31081 3480 School: **Oracle Unit: Building ID:** Address: 1631 W Jonquil Terrace Region: 01 Mail Room: Asbestos Surveyor: Falasz, Mike X CHECK HERE IF NO CHANGE TO ASBESTOS Survey Date: 12/17/2018 Email Address: A copy of the 2016/2017 notice to parents and staff regarding the asbestos management plan notifications was distributed via: Notice printed in school's newsletter Each child's backpack Notice printed in school's calendar Other HA No Material Description Material Location Asbestos Friable Damage Damage Change in Assessment Category Material Material Damage Quantity Units Type Category Quantity Type Room 311, 311 Kitchen, 12"x12" White w/ Black YES X NO 01 SF 6138 Auditorium & Balcony -Miscellaneous No Loc 3 Specks VFT 1921 2016 - Fall: No Change Comments: 2017 - Fall: No Change Comments: 2017 - Spring: No Change Comments: 2018 - Fall: No Change Comments:

Page 1

02	12"x12" White w/ Black Specks VFT Mastic	6138	SF	Room 311, 311 Kitchen, Auditorium & Balcony - 1921	Miscellaneous	No	None	0	YES	X NO
2016 - Fall: N	o Change		<u> </u>							
Comments:	o onange									
2017 - Fall: N	o Change									
Comments:										
2017 - Spring	: No Change									
Comments:										
2018 - Fall: N	o Change									
Comments:										

Type

Material

Category

Friable

Damage

Туре

Damage

Quantity

Damage

Units

Change in Assessment Category

Oracle Unit: 31081

Page 2

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
03	12"x12" Brown w/ White & Brown Specks VFT	1620	SF	Room 201, 208 - 1921		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No

Material Description

Material

Quantity

Material

Units

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Categor
04	12"x12" Brown w/ White & Brown Specks VFT Mastic	1620	SF	Room 201, 208 - 1921		Miscellaneous	No	None	0		YES X NO
2016 - Fall: N	lo Change										

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
05	12"x12" Cream w/ Light Brown Specks VFT	425	SF	Room 107 (Under HA 46 & 46A) - 1921		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessm	nent Category
06	12"x12" Cream w/ Light Brown Specks VFT Mastic	425	SF	Room 107 (Under HA 46 & 46A) - 1921		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change				1							

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
07	12"x12" Dark Tan w/ White Specks VFT	425	SF	Room 107 (Under HA 46 & 46 A) - 1921		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Categor
08	12"x12" Dark Tan w/ White Specks VFT Mastic	425	SF	Room 107 (Under HA 46 & 46 A) - 1921		Miscellaneous	No	None	0		YES X NO
2016 - Fall: N	lo Change										

[
2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
09	12"x12" Gray w/ White Specks VFT	275	SF	Main Office Public Area - 1921		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

Page 5

10	12"x12" Gray w/ White Specks VFT Mastic	275	SF	Main Office Public Area - 1921		Miscellaneous	No	None	0		YES	X NO
2016 Falls	No Changa				1							
2016 - Fall:	No Change											
Comments:												
2017 - Fall:	No Change											
Comments:												
2017 - Sprir	ng: No Change											
Comments:												
					1							
2018 - Fall:	No Change											
Comments:	<u> </u>											
					-							
,					-							
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Assessi	ment Category

Type

Type

Material

Category

Category

Miscellaneous

Friable

No

Damage

Type

Type

None

Damage

Quantity

Quantity

0

Damage

Units

Units

YES

	1321	
2016 - Fall: No Change		
Comments:		
2017 - Fall: No Change		
Comments:		
2017 - Spring: No Change		
Comments:		
2018 - Fall: No Change		
Comments:		

Quantity

415

Units

SF

HA No

11

Material Description

9"x9" Brown w/ Cream

Stripes VFT

Material

Units

Material

Quantity

Material Location

Principal's Office & Main

Office (Under HA # 44) -

Change in Assessment Category

X NO

12	9"x9" Brown w/ Cream Stripes VFT Mastic	415	SF	Principal's Office & Main Office (Under HA # 44)- 1921		Miscellaneous	No	None	0		YES	X NO
		•	•	•		•	•	•	•	•	•	
2016 - Fall	: No Change											
Comments	::											
2017 - Fall	: No Change				1							
Comments);											
	-				7							
2017 - Spr	ing: No Change				1							
Comments):				1							
2018 - Fall	: No Change				1							
Comments	s:				1							
					_							
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Assess	sment Category
		Quantity	Units		Type	Category		Type	Quantity	Units		

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

Change in Assessment Category

X NO

YES

13	Brown Linoleum	0	Counselor Office (Under HA # 44) - 1921
2016 - Fall: N	lo Change		
Comments:			
2017 - Fall: N	lo Change		
Comments:			
2017 - Spring	g: No Change		
Comments:			
2018 - Fall: N	lo Change		
Comments:			

Material

Quantity

Material

Units

Material Location

Principal's Office & Main Office (Under HA # 44)-

HA No

Material Description

	14	Brown Linoleum Mastic	0		Counselor Office (Under HA # 44) - 1921							YES	X NO
Γ	2016 - Fall: N	o Change]							
_	Comments:	<u> </u>											
-	2017 - Fall: N	o Change				1							
_	Comments:	J											
-	2017 - Spring	: No Change				1							
	Comments:	<u> </u>											
F	2018 - Fall: N	o Change				1							
	Comments:	•											
L						J							
Γ	HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos	Material Category	Friable	Damage	Damage Quantity	Damage Units	Change in Assess	ment Category
L			Quantity	Units		Туре	Category		Туре	Quantity	Units		
	15	Hard Coat Plaster	0		Throughout - 1921							YES	X NO

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

Material Location

Counselor Office (Under

HA No

2016 - Fall: No Change

Material Description

Material

Quantity

Material

Units

16	Drywall Joint Compound	0		Throughout - 1978							YES	X NO
2016 - Fall:	No Change				7							
Comments:												
2017 - Fall:	No Change											
Comments:												
	g: No Change											
Comments:					_							
2018 - Fall:	No Change											
Comments:												
					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category

Type

Material

Category

Miscellaneous

No

Friable

Damage

Туре

None

0

Damage

Quantity

Damage

Units

Change in Assessment Category

			1978
2016 - Fall: No	o Change		
Comments:			
2017 - Fall: No	o Change		
Comments:			
2017 - Spring:	: No Change		
Comments:			
2018 - Fall: No	o Change		
Comments:			

5380

SF

HA No

17

Material Description

12"x12" Blue VFT

Material

Quantity

Material

Units

Material Location

Lunchroom, &

Lunchroom Upper Hall, 2nd Floor Teachers

Lunchroom Bathrooms-

YES

X NO

18 12"x12" Blue VFT Mastic 5380 SF Lunchroom Upper Hall, 2nd Floor Teachers Lunchroom Bathrooms-1978 Miscellaneous No None 0	HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
	18	12"x12" Blue VFT Mastic	5380	SF	Lunchroom Upper Hall, 2nd Floor Teachers Lunchroom Bathrooms-		Miscellaneous	No	None	0		YES	X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	
19	12"x12" Brown VFT	100	SF	Lunchroom- 1978		Miscellaneous	No	None	0		YES X NO	

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
20	12"x12" Brown VFT Mastic	100	SF	Lunchroom- 1978		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	o Change											

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	
21	12"x12" Beige VFT	100	SF	Main Office (Under HA # 44) - 1921		Miscellaneous	No	None	0		YES X NO	

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

2016 - Fall:	No Change										
Comments:	<u> </u>										
2017 - Fall:	No Chango										
Comments:	No Change										
2017 Caria	a. No Chango										
Comments:	ig: No Change				_						
2018 - Fall:	No Change										
Comments:											
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Assessment Category
TIANO	waterial Description	Quantity	Units	Matchai Eocation	Type	Category	Thable	Type	Quantity	Units	Change in Assessment Category

Type

Material

Category

Miscellaneous

Friable

No

Damage

Туре

None

Damage

Quantity

0

Damage

Units

23	2'x4' Ceiling Tile	0	Kitchen, Kitchen Office, Kitchen Prep Area - 1978							
2016 - Fall: No Change										
Comments:	Comments:									
2017 - Fall:	2017 - Fall: No Change									
Comments:										
2017 - Spri	ng: No Change									
Comments:										
2018 - Fall: No Change										
Comments:	Comments:									

Material

Quantity

100

Material

Units

SF

Material Location

44) - 1921

Main Office (Under HA #

HA No

22

Material Description

12"x12" Beige VFT Mastic

Page 12

Change in Assessment Category

YES

YES

X NO

X NO

29	12" X 12" Cream w/ Blue & Purple Specks VFT	16000	SF	Throughout 1st, 2nd, 3rd, 4th floors & Elevator - 1998		Miscellaneous	No	None	0		YES	X NO
					7	•	•		•			
2016 - Fall:	No Change											
Comments												
					1							
2017 - Fall:	No Change											
Comments	•				1							
2017 - Spri	ng: No Change											
Comments	•											
0040 F-II	N. Observe											
	No Change											
Comments												
]							
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Assess	ment Category

Type

Type

Material

Category

Category

Miscellaneous

Friable

No

Damage

Type

Type

None

Damage

Quantity

Quantity

0

Damage

Units

Units

			1990
2016 - Fall: No Ch	nange		
Comments:			
2017 - Fall: No Ch	nange		
Comments:			
2017 - Spring: No	Change		
Comments:			
2018 - Fall: No Ch	nange		
Comments:			

Quantity

16000

Units

SF

HA No

30

Material Description

12" X 12" Cream w/ Blue &

Purple Specks VFT Mastic

Material

Units

Material

Quantity

Material Location

Throughout 1st, 2nd, 3rd,

4th floors & Elevator -

Change in Assessment Category

X NO

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
31	12" X 12" Blue VFT	1700	SF	Throughout 1st, 2nd, 3rd, 4th floors - 1998		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change											

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
32	12" X 12" Blue VFT Mastic	1700	SF	Throughout 1st, 2nd, 3rd, 4th floors - 1998		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

33	2' x 4' Ceiling Tile	34000	SF	Throughout - 1998	Miscellaneous	No	None	0	YES	X NO
2016 - F	all: No Change									
Comme	nts:									
	all: No Change									
Comme	nts:									
2017 - S	pring: No Change									
Comme	nts:									
2018 - F	all: No Change									
Comme	nts:									

Type

Material

Category

Damage Quantity Damage

Units

Change in Assessment Category

Damage

Туре

Friable

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
34	2' x 2' Ceiling Tile	2100	SF	Kitchen - 1998		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

Material

Quantity

Material

Units

Material Location

HA No

Material Description

35	Grey Linoleum	800	SF	Kitchen Serving Area - 1998		Miscellaneous	No	None	0	YES	X NO
2016 - Fall: N	o Change										
Comments:	Comments:										
2017 - Fall: N	2017 - Fall: No Change										
Comments:											
2017 - Spring	: No Change										
Comments:											
2018 - Fall: N	o Change										
Comments:											

Type

Material

Category

Friable

Damage

Туре

Damage

Quantity

Damage

Units

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
36	Grey Linoleum Mastic	800	SF	Kitchen Serving Area - 1998		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

Material

Quantity

Material

Units

HA No

Material Description

37	Spray on Fireproofing	26000	SF	Throughout - 1998		Surface	Yes	None	0		YES	X NO
2016 - Fall	: No Change											
Comments	~											
2017 - Fall	: No Change											
Comments												
2017 - Spri	ing: No Change											
Comments	:											
2018 - Fall	: No Change											
Comments	:											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category

Type

Material

Miscellaneous

Category

Friable

No

Damage

Туре

None

Damage

Quantity

0

Damage

Units

2016 - Fall: N	o Change										
Comments:											
2017 - Fall: N	o Change										
Comments:											
2017 - Spring	: No Change										
Comments:											
2018 - Fall: N	o Change										
Comments:											

3500

Material

Quantity

Material

Units

LF

Material Location

Throughout - 1998

HA No

38

Material Description

Baseboard

YES

X NO

39	Baseboard Mastic	3500	LF	Throughout - 1998		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	No Change				1							
Comments:	<u> </u>]							
2017 - Fall:	2017 - Fall: No Change											
Comments:	-]										
2017 - Sprin	g: No Change				-							
Comments:												
2018 - Fall:	No Change				-							
Comments:												
					J							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category

Type

Material

Category

Friable

Damage

Туре

Damage

Quantity

Damage

Units

40	Drywall	500	SF	Throughout - 1998	Miscellaneous	Yes	None	0
2016 - Fall: N	lo Change							
2017 - Fall: N	lo Change							
2017 - Spring	g: No Change							
Comments:								

HA No

2018 - Fall: No Change

Comments:

Material Description

Material

Quantity

Material

Units

Material Location

YES

X NO

											-
2016 - Fall: N	No Change										
Comments:	to onange										
2017 - Fall: N	No Change										
Comments:	_										
2017 - Spring	g: No Change										
Comments:											
2018 - Fall: N	No Change										
Comments:											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category

Type

Material

Category

Miscellaneous

Miscellaneous

Friable

Yes

No

Damage

Type

None

None

Damage

Quantity

0

0

Damage

Units

1500

HA No

41

42

Material Description

Drywall Joint Compound

Light Blue Rubber Flooring

Material

Units

LF

SF

Material Quantity

100

Material Location

Throughout -1998

Gym - 1998

Change in Assessment Category

X NO

X NO

YES

43	Light Blue Rubber Flooring Mastic	1500	SF	Gym - 1998		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	No Change											
Comments:	<u> </u>											
2017 - Fall:	No Change											
Comments:					1							
2017 - Sprir	ng: No Change				_							
Comments:					=							
2018 - Fall:	No Change											
Comments:					 							
					1							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category

Type

Material

Category

Miscellaneous

No

Friable

Damage

Type

None

0

Damage

Quantity

Damage

Units

44	Carpet Mastic	1200	SF	Office, Counselors Office, Room 103 & Engineers Office - 1921
2016 Fall:	No Change			
Comments				
2017 - Fall:	No Change			
Comments	•			
2017 - Spri	ng: No Change			
Comments				
2018 - Fall:	No Change			
Comments			•	
	_	•	•	

HA No

Material Description

Material

Quantity

Material

Units

Material Location

Principals Office, Main

Page 20

Change in Assessment Category

X NO

45	Carpet Mastic	1200	SF	Room 250 (Library) - 1998 Annex	Miscellaneous	No	None	0	YES	X NO
2016 - Fall: N	lo Change									
Comments:	io Change									
Comments.										
2017 - Fall: N	lo Change									
Comments:	_									
2017 - Spring	: No Change									
Comments:	•									
2018 - Fall: N	lo Change									
Comments:										

Type

Material

Category

Friable

Damage

Туре

Damage

Quantity

Damage

Units

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
46	12 x 12 inch Light Blue VFT	850	SF	Room 107-1921 Building		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No

Material Description

Material

Quantity

Material

Units

Oracle Unit: 31081

46A	12 x 12 inch Light Blue VFT Mastic	850	SF	Room 107-1921 Building		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	No Change]							
Comments:	<u> </u>											
2017 - Fall:	No Change											
Comments:	<u> </u>				1							
2017 - Sprin	ng: No Change											
Comments:]							
2018 - Fall:	No Change											
Comments:												
					J							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category
				1st through 4th Fl.								

Type

Material

Category

Miscellaneous

No

Friable

Damage

Type

None

0

Damage

Quantity

Damage

Units

15000

SF

HA No

47

Material Description

Terrazzo

Material

Quantity

Material

Units

Material Location

Corridors, Restrooms,

Stairwells & Vestibules -

Change in Assessment Category

X NO

2016 - Fall:	: No Change										
Comments	:										
	: No Change										
Comments	:										
2017 - Spri	ng: No Change										
Comments	:										
2018 - Fall:	: No Change										
Comments	:										
<u> </u>											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category

Type

Material

Category

Miscellaneous

Miscellaneous

Friable

No

No

Damage

Type

None

None

Damage

Quantity

0

0

Damage

Units

600

HA No

48

49

Material Description

Fire Doors

Carpet Mastic

Material

Quantity

16

Material

Units

EΑ

SF

Material Location

Stairwells - 1998 Bldgs.

Teacher's Lounge - 1978

Change in Assessment Category

X NO

X NO

YES

50	Decorative Plaster	1800	SF	Auditorium & Stage- 1921 bldg		Miscellaneous	No	None	0		YES	X NO
2016 - Fa	ıll: No Change				1							
Commen												
2017 - Fa	ıll: No Change											
Commen												
2017 - Sp	oring: No Change											
Commen	ts:											
2018 - Fa	III: No Change											
Commen	ts:											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
51	Terrazzo	5356	SF	1st Floor Corridors, Entrance Vestibules.		Miscellaneous	No	None	0		YES	X NO

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

HA No

Material Description

Material

Quantity

Material

Units

Material Location

Toilet under the stairs -

1921 bldg

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
52	12" x 12" Sand VFT	180	SF	Lunchroom Hallway - 1978 bldg		Miscellaneous	No	None	0		YES X NO
2016 - Fall: N Comments:	lo Change										
2017 - Spring	ı: No Change										

Comments:

2017 - Fall: No Change
Comments:

2018 - Fall: No Change Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
52A	12" x 12" Sand VFT Mastic	180	SF	Lunchroom Hallway - 1978 bldg		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
53	12" X 12" Blue w/ Beige Specks VFT	200	SF	Teacher Toilet Rooms - 1978 Bldg		Miscellaneous	No	None	0		YES X NO
2016 - Fall: N	lo Change]						

2016 - Fall: No Change
Comments:
2047 F.II N. Ol
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
54	12" X 12" Blue w/ Beige Specks VFT Mastic	200	SF	Teacher Toilet Rooms - 1978 Bldg		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:

Page 26

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
В	MJP E/F/V on Fiberglass Pipe Insulation	216	LF	1st - 3rd Fir. Boy's & Girl's Toilets, Boiler Rm, E. and W. Air Tunnels, Tank Rm, Engine Rm- 1921		TSI	Yes	None	0		YES	X NO
2016 - Fall: N	o Change											

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
С	Cardboard Pipe Insulation	250	LF	Boiler Rm, Tank Rm, Coal Rm, Elect. Rm, 103 Tlt, Princ. Tlt, 2nd Flr Jan. closet by Boys Tlt -1921		TSI	Yes	Loc	5		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

	HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
	D	MJP E/F/V on Cardboard Pipe Insulation	99	LF	Boiler Rm, Tank Rm, Coal Rm, Elect. Rm, 103 Tlt, Princ. Tlt, 2nd Flr Jan. closet by Boys Tlt -1921		TSI	Yes	None	0		YES X NO
1	2010 = 11 11											

2016 - Fall: No Change
Comments:
2047 0 : N 01
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
Е	Aircell Pipe Insulation	1800	LF	Rm 105 Tlt, 1st Fl Jan Clst By Rm 105, Rm 102, 1st Fl Corr., Mn Offc, Basement- 1921		TSI	Yes	Dist	45		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
F	MJP E/F/V on Aircell Pipe Insulation	240	LF	Rm 105 Tlt, 1st Fl Jan Clst By Rm 105, Rm 102, 1st Fl Corr., Mn Offc, Basement- 1921		TSI	Yes	Dist	30		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
G	Boiler Gaskets #1 & #2	10	LF	Boiler Room- 1921		TSI	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:

Н	Pipe Insulation	2	LF	Teacher's Lounge - 1978		181	Yes	None	0		YES	X NO
2016 Fall:	No Change				7							
Comments:												
2017 - Fall:	No Change											
Comments:												
2017 - Sprir	ng: No Change											
Comments:					1							
2018 - Fall:	No Change											
Comments:	-				1							
					1							
					_							
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Assess	ment Category

Type

Material

TSI

Category

Friable

Yes

Damage

Type

None

Damage

Quantity

0

Damage

Units

		Quantity	Units		Type	Category		Type	Quantity	Units		
1	Mag Block Tank Insulation	250	SF	Tank Room- 1921		TSI	Yes	None	0		YES	X NO
2016 - Fall: No Comments: 2017 - Spring: Comments:	· ·											

2017 - Fall: No Change Comments: 2018 - Fall: No Change Comments:

HA No

Н

Material Description

MJP E/F/V on Fiberglass

Material

Quantity

2

Material

Units

LF

Material Location

Teacher's Lounge - 1978

Change in Assessment Category

X NO

ALL LEA Responsibilities, for this school, will be met.

Robert Christlieb

NOTICE TO PARENTS AND STAFF REGARDING THE ASBESTOS MANAGEMENT PLAN NOTIFICATION

School: Stephen F Gale Elementary Community Academy
Date: 12/17/2018
This is to notify you in accordance with Illinois and Federal Asbestos Regulations, that a copy of the Asbestos Management Plan is available at each school during school hours by appointment. Requests to review the Asbestos Management Plan must be made at least 24 hours in advance.
Also please be advised that CPS conducts asbestos inspections of all Schools every three years. The last inspection was completed in 2016. Asbestos surveillances are conducted every six months.
CHECK ONE
A copy of this notice was sent home in each child's backpack.
A copy of this notice was printed in the school's newsletter and sent home with each child
A copy of this notice was printed in the school's calendar and sent home with each child
Other.
A COPY OF THIS NOTICE MUST BE PLACED IN THE

VFT = Vinyl Floor Tile
Oracle Unit: 31081

SCHOOL'S ASBESTOS MANAGEMENT PLAN.