

Chicago Public Schools

6 Month Asbestos Surveillance

2018 - Fall

School: Lincoln Park High School
Address: 2001 N. Orchard

Oracle Unit: 46321
Region: 02

Building ID: 1620
Mail Room: 33

CHECK HERE IF NO CHANGE TO ASBESTOS

Asbestos Surveyor: Nixon, Ricky
Survey Date: 1/10/2019
Email Address: rnixon1@cps.edu

A copy of the 2016/2017 notice to parents and staff regarding the asbestos management plan notifications was distributed via:
 Each child's backpack
 Notice printed in school's newsletter
 Notice printed in school's calendar
 Other

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
37-01	12"x12" Tan w/ Brown & White Specks VFT	14410	SF	1st, 2nd & 3rd Floor Corridors, Room 102 Corridors, Room 102 - 1937		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:n/a
2017 - Spring: No Change
Comments:
2018 - Fall: Abated
Comments:n/a
2018 - Spring : No Change
Comments:n/a

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
37-02	12"x12" Tan w/ Brown & White Specks VFT Mastic	14410	SF	1st, 2nd & 3rd Floor Corridors, Room 102 - 1937		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:n/a
2018 - Fall: Abated
Comments:n/a
2018 - Spring : No Change
Comments:n/a

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
37-03	12"x12" Gray w/ Gray Streaks VFT	3603	SF	2nd Floor Teachers Lounge, Office By Room 207, 207A & Boy's Locker Room - 1937		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:n/a
2018 - Spring : No Change
Comments:n/a
2018 - Fall: Abated
Comments:n/a

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
37-04	12"x12" Gray w/ Gray Streaks VFT Mastic	3603	SF	2nd Floor Teachers Lounge, Office By Room 207, & Boy's Locker Room - 1937		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:n/a
2018 - Fall: Abated
Comments:n/a
2018 - Spring : No Change
Comments:n/a

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
37-05	12"x12" Beige w/ Brown & White Speckles VFT	7236	SF	Rooms 208, 111,103A; NOT OBERVED in Girls Locker Room - 1937		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:n/a
2018 - Fall: Abated
Comments:n/a
2018 - Spring : No Change
Comments:n/a

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
37-06	12"x12" Beige w/ Brown & White Speckles VFT Mastic	7236	SF	Rooms 208, 111,103A; NOT OBSERVED in Girls Locker Room - 1937 Bldg		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:n/a
2018 - Fall: Abated
Comments:n/a
2018 - Spring : No Change
Comments:n/a

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
37-07	12"x12" Off White w/ Tan Streaks VFT	1319	SF	Main Office & Room 101 - 1937		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2016 - Fall: No Change
Comments:
2017 - Fall: Abated
Comments:n/a
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:n/a
2018 - Fall: Abated
Comments:n/a

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
37-08	12"x12" Off White w/ Tan Streaks VFT Mastic	1319	SF	Main Office & Room 101 - 1937		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: Abated
Comments:n/a
2018 - Fall: Abated
Comments:n/a
2018 - Spring : No Change
Comments:n/a

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
37-09	12"x12" Black w/ White Streaks VFT NOT OBSERVED			Main Office - 1937 (Not Observed)		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2016 - Fall: No Change
Comments:
2017 - Fall: Abated
Comments:n/a
2017 - Spring: No Change
Comments:
2018 - Fall: Abated
Comments:n/a
2018 - Spring : No Change
Comments:n/a

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
37-10	12"x12" Black w/ White Streaks VFT Mastic NOT OBSERVED			Main Office - 1937 (Not Observed)		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: Abated
Comments:n/a
2018 - Spring : No Change
Comments:n/a
2018 - Fall: Abated
Comments:n/a

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
37-11	12"x12" Tan w/ Gray Streaks VFT	10	SF	Hallway By Principal's Stairs, Main Office - 1937		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:n/a
2018 - Spring : No Change
Comments:n/a
2018 - Fall: Abated
Comments:n/a

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
37-12	12"x12" Tan w/ Gray Streaks VFT Mastic	10	SF	Hallway By Principal's Stairs; Main Office - 1937		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:n/a
2018 - Fall: Abated
Comments:n/a
2018 - Spring : No Change
Comments:n/a

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
37-15	9"x9" Brown w/ Gray Streaks VFT	12	SF	Room 103 Rear Office - 1937 Bldg		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2016 - Fall: No Change
Comments:
2017 - Fall: Abated
Comments:n/a
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:n/a
2018 - Fall: Abated
Comments:n/a

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
37-16	9"x9" Brown w/ Gray Streaks VFT Mastic	12	SF	Room 103 Rear Office - 1937 Bldg		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: Abated
Comments:n/a
2018 - Fall: Abated
Comments:n/a
2018 - Spring : No Change
Comments:n/a

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
37-17	9"x9" Green w/ White Streaks VFT	491	SF	Room 100A, 100, Room 102 , Room 102 Vault - 1937		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:n/a
2018 - Fall: Abated
Comments:n/a
2018 - Spring : No Change
Comments:n/a

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
37-18	9"x9" Green w/ White Streaks VFT Mastic	400	SF	Room 100A, 100, 102, Room 102 Vault - 1937		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:n/a
2018 - Fall: Abated
Comments:n/a
2018 - Spring : No Change
Comments:n/a

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
37-19	9"x9" Gray w/ White Streaks VFT	400	SF	Room 102, 100A, 100 - 1937		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:n/a
2017 - Spring: No Change
Comments:
2018 - Fall: Abated
Comments:n/a
2018 - Spring : No Change
Comments:n/a

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
37-20	9"x9" Gray w/ White Streaks VFT Mastic	400	SF	Room 102, 100A, 100 - 1937		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:n/a
2018 - Spring : No Change
Comments:n/a
2018 - Fall: Abated
Comments:n/a

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
37-21	2'x2' Off White Ceiling Tile	4500	SF	Room 308, 301, 111, 312, 106 Throughout - 1937		Miscellaneous	Yes	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:n/a
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:n/a
2018 - Fall: Abated
Comments:n/a

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
37-22	Paperwrap Pipe Insulation	1678	LF	Boy's & Girl's Toilets Pipe Chases, Swimming Pool, Tunnels, & N, W, & E 232 Office Principals Office; Crawlspace - 1937		TSI	Yes	Dist	100		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2016 - Fall: No Change
Comments:
2017 - Spring: Abated
Comments:removed 2012
2017 - Fall: Abated
Comments:n/a
2018 - Fall: Abated
Comments:n/a
2018 - Spring : No Change
Comments:n/a

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
37-23	MJP E/F/V on Paperwrap Pipe Insulation	390	LF	Boy's & Girl's Toilets Pipe Chases, Swimming Pool, Tunnels, & N, W, & E Crawlspace - 1937		TSI	Yes	Dist	50		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2016 - Fall: No Change
Comments:
2017 - Fall: Abated
Comments:n/a
2017 - Spring: Abated
Comments:removed 2012
2018 - Fall: Abated
Comments:n/a
2018 - Spring : No Change
Comments:n/a

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
37-24	MJP E/F/V on Fiberglass Pipe Insulation	300	SF	106, Pool, Tunnels, Crawlspace, Rifle Storage, Engine Room, Plenum C - 1937		TSI	Yes	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:n/a
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:n/a
2018 - Spring : No Change
Comments:n/a

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
37-25	Mag Block Pipe Insulation	2845	LF	Swimming Pool, NS Air Tunnel, NE Crawlspace, Rifle Range & Storage, GMV, Eng Rm, & Plenum - 1937		TSI	Yes	Dist	375		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2016 - Fall: No Change
Comments:
2017 - Fall: Abated
Comments:n/a
2017 - Spring: No Change
Comments:
2018 - Fall: Abated
Comments:n/a
2018 - Spring : No Change
Comments:n/a

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
37-26	MJP E/F/V on Mag Block Pipe Insulation	164	LF	Swimming Pool, NS Air Tunnel, NE Crawlspace, Rifle Range & Storage, GMV, Eng Rm, & Plenum - 1937		TSI	Yes	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: Abated
Comments:n/a
2018 - Fall: Abated
Comments:n/a
2018 - Spring : No Change
Comments:n/a

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
37-27	Air Cell Duct Insulation	6450	SF	West & NW Crawl Spaces, Rifle Range & Storage - 1937		TSI	Yes	Dist	100		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: Abated
Comments:n/a
2018 - Fall: No Change
Comments:n/a
2018 - Spring : No Change
Comments:n/a

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
37-28	Aircell Pipe Insulation	3077	LF	Basement Corridor, Throughout - 1937 Bldg (See Hatching Maps)		TSI	Yes	Dist	10		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: Abated
Comments:n/a
2018 - Spring : No Change
Comments:n/a
2018 - Fall: No Change
Comments:n/a

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
37-29	MJP E/F/V on Aircell Pipe Insulation	465	LF	Throughout - 1937 (See Hatching Maps)		TSI	Yes	Dist	5		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:n/a
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:n/a
2018 - Fall: No Change
Comments:n/a

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
37-30	Hard Coat Plaster	120000	SF	Throughout - 1937		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:n/a
2018 - Fall: No Change
Comments:n/a
2018 - Spring : No Change
Comments:n/a

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
37-31	Exterior Window Caulk	30000	SF	Throughout - 1937		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:n/a
2018 - Fall: No Change
Comments:n/a
2018 - Spring : No Change
Comments:n/a

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
37-37	Exterior Window Caulk	30000	SF	Throughout - 1937		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:n/a
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:n/a
2018 - Spring : No Change
Comments:n/a

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
37-38	Terrazo	2000	SF	Stairwells - 1937 bldg.		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:n/a
2018 - Spring : No Change
Comments:n/a
2018 - Fall: No Change
Comments:n/a

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
37-39	Carpet Mastic	4000	SF	1937 - Bldg., Library and Main Office, 207A, 103, 100 Corridor		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2016 - Fall: No Change
Comments:
2017 - Fall: Abated
Comments:n/a
2017 - Spring: Abated
Comments:removed 2012
2018 - Spring : No Change
Comments:n/a
2018 - Fall: Abated
Comments:n/a

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
37-40	12 x 12 Mixed Gray Speckled VFT	1200	SF	114K, 134B, 134C Bldg 1937		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:n/a
2018 - Spring : No Change
Comments:n/a
2018 - Fall: Abated
Comments:n/a

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
37-41	12 x 12 Mixed Gray Speckled Mastic	1200	SF	114 K, 134 B, 134 C Bldg 1937		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:n/a
2018 - Spring : No Change
Comments:n/a
2018 - Fall: Abated
Comments:n/a

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
37-42	Beige Linoleum & Mastic	700	SF	Rm 304 Bldg 1937		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:n/a
2017 - Spring: No Change
Comments:
2018 - Fall: Abated
Comments:n/a
2018 - Spring : No Change
Comments:n/a

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
37-43	Beige Linoleum & Mastic	700	SF	Rm 304 Bldg 1937		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:n/a
2018 - Fall: Abated
Comments:n/a
2018 - Spring : No Change
Comments:n/a

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
37-44	14 x 14 Gray w/ Black Spots VFT	500	SF	Auditorium Lobby Bldg 1937		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: Abated
Comments:n/a
2018 - Fall: Abated
Comments:n/a
2018 - Spring : No Change
Comments:n/a

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
37-45	14 x 14 Gray w/ Black Spots Mastic	500	SF	Auditorium Lobby Bldg 1937		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2016 - Fall: No Change
Comments:
2017 - Fall: Abated
Comments:n/a
2017 - Spring: No Change
Comments:
2018 - Fall: Abated
Comments:n/a
2018 - Spring : No Change
Comments:n/a

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
37-46	2 x 2 Ceiling Tile	1000	SF	Rm 308, 301 Bldg 1937		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:n/a
2018 - Fall: Abated
Comments:n/a
2018 - Spring : No Change
Comments:n/a

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
37-47	14 x 14 Blue Speckled VFT	700	SF	Auditorium Bldg 1937		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2016 - Fall: No Change
Comments:
2017 - Fall: Abated
Comments:n/a
2017 - Spring: No Change
Comments:
2018 - Fall: Abated
Comments:n/a
2018 - Spring : No Change
Comments:n/a

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
37-48	14 x 14 Blue Specked Mastic	700	SF	Auditorium Bldg 1937		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2016 - Fall: No Change
Comments:
2017 - Fall: Abated
Comments:n/a
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:n/a
2018 - Fall: Abated
Comments:n/a

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
37-49	12 x 12 Mixed Beige Speckled VFT	1575	SF	Rm 308, 206, 110, 108 Bldg 1937		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:n/a
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:n/a
2018 - Fall: Abated
Comments:n/a

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
37-50	12 x 12 Mix Beige Speckled Mastic	1575	SF	Rm 208, 206, 110, 108 Bldg 1937		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:n/a
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:n/a
2018 - Fall: Abated
Comments:n/a

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
38	12 x 12 Off White with Tan Streaks VFT	1000	SF	162A and B, Councillor's Office		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: Abated
Comments:n/a
2018 - Spring : No Change
Comments:n/a
2018 - Fall: Abated
Comments:n/a

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
39	12 x 12 Off White with Tan Streaks Mastic	1000	SF	162A and B, Councillor's Office		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: Abated
Comments:n/a
2018 - Spring : No Change
Comments:n/a
2018 - Fall: Abated
Comments:n/a

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
40	Linoleum	6300	SF	172 (PKA 152), 252, 257, 250, 251, 253, and Library		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:n/a
2018 - Spring : No Change
Comments:n/a
2018 - Fall: No Change
Comments:n/a

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
41	Linoleum Adhesive	6300	SF	172 (PKA 152), 252, 257, 250, 251, 253 and Library		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:n/a
2018 - Spring : No Change
Comments:n/a
2018 - Fall: No Change
Comments:n/a

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
42	Tan Linoleum	700	SF	Room 121, Room 262 & 265		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:n/a
2018 - Spring : No Change
Comments:n/a
2018 - Fall: No Change
Comments:n/a

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
43	Tan Linoleum Adhesive	700	SF	Room 121; Room 262 & 265		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:n/a
2018 - Spring : No Change
Comments:n/a
2018 - Fall: No Change
Comments:n/a

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
44	2' x 4' Lay In Ceiling Panels	700	SF	Room 121; 110, 109, 108		Miscellaneous	Yes	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:n/a
2018 - Spring : No Change
Comments:n/a
2018 - Fall: No Change
Comments:n/a

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
45	Insulation in Walls and Vault Door	91	SF	Room 102		TSI	Yes	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:n/a
2018 - Spring : No Change
Comments:n/a
2018 - Fall: Abated
Comments:n/a

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
46	2' x 4' Lay In Ceiling Panels	500	SF	Room 153		Miscellaneous	Yes	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:n/a
2018 - Spring : No Change
Comments:n/a
2018 - Fall: Abated
Comments:n/a

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
47	Linoleum	305	SF	1899 - Science Copy Room		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:n/a
2018 - Spring : No Change
Comments:n/a
2018 - Fall: Abated
Comments:n/a

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
48	Linoleum Adhesive	305	SF	1899 - Science Copy Room		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:n/a
2018 - Spring : No Change
Comments:n/a
2018 - Fall: Abated
Comments:n/a

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
49	12 x 12 Green with White Floor Tile (NOT OBSERVED)	126	SF	Room 102		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:n/a
2018 - Spring : No Change
Comments:n/a
2018 - Fall: Abated
Comments:n/a

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
50	12 x 12 Green with White Floor Tile Adhesive (NOT OBSERVED)	126	SF	Room 102		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:n/a
2018 - Spring : No Change
Comments:n/a
2018 - Fall: Abated
Comments:n/a

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
51	12 x 12 Gray with White Floor Tile (NOT OBSERVED)	126	SF	Room 102		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:n/a
2018 - Spring : No Change
Comments:n/a
2018 - Fall: Abated
Comments:n/a

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
52	12 x 12 Gray with White Floor Tile Mastic (NOT OBSERVED)	126	SF	Room 102 (Not Observed)		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:n/a
2018 - Spring : No Change
Comments:n/a
2018 - Fall: Abated
Comments:n/a

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
53	12 x 12 Gray with Gray Floor Tile	20	SF	Room 102		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:n/a
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:n/a
2018 - Fall: Abated
Comments:n/a

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
53A	12 x 12 Gray with Gray Floor Tile Mastic	20	SF	Room 102		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:n/a
2018 - Spring : No Change
Comments:n/a
2018 - Fall: Abated
Comments:n/a

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
54	12 x 12 Ceiling Tile	750	SF	Room 111		Miscellaneous	Yes	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:n/a
2018 - Spring : No Change
Comments:n/a
2018 - Fall: No Change
Comments:n/a

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
55	12 x 12 Light Blue with White and Brown Streaks Floor Tile	750	SF	Room 111		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2016 - Fall: No Change
Comments:
2017 - Spring: Abated
Comments:removed 2012
2017 - Fall: No Change
Comments:n/a
2018 - Spring : No Change
Comments:n/a
2018 - Fall: No Change
Comments:n/a

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
56	12 x 12 Light Blue with White and Brown Streaks Mastic	750	SF	Room 111		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2016 - Fall: No Change
Comments:
2017 - Spring: Abated
Comments:removed 2012
2017 - Fall: No Change
Comments:n/a
2018 - Spring : No Change
Comments:n/a
2018 - Fall: No Change
Comments:n/a

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
61-01	12"x12" White w/ Grey Speckles VFT			1st Floor West Corridor By Lobby - 1961		Miscellaneous	No	None			<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:n/a
2017 - Spring: No Change
Comments:
2018 - Fall: Abated
Comments:n/a
2018 - Spring : No Change
Comments:n/a

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
61-02	12"x12" White w/ Gray Speckles VFT Mastic			1st Floor West Corridor By Lobby - 1961		Miscellaneous		None			<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:n/a
2017 - Spring: No Change
Comments:
2018 - Fall: Abated
Comments:n/a
2018 - Spring : No Change
Comments:n/a

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
61-03	12"x12" Black w/ White Speckles VFT	1200	SF	1st Floor West Corridor By Lobby - 1961		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:n/a
2017 - Spring: No Change
Comments:
2018 - Fall: Abated
Comments:n/a
2018 - Spring : No Change
Comments:n/a

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
61-04	12"x12" Black w/ White Speckles VFT Mastic	1200	SF	1st Floor West Corridor By Lobby - 1961		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:n/a
2018 - Fall: Abated
Comments:n/a
2018 - Spring : No Change
Comments:n/a

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
61-05	12"x12" Black w/ White Streaks VFT-NOT OBSERVED	620	SF	Auditorium - 1937 (Not observed)		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2016 - Fall: No Change
Comments:
2017 - Fall: Abated
Comments:n/a
2017 - Spring: Abated
Comments:removed 2012
2018 - Fall: Abated
Comments:n/a
2018 - Spring : No Change
Comments:n/a

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
61-06	12"x12" Black w/ White Streaks VFT Mastic NOT OBSERVED	620	SF	Auditorium - 1937 (Not Observed)		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2016 - Fall: No Change
Comments:
2017 - Spring: Abated
Comments:removed 2012
2017 - Fall: Abated
Comments:n/a
2018 - Fall: Abated
Comments:n/a
2018 - Spring : No Change
Comments:n/a

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
61-07	12"x12" Coffee w/ White & Brown Streaks VFT	3200	SF	Room 108, Room 257 & North Corridor - 1961		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:n/a
2018 - Fall: Abated
Comments:n/a
2018 - Spring : No Change
Comments:n/a

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
61-08	12"x12" Coffee w/ White & Brown Streaks VFT Mastic	3200	SF	Room 108 & North Corridor - 1961		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:n/a
2018 - Spring : No Change
Comments:n/a
2018 - Fall: Abated
Comments:n/a

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
61-09	12"x12" Red VFT	6700	SF	Lunchroom - 1937		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:n/a
2018 - Spring : No Change
Comments:n/a
2018 - Fall: Abated
Comments:n/a

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
61-10	12"x12" Red VFT Mastic	6700	SF	Lunchroom - 1937		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:n/a
2018 - Fall: Abated
Comments:n/a
2018 - Spring : No Change
Comments:n/a

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
61-11	9"x9" Black w/ White Streaks VFT-NOT OBSERVED	434	SF	West Stairwell & Auditorium Stairwell - 1937 (Not Observed)		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2016 - Fall: No Change
Comments:
2017 - Spring: Abated
Comments:removed 2012
2017 - Fall: Abated
Comments:n/a
2018 - Spring : No Change
Comments:n/a
2018 - Fall: Abated
Comments:n/a

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
61-12	9"x9" Brown w/ White Streaks VFT NOT OBSERVED	360	SF	Auditorium Balcony - 1937 (Not Observed)		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2016 - Fall: No Change
Comments:
2017 - Spring: Abated
Comments:removed 2012
2017 - Fall: Abated
Comments:n/a
2018 - Spring : No Change
Comments:n/a
2018 - Fall: Abated
Comments:n/a

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
61-13	9"x9" Brown w/ White Streaks VFT Mastic NOT OBSERVED	360	SF	Auditorium Balcony - 1937 (Not Observed)		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2016 - Fall: No Change
Comments:
2017 - Spring: Abated
Comments:removed 2012
2017 - Fall: Abated
Comments:n/a
2018 - Spring : No Change
Comments:n/a
2018 - Fall: Abated
Comments:n/a

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
61-14	9"x9" Gray w/ White Streaks VFT Not Observed in Rooms 109 & 110	2561	SF	Teacher's Lunchroom; Not Observed in Rooms 109 & 110 - 1937		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:n/a
2018 - Spring : No Change
Comments:n/a
2018 - Fall: Abated
Comments:n/a

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
61-15	9"x9" Gray w/ White Streaks VFT Mastic	2561	SF	Teacher's Lunchroom; Not Observed in Rooms 109 & 110 - 1937		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:n/a
2017 - Spring: No Change
Comments:
2018 - Fall: Abated
Comments:n/a
2018 - Spring : No Change
Comments:n/a

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
61-16	Black w/ White Streaks Linoleum NOT OBSERVED			East and West Stairwells, Auditorium Stairwell - 1961		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:n/a
2017 - Spring: Abated
Comments:removed 2012
2018 - Fall: Abated
Comments:n/a
2018 - Spring : No Change
Comments:n/a

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
61-17	Black w/ White Streaks Linoleum Mastic NOT OBSERVED			East and West Stairwells, Auditorium Stairwell - 1961		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2016 - Fall: No Change
Comments:
2017 - Spring: Abated
Comments:removed 2012
2017 - Fall: No Change
Comments:n/a
2018 - Spring : No Change
Comments:n/a
2018 - Fall: Abated
Comments:n/a

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
61-18	2'x2' White Speckled w/ Inch Wormy Ceiling Tile	10000	SF	2nd Floor West Corridor - 1961		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: Abated
Comments:n/a
2018 - Spring : No Change
Comments:n/a
2018 - Fall: Abated
Comments:n/a

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
61-19	1'x1' White Ceiling Tile	7000	SF	2nd Fl NW & SW Stairwells, Auditorium, Room 108, 109 & 110 - 1961		Miscellaneous	Yes	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: Abated
Comments:n/a
2018 - Fall: Abated
Comments:n/a
2018 - Spring : No Change
Comments:n/a

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
61-20	1'x1' Off White w/ Speckles Ceiling Tile	6700	SF	Lunchroom - 1961		Miscellaneous	Yes	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:n/a
2018 - Fall: Abated
Comments:n/a
2018 - Spring : No Change
Comments:n/a

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
61-21	1'x1' Off White w/ Large Wormy Ceiling Tile	6700	SF	Teachers Lunchroom by Kitchen - 1961		Miscellaneous	Yes	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:n/a
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:n/a
2018 - Fall: Abated
Comments:n/a

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
61-22	Air Cell Pipe Insulation	935	LF	NW & NE Crawlspace & Paint Storage - 1961		TSI	Yes	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:n/a
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:n/a
2018 - Fall: Abated
Comments:n/a

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
61-23	MJP E/F/V on Air Cell Pipe Insulation	48	LF	NW & NE Crawlspace & Paint Storage - 1961		TSI	Yes	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:n/a
2017 - Spring: No Change
Comments:
2018 - Fall: Abated
Comments:n/a
2018 - Spring : No Change
Comments:n/a

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
61-24	Mag Block Pipe Insulation	2500	LF	NE Crawlspace - 1961		TSI	Yes	Dist	50		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:n/a
2018 - Fall: Abated
Comments:n/a
2018 - Spring : No Change
Comments:n/a

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
61-25	MJP E/F/V on Mag Block Pipe Insulation	100	LF	NE Crawlspace - 1961		TSI	Yes	Dist	20		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:n/a
2017 - Spring: No Change
Comments:
2018 - Fall: Abated
Comments:n/a
2018 - Spring : No Change
Comments:n/a

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
61-26	Paperwrap Pipe Insulation	350	LF	NE Crawlspace - 1961		TSI	Yes	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:n/a
2017 - Spring: No Change
Comments:
2018 - Fall: Abated
Comments:n/a
2018 - Spring : No Change
Comments:n/a

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
61-27	MJP E/F/V on Paperwrap Pipe Insulation	37	LF	NE Crawlspace - 1961		TSI	Yes	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:n/a
2018 - Fall: Abated
Comments:n/a
2018 - Spring : No Change
Comments:n/a

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
61-28	Aircell Duct Insulation	100	SF	Paint Storage Room - 1961		TSI	Yes	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:n/a
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:n/a
2018 - Fall: Abated
Comments:n/a

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
61-29	9"x9" Black w/ White Streaks VFT Mastic	434	SF	West Stairwell & Auditorium Stairwell - 1961		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:n/a
2017 - Spring: No Change
Comments:
2018 - Fall: Abated
Comments:n/a
2018 - Spring : No Change
Comments:n/a

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
61-30	Carpet Mastic	1000	SF	1961 FA - Engineer's Office and CPS area office, 182		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: Abated
Comments:n/a
2018 - Spring : No Change
Comments:n/a
2018 - Fall: Abated
Comments:n/a

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
61-31	2' x 2' Dot Wave Ceiling Tile (NOT OBSERVED)	500	SF	1961 - FA - Room 153		Miscellaneous					<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:n/a
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:n/a
2018 - Fall: Abated
Comments:n/a

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
61-32	Lab Counter Tops	200	SF	Rm 252, 251 Bldg 1961		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:n/a
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:n/a
2018 - Spring : No Change
Comments:n/a

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
61-33	9 x 9 VFT Gray w/ white streaks	40	SF	Rm 258A Bldg 1961		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:n/a
2018 - Spring : No Change
Comments:n/a
2018 - Fall: Abated
Comments:n/a

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
61-34	9 x 9 Mastic Gray w/ white streaks	40	SF	Rm 258A Bldg 1961		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:n/a
2017 - Spring: No Change
Comments:
2018 - Fall: Abated
Comments:n/a
2018 - Spring : No Change
Comments:n/a

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
61-35	12 x 12 Gray Speckled VFT	500	SF	Rm 163C Bldg 1961		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: Abated
Comments:n/a
2018 - Fall: Abated
Comments:n/a
2018 - Spring : No Change
Comments:n/a

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
61-36	12 x 12 Gray Speckled Mastic VFT	500	SF	Rm 163C Bldg 1961		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: Abated
Comments:n/a
2018 - Fall: Abated
Comments:n/a
2018 - Spring : No Change
Comments:n/a

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
61-37	12 x 12 Mixed Beige Speckled VFT	1000	SF	Rm 180 and 180 A Bldg 1961		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2016 - Fall: No Change
Comments:
2017 - Fall: Abated
Comments:n/a
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:n/a
2018 - Fall: Abated
Comments:n/a

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
61-38	12 x 12 Mixed Beige Mastic	1000	SF	Rm 180 and 180A Bldg 1961		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2016 - Fall: No Change
Comments:
2017 - Fall: Abated
Comments:n/a
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:n/a
2018 - Fall: Abated
Comments:n/a

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
61-39	12 x 12 Brown Speckled VFT	500	SF	Rms 170 and 172 Bldg 1961		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:n/a
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:n/a
2018 - Fall: Abated
Comments:n/a

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
61-40	12 x 12 Brown Speckled Mastic	500	SF	Rms 170 and 172 Bldg 1961		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:n/a
2018 - Fall: Abated
Comments:n/a
2018 - Spring : No Change
Comments:n/a

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
61-41	12 x 12 Blue w/ Black and white Specs VFT	600	SF	Rms 154 Bldg 1961		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2016 - Fall: No Change
Comments:
2017 - Fall: Abated
Comments:n/a
2017 - Spring: No Change
Comments:
2018 - Fall: Abated
Comments:n/a
2018 - Spring : No Change
Comments:n/a

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
61-42	12 x 12 Blue w/ Black and white Specs Mastic	600	SF	Rm 154 Bldg 1961		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2016 - Fall: No Change
Comments:
2017 - Fall: Abated
Comments:n/a
2017 - Spring: No Change
Comments:
2018 - Fall: Abated
Comments:n/a
2018 - Spring : No Change
Comments:n/a

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
99-01	12"x12" Gray w/ White Specks VFT	12635	SF	1st, 2nd, & 3rd Floor Corridors, 2nd Fl Womens Toilet, Rooms 229, 125, & 113A (Not Observed)- 1899		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:n/a
2018 - Spring : No Change
Comments:n/a
2018 - Fall: Abated
Comments:n/a

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
99-02	12"x12" Gray w/ White Specks VFT Mastic	12635	SF	1st, 2nd, & 3rd Floor Corridors, 2nd Fl Womens Toilet, Rooms 229, 125, & 113A(Not Observed) - 1899		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:n/a
2018 - Spring : No Change
Comments:n/a
2018 - Fall: Abated
Comments:n/a

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
99-03	12"x12" White w/ Gray Specks VFT	780	SF	Room 215 - 1899		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:n/a
2018 - Fall: Abated
Comments:n/a
2018 - Spring : No Change
Comments:n/a

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
99-04	12"x12" White w/ Gray Specks VFT Mastic	780	SF	Room 215 - 1899		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2016 - Fall: No Change Comments:
2017 - Fall: No Change Comments:n/a
2017 - Spring: No Change Comments:
2018 - Fall: Abated Comments:n/a
2018 - Spring : No Change Comments:n/a

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
99-05	12"x12" Beige w/ Brown Specks VFT	5200	SF	Rooms 223, 217, 219, 217A, 224, & storage 217B & C - 1899		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2016 - Fall: No Change Comments:
2017 - Fall: No Change Comments:n/a
2017 - Spring: No Change Comments:
2018 - Spring : No Change Comments:n/a
2018 - Fall: Abated Comments:n/a

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
99-06	12"x12" Beige w/ Brown Specks VFT Mastic	5200	SF	Rooms 223, 217, 219, 217A, 224, & 224 Storage (Not Observed) 217B & C - 1899		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:n/a
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:n/a
2018 - Fall: Abated
Comments:n/a

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
99-07	12"x12" Light Brown w/ Brown & White Specks VFT	2465	SF	Rooms 113A (NOT OBSERVED), 14 & 122 - 1899		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:n/a
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:n/a
2018 - Fall: Abated
Comments:n/a

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
99-08	12"x12" Lt Brn w/ Brown & White Specks VFT Mastic	2465	SF	Rooms 113A & 122(NOT OBSERVED), 14 - 1899		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:n/a
2018 - Fall: Abated
Comments:n/a
2018 - Spring : No Change
Comments:n/a

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
99-09	12"x12" Brown w/ White Streaks VFT	800	SF	Room 112 (NOT OBSERVED), 14 - 1899		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:n/a
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:n/a
2018 - Fall: Abated
Comments:n/a

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
99-10	12"x12" Brown w/ White Streaks VFT Mastic	800	SF	Room 112, 14 - 1899		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:n/a
2017 - Spring: No Change
Comments:
2018 - Fall: Abated
Comments:n/a
2018 - Spring : No Change
Comments:n/a

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
99-11	12"x12" Off White w/ Light Brown Streaks VFT	2555	SF	Room 14 Foyer, 29, 23 - 1899		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:n/a
2018 - Fall: Abated
Comments:n/a
2018 - Spring : No Change
Comments:n/a

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
99-12	12"x12" Off White w/ Light Brn Streaks VFT Mastic	2555	SF	Room 14 Foyer, 29, 23 (NOT OBSERVED) - 1899		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:n/a
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:n/a
2018 - Fall: Abated
Comments:n/a

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
99-13	9"x9" Tan w/ Brown & White Streaks VFT	11670	SF	Throughout - 1899 (See Hatching Maps) 119, 114 A & B & C, D,E, F, G, 022, 032, 036, Counselors Corridor		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:n/a
2018 - Spring : No Change
Comments:n/a
2018 - Fall: Abated
Comments:n/a

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
99-14	9"x9" Tan w/ Brown & White Streaks VFT Mastic	11670	SF	Throughout - 1899 (See Hatching Maps)		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:n/a
2017 - Spring: No Change
Comments:
2018 - Fall: Abated
Comments:n/a
2018 - Spring : No Change
Comments:n/a

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
99-15	9"x9" Green w/ White Streaks VFT (NOT OBSERVED)	305	SF	Science Copy Room - 1899		Miscellaneous					<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2016 - Fall: No Change
Comments:
2017 - Fall: Abated
Comments:n/a
2017 - Spring: No Change
Comments:
2018 - Fall: Abated
Comments:n/a
2018 - Spring : No Change
Comments:n/a

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
99-16	9"x9" Green w/ White Streaks VFT Mastic (NOT OBSERVED)	305	SF	Science Copy Room - 1899		Miscellaneous		None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2016 - Fall: No Change
Comments:
2017 - Fall: Abated
Comments:n/a
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:n/a
2018 - Fall: Abated
Comments:n/a

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
99-17	9"x9" Tan VFT	1930	SF	Room 14 (Under HA 99-10) (Not Observed)- 1899		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:n/a
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:n/a
2018 - Fall: Abated
Comments:n/a

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
99-18	9"x9" Tan VFT Mastic	1930	SF	Room 14 (Under HA 99-10) (Not Observed)- 1899		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:n/a
2017 - Spring: No Change
Comments:
2018 - Fall: Abated
Comments:n/a
2018 - Spring : No Change
Comments:n/a

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
99-19	9"x9" Rust VFT	1930	SF	Room 14 (Under HA 99-10 and 99-17) (NOT OBSERVED) - 1899		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:n/a
2017 - Spring: No Change
Comments:
2018 - Fall: Abated
Comments:n/a
2018 - Spring : No Change
Comments:n/a

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
99-20	9"x9" Rust VFT Mastic	1930	SF	Room 14 (Under HA 99-10 and 99-17) (NOT OBSERVED) - 1899		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:n/a
2018 - Fall: Abated
Comments:n/a
2018 - Spring : No Change
Comments:n/a

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
99-21	2'x2' White w/ Wormy Grooves Ceiling Tile	1200	SF	Library, Work Room A & B, 221 (NOT OBSERVED) - 1899		Miscellaneous	Yes	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:n/a
2017 - Spring: No Change
Comments:
2018 - Fall: Abated
Comments:n/a
2018 - Spring : No Change
Comments:n/a

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
99-22	1'x1' White w/ Wormy Grooves Ceiling Tile	3200	SF	Room 217, 217 A & B, 221- 1899		Miscellaneous	Yes	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:n/a
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:n/a
2018 - Fall: Abated
Comments:n/a

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
99-23	2'x4' White w/ Wormy Grooves Ceiling Tile	1200	SF	Room 227 - 1899		Miscellaneous	Yes	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:n/a
2018 - Spring : No Change
Comments:n/a
2018 - Fall: Abated
Comments:n/a

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
99-24	2'x4' White w/ Pin Holes Ceiling Tile	400	SF	Engineers Office - 1899		Miscellaneous	Yes	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:n/a
2018 - Spring : No Change
Comments:n/a
2018 - Fall: Abated
Comments:n/a

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
99-25	Transite Table Tops (ABATED)			Rooms 23, 29, 124, 127, 129, 224, 229 - 1899 ABATED		Miscellaneous					<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:n/a
2018 - Spring : No Change
Comments:n/a
2018 - Fall: Abated
Comments:n/a

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
99-26	Paperwrap Pipe Insulation	708	LF	Throughout (See Hatching Maps) - 1899		TSI	Yes	Dist	80		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:n/a
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:n/a
2018 - Fall: Abated
Comments:n/a

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
99-27	MJP E/F/V on Paperwrap Pipe Insulation	77	LF	Throughout (See Hatching Maps) - 1899		TSI	Yes	Dist	5		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:n/a
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:n/a
2018 - Fall: Abated
Comments:n/a

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
99-28	Aircell Pipe Insulation	2940	LF	Rooms 127, 23, 27, 24, & Engineer's Office, Boiler Pump & Sprinkler Rms, Store Rm by 14 - 1899		TSI	Yes	Dist	50		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:n/a
2018 - Fall: Abated
Comments:n/a
2018 - Spring : No Change
Comments:n/a

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
99-29	MJP E/F/V on Aircell Pipe Insulation	587	LF	Rooms 127, 23, 27, 24, & Engineer's Office, Boiler Pump & Sprinkler Rms, Store Rm by 14 - 1899		TSI	Yes	Dist	10		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:n/a
2017 - Spring: No Change
Comments:
2018 - Fall: Abated
Comments:n/a
2018 - Spring : No Change
Comments:n/a

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
99-30	MJP E/F/V on Fiberglass Pipe Insulation	680	SF	Boiler & Tank Rooms, Basement Corridor, 127, 129, 124, 122, 29, 24 Closet, Engineers Office - 1899		TSI	Yes	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:n/a
2017 - Spring: No Change
Comments:
2018 - Fall: Abated
Comments:n/a
2018 - Spring : No Change
Comments:n/a

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
99-31	Mag Block Pipe Insulation	100	LF	Basement Corridor - 1899		TSI	Yes	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2016 - Fall: No Change
Comments:
2017 - Fall: Abated
Comments:n/a
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:n/a
2018 - Fall: Abated
Comments:n/a

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
99-32	MJP E/F/V on Mag Block Pipe Insulation	10	LF	Basement Corridor By Plenum Sliding Door - 1899		TSI	Yes	None	2		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: Abated
Comments:n/a
2018 - Spring : No Change
Comments:n/a
2018 - Fall: Abated
Comments:n/a

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
99-33	Water Tank Insulation	300	SF	Boiler Room - 1899		TSI	Yes	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: Abated
Comments:n/a
2018 - Fall: Abated
Comments:n/a
2018 - Spring : No Change
Comments:n/a

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
99-34	Hardcoat Plaster	100000	SF	Throughout - 1899		Surface	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:n/a
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:n/a
2018 - Fall: No Change
Comments:n/a

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
99-35	Exterior Window Caulk			Throughout - 1899		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:n/a
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:n/a
2018 - Fall: No Change
Comments:n/a

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
99-36	Beige Linoleum	6400	SF	Room 121 (Science Room) - 1899		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:n/a
2018 - Spring : No Change
Comments:n/a
2018 - Fall: No Change
Comments:n/a

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
99-37	Beige Linoleum Mastic	6400	SF	Room 121 (Science Room), 229A, 229, 127, 129, 124, 023, 027 - 1899		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:n/a
2018 - Spring : No Change
Comments:n/a
2018 - Fall: No Change
Comments:n/a

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
99-38	Gray Linoleum NOT OBSERVED	700	SF	1899 Bldg., 121 (Not Observed)		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:n/a
2018 - Spring : No Change
Comments:n/a
2018 - Fall: Abated
Comments:n/a

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
99-38A	Gray Linoleum Mastic- NOT OBSERVED	700	SF	1899 Bldg., Room 121 (Not Observed)		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:n/a
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:n/a
2018 - Fall: Abated
Comments:n/a

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
99-39	Terrazzo	3000	SF	Stairwells - 1899 Bldg.		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:n/a
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:n/a
2018 - Fall: No Change
Comments:n/a

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
99-40	Carpet Mastic	700	SF	1899 - Bldg. Room 112-Library		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: Abated
Comments:n/a
2018 - Fall: Abated
Comments:n/a
2018 - Spring : No Change
Comments:n/a

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
99-41	Black Lab Counter Tops	2200	SF	Rm 229, 224 Rm 121, 121C, 023, 027 Bldg 1899		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:n/a
2018 - Spring : No Change
Comments:n/a
2018 - Fall: No Change
Comments:n/a

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
99-42	Fume Hood	160	SF	Rms 224, 023, 027 Bldg 1899		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:n/a
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:n/a
2018 - Fall: Abated
Comments:n/a

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
99-43	12 x 12 Yellow Speckled VFT	1400	SF	Rm 213A, Rm 221, 113A		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: Abated
Comments:n/a
2018 - Fall: Abated
Comments:n/a
2018 - Spring : No Change
Comments:n/a

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
99-44	12 x 12 Yellow Speckled Mastic	1400	SF	Rm 213A Rm 221, 113 A Bldg 1899		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: Abated
Comments:n/a
2018 - Fall: Abated
Comments:n/a
2018 - Spring : No Change
Comments:n/a

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
99-45	12 x 12 Mixed Beige VFT	2150	SF	Rm 125, 125 Foyer, Rm 122 Bldg 1899		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:n/a
2018 - Fall: Abated
Comments:n/a
2018 - Spring : No Change
Comments:n/a

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
99-46	12 x 12 Mixed Beige Speckled Mastic	2150	SF	Rm 125, 125 Foyer, Rm 122 Bldg 1899		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:n/a
2017 - Spring: No Change
Comments:
2018 - Fall: Abated
Comments:n/a
2018 - Spring : No Change
Comments:n/a

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
99-47	12 x 12 Mixed Gray Speckled VFT		SF	1st Flr Counselor's Corridor, 3rd Flr Elevator Lobby, Basement Elevator Lobby		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:n/a
2018 - Fall: Abated
Comments:n/a
2018 - Spring : No Change
Comments:n/a

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
99-48	12 x 12 Mixed Gray Speckled Mastic		SF	1st Flr Counselor's Corridor, 3rd Flr Elevator Lobby. Basement Elevator Lobby Bldg 1937		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:n/a
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:n/a
2018 - Fall: Abated
Comments:n/a

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
99-49	Drywall System	400	SF	Rm 213A		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:n/a
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:n/a
2018 - Fall: Abated
Comments:n/a

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
FA-01	12"x12" Black w/ White Streaks VFT	8500	SF	1st & 2nd Floor Corridors - 1961FA		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:good
2017 - Fall: Abated
Comments:n/a
2018 - Fall: Abated
Comments:none
2018 - Spring : No Change
Comments:n/a

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
FA-02	12"x12" Black w/ White Streaks VFT Mastic	8500	SF	1st & 2nd Floor Corridors - 1961FA		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:good
2017 - Fall: Abated
Comments:n/a
2018 - Spring : No Change
Comments:n/a
2018 - Fall: Abated
Comments:none

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
FA-03	12"x12" White w/ Tan Streaks VFT	12800	SF	Band Rm, ROTC, 153, 151, 155, 157, 159, 161, 163A, 253 - 1961FA, 163B, 257, 172, 176A, 176		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:good
2017 - Fall: Abated
Comments:n/a
2018 - Fall: Abated
Comments:none
2018 - Spring : No Change
Comments:n/a

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
FA-04	12"x12" White w/ Tan Streaks VFT Mastic	12800	SF	Band Rm, ROTC, 153, 151, 155, 157, 159, 161, 163A, 253 - 1961FA		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:good
2017 - Fall: Abated
Comments:n/a
2018 - Fall: Abated
Comments:none
2018 - Spring : No Change
Comments:n/a

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
FA-05	12"x12" Cream w/ Tan & White Streaks VFT NOT OBSERVED	6300	SF	Gym - 1961FA (Not Observed)		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2016 - Fall: No Change
Comments:
2017 - Fall: Abated
Comments:n/a
2017 - Spring: No Change
Comments:good
2018 - Fall: No Change
Comments:none
2018 - Spring : No Change
Comments:n/a

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
FA-06	12"x12" Cream w/ Tan & White Streaks VFT Mastic NOT OBSERVED	6300	SF	Gym - 1961FA- (Not Observed)		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2016 - Fall: No Change
Comments:
2017 - Fall: Abated
Comments:n/a
2017 - Spring: No Change
Comments:good
2018 - Fall: No Change
Comments:none
2018 - Spring : No Change
Comments:n/a

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
FA-07	12"x12' White w/ Gray Speckles VFT	1600	SF	Lunch Room, 164 - 1961FA		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2016 - Fall: No Change
Comments:
2017 - Fall: Abated
Comments:n/a
2017 - Spring: No Change
Comments:good
2018 - Spring : No Change
Comments:n/a
2018 - Fall: Abated
Comments:none

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
FA-08	12"x12' White w/ Gray Speckles VFT Mastic	1600	SF	Lunch Room, 164 - 1961FA		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2016 - Fall: No Change
Comments:
2017 - Fall: Abated
Comments:n/a
2017 - Spring: No Change
Comments:good
2018 - Fall: Abated
Comments:none
2018 - Spring : No Change
Comments:n/a

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
FA-09	12"x12" Black w/ White Speckles VFT	1600	SF	Lunch Room, 164 - 1961FA		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:good
2017 - Fall: Abated
Comments:n/a
2018 - Fall: Abated
Comments:none
2018 - Spring : No Change
Comments:n/a

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
FA-10	12"x12" Black w/ White Speckles VFT Mastic	1600	SF	Lunch Room, 164 - 1961FA		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2016 - Fall: No Change
Comments:
2017 - Fall: Abated
Comments:n/a
2017 - Spring: No Change
Comments:
2018 - Fall: Abated
Comments:none
2018 - Spring : No Change
Comments:n/a

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
FA-11	9"x9" Beige w/ White Spots VFT	9475	SF	Throughout - 1961FA (See Hatching Maps) 253B		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:n/a
2017 - Spring: No Change
Comments:
2018 - Fall: Abated
Comments:none
2018 - Spring : No Change
Comments:n/a

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
FA-12	9"x9" Beige w/ White Spots VFT Mastic	9475	SF	Throughout - 1961FA (See Hatching Maps)		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:n/a
2017 - Spring: No Change
Comments:
2018 - Fall: Abated
Comments:none
2018 - Spring : No Change
Comments:n/a

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
FA-13	9"x9" Gray w/ Black Streaks VFT	104	SF	Closet by Boiler Room - 1961FA		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2016 - Fall: No Change
Comments:
2017 - Fall: Abated
Comments:n/a
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:n/a
2018 - Fall: Abated
Comments:n/a

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
FA-14	9"x9" Gray w/ Black Streaks VFT Mastic	104	SF	Closet by Boiler Room - 1961FA		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2016 - Fall: No Change
Comments:
2017 - Fall: Abated
Comments:n/a
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:n/a
2018 - Fall: Abated
Comments:n/a

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
FA-15	9"x9" Beige w/ Orange & White Spots VFT (NOT OBSERVED)	1900	SF	Rooms 252, Counselors Office, Library, 152-1961FA		Miscellaneous					<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2016 - Fall: No Change
Comments:
2017 - Fall: Abated
Comments:n/a
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:n/a
2018 - Fall: Abated
Comments:n/a

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
FA-16	9"x9" Beige w/ Orange & White Spots VFT Mastic (NOT OBSERVED)	1900	SF	Rooms 252, Counselors Office, Library, 152 - 1961FA		Miscellaneous					<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: Abated
Comments:n/a
2018 - Spring : No Change
Comments:n/a
2018 - Fall: Abated
Comments:n/a

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
FA-17	9"x9" Green w/ Black & White Streaks VFT (NOT OBSERVED)	104	SF	Closet by Boiler Room - 1961FA		Miscellaneous					<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2016 - Fall: No Change
Comments:
2017 - Fall: Abated
Comments:n/a
2017 - Spring: No Change
Comments:
2018 - Fall: Abated
Comments:n/a
2018 - Spring : No Change
Comments:n/a

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
FA-18	9"x9" Green w/ Black & White Streaks VFT Mastic (NOT OBSERVED)	104	SF	Closet by Boiler Room - 1961FA		Miscellaneous					<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: Abated
Comments:n/a
2018 - Fall: Abated
Comments:n/a
2018 - Spring : No Change
Comments:n/a

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
FA-19	9"x9" Black VFT	350	SF	2nd Floor Slop Sink - 1961FA 156 & 158 Foyer		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: Abated
Comments:n/a
2018 - Fall: Abated
Comments:n/a
2018 - Spring : No Change
Comments:n/a

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
FA-20	9"x9" Black VFT Mastic	350	SF	2nd Floor Slop Sink - 1961FA		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2016 - Fall: No Change
Comments:
2017 - Fall: Abated
Comments:n/a
2017 - Spring: No Change
Comments:
2018 - Fall: Abated
Comments:n/a
2018 - Spring : No Change
Comments:n/a

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
FA-23	1'x1' Small Hole Ceiling Tile NOT OBSERVED	20000	SF	Throughout 1961FA		Miscellaneous	Yes	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: Abated
Comments:n/a
2018 - Spring : No Change
Comments:n/a
2018 - Fall: Abated
Comments:n/a

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
FA-24	1'x1' Medium Hole Ceiling Tile	20000	SF	Throughout - 1961FA		Miscellaneous	Yes	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: Abated
Comments:n/a
2018 - Spring : No Change
Comments:n/a
2018 - Fall: Abated
Comments:n/a

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
FA-25	2'x2' Ceiling Tile	1600	SF	Lunch Room - 1961FA		Miscellaneous	Yes	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2016 - Fall: No Change
Comments:
2017 - Fall: Abated
Comments:n/a
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:n/a
2018 - Spring : No Change
Comments:n/a

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
FA-26	Mag Block Pipe Insulation	5165	SF	Boiler Room, All Crawlspace and Tunnels - 1961FA		TSI	Yes	Dist	500		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:n/a
2018 - Spring : No Change
Comments:n/a
2018 - Fall: No Change
Comments:n/a

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
FA-27	MJP E/F/V on Mag Block Pipe Insulation	285	LF	Boiler Room, All Crawlspace and Tunnels - 1961FA		TSI	Yes	Dist	100		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:n/a
2018 - Spring : No Change
Comments:n/a
2018 - Fall: No Change
Comments:n/a

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
FA-28	MJP E/V/F on Fiberglass Pipe Insulation	145	LF	Northwest Tunnel, Fan Room and Boiler Room - 1961 FA		TSI	Yes	Dist	50		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:n/a
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:n/a
2018 - Spring : No Change
Comments:n/a

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
FA-29	Paperwrap Pipe Insulation	1800	LF	Tunnels, Boiler Room, & Fan Room - 1961FA		TSI	Yes	Dist	400		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:n/a
2018 - Fall: No Change
Comments:n/a
2018 - Spring : No Change
Comments:n/a

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
FA-30	MJP E/F/V on Paperwrap Pipe Insulation	150	LF	Tunnels, Boiler Room, & Fan Room - 1961FA		TSI	Yes	Dist	50		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:n/a
2018 - Spring : No Change
Comments:n/a
2018 - Fall: No Change
Comments:n/a

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
FA-31	Exterior Window Caulk	300	LF	Throughout - 1961FA		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:n/a
2018 - Spring : No Change
Comments:n/a
2018 - Fall: No Change
Comments:n/a

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
FT-001	9x9 Beige Floor Tile	800	SF	Engineer's Office and Maintenance Room		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:good
2017 - Fall: No Change
Comments:n/a
2018 - Spring : No Change
Comments:n/a
2018 - Fall: No Change
Comments:none

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
FTM-001	9x9 Beige Floor Tile Mastic	800	SF	Engineer's Office and Maintenance Room		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:good
2017 - Fall: No Change
Comments:n/a
2018 - Spring : No Change
Comments:n/a
2018 - Fall: No Change
Comments:none

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

ALL LEA Responsibilities, for this school, will be met.



Robert Christlieb

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

NOTICE TO PARENTS AND STAFF REGARDING THE
ASBESTOS MANAGEMENT PLAN NOTIFICATION

School: Lincoln Park High School

Date: 1/21/2019

This is to notify you in accordance with Illinois and Federal Asbestos Regulations, that a copy of the Asbestos Management Plan is available at each school during school hours by appointment. Requests to review the Asbestos Management Plan must be made at least 24 hours in advance.

Also please be advised that CPS conducts asbestos inspections of all Schools every three years. The last inspection was completed in 2016. Asbestos surveillances are conducted every six months.

CHECK ONE

- A copy of this notice was sent home in each child's backpack.
- A copy of this notice was printed in the school's newsletter and sent home with each child
- A copy of this notice was printed in the school's calendar and sent home with each child
- Other.
-

A COPY OF THIS NOTICE MUST BE PLACED IN THE
SCHOOL'S ASBESTOS MANAGEMENT PLAN.

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.