Chicago Public Schools

6 Month Asbestos Surveillance 2018 - Fall

George Washington Carver Military Academy HS 46381 1850 School: **Oracle Unit: Building ID:** Address: 13100 S. Doty Region: Mail Room: Asbestos Surveyor: Brown, David X CHECK HERE IF NO CHANGE TO ASBESTOS Survey Date: 12/26/2018 Email Address: A copy of the 2016/2017 notice to parents and staff regarding the asbestos management plan notifications was distributed via: Notice printed in school's newsletter X Other notice Each child's backpack Notice printed in school's calendar HA No Material Description Material Location Friable Damage Change in Assessment Category Material Asbestos Material Damage Damage Quantity Units Type Category Quantity Type Lunchroom, Gym Office, YES X NO 12x12 Dark Brown Floor Attendance Room, 003A 14430 SF Miscellaneous No None 0 Auditorium Basement 2016 - Fall: No Change Comments: 2017 - Fall: No Change Comments: 2017 - Spring: No Change Comments: 2018 - Fall: No Change Comments: 2018 - Spring: No Change Comments:

003B	12x12 Tan Floor Tile	Attendance Room, Locker Rooms, Health Room, Drivers Ed Room		Miscellaneous			YES	X NO
			1					
2016 - Fall: N	lo Change							
Comments:								
2017 - Spring	g: No Change							
Comments:			1					
2017 - Fall: N	lo Change]					
Comments:]					
2018 - Spring	g : No Change							
Comments:	-		1					
2018 - Fall: N	lo Change							
Comments:								
			1					
			_					

Asbestos

Type

Material

Category

Damage Quantity Damage

Units

Change in Assessment Category

Damage

Туре

Friable

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
003C	12x12 Olive Green Floor Tile	5000	SF	Gym Balcony, Stairs, Elevators		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No

Material Description

Material

Quantity

Material

Units

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessme	ent Category
003D	12x12 Gray Floor Tile Mastic			Basement Corridors		Miscellaneous					YES	X NO
2016 - Fall:	: No Change											
Comments												
2017 - Fall:	: No Change											
Comments												
2017 - Spri	ng: No Change											
Comments	<u> </u>											
2018 - Fall:	: No Change											
Comments	:											
2018 - Spri	ng : No Change											
Comments												
IIA NI-	Material Description	Matarial	Matarial	Metavial Lagation	Ashastas	Name and all	Frieble	Damasa	Damana		Ohanna in Aassaans	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
003E	12x12 Off White Floor Tile			Room 109		Miscellaneous					YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
006A	12x12 Dark Brown Floor Tile Mastic	14430	SF	Lunchroom, Gym Office, Attendance Room, Auditorium Basement Hallway		Miscellaneous	No	None	0		YES X NO

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
006B	12x12 Tan FloorTile Mastic	10770	SF	139, Attendance Room, Locker Rooms, Gym Stairs, Balcony to Gym, Health Room, Drivers Ed Rm		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2010 0 1 11 01	
2018 - Spring : No Change	
Comments:	
2018 - Fall: No Change	
Comments:	
	·

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
006C	12x12 Olive Green Floor Tile Mastic	5000	SF	Gym Balcony, Stairs, Elevators Lobbies		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

006D	12x12 Gray Floor Tile Mastic	700	SF	Basement Corridors		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	No Change				1							
Comments:	. to onego											
2017 - Fall:	No Change											
Comments:	V											
2017 - Sprin	ng: No Change											
Comments:												
2018 - Fall:	No Change											
Comments:	_											
2018 - Sprin	ng : No Change				_							
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
006E	12x12 Off White Floor Tile Mastic	800	SF	Room 109		Miscellaneous	No	None	0		YES	X NO

Asbestos

Type

Material

Category

Friable

Damage

Type

Damage

Units

Damage

Quantity

Change in Assessment Category

Material

Units

Material

Quantity

Material Location

HA No

2016 - Fall: No Change

2017 - Spring: No Change

2018 - Spring : No Change

2017 - Fall: No Change

2018 - Fall: No Change

Comments:

Comments:

Comments:

Comments:

Comments:

Material Description

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	Assess	ment Category
013A	Brown Carpet Mastic			Hallway in Front of Office, Room 228, Auditorium and Band Room		Miscellaneous					YES		X NO
2016 - Fal	: No Change]								
Comments	S:												
2017 - Fal	: No Change				_								
Comments													
2017 - Spr	ing: No Change				_								
Comments					-								
					1								
2018 - Fall Comments	: No Change				1								
Comment). 												
	ing : No Change												
Comments	S:				_								
					1								
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in	Assess	ment Category
013B	Blue Carpet Mastic			Throughout Classrooms, Main Office, Rooms 214, 216, 138, 206, 208 and 210		Miscellaneous					YES		X NO
2016 - Fal	: No Change				1								
Comments					1								
2017 - Spr Comments	ing: No Change				1								
Comments). 				1								
	: No Change												
Comments	S:				_								
2018 - Spr	ing : No Change				-								
Comments]								
2018 - Fal	: No Change				-								
Comments					1								

013C	Wine Carpet Mastic			Library		Miscellaneous					YES	X NO
2016 - Fall:	No Change]							
Comments:												
2017 - Fall:	No Change											
Comments:					_							
2017 - Sprir	ng: No Change											
Comments:					-							
2018 - Fall:					<u> </u>							
Comments:					1							
	ng : No Change											
Comments:					1							
					J							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
013D	Green Carpet Mastic	1070	SF	Teachers Lunch Room and Center Media Room		Miscellaneous	No	None	0		YES	X NO

Asbestos

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

Change in Assessment Category

HA No

2016 - Fall: No Change

2017 - Fall: No Change

2017 - Spring: No Change

2018 - Fall: No Change

2018 - Spring : No Change

Comments:

Comments:

Comments:

Comments:

Comments:

Material Description

Material

Units

Material

Quantity

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
013H	9x9 Beige w/ Multi-Colored Streaks Floor Tile - NOT OBSERVED	260	SF	1st Floor Women's Washroom and Corridor (West End)		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change			•	7							
Comments:	40 Orlange				+							
Comments.					†							
2017 - Spring	g: No Change											
Comments:					1							
2017 - Fall: N	lo Change											
Comments:												
2018 - Spring	g : No Change											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
014	Spray on Insulation	800	SF	Entrance to Auditorium		Surface	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

Comments:

Comments:

2018 - Fall: No Change

Page 9

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
015	12x12 Acoustical Ceiling Tile	5500	SF	throughout Basement, 1st fFoor Band Rooms		Miscellaneous	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category
020	12" x 12" Brown with Tan/White Streaks Floor Tile & Adhesive	60000	SF	Basement Hallway, 1st and 2nd Floor Hallways, Drill Hall, 1st Floor Meeting Room, Rooms 206, 208, 216, 218, 228, 109, 136, 138, main office		Miscellaneous	No	None	0		YES	X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
021	12" x 12" White w/ White & Pink Speckles Floor Tile and Adhesive	1000	SF	136		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
022	Insulation on Boiler Exhaust Pipes	100	LF	Boiler Room and Pool Mechanical Room		TSI	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
023	Insulation on Hot Water Tank	200	SF	Pool Mechanical Room		TSI	Yes	None	0		YES X NO
2016 - Fall: N	o Change										

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2040 0 : N 0
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
024	MJP E/F/V on Fiberglass Pipe Insulation	200	LF	Boiler Room, Loading Dock/Garage, Pool Mechanical Room		TSI	Yes	None	0		YES X NO

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
025	Tan and Brown Streaked Linoleum & Adhesive	500	SF	134		Miscellaneous	No	None	0		YES X NO
					1						_

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
026	1 x 1 Ceiling Tile Splined	5000	SF	Basement Hallway and Auditorium		Miscellaneous	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in	Assess	ment Category
027	Beige Terrazzo	10000	SF	2nd Floor Landings, Rooms 1-10, and Stairs		Miscellaneous	No	None	0		YES		X NO
2016 - Fall: N	lo Change]								
Comments:	•												
2017 - Spring	g: No Change												
Comments:	•												
2017 - Fall: N	lo Change												
Comments:													
2018 - Fall: N	lo Change												
Comments:													
2018 - Spring	g : No Change												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
028	Drywall	100000	SF	Throughout School		Miscellaneous	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
100M	Adhesive for Brown with White Streaks Stair Treads	1200	SF	Throughout		Miscellaneous	No	None	0		YES X NO
2016 - Fall: N	o Change										

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
101	White Woven Insulation on Electrical Copper Wires	100	LF	Auditorium StageLights- in Place or Dismantled		Miscellaneous	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
102	12"x12" Floor Tile	500	SF	Attendance Office		Miscellaneous	No	None	0		YES	X NO
2016 - Fall	I: No Change											
Comments	S:											
2017 - Fall	I: No Change											
Comments	3:											
2017 - Spr	ring: No Change											
Comments	S:											
2018 - Spr	ring : No Change											
Comments	S:											
2018 - Fall	I: No Change											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
102M	Adhesive for 12"x12" Floor Tile	500	SF	Attendance Office		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
103	Fireproof Insulation	1000	SF	Ceiling of the Auditorium		Surface	Yes	Dist	30		YES	X NO
2016 - Fall	: No Change]							
Comments	:											
2017 - Spri	ing: No Change											
Comments												
2017 - Fall	: No Change											
Comments												
2018 - Fall	: No Change											
Comments	:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
104	12 x 12 VFT Gray w/ Mixed Blue Specs	1200	SF	Boys Locker Room, Girls Locker Room		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2018 - Fall: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	

2018 - Spring : No Change

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
104M	12 x 12 VFT Gray w/ Mixed Blue Specs Mastic	1200	SF	Boys Locker Room, Girls Locker Room		Miscellaneous	No	None	0		YES X NO
2016 - Fall: N	o Change										

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2010 Caring Ala Changa
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
105	12 x 12 VFT Green	4500	SF	Activity Room, 2nd Floor West Gym Corridor		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
105M	12 x 12 VFT Green Mastic	4500	SF	Activity Room, 2nd Floor West Gym Corridor		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: No Change Comments:												
2017 - Spring: No Change												
Comments: 2017 - Fall: No Change												

Comments:

2018 - Spring : No Change

Comments:

2018 - Fall: No Change

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
106	12 x 12 Black VFT w/ white	1200	SF	Lunchroom		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:
·

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
106M	12 x 12 Black VFT w/ White Specs Mastic	1200	SF	Lunchroom		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

ALL LEA Responsibilities, for this school, will be met.

Robert Christlieb

NOTICE TO PARENTS AND STAFF REGARDING THE ASBESTOS MANAGEMENT PLAN NOTIFICATION

School:	George Washington Carver Military Academy HS
Date:	12/21/2018
the Asbest	notify you in accordance with Illinois and Federal Asbestos Regulations, that a copy of cos Management Plan is available at each school during school hours by appointment. to review the Asbestos Management Plan must be made at least 24 hours in advance.
The last ins	e be advised that CPS conducts asbestos inspections of all Schools every three years. spection was completed in 2016. surveillances are conducted every six months.
CHECK ON	<u>NE</u>
A co	opy of this notice was sent home in each child's backpack.
A co	opy of this notice was printed in the school's newsletter and sent home with each child
A co	opy of this notice was printed in the school's calendar and sent home with each child
X Oth	er. notice
	OF THIS NOTICE MUST BE PLACED IN THE

VFT = Vinyl Floor Tile
Oracle Unit: 46381

SCHOOL'S ASBESTOS MANAGEMENT PLAN.