Chicago Public Schools

6 Month Asbestos Surveillance 2018 - Fall

Paul Laurence Dunbar Career Academy High School 53021 1030 School: **Oracle Unit: Building ID:** Address: 3000 S. King Dr. Region: Mail Room: Asbestos Surveyor: Collins, Michael X CHECK HERE IF NO CHANGE TO ASBESTOS Survey Date: 1/10/2019 Email Address: mdcollins5@cps.edu A copy of the 2016/2017 notice to parents and staff regarding the asbestos management plan notifications was distributed via: Notice printed in school's newsletter Each child's backpack Notice printed in school's calendar Other HA No Material Description Material Location Asbestos Friable Damage Damage Change in Assessment Category Material Material Damage Quantity Units Type Category Quantity Type Office Complex, 101, YES X NO 1 A Blue Carpet Mastic 106, 132 2016 - Fall: No Change Comments: 2017 - Spring: No Change Comments: 2017 - Fall: No Change Comments: 2018 - Spring: No Change Comments: 2018 - Fall: No Change Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asso	essment Category
1 B	Beige Carpet Mastic	200	SF	Engineer's Office		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change]							
Comments:	-											
2017 - Fall: N	lo Change				1							
Comments:	J											
2017 - Spring	g: No Change				1							
Comments:												
2018 - Spring	g : No Change				1							
Comments:												
2018 - Fall: N	lo Change											
Comments:	go				Ī							
					J							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
1 C	Gold Carpet Mastic			Room 9-C		Miscellaneous		None			YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

2 A	9" x 9' Dark Green Floor Tiles w/White Streaks	1st, 2nd and 3rd Floor Corridors and Gym Balcony, Closet	Miscellaneous			YES	X NO
0040 = 11 1			٦				
2016 - Fall: N	No Change						
Comments:							
2017 - Fall: N	No Change						
Comments:	-		1				
2017 - Spring	g: No Change		1				
Comments:							
2018 - Fall: N	No Change						
Comments:							
2018 - Spring	g : No Change						
Comments:	-		1				
]				
			_				

Type

Material

Category

Miscellaneous

Asbestos

Type

Material

Category

Friable

Friable

Damage

Туре

Damage

Type

Damage

Quantity

Damage

Quantity

Damage

Damage

Units

Units

2 0	w/Dark Green Streaks		Balcony, Closet
204C Falls N	la Changa		
2016 - Fall: N	no Change		
Comments:			
2017 - Spring	g: No Change		
Comments:			
2017 - Fall: N	lo Change		
Comments:			
2018 - Spring	g : No Change		
Comments:			
2018 - Fall: N	lo Change		
Comments:	·	•	
		•	

Material

Quantity

Material

Units

HA No

HA No

2 B

Material Description

Material Description

9" x 9" White Floor Tile

w/Dark Green Streaks

Material

Units

Material

Quantity

Material Location

Material Location

Various 1st, 2nd, and 3rd

Floor Corridors and Gym

Change in Assessment Category

Change in Assessment Category

X NO

YES

2 C	9" x 9" Bright Green Floor Tile w/ White Streaks	As Patches in the 1st and 3rd Floor Corridors		Miscellaneous	None		YES	X NO
2016 - Fall: N	o Change		1					
Comments:	J							
2017 - Spring	: No Change							
Comments:			1					
2017 - Fall: N	o Change		-					
Comments:			1					
2018 - Spring	: No Change		-					
Comments:	J							
2018 - Fall: N	o Change							
Comments:								
]					

Type

Material

Category

Damage Quantity Damage

Units

Change in Assessment Category

Damage

Type

Friable

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
2 D	9" x 9" White Floor Tile w/Bright Green Streaks			1st, 2nd, and 3rd Floor Corridors		Miscellaneous		None			YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:
· · · · · · · · · · · · · · · · · · ·

HA No

Material Description

Material

Quantity

Material

Units

2 E	9" x 9" Brown w/Brown Floor Tile	Rooms 100 & 140 and the 1st Floor Corridor		Miscellaneous			YES	X NO
2016 - Fall: N	o Change		1					
Comments:	o change							
2017 - Spring	: No Change							
Comments:								
0015 5 11 11			_					
2017 - Fall: N	o Change							
Comments:								
2018 - Spring	: No Change		1					
Comments:	<u> </u>							
2018 - Fall: N	o Change		-					
Comments:	· · · · · · · · · · · · · · · · · ·		1					
]					

Type

Material

Category

Damage Quantity Damage

Units

Change in Assessment Category

Damage

Type

Friable

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
2 F	9"x9" Gray w/Lt. Gray & Black Streaks Floor Tile	10692	SF	13 A & B, Dressing Rooms, and Various Classrooms Throughout Building		Miscellaneous	No	Dist	50		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No

Material Description

Material

Quantity

Material

Units

Material Location

VFT = Vinyl Floor Tile Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in As	sessment Category
2 G	9" x 9" Lt. Gray Floor Tile w/Gray & Black Streaks	10692	SF	13 A & B, Dressing Rooms, and Various Classrooms Throughout Building		Miscellaneous	No	Dist	50		YES	X NO
2016 - Fall	II: No Change											
Comments	<u> </u>											
2017 Cnr	ring, No Changa											
Comments	ring: No Change s:											
2017 - Fall	II: No Change											
Comments												
2018 - Spr	ring : No Change											
Comments	S:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
2 H	9" x 9" Light Brn Floor Tile w/White & Blk Streaks			Rooms 311 and 212		Miscellaneous		None			YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

2018 - Fall: No Change

Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
	9" x 9" White Floor Tile	Quantity	Office	_	Турс			Турс	Quantity	OTIILS	 	
21	w/Lt Brn & Blk Streaks			Rooms 212 and 311		Miscellaneous					YES	X NO
2016 - Fall: N	lo Change											
Comments:	•											
2017 - Fall: N	lo Change											
Comments:	•											
2017 - Spring	g: No Change											
Comments:												
2018 - Spring	g : No Change											
Comments:												
2018 - Fall: N	lo Change											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
2 J	9" x 9" Brown Floor Tile w/ White Streaks	3800	SF	Auditorium		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	ssessment Category
3 AA	12" x 12" Gray Floor Tile	1200	SF	Band Room, Chorus Room, Hall, Foyer & Practice Room		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	No Change					•	•	•	•	•	•	
Comments:												
2017 - Sprir	ng: No Change											
Comments:												
2017 - Fall:	No Change											
Comments:												
2018 - Sprir	ng : No Change											
Comments:												
2018 - Fall:	No Change				_							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
3 AB	12" x 12" Multi-Blue Floor Tile			Room 208		Miscellaneous					YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
3 AC	12" x 12" Beige Floor Tile - Removed			Room 128		Miscellaneous					YES	X NO
2016 - Fall: N	lo Change]							
Comments:												
2017 - Spring	g: No Change				-							
Comments:]							
2017 - Fall: N	lo Change											
Comments:					-							
2018 - Spring	ј : No Change											
Comments:					-							
2018 - Fall: N	lo Change											
Comments:					_							
					J							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
3 AD	12" x 12" Gray Floor Tile - Removed			Room 128		Miscellaneous					YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
3 AE	12" x 12" White Floor Tile w/ Blue Streaks	600	SF	Room 208, 100, 128		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
, v
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
3 AF	12" x 12" Gray Floor Tile w/ Black Streaks	20	SF	Room 206, 204, 208, 100, 128		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
3 B	12"x12" Gray Floor Tile w/ White & Black Streaks			Men's Lounge		Miscellaneous					YES	X NO
2016 - Fall: N	o Change											
2017 - Spring	· No Change											
Comments:	. No Onlinge											
2017 - Fall: N	o Change											
Comments:												
2018 - Fall: N	o Change											
Comments:												
2018 - Spring	: No Change											
Comments:												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
3 C	12"x12" Dark Gray Floor Tile w/ Black Streaks			Rooms 100, 140, 305, 308, and 313		Miscellaneous					YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:
· · · · · · · · · · · · · · · · · · ·

3 D	12"x12" Brown Floor Tile w/ Dk Brn & Wh Streaks (Removed)	Boys Gym, Lunch Room, Classrooms and Corridors		Miscellaneous			YES	X NO
	·		1					
2016 - Fall: N	No Change							
Comments:								
2017 - Fall: N	lo Change							
Comments:								
			1					
2017 - Spring	g: No Change							
Comments:								
			1					
2018 - Spring	g : No Change							
Comments:								
2018 - Fall: N	lo Change							
Comments:			1					
			•					

Type

Material

Category

Friable

Damage

Туре

Damage

Quantity

Damage

Units

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
3 E	12"x12" White Floor Tile w/ Brown Streaks			Boys Gym, Lunch Room, Classrooms and Corridors		Miscellaneous					YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No

Material Description

Material

Quantity

Material

Units

3 F	12"x12" Light Brown Floor Tile w/ White Streaks	1st Floor Corridor by Ramps and as a Patch in 2nd Floor Corridor, 114, 207	Miscellaneo	ıs		YES	X NO
2016 - Fall: N	lo Change						
Comments:							
2017 - Spring	ı: No Change						
Comments:	,						
2017 - Fall: N	lo Change						
Comments:	•						
2018 - Fall: N	lo Change						
Comments:	V						
2018 - Spring	: No Change						
Comments:	-						

Type

Material

Category

Damage Quantity Damage

Units

Change in Assessment Category

Damage

Type

Friable

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
3 G	12"x12" Gray Floor Tile w/ Dk Gray & White Streaks			Rooms 100, 119, 121, 140, 305, 306, 308, and 313		Miscellaneous					YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No

Material Description

Material

Quantity

Material

Units

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in As	sessment Category
3 H	12"x12" Beige Floor Tile w/ White Streaks			1st Floor Corridor by Ramps and as a Patch in 2nd Floor Corridor, 114, 207, 307		Miscellaneous					YES	X NO
204C Falls	No Change				1							
2016 - Fall:	<u> </u>											
Comments:												
2017 - Fall:	No Change											
Comments:												
2017 - Sprir	ng: No Change											
Comments:												
					1							
2018 - Fall:	No Change											
Comments:												
					1							
2018 - Sprir	ng : No Change											
Comments:					1							
					1							
					_							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
31	12"x12" Brown Floor Tile			Room 138		Miscellaneous					YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

3 J	12"x12" Beige Floor Tile			Room 138		Miscellaneous					YES	X NO
2016 - Fall:	No Change]							
Comments:	<u> </u>				1							
2017 - Fall:	No Change				-							
Comments:					<u> </u>							
	g: No Change				=							
Comments:					1							
2018 - Fall:	No Change											
Comments:					=							
	ig : No Change											
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
3 K	12"x12" Green Floor Tiles			As Patches in the 1st and 3rd Floor Corridors		Miscellaneous					YES	X NO

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

Material Location

HA No

Material Description

Material

Quantity

Material

Units

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
3 L	12"x12" Light Green Floor Tiles			As Patches in the 1st and 3rd Floor Corridors		Miscellaneous					YES	X NO
2016 - Fall: No	o Change											
Comments:												
2017 - Spring:	: No Change											
Comments:												
2017 - Fall: No	o Change											
Comments:												
2018 - Fall: No	o Change											
Comments:												
2018 - Spring	: No Change											
Comments:												
					1							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
3 M	12" x 12" Gray Floor Tile			1st Floor Corridor Ramps		Miscellaneous					YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
3 N	12" x 12" Gray Floor Tile w/White Streaks	600	SF	Room 104		Miscellaneous	No	None	0		YES X NO
2016 - Fall: N	o Change										

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
3 O	12" x 12" White Floor Tile	900	SF	Room 132,106		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
3 P	12" x 12" Blue Floor Tile	450	SF	Room 132		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: No Change Comments:												

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 Chring: No Change
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
3 Q	12" x 12" Black Floor Tile	1100	SF	Room 105		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
3 R	12" x 12" White Floor Tile	1100	SF	Room 105		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change Comments: 2017 - Spring: No Change Comments: 2017 - Fall: No Change Comments: 2018 - Spring: No Change Comments: 2018 - Fall: No Change Comments:	
Comments: 2017 - Spring: No Change Comments: 2017 - Fall: No Change Comments: 2018 - Spring: No Change Comments: 2018 - Fall: No Change	
2017 - Spring: No Change Comments: 2017 - Fall: No Change Comments: 2018 - Spring : No Change Comments: 2018 - Fall: No Change	2016 - Fall: No Change
Comments: 2017 - Fall: No Change Comments: 2018 - Spring : No Change Comments: 2018 - Fall: No Change	Comments:
Comments: 2017 - Fall: No Change Comments: 2018 - Spring : No Change Comments: 2018 - Fall: No Change	
2017 - Fall: No Change Comments: 2018 - Spring : No Change Comments: 2018 - Fall: No Change	2017 - Spring: No Change
Comments: 2018 - Spring : No Change Comments: 2018 - Fall: No Change	Comments:
Comments: 2018 - Spring : No Change Comments: 2018 - Fall: No Change	
2018 - Spring : No Change Comments: 2018 - Fall: No Change	2017 - Fall: No Change
Comments: 2018 - Fall: No Change	Comments:
Comments: 2018 - Fall: No Change	2019 Caring : No Change
2018 - Fall: No Change	1 0 0
	Comments:
Comments:	2018 - Fall: No Change
	Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
3 S	12" x 12" Light Blue Floor Tile	175	SF	Room 104, 134, Social Room, 300B		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:
·

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
3 T	12" x 12" Light Brown Floor Tile	2400	SF	Rooms 114, 116, 117, 119, 130, and 206		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Ÿ
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
3 U	12" x 12" Beige Floor Tile	2400	SF	Rooms 114, 116, 117, 119, 130, and 206		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

3 V	12" x 12" Dark Brown w/Dk Brn & Lt Brn Streak FT (Removed)		On Cabinets in Various Classrooms		Miscellaneous			YES	X NO
004C Fall N	In Ohanana	<u> </u>	<u> </u>	1					
2016 - Fall: N	io Change								
Comments:									
2017 - Fall: N	lo Change								
Comments:									
2017 - Spring	g: No Change								
Comments:									
2018 - Spring	g : No Change								
Comments:									
2018 - Fall: N	lo Change								
Comments:									
1				_					

Type

Material

Category

Miscellaneous

Asbestos

Type

Material

Category

Friable

Friable

Damage

Туре

Damage

Type

Damage

Quantity

Damage

Quantity

Damage

Damage

Units

Units

		-	
3 W	12" x 12" Gray Floor Tile w/ Light Gray Streaks (Removed)		On Cabinets in Various Classrooms
2016 - Fall: N	o Change		
Comments:			
2017 - Spring	: No Change		
Comments:			
2017 - Fall: N	o Change		
Comments:			
2018 - Spring	: No Change		
Comments:			
2018 - Fall: N	o Change		
Comments:			
	_		

Material

Quantity

Material

Units

HA No

HA No

Material Description

Material Description

Material

Units

Material

Quantity

Material Location

Material Location

Change in Assessment Category

Change in Assessment Category

X NO

YES

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category
3 X	12" x 12" Multi-Brown Floor Tile			Rooms 201 and 203		Miscellaneous					YES	X NO
2016 - Fall: N	lo Change				1							
Comments:												
2017 - Fall: N	lo Change											
Comments:												
2017 - Spring	j: No Change											
Comments:												
2018 - Spring	j : No Change											
Comments:												
2018 - Fall: N	lo Change											
Comments:												
					1							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
3 Y	12" x 12" Beige Floor Tile			Rooms 201		Miscellaneous					YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
3 Z	12" x 12" Light Green Floor Tile			Band Room, Chorus Room, Hall and Foyer		Miscellaneous					YES	X NO
2016 - Fall: N	lo Change											
Comments:												
2017 - Fall: N	lo Change											
Comments:												
2017 0	N. O.											
2017 - Spring	g: No Change											
Comments:												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
ЗА	12" x12" White Floor Tile w/ Blue and Gray Streaks	2700	SF	Rms 224, 222, 310, 225, 221A, 217, 211, 207, 306and 312		Miscellaneous	No	None	0		YES X NO

2018 - Spring : No Change

2018 - Fall: No Change

Comments:

Comments:

2018 - Spring : No Change Comments: 2018 - Fall: No Change	4	Outer Wrap Over Fiberglass Insulation on HVAC Unit		Room 122- ABATED		TSI				YES	X NO
Comments: 2017 - Spring: No Change Comments: 2017 - Fall: No Change Comments: 2018 - Spring: No Change Comments: 2018 - Fall: No Change	0040 5-11 N	. 0	•		1	•	•		•	•	
2017 - Spring: No Change Comments: 2017 - Fall: No Change Comments: 2018 - Spring: No Change Comments: 2018 - Fall: No Change		io Change									
Comments: 2017 - Fall: No Change Comments: 2018 - Spring : No Change Comments: 2018 - Fall: No Change	Comments:										
Comments: 2017 - Fall: No Change Comments: 2018 - Spring : No Change Comments: 2018 - Fall: No Change											
2017 - Fall: No Change Comments: 2018 - Spring : No Change Comments: 2018 - Fall: No Change	2017 - Spring	r: No Change									
2017 - Fall: No Change Comments: 2018 - Spring : No Change Comments: 2018 - Fall: No Change	Comments:										
Comments: 2018 - Spring : No Change Comments: 2018 - Fall: No Change					1						
2018 - Spring : No Change Comments: 2018 - Fall: No Change	2017 - Fall: N	lo Change									
Comments: 2018 - Fall: No Change	Comments:	-]						
Comments: 2018 - Fall: No Change					1						
Comments: 2018 - Fall: No Change	2018 - Spring	ı : No Change									
2018 - Fall: No Change		<u> </u>									
	2018 - Fall: N	lo Change			1						
	Comments:	<u> </u>			1						
					1						

Type

Material

Category

Damage

Туре

Friable

Damage

Quantity

Damage

Units

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
5	Insulation on Suspended HVAC Unit			Room 122		TSI					YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No

Material Description

Material

Quantity

Material

Units

6	Fiberglass Insulation Backing on HVAC Unit		Room 122- ABATED		TSI			YES	X NO
				1					
2016 - Fall: N	o Change								
Comments:									
2017 - Spring	: No Change								
Comments:	<u> </u>								
•									
2017 - Fall: N	o Change								
Comments:	-								
2019 Spring	· No Changa								
	: No Change								
Comments:									
0040 5 11 11	01								
2018 - Fall: N	o Change								
Comments:									
		-							

Type

Material

Category

Damage Quantity Damage

Units

Change in Assessment Category

Damage

Type

Friable

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
7	Plaster			Throughout Building		Surface					YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No

Material Description

Material

Quantity

Material

Units

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessm	nent Category
8	Plaster Above Ceiling Tiles			Shop Wing		Surface					YES	X NO
2016 - Fall: N	lo Change				7							
Comments:	J											
2017 - Spring	ı: No Change				_							
Comments:	J				1							
2017 - Fall: N	lo Change				-							
Comments:					1							
2018 - Spring	ı : No Change				-							
Comments:					1							
2018 - Fall: N	lo Change				-							
Comments:	<u> </u>]							
					_							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
9	Drywall Joint Compound			Room 108		Miscellaneous					YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

Page 26

		Quantity	Units		Туре	Category	Туре	Quantity	Units		
10	Ceramic Floor Tile Grout			Washrooms		Miscellaneous				YES	X NO
2016 - Fall: N	o Change										
Comments:	3 -										
2017 - Spring	: No Change										
Comments:											
2017 - Fall: N	o Change										
Comments:											
2018 - Spring	: No Change										
Comments:											
2018 - Fall: N	o Change										
Comments:											
					J						

Material

Damage

Friable

Damage

Damage

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
11	Peg Board	2000	SF	Auditorium Walls		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No

Material Description

Material

Material

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
12	Terrazzo			Foyer		Miscellaneous					YES	X NO
2016 - Fall:	No Change											
Comments:												
2017 - Sprir	ng: No Change											
Comments:												
2017 - Fall:	No Change											
Comments:												
2018 - Sprir	ng : No Change											
Comments:												
2018 - Fall:	No Change											
Comments:												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
13 A	9"x9" Dk Green Floor Tile w/ White Streaks Mastic (REMOVED)			1st, 2nd & 3rd Floor Corridors		Miscellaneous		None			YES X NO

016 - Fall: No Change	
Comments:	
017 - Fall: No Change	
Comments:	
017 - Spring: No Change	
Comments:	
018 - Fall: No Change	
Comments:	
018 - Spring : No Change	
Comments:	

HA No

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
13 B	9" x 9" White Floor Tile w/Dark Grn Streaks Mastic			1st, 2nd & 3rd Floor Corridors		Miscellaneous		None			YES	X NO
2016 - Fall	: No Change							•		•		
Comments	:											
2017 - Spr	ing: No Change											
Comments	:											
2017 - Fall	: No Change											
Comments	:											
2018 - Spr	ing : No Change											
Comments	:											
2018 - Fall	· No Change											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
13 D	9" x 9" White Floor Tile w/ Lt Grn Streaks Mastic			As Patches in the 1st & 3rd Floor Corridors		Miscellaneous		None			YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
13 E	9" x 9" Brown Floor Tile w/ Brown Streaks Mastic			1st Floor Corridor, Rooms 100		Miscellaneous		None			YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
13 F	9"x9" Gray FloorTile w/Lt. Gray & Blk Strks Mastic	1250	SF	13A&B, Dressing Rms, 100,103- 105,119,120,128,140,200 , 208,211,212,214,217,221 A&B,225,300, 301, 214, 223, Band Room, 223A, and 222I		Miscellaneous	No	Dist	100		YES X NO

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
13 G	9" x 9" Lt Gray VFT w/ Gray & Blk Strks Mastic	10692	SF	3 A&B, Dressing Rooms, and Various Classrooms Throughout Building		Miscellaneous	No	None	0		YES X NO
2016 - Fall: N	lo Change	•	•	•]	•	•	•	•	•	

2016 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
13 H	9"x9" Lt Brn Floor Tile w/Wh & Blk Streaks Mastic			Rooms 212 & 311		Miscellaneous		None			YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
13 J	9" x 9" Brown Floor Tile w/White Streaks Mastic			Auditorium		Miscellaneous					YES	X NO
2016 - Fall: N	lo Change				7							
Comments:												
2017 - Fall: N	lo Change											
Comments:												
2017 - Spring	g: No Change				=							
Comments:												
2018 - Spring	g : No Change											
Comments:												
2018 - Fall: N	lo Change				=							
Comments:												
					_							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
13C	9" x 9" Bright Grn Floor Tile w/ Wh Streaks Mastic			As Patches in the 1st & 3rd Floor Corridors		Miscellaneous		None			YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:
· · · · · · · · · · · · · · · · · · ·

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	ssessr	nent Category
14 A	12" x 12" White FT w/Blue & Grey Streaks Mastic			Rooms 222, 224, 310, and 312		Miscellaneous		None			YES		X NO
2016 - Fall: N	lo Change				1								
Comments:													
2017 - Spring	g: No Change												
Comments:													
2017 - Fall: N	lo Change												
Comments:													
2018 - Spring	g : No Change												
Comments:													
2018 - Fall: N	lo Change												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
14 AA	12" x 12" Gray Floor Tile Mastic	1200	SF	Band Room Hall, Chorus Room, Foyer & Practice Room		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

Comments:

		Quantity	Units		Type	Category		Туре	Quantity	Units	_	
14 AB	12" x 12" Multi-Blue Floor Tile Mastic	1600	SF	Room 208		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	No Change											
Comments:												
2017 - Sprir	ng: No Change											
Comments:												
2017 - Fall:	No Change											
Comments:												
2018 - Sprir	ng : No Change											
Comments:	·			·								
2018 - Fall:	No Change											

Material

Friable

Damage

Damage

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
14 AC	12" x 12" Beige Floor Tile Mastic - Replaced			Room 128		Miscellaneous					YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No

Comments:

Material Description

Material

Material Material Location

Damage Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
14 AD	12" x 12" Blue Floor Tile Mastic - Replaced			Room 128		Miscellaneous					YES	X NO
2016 - Fall:	No Change							•		•		
Comments:	<u> </u>											
2017 - Fall:	No Change											
Comments:												
2017 - Sprin	g: No Change											
Comments:												
2018 - Sprin	g : No Change											
Comments:												
2018 - Fall:	No Change											
Comments:												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
14 AE	12" x 12" White Floor Tile w/ Blue Streaks Mastic	600	SF	Room 208		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
14 AF	12" x 12" Gray Floor Tile w/ Black Streaks Mastic	20	SF	Room 208		Miscellaneous	No	None	0		YES X NO
2016 - Fall: No Change											

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
14 B	12" x 12" Gray VFT w/ Wh & Blk Streaks Mastic	200	SF	Men's Lounge		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

14 C	12" x 12" Dk Gray Floor Tile w/Blk Streaks Mastic	5400	SF	Rooms 140, 211, 214, 217, 305, 308, and 313		Miscellaneous	No	None	0	YES	X NO
2016 - Fa	II: No Change				1						
					-						
Comment	S:										
2215 5											
	II: No Change										
Comment	s:										
2017 - Sp	ring: No Change										
Comment	S:										
2018 - Sp	ring : No Change										
Comment											
2018 - Fa	II: No Change										
Comment											
20	.										

Type

Material

Category

Damage Type

Friable

Damage Quantity Damage

Units

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
14 D	12" x12" Brown VFT w/ Dk Brn & White Strks Mastic			Boys Gym, Lunchroom, 1st and 2nd Floor Corridors, 114, 201, 213, 215, 216, 218-220, 223, 227, 303		Miscellaneous					YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No

Material Description

Material

Quantity

Material

Units

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
14 E	12" x 12" White Floor Tile w/Brown Streaks Mastic	25000	SF	Boys Gym, Lunchroom, 1st and 2nd Floor Corridors, 114, 201, 213, 215, 216, 218-220, 223, 227, 303		Miscellaneous	No	Dist	20		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

Oracle Unit: 53021

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
14 F	12"x12" Lt Brown Floor Tile w/White Streaks Mastic	750	SF	1st Floor Corridor by Ramps and as a Patch in the 2nd Floor Corridor		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
14 G	12"x12"Gray Floor Tile w/Dk Gray/Wh Streaks Mastic	8300	SF	Rooms 100, 119, 121, 140, 305, 306, 308, 313, 209 Library		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
14 H	12" x 12" Beige Floor Tile w/White Streaks Mastic	250	SF	1st Floor Corridor by Ramps and as a Patch in the 2nd Floor Corridor		Miscellaneous	No	None	0		YES	X NO
0040 5 11 11	. 01				 1							

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
14 I	12" x 12" Brown Floor Tile Mastic			Room 138		Miscellaneous					YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	sessment Category
14 J	12" x 12" Beige Floor Tile Mastic			Room 138		Miscellaneous					YES	X NO
2016 - Fall: N	lo Change]							
Comments:	•											
2017 - Fall: N	lo Change											
Comments:	•											
2017 - Spring	g: No Change											
Comments:												
2018 - Spring	g : No Change											
Comments:												
2018 - Fall: N	lo Change											
Comments:	•											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
14 K	12" x 12" Green Floor Tile Mastic			1st, 2nd & 3rd Floor Corridors as Patches		Miscellaneous		None			YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

		Quantity	Units		Type	Category	Type	Quantity	Units		
14 L	12" x 12" Light Green Floor Tile Mastic			1st, 2nd & 3rd Floor Corridors as Patches		Miscellaneous	None			YES	X NO
2016 - Fall: N	lo Change				7						
Comments:											
2017 - Fall: N	lo Change				1						
Comments:	J										
2017 - Spring	: No Change				1						
Comments:	•]						
2018 - Spring	ı : No Change				1						
Comments:											
2018 - Fall: N	lo Change				-						

Material

Friable

Damage

Damage

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
14 M	12" x 12" Gray Floor Tile Mastic	550	SF	1st Floor Corridor Ramps		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No

Comments:

Material Description

Material

Material Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	sessment Category
14 N	12" x 12" Gray Floor Tile w/White Streaks Mastic			Room 104		Miscellaneous					YES	X NO
2016 - Fall: N	lo Change											
Comments:	<u> </u>											
2017 - Fall: N	lo Change											
Comments:												
2017 - Spring	g: No Change											
Comments:												
2018 - Spring	g : No Change											
Comments:												
2018 - Fall: N	lo Change											
Comments:												
					_							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
14 O	12" x 12" White Floor Tile Mastic			Room 132		Miscellaneous					YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
14 P	12" x 12" Blue Floor Tile Mastic			Room 132		Miscellaneous					YES	X NO
2016 - Fall: I	No Change											
Comments:					_							
2017 - Sprin	g: No Change											
Comments:												
2017 - Fall: I	No Change											
Comments:												
2018 - Sprin	g : No Change											
Comments:	<u> </u>											
2018 - Fall: I	No Change				-							
Comments:	J											
					1							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
14 Q	12" x 12" Black Floor Tile Mastic	1100	SF	Room 105		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
14 R	12" x 12" White Floor Tile Mastic	1500	SF	Room 105		Miscellaneous	No	None	0		YES X NO
2016 - Fall: No Change											

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
14 S	12" x 12" Light Blue Floor Tile Mastic	600	SF	Room 104, 221B, 223		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
14 T	12" x 12" Light Brown Floor Tile Mastic	700	SF	Rooms114, 117, 119, 130, 206, & 207		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
14 U	12" x 12" Beige Floor Tile Mastic	700	SF	Rooms 114, 117, 119, 130, 206, & 207		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	essment Category
14 V	12"x12" Dk Brn Floor Tile w/Dk Brn & Lt Brn Mastic			On Cabinets in Various Classrooms		Miscellaneous		None			YES	X NO
2016 - Fall: N	lo Change]							
Comments:	•											
2017 - Fall: N	lo Change											
Comments:												
2017 - Spring	: No Change											
Comments:					_							
2018 - Spring	: No Change											
Comments:												
2018 - Fall: N	lo Change											
Comments:												
					_							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
14 W	12"x12" Gray Floor Tile w/Lt. Gray Streaks Mastic			On Cabinets in Various Classrooms		Miscellaneous		None			YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:
·

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category
14 X	12" x 12" Multi-Brown Floor Tile Mastic			Room 201 and 203		Miscellaneous					YES	X NO
2016 - Fall: N	lo Change				1							
Comments:												
2017 - Spring	g: No Change											
Comments:												
2017 - Fall: N	lo Change											
Comments:												
2018 - Fall: N	lo Change											
Comments:												
2018 - Spring	j : No Change											
Comments:												
					1							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
14 Y	12" x 12" Beige Floor Tile Mastic			Rooms 201 and 203		Miscellaneous		None			YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

Page 49

14 Z	12" x 12" Light Green Floor Tile Mastic	Band Room, Chorus Room, Hall and Foyer		Miscellaneous			YES	X NO
			7					
2016 - Fall: N	o Change							
Comments:								
2017 - Fall: N	o Change							
Comments:			1					
			1					
2017 - Spring	: No Change							
Comments:								
2018 - Spring	: No Change							
Comments:	-		1					
			1					
2018 - Fall: N	o Change]					
Comments:								
]					
			=					

Type

Material

Category

Damage Quantity Damage

Units

Change in Assessment Category

Damage

Type

Friable

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
15	Drywall			Rooms 132 & 303 and the Office Complex		Miscellaneous					YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:
· · · · · · · · · · · · · · · · · · ·

HA No

Material Description

Material

Quantity

Material

Units

Material Location

Page 50

		Quantity	Units		Type	Category	Туре	Quantity	Units		
16 A	Black Baseboard			Throughout Building		Miscellaneous				YES	X NO
2016 - Fall: N	No Change			•]	•	•				
Comments:											
2017 - Fall: N	No Change										
Comments:					_						
	g: No Change										
Comments:											
2018 - Fall: N	No Change										
Comments:											
	g : No Change										
Comments:											
					_						
	11.0						 1	1	_	01 1 1	

Material

Damage

Friable

Damage

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
16 B	Blue Baseboard			Office Complex and Room 310		Miscellaneous					YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No

Material Description

Material

Material Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
16 C	4" Beige Baseboard	300	LF	Band Room, Hall, Foyer and Chorus Room		Miscellaneous	No	None	0		YES	X NO
2016 - Fal	II: No Change]							
Comment	S:											
2017 - Sp	ring: No Change				-							
Comment	S:]							
2017 - Fal	II: No Change				-							
Comment	s:											
2018 - Fal	II: No Change				-							
Comments					7							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
16 D	4" Dark Gray Baseboard	150	LF	Room 208		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

2018 - Spring : No Change

Comments:

		Quantity	Units		Type	Category		Туре	Quantity	Units		
17 A	Black Baseboard Mastic			Throughout Building		Miscellaneous					YES	X NO
2016 - Fall: N	lo Change]							
Comments:	<u> </u>											
2017 - Fall: N	lo Change				<u> </u>							
Comments:												
2017 - Spring	g: No Change											
Comments:					_							
2018 - Fall: N	lo Change											
Comments:												
	g : No Change											
Comments:	·				_							
					J							
	The state of the s			I a a a a a a a a a a a a a a a a a a a	1		T =	_	_		0	

Material

Damage

Friable

Damage

Damage Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
17 B	Blue Baseboard Mastic			Office Complex and Room 310		Miscellaneous					YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No

Material Description

Material

Material Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
17 C	4" Beige Baseboard Mastic	300	LF	Band Room, Chorus Room, Hall and Foyer		Miscellaneous	No	None	0		YES X NO
2016 - Fall: N	o Change										

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2010 0 : 11 01
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
17 D	4" Dark Gray Baseboard Mastic	150	LF	Room 208		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

18	Tank # 1 Insulation Jacket (Closest to Door)		Boiler House		TSI			YES	X NO
				_					
2016 - Fall: N	lo Change								
Comments:									
2017 - Spring	: No Change								
Comments:									
2017 - Fall: N	lo Change								
Comments:									
				1					
2018 - Spring	ı: No Change								
Comments:									
2018 - Fall: N	lo Change								
Comments:		1							
				1					

Type

Material

Category

Damage Quantity Damage

Units

Change in Assessment Category

Damage

Type

Friable

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
19	Tank Insulation Jacket (Middle Tank)			Boiler House		TSI					YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No

Material Description

Material

Quantity

Material

Units

20	Tank Insulation Jacket (Farthest From Door)		Boiler House		TSI			YES	X NO
2016 - Fall: N	Jo Change]					
	NO Criarige								
Comments:									
2017 - Spring	g: No Change								
Comments:									
2017 - Fall: N	No Change								
Comments:									
2018 - Spring	g : No Change]					
Comments:	-			1					
				1					
2018 - Fall: N	No Change								
Comments:									
				1					
				1					

Type

Material

Category

Damage Quantity Damage

Units

Change in Assessment Category

Damage

Type

Friable

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
21	Tank Insulation Jacket (Lower Level)			Boiler House		TSI					YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No

Material Description

Material

Quantity

Material

Units

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessi	ment Category
22	Linear Pipe Insulation			Boiler House		TSI					YES	X NO
2016 - Fall: N	lo Change											
Comments:	<u> </u>											
2017 - Spring	: No Change				_							
Comments:												
2017 - Fall: N	lo Change											
Comments:					_							
2018 - Spring	: No Change											
Comments:					_							
2018 - Fall: N	lo Change											
Comments:												
					_							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
23	Steam Line Joints			Boiler House		TSI					YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:
· · · · · · · · · · · · · · · · · · ·

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
24	Cinder Block			Boiler House		Miscellaneous					YES	X NO
2016 - Fall: N	lo Change											
Comments:	.											
2017 - Spring	g: No Change											
Comments:	•											
2017 - Fall: N	lo Change											
Comments:												
2018 - Spring	g : No Change											
Comments:												
2018 - Fall: N	No Change											
Comments:												
	T				T				_	_	1 01 1 1	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
25	Cinder Block Mortar			Boiler House		Miscellaneous					YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

		Quantity	Units		Type	Category	Туре	Quantity	Units		
26	Finished Brick (Glazed)			Boiler House Washroom		Miscellaneous				YES	X NO
2016 - Fall: No	o Change										
Comments.											
2017 - Spring	: No Change										
Comments:	<u> </u>										
0047 F.II N	. 01										
2017 - Fall: N	o Change										
Comments:											
2018 - Spring	: No Change										
Comments:	Ţ.										
2018 - Fall: N	o Change										
Comments:	<u> </u>										

Material

Damage

Friable

Damage

Damage

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
27	Finished (Glazed) Brick Mortar			Boiler House Washroom		Miscellaneous					YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No

Material Description

Material

Material

		Quantity	Units		Туре	Category	Туре	Quantity	Units		
28	Terrazzo Stall Panels			Boiler House Washroom		Miscellaneous				YES	X NO
2016 - Fall: N	lo Change]						
Comments:	<u> </u>				1						
2017 - Spring	ı: No Change										
Comments:											
2017 - Fall: N	lo Change				-						
Comments:											
2018 - Spring	: No Change				=						
Comments:											
2018 - Fall: N	lo Change										
Comments:					=						
					j						

Material

Friable

Damage

Damage

Material Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
29	Aircell Pipe Insulation			Boiler House Washroom Behind Wall- In Chase		TSI					YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No

Material Description

Material

Page 60

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessme	ent Category
30	Tank Insulation			Basement		TSI					YES	X NO
2016 - Fall: N	o Change]							
Comments:]							
2017 - Spring	: No Change											
Comments:												
2017 - Fall: N	o Change											
Comments:												
2018 - Spring	: No Change											
Comments:												
2018 - Fall: N	o Change											
Comments:	•											
					J							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
31	Cinder Block Mortar			Throughout Building		Miscellaneous					YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

		Quantity	Units		Type	Category	Туре	Quantity	Units		
32	Interior Brick			Throughout Building		Miscellaneous				YES	X NO
2016 - Fall: N	lo Change]						
Comments:					1						
2017 - Spring	g: No Change										
Comments:											
2017 - Fall: N	lo Change										
Comments:					-						
	g : No Change										
Comments:					=						
2018 - Fall: N	lo Change										
Comments:					-						
L					1						
	11 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1						 _	1		01 1 1	

Material

Damage

Friable

Damage

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
33	Interior Brick Mortar			Throughout Building		Miscellaneous					YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No

Material Description

Material

Material Material Location

		Quantity	Units		Туре	Category	Туре	Quantity	Units		
34	Ceiling Material			Basement Boiler Room		Miscellaneous				YES	X NO
2016 - Fall: N	lo Change										
Comments:											
2017 - Spring	g: No Change										
Comments:	•										
2017 - Fall: N	lo Change										
Comments:											
2018 - Spring	g : No Change										
Comments:											
2018 - Fall: N	lo Change										
Comments:	-										

Material

Damage

Friable

Damage

Damage

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
35	Terrazzo Stairs and Landings/foyers			Throughout Stairways		Miscellaneous					YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:
· · · · · · · · · · · · · · · · · · ·

HA No

Material Description

Material

Material

		Quantity	Units		Туре	Category	Туре	Quantity	Units		
36	Clay Tile			Entrances and Exits		Miscellaneous				YES	X NO
2016 - Fall: N	lo Change										
Comments:											
2017 - Spring	j: No Change										
Comments:											
2017 - Fall: N	lo Change										
Comments:	•										
2018 - Spring	; No Change										
Comments:											
2018 - Fall: N	lo Change										
Comments:	Ŭ										
										•	

Material

Friable

Damage

Damage

Damage

Material Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
37	Clay Tile Mortar			Entrances and Exits		Miscellaneous					YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No

Material Description

Material

		Quantity	Units		Type	Category	Туре	Quantity	Units		
38	Window Glazing			Throughout Building		Miscellaneous				YES	X NO
2016 - Fall: N	lo Change]						
Comments:	· · · · · · · · · · · · · · · · · · ·										
2017 - Spring	g: No Change										
Comments:					_						
2017 - Fall: N	lo Change				1						
Comments:											
	g : No Change				_						
Comments:					-						
2018 - Fall: N	lo Change				_						
Comments:											
	14 4 1 1 5 1 1 1						 1	1		01 1 1	

Material

Damage

Friable

Damage

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
39	Window Caulk (Grout)			Throughout Building		Miscellaneous					YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No

Material Description

Material

Material Location

		Quantity	Units		Туре	Category	Туре	Quantity	Units		
40	Window Sill Mortar			Throughout Classrooms		Miscellaneous				YES	X NO
2016 - Fall: N	lo Change]						
Comments:	<u> </u>]						
2017 - Spring	g: No Change										
Comments:					<u> </u>						
2017 - Fall: N	lo Change										
Comments:					<u> </u>						
	j : No Change										
Comments:					<u> </u>						
2018 - Fall: N	lo Change										
Comments:					 						
					J						
							 _	_	_		

Material

Damage

Friable

Damage

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
41	Finished (Glazed) Brick			Throughout Building		Miscellaneous					YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:
· · · · · · · · · · · · · · · · · · ·

HA No

Material Description

Material

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
42	Finished (Glazed) Brick Mortar			Throughout Building		Miscellaneous					YES	X NO
2016 - Fall: N	lo Change				7							
Comments:	Ü											
2017 - Fall: N	lo Change				_							
Comments:	<u> </u>				=							
2017 - Spring	g: No Change											
Comments:												
2018 - Spring	g : No Change											
Comments:												
2018 - Fall: N	lo Change											
Comments:												
	1							T _	_	_	1 01 1 1	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
43	Terrazzo Stall Panels			All Washrooms		Miscellaneous					YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessm	nent Category
44	1' x 1' Ceiling Tile (Acoustical)			As Patches in Foyer and Corridors		Miscellaneous					YES	X NO
2016 - Fall: N	lo Change]							
Comments:												
2017 - Fall: N	lo Change											
Comments:												
2017 - Spring	ı: No Change				_							
Comments:												
2018 - Spring	: No Change											
Comments:					=							
2018 - Fall: N	lo Change											
Comments:					-							
					1							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
45	1' x 1' Ceiling Tiles			1st, 2nd, and 3rd Floor Corridors		Miscellaneous					YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:
·

		Quantity	Units		Туре	Category	Туре	Quantity	Units		
46	1' x 1' (Spline) Ceiling Tiles with Holes			1st, 2nd, and 3rd Floor Corridors		Miscellaneous				YES	X NO
2016 - Fall: N	lo Change										
Comments:					4						
2017 - Fall: N	lo Change										
Comments:											
2017 - Spring	g: No Change				1						
Comments:											
2018 - Fall: N	lo Change				+						
Comments:	<u> </u>										
2018 - Spring	g : No Change				-						
Comments:					1						

Material

Damage

Friable

Damage

Material Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
47	2' x 4' Lay-In Ceiling Panels	1500	SF	Rooms 311 and 110		Miscellaneous	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No

Material Description

Material

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
48	1' x 2' Slotted Ceiling Tile			Shop Wing and Gym		Miscellaneous					YES	X NO
2016 - Fall: N	lo Change]							
Comments:	· · · · · · · · · · · · · · · · · · ·											
2017 - Fall: N	lo Change											
Comments:	J											
2017 - Spring	: No Change											
Comments:	•											
2018 - Fall: N	lo Change											
Comments:	Ţ,											
2018 - Spring	ı : No Change											
Comments:	·											
					_							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
49	2' x 8' Textured Ceiling Panels			Rms 122, 124, and 126		Miscellaneous					YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
· · · · · · · · · · · · · · · · · · ·

HA No N	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
50 2	2' x 8' Smooth Ceiling Tile			Shop Wing		Miscellaneous					YES	X NO
2016 - Fall: No	Change											
Comments:	•											
2017 - Fall: No	Change											
Comments:												
2017 - Spring: N	No Change											
Comments:												
2018 - Fall: No	Change											
Comments:												
2018 - Spring : I	No Change											
Comments:	_											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
51	Insulation Behind Pegboard Walls			Auditorium		TSI					YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No

		Quantity	Units		Туре	Category	Туре	Quantity	Units		
52	Roof Flashing - Not AHERA			Shop Roof		Miscellaneous				YES	X NO
2016 - Fall: N	o Change										
Comments:											
2017 - Spring	: No Change										
Comments:											
2017 - Fall: N	o Change										
Comments:											
2018 - Spring	: No Change										
Comments:											
2018 - Fall: No Change											
Comments:											
L					J						

Material

Friable

Damage

Damage

Damage

Change in Assessment Category

H	A No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
5	3	Lab Tops and Sinks	500	SF	Rooms 117, 310, 312, 222, and 224		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No

Material Description

Material

Material

54	Fiberglass Insulation on Suspended HVAC Unit		Room 122		TSI			YES	X NO
				1					
2016 - Fall: N	o Change								
Comments:									
2017 - Spring	: No Change								
Comments:	<u> </u>								
•									
2017 - Fall: N	o Change								
Comments:									
0040 0 0	NI- Observe								
	: No Change								
Comments:									
2018 - Fall: N	o Change								
Comments:									

Type

Material

Category

Damage Quantity Damage

Units

Change in Assessment Category

Damage

Type

Friable

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
55	Vibration Collars	50	LF	Dressing Room, Janitor's Closet in Girl's Locker Room, Room 310 & Electrical Room in Room 206		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No

Material Description

Material

Quantity

Material

Units

56	Terrazzo Sinks			Washrooms		Miscellaneous					YES	X NO
2016 - Fall: I	No Change				7							
Comments:]							
	g: No Change				_							
Comments:					-							
2017 - Fall: I	No Change											
Comments:					_							
	g : No Change											
Comments:					_							
2018 - Fall: I	No Change											
Comments:					_							
					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
57	Insulation Inside Firedoors	160	SF	Exits and Boiler Room		Miscellaneous	No	None	0		YES	X NO

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

Change in Assessment Category

HA No

2016 - Fall: No Change

2017 - Spring: No Change

2018 - Spring : No Change

2017 - Fall: No Change

Comments:

Comments:

Comments:

Comments:

Material Description

Material

Quantity

Material

Units

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
58	Exterior Dark Brick - Not AHERA			Exterior of Main Building		Miscellaneous					YES	X NO
2016 - Fall: N	lo Change]							
Comments:	<u> </u>											
2017 - Spring	g: No Change											
Comments:]							
2017 - Fall: N	lo Change				_							
Comments:												
2018 - Spring	g : No Change											
Comments:												
2018 - Fall: N	lo Change				-							
Comments:												
					J							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
59	Exterior Dark Brick Mortar - Not AHERA			Exterior of Main Building		Miscellaneous					YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category
60	Exterior Light Face Brick - Not AHERA			Exterior of Main Building		Miscellaneous					YES	X NO
2016 - Fall: N	lo Change]							
Comments:	•											
2017 - Spring	ı: No Change				-							
Comments:	J											
2017 - Fall: N	lo Change				_							
Comments:	J											
2018 - Spring	ı : No Change											
Comments:	, <u> </u>											
2018 - Fall: N	lo Change				<u> </u>							
Comments:												
					J							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
61	Exterior Light Face Brick Mortar - Not AHERA			Exterior of Main Building		Miscellaneous					YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:
· · · · · · · · · · · · · · · · · · ·

Futurior Dear Cross t Net	
62 Exterior Door Grout - Not AHERA Exterior of Main Building Miscellaneous	X NO
2016 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
63	Exterior Blue Brick - Not AHERA			Exterior of Main Building		Miscellaneous					YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No

		Quantity	Units		Туре	Category	Туре	Quantity	Units		
64	Exterior Blue Brick Mortar - Not AHERA			Exterior of Main Building		Miscellaneous				YES	X NO
2016 - Fall:	No Change										
Comments:											
2017 - Sprin	g: No Change										
Comments:											
2017 - Fall:	No Change										
Comments:											
2018 - Sprin	g : No Change										
Comments:											
2018 - Fall:	No Change										
Comments:											

Material

Damage

Friable

Damage

Damage

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
65	Exterior Window Grout - Not AHERA			Exterior of Main Building		Miscellaneous					YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No

Material Description

Material

Material

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
66	Roof - Not AHERA			Boiler House		Miscellaneous					YES	X NO
2016 - Fall: N	lo Change				7							
Comments:	J											
2017 - Spring	g: No Change											
Comments:	-											
2017 - Fall: N	lo Change											
Comments:												
2018 - Spring	j : No Change											
Comments:					_							
2018 - Fall: N	lo Change											
Comments:		·		·	_							
						1		1 -	_	_	1 01 1 4	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
67	Roof Flashing - Not AHERA			Boiler House		Miscellaneous					YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

		Quantity	Units		Type	Category	Туре	Quantity	Units		
68	Roof - Not AHERA			Main Building		Miscellaneous				YES	X NO
2016 - Fall: N	lo Change										
Comments.											
2017 - Spring	g: No Change										
Comments:											
2017 - Fall: N	lo Change				<u> </u>						
Comments:	5]						
2018 - Spring	g : No Change										
Comments:											
2018 - Fall: N	lo Change										
Comments:	-]						
					J						

Material

Friable

Damage

Damage

Damage

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
69	Roof Flashing - Not AHERA			Main Building		Miscellaneous					YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No

Material Description

Material

Material

Material Location

Page 80

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
70	Mastic on Wall			Room 128 - Material not observed		Miscellaneous					YES	X NO
2016 - Fall: N	No Change				1							
Comments:												
2017 - Fall: N	No Change											
Comments:												
2017 - Spring	g: No Change											
Comments:												
2018 - Spring	g : No Change											
Comments:												
2018 - Fall: N	No Change											
Comments:												
					_							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
71	1' x 1' Fissured Ceiling Tile Mastic	10000	SF	Throughout Building, Cafeteria		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
· · · · · · · · · · · · · · · · · · ·

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category
72	2' x 4' Ceiling Panels	2400	SF	Room 208, 117		Miscellaneous	Yes	None	0		YES	X NO
2016 - Fall: No Change Comments:												

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2019 Chring : No Chango
2018 - Spring : No Change
Comments:
2040 5 11 11 01
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
73	Drywall	1600	SF	Room 208		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
74	Drywall Compound	200	LF	Room 208		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	No Change											
Comments:												
2017 - Fall:	No Change											
Comments:												
2017 - Sprin	g: No Change											
Comments:												
2018 - Sprin	g : No Change											
Comments:												
2018 - Fall:	No Change											
Comments:	-											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
75	Boiler Gaskets	10	SF	Bryan Boiler in Basement		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
76	12" x 12" Multi-Gray Floor Tile	2000	SF	Rooms 203 & 205		Miscellaneous	No	None	0		YES X NO
0040 5 11 11					i						

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
77	12" x 12" Multi-Gray Floor Tile Mastic	2000	SF	Rooms 203 & 205		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
78	1' x 1' White Small Fissured Ceiling Tile	4700	SF	Lunchroom		Miscellaneous	Yes	None	0		YES X NO
2016 Fall: N	o Chango				1						

L		
		<u> </u>
2016 - Fall: No Change		
Comments:		
2017 - Fall: No Change		
Comments:		
2017 - Spring: No Change		
Comments:		
2018 - Fall: No Change		
Comments:		
2018 - Spring : No Change		
Comments:		

НА	\ No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
80)	12 x 12 gold and beige pattern FT	2000	SF	114, 207, 206, 204, 107		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
80M	12 x 12 gold and beige pattern VFT mastic	2000	SF	114, 207, 206, 204, 107		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
81	12x12 Blueish Grey w/ Dark Grey & White Floor Tile	800	SF	Rm 128, 100		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
82	12x12 Blueish Grey w/Dark Grey & White Floor Tile Mastic	800	SF	Rm 128, 100		Miscellaneous	No	None	0		YES X NO
	•					•		•	•		

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
83	12x12 Lt Grey w/Dark Grey & White Floor Tile	3200	SF	Rm 100, 128, 203, 301, 300, 308		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
84	12x12 Lt Grey w/Dark Grey & White Floor Tile Mastic	3200	SF	Rm 100, 128, 203, 301, 300, 308		Miscellaneous	No	None	0		YES X NO
•											

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
, v
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
85	12" X 12" Blotted Blue VFT	26000	SF	Throughout Hallways and Various Rooms		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
86	12" X 12" Light Blue VFT	4000	SF	Throughout Hallways and Various Classrooms		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change											
Comments:	<u> </u>											
2017 - Spring	: No Change											
Comments:												
2017 - Fall: N	lo Change											
Comments:	•											
2018 - Spring	: No Change											
Comments:												
2018 - Fall: N	lo Change											
Comments:	J											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
87	Mastic for HA 85 and 86	30000	SF	Throughout Hallways and Various Classrooms		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:
· · · · · · · · · · · · · · · · · · ·

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
88	12" x 12" Red Floor Tile	200	SF	Adjacent to Girl's Gym - 1st Floor		Miscellaneous	No	None	0		YES X NO
2016 - Fall: No Change											

2016 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2018 - Fall: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	
89	Mastic Associated w/ 12" x 12" Red Floor Tile	200	SF	Adjacent to Girl's Gym - 1st Floor		Miscellaneous	No	None	0		YES X NO	

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	essment Category
251	Gray Carpet Adhesive			1st Floor Corridor, CPS ID		Miscellaneous					YES	X NO
2016 - Fall: N	lo Change				1							
Comments:												
2017 - Fall: N	lo Change											
Comments:												
2017 - Spring	j: No Change											
Comments:												
2018 - Spring	j : No Change											
Comments:												
2018 - Fall: N	lo Change											
Comments:												
					_							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
1030	12" x 12" White Floor Tile w/ Blue Streaks Mastic	600	SF	208		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:
·

Page 91

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
А	Aircell Pipe Insulation	500	LF	Pipe Chases, Boiler Room and Throughout Building		TSI	Yes	Loc	15		YES X NO
		•		•	1	•	•	•	•		

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
В	(Cardboard) Paperwrap Pipe Insulation	600	LF	Boiler Room and Throughout Building, rm 115, 125		TSI	Yes	Loc	1		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

С	Aircell Duct Insulation	Abated in 1992 - See 2004 Comments		TSI			YES	X NO
2016 Fall N	la Changa		7					
2016 - Fall: N	io Change							
Comments:								
2017 - Spring	j: No Change							
Comments:								
			1					
2017 - Fall: N	lo Change]					
Comments:								
2018 - Fall: N	lo Change							
Comments:								
			1					
2018 - Spring	j : No Change							
Comments:			1					
			1					
			_					

Type

Material

Category

Damage Quantity Damage

Units

Change in Assessment Category

Damage

Type

Friable

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
D	Mag Block Insulation			Boilers in Boiler House - Abated 1992		TSI					YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No

Material Description

Material

Quantity

Material

Units

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	essment Category
E	Mag Block Pipe Insulation			Boiler House - Abated 1992		TSI					YES	X NO
2016 - Fall: N	lo Change]							
Comments:					1							
2017 - Spring	: No Change				_							
Comments:												
2017 - Fall: N	lo Change				_							
Comments:												
2018 - Fall: N	lo Change				_							
Comments:					-							
2018 - Spring	: No Change				=							
Comments:					1							
					1							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
F	Mag Block Duct Insulation			Boiler House - Abated 1992		TSI					YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
G	Fittings on Fiberglass Pipe Insulation	60	LF	Main Building		TSI	Yes	None	0		YES X NO
2016 - Fall: No Change											

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
HA-1000	White woven electrical wire insulation	50	LF	Auditorium stage light fixtures		Miscellaneous	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in As	sessment Category
13 I	9"x 9" White Floor Tile w/Brn & Blk Streaks Mastic			Rooms 212 and 311		Miscellaneous					YES	X NO
2016 - Fall: N	lo Change]							
Comments:	<u> </u>											
2017 - Fall: N	lo Change											
Comments:	Ü											
2017 - Spring	: No Change											
Comments:												
2018 - Spring	: No Change											
Comments:	<u> </u>											
2018 - Fall: N	lo Change											
Comments:	<u> </u>											
					_							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
J	Cementitious Pipe Joint Insulation on Aircell Pipe	50	LF	Pipe Chases, Boiler Room and Throughout Building		TSI	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

Page 96

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
K	Cementitious Pipe Joint Insulation on Paperwrap	20	LF	Boiler Room, Pipe Chases and Throughout Building		TSI	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

Oracle Unit: 53021

ALL LEA Responsibilities, for this school, will be met.

Robert Christlieb

NOTICE TO PARENTS AND STAFF REGARDING THE ASBESTOS MANAGEMENT PLAN NOTIFICATION

School: Paul Laurence Dunbar Career Academy High School
Date: 12/19/2017
This is to notify you in accordance with Illinois and Federal Asbestos Regulations, that a copy of the Asbestos Management Plan is available at each school during school hours by appointment. Requests to review the Asbestos Management Plan must be made at least 24 hours in advance.
Also please be advised that CPS conducts asbestos inspections of all Schools every three years. The last inspection was completed in 2016. Asbestos surveillances are conducted every six months.
CHECK ONE
A copy of this notice was sent home in each child's backpack.
A copy of this notice was printed in the school's newsletter and sent home with each child
A copy of this notice was printed in the school's calendar and sent home with each child
Other.

A COPY OF THIS NOTICE MUST BE PLACED IN THE

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

SCHOOL'S ASBESTOS MANAGEMENT PLAN.

Oracle Unit: 53021