Chicago Public Schools

6 Month Asbestos Surveillance 2018 - Fall

Hope Institute Learning Academy 63031 1650 School: **Oracle Unit: Building ID:** Address: 1628 W. Washington Region: 03 Mail Room: 35 Asbestos Surveyor: Trueblood, Donald X CHECK HERE IF NO CHANGE TO ASBESTOS Survey Date: 1/9/2019 Email Address: A copy of the 2016/2017 notice to parents and staff regarding the asbestos management plan notifications was distributed via: Notice printed in school's newsletter Each child's backpack Notice printed in school's calendar Other HA No Material Description Material Location Asbestos Friable Damage Damage Change in Assessment Category Material Material Damage Quantity Units Type Category Quantity Type Yellow Refractory Brick YES X NO Boiler Room Miscellaneous From Furnace Interior 2016 - Fall: No Change Comments: 2017 - Spring: No Change Comments: 2017 - Fall: No Change Comments: 2018 - Spring: No Change Comments: 2018 - Fall: No Change Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category
2	Red Refractory Brick (Stored in Furnace Door)			Boiler Room		Miscellaneous					YES	X NO
2016 - Fall: N	lo Change				7							
Comments:					1							
2017 - Spring	g: No Change				-							
Comments:												
2017 - Fall: N	lo Change				_							
Comments:					_							
2018 - Spring	j : No Change											
Comments:					_							
2018 - Fall: N	lo Change											
Comments:					-							
					_							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
3	Red Refractory Brick (in Furnace)			North Port		Miscellaneous					YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

Page 2

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category
4	Refractory Mortar (In Furnace)			Boiler Room		Miscellaneous					YES	X NO
2016 - Fall: N	lo Change				1							
Comments:	<u> </u>											
2017 - Spring	ı: No Change											
Comments:												
2017 - Fall: N	lo Change											
Comments:												
2018 - Spring	; No Change											
Comments:												
2018 - Fall: N	lo Change											
Comments:	•											
					J							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
5	Furnace Exterior Brick			Boiler Room		Miscellaneous					YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessr	nent Category
6	Furnace Exterior Refractory Plaster			Boiler Room		Miscellaneous					YES	X NO
2016 - Fall: N	lo Change				7							
Comments:	Ü											
2017 - Spring	ı: No Change											
Comments:	J											
2017 - Fall: N	lo Change				+							
Comments:												
2018 - Spring	ı : No Change				+							
Comments:	<u> </u>											
2018 - Fall: N	lo Change				+							
Comments:	Ü											
	_					1						

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
7	Mortar for Furnace Exterior			Boiler Room		Miscellaneous					YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	essment Category
8	Refractoring Plaster of Lower Wall Furnace			Boiler Room		Miscellaneous					YES	X NO
2016 - Fall: N	No Change											
Comments:	<u> </u>											
2017 - Spring	g: No Change											
Comments:												
2017 - Fall: N	No Change											
Comments:					_							
	g : No Change											
Comments:					_							
2018 - Fall: N	No Change											
Comments:					_							
					_1							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
9	Wall Plaster	100	SF	Boiler Room		Surface	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:
·

10	Cementitious Boiler Door Insulation		Boiler Room		TSI			YES	X NO
				1					
2016 - Fall: N	o Change								
Comments:									
2017 - Spring	: No Change								
Comments:	<u> </u>								
2017 - Fall: N	o Change								
Comments:									
2018 - Spring	: No Change								
Comments:									
2018 - Fall: N	o Change								
Comments:									

Type

Material

Category

Damage Quantity Damage

Units

Change in Assessment Category

Damage

Type

Friable

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
11	Boiler Door Gasket			Boiler Room		Miscellaneous					YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No

Material Description

Material

Quantity

Material

Units

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessmo	ent Category
12	Boiler Interior Fiber (Insulation)			Boiler Room		Miscellaneous					YES	X NO
2016 - Fall: N	lo Change				1							
Comments:	<u> </u>											
2017 - Spring	: No Change				1							
Comments:												
2017 - Fall: N	lo Change											
Comments:												
2018 - Spring	: No Change											
Comments:												
2018 - Fall: N	lo Change											
Comments:	•											
					_							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
13	Roof of Furnace (Plaster)			Boiler Room		Miscellaneous					YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:
· · · · · · · · · · · · · · · · · · ·

Page 7

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
14	Plaster Ceiling			Boiler Room		Miscellaneous					YES	X NO
2016 - Fall: N	No Change											
Comments:	<u> </u>											
2017 - Spring	g: No Change											
Comments:												
2017 - Fall: N	No Change											
Comments:												
2018 - Spring	g : No Change											
Comments:												
2018 - Fall: N	No Change											
Comments:												
r	,			,			,	_			•	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
15	Refractory Glazing Inside Furnace			Boiler Room		Miscellaneous					YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category
16	Covering on Tank on Top of Furnace			Boiler Room		Miscellaneous					YES	X NO
2016 - Fall: N	o Change]							
Comments:					1							
2017 - Spring	: No Change											
Comments:					1							
2017 - Fall: N	o Change											
Comments:												
2018 - Spring	: No Change											
Comments:												
2018 - Fall: N	o Change				1							
Comments:					1							
					J							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
17	Plaster on Top of West Furnace			Boiler Room		Miscellaneous					YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

Page 9

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category
18	Insulation Around Tank on Top of Furnace			Boiler Room		Miscellaneous					YES	X NO
2016 - Fall: N	lo Change				1							
Comments:	<u> </u>											
2017 - Spring	: No Change				1							
Comments:]							
2017 - Fall: N	lo Change				1							
Comments:	•											
2018 - Spring	: No Change											
Comments:]							
2018 - Fall: N	lo Change				-							
Comments:	.											
					J							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
19	Interior Brick			Boiler Room		Miscellaneous					YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category
20	Interior Brick Mortar			Boiler Room		Miscellaneous					YES	X NO
2016 - Fall: N	lo Change				7							
Comments:	<u> </u>											
2017 - Spring	ı: No Change											
Comments:	,											
2017 - Fall: N	lo Change											
Comments:	J											
2018 - Spring	ı : No Change											
Comments:												
2018 - Fall: N	lo Change				+							
Comments:												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
21	Exterior Brick - Not AHERA			Exterior of Building		Miscellaneous					YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category
22	Exterior Brick Mortar - Not AHERA			Exterior of Building		Miscellaneous					YES	X NO
2016 - Fall: N	lo Change				1							
Comments:	V]							
2017 - Spring	g: No Change				-							
Comments:]							
2017 - Fall: N	lo Change]							
Comments:												
2018 - Spring	; No Change											
Comments:												
2018 - Fall: N	lo Change											
Comments:												
					J							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
23	Exterior Glazed Brick - Not AHERA			Exterior of Building (Around Window)		Miscellaneous					YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:
· · · · · · · · · · · · · · · · · · ·

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
24	TSI Covering (Elbows, Valves, Fittings)	25	SF	Throughout Bldg. Basement Boiler Room & Adjacent to Boiler Rm.		TSI	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
25	TSI on Elbow, Valves & Fittings	25	SF	Throughout Bldg. Basement Boiler Room & Adjacent to Boiler Rm.		TSI	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category
26	Exterior Door Caulk - Not AHERA			Exterior of Building		Surface					YES	X NO
2016 - Fall: N	o Change]							
Comments:	Ü											
2017 - Spring	: No Change											
Comments:	-											
2017 - Fall: N	o Change				_							
Comments:												
2018 - Spring	: No Change											
Comments:												
2018 - Fall: N	o Change				_							
Comments:												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
27	Exterior Window Caulk - Not AHERA			Exterior of Building		Surface					YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

Page 14

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
28	12" x 12" Tan Floor Tile	1250	SF	Lunchroom		Miscellaneous	No	None	0		YES X NO
2016 - Fall: N	2016 - Fall: No Change										

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
28 M	12" x 12" Tan Floor Tile Mastic	1250	SF	Lunchroom		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:
·

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	essment Category
29	12" x 12" Grey-Brown Floor Tile	200	SF	Lunchroom		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: I	No Change											
Comments:												
2017 - Fall: I	No Change											
Comments:	<u> </u>											
2017 - Sprin	g: No Change											
Comments:												
2018 - Sprin	g : No Change											
Comments:												
2018 - Fall: I	No Change											
Comments:	5											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
29 M	12" x 12" Grey-Brown Floor Tile Mastic			Lunchroom		Miscellaneous					YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
30	12"x12" Wt. w/BurntOrange&Black Streaks Floor Tile ABATED			Lunchroom, Physical Therapy, Office, Rooms 104, 109, 111,201,203,205,207,209 ,211,213,215,217,etc.		Miscellaneous					YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
30 M	12"x12" Wt. w/BurntOrange&Black Streaks FT Mastic ABATED			Lunchroom, Physical Therapy, Office, Rooms 104, 109, 111, 201,203,205,207,209,211 ,213,215,217,etc.		Miscellaneous					YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
31	9" x9" Burnt Orange Floor Tile ABATED			Closet Room 108, Rooms 101, 103, 105, 109, 163, 167, 168B. 173, 175		Miscellaneous					YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

31 M	9" x9" Burnt Orange Floor Tile Mastic ABATED			Closet Room, Rooms 108, 101, 103, 105, 109, 163, 167, 168B. 173, 175		Miscellaneous					YES	X NO
2016 - Fa	ıll: No Change				7							
Comment					1							
2017 - Sp	oring: No Change				-							
Comment												
2017 - Fa	III: No Change				-							
Comment	ts:											
2018 - Sp	oring : No Change				-							
Comment	ts:											
2018 - Fa	III: No Change				-							
Comment	ts:											
					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
32	Fiber Interlocking 2' x 2'			Lunchroom		Miscellaneous					VES	X NO

Type

Material

Category

Miscellaneous

Friable

Damage

Type

Damage

Units

Damage

Quantity

Change in Assessment Category

HA No

32

Material Description

Ceiling Tile

Material

Units

Material

Quantity

Material Location

Closet Boom, Booms

Lunchroom

X NO

YES

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessr	nent Category
33	2' x 4' Ceiling Tile (Fissured)			1st Floor Hallway		Miscellaneous					YES	X NO
2016 - Fall: N	o Change											
Comments:	J											
2017 - Spring	: No Change											
Comments:												
2017 - Fall: N	o Change											
Comments:												
2018 - Spring	: No Change											
Comments:												
2018 - Fall: N	o Change				_							
Comments:												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
34	Stair Tread			Stairs		Miscellaneous					YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:
·

Page 20

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
34 M	Mastic Under Stair Tread			Stairs		Miscellaneous					YES X NO
2016 - Fall	: No Change										
Comments											
2017 - Spr	ing: No Change										
Comments											
2017 - Fall	: No Change										
Comments	<u> </u>										
2018 - Spr	ing : No Change										
Comments	S:										
2018 - Fall	: No Change										
Comments											
LIA NI-	Material Description	Matarial	Matarial	Matarial Lagation	A = b = = 4 = =	Maradal .	Frields	Damasa	Damasa		Character Assessment Catagon

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
35	Tile Edging ABATED			Assembly Hall Stage		Miscellaneous					YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:
·

HA No

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessr	ment Category
35 M	Tile Edging Mastic ABATED			Assembly Hall Stage		Miscellaneous					YES	X NO
2016 - Fall: N	lo Change]							
Comments:	Ü											
2017 - Spring	ı: No Change				<u> </u>							
Comments:	,											
2017 - Fall: N	lo Change											
Comments:	<u> </u>											
2018 - Spring	ı : No Change											
Comments:	, <u> </u>											
2018 - Fall: N	lo Change											
Comments:												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
36	Plaster Wall (Decorative)			Assembly Hall		Miscellaneous					YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
37	Black Baseboard	200	LF	Bathrooms 1st Floor Men's & Women's		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change				1							
Comments:	Ü											
2017 - Fall: N	lo Change											
Comments:	J											
2017 - Spring	g: No Change											
Comments:												
2018 - Spring	g : No Change				1							
Comments:	.											
2018 - Fall: N	lo Change											
Comments:	<u> </u>											
					_							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
37 M	Black Baseboard Mastic			Bathrooms 1st Floor Men's & Women's		Miscellaneous					YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
38	Carpet Mastic			Room 161		Miscellaneous					YES	X NO
2016 - Fall: N	lo Change											
Comments:	J											
2017 - Spring	g: No Change											
Comments:												
2017 - Fall: N	lo Change											
Comments:												
	g : No Change											
Comments:												
2018 - Fall: N	lo Change											
Comments:					_							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
39	9" x 9" Tan Floor Tile ABATED			Room 300		Miscellaneous					YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	essment Category
39 M	9" x 9" Tan Floor Tile Mastic ABATED			Room 300		Miscellaneous					YES	X NO
2016 - Fall: N	lo Change											
Comments:												
2017 - Spring	g: No Change											
Comments:												
2017 - Fall: N	lo Change											
Comments:					_							
	g : No Change											
Comments:					_							
2018 - Fall: N	lo Change											
Comments:					_							
					_							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
40	9" x 9" Orange Floor Tile ABATED			Room 300		Miscellaneous					YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:
·

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in As	sessment Category
40 M	9" x 9" Orange Floor Tile Mastic ABATED			Room 300		Miscellaneous					YES	X NO
2016 - Fall: N	lo Change				1							
Comments:												
2017 - Spring	g: No Change											
Comments:												
2017 - Fall: N	lo Change											
Comments:												
	g : No Change											
Comments:												
2018 - Fall: N	lo Change											
Comments:												
					_							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
41	9" x 9" White & Beige Floor Tile ABATED			Room 301		Miscellaneous					YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:
·

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
41 M	9" x 9" White & Beige Floor Tile Mastic ABATED			Room 301		Miscellaneous					YES	X NO
2016 - Fall: N	lo Change]							
Comments:	J				- -							
2017 - Spring	g: No Change				_							
Comments:												
2017 - Fall: N	lo Change											
Comments:					-							
2018 - Spring	j : No Change											
Comments:					-							
2018 - Fall: N	lo Change											
Comments:					-							
]							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
42	9" x 9" Green Floor Tile ABATED			Room 301		Miscellaneous					YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessi	ment Category
42 M	9" x 9" Green Floor Tile Mastic ABATED			Room 301		Miscellaneous					YES	X NO
2016 - Fall: N	o Change				7							
Comments:												
2017 - Spring	: No Change											
Comments:												
2017 - Fall: N	o Change											
Comments:					4							
2018 - Spring	: No Change											
Comments:					4							
2018 - Fall: N	o Change											
Comments:					4							
					_							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
43	Veneer Plaster			Room 301		Miscellaneous					YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:
· · · · · · · · · · · · · · · · · · ·

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessi	ment Category
44	Substrate Plaster			Room 301		Miscellaneous					YES	X NO
2016 - Fall: N	lo Change]							
Comments:	•]							
2017 - Spring	: No Change				1							
Comments:	<u> </u>											
2017 - Fall: N	lo Change				1							
Comments:	<u> </u>											
2018 - Spring	: No Change				1							
Comments:												
2018 - Fall: N	lo Change				-							
Comments:]							
					J							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
45	Metal Roof Flashing Caulk - Not AHERA			Roof		Miscellaneous					YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

Page 29

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessm	nent Category
46	12" x 12" Red/Brown Floor Tile ABATED			Assembly Hall		Miscellaneous					YES	X NO
2016 - Fall: N	o Change]							
Comments:	<u> </u>											
2017 - Fall: N	o Change											
Comments:	<u> </u>											
2017 - Spring	: No Change											
Comments:												
2018 - Spring	: No Change											
Comments:												
2018 - Fall: N	o Change											
Comments:												
					J							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
46 M	12" x 12" Red/Brown Floor Tile Mastic ABATED			Assembly Hall		Miscellaneous					YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category
47	12" x 12" Dark Brown Floor Tile ABATED			Assembly Hall		Miscellaneous					YES	X NO
2016 - Fall: N	o Change]							
Comments:	<u> </u>											
2017 - Fall: N	o Change				_							
Comments:												
2017 - Spring	: No Change											
Comments:					-							
2018 - Spring	: No Change											
Comments:					_							
2018 - Fall: N	o Change]							
Comments:					-							
					J							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
47 M	12" x 12" Dark Brown Floor Tile Mastic ABATED			Assembly Hall		Miscellaneous					YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:
· · · · · · · · · · · · · · · · · · ·

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category
48	9" x 9" Dark Orange Brown Accent Floor Tile ABATED			Rooms 154, 155 & 156		Miscellaneous					YES	X NO
2016 - Fall: N	lo Change				1							
Comments:	Ü]							
2017 - Fall: N	lo Change				-							
Comments:]							
2017 - Spring	ı: No Change											
Comments:					-							
2018 - Spring	: No Change				<u> </u>							
Comments:					_							
2018 - Fall: N	lo Change											
Comments:												
					J							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
48 M	9"x9" Dark Orange Brown Accent Floor Tile Mastic ABATED			Rooms 154, 155 & 156		Miscellaneous					YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
49	9" x 9" Orange/Brown Blended Accent Floor Tile			Rooms 154, 155, & 156		Miscellaneous					YES	X NO
2016 - Fall: N	lo Change]							
Comments:												
2017 - Fall: N	lo Change				-							
Comments:												
2017 - Spring	g: No Change				}							
Comments:												
2018 - Spring	g : No Change											
Comments:												
2018 - Fall: N	lo Change				-							
Comments:												
					J							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
49 M	9"x9"Orange/Brown Blended Accent Floor Tile Mastic ABATED			Rooms 154, 155, & 156		Miscellaneous					YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	sessment Category
50	9" x 9" Light Orange Floor Tile ABATED			Room 166		Miscellaneous					YES	X NO
2016 - Fall: N	lo Change]							
Comments:]							
2017 - Fall: N	lo Change											
Comments:												
2017 - Spring	j: No Change											
Comments:					<u> </u>							
2018 - Spring	j : No Change											
Comments:					 							
2018 - Fall: N	lo Change											
Comments:					 							
					1							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
50 M	9" x 9" Light Orange Floor Tile Mastic ABATED			Room 166		Miscellaneous					YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

51	9" x 9" Tan (Dark Orange) Streaked Floor Tile ABATED			Rooms 173 & 175		Miscellaneous					YES	X NO
2016 - Fall: N	Vo Change				1							
Comments:	10 Orlange											
2017 - Fall: N	No Change											
Comments:	_											
2017 - Sprine	g: No Change				_							
Comments:												
2018 - Spring	g : No Change				_							
Comments:	J J											
2018 - Fall: N	No Change				1							
Comments:	<u> </u>											
					J							
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Assess	ment Category

Type

Asbestos

Type

Material

Category

Category

Miscellaneous

Friable

Damage

Type

Туре

Damage

Quantity

Quantity

Units

YES

X NO

Damage

Units

51 M	9" x 9" Tan (Dk Orange) Streaked Floor Tile Mastic ABATED			Rooms 173 & 175					
2016 - Fall: No Change									
Comments:									
2017 - Spring	2017 - Spring: No Change								
Comments:									
2017 - Fall: N	o Change								
Comments:									
2018 - Spring	: No Change								
Comments:									
2018 - Fall: N	o Change								
Comments:			•						
			·						

Quantity

Units

HA No

Material Description

Material

Units

Material

Quantity

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	essment Category
52	9" x 9" Tan & Light Orange Floor Tile ABATED			Room 186, Copy Center, 13 B		Miscellaneous					YES	X NO
2016 - Fall: N	lo Change]							
Comments:	-				1							
2017 - Fall: N	lo Change											
Comments:					-							
2017 - Spring	: No Change											
Comments:					-							
2018 - Spring	: No Change											
Comments:					-							
2018 - Fall: N	lo Change											
Comments:					=							
					J							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
52 M	9" x 9" Tan & Light Orange Floor Tile Mastic ABATED			Room 186, Copy Center, 13 B		Miscellaneous					YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category
53	9" x 9" Dark Orange Floor Tile			Room 186, Copy Center		Miscellaneous					YES	X NO
2016 - Fall: N	lo Change											
Comments:												
2017 - Fall: No Change												
Comments:												
2017 - Spring	: No Change											
Comments:												
2018 - Spring	: No Change											
Comments:												
2018 - Fall: N	lo Change											
Comments:	<u> </u>											
					J							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
53 M	9" x 9" Tan/Dark Orange Floor Tile Mastic			Room 186, Copy Center,		Miscellaneous					YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

Page 37

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
54	12" x 12" Dark Beige Floor Tile			Entrance by Dock		Miscellaneous					YES	X NO
2016 - Fall: N	o Change				1							
Comments:	<u> </u>											
2017 - Fall: N	o Change	1										
Comments:	<u> </u>											
2017 - Spring	: No Change											
Comments:	J											
2018 - Spring	: No Change											
Comments:	<u> </u>											
2018 - Fall: N	o Change											
Comments:	Ü											
					_							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
54 M	12" x 12" Dark Beige Floor Tile Mastic ABATED			Entrance by Dock		Miscellaneous					YES X NO
2016 - Fall: N	o Change										

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:
· · · · · · · · · · · · · · · · · · ·

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessn	nent Category
55	Linoleum Floor Sheeting			1st Floor Dressing Room by Pool		Miscellaneous					YES	X NO
2016 - Fall: N	lo Change]							
Comments:	J											
2017 - Spring	ı: No Change											
Comments:	,											
2017 - Fall: N	lo Change											
Comments:	<u> </u>											
2018 - Spring	ı : No Change											
Comments:	, J											
2018 - Fall: N	lo Change											
Comments:	y -											
]							
											1	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
56	9" x 9" Red Floor Tile ABATED			Room 183, 1st Floor Storage, Vault in Main Office		Miscellaneous					YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
56 M	9" x 9" Red Floor Tile Mastic ABATED			Room 183, 1st Floor Storage		Miscellaneous					YES	X NO
2016 - Fall: N	lo Change											
Comments:												
2017 - Spring	g: No Change											
Comments:					_							
2017 - Fall: N	lo Change				_							
Comments:					_							
	g : No Change											
Comments:					_							
2018 - Fall: N	lo Change											
Comments:					_							
					_							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
57	12" x 12" Black Floor Tile ABATED			Hallway at Engineer's Office and Engineer's Office		Miscellaneous					YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

57m	12" x 12" Black Floor Tile Mastic ABATED			Hallway at Engineer's Office and Engineer's Office		Miscellaneous					YES	X NO
2016 - Fal	I: No Change				7							
Comment												
2017 - Sp	ring: No Change				-							
Comment]							
2017 - Fal	I: No Change				-							
Comment	S:											
2018 - Sp	ring : No Change											
Comment	S:				_							
2018 - Fal	I: No Change											
Comment	S:											
					_							
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Assess	sment Category

Type

Type

Material

Category

Category

Miscellaneous

Friable

Damage

Type

Туре

Damage

Quantity

Quantity

Units

YES

X NO

Damage

Units

Quantity

Units

Roof

HA No

58

Material Description

Roof Flashing - NON-

AHERA

Material

Quantity

Material

Units

Material Location

59	Cardboard Pipe Insulation	Accessible Insulation Abated	TSI	N	None		YES	X NO
0040 5-11 1	I. Oli a con		٦					
2016 - Fall: N	No Change		1					
Comments:								
			1					
2017 - Spring	g: No Change							
Comments:								
2017 - Fall: N	lo Change							
Comments:								
2018 - Spring	g : No Change							
Comments:								
			<u> </u>					
2018 - Fall: N	lo Change							
Comments:			1					
]					

Type

Material

Category

Damage Type

Friable

Damage Quantity Damage

Units

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
60	Cementitious Joint Insulation - Cardboard Pipe Lag			Throughout Facility - All Accessible Insulation Abated		TSI		None			YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No

Material Description

Material

Quantity

Material

Units

61	Aircell Pipe Insulation	Accessible Insulation Abated	TSI	None		YES	X NO
2016 - Fall:	No Change]				
			4				
Comments:							
2017 - Sprir	ng: No Change						
Comments:							
2017 - Fall:	No Change						
Comments:			1				
			1				
2018 - Sprir	ng : No Change		1				
Comments:	-		1				
			1				
2018 - Fall:	No Change						
Comments:			1				
			1				
			-				

Type

Material

Category

Damage Quantity Damage

Units

Change in Assessment Category

Damage

Type

Friable

62 Cementitious Pipe Joint Insulation on Aircell Lag Accessible Insulation TSI None YES X	HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Categor
Abated About All All All All All All All All All Al	62	Cementitious Pipe Joint Insulation on Aircell Lag			Accessible Insulation		TSI		None			YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No

Material Description

Material

Quantity

Material

Units

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
63	Aircell Duct Insulation			Abated		Miscellaneous					YES	X NO
2016 - Fall: N	lo Change											
Comments:	Ü											
2017 - Spring	: No Change											
Comments:												
2017 - Fall: N	lo Change				1							
Comments:												
2018 - Spring	ı : No Change				=							
Comments:												
2018 - Fall: N	lo Change											
Comments:												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
64	9" x 9" Dark Brown Floor Tile ABATED			SR217 & SR110		Miscellaneous					YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:
· · · · · · · · · · · · · · · · · · ·

HA No

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	essment Category
65	9" x 9" Dark Brown Floor Tile Mastic ABATED			SR217 & SR110		Miscellaneous					YES	X NO
2016 - Fall: N	lo Change											
Comments:												
2017 - Spring	g: No Change											
Comments:												
2017 - Fall: N	lo Change											
Comments:												
2018 - Spring	g : No Change											
Comments:					_							
2018 - Fall: N	lo Change											
Comments:												
L					J							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
66	9" x 9" Medium Brown Floor Tile w/Wh Streaks ABATED			Room 257		Miscellaneous					YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

67	Tile w/Wh Streaks Mastic ABATED			Room 257		Miscellaneous					YES	X NO
2016 - Fa	II: No Change			•	7			·	•		•	
Comment					-							
Comment	5.				+							
2017 - Sp	ring: No Change											
Comment	S:											
0047 Fo	II. No Change				_							
	II: No Change											
Comment	S:				_							
2018 - Sp	ring : No Change											
Comment												
2018 - Fa	II: No Change											
Comment												
	- -				_							
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Assess	ment Category

Type

Type

Material

Category

Category

Miscellaneous

Friable

Туре

Damage

Туре

Damage

Quantity

Quantity

Damage

YES

X NO

Units

Units

Change in Assessment Category

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

Quantity

Units

HA No

68

Material Description

9" x 9" Brown Speckled Floor Tile ABATED

Material

Units

Material

Quantity

Material Location

Room 293

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
69	9" x 9" Brown Speckled Floor Tile Mastic ABATED			Room 293		Miscellaneous					YES	X NO
2016 - Fall: N	lo Change											
Comments:												
2017 - Spring	ı: No Change				-							
Comments:	•]							
2017 - Fall: N	lo Change				-							
Comments:	<u> </u>				1							
2018 - Spring	ı : No Change				-							
Comments:	•]							
2018 - Fall: N	lo Change				-							
Comments:	V]							
					_							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
70	9" x 9" Light Brown Floor Tile ABATED			Rooms 100, 202, 204 A, 206, 210, 265		Miscellaneous					YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	
71	9" x 9" Light Brown Floor Tile Mastic ABATED			Rooms 100, 202, 204 A, 206, 210, and 265		Miscellaneous					YES	X NO
2016 - Fall: N Comments:	2016 - Fall: No Change Comments:											

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
·

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
72	9" x 9" Brown Spotted Floor Tile	3000	SF	Rooms 101, 160, 185, and 187		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:
·

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
73	9" x 9" Brown Spotted Floor Tile Mastic ABATED			Rooms 101, 160, 185, and 187		Miscellaneous					YES	X NO
2016 - Fall: N	lo Change]							
Comments:												
2017 - Spring	j: No Change											
Comments:					<u> </u>							
2017 - Fall: N	lo Change											
Comments:					-							
	j : No Change				-							
Comments:					-							
2018 - Fall: N	lo Change											
Comments:					-							
					J							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
74	4" Black Baseboard			Room 107A, 1st Floor Men and Women Restrooms		Miscellaneous					YES X NO

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asso	essment Category
75	4" Black Baseboard Adhesive			Room 107A		Miscellaneous					YES	X NO
2016 - Fall: N	lo Change											
Comments:												
2017 - Fall: N	lo Change											
Comments:												
2017 - Spring	g: No Change											
Comments:												
	g : No Change											
Comments:												
2018 - Fall: N	lo Change											
Comments:												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
76	Transite Sink & Counter ABATED			Rooms 280 & 282		Miscellaneous					YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:
·

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
77	Desk Tops ABATED			Rooms 280 & 282		Miscellaneous					YES	X NO
2016 - Fall:	No Change											
Comments:												
2017 - Fall:	No Change											
Comments:												
2017 - Sprin	ng: No Change											
Comments:	-											
2018 - Sprin	ng : No Change				-							
Comments:												
2018 - Fall:	No Change											
Comments:	Ţ											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
78	Brown Border Tile ABATED			Under Radiators in Room 301		Miscellaneous					YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category
79	Brown Border Tile Mastic ABATED			Under Radiators in Room 301		Miscellaneous					YES	X NO
2016 - Fall: N	lo Change											
Comments:	•											
2017 - Fall: N	lo Change											
Comments:												
2017 - Spring	: No Change											
Comments:												
2018 - Spring	: No Change											
Comments:												
2018 - Fall: N	lo Change											
Comments:												
					1							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
80	Fume Hood Components ABATED			Room 280		Miscellaneous					YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
81	White Rolled Flooring			Room 280		Miscellaneous					YES	X NO
2016 - Fall:	No Change											
Comments:												
2017 - Fall:	No Change											
Comments:												
2017 - Spri	ng: No Change											
Comments:	· ·											
2018 - Spri	ng : No Change											
Comments:												
2018 - Fall:	No Change											
Comments:												
	T			T				T _				

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
82	White Rolled Flooring Adhesive			Room 280		Miscellaneous					YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No

83	12" x 12" Light Beige Speckled Floor Tile ABATED	2nd Floor Stairwell #6 Landing and Room 212A		Miscellaneous			YES	X NO
2016 - Fall: N	lo Change		1					
Comments:	io Change		-					
Comments.			-					
2017 - Fall: N	lo Change							
Comments:	-							
2017 - Spring	g: No Change							
Comments:								
	g : No Change							
Comments:								
0040 5 11 1			-					
2018 - Fall: N	lo Change							
Comments:								

Type

Material

Category

Miscellaneous

Asbestos

Type

Material

Category

Friable

Friable

Damage

Туре

Damage

Type

Damage

Quantity

Damage

Quantity

Damage

Damage

Units

Units

		_		
84	12" x 12" Light Beige Speckled Floor Tile Mastic ABATED			2nd Floor Stairwell #6 Landing and Room 212A
2016 - Fall: N	lo Change			
Comments:				
2017 - Fall: N	lo Change			
Comments:				
2017 - Spring	յ։ No Change			
Comments:				
2018 - Spring	j : No Change			
Comments:				
2018 - Fall: N	lo Change			
Comments:	·			_
			•	

Material

Quantity

Material

Units

HA No

HA No

Material Description

Material Description

Material

Units

Material

Quantity

Material Location

Material Location

Change in Assessment Category

Change in Assessment Category

X NO

YES

85	9" x 9" Black w/White Streaks Floor Tile ABATED		Room 212		Miscellaneous			YES	X NO
				1					
2016 - Fall: N	o Change								
Comments:									
2017 - Fall: N	o Change								
Comments:									
2017 - Spring	: No Change								
Comments:	_								
2018 - Spring	: No Change								
Comments:									
2018 - Fall: N	o Change								
Comments:									
	·	·	 						

Type

Material

Category

Damage Quantity Damage

Units

Change in Assessment Category

Damage

Type

Friable

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
86	9" x 9" Black w/White Streaks Floor Tile Mastic ABATED			Room 212		Miscellaneous					YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No

Material Description

Material

Quantity

Material

Units

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
87	Plaster	200000	SF	Throughout School		Miscellaneous	Yes	None	0		YES	X NO
2016 - Fall: N	lo Change]							
Comments:												
2017 - Spring	g: No Change											
Comments:												
2017 - Fall: N	lo Change				1							
Comments:												
2018 - Fall: N	lo Change				1							
Comments:												
2018 - Spring	g : No Change				1							
Comments:												
					_							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
88	2 x 4 Ceiling Tiles	60000	SF	Rooms 115, 116, 127, 129, 204, 218, 219, 221, 227, 233, 235, 245, 249, 264		Miscellaneous	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
89	Grey Ceramic Flooring & Grout	6600	SF	1, 2, 3, Floor Boys & Girls Bathroom		Miscellaneous	No	None	0		YES X NO
2016 - Fall: N	o Change										

2016 - Fall: No Change Comments: 2017 - Spring: No Change Comments: 2017 - Fall: No Change Comments: 2018 - Fall: No Change Comments: 2018 - Spring : No Change Comments:	
Comments: 2017 - Spring: No Change Comments: 2017 - Fall: No Change Comments: 2018 - Fall: No Change Comments: 2018 - Spring : No Change	
2017 - Spring: No Change Comments: 2017 - Fall: No Change Comments: 2018 - Fall: No Change Comments: 2018 - Spring : No Change	2016 - Fall: No Change
Comments: 2017 - Fall: No Change Comments: 2018 - Fall: No Change Comments: 2018 - Spring : No Change	Comments:
Comments: 2017 - Fall: No Change Comments: 2018 - Fall: No Change Comments: 2018 - Spring : No Change	
2017 - Fall: No Change Comments: 2018 - Fall: No Change Comments: 2018 - Spring : No Change	2017 - Spring: No Change
Comments: 2018 - Fall: No Change Comments: 2018 - Spring : No Change	Comments:
Comments: 2018 - Fall: No Change Comments: 2018 - Spring : No Change	
2018 - Fall: No Change Comments: 2018 - Spring : No Change	2017 - Fall: No Change
Comments: 2018 - Spring : No Change	Comments:
Comments: 2018 - Spring : No Change	2018 - Fall: No Change
Comments:	2018 - Spring : No Change
	Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
90	Grey Ceramic Flooring Mastic	6600	SF	1, 2, 3, Boys & Girls Bathroom		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in As	ssessment Category
91	Red Ceramic Flooring and Grout	2100	SF	1st Floor Kitchen		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: I	No Change				\exists							
Comments:												
2017 - Sprin	g: No Change											
Comments:												
2017 - Fall: I	No Change											
Comments:	-											
2018 - Fall: I	No Change											
Comments:	J											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
92	Red Ceramic Flooring Mastic	2100	SF	1st Floor Kitchen		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

2018 - Spring : No Change

Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in	Assess	ment Category
93	12 x 12 White w/Black & Brown Floor Tile	6000	SF	Wheel Chair Ramps		Miscellaneous	No	None	0		YES		X NO
2016 - Fall: N	No Change]								
Comments:													
2017 - Fall: N	No Change												
Comments:	<u> </u>]								
2017 - Spring	g: No Change				1								
Comments:]								
2018 - Fall: N	No Change				1								
Comments:	•]								
2018 - Spring	g : No Change												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
93M	12 x 12 White Floor Tile Mastic	6000	SF	Wheel Chair Ramps		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
94	Gold and Brown Carpet Mastic	3000	SF	Assembly Hall		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: No Change Comments:												
2017 - Spring: No Change Comments:												

2017 - Fall: No Change Comments:

2018 - Fall: No Change Comments:

2018 - Spring : No Change

Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
95	12 x 12 Dark Brown Floor Tile	300	SF	Engineer Office and Hallway		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
95M	12 x 12 Dark Brown Floor Tile Mastic	300	SF	Engineer Office and Hallway		Miscellaneous	No	None	0		YES X NO
2016 - Fall: N	o Change										

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2018 - Fall: No Change	
Comments:	
2010 0 1 11 01	
2018 - Spring : No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
96	Drywall	2500	SF	Lunch Room Main Entrance		Miscellaneous	No	None	0		YES X NO

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
97	Drywall Joint Compound	2500	SF	Lunch Room Main Entrance		Miscellaneous	No	None	0		YES	X NO
2016 - Fall	: No Change	•						•				
Comments	<u> </u>											
2017 - Spr	ing: No Change											
Comments	:											
2017 - Fall	: No Change											
Comments	:											
2018 - Fall	: No Change											
Comments	:											
2018 - Spr	ing : No Change											
Comments												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
98	12 x 12 Tan w Grey Floor Tile	50000	SF	1, 2, 3, Floor Classrooms, Storage Rooms and Janitor Closets		Miscellaneous	No	None	0		YES X NO

016 - Fall: No Change	
Comments:	
017 - Fall: No Change	
Comments:	
017 - Spring: No Change	
Comments:	
018 - Fall: No Change	
Comments:	
018 - Spring : No Change	
Comments:	

HA No

	Quantity	Units		Туре	Category		Туре	Quantity	Units	Change in Assessment Category
98M 12 x 12 Tar Mastic	an Floor Tile 50000	SF	1, 2, 3, Floor Classrooms Storage Rooms and Janitor Closets		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	-
2017 - Spring: No Change	
Comments:	
018 - Fall: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
99	12 x 12 White w/ Brown Streaks	12000	SF	1, 2, 3, Stairwell Landing, Main Entrance, 100 A-G, 101 A-F and Hallways		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
99M	12 x 12 Wite Floor Tile Mastic	12000	SF	1, 2, 3, Stairwell Landings, Main Entrance 100A - G, 101 A-F and Hallwasys		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2018 - Fall: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
100	12 x 12 Dark Grey Floor Tile	800	SF	Assembly Hall Stage		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
100M	12 x 12 Dark Grey Floor Tile Mastic	800	SF	Assembly Hall Stage		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N Comments:	lo Change											

2016 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2018 - Fall: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
101	12 x 12 Sea Green Floor Tile	100	SF	Hallway by 105-107		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:
·

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
101M	12 x 12 Sea Green Floor Tile Mastic	100	SF	Hallway by 105-107		Miscellaneous	No	None	0		YES X NO
204C Fall N	2010. Fall Na Charge										

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
102	12 x 12 Dark Brown Floor Tile	100	SF	Hallway by 301, 221		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
102M	12 x 12 Floor Tile Mastic	100	SF	Hallway by 301, 221		Miscellaneous	No	None	0		YES X NO
2016 - Fall: N	2016 - Fall: No Change										

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
OOAO Fall No Observe	
2018 - Fall: No Change	
Comments:	
2040 Carian Na Channa	
2018 - Spring : No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
103	12 x 12 Yellow Floor Tile	200	SF	3rd Floor Hallway, Room 300 Main Entrance		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
103M	12 x 12 Yellow Floor Tile Mastic	200	SF	3rd Floor Hallway, 301 Main Entrance		Miscellaneous	No	None	0		YES X NO
2016 - Fall: N	o Change										

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
104	12 x 12 Dark Blue Floor Tile	100	SF	3rd Floor Hallway Main Entrance		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:
·

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
104M	12 x 12 Dark Blue Floor Tile Mastic	100	SF	3rd Floor Hallway Main Entrance		Miscellaneous	No	None	0		YES X NO
2016 - Fall: N	o Change										

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
105	12 x 12 Red Floor Tile	400	SF	2nd Floor Hallway Main Entrance		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
105M	12 x 12 Red Floor Tile Mastic	400	SF	2nd Floor Hallway Main Entrance		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N Comments:	o Change											

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 Chring: No Change
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
200	2 X 4 Solid Ceiling Tile	50000	SF	1st, 2nd, and 3rd Floor Corridors		Miscellaneous	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:
·

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
201	12" X 12" Light brown w/Speckles VFT	2500	SF	Room 300, 302		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
, v
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
202	12" X 12" Light brown w/Speckles VFT Mastic	2500	SF	Room 300, 302		Miscellaneous	No	Dist	20		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:
·

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
203	12" X 12" White w/dotts VFT	3000	SF	Ramps, inclines in corridors		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
204	12" X 12" White w/dotts VFT Mastic	3000	SF	Ramps, inclines in corridors		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:
·

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
205	12" X 12" Beige w/Brown Streak VFT	75000	SF	Corridors, Office		Miscellaneous	No	None	0		YES X NO
2016 - Fall: N	lo Change										

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	
2018 - Fall: No Change	
Comments:	
	· ·

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
206	12" X 12" Beige w/Brown Streak VFT Mastic	75000	SF	Corridors, Office		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:
·

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
207	12" X 12" Blue w/White Speckle VFT	3000	SF	Hallway		Miscellaneous	No	None	0		YES X NO
2016 - Fall: N	lo Change										

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2040 0 : N 0
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
208	12" X 12" Blue w/White Speckle VFT Mastic	3000	SF	Hallway		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:
·

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
209	12" X 12" Dark Brown VFT	3000	SF	Hallway		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N Comments:	o Change											

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
210	12" X 12" Dark Brown VFT Mastic	3000	SF	Hallway		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:
·

Page 75

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
211	12" X 12" Mustard VFT	3000	SF	Hallway		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: I	No Change											
Comments:												
2017 - Fall: I	No Change											
Comments:												
2017 - Sprin	g: No Change											
Comments:												
2018 - Sprin	g : No Change											
Comments:	-											
2018 - Fall: I	No Change											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
212	12" X 12" Mustard VFT Mastic	3000	SF	Hallway		Miscellaneous	No	None			YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
213	12" X 12" Dark Green VFT	3000	SF	Hallway		Miscellaneous	No	None	0		YES X NO
2016 - Fall: No Change											

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
214	12" X 12" Dark Green VFT Mastic	3000	SF	Hallway		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Quantity	Units	Material Location	Type	Category	Friable	Type	Quantity	Units	Change in Asses	ssment Category
215	12" X 12" Red VFT	3000	SF	Hallway		Miscellaneous	No	None	0		YES	X NO
2016 - Fall	: No Change	·						•	•			
Comments	S:				_							
•	ing: No Change											
Comments	S:				_							
2017 - Fall	· No Change											

2017 - Fall: No Change Comments:

2018 - Spring : No Change Comments:

2018 - Fall: No Change

Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
216	12" X 12" Red VFT Mastic	3000	SF	Hallway		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:
·

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
217	12" X 12" Light brown w/Speckles VFT	100000	SF	Rooms 102, 104, 106A, 106B, 107, 105, 103, 108, 110, 112, 113, 111, 109, 136, 317, 138, 120, 122, 124, 125, 131, 133, 130, 128, 126, 136, 137, 138,208, 216, 218c, 222, 223, 225, 226, 227, 228,229, 230, 221, 231, 234, 236, 238, 240, 239, 237, 242, 243, 248		Miscellaneous	No	None	0		YES X NO

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
218	12" X 12" Light Brown w/Specles VFT Mastic	100000	SF	Rooms 102, 104, 106A, 106B, 107, 105, 103, 108, 110, 112, 113, 111, 109, 136, 317, 138, 120, 122, 124, 125, 131, 133, 130, 128, 126, 136, 137, 138, 200-215 A+B, 216, 218c, 221-229, 230, 231, 234, 236, 238, 240, 239, 237, 242, 243, 246-249		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
219	12" X 12" Turquoise Strips VFT	20	SF	Room 100B		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
220	12" X 12" Turquoise Strips VFT Mastic	20	SF	Room 100B		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:
·

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
221	12" X 12" Green Strips VFT	20	SF	Room 127, 129, Lunch Room, 233		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
, v
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
222	12" X 12" Green Strips VFT Mastic	20	SF	Room 127, 129, Lunchroom, 233		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category
223	White Linoleum	1400	SF	Room 233, 235		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N Comments:	o Change											

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
224	White Linoleum Adhesive	1400	SF	Room 233, 235		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:
·

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
225	Lab Counter Top	20	SF	Room 233, 235, 237		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N Comments:	o Change											

2016 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
226	Brown Carpet	250	SF	Room 244 (Exercise Room)		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
227	Brown Carpet Adhesive	20	SF	Room 244 (Exercise Room)		Miscellaneous	No	None	0		YES X NO
2016 - Fall: N	o Change										

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	
228	Climbing Wall	300	SF	Room 221		Miscellaneous	No	None	0		YES X NO	

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:
·

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
229	Elevator Brake Shoe	210	SF	Elevators		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: No Change Comments:												

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
0040 0 0 d o No Olovo
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
230	White Sink under coating	13	SF	Rooms 200, 202, 220, 204, 206, 203, 201, 204,211, 215, 212, 210		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
231	2 X 4 Pinhole Ceiling Tile	2500	SF	Lunchroom and Kitchen		Miscellaneous	Yes	None	0		YES	X NO
2016 - Fall:	: No Change]							
Comments	:											
2017 - Spri	ing: No Change				-							
Comments	:											
2017 - Fall:	: No Change				-							
Comments	:											
2018 - Spri	ing : No Change				-							
Comments	:											
2018 - Fall:	2018 - Fall: No Change											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	
232	2 X 4 Pin and Furrow Tile	1600	SF	127, 129		Miscellaneous	Yes	None	0		YES X NO	

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

Comments:

Page 87

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
233	Brown Multi-colored Carpet Adhesive	3700	SF	Auditorium		Miscellaneous	No	None	0		YES X NO
2016 - Fall: No Change Comments:											

2016 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
234	12" x 12" Ceiling Tile	1500	SF	1st Floor Library Loading Dock		Miscellaneous	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

ALL LEA Responsibilities, for this school, will be met.

Robert Christlieb

NOTICE TO PARENTS AND STAFF REGARDING THE ASBESTOS MANAGEMENT PLAN NOTIFICATION

School: Hope Institute Learning Academy
Date:1/11/2019
This is to notify you in accordance with Illinois and Federal Asbestos Regulations, that a copy of the Asbestos Management Plan is available at each school during school hours by appointment. Requests to review the Asbestos Management Plan must be made at least 24 hours in advance.
Also please be advised that CPS conducts asbestos inspections of all Schools every three years. The last inspection was completed in 2016. Asbestos surveillances are conducted every six months.
CHECK ONE
A copy of this notice was sent home in each child's backpack.
A copy of this notice was printed in the school's newsletter and sent home with each child
A copy of this notice was printed in the school's calendar and sent home with each child
Other.
A COPY OF THIS NOTICE MUST BE PLACED IN THE

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

SCHOOL'S ASBESTOS MANAGEMENT PLAN.

Oracle Unit: 63031