Chicago Public Schools

6 Month Asbestos Surveillance 2018 - Fall

YCCS-Austin Career Education Center HS Building ID: 1121Q 66611 School: **Oracle Unit:** Address: 5352 W. Chicago Ave. Region: Mail Room: Asbestos Surveyor: ABALLARD1 X CHECK HERE IF NO CHANGE TO ASBESTOS Survey Date: 12/21/2018 Email Address: A copy of the 2016/2017 notice to parents and staff regarding the asbestos management plan notifications was distributed via: Notice printed in school's newsletter X Other Letter Mailed Each child's backpack Notice printed in school's calendar HA No Material Description Material Location Asbestos Friable Damage Damage Change in Assessment Category Material Material Damage Quantity Units Type Category Quantity Type Throughout the Building-YES X NO 01 SF Drywall 27000 1st/2nd Partition Miscellaneous No None 0 Walls/2nd Floors Ceiling 2016 - Fall: No Change Comments: 2017 - Spring: No Change Comments: 2017 - Fall: No Change Comments: 2018 - Spring: No Change Comments: 2018 - Fall: No Change Comments:

Oracle Unit: 66611

	HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
	02	Joint Compound associated with Drywall	27000	SF	Throughout the Building- 1st/2nd Partition Walls/2nd Floors Ceiling		Miscellaneous	No	None	0		YES	X NO
Ī	2016 - Fall: N	o Change											

2016 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
03	2'x 4' Accoustical Drop-In Ceiling Tiles	11000	SF	Throughout the First Floor		Miscellaneous	Yes	None	200		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in As	sessment Category
04	Terrazzo	2000	SF	1st Floor-Men's/Women/s Restroom, SW Classroom, Computer Lab, Areas of Hallway		Miscellaneous	No	None	0		YES	X NO
2016 - Fall	No Change]							
Comments	•											
2017 - Spri	ng: No Change											
Comments	:											
2017 - Fall:	No Change				-							
Comments	:											
2018 - Spri	ng : No Change				-							
Comments	:											
2018 - Fall:	No Change											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
05	1.5'x 1.5' Tan Faux Marble VFT	2860	SF	1st Floor-Teacher's Lounge and Auditorium & Attendance Office		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change Comments:
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment (Category
06	Mastic associated with 1.5'x 1.5' Tan VFT(HA #05)	2860	SF	1st Floor-Teacher's Lounge and Auditorium & Attendance Office		Miscellaneous	No	None	0		YES X	NO
2016 - Fall: No Change Comments:												

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
07	Carpet Glue	5800	SF	North/South Hallway, Counsellors Office, East/West Hallway		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change		
Comments:		
2017 - Spring: No Change		
Comments:		
2017 - Fall: No Change		
Comments:		
2018 - Spring : No Change		
Comments:		
2018 - Fall: No Change		
Comments:		
	•	

		Quantity	Units		Type	Category		Type	Quantity	Units		
08	4" Black Baseboard	250	LF	Classrooms 1-6, Classroom 8, Men's & Women's Washrooms and Computer Lab		Miscellaneous	No	None	0		YES	X NO
2016 - Fall	: No Change				7							
Comments	:											
	ing: No Change											
Comments	:				4							
	: No Change											
Comments	:				4							
	ing : No Change											
Comments	:				-							

Material

Damage

Friable

Damage

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
09	Adhesive Associate w/ 4" Black Baseboard (HA #8)	250	LF	Classrooms 1-6, Classroom 8, Men's & Women's Washrooms and Computer Lab		Miscellaneous	No	None	0		YES X NO

			and Compator Lab	
2016 - Fall: N	o Change			
Comments:				
2017 - Spring	: No Change			
Comments:				
2017 - Fall: N	o Change			
Comments:				
2018 - Spring	: No Change			
Comments:				
2018 - Fall: N	o Change			
Comments:				
•		•		

HA No

2018 - Fall: No Change

Comments:

Material Description

Material

Material Material Location

VFT = Vinyl Floor Tile Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure. Damage Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
10	4" Blue Baseboard	100	LF	Dean's Office, Councellor's Office, Registar's Office, Director's Office and Small Office in Director's Office		Miscellaneous	No	None	0		YES X NO

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
11	Adhesive Associated w/4" Blue Baseboard (HA 10)	100	LF	Dean's Office, Councellor's Office, Registar's Office, Director's Office and Small Office in Director's Office		Miscellaneous	No	None	0		YES X NO
2016 - Fall	I: No Change]						

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

Oracle Unit: 66611

12	4" Tan Baseboard	420	LF	Auditorium, Offices in Auditorium, and Staff Lounge		Miscellaneous	No	None	0	YES	X NO
					7						
2016 - Fall: I	No Change										
Comments:											
2017 - Sprin	g: No Change										
Comments:											
2017 - Fall: N	No Change										
Comments:	-										
2018 - Sprin	g : No Change										
Comments:											
2018 - Fall: I	No Change										
Comments:											

Type

Material

Category

Damage Type

Friable

Damage Quantity Damage

Units

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
13	Adhesive Associated w/4" Tan Baseboard (HA 12)	420	LF	Auditorium, Offices in Auditorium, and Staff Lounge		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No

Material Description

Material

Quantity

Material

Units

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
14	4" Tan Baseboard	600	LF	Corridors, Classroom 7 and Water Heater Room		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	No Change]							
Comments:												
2017 - Spring	g: No Change				-							
Comments:												
2017 - Fall: N	No Change											
Comments:					1							
2018 - Spring	g : No Change											
Comments:												
2018 - Fall: N	No Change											
Comments:	<u> </u>											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
15	Adhesive Associated w/4" Tan Baseboard (HA 14)	600	LF	Corridors, Classroom 7 and Water Heater Room		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:
· · · · · · · · · · · · · · · · · · ·

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
16	12"x 12" Gray Floor Tile	420	SF	1st Floor-North (Back) Hallway		Miscellaneous	No	Dist	10		YES X NO
2016 - Fall: No Change Comments:											

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
17	Mastic associated w/12"x12" Gray VFT (HA 16)	420	SF	1st Floor-North (Back) Hallway		Miscellaneous	No	Dist	10		YES X NO

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
18	Green Linoleum	80	SF	1st Floor Under Southwest Stairwell		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: No Change Comments:												

2018 - Fall: No Change Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
19	Mastic Associated w/Green Linoleum	80	SF	1st Floor-Under Southwest Stairwell		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
20	9"x9" Maroon Floor Tile	340	SF	Under Stairway in Counsellor's Office and Second Floor Northwest Storage		Miscellaneous	No	None	0		YES X NO
2016 - Fall: No Change Comments:]						

2016 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	
2040 Fall Na Obanas	
2018 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
21	Mastic Associated w/9"x9" Maroon VFT(HA 20)	340	SF	Under Stairway in Counsellor's Office and Second Floor Northwest Storage		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

		Quantity	Units		Type	Category		Туре	Quantity	Units	3	,
22	Gray Sheet Flooring	700	SF	2nd Floor-North and South Storage Areas		Miscellaneous	No	Dist	100		YES	X NO
2016 - Fall: No	o Change				7							
Comments:	<u> </u>											
2017 - Spring:	: No Change											
Comments:												
2017 - Fall: No	o Change											
Comments:												
2018 - Spring	: No Change											
Comments:												
2018 - Fall: No	o Change											
Comments:												
					_							

Material

Friable

Damage

Damage

Damage

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
23	Mastic Associated w/Gray Sheet Flooring (HA 22)	700	SF	2nd Floor North and South Storage		Miscellaneous	No	None	0		YES X NO
					1						

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No

Material Description

Material

Material

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
24	9"x9" Blue/Brown/Tan VFT	450	SF	2nd Floor-East Storage		Miscellaneous	No	None	0		YES	X NO
2016 - Fal	II: No Change]							
Comments												
2017 - Spi	ring: No Change											
Comments	S:											
2017 - Fal	II: No Change				=							
Comments	S:											
2018 - Spi	ring : No Change				=							
Comments	s:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
24A	9 x 9 VFT Blue w/ white streaks	150	SF	2nd Floor Storage Rooms		Miscellaneous	No	Dist	5		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

2018 - Fall: No Change

Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category
24B	9 x 9 VFT Brown w/ Tan Streaks	150	SF	2nd Floor Storage Rooms		Miscellaneous	No	Dist	5		YES	X NO
2016 - Fall: N Comments:	o Change											

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	
2018 - Fall: No Change	
Comments:	·

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
24C	9 x 9 VFT Gray w/ Black & White Streaks	150	SF	2nd Floor Storage Rooms		Miscellaneous	No	Dist	5		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
25	Mastic Associated with Blue/Brown/Tan VFT (HA 24)	450	SF	2nd Floor-East Storage		Miscellaneous	No	None	0		YES X NO
2016 - Fall: N	No Change			· -]	•					•

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 0 : 11 01
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
25A	9 x 9 Mastic Blue w/ White Streaks	150	SF	2nd Floor Storage Rooms		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
25B	9 x 9 Mastic Brown w/ Tan Streaks	150	SF	2nd Floor Storage Rooms		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: No Change												
Comments:	Comments:											
2017 - Fall:	No Change											
Comments:	Comments:											
2017 - Spring: No Change												
Comments:												

					ı						
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
250	9 x 9 Mastic Gray w/ Black	150	QE.	2nd Floor Storage Booms		Missollanagus	No	None	0		

Miscellaneous

No

None

0

2nd Floor Storage Rooms

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

150

SF

2018 - Spring : No Change

& White Streaks

2018 - Fall: No Change

Comments:

Comments:

25C

X NO

YES

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
26	12"x 12" White Circle Patterned VFT	100	SF	2nd Floor Restroom-NE		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N Comments:	2016 - Fall: No Change											

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
27	Mastic Associated w/12"x12" White VFT (HA 26)	100	SF	2nd Floor Bathroom-NE		Miscellaneous	No	None	0		YES X NO

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
28	12 x 12 Orangy Brown Ceramic Tile Grout	1500	SF	1st Floor NE Classroom and 1st Floor Corridor		Miscellaneous	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
29	12 x 12 Orangy Brown Ceramic Tile Adhesive	1500	SF	1st Floor NE Classroom and 1st Floor Corridor		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
30	Terrazzo	1800	SF	Corridors (Beneath Carpeting), Computer Lab, Classroom 8, Men's and Women's Washrooms, Water Heater Room, Landing leading to Second Floor, Computer Lab and possibly beneath the carpeting in the remainder of the school		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in As	sessment Category
31	Science Countertop	18	SF	Classroom 8		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	No Change]							
Comments:	-											
2017 - Spring	g: No Change				1							
Comments:												
2017 - Fall: N	No Change				1							
Comments:	Ŭ											
2018 - Spring	g : No Change				_							
Comments:	g · · · · · · · · · · · · · · · · · · ·											
2018 - Fall: N	No Change											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
32	Laminated Hardwood Floor	1800	SF	Rooms 1, 2, 3, 4, 5, 6		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
33	Blue Carpet Mastic	1100	SF	Dean's Office, Counsellor's Office, Registar's Office, Director's Office, and small office in Director's Office		Miscellaneous	No	None	0		YES X NO
2016 - Fall: Comments	: No Change s:]						

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

Oracle Unit: 66611

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	essment Category
34	Red and Black, Grey, Black, Red and Cream Carpet Mastic	1000	SF	Stairwells, 2nd Floor Storage Areas		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	No Change	•		•]							

2016 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
35	9 X 9 VFT Brown w/ Orange & White Streaks	550	SF	1st Floor- Special Ed Office-Both Closets & Back Hallway under #16 & #17; 2nd Floor Storage- East & West		Miscellaneous	No	Dist	10		YES X NO

		- 10 1 1 g - 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
2016 - Fall: No Change		
Comments:		
2017 - Spring: No Change		
Comments:		
2017 - Fall: No Change		
Comments:		
2018 - Spring : No Change		
Comments:		
2018 - Fall: No Change		
Comments:		

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
36	9 x 9 Mastic Brown w/ Orange & White Streaks	550	SF	1st Floor- Special Ed Office-Both Closets & Back Hallway under #16 & #17; 2nd Floor Storage- East & West		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
37	9 x 9 Green w/ Gray Streaks -VFT	200	SF	2nd Floor Storage Room Center		Miscellaneous	No	None	0		YES X NO
2016 - Fall: N	o Change										

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2040 0 : N 0
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
38	9 x 9 Green with Gray Streaks Mastic	200	SF	2nd Floor Storage Room Center		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:
·

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
39	9 x 9 Yellow w/ Green Streaks VFT	150	SF	2nd Floor Storage Center		Miscellaneous	No	None	0		YES	X NO
2016 - Fal	II: No Change]							
Comments	s:											
2017 - Spi	ring: No Change											
Comments	S:				 							
2017 - Fal	II: No Change											
Comments	S:				<u> </u>							
2018 - Spi	ring : No Change											
Comments	s:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
40	9 x 9 Yellow w/ Green Streaks Mastic	150	SF	2nd Floor Storage Center		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

2018 - Fall: No Change

Comments:

HA No	Material Description	Quantity	Units	Material Location	Type	Category	Friable	Type	Quantity	Units	Change in Asses	ssment Category
41	9 x 9 Dark Blue w/ Black & Gray Streaks VFT	50	SF	2nd Floor Storage Room		Miscellaneous	No	None	0		YES	X NO
2016 - Fall	l: No Change											
Comments	3:											
2017 - Spr	ing: No Change											
Comments	S:											
2017 - Fall	l: No Change											
Comments:					=							

2018 - Spring : No Change Comments:

2018 - Fall: No Change

Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
42	9 x 9 Dark Blue with Black & Gray Streaks Mastic	50	SF	2nd Floor Storage Room		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

Page 27

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
43	Adhesive Behind Whiteboards	1000	SF	Classrooms		Miscellaneous	No	None			YES	X NO
2016 - Fall: I	No Change											
Comments:	<u> </u>											
2017 - Sprin	g: No Change											
Comments:												
2017 - Fall: I	No Change											
Comments:												
2018 - Sprin	g : No Change											
Comments:												
2018 - Fall: I	No Change											
Comments:												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
44	Red Sheet Flooring	100	SF	Middle Section of Second Floor Beneath Carpet		Miscellaneous	No	None			YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

Page 28

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	essment Category
45	Red Sheet Flooring Adhesive	100	SF	Middle Section of Second Floor Beneath Carpet		Miscellaneous	No	None			YES	X NO
2016 - Fall: N	No Change]							
Comments:												
2017 - Spring	g: No Change				=							
Comments:												
2017 - Fall: N	No Change				=							
Comments:												
2018 - Spring	g : No Change				=							
Comments:												
2018 - Fall: N	No Change											
Comments:	<u> </u>				=							
					J							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
46	Sink Undercoat	8	SF	Staff Lounge		Miscellaneous	No	None			YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:
· · · · · · · · · · · · · · · · · · ·

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
47	Paneling Adhesive	1800	SF	Throughout First Floor with the Exception of the Washrooms, Water Heater Room and Staff Lounge		Miscellaneous	No	None			YES X NO

		Louingo
2016 - Fall: No Change		
Comments:		
2017 - Spring: No Change		
Comments:		
2017 - Fall: No Change		
Comments:		
2018 - Spring : No Change		
Comments:		
2018 - Fall: No Change		
Comments:		

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
48	Green Patterned Carpet Adhesive	3000	SF	Middle and Northeast Section of Second Floor		Miscellaneous	No	None			YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

49	Floor Tile (Beneath Carpeting)	100	SF	Middlewest Section of Second Floor		Miscellaneous	No	None			YES	X NO
2016 - Fall	l: No Change				7							
Comments	•											
2017 - Spr	ing: No Change				1							
Comments	S:											
2017 - Fall	l: No Change				1							
Comments	3:											
2018 - Spr	ing : No Change				=							
Comments	S:											
2018 - Fall	l: No Change											
Comments	S:											
					_1							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
50	Floor Tile Mastic Asssoc.	100	SF	Middle West Section of		Miscellaneous	No	None			YES	X NO

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

Material Location

Second Floor

HA No

Material Description

Floor Tile (Beneath

with HA 50

Material

Quantity

Material

Units

Page 31

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
51	Roofing Material	13700	SF	Roof		Miscellaneous	No	None			YES	X NO
2016 - Fall: Comments:	No Change											
	g: No Change											
Comments:	g. 140 Change											
2017 - Fall: I	No Change											
Comments:												
2018 - Sprin	g : No Change											
Comments:												
2018 - Fall: I	No Change											
Comments:												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
52	Tan Ceramic Wall Tile Grout	750	SF	Men's and Women's Washrooms		Miscellaneous	No	None			YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
53	Tan Ceramic Wall Tile Adhesive	750	SF	Men's & Women's Washrooms		Miscellaneous	No	None			YES	X NO
2016 - Fall: N	lo Change]							
Comments:	J				1							
2017 - Spring	g: No Change				-							
Comments:	, <u> </u>				1							
2017 - Fall: N	lo Change				-							
Comments:	<u> </u>				1							
2018 - Spring	g : No Change				-							
Comments:	,				1							
2018 - Fall: N	lo Change				-							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
54	Green Ceramic Wall Tile Grout	300	SF	Staff Lounge		Miscellaneous	No	None			YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asso	essment Category
55	Green Ceramic Wall Tile Adhesive	300	SF	Staff Lounge		Miscellaneous	No	None			YES	X NO
2016 - Fall: Comments:	No Change		•]					•		
Comments.												
2017 - Sprin	g: No Change											
Comments:												
2017 - Fall:	No Change											
Comments:												
2018 - Sprin	g : No Change											
Comments:	<u> </u>											
2018 - Fall:	No Change											
Comments:												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
56	4" Brown Baseboard	120	LF	Warrier Lounge		Miscellaneous	No	None			YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:
· · · · · · · · · · · · · · · · · · ·

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
57	4" Brown Baseboard Adhesive	120	SF	Warrier Lounge		Miscellaneous		None			YES	X NO
2016 - Fall:	No Change											
Comments:												
2017 - Sprin	g: No Change											
Comments:												
2017 - Fall:	No Change											
Comments:												
2018 - Sprin	g : No Change											
Comments:												
2018 - Fall:	No Change											
Comments:												
II .					1							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
58	Striped Sheet Flooring	200	SF	East Side of Second Floor South Room		Miscellaneous	No	None			YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
59	Striped Sheet Flooring Adhesive	200	SF	East Side of Second Floor South Room		Miscellaneous	No	None			YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

Oracle Unit: 66611

ALL LEA Responsibilities, for this school, will be met.

Robert Christlieb

NOTICE TO PARENTS AND STAFF REGARDING THE ASBESTOS MANAGEMENT PLAN NOTIFICATION

School: Y	CCS-Austin Career Education Center HS
Date: 1	2/21/2018
the Asbestos	ify you in accordance with Illinois and Federal Asbestos Regulations, that a copy of Management Plan is available at each school during school hours by appointment. review the Asbestos Management Plan must be made at least 24 hours in advance.
The last insp	be advised that CPS conducts asbestos inspections of all Schools every three years. ection was completed in 2016. rveillances are conducted every six months.
CHECK ONE	
A cop	y of this notice was sent home in each child's backpack.
A cop	y of this notice was printed in the school's newsletter and sent home with each child
A cop	y of this notice was printed in the school's calendar and sent home with each child
X Other.	. Letter Mailed
A COPY (OF THIS NOTICE MUST BE PLACED IN THE

VFT = Vinyl Floor Tile
Oracle Unit: 66611

SCHOOL'S ASBESTOS MANAGEMENT PLAN.