Chicago Public Schools

6 Month Asbestos Surveillance 2015 - Fall

Perkins Bass School 22161 2180 School: **Oracle Unit: Building ID:** Address: 1140 W. 66th Region: 05 Mail Room: Asbestos Surveyor: Dixon, Mr. Charles Wayne **CHECK HERE IF NO CHANGE TO ASBESTOS** 9/29/2015 Survey Date: Email Address: cwdixon@cps.edu A copy of the 2013/2014 notice to parents and staff regarding the asbestos management plan notifications was distributed via: X Notice printed in school's newsletter Notice printed in school's calendar Other Each child's backpack HA No Asbestos Material Description Material Material Material Location Material Friable Damage Damage Damage Change in Assessment Category Category Quantity Units Type Type Quantity Units YES X NO 01 hard coat plaster 75000 SF throughout 1894 building Surface Yes None 0 2013 - Fall: No Change Comments: 2014- Spring: No Change Comments: 2014 - Fall: No Change Comments: 2015- Spring: No Change Comments: 2015 - Fall: No Change Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	essment Category
02	12x12 beige floor tile	6500	SF	1894 - rm 08, 07, 01 & bsmnt crrdr & playrms, rm 106, 103, 104, 107 & 108 & 1st fir storage & wardrobes, rooms 303-307, counselor's office, and principals office closet		Miscellaneous	No	None	0		YES	X NO

2013 - Fall: No Change	
Comments:	

2014 - Fall: Damaged
Comments:Damaged 8/2013

2014- Spring: No Change	
Comments:	

2	2015 - Fall: No Change
C	Comments:

2015- Spring: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
2	12x12 beige floor tile	0	SF	Various Rooms		Miscellaneous	No	None	0		YES	X NO
2013 - Fall: N	No Change				٦							
Comments:	J											
2014 - Fall: N	No Change]							
Comments:												
2014- Spring	ı: No Change											
Comments:												
2015- Spring	ı: No Change											
Comments:	, ,											
2015 - Fall: N	No Change				٦							
Comments:												
					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
03	9x9 black with white streaks floor tile	200	SF	1894 bldg - engineer's office		Miscellaneous	No	None	0		YES	X NO
2013 - Fall: N	No Change			<u> </u>	7							
					-							

2013 - Fall: No Change	
Comments:	

2014 - Fall: Other

Comments:Covered over with 12 X 12 Per AFM Aproval.

2014- Spring: No Change Comments:

2015- Spring: No Change Comments:

2015 - Fall: No Change Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	essment Category
04	hardcoat plaster	10400	SF	1939 building- basement assembly hall & platform		Surface	No	None	0		YES	X NO
2013 - Fall: N	No Change]							
Comments:												
2014 - Fall: N	No Change]							
Comments:												
2014- Spring	: No Change											
Comments:												
2015- Spring	: No Change											
Comments:	•											
2015 - Fall: N	No Change				1							
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	essment Category
07	9x9 floor tile	3000	SF	1960 bldg- 1st & 2nd floor west corridor		Miscellaneous	No	None	0		YES	X NO
2013 - Fall: N	No Change				7							
Comments:	Ŭ											
2014- Spring	: No Change				7							
Comments:	•											
2014 - Fall: F	Repaired				1							
Comments:Area by 111 & Teachers washroom.]							
2015- Spring: No Change				1								

Comments:

Comments:

2015 - Fall: No Change

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in As	sessment Category
09	12x12 floor tile mastic	5600	SF	1894 - rm 08,07,01 & bsmnt crrdr & playrms, rm 106,103, 104 & 1st flr strge & wardrobes, rm 303-307		Miscellaneous	No	None	0		X YES	NO
2013 - Fall:	: Damaged]							

Comments:Room 001 will be Repaired/Abated during the Christmas Break By Public Building Commission.

2014- Spring: No Change	
Comments:	

2014 - Fall: No Change	
Comments:	

2015- Spring: No Change	
Comments:	

2	2015 - Fall: No Change
(Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	
10	9x9 floor tile mastic	200	SF	1894 bldg - engineer's office & toilet		Miscellaneous	No	None	0		YES	X NO

2013 - Fall: No Change	
Comments:	

2014 - Fall: Other

Comments:Covered over with 12 X 12 per AFM approval.

2014- Spring: No Change	
Comments:	

2015 - Fall: Other
Comments: Tile covered over with 12 X 12 blue tile 2013.

2015- Spring: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in As	sessment Category
11	9x9 floor tile mastic	3000	SF	1960 bldg- 1st & 2nd floor west corridor		Miscellaneous	No	None	0		YES	X NO
2013 - Fal	l: No Change											
Comments												
2014- Spri	ng: No Change]							
	l: No Change]							
Comments	S:											
2015- Spri	ng: No Change											
Comments	S:											
2015 - Fal	l: No Change]							
Comments												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in As	sessment Category
BB-1	baseboard	900	LF	1st, 2nd, 3rd floor corridors - 1894 building		Miscellaneous					X YES	NO
2013 - Fal	l: Repaired											

Comments:Baseboard Replaced this summer.

2014- Spring: No Change

Comments:

2014 - Fall: No Change

Comments:

2015- Spring: No Change

Comments:

2015 - Fall: No Change

Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Catego	
BBM-1	baseboard mastic	900	LF	1st, 2nd, 3rd floor corridors - 1894 building		Miscellaneous					X YES	NO
2013 - Fall: Repaired												
Comments:Baseboard Replaced this summer.					1							

2014 - Fall: No Change Comments:

2014- Spring: No Change Comments:

2015- Spring: No Change Comments:

2015 - Fall: No Change Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessi	ment Category
CM-1	blue carpet mastic	1750	SF	Room 303, 305, Art Room		Miscellaneous	No	None	0		X YES	NO

2013 - Fall: Abated

Comments:Carpet Removed by Public Building commison and replaced with vinyl tile.

2014 - Fall: Other Comments:Removed 8/2013

2014- Spring: Abated Comments:Replaced by PBC 8/2013

2015- Spring: No Change Comments:

2015 - Fall: No Change Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
CM-2	light blue carpet mastic	180	SF	assistant principal's office		Miscellaneous	No	None	0		YES	X NO
2013 - Fall	: No Change]							
Comments	:											
	ng: No Change]							
Comments	:											
2014 - Fall	: No Change]							
Comments												
2015- Spri	ng: No Change]							
Comments]							
2015 - Fall	: No Change]							
Comments												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asso	essment Category
CT1	2 X 4 Ceiling Tile	800	SF	Kitchen		Miscellaneous	No	None	0		YES	X NO
2013 - Fall	: No Change]							
Comments	· ·											
2014- Spri	ng: No Change				1							
Comments												
2014 - Fall	: No Change]							
Comments												
2015 - Fall	: No Change				1							
Comments												
2015- Spri	ng: No Change				- 1							
Comments												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	essment Category
CT2	2 X 4 Ceiling Tile	2730	SF	Room 303, 305, Art Room, Principal Office, Lunchroom		Miscellaneous	No	None	0		YES	X NO
2013 - Fall:	No Change											
Comments:												
2014- Sprin	g: No Change											
Comments:												
2014 - Fall:	No Change											
Comments:	Ţ.											
2015- Sprin	g: No Change											
Comments:												
2015 - Fall:	No Change											
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	essment Category
FT-1	9x9 tan floor tile	100	SF	basement bathroom, engineer's toilet		Miscellaneous	No	None	0		YES	X NO
2013 - Fall:	No Change											
Comments:												
2014- Sprin	g: No Change											
Comments:												
2014 - Fall:	No Change											
Comments:												
2015- Sprin	g: No Change											
Comments:												
2015 - Fall:	No Change											
Comments:					7							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	sessment Category
FT-10	12x12 blue floor tile	15	SF	Faculty room		Miscellaneous	No	None	0		YES	X NO
	No Change											
Comments:												
2014- Sprin	g: No Change											
	No Change											
Comments:												
2015- Sprin	g: No Change											
Comments:												
2015 Fall:	No Change											
Comments:												
Commonic												
							•					
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	sessment Category
FT-11	12x12 brown floor tile	75	SF	Principal rest room, storage closet, main office safe		Miscellaneous	No	None	0		YES	X NO
2013 - Fall·	No Change											
Comments:												
	No Change											
Comments:												
2014- Sprin	g: No Change											
Comments:												
2015- Sprin	ıg: No Change											
Comments:												
					<u></u> '							
	No Change											
Comments:												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
FT-12	12x12 brown floor tile mastic	75	SF	Principal rest room, storage closet, main office safe		Miscellaneous	No	None	0		YES	X NO
2013 - Fall:	No Change			·	j							
Comments:	_											
2014- Spring	g: No Change				7							
Comments:												
2014 - Fall:	No Change											
Comments:												
2015- Spring	g: No Change				7							
Comments:	<u>g </u>											
2015 - Fall:	No Change				٦							
Comments:	140 Change											
					<u></u>							
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Asse	essment Category
1,,,,,,	Material Becompiler	Quantity	Units	Material Location	Туре	Category	Triable	Туре	Quantity	Units	Onango in 71000	ociment category
FT-2	12x12 light brown w/white specks floor tile	600	SF	stair case landing-1894		Miscellaneous	No	None			YES	X NO
2013 - Fall:	No Change				7							
Comments:												
2014- Spring	g: No Change											
Comments:												
2014 - Fall	No Change				٦							
2014 - Fall: Comments:	110 Onango											
2015- Spring	g: No Change				_ 7							
Comments:	g. No Change											
	No Chango				_ 							
2015 - Fall: Comments:	ino change				+							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asso	essment Category
FT-3	12x12 brown w/white flecks floor tile	750	SF	room 302 and Wardrobes		Miscellaneous	No	None	0		YES	X NO
2013 - Fall	: No Change]							
Comments	:											
2014- Spri	ng: No Change]							
Comments	:]							
2014 - Fall	: No Change]							
Comments]							
2015- Spri	ng: No Change]							
Comments]							
2015 - Fall	: No Change]							
Comments												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	essment Category
FT-4	12x12 white w/thin flecks floor tile	750	SF	room 308		Miscellaneous	No	None	0		YES	X NO
2013 - Fall	: No Change]							
Comments												
2014- Spri	ng: No Change				1							
Comments					-							
2014 Fall	: No Change				<u>.</u> 1							
Comments					-							
2045 Cmri	an Na Changa				<u>.</u> 1							
Comments	ng: No Change ::				<u> </u>							
					J 1							
2015 - Fall Comments	: No Change ·				-							
Comments	·•				1							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
FT-5	linoleum	2400	SF	room 109, 113		Miscellaneous	No	None	0		YES	X NO
2013 - Fall: N	No Change											
Comments:	•											
2014 - Fall: N	No Change											
Comments:	J											
2014- Spring	: No Change											
Comments:												
2015- Spring	: No Change											
Comments:												
2015 - Fall: N	No Change											
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
FT-6	9x9 dark tan w/brown streaks floor tile	6700	SF	room 115, 213, 214, 216, 208, 210,209,217,2nd floor faculty room		Miscellaneous	No	None	0		YES	X NO
2013 - Fall: N	No Change											
Comments:												

2014- Spring: No Change

2014 - Fall: No Change

2015- Spring: No Change

Comments:

Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	essment Category
FT-7	12x12 off white w/brown & gray flecks floor tile	750	SF	room 211		Miscellaneous	No	None			YES	X NO
2013 - Fall	: No Change											
Comments	:											
2014- Spri	ng: No Change				1							
Comments												
2014 - Fall	: No Change				7							
Comments												
2015- Spri	ng: No Change				- 1							
Comments												
					- 1							
2015 - Fall Comments	:Room 211 replaced witl	n carpet in	the sumr	ner of 2013 by PBC.								
		. сапрот			<u> </u>							
HA No	Material Description	Motorial	Motorial	Motorial Location	Ashastas	Motorial	Frieble	Damaga	Domoso	Domoso	Change in Ass	acament Catagoni
HA NO	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	essment Category
FT-8	12x12 brown w/white specks floor tile	300	SF	hall between 1939, 1960		Miscellaneous	No	None	0		YES	X NO
2013 - Fall	: No Change				1							
Comments	Ÿ											
2014- Spri	ng: No Change				1							
Comments												
2014 - Fall	: No Change				7							
Comments												
2015 Spri	ng: No Change				- 1							
Comments					-							
2015 - Fall	: No Change				-]							
Comments												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	sessment Category
FT-9	12x12 blue floor tile	2400	SF	auditorium		Miscellaneous	No	None	0		YES	X NO
2013 - Fall	: No Change											
Comments);											
2014- Spri	ng: No Change											
Comments												
2014 - Fall	: No Change											
Comments): :											
2015- Spri	ng: No Change											
Comments	· ·											
2015 - Fall	: No Change											
Comments												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	sessment Category
FTM-1	mastic beneath 9x9 tan	100	SF	basement bathroom,		Miscellaneous	No	None	0		VES	X NO

	material 2 coonpact	Quantity	Units		Туре	Category		Type	Quantity	Units	onango m ricoccomom c	alogo.,
FTM-1	mastic beneath 9x9 tan floor tile	100	SF	basement bathroom, engineer's office toilet		Miscellaneous	No	None	0		YES X	10

2013 - Fall: No Change Comments:

2014 - Fall: No Change Comments:

2014- Spring: No Change Comments:

2015- Spring: No Change Comments:

2015 - Fall: Other Comments: Engineers office tile covered over with 12 X 12 blue tile.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	sessment Category
FTM-2	12x12 light brown w/white specks floor tile mastic	600	SF	stair case landing-1894		Miscellaneous	No	None	0		YES	X NO
2013 - Fall:	No Change											
Comments												
	ıg: No Change											
Comments												
	No Change											
Comments												
2015- Sprir	ng: No Change											
Comments												
2015 - Fall:	No Change											
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	sessment Category
FTM-3	12x12 brown w/white flecks floor tile mastic	750	SF	room 302		Miscellaneous	No	None			YES	X NO
2013 - Fall:	No Change											
Comments												
2014- Sprin	ng: No Change				7							
Comments												
2014 - Fall:	No Change				7							
Comments												
2015- Sprir	ıg: No Change				٦							
Comments:												
2015 - Fall·	No Change				7							
Comments:												

FTM-4 to the methin flecks floor tile measter floor tile floor													
## Nor Change Comments: 2014 - Spring: No Change Comments: 2015 - Fall: No Change Comments: 2016 - Fall: No Change Comments: 2017 - Fall: No Change Comments: 2018 - Fall: No Change Comments: 2019 - Fall: No Change Comments: 2019 - Fall: No Change Comments: 2019 - Fall: No Change Comments: 2010 - Fall: No Change Comments: 2011 - Fall: No Change Comments: 2012 - Fall: No Change Comments: 2013 - Fall: No Change Comments: 2014 - Fall: No Change Comments: 2015 - Fall: No Change Comments: 2016 - Fall: No Change Comments: 2017 - Fall: No Change Comments: 2018 - Fall: No Change Comments: 2019 - Fall: No Change Comments:	HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	sessment Category
Comments: 2014 - Spring: No Change Comments: 2015 - Spring: No Change Comments: 2015 - Fall: No Change Comments: 2015 - Fall: No Change Comments: 2016 - Spring: No Change Comments: 2017 - Fall: No Change Comments: 2018 - Fall: No Change Comments: 2019 - Fall: No Change Comments: 2010 - Fall: No Change Comments: 2010 - Fall: No Change Comments: 2011 - Fall: No Change Comments: 2012 - Fall: No Change Comments: 2013 - Fall: No Change Comments: 2014 - Spring: No Change Comments: 2015 - Fall: No Change Comments: 2016 - Fall: No Change Comments: 2017 - Fall: No Change Comments: 2018 - Fall: No Change Comments: 2019 - Fall: No Change Comments: 2010 - Fall: No Change Comments:	FTM-4		750	SF	room 308		Miscellaneous	No	None	0		YES	X NO
2014 - Spring; No Change Comments: 2014 - Fall: No Change Comments: 2015 - Spring: No Change Comments: 2015 - Fall: No Change Comments: 2016 - Spring: No Change Comments: 2017 - Fall: No Change Comments: 2018 - Fall: No Change Comments: 2019 - Fall: No Change Comments: 2010 - Fall: No Change Comments: 2011 - Fall: No Change Comments: 2012 - Fall: No Change Comments: 2013 - Fall: No Change Comments: 2014 - Spring: No Change Comments: 2015 - Spring: No Change Comments: 2015 - Fall: No Change Comments: 2015 - Fall: No Change Comments: 2015 - Fall: No Change Comments:		lo Change											
Comments: 2014 - Fall: No Change Comments: 2015 - Spring: No Change Comments: 2015 - Fall: No Change Comments: HA No Material Description Material Quantity Units Material Location Type Category FTM-5 linoleum mastic 2400 SF room 109, 114, 113 Miscellaneous No None 0 Type X No 2013 - Fall: No Change Comments: 2014 - Fall: No Change Comments: 2015 - Fall: No Change Comments: 2016 - Spring: No Change Comments: 2017 - Fall: No Change Comments: 2018 - Spring: No Change Comments: 2019 - Spring: No Change Comments: 2010 - Fall: No Change Comments: 2011 - Fall: No Change Comments: 2012 - Fall: No Change Comments: 2013 - Fall: No Change Comments: 2014 - Fall: No Change Comments: 2015 - Spring: No Change Comments:	Comments:												
2014 - Fall: No Change Comments: 2015 - Spring: No Change Comments: 2015 - Fall: No Change Comments: HA NO Material Description Material Quantity Units Material Location Units Material Location Type Category Friable Damage Quantity Units Change in Assessment Category FTM-5 linoleum mastic 2400 SF room 109, 114, 113 Miscellaneous No None 0 Tyes X No 2013 - Fall: No Change Comments: 2014 - Spring: No Change Comments: 2014 - Fall: No Change Comments: 2015 - Fall: No Change Comments:	2014- Spring	: No Change											
Comments: 2015 - Spring: No Change Comments: 2015 - Fall: No Change Comments: HA No Material Description Material Oquantity Units Material Location Units Pripe Category Type Category Type Quantity Units Pripe Quantity Units No Change Comments: ETM-5 linoleum mastic 2400 SF room 108, 114, 113 Miscellaneous No None 0 Image Units No Change Comments: 2014 - Fall: No Change Comments: 2014 - Fall: No Change Comments: 2015 - Spring: No Change Comments: 2015 - Spring: No Change Comments: 2015 - Spring: No Change Comments: 2015 - Fall: No Change Comments: 2015 - Fall: No Change Comments:	Comments:												
Comments: 2015 - Spring: No Change Comments: 2015 - Fall: No Change Comments: HA No Material Description Material Oquantity Units Material Location Units Pripe Category Type Category Type Quantity Units Pripe Quantity Units No Change Comments: ETM-5 linoleum mastic 2400 SF room 108, 114, 113 Miscellaneous No None 0 Image Units No Change Comments: 2014 - Fall: No Change Comments: 2014 - Fall: No Change Comments: 2015 - Spring: No Change Comments: 2015 - Spring: No Change Comments: 2015 - Spring: No Change Comments: 2015 - Fall: No Change Comments: 2015 - Fall: No Change Comments:	2014 - Fall: N	lo Change				\neg							
Comments: 2015 - Fall: No Change Comments: HA No Material Description Material Units Material Location Type Miscellaneous No None Damage Quantity Units Type Quantity Units Change Type Quantity Units Change FTM-5 linoleum mastic 2400 SF room 109, 114, 113 Miscellaneous No None 0 Type X X No 2013 - Fall: No Change Comments: 2014 - Spring: No Change Comments: 2015 - Fall: No Change	Comments:												
2015 - Fall: No Change Comments: HA No Material Description Material Material Location Quantity Units Material Location Type Category Friable Damage Damage Quantity Units Change in Assessment Category FTM-5 linoleum mastic 2400 SF room 109, 114, 113 Miscellaneous No None 0 Type X x No 2013 - Fall: No Change Comments: 2014 - Spring: No Change Comments: 2015 - Spring: No Change Comments: 2015 - Fall: No Change Comments: 2015 - Fall: No Change Comments:	2015- Spring	: No Change											
Comments: HA No Material Description Material Quantity Units Material Location Type Category Friable Category Type Quantity Units Damage Type Quantity Units Units No Change Comments: 2400 SF room 109, 114, 113 Miscellaneous No None 0 Type Quantity Units No Change Comments: 2013 - Fall: No Change Comments: 2014 - Fall: No Change Comments: 2015 - Spring: No Change Comments: 2015 - Fall: No Change Comments:	Comments:												
HA No Material Description Material Material Location Type Category Friable Category Type Quantity Units Units Vinits Material Location Type Category Type Category Type Quantity Units Units Vinits V	2015 - Fall: N	lo Change											
Quantity Units Type Category Type Quantity Units	Comments:												
Quantity Units Type Category Type Quantity Units													
2013 - Fall: No Change Comments: 2014- Spring: No Change Comments: 2014 - Fall: No Change Comments: 2015- Spring: No Change Comments: 2015 - Fall: No Change	HA No	Material Description			Material Location			Friable				Change in Ass	sessment Category
Comments: 2014- Spring: No Change Comments: 2014 - Fall: No Change Comments: 2015- Spring: No Change Comments: 2015 - Fall: No Change	FTM-5	linoleum mastic	2400	SF	room 109, 114, 113		Miscellaneous	No	None	0		YES	X NO
2014- Spring: No Change Comments: 2014 - Fall: No Change Comments: 2015- Spring: No Change Comments: 2015 - Fall: No Change	2013 - Fall: N	lo Change											
Comments: 2014 - Fall: No Change Comments: 2015- Spring: No Change Comments: 2015 - Fall: No Change	Comments:												
2014 - Fall: No Change Comments: 2015- Spring: No Change Comments: 2015 - Fall: No Change	2014- Spring	: No Change											
Comments: 2015- Spring: No Change Comments: 2015 - Fall: No Change	Comments:	-											
2015- Spring: No Change Comments: 2015 - Fall: No Change	2014 - Fall: N	lo Change											
Comments: 2015 - Fall: No Change	Comments:	•											
Comments: 2015 - Fall: No Change	2015- Spring	: No Change											
	Comments:	•											
	2015 - Fall: N	lo Change											
	Comments:												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	essment Category
FTM-6	9x9 dark tan w/brown streaks floor tile mastic	6700	SF	room 115, 213, 214, 216, 208, 210,209,217, 2nd floor faculty room		Miscellaneous	No	None	0		YES	X NO
2013 - Fall:	No Change				1							
Comments:												
2014 - Fall:	No Change]							
Comments:	110 Gridings											
2014- Spring	g: No Change]							
Comments:	g. 110 Onango											
2015- Spring	g: No Change]							
Comments:	g. 110 Onango											
2015 - Fall:	No Change]							
Comments:]							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	essment Category
FTM-7	12x12 off wht w/brwn & gray flecks flr tile mastic	750	SF	room 211		Miscellaneous	No	None	0		YES	X NO
2013 - Fall:	No Change]							
Comments:]							
2014 - Fall:	No Change]							
Comments:	3 -]							
2014- Sprine	g: No Change]							
Comments:]							

Comments:Room 211 replaced with carpet the summer of 2013 by PBC.

2015- Spring: No Change

Comments:

2015 - Fall: Other

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in As	sessment Category
FTM-8	12x12 brown w/white specks floor tile mastic	300	SF	hall between 1939, 1960		Miscellaneous	No	None	0		YES	X NO
2013 - Fall: I	No Change]							
Comments:												
2014 - Fall: I	No Change											
Comments:												
2014- Spring	g: No Change				1							
Comments:	g. No Change											
	N. O.				- -							
2015- Spring Comments:	g: No Change											
Comments.												
2015 - Fall: I	No Change											
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in As	sessment Category
FTM-9	12x12 blue floor tile mastic	2400	SF	Auditorium		Miscellaneous	No	None	0		YES	X NO
2013 - Fall: I	No Change				1							
Comments:												
2014- Spring	g: No Change											
Comments:	g. 140 Onlange											
					7							
2014 - Fall: Comments:	No Change											
Comments.												
	g: No Change											
Comments:												
2015 - Fall: I	No Change				1							
Comments:												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	sessment Category
G	Acoustical Plaster	15000	SF	1960 building, rms 117,115,113,110,108,111 ,109, girls&boys rr, JC, stairs		Surface					YES	X NO
2013 - Fall:	No Change]							
Comments:												
2014- Sprin	g: No Change				1							
Comments:												
2014 - Fall:	No Change											
Comments:	_											
2015- Sprin	g: No Change											
Comments:	•											
2015 - Fall:	No Change											
Comments:	.											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	sessment Category
1	aircell pipe	200	LF	1894 bldg - boys playroom, storage, book room, girls playroom, fan room		TSI	No	None	0		YES	X NO
2013 - Fall:	No Change				1							
Comments:	J											
2014- Sprin	g: No Change											
Comments:												
2014 - Fall:	No Change				1							
Comments:												
2015- Sprin	g: No Change											
Comments:	g											
2015 - Fall:	No Change				1							
Comments:	criarigo											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	essment Category
J	aircell joints	30	LF	1894 bldg - boys playroom, storage, book room, girls playroom, fan room		TSI	No	None	0		YES	X NO
2013 - Fall:	: No Change				7							
Comments	:											
	ng: No Change											
Comments	:											
	: No Change]							
Comments	:											
	ng: No Change											
Comments	:											
	: No Change											
Comments	:											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	essment Category
К	cardboard pipe	200	LF	1894 bldg- basement boys & girls playroom, fan room, toilets, corridors		TSI	No	None	0		YES	X NO
2013 - Fall:	: No Change				7							
Comments]							
2014- Sprir	ng: No Change				7							
Comments					1							

2014 - Fall: No Change

2015- Spring: No Change

2015 - Fall: No Change

Comments:

Comments:

Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in As	sessment Category
L	cardboard joints	20	LF	1894 bldg- basement boys & girls playroom, fan room, toilets, corridors		TSI	No	None	0		YES	X NO
2013 - Fall:	No Change											
Comments:	J											
2014- Sprine	g: No Change											
Comments:	<u> </u>											
2014 - Fall:	No Change											
Comments:	J											
2015- Sprine	g: No Change											
Comments:	<u> </u>											
2015 - Fall:	No Change											
Comments:	J -											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in As	sessment Category
N	fiberglass joints	60	LF	1894 bldg-basement boys & girls toilets & playrooms, toilets, fan room		TSI					YES	X NO
2013 - Fall:	No Change											
Comments:												
2014- Sprine	g: No Change											
Comments:	<u> </u>											
2014 - Fall:	No Change											
Comments:	J -											
2015- Sprine	g: No Change											
Comments:	<u> </u>											
2015 - Fall:	No Change											
Comments:	<u> </u>											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
0	aircell pipe lag	900	LF	1939 building- basement assembly room, platform, fan room		TSI	Yes	None	0		YES	X NO
2013 - Fall: N	lo Change]							
Comments:	to onango											
2014- Spring	: No Change											
Comments:												
2014 - Fall: N	lo Change]							
Comments:	<u> </u>											
0045 0 :	NI OI				- 1							
2015- Spring	: No Change											
Comments:												
2015 - Fall: N	lo Change											
Comments:	<u> </u>											
	Inc. (15)	T		Lagaretta e		Tana di I	Levis		T 5			
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
Р	aircell pipe-1960 bldg	100	LF	1960 bldg- 2nd floor stairwells (between room 217 & 210, between rooms 209 &mens bathroom)		TSI	Yes	None	0		YES	X NO
2013 - Fall: N	lo Change]							
Comments:												
2014 Corio	. No Change				1							
2014- Spring Comments:	. No Change											
Comments.					J							
2014 - Fall: N	lo Change											
Comments:												
2015- Spring	· No Change]							
Comments:												
2015 - Fall: N	lo Change]							
Comments:												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	essment Category
Q	aircell joints	50	LF	1939 bldg - plaform, fan room		TSI	Yes	None	0		YES	X NO
2013 - Fall:	No Change											
Comments:]							
2014- Sprin	g: No Change]							
Comments:]							
2014 - Fall:	No Change]							
Comments:												
2015- Sprin	g: No Change]							
Comments:												
2015 - Fall:	No Change											
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	essment Category
R	fiberglass joints- ABATED	0	LF	1960 bldg- 2nd floor west corridor		Miscellaneous					YES	X NO
2013 - Fall:	No Change]							
Comments:												
2014- Sprin	g: No Change											
Comments:												
2014 - Fall:	No Change											
Comments:												
2015- Sprin	g: No Change]							
Comments:]							
2015 - Fall:	No Change]							
Comments:												

ALL LEA Responsibilities, for this school, will be met.

Lynn A.Crivello

Sym & Crwill

NOTICE TO PARENTS AND STAFF REGARDING THE ASBESTOS MANAGEMENT PLAN NOTIFICATION

School:	Perkins Bass School
Date:	10/1/2015
the Asbes	notify you in accordance with Illinois and Federal Asbestos Regulations, that a copy of tos Management Plan is available at each school during school hours by appointment. to review the Asbestos Management Plan must be made at least 24 hours in advance.
The last in	se be advised that CPS conducts asbestos inspections of all Schools every three years. aspection was completed in 2013. surveillances are conducted every six months.
CHECK O	<u>NE</u>
A c	copy of this notice was sent home in each child's backpack.
X A c	copy of this notice was printed in the school's newsletter and sent home with each child
A c	copy of this notice was printed in the school's calendar and sent home with each child
Oth	ner.
	Y OF THIS NOTICE MUST BE PLACED IN THE HOOL'S ASBESTOS MANAGEMENT PLAN.

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

Oracle Unit: 22161