## **Chicago Public Schools**

### 6 Month Asbestos Surveillance

2015 - Fall

		Greeley Schoo heridan Road					Oracle Unit: Region:	226 01	61	Buildin Mail Ro	•	
	HERE IF NO CH	ANGE T	O ASBE	STOS s	sbestos Surveyor: urvey Date: mail Address:	11/5/20	15					
	A copy of the 2013/20	014 notice to	parents and	d staff regarding	the asbestos manag	gement plan n	otifications w	vas distribute	ed via:			
	Each child's backp	ack	X Notice	printed in school	's newsletter	Notice p	rinted in scho	ool's calenda	r Ot	her		
HA No	Material Description	Material Quantity	Material Units	Material Location	n Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in As	sessment Category
03	24"x24" Smooth Gray Ceiling Tile	0		1st, 2nd, & 3rd Flo Classrooms, Office Library							YES	XNO
2013 - Fall: N Comments:	lo Change											
2014- Spring: Comments:	: No Change											
2014 - Fall: N Comments:	lo Change											
2015- Spring: Comments:	: No Change											
2015 - Fall: N Comments:	lo Change											
Comments.												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category
04	24"x24" Rough Gray Ceiling Tile	0		1st, 2nd, & 3rd Floor Corridors, Lunch Room							YES	X NO

2013 - Fall: No Change	
Comments:	

2014- Spring: No Change	
Comments:	

2014 - Fall: No Change	
Comments:	

	2015- Spring: No Change
Comments:	Comments:

2015 - Fall: No Change	
Comments:	
	_

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category
05	24"x24" Smooth Dots Ceiling Tile	0		Home Management Room (215,216), Kitchen							YES	X NO

2013 - Fall: No Change	
Comments:	

2014- Spring: No Change	
Comments:	

2014 - Fall: No Change	
Comments:	

2015- Spring: No Change	
Comments:	

2015 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category
08	Exterior Sink Coating	100	SF	Throughout ( See Hatching Maps )		Miscellaneous	No	None	0		YES	XNO

2013 - Fall: No Change	
Comments:	

2014- Spring: No Change	
Comments:	

2014 - Fall: No Change	
Comments:	

2015 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessn	nent Category
09	12"x12" Beige w/ Brown Streaks VFT	19400	SF	Throughout(See Hatching Maps)		Miscellaneous	No	None	0		YES	XNO

Comments:	2013 - Fall: No Change	
	Comments:	

2014- Spring: No Change	
Comments:	

2014 - Fall: No Change	
Comments:	

2015- Spring: No Change	
Comments:	

2015 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category
10	12"x12" Beige w/ Brown Streaks VFT Mastic	19400	SF	Throughout ( See Hatching Maps )		Miscellaneous	No	None	0		YES	XNO

2013 - Fall: No Change	
Comments:	

2014- Spring: No Change	
Comments:	

2014 - Fall: No Change	
Comments:	

2015 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	
11	Vinyl Baseboard	0		Throughout			No				YES X NO	i -

2013 - Fall: No Change	
Comments:	

2014- Spring: No Change	
Comments:	

2014 - Fall: No Change	
Comments:	

2015- Spring: No Change	
Comments:	

2015 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category
13	12"x12" Cream w/ Beige Wave VFT	0		Not Observed (Rooms 218)		Miscellaneous		None	0		YES	XNO

2013 - Fall: No Change	
Comments:	

2014- Spring: No Change
Comments:

2014 - Fall: No Change	
Comments:	

2015- Spring: No Change	
Comments:	

2015 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessr	nent Category
14	12"x12" Cream w/ Beige Wave VFT Mastic	0	SF	Not Observed-Room 218		Miscellaneous	No	None	0		YES	X NO

2013 - Fall: No Change	
Comments:	

2014- Spring: No Change	
Comments:	

2014 - Fall: No Change	
Comments:	

2015- Spring: No Change	
Comments:	

2015 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
15	12"x12" Royal Blue VFT	1800	SF	Lunchroom		Miscellaneous	No	None	0		YES	X NO

2013 - Fall: No Change	
Comments:	

2014- Spring: No Change	
Comments:	

2014 - Fall: No Change	
Comments:	

2015- Spring: No Change	
Comments:	

2015 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
16	12"x12" Royal Blue VFT Mastic	1800	SF	Lunchroom		Miscellaneous	No	None	0		YES	XNO

2013 - Fall: No Change	
Comments:	

2014- Spring: No Change	
Comments:	

2014 - Fall: No Change	
Comments:	

Comments:	2015- Spring: No Change	
	Comments:	

2015 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
17	MJP on Fiberglass Pipe Insulation	0		2nd Floor Boys Toilet, Penthouse, Boiler Room, Gym, Pump Room, Storage 117 (Behind Engineers Office)							YES	XNO

2013 - Fall: No Change	
Comments:	

2014- Spring: No Change	
Comments:	

2014 - Fall: No Change

Comments:

2015- Spring: No Change Comments:

2015 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
18	12"x12" Beige w/ Grey Streaks VFT	40	SF	Elevator		Miscellaneous	No	None	0		YES	X NO

2013 - Fall: No Change	
Comments:	

2014- Spring: No Change Comments:

2014 - Fall: No Change	
Comments:	

2015 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category
19	12"x12" Beige w/ Grey Streaks VFT Mastic	40	SF	Elevator		Miscellaneous	No	None	0		YES	XNO

2013 - Fall: No Change	
Comments:	

2014- Spring: No Change	
Comments:	

2014 - Fall: No Change Comments:

2015- Spring: No Change Comments:

2015 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
20	Carpet mastic	144000	SF	Rooms 145, 151, 147, 148, 217, 219, 220, 221, 221B, 215, 320, 316, 317, 318, 322, 323, 325, 328		Miscellaneous	No	None	0		X YES NO

#### 2013 - Fall: Other

Comments:148 carpet/mastic removed, replaced wit VFT

#### 2014- Spring: No Change

Comments:

#### 2014 - Fall: Other

Comments:Mastic sampled, no asbestos, carpet removed from rooms 145,151,147,148,221,221b,215

2015- Spring: No Change

Comments:

2015 - Fall: No Change Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
21	Black sink coating	84	SF	Rooms 144, 145, 146, 147, 148, 151, 316, 317, 320, 321, 322, 325, 326, 328		Miscellaneous	No	None	0		YES	XNO

2013 - Fall: No Change	٦
Comments:	
	_

2014- Spring: No Change	
Comments:	

2014 - Fall: No Change Comments:

2015- Spring: No Change	
Comments:	

2015 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category
22	12"X12" Brown VFT	5600	SF	Rooms 140, 141, 144, 146, 321, 324, 326		Miscellaneous	No	None	0		YES	X NO

2013 - Fall: No Change	
Comments:	

2014- Spring: No Change	
Comments:	

2014 - Fall: No Change	
Comments:	

2015 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
23	12"X12" Brown VFT Mastic	5600	SF	Rooms 140, 141, 144, 146, 321, 324, 326		Miscellaneous	No	None	0		YES	X NO

2013 - Fall: No Change	
Comments:	

2014- Spring: No Change
Comments:

2014 - Fall: No Change	
Comments:	

Comments:	2015- Spring: No Change	
	Comments:	

2015 - Fall: No Change	
Comments:	
	_

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment C	ategory
24	White sink coating	40	SF	Rooms 215, 216, 218, and 2nd floor Teachers Lounge		Miscellaneous	No	None	0		YES X	0

2013 - Fall: No Change	
Comments:	

2014- Spring: No Change	
Comments:	

2014 - Fall: No Change	
Comments:	

2015- Spring: No Change	
Comments:	

2015 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category
25	Plaster ceiling	2800	SF	Room 312, Stairwells, Bathrooms 1st, 2nd and 3rd floors, Library, Janitors Closet		Miscellaneous	No	None	0		YES	X NO

2013 - Fall: No Change	
Comments:	

2014- Spring: No Change	
Comments:	

2014 - Fall: No Change	
Comments:	

2015- Spring: No Change	
Comments:	

2015 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category
26	12x12 Gray w/ gray and white streaks VFT	2500	SF	Rooms 147,145,151		Miscellaneous	No	None	0		YES	X NO

2013 - Fall: No Change
Comments:
2014 - Fall: No Change
Comments:
2014- Spring: No Change
Comments:
2015- Spring: No Change
Comments:

2015 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category
27	12x12 Gray w/ gray and white streaks VFT Mastic	2500	SF	Rooms 147,145, 151		Miscellaneous	No	None	0		YES	XNO

2013 - Fall: No Change	
Comments:	

2014 - Fall: No Change	
Comments:	

2015- Spring: No Change Comments:

2015 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
28	12x12 White w/Gray Streaks VFT	700	SF	Room 218		Miscellaneous	No	None	0		YES	XNO

Common antes	all: No Change	13 - Fall: No Change
Comments:	its:	mments:

2014 - Fall: No Change	
Comments:	

2014- Spring: No Change	
Comments:	

2015 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category
29	12x12 White w/Gray Streaks VFT Mastic	700	SF	Room 218		Miscellaneous	No	None	0		YES	X NO

2013 - Fall: No Change	
Comments:	

2014- Spring: No Change	
Comments:	

2014 - Fall: No Change	
Comments:	

2015 - Fall: No Change	
Comments:	

ALL LEA Responsibilities, for this school, will be met.

Syn & Crwill

Lynn A.Crivello

#### NOTICE TO PARENTS AND STAFF REGARDING THE ASBESTOS MANAGEMENT PLAN NOTIFICATION

School: Horace Greeley School Date: 11/5/2015

This is to notify you in accordance with Illinois and Federal Asbestos Regulations, that a copy of the Asbestos Management Plan is available at each school during school hours by appointment. Requests to review the Asbestos Management Plan must be made at least 24 hours in advance.


Also please be advised that CPS conducts asbestos inspections of all Schools every three years. The last inspection was completed in 2013.

Asbestos surveillances are conducted every six months.

#### CHECK ONE

A copy of this notice was sent home in each child's backpack.

X A copy of this notice was printed in the school's newsletter and sent home with each child



Other.

# A COPY OF THIS NOTICE MUST BE PLACED IN THE SCHOOL'S ASBESTOS MANAGEMENT PLAN.