# **Chicago Public Schools**

# 6 Month Asbestos Surveillance

2015 - Fall

	School: STEM Ma Address: 1522 W. I	agnet Acaden Fillmore	лу				acle Unit: gion:	227 <sup>-</sup> 03	11	Buildir Mail Ro	-	
	HERE IF NO CH				Asbestos Surveyo Survey Date: Email Address:	10/20/201						
	A copy of the 2013/20			-	ng the asbestos man pol's newsletter			was distribute ool's calendai		ther		
HA No	Material Description	Material Quantity	Material Units	Material Loca	ation Asbesto Type	s Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in As	sessment Category
1	9" x 9" Dark Green Floor Tile	903	SF	Room 314 - 18 Building	84	Miscellaneous	No	None	0		X YES	NO
2014- Spring: Comments:w 2014 - Fall: A Comments:A 2015- Spring: Comments:re	as been removed sum Abated as removed in summe bated BATED SUMMER 20 Abated moved in summer of a	er of 2011 11										
2015 - Fall: A Comments:re	bated moved in summer 20	15										

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category
2	9" x 9" Tan Floor Tile (Under Carpet)	700	SF	Principal's Office & Throughout Basement		Miscellaneous		None			YES	XNO

2013 - Fall: No Change	
Comments:	

2014- Spring: No Change
Comments:

2014 - Fall: No Change Comments:

2015- Spring: No Change Comments:

2015 - Fall: No Change
Comments: Principal office have wood floor. Main office has carpet over tiles

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
3	12" x 12" Tan Floor Tile - ABATED			Basement, 3rd Floor Corridor and Gym - ROOM 212 NOT ABATED		Miscellaneous					YES X NO

2013 - Fall: No Change	
Comments:	

2014- Spring: No Change Comments:

2014 - Fall: No Change	
Comments:	

2015- Spring: No Change Comments:

2015 - Fall: No Change Comments:no change

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessi	ment Category
4	Red Linoleum	800	SF	Engineer's Office - 1884 Building		Miscellaneous	No	None	0		X YES	NO

2013 - Fall: Damaged
Commente: floor in poor condition has some

Comments:floor in poor condition has some

2014- Spring: Damaged Comments:floor in poor condition, breaking up in some areas

2014 - Fall: Damaged Comments:FLOOR IN POOR CONDITION, BREAKING UP IN SOME AREAS

2015- Spring: Damaged Comments:floor in poor condition, breaking up in some areas

#### 2015 - Fall: Damaged Comments:floor in poor condition

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
5A	9" x 9" Tan Floor Tile (Under Carpet)	700	SF	Room 202 - 1911 Building		Miscellaneous	No	Unknown			X YES NO

2013 - Fall: Abated Comments:abated, summer 2011

2014- Spring: Abated
Comments:was removed in summer of 2011

2014 - Fall: Abated Comments:ABATED SUMMER 2011

2015- Spring: Abated Comments:removed in summer of 2011

2015 - Fall: Abated

Comments:removed in summer 2011

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category
5B	9" x 9" Tan Floor Tile Mastic (Under Carpet)	700	SF	Room 202 - 1911 Building		Miscellaneous	No	Unknown	0		X YES	NO

2013 - Fall: Abated
Comments:new floor summer 2011

2014- Spring: Abated
Comments:new floor in summer of 2011

2014 - Fall: Abated Comments:NEW FLOOR SUMMER 2011

2015- Spring: Abated Comments:new floor installed in summer of 2011

2015 - Fall: Abated Comments:new floor installed on summer 2011

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Catego
6	Gray Linoleum			Room 210		Miscellaneous					X YES NO

# 2013 - Fall: Abated

Comments:gray linoleum has been removed room 210 has a woode floor

2014- Spring: Abated Comments:gray linoleum was removed, rm 210 has a wood floor

2014 - Fall: Abated

Comments:210 HAS WOODEN FLOOR

2015- Spring: Abated

Comments:gray linoleum was removed, rm 210 has a wooden floor

2015 - Fall: Abated

Comments:grey linileum removed,wood floor installed

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category
7	Plaster			Throughout the 1911 Building		Miscellaneous					YES	XNO

2013 - Fall: No Change	
Comments:	

2014- Spring: No Change
Comments:

2014 - Fall: No Change	
Comments:	

2015- Spring: No Change	
Comments:	

2015 - Fall: No Change	
Comments:no change	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
8	Plaster			Throughout the 1884 Building		Surface					YES	X NO

2013 - Fall: No Change	
Comments:	

2014- Spring: No Change	
Comments:	

2014 - Fall: No Change	
Comments:	

2014 - Fall: No Change
Comments:
2015- Spring: No Change
Comments:

2015 - Fall: No Change	
Comments:no change	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category
9	12" x 12" Brown Floor Tile - Not Observed			Teacher's Washroom by Room 309		Miscellaneous					YES	XNO

# 2013 - Fall: No Change

Comments: there is no teachers washroom by room 309

2014- Spring: No Change Comments:there is no teachers washroom by rm 309

2014 - Fall: No Change Comments:NO TEACHERS WASHROOM BY ROOM 309

2015- Spring: No Change

Comments: there is no teachers washroom by rm 309

2015 - Fall: No Change Comments:No teacher washroom by 309

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessm	nent Category
10	Fireproofing - ABATED			Boiler Room		Miscellaneous					YES	X NO

2013 - Fall: No Change	
Comments:	

2014- Spring: No Change	
Comments:	

2014 - Fall: No Change Comments:

2015- Spring: No Change Comments:

2015 - Fall: No Change Comments:no change

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
11	Roof Material & Flashing - Non-AHERA			Roof		Miscellaneous					X YES	NO

2013 - Fall: Abated	
Comments:roof was replaced in summer 2011	

2014- Spring: Abated Comments:roof was replaced in summer of 2011

2014 - Fall: Abated Comments:REPLACED SUMMER 2011

2015- Spring: Abated Comments:roof was replaced in summer of 2011

2015 - Fall: Deteriorated Comments:Roof have 5 spot,corners,who need repair material deteriorated from standing water

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Catego	ry
12	9" x 9" Dark Green Floor Tile Mastic	903	SF	Room 314 - 1884 Building		Miscellaneous	No	None	0		X YES NO	

2013 - Fall: Abated

Comments:was removed in summer 2011

2014- Spring: Abated Comments:was removed in summer of 2011

2014 - Fall: Abated Comments:ABATED SUMMER 2011

2015- Spring: Abated Comments:was removed in summer of 2011

2015 - Fall: Abated

Comments:removed in summer 2011

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category
13	12" x 12" Blue Floor Tile	2700	SF	Main Office, Principal's Office - 1911 Building and Room 311 - 1884 Building		Miscellaneous	No	None	0		YES	X NO

2013 - Fall: No Change	
Comments:tile is under new carpet	

2014- Spring: No Change
Comments:tile is under new carpet in these areas

2014 - Fall: No Change Comments:TILE UNDER NEW CARPET

2015- Spring: No Change

Comments:tile is under new carpet in these areas

2015 - Fall: No Change Comments:Principal office wood flooring,Main office carpet over tiles

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
14	Red Linoleum Mastic	800	SF	Engineer's Office - 1884 Building		Miscellaneous	No	None	0		YES	X NO

2013 - Fall: No Change	
Comments:	

2014- Spring: No Change Comments:

2014 - Fall: No Change Comments:

2015- Spring: No Change Comments:

2015 - Fall: No Change Comments:no change

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category
15	9" x 9" Brown Floor Tile Mastic	15	SF	Room 314 - 1884 Building		Miscellaneous		Unknown			X YES	NO

2013 - Fall: Aba	ed
Comments:has	peenremoved summer 2011

2014- Spring: Abated
Comments:has been removed in summer of 2011

2014 - Fall: Abated Comments:ABATED SUMMER 2011

2015- Spring: Abated Comments:has been removed in summer of 2011

2015 - Fall: Abated
Comments:removed in summer 2011

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category
16A	12" x 12" Beige (& Gray) Floor Tile Mastic	2700	SF	Rooms 302 & 308 and the Stage in the Auditorium		Miscellaneous	No	None	0		YES	XNO

2013 - Fall: No Change	
Comments:	

2014- Spring: No Change	
Comments:	

2014 - Fall: No Change	
Comments:	

	2015- Spring: No Change	
Comments:	Comments:	

2015 - Fall: No Change	
Comments:hardwood floor	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
16B	12" x 12" Brown Floor Tile Mastic	1400	SF	Rooms 212 & 013 - 1884 Building		Miscellaneous	No	None	0		X YES	NO

2013 - Fall: Abated	
Comments:has been removed in summer 2011	

2014 - Fall: Abated	
Comments:ABATED SUMMER2011	

2014- Spring: Abated
Comments:has been removed in summer of 2011

2015- Spring: Abated Comments:has been removed in summer of 2011

2015 - Fall: Abated	
Comments:at summer 2011	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
16C	12" x 12" Gray (w/White & Gray) Floor Tile Mastic	3000	SF	Landings by Rooms 210 & 109 & Room 102		Miscellaneous	No	None	0		

2013 - Fall: Abated	
Comments:summer 2011	

2014- Spring: Abated Comments:in the summer of 2011

Comments:SUMMER 2011	

2015 - Fall: No Change Comments:no change

2015- Spring: Abated Comments:in the summer of 2011

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
17	Brown Linoleum			1884 Building - Basement- Engineer's Office, Hall & Storage Room.		Miscellaneous					X YES	NO

#### 2013 - Fall: Abated

Comments:has been removed from hall and storage room, engineers office has red linoleum and some brown in storage room next to engineers office

2014-	Spring:	Abated

Comments:has been removed from corridor, eng's office has red linoleum and some brown in storage rm next to eng's office

2014 - Fall: Abated

Comments:ABATED FROM HALL AND STORAGE, ENG. OFFICE HAS RED LINOLEUM AND SOME BROWN IN STORAGE ROOM NEXT TO ENG. OFFICE

# 2015- Spring: Abated

Comments:has been removed from corridor, eng's office has red linoleum and some brown in storage room next to eng's office

2015 - Fall: No Change

Comments:no change

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category
19	9" x 9" Tan Floor Tile Mastic (Under Carpet)	700	SF	Principal's Office & Throughout Basement		Miscellaneous		None			YES	XNO

## 2013 - Fall: No Change

Comments:new carpet was installed over existing

2014- Spring: No Change Comments:new carpet was installed over existing tile

2014 - Fall: No Change Comments:NEW CARPET INSTALLED OVER EXISTING

2015- Spring: No Change

Comments:new carpet was installed over existing one.

2015 - Fall: No Change

Comments:principal office have hardwood floor,main office not abated have tiles under carpet

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
20	9" x 9" Brown Floor Tile	15	SF	Room 314 - 1884 Building		Miscellaneous		None			

2013 - Fall: Abated Comments:has been removed in summer 2011

2014- Spring: Abated Comments:has been removed in summer of 2011

2014 - Fall: Abated Comments:ABATED SUMMER 2011

2015- Spring: Abated Comments:has been removed in summer of 2011

2015 - Fall: Abated

Comments:removed summer 2011

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
21	12" x 12" Brown Floor Tile			Rooms 212 & 013 - 1884 Building		Miscellaneous	No				X YES	NO

2	013 - Fall: Abated
С	omments:summer 2011

2014- Spring: Abated	
Comments:in the summer of 2011	

2014 - Fall: Abated Comments:ABATED SUMMER 2011

2015- Spring: Abated Comments:in the summer of 2011

2015 - Fall: Abated	
Comments:summer 2011	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessme	ent Category
22	12" x 12" Beige Floor Tile w/Gray Streaks	2700	SF	Rooms 302 and 308 & Auditorium Stage		Miscellaneous	No	None	0		YES	X NO

# 2013 - Fall: No Change Comments:stage has hard wood flooring

2014- Spring: No Change Comments:the stage has hardwood flooring

2014 - Fall: No Change Comments:STAGE, HARDWOOD FLOOR

2015- Spring: No Change Comments:the stage has hardwood flooring

2015 - Fall: No Change Comments:no change

H	IA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category
	23	12" x 12" Beige Floor Tile Mastic			Room 201		Miscellaneous					YES	X NO

2013 - Fall: No Change	
Comments:	

2014- Spring: No Change	_
Comments:	

2014 - Fall: No Change	
Comments:	

-	
Comments:	

2015 - Fall: No Change	
Comments:no change	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	
24	Pink Linoleum			Room 210		Miscellaneous					X YES	NO

# 2013 - Fall: Abated Comments:room 210 has hard wood floors

2014- Spring: Abated Comments:room 210 has hardwood flooring

2014 - Fall: Abated Comments:210 HAS HARD WOOD FLOORS

#### 2015- Spring: Abated Comments:room 210 has hard wood flooring

2015 - Fall: Abated

Comments:have wood flooring

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category
25	2' x 4' Lay In Ceiling Panels	2000	SF	Women's Teacher's Washrooms on the 2nd & 3rd Floors		Miscellaneous	Yes	None	0		X YES	NO

2013 - Fall: Abated	
Comments:summer 2011	

2014- Spring: Abated	
Comments:in the summer of 2011	

2014 - Fall: Abated	
Comments:SUMMER 2011	

2015- Spring: Abated Comments:in the summer of 2011

2015 - Fall: Abated	
Comments:summer 2011	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	
26	12" x 12" Beige Floor Tile w/White & Gray Streaks			Hall Landings by Room 102		Miscellaneous					X YES NO	

2013 - Fall: Abated	
Comments:summer 2011	

2014- Spring: Abated
Comments: in the summer of 2011

2014 - Fall: Abated	
Comments:SUMMER 2011	

2015- Spring: Abated Comments:in the summer of 2011

2015 - Fall: Abated Comments:summer 2011

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	
27	Carpet Mastic	700	SF	Room 208		Miscellaneous		None			X YES	NO

2013 - Fall: Abated
Comments:has been removed in summer 2011

2014- Spring: Abated Comments:has been removed in the summer of 2011

2014 - Fall: Abated Comments:ABATED SUMMER 2011

2015- Spring: Abated Comments:has been removed in the summer of 2011

2015 - Fall: Abated Comments:removed in summer 2011

ŀ	HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
2	28	Blue Floor Tile Mastic			Hall at Exit by Office		Miscellaneous					

2013 - Fall: Abated	
Comments:summer 2011	

2014- Spring: Abated Comments:in the summer of 2011

2014 - Fall: Abated	
Comments:SUMMER 2011	

2015- Spring: Abated Comments:in the summer of 2011

2015 - Fall: Abated Comments:summer 2011

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
29	Interior Window Grout			Interior Windows		Surface					X YES	NO

2013 - Fall: Abated	
Comments:new windows installed	

2014- Spring: Abated
Comments:new windows have been installed

2014 - Fall: Abated Comments:NEW GROUT INSTALLED ALONG WITH NEW WINDOWS

2015- Spring: Abated Comments:new windows have been installed

2015 - Fall: Abated Comments:summer 2011 new windows installed with new grout

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
30	Interior Bricks			Throughout 1884 Building		Miscellaneous					YES	X NO

2013 - Fall: No Change	
Comments:	

2014- Spring: No Change	
Comments:	

2014 - Fall: No Change	
Comments:	

2015- Spring: No Change	
Comments:	

2015 - Fall: No Change	
Comments:no change	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
31	Interior Brick Mortar			Throughout 1884 Building		Miscellaneous					YES	X NO

2013 - Fall: No Change	
Comments:	

2014- Spring: No Change
Comments:

2014 - Fall: No Change	
Comments:	

2015- Spring: No Change Comments:

2015 - Fall: No Change	
Comments:no change	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
32	Cinder Block Mortar			Throughout 1884 Basement		Miscellaneous					YES	X NO

2013 - Fall: No Change	
Comments:	

2014- Spring: No Change	
Comments:	

2014 - Fall: No Change	
Comments:	

2015- Spring: No Change	
Comments:	

2015 - Fall: No Change	
Comments:no change	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
33	Fire Door Insulation	40	SF	Throughout 1911 & 1884 Buildings		TSI	No	None	0		X YES	NO

2013 - Fall: Other
Comments:new doors installed in summer 2011

2014- Spring: Other Comments:all new doors installed in summer of 2011

2014 - Fall: Other Comments:NEW DOORS INSTALLED SUMMER 2011

2015- Spring: Other

Comments: all new doors installed in the summer of 2011

2015 - Fall: Other Comments:all new doors installed in summer 2011

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
34	Ceramic Tile Grout - Floor	1000	SF	Throughout Boy's & Girl's Washrooms - 1911 Building		Miscellaneous	No	None	0		

#### 2013 - Fall: Abated

Comments:new tile and grout in summer 2011

2014- Spring: Abated Comments:new tile and grout was installed in summer of 2011

2014 - Fall: Abated Comments:NEW TILE AND GROUT SUMMER 2011

2015- Spring: Abated

Comments:new tile and grout was installed in the summer of 2011

2015 - Fall: Abated

Comments:new floor and grout in summer 2011

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	
35	Baseboards			Room 013 of the 1884 Building & Room 308 of the1911 Building		Miscellaneous						

#### 2013 - Fall: Abated

Comments:new baseboards installed summer 2011

2014- Spring: Abated Comments:new baseboards installed in summer of 2011

2014 - Fall: Abated Comments:NEW BASEBOARDS SUMMER 2011

2015- Spring: Abated Comments:new baseboards installed in the summer of 2011

2015 - Fall: Abated Comments:new baseboard in summer 2011

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	
36	Baseboard Mastic			Room 013 of the 1884 Building & Room 308 of the1911 Building		Miscellaneous					X YES NO	

2013 - Fall: Abated

Comments:new base boards installed summer 2011

2014- Spring: Abated Comments:new baseboards installed in summer of 2011

2014 - Fall: Abated Comments:NEW BASEBOARDS SUMMER 2011

2015- Spring: Abated Comments:new baseboards installed in the summer of 2011

2015 - Fall: Abated

Comments:new baseboards installed in summer 2011

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	
37	Exterior Brick			Exterior of the 1911 Building		Miscellaneous					YES	XNO

2013 - Fall: No Change	
Comments:	

2014- Spring: No Change
Comments:

2014 - Fall: No Change	
Comments:	

2015- Spring: No Change	
Comments:	

2015 - Fall: No Change	
Comments:no change	

HA No	)	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	
38		Exterior Brick Mortar			Exterior of the 1911 Building		Miscellaneous					YES	X NO

Comments:	

2014- Spring: No Change	
Comments:	

2014 - Fall: No Change	
Comments:	

2015- Spring: No Change	
Comments:	

2015 - Fall: No Change	
Comments:no change	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
39	Exterior Window Grout			Exterior Windows of the 1911 Building		Miscellaneous					YES	X NO

2013 - Fall: No Change	
Comments:	

2014- Spring: No Change
Comments:

2014 - Fall: No Change	
Comments:	

2015- Spring: No Change	
Comments:	

2015 - Fall: No Change	
Comments:no change	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category
40	Exterior Brick			Exterior of the 1884 Building		Miscellaneous					YES	X NO

2013 - Fall: No Change	
Comments:	

2014- Spring: No Change	
Comments:	

2014 - Fall: No Change	
Comments:	

2015- Spring: No Change	
Comments:	

2015 - Fall: No Change	
Comments:no change	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category
41	Exterior Mortar			Exterior of the 1814 Building		Miscellaneous					YES	XNO

2013 - Fall: No Change	
Comments:	

2014- Spring: No Change
Comments:

2014 - Fall: No Change	
Comments:	

2015- Spring: No Change Comments:

2015 - Fall: No Change	
Comments:no change	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment	Category
42	Exterior Window Grout			Exterior of the 1884 Building		Miscellaneous					YES	NO

2013 - Fall: No Change	
Comments:	

2014- Spring: No Change	
Comments:	

2014 - Fall: No Change	
Comments:	

2015- Spring: No Change	
Comments:	

2015 - Fall: No Change	
Comments:no change	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
43	Tank Insulation	1000	SF	Boiler Room		Miscellaneous	No	None	0		YES	XNO

2013 - Fall: No Change	
Comments:	

2014- Spring: No Change	
Comments:	

2014 - Fall: No Change	
Comments:	

2015- Spring: No Change	
Comments:	

2015 - Fall: No Change	
Comments:no change	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
44	Exterior Brick Used to Block Windows			Exterior of the 1884 Building		Miscellaneous					YES	X NO

2013 - Fall: No Change	
Comments:	

2014- Spring: No Change	
Comments:	

2014 - Fall: No Change	
Comments:	

2015- Spring: No Change	
Comments:	

2015 - Fall: No Change	
Comments:no change	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category
45	Brick Mortar Used to Block Windows			Exterior of the 1884 Building		Miscellaneous					YES	XNO

2013 - Fall: No Change	
Comments:	

2014- Spring: No Change
Comments:

2014 - Fall: No Change Comments:

2015- Spring: No Change Comments:

2015 - Fall: No Change	
Comments:no change	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
46	Spray-on Insulation			Electric Room on the 1st Floor of the 1911 Building, Boiler Room Ceiling by Back Door- 1911 Bldg.		TSI					

2013 - Fall: No Change	
Comments:	

2014- Spring: No Change Comments:

Comments.

2014 - Fall: No Change Comments:

2015- Spring: No Change Comments:

2015 - Fall: No Change	
Comments:no change	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
47	Blue Floor Tile			Hall at Exit by Office		Miscellaneous					X YES	NO

2013 - Fall: Abated
Comments:summer 2011

2014- Spring: Abated	
Comments:in the summer of 2011	

2014 - Fall: Abated	
Comments:SUMMER 2011	

2015- Spring: Abated Comments:in the summer of 2011

2015 - Fall: Abated	
Comments:in summer 2011	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	
48	Terrazzo Flooring	1000	SF	Throughout the 1911 Building Stairs		Miscellaneous	No	None	0		YES X	NO

## 2013 - Fall: No Change Comments:there is no terrazo flooring in the building

2014- Spring: No Change Comments:there is no terrazzo flooring in the building

2014 - Fall: No Change Comments:NO TERRAZO IN BUILDING

2015- Spring: No Change Comments:there is no terrazo flooring in the building

2015 - Fall: No Change Comments:no terazzo floring in building

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category
49	12" x 12" Blue Floor Tile Mastic	2700	SF	Main Office & Principal's Office of the 1911 Building & Room 311 of the 1884 Building		Miscellaneous		None			X YES	NO

#### 2013 - Fall: Abated

Comments:principal and main office not abated only new carpet over existing, room 311 was abated and is now bathroom.

#### 2014- Spring: Abated

Comments:new carpet was placed over the existing floor, rm 311 was abated and is now a washroom

2014 - Fall: Abated

Comments:ROOM 311 WAS ABATED AND IS NOW BATHROOM, PRINCIPAL AND MAIN OFFICE HAD NEW CARPET INSTALLED OVER EXISTING

## 2015- Spring: Abated

Comments:new carpet was placed over the existing floor, room 311 was abated and is now a washroom

#### 2015 - Fall: Abated

Comments:room 311 abated and is bathroom now.main office have carpet over tile, Principal office wood floor

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category
53	12"x12" Beige Floor Tile w/Gray & White Streaks	2200	SF	The Stair Landings of the 1884 Building & Room 102 of the 1911 Building		Miscellaneous		None			X YES	NO

#### 2013 - Fall: Abated

Comments:room 102 is now the kitchen and lunchrrom and was abated. landing has been abated also.

#### 2014- Spring: Abated

Comments:rm 102 is now the kitchen and lunchroom and was abated, landing was also abated

# 2014 - Fall: Abated

Comments:102 IS NOW KITCHEN AND LUNCHROOM AND WAS ABATED ALONG WITH THE LANDING

#### 2015- Spring: Abated

Comments:room 102 is now the kitchen and lunchroom was abated. landing has been abated also

#### 2015 - Fall: Abated

Comments:room 102 is kitchen and lunchroom was abated,landing also abated

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
54	Purple Carpet Mastic	700	SF	Room 206/208		Miscellaneous		None			X YES	NO

2013 - Fall: Abated	
Comments:has been removed summer 2011	
2014- Spring: Abated	
Comments:was removed in 2011	
2014 - Fall: Abated	

Comments:ABATED SUMMER 2011

2015- Spring: Abated Comments:was removed in 2011

Comments.was removed in 2011

2015 - Fall: Abated	
Comments:removed in summer 2011	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	
55	Linoleum Flooring	2200	SF	Gymnasium - 1911 Building		Miscellaneous		None				

# 2013 - Fall: Abated

Comments:now has new hard wood flooring, summer 2011

2014- Spring: Abated Comments:was replaced with hardwood flooring in summer of 2011

2014 - Fall: Abated Comments:NOW HAS NEW HARD WOOD FLOORING, SUMMER 2011

# 2015- Spring: Abated

Comments:was replaced with hardwood flooring in the summer of 2011

# 2015 - Fall: Abated

Comments:wood flooring in summer 2011

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	
56	Linoleum Flooring Mastic	2200	SF	Gymnasium		Miscellaneous		None			X YES	NO

|--|

Comments:now has hard wood flooring, summer 2011

2014- Spring: Abated Comments:it now has hardwood flooring since the summer of 2011

2014 - Fall: Abated Comments:NOW HAS HRD WOOD FLOORING, SUMMER 2011

2015- Spring: Abated

Comments: it now has hardwood flooring since the summer of 2011

2015 - Fall: Abated Comments:wood flooring

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category
57	Blue Carpet Masric			Main Office, Principal's Office, Room 202 - 1911 Building		Miscellaneous		None			X YES	NO

#### 2013 - Fall: Abated

Comments:principal and main office has not been abated only new carpet over existing, room 202 has been abated and has new floor

#### 2014- Spring: Abated

Comments:principal and main office was not abated just new carpet installed over existing floor. room 202 was abated and has new floor

#### 2014 - Fall: Abated

Comments:202 HAS BEEN ABATED AND HAS NEW FLOOR, PRINCIPAL AND MAIN OFFICE HAS NEW CARPET INSTALLED OVER EXISTING

## 2015- Spring: Abated

Comments:main office was not abated, just new carpet over existing, principals office is hardwood floor, and rm 202 was abated and has new floor

#### 2015 - Fall: Abated

Comments:main office not abated,tiles under new carpet im main office,room 202 was abated and have new floort

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
58	4" Brown Vinyl Baseboard			1911 Building Gym/Assembly Hall		Miscellaneous					X YES	NO

2013 - Fall: Abated
Comments:has been removed, summer 2011

2014- Spring: Abated
Comments:was removed in the summer of 2011

2014 - Fall: Abated	
Comments:ABATED SUMMER 2011	

2015- Spring: Abated Comments:was removed in summer of 2011

2015 - Fall: No Change	
Comments:no change	

HA No	Material Descri	otion Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
59	4" Brown Vinyl Ba Adhesive	seboard -		1911 Building - Gym/Assembly Hall		Miscellaneous		None			X YES	NO

# 2013 - Fall: Abated Comments:has been removed, summer 2011

2014- Spring: Abated Comments:was removed in the summer of 2011

2014 - Fall: Abated Comments:ABATED SUMMER 2011

2015- Spring: Abated Comments:was emoved in the summer of 2011

2015 - Fall: Abated Comments:removed in summer 2011

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
60	12"x12" Gray Speckle Floor Tile	840	SF	1911 Building - Old Lunchroom, Room 102		Miscellaneous		None			X YES	NO

2013 - Fall: Abated	
Comments:new floor in summer 2011	

2014- Spring: Abated
Comments:new floor installed in the summer of 2011

2014 - Fall: Abated	
Comments:NEW FLOOR SUMMER 2011	

2015- Spring: Abated Comments:new floor installed in the summer of 2011

2015 - Fall: Abated Comments:summer 2011

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	
61	12"x12" Gray Speckle Floor Tile - Mastic	840	SF	1191 Building - Old Lunchroom/Room 102		Miscellaneous		None			X YES NO	

# 2013 - Fall: Abated Comments:new floor in summer 2011

2014- Spring: Abated Comments:new floor installed in the summer of 2011

2014 - Fall: Abated Comments:NEW FLOOR SUMMER 2011

#### 2015- Spring: Abated Comments:new floor installed in the summer of 2011

2015 - Fall: Abated Comments:new floor in summer 2011

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	
62	2" Brown Vinyl Baseboard	100	LF	1911 Building - Old Lunchroom/Room 102		Miscellaneous	No	None	0		X YES	NO

2013 - Fall: Abated
Comments: new baseboard installed in summer 2011

2014- Spring: Abated Comments:new baseboard was installed in the summer of 2011

2014 - Fall: Abated Comments:NEW BASEBOARD INSTALLED SUMMER 2011

2015- Spring: Abated Comments:new baseboard was installed in the summer of 2011

2015 - Fall: Abated Comments:nwe baseboard installed in summer 2011

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	
63	2" Brown Vinyl Baseboard - Adhesive	100	LF	1911 Building - Old Lunchroom/Room 102		Miscellaneous	No	None	0		X YES NO	

## 2013 - Fall: Abated

Comments:new baseboard installed in summer 2011

2014- Spring: Abated Comments:new baseboard installed in the summer of 2011

2014 - Fall: Abated Comments:NEW BASEBOARD INSTALLED SUMMER 2011

2015- Spring: Abated

Comments:new baseboard installed in the summer of 2011

2015 - Fall: Abated

Comments:new baseboard installed in summer 2011

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category
64	12"x12" Brown Speckled Floor Tile	900	SF	1884 Building - Room 103		Miscellaneous	No	None			X YES	NO

2013 - Fall: Other	
Comments:room 103 does not exist	

2014- Spring: Other	
Comments:room 103 does not exist	

2014 - Fall: Other Comments:103 DOES NOT EXIST

2015- Spring: Other Comments:room 103 does not exist

2015 - Fall: Other	
Comments:not exist	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	
65	12"x12" Tan Speckled Floor Tile - Mastic	900	SF	1884 Building - Room 103		Miscellaneous	No				X YES NO	

2013 - Fall: Other	
Comments:room 103 does not exist	

2014- Spring: Other Comments:room 103 does not exist

2014 - Fall: Other Comments:103 DOES NOT EXIST

2015- Spring: Other Comments:room 103 does not exist

2015 - Fall: Other

Comments:room 103 noe exist

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessm	ent Category
66	Ceramic Baseboard Grout	120	LF	1911 Building - 2nd and 3rd Floor Girls' and Teacher's Washrooms		Miscellaneous	No	None	0		X YES	NO

#### 2013 - Fall: Abated

Comments:girls washroom abated and new floors summer 2011. 3rd floor teachers washroom is gone, 2nd floor teachers the same

#### 2014- Spring: Abated

Comments: girls washroom was abated and new floors tiles and grout was installed in the summer of 2011. 3rd floor teachers washroom is gone. 2nd floor teachers is the same.

2014 - Fall: Abated

Comments:GIRLS WASHROOM ABATED, NEW FLOORS SUMMER 2011. 3RD FLOOR TEACHERS WASHROOM HAS BEEN ELIMINATED, 2ND FLOOR TEACHERS IS THE SAME.

#### 2015- Spring: Abated

Comments: girls washroom was abated and new floors tiles and grout was installed in the summer of 2011. 3rd floor teachers washroom is gone. 2nd floor teachers washroom is the same

#### 2015 - Fall: Abated

Comments:no change

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category
67	Ceramic Baseboard Grout - Adhesive	120	LF	1911 Building - 2nd and 3rd Floor Girls' and Teacher's Washrooms		Miscellaneous	No	None	0		X YES	NO

#### 2013 - Fall: Abated

Comments:girls washroom abated and new floors installed summer 2011. 3rd floor teachers washroom is gone, 2nd floor teachers the same.

#### 2014- Spring: Abated

Comments:girls washroom was abated and new floor tile and grout was installed in the summer of 2011. the 3rd floor teachers washroom is gone

2014 - Fall: Abated

Comments:GIRLS WASHROOM ABATED, NEW FLOORS INSTALLED SUMMER 2011. 3RD FLOOR TEACHERS WASHROOM HAS BEEN ELIMINATED, 2ND FLOOR TEACHERS IS THE SAME

#### 2015- Spring: Abated

Comments:girls washroom was abated and new floor tile and grout was installed in the summer of 2011. the 3rd floor teachers wqashroom is gone

#### 2015 - Fall: Abated

Comments:girls washroom was abated and new floors and gout installed in summer 2011.3rd floor teacher washroom is gone

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
68	12"x12" Patched Floor Tile	10	SF	1884 Building - Room 314		Miscellaneous		None			X YES	NO

2013 - Fall: Abated
Comments:room 314 is now 414 summer 2011

Comments:room 314 is now 414 summer 2011

2014- Spring: Abated Comments:room 314 is now room414 since summer of 2011

2014 - Fall: Abated Comments:314 IS NOW 414 SUMMER 2011

2015- Spring: Abated

Comments:room 314 is now 414 since the summer of 2011

2015 - Fall: No Change Comments:no change

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
69	12"x12" Patched Floor Tile - Mastic	10	SF	1884 Building - Room 314		Miscellaneous		None			

#### 2013 - Fall: Abated

Comments:room 314 is now 414 summer 2011

2014- Spring: Abated Comments:room 314 is now room 414 since summer of 2011

2014 - Fall: Abated Comments:314 IS NOW 414 SUMMER 2011

2015- Spring: Abated

Comments:314 is now 414 since the summer of 2011

2015 - Fall: Abated

Comments:room 314 is 414 from summer 2011

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category
70	Dark Blotted Beige VFT	1000	SF	Lunchroom, Exit 3 entrance		Miscellaneous	No	None	0		YES	X NO

2013 - Fall: No Change	
Comments:	

2014- Spring: No Change	
Comments:	

2014 - Fall: No Change	
Comments:	

2015 - Fall: No Change	
Comments:no change	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessme	ent Category
71	Dark Blotted Beige VFT Mastic	1000	SF	Lunchroom, Exit 3 entrance		Miscellaneous	No	None	0		YES	X NO

	2013 - Fall: No Change
Comments:	Comments:

2014- Spring: No Change	
Comments:	

2014 - Fall: No Change	
Comments:	

2015- Spring: No Change
Comments:

2015 - Fall: No Change	
Comments:no change	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
72	12" X 12" Tan Texture VFT	100	SF	West Corridor		Miscellaneous	No	None	0		YES	XNO

2013 - Fall: No Change	
Comments:	

2014- Spring: No Change	
Comments:	

2014 - Fall: No Change	
Comments:	

2015 - Fall: No Change	
Comments:no change	

Н	IA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessme	ent Category
7	3	12" X 12" Tan Texture VFT Mastic	100	SF	West Corridor		Miscellaneous	No	None	0		YES	X NO

2013 - Fall: No Change	
Comments:	

2014- Spring: No Change	
Comments:	

2014 - Fall: No Change	
Comments:	

2015- Spring: No Change	
Comments:	

2015 - Fall: No Change	
Comments:no change	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category
74	Brown Rubber Floor Adhesive	1000	SF	Stairwells		Miscellaneous	No	None	0		YES	XNO

2013 - Fall: No Change	
Comments:	

2014- Spring: No Change	
Comments:	

2014 - Fall: No Change	
Comments:	

2015 - Fall: No Change	
Comments:no change	

HA No	0	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	
75		2' X 2' Green Carpet Adhesive	1000	SF	Office		Miscellaneous	No	None	0		YES	XNO

	2013 - Fall: No Change
Comments:	Comments:

2014- Spring: No Change	
Comments:	

2014 - Fall: No Change	
Comments:	

2015- Spring: No Change	
Comments:	

2015 - Fall: No Change	
Comments:no change	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category
76	2' X 2' Blue Carpet Adhesive	1800	SF	Room 206, 208		Miscellaneous	No	None	0		YES	XNO

2013 - Fall: No Change	
Comments:	

2014- Spring: No Change	
Comments:	

2014 - Fall: No Change	
Comments:	

2015 - Fall: No Change	
Comments:no change	

HA N	No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
77		Lab Counter tops	3	EA	Room 314, 214, 114		Miscellaneous	No	None	0		YES	X NO

2013 - Fall: No Change	
Comments:	

2014- Spring: No Change	
Comments:	

2014 - Fall: No Change	
Comments:	

2015- Spring: No Change	
Comments:	

2015 - Fall: No Change	
Comments:no change	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category
78	12" X 12" lite Beige VFT	16000	SF	Classroom 104 and Corridor		Miscellaneous	No	None	0		YES	XNO

2013 - Fall: No Change	
Comments:	

2014- Spring: No Change	
Comments:	

2014 - Fall: No Change	
Comments:	

2015 - Fall: No Change	
Comments:no change	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessme	nt Category
79	12" X 12" lite Beige VFT Mastic	1600	SF	Classroom 104 and Corridor		Miscellaneous	No	None	0		YES	X NO

Commonts:	2013 - Fall: No Change
comments.	Comments:

2014- Spring: No Change	
Comments:	

2014 - Fall: No Change	
Comments:	

2015- Spring: No Change	
Comments:	

2015 - Fall: No Change	
Comments:no change	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category
A	Air Cell Pipe Insulation	100	SF	Pipe Chases and Within Walls		TSI	Yes	None	0		YES	X NO

2013 - Fall: No Change	
Comments:	

2014- Spring: No Change
Comments:

2014 - Fall: No Change	
Comments:	

2015 - Fall: No Change	
Comments:no change	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessme	ent Category
В	Cementitous Joints on Aircell Pipe Insulation	100	SF	Pipe Chases and Within Walls		TSI	Yes	None	0		YES	X NO

2013 - Fall: No Change	
Comments:	

2014- Spring: No Change	
Comments:	

2014 - Fall: No Change	
Comments:	

2015- Spring: No Change	
Comments:	

2015 - Fall: No Change	
Comments:no change	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
С	Cardboard Pipe Insulation	100	SF	Pipe Chases and Within Walls		TSI	Yes	None	0		YES	X NO

2013 - Fall: No Change	
Comments:	

2014 - Fall: No Change	
Comments:	

2015- Spring: No Change Comments:

2015 - Fall: No Change	
Comments:no change	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment (	ategory
D	Cementitous Joint Insulation off Cardboard	100	SF	Pipe Chases and Within Walls		TSI	Yes	None	0		YES X	٩O

2013 - Fall: No Change	
Comments:	

2014- Spring: No Change	
Comments:	

2014 - Fall: No Change	
Comments:	

Comments:no change	2015 - Fall: No Change	
	Comments:no change	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
E	Powder Pipe Insulation	100	SF	Pipe Chases and Within Walls		TSI	Yes	None	0		YES	X NO

2013 - Fall: No Change	
Comments:	

2014 - Fall: No Change
Comments:

2014- Spring: No Change	
Comments:	

2015 - Fall: No Change	
Comments:no change	

Н	HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessme	ent Category
F	=	Powder Elbows	100	SF	Pipe Chases and Within Walls		TSI	Yes	None	0		YES	X NO

O service sta	all: No Change	2013 - Fall: No Change
Comments:	its:	Comments:

2014- Spring: No Change	
Comments:	

2014 - Fall: No Change Comments:

2015- Spring: No Change	
Comments:	

2015 - Fall: No Change	
Comments:no change	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
G	Boiler Gasket	10	LF	Boiler Room		Miscellaneous	No	None	0		YES	XNO

2013 - Fall: No Change	
Comments:	

2014- Spring: No Change	
Comments:	

2014 - Fall: No Change	
Comments:	
	_

2015 - Fall: No Change	
Comments:no change	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category
Н	Boiler Packing	100	SF	Boiler Room		TSI	Yes	None	0		YES	X NO

-	
Comments:	

2014- Spring: No Change	
Comments:	

2014 - Fall: No Change	
Comments:	

2015- Spring: No Change	
Comments:	

2015 - Fall: No Change	
Comments:no change	

HA N	lo	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	
Ι		Tank Insulation - Abated 1994			Boiler Room		Miscellaneous					YES	X NO

2013 - Fall: No Change	
Comments:	

2014- Spring: No Change	
Comments:	

2014 - Fall: No Change	
Comments:	

2015- Spring: No Change	
Comments:	

2015 - Fall: No Change	
Comments:no change	

HA N	lo	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	
J		Kiln					Miscellaneous	No	None			X YES	NO

### 2013 - Fall: Abated Comments:removed from building in spring 2011

2014 - Fall: Abated Comments:ABATED SPRIMG 2011

2014- Spring: Abated Comments:removed from building in the spring of 2011

# 2015- Spring: Abated

Comments:removed from building in the spring of 2011

2015 - Fall: Abated

Comments:removed in summer 2011

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	
К	Aircell Pipe Insulation	100	SF	Pipe Chases and Within Walls		TSI	No	None	0		YES	X NO

2013 - Fall: No Change	
Comments:	

2014- Spring: No Change
Comments:

2014 - Fall: No Change	
Comments:	

2015 - Fall: No Change	
Comments:no change	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessme	nt Category
L	Cementitous Joint Insulation on Aircell	100	SF	Pipe Chases and Within Walls		TSI	Yes	None	0		YES	X NO

Comments:	

2014- Spring: No Change	
Comments:	

2014 - Fall: No Change	
Comments:	

2015- Spring: No Change	
Comments:	

2015 - Fall: No Change	
Comments:no change	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category
М	Cardboard Pipe Insulation	100	LF	Pipe Chases and Within Walls		TSI	No	None	0		YES	X NO

2013 - Fall: No Change	
Comments:	

2014- Spring: No Change
Comments:

2014 - Fall: No Change	
Comments:	

2015 - Fall: No Change	
Comments:no change	

HA No	)	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category
Ν		Cementitous Pipe Joint Insulation off Cardboard	100	SF	Pipe Chases and Within Walls		TSI	Yes	None	0		YES	XNO

2013 - Fall: No Change	
Comments:	

2014 - Fall: No Change	
Comments:	

2014- Spring: No Change	
Comments:	

2015- Spring: No Change	
Comments:	

2015 - Fall: No Change	
Comments:no change	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
0	Powder Pipe Insulation	100	LF	Pipe Chases and Within Walls		TSI	Yes	None	0		YES	X NO

2013 - Fall: No Change	
Comments:	

2014 - Fall: No Change	
Comments:	

2014- Spring: No Change	
Comments:	

2015 - Fall: No Change	
Comments:no change	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category
Р	Powder Elbows	100	SF	Pipe Chases and Within Walls		TSI	Yes	None	0		YES	X NO

Comments:	

2014- Spring: No Change	
Comments:	

2014 - Fall: No Change	
Comments:	

2015- Spring: No Change	
Comments:	

2015 - Fall: No Change	
Comments:no change	

ALL LEA Responsibilities, for this school, will be met.

Sym & Criville

Lynn A.Crivello

# NOTICE TO PARENTS AND STAFF REGARDING THE ASBESTOS MANAGEMENT PLAN NOTIFICATION

School:	STEM Magnet Academy
Date:	10/20/2015

This is to notify you in accordance with Illinois and Federal Asbestos Regulations, that a copy of the Asbestos Management Plan is available at each school during school hours by appointment. Requests to review the Asbestos Management Plan must be made at least 24 hours in advance.

Also please be advised that CPS conducts asbestos inspections of all Schools every three years. The last inspection was completed in 2013.

Asbestos surveillances are conducted every six months.

# CHECK ONE

X A copy of this notice was printed in the school's newsletter and sent home with each child



Other.

# A COPY OF THIS NOTICE MUST BE PLACED IN THE SCHOOL'S ASBESTOS MANAGEMENT PLAN.