Chicago Public Schools

6 Month Asbestos Surveillance 2015 - Fall

J W Von Goethe School 23341 3560 School: **Oracle Unit: Building ID:** Address: 2236 N. Rockwell Avenue Region: 02 Mail Room: 35 Asbestos Surveyor: **CHECK HERE IF NO CHANGE TO ASBESTOS** Survey Date: 11/9/2015 Email Address: A copy of the 2013/2014 notice to parents and staff regarding the asbestos management plan notifications was distributed via: X Notice printed in school's newsletter Each child's backpack Notice printed in school's calendar Other HA No Material Description Material Material Location Asbestos Friable Damage Change in Assessment Category Material Damage Damage Quantity Units Type Category Quantity Type Throughout - 1885 YES 01 SF X NO Hard Coat Plaster 60000 Miscellaneous None Building 2013 - Fall: No Change Comments: 2014- Spring: No Change Comments: 2014 - Fall: No Change Comments: 2015- Spring: No Change Comments: 2015 - Fall: No Change Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	sessment Category
02	2'x4' Ceiling Tile	500	SF	Room 106 - 1885 Building		Miscellaneous	Yes	Dist	8		YES	X NO
2013 - Fall: N	No Change											
Comments:												
2014- Spring	: No Change											
Comments:	_											
2014 - Fall: N	No Change											
Comments:	<u> </u>											
2015- Spring	: No Change											
Comments:	•											
2015 - Fall: N	No Change											
Comments:												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category
03	12"x12" Brown VFT	16700	SF	Throughout - 1885 Building		Miscellaneous	No	None	0		YES	X NO

2013 - Fall: No Change	
Comments:	

2014- Spring: Damaged
Comments:Tiles throughout classrooms broken and mastic is open and also in bad condition

2014 - Fall: No Change Comments:

2015- Spring: Damaged
Comments:BROKEN TILES THROUGHOUT VARIOUS ROOMS

2015 - Fall: No Change Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
04	12"x12" Beige w/ Brown Spots VFT	2500	SF	Rooms 106 & 206 - 1st , 2nd floor corridors. 1885 Building		Miscellaneous	No	None			YES	X NO
2013 - Fall: N	lo Change				1							
Comments:	io Change				_							
Comments:					_							
2014- Spring:	: No Change											
Comments:												
2014 - Fall: N	lo Chango				7							
Comments:	io Change											
Comments.												
2015- Spring:	: No Change											
Comments:												
0045 5 11 1	. 0				- 1							
2015 - Fall: N	lo Change				_							
Comments.												
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Ass	essment Category
	·	Quantity	Units		Type	Category		Type	Quantity	Units		
05	12"x12" White VFT	1500	SF	First and Second Floor Hallways- 1885 Building		Miscellaneous	No	None			YES	X NO
2013 - Fall: N	lo Change]							
Comments:	io Griarigo				1							
2014- Spring:	: No Change											
Comments:												
2014 - Fall: N	lo Change				1							
Comments:	io Change				1							
					<u></u>							
2015- Spring:	: No Change											
Comments:												
0045 5-11 1	la Ohanana				7							
2015 - Fall: N	io Cnange											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asso	essment Category
06	12"x12" Brown w/ White Spots VFT	1500	SF	First and Second Floor Hallways- 1885 Building		Miscellaneous	No	None			YES	X NO
2013 - Fal	I: No Change				7							
Comments	3:											
2014- Spri	ing: No Change				7							
Comments												
2014 - Fal	I: No Change				7							
Comments	Ţ											
2015- Spri	ing: No Change				7							
Comments	·											
2015 - Fal	I: No Change				7							
Comments												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asso	essment Category
			1	Rooms 001, 002, 003,		1		1				

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category
07	Air Cell Pipe Insulation	180	LF	Rooms 001, 002, 003, 004, Boiler Room, Coal Room- 1885 Building		TSI	Yes	Loc	1		YES	X NO

2013 - Fall: No Change	
Comments:	_

2014- Spring: No Change Comments:

2014 - Fall: Damaged Comments:Damaged pipe insulation to piping in boiler room, minimal 3ft

2015- Spring: Damaged Comments:Loose insulation

2015 - Fall: No Change Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
08	MJP E/F/V on Aircell Pipe Insulation	35	LF	Rooms 001, 002, 003, 004, Boiler Room, Coal Room, Basement corridor's- 1885 Building		TSI	Yes	Dist	3		YES	X NO
2013 - Fall: N	lo Change]							

2013 I dil. No Ollarigo
Comments:
2014- Spring: No Change
Comments:
2014 - Fall: No Change
Comments:
2015- Spring: No Change
Comments:
2015 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	sessment Category
09	Cardboard Pipe Insulation	320	LF	Coal Room, Room 003, Room 004 and 004 Storage Room, Basement Corridor, South Fan Room- 1885 Building		TSI	Yes	None	0		YES	X NO
2013 - Fall	: No Change]							
Comments	S:											
2014- Spri	ng: No Change											
Comments	5:											

2014 - Fall: No Change	
Comments:	

2015- Spring: No Change	
Comments:	

2015 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	essment Category
10	MJP E/F/V on Cardboard Pipe Insulation	21	LF	Coal Room, Room 003, Room 004 and 004 Storage Room, Basement Corridor, South Fan Room- 1885 Building		TSI	Yes	Loc	1		YES	X NO

2013 - Fall: No Change	
Comments:	

2014- Spring: No Change	
Comments:	

2014 - Fall: Damaged
Comments: Deteriorating around leak and the unions throughout

2015- Spring: No Change	
Comments:	

2015 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
11	MJP E/F/V on Fiberglass Pipe Insulation	124	LF	Basement Girls Toilet, Rooms 001, 003, 004, 104 wardrobe, Basement Corridor, Pump Room, N. Fan Room- 1885 Building		TSI	Yes	Loc	17		YES	X NO
2013 - Fall:	No Change				1							
Comments]							
2014- Sprin	ng: No Change]							
Comments]							
2014 - Fall:	No Change				1							
Comments]							
2015- Sprir	ng: No Change				1							
Comments]							
2015 - Fall:	No Change				1							
Comments												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category
12	Aircell Duct Insulation	480	SF	Basement Corridor- 1885 Building		TSI	Yes	Dist	2		YES	X NO

2013 - Fall: No Change	
Comments:	

2014- Spring: No Change	
Comments:	

2014 - Fall: Deteriorated
Comments:crumbling throughout areas of duct work

2015- Spring: Damaged	
Comments:Loose and damaged pipe insulation	

2015 - Fall: Deteriorated
Comments:DUCT insulation coming loose

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	essment Category
13	12"x12" Brown VFT Mastic	18450	SF	Throughout - 1885 Building		Miscellaneous	No	None	0		YES	X NO
2013 - Fall: N	lo Change				7							
Comments:	ge											
2014- Spring	· Damaged				7							
	lastic throughout is in I	bad condit	ion , popp	oing up and								
2014 - Fall: N	lo Change				7							
Comments:	io onango											
2015- Spring	· Damaged				_]							
	lastic visible from brok	en tiles th	roughout	rooms	-							
					- -							
2015 - Fall: N	lo Change				-							
Comments.												
		_						_				
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	essment Category
14	12"x12" Beige w/ Brown Spots VFT Mastic	1350	SF	Rooms 106 & 206- 1885 Building		Miscellaneous	No	None	0		YES	X NO
2013 - Fall: N	lo Change				7							
Comments:	Ŭ											
2014- Spring	· No Change				7							
Comments:												
2014 - Fall: N	lo Chango				- 7							
Comments:	io Change											
	N. Observe				- -							
2015- Spring Comments:	: No Change				-							
					J ¬							
2015 - Fall: N	lo Change				4							
Comments:												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
15	12"x12" White VFT Mastic	2500	SF	First and Second Floor Hallways- 1885 Building		Miscellaneous	No	None	0		YES	X NO
2013 - Fall: N	lo Change											
Comments:												
2014- Spring	: No Change											
Comments:												
2014 - Fall: N	lo Change											
Comments:	-											
2015- Spring	: No Change											
Comments:												
2015 - Fall: F	Repaired				1							
Comments:R	eplace broken tiles											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
16	12" x12" Brown w/ White Spots VFT Mastic	2500	SF	First and Second Floor Corridors- 1885 Building		Miscellaneous	No	None	0		YES	X NO
2013 - Fall: N	lo Change				1							
Comments:	· ·											
2014- Spring	: No Change				1							
Comments:	- - - - - - - - - - -											

2014 - Fall: No Change

2015- Spring: No Change

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	essment Category
17	9" x 9" Brown w/ Streaks VFT	180	SF	Room 308 Wardrobe- 1885 Building		Miscellaneous	No	None	0		YES	X NO
2013 - Fall: N	No Change											
Comments:												
2014- Spring Comments:	: No Change											
					_							
2014 - Fall: N Comments:	No Change											
2015- Spring	: No Change											
Comments:												
2015 - Fall: N	No Change											
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	essment Category
18	9" x 9" Brown w/ Streaks VFT Mastic	180	SF	Room 308 Wardrobe- 1885 Building		Miscellaneous	No	None	0		YES	X NO
2013 - Fall: N	No Change				\exists							
Comments:	Ü											
2014- Spring	: No Change											
Comments:												
2014 - Fall: N	No Change											
Comments:												
2015- Spring	: No Change				7							

Comments:

2015 - Fall: No Change

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
19	12" x 12" White w/ Brown Specks VFT (NOT OBSERVED)	0	SF	Room # 500 through # 503 - 1987 Annex		Miscellaneous	No	None			YES	X NO
2013 - Fall:	No Change											
Comments:												
2014- Sprin	g: No Change											
Comments:												
2014 - Fall: Comments:	No Change											
	N. Ol				- ¬							
Comments:	g: No Change											
2015 - Fall:	No Change											
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
20	12" x 12" White w/ Brown Specks VFT Mastic (NOT OBSERVED)			Room # 500 through # 503 - 1987 Annex		Miscellaneous	No	None			YES	X NO
2013 - Fall:	No Change				7							
Comments:												
2014- Sprin	g: No Change				7							
Comments:												
2014 - Fall:	No Change				7							
Comments:	<u> </u>											
2015- Sprin	g: No Change				٦							
Comments:												
2015 Fall:	No Chango				7							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	essment Category
21	12" x 12" Brown w/ Wht. & Black Specks VFT(NOT OBSERVED)			Throughout - 1987 Annex		Miscellaneous	No	None			YES	X NO
2013 - Fall: N	No Change											
Comments:	Ü											
2014- Spring	g: No Change				1							
Comments:	,go											
2014 - Fall: N	No Chango				- 1							
Comments:	No Change											
					<u>-</u> -							
2015 - Fall: Note:	No Change											
Comments.					_							
2015- Spring	g: No Change											
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	essment Category
22	12" x 12" Brown w/ Wht. & Black Specks VFT Mastic (ABATED)		SF	Throughout (See Hatching Maps) - 1987 Annex							YES	X NO
2013 - Fall: N	No Change											
Comments:												
2014- Spring	g: No Change				7							
Comments:	g. 140 Orlange											
					7							
2014 - Fall: Note:	No Change											
Comments.					_							
2015- Spring	g: No Change											
Comments:												
2015 - Fall: N	No Change											
Comments:												

IIA NI-	I Material December	I Maradal	I Martania I	I Maradal Landon	A -11	I Martarial	L marion.	I B	I D	I D	Observa in Ass	
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	essment Category
	12" x 12" Beige w/ Brown	,		Room 400, AP Room -	71 -	,		71 -	1		-	
23	Specks VFT			1987 Annex							YES	X NO
2012 Fall N	la Changa	•						•	•			
2013 - Fall: N Comments:	io Change				-							
Comments.												
2014- Spring	: No Change											
Comments:												
2014 - Fall: N	lo Change				٦							
Comments:	io Change				-							
Commonto.					_							
2015- Spring	: No Change											
Comments:												
2015 - Fall: N	lo Change				٦							
Comments:	io Oriange											
					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos	Material	Friable	Damage	Damage Quantity	Damage Units	Change in Ass	essment Category
	12" x 12" Beige w/ Brown	Quantity	Ullits		Туре	Category		Туре	Quantity	Units		
24	Specks VFT Mastic (NOT OBSERVED)			Room 400, AP Room - 1987 Annex							YES	X NO
	OBSERVED)			1007 Tuniox								
2013 - Fall: N	lo Change											
Comments:												
2014- Spring	· No Change				7							
Comments:	. Tto Change				-							
2014 - Fall: N	lo Change											
Comments:												
2015- Spring	: No Change				7							
Comments:	.											
2015 5					_ ¬							
2015 - Fall: N	lo Change				-							
Comments:					_							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asso	essment Category
25	12" x 12" White w/ Blue Specks VFT (NOT OBSERVED)			Room # 401 - 1987 Annex							YES	X NO
	: No Change											
Comments	:											
2014- Sprii	ng: No Change											
Comments												
2014 - Fall	: No Change											
Comments												
2015- Sprii	ng: No Change											
Comments												
Comments	: No Change											
Comments	•											
		T	T	Lancata	1	T	1	T	T			
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asso	essment Category
26	12" x 12" White w/ Blue Specks VFT Mastic (NOT OBSERVED)			Room # 401 - 1987 Annex							YES	X NO
2013 - Fall	: No Change											
Comments												
2014- Sprii	ng: No Change											
Comments												
2014 Fall	. No Change											
Comments	: No Change :											
2015- Sprii Comments	ng: No Change											
Comments	•											
	: No Change											
Comments												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	essment Category
27	1' x 1' White w/ Grooves Ceiling Tile	20000	SF	Throughout - 1987 Annex		Miscellaneous	Yes	None	0		YES	X NO
2013 - Fall: N	lo Change]							
Comments:												
2014- Spring:	: Damaged]							
	iles fell do to univent l	eaks above	9]							
2014 - Fall: N	lo Change]							
Comments:	•]							
2015- Spring:	: No Change]							
Comments:	<u> </u>											
2015 - Fall: R	Repaired]							
	epaired tiles that were	water dar	naged]							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	essment Category
28	1' x 1' White w/ Grooves Ceiling Tile Mastic	20000	SF	Throughout - 1987 Annex		Miscellaneous	Yes	None	0		YES	X NO

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
28	1' x 1' White w/ Grooves Ceiling Tile Mastic	20000	SF	Throughout - 1987 Annex		Miscellaneous	Yes	None	0		YES	X NO

2013 - Fall: No Change Comments:

2014- Spring: Damaged Comments:Tiles have fell do to leaking above

2014 - Fall: No Change Comments:

2015- Spring: No Change Comments:

2015 - Fall: Repaired Comments:Replaced fallen tiles

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
29	1' x 1' White w/ Dots and Grooves Ceiling Tile	1200	SF	Room 400 - 1987 Annex		Miscellaneous	Yes	None	0		YES	X NO
2013 - Fall: N	lo Change]							
Comments:												
2014- Spring	: No Change											
Comments:	•											
2014 - Fall: N	lo Change											
Comments:	go											
2015- Spring	· No Change				7							
Comments:	. 140 Change											
2015 Falls N	la Changa				- 7							
2015 - Fall: N	io Change											
Comments.					_							
		_			_		_	_				
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
30	1' x 1' White w/ Dots & Grooves Clng. Tile Mastic	1200	PERCEN T	Room 400 - 1987 Annex		Miscellaneous	Yes	None	0		YES	X NO
2013 - Fall: N	lo Change				7							
Comments:	J											
2014- Spring	· No Change				1							
Comments:	. No Change											
					⊒ ¬							
2014 - Fall: N Comments:	lo Change											
					<u></u>							
2015- Spring	: No Change											
Comments:												

2015 - Fall: No Change

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in As	sessment Category
31	Vinyl Baseboard	3500	LF	Throughout - 1987 Annex		Miscellaneous	No	None	0		YES	X NO
2013 - Fall: N	No Change											
Comments:]							
2014- Spring	: No Change				1							
Comments:	,go											
2044 Falls N	Ja Changa				- 1							
2014 - Fall: Note:	No Change				1							
Comments.					<u> </u> _							
2015- Spring	: No Change											
Comments:]							
2015 - Fall: N	No Change				7							
Comments:	3											
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in As	sessment Category
TIANO	Waterial Description	Quantity	Units	Waterial Education	Type	Category	Thabic	Type	Quantity	Units	Onange in As	ocosment Oategory
32	Vinyl Baseboard Mastic	3500	LF	Throughout - 1987 Annex		Miscellaneous	No	None	0		YES	X NO
2013 - Fall: N	No Change]							
Comments:	Ţ											
2014 Spring	: No Change				7							
Comments:	i. No Change											
]							
2014 - Fall: N	No Change											
Comments:]							
2015- Spring	: No Change				1							
Comments:]							
	No Change]							
Comments: 2015 - Fall: N Comments:	No Change]							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	sessment Category
33	Drywall	50000	SF	Throughout - 1987 Annex		Miscellaneous	No	None	0		YES	X NO
2013 - Fall: N	lo Change											
Comments:												
2014- Spring:	: Damaged											
	rywall is cracking and	splitting th	roughout	do to settling of								
2014 - Fall: N	lo Change											
Comments:	J											
2015- Spring:	: No Change											
Comments:	ge											
2015 - Fall: D)amaged											
	allway has cracks forn	ning down	drywall									
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	sessment Category
34	Drywall Joint Compound	5000	LF	Throughout - 1987 Annex		Miscellaneous	No	None	0		YES	X NO
2013 - Fall: N	lo Change											
Comments:	Ţ.											
2014- Spring:	: Damaged											
	rywall is splitting in are	as throug	hout									
2014 - Fall: N	lo Change											
Comments:												
2015- Spring:	: No Change											
Comments:												
2015 - Fall: N	lo Change											
Comments:												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	essment Category
35	12 x 12 White with Gray and Brown Specs Floor Tile		SF	LunchroomREMOVED		Miscellaneous	No	None			YES	X NO
	: No Change											
Comments	:											
2014- Sprii	ng: No Change											
Comments												
	: No Change]							
Comments	:											
2015- Sprii	ng: No Change											
Comments	•											
2015 - Fall	: No Change											
Comments	•											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	essment Category
36	12 x 12 White with Gray and Brown Specs Floor Tile		SF	LunchroomREMOVED		Miscellaneous	No	None	0		YES	X NO
2013 - Fall	: No Change											
Comments												
2014- Sprii	ng: No Change											
Comments					_							
	: No Change											
Comments	•											
2015- Sprii	ng: No Change											
Comments												
2015 - Fall	No Change				1							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	essment Category
37	12x12 White w/ Tan Specs VFT	14000	SF	1st fl classrooms (400 thru 405) + staff rooms #06-#09; 2nd fl classrooms(500 thru 507)1987 annex bldg		Miscellaneous	No	None	0		YES	X NO
2013 - Fal	I: No Change				٦							
Comments	U											
2014- Spri	ng: No Change											
Comments	S:											
2014 - Fal	I: No Change											
Comments	S:				1							

2015- Spring: No Change

2015 - Fall: No Change

Comments:

Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
37M	12x12 White w/ tan specs VFT Mastic	14000	SF	1st fl classrooms (400 thru 405) + staff rooms #06-#09; 2nd fl classrooms(500 thru 507)1987 annex bldg		Miscellaneous	No	None	0		YES X NO
2042 Falls	No Change				7						
2013 - Fall:					4						
Comments:											
2014- Sprin	g: No Change				7						
Comments:					7						
2014 - Fall:	No Change										
Comments:											
0045 0	an Na Obanas				7						
	g: No Change				4						
Comments:											
2015 - Fall:	No Change				7						
Comments:					1						
					-						

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category
38	12x12 Green with Gray + Dark Green specs VFT	7800	SF	1st fl corridor (4000 SF); 2nd fl corridor (3800 SF)1987 annex bldg		Miscellaneous	No	None	0		YES	X NO

2013 - Fall: No Change	
Comments:	

2014- Spring: Damaged
Comments:Tiles and underlayment coming up, building is settling

2014 - Fall: Damaged
Comments:FLOOR SETTLING, TILES CRACKING

2015- Spring: No Change Comments:

2015 - Fall: No Change Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
38M	12x12 Green w/ gray + Dark green specs VFT Mastic	7800	SF	1st fl corridor (4000 SF); 2nd fl corridor (3800 SF)		Miscellaneous	No	None	0		YES	X NO
		•		•		•		•	•	•		
2013 - Fall: N	lo Change											
Comments:												
					1							
2014- Spring:	Damaged											
	les and underlaymen	t coming up	o, coorrido	or is uneven								
2014 - Fall: D	amaged											
Comments:Fl	LOOR SETTLING, TI	LES CRAC	KING									
2015- Spring:	No Change]							
Comments:]							
2015 - Fall: R	epaired]							
	eplace broken tile											
	•				•							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category
39	White Spray-On Under sink coating	3	SF	under sink in cabinet room #4021987 annex		Surface	No	None	0		YES	X NO

2013 - Fall: No Change	
_	
Comments:	

2014- Spring: No Change	
Comments:	

2014 - Fall: No Change	
Comments:	

2015- Spring: No Change	
Comments:	

2015 - Fall: No Change	
Comments:	

ALL LEA Responsibilities, for this school, will be met.

Lynn A.Crivello

Sym & Crwill

NOTICE TO PARENTS AND STAFF REGARDING THE ASBESTOS MANAGEMENT PLAN NOTIFICATION

Date:
the Asbestos Management Plan is available at each school during school hours by appointment.
the Asbestos Management Plan is available at each school during school hours by appointment.
Trequests to review the rispestes management i lan must be made at least 24 hours in advance.
Also please be advised that CPS conducts asbestos inspections of all Schools every three years The last inspection was completed in 2013. Asbestos surveillances are conducted every six months.
CHECK ONE
A copy of this notice was sent home in each child's backpack.
X A copy of this notice was printed in the school's newsletter and sent home with each child
A copy of this notice was printed in the school's calendar and sent home with each child
Other.
A COPY OF THIS NOTICE MUST BE PLACED IN THE

VFT = Vinyl Floor Tile
Oracle Unit: 23341

SCHOOL'S ASBESTOS MANAGEMENT PLAN.