Chicago Public Schools

6 Month Asbestos Surveillance

2015 - Fall

24191

Oracle Unit:

	Address: 615 W. I	Kemper Place					Re	gion:	02		Mail Ro	oom: 33	
	K HERE IF NO CH	IANGE TO	O ASBE	STOS	Asbestos Sur Survey Date: Email Addres	-	10/19/201	5					
	A copy of the 2013/2	014 notice to	parents an	d staff regar	ding the asbesto	s managen	nent plan not	ifications v	was distribute	d via:			
	Each child's backp	back	Notice	orinted in sc	chool's newslette	er	Notice prin	ited in sch	ool's calendai	X Oti	her website	e	
HA No	Material Description	Material Quantity	Material Units	Material Lo	ocation Asl Typ		Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	sessment Category
03	Carpet Mastic	500	SF	Room 100		r	Miscellaneous	No	None	0		YES	X NO
Comments 2014- Spri Comments 2014 - Fall Comments 2015- Spri Comments	ng: No Change 3: I: No Change 5: ng: No Change 3:												
2015 - Fall Comments	l: No Change s:												

Abraham Lincoln Elementary School

School:

Building ID: 4480

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category
04	12"x12" White VFT - NOT OBSERVED	6500	SF	Throughout - 1894 Bldg		Miscellaneous		None	0		YES	XNO

2013 - Fall: No Change	
Comments:	

2014- Spring: No Change	
Comments:	

2015- Spring: No Change Comments:

2015 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category
05	9"x9" Beige VFT - NOT OBSERVED	250	SF	Engineer's Office, Kitchen Storage - 1894 Bldg		Miscellaneous	No				YES	X NO

Comments:	2013 - Fall: No Change	
	Comments:	

2014- Spring: No Change	
Comments:	

2015- Spring: No Change	
Comments:	

2015 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category
06	12"x12" White VFT Mastic - NOT OBSERVED	50	SF	Throughout - 1894 Bldg (See Hatching Maps)		Miscellaneous	No				YES	XNO

2013 - Fall: No Change	
Comments:	

2014- Spring: No Change
Comments:

2014 - Fall: No Change	
Comments:	

2015- Spring: No Change	
Comments:	

2015 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessm	ent Category
07	9"x9" Beige VFT Mastic - NOT OBSERVED	250	SF	Engineer's Office, Kitchen Storage - 1894 Bldg		Miscellaneous	No				YES	X NO

2013 - Fall: No Change	
Comments:	

2014- Spring: No Change	
Comments:	

2014 - Fall: No Change	
Comments:	

2015- Spring: No Change	
Comments:	

2015 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category
08	9"x9" Black VFT - NOT OBSERVED	250	SF	Engineers Office, Kitchen Storage - 1894 Bldg		Miscellaneous	No				YES	XNO

2013 - Fall: No Change	
Comments:	

2014- Spring: No Change
Comments:

2014 - Fall: No Change	
Comments:	

2015 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category
09	9"x9" Black VFT Mastic - NOT OBSERVED	250	SF	Engineers Office, Kitchen Storage - 1894 Bldg		Miscellaneous	No				YES	X NO

Comments:	2013 - Fall: No Change	
Comments.	Comments:	

2014- Spring: No Change	
Comments:	

2014 - Fall: No Change	
Comments:	

2015- Spring: No Change	
Comments:	

2015 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category
10	12"x12" Off White VFT	4000	SF	1st, 2nd & 3rd Floor Corridors, 303 - 1939 Bldg		Miscellaneous	No	None	0		YES	XNO

2013 - Fall: No Change	
Comments:	

2014- Spring: No Change	
Comments:	

2014 - Fall: No Change	
Comments:	

2015 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	
11	12"x12" Off White VFT Mastic	4000	SF	1st, 2nd & 3rd Floor Corridors, Rm 303 - 1939 Bldg		Miscellaneous	No	None	0		YES	X NO

2013 - Fall: No Change	
Comments:	

2014- Spring: No Change Comments:

2014 - Fall: No Change	
Comments:	

2015 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	
12	Hard Coat Plaster	38000	SF	Throughout - 1939 Bldg		Miscellaneous	No	None	0		YES	X NO

2013 - Fall: No Change	
Comments:	

2014- Spring: No Change	
Comments:	

2014 - Fall: No Change	
Comments:	

2015 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	
13	12"x12" White w/ Tan Specks VFT	1900	SF	Basement Corridor, Room 007 - 1894 Bldg		Miscellaneous	No	None	0		YES	X NO

2013 - Fall: No Change	
Comments:	

2014- Spring: No Change	
Comments:	

2014 - Fall: No Change	
Comments:	

2015- Spring: No Change	
Comments:	

2015 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category
14	12"x12" White w/ Tan Specks Mastic	700	SF	Basement Corridor, Room 007 - 1894 Bldg		Miscellaneous	No	None	0		YES	XNO

2013 - Fall: No Change	
Comments:	

2014- Spring: No Change
Comments:

2014 - Fall: No Change	
Comments:	

2015 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessn	nent Category
15	12" x 12" CT w/grooves	5000	SF	Corridors in Bldg 1894		Miscellaneous	No	None	0		YES	X NO

2013 - Fall: No Change	
Comments:	

2014- Spring: No Change	
Comments:	

2014 - Fall: No Change	
Comments:	

Comments:	2015- Spring: No Change	
	Comments:	

2015 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
16	2x4 Ceiling Tiles with Holes	350	SF	Bldg 1894 - Basement		Miscellaneous	Yes	None	0		YES	XNO

2013 - Fall: No Change	
Comments:	

2014- Spring: No Change	
Comments:	

2014 - Fall: No Change	
Comments:	

2015 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category
17	Terrazo	8800	SF	Link between bldgs 1894 and 1939 stairwells		Miscellaneous	No	None	0		YES	X NO

2013 - Fall: No Change	
Comments:	

2014- Spring: No Change	
Comments:	

2014 - Fall: No Change	
Comments:	

2015- Spring: No Change	
Comments:	

2015 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
18	Ceramic Tile Grout	2400	SF	Restrooms Main Office		Surface	Yes	None	0		YES	XNO

2013 - Fall: No Change	
Comments:	

2014- Spring: No Change	
Comments:	

2014 - Fall: No Change	
Comments:	

	2015 - Fall: No Change
Comments:	Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessmen	t Category
19	Ceramic Tile Adhesive	2400	SF	Restrooms and Main Office		Miscellaneous	No	None	0		YES	NO

2013 - Fall: No Change	
Comments:	

2014- Spring: No Change	
Comments:	

2014 - Fall: No Change	
Comments:	

Comments:	2015- Spring: No Change	
	Comments:	

Comments:	2015 - Fall: No Change	
	Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category
20	12"x12" Cream Colored Floor Tile (Not Observed)	120	SF	Engineer's Office		Miscellaneous	No	None	0		YES	XNO

2013 - Fall: No Change	
Comments:	

2014- Spring: No Change	
Comments:	

2014 - Fall: No Change	
Comments:	

2015- Spring: No Change	
Comments:	

Common and a	2015 - Fall: No Change
Comments:	Comments:

ł	HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category
2	21	12"x12" Cream Colored Floor Tile Mastic	120	SF	Engineer's Office		Miscellaneous	No	None	0		YES	XNO

2013 - Fall: No Change	
Comments:	

2014- Spring: No Change	
Comments:	

2014 - Fall: No Change	
Comments:	

2015- Spring: No Change	
Comments:	

2015 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category
22	12"x12" Tan Floor Tile	60	SF	Engineer's Office		Miscellaneous	No	None	0		YES	XNO

2013 - Fall: No Change	
Comments:	

2014- Spring: No Change	
Comments:	

2014 - Fall: No Change	
Comments:	

Comments:	2015 - Fall: No Change
Comments.	Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Cate
23	12"x12" Tan Floor Tile Mastic	60	SF	Engineer's Office		Miscellaneous	No	None	0		YES X NO

Commonts:	2013 - Fall: No Change
comments.	Comments:

2014- Spring: No Change	
Comments:	

2014 - Fall: No Change	
Comments:	

2015- Spring: No Change	
Comments:	

2015 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	
24	12 x 12 Off White VFT	5400	SF	3rd Floor Corridor, Rm 309, 2nd Floor Corridor, Rm 209, 1st Floor Corridor, Room 012- 1894 Bldg		Miscellaneous	No	None	0		YES	XNO

2013 - Fall: No Change	
Comments:	

2014- Spring: No Change	
Comments:	

2014 - Fall: No Change
Comments:

2015 - Fall: No Change	
Comments:	

2015- Spring: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	
25	12 x 12 Off White VFT Mastic	5400	SF	3rd Floor Corridor, Rm 309, 2nd Floor Corridor, Rm 209, 1st Floor Corridor, Room 012- 1894 Bldg		Miscellaneous	No	None	0		YES	XNO

2013 - Fall: No Change	
Comments:	

2014- Spring: No Change
Comments:

2015 - Fall: No Change Comments:

2015- Spring: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	
26	12 x 12 CT with Grooves	6900	SF	3rd Flr Corridor, 2nd Flr Corridor, 1st Flr Corridor, Walls in Assembly Hall		Miscellaneous	Yes	None	0)

2013 - Fall: No Change	
Comments:	

2014- Spring: No Change Comments:

2014 - Fall: No Change	
Comments:	

2015- Spring: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
27	12 x 12 Beige Speckled VFT	2000	SF	New Lunchroom (Old Teachers Lounge & Lunchroom Combined, Room 109 & 118) Supply Room - 1894 Bldg		Miscellaneous	No	None	0		YES	XNO

2013 - Fall: No Change	
Comments:	

2014- Spring: No Change	
Comments:	

Commonte	- Fall: No Change	2014 - Fall: No Change
Comments.	ments:	Comments:

2015 - Fall: No Change	
Comments:	
	_

2015- Spring: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
28	12 x 12 Beige Speckled Mastic	2000	SF	New Lunchroom (Old Teachers Lounge & Lunchroom Combined, Room 109 & 118) Supply Room - 1894 Blda		Miscellaneous	No	None	0		YES	XNO

2013 - Fall: No Change	
Comments:	

2014- Spring: No Change	
Comments:	

Comments:	2015 - Fall: No Change	
	Comments:	

2015- Spring: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category
29	Carpet mastic (Carpet Tile Gray with Stripe Pattern)	1800	SF	Room 108 & 110		Miscellaneous	No	None	0		YES	XNO

2013 - Fall: No Change	
Comments:	

2014- Spring: No Change Comments:

2014 - Fall: No Change	
Comments:	

2015- Spring: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
В	Cardboard Pipe Insulation	235	LF	Pump, Sprinkler & Boiler Rooms, Bsmt Storage Room Office & Toilet, Mech. Rm South of Fan Room - 1894		TSI	Yes	None	0		YES	XNO

2013 - Fall: No Change	
Comments:	

2014 - Fall: No Change
Comments:

2015- Spring: No Change Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
с	Aircell Pipe Insulation	320	LF	Bsmt Boys Toilet, Storage Office Toilet, Mech Rm South Of Fan Rm, Eng Off, Pump & Boiler Rms - 1894		TSI	Yes	None	0		YES	XNO

2013 - Fall: No Change	
Comments:	

2014- Spring: No Change
Comments:

2014 - Fall: No Change

Comments:

2015- Spring: No Change Comments:

2015 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessm	nent Category
D	Mag Block Pipe Insulation	200	LF	Mech Room South of Fan Room, Pump Room, Janitor's closet on 2nd floor - 1894 Bldg		TSI	Yes	None	0		YES	XNO

2013 - Fall: No Change	
Comments:	

2014- Spring: No Change	
Comments:	

2014 - Fall: No Change Comments:

2015- Spring: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category
E	MJP E/F/V on Mag Block Pipe Insulation	8	LF	Mech Room South of Fan Room, Pump Room - 1894 Bldg		TSI	Yes	None	0		YES	XNO

2013 - Fall: No Change	
Comments:	

2014- Spring: No Change	
Comments:	

Comments:	2014 - Fall: No Change	
	Comments:	

2015 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
F	MJP E/F/V on Cardboard Pipe Insulation	33	LF	Pump, Sprinkler & Boiler Rooms, Bsmt Storage Room Office & Toilet, Mech. Rm South of Fan Room - 1894		TSI	Yes	None	0		

2013 - Fall: No Change

Comments:

2014- Spring: No Change	
Comments:	

2015 - Fall: No Change	
Comments:	

2015- Spring: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
G	MJP E/F/V on Aircell Pipe Insulation	18	LF	Bsmt Boys Toilet, Storage Office Toilet, Mech Rm South Of Fan Rm, Eng Off, Pump & Boiler Rms - 1894		TSI	Yes	None	0		YES	X NO

2013 - Fall: No Change	
Comments:	

2014 - Fall: No Change	
Comments:	

2014- Spring: No Change	
Comments:	

2015- Spring: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
н	MJP E/F/V on Fiberglass Pipe Insulation	80	SF	Storage Office Toilet, Bsmt Boys & Girls Toilets, Mech Rm S of Fan Rm, Pump and Boiler Rooms - 1894		TSI	Yes	None	0		YES	XNO

2013 - Fall: No Change	
Comments:	

2014- Spring: No Change
Comments:

2015- Spring: No Change Comments:

2015 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	
I	Aircell Duct Insulation	2500	SF	Crawlspace - 1939 Bldg		TSI	Yes	Dist	20		YES	X NO

2013 - Fall: No Change	
Comments:	

2014 - Fall: No Change Comments:

2014- Spring: No Change	
Comments:	

2015- Spring: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
J	Aircell Pipe Insulation	3000	LF	1st-3rd Flr Boys & Girls Toilet Chases, 2nd Fl Mech Rm, Tunn., Crwlspce,Bsmt Cor, Fan Rm - 1939 Bldo		TSI	Yes	Dist	20		YES	XNO

2013 - Fall: No Change	
Comments:	
Commenta.	

2014 - Fall: No Change	
Comments:	

2015- Spring: No Change Comments:

2015 - Fall: No Change Comments:

> *VFT* = *Vinyl Floor Tile Friable* = *Can be crumbled, pulverized, or reduced to powder by hand pressure.*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
к	MJP E/F/V on Aircell Pipe Insulation	450	LF	1st-3rd FIr Boys & Girls Toilet Chases, 2nd FI Mech Rm, Tunn., Crwlspce,Bsmt Cor, Fan Rm - 1939 Blda		TSI	No	Dist	20		YES	XNO

2013 - Fall: No Change	
Comments:	

2014 - Fall: No Change	
Comments:	

2015 - Fall: No Change Comments:

2015- Spring: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
L	Cardboard Pipe Insulation	2000	LF	Sub-Basement Corridor, Fan Rm, Crawlspace, Tunnel, 1st Fl Janitors Closet - 1939 Bldg		TSI	Yes	None	0		YES X NO

2013 - Fall: No Change	
Comments:	

2014- Spring: No Change	
Comments:	

2014 - Fall: No Change Comments:

2015- Spring: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessi	ment Category
М	MJP E/F/V on Cardboard Pipe Insulation	250	SF	Sub-Basement Corridor, Fan Rm, Crawlspace, Tunnel - 1939 Bldg		TSI	Yes	None	0		YES	XNO

2013 - Fall: No Change	
Comments:	

2014- Spring: No Change	
Comments:	

Comments:	2014 - Fall: No Change	
	Comments:	

2015- Spring: No Change	
Comments:	

	2015 - Fall: No Change
Comments:	Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category
Ν	MJP E/F/V on Fiberglass Pipe Insulation	20	LF	Sub-Basement Corridor - 1939 Bldg		TSI	Yes	None	0		YES	XNO

2013 - Fall: No Change
v
Comments:
2014- Spring: No Change
Comments:
2014 - Fall: No Change
Comments:
2015 - Fall: No Change
Comments:

ALL LEA Responsibilities, for this school, will be met.

Sym & Criville

Lynn A.Crivello

NOTICE TO PARENTS AND STAFF REGARDING THE ASBESTOS MANAGEMENT PLAN NOTIFICATION

School:	Abraham Lincoln Elementary School
Date:	10/19/2015

This is to notify you in accordance with Illinois and Federal Asbestos Regulations, that a copy of the Asbestos Management Plan is available at each school during school hours by appointment. Requests to review the Asbestos Management Plan must be made at least 24 hours in advance.


Also please be advised that CPS conducts asbestos inspections of all Schools every three years. The last inspection was completed in 2013.

Asbestos surveillances are conducted every six months.

CHECK ONE

	A copy of this notice was sent home in each child's backpack.
--	---

A copy of this notice was printed in the school's newsletter and sent home with each child



X Other. website

A COPY OF THIS NOTICE MUST BE PLACED IN THE SCHOOL'S ASBESTOS MANAGEMENT PLAN.