Chicago Public Schools

6 Month Asbestos Surveillance 2015 - Fall

Helen C Peirce School Of International Studies 24891 5360 School: **Oracle Unit: Building ID:** Address: 1423 W Bryn Mawr Avenue Region: 01 Mail Room: Asbestos Surveyor: Cartell, Mr. Richard J **CHECK HERE IF NO CHANGE TO ASBESTOS** Survey Date: 10/26/2015 Email Address: rjcartell@cps.edu A copy of the 2013/2014 notice to parents and staff regarding the asbestos management plan notifications was distributed via: X Notice printed in school's newsletter Each child's backpack Notice printed in school's calendar Other HA No Material Description Material Location Friable Damage Change in Assessment Category Material Asbestos Material Damage Damage Quantity Units Category Quantity Type Type 2'x4' Ceiling Tile w/ White Rm 301, 1st, 2nd, & 3rd YES SF X NO 01 3200 0 Miscellaneous Yes None Speckles Floor - 1914 Building 2013 - Fall: No Change Comments: 2014- Spring: No Change Comments: 2014 - Fall: Damaged Comments:8 SQFT 2015- Spring: No Change Comments: 2015 - Fall: Damaged Comments:2 sq ft

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	essment Category
03	12"x12" Beige w/ Brown Streaks VFT	2400	SF	Rm 300, 200 (Under Carpet)- 1914 Building		Miscellaneous	No	None	0		YES	X NO
2013 - Fall:	No Change											
Comments:												
	g: No Change											
Comments:												
2014 - Fall:	No Change				7							
Comments:												
2015- Sprin	g: No Change				7							
Comments:												
	No Change											
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	essment Category
06	9"x9" Tan w/ Brown Streaks VFT	900	SF	Kindergarten (Rm 101) - 1914 Building		Miscellaneous	No	None	0		YES	X NO
2013 - Fall:	No Change											
Comments:												
2014- Sprin	g: No Change				7							
Comments:												
2014 - Fall:	No Change				7							
Comments:												
2015- Sprin	g: No Change				7							

Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	essment Category
07	Hardcoat Plaster	0	SF	Throughout - 1914 Building		Surface	No	None			YES	X NO
2013 - Fall: N	No Change											
Comments:												
2014- Spring	: No Change											
Comments:												
2014 - Fall: N	No Change											
Comments:												
2015- Spring	ı: No Change											
Comments:												
2015 - Fall: N	No Change											
Comments:	Ü											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	essment Category
08	12"x12" Beige w/ Brown Streaks VFT Mastic	1500	SF	Rm 300, 200 (Under Carpet) - 1914 Building		Miscellaneous	No	None	0		YES	X NO
2013 - Fall: N	No Change											
Comments:	•											
2014- Spring	ı: No Change											
Comments:	•											
2014 - Fall: N	No Change											
Comments:	Ŭ											
2015- Spring	ı: No Change											

Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	essment Category
10	9"x9" Tan w/ Brown Streaks VFT Mastic	670	SF	Kindergarten (Rm 101) - 1914 Building		Miscellaneous	No	None	0		YES	X NO
2013 - Fall: I	No Change				7							
Comments:]							
2014- Spring	g: No Change				7							
Comments:]							
2014 - Fall: I	No Change				7							
Comments:	J											
2015- Spring	g: No Change				7							
Comments:	<u></u>]							
2015 - Fall: I	No Change				7							
Comments:	ito onango				1							
					_							
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Ass	sessment Category
	'	Quantity	Units		Туре	Category		Туре	Quantity	Units	Ů	
11	12"x12" Tan w/ Grey Streaks VFT	800	SF	Rm 105 - 1914 Building		Miscellaneous	No	None	0		YES	X NO
2013 - Fall: I	No Change				7							
Comments:	J											
2014- Spring	g: No Change				7							
Comments:]							
2014 - Fall: I	No Change				7							
Comments:	go				_							
2015- Spring	g: No Change				7							
Comments:	g. 140 Onlango											
2015 - Fall:	No Change				-]							
Comments:	ino Change				1							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	sessment Category
12	12"x12" Tan w/ Brown Streaks VFT	500	SF	Old Engineer Offices, Assemby Stage - 1914 Building		Miscellaneous	No	None	0		YES	X NO
2013 - Fall	: No Change											
Comments												
2011 Cmri	an Na Changa				- 7							
Comments	ng: No Change											
Comments	•											
	: No Change											
Comments												
2015- Sprir	ng: No Change				7							
Comments												
					- -							
	: No Change				_							
Comments	:											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	sessment Category
13	12"x12" Off White w/ White Streaks VFT	800	SF	Rm 103 - 1914 Building		Miscellaneous	No	None	0		YES	X NO
2013 - Fall	: No Change				7							
Comments												
0044 0	. N. Olasas				- 7							
Comments	ng: No Change				_							
Comments	•											
2014 - Fall	: Damaged											
Comments	:8 SQFT											
2015- Sprin	ng: No Change				٦							
Comments					=							

2015 - Fall: Damaged Comments:8 sq ft

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	essment Category
14	9"x9" Green w/ White Streaks VFT	30	SF	Rm 101 - 1914 Building		Miscellaneous	No	None	0		YES	X NO
2013 - Fall:	No Change											
Comments:												
	g: No Change											
Comments:												
2014 - Fall:	No Change											
Comments:												
2015- Spring	g: No Change											
Comments:												
2015 - Fall:	No Change											
Comments:	<u> </u>											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	essment Category
15	9"x9" Maroon VFT	200	SF	1st FI Teachers Rm (under carpet), 1914 Building		Miscellaneous	No	None	0		YES	X NO
2013 - Fall:	No Change											
Comments:	i to Onlango											
2014- Spring	g: No Change				٦							
Comments:	g. 110 Onlango											
2014 - Fall:	Inaccessible				7							
Comments:I	Not Found											
2015 Spring	g: No Change				_ _							
Comments:	g. No Change											
	la a a a a a ib.l -				_ ¬							
Comments:	Inaccessible Not found				-							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
16	2'x4' Wormy White Ceiling Tile	500	SF	1st FI Teachers Rm - 1914 Building		Miscellaneous	Yes	None	0		YES	X NO
2013 - Fall: N	lo Change											
Comments:												
2014- Spring	: No Change											
Comments:												
2014 - Fall: Ir	naccessible											
Comments:N	lot Found											
2015- Spring	: No Change											
Comments:												
2015 - Fall: Ir	naccessible											
Comments:N	lot found											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
17	9"x9" Maroon VFT Mastic	200	SF	1st FI Teachers Rm - 1914 Building		Miscellaneous	No	None	0		YES	X NO
2013 - Fall: N	lo Change											
Comments:	•											
2014- Spring	: No Change											
Comments:												
2014 - Fall: Ir	naccessible											

Comments:Not Found

Comments:

2015- Spring: No Change

2015 - Fall: Inaccessible Comments:Not found

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	sessment Category
18	12"x12" Tan w/ Grey Streaks VFT Mastic	800	SF	Rm 105 - 1914 Building		Miscellaneous	No	None	0		YES	X NO
2013 - Fall:	No Change											
Comments:												
2014- Spring Comments:	g: No Change											
2014 - Fall:	No Change											
Comments:												
2015- Spring	g: No Change											
Comments:												
2015 - Fall:	No Change				7							
Comments:	<u> </u>											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	sessment Category
19	9"x9" Green w/ White Streaks VFT Mastic	30	SF	Rm 101 - 1914 Building		Miscellaneous	No	None	0		YES	X NO
2013 - Fall:	No Change											
Comments:												
2014 Spring	g: No Change											
Comments:	g. No Change											
					- -							
2014 - Fall: Comments:	No Change				_							
	g: No Change				_							
Comments:					1							

2015 - Fall: No Change

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	sessment Category
20	12"x12" Off White w/ White Streaks VFT Mastic	750	SF	Rm 103 - 1914 Building		Miscellaneous	No	None	0		YES	X NO
2013 - Fall: N	lo Change				7							
Comments:	-											
2014- Spring:	: No Change				7							
Comments:												
2014 - Fall: D	amaged											
Comments:8	SQFT											
2015- Spring:	: No Change											
Comments:												
2015 - Fall: D	amaged				7							
Comments:8	sqft											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category
21	12" x 12" White w/ Blue Specks VFT	4800	SF	Room # 320- 325, 328, 329, 331, 337 - 1999 Annex		Miscellaneous	No	None	0		YES	X NO

2013 - Fall: No Change	
Comments:	

2014- Spring: No Change	
Comments:	

20	14 - Fall: No Change
Co	omments:

2015- Spring: No Change
Comments:

2015 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
22	12" x 12" White w/ Blue Specks VFT Mastic	4800	SF	Room # 320- 325, 328, 329, 331, 337 - 1999 Annex		Miscellaneous	No	None	0		YES	X NO
2013 - Fall	: No Change											
Comments);											
2014- Spri	ng: No Change											
Comments	:											
2014 - Fall	: No Change											
Comments	:											
2015- Spri	ng: No Change											
Comments	:											
	: No Change											
Comments	:											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
23	12" x 12" White w/ Pink Specks VFT	4800	SF	Room # 223- 225, 227- 229, 229 A, 231 - 1999 Annex		Miscellaneous	No	None	0		YES	X NO
2013 - Fall	: No Change											
Comments	:											
	ng: No Change											
Comments): -											
	: No Change											
Comments	S:											
2015- Spri	ng: No Change				7							

Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
24	12" x 12" White w/ Pink Specks VFT Mastic	4800	SF	Room # 223- 225, 227- 229, 229 A, 231 - 1999 Annex		Miscellaneous	No	None	0		YES	X NO
2013 - Fall: N	lo Change]							
Comments:												
2014- Spring Comments:	: No Change											
2014 - Fall: N Comments:	lo Change											
2015- Spring Comments:	: No Change											
2015 - Fall: N Comments:	lo Change											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
25	12" x 12" White w/ Green Specks VFT	7200	SF	Room 120C, 121&Storage&Bathroom, 122&Stor&Bath.,123&Sto r&Bath.,124A,126&Stor.& Bath.,129 -1999 Annex		Miscellaneous	No	None	0		YES	X NO
2013 - Fall: N	lo Change]							
Comments:	J]							
2014- Spring Comments:	: No Change											
2014 - Fall: N Comments:	lo Change											
2015- Spring Comments:	: No Change											
2015 - Fall: N	lo Change]							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
26	12" x 12" White w/ Green Specks VFT Mastic	7200	SF	Room 120C, 121&Storage&Bathroom, 122&Stor&Bath.,123&Sto r&Bath.,124A,126&Stor.& Bath.,129 -1999 Annex		Miscellaneous	No	None	0		YES	X NO
2013 - Fall: N	lo Change]							
Comments:	J											
2014- Spring	: No Change				1							
Comments:	go				<u> </u>							
2014 - Fall: N	lo Change				1							
Comments:	to onango											
2015- Spring	· No Change				7							
Comments:	. 140 Onange				-							
2015 - Fall: N	lo Change				- 1							
Comments:	vo onange											
					-							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
27	12" x 12" Yellow VFT	8000	SF	Room 121-123, 124A, 126, 223-225, 227-229, 231, 320-325, 328, 329, 331, 1999 Annex		Miscellaneous	No	None	0		YES	X NO
2013 - Fall: N	lo Change]							
Comments:]							
2014- Spring	: No Change				7							

Comments:

Comments:

Comments:

2014 - Fall: No Change

2015- Spring: No Change

HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in As	sessment Category
		Quantity	Units		Type	Category		Type	Quantity	Units		
28	12" x 12" Yellow VFT Mastic	1800	SF	Room 121-123, 124A, 126, 223-225, 227-229, 231, 320-325, 328, 329, 331 - 1999 Annex		Miscellaneous	No	None	0		YES	X NO
2013 - Fal	I: No Change				7							
Comments												
					_ _							
2014- Spri	ng: No Change											
Comments	S:											
					_ _							
2014 - Fal	l: No Change											
Comments	S:											
					_							
2015- Spri	ng: No Change											
Comments	S:											
2015 - Fal	I: No Change				7							
Comments												
					-							
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in As	sessment Category
		Quantity	Units		Type	Category		Type	Quantity	Units		
29	12" x 12" Blue VFT	1800	SF	Room 121-123, 124A, 126, 223-225, 227-229, 224, 225, 227-229, 226, 227-229,		Miscellaneous	No	None	0		YES	X NO

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
29	12" x 12" Blue VFT	1800	SF	Room 121-123, 124A, 126, 223-225, 227-229, 231, 320-325, 328, 329, 331 - 1999 Annex		Miscellaneous	No	None	0		YES	X NO

2013 - Fall: No Change	
Comments:	

2014- Spring: No Change
Comments:

2014 - Fall: No Change	
Comments:	

2015- Spring: No Change
2015- Spring. No Change
Comments:

2015 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
30	12" x 12" Blue VFT Mastic	1800	SF	Room 121-123, 124A, 126, 223-225, 227-229, 231, 320-325, 328, 329, 331 - 1999 Annex	1,700	Miscellaneous	No	None	0	O.m.o	YES	X NO
2013 - Fall: N	No Change				1							
Comments:	5]							
2014- Spring Comments:	: No Change											
2014 - Fall: N	No Change]							
Comments:]							
2015- Spring	y: No Change]							
Comments:]							
2015 - Fall: N	No Change				1							
Comments:	_]							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
31	12" x 12" Peach VFT	1800	SF	Room 121-123, 124A, 126, 223-225, 227-229, 231, 320-325, 328, 329, 331 - 1999 Annex		Miscellaneous	No	None	0		YES	X NO

2013 - Fall: No Change		
Comments:		

2014- Spring: No Change
Comments:

2014 - Fall: No Change	
Comments:	

2015- Spring: No Change
Comments:

2015 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	essment Category
32	12" x 12" Peach VFT Mastic	1800	SF	Room 121-123, 124A, 126, 223-225, 227-229, 231, 320-325, 328, 329, 331 - 1999 Annex		Miscellaneous	No	None	0		YES	X NO
2013 - Fall:	No Change				Ī							
Comments:	•]							
2014- Sprin	g: No Change]							
Comments:]							
2014 - Fall:	No Change				Ī							
Comments:]							
2015- Sprin	g: No Change]							
Comments:												
2015 - Fall:	No Change				1							
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	essment Category
33	12" x 12" Green VFT	1800	SF	Room 121-123, 124A, 126, 223-225, 227-229, 231, 320-325, 328, 329, 331 - 1999 Annex		Miscellaneous	No	None	0		YES	X NO

2013 - Fall: No Change	
Comments:	

2014 Folly No Change
2014 - Fall: No Change
Comments:

2014- Spring: No Change	
Comments:	

2015 Chring, No Change
2015- Spring: No Change
Comments:

2015 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	essment Category
34	12" x 12" Green VFT Mastic	1800	SF	Room 121-123, 124A, 126, 223-225, 227-229, 231, 320-325, 328, 329, 331 - 1999 Annex		Miscellaneous	No	None	0		YES	X NO
2013 - Fall	No Change				1							
Comments	· ·											
					<u>-</u> 1							
	ng: No Change											
Comments	•]							
2014 - Fall:	No Change				7							
Comments	<u> </u>											
2015 Conti	an Na Changa				- 1							
	ng: No Change				4							
Comments	:											
2015 - Fall:	No Change				1							
Comments					1							
					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	essment Category
35	Green Linoleum	3000	SF	Cafeteria, Kitchen, Serving Area, Room 124 Hallway - 1999 Annex		Miscellaneous	No	None	0		YES	X NO
2013 - Fall:	No Change				1							
Comments	<u> </u>											
					- -							
	ng: No Change				_							
Comments	:											

2014 - Fall: Damaged Comments:2 SQFT

2015 - Fall: Damaged Comments:2 sq ft

Comments:

2015- Spring: No Change

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	sessment Category
36	Green Linoleum Mastic	3000	SF	Cafeteria, Kitchen, Serving Area, Room 124 Hallway - 1999 Annex		Miscellaneous	No	None	0		YES	X NO
2013 - Fall:	No Change											
Comments:												
2014- Sprin	g: No Change											
Comments:												
2014 - Fall:	Damaged				7							
Comments:												
2015- Sprin	ıg: No Change				- 1							
Comments:												
0045 5-11-	Damarad				<u>-</u> 1							
2015 - Fall: Comments:												
	20 04 11											
HA No	Material Description	Matarial	Matarial	Material Location	Ashastas	Matarial	Frieble	Damana	Damana	Domesti	Channa in Ass	
HA NO	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	sessment Category
37	Tan Linoleum	1500	SF	Cafeteria - 1999 Annex		Miscellaneous	No	None	0		YES	X NO
2013 - Fall:	No Change				1							
Comments:												
2014- Sprin	ıg: No Change											
Comments:												
2014 - Fall:	Damaged				1							
Comments:												
2015 Sprin	g: No Change				- 7							
Comments:												
2015 - Fall:	Damaged				1							
Comments:					1							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	essment Category
38	Tan Linoleum Mastic	1500	SF	Cafeteria - 1999 Annex		Miscellaneous	No	None	0		YES	X NO
2013 - Fall: I	No Change]							
Comments:												
2014- Spring Comments:	g: No Change											
2014 - Fall: []							
Comments:2	23 SQFT											
2015- Spring	g: No Change				7							
Comments:	g. 140 Orlange											
					- -							
2015 - Fall: I Comments:2												
Comments.2	:5 SY II											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	essment Category
39	2' x 4' Grooves Ceiling Tile	7000	SF	Throughout - 1999 Annex		Miscellaneous	Yes	None	0		YES	X NO
2013 - Fall: I	No Change				1							
Comments:	10 0.1.ago											
2014- Spring	g: No Change				-]							
Comments:	g. 140 Orlange											
					<u>-</u> 7							
2014 - Fall: [
Comments:8	SU SQF I											
	g: No Change											
Comments:												
2015 - Fall: [Damaged				1							
Comments:8												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	essment Category
40	2' x 2' White Ceiling Tile	3500	SF	Kitchen, Serving Area, Room 125 A, 1999 Annex		Miscellaneous	Yes	None	0		YES	X NO
2013 - Fall	: No Change											
Comments]							
2014- Sprii Comments	ng: No Change]							
Comments	•				<u></u>							
	: No Change				=							
Comments	:]							
2015- Spri	ng: No Change											
Comments	:											
2015 - Fall	: No Change]							
Comments												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	essment Category
41	Drywall	3500	SF	Throughout, 1999 Annex		Miscellaneous	Yes	None	0		YES	X NO
2013 - Fall	: No Change]							
Comments												
2014 Spri	ng: No Change				- 1							
Comments												
]							
2014 - Fall Comments	: Damaged											
Comments	.30 3QF1				<u> </u> _							
	ng: No Change											
Comments	:				J							
2015 - Fall	: Damaged											
Comments	:30 sa ft											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	essment Category
42	Drywall Joint Compound	350	LF	Throughout, 1999 Annex		Miscellaneous	Yes	None	0		YES	X NO
2013 - Fall:	No Change]							
Comments:	-]							
2014- Sprin	g: No Change]							
Comments:]							
2014 - Fall:]							
Comments:	30 SQFT											
	g: No Change]							
Comments:												
2015 - Fall:]							
Comments:	30 sq ft											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	essment Category
43	Spray-On Fireproofing	1500	SF	Rm 226 Mech., Rm 131 Plumbing Rm, Rm 130 Elect. Rm, Kitchen Stairs, Rm 124B Stor - 1999 Annex		Surface	Yes	None	0		YES	X NO
2013 - Fall:	No Change]							
Comments:]							

2013 - Fall: No Change	
Comments:	

2014- Spring: No Change Comments:

2014 - Fall: Damaged Comments:25 SQFT

2015- Spring: No Change Comments:

2015 - Fall: Damaged Comments:25 sq ft

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	essment Category
44	12"x12" White with color specks VFT	800	SF	Kindergarden Rm. 101 - 1914 Bldg.		Miscellaneous	No	None	0		YES	X NO
2013 - Fall: N	lo Change]							
Comments:												
2014- Spring	: No Change											
Comments:												
2014 - Fall: N	lo Change				7							
Comments:												
2015- Spring	· No Change				7							
Comments:	. 140 Onango				-							
2015 - Fall: N	la Changa				- 7							
Comments:	io Change				-							
LIA NI-	L Material December	NA-1-2-1	I Maria dal	Matadallasadas	A -1:1	T Marta dal	Leann	T.D	I B	I Barrage	Observato Ass	
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	sessment Category
44 A	12"x12" White with color specks (MASTIC)	800	SF	Kindergarden Rm 101 - 1914 Bldg.		Miscellaneous	No	None	0		YES	X NO
2013 - Fall: N	lo Change				7							
Comments:	- Consuming of											
2014- Spring	· No Change				7							
Comments:	. 140 Orlange				-							
0044 Fall N	In Ohanan				- 7							
2014 - Fall: N Comments:	io Change				-							
					」 ¬							
2015- Spring Comments:	: No Change				-							
					_ _							
2015 - Fall: N	lo Change											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	essment Category
45	12"x12" White with pink & blue specks VFT	400	SF	1st fl. Corridor (by room 106) - 1914 Bldg.		Miscellaneous	No	None	0		YES	X NO
2013 - Fall	No Change				7							
Comments]							
2014- Sprii	ng: No Change				7							
Comments												
2014 - Fall	No Change				7							
Comments	:											
2015 - Fall	No Change				7							
Comments	•											
2015- Sprii	ng: No Change				7							
Comments]							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	sessment Category
45 A	12"x12" White with pink & blue specks (MASTIC)	400	SF	1st floor corridor (by room 106) - 1914 Bldg.		Miscellaneous	No	None	0		YES	X NO
2013 - Fall	No Change				7							
Comments	· · · · · · · · · · · · · · · · · · ·											

2014- Spring: No Change Comments:

2014 - Fall: No Change Comments:

2015- Spring: No Change Comments:

2015 - Fall: No Change Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	essment Category
46	12"x12" White with green specks VFT	800	SF	Room 106 (Counselor's office) - 1914 bldg.		Miscellaneous	No	None			YES	X NO
2013 - Fall:	No Change											
Comments:												
2014 - Fall:	No Change											
Comments:												
	g: No Change											
Comments:												
2015- Sprin	g: No Change				7							
Comments:												
2015 - Fall:	No Change											
Comments:	•											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	essment Category
46 A	12"x12" White with green specks (MASTIC)	800	SF	Room 106 (Counselor's Office) 1914 Bldg.		Miscellaneous	No	None	0		YES	X NO
2013 - Fall:	No Change				7							
Comments:	•											
2014 - Fall:	No Change				7							
Comments:	y -]							
2014- Sprin	g: No Change				7							
Comments:												

2015- Spring: No Change

2015 - Fall: No Change

Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	sessment Category
47	Carpet Mastic	2000	SF	Rooms 300, 306A, 200, 206, 109, Gym/Assembly hall between aisles		Miscellaneous	No	None	0		YES	X NO
2013 - Fall:	: No Change											
Comments												
2014- Sprir	ng: No Change				7							
Comments												
2014 - Fall:	: No Change				7							
Comments												
204E Contin	an Na Changa				- 1							
Comments	ng: No Change											
					_							
	: No Change											
Comments												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	sessment Category
48	Terrazzo	4500	SF	1st, 2nd, 3rd floor Corridors, stairwells, all toilets - Annex 1999 Bldg.		Miscellaneous	No	None	0		YES	X NO
2013 - Fall:	: No Change											
Comments												
2014- Sprin	ng: No Change				1							
Comments												
2014 Falls	Domogod				- 1							
2014 - Fall: Comments					<u> </u>							
					_ _							
	ng: No Change											
Comments					_							
2015 - Fall:												
Comments	:20 sq ft											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	essment Category
49	Fire Door	2	EA	Stage entrance, projector room		Miscellaneous	No	None			YES	X NO
2013 - Fall:	No Change]							
Comments:												
2014- Sprin	g: No Change]							
Comments:												
2014 - Fall:	No Change]							
Comments:												
2015 - Fall:	No Change]							
Comments:]							
2015- Sprin	g: No Change]							
Comments:]							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	essment Category
50	Curtain wall	850	SF	Assembly Hall Gymnasium		Miscellaneous	No	None	0		YES	X NO
2013 - Fall:	No Change				1							
Comments:												
2014- Sprin	g: No Change]							
Comments:												
2014 - Fall:	Damaged											
Comments:												
2015 - Fall:	Damaged]							
Comments:]							
2015- Sprin	g: No Change]							
Comments:					1							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
А	Aircell Pipe Insulation	20	LF	1st Fl Engine Room, North Fan Room,105, Kindergarden Wardrobe - 1914 Bldg		TSI	Yes	None	0		YES	X NO
2013 - Fall: N	lo Change				1							
Comments:]							
2014 - Fall: I	naccessible]							
Comments:N	lot Found]							
2014- Spring	: No Change]							
Comments:]							
2015- Spring	: No Change]							
Comments:]							
2015 - Fall: N	lo Change]							
Comments:]							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
A6	Exterior Caulk (NOT OBSERVED)	50	LF	Throughout Exterior Windows - 1914 Building (NOT OBSERVED)		Miscellaneous					YES	X NO
2013 - Fall: N	lo Change				1							
Comments:	<u> </u>]							
2014- Spring	: No Change				1							
Comments:	•]							
2014 - Fall: I	naccessible				1							
Comments:N]							
2015 - Fall: I	naccessible				1							
Comments:N]							
2015- Spring	: No Change				1							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in As	sessment Category
A7	Transite Pipe	100	LF	Attic Above Girls Toilet - Fieldhouse		Miscellaneous	No	None	0		YES	X NO
2013 - Fall: N	No Change				7							
Comments:	•											
2014 - Fall: I												
2014- Spring Comments:	: No Change											
2015 - Fall: I]							
2015- Spring Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in As	sessment Category
В	MJP on Fiberglass Pipe Insulation	70	LF	Engine & Tank Rm, South Fan Rm, Boys, Girls & Teachers Toilet Chases - 1914 Bldg.		TSI	Yes	None	0		YES	X NO
2013 - Fall: N Comments:	No Change											
2014- Spring Comments:	: No Change											
2014 - Fall: N	No Change											
2015 - Fall: No Change Comments:												
2015- Spring Comments:	: No Change]										

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
С	Mag Block Pipe Insulation	614	LF	Boiler Rm, Engine Rm, 1914 Building		TSI	Yes	None	0		YES	X NO
2013 - Fall: N	No Change				7							
Comments:	J											
2014 - Fall: [Damaged				7							
Comments:4	LFT											
2014- Spring	: No Change				7							
Comments:												
2015 - Fall: [Damaged				7							
Comments:4	· lft											
2015- Spring	: No Change				٦							
Comments:	J											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
D	MJP on Mag Block Pipe Insulation	82	LF	Boiler Rm, Engine/Fan Rm - 1914 Building		TSI	Yes	None	0		YES	X NO
2013 - Fall: No Change												

2014 - Fall: No Change Comments:

2014- Spring: No Change Comments:

2015- Spring: No Change Comments:

2015 - Fall: No Change Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
Е	Cardboard Pipe Insulation	226	LF	Fan Rm South, 1st Floor Hallway, Room 102, Kindergarden Toilet, Lunch Rm Managers Office -1914 Bldg		TSI	Yes	None	0		YES X NO
2013 - Fall: N	No Chango				1						
Comments:	NO Change										
Comments.]						
2014- Spring	g: No Change]						
Comments:	-										
					7						
2014 - Fall: I											
Comments:N	Not Found]						
2015 - Fall: I	naccessible										
Comments:N	lot found										
2015- Spring	ı: No Change				1						
Comments:	J. 140 Onlange										
					_						
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category
F	MJP on Cardboard Pipe Insulation	50	LF	Fan Rm South - 1914 Building		TSI	Yes	None	0		YES	X NO

2013 - Fall: No Change	
Comments:	

2014 - Fall: Inaccessible	
Comments:Not Found	

2014- Spring: No Change	
Comments:	

2015 - Fall: Inaccessible
Comments:Not found

2015- Spring: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A
Н	MJP on Aircell Pipe Insulation	41	LF	Engine Rm, North Fan Rm - 1914 Building		TSI	Yes	None	0		YES
2013 - Fal	I: No Change										
Comments	<u> </u>										
2014- Spr	ing: No Change										
Comments	S:										
2014 - Fal	l: Inaccessible				\neg						
Comments	s:Not Found										
2015 - Fal	l: Inaccessible										
Comments	s:Not found			<u> </u>							

2015- Spring: No Change

Comments:

Change in Assessment Category

X NO

ALL LEA Responsibilities, for this school, will be met.

Lynn A.Crivello

Sym & Crwill

NOTICE TO PARENTS AND STAFF REGARDING THE ASBESTOS MANAGEMENT PLAN NOTIFICATION

School: Helen C Peirce School Of International Studies
Date: 10/30/2015
This is to notify you in accordance with Illinois and Federal Asbestos Regulations, that a copy of the Asbestos Management Plan is available at each school during school hours by appointment. Requests to review the Asbestos Management Plan must be made at least 24 hours in advance.
Also please be advised that CPS conducts asbestos inspections of all Schools every three years. The last inspection was completed in 2013. Asbestos surveillances are conducted every six months.
CHECK ONE
A copy of this notice was sent home in each child's backpack.
X A copy of this notice was printed in the school's newsletter and sent home with each child
A copy of this notice was printed in the school's calendar and sent home with each child
Other.
A COPY OF THIS NOTICE MUST BE PLACED IN THE SCHOOL'S ASBESTOS MANAGEMENT PLAN.

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

Oracle Unit: 24891