Chicago Public Schools

6 Month Asbestos Surveillance 2015 - Fall

25071

Oracle Unit:

Address: 5631 S. Kimbark Region: Mail Room: Asbestos Surveyor: Allen, Mr. Christopher Wright X CHECK HERE IF NO CHANGE TO ASBESTOS 11/5/2015 Survey Date: Email Address: cwallen@cps.edu A copy of the 2013/2014 notice to parents and staff regarding the asbestos management plan notifications was distributed via: Notice printed in school's newsletter Notice printed in school's calendar Other Each child's backpack HA No Asbestos **Material Description** Material Material Material Location Material Friable Damage Damage Damage Change in Assessment Category Category Quantity Units Type Type Quantity Units Throughout 1893 YES X NO 01 Hard Plaster 40000 SF Surface No None 0 Construction 2013 - Fall: No Change Comments: 2014- Spring: No Change Comments: 2014 - Fall: No Change Comments: 2015- Spring: No Change Comments: 2015 - Fall: No Change Comments:

William H Ray School

School:

5560

Building ID:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	essment Category
02A	12x12 beige w/tan streaks floor tile	1550	SF	basement art room		Miscellaneous	No	None	0		YES	X NO
2013 - Fall: N	lo Change											
Comments:												
2014 - Fall: N	lo Change				7							
Comments:	Ü											
2014- Spring:	: No Change				٦							
Comments:	ge											
2015 - Fall: N	lo Change				7							
Comments:	ge											
2015- Spring:	· No Change				7							
Comments:	. IVO Onlange											
					<u>-</u>							
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Ass	essment Category
10.110	Material Booonplion	Quantity	Units	Waterial Education	Туре	Category	i nabio	Type	Quantity	Units	onango in 7100	ocomoni catogory
02B	12x12 black floor tile	300	SF	room 306		Miscellaneous	No	None	0		YES	X NO
2013 - Fall: N	lo Change				7							
Comments:												
2014 - Fall: N	lo Change											
Comments:	g											
2014- Spring:	· No Change				٦							
Comments:	. Ito change											
2015- Spring:	· No Chango				_ _							
Comments:	. No Change				+							
	lo Chango				_ _							
2015 - Fall: N Comments:	io Change				+							
					_							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	essment Category
02C	12x12 white floor tile	300	SF	room 306		Miscellaneous	No	None	0		YES	X NO
2013 - Fall:	No Change											
Comments:												
2014- Spring	g: No Change											
Comments:												
2014 - Fall:	No Change											
Comments:												
2015- Spring	g: No Change											
Comments:												
2015 - Fall:	No Change											
Comments:												
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Ass	essment Category
		Quantity	Units		Туре	Category		Туре	Quantity	Units		,
02D	12x12 beige streaked floor tile	430	SF	1st, 2nd, 3rd floor corridors (patches)		Miscellaneous	No				YES	X NO
2013 - Fall:	No Change											
	2nd & 3rd floor blue tile)										
2014 - Fall·	No Change											
2014 - Fall: Comments:	110 Change											
					<u> </u>							
Comments:	g: No Change											
					<u> </u>							
2015 - Fall:	No Change											
Comments:												

2015- Spring: No Change

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	essment Category
02E	12x12 orange floor tile			1st floor corridor - outside boys toilet		Miscellaneous	No				X YES	NO
2013 - Fall:]							
Comments	:Biege tile in corridor											
2014 - Fall:	No Change											
Comments												
2014- Sprir	na: Other				1							
	:staff lounge 12x12 ora	nge tile out	side wash	room								
2015 - Fall:	No Change				1							
Comments												
2015- Sprin	ng: No Change				- 1							
Comments												
Comments	•				<u></u>							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	essment Category
02F	12x12 tan floor tile	4770	SF	Classrooms 303, 305, 310, 311, 313, 203, 205, 208, 101, 102, 105, 107, eng office		Miscellaneous	Yes	None	0		YES	X NO
2013 - Fall	No Change]							
Comments												
2014- Sprin	ng: No Change				- 1							
Comments												
					_							
	No Change											
Comments	:											
2015 - Fall:	No Change											

Comments:

2015- Spring: No Change

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	sessment Category
03A	9x9 black floor tile			main office - principal's office, bathroom, vault		Miscellaneous	No				X YES	NO
2013 - Fall:												
Comments:	Carpet squares Pricipa	al office										
2014- Sprin												
Comments:	12x12 carpet square	washroom	12x12 wh	iite								
2014 - Fall:	No Change											
Comments:												
2015- Sprin	g: No Change											
Comments:												
2015 - Fall:	No Change											
Comments:												
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Ass	sessment Category
		Quantity	Units		Туре	Category		Туре	Quantity	Units		
03B	9x9 white floor tile			main office - principal's office, bathroom & vault		Miscellaneous	No				YES	X NO
2013 - Fall:	No Change											
Comments:	<u> </u>											
2014 - Fall:	No Change											
Comments:	<u> </u>											
2014- Sprin	a: Other											
	12x12 white											
2015- Sprin	ıg: No Change											
Comments:												
2015 - Fall:	No Change											
Comments:												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
03C	9x9 green floor tile			engineer's toilet		Miscellaneous	No				X YES	NO
2013 - Fall: C	Other											
Comments:B	lue											
2014- Spring	: No Change											
Comments:	_											
2014 - Fall: N	lo Change											
Comments:	Ğ											
2015 - Fall: N	lo Change				٦							
Comments:	g-											
2015- Spring	· No Change											
Comments:	. rto Onango											
					_							
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Assess	sment Category
	,	Quantity	Units		Туре	Category		Туре	Quantity	Units	<u> </u>	
05	linoleum			basement ladie's room		Miscellaneous					X YES	NO
2013 - Fall: C	Other											
Comments:B												
2014- Spring	· No Change											
Comments:	. rto onango											
2014 - Fall: N	lo Change				_ 							
2014 - Fall: N Comments:	40 Orlange											
2015- Spring					_ _							
Comments:	. No Change											
	In Ohanan				- ¬							
2015 - Fall: N Comments:	vo Cnange				\dashv							

Comments: Comm											
Comments: Comm	HA No	Material Description		Material Location			Friable	Damage Type	Damage Quantity	Change in Ass	essment Category
Comments: 2014 - Spring: No Change Comments: 2015 - Spring: No Change Comments: 2015 - Fall: No Change Comments: 2015 - Fall: No Change Comments: 2016 - Fall: No Change Comments: 2017 - Fall: No Change Comments: 2018 - Fall: No Change Comments: 2019 9x9 floor tile- ABATED 1955 building (demolished) Miscellaneous Miscel	08	12x12 floor tile- ABATED		1955 building (demolished)		Miscellaneous				YES	X NO
2014 - Spring: No Change Comments: 2014 - Fall: No Change Comments: 2015 - Spring: No Change Comments: 2015 - Fall: No Change Comments: 2015 - Fall: No Change Comments: 2015 - Fall: No Change Comments: 2016 - Fall: No Change Comments: 2017 - Fall: No Change Comments: 2018 - Fall: No Change Comments: 2019	2013 - Fall: N	lo Change			\neg						
Comments: 2014 - Fall: No Change Comments: 2015 - Spring: No Change Comments: 2015 - Fall: No Change Comments: HA No Material Description Material Ouantity Units Material Location Type Category 9 seption tile-ABATED Material Description (demolished) 1955 building (demolished) 2014 - Fall: No Change Comments: 2015 - Fall: No Change Comments: 2016 - Spring: No Change Comments: 2017 - Fall: No Change Comments: 2018 - Spring: No Change Comments: 2019 - Spring: No Change Comments: 2011 - Fall: No Change Comments: 2012 - Fall: No Change Comments: 2015 - Spring: No Change Comments: 2016 - Spring: No Change Comments: 2017 - Fall: No Change Comments: 2018 - Spring: No Change Comments: 2019 - Spring: No Change Comments: 2019 - Spring: No Change Comments: 2010 - Spring: No Change Comments:	Comments:										
Comments: 2014 - Fall: No Change Comments: 2015 - Spring: No Change Comments: 2015 - Fall: No Change Comments: HA No Material Description Material Ouantity Units Material Location Type Category 9 seption tile-ABATED Material Description (demolished) 1955 building (demolished) 2014 - Fall: No Change Comments: 2015 - Fall: No Change Comments: 2016 - Spring: No Change Comments: 2017 - Fall: No Change Comments: 2018 - Spring: No Change Comments: 2019 - Spring: No Change Comments: 2011 - Fall: No Change Comments: 2012 - Fall: No Change Comments: 2015 - Spring: No Change Comments: 2016 - Spring: No Change Comments: 2017 - Fall: No Change Comments: 2018 - Spring: No Change Comments: 2019 - Spring: No Change Comments: 2019 - Spring: No Change Comments: 2010 - Spring: No Change Comments:	2014- Spring:	: No Change									
Comments: 2015 - Spring: No Change Comments: 2015 - Fall: No Change Comments: HA No Material Description Material Quantity Units Material Location Units Type Category 09	Comments:	_									
Comments: 2015 - Spring: No Change Comments: 2015 - Fall: No Change Comments: HA No Material Description Material Quantity Units Material Location Units Type Category Friable Type Quantity Units Damage Quantity Units No Change Comments: 2015 - Fall: No Change Comments: 2016 - Fall: No Change Comments: 2017 - Fall: No Change Comments: 2018 - Fall: No Change Comments: 2019 - Spring: No Change Comments: 2016 - Spring: No Change Comments: 2016 - Fall: No Change Comments: 2017 - Fall: No Change Comments: 2018 - Spring: No Change Comments: 2019 - Spring: No Change Comments:	2014 - Fall: N	lo Change									
Comments: 2015 - Fall: No Change Comments: HA No Material Description Material Material Location Material Location Type Material Friable Damage Type Damage Quantity Units Passessment Category 09 9x9 floor tile- ABATED 1955 building (demolished) Miscellaneous 1979 Miscellaneous 1979 Miscellaneous 1970 Miscellaneou	Comments:	•									
2015 - Fall: No Change Comments: HA No Material Description Material Quantity Units Material Location Type Category Friable Damage Quantity Units Change in Assessment Category 9x9 floor tile- ABATED Syring: No Change Comments: 2014 - Fall: No Change Comments: 2015 - Fall: No Change Comments: 2015 - Fall: No Change Comments: 2016 - Fall: No Change Comments: 2017 - Fall: No Change Comments: 2018 - Fall: No Change Comments: 2019 - Fall: No Change Comments: 2010 - Fall: No Change Comments: 2011 - Fall: No Change Comments: 2015 - Fall: No Change Comments: 2015 - Fall: No Change	2015- Spring:	: No Change									
Comments: HA No Material Description Material Quantity Units Material Location Type Category Friable Category Type Quantity Units Damage Type Quantity Units Priable Damage Quantity Units Change Change in Assessment Category Miscellaneous Damage Type Quantity Units Change Comments: 2013 - Fall: No Change Comments: 2014 - Fall: No Change Comments: 2015 - Spring: No Change Comments: 2015 - Fall: No Change Comments: 2015 - Fall: No Change Comments:	Comments:	•									
Comments: HA No Material Description Material Quantity Units Material Location Type Category Friable Category Type Quantity Units Damage Type Quantity Units Priable Damage Quantity Units Change Change in Assessment Category Miscellaneous Damage Type Quantity Units Change Comments: 2013 - Fall: No Change Comments: 2014 - Fall: No Change Comments: 2015 - Spring: No Change Comments: 2015 - Fall: No Change Comments: 2015 - Fall: No Change Comments:	2015 - Fall: N	lo Change									
Quantity Units Type Category Type Quantity Units Wiscellaneous Wiscellaneous Wiscellaneous Version Type Quantity Units Version Type Quantity U	Comments:	•									
Quantity Units Type Category Type Quantity Units Units Miscellaneous Units Miscellaneous Units Miscellaneous Units Type Category Type Quantity Units Type Quantity Units Miscellaneous Units Miscellaneous Version In the International Internat											
2013 - Fall: No Change Comments: 2014 - Fall: No Change Comments: 2015 - Spring: No Change Comments: 2015 - Fall: No Change Comments:	HA No	Material Description		Material Location			Friable		Damage Quantity	Change in Ass	essment Category
Comments: 2014- Spring: No Change Comments: 2014 - Fall: No Change Comments: 2015- Spring: No Change Comments: 2015 - Fall: No Change	09	9x9 floor tile- ABATED				Miscellaneous				YES	X NO
2014- Spring: No Change Comments: 2014 - Fall: No Change Comments: 2015- Spring: No Change Comments: 2015 - Fall: No Change	2013 - Fall: N	lo Change									
Comments: 2014 - Fall: No Change Comments: 2015 - Fall: No Change 2015 - Fall: No Change	Comments:										
2014 - Fall: No Change Comments: 2015- Spring: No Change Comments: 2015 - Fall: No Change	2014- Spring:	: No Change									
Comments: 2015- Spring: No Change Comments: 2015 - Fall: No Change	Comments:										
2015- Spring: No Change Comments: 2015 - Fall: No Change	2014 - Fall: N	lo Change									
Comments: 2015 - Fall: No Change	Comments:										
2015 - Fall: No Change	2015- Spring:	: No Change									
	Comments:		 								
Comments:		lo Change									
	Comments:										

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
10	wallboard	450	SF	basement art room, fire pump room		Miscellaneous	No	None	0		YES	X NO
2013 - Fall	: No Change											
Comments	:Hard plaster art room]							
2014- Sprii Comments	ng: No Change :]							
2014 - Fall	: No Change				_ _							
Comments					_							
2015- Sprii	ng: No Change				7							
Comments												
2015 - Fall	: No Change				7							
Comments	:											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
11A	12x12 beige w/tan streaks floor tile mastic	1550	SF	basement - art room		Miscellaneous	No	None	0		YES	X NO
2013 - Fall	: No Change				7							
Comments												
2014 - Fall	: No Change				7							
Comments												
2014- Sprii	ng: No Change				7							
Comments												
2015 - Fall	: No Change				7							
Comments												
2015- Sprii	ng: No Change											
Comments	:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	essment Category
11B	12x12 black floor tile mastic	1000	SF	room 306	Турс	Miscellaneous	No	None	Quartity	Offits	YES	X NO
2013 - Fall: No	o Change								1			
Comments:	<u> </u>											
2014 - Fall: No	o Change											
Comments:												
2014- Spring:	No Change											
Comments:												
2015- Spring:	No Change											
Comments:												
2015 - Fall: No	o Change											
Comments:												
			T			T	T =	T =		T		
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	essment Category
11C	12x12 white floor tile mastic	1000	SF	room 306		Miscellaneous					YES	X NO
2013 - Fall: No	o Change											
Comments:												
2014- Spring:	No Change											
Comments:												
2014 - Fall: No	o Change											
Comments:												
2015- Spring:	No Change											
Comments:												
2015 - Fall: No	o Change											
Comments:												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
11D	12x12 beige streaked floor tile mastic			1st, 2nd, 3rd floor corridors (patches)		Miscellaneous	Yes				X YES	NO
			•			-						
2013 - Fall: C	Other											
Comments:2	nd and 3rd fl Blue											
					_							
2014 - Fall: N	lo Change											
Comments:	•											
2014- Spring	: No Change				7							
Comments:	<u> </u>											
2015 - Fall: N	lo Change				7							
Comments:	•]							
2015- Spring	: No Change				7							
Comments:												
					_							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category
11E	12x12 orange floor tile mastic			1st floor corridor - outside boys toilet		Miscellaneous	No				X YES	NO

2013 - Fall: Other	
Comments:N/A	

2014 - Fall: No Change	
Comments:	

2014- Spring: Other
Comments:location staff lounge 12x12

2015 - Fall: No Change	
Comments:	

2015- Spring: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	essment Category
11F	12x12 tan floor tile mastic	4770	SF	Classrooms 303, 305, 310, 311, 313, 203, 205, 208, 101, 102,105,107, engineer'sn office		Miscellaneous	No	None	0		YES	X NO
2013 - Fall: N	o Change											
Comments:	Ğ											
2014- Spring: Comments:	No Change]							
2014 - Fall: N	o Change]							
Comments:												
2015 - Fall: N	o Change											
Comments:												
2015- Spring:	No Change											
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	sessment Category
12A	9x9 black floor tile mastic (Abated)			main office - principal's office, washroom, vault		Miscellaneous					YES	X NO
2013 - Fall: N	o Change											
Comments:												
2014- Spring:	No Change											
Comments:												
2014 - Fall: N	o Change											
Comments:												
2015- Spring:	No Change											
Comments:												
2015 - Fall: N	o Change											
Comments:												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	essment Category
12B	9x9 white floor tile mastic (Abated)			main office - principal's office, bathroom & vault		Miscellaneous					YES	X NO
2013 - Fall:	No Change											
Comments:												
2014 - Fall:	No Change				7							
Comments:												
2014- Sprin	g: No Change				7							
Comments:												
2015- Sprin	g: No Change				7							
Comments:					-							
2015 Fall:	No Change				_ 							
Comments:	110 Change				-							
					_							
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Ass	essment Category
		Quantity	Units		Туре	Category		Туре	Quantity	Units	J. J. J.	
12C	9x9 green floor tile mastic			engineer's toilet		Miscellaneous					X YES	NO
2013 - Fall:	Other				7							
	cement floor											
2014- Sprin	g: No Change				7							
Comments:												
2014 - Fall:	No Change				7							
Comments:					-							
2015 Fall:	No Change				- 7							
Comments:	ino Change				_							
	a. No Chango				_ _							
Comments:	g: No Change				-							
					_							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	sessment Category
13	linoleum mastic	9	SF	basement ladie's room		Miscellaneous					YES	X NO
2013 - Fall: N	lo Change											
Comments:												
2014- Spring	: No Change											
Comments:												
2014 - Fall: N	lo Change				1							
Comments:	ge											
2015- Spring	: No Change				7							
Comments:	J											
2015 - Fall: N	lo Change											
Comments:	ge											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	sessment Category
14	12x12 floor tile mastic- ABATED			1955 building- (building demolished)		Miscellaneous					YES	X NO
2013 - Fall: N	lo Change											
Comments:	<u> </u>											
2014- Spring	· No Change											
Comments:												
2014 - Fall: N	lo Change				-]							
Comments:	io Onange											
2015- Spring	· No Chango				- 7							
Comments:	. No Change											
	la Changa				<u> </u>							
2015 - Fall: N Comments:	io Cnange											
2 3.1.1.101110.					_							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
15	9x9 floor tile mastic- ABATED			1955 building- (building demolished)		Miscellaneous					YES	X NO
2013 - Fall: I	No Change											
Comments:												
2014- Spring	g: No Change				7							
Comments:												
2014 - Fall: I	No Change				7							
Comments:	<u> </u>]							
2015- Spring	g: No Change				7							
Comments:]							
2015 - Fall: I	No Change				7							
Comments:	V											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
16	brown vinyl baseboard	200	LF	basement art room		Miscellaneous	No	None	0		YES	X NO
2013 - Fall: I	No Change				7							
Comments:												
2014- Spring	g: No Change				7							
Comments:												
2014 - Fall: I	No Change				7							
Comments:												
2015- Spring	g: No Change				7							
Comments:												
2015 - Fall: I	No Change											
Comments:	_											

				1			_					
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	sessment Category
17	brown vinyl baseboard mastic	200	LF	basement art room		Miscellaneous	No	None	0		YES	X NO
2013 - Fall: N	No Change				\neg							
Comments:												
2014- Sprinc	: No Change											
Comments:	J											
2014 - Fall: N	No Change				\neg							
Comments:	to onlango											
2015- Spring	: No Change				_							
Comments:	. No Change											
	In Ohanan				-							
2015 - Fall: Note: 1	No Change				_							
COMMITTORIO.												
HA No	Material Description	Matarial	Matarial	Material Leasting	A ala anta a	Material	Frieble	Damana	Damasa	Damassa	Change in As	
HA NO	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	sessment Category
18	drywall compound	200	SF	basement art room		Surface	No	None	0		YES	X NO
2013 - Fall: N	No Change											
Comments:	Ţ.											
2014- Spring	: No Change											
Comments:	,											
2014 - Fall: N	lo Change				\neg							
Comments:	10 Orlange											
204E Corios	No Change				<u>-</u>							
Comments:	: No Change											
					<u> </u>							
2015 - Fall: Note: 1	No Change				_							
Comments.												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
19A	12x12 green floor tile			Staff lounge - kitchen		Miscellaneous	No				X YES	NO
2013 - Fall: C Comments:W					3							
2014- Spring Comments:	: No Change				}							
2014 - Fall: N Comments:	lo Change											
2015- Spring Comments:	: No Change]							
2015 - Fall: N Comments:	lo Change											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
19B	12x12 green floor tile mastic			Staff lounge - kitchen		Miscellaneous	No				X YES	NO
2013 - Fall: C Comments:W												
2014- Spring Comments:	: No Change]							
2014 - Fall: N	lo Change											

2015- Spring: No Change

2015 - Fall: No Change

Comments:

	1	T		T		T	T =		_	T -		
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in As	sessment Category
20	Hard Plaster	4500	SF	Auditorium		Surface	No	None	500		YES	X NO
2013 - Fall:	No Change											
Comments:												
2014- Spring	g: No Change				\neg							
Comments:												
2014 - Fall:	No Change				7							
Comments:												
2015- Spring	g: No Change				\neg							
Comments:												
2015 - Fall:	No Change											
Comments:	-											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in As	sessment Category
21	ceiling plaster	10160	SF	throughout basement		Surface	Yes	None	0		YES	X NO
2013 - Fall:	No Change				7							
Comments:	Ü											
2014- Sprin	g: No Change				\neg							
Comments:												
2014 - Fall:	No Change											
Comments:	J											
2015- Spring	g: No Change											
Comments:												
2015 - Fall:	No Change											
Comments:	<u> </u>											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Type	Quantity	Units Units	Change in Assessment Category
22	12"x12" Light Blue VFT	6700	SF	Basement Storage, Boys Restroom, Lunchroom,Corridor,Girls Playroom, Room 312,		Miscellaneous	No	None	0		YES X NO
2013 - Fall: N	o Change]						
Comments:											
2014- Spring:	No Change]						
Comments:	J]						
2014 - Fall: N	lo Change]						
Comments:											
2015- Spring:	No Change]						
Comments:											
2015 - Fall: N	o Change]						
Comments:											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
23	12"x12" Light Blue VFT Mastic	6700	SF	Basement Storage, Boys Restroom, Lunchroom,Corridor,Girls Playroom, Room 312,		Miscellaneous	No	None	0		YES	X NO

2013 - Fall: No Change	
Comments:	

2014- Spring: No Change	
Comments:	

2014 - Fall: No Change
Comments:

2015- Spring: No Change
Comments:

2015 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	essment Category
24	12"x12" Dark Blue VFT	2400	SF	Basement,1st,2nd,3rd Floor Corridors, Adjust. Office,		Miscellaneous	No	None	0		YES	X NO
2013 - Fall	: No Change											
Comments	:											
2014- Sprii	ng: No Change											
Comments												
	: No Change]							
Comments	:											
	ng: No Change											
Comments	:											
	: No Change											
Comments	:											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	essment Category
25	12"x12" Dark Blue VFT Mastic	2400	SF	Basement,1st,2nd,3rd Floor Corridors, Adjust. Office,		Miscellaneous	No	None	0		YES	X NO
2013 - Fall	: No Change											
	:1st floor biege											
2014- Spri	ng: No Change											
Comments												
2014 - Fall	: No Change											
Comments	:											
2015- Spri	ng: No Change											
Comments												
2015 - Fall	: No Change				7							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	sessment Category
26	Lab Table Tops	432	SF	Room 309		Miscellaneous	No	None	0		YES	X NO
2013 - Fall: I	No Change											
Comments:												
2014- Spring	g: No Change											
Comments:												
2014 - Fall: N	No Change				7							
Comments:	10 Orlange											
	g: No Change				_							
Comments:					_							
2015 - Fall: I	No Change											
Comments:												
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Ass	sessment Category
TIA NO	Matchai Description	Quantity	Units	Waterial Education	Type	Category	Thabic	Type	Quantity	Units	Change in Ass	ocosment Oatogory
27	12"x12" Light Green VFT	3200	SF	1st Floor Corridor, Storage Room, Principles Office.		Miscellaneous	No	None	0		YES	X NO
2013 - Fall: N	No Change				1	•						
Comments:	NO Change				1							
					<u></u>							
	g: No Change											
Comments:												
2014 - Fall: N	No Change]							
Comments:	J											
201E Carina	y No Change				٦							
Comments:	g: No Change				1							
					<u></u>							
2015 - Fall: N	No Change											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
28	12"x12" Light Green VFT Mastic	3200	SF	1st Floor Corridor, Storage Room, Principles Office.		Miscellaneous	No	None	0		YES	Х NO
2013 - Fall:	No Change				1							
Comments:	-]							
2014- Sprin	g: No Change				1							
Comments:]							
2014 - Fall:	No Change				1							
Comments:	<u> </u>]							
2015- Sprin	g: No Change				1							
Comments:]							
2015 - Fall:	No Change				1							
Comments:												
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Asses	ssment Category
		Quantity	Units		Туре	Category		Туре	Quantity	Units		
29	12"x12" Dark Green VFT	3200	SF	1st Floor Corridor and Office		Miscellaneous	No	None	0		YES	X NO
2013 - Fall:	No Change				1							
Comments:]							
2014- Sprin	g: No Change				7							
Comments:]							
2014 - Fall:	No Change				1							
Comments:	go]							
2015- Sprin	g: No Change				1							
Comments:												
2015 - Fall:	No Change				7							
Comments:					1							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	sessment Category
30	12"x12" Dark Green VFT Mastic	3200	SF	1st Floor Corridor and Office		Miscellaneous	No	None	0		YES	X NO
2013 - Fall: N	o Change											
Comments:												
2014- Spring:	No Change											
Comments:	-											
2014 - Fall: N	o Change											
Comments:	.											
2015- Spring:	No Change											
Comments:	Ü											
2015 - Fall: N	o Change											
Comments:	<u> </u>											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	sessment Category
А	mag block boiler insulation- ABATED			boiler room- material abated and boiler removed in 1994		Miscellaneous					YES	X NO
2013 - Fall: N	o Change											
Comments:												
2014 - Fall: N	o Change											
Comments:	.											
2014- Spring:	No Change											
Comments:	<u> </u>											
2015- Spring:	No Change											
Comments:	<u> </u>											
2015 - Fall: N	o Change											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	essment Category
Е	cardboard pipe covering	40	SF	attic - tank		TSI	No	None	0		YES	X NO
	: No Change											
Comments	:											
2014 - Fall	: No Change											
Comments												
2014- Spri	ng: No Change											
Comments												
2015- Spri	ng: No Change											
Comments												
					<u> </u>							
Comments	: No Change											
Commonte	•											
	Two dipoles			I see a see		T. A. C. C. L.	Levis	T 6	15	T.5		
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	essment Category
F	cardboard pipe fittings	3	LF	attic - tank		TSI	Yes	None	0		YES	X NO
2013 - Fall	: No Change											
Comments												
2014- Spri	ng: No Change											
Comments												
0044	No Oboro											
Comments	: No Change ·											
	ng: No Change											
Comments	•											
	: No Change											
Comments	:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	sessment Category
G	aircell pipe insulation			original (1893) building air chamber		TSI					YES	X NO
2013 - Fall:	No Change											
Comments:												
2014 - Fall:	No Change											
Comments:	J											
2014- Sprin	g: No Change				7							
Comments:	g. 140 Orlange				-							
201E Caria	a. No Chango				= 7							
Comments:	g: No Change				+							
					_							
2015 - Fall:	No Change											
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	sessment Category
Н	aircell pipe joints	6	FITTING	basement teachers lounge		TSI	No	Dist	1		YES	X NO
2013 - Fall:	No Change				٦							
Comments:	3											
2014 - Fall:	No Change											
Comments:	140 Change											
0044 0 :	N. Ol				_							
Comments:	g: No Change											
	g: No Change											
Comments:												
2015 - Fall:	No Change											
Comments:												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	essment Category
I	preform pipe covering- ABATED			1893 building		Miscellaneous					YES	X NO
2013 - Fall: N	lo Change											
Comments:												
2014- Spring:	: No Change											
Comments:	J											
2014 - Fall: N	lo Change											
Comments:	ge											
2015- Spring:	No Change											
Comments:	. No onange											
	lo Chango				- -							
2015 - Fall: N Comments:	lo Change				-							
LIA NIS	Material Description	Matarial	Matarial	Material Legation	A = h = = + = =	Matarial	Friels	Damana	Damana	Damana	Ohanna in Ana	
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	essment Category
K	water meter packing	5	FITTING	basement fire pump room, Basement Teacher's Lounge		TSI	No	None	0		YES	X NO
2013 - Fall: N	lo Change				7							
Comments:												
2014- Spring:	No Change											
Comments:	. No onango				-							
2014 - Fall: N	lo Chango				_ _							
Comments:	lo Change											
204E Carian	No Change				-							
2015- Spring: Comments:	: No Change											
2015 - Fall: N Comments:	lo Change											
Comments:												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
0	cardboard pipe covering- ABATED			1955 addition- (building demolished)		Miscellaneous					YES	X NO
2013 - Fall: N	No Change											
Comments:												
2014- Spring	: No Change				7							
Comments:	-											
2014 - Fall: N	No Change				7							
Comments:	J											
2015- Spring	: No Change				7							
Comments:	3]							
2015 - Fall: N	No Change				7							
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
Р	cardboard pipe joint- ABATED			1955 addition- (building demolished)		Miscellaneous					YES	X NO
2013 - Fall: N	No Change				7							
Comments:												
2014 - Fall: N	No Change				7							
Comments:	J											
2014- Spring	: No Change				7							
Comments:]							
2015- Spring	: No Change				7							
Comments:]							
2015 - Fall: N	No Change				7							
Comments:	to onlingo				_							
·												

110.51	Turk tip tr	T	T	Lagren e		I sa e e e	Levis			1.5		
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
	aircell pipe insulation-			1955 building addition-	.76.4	- Carregory		- 77				
Q	ABATED			(building demolished)		Miscellaneous					YES	X NO
2013 - Fall:	No Chango				7			_				
Comments:	INO Change				-							
Oominichts.												
	g: No Change											
Comments:												
2014 - Fall:	No Change				7							
Comments:	140 Onlange											
					⊒ -,							
	g: No Change											
Comments:					_							
2015 - Fall:	No Change				7							
Comments:	onango				1							
					_							
		,			1		,	_	1			
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
		Quantity	Office	4055 addition (building	Туро	Category		Туро	Quartity	OTINO		
R	aircell pipe joints- ABATED			1955 addition- (building demolished)		Miscellaneous					YES	X NO
2013 - Fall:	No Change				7							
Comments:	Ü											
2014 Caria	a. No Chango				٦							
Comments:	g: No Change				-							
Comments.					_							
2014 - Fall:	No Change											
Comments:												
2015- Sprin	g: No Change				7							
Comments:	g											
					- -							
2015 - Fall:	No Change				4							
Comments:					_							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	sessment Category
S	Cementious Pipe Fittings			Girls and Boys bathrooms - pipe chases		TSI	No	None	0		YES	X NO
2013 - Fall: N	lo Change]							
Comments:												
2014- Spring	: No Change]							
Comments:												
2014 - Fall: N	lo Change]							
Comments:												
	: No Change]							
Comments:]							
2015 - Fall: N	lo Change]							
Comments:]							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	sessment Category
Т	Pipe Insulation			Girls and Boys bathrooms - pipe chases		TSI	No	None	0		YES	X NO
2013 - Fall: N	lo Change]							
Comments:	J											
2014- Spring	: No Change]							
Comments:												
2014 - Fall: N	lo Change]							
Comments:												
2015 - Fall: N	lo Change]							
Comments:	to onango				 							
2015- Spring	: No Change				1							
Comments:]							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	essment Category
U	incinerator brick	125	SF	boiler room		TSI	No	None			YES	X NO
	: No Change											
Comments	· ·											
2014 - Fall	: No Change				7							
Comments												
2014- Sprii	ng: No Change				7							
Comments	:											
2015- Sprii	ng: No Change				7							
Comments	:											
2015 - Fall	: No Change				7							
Comments												
					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	essment Category
V	Cementitous Pipe Fittings	10	LF	Engineer's Storage and Fire Pump Room		TSI	No	None			YES	X NO
2013 - Fall	: No Change				7							
Comments	· ·											
2014 Fall	: No Change				- 7							
Comments												
					<u> </u> -							
	ng: No Change											
Comments	•											
2015- Sprii	ng: No Change				7							
Comments												
2015 - Fall	No Change				7							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	sessment Category
W	Pipe Insulation	85	LF	Engineer's Storage and Fire Pump Room		TSI	No	None			YES	X NO
	No Change											
Comments												
2014 - Fall:	No Change				7							
Comments												
2014- Sprin	ıg: No Change				7							
Comments												
2015- Sprin	ıg: No Change				7							
Comments:												
					- ¬							
2015 - Fall: Comments:	No Change				_							
Comments	·											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	sessment Category
Χ	Material behind metal ceiling and walls	200	SF	Auditorium Fan Room		Surface	No	None			YES	X NO
2013 - Fall:	No Change				7							
Comments												
2014- Sprin	ıg: No Change				7							
Comments					1							
2014 Fall:	No Change				- 7							
Comments:					-							
					_ _							
2015- Sprir Comments:	ng: No Change											
Comments					J							
	No Change	-										
Comments:					_							

ALL LEA Responsibilities, for this school, will be met.

Lynn A.Crivello

Sym & Crwill

NOTICE TO PARENTS AND STAFF REGARDING THE ASBESTOS MANAGEMENT PLAN NOTIFICATION

School:	William H Ray School
Date:	11/5/2015
the Asbes	notify you in accordance with Illinois and Federal Asbestos Regulations, that a copy of tos Management Plan is available at each school during school hours by appointment. to review the Asbestos Management Plan must be made at least 24 hours in advance.
The last in	se be advised that CPS conducts asbestos inspections of all Schools every three years aspection was completed in 2013. Surveillances are conducted every six months.
CHECK O	<u>NE</u>
A c	copy of this notice was sent home in each child's backpack.
A c	copy of this notice was printed in the school's newsletter and sent home with each child
A c	copy of this notice was printed in the school's calendar and sent home with each child
Oth	ner.

VFT = Vinyl Floor Tile
Oracle Unit: 25071

SCHOOL'S ASBESTOS MANAGEMENT PLAN.