

Chicago Public Schools

School Shoesmith School
Address 1330 E. 50th St.

Chicago, IL 60615-

Unit 5920 Building ID 5920
Region 4 General Services Route 41

Fall 2009

6 Month Asbestos Surveillance

Asbestos Surveyor: _____

Survey Date: _____

Contact Phone #: _____

Check here if no change.

Please send a copy of this report to Lynn Crivello, 125 S. Clark St., 17th Floor, GSR #125

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	
11	Baseboards	0	LF	Throughout	Assumed	MISC	No					
3YR Inspector Comments: 2004 and 2007 Comments - This material was not observed.												
Condition Changed in Fall 2007			LF		Assumed	MISC						
Comments: Abated in 2005 - 6 rehab												
Condition Not Changed in Spring 2008			LF		Assumed	MISC						
Comments:												
Condition Not Changed in Fall 2008			LF		Assumed	MISC						
Comments:												
Condition Not Changed in Spring 2009			LF		Assumed	MISC						
Comments:												
Fall 2009												YES NO
Comment:												

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
12	Baseboard Mastic	0	LF	Throughout	Assumed	MISC	No				
3YR Inspector Comments: 2004 and 2007 Comments - This material was not observed.											
Condition Changed in Fall 2007			LF		Assumed	MISC					
Comments: Abated in 2005 - 6 rehab											
Condition Not Changed in Spring 2008			LF		Assumed	MISC					
Comments:											
Condition Not Changed in Fall 2008			LF		Assumed	MISC					
Comments:											
Condition Not Changed in Spring 2009			LF		Assumed	MISC					
Comments:											
Fall 2009											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
16	Interior Door Caulk	50	LF	Throughout Building at Entrance Doors	Chrysotile	MISC	No	None		LF	
3YR Inspector Comments: 2004 Comments - One set of doors was abated.											
Condition Not Changed in Fall 2007			LF		Chrysotile	MISC				LF	
Comments:											
Condition Not Changed in Spring 2008			LF		Chrysotile	MISC				LF	
Comments:											
Condition Not Changed in Fall 2008			LF		Chrysotile	MISC				LF	
Comments:											
Condition Not Changed in Spring 2009			LF		Chrysotile	MISC				LF	
Comments:											
Fall 2009											YES NO
Comment:											

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
20	Vibration Collar	20	LF	Kitchen Store Room	Assumed	MISC	No	None		LF	
3YR Inspector Comments:											
Condition Not Changed in Fall 2007			LF		Assumed	MISC					LF
Comments:											
Condition Not Changed in Spring 2008			LF		Assumed	MISC					LF
Comments:											
Condition Not Changed in Fall 2008			LF		Assumed	MISC					LF
Comments:											
Condition Not Changed in Spring 2009			LF		Assumed	MISC					LF
Comments:											
Fall 2009											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
21	Vault Door Insulation	28	SF	Main Office	Assumed	MISC	No	None	0	SF	
3YR Inspector Comments: The insulation is enclosed inside the vault door.											
Condition Not Changed in Fall 2007			SF		Assumed	MISC					SF
Comments:											
Condition Not Changed in Spring 2008			SF		Assumed	MISC					SF
Comments:											
Condition Not Changed in Fall 2008			SF		Assumed	MISC					SF
Comments:											
Condition Not Changed in Spring 2009			SF		Assumed	MISC					SF
Comments:											
Fall 2009											YES NO
Comment:											

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
22	Interior Fire Doors Insulation	28	SF	Boiler Room	Assumed	MISC	Yes	None	0	SF	
3YR Inspector Comments: The insulation is enclosed inside the fire doors.											
Condition Not Changed in Fall 2007			SF		Assumed	MISC				SF	
Comments:											
Condition Not Changed in Spring 2008			SF		Assumed	MISC				SF	
Comments:											
Condition Not Changed in Fall 2008			SF		Assumed	MISC				SF	
Comments:											
Condition Not Changed in Spring 2009			SF		Assumed	MISC				SF	
Comments:											
Fall 2009											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
23	Incinerator Brick	60	SF	Incinerator Room	Assumed	MISC	No	Unknown	0		
3YR Inspector Comments: 2001/2004/2007 Comments - The interior of the incinerator was inaccessible.											
Condition Changed in Fall 2007			SF		Assumed	MISC					
Comments: Removed and abated in 2005 - 6 rehab											
Condition Not Changed in Spring 2008			SF		Assumed	MISC					
Comments:											
Condition Not Changed in Fall 2008			SF		Assumed	MISC					
Comments:											
Condition Not Changed in Spring 2009			SF		Assumed	MISC					
Comments:											
Fall 2009											YES NO
Comment:											

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
24	Incinerator Brick Mortar		SF	Incinerator Room	Assumed	MISC	No				
3YR Inspector Comments: 2001 Comments - The interior of the incinerator was inaccessible. 2004 Comments - This material was not observed. 2007 Comments - This material was not observed.											
Condition Changed in Fall 2007			SF		Assumed	MISC					
Comments: Removed in 2005-6 rehab											
Condition Not Changed in Spring 2008			SF		Assumed	MISC					
Comments:											
Condition Not Changed in Fall 2008			SF		Assumed	MISC					
Comments:											
Condition Not Changed in Spring 2009			SF		Assumed	MISC					
Comments:											
Fall 2009											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
25	12" X 12" White w/Blue Speckles Floor Tile	6350	SF	See Comments for Locations	Assumed	MISC	No	None	0	SF	
3YR Inspector Comments: Locations - 1st - 2nd Floor Corridors, Classrooms, Main Office, Principal's & Asst. Principal's Office, Teacher's Resource Room, Counselor's Offices, Lunchroom and Stair Landings.											
Condition Changed in Fall 2007			SF		Assumed	MISC				SF	
Comments: Removed/abated 2005 - 6 rehab											
Condition Not Changed in Spring 2008			SF		Assumed	MISC				SF	
Comments:											
Condition Not Changed in Fall 2008			SF		Assumed	MISC				SF	
Comments:											
Condition Not Changed in Spring 2009			SF		Assumed	MISC				SF	
Comments:											
Fall 2009											YES NO
Comment:											

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
26	12" X 12" Blue Floor Tile	15170	SF	See Comments for Locations	Assumed	MISC	No	None	0	SF	
3YR Inspector Comments: Locations - 1st - 2nd Floor Corridors, Classrooms, Main Office, Principal's & Asst. Principal's Office, Teacher's Resource Room, Counselor's Offices, Lunchroom, Stair Landings, Janitor's Closets, 2nd Floor Teacher's Washroom and Stage Stair Landings.											
Condition Not Changed in Fall 2007			SF		Assumed	MISC					SF
Comments:											
Condition Not Changed in Spring 2008			SF		Assumed	MISC					SF
Comments:											
Condition Not Changed in Fall 2008			SF		Assumed	MISC					SF
Comments:											
Condition Not Changed in Spring 2009			SF		Assumed	MISC					SF
Comments:											
Fall 2009											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
27	12" X 12" Purple Floor Tile	2008	SF	1st & 2nd Floor Corridors and Stair Landings	Assumed	MISC	No	None	0	SF	
3YR Inspector Comments:											
Condition Not Changed in Fall 2007			SF		Assumed	MISC					SF
Comments:											
Condition Not Changed in Spring 2008			SF		Assumed	MISC					SF
Comments:											
Condition Not Changed in Fall 2008			SF		Assumed	MISC					SF
Comments:											
Condition Not Changed in Spring 2009			SF		Assumed	MISC					SF
Comments:											
Fall 2009											YES NO
Comment:											

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
28	Mastic Associated with 12" x 12" Floor Tile	21400	SF	Throughout School (HA 25-27)	Assumed	MISC	No	None		SF	
3YR Inspector Comments:											
Condition Not Changed in Fall 2007			SF		Assumed	MISC				SF	
Comments:											
Condition Not Changed in Spring 2008			SF		Assumed	MISC				SF	
Comments:											
Condition Not Changed in Fall 2008			SF		Assumed	MISC				SF	
Comments:											
Condition Not Changed in Spring 2009			SF		Assumed	MISC				SF	
Comments:											
Fall 2009											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
3	Hard Plaster	540	SF	Kitchen	Assumed	SURFACE	No	None	0	SF	
3YR Inspector Comments:											
Condition Not Changed in Fall 2007			SF		Assumed	SURFACE				SF	
Comments:											
Condition Not Changed in Spring 2008			SF		Assumed	SURFACE				SF	
Comments:											
Condition Not Changed in Fall 2008			SF		Assumed	SURFACE				SF	
Comments:											
Condition Not Changed in Spring 2009			SF		Assumed	SURFACE				SF	
Comments:											
Fall 2009											YES NO
Comment:											

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
30	1' x 1' Off White RPH Ceiling Tile Adhesive	0	SF	Throughout School	Assumed	MISC	No				
3YR Inspector Comments: The 1' X 1' ceiling tile system through-out the school is a spline system. This material does not exist.											
Condition Not Changed in Fall 2007			SF		Assumed	MISC					
Comments:											
Condition Not Changed in Spring 2008			SF		Assumed	MISC					
Comments:											
Condition Not Changed in Fall 2008			SF		Assumed	MISC					
Comments:											
Condition Not Changed in Spring 2009			SF		Assumed	MISC					
Comments:											
Fall 2009											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
31	1'x1' White Sm.Fissured w/RPHCeilingTile(Patching)	130	SF	Rooms 108, 106, 104 and the 2nd Floor North Stairwell and Hallway, Teachers Lounge	Assumed	MISC	Yes	None	0	SF	
3YR Inspector Comments:											
Condition Changed in Fall 2007			SF		Assumed	MISC			2	SF	
Comments: Two tiles missing in 2nd floor hallway on the north side.											
Condition Not Changed in Spring 2008			SF		Assumed	MISC				SF	
Comments:											
Condition Not Changed in Fall 2008			SF		Assumed	MISC				SF	
Comments:											
Condition Not Changed in Spring 2009			SF		Assumed	MISC				SF	
Comments:											
Fall 2009											YES NO
Comment:											

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
32	1'x1' White Lg.Fissured w/RPHCeilingTile(Patching)	283	SF	2nd Floor North Stairwell, 104, 106, 203, 206, 208, and Corridors, Teachers Lounge and Janitors clos	Assumed	MISC	Yes	None	0	SF	
3YR Inspector Comments:											
Condition Not Changed in Fall 2007			SF		Assumed	MISC				SF	
Comments:											
Condition Not Changed in Spring 2008			SF		Assumed	MISC				SF	
Comments:											
Condition Not Changed in Fall 2008			SF		Assumed	MISC				SF	
Comments:											
Condition Not Changed in Spring 2009			SF		Assumed	MISC				SF	
Comments:											
Fall 2009											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
33	1'x1' White Med.Fissuredw/RPHCeilingTile(Patching)	150	SF	Rooms 103-106 and the 1st Floor Janitor's Closet	Assumed	MISC	Yes	None	0	SF	
3YR Inspector Comments:											
Condition Not Changed in Fall 2007			SF		Assumed	MISC				SF	
Comments:											
Condition Not Changed in Spring 2008			SF		Assumed	MISC				SF	
Comments:											
Condition Not Changed in Fall 2008			SF		Assumed	MISC				SF	
Comments:											
Condition Not Changed in Spring 2009			SF		Assumed	MISC				SF	
Comments:											
Fall 2009											YES NO
Comment:											

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
34	Chalk/Marker Board Adhesive	2560	SF	1st and 2nd Floor Classrooms, Teachers Lounge and Offices	Assumed	MISC	No	None	0	SF	
3YR Inspector Comments:											
Condition Not Changed in Fall 2007			SF		Assumed	MISC				SF	
Comments:											
Condition Not Changed in Spring 2008			SF		Assumed	MISC				SF	
Comments:											
Condition Not Changed in Fall 2008			SF		Assumed	MISC				SF	
Comments:											
Condition Not Changed in Spring 2009			SF		Assumed	MISC				SF	
Comments:											
Fall 2009											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
35	2' x 2' Off-white Ceiling Tiles	2900	SF	Gym	Assumed	MISC	Yes	None	0	SF	
3YR Inspector Comments:											
Condition Not Changed in Fall 2007			SF		Assumed	MISC				SF	
Comments:											
Condition Not Changed in Spring 2008			SF		Assumed	MISC				SF	
Comments:											
Condition Not Changed in Fall 2008			SF		Assumed	MISC				SF	
Comments:											
Condition Not Changed in Spring 2009			SF		Assumed	MISC				SF	
Comments:											
Fall 2009											YES NO
Comment:											

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
36	2' x 2' Off-white Ceiling Tile Mastic	2900	SF	Gym	Assumed	MISC	No	None	0	SF	
3YR Inspector Comments:											
Condition Not Changed in Fall 2007			SF		Assumed	MISC				SF	
Comments:											
Condition Not Changed in Spring 2008			SF		Assumed	MISC				SF	
Comments:											
Condition Not Changed in Fall 2008			SF		Assumed	MISC				SF	
Comments:											
Condition Not Changed in Spring 2009			SF		Assumed	MISC				SF	
Comments:											
Fall 2009											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
37	Pipe Insulation			Crawl Spaces, Pipe Chase in Washrooms, Loft Above Stage, 101, 103 - 108, 206,	Assumed	TSI	Yes	Unknown	0	SF	
3YR Inspector Comments: 2004 Comments - The quantity of this material is not known. Accesses to pipe chase are sealed and caulked. The engineer says there is damage and it is distributed. Crawlspace areas that could be observed appeared to be fiberglass with hard elbows. Also, 25 LF of elbows are in the stage area are fiberglass insulation (in good shape), but aircell insulation may exist.											
Condition Not Changed in Fall 2007					Assumed	TSI				SF	
Comments:											
Condition Not Changed in Spring 2008					Assumed	TSI				SF	
Comments:											
Condition Not Changed in Fall 2008					Assumed	TSI				SF	
Comments:											
Condition Not Changed in Spring 2009					Assumed	TSI				SF	
Comments:											
Fall 2009											YES NO
Comment:											

VFT = Vinyl Floor Tile
 Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
38	1' X 1' Small Fissured Ceiling Tile	850	SF	101, 103-108, 206, 1st and 2nd Fl Corridors, Teachers Lounge and Janitor's Closet	Assumed	MISC	No	None	0	SF	
3YR Inspector Comments:											
Condition Not Changed in Fall 2007			SF		Assumed	MISC					SF
Comments:											
Condition Not Changed in Spring 2008			SF		Assumed	MISC					SF
Comments:											
Condition Not Changed in Fall 2008			SF		Assumed	MISC					SF
Comments:											
Condition Not Changed in Spring 2009			SF		Assumed	MISC					SF
Comments:											
Fall 2009											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
39	1' X 1' Large fissured Ceiling Tiles	253	SF	104, 106, 1st Fl Corridor, 203, 206, 208	Assumed	MISC	No	None	0	SF	
3YR Inspector Comments:											
Condition Not Changed in Fall 2007			SF		Assumed	MISC					SF
Comments:											
Condition Not Changed in Spring 2008			SF		Assumed	MISC					SF
Comments:											
Condition Not Changed in Fall 2008			SF		Assumed	MISC					SF
Comments:											
Condition Not Changed in Spring 2009			SF		Assumed	MISC					SF
Comments:											
Fall 2009											YES NO
Comment:											

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
4	Drywall	240	SF	Mechanical and Electrical Rooms	Assumed	MISC	No	None	0	SF	
3YR Inspector Comments:											
Condition Not Changed in Fall 2007											SF
Comments:											
Condition Not Changed in Spring 2008											SF
Comments:											
Condition Not Changed in Fall 2008											SF
Comments:											
Condition Not Changed in Spring 2009											SF
Comments:											
Fall 2009											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
40	Sink Undercoating	4	SF	206	Assumed	MISC	No	None	0	SF	
3YR Inspector Comments:											
Condition Not Changed in Fall 2007											SF
Comments:											
Condition Not Changed in Spring 2008											SF
Comments:											
Condition Not Changed in Fall 2008											SF
Comments:											
Condition Not Changed in Spring 2009											SF
Comments:											
Fall 2009											YES NO
Comment:											

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
41	Stair Tread Covering	416	SF	All Stairways and Stage	Assumed	MISC	No	None	0	SF	
3YR Inspector Comments:											
Condition Not Changed in Fall 2007			SF		Assumed	MISC					SF
Comments:											
Condition Not Changed in Spring 2008			SF		Assumed	MISC					SF
Comments:											
Condition Not Changed in Fall 2008			SF		Assumed	MISC					SF
Comments:											
Condition Not Changed in Spring 2009			SF		Assumed	MISC					SF
Comments:											
Fall 2009											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
42	Stair Tread Covering Mastic	416	SF	All Stairways and Stage	Assumed	MISC	No	None	0	SF	
3YR Inspector Comments:											
Condition Not Changed in Fall 2007			SF		Assumed	MISC					SF
Comments:											
Condition Not Changed in Spring 2008			SF		Assumed	MISC					SF
Comments:											
Condition Not Changed in Fall 2008			SF		Assumed	MISC					SF
Comments:											
Condition Not Changed in Spring 2009			SF		Assumed	MISC					SF
Comments:											
Fall 2009											YES NO
Comment:											

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
43	4" Black vinyl Baseboard	308	LF	Lunchroom, Offices, 100-108, 202-208, Stage, East Entrance, Library	Assumed	MISC	No	None	0	LF	
3YR Inspector Comments:											
Condition Not Changed in Fall 2007			LF		Assumed	MISC					LF
Comments:											
Condition Not Changed in Spring 2008			LF		Assumed	MISC					LF
Comments:											
Condition Not Changed in Fall 2008			LF		Assumed	MISC					LF
Comments:											
Condition Not Changed in Spring 2009			LF		Assumed	MISC					LF
Comments:											
Fall 2009											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
44	4" Black vinyl Baseboard Mastic	308	LF	Lunchroom, Offices, 100-108, 202-208, Stage, East Entrance, Library	Assumed	MISC	No	None	0	LF	
3YR Inspector Comments:											
Condition Not Changed in Fall 2007			LF		Assumed	MISC					LF
Comments:											
Condition Not Changed in Spring 2008			LF		Assumed	MISC					LF
Comments:											
Condition Not Changed in Fall 2008			LF		Assumed	MISC					LF
Comments:											
Condition Not Changed in Spring 2009			LF		Assumed	MISC					LF
Comments:											
Fall 2009											YES NO
Comment:											

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
45	Chalk Board Adhesive	1040	SF	100, 102, 104-109, Teachers Lounge and 203-208	Assumed	MISC	No	None	0	SF	
3YR Inspector Comments:											
Condition Not Changed in Fall 2007			SF		Assumed	MISC					SF
Comments:											
Condition Not Changed in Spring 2008			SF		Assumed	MISC					SF
Comments:											
Condition Not Changed in Fall 2008			SF		Assumed	MISC					SF
Comments:											
Condition Not Changed in Spring 2009			SF		Assumed	MISC					SF
Comments:											
Fall 2009											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
46	Marker Board Adhesive	960	SF	100, 102, 104-109, 203-208	Assumed	MISC	No	None	0	SF	
3YR Inspector Comments:											
Condition Not Changed in Fall 2007			SF		Assumed	MISC					SF
Comments:											
Condition Not Changed in Spring 2008			SF		Assumed	MISC					SF
Comments:											
Condition Not Changed in Fall 2008			SF		Assumed	MISC					SF
Comments:											
Condition Not Changed in Spring 2009			SF		Assumed	MISC					SF
Comments:											
Fall 2009											YES NO
Comment:											

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
47	12" X 12" Beige w/Brown Specks Floor Tile	1260	SF	Classrooms in the mobile trailer unit	Assumed	MISC	No	None	0	SF	
3YR Inspector Comments:											
Condition Not Changed in Fall 2007			SF		Assumed	MISC					SF
Comments:											
Condition Not Changed in Spring 2008			SF		Assumed	MISC					SF
Comments:											
Condition Not Changed in Fall 2008			SF		Assumed	MISC					SF
Comments:											
Condition Not Changed in Spring 2009			SF		Assumed	MISC					SF
Comments:											
Fall 2009											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
48	12" X 12" Beige w/Brown Specks Floor Tile Mastic	1260	SF	Classrooms in the mobile trailer unit	Assumed	MISC	No	None	0	SF	
3YR Inspector Comments:											
Condition Not Changed in Fall 2007			SF		Assumed	MISC					SF
Comments:											
Condition Not Changed in Spring 2008			SF		Assumed	MISC					SF
Comments:											
Condition Not Changed in Fall 2008			SF		Assumed	MISC					SF
Comments:											
Condition Not Changed in Spring 2009			SF		Assumed	MISC					SF
Comments:											
Fall 2009											YES NO
Comment:											

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
49	5" Beige Base Boards	200	LF	Classrooms in the mobile trailer unit	Assumed	MISC	No	None	0	LF	
3YR Inspector Comments:											
Condition Not Changed in Fall 2007			LF		Assumed	MISC				LF	
Comments:											
Condition Not Changed in Spring 2008			LF		Assumed	MISC				LF	
Comments:											
Condition Not Changed in Fall 2008			LF		Assumed	MISC				LF	
Comments:											
Condition Not Changed in Spring 2009			LF		Assumed	MISC				LF	
Comments:											
Fall 2009											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
50	5" Beige Base Board Mastic	200	LF	Classrooms in the mobile trailer unit	Assumed	MISC	No	None	0	LF	
3YR Inspector Comments:											
Condition Not Changed in Fall 2007			LF		Assumed	MISC				LF	
Comments:											
Condition Not Changed in Spring 2008			LF		Assumed	MISC				LF	
Comments:											
Condition Not Changed in Fall 2008			LF		Assumed	MISC				LF	
Comments:											
Condition Not Changed in Spring 2009			LF		Assumed	MISC				LF	
Comments:											
Fall 2009											YES NO
Comment:											

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
51	4' X 8' Ceiling Panels	1518	SF	All ceilings in the mobile trailer unit	Assumed	MISC	No	None	0	SF	
3YR Inspector Comments:											
Condition Not Changed in Fall 2007			SF		Assumed	MISC					SF
Comments:											
Condition Not Changed in Spring 2008			SF		Assumed	MISC					SF
Comments:											
Condition Not Changed in Fall 2008			SF		Assumed	MISC					SF
Comments:											
Condition Not Changed in Spring 2009			SF		Assumed	MISC					SF
Comments:											
Fall 2009											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
52	Insulation In Metal Walls	1780	SF	Exterior walls in the mobile trailer unit	Assumed	TSI	Yes	None	0	SF	
3YR Inspector Comments:											
Condition Not Changed in Fall 2007			SF		Assumed	TSI					SF
Comments:											
Condition Not Changed in Spring 2008			SF		Assumed	TSI					SF
Comments:											
Condition Not Changed in Fall 2008			SF		Assumed	TSI					SF
Comments:											
Condition Not Changed in Spring 2009			SF		Assumed	TSI					SF
Comments:											
Fall 2009											YES NO
Comment:											

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
53	Yellow Rolled Flooring	192	SF	Entrances and Washrooms in the mobile trailer unit	Assumed	MISC	No	None	0	SF	
3YR Inspector Comments:											
Condition Not Changed in Fall 2007											SF
Comments:											
Condition Not Changed in Spring 2008											SF
Comments:											
Condition Not Changed in Fall 2008											SF
Comments:											
Condition Not Changed in Spring 2009											SF
Comments:											
Fall 2009											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
54	Yellow Rolled Flooring Adhesive	192	SF	Entrances and Washrooms in the mobile trailer unit	Assumed	MISC	No	None	0	SF	
3YR Inspector Comments:											
Condition Not Changed in Fall 2007											SF
Comments:											
Condition Not Changed in Spring 2008											SF
Comments:											
Condition Not Changed in Fall 2008											SF
Comments:											
Condition Not Changed in Spring 2009											SF
Comments:											
Fall 2009											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
55	Interior Wall Panels	760	SF	Interior walls of the mobile trailer unit	Assumed	MISC	No	None	0	SF	
3YR Inspector Comments:											
Condition Not Changed in Fall 2007											
Comments:											
Condition Not Changed in Spring 2008											
Comments:											
Condition Not Changed in Fall 2008											
Comments:											
Condition Not Changed in Spring 2009											
Comments:											
Fall 2009											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
6A	9" x 9" Grey Floor Tile - Abated	0	SF	Center Stairwell & Room 207 & Outside Room 202, Incinerator Room, Engineer's Office, Corridors	Chrysotile	MISC	No	None		SF	
3YR Inspector Comments: 2001 Comments - No Damage floor tile was observed. No 9"x9" Grey Floor Tile was not observed in the boiler room washroom and stairs. 12"x12" Grayish Speckled floor tile was observed in the boiler room washroom and stairs. No information concerning floor tile removal or asbestos abatement was available at the school. 2004 Comments - This material was abated in 2003.											
Condition Not Changed in Fall 2007											
Comments:											
Condition Not Changed in Spring 2008											
Comments:											
Condition Not Changed in Fall 2008											
Comments:											
Condition Not Changed in Spring 2009											
Comments:											
Fall 2009											YES NO
Comment:											

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
6B	9" x 9" White Floor Tile - Abated	0	SF	Throughout Corridors & Locker Room	Chrysotile	MISC	No	None		SF	
3YR Inspector Comments: 2004 Comments - This material was abated in 2003.											
Condition Not Changed in Fall 2007			SF		Chrysotile	MISC				SF	
Comments:											
Condition Not Changed in Spring 2008			SF		Chrysotile	MISC				SF	
Comments:											
Condition Not Changed in Fall 2008			SF		Chrysotile	MISC				SF	
Comments:											
Condition Not Changed in Spring 2009			SF		Chrysotile	MISC				SF	
Comments:											
Fall 2009											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
6C	9" x 9" Black Floor Tile - Abated	0	SF	Throughout Corridors & Locker Room	Chrysotile	MISC	Yes	None		SF	
3YR Inspector Comments: 2004 Comments - This material was abated in 2003.											
Condition Not Changed in Fall 2007			SF		Chrysotile	MISC				SF	
Comments:											
Condition Not Changed in Spring 2008			SF		Chrysotile	MISC				SF	
Comments:											
Condition Not Changed in Fall 2008			SF		Chrysotile	MISC				SF	
Comments:											
Condition Not Changed in Spring 2009			SF		Chrysotile	MISC				SF	
Comments:											
Fall 2009											YES NO
Comment:											

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
6D	9" x 9" Tan w/Spots Floor Tile - Abated	0	SF	Rooms 204, 208, & 107, Lunchroom P.E., Lunchroom NW	Chrysotile	MISC	No	None		SF	
3YR Inspector Comments: 2004 Comments - This material was abated in 2003.											
Condition Not Changed in Fall 2007			SF		Chrysotile	MISC				SF	
Comments:											
Condition Not Changed in Spring 2008			SF		Chrysotile	MISC				SF	
Comments:											
Condition Not Changed in Fall 2008			SF		Chrysotile	MISC				SF	
Comments:											
Condition Not Changed in Spring 2009			SF		Chrysotile	MISC				SF	
Comments:											
Fall 2009											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
6E	9" x 9" Pink Floor Tile - Abated	0	SF	Room 100	Chrysotile	MISC	No	None		SF	
3YR Inspector Comments: 2004 Comments - This material was abated in 2003.											
Condition Not Changed in Fall 2007			SF		Chrysotile	MISC				SF	
Comments:											
Condition Not Changed in Spring 2008			SF		Chrysotile	MISC				SF	
Comments:											
Condition Not Changed in Fall 2008			SF		Chrysotile	MISC				SF	
Comments:											
Condition Not Changed in Spring 2009			SF		Chrysotile	MISC				SF	
Comments:											
Fall 2009											YES NO
Comment:											

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
6F	9" x 9" Blue Floor Tile - Abated	0	SF	Room 100	Chrysotile	MISC	No	None		SF	
3YR Inspector Comments: 2004 Comments - This material was abated in 2003.											
Condition Not Changed in Fall 2007			SF		Chrysotile	MISC				SF	
Comments:											
Condition Not Changed in Spring 2008			SF		Chrysotile	MISC				SF	
Comments:											
Condition Not Changed in Fall 2008			SF		Chrysotile	MISC				SF	
Comments:											
Condition Not Changed in Spring 2009			SF		Chrysotile	MISC				SF	
Comments:											
Fall 2009											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
6G	9" x 9" Brown w/Spots Floor Tile - Abated	0	SF	Main Office Area, Rooms 203 & 205	Chrysotile	MISC	No	None		SF	
3YR Inspector Comments: 2004 Comments - This material was abated in 2003.											
Condition Not Changed in Fall 2007			SF		Chrysotile	MISC				SF	
Comments:											
Condition Not Changed in Spring 2008			SF		Chrysotile	MISC				SF	
Comments:											
Condition Not Changed in Fall 2008			SF		Chrysotile	MISC				SF	
Comments:											
Condition Not Changed in Spring 2009			SF		Chrysotile	MISC				SF	
Comments:											
Fall 2009											YES NO
Comment:											

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
6H	9" x 9" Brown Striped Floor Tile - Abated	0	SF	Lunchroom, Rooms 103, 203, 204, 205 & 208	Chrysotile	MISC	No	None		SF	
3YR Inspector Comments: 2004 Comments - This material was abated in 2003.											
Condition Not Changed in Fall 2007			SF		Chrysotile	MISC				SF	
Comments:											
Condition Not Changed in Spring 2008			SF		Chrysotile	MISC				SF	
Comments:											
Condition Not Changed in Fall 2008			SF		Chrysotile	MISC				SF	
Comments:											
Condition Not Changed in Spring 2009			SF		Chrysotile	MISC				SF	
Comments:											
Fall 2009											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
6I	9" x 9" Grey w/Spots Floor Tile - Abated	0	SF	Rooms 104, 105, 107, 108 & 207	Chrysotile	MISC	No	None		SF	
3YR Inspector Comments: 2004 Comments - This material was abated in 2003.											
Condition Not Changed in Fall 2007			SF		Chrysotile	MISC				SF	
Comments:											
Condition Not Changed in Spring 2008			SF		Chrysotile	MISC				SF	
Comments:											
Condition Not Changed in Fall 2008			SF		Chrysotile	MISC				SF	
Comments:											
Condition Not Changed in Spring 2009			SF		Chrysotile	MISC				SF	
Comments:											
Fall 2009											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
8	9" x 9" Floor Tile Mastic			Throughout Building	Chrysotile	MISC	No				
3YR Inspector Comments: 2001 Comments - The 9" x 9" floor tile mastic was separated to associate with the corresponding floor tile during the 1998 reinspection. 2004 Comments - This material was abated in 2003.											
Condition Changed in Fall 2007					Chrysotile	MISC					
Comments: Abated/removed in 2005 - 6 rehab											
Condition Not Changed in Spring 2008					Chrysotile	MISC					
Comments:											
Condition Not Changed in Fall 2008					Chrysotile	MISC					
Comments:											
Condition Not Changed in Spring 2009					Chrysotile	MISC					
Comments:											
Fall 2009											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
8A	12" x 12" Tan Floor Tile Mastic - Abated	0	SF	North Lobby, North Stairwell & North 2nd Floor Hallway	Chrysotile	MISC	No	None		SF	
3YR Inspector Comments: 2004 Comments - This material was abated in 2003.											
Condition Not Changed in Fall 2007			SF		Chrysotile	MISC				SF	
Comments:											
Condition Not Changed in Spring 2008			SF		Chrysotile	MISC				SF	
Comments:											
Condition Not Changed in Fall 2008			SF		Chrysotile	MISC				SF	
Comments:											
Condition Not Changed in Spring 2009			SF		Chrysotile	MISC				SF	
Comments:											
Fall 2009											YES NO
Comment:											

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
8B	12" x 12" Light Brown Floor Tile Mastic - Abated	0	SF	Room 202, Entrance To 2nd Floor Bathroom	Chrysotile	MISC	No	None		SF	
3YR Inspector Comments: 2004 Comments - This material was abated in 2003.											
Condition Not Changed in Fall 2007			SF		Chrysotile	MISC				SF	
Comments:											
Condition Not Changed in Spring 2008			SF		Chrysotile	MISC				SF	
Comments:											
Condition Not Changed in Fall 2008			SF		Chrysotile	MISC				SF	
Comments:											
Condition Not Changed in Spring 2009			SF		Chrysotile	MISC				SF	
Comments:											
Fall 2009											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
8C	9" x 9" Grey Floor Tile Mastic - Abated	0	SF	Boiler Room Washroom, Center Stairwell & Room 207 & Outside Room 202	Chrysotile	MISC	No	None		SF	
3YR Inspector Comments: 2004 Comments - This material was abated in 2003.											
Condition Not Changed in Fall 2007			SF		Chrysotile	MISC				SF	
Comments:											
Condition Not Changed in Spring 2008			SF		Chrysotile	MISC				SF	
Comments:											
Condition Not Changed in Fall 2008			SF		Chrysotile	MISC				SF	
Comments:											
Condition Not Changed in Spring 2009			SF		Chrysotile	MISC				SF	
Comments:											
Fall 2009											YES NO
Comment:											

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
8D	9" x 9" White Floor Tile Mastic - Abated	0	SF	Throughout Corridors & Locker Room	Chrysotile	MISC	No	None		SF	
3YR Inspector Comments: 2004 Comments - This material was abated in 2003.											
Condition Not Changed in Fall 2007			SF		Chrysotile	MISC				SF	
Comments:											
Condition Not Changed in Spring 2008			SF		Chrysotile	MISC				SF	
Comments:											
Condition Not Changed in Fall 2008			SF		Chrysotile	MISC				SF	
Comments:											
Condition Not Changed in Spring 2009			SF		Chrysotile	MISC				SF	
Comments:											
Fall 2009											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
8E	9" x 9" Black Floor Tile Mastic - Abated	0	SF	Throughout Corridors & Locker Room	Chrysotile	MISC	No	None		SF	
3YR Inspector Comments: 2004 Comments - This material was abated in 2003.											
Condition Not Changed in Fall 2007			SF		Chrysotile	MISC				SF	
Comments:											
Condition Not Changed in Spring 2008			SF		Chrysotile	MISC				SF	
Comments:											
Condition Not Changed in Fall 2008			SF		Chrysotile	MISC				SF	
Comments:											
Condition Not Changed in Spring 2009			SF		Chrysotile	MISC				SF	
Comments:											
Fall 2009											YES NO
Comment:											

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
8F	9" x 9" Tan w/Spots Floor Tile Mastic - Abated	0	SF	Rooms 204, 208, & 107, Lunchroom P.E., Lunchroom NW	Chrysotile	MISC	No	None		SF	
3YR Inspector Comments: 2004 Comments - This material was abated in 2003.											
Condition Not Changed in Fall 2007			SF		Chrysotile	MISC				SF	
Comments:											
Condition Not Changed in Spring 2008			SF		Chrysotile	MISC				SF	
Comments:											
Condition Not Changed in Fall 2008			SF		Chrysotile	MISC				SF	
Comments:											
Condition Not Changed in Spring 2009			SF		Chrysotile	MISC				SF	
Comments:											
Fall 2009											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
8g	9" x 9" Pink Floor Tile Mastic - Abated	0	SF	Room 100	Chrysotile	MISC	No	None		SF	
3YR Inspector Comments: 2004 Comments - This material was abated in 2003.											
Condition Not Changed in Fall 2007			SF		Chrysotile	MISC				SF	
Comments:											
Condition Not Changed in Spring 2008			SF		Chrysotile	MISC				SF	
Comments:											
Condition Not Changed in Fall 2008			SF		Chrysotile	MISC				SF	
Comments:											
Condition Not Changed in Spring 2009			SF		Chrysotile	MISC				SF	
Comments:											
Fall 2009											YES NO
Comment:											

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
8h	9" x 9" Blue Floor Tile Mastic - Abated	0	SF	Room 100	Chrysotile	MISC	No	None		SF	
3YR Inspector Comments: 2004 Comments - This material was abated in 2003.											
Condition Not Changed in Fall 2007			SF		Chrysotile	MISC				SF	
Comments:											
Condition Not Changed in Spring 2008			SF		Chrysotile	MISC				SF	
Comments:											
Condition Not Changed in Fall 2008			SF		Chrysotile	MISC				SF	
Comments:											
Condition Not Changed in Spring 2009			SF		Chrysotile	MISC				SF	
Comments:											
Fall 2009											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
8i	9" x 9" Brown w/Spots Floor Tile Mastic - Abated	0	SF	Main Office Area, Rooms 203 & 205	Chrysotile	MISC	No	None		SF	
3YR Inspector Comments: 2004 Comments - This material was abated in 2003.											
Condition Not Changed in Fall 2007			SF		Chrysotile	MISC				SF	
Comments:											
Condition Not Changed in Spring 2008			SF		Chrysotile	MISC				SF	
Comments:											
Condition Not Changed in Fall 2008			SF		Chrysotile	MISC				SF	
Comments:											
Condition Not Changed in Spring 2009			SF		Chrysotile	MISC				SF	
Comments:											
Fall 2009											YES NO
Comment:											

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
8j	9" x 9" Brown Stripe Floor Tile Mastic - Abated	0	SF	Lunchroom, Rooms 103, 203, 204, & 205	Chrysotile	MISC	No	None		SF	
3YR Inspector Comments: 2004 Comments - This material was abated in 2003.											
Condition Not Changed in Fall 2007			SF		Chrysotile	MISC				SF	
Comments:											
Condition Not Changed in Spring 2008			SF		Chrysotile	MISC				SF	
Comments:											
Condition Not Changed in Fall 2008			SF		Chrysotile	MISC				SF	
Comments:											
Condition Not Changed in Spring 2009			SF		Chrysotile	MISC				SF	
Comments:											
Fall 2009											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
8k	9" x 9" Grey w/Spots Floor Tile Mastic - Abated	0	SF	Rooms 104, 105, 107, 108 & 207	Chrysotile	MISC	No	None		SF	
3YR Inspector Comments: 2004 Comments - This material was abated in 2003.											
Condition Not Changed in Fall 2007			SF		Chrysotile	MISC				SF	
Comments:											
Condition Not Changed in Spring 2008			SF		Chrysotile	MISC				SF	
Comments:											
Condition Not Changed in Fall 2008			SF		Chrysotile	MISC				SF	
Comments:											
Condition Not Changed in Spring 2009			SF		Chrysotile	MISC				SF	
Comments:											
Fall 2009											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
9	Ceramic Tile Grout	2350	SF	Kitchen/Toilets Throughout	Assumed	MISC	No	None	0	SF	
3YR Inspector Comments:											
Condition Not Changed in Fall 2007			SF		Assumed	MISC				SF	
Comments:											
Condition Not Changed in Spring 2008			SF		Assumed	MISC				SF	
Comments:											
Condition Not Changed in Fall 2008			SF		Assumed	MISC				SF	
Comments:											
Condition Not Changed in Spring 2009			SF		Assumed	MISC				SF	
Comments:											
Fall 2009											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
A	Boiler Insulation - Abated	0	SF	Boiler Room	Amosite	TSI	Yes	None		SF	
3YR Inspector Comments: 2001 Comments - Material was sampled in 1989. No damage was visible during this reinspection. 2004 Comments - This material has been abated.											
Condition Not Changed in Fall 2007			SF		Amosite	TSI				SF	
Comments:											
Condition Not Changed in Spring 2008			SF		Amosite	TSI				SF	
Comments:											
Condition Not Changed in Fall 2008			SF		Amosite	TSI				SF	
Comments:											
Condition Not Changed in Spring 2009			SF		Amosite	TSI				SF	
Comments:											
Fall 2009											YES NO
Comment:											

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
B	Tank Insulation	0	SF	Boiler Room	Assumed	TSI	Yes	None		SF	
3YR Inspector Comments: 2001 Comments - No damaged tank insulation was observed during this reinspection. 2004 Comments - This material has been abated.											
Condition Changed in Fall 2007			SF		Assumed	TSI				SF	
Comments: Abated in 2004 - 5 rehab project											
Condition Not Changed in Spring 2008			SF		Assumed	TSI				SF	
Comments:											
Condition Not Changed in Fall 2008			SF		Assumed	TSI				SF	
Comments:											
Condition Not Changed in Spring 2009			SF		Assumed	TSI				SF	
Comments:											
Fall 2009											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
C	Boiler Breeching	0	SF	Boiler Room	Amosite	TSI	Yes	None		SF	
3YR Inspector Comments: 2001 Comments - No damaged breeching was observed during this reinspection. Material was sampled in 1989. 2004 Comments - This material has been abated.											
Condition Changed in Fall 2007			SF		Amosite	TSI				SF	
Comments: Abated in 2004 - 5 rehab project											
Condition Not Changed in Spring 2008			SF		Amosite	TSI				SF	
Comments:											
Condition Not Changed in Fall 2008			SF		Amosite	TSI				SF	
Comments:											
Condition Not Changed in Spring 2009			SF		Amosite	TSI				SF	
Comments:											
Fall 2009											YES NO
Comment:											

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
D	Joint Compound Off Fiberglass Pipe Insulation	300	SF	Tunnel, Gym Teacher's Office, Equipment Room & Gym Storage Room	Chrysotile/Amosite	TSI	Yes	None		SF	
3YR Inspector Comments: 2001 Comments - No damaged fiberglass joint compound was observed during this reinspection. Material was sampled in 1989. 2004 Comments - This material has been abated in the Boiler Room.											
Condition Not Changed in Fall 2007			SF		Chrysotile/Amosite	TSI				SF	
Comments:											
Condition Not Changed in Spring 2008			SF		Chrysotile/Amosite	TSI				SF	
Comments:											
Condition Not Changed in Fall 2008			SF		Chrysotile/Amosite	TSI				SF	
Comments:											
Condition Not Changed in Spring 2009			SF		Chrysotile/Amosite	TSI				SF	
Comments:											
Fall 2009											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
E	Duct Manifold	500	SF	Mechanical Room	Chrysotile	TSI	Yes	Unknown		SF	
3YR Inspector Comments: Material was sampled in 1989. No damage was visible during this reinspection. The mechanical room was locked during the 2007 asbestos survey.											
Condition Not Changed in Fall 2007			SF		Chrysotile	TSI				SF	
Comments:											
Condition Not Changed in Spring 2008			SF		Chrysotile	TSI				SF	
Comments:											
Condition Not Changed in Fall 2008			SF		Chrysotile	TSI				SF	
Comments:											
Condition Not Changed in Spring 2009			SF		Chrysotile	TSI				SF	
Comments:											
Fall 2009											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
F	Insulation Board			Above Ceiling	Assumed	MISC	No	None		SF	
3YR Inspector Comments: 2004/2007 Comments - This material was not observed.											
Condition Not Changed in Fall 2007					Assumed	MISC				SF	
Comments:											
Condition Not Changed in Spring 2008					Assumed	MISC				SF	
Comments:											
Condition Not Changed in Fall 2008					Assumed	MISC				SF	
Comments:											
Condition Not Changed in Spring 2009					Assumed	MISC				SF	
Comments:											
Fall 2009											YES NO
Comment:											


HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
INW	Interior Window Caulk			Throughout Building	Chrysotile	MISC	No	None		SF	
3YR Inspector Comments: 2004 Comments - Abated 2005											
Condition Not Changed in Fall 2007					Chrysotile	MISC				SF	
Comments:											
Condition Not Changed in Spring 2008					Chrysotile	MISC				SF	
Comments:											
Condition Not Changed in Fall 2008					Chrysotile	MISC				SF	
Comments:											
Condition Not Changed in Spring 2009					Chrysotile	MISC				SF	
Comments:											
Fall 2009											YES NO
Comment:											

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	
OTW	Exterior Window Caulk - Not AHERA			Exterior	Chrysotile							
3YR Inspector Comments: Abated 2005												
Condition Changed in Fall 2007					Chrysotile							
Comments: Abated and removed with 2006/7 rehab												
Condition Not Changed in Spring 2008					Chrysotile							
Comments:												
Condition Not Changed in Fall 2008					Chrysotile							
Comments:												
Condition Not Changed in Spring 2009					Chrysotile							
Comments:												
Fall 2009											YES	NO
Comment:												

All LEA Responsibilities, for this school, will be met.



 Lynn A. Crivello