Chicago Public Schools

6 Month Asbestos Surveillance 2015 - Fall

29011

Oracle Unit:

Address: 6220 N Olcott Avenue Region: 01 Mail Room: Asbestos Surveyor: Bogdal, Mr. Timothy X CHECK HERE IF NO CHANGE TO ASBESTOS Survey Date: 10/28/2015 Email Address: tbogdal@cps.edu A copy of the 2013/2014 notice to parents and staff regarding the asbestos management plan notifications was distributed via: Notice printed in school's newsletter X Other email Each child's backpack Notice printed in school's calendar HA No Material Description Material Location Asbestos Friable Damage Change in Assessment Category Material Material Damage Damage Quantity Units Type Category Quantity Type YES 01 0 X NO Hard Coat Plaster Throughout 1948 2013 - Fall: No Change Comments: 2014- Spring: No Change Comments: 2014 - Fall: No Change Comments: 2015- Spring: No Change Comments: 2015 - Fall: No Change Comments:

Thomas A Edison Regional Gifted Center

School:

2220

Building ID:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	essment Category
03	9"x9" Brown w/ Orange Streaks VFT	40	SF	Main Office Storage, 1948		Miscellaneous	No	None	0		YES	X NO
2013 - Fall: N	o Change											
Comments:												
2014- Spring:	No Change											
Comments:												
2014 - Fall: N	o Change											
Comments:												
2015- Spring:	No Change											
Comments:												
2015 - Fall: N	o Change											
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	essment Category
04	12"x12" Beige w/ Brown Specks VFT	9000	SF	Main Office, 1st & 2nd Floor Corridors, Rooms 103, & 106, 1948		Miscellaneous	No	None	0		YES	X NO
2013 - Fall: N	lo Change				1							
Comments:	-											
2014- Spring:	No Change				1							
Comments:	~											
2014 - Fall: N	lo Change											
Comments:												

2015 - Fall: No Change

Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	sessment Category
05	2'x2' Acoustic Ceiling Tile	1400		Room 102, 104, 1948							YES	X NO
	No Change											
Comments:												
2014- Sprin	g: No Change											
Comments:												
2014 - Fall:	No Change											
Comments:	J											
2015- Sprin	g: No Change				\neg							
Comments:												
2015 - Fall:	No Change				\neg							
Comments:												
												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	sessment Category
07	9"x9" Brown w/ Orange	40	SF	Main Office Storage,	Турс	Miscellaneous	No	None	0	Office	YES	X NO
	Streaks VFT Mastic			1948								<u> </u>
	No Change											
Comments:												
2014- Sprin	g: No Change											
Comments:												
	No Change											
Comments:												
2015- Sprin	g: No Change											
Comments:												
2015 - Fall:	No Change											
Comments:												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
08	12"x12" Beige w/ Brown Specks VFT Mastic	9000	SF	Main Office, 1st & 2nd Floor Corridors, Room 103, 1948		Miscellaneous	No	None	0		YES	X NO
2013 - Fall	No Change											
Comments]							
2014- Sprii	ng: No Change				1							
Comments					<u> </u>							
2014 - Fall	No Change]							
Comments					<u> </u>							
2015- Sprii	ng: No Change]							
Comments					 							
2015 - Fall	No Change]							
Comments]							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
10	12"x12" Beige w/ Brown Specks VFT	8600	SF	1st & 2nd Floor Corridors, 1954		Miscellaneous	No	None	0		X YES	NO
2013 - Fall	Abated]							
Comments	:170 sq ft abated											
2014- Sprii	ng: No Change]							
Comments]							
2014 - Fall	No Change]							
Comments]							

2015 - Fall: No Change

Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	essment Category
11	12"x12" Beige w/ Brown Specks VFT Mastic	9000	SF	1st & 2nd Floor Corridors, 1954		Miscellaneous	No	None	0		X YES	NO
2013 - Fall:	Abated]							
Comments:	170 sq ft abated]							
2014- Sprin	g: No Change]							
Comments:]							
2014 - Fall: Comments:												
]							
	g: No Change				<u> </u>							
Comments:]							
	No Change											
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	essment Category
12	Linoleum Under 12"x12" Gray VFT	700	SF	Room 107, 1954		Miscellaneous	No	None			YES	X NO
2013 - Fall:	No Change]							
Comments:												
2014- Sprin	g: No Change				1							
Comments:												
2014 - Fall:	No Change				1							
Comments:	ivo change											
0045 Omnin	No Observe				1							
Comments:	g: No Change				-							
					J 1							
2015 - Fall:	No Change				1							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
14	Hard Coat Plaster	0		Throughout 1954							YES	X NO
2013 - Fall:	No Change											
Comments:												
	g: No Change											
Comments:												
	No Change											
Comments:												
	g: No Change											
Comments:												
	No Change											
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
15	Duct Vibration Isolators	0	SF	Fan Room, 1948		Miscellaneous		None			YES	X NO
2013 - Fall:	No Change											
Comments:												
2014- Sprin	g: No Change											
Comments:												
	No Change											
Comments:												
	g: No Change											
Comments:												
	No Change											
Comments:												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
16	2'x2' Tectum Ceiling Tile	2000	SF	Gym, 1948							YES	X NO
2013 - Fall	: No Change											
Comments	S:											
2014- Spri	ng: No Change											
Comments	5:											
					<u></u>							
Comments	: No Change											
Comments). 											
	ng: No Change											
Comments	S:											
2015 - Fall	: No Change											
Comments												
LIA No	Material Decements	Matarial	Matarial	Material Leasting	Ashastas	Matarial	Estable	Damasa	Damasa	Damasa	Change in Ass	C-t
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
17	9"x9" Orange w/ Beige Streaks VFT	40	SF	Main Office Storage, 1948		Miscellaneous	No	None	0		YES	X NO
2013 - Fall	: No Change											
Comments												
2014- Spri	ng: No Change											
Comments	S											
2014 - Fall	: No Change											
Comments												
2015 Spri	ng: No Change											
Comments	rig. No Change											
2015 - Fall	: No Change											
Comments	S:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	sessment Category
18	9"x9" Orange w/ Beige Streaks VFT Mastic	40	SF	Main Office Storage, 1948		Miscellaneous	No	None	0		YES	X NO
2013 - Fall:	: No Change											
Comments	:											
2014- Sprir Comments	ng: No Change :											
2014 - Fall: Comments	: No Change :											
2015- Sprir Comments	ng: No Change :											
2015 - Fall: Comments	: No Change											
Comments												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	sessment Category
19	1'x2' Black VFT	20	SF	Main Office Storage, 1948		Miscellaneous	No	None	0		YES	X NO
2013 - Fall:	: No Change											
Comments	:											
2014- Sprir	ng: No Change											
Comments												
2014 - Fall:	: No Change											
Comments												
2015- Sprir	ng: No Change											
Comments												
2015 - Fall:	: No Change											
Comments												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	essment Category
20	1'x2' Black VFT Mastic	20	SF	Main Office Storage, 1948		Miscellaneous	No	None	0		YES	X NO
2013 - Fall:	No Change]							
Comments:	J]							
2014- Spring	g: No Change											
] 1							
2014 - Fall:	No Change											
Comments:]							
2015- Spring	g: No Change]							
Comments:												
2015 - Fall:	No Change]							
Comments:	<u> </u>]							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	essment Category
21	12"x12" White w/ Beige Specks VFT	2250	SF	Main Office & Rooms 202, 200A & 200B, Room 103 (Under HA# 41)		Miscellaneous	No	None	0		YES	X NO
2013 - Fall:	No Change											

2014- Spring: No Change	
Comments:	

2014 - Fall: No Change Comments:

2015- Sp	ring: No Change
Commen	ts:

2015 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	sessment Category
22	12"x12" White w/ Beige Specks VFT Mastic	2250	SF	Main Office & Rooms 202, 200A & 200B, Room 103 (Under HA# 41)		Miscellaneous	No	None	0		YES	X NO
2013 - Fall	: No Change]							
Comments]							
2014- Spri	ng: No Change				7							
Comments					1							
					J							
	: No Change											
Comments	:											
2015- Spri	ng: No Change]							
Comments					1							
					- 1							
	: No Change											
Comments]							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	sessment Category
23	12"x12" Gray w/ White & Gray Specks VFT	1350	SF	Room 107, 1954		Miscellaneous	No	None	0		YES	X NO
2013 - Fall	: No Change				7							
Comments					1							
					7							
	ng: No Change											
Comments	j:											
2014 - Fall	: No Change				1							
Comments												
2015 Cari	ng: No Chango	-			1							
Comments	ng: No Change ·				-							
	•				1							

2015 - Fall: No Change

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	sessment Category
24	12"x12" Gray w/ White & Gray Specks VFT	1350	SF	Room 107, 1954; 1st Floor Boys and Girls Toilets and 1st Floor Corridor Patch Near Rm 102		Miscellaneous	No	None	0		YES	X NO
2013 - Fall: N	No Change				1							
Comments:												
2014- Spring Comments:	: No Change]							
2014 - Fall: N	No Change				1							
Comments:	<u> </u>]							
2015- Spring	: No Change				1							
Comments:]							
2015 - Fall: N	No Change				1							
Comments:	<u> </u>]							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	sessment Category
25	12"x12" Tan w/ Brown Specks VFT	80	SF	Room 107 Toilet & Teacher's Toilet, 1954		Miscellaneous	No	None	0		YES	X NO
2013 - Fall: N	No Change				1							
Comments:	<u> </u>]							
2014- Spring	: No Change				1							
Comments:	J	1										

2015 - Fall: No Change

Comments: Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	essment Category
26	12"x12" Tan w/ Brown Specks VFT Mastic	80	SF	Room 107 Toilet & Teacher's Toilet, 1954		Miscellaneous	No	None	0		YES	X NO
	No Change											
Comments	•											
2014- Sprir	ng: No Change											
Comments												
2014 - Fall:	No Change											
Comments												
2015- Sprir	ng: No Change											
Comments												
2015 - Fall:	No Change											
Comments												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	essment Category
27	12"x12" Dark Brown w/ Cream Streaks VFT	50	SF	107 Store Room, 1954		Miscellaneous	No	None	0		YES	X NO
2013 - Fall:	No Change											
Comments												
2014- Sprir	ng: No Change				7							
Comments												
2014 Falls	No Chango				- 7							
Comments	No Change											
					<u> </u>							
2015- Sprir Comments	ng: No Change											
Comments	•											

2015 - Fall: No Change

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	essment Category
28	12"x12" Dark Brown w/ Cream Streaks VFT Mastic	50	SF	107 Storeroom, 1954		Miscellaneous	No	None	0		YES	X NO
2013 - Fall: N	No Change				1							
Comments:	<u> </u>											
2014- Spring Comments:	: No Change]							
]							
2014 - Fall: N	No Change											
Comments:												
2015- Spring	: No Change]							
Comments:												
2015 - Fall: N	No Change				1							
Comments:	<u> </u>											
					-							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	essment Category
29	12"x12" Beige w/ Cream & Brown Streaks VFT	2750	SF	Rooms 109, 211, & 209, Rm 109 (under exisring floor tile)1954		Miscellaneous	No	None	0		YES	X NO
		<u> </u>						<u></u>				

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
29	12"x12" Beige w/ Cream & Brown Streaks VFT	2750	SF	Rooms 109, 211, & 209, Rm 109 (under exisring floor tile)1954		Miscellaneous	No	None	0		YES	X NO

2013 - Fall: No Change	
Comments:	

2014- Spring: No Change	
Comments:	

2	2014 - Fall: No Change
(Comments:

2015- Spring: No Change
Comments:

2015 - Fall: No	Change
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	essment Category
30	12"x12" Beige w/ Cream & Brown Streaks VFT Mastic	2750	SF	Rooms 109, 211, & 209, 1954		Miscellaneous	No	None	0		YES	X NO
2013 - Fall	: No Change				7							
Comments	:]							
2014- Spri	ng: No Change				7							
Comments	:]							
2014 - Fall	: No Change				7							
Comments												
2015- Spri	ng: No Change				7							
Comments]							
2015 - Fall	: No Change				7							
Comments												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	essment Category
31	12"x12" White VFT	0		Room 111 Countertop, 1954Not observed							YES	X NO
2013 - Fall	: No Change				7							
Comments]							
2014- Spri	ng: No Change				7							
Comments												
2014 - Fall	: No Change				7							
Comments												
2015- Spri	ng: No Change				7							
Comments												
2015 - Fall	: No Change											
Comments					1							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in As	sessment Category
32	12"x12" White VFT Mastic	0		Room 111 Countertop, 1954 Not observed							YES	X NO
2013 - Fall: N	lo Change											
Comments:												
2014 - Fall: N	lo Change				7							
Comments:	V											
2014- Spring	: No Change				٦							
Comments:	ge											
2015- Spring	· No Change				٦							
Comments:	. No Change											
0045 Fall N	In Ohanan				- -							
2015 - Fall: N Comments:	io Change											
Commonto.					_							
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Ac	sessment Category
TIA NO	Material Description	Quantity	Units	iviateriai Location	Type	Category	Fliable	Type	Quantity	Units	Change in As	sessment Category
33	2'x4' Speckled Ceiling Tile	9000	SF	Throughout 1948			Yes				YES	X NO
2013 - Fall: N	lo Change				7							
Comments:												
2014- Spring	: No Change				7							
Comments:												
2014 - Fall: N	lo Change				٦							
Comments:	io change											
2015- Spring	· No Chango				_ 							
Comments:	. No Change											
	la Ohana				_ _							
2015 - Fall: N Comments:	io Cnange				-							
Commonto.												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
34	2'x4' Speckled Ceiling Tile	9000	SF	Throughout 1954		Miscellaneous	Yes	None			YES	X NO
	: No Change											
Comments	:											
	ng: No Change											
Comments	:											
	: No Change											
Comments												
2015- Spri	ng: No Change				7							
Comments												
2015 - Fall	: No Change				7							
Comments												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asso	essment Category
35	Light Gray w/ Black Streaks Linoleum	0		Room 211 Countertop, 1954 Not observed							YES	X NO
2013 - Fall	: No Change				7							
Comments												
2014- Spri	ng: No Change				٦							
Comments												
2014 Fall	: No Change				_							
Comments												
					_ _							
Comments	ng: No Change											
					」 ¬							
2015 - Fall Comments	: No Change				-							
Comments												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	essment Category
36	Light Gray w/ Black Streaks Linoleum Mastic	0		Room 211 Countertop, 1954 Not observed							YES	X NO
	No Change											
Comments	:											
2014- Sprir Comments	ng: No Change :											
2014 - Fall:	No Change											
Comments												
2015- Sprir	ng: No Change											
Comments												
2015 - Fall	No Change				_							
Comments					_							
					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	essment Category
37	Exterior Window Caulk (Not Observed)	0	LF	Throughout 1948	Туро	Miscellaneous	Yes	None	0	Omic	YES	X NO
2013 - Fall	No Change											
Comments												
2014 Sprin	ng: No Change				_ 7							
Comments					-							
					→ ¬							
2014 - Fall: Comments	No Change											
					」 ■							
	ng: No Change											
Comments												
	No Change											
Comments	•											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
39	12"x12" White w/ Tan Spots VFT	1400	SF	Room 109; 111 (under HA#47), 1954		Miscellaneous	No	None	0		YES	X NO
2013 - Fall: N	lo Change				7							
Comments:	J											
2014- Spring:	: No Change				7							
Comments:												
2014 - Fall: N	lo Change				7							
Comments:												
2015- Spring:	: No Change				7							
Comments:	- True Griainge											
2015 - Fall: N	lo Change				7							
Comments:	io onango											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
40	12"x12" White w/ Tan Spots VFT Mastic	1400	SF	Room 109; 111 (under HA#47), 1954		Miscellaneous	No	None	0		YES	X NO
2013 - Fall: N	lo Change											
Comments:					_							

2014- Spring: No Change	
Comments:	

2014 - Fal	l: No Change		
Comments	S:		

2015- Spring: No Change	
Comments:	

2015 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asso	essment Category
41	12"x12" White w/ Black & Grey Streaks VFT	50	SF	MDF Room (In Library Room 207), 1954		Miscellaneous	No	None	0		YES	X NO
2013 - Fall: I	No Change				٦							
Comments:	<u> </u>											
	g: No Change											
Comments:												
2014 - Fall: I	No Change											
Comments:												
2015- Spring	g: No Change				7							
Comments:												
2015 - Fall: I	No Change				7							
Comments:	To ottomige											
					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asso	essment Category
42	12"x12" White w/ Black & Grey Streaks VFT Mastic	50	SF	MDF Room (In Library Room 207), 1954		Miscellaneous	No	None	0		YES	X NO
2013 - Fall: I	No Change				7							
					⊣							

2014- Spring: No Change	
Comments:	

2014 - Fall: No Change	
Comments:	

2015	5- Spring: No Change	
Com	nments:	

2015 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
43	12"x12" Gray & Tan VFT	50	SF	1st and 2nd floors near elevator		Miscellaneous	No	None	0		YES	X NO
2013 - Fall: N	o Change											
Comments:												
2014- Spring:	No Change]							
Comments:												
2014 - Fall: N	o Change											
Comments:												
2015- Spring:	No Change											
Comments:												
2015 - Fall: N	o Change											
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
44	12"x12" Gray & Tan VFT Mastic	50	SF	1st and 2nd floors near elevator		Miscellaneous	No	None	0		YES	X NO
2013 - Fall: N	o Change				7							
Comments:	<u> </u>]							
2014- Spring:	No Change				7							
Comments:]							
2014 - Fall: N	o Change											
Comments:												

2015 - Fall: No Change

Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	essment Category
45	12"x12" Tan w/Cream Streaks VFT	50	SF	First and Second Floor Near Elevator		Miscellaneous	No	None	0		YES	X NO
2013 - Fall: I	No Change											
	g: No Change]							
2014 - Fall: N	No Change]							
2015- Spring Comments:	g: No Change											
2015 - Fall: N	No Change				_							
					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	essment Category
46	12"x12" Tan VFT w/cream Stks Mastic	50	SF	1st and 2nd Floors Near Elevator		Miscellaneous	No	None	0		YES	X NO
2013 - Fall: Note: Comments:	No Change											
2014- Spring Comments:	g: No Change				-							
2014 - Fall: 1 Comments:	No Change				_							
2015 - Fall: N	No Change				_							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
47	12"X 12" Lt. Beige Floor Tile	850	SF	Room 111		Miscellaneous	No	None	0		YES	X NO
2013 - Fall:	No Change											
Comments:												
2014- Spring	g: No Change											
Comments:												
2014 - Fall:	No Change											
Comments:	•											
2015- Spring	g: No Change											
Comments:	<u> </u>											
2015 - Fall:	No Change											
Comments:	·····g											
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Asso	essment Category
		Quantity	Units		Туре	Category		Туре	Quantity	Units		
48	12"X 12" Lt. Beige Floor Tile MASTIC	850	SF	Room 111		Miscellaneous	No	None	0		YES	X NO
2013 - Fall:	No Change											
Comments:	Ü											
2014- Sprine	g: No Change				\neg							
Comments:												
2014 - Fall:	No Change				\neg							
2014 - Fall: Comments:	go											
2015- Spring	g: No Change											
Comments:	g 10 Onango											
2015 - Fall:	No Change				_							
Comments:	110 Onlange											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	essment Category
49	Carpet Mastic	1500	SF	Rms 207, 208 (1954 Bldg)		Miscellaneous	No	None	0		YES	X NO
2013 - Fal	: No Change				\neg							
Comments												
2014- Spri	ng: No Change											
Comments												
2014 - Fal	: No Change											
Comments	i:											
2015- Spri	ng: No Change											
Comments	:											
2015 - Fal	: No Change											
Comments).											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	essment Category
50	Drywall, Tape, and Compounds	1000	SF	Rms 207, 208 (1954 Bldg)		Miscellaneous	Yes	None	0		YES	X NO
2013 - Fal	: No Change				\neg							
Comments	· ·											
2014- Spri	ng: No Change											
Comments												

2014 - Fall: No Change

2015- Spring: No Change

2015 - Fall: No Change

Comments:

Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	essment Category
51	Vinyl Baseboard Matic	150	LF	Rms 207, 208 (1954 Bldg)		Miscellaneous	No	None	0		YES	X NO
2013 - Fall:	No Change											
Comments												
2014- Sprir	ng: No Change				7							
Comments												
2014 - Fall:	No Change				7							
Comments	:											
2015- Sprir	ng: No Change				7							
Comments												
2015 - Fall:	No Change				٦							
Comments												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	essment Category
52	Terrazzo	1200	SF	Stairwells (1948 Bldg)		Miscellaneous	No	None	0		YES	X NO
2013 - Fall:	No Change				<u> </u>							
Comments												
2014- Sprir	ng: No Change				٦							
Comments	:											
2014 - Fall:	No Change				٦							
Comments												
2015- Sprir	ng: No Change				٦							
Comments:					_							
2015 - Fall·	No Change				٦							
Comments					┥							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asso	essment Category
53	Terrazzo	600	SF	Stairwells (1954 Bldg)		Miscellaneous	No	None	0		YES	X NO
2013 - Fall	: No Change											
Comments	:											
2014- Spri	ng: No Change											
Comments	:											
2014 Fall	: No Change				٦							
Comments					-							
					<u></u>							
	ng: No Change											
Comments	<u>:</u>											
	: No Change											
Comments	:											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	essment Category
54	Carpet Mastic	200	SF	Principal's Office (1948 Bldg)		Miscellaneous	No	None	0		YES	X NO
2013 - Fall	: No Change				7							
Comments												
2014 Spri	ng: No Change				_							
Comments					_							
					⊣							
	: No Change				4							
Comments	:											
	: No Change											
Comments	:											
2015- Spri	ng: No Change				7							
Comments					1							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	essment Category
55	12"x12" brown and white VFT	800	SF	Room 206		Miscellaneous	No	None	0		YES	X NO
2013 - Fall:												
Comments:												
2014- Sprin	g: No Change											
Comments:	g. 110 Griarigo											
2044 Falls	No Change				_							
2014 - Fall: Comments:												
					_							
	g: No Change											
Comments:												
2015 - Fall:	No Change											
Comments:												
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Ass	essment Category
	material Decemption	Quantity	Units	material Essation	Туре	Category		Туре	Quantity	Units	enange in 7 too	Jacomoni Galogoly
55A	12"x12" brown and white VFT MASTIC	800	SF	Room 206		Miscellaneous	No	None	0		YES	X NO
2013 - Fall:	No Change											
Comments:												
2011 Corio	a. No Change				_							
Comments:	g: No Change											
					<u></u>							
2014 - Fall:												
Comments:												
2015 - Fall:	No Change											
Comments:												
2015 Cn=i-	a: No Change	·			\neg							
Comments:	g: No Change				-							
					ı							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
С	Paperwrap Pipe Insulation	0	LF	1st & 2nd Floor Boys Toilet Pipe Chases, 1948		Miscellaneous	Yes	None	0		YES	X NO
2013 - Fall: N	lo Change]							
Comments:	10 Onlango											
2014 - Fall: N	No Change]							
Comments:	<u> </u>]							
2014- Spring	: No Change]							
Comments:]							
2015 - Fall: N	No Change]							
Comments:]							
2015- Spring	: No Change]							
Comments:												
					•							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessi	ment Category
D	MJP E/F/V on Paperwrap Pipe Insulation	17	LF	1st & 2nd Floor Boys Toilet Pipe Chases, 1948		TSI	Yes	None	0		X YES	NO

2013 - Fall: Abated	
Comments:2nd floor slop sink 12 If abated	

2014- Spring: No Change Comments:

2014 - Fall: No Change Comments:

2015- Spring: No Change Comments:

2015 - Fall: No Change Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in As	sessment Category
J	Aircell Pipe Insulation	20	LF	1st & 2nd Floor Boy's Toilet Pipe Chases, 1948		TSI	Yes	None	0		YES	X NO
2013 - Fall: N	lo Change]							
Comments:]							
2014 - Fall: N	lo Change]							
Comments:												
2014- Spring:	: No Change]							
Comments:	Ü]							
2015 - Fall: N	lo Change]							
Comments:]							
2015- Spring:	· No Change				1							
Comments:	. No onango				-							
					-							
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in As	sessment Category
	·	Quantity	Units		Туре	Category		Туре	Quantity	Units		
L	Blown-In Insulation	0		Attic, 1948							YES	X NO
2013 - Fall: N	lo Change]							
Comments:												
2014 - Fall: N	lo Change]							
Comments:	•											
2014- Spring:	: No Change]							
Comments:												
2015 - Fall: N	lo Change]							
Comments:	io onango											
2015- Spring:	· No Change				1							
Comments:	. No onange				-							
					-							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Cł
М	2" Fiberglass Insulation	0		Attic, 1948							
2013 - Fal	I: No Change	•]	•			•		
Comments											
2014- Spri	ing: No Change										
Comments	3:										
2014 - Fal	I: No Change										
Comments	3:										
2015 - Fal	I: No Change										
Comments	3:										
2015- Spri	ing: No Change				1						

Comments:

Change in Assessment Category

YES

X NO

ALL LEA Responsibilities, for this school, will be met.

Lynn A.Crivello

Sym & Crwill

NOTICE TO PARENTS AND STAFF REGARDING THE ASBESTOS MANAGEMENT PLAN NOTIFICATION

School: Thomas A Edison Regional Gifted Center
Date: 10/27/2015
This is to notify you in accordance with Illinois and Federal Asbestos Regulations, that a copy of the Asbestos Management Plan is available at each school during school hours by appointment. Requests to review the Asbestos Management Plan must be made at least 24 hours in advance.
Also please be advised that CPS conducts asbestos inspections of all Schools every three years. The last inspection was completed in 2013. Asbestos surveillances are conducted every six months.
CHECK ONE
A copy of this notice was sent home in each child's backpack.
A copy of this notice was printed in the school's newsletter and sent home with each child
A copy of this notice was printed in the school's calendar and sent home with each child
X Other. email
A COPY OF THIS NOTICE MUST BE PLACED IN THE

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

SCHOOL'S ASBESTOS MANAGEMENT PLAN.