Chicago Public Schools

6 Month Asbestos Surveillance 2015 - Fall

29051

Oracle Unit:

Address: 3600 W. Fifth Region: 03 Mail Room: Asbestos Surveyor: Wallace, Mr. Philip John X CHECK HERE IF NO CHANGE TO ASBESTOS Survey Date: 10/28/2015 Email Address: pjwallace@cps.edu A copy of the 2013/2014 notice to parents and staff regarding the asbestos management plan notifications was distributed via: X Notice printed in school's newsletter Each child's backpack Notice printed in school's calendar Other HA No Material Description Material Location Friable Damage Change in Assessment Category Material Asbestos Material Damage Damage Quantity Units Type Category Quantity Type YES 001 0 SF X NO Sprayed On Fireproofing Second Floor Mechanical Surface 2013 - Fall: No Change Comments: 2014- Spring: No Change Comments: 2014 - Fall: No Change Comments: 2015- Spring: No Change Comments: 2015 - Fall: No Change Comments:

Leif Ericson Scholastic Academy

School:

3240

Building ID:

HA No	Material Description	Motorial	Motorial	Material Location	Ashastas	Material	Erioblo	Domogo	Domogo	Domogo	Change in Asse	ssment Category
HA INO	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
1	Sprayed on Fireproofing Insulation	0	SF	Second Floor Mechanical Room		Surface					YES	X NO
2013 - Fall:	No Change]							
Comments:	J]							
2014 - Fall:	No Chango				1							
Comments:	140 Change											
					J 1							
	g: No Change				-							
Comments:												
	g: No Change											
Comments:												
2015 - Fall:	No Change]							
Comments:	J											
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Asse	essment Category
111/11/0	Waterial Bosonphion	Quantity	Units	Waterial Location	Туре	Category	Tilabio	Type	Quantity	Units	l	comonic category
1A	Spray-on Fireproofing			Boiler Room							YES	X NO
2013 - Fall:	No Change]							
Comments:												
2014- Spring	g: No Change				1							
Comments:	g. No onange											
					1							
2014 - Fall: Comments:	No Change				-							
Comments.]							
2015 - Fall:	No Change											
Comments:												
2015- Sprine	g: No Change]							
Comments:]							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
2	Sprayed on Fireproofing	1000	SF	Second Floor Mechanical Room		Surface	Yes	None	0		YES	X NO
2013 - Fall: N Comments:	lo Change											
2014- Spring Comments:	: No Change											
2014 - Fall: N Comments:	lo Change											
2015 - Fall: N Comments:	lo Change											
2015- Spring Comments:	: No Change											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
2A	2' x 4' Random Dot Ceiling Panels	32000	SF	Lunchroom, Corridors and Classrooms		Miscellaneous	Yes	None	0		YES	X NO
2013 - Fall: N Comments:	lo Change											
2014 - Fall: N Comments:	lo Change											
2014- Spring Comments:	: No Change											
2015 - Fall: N	lo Change											

Comments:

2015- Spring: No Change

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
2B	2' x 4' Random Dot (Dense Pattern) Ceiling Panels		SF	Corridors and Classrooms		Miscellaneous					YES	X NO
2013 - Fall:	No Change											
Comments:	Ü											
2014 - Fall:	No Change				7							
Comments:	. ro on ango											
2014- Sprine	g: No Change				7							
Comments:	g											
2015 - Fall:	No Change				7							
Comments:	110 Chango											
2015- Spring	g: No Change				- 7							
Comments:	g. 140 Onlange											
					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
		Quantity	Offics		Туре	Category		Туре	Quantity	Offics		
3	1' x 1' Dotted Ceiling Tile			Special Projects Room							YES	X NO
2013 - Fall:	No Change				7							
Comments:												
2014- Spring	g: No Change				7							
Comments:	<u> </u>											
2014 - Fall:	No Change				7							
Comments:												
2015 - Fall:	No Change				7							
Comments:	. to onango											
2015- Spring	g: No Change				7							
Comments:	g. 140 Onlango				_							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
4	1' x 1' Fissured Ceiling Tile			1st Floor Rotunda							YES	X NO
2013 - Fall: N	No Change											
Comments:												
2014- Spring	ı. Damaged											
Comments:T	ile water stained											
					-							
2014 - Fall: Note:	No Change											
Comments:												
2015 - Fall: N	No Change											
Comments:												
2015- Spring	ı. No Change				\neg							
Comments:	g. 140 Onange											
		_										
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
5	9" x 9" Grey Floor Tile	2250	SF	1st Floor & 2nd Floor Rooms 201, 212, 218		Miscellaneous	No	None	0		YES	X NO
2013 - Fall: N	No Change				\neg							
Comments:	10 Onlange											
					⊣ ¬							
2014- Spring Comments:	g: No Change											
Comments.												
2014 - Fall: N Comments:	No Change											
Comments:												
2015 - Fall: N	Vo Change				\neg							
Comments:	NO Criange											
					⊣ ¬							
2015- Spring	g: No Change											
Comments:												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	essment Category
6	12" x 12" Tan Floor Tile	3000	SF	1st Floor Offices, Teacher's Lunchroom and Kitchen		Miscellaneous	No	None	0		YES	X NO
2013 - Fall: N	o Change											
Comments:	o oago											
2044 Falls N	o Change				_ _							
2014 - Fall: N Comments:	o Change											
					<u></u>							
2014- Spring:	No Change											
Comments:												
2015 - Fall: N	o Change											
Comments:	<u> </u>											
2045 Consistence	No Observe				_ _							
2015- Spring: Comments:	No Change											
Comments.												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	essment Category
7	Acoustical Ceiling Tile			Auditorium							YES	X NO
2013 - Fall: N	o Change											
Comments:	o onango											
					⊣ ¬							
2014- Spring: Comments:wa												
Comments.wa	ater damaged											
2014 - Fall: N	o Change											
Comments:												
2015 - Fall: N	o Change				7							
Comments:	o onango											
					_ ¬							
2015- Spring:	No Change				4							
Comments:												

HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Assessment Category
		Quantity	Units		Туре	Category		Туре	Quantity	Units	
8	9" x 9" Grey Floor Tile Mastic	2250	SF	1st Floor & 2nd Floor rooms 201, 212, 218		Miscellaneous	No	None	0		X YES NO
2013 - Fall	: Damaged										
	s:Tile coming up from flo	oor									
2014- Spri	ng: No Change										
Comments											
2014 - Fall	: No Change										
Comments	S:										
2015 - Fall	: No Change										
Comments	S:										
2015- Spri	ng: No Change										
Comments	S:										
HA No	Material Description	Material	Material	Material Location	Ashestos	Material	Friable	Damage	Damage	Damage	Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category
9	12" x 12" Tan Floor Tile Mastic	5355	SF	1st Floor Offices, Lunchroom and Kitchen		Miscellaneous	No	None	0		YES	X NO

2013 - Fall: No Change	
Comments:	

2014- Spring: Damaged
Comments:flood tiles coming up from floor

2014 - Fall: No Change	
Comments:	

	2015 - Fall: No Change
(Comments:

2015- Spring: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asso	essment Category
10	Insulation Inside of Vault Door	20	SF	Main Office		TSI	No	None	0		YES	X NO
2013 - Fall	: No Change											
Comments	:											
2014- Spri	ng: No Change											
Comments	:											
2014 - Fall	: No Change											
Comments												
2015 - Fall	: No Change											
Comments												
2015- Spri	ng: No Change											
Comments												
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Ass	essment Category
		Quantity	Units		Туре	Category		Туре	Quantity	Units		
11	Kiln Insulation	20	SF	Room 110		TSI	No	None	0		YES	X NO
2013 - Fall	: No Change											
Comments												
2014- Spri	ng: No Change											
Comments												
2014 - Fall	: No Change											
Comments												
201E Fall	: No Change											
Comments												
					<u> </u>							
Comments	ng: No Change ::											
	•				1							

HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Asses	ssment Category
		Quantity	Units		Type	Category		Type	Quantity	Units		
12	Stack Interior Material			Boiler Room							YES	X NO
2013 - Fall: N	No Change]							
Comments:												
2014- Spring	y: No Change]							
Comments:												
2014 - Fall: N	No Change]							
Comments:]							
2015 - Fall: N	No Change]							
Comments:]							
2015- Spring	ı: No Change]							
Comments:	•]							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
13	2' x 4' Ceiling Panels w/ Symmetrical Dots			Girl's and Boy's 1st & 2nd Floor Washrooms							YES	X NO
2013 - Fall: N	No Change]							
Comments:]							
2014- Spring	: No Change]							
Comments:]							
2014 - Fall: N	No Change]							
Comments:]							
2015 - Fall: N	No Change]							
Comments:												
	j: No Change]							
Comments:]							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
14	9" x 9" Beige Floor Tile	15200	SF	Auditorium, Vault, Rooms 101, 103, 104, 107, 108, 112, 202, 203, 206, 207, 210, 211, 214-216, 219, 220, 224		Miscellaneous	No	None	0		YES	X NO
2013 - Fall:	No Change											
Comments:												
2014- Spring: No Change												
Comments:	omments:											

2014 - Fall: No Change	
Comments:	

2015 - Fall: No Change	
Comments:	

2015- Spring: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	essment Category
15	9" x 9" Beige Floor Tile Mastic	15200	SF	Auditorium, Vault, Rooms 101, 103, 104, 107, 108, 112, 202, 203, 206, 207, 210, 211, 214-216, 219, 220, 224		Miscellaneous	No	None	0		YES	X NO
2013 - Fall:]							
Comments:												
2014- Sprin Comments:	g: No Change											
2014 - Fall: Comments:												
2015 - Fall: Comments:												
2015- Sprin Comments:	g: No Change]							
HA No	Material Description	Matarial	Matarial	Material Leasting	Ashastas	Matarial	Frieble	Damana	Damana	Damana	Channa in Ana	
HA NO	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	essment Category
16	12" x 12" Blue Floor Tile	750	SF	Room 102		Miscellaneous	No	None	0		YES	X NO
2013 - Fall:]							
Comments:												
2014- Sprin Comments:	g: No Change											
2014 - Fall: Comments:												
2015 - Fall: Comments:	No Change											
	g: No Change]							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
17	12" x 12" Blue Floor Tile Mastic			Room 102							YES	X NO
2013 - Fall: N	No Change											
Comments:												
2014- Spring	g: No Change											
Comments:	_											
2014 - Fall: N	No Change											
Comments:												
2015 - Fall: N	No Change											
Comments:	<u> </u>											
2015- Spring	g: No Change											
Comments:	<u> </u>											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
18	9' x 9' White Floor Tile	2400	SF	Rooms 109 & 115		Miscellaneous	No	None	0		YES	X NO
2013 - Fall: N	No Change											
Comments:												
2014- Spring	g: No Change											
Comments:	-											
2014 - Fall: N	No Change											
Comments:												
2015 - Fall: N	No Change											
Comments:												
2015- Spring	g: No Change											
Comments:												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
19	9' x 9' White Floor Tile Mastic	2400	SF	Rooms 109 & 115		Miscellaneous	No	None	0		YES	X NO
2013 - Fall: Comments:	No Change]							
Comments.												
2014- Spring	g: No Change											
Comments:												
2014 - Fall:	No Change											
Comments:												
2015 - Fall:	No Change											
Comments:												
2015- Spring	g: No Change				7							
Comments:												
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Asse	essment Category
TIANO	Material Description	Quantity	Units	Material Location	Type	Category	Filable	Type	Quantity	Units	Change in Asse	essinent Category
20	9" x 9" Marble Grey Floor Tile	9000	SF	1st & 2nd Floor Corridors		Miscellaneous	No	None	0		YES	X NO
2013 - Fall:	No Change				7							
Comments:	<u> </u>											
2014 Spring	g: No Change				٦							
Comments:	g. No Change				_							
2014 - Fall: Comments:	No Change											
Comments:												
2015 - Fall:	No Change											
Comments:]							

2015- Spring: No Change

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	essment Category
21	9" x 9" Marble Grey Floor Tile Mastic	9000	SF	1st & 2nd Floor Corridors		Miscellaneous	No	None	0		YES	X NO
2013 - Fall: N	lo Change]							
Comments:]							
2014- Spring:	: Damaged											
	iles coming up from flo	or]							
2014 - Fall: N	lo Change]							
Comments:	Ţ.]							
2015 - Fall: N	lo Change]							
Comments:	<u> </u>]							
2015- Spring:	: No Change]							
Comments:]							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	essment Category
22	9" x 9" Olive Green Floor Tile	1200	SF	Room 111		Miscellaneous	No	None	0		YES	X NO
2013 - Fall: N	lo Change]							
Comments:	Ţ.]							
2014- Spring:	: No Change]							
Comments:	V]							

2014 - Fall: No Change

2015 - Fall: No Change

2015- Spring: No Change

Comments:

Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
23	9" x 9" Olive Green Floor Tile Mastic	1200	SF	Room 111		Miscellaneous	No	None	0		YES	X NO
2013 - Fall: N	No Change											
Comments:												
2014- Spring	: No Change											
Comments:	J											
2014 - Fall: N	No Change											
Comments:	10 0ago											
2015 - Fall: N	No Change											
Comments:	10 Onange											
	u No Chango											
2015- Spring Comments:	j. No Change											
Commenter												
HA No	I Material December	I Maradal	I Martanial	I Matadalla andan	Ashastas	T Maria dal	Leann	I D		I B	Ohanana ta Asa	
HA NO	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
24	9" x 9" Dark Gray Floor Tile	2000	SF	1st Floor Corridor		Miscellaneous	No	None	0		YES	X NO
2013 - Fall: N	No Change											
Comments:												
2014- Spring	ı. Damaded											
Comments:ti	les coming up from floo	or										
2014 Fall: N	Jo Chango				<u> </u>							
2014 - Fall: N Comments:	NO Change											
2015 - Fall: N	No Change											
2015- Spring Comments:	g: No Change											
Comments.												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
25	9" x 9" Dark Gray Floor Tile Mastic			1st Floor Corridor							YES	X NO
2013 - Fall: N	No Change											
Comments:												
2014- Spring	: Damaged				7							
Comments:n	o tile											
2014 - Fall: N	No Change				7							
Comments:	io onango											
2015 - Fall: N	lo Change				7							
Comments:	10 Orlange				_							
	No Change				- 7							
2015- Spring Comments:	. No Change				1							
•					_							
HA No	Material Description	Material	Material	Material Location	Ashastas	Material	Friable	Damaga	Domose	Domoss	Change in Ass	essment Category
HA NO	Material Description	Quantity	Units	Material Location	Asbestos Type	Category	Filable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
26	9" x 9" Tan Floor Tile w/ Specks	150	SF	2nd Floor North Corridor End Office		Miscellaneous	No	None	0		YES	X NO
2013 - Fall: N	No Change				7							
Comments:					_							
2014- Spring	· No Change				7							
Comments:	. 140 Chango				1							
2014 - Fall: N	Jo Chango				-]							
2014 - Fall: N Comments:	NO Change											
					- 1							
2015 - Fall: N	No Change				_							
					J 7							
2015- Spring Comments:	: No Change				-							
Committee its.					1							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	essment Category
27	9" x 9" Tan Floor Tile w/ Specks Mastic	150	SF	2nd Floor North Corridor End Office		Miscellaneous	No	None	0		YES	X NO
2013 - Fall: N	lo Change											
Comments:												
2014- Spring	: No Change											
Comments:												
2014 - Fall: N	lo Change											
Comments:	_											
2015 - Fall: N	lo Change											
Comments:	•											
2015- Spring	: No Change				7							
Comments:	<u> </u>											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	essment Category
28	12" x 12" Light Beige Floor Tile	200	SF	1st Floor Foyer & Corridor by Boiler Room Stairs		Miscellaneous	No	None	0		YES	X NO
2013 - Fall: N	lo Change]							
Comments:	<u> </u>											
2014- Spring	: No Change]							
2014- Spring Comments:	J											
2014 - Fall: N	lo Change				7							
Comments:	y-											
2015 - Fall: N	lo Change											

Comments:

2015- Spring: No Change

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
29	12" x 12" Light Beige Floor Tile Mastic	200	SF	1st Floor Foyer & Corridor by Boiler Room Stairs		Miscellaneous	No	None	0		YES	X NO
2013 - Fall:	No Change											
Comments:												
2014- Sprin	g: No Change				7							
Comments:												
2014 - Fall [.]	No Change				1							
Comments:												
2015- Sprin	g: No Change				1							
Comments:												
2015 Falls	No Change				<u>-</u>]							
Comments:	No Change											
Common.					<u></u>							
	1			1	1	T					1	_
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
30	12" x 12" Brown Floor Tile	620	SF	North End of 1st Floor Corridor		Miscellaneous	No	None	0		YES	X NO
2013 - Fall:	No Change]							
Comments:												
2014- Sprin	g: Damaged				1							
	Tile coming off the floor											
2014 - Fall:	No Change				7							
Comments:	INO Change											
2045 Falls	No Change				- 1							
Comments:	No Change											
					<u></u>							
2015- Sprin	g: No Change				1							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	essment Category
31	12" x 12" Brown Floor Tile Mastic	500	SF	North End of 1st Floor Corridor		Miscellaneous	No	None	0		YES	X NO
2013 - Fall: I	No Change				7							
Comments:	<u> </u>											
2014- Spring	n: Damaged				7							
	Tile coming off floor											
2014 - Fall: I	No Change				٦							
Comments:	110 Onango											
2015 - Fall: I	No Change				_ 							
Comments:	No Change											
	N. Olasas				⊣ ¬							
Comments:	g: No Change				-							
COMMITTORING.					_							
IIA NI-	I Material December	T Maria dal	L Marta dal	L Maradal Landon	Ashastas	Lancerer	Lezani	D	I B	I B	Observe to Ass	
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	essment Category
32	Hard Ceiling Plaster			Book Room by the Gymnasium							YES	X NO
2013 - Fall: I	No Change											
Comments:	J											
2014- Spring	g: No Change				٦							
Comments:	g. 110 Onlango											
2014 - Fall: I	No Change				_ 							
Comments:	No Change											
0045	Na Ohanan				_ _							
2015 - Fall: I Comments:	No Change											
					」 ¬							
2015- Spring Comments:	g: No Change				_							
Comments.					_							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
33	12" x 12" White Floor Tile	500	SF	Auditorium		Miscellaneous	No	None	0		YES	X NO
2013 - Fall	: No Change											
Comments	:											
	ng: No Change											
Comments	:											
2014 - Fall	: No Change											
Comments	:											
2015 - Fall	: No Change											
Comments												
2015- Spri	ng: No Change											
Comments	S:											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
34	12" x 12" White Floor Tile Mastic	500	SF	Auditorium		Miscellaneous	No	None	0		YES	X NO
2013 - Fall	: No Change											
Comments												
2014- Spri	ng: No Change											
Comments): :											
2014 - Fall	: No Change											
Comments):											
2015 - Fall	: No Change											
Comments												
2015- Spri	ng: No Change											
Comments).).											

	T									T _		
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	sessment Category
		- Cuarriny	O'mio		.,,,,,	catego.y		.,,,,,	- Cuarring	00		
35	Incinerator Lining			Boiler Room		Miscellaneous					YES	X NO
2013 - Fall: N	o Change											
Comments:	ge											
					<u> </u>							
2014 - Fall: N	o Change				_							
Comments:												
2014- Spring:	No Change											
Comments:	<u> </u>											
2015 Carina	No Change				\neg							
2015- Spring: Comments:	No Change				_							
Comments.												
2015 - Fall: N	o Change											
Comments:												
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Acc	sessment Category
TIANO	Material Description	Quantity	Units	Material Location	Type	Category	THADIC	Type	Quantity	Units	Change in Ass	sessifient Category
36	Window Caulk	6300	SF	Throughout Building Interior		Miscellaneous	Yes	None	0		YES	X NO
2013 - Fall: N	o Change											
Comments:	<u> </u>											
2014 Caring	No Changa				\neg							
2014- Spring: Comments:	ino Change											
Comments.												
2014 - Fall: N	o Change											
Comments:												
2015 - Fall: N	o Change											
Comments:	o Onange											
					<u></u> -							
2015- Spring:	No Change											
Comments:												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
37	Vibration Isolator Cloth			2nd Floor Mechanical Room		Miscellaneous					YES	X NO
2013 - Fall: N	No Change											
Comments:												
2014- Spring	: No Change				7							
Comments:	<u> </u>											
2014 - Fall: N	No Change				7							
Comments:	<u> </u>											
2015 - Fall: N	No Change				٦							
Comments:	<u> </u>											
2015- Spring	: No Change											
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
38	Exterior Brick - not AHERA			Building Exterior							YES	X NO
2013 - Fall: N	No Change				7							
Comments:												
2014- Spring	: No Change				7							
Comments:	· ·											
2014 - Fall: N	No Change				7							
Comments:	.											
2015 - Fall: N	No Change				7							
Comments:	J											
2015- Spring	: No Change				\neg							
Comments:												

	T							_	_	T =		
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
	F D. I.M.	Quantity	Ornio		1,750	Galogory		1,700	Quartity	OTINO		
39	Exterior Brick Mortar - not AHERA			Building Exterior							YES	X NO
		1	l					1				
2013 - Fall: N	No Change											
Comments:												
2014- Spring	ı: No Change											
Comments:	,g											
					<u> </u>							
2014 - Fall: N	No Change											
Comments:												
2015 - Fall: N	No Change											
Comments:												
					<u> </u>							
	ı: No Change											
Comments:												
LIA NIa	Markedal Basedaria	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Asse	ssment Category
HA NO	Material Description	Ivialellai										
HA No	Material Description	Quantity	Units		Type	Category		Type	Quantity	Units	J	
					Туре	Category	Yes	Туре	Quantity			X NO
40	Water Tank Insulation			Boiler Room	Туре	Category	Yes	Type	Quantity		YES	X NO
40	Water Tank Insulation				Туре	Category	Yes	Туре	Quantity			X NO
	Water Tank Insulation				Туре	Category	Yes	Type	Quantity			X NO
40 2013 - Fall: N Comments:	Water Tank Insulation No Change				Туре	Category	Yes	Туре	Quantity			X NO
40 2013 - Fall: Note The Comments: 2014- Spring	Water Tank Insulation				Туре	Category	Yes	Туре	Quantity			X NO
40 2013 - Fall: N Comments:	Water Tank Insulation No Change				Type	Category	Yes	Туре	Quantity			X NO
40 2013 - Fall: N Comments: 2014- Spring Comments:	Water Tank Insulation No Change J: No Change				Type	Category	Yes	Туре	Quantity			X NO
40 2013 - Fall: Note The Comments: 2014- Spring	Water Tank Insulation No Change J: No Change				Type	Category	Yes	Туре	Quantity			X NO
40 2013 - Fall: N Comments: 2014- Spring Comments: 2014 - Fall: N Comments:	Water Tank Insulation No Change g: No Change No Change				Туре	Category	Yes	Туре	Quantity			X NO
40 2013 - Fall: N Comments: 2014- Spring Comments: 2014 - Fall: N Comments:	Water Tank Insulation No Change g: No Change No Change				Type	Category	Yes	Туре	Quantity			X NO
40 2013 - Fall: N Comments: 2014- Spring Comments: 2014 - Fall: N Comments:	Water Tank Insulation No Change g: No Change No Change				Type	Category	Yes	Туре	Quantity			X NO
2013 - Fall: N Comments: 2014- Spring Comments: 2014 - Fall: N Comments: 2015 - Fall: N Comments:	Water Tank Insulation No Change I: No Change No Change No Change				Type	Category	Yes	Туре	Quantity			X NO
2013 - Fall: N Comments: 2014- Spring Comments: 2014 - Fall: N Comments: 2015 - Fall: N Comments:	Water Tank Insulation No Change g: No Change No Change				Type	Category	Yes	Туре	Quantity			X NO

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
41	Wire Insulation on Stage lights	50	SF	Auditorium		Miscellaneous	No	None	0		YES	X NO
2013 - Fall:	: No Change											
Comments												
2014- Sprir	ng: No Change											
Comments												
2014 - Fall:	: No Change											
Comments	•											
2015 - Fall:	: No Change											
Comments												
2015- Sprir	ng: No Change											
Comments												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
		-		D 100 100 110			-		-	-		

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
42	9" x 9"Grey Floor Tile w/Dk & Lt Grey Streaks	11880	SF	Rooms 106, 109, 110, 113, 115, 201, 204, 205, 208, 209, 212, 213, 217, 218, 222		Miscellaneous	No	None	0		YES	X NO

2013 - Fall: No Change	
Comments:	

2014- Spring: No Change
Comments:

2014 - Fall: No Change
Comments:

2015 - Fall: No Change
Comments:

I	2015- Spring: No Change
	Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
43	9"x9"Grey Floor Tile w/Dk & Lt Grey Streaks Mastic	9600	SF	Rooms 106, 109, 110, 113, 115, 201, 204, 205, 208, 209, 212, 213, 217, 218, 222		Miscellaneous	No	None	0		YES X NO
2013 - Fall:	No Change				7						
Comments:	<u> </u>										
2014- Sprin	g: No Change				7						
Comments:											
2014 - Fall:	No Change										
Comments:											
2015 - Fall:	No Change]						
Comments:											
2015- Sprin	g: No Change]						
Comments:											
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category
44	12" x 12" Off-White Spots Floor Tile w/ White	1200	SF	Office Complex, Counselor's Office, Photo Lab, Room before 2nd Floor Mechanical Room		Miscellaneous	No	None	0		YES	X NO

2013 - Fall: No Change	
Comments:	

2014- Spring: No Change
Comments:

2014 - Fall: No Change
Comments:

2015 - Fall: No Change
Comments:

2015- Spring: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
45	12" x 12" Off-White Floor Tile w/ White Mastic	1200	SF	Office Complex, Counselor's Office, Photo Lab, Room before 2nd Floor Mechanical Room		Miscellaneous	No	None	0		YES	X NO
2012 Fall: N	lo Chango				1							
2013 - Fall: N	io Change				-							
Comments:]							
2014- Spring:	: No Change]							
Comments:]							
2014 - Fall: N	lo Chango				7							
Comments:	io Change											
Comments.]							
2015 - Fall: N	lo Change				1							
Comments:					1							
					<u>.</u>							
2015- Spring:	: No Change											
Comments:]							
<u> </u>				T				T -	_	T _		_
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
		Quantity	Office		Турс	Category		Турс	Quantity	Office		
46	12" x 12" Brown Floor Tile	200	SF	MDF Room		Miscellaneous	No	None	0		YES	X NO
40				WIDT ROOM		····oconariocac		140110			IES	X
	lo Change			WD1 ROOM	<u> </u> 			Tions	ľ		TES	X
2013 - Fall: N	lo Change			NIET KOOTII]	ood		THORE			YES	X
	lo Change			INDI KOOM]			Trong			TES	X
2013 - Fall: N Comments:	<u> </u>			INDI KOOM	<u> </u> 			THE STATE OF THE S	<u> </u>		LITES	<u> </u>
2013 - Fall: N Comments:	<u> </u>			INDI NOOM			1.0	Trons	, Control of the cont		<u></u> TES	KING
2013 - Fall: N Comments: 2014- Spring: Comments:	: No Change			INDI KOOM]	The second secon		Total	<u> </u>		LITES	KING
2013 - Fall: N Comments: 2014- Spring: Comments: 2014 - Fall: N	: No Change			INDI NOOM]	The second secon	<u> </u>	Total	<u> </u>		LITES	<u> </u>
2013 - Fall: N Comments: 2014- Spring: Comments:	: No Change			INDI KOOM				Trons	, Control of the cont		LITES	<u> </u>
2013 - Fall: N Comments: 2014- Spring: Comments: 2014 - Fall: N Comments:	: No Change lo Change			INDI KOOM				Trons			LITES	<u> </u>
2013 - Fall: N Comments: 2014- Spring: Comments: 2014 - Fall: N Comments: 2015 - Fall: N	: No Change lo Change			INDI NOOM				Trons			LITES	<u> </u>
2013 - Fall: N Comments: 2014- Spring: Comments: 2014 - Fall: N Comments:	: No Change lo Change			INDI NOOM				Trons			<u> </u>	<u> </u>
2013 - Fall: N Comments: 2014- Spring: Comments: 2014 - Fall: N Comments: 2015 - Fall: N Comments:	: No Change lo Change lo Change			INDI NOOM				Total			LITES	<u> </u>
2013 - Fall: N Comments: 2014- Spring: Comments: 2014 - Fall: N Comments: 2015 - Fall: N	: No Change lo Change lo Change			INDI NOOM				Trons			LITES	<u> </u>

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	sessment Category
47	12" x 12" Brown Floor Tile Mastic	200	SF	MDF Room		Miscellaneous	No	None	0		YES	X NO
2013 - Fall	: No Change											
Comments												
2014- Spri	ng: No Change											
					⊒ ¬							
2014 - Fall Comments	: No Change											
	: No Change											
Comments	:											
2015- Spri	ng: No Change											
Comments	:											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	sessment Category
48	12x12 Tan VFT patches	54	SF	Room 103, 115		Miscellaneous	No	Loc	0		YES	X NO
2013 - Fall	: No Change											
Comments	· ·											
2014 - Fall	: No Change				\neg							
Comments												
0011 0 :	N. O.				-							
Comments	ng: No Change											
					<u></u>							
	: No Change											
Comments	:											
2015- Spri	ng: No Change											
Comments												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	sessment Category
49	12x12 Tan VFT patches mastic	54	SF	Room 103, 115		Miscellaneous	No	None	0		YES	X NO
2013 - Fall:	: No Change											
Comments	:											
2014- Sprir	ng: No Change											
Comments	:											
2014 - Fall:	: No Change				\neg							
Comments												
2015 - Fall	: No Change											
Comments												
2015- Sprir	ng: No Change											
Comments												
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Acc	sessment Category
TIA NO	Material Description	Quantity	Units	Material Location	Type	Category	Filable	Type	Quantity	Units	Change in Ass	sessifient Category
50	12x12 Brown VFT patches	65	SF	Room 103		Miscellaneous	No	None	0		YES	X NO
2013 - Fall	: No Change	•					•					
Comments												
2014- Sprir	ng: No Change				\neg							
Comments												
2014 Falls	: No Change											
Comments												
					<u> </u>							
Comments	: No Change											
					<u> </u>							
2015- Sprir Comments	ng: No Change											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	essment Category
51	12x12 Brown VFT patches mastic	65	SF	Room 103		Miscellaneous	No	None	0		YES	X NO
2013 - Fall: N	lo Change											
Comments:												
2014- Spring: Comments:	: No Change											
2014 - Fall: N	lo Change											
Comments:												
2015 - Fall: N	lo Change											
Comments:	Ţ.											
2015- Spring:	: No Change											
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	essment Category
52	12x12 Yellow VFT patches	160	SF	Room 115, 111		Miscellaneous	No	None	0		YES	X NO
2013 - Fall: N	lo Change											
Comments:												
2014- Spring:	· No Change											
Comments:	. 110 Onlango											
2014 - Fall: N	lo Change				_							
Comments:	io Orlange											
2015 - Fall: N	lo Chongo											
Comments:	io Change											
	N. Ohman				<u> </u>							
2015- Spring: Comments:	: No Change											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	sessment Category
53	12x12 Yellow VFT mastic	160	SF	Rooms 115,111		Miscellaneous	No	None	0		YES	X NO
2013 - Fall:	No Change											
Comments												
	ng: No Change											
Comments												
	No Change											
Comments												
2015 - Fall:	No Change											
Comments												
	ng: No Change											
Comments												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	sessment Category
54	T.S.I.	10	LF	Room 113		TSI	Yes	None	0		YES	X NO
2013 - Fall:	No Change											
Comments												
2014- Sprir	ng: No Change											
Comments												
2014 - Fall:	No Change				\neg							
Comments												
2015 - Fall:	No Change											
Comments												
2015- Sprir	ng: No Change											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
55	9x9 Green floor tile	405	SF	Teacher's Lunchroom, backroom, 1st floor janitor's room		Miscellaneous	No	Dist	20		YES	X NO
2013 - Fall: N	lo Change											
Comments:												
2014- Spring	: No Change											
Comments:	Ü											
2014 - Fall: N	lo Change											
Comments:	io onango											
2015 - Fall: N	lo Change				7							
Comments:	40 Orlange											
2015- Spring	. No Changa				_ _							
Comments:	. No Change											
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Asse	essment Category
TIANO	Material Description	Quantity	Units	Waterial Education	Type	Category	THADIC	Type	Quantity	Units	Onange in Asse	SSITICITE CATEGOTY
56	9x9 green floor tile mastic	405	SF	Teacher's room, backroom, 1st floor janitor's room		Miscellaneous	No	None	0		YES	X NO
2013 - Fall: N	lo Change											
Comments:												
2014- Spring	· No Change											
Comments:	. 110 Gridings											
2014 - Fall: N	lo Change				7							
Comments:	40 Orlange											
2015 - Fall: N	la Changa				_ _							
Comments:	NO Change											
	N. Olavas				⊣ ¬							
2015- Spring Comments:	: No Change				\dashv							
					1							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	sessment Category
57	Brown Ceramic Floor Tile	2300	SF	1st, 2nd Floor Boys Bathroom		Miscellaneous	No	None	0		YES	X NO
2013 - Fall: N	lo Change											
Comments:												
2014- Spring	: No Change											
Comments:	•											
2014 - Fall: N	lo Chango											
Comments:	io Change											
2015 - Fall: N	lo Change											
Comments:												
2015- Spring	: No Change											
Comments:	•											
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Ass	sessment Category
TIANO	Material Description	Quantity	Units	Material Location	Type	Category	Filable	Type	Quantity	Units	Change in Ass	sessifient Category
58	Brown Ceramic Floor Tile Mastic	2300	SF	1st, 2nd, floor Boys Bathroom		Miscellaneous	No	None	0		YES	X NO
2013 - Fall: N	lo Change											
Comments:	io chango											
2014- Spring Comments:	: No Change											
Comments:												
2014 - Fall: N	lo Change											
Comments:												
2015 - Fall: N	lo Chango											
Comments:	io Griange											
					<u></u>							
2015- Spring	: No Change											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
59	White Grey Terrazzo	14500	SF	1st Floor Entrance and Stairs and Landings in 2nd Floor		Miscellaneous	No	None	0		YES	X NO
2013 - Fall	: No Change											
Comments	:											
2014- Spri	ng: No Change											
Comments												
2014 - Fall	: No Change											
Comments												
2015 - Fall	: No Change				\neg							
Comments												
2015- Spri	ng: No Change				٦							
Comments												
					_							
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Asse	ssment Category
		Quantity	Units		Туре	Category		Туре	Quantity	Units		
60	Blue Ceramic Floor Tile and Grout	2300	SF	1st, 2nd, Floor Girls Bathroom		Miscellaneous	No	None	0		YES	X NO
2013 - Fall	: No Change											
Comments												
2014- Spri	ng: No Change				\neg							
Comments												
2014 - Fall	: No Change											
Comments	: :											
2015 - Fall	: No Change				_ 							
Comments												
2015 Cori	na: No Chango				_ _							
Comments	ng: No Change :				\dashv							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	essment Category
61	Blue Ceramic Floor Tile Mastic	2300	SF	1st, 2nd Floor Girls Bathroom		Miscellaneous	No	None	0		YES	X NO
2013 - Fall: N Comments:	lo Change											
2014- Spring Comments:	: No Change											
2014 - Fall: N Comments:	lo Change]							
2015 - Fall: N Comments:	lo Change]							
2015- Spring Comments:	: No Change]							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	essment Category
А	Hard Joint Compound on Fiberglass Pipe Runs	210	LF	Above Ceilings in Corridors, Locker Rooms, etc.		TSI	Yes	None	0		YES	X NO
2013 - Fall: N Comments:	lo Change]							
2014- Spring Comments:	: No Change											
2014 - Fall: N Comments:	lo Change											

2015- Spring: No Change

2015 - Fall: No Change

Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
В	Insulation on Air Handling Unit			2nd Floor Mechanical Room		Miscellaneous					YES	X NO
2013 - Fall: I	No Change				7							
Comments:												
2014 - Fall: I	No Change				7							
Comments:	_											
2014- Spring	g: No Change				7							
Comments:	•											
2015- Spring	g: No Change				7							
Comments:	, ,											
2015 - Fall: I	No Change				٦							
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
С	Boiler Tank Insulation			Boiler Room		TSI					YES	X NO
2013 - Fall: I	No Change				7							
Comments:	Ŭ											
2014- Spring	g: No Change				7							
Comments:	,											
2014 - Fall: I	No Change				7							
Comments:												
2015 - Fall: I	No Change				٦							
Comments:												
2015- Spring	g: No Change				٦							
Comments:	<u> </u>											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
C 1	Metal Jacketed Tank Insulation			Boiler Room							YES	X NO
2013 - Fall: N	No Change											
Comments:												
2014- Spring	g: No Change											
Comments:												
2014 - Fall: N	No Change											
Comments:	-											
2015 - Fall: N	No Change											
Comments:	<u> </u>											
2015- Spring	g: No Change											
Comments:	<u> </u>											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
C 2	Front Boiler Gasket			Boiler Room							YES	X NO
2013 - Fall: N	No Change											
Comments:	-											
2014- Spring	g: No Change											
Comments:												
2014 - Fall: N	No Change											
Comments:	-											
2015- Spring	g: No Change											
Comments:	_											
2015 - Fall: N	No Change											
Comments:	<u> </u>											

HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Asse	essment Category
	· ·	Quantity	Units		Type	Category		Туре	Quantity	Units	Ü	3 ,
C 3	Rear Gasket on Cleaver Brooks Boiler			Boiler Room							YES	X NO
2013 - Fall: I	No Change											
Comments:	-											
2014- Spring	g: No Change											
Comments:	y o o a g o											
2014 - Fall: I	No Chango											
Comments:	No Change											
					<u>-</u> -							
2015 - Fall: I Comments:	No Change											
Comments.												
	g: No Change											
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
C 4	Boiler Burner Gasket			Boiler Room							YES	X NO
2013 - Fall: I	No Change											
Comments:	<u> </u>											
2014 - Fall: I	No Change											
Comments:	10 Onange											
0044 0	N. Observe				-							
Comments:	g: No Change											
2015 - Fall: I	No Change											
Comments:												
	g: No Change											
Comments:												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A
D	Boiler Breeching Insulation			Boiler Room		TSI					YES
2013 - Fal	II: No Change	•									
Comments	S:										
2014- Spri	ing: No Change										
Comments	S:										
2014 - Fal	II: No Change										
Comments	S:										
2015- Spri	ing: No Change										
Comments	s:										
2015 - Fal	II: No Change										

Comments:

Change in Assessment Category

X NO

ALL LEA Responsibilities, for this school, will be met.

Lynn A.Crivello

Sym & Crwill

NOTICE TO PARENTS AND STAFF REGARDING THE ASBESTOS MANAGEMENT PLAN NOTIFICATION

School:	Leif Ericson Scholastic Academy
Date:	11/2/2015
the Asbest	ootify you in accordance with Illinois and Federal Asbestos Regulations, that a copy of os Management Plan is available at each school during school hours by appointment.
Requests t	to review the Asbestos Management Plan must be made at least 24 hours in advance.
The last ins	e be advised that CPS conducts asbestos inspections of all Schools every three years. spection was completed in 2013. surveillances are conducted every six months.
CHECK ON	<u>NE</u>
A co	opy of this notice was sent home in each child's backpack.
X A co	opy of this notice was printed in the school's newsletter and sent home with each child
A co	opy of this notice was printed in the school's calendar and sent home with each child
Oth	er.
4 00DV	A OF THIS NOTICE MILET BE DIA OFD IN THE
A COPY	OF THIS NOTICE MUST BE PLACED IN THE

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

SCHOOL'S ASBESTOS MANAGEMENT PLAN.