Chicago Public Schools

6 Month Asbestos Surveillance 2015 - Fall

	School: Inter-Am Address: 851 W. V	erican Magne Vaveland	t				acle Unit: egion:	2919 01	91	Buildin Mail Ro		
X CHECK	HERE IF NO CH	ANGE TO	O ASBE	STOS S	sbestos Surveyor: urvey Date: mail Address:	11/10/201	15					
	A copy of the 2013/20 Each child's backpools		_	d staff regarding	_	-		vas distribute pol's calendar		her Postea	!	
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in As	ssessment Category
03	9"x9" Beige VFT	30	SF	Engineers Office - Bldg.	1915	Miscellaneous	No	None	0		YES	X NO
2013 - Fall: N Comments:	o Change											
2014- Spring: Comments:	No Change											
2014 - Fall: N Comments:	o Change											
2015- Spring: Comments:	No Change											
2015 - Fall: N Comments:	o Change											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category
04	12"x12" Mustard w/ White & Brown Specks VFT	1625	SF	Main Office, Stage Storage - 1915 Bldg.		Miscellaneous	No	None	0		X YES	NO
					7							
2013 - Fall: O	ther											
Comments:Er	ncapsulated											
					1							
2014- Spring:	No Change											
Comments:	-											
					1							
2014 - Fall: No	o Change											
Comments:												
					-							
2015- Spring:	No Change											
Comments:												
					_							
2015 - Fall: No	o Change											
Comments:												
	_		•		_							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	
05	Drywall Joint Compound	80	LF	Room 104, 109 - 1915 Bldg.		Miscellaneous	Yes	None	0		X YES	NO

2013 - Fall: Other		
Comments:Room 104 removed.	No change 109	

2014- Spring: No Change	
Comments:	

2014 - Fall: No Change
Comments:

2015- Spring: No Cha	nge
Comments:	

2015 - Fall: No Change	
Comments:	

HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Ass	sessment Category
		Quantity	Units		Type	Category		Type	Quantity	Units		
06	9"x9" Beige VFT Mastic	80	SF	Engineers Office - 1915 Bldg		Miscellaneous	No	None	0		YES	X NO
2013 - Fall: N	lo Change				7							
Comments:	-											
2014- Spring	: No Change											
Comments:	V											
2014 - Fall: N	lo Change											
Comments:												
2015- Spring	: No Change				1							
Comments:	.											
2015 - Fall: N	lo Change											
Comments:	J											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessr	ment Category
07	12"x12" Mustard w/ White & Brn Specks VFT Mastic	1625	SF	Main Office, Stage Storage - 1915 Bldg.		Miscellaneous	No	None	0		X YES	NO

2013 - Fall: Other	
Comments:Encapsulated	

2014- Spring: No Change Comments:

2014 - Fall: No Change Comments:

2015- Spring: No Change Comments:

2015 - Fall: No Change Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
08	9"x9" Black VFT Mastic - ABATED IN 2006	0		3rd Floor Corridor - 1936 Bldg. ABATED IN 2006		Miscellaneous		None			X YES	NO
2013 - Fall: A	Abated											
Comments:F	Report?											
2014- Spring	g: No Change]							
Comments:												
2014 - Fall: I	No Change]							
Comments:]							
2015- Spring	g: No Change				1							
Comments:	g. 140 Orlange											
2015 Falls	No Chango				- 1							
2015 - Fall: Comments:	No Change				<u> </u>							
					J							
	Tari i i i i i i i i i i i i i i i i i i	T			T		1 =	T =	T	T		
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
09	9"x9" Black VFT - ABATED IN 2006	0		3rd Floor Corridor - 1936 Bldg. ABATED IN 2006		Miscellaneous		None			X YES	NO
2013 - Fall: /	Abated]							
Comments:F]							
2014- Spring	g: No Change		-		1							
Comments:	g. 140 Onlange				-							
					4							

2015- Spring: No Change

2015 - Fall: No Change

Comments:

Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
10	12"x12" Tan w/ White & Brown Specks VFT - ABATED IN 2006			1st & 2nd Floor Corridors, Room 115 - 1936 Bldg. ABATED IN 2006							X YES	NO
2013 - Fall: A	hated				1							
Comments:R												
	•				<u>.</u>							
2014- Spring: Comments:	: No Change											
Comments:]							
2014 - Fall: N	lo Change				1							
Comments:	<u> </u>											
0045 0 :	N. O.				- 1							
2015- Spring: Comments:	: No Change											
Comments.]							
2015 - Fall: N	lo Change]							
Comments:	•											
LIA NIa	Metavial Description	Matarial	Matarial	Matarial Lagation	A a b a a t a a	I Matarial	Taialala	Damana	I Damasa	Damana	Change in Ass	
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
	12"x12" Tan w/ White &			1st & 2nd Floor Corridors,				71				
11	Brown Specks VFT Mastic - ABATED IN 2006			Room 115 - 1936 Bldg. ABATED IN 2006		Miscellaneous		None			X YES	NO
0040 5 11 4		<u> </u>		7.57.7.25 11.2000	1	ı		-I			1	
2013 - Fall: A Comments:R	abated				-							
Comments.R	eport?]							
2014- Spring:	: No Change]							
Comments:	-											
0044 Fall N	la Ohanana				1							
2014 - Fall: N Comments:	io Change											
Comments.					J							
2015- Spring:	: No Change				1							
Comments:												
2015 - Fall: N	lo Chango											
ZUID - Fall. IN	io Griariye				ĺ							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
14	9"x9" Brown VFT ABATED IN 2006			3rd Floor Corridor - 1936 Bldg. ABATED IN 2006		Miscellaneous		None			X YES	NO
2013 - Fall:	Abated				7							
Comments:												
2014- Sprin	g: No Change				1							
Comments:					1							
					<u>.</u> 7							
	No Change											
Comments]							
2015- Sprir	g: No Change				1							
Comments												
2015 - Fall:	No Change				1							
Comments:												
Comments					J							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
15	9"x9" Brown VFT Mastic ABATED IN 2006			3rd Fl Corridor - 1936 Bldg. ABATED IN 2006		Miscellaneous		None			X YES	NO
2013 - Fall:	Abated]							
Comments												
2211 2					<u>.</u> 1							
	g: No Change				-							
Comments]							
2014 - Fall:	No Change				1							
Comments												
2015- Sprir	g: No Change				1							
Comments:					1							
					_							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
16	12"x12" Mustard w/ Brown & White Specks VFT	155	SF	3rd Floor Teachers Toilet , Room 327- 1936 Bldg.		Miscellaneous	No	None	0		YES X NO
2013 - Fall: N	No Change]						
Comments:	<u> </u>										
2014- Spring	g: No Change]						
Comments:]						
2014 - Fall: N	No Change]						
Comments:											
	g: No Change										
Comments:											
2015 - Fall: N	No Change				1						
Comments:	•]						
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessi	ment Category
17	12"x12" Mustard w/ Brown & White Specks VFT Mastic	155	SF	3rd Floor Teachers Toilet , Room 327- 1936 Bldg.		Miscellaneous	No	None	0		YES	X NO

2013 - Fall: No Change	
Comments:	

2014- Spring: No Change	
Comments:	

2014 - Fall: No Change	
Comments:	

2015- Spring: No Change	
Comments:	

2015 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
18	12"x24" Black VFT ABATED IN 2006			3rd Fl Corridor Border - 1936 Bldg. ABATED IN 2006		Miscellaneous		None			X YES	NO
2013 - Fall: Al	hated				7							
Comments:Re												
	•											
2014- Spring:	No Change											
Comments:												
2014 - Fall: N	o Change											
Comments:	o onango											
2015- Spring:	No Change											
Comments:												
2015 - Fall: N	o Change											
Comments:	o onango											
		•										
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
19	12"x24" Black VFT Mastic ABATED IN 2006			3rd FI Corridor Border - 1936 Bldg, ABATED IN 2006							X YES	NO
2013 - Fall: Al	hatad											
Comments:Re												
Comments.re	ороп:											
2014- Spring:	No Change											
Comments:												
2014 - Fall: N	o Chango				7							
Comments:	o Change											
Comments:												
2015- Spring:	No Change											
Comments:												
2015 - Fall: N	o Change				7							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in As	sessment Category
20	Hard Coat Plaster	0		Throughout - 1936 Bldg.							YES	X NO
2013 - Fall: N	No Change]							
Comments:												
2014- Spring	: No Change]							
Comments:												
2014 - Fall: N	No Change]							
Comments:												
2015- Spring	: No Change]							
Comments:]							
2015 - Fall: N	No Change]							
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in As	sessment Category
21	12"x12" Beige w/ White & Brown Streaks VFT	500	SF	2nd Floor SE Stairs Toilet and 1st FLoor Southeast Stairs Womens Toilet - 1915 Bldg.		Miscellaneous	No	None	0		YES	X NO
2013 - Fall: N	No Change				1							
Comments:	J]							
2014- Spring	: No Change				ĺ							
Comments:]							
2014 - Fall: N	No Change				1							
Comments:]							
2015- Spring	: No Change				1							
Comments:	•]							
2015 - Fall: N	No Change				1							
Comments:												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
22	12"x12" Beige w/ White & Brown Streaks VFT Mastic	500	SF	2nd Floor SE Stairs Toilet and 1st floor Southeast Stairs Womens Toilet - 1915 Bldg.		Miscellaneous	No	None	0		YES	X NO
2013 - Fall: N	No Change]							
Comments:	-]							
2014- Spring	g: No Change]							
Comments:	.]							
2014 - Fall: N	No Change]							
Comments:]							
2015- Spring	g: No Change]							
Comments:												
2015 - Fall: N	No Change]							
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
23	12"x12" Tan w/ White & Brown Flecks VFT	600	SF	2nd Floor Room 230 (Former Kitchen) - 1915 Bldg.		Miscellaneous	No	None	0		YES	X NO
2013 - Fall: N	No Change	•	•	•]	-	•	•	•	•	,	

2013 - Fall: No Change
Comments:

2014- Spring: No Change Comments:

2014 - Fall: No Change Comments:

2015- Spring: No Change

Comments:

2015 - Fall: No Change

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
24	12"x12" Tan w/ White & Brown Flecks VFT Mastic	600	SF	2nd Floor Room 230 (Former Kitchen) - 1915 Bldg.		Miscellaneous	No	None	0		YES	X NO
2013 - Fall	: No Change											
Comments												
0044 0	an Na Ohanan				- 7							
Comments	ng: No Change				-							
Comments	•											
	: No Change											
Comments	•											
2015- Sprin	ng: No Change				7							
Comments					1							
					<u>-</u>							
	: No Change											
Comments												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
25	12"x12" Beige w/ Brown & White Specks VFT	600	SF	2nd Floor Room 230 (Former Kitchen) - 1915 Bldg.		Miscellaneous	No	None	0		YES	X NO
2013 - Fall	: No Change				7							
Comments												
					<u>-</u>							
	ng: No Change				4							
Comments												
2014 - Fall	: No Change				7							
Comments	:											
2015- Sprie	ng: No Change				7							
Comments					1							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
26	12"x12" Beige w/ Brown & White Specks VFT Mastic	600	SF	2nd Floor Room 230 (Former Kitchen) - 1915 Bldg.		Miscellaneous	No	None	0		YES	X NO
2013 - Fall	: No Change				7							
Comments					1							
2014 Cpris	ay No Changa				- 7							
Comments	ng: No Change				+							
					_ _							
	: No Change											
Comments	•											
2015- Sprir	ng: No Change				7							
Comments												
2015 Falls	: No Change				٦							
Comments					-							
Commonto	•											
		_										
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
27	9"x9" Tan w/ Black & White Streaks VFT	310	SF	1st FIr NE Stairwell Teachers (W) Toilet - 1915 Bldg.		Miscellaneous	No	None	0		YES	X NO
2013 - Fall:	: No Change				7							
Comments												
0044 0	. N. Olasas				_ ¬							
Comments	ng: No Change				+							
Comments	•											
	: No Change											
Comments	:											
2015- Sprir	ng: No Change				1							
Comments												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	sessment Category
28	9"x9" Tan w/ Black & White Streaks VFT Mastic	310	SF	1st Flr NE Stairwell Teachers (W) Toilet - 1915 Bldg.		Miscellaneous	No	None	0		YES	X NO
2013 - Fall	: No Change				\neg							
Comments												
					- -							
	ng: No Change				_							
Comments	:											
2014 - Fall	: No Change											
Comments												
2045 Cm #i	an Na Changa				\neg							
Comments	ng: No Change											
Comments	•											
2015 - Fall	: No Change											
Comments												
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Ass	sessment Category
10110	Material Boompton	Quantity	Units	Material Ecoation	Туре	Category	Thablo	Type	Quantity	Units	Change in 7100	occomonic category
29	9"x9" Chocolate w/ Wht & Dk. Brown Strks VFT	75	SF	1st Floor NE Stairwell Teachers (W) Toilet - 1915 Bldg.		Miscellaneous	No	None	0		YES	X NO
2013 - Fall	: No Change				\neg							
Comments												
					-							
	ng: No Change											
Comments	•											
2014 - Fall	: No Change											
Comments												
2045 0	an Na Change	<u> </u>			\neg							
Comments	ng: No Change				\dashv							
COHINEINS												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	essment Category
30	9"x9" Chocolate w/ Wht & Dk. Brwn Strks VFT Mastic	75	SF	1st Floor NE Stairwell Teachers (W) Toilet - 1915 Bldg.		Miscellaneous	No	None	0		YES	X NO
2013 - Fall:	No Change				1							
Comments:]							
2014 Sprin	g: No Change				1							
Comments:	<u> </u>				-							
					_							
	No Change											
Comments:												
2015- Sprir	g: No Change]							
Comments:												
2045 Falls	No Change				1							
Comments:	No Change				-							
Comments.]							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	essment Category
31	9"x9" Tan w/ Orange & Cream Streaks VFT	40	SF	Boiler Room Toilet - 1915 Bldg.		Miscellaneous	No	None	0		YES	X NO
2013 - Fall:	No Change				1							
Comments:												
0044 Omnin	an Na Ohanan				- 1							
Comments:	g: No Change											
Comments.]							
2014 - Fall:	No Change]							
Comments:	-]							
2015- Sprin	ıg: No Change				1							
Comments:					1							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
32	9"x9" Tan w/ Orange & Cream Streaks VFT Mastic	40	SF	Boiler Room Toilet - 1915 Bldg.		Miscellaneous	No	None	0		YES	X NO
	No Change]							
Comments	•											
2014- Sprir Comments	ng: No Change :											
2014 - Fall:	No Change]							
Comments												
2015- Sprir	ng: No Change]							
Comments												
2015 - Fall:	No Change				1							
Comments												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
33	Carpet Mastic	1200	SF	Library (Room 307 / 308)		Miscellaneous	No	None	0		YES	X NO
2013 - Fall:	No Change]							
Comments												
2014- Sprir	ng: No Change]							
Comments												
2014 Falls	No Change				1							
Comments												
					1							
Comments	ng: No Change											
] 1							
2015 - Fall: Comments	No Change											
COMMENTS					i							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
34	12 x 12 inch Beige w/Black & Pink Specks VFT ABATED IN 2006			North Corridor near Rooms 208-215 ABATED IN 2006		Miscellaneous		None			YES	X NO
2013 - Fall: N	lo Change											
Comments:	_											
2014- Spring	: No Change											
Comments:												
2014 - Fall: N	lo Change											
Comments:												
2015- Spring	· No Change											
Comments:	. 110 Ghango											
2015 - Fall: N	lo Change											
Comments:	NO Change											
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Asso	essment Category
-	·	Quantity	Units		Туре	Category		Туре	Quantity	Units	J	
34 A	12 x 12 inch Beige w/Blk & Pnk Specks VFT Mastic ABATED IN 2006			North Corridor near Rooms 208-215 ABATED IN 2006		Miscellaneous		None			YES	X NO
2013 - Fall: N	lo Change											
Comments:	•											
2014- Spring	: No Change											
Comments:	•											
2014 - Fall: N	lo Change											
Comments:	go											
2015- Spring	· No Change											
Comments:	o onango											
2015 - Fall: N	lo Change											
Comments:	to onange											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
35	12 x 12 inch White w/Gray Specks VFT	115	SF	Men's Toilet near Room 101 (Under NW Stairwell)		Miscellaneous	No	None	0		YES	X NO
2013 - Fall: N	lo Change]							
Comments:	<u> </u>]							
2014- Spring	: No Change]							
Comments:	J]							
2014 - Fall: N	lo Change]							
Comments:	<u> </u>]							
2015- Spring	: No Change]							
Comments:	<u> </u>]							
2015 - Fall: N	lo Change]							
Comments:	5]							
HA No	Material Description	Material Quantity	Material	Material Location	Asbestos	Material Category	Friable	Damage Type	Damage Quantity	Damage	Change in Asses	sment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessi	ment Category
35 A	12 x 12 inch White w/Gray Specks VFT Mastic	115	SF	Men's Toilet near Room 101 (Under NW Stairwell)		Miscellaneous	No	None	0		YES	X NO

2013 - Fall: No Change	
Comments:	

Ī	2014- Spring: No Change
	Comments:

2014 - Fall: No Change
Comments:

2015- Spring: No Change	
Comments:	

2015 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
36	Terrazzo	3000	SF	Soutwest and South Stairwells and Landings on All Floors		Miscellaneous	No	None	0		YES	X NO
2013 - Fall:	No Change				7							
Comments:	J											
2014 - Fall:	No Change				7							
Comments:	· ·				<u> </u>							
2014- Spring	g: No Change				7							
Comments:	<i>-</i>]							
2015- Spring	g: No Change				7							
Comments:	g											
2015 - Fall:	No Change				٦							
Comments:	110 Onlango											
					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
37	12"X12" Purple w/Specks VFT	1800	SF	Room 331, Pre-K Room 111		Miscellaneous	No	None	0		YES	X NO
2013 - Fall:	No Change				7							
Comments:					_							
2014 - Fall:	No Change				7							
Comments:												
2014- Spring	g: No Change				7							
Comments:												
2015- Spring	g: No Change				_ _							
Comments:												
2015 - Fall:	No Change				7							
2015 - Fall: No Change Comments:					=							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
37A	12"X12" Purple w/Specks VFT Mastic12"X12" Purple w/Specks VFT Mastic	1800	SF	Room 331, Pre-K Room 111		Miscellaneous	No	None	0		YES	X NO
2013 - Fall:	No Change				7							
Comments												
2014- Sprir	ng: No Change				7							
Comments	<u> </u>											
					- -							
	No Change				4							
Comments												
2015 - Fall:	No Change											
Comments	•											
2015 Cm min	an Na Changa				٦							
Comments	ng: No Change				-							
Comments	•											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
38	12"X12" Off-white w/Tan Specks VFT	4000	SF	1st, 2nd, and 3rd Floor Corridors - 1936 Bldg		Miscellaneous	No	None	0		YES	X NO
2013 - Fall	No Change				7							
Comments	<u>~</u>				1							
					- -							
	No Change											
Comments	:											
2014- Sprir	ng: No Change				7							
Comments					1							
0045 0	an Na Ohana				- 7							
2015- Sprir Comments	ng: No Change				-							
					1							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	essment Category
38A	12"X12" Off-white w/Tan Specks VFT Mastic	4000	SF	1st, 2nd, and 3rd Floor Corridors - 1936 Bldg		Miscellaneous	No	None	0		YES	X NO
2013 - Fall:	No Change				\exists							
Comments:	i to Onlango											
2014 Sprin	g: No Change				_							
Comments:	g. No Change											
					→ ¬							
2014 - Fall:	No Change											
Comments:												
2015- Spring	g: No Change											
Comments:												
2015 - Fall:	No Change				7							
Comments:	ino Change				\dashv							
Comments.												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	essment Category
39	12"X12" Off-white w/Tan Specks VFT	10000	SF	1st, 2nd, and 3rd Floor Corridors (Vestibule)/Corridor (Outside Main Office) - 1915 Bldg		Miscellaneous	No	None	0		YES	X NO
2013 - Fall:	No Change			· •	7							
Comments:	. to Onlange											
					-							
2014 - Fall:	No Change											
Comments:												
2014- Spring	g: No Change											
Comments:	-											

2015- Spring: No Change

Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable
39A	12"X12" Off-white w/Tan Specks VFT Mastic	10000	SF	1st, 2nd, and 3rd Floor Corridors (Vestibule)/Corridor (Outside Main Office) - 1915 Bldg		Miscellaneous	No
2013 - Fall	: No Change				7		
Comments							
2014- Spri	ng: No Change				7		
Comments							
2014 - Fall	: No Change						
Comments							
2015- Spri	ng: No Change						
Comments	<u> </u>						
2015 - Fall	: No Change						
Comments	S:						

Damage Quantity

0

Damage

Units

Change in Assessment Category

YES

X NO

Friable

Damage

Туре

None

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	sessment Category
40	12"X12" Off-white w/ Blue Specks VFT	2000	SF	Main Office Areas Including Toilets, Closets and Principal's Office - Currently Counselor's Offices (under existing VFT) - 1915 Bldg		Miscellaneous	No	None	0		YES	X NO
2013 - Fall	: No Change				1							
Comments	•				=							
2014 - Fall	: No Change				7							
Comments												
2014 Spri	ng: No Change				- 1							
Comments	· ·				_							

2015- Spring: No Change

2015 - Fall: No Change

Comments:

Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	essment Category
40A	12"X12" Off-white w/ Blue Specks VFT Mastic	2000	SF	Main Office Areas Including Toilets, Closets and Principal's Office - Currently Counselor's Offices (under existing VFT) - 1915 Bldg		Miscellaneous	No	None	0		YES	X NO
2013 - Fall:	No Change				7							
Comments:	<u> </u>]							
2014- Sprine	g: No Change				7							
Comments:												
2014 - Fall:	No Change				7							
Comments:												
2015- Spring	g: No Change											
Comments:	•											
2015 - Fall:	No Change				1							
Comments:	J											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	essment Category
41	12"X12" Yellow VFT	1000	SF	Pre-K Room 112		Miscellaneous	No	None	0		YES	X NO
2013 - Fall:	No Change			1]	1	1	1	1	l		

2013 - Fall: No Change
Comments:

2014- Spring: No Change
Comments:

2014 - Fall: No Change	
Comments:	

2015- Spring: No Change
Comments:

2015 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in As	sessment Category
41A	12"X12" Yellow VFT Mastic	1000	SF	Pre-K Room 112		Miscellaneous	No	None	0		YES	X NO
2013 - Fall: I	No Change											
Comments:												
2014 - Fall: 1 Comments:	No Change											
2014- Spring Comments:	g: No Change				-							
2015- Spring	g: No Change]							
Comments:												
2015 - Fall: I	No Change											
Comments:					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in As	sessment Category
42	White Linoleum Flooring	1000	SF	1st Floor Kitchen, Toilet, Offices and Dishwasher Room 134		Miscellaneous	No	None	0		YES	X NO
2013 - Fall: I	No Change				7							
Comments:												
2014- Spring	g: No Change				7							
Comments:]							
2014 - Fall: 1 Comments:	No Change											
					J ¬							
2015 - Fall: Note: 1	No Change											
2015- Spring Comments:	g: No Change											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
42A	White Linoleum Flooring Mastic	1000	SF	1st Floor Kitchen, Toilet, Offices and Dishwasher Room 134		Miscellaneous	No	None	0		YES	X NO
2013 - Fall: N	lo Change				7							
Comments:	io Change				+							
					_							
2014 - Fall: N	lo Change											
Comments:												
2014- Spring:	· No Change				7							
Comments:	. No Change				+							
Comments.					_							
2015- Spring:	: No Change											
Comments:												
2045 Fall N	la Changa				٦							
2015 - Fall: N	io Change				4							
Comments.												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	essment Category
43	2' X 4' While Ceiling Tiles	1000	SF	1st Floor New Kitchen, Toilet and Offices		Miscellaneous	Yes	None	0		YES	X NO
2013 - Fall: N	lo Change				7							
Comments:	io oriange				1							
2014- Spring:	: No Change											
Comments:												
2014 - Fall: N	lo Chango				7							
Comments:	io Change											
Comments.					_							
2015 - Fall: N	lo Change											
Comments:												
0045 0 :	N. Observe				7							
2015- Spring:	: No Change											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asso	essment Category
44	Blue Linoleum Flooring	1000	SF	1st Floor North Lunchroom		Miscellaneous	No	None	0		YES	X NO
2013 - Fal	l: No Change											
Comments	S:											
2014- Spri	ng: No Change											
Comments	S:											
2014 - Fal	: No Change											
Comments	S:											
2015- Spri	ng: No Change											
Comments												
2015 - Fal	l: No Change											
Comments												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	essment Category
44A	Blue Linoleum Flooring, Mastic	1000	SF	1st Floor North Lunchroom		Miscellaneous	No	None	0		YES	X NO
2013 - Fal	: No Change											
Comments												
2014 - Fal	: No Change											
Comments												
2014- Spri	ng: No Change				\neg							
Comments	S:											
2015- Spri	ng: No Change											
Comments												
2015 - Fal	: No Change											
Comments);											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	sessment Category
45	Pink Linoleum Flooring	1000	SF	1st Floor South Lunch Room		Miscellaneous	No	None	0		YES	X NO
2013 - Fall:	No Change											
Comments	:											
2014- Sprin	ng: No Change											
Comments												
2014 - Fall:	No Change											
Comments												
2015- Sprir	ng: No Change				7							
Comments												
2015 - Fall:	No Change											
Comments												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	sessment Category
45A	Pink Linoleum Flooring Mastic	1000	SF	1st Floor South Lunch Room		Miscellaneous	No	None	0		YES	X NO
2013 - Fall:	No Change											
Comments												
2014- Sprir	ng: No Change				\neg							
Comments												
2014 - Fall:	No Change				\neg							
Comments:												
2015 - Fall:	No Change											
Comments												
2015- Sprir	ng: No Change											
Commente					7							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
46	12" X 12" aqua blue VFT	2000	SF	Counselor's Offices 238 (Former Main Office) - 1915 Bldg		Miscellaneous	No	None	0		YES	X NO
2013 - Fall	: No Change]							
Comments	:											
2014- Spri	ng: No Change											
Comments												
	: No Change											
Comments	:											
	ng: No Change											
Comments	:											
	: No Change											
Comments	:											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
46A	12" X 12" aqua blue, Mastic	2000	SF	Counselor's Offices 238 (Former Main Office) - 1915 Bldg		Miscellaneous	No	None	0		YES	X NO
2013 - Fall	: No Change				7							
Comments												
2014- Spri	ng: No Change				7							
Comments]							
2014 - Fall	: No Change				7							
Comments												
2015 - Fall	: No Change				7							
Comments]							
2015- Spri	ng: No Change				7							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	sessment Category
В	MJP on Fiberglass Pipe Insulation	0		Throughout, 1915 Bldg.							YES	X NO
2013 - Fall:	No Change											
Comments:												
2014 - Fall:	No Change				7							
Comments:												
2014- Spring	g: No Change				7							
Comments:												
2015- Spring	g: No Change				7							
Comments:												
2015 - Fall:	No Change				٦							
Comments:	. ro onango											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	sessment Category
С	Cardboard Pipe Insulation	543	LF	Throughout (See Hatching Maps) - 1915 Bldg.		TSI	Yes	None	0		YES	X NO
2013 - Fall:	No Change				7							
Comments:	. to onango											
2014- Spring	g: No Change				٦							
Comments:	g. 110 Ondingo											
2014 - Fall:	No Change				7							
Comments:	140 Change				-							
2015- Spring	g: No Change				_ 							
Comments:	g. No Change				=							
	No Chango				_ _							
2015 - Fall: Comments:	ino change				1							

					•			_	_			
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
D	MJP on Cardboard Pipe Insulation	83	LF	Throughout (See Hatching Maps) - 1915 Bldg.		TSI	Yes	None	0		YES	X NO
2013 - Fall:	No Change											
Comments:												
	g: No Change											
Comments:												
2014 - Fall:	No Change											
Comments:												
2015- Sprin	g: No Change											
Comments:												
2015 - Fall:	No Change											
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
E	Aircell Pipe Insulation	1250	LF	Throughout (See Hatching Maps)- 1915		TSI	Yes	None	0		YES	X NO
2013 - Fall:	No Change											
Comments:												
2014- Sprin	g: No Change											
Comments:												
2014 - Fall:	No Change											
Comments:	J											
2015- Sprin	g: No Change											
Comments:												
2015 - Fall:	No Change											
Comments:					1							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
F	MJP on Air Cell Pipe Insulation	157	LF	Throughout (See Hatching Maps)- 1915		TSI	Yes	None	0		YES	X NO
2013 - Fal	I: No Change											
Comments												
2014- Spri	ng: No Change											
Comments												
2014 - Fal	I: No Change											
Comments	S:											
2015- Spri	ng: No Change											
Comments												
2015 - Fal	I: No Change											
Comments												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
G	Mag Block Pipe Insulation	10	LF	Engineers Crawl Space - 1915 Bldg.		TSI	Yes	None	0		YES	X NO
2013 - Fal	I: No Change											
Comments	S:											
2014 - Fal	I: No Change				7							
Comments												
2014- Spri	ng: No Change				1							
Comments												
2015- Spri	ng: No Change				1							
Comments												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
Н	MJP on Mag Block Pipe Insulation	0	LF	Engineers Crawl Space - 1915 Bldg.		TSI	Yes	None	0		YES	X NO
2013 - Fall: N	lo Change											
2014- Spring:	: No Change]							
Comments:												
2014 - Fall: N Comments:	lo Change											
2015- Spring: Comments:	: No Change											
2015 - Fall: N	lo Change]							
Comments.					J							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	essment Category
1	Return Tank Cover Insulation	128	SF	Coal Rm - 1915 Bldg.		TSI	Yes	None	0		YES	X NO
2013 - Fall: N	lo Change				1							
Comments:	· ·											
2014 - Fall: N	lo Change]							
Comments:												
2014- Spring:	: No Change											
Comments:												
2015- Spring: Comments:	: No Change											
					_							
2015 - Fall: N	lo Change											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	essment Category
J	Tank Cover Insulation	100	SF	Pump Rm - 1915 Bldg.		TSI	Yes	None	0		YES	X NO
2013 - Fall	: No Change											
Comments												
2014- Sprii	ng: No Change											
Comments):											
2014 - Fall	: No Change											
Comments): 											
2015- Sprii	ng: No Change											
Comments): 											
2015 - Fall	: No Change											
Comments	S:											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	essment Category
L	Incinerator Top Insulation	0		Boiler Rm - 1915 Bldg.							X YES	NO
2013 - Fall	: Other			•						•		
Comments												
2014- Spri	ng: No Change											
Comments												
2014 - Fall	: No Change											
Comments												
2015- Spri	ng: No Change											
Comments												
2015 - Fall	: No Change											
Comments												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity
M	Aircell Pipe Insulation	490	LF	Basement Locker Room (Fan Room), Unexcavated Area, Southwest Stairwell - 1936 Bldg.		TSI	Yes	None	0
2013 - Fa	II: No Change				1				
Commen									
Oommon									
2014 - Fa	II: No Change								
	la:								
Commen	is:				<u> </u>				
]				
2014- Sp	ring: No Change]				
	ring: No Change]				
2014- Sp Commen	ring: No Change]				

Damage

Units

Change in Assessment Category

YES

X NO

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	essment Category
N	MJP on Aircell Pipe Insulation	65	LF	Basement Locker Room (Fan Room), Unexcavated Area, Southwest Stairwell - 1936 Bldg.		TSI	Yes	None	0		YES	X NO
2013 - Fall: N	No Change											
Comments:	to onango											
2011 Carina	No Change				- 7							
Comments:	: No Change											
					_							
2014 - Fall: N	No Change											
Comments:												
2015- Spring	: No Change											
Comments:												
2015 - Fall: N	No Change											
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	sessment Category
0	MJP on Fiberglass Pipe Insulation	40	LF	Air Tunnel, Unexcavated Area, Basement Locker Room(Fan Room) - 1936 Bldg.		TSI	Yes	None	0		YES	X NO
2013 - Fall: N	No Change				1							
Comments:	to on ango											
2014 Carina	u No Chango				- 7							
2014- Spring: No Change Comments:				1								
					_							
2014 - Fall: No Change												
Comments:				_								

2015- Spring: No Change

Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	
Р	Mag Block Pipe Insulation	80	LF	Basement Locker Rm (Fan Room)- 1936 Bldg.		TSI	Yes	None	0		YES	X NO
2013 - Fall: N	No Change				7							
Comments:												
2014 - Fall: N	No Change				7							
Comments:												
2014- Spring	: No Change				7							
Comments:	-											
2015- Spring	: No Change											
Comments:												
2015 - Fall: N	No Change											
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
Q	MJP on Mag Block Pipe Insulation	6	LF	Basement Locker Rm (Fan Room)- 1936 Bldg.		TSI	Yes	None	0		YES	X NO
2013 - Fall: N	No Change				7							
Comments:												
2014- Spring	: No Change				7							
Comments:	-											
2014 - Fall: N	No Change				7							
Comments:												
2015- Spring	: No Change				7							
Comments:												

ALL LEA Responsibilities, for this school, will be met.

Lynn A.Crivello

Sym & Crwill

NOTICE TO PARENTS AND STAFF REGARDING THE ASBESTOS MANAGEMENT PLAN NOTIFICATION

School: Inter-American Magnet
Date: 11/10/2015
This is to notify you in accordance with Illinois and Federal Asbestos Regulations, that a copy of the Asbestos Management Plan is available at each school during school hours by appointment. Requests to review the Asbestos Management Plan must be made at least 24 hours in advance.
Also please be advised that CPS conducts asbestos inspections of all Schools every three years. The last inspection was completed in 2013. Asbestos surveillances are conducted every six months.
CHECK ONE
A copy of this notice was sent home in each child's backpack.
A copy of this notice was printed in the school's newsletter and sent home with each child
A copy of this notice was printed in the school's calendar and sent home with each child
X Other. Posted
A COPY OF THIS NOTICE MUST BE PLACED IN THE

VFT = Vinyl Floor Tile

SCHOOL'S ASBESTOS MANAGEMENT PLAN.

Oracle Unit: 29191