# **Chicago Public Schools**

## 6 Month Asbestos Surveillance

2015 - Fall

		Beasley Academic Center Magnet 5255 S. State		Oracle Unit: Region:	29321 04	Building ID: Mail Room:	6660 42
CHECK HER	RE IF N	O CHANGE TO ASBESTOS	Asbestos Surveyor: Survey Date: Email Address:	Ford, Mr. James Patrick 10/23/2015 jford@cps.edu			

	A copy of the 2013/2014 notice to parents and staff regarding the asbestos management plan notifications was distributed via:											
	Each child's backp	ack	X Notice	printed in school's news	letter	Notice pr	rinted in scho	ool's calenda	r	Other		
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity		Change in As	sessment Category
1	Plaster material			Mens bathroom, JC across rm 236, JC across rm 285, 1st floor belw stairway #5 #4 #6, plus addn areas							YES	XNO
2013 - Fall: N	lo Change				]							
Comments:					]							
2014- Spring	: No Change				]							
Comments:	~				]							
2014 - Fall: N	lo Change				]							
Comments:					]							
2015- Spring	: No Change				]							
Comments:					]							
2015 - Fall: N	lo Change				]							
Comments:					]							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
2	Fireproofing Material										YES	X NO

2013 - Fall: No Change	
Comments:	

2014- Spring: No Change	
Comments:	

2014 - Fall: No Change	
Comments:	

2015- Spring: No Change	
Comments:	

2015 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
3	2 X 4 long deep pressed wormy pinhole			Drop in ceiling panels room 232 NC, 236 SW corner							YES	XNO

2013 - Fall: No Change	
Comments:	

2014- Spring: No Change	
Comments:	

2014 - Fall: No Change	
Comments:	

2015- Spring: No Change	
Comments:	

2015 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
4	1 X 1 acoustical CT			1st floor kitchen							X YES	NO

2013 - Fall: Repaired
Comments: missing pieces replaced Oct. 2013

2014- Spring: Repaired Comments:some tiles have been repaired/replaced

2014 - Fall: No Change	
Comments:	

2015- Spring: No Change Comments:

2015 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Catego
5	2 X 4 Smooth CT			Auditorium by main doors N, C, S, by N pillar at door to band rm area, by S pillar							YES XNO

2013 - Fall: No Change	
Comments:	

2014- Spring: No Change Comments:

2014 - Fall: No Change	
Comments:	

2015- Spring: No Change Comments:

2015 - Fall: No Change Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category
6	12 X 12 Beige with chocolate speaks floor tile	20000	SF	istributed in building interior, Throughout Classrooms & Office, Gym areas etc.		Miscellaneous	No	None	0		YES	X NO

2013 - Fall: No Change	
Comments:	

2014- Spring: No Change	
Comments:	

2014 - Fall: No Change
Comments:

2015- Spring: Repaired Comments:repairs made in 247,268, auditorium stage

2015 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessr	nent Category
6A	12 X 12 Off-white with dark gray streaks	2000	SF	Room 142 public space		Miscellaneous	No	None	0		YES	XNO

2013 - Fall: No Change
Comments:
2014 - Fall: No Change
Comments:
2014- Spring: No Change
Comments:
2015- Spring: No Change
O a man a materia

Comments: 2015 - Fall: No Change

Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category
6B	12 X 12 Light beige with rust streaks	600	SF	Room 234		Miscellaneous	No	None	0		YES	XNO

2013 - Fall: No Change	
Comments:	

2014- Spring: No Change	
Comments:	

2014 - Fall: No Change	
Comments:	

2015 - Fall: No Change	
Comments:	

2015- Spring: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessm	ent Category
7	Block Duct Insulation					TSI					YES	X NO

2013 - Fall: No Change	
Comments:	

2014- Spring: No Change	
Comments:	

2014 - Fall: No Change	
Comments:	

2015- Spring: No Change	
Comments:	

2015 - Fall: No Change	
Comments:	

1 AH	No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category
8		Black lab tabletop material			Broken abandoned material from room 216							YES	XNO

2013 - Fall: No Change	
Comments:	

2014- Spring: No Change	
Comments:	

2014 - Fall: No Change	
Comments:	

2015- Spring: No Change	
Comments:	

2015 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
9	Fire proofing patch										YES	X NO

2013 - Fall: No Change	
Comments:	

2014- Spring: No Change	
Comments:	

2014 - Fall: No Change	
Comments:	

Comments:	2015- Spring: No Change	
	Comments:	

2015 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category
10	Mastic 12 X 12 Beige with chocolate specks FT	75000	SF	Distributed in building interior, Throughout Classrooms & Office, Gym areas etc.		Miscellaneous	No	None	0		YES	X NO

2013 - Fall: No Change	
Comments:	

2014- Spring: No Change	
Comments:	

2014 - Fall: No Change	
Comments:	

2015- Spring: No Change	
Comments:	

2015 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
10A	Mastic 12 X 12 off-white with dark gray streaks			Room 162 public space and Room 142							YES	XNO

2013 - Fall: No Change	
Comments:	

2014 - Fall: No Change Comments:

2014- Spring: No Change	
Comments:	

	o Change
Comments:	

2015 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
10B	Mastic 12" X 12" light beige with rust streaks			Room 234							YES	X NO

2013 - Fall: No Change	
Comments:	

2014- Spring: No Change	
Comments:	

2014 - Fall: No Change	
Comments:	

2015 - Fall: No Change	
Comments:	

2015- Spring: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category
11	Roofing material			Exterior of building - Non AHERA		Miscellaneous		None			YES	X NO

Comments:	

2014- Spring: No Change	
Comments:	

2014 - Fall: No Change	
Comments:	

2015- Spring: No Change	
Comments:	

2015 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
12	Orange mix carpet adhesive			In LRC, 248 NE side, In room 226 by side of door, in room 214 by side of door							YES	XNO

2013 - Fall: No Change	
Comments:	

2014- Spring: No Change	
Comments:	

2014 - Fa	all: Abated	

Comments:carpeting replaced with carpet squares July 2014

2015- Spring: Abated Comments:abate 2014

2015 - Fall: Abated Comments:carpeting replaced July 2014

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
13	Interior brick material			Room 211 SE corner, 225 SW corner, 114 SW corner							YES X NO

2013 - Fall: No Change	
Comments:	

2014- Spring: No Change	
Comments:	

2014 - Fall: No Change	
Comments:	

2015- Spring: No Change	
Comments:	

2015 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
14	Interior brick mortar			Room 211 SE corner, Room 275 SW corner, Room 114 SW corner							YES	XNO

2013 - Fall: No Change	
Comments:	

2014- Spring: No Change	
Comments:	

2014 - Fall: No Change	
Comments:	

2015- Spring: No Change
Comments:

2015 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
15	Black Vinyl Baseboard			Rm 216 S side, Rm 297 S wall close to E side, Rm 218							YES X NO

2013 - Fall: No Change	
Comments:	

2014- Spring: No Change	
Comments:	

2014 - Fall: No Change	
Comments:	

2015 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
16	Adhesive Black VBB			Rm 216 S side, Rm297 S wall close to E side, Rm 218							YES	XNO

2013 - Fall: No Change	
Comments:	

2014- Spring: No Change	
Comments:	

2014 - Fall: No Change	
Comments:	

2015- Spring: No Change
Comments:

2015 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessr	nent Category
17	Brown VBB			Rm 216 E lower corner of door frame, Rm 234, Engineer's office rm 109							YES	XNO

2013 - Fall: No Change	
Comments:	

2014- Spring: No Change	
Comments:	

2014 - Fall: No Change	
Comments:	

2015 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category
18	Adhesive brown VBB			Rm 216 E lower corner of door frame, Rm 234, Rm 109 Engineers office							YES	XNO

2013 - Fall: No Change	
Comments:	

2014- Spring: No Change	
Comments:	

2014 - Fall: No Change	
Comments:	

2015- Spring: No Change
Comments:

2015 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category
19	Brick Red Carpet Adhesive			Room120							YES	XNO

2013 - Fall: No Change	
Comments:	

2014- Spring: No Change Comments:throw rug on tile floor

2014 - Fall: No Change	
Comments:	

2015- Spring: Abated Comments:abated 1/2014

2015 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
20	Green carpet adhesive			Faculty dining room 152, SW corner, SE corner, NE corner							YES	XNO

2013 - Fall: No Change	
Comments:	

2014- Spring: No Change	
Comments:	

2014 - Fall: Abated Comments:carpeting replaced with VCT floor tile July 2014

2015- Spring: Abated Comments:abated 7/2014

2015 - Fall: Abated	
Comments:floor tile July 2014	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
21	Pink mix carpet adhesive			Rm 213, 277 , 275 all by the door side							X YES NO

2013 - Fall: Abated	
Comments:carpet/adhesive do not exist. VCT floor tile	

2014- Spring: No Change	
Comments:throw rug on tile floor	

2014 - Fall: No Change	
Comments:	

2015 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
22	Drywall board			In band room additions							YES	X NO

2013 - Fall: No Change	
Comments:	

2014- Spring: No Change	
Comments:	

2014 - Fall: No Change	
Comments:	

2015- Spring: No Change	
Comments:	

2015 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
23	Light pink and orange mix stage curtain			Auditorium							YES	X NO

2013 - Fall: No Change	
Comments:	

2014- Spring: No Change	
Comments:some torn areas of curtain	
	_

2014 - Fall: No Change	
Comments:	

2015 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category
24	Stored light brown mix linoleum sheeting			New auditorium stage area		Miscellaneous					YES	XNO

2013 - Fall: No Change	
Comments:	

2014- Spring: No Change
Comments:

2014 - Fall: No Change	
Comments:	

2015- Spring: No Change	
Comments:	

Common and a	2015 - Fall: No Change
Comments:	Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Ca	itegory
25	Original Orange carpet adhesive			In band room							YES	C

2013 - Fall: No Change	
Comments:	

2014 - Fall: Abated Comments:carpeting replaced with carpet squares July 2014

2015- Spring: Abated Comments:abated 7/2014

2015 - Fall: Abated

Comments:carpeting replaced July 2014

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
26	Kiln wire insulation material	10	LF	Room 298		Miscellaneous	No	None	0		YES	X NO

2013 - Fall: No Change	
Comments:	

2014- Spring: No Change	
Comments:	

2014 - Fall: No Change	
Comments:	

2015- Spring: No Change	
Comments:	

2015 - Fall: No Change	
Comments:	
	_

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category
27	Interior door caulk			Room 275 SE and SW corners, Rm 114 SE corner							YES	XNO

2013 - Fall: No Change	
Comments:	

2014- Spring: No Change	
Comments:	

2014 - Fall: No Change	
Comments:	

2015- Spring: No Change	
Comments:	

2015 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
28	Sinktops joining compound			Room 232 E. sink, Rm 297 C and W sinks							YES	X NO

2013 - Fall: No Change	
Comments:	

2014- Spring: No Change
Comments:

2014 - Fall: No Change	
Comments:	

2015- Spring: No Change	
Comments:	

2015 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
29	Electric kiln door backing material			Rm 298							YES	X NO

2013 - Fall: No Change	
Comments:	

2014- Spring: No Change	
Comments:	

2014 - Fall: No Change	
Comments:	

2015- Spring: No Change	
Comments:	

2015 - Fall: No Change	
Comments:	

ſ	HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	
	30	Electric kiln inside material on metal backing			Room 298							YES	XNO

2013 - Fall: No Change	
Comments:	

2014- Spring: No Change	
Comments:	

2014 - Fall: No Change	
Comments:	
	_

2015- Spring: No Change	
Comments:	

2015 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	
31	Pink green mix carpet adhesive			Room 111 by E doorside, by W doorside, by NW corner							YES	X NO

### 2013 - Fall: No Change Comments:throw rug, appears to be no adhesive

2014- Spring: No Change	
Comments:throw rug on tile floor	

2014 - Fall: No Change	
Comments:	

2015 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category
32	Light brown carpet adhesive			Room 29 by doorside, throughout building							YES	X NO

2013 - Fall: No Change
Comments:throw rug, appears to be no adhesive
2014- Spring: No Change

Comments:throw rug on tile floor

2014 - Fall: No Change	
Comments:	

2015- Spring: No Change Comments:

2015 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessme	nt Category
33	Blue carpet adhesive with 12 X 12 underneath	600	SF	Room 162		Miscellaneous	No	None	0		YES	K NO

2013 - Fall: No Change	
Comments:	

2014- Spring: No Change Comments:throw rug on tile floor

2014 - Fall: No Change	
Comments:	

2015- Spring: No Change Comments:

2015 - Fall: No Change Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
34	Exterior metal window caulking			S, E, and NE courtyard wall windows, Non- AHERA							YES	XNO

2013 - Fall: No Change	
Comments:	

2014- Spring: No Change	
Comments:	

Comments:	2014 - Fall: No Change	
	Comments:	

2015 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
35	Exterior metal door caulking			S and NE courtyard doors, SE entrance way							YES	X NO

2013 - Fall: No Change	
Comments:	

2014- Spring: No Change	
Comments:	

2014 - Fall: No Change	
Comments:	

Comments:	2015- Spring: No Change	
Comments.	Comments:	

2015 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
36	Exterior brick			E, N, and S courtyard walls Non-AHERA		Miscellaneous					YES	X NO

2013 - Fall: No Change	
Comments:	

2014- Spring: No Change
Comments:

2014 - Fall: No Change	
Comments:	

Comments:	2015 - Fall: No Change
Comments.	Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessmer	t Category
37	Exterior brick mortar			E, N, and S courtyard walls Non-AHERA		Miscellaneous					YES	NO

2013 - Fall: No Change	
Comments:	

2014- Spring: No Change	
Comments:	

2014 - Fall: No Change	
Comments:	

2015- Spring: No Change	
Comments:	

2015 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
38	Joint-compound of drywall board			2nd floor east band room areas							YES	X NO

2013 - Fall: No Change	
Comments:	

2014- Spring: No Change	
Comments:	

2014 - Fall: No Change	
Comments:	

2015- Spring: No Change	
Comments:	

2015 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
39	Interior Window Caulk			Throughout Classroom in Bldg.							YES	X NO

2013 - Fall: No Change	
Comments:	

2014- Spring: No Change	
Comments:	

2014 - Fall: No Change	
Comments:	

	2015- Spring: No Change	
Comments:	Comments:	

2015 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
40	Orange Carpet Mastic			Principal's Office & Administrative area							YES	X NO

2013 - Fall: No Change	
Comments:	

2014- Spring: Abated Comments:orange carpet replaced with new carpet Jan. 2014

2014 - Fall: Abated Comments:carpeting replaced with new carpeting January 2014

2015- Spring: Abated Comments:abated 1/2014

2015 - Fall: Abated	
Comments:carpeting replaced January 2014	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
41	12"x12" Beige Floor Tile w/Brn, wht & Gray Streaks	600	SF	Boy's & Girl's Locker areas		Miscellaneous	No	None	0		YES	X NO

Comments:	ange	2013 - Fall: No Change
Commonitor		Comments:

2014- Spring: No Change	
Comments:	

2014 - Fall: No Change	
Comments:	

2015- Spring: No Change
Comments:

2015 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category
42	12"x12" Beige FT w/Brn, wht & Gray Streaks Mastic	600	SF	Boy's & Girl's Locker areas		Miscellaneous	No	None	0		YES	XNO

2013 - Fall: No Change	
Comments:	

2014- Spring: No Change	
Comments:	

2014 - Fall: No Change	
Comments:	

2015 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
43	Hood Vibration Collar	8	SF	Room 298		Miscellaneous	No	None	0		YES	X NO

Comments	2013 - Fall: No Change
Comments.	Comments:

2014- Spring: No Change	
Comments:	

2014 - Fall: No Change	
Comments:	

2015- Spring: No Change	
Comments:	

2015 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
44	Spray-on Fireproofing			Maintenance Dock		Surface					YES	XNO

2013 - Fall: No Change	
Comments:	

2014- Spring: No Change	
Comments:	

2014 - Fall: No Change	
Comments:	

2015- Spring: No Change	
Comments:	

2015 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
45	2' X 4' White Ceiling Tile w/ Pinhole	1000	SF	1st Floor Hallway by Windows		Miscellaneous	Yes	None	0		YES	X NO

-	
Comments:	

2014- Spring: No Change	
Comments:	

2014 - Fall: No Change	
Comments:	

2015 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category
46	2' X 4' White Smooth Ceiling Tile	13000	SF	2nd Floor Hallways and Classrooms		Miscellaneous	Yes	None	0		YES	XNO

2013 - Fall: No Change	
Comments:	

2014- Spring: No Change
Comments:

2014 - Fall: No Change	
Comments:	

	2015 - Fall: No Change	
Comments:	Comments:	

2015- Spring: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessr	nent Category
47	12" x 12" Beige w/ Dark Spots Floor Tile	40000	SF	1st and 2nd Floor Hallways and Classrooms		Miscellaneous	No	None	0		YES	X NO

2013 - Fall: No Change	
Comments:	

2014- Spring: No Change	
Comments:	

2014 - Fall: No Change	
Comments:	

2015 - Fall: No Change	
Comments:	

Comments:	2015- Spring: No Change	
	Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessr	nent Category
48	12" x 12" Beige w/ Dark Spots Floor Tile Mastic	40000	SF	1st and 2nd Floor Hallways and Classrooms		Miscellaneous	No	None	0		YES	XNO

2013 - Fall: No Change	
Comments:	
2014- Spring: No Change	
Comments:	
2014 - Fall: No Change	
Comments:	

2014- Spring: No Change	
Comments:	

2014 - Fall: No Change	
Comments:	

2015 - Fall: No Change Comments:

2015- Spring: No Change	
Comments:	

ALL LEA Responsibilities, for this school, will be met.

Syn & Crwill

Lynn A.Crivello

#### NOTICE TO PARENTS AND STAFF REGARDING THE ASBESTOS MANAGEMENT PLAN NOTIFICATION

School:	Beasley Academic Center Magnet
Date:	10/16/2015

This is to notify you in accordance with Illinois and Federal Asbestos Regulations, that a copy of the Asbestos Management Plan is available at each school during school hours by appointment. Requests to review the Asbestos Management Plan must be made at least 24 hours in advance.

Also please be advised that CPS conducts asbestos inspections of all Schools every three years. The last inspection was completed in 2013.

Asbestos surveillances are conducted every six months.

#### CHECK ONE

X A copy of this notice was printed in the school's newsletter and sent home with each child



Other.

# A COPY OF THIS NOTICE MUST BE PLACED IN THE SCHOOL'S ASBESTOS MANAGEMENT PLAN.