Chicago Public Schools

6 Month Asbestos Surveillance 2015 - Fall

	Address: Nancy B S	efferson Alte amilton	ernative Sch	ool			acle Unit: egion:	03)11	Buildir Mail Ro		
X CHEC	K HERE IF NO CHA	NGE TO	O ASBE	STOS Survey	os Surveyor: Date: ddress:							
	A copy of the 2013/201 Each child's backpa		-	d staff regarding the as				was distribute ool's calenda		her		
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	essment Category
1	1" x 1" Ceiling Tile with Dots, Metal	12500	SF	Throughout Building		Miscellaneous	Yes	None	0		YES	X NO
	: No Change ::No Change											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	sessment Category
02	Spray-on Spray-on Material	9000	SF	Above Drop Ceiling on Beams Throughout School		Surface	Yes	None			YES	X NO
	: No Change :No Change]							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	essment Category
03	Plaster Walls	10000	SF	Throughout School		Surface	No	None	0		YES	X NO
	: No Change :No Change	•	•]	•		•		•		

VFT = Vinyl Floor Tile Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Asse	essment Category
		Quantity	Units		Type	Category		Type	Quantity	Units		
04	Interior Brick			Throughout School		Miscellaneous	No	None	0		YES	X NO
2013 - Fall: N	o Change				7							
Comments:N	o Change											
					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
05	Interior Brick Mortar			Throughout building		Miscellaneous	No	None	0		YES	X NO
2013 - Fall: N	o Change											
Comments:N					-							
	<u> </u>											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
06	Window Glazing			Throughout Building		Miscellaneous					YES	X NO
2013 - Fall: N	o Change				7							
Comments:N												
					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
07	Fiberglass Pipe Insulation			Throughout Building		TSI					YES	X NO
2013 - Fall: N	o Change				7							

Comments:No Change

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	sessment Category
08	12" x 12" Beige VFT	8000	SF	Throughout School		Miscellaneous	No	None	0		YES	X NO
2013 - Fall:	: No Change											
	:No Change											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	sessment Category
09	12" x 12" Beige VFT Mastic	8000	SF	Throughout Building		Miscellaneous	No	None	0		YES	X NO
2013 - Fall:	: No Change											
	:No Change											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	sessment Category
10	12" x 12" Tan VFT			Not located							YES	X NO
2013 - Fall:	: No Change											
	:No Change											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	sessment Category
11	12" x 12" Tan VFT Mastic			Not found							YES	X NO
2013 - Fall:	: No Change											
	:No Change											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	sessment Category
12	Cinder Block Wall	400	SF	Storage Room		Miscellaneous	No	None	0		YES	X NO
2013 - Fall: N	lo Change											
Comments:N	o Change											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	essment Category
13	Cinder Block Wall Mortar	400	SF	Storage Room		Miscellaneous	No	None	0		YES	X NO
2013 - Fall: N	lo Change											
Comments:N	o Change											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	essment Category
14	Room Divider Insulation- Plaster Wall			Room 309		Miscellaneous	No	None			YES	X NO
2013 - Fall: N	lo Change											
Comments:N	o Change											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	essment Category
15	12" x 12" Multi-Beige VFT	200	SF	Counslers Office		Miscellaneous	No	None	0		YES	X NO

2013 - Fall: No Change Comments:No Change

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	sessment Category
16	12" x 12" Multi-Beige VFT Mastic	200	SF	Counslers Office		Miscellaneous	No	None	0		YES	X NO
2013 - Fall:	No Change				7							
Comments:I												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	sessment Category
17	12" x 12" Gray VFT			Not Found							YES	X NO
2013 - Fall:	No Change											
Comments:I												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	sessment Category
18	12" x 12" Gray VFT Mastic			Not found							YES	X NO
2013 - Fall:	No Change											
Comments:I												
					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	sessment Category
19	Gray Carpet Glue	1200	SF	North and South Bathroom floor tile and mastic, Chapel, Library		Miscellaneous	No	None	0		YES	X NO
2013 - Fall:	No Change				7							
Comments:I												

				•								
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	sessment Category
20	Insulation on Room Divider	500	SF	South and North Chapel		TSI	No	None	0		YES	X NO
2013 - Fall: I	No Change]							
Comments:N												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	sessment Category
21	1.5" x 1.5" Ceiling Tile w/ Dots, Metal	500	SF	All Purpose Room, Class 200, Store Room		Miscellaneous	No	None	0		YES	X NO
2013 - Fall: I	No Change											
Comments:N												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	sessment Category
22	Gray Vinyl Room Divider			Not present at time of Inspection		Miscellaneous	No	None			YES	X NO
2013 - Fall: I	No Change											
Comments:N	No Change											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	sessment Category
23	Sheetrock	500	SF	All Purpose Room		Miscellaneous	No	None	0		YES	X NO
2013 - Fall: I	No Change				7							
Comments:N												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	sessment Category
23A	Sheet Rock Joint Compound	200	SF	All Purpose Room/Detention Area		Miscellaneous	No	None	0		YES	X NO
2013 - Fall:	: No Change											
Comments	:No Change											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	sessment Category
24	Finished Brick Mortar	250	SF	All Purpose Room		Miscellaneous	No	None	0		YES	X NO
2013 - Fall:	: No Change											
Comments	:No Change											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	sessment Category
25	Vinyl Inlay	10350	SF	Gym Room Floor		Miscellaneous	No	None	0		YES	X NO
2013 - Fall:	: No Change											
	:No Change											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	sessment Category
26	Fire Door Insulation	500	SF	Throughout School Corridors		TSI	No	None	0		YES	X NO
2013 - Fall	: No Change											
	:No Change											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	sessment Category
27	Duct Wrap			Above Drop Ceiling Throughout School		TSI	Yes				YES	X NO
2013 - Fall:	No Change											
	:No Change											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	sessment Category
28	Fiberglass Joints			Above Drop Ceiling Throughout School		TSI	Yes				YES	X NO
2013 - Fall:	No Change											
Comments	:No Change											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	sessment Category
29	Carpet Adhesive	5000	SF	Rms 212, 214, 216, Chapel		Miscellaneous	No	None	0		YES	X NO
2013 - Fall:	No Change											
	:No Change											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	sessment Category
30	12" x 12" Gray Floor Tile			Room 205		Miscellaneous	No	None			YES	X NO
2013 - Fall	No Change	•	•			•	-	•	•	·		
	:No Change											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	sessment Category
31	12" x 12" Gray Floor Tile Mastic			Room 205		Miscellaneous	No				YES	X NO
2013 - Fall: I	No Change				1							
Comments:N												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	sessment Category
32	12" x 12" White w/ Gray Floor Tile			Main Office		Miscellaneous	No	None			YES	X NO
2013 - Fall: I]							
Comments:N	No Change											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	sessment Category
33	12" x 12" White w/Gray Floor Tile Mastic			Main Office		Miscellaneous	No	None			YES	X NO
2013 - Fall: I	No Change				1							
Comments:N												
	•				_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	sessment Category
34	12" x 12" Multi-Beige Floor Tile	4800	SF	Rooms 200,200A,200B, 203A,203B,205,206,212, 216,219, Bathroom, Library, North/South Hall, Post 26 & 27, Chaplin Office		Miscellaneous	No	None	0		YES	X NO
2013 - Fall: I												
Comments:N	No Change											

	T			T								
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	sessment Category
35	12" x 12" Multi-Beige Floor Tile Mastic	2700	SF	Rooms 200, 200A, 200B, 203A,203B,205,206, 212,216,219 Bathroom, Library, North/South Hall, Post 26 & 27, Chaplin Office		Miscellaneous	No	None	0		YES	X NO
2013 - Fall: N	lo Change				1							
Comments:N	<u> </u>											
					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	sessment Category
36	12" x 12" Parquae Linoleum	25	SF	Room 214 Bathroom		Miscellaneous	No	None	0		YES	X NO
2013 - Fall: N	lo Change				1							
Comments:N												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	sessment Category
37	12" x 12" Parquae Linoleum Adhesive	25	SF	Room 214 Bathroom		Miscellaneous	No	None	0		YES	X NO
2013 - Fall: N	lo Change]							
Comments:N												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	essment Category
38	4" Medium Brown Vinyl Baseboard	635	SF	Post 26 & 27, Rooms 200, 200A, 200B and 327		Miscellaneous	No	None	0		YES	X NO
2013 - Fall: N	lo Change]							
Comments:N												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	sessment Category
39	4" Medium Brown Vinyl Baseboard Mastic	635	SF	Post 26 & 27, Rooms 200, 200A, 200B and 327		Miscellaneous	No	None	0		YES	X NO
2013 - Fall: N	lo Change]							
Comments:N												
					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	sessment Category
40	Sink Coating	60	SF	Rooms 216, 217, 317, 323		Miscellaneous	No	None			YES	X NO
2013 - Fall: N	lo Change				1							
Comments:N												
					-							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	sessment Category
41	2" Dark Brown Baseboard	2400	LF	Post Office Rooms 26 and 27, rooms 200, 200A, 200B, 210, 211, 212, 214, 216, 217, 218, 310, 314, 316, 317, 318, 320, and 327, Supervisors Office		Miscellaneous	No	None	0		YES	X NO
2013 - Fall: N	lo Change				1							
Comments:N					1							
					1							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	sessment Category
42	2" Dark Brown Baseboard Mastic	2400	LF	Post Office Rooms 26 and 27, rooms 200, 200A, 200B, 210, 211, 212, 214, 216, 217, 218, 310, 314, 316, 317, 318, 320 and 327, Supervisors Office		Miscellaneous	No	None	0		YES	X NO
2013 - Fall: N	lo Change]							
Comments:N	o Change				1							

				T				T =				
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	essment Category
43	Transite Sink/Counter Tops	400	SF	Room 216, 316		Miscellaneous	No	None			YES	X NO
2013 - Fall:	: No Change											
Comments	:No Change											
	- Lucius de	T. A. A. A. A. A.	T. A	1		I sa c · · ·	le	T-5	1.5			
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	essment Category
44	Baseboard 8" Dark Tan	60	LF	Multi Purpose Room		Miscellaneous	No	None	0		YES	X NO
2013 - Fall:	: No Change											
Comments	:No Change											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	essment Category
44m	Baseboard Mastic	60	LF	Multi Purpose Room		Miscellaneous	No	None	0		YES	X NO
2013 - Fall:	: No Change				\neg							
Comments	:No Change											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	essment Category
45	Terrazzo Flooring	1000	SF	Lobby Entrance		Miscellaneous	No	None	0		YES	X NO
2013 - Fall:	: No Change	•	•	•			•	•		•		
	:No Change											

_				<u></u>		•						
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	sessment Category
46	12x12 white with green & rose Specs	600	SF	2nd Floor Supervisor's Office & Toilet-Northside		Miscellaneous	No	None	0		YES	X NO
2013 - Fall:	No Change											
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	sessment Category
46m	12x12 White with Green & Rose Specs Mastic	600	SF	2nd Floor Supervisor's Office & Toilet -Northside		Miscellaneous	No	None	0		YES	X NO
2013 - Fall:	No Change											
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	sessment Category
47	12"x12" Beige Floor Tile (Patching Material)	1500	SF	Throughout School		Miscellaneous	No	None	0		YES	X NO
2013 - Fall:	No Change				1							
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	sessment Category
48	12"x12" Beige Floor Tile Mastic (Patching Material)	1500	SF	Throughout School		Miscellaneous	No	None	0		YES	X NO
2013 - Fall:	No Change				1							
Comments:												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
49	12"x12" Dark brown w/Light Brown FT	75	SF	By Room 305 as Patch Hallway		Miscellaneous	No	None	0		YES	X NO
2013 - Fall: No Change												

HA	\ No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category
49	9M	12"x12" Dark brown w/Light Brown FT Mastic	75	SF	By Room 305 as Patch Hallway		Miscellaneous	No	None	0		YES	X NO

2013 - Fall: No Change	
Comments:No Change	

Comments:No Change

ALL LEA Responsibilities, for this school, will be met.

Lynn A.Crivello

Sym & Crwill

NOTICE TO PARENTS AND STAFF REGARDING THE ASBESTOS MANAGEMENT PLAN NOTIFICATION

School: Date:	Nancy B Jefferson Alternative School
the Asbes	notify you in accordance with Illinois and Federal Asbestos Regulations, that a copy of stos Management Plan is available at each school during school hours by appointment. to review the Asbestos Management Plan must be made at least 24 hours in advance.
The last in	se be advised that CPS conducts asbestos inspections of all Schools every three years. is spection was completed in 2013. surveillances are conducted every six months.
CHECK OI	<u>NE</u>
A c	copy of this notice was sent home in each child's backpack.
A c	copy of this notice was printed in the school's newsletter and sent home with each child
A c	copy of this notice was printed in the school's calendar and sent home with each child
Oth	ner.
۸ COD	Y OF THIS NOTICE MUST BE PLACED IN THE

VFT = Vinyl Floor Tile Oracle Unit: 30011

SCHOOL'S ASBESTOS MANAGEMENT PLAN.