Chicago Public Schools

6 Month Asbestos Surveillance 2015 - Fall

Jose De Diego Community Academy 31261 Building ID: 7420 School: **Oracle Unit:** Address: 1313 N.Claremont Region: 02 Mail Room: 35 Asbestos Surveyor: X CHECK HERE IF NO CHANGE TO ASBESTOS Survey Date: 10/13/2015 Email Address: A copy of the 2013/2014 notice to parents and staff regarding the asbestos management plan notifications was distributed via: X Notice printed in school's newsletter Each child's backpack Notice printed in school's calendar Other HA No Material Description Material Material Location Asbestos Friable Damage Change in Assessment Category Material Damage Damage Quantity Units Type Category Quantity Type 12"x12" Beige w/ Brown Rooms 302, 315, 133, YES 80 SF X NO 4200 No 0 Miscellaneous None Specks VFT 007, 028, 301, 303 2013 - Fall: No Change Comments: 2014- Spring: No Change Comments: 2014 - Fall: No Change Comments: 2015- Spring: No Change Comments: 2015 - Fall: No Change Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
8F	Mag Block Pipe Insulation	700	LF	Boiler Room, Pump Room, East Basement Corridor, Coal Room		TSI	Yes	None	0		X YES	NO
2013 - Fall: A	bated											
Comments:N	ew water lines installe	d										
2014- Spring	: No Change											
Comments:												
2014 - Fall: No Change												
Comments:												
2015- Spring	: No Change											
Comments:												
2015 - Fall: No Change												
Comments:	_											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
09	12"x12" Beige w/ Brown Specks VFT Mastic	4200	SF	Rooms 302, 315, 133, 007, 028, 301 ,303		Miscellaneous	No	None	0		YES	X NO
2013 - Fall: N	lo Change											
Comments:	•											
2014- Spring	: No Change											
Comments:												
2014 - Fall: No Change												
Comments:												

2015- Spring: No Change

2015 - Fall: No Change

Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
9G	MJP E/F/V on Mag Block Tank Insulation	30	LF	Boiler Room, Pump Room, East Basement Corridor, Coal Room		TSI	Yes	None	0		X YES	NO
2013 - Fall:	Abated				7							
	New water lines installe	ed										
2014 Sprin	g: No Change				7							
Comments:	•											
					- 1							
	No Change											
Comments:												
2015- Sprin	g: No Change											
Comments:												
2015 - Fall:	No Change				7							
Comments:												
00111111011101					_							
										_		
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
10	9"x9" Beige VFT-NOT OBSERVED	450	SF	Rooms 009		Miscellaneous	No	None	0		YES	X NO
2013 - Fall	No Change				7							
Comments:												
2211 2					- -							
2014- Spring: No Change Comments:												
Comments.												
2014 - Fall:	No Change											
Comments:												
2015- Sprin	ıg: No Change				7							
Comments:					1							
					-							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
10H	MJP E/F/V on Fiberglass Pipe Insulation	300	SF	Throughout		TSI	No	None	0		X YES	NO
2013 - Fall	: Abated											
Comments:New water lines installed												
2014- Spri	ng: No Change											
Comments												
2014 - Fall	: No Change											
Comments												
2015- Spri	ng: No Change											
Comments												
2015 - Fall	: No Change											
Comments												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
		-	1				+					

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category
11	9"x9" Beige VFT Mastic- NOT OBSERVED	450	SF	Rooms 314 & 009		Miscellaneous	No		0		YES	X NO

2013 - Fall: No Change	
Comments:	

2014- Spring: No Change	
Comments:	

2014 - Fall: No Change	
Comments:	

2015- Spring: No Change	
Comments:	

2015 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	essment Category
111	Cardboard Pipe Insulation	3000	LF	Throughout		TSI	Yes	None	0		X YES	NO
2013 - Fall:		.1										
Comments:	New water lines installe	<u>:a</u>										
2014- Sprin	g: No Change											
Comments:												
2014 Falls	No Chango				_ _							
2014 - Fall: Comments:	No Change											
Comments.												
2015- Spring: No Change												
Comments:												
2015 - Fall:	No Change											
Comments:	<u> </u>											
LIA NI-	Material Description	Matarial	Matarial	Matarial Lagation	A ala a ata a	Matarial	Frieble	Damana	Domesia	Damassa	Chanas in Ass	
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	essment Category
12	Orange Linoleum	10	SF	1st through 3rd Floor Janitors Closets		Miscellaneous	No	None	0		YES	X NO
2013 - Fall:	No Change											
Comments:												
2014 Sprin	a: No Chango											
2014- Spring: No Change Comments:												
Comments.					<u></u>							
	2014 - Fall: No Change											
Comments:	Comments:											

2015- Spring: No Change

2015 - Fall: No Change

Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
12J	MJP E/F/V on Cardboard Pipe Insulation	75	LF	Throughout		TSI	Yes	None	0		X YES	NO
2013 - Fall: A	Abated											
Comments:n	ew water lines installe	d										
2014- Spring: No Change												
Comments:												
2014 - Fall: N	lo Change				7							
Comments:												
2015- Spring: No Change					٦							
Comments:												
2015 - Fall: N	lo Change				\neg							
Comments:	io Change											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
13	Orange Linoleum Mastic	10	SF	1st through 3rd Floor Janitors Closets		Miscellaneous	No	None	0		YES	X NO
2013 - Fall: N	lo Change				7							
					 							

2013 - Fall: No Change
Comments:

2014- Spring: No Change Comments:

2014 - Fall: No Change Comments:

2015- Spring: No Change Comments:

2015 - Fall: No Change Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asso	essment Category
14	12"x12" White w/ Yellow Specks VFT	18210	SF	Throughout		Miscellaneous	No	None	0		YES	X NO
2013 - Fall	: No Change											
Comments	· ·											
2014- Sprii	ng: No Change											
Comments												
2014 - Fall	: No Change											
Comments												
2015- Sprii	ng: No Change				\neg							
Comments												
2015 - Fall: No Change												
Comments												
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Ass	essment Category
	,	Quantity	Units		Туре	Category		Туре	Quantity	Units		
15	12"x12" White w/ Yellow Specks VFT Mastic	18210	SF	Throughout		Miscellaneous	No	None	0		YES	X NO
2013 - Fall	: No Change											
Comments	:											
2014- Sprir	ng: No Change											
Comments												
2014 - Fall	: No Change											
Comments:												
2015- Sprin	ng: No Change				\neg							
Comments												
2015 - Fall	: No Change											
Comments												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
16	12"x12" Beige w/ Brown Streaks VFT	8500	SF	Room 019, 101, 102, 104, 105, 120, 305, 332		Miscellaneous	No	None	0		YES	X NO
2013 - Fall	: No Change											
Comments): :											
2014- Spri	ng: No Change				7							
Comments												
2014 - Fall	: No Change				7							
Comments	<u> </u>											
2015- Spri	ng: No Change				7							
Comments												
2015 - Fall	: No Change				7							
Comments												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
						1			+	+		

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	
17	12"x12" Beige w/ Brown Streaks VFT Mastic	8500	SF	Room 019, 101, 102, 104, 105, 120, 305, 332		Miscellaneous	No	None	0		YES	X NO

2013 - Fall: No Change	
Comments:	

Ī	2014- Spring: No Change
	Comments:

2014 - Fall: No Change
Comments:

2015- Spring: No Change	
Comments:	

2015 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
18	12"x12" Brown w/ White Specks VFT	10300	SF	Room 028, 127, 129, 131, 214, 218, 313, 327, 332		Miscellaneous	No	None	0		YES	X NO
2013 - Fall: N	lo Change				1							
Comments:	to change											
2014 Spring	: No Change				- 1							
Comments:	. No Change				1							
					- -							
2014 - Fall: N	lo Change				_							
Comments:]							
	: No Change											
Comments:												
2015 - Fall: N	lo Change				1							
Comments:	<i>y</i> .											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
19	12"x12" Brown w/ White Specks VFT Mastic	10300	SF	Room 028, 127, 129, 131, 214, 218, 313, 327, 332		Miscellaneous	No	None	0		YES	X NO
2013 - Fall: N	lo Change				1		•					
Comments:	vo change				1							
					7							
2014- Spring Comments:	: No Change				1							
Comments.					J							
2014 - Fall: N	lo Change											
Comments:]							

2015- Spring: No Change

2015 - Fall: No Change

Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	sessment Category
20	9"x9" Brown VFT (NOT OBSERVED)	700	SF	Room 325		Miscellaneous					YES	X NO
	No Change											
Comments:												
2014- Sprin	g: No Change											
Comments:												
2014 - Fall:	No Change											
Comments:												
2015- Sprin	g: No Change											
Comments:												
2015 - Fall:	No Change											
Comments:	go											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	sessment Category
21	9"x9" Brown VFT Mastic (NOT OBSERVED)	700	SF	Room 325		Miscellaneous					YES	X NO
2013 - Fall:	No Change											
Comments:												
2014- Sprin	g: No Change											
Comments:	g											
2014 - Fall·	No Change				\neg							
Comments:	TTO Officings											
2015- Sprin	g: No Change				\neg							
Comments:												
2015 - Fall	No Change											
Comments:												
		-		·								

HA No Material Description Material Material Location Asbestos Material Friable Damage Damage Damage Change in Ass Type Category Type Quantity Units	essment Category
22 12"x12" Sand VFT 2700 SF Public Area, Main Office, Room 130, 227 Miscellaneous Yes None 0	X NO
2013 - Fall: No Change	
Comments:	
2014- Spring: No Change	
Comments:	
2014 - Fall: No Change	
Comments:	
2015- Spring: No Change	
Comments:	
2015 - Fall: No Change	
Comments:	
HA No Material Description Material Material Location Asbestos Material Friable Damage Damage Damage Change in Ass Type Category Type Quantity Units	essment Category
23 12"x12" Sand VFT Mastic 2700 SF Public Area, Main Office, Room 130, 227 Miscellaneous No None 0 TYES	X NO
2013 - Fall: No Change	
Comments:	
2014- Spring: No Change	
Comments:	
2014 - Fall: No Change	
Comments:	
2015- Spring: No Change	
2015- Spring: No Change Comments:	

HA NO	Material Description	Quantity	Units	Material Location	Type	Category	Friable	Type	Quantity	Units	Change in Assess	ment Category
24	12"x12" White w/ Gray Specks VFT	3500	SF	Room 114, 122, 319, 321, 228 Library Office & Storage, 2nd Floor Corridor & Storage		Miscellaneous	No	None	0		YES	X NO
2013 - Fall:	No Change				1							
Comments]							
2014- Sprir	ng: No Change				1							
Comments	:]							
2014 - Fall:	No Change]							
Comments]							
2015- Sprir	ng: No Change]							
Comments	:]							
2015 - Fall:	No Change]							
Comments	:]							
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Assess	ment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
25	12"x12" White w/ Gray Specks VFT Mastic	3500	SF	Room 114, 122, 319, 321, 228 Library Office & Storage, 2nd Floor Corridor & Storage		Miscellaneous	No	None	0		YES	X NO

2013 - Fall: No Change	
Comments:	

2014- Spring: No Change	
Comments:	

2014 - Fall: No Change	
Comments:	

2015- Spring: No Change	
Comments:	

2015 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
26	12"x12" Brown w/ White Dots VFT	250	SF	3rd Floor Teacher's Lounge		Miscellaneous	No	None	0		YES	X NO
2013 - Fall:	No Change											
Comments												
2014- Sprir	ng: No Change											
Comments												
2014 - Fall:	No Change											
Comments												
2015- Sprir	ng: No Change											
Comments												
2015 - Fall:	No Change											
Comments												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
27	12"x12" Brown w/ White Dots VFT Mastic	250	SF	3rd Floor Teacher's Lounge		Miscellaneous	No	None	0		YES	X NO
2013 - Fall:	No Change											
Comments												
2014- Sprir	ng: No Change				\neg							
Comments												
2014 - Fall:	No Change											
Comments												
2015- Sprir	ng: No Change											
Comments												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	essment Category
28	12"x12" Gray VFT	1500	SF	Kitchen Office		Miscellaneous	No	None	0		YES	X NO
	: No Change											
Comments	:											
2014- Spri	ng: No Change											
Comments												
2014 - Fall	: No Change											
Comments												
2015 Cpri	ng: No Change											
Comments												
	: No Change											
Comments	:											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	essment Category
29	12"x12" Gray VFT Mastic	150	SF	Kitchen Office		Miscellaneous	No	None	0		YES	X NO
2013 - Fall	: No Change											
Comments												
2014- Spri	ng: No Change											
Comments												
0044 5 11	N. O.											
Comments	: No Change :											
	ng: No Change											
Comments	:											
2015 - Fall	: No Change											
Comments												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
30	12"x12" Green VFT	2500	SF	Kitchen Storage, Room 218 Storage, Gymnasium Office & Storage		Miscellaneous	No	None	0		YES	X NO
2013 - Fall: I	No Change				1							
Comments:	-]							
2014- Spring	g: No Change				1							
Comments:	,]							
2014 - Fall: I	No Change				1							
Comments:]							
2015- Spring	g: No Change				1							
Comments:	y. He change]							
2015 - Fall: I	No Change				1							
Comments:	10 Onango				1							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
31	12"x12" Green VFT Mastic	2500	SF	Kitchen Storage, Room 218 Storage, Gymnasium Office & Storage	, , , , , , , , , , , , , , , , , , ,	Miscellaneous	No	None	0		YES	X NO
2013 - Fall: I	No Change				1							
Comments:]							
2014- Spring	g: No Change				1							
Comments:	,go]							
2014 - Fall: I	No Change				1							
2014 - Fall: I Comments:	10 Chango											
	g: No Change				7							
Comments:	g. No Change				-							
2015 - Fall: I	Vo Change				- 1							
Comments:	10 Onange				1							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	sessment Category
32	12"x12" White VFT	1200	SF	Room 335		Miscellaneous	No	None	0		YES	X NO
	: No Change											
Comments	:											
	ng: No Change											
Comments	:											
2014 - Fall	: No Change											
Comments	:											
2015- Spri	ng: No Change											
Comments												
2015 - Fall	: No Change											
Comments												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	sessment Category
33	12"x12" White VFT Mastic	1200	SF	Room 335		Miscellaneous	No	None	0		YES	X NO
2013 - Fall	: No Change											
Comments												
2014- Spri	ng: No Change				\neg							
Comments												
2014 - Fall	: No Change				\neg							
Comments												
2015- Spri	ng: No Change				_							
Comments												
2015 - Fall	: No Change				_							
Comments					\dashv							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in As	sessment Category
34	9"x9" Gray VFT - NOT PBSERVED	320	SF	Rooms 331		Miscellaneous	No	None	0		YES	X NO
	No Change											
Comments	:											
2014- Sprir Comments	ng: No Change :											
2014 - Fall:	No Change											
Comments												
2015- Sprir	ng: No Change											
Comments												
2015 - Fall:	No Change											
Comments												
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in As	sessment Category
		Quantity	Units		Туре	Category		Туре	Quantity	Units		
35	9"x9" Gray VFT Mastic	320	SF	Rooms 331		Miscellaneous	No	None	0		YES	X NO
2013 - Fall:	No Change											
Comments												
2014- Sprir	ng: No Change											
Comments												
2014 - Fall:	No Change											
Comments												
Comments	ng: No Change :											
					<u> </u>							
2015 - Fall: Comments	No Change											
Comments	•											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	essment Category
36	12"x12" White w/ Brown Specks VFT	930	SF	Room 235 & 025 Toilet		Miscellaneous	No	None	0		YES	X NO
2013 - Fall:	No Change]							
Comments:												
2014- Sprin	g: No Change				7							
Comments:												
2014 - Fall:	No Change				7							
Comments:												
2015- Sprin	g: No Change				7							
Comments:	g											
2015 - Fall:	No Change				7							
Comments:	140 Ondrige											
					_							
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Ass	essment Category
11/110	Material Becomption	Quantity	Units	Material Education	Туре	Category	Tidolo	Туре	Quantity	Units	Onlange in 7100	ocomoni Catogory
37	12"x12" White w/ Brown Specks VFT Mastic	930	SF	Room 235 & 025 Toilet		Miscellaneous	No	None	0		YES	X NO
2013 - Fall:	No Change				7							
Comments:	<u> </u>											
2014- Sprin	g: No Change				7							
Comments:	g											
2014 - Fall:	No Change				7							
Comments:	THO Change				=							
2015- Sprin	g: No Change				- 7							
Comments:	g. No Change				=							
2015 - Fall:	No Change				- 7							
ZUIU I all.	110 Change				I							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asso	essment Category
38	12"x12" Beige w/ Black Specks VFT	3500	SF	Room 024, 223, 229, 231, 233, Gymnasium Office & Storage		Miscellaneous	No	None	0		YES	X NO
2013 - Fall: N	No Change											
Comments:												
2014- Spring	ı: No Change											
Comments:	g. No Change											
2014 - Fall: N	No Change											
Comments:												
	g: No Change											
Comments:												
2015 - Fall: N	No Change											
Comments:	10 Onango											
					<u></u>							
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Domoseo	Domoso	Domose	Change in Ass	essment Category
HA NO	Material Description	Quantity	Units	Material Location	Type	Category	Fliable	Damage Type	Damage Quantity	Damage Units	Change in Assi	essment Category
39	12"x12" Beige w/ Black Specks VFT Mastic	3500	SF	Room 024, 223, 229, 231, 233, Gymnasium Office & Storage		Miscellaneous	No	None	0		YES	X NO
2013 - Fall: N	Vo Change											
Comments:	10 Orlange											
2014- Spring: No Change Comments:												
Comments.												
2014 - Fall: N	No Change											
Comments:												
2015- Spring	g: No Change				7							

Comments:

2015 - Fall: No Change

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asso	essment Category
40	12"x12" White w/ Green Specks VFT	2400	SF	Room 005, 107, 109 Office, 233, Main Office Toilet, 1st Floor Corridor		Miscellaneous	Yes	None	0		YES	X NO
2013 - Fall: N	lo Change											
Comments:	10 011a11g0											
					- -							
2014- Spring	: No Change											
Comments:												
2014 - Fall: N	lo Change											
Comments:	to onango											
					_							
2015- Spring	: No Change											
Comments:												
2015 - Fall: N	lo Change											
Comments:	to oriango											
					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asso	essment Category
41	12"x12" White w/ Green Specks VFT Mastic	2400	SF	Room 005, 107, 109 Office, 233, Main Office Toilet, 1st Floor Corridor		Miscellaneous	No	None	0		YES	X NO
2013 - Fall: N	lo Change				1							
Comments:	to oriango											
					_							
2014 - Fall: N	lo Change											
Comments:												
2014- Spring	· No Change				1							
Comments:	. 140 Onlange											
					_							
2015- Spring	: No Change											

Comments:

2015 - Fall: No Change

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
42	12"x12" Tan w/ White Specks VFT	2400	SF	Rooms 021, 023		Miscellaneous	No	None	0		YES	X NO
2013 - Fall:	No Change											
Comments:												
2014- Spring	g: No Change											
Comments:												
2014 - Fall:	No Change											
Comments:												
2015- Spring	g: No Change											
Comments:												
2015 - Fall:	No Change											
Comments:	J											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
43	12"x12" Tan w/ White Specks VFT Mastic	2400	SF	Rooms 021, 023		Miscellaneous	No	None	0		YES	X NO
2013 - Fall:	No Change											
Comments:	Ü											
2014- Spring	g: No Change											
Comments:	<i>y</i>											
2014 - Fall:	2014 - Fall: No Change											
Comments:												
2015- Spring	2015- Spring: No Change											
Comments:	<i>J</i> J -											
2015 - Fall:	No Change											
Comments:												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	essment Category
44	12"x12" Brown VFT	140	SF	Room 125 (Under Carpet)		Miscellaneous	No	None	0		YES	X NO
2013 - Fall:	No Change											
Comments												
2014- Sprir	ng: No Change											
Comments												
	No Change											
Comments												
2015- Sprir	ng: No Change											
Comments												
2015 - Fall:	No Change											
Comments												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	essment Category
45	12"x12" Brown VFT Mastic	140	SF	Room 125 (Under Carpet)		Miscellaneous	No	None	0		YES	X NO
2013 - Fall:	No Change											
Comments												
2014- Sprir	ng: No Change											
Comments												
2014 - Fall: No Change												
Comments												
2015- Sprir	ng: No Change											
Comments												
2015 - Fall	No Change	\neg										

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	sessment Category
46	12"x12" Blue VFT	400	SF	Room 019		TSI	No	None	0		YES	X NO
	: No Change											
Comments	:											
2014- Spri	ng: No Change											
Comments												
2014 - Fall	: No Change											
Comments												
2045 Cmri	an Na Changa				<u> </u>							
Comments	ng: No Change											
	: No Change											
Comments	•											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	sessment Category
47	12"x12" Blue VFT Mastic	400	SF	Room 019		Miscellaneous	No	None	0		YES	X NO
2013 - Fall	: No Change											
Comments												
2014 Spri	ng: No Change				\neg							
Comments												
					<u> </u>							
2014 - Fall: No Change Comments:												
Comments												
	ng: No Change											
Comments	:											
2015 - Fall	: No Change											
Comments												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	essment Category
48	12"x12" Green w/ White Streaks VFT	2700	SF	Supply Room Basement, Woodshop		Miscellaneous	No	None	0		YES	X NO
2013 - Fall:	No Change											
Comments:												
2014- Spring	g: No Change											
2014 - Fall:	No Change											
Comments:												
2015- Spring	g: No Change				7							
Comments:												
2015 - Fall:	No Change				7							
Comments:	No Change				-							
					_							
	T		T	1 =		1 =	1 =	T	_			
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	essment Category
49	12"x12" Green w/ White Streaks VFT Mastic	2700	SF	Supply Room Basement, Woodshop	7.	Miscellaneous	No	None	0		YES	X NO
2013 - Fall:	No Change		•	•	<u>. </u>				•	•		
Comments:	140 Change											
					_ _							
2014- Spring Comments:	g: No Change				-							
Comments.												
	2014 - Fall: No Change											
Comments:												
2015- Spring	2015- Spring: No Change											
Comments:	g. 110 Onango											
	N. O.				- 7							
2015 - Fall: Comments:	No Change				-							
Comments.					_i							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	sessment Category
50	Transite Table Tops	500	SF	Rooms 314, 318, 218, & 218 Storage		Miscellaneous	No	None	0		YES	X NO
2013 - Fall: N	lo Change]							
Comments:												
2014- Spring:	: No Change											
Comments:												
2014 - Fall: N	lo Change											
Comments:												
2015- Spring:	: No Change											
Comments:	Ğ											
2015 - Fall: N	lo Change				7							
Comments:	io onango											
					_							
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Ass	sessment Category
1,1,1,10	Material Becompiler	Quantity	Units	Waterial Ecoation	Туре	Category	Thable	Туре	Quantity	Units	onango in 7 loc	occinioni Catogory
51	Hard Coat Plaster	200000	SF	Throughout		Miscellaneous	No	None	0		YES	X NO
2013 - Fall: N	lo Change											
Comments:	.o o.i.ago											
2014 Caring	No Chango				- 1							
2014- Spring: Comments:	. No Change											
					<u></u>							
2014 - Fall: No Change												
Comments:												
2015- Spring: No Change												
Comments:												
2015 - Fall: N	lo Change											
Comments:	omments:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	sessment Category
52	Interior Window Caulk	150000	SF	Interior Windows		Miscellaneous	No	None	0		YES	X NO
2013 - Fall: No	o Change											
Comments:												
2014- Spring:	No Change											
Comments:												
2014 - Fall: No	o Change				\neg							
Comments:												
2015- Spring:	No Change											
Comments:												
2015 - Fall: No	o Change				$\overline{}$							
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	sessment Category
53	Exterior Window Caulk	150000	SF	Exterior Windows		Miscellaneous	No	None	0		YES	X NO
2013 - Fall: No	o Change											
Comments:	-											
2014- Spring:	No Change											
Comments:												
2014 - Fall: No	o Change											
Comments:												
2015- Spring: No Change					$\overline{}$							
Comments:												
2015 - Fall: No	o Change											
Comments:												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	essment Category
54	12" x 12" White w/ Rust Streaks VFT	1200	SF	Room 025, 024		Miscellaneous	No	None	0		YES	X NO
	: No Change											
Comments	:											
2014- Sprii	ng: No Change				\neg							
Comments												
	: No Change											
Comments	:											
2015 - Fall	: No Change											
Comments												
	ng: No Change											
Comments	:											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	essment Category
55	12" x 12" White w/ Rust Streaks VFTMastic	1200	SF	Room 025, 024		Miscellaneous	No	None	0		YES	X NO
2013 - Fall	: No Change				\neg							
Comments	·											
2014 Spri	ng: No Change				\neg							
Comments												
					<u> </u>							
	2014 - Fall: No Change Comments:											
					<u></u>							
	ng: No Change											
Comments	:											
2015 - Fall	No Change											

2013 - Fall: Other Comments:Replaced 2014- Spring: No Change Comments: 2014 - Fall: No Change Comments: 2015- Spring: No Change Comments: 2015 - Fall: No Change	HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	essment Category
Comments: Replaced 2014- Spring: No Change Comments: 2014 - Fall: No Change Comments: 2015- Spring: No Change Comments: 2015 - Fall: No Change	56	2'x4' Dot Ceiling Tile	0	SF	Room 007		Miscellaneous	Yes	None	0		X YES	NO
Comments: Replaced 2014- Spring: No Change Comments: 2014 - Fall: No Change Comments: 2015- Spring: No Change Comments: 2015 - Fall: No Change	2013 - Fall: C	Other											
Comments: 2014 - Fall: No Change Comments: 2015- Spring: No Change Comments: 2015 - Fall: No Change	Comments:R	teplaced											
2014 - Fall: No Change Comments: 2015- Spring: No Change Comments: 2015 - Fall: No Change	2014- Spring	: No Change											
Comments: 2015- Spring: No Change Comments: 2015 - Fall: No Change	Comments:	Comments:											
2015- Spring: No Change Comments: 2015 - Fall: No Change	2014 - Fall: N	lo Change											
Comments: 2015 - Fall: No Change	Comments:	-											
Comments: 2015 - Fall: No Change	2015- Spring	: No Change											
		<u> </u>											
	2015 - Fall: N	lo Change											
Comments:	Comments:												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
57	2'x4'Dot/Wave Ceiling Tile	0	SF	Throughout building		Miscellaneous	Yes	None	0		X YES	NO

2013 - Fall: Other	
Comments:Replaced	

2014- Spring: No Change Comments:

2014 - Fall: No Change Comments:

2015- Spring: No Change Comments:

2015 - Fall: No Change Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
58	2'x2' dot/wave celing tile	1000	SF	Room 025		Miscellaneous	Yes	None	0		X YES	NO
2013 - Fall: O												
2014- Spring: Comments:												
2014 - Fall: N Comments:	lo Change											
2015- Spring: Comments:	: No Change											
2015 - Fall: N Comments:	lo Change											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
59	Terrazo	4000	SF	Auditorium Lobby and South Stairs		Miscellaneous	No	None	0		YES	X NO
2013 - Fall: N Comments:	lo Change											
2014- Spring: Comments:	: No Change											
2014 - Fall: N Comments:	lo Change											

2015- Spring: No Change

2015 - Fall: No Change

Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	essment Category
60	Brown Ceramic Tile Grout	1010	SF	1st, 2nd, and 3rd Floor South Boys Washrooms		Miscellaneous	Yes	None	0		YES	X NO
2013 - Fall: N Comments:	No Change]							
2014- Spring Comments:	: No Change											
2014 - Fall: N Comments:	No Change]							
2015- Spring Comments:	: No Change				}							
2015 - Fall: N Comments:	No Change											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	essment Category
61	Brown Ceramic Tile Adhesive	1010	SF	1st, 2nd, and 3rd Floor South Boys Washrooms		Miscellaneous	No	None	0		YES	X NO
2013 - Fall: N Comments:	No Change											
2014- Spring Comments:	: No Change]							
2014 - Fall: N Comments:	No Change]							
2015- Spring	: No Change]							

Comments:

2015 - Fall: No Change

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
62	Blue Ceramic Tile Grout	2300	SF	1st, 2nd, and 3rd Floor Girls Washrooms (All)		Miscellaneous	Yes	None	0		YES	X NO
2013 - Fall: N	lo Change											
Comments:												
2014- Spring	: No Change											
Comments:												
2014 - Fall: N	lo Change											
Comments:												
2015- Spring	: No Change											
Comments:												
2015 - Fall: N	lo Change											
Comments:	Ğ											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
63	Blue Ceramic Tile Adhesive	2300	SF	1st, 2nd, and 3rd Floor Girls Washrooms (All)		Miscellaneous	No	None	0		YES	X NO
2013 - Fall: N	lo Change											
Comments:	-											
2014- Spring	: No Change											
Comments:	•											
2014 - Fall: N	lo Change											
Comments:	V											
2015- Spring	: No Change											

Comments:

2015 - Fall: No Change

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	essment Category
64	Gray Ceramic Tile Grout	750	SF	1st, 2nd, and 3rd Floor South Boys Washrooms		Miscellaneous	Yes	None	0		YES	X NO
2013 - Fall: Comments:												
2014- Sprin Comments:	g: No Change											
2014 - Fall: Comments:	<u> </u>											
2015- Sprin Comments:	g: No Change											
2015 - Fall: Comments:												
					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	essment Category
65	Gray Ceramic Tile Adhesive	750	SF	1st, 2nd, and 3rd Floor South Boys Washrooms		Miscellaneous	No	None	0		YES	X NO
2013 - Fall: Comments:												
2014- Sprin Comments:	g: No Change											
2014 - Fall: Comments:	No Change											
	g: No Change				_							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	sessment Category
66	White Ceramic Tile Grout (Floor and Walls)	2000	SF	Basement Locker Room		Miscellaneous	No	None	0		YES	X NO
2013 - Fall	: No Change]							
Comments	:											
	ng: No Change											
Comments) <u>.</u>											
2014 - Fall	: No Change											
Comments):											
2015- Spri	ng: No Change											
Comments).											
2015 - Fall	: No Change				7							
Comments	<u> </u>											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	sessment Category
68	Multi-color Carpet Adhesive	1100	SF	Rooms 325, 317, 225, 125		Miscellaneous	No	None	0		YES	X NO
2013 - Fall	: No Change											
Comments	S:											
2014 - Fall	: No Change				7							
Comments												
2014- Spri	ng: No Change				7							
Comments]							
2015 - Fall	: No Change				7							

Comments:

2015- Spring: No Change

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
69	Blue Carpet Adhesive	430	SF	Room 217 and Chief Engineer's Office (015)		Miscellaneous	No	None	0		YES	X NO
2013 - Fall: N	No Change											
Comments:												
2014- Spring	g: No Change											
Comments:												
2014 - Fall: N	No Change											
Comments:	-											
2015- Spring	ı: No Change											
Comments:	, G											
2015 - Fall: N	No Change											
Comments:	To Change											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
70	Red Carpet Adhesive	350	SF	Rooms 117, 217, 314 and 317		Miscellaneous	No	None	0		YES	X NO
2013 - Fall: N	No Change											
Comments:												
2014- Spring	g: No Change				7							
Comments:	J. 140 Onlango											
2014 Fall: N	No Chango				_ _							
2014 - Fall: Note:	No Change											
					_ _							
2015- Spring Comments:	g: No Change											
Commonto.					_							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
71	Maroon Carpet Adhesive	1200	SF	Offices		Miscellaneous	No	None	0		YES	X NO
2013 - Fall:	: No Change											
Comments												
2014- Sprir	ng: No Change											
Comments												
2014 - Fall:	: No Change											
Comments	<u> </u>											
2015- Sprir	ng: No Change											
Comments	· ·											
2015 - Fall:	: No Change											
Comments	:											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
		_	1				-	-		+		

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessi	ment Category
72	1 x 1 White Fissured Ceiling Tile	0	SF	Lunch Room (332)		Miscellaneous	Yes	None	0		X YES	NO

2013 - Fall: Other Comments:Replaced

2014- Spring: No Change Comments:

2014 - Fall: No Change Comments:

2015- Spring: No Change Comments:

2015 - Fall: No Change Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
73	12x12 OffWhite w/ Orange Specks VFT	2200	SF	203,103,712 & 116		Miscellaneous	No	None	0		YES	X NO
2013 - Fall: N	No Change											
Comments:	<u> </u>											
2014- Spring	ı: No Change											
Comments:	: No Change											
2014 - Fall: N	No Change											
Comments:												
2015- Spring	ı: No Change											
Comments:	-											
2015 - Fall: N	No Change											
Comments:	_											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
74	12x12 OffWhite w/ Orange Specks VFT Mastic	2200	SF	203,103,212 &116		Miscellaneous	No	None	0		YES	X NO
2013 - Fall: N	No Change											
Comments:	<u> </u>											
2014- Spring	ı: No Change											
Comments:	<u> </u>											

2015- Spring: No Change

2015 - Fall: No Change

Comments:

Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	essment Category
75	12x12 White w/ Multi Color Specks	800	SF	118		Miscellaneous	No	None	0		YES	X NO
2013 - Fall:	No Change				\neg							
Comments:												
2014- Spring	g: No Change											
Comments:												
2014 - Fall:	No Change											
Comments:												
	g: No Change											
Comments:												
2015 - Fall:	No Change											
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	essment Category
76	12x12 White w/ Multi Color Specks	800	SF	118		Miscellaneous	No	None	0		YES	X NO
2013 - Fall:	No Change											
Comments:	-											
2014- Spring	g: No Change											
Comments:	•											
2014 - Fall:	No Change											
Comments:												
	g: No Change											
Comments:												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
Α	MJP E/F/V on Aircell Pipe Insulation	350	LF	Throughout		TSI	Yes	None	0		X YES	NO
					_							
2013 - Fall: A	bated											
Comments:N	ew water lines installe	d										
		-										
2014- Spring	: No Change											
Comments:												
2014 - Fall: N	lo Change											
Comments:												
201E Carina	. No Change				\neg							
2015- Spring	: No Change											
Comments:												
2015 - Fall: N	lo Change											
Comments:												
					_							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessi	ment Category
В	Mag Block Tank Insulation	1000	SF	Pump Room, Boiler Room		TSI	Yes	None	0		X YES	NO

2013 - Fall: Abated	
Comments: New water lines installed	

2014 - Fall: No Change	
Comments:	

2014- Spring: No Change	
Comments:	

2015- Spring: No Change
Comments:

2015 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
С	Aircell Pipe Insulation	2500	LF	Throughout		TSI	Yes	Dist	5		X YES	NO
2012 Fall: A	hatad											

2013 - Fall: Abated	
Comments:New water lines installed	

2014- Spring: No Change	
Comments:	

2014 - Fall: No Change	
Comments:	

2015 - Fall: No Change
Comments:

201	15- Spring: No Change
Cor	mments:

ALL LEA Responsibilities, for this school, will be met.

Lynn A.Crivello

Sym & Crwill

NOTICE TO PARENTS AND STAFF REGARDING THE ASBESTOS MANAGEMENT PLAN NOTIFICATION

School: Jose De Diego Community Academy
Date:10/13/2015
This is to notify you in accordance with Illinois and Federal Asbestos Regulations, that a copy of the Asbestos Management Plan is available at each school during school hours by appointment. Requests to review the Asbestos Management Plan must be made at least 24 hours in advance.
Also please be advised that CPS conducts asbestos inspections of all Schools every three years. The last inspection was completed in 2013. Asbestos surveillances are conducted every six months.
CHECK ONE
A copy of this notice was sent home in each child's backpack.
X A copy of this notice was printed in the school's newsletter and sent home with each child
A copy of this notice was printed in the school's calendar and sent home with each child
Other.
A COPY OF THIS NOTICE MUST BE PLACED IN THE

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

SCHOOL'S ASBESTOS MANAGEMENT PLAN.