

Chicago Public Schools

6 Month Asbestos Surveillance

Fall 2011

School Schurz High School
Address 3601 N. Milwaukee Ave.

Oracle Unit 46281 **Building ID** 1530
Region 1 **General Services Route** 29

Asbestos Surveyor: _____

Survey Date: _____

E-mail Address: _____

CHECK HERE IF NO CHANGE TO ASBESTOS

A copy of the 2011/2012 notice to parents and staff regarding the asbestos management plan notification was distributed via:

Each child's backpack
 Notice printed in school's newsletter/calendar
 Other _____

Principal Signature _____

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
01	12"x12" Tan w/ White Streaks VFT	32604	SF	Throughout - 1908 (See Hatching Maps); Corridor at Rm 112	Chrysotile	MISC	No	Dist	225	SF	
<i>3YR Inspector Comments: 2007 - No change since last inspection</i>											
Condition Not Changed in Fall 2010			SF		Chrysotile	MISC				SF	
<i>Comments: ADA project</i>											
Condition Changed in Spring 2011			SF		Chrysotile	MISC				SF	
<i>Comments: 909 SF removed in ADA Rehab</i>											
Fall 2011											YES NO
Comment:											

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

Oracle Unit: 46281

Page 1

Please send a copy of this report to Lynn Crivello, 125 S. Clark St., 17th Floor, GSR #125

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
02	9"x9" Brown w/ White Specks VFT	3700	SF	Rm 219- 222, 319, 320 Vault, 321 - 1908 Bldg.	Chrysotile	MISC	No	Dist	400	SF	
3YR Inspector Comments: 2007 - No change since last inspection. In 2010, Rm 320 Material was Concealed Under HA# 107, HA#108, HA# 104, and HA #105.											
Condition Changed in Fall 2010			SF		Chrysotile	MISC				SF	
Comments: ADA project											
Condition Changed in Spring 2011			SF		Chrysotile	MISC				SF	
Comments: 2740 SF removed in ADA Rehab also 60 fittings											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
04	12"x12" Tan w/ White Streaks VFT Mastic	32604	SF	Throughout - 1908 (See Hatching Maps)	Chrysotile	MISC	No	None	0		
3YR Inspector Comments: 2007 - No change since last inspection											
Condition Not Changed in Fall 2010			SF		Chrysotile	MISC					
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC					
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
05	9"x9" Brown w/ White Specks VFT Mastic	3600	SF	Rm 219- 222, 319, 320, 321 - 1908 Bldg.	Chrysotile	MISC	No	None	0		
3YR Inspector Comments: 2007 - No change since last inspection											
Condition Changed in Fall 2010			SF		Chrysotile	MISC					
Comments: ADA Project											
Condition Changed in Spring 2011			SF		Chrysotile	MISC					
Comments: 2350 SF removed in ADA Rehab											
Fall 2011											YES NO
Comment:											

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
07	12"x12" Tan w/ White Streaks VFT	5665	SF	Rm 305, 1st through 3rd Fl Corridor, 3rd Fl Girls Toilet - 1915 Bldg.	Chrysotile	MISC	No	None	0		
3YR Inspector Comments: 2007 - No change since last inspection. Rm 105 (750 SF) removed from list in 2010.											
Condition Not Changed in Fall 2010			SF		Chrysotile	MISC					
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC					
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
08	12"x12" Tan w/ White Streaks VFT Mastic	5665	SF	Rm 305, 1st through 3rd Fl Corridor, 3rd Fl Girls Toilet - 1915 Bldg.	Chrysotile	MISC	No	None			
3YR Inspector Comments: 2007 - No change since last inspection. Rm 105 (750 SF) removed from list in 2010.											
Condition Not Changed in Fall 2010			SF		Chrysotile	MISC					
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC					
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
09	9"x9" Green w/ White Specks VFT	340	SF	Rm 303 - 1915 Bldg.	Chrysotile	MISC	No	None	0		
3YR Inspector Comments: 2007 - No change since last inspection											
Condition Not Changed in Fall 2010			SF		Chrysotile	MISC					
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC					
Comments:											
Fall 2011											YES NO
Comment:											

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
10	9"x9" Green w/ White Specks VFT Mastic	340	SF	Rm 303 - 1915 Bldg.	Chrysotile	MISC	No	None	0		
3YR Inspector Comments: 2007 - No change since last inspection											
Condition Not Changed in Fall 2010			SF		Chrysotile	MISC					
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC					
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
1009	Boiler #1 (small)	350	SF		Assumed	TSI	Yes	None	0		
3YR Inspector Comments: 2008 - material identified during the January 23, 2008 audit visit. Initial inspections assigned Has numbers B,C,D. Test to confirm asbestos content											
Condition Changed in Fall 2010			SF		Assumed	TSI					
Comments: Boiler Project											
Condition Changed in Spring 2011			SF		Assumed	TSI					
Comments: 300 SF removed in Boiler Project											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
103	MJP E/F/V on Fiberglass Pipe Insulation	0		1st Floor Men's Faculty Toilet, 2nd & 3rd Floor Girls Toilets (chases) - 1908	Assumed	TSI	Yes	None	0		
3YR Inspector Comments:											
Condition Changed in Fall 2010					Assumed	TSI					
Comments: ADA Project											
Condition Changed in Spring 2011					Assumed	TSI					
Comments: 10 LF and 109 fittings removed in ADA Rehab											
Fall 2011											YES NO
Comment:											

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
104	Green Linoleum	400	SF	Room 365, Prep Room and Storage Room - 1923, Rm 320	Assumed	MISC	No	None	0		
3YR Inspector Comments: Rm 320 Added in 2010.											
Condition Not Changed in Fall 2010			SF		Assumed	MISC					
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC					
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
105	Green Linoleum Mastic	400		Room 365, Prep Room and Storage Room - 1923; Rm 320	Assumed	MISC	No	None	0		
3YR Inspector Comments:											
Condition Not Changed in Fall 2010					Assumed	MISC					
Comments:											
Condition Not Changed in Spring 2011					Assumed	MISC					
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
107	12" x 12" Gray w/ White Speck VFT	1400	SF	Room 215 - 1908	Assumed	MISC	No	None	0		
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			SF		Assumed	MISC					
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC					
Comments:											
Fall 2011											YES NO
Comment:											

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
108	12" x 12" Gray w/ White Speck VFT Mastic	1400	SF	Roon 215 - 1908	Assumed	MISC	No	None	0		
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			SF		Assumed	MISC					
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC					
Comments:											
Fall 2011										YES	NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
109	12" x 12" Orange Cork VFT	4500	SF	Library - 1908	Assumed	MISC	No	None	0		
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			SF		Assumed	MISC					
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC					
Comments:											
Fall 2011										YES	NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
11	12"x12" Tan w/ White Streaks VFT	18061	SF	Throughout - 1923 (See Hatching Maps)	Chrysotile	MISC	No	Dist	35	SF	
3YR Inspector Comments: 2007 - No change since last inspection											
Condition Not Changed in Fall 2010			SF		Chrysotile	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC				SF	
Comments:											
Fall 2011										YES	NO
Comment:											

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
110	12" x 12" Orange Cork VFT Mastic	4500	SF	Library - 1908	Assumed	MISC	No	None	0		
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			SF		Assumed	MISC					
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC					
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
111	Carpet Mastic	4500	SF	Library - 1908	Assumed	MISC	No	None	0		
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			SF		Assumed	MISC					
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC					
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
112	Carpet Adhesive	4934	SF	Main Office, Nurse Office 128, 125A, 114, 110, 115, Teacher/Staff Room, 376, 301	Assumed	MISC	No	None	0		
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			SF		Assumed	MISC					
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC					
Comments:											
Fall 2011											YES NO
Comment:											

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
113	12"x12" Powder-Blue w/White and Blue Streaks VFT	2000	SF	Rm 311 (1915 Addition)	Assumed	MISC	No	None	0		
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			SF		Assumed	MISC					
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC					
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
113M	12"x12" Powder-Blue w/White and Blue Streaks VFT Mastic	2000	SF	Rm 311 (1915 Addition)	Assumed	MISC	No	None	0		
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			SF		Assumed	MISC					
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC					
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
12	12"x12" Tan w/ White Streaks VFT Mastic	18061	SF	Throughout - 1923 (See Hatching Maps)	Chrysotile	MISC	No	None	0		
3YR Inspector Comments: 2007 - No change since last inspection											
Condition Not Changed in Fall 2010			SF		Chrysotile	MISC					
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC					
Comments:											
Fall 2011											YES NO
Comment:											

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
13	9"x9" Cocoa w/ White & Brown Streaks VFT	7260	SF	Room 363, 234, 235, 236, 361, 369 - 1923	Chrysotile	MISC	No	None	0		
3YR Inspector Comments: 2007 - No change since last inspection. Rms 234, 235, 236, 361, 369 added in 2010, Total Added Area 2500 SF.											
Condition Not Changed in Fall 2010			SF		Chrysotile	MISC					
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC					
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
14	9"x9" Cocoa w/ White & Brown Streaks VFT Mastic	7260	SF	Room 363, 234, 235, 236, 361, 369 - 1923	Chrysotile	MISC	No	None	0		
3YR Inspector Comments: 2007 - No change since last inspection. Rms 234, 235, 236, 361, 369 added in 2010, Total Added Area 2500 SF.											
Condition Not Changed in Fall 2010			SF		Chrysotile	MISC					
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC					
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
17	12"x12" White w/ Light Brown Streaks VFT	0	SF	Rooms 311 - 1915 (Removed)	Chrysotile	MISC	No			SF	
3YR Inspector Comments: 2007 - Wood floor in room 306, 2008 -material not observed in rm. 311 during the 1/23/08 audit visit. Removed From Rm 311, Per 2010 Re-inspection.											
Condition Not Changed in Fall 2010			SF		Chrysotile	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC				SF	
Comments:											
Fall 2011											YES NO
Comment:											

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
18	12"x12" White w/ Light Brown Streaks VFT Mastic	0	SF	Rooms 306 & 311 - 1915 (Both Removed)	Chrysotile	MISC	No				
3YR Inspector Comments: 2007 - No change since last inspection; Per 2010 Re-inspection, Rm 311 Removed 2000 SF; Rm 306 Removed 1000 SF, the Latter Now Wood Area.											
Condition Not Changed in Fall 2010			SF		Chrysotile	MISC					
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC					
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
19	9"x9" Red w/ Black & White Specks VFT	340	SF	Room 303 - 1915	Chrysotile	MISC	No	None	0		
3YR Inspector Comments: 2007 - No change since last inspection											
Condition Not Changed in Fall 2010			SF		Chrysotile	MISC					
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC					
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
20	9"x9" Red w/ Black & White Specks VFT Mastic	340	SF	Room 303 - 1915	Chrysotile	MISC	No	None	0		
3YR Inspector Comments: 2007 - No change since last inspection											
Condition Not Changed in Fall 2010			SF		Chrysotile	MISC					
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC					
Comments:											
Fall 2011											YES NO
Comment:											

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
21	9"x9" Brown w/ White & Black Streaks VFT	20	SF	Room 303 - 1915	Chrysotile	MISC	No	None	0		
3YR Inspector Comments: 2007 - No change since last inspection											
Condition Not Changed in Fall 2010			SF		Chrysotile	MISC					
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC					
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
22	9"x9" Brown w/ White & Black Streaks VFT Mastic	20	SF	Room 303 - 1915	Chrysotile	MISC	No	None	0		
3YR Inspector Comments: 2007 - No change since last inspection											
Condition Not Changed in Fall 2010			SF		Chrysotile	MISC					
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC					
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
23	24" X 6" Black VFT	70	SF	Room 303 - 1915	Chrysotile	MISC	No	None	0		
3YR Inspector Comments: 2007 - No change since last inspection											
Condition Not Changed in Fall 2010			SF		Chrysotile	MISC					
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC					
Comments:											
Fall 2011											YES NO
Comment:											

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
24	24" X 6" Black VFT	70	SF	Room 303 - 1915	Chrysotile	MISC	No	None	0		
3YR Inspector Comments: 2007 - No change since last inspection											
Condition Not Changed in Fall 2010			SF		Chrysotile	MISC					
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC					
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
25	12"x12" Beige w/ Brown & White Streaks VFT	750	SF	Room 309 - 1915	Assumed	MISC	No	None	0		
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			SF		Assumed	MISC					
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC					
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
26	12"x12" Beige w/ Brown & White Streaks VFT Mastic	750	SF	Room 309 - 1915	Assumed	MISC	No	None	0		
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			SF		Assumed	MISC					
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC					
Comments:											
Fall 2011											YES NO
Comment:											

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
27	12"x12" Brown w/ White Specks VFT	1150	SF	1st, 2nd, & 3rd Floor Corridors - 1915	Chrysotile	MISC	No	Dist	40	SF	
3YR Inspector Comments: 2007 - No change since last inspection											
Condition Changed in Fall 2010			SF		Chrysotile	MISC				SF	
Comments: ADA Project											
Condition Changed in Spring 2011			SF		Chrysotile	MISC				SF	
Comments: 582 SF removed in ADA Rehab											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
28	12"x12" Brown w/ White Specks VFT Mastic	1150	SF	1st, 2nd, & 3rd Floor Corridors - 1915	Chrysotile	MISC	No		0		
3YR Inspector Comments: 2007 - No change since last inspection											
Condition Not Changed in Fall 2010			SF		Chrysotile	MISC					
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC					
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
31	12"x12" Beige w/ White & Orange Streaks VFT	1810	SF	Room 310 and 341 - 1923	Chrysotile	MISC	No	None	0		
3YR Inspector Comments: 2007 - No change since last inspection											
Condition Not Changed in Fall 2010			SF		Chrysotile	MISC					
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC					
Comments:											
Fall 2011											YES NO
Comment:											

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
32	12"x12" Beige w/ White & Orange Streaks VFT Mastic	1810	SF	Room 310 and 341 - 1923	Chrysotile	MISC	No	None	0		
3YR Inspector Comments: 2007 - No change since last inspection											
Condition Not Changed in Fall 2010			SF		Chrysotile	MISC					
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC					
Comments:											
Fall 2011										YES	NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
33	9"x9" Cocoa w/ White & Brown Short Streaks VFT	3324	SF	3rd Floor Hallway - 1923	Chrysotile	MISC	No	None	0		
3YR Inspector Comments: 2007 - No change since last inspection											
Condition Not Changed in Fall 2010			SF		Chrysotile	MISC					
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC					
Comments:											
Fall 2011										YES	NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
34	9"x9" Cocoa w/ White & Brn Short Strks VFT Mastic	3324	SF	3rd Floor Hallway - 1923	Chrysotile	MISC	No	None	0		
3YR Inspector Comments: 2007 - No change since last inspection											
Condition Not Changed in Fall 2010			SF		Chrysotile	MISC					
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC					
Comments:											
Fall 2011										YES	NO
Comment:											

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
35	12"x 12" Cocoa w/ White & Brown Long Streaks VFT	924	SF	Cafeteria, Serving Area, Room 253 - 1923	Chrysotile	MISC	No	Loc	70	SF	
3YR Inspector Comments: 2007 - No change since last inspection 2008 - material was not found in Cafeteria, Serving area during the audit visit on 1/23/08											
Condition Not Changed in Fall 2010			SF		Chrysotile	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC				SF	
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
36	12"x12" Cocoa w/ Wht. & Brwn. Lng Strks VFT Mastic	924	SF	Cafeteria, Serving Area, Room 253 - 1923	Chrysotile	MISC	No	None	0		
3YR Inspector Comments: 2007 - No change since last inspection 2008 - material was not found in Cafeteria, Serving area during the audit visit on 1/23/08											
Condition Not Changed in Fall 2010			SF		Chrysotile	MISC					
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC					
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
39	9"x9" Pine Green w/ White Streaks VFT	3620	SF	Cafeteria - 1923	Chrysotile	MISC	No	Loc	50	SF	
3YR Inspector Comments: 2007 - No change since last inspection 2008 - during the 1/23/08 audit visit removal was requested by the Engineer											
Condition Not Changed in Fall 2010			SF		Chrysotile	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC				SF	
Comments:											
Fall 2011											YES NO
Comment:											

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
40	9"x9" Pine Green w/ White Streaks VFT Mastic	3620	SF	Cafeteria - 1923	Chrysotile	MISC	No	None	0	SF	
3YR Inspector Comments: 2007 - No change since last inspection 2008 - during the 1/23/08 audit visit removal was requested by the Engineer											
Condition Not Changed in Fall 2010			SF		Chrysotile	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC				SF	
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
41	9"x9" White w/ Pine Green Streaks VFT	3620	SF	Cafeteria - 1923	Chrysotile	MISC	No	Loc	100	SF	
3YR Inspector Comments: 2007 - No change since last inspection 2008 - during the 1/23/08 audit visit removal was requested by the Engineer											
Condition Not Changed in Fall 2010			SF		Chrysotile	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC				SF	
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
42	9"x9" White w/ Pine Green Streaks VFT Mastic	3620	SF	Cafeteria - 1923	Chrysotile	MISC	No	None	0	SF	
3YR Inspector Comments: 2007 - No change since last inspection 2008 - during the 1/23/08 audit visit removal was requested by the Engineer											
Condition Not Changed in Fall 2010			SF		Chrysotile	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC				SF	
Comments:											
Fall 2011											YES NO
Comment:											

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
47	Brown Linoleum	504	SF	Teacher's Rest Area & Room 376 - 1923	Chrysotile	MISC	No	None	0		
3YR Inspector Comments: 2007 - Room is carpeted 2008 - during the 1/23/08 audit visit inspector confirmed that linoleum is still in place beneath the newer carpet. In 2010 Teachers Rest Area and Rm 376 the Material was Covered By Gray-Blue w/Orange Specks Carpet.											
Condition Not Changed in Fall 2010			SF		Chrysotile	MISC					
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC					
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
55	12"x12" Gray w/ White & Brown Spots VFT	2050	SF	Room 212, 340 - 1923, 315	Chrysotile	MISC	No	Dist	300	SF	
3YR Inspector Comments: 2007 - No change since last inspection 2008 - During the audit visit on 1/23/08 inspector observed material matching the description in rm. 315 (total 1250 s.f.) It is over 25% damaged and needs removal/repair											
Condition Changed in Fall 2010			SF		Chrysotile	MISC				SF	
Comments: ADA Project											
Condition Changed in Spring 2011			SF		Chrysotile	MISC				SF	
Comments: 1,300 SF removed from room 315 in ADA Rehab											
Fall 2011											YES NO
Comment:											

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
56	12"x12" Gray w/ White & Brown Spots VFT Mastic	2050	SF	Room 212, 340 - 1923, 315	Chrysotile	MISC	No	Dist	300	SF	
3YR Inspector Comments: 2007 - No change since last inspection 2008 - During the audit visit on 1/23/08 inspector observed material matching the description in rm. 315 (total 1250 s.f.) It is over 25% damaged and needs removal/repair											
Condition Not Changed in Fall 2010			SF		Chrysotile	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC				SF	
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
57	9"x9" Gray VFT	750	SF	Room 128 - 1923	Chrysotile	MISC	No	None	0		
3YR Inspector Comments: 2007 - No change since last inspection											
Condition Not Changed in Fall 2010			SF		Chrysotile	MISC					
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC					
Comments:											
Fall 2011											YES NO
Comment:											

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
58	9"x9" Gray VFT Mastic	750	SF	Room 128 - 1923	Chrysotile	MISC	No	None	0		
3YR Inspector Comments: 2007 - No change since last inspection											
Condition Not Changed in Fall 2010			SF		Chrysotile	MISC					
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC					
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
59	12"x12" Brown w/ White Specks VFT	4900	SF	1st Floor through 4th Floor Corridors - 1908	Chrysotile	MISC	No	None	0		
3YR Inspector Comments: 2007 - No change since last inspection											
Condition Not Changed in Fall 2010			SF		Chrysotile	MISC					
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC					
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
60	12"x12" Brown w/ White Specks VFT Mastic	4900	SF	1st Floor through 4th Floor Corridors - 1908	Chrysotile	MISC	No	None	0		
3YR Inspector Comments: 2007 - No change since last inspection											
Condition Not Changed in Fall 2010			SF		Chrysotile	MISC					
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC					
Comments:											
Fall 2011											YES NO
Comment:											

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
61	12"x12" White w/ Gray Streaks VFT	3475	SF	Main Office & Room 315 & 117 - 1908	Chrysotile	MISC	No	Dist	25		
3YR Inspector Comments: 2007 - No change since last inspection											
Condition Not Changed in Fall 2010			SF		Chrysotile	MISC					
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC					
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
62	12"x12" White w/ Gray Streaks VFT Mastic	3475	SF	Main Office & Room 315 & 117 - 1908	Chrysotile	MISC	No	None	0		
3YR Inspector Comments: 2007 - No change since last inspection											
Condition Not Changed in Fall 2010			SF		Chrysotile	MISC					
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC					
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
63	9'x9" Beige w/ Brown & White Streaks VFT	350	SF	Room 316 - 1908	Chrysotile	MISC	No	None	0		
3YR Inspector Comments: 2007 - No change since last inspection											
Condition Not Changed in Fall 2010			SF		Chrysotile	MISC					
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC					
Comments:											
Fall 2011											YES NO
Comment:											

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
69	9"x9" Green w/ White Streaks VFT	500	SF	Room 116 - 1908	Chrysotile	MISC	No	None	0		
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			SF		Chrysotile	MISC					
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC					
Comments:											
Fall 2011										YES	NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
70	9"x9" Green w/ White Streaks VFT Mastic	500	SF	Room 116 - 1908	Chrysotile	MISC	No	None	0		
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			SF		Chrysotile	MISC					
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC					
Comments:											
Fall 2011										YES	NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
71	9"x9" Black w/ White Streaks VFT	1300	SF	Room 116 - 1908	Chrysotile	MISC	No	None	0	SF	
3YR Inspector Comments: 2007 - No change since last inspection 2008 - damage was noted during the 1/23/08 audit visit											
Condition Not Changed in Fall 2010			SF		Chrysotile	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC				SF	
Comments:											
Fall 2011										YES	NO
Comment:											

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
72	9"x9" Black w/ White Streaks VFT Mastic	1300	SF	Room 116 - 1908	Chrysotile	MISC	No	None	0	SF	
3YR Inspector Comments: 2007 - No change since last inspection 2008 - damage was noted during the 1/23/08 audit visit											
Condition Not Changed in Fall 2010			SF		Chrysotile	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC				SF	
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
77	9"x9" Brown w/ White & Red Streaks VFT	650	SF	Room 018 & Hallway -1908	Chrysotile	MISC	No	Dist	150	SF	
3YR Inspector Comments: 2007 - No change since last inspection											
Condition Not Changed in Fall 2010			SF		Chrysotile	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC				SF	
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
78	9"x9" Brown w/ White & Red Streaks VFT Mastic	650	SF	Room 018 & Hallway - 1908	Chrysotile	MISC	No	None	0		
3YR Inspector Comments: 2007 - No change since last inspection											
Condition Not Changed in Fall 2010			SF		Chrysotile	MISC					
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC					
Comments:											
Fall 2011											YES NO
Comment:											

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
79	9"x9" Tan w/ Brown & White Streaks VFT	650	SF	Room 018 & Hallway - 1908	Chrysotile	MISC	No	Dist	150	SF	
3YR Inspector Comments: 2007 - No change since last inspection											
Condition Not Changed in Fall 2010			SF		Chrysotile	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC				SF	
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
80	9"x9" Tan w/ Brown & White Streaks VFT Mastic	650	SF	Room 018 & Hallway - 1908	Chrysotile	MISC	No	None	0		
3YR Inspector Comments: 2007 - No change since last inspection											
Condition Not Changed in Fall 2010			SF		Chrysotile	MISC					
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC					
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
81	9"x9" Gray w/ White Swirls VFT	1900	SF	Library (Underneath Carpet, HA # 111, # 109 & # 110) - 1908	Chrysotile	MISC	No	None	0		
3YR Inspector Comments: 2007 - No change since last inspection											
Condition Not Changed in Fall 2010			SF		Chrysotile	MISC					
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC					
Comments:											
Fall 2011											YES NO
Comment:											

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
82	9"x9" Gray w/ White Swirls VFT Mastic	1900	SF	Library (Underneath Carpet, HA # 111, # 109 & # 110) - 1908	Chrysotile	MISC	No	None	0		
3YR Inspector Comments: 2007 - No change since last inspection											
Condition Not Changed in Fall 2010			SF		Chrysotile	MISC					
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC					
Comments:											
Fall 2011										YES	NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
83	9"x9" White w/ Black Swirls VFT	1900	SF	Library (Underneath Carpet, HA # 111, # 109 & # 110) - 1908	Chrysotile	MISC	No	None	0		
3YR Inspector Comments: 2007 - No change since last inspection											
Condition Not Changed in Fall 2010			SF		Chrysotile	MISC					
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC					
Comments:											
Fall 2011										YES	NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
84	9"x9" White w/ Black Swirls VFT Mastic	1900	SF	Library (Underneath Carpet, HA # 111, # 109 & # 110) - 1908	Chrysotile	MISC	No	None	0		
3YR Inspector Comments: 2007 - No change since last inspection											
Condition Not Changed in Fall 2010			SF		Chrysotile	MISC					
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC					
Comments:											
Fall 2011										YES	NO
Comment:											

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
85	12"x24" Gray w/ Black & White Swirls VFT	200	SF	Library (Underneath Carpet, HA # 111, # 109 & # 110) - 1908	Chrysotile	MISC	No	None	0		
3YR Inspector Comments: 2007 - No change since last inspection											
Condition Not Changed in Fall 2010			SF		Chrysotile	MISC					
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC					
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
86	12"x24" Gray w/ Black & White Swirls VFT Mastic	200	SF	Library (Underneath Carpet, HA # 111, # 109 & # 110) - 1908	Chrysotile	MISC	No	None	0		
3YR Inspector Comments: 2007 - No change since last inspection											
Condition Not Changed in Fall 2010			SF		Chrysotile	MISC					
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC					
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
87	Stair Tread Tile Yellow w/ Gold Specks VFT	35	SF	Library (Underneath Carpet, HA # 111, # 109 & # 110) - 1908	Chrysotile	MISC	No	None	0		
3YR Inspector Comments: 2007 - No change since last inspection											
Condition Not Changed in Fall 2010			SF		Chrysotile	MISC					
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC					
Comments:											
Fall 2011											YES NO
Comment:											

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
88	Stair Tread Tile Yellow w/ Gold Specks VFT Mastic	35	SF	Library (Underneath Carpet, HA # 111, # 109 & # 110)- 1908	Chrysotile	MISC	No	None	0		
3YR Inspector Comments: 2007 - No change since last inspection											
Condition Not Changed in Fall 2010			SF		Chrysotile	MISC					
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC					
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
89	Stair Tread Tile Gray w/ White Marble VFT	20	SF	Library (Underneath Carpet, HA # 111, # 109 & # 110) - 1908	Chrysotile	MISC	No	None	0		
3YR Inspector Comments: 2007 - No change since last inspection											
Condition Not Changed in Fall 2010			SF		Chrysotile	MISC					
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC					
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
90	Stair Tread Tile Gray w/ White Marble VFT Mastic	20	SF	Library (Underneath Carpet, HA # 111, # 109 & # 110) - 1908	Chrysotile	MISC	No	None	0		
3YR Inspector Comments: 2007 - No change since last inspection											
Condition Not Changed in Fall 2010			SF		Chrysotile	MISC					
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC					
Comments:											
Fall 2011											YES NO
Comment:											

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
91	12"x12" Tan w/ Red & Black Streaks VFT	1020	SF	Room 120 - 1908	Chrysotile	MISC	No	None	0		
3YR Inspector Comments: 2007 - No change since last inspection											
Condition Not Changed in Fall 2010			SF		Chrysotile	MISC					
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC					
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
92	12"x12" Tan w/ Red & Black Streaks VFT Mastic	1020	SF	Room 120 - 1908	Chrysotile	MISC	No	None	0		
3YR Inspector Comments: 2007 - No change since last inspection											
Condition Not Changed in Fall 2010			SF		Chrysotile	MISC					
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC					
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
93	9"x9" Gray w/ Black & White Streaks VFT	120	SF	Room 120 - 1908	Chrysotile	MISC	No	None	0		
3YR Inspector Comments: 2007 - No change since last inspection											
Condition Not Changed in Fall 2010			SF		Chrysotile	MISC					
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC					
Comments:											
Fall 2011											YES NO
Comment:											

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
94	9"x9" Gray w/ Black & White Streaks VFT Mastic	120	SF	Room 120 - 1908	Chrysotile	MISC	No	None	0		
3YR Inspector Comments: 2007 - No change since last inspection											
Condition Not Changed in Fall 2010			SF		Chrysotile	MISC					
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC					
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
95	9"x9" Dark Green w/ White Streaks VFT	500	SF	Room 126 - 1908	Chrysotile	MISC	No	None	0		
3YR Inspector Comments: 2007 - No change since last inspection											
Condition Not Changed in Fall 2010			SF		Chrysotile	MISC					
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC					
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
96	9"x9" Dark Green w/ White Streaks VFT Mastic	500	SF	Room 126 - 1908	Chrysotile	MISC	No	None	0		
3YR Inspector Comments: 2007 - No change since last inspection											
Condition Not Changed in Fall 2010			SF		Chrysotile	MISC					
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC					
Comments:											
Fall 2011											YES NO
Comment:											

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
97	Tan Spotted Linoleum	400	SF	Third Floor Men's and Women's Teachers Toilet - 1908	Chrysotile	MISC	No	None	0		
3YR Inspector Comments:											
Condition Not Changed in Fall 2010											
Comments:											
Condition Not Changed in Spring 2011											
Comments:											
Fall 2011										YES	NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
98	Tan Spotted Linoleum Mastic	400	SF	Third Floor Men's and Women's Teachers Toilet - 1908	Chrysotile	MISC	No	None	0		
3YR Inspector Comments:											
Condition Not Changed in Fall 2010											
Comments:											
Condition Not Changed in Spring 2011											
Comments:											
Fall 2011										YES	NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
AA	Air Cell Pipe Insulation	14	LF	3rd Floor Janitor's Closet By Room 301- 1915	Chrysotile	TSI	Yes	None	0		
3YR Inspector Comments: 2007 - No change since last inspection											
Condition Not Changed in Fall 2010											
Comments:											
Condition Not Changed in Spring 2011											
Comments:											
Fall 2011										YES	NO
Comment:											

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
BB	MJP E/F/V on Air Cell Pipe Insulation	6	LF	3rd Floor Janitor's Closet By Room 301 - 1915; 1st Floor Girls Toilet Added in 2010	Chrysotile	TSI	Yes	None	0		
3YR Inspector Comments: 2007 - No change since last inspection; 1st Floor Girls Toilet, Across From Locker Room, (5 SF) Added in 2010											
Condition Not Changed in Fall 2010			LF		Chrysotile	TSI					
Comments:											
Condition Not Changed in Spring 2011			LF		Chrysotile	TSI					
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
CC	MJP E/F/V on Fiberglass Pipe Insulation	20	LF	First Floor Girl's Toilet, First Floor Corridor - 1915	Chrysotile	TSI	Yes	None	0		
3YR Inspector Comments: Summer 2009 - 9 fittings removed in Girl's R/R on 1st floor, 1915 bldg to prepare for ADA upgrade, remaining piping for "old" toilets and wet wall behind them were not abated.											
Condition Not Changed in Fall 2010			LF		Chrysotile	TSI					
Comments:											
Condition Not Changed in Spring 2011			LF		Chrysotile	TSI					
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
DD	MJP E/F/V on Mag Block Pipe Insulation	1	LF	Janitor's Closet By Room 301 - 1915	Chrysotile	TSI	Yes	None	0		
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			LF		Chrysotile	TSI					
Comments:											
Condition Not Changed in Spring 2011			LF		Chrysotile	TSI					
Comments:											
Fall 2011											YES NO
Comment:											

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
E	Boiler Gasket	1	SF	Boiler Room - 1923	Chrysotile	TSI	Yes	None	0		
3YR Inspector Comments: 2007 - No change since last inspection											
Condition Not Changed in Fall 2010			SF		Chrysotile	TSI					
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	TSI					
Comments:											
Fall 2011										YES	NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
EE	Mag Block Pipe Insulation	14	LF	Janitor's Closet By Room 301 - 1915	Chrysotile	TSI	Yes	None	0		
3YR Inspector Comments: 2007 - No change since last inspection											
Condition Not Changed in Fall 2010			LF		Chrysotile	TSI					
Comments:											
Condition Not Changed in Spring 2011			LF		Chrysotile	TSI					
Comments:											
Fall 2011										YES	NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
F	Boiler Gasket	1	SF	Boiler Room - 1923	Chrysotile	TSI	Yes	None	0		
3YR Inspector Comments: 2007 - No change since last inspection											
Condition Not Changed in Fall 2010			SF		Chrysotile	TSI					
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	TSI					
Comments:											
Fall 2011										YES	NO
Comment:											

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
HA-1000	2'x4' white ceiling tiles with random fis & holes	20000	SF	Throughout	Assumed	MISC	Yes	None	0		
3YR Inspector Comments: 2008 - material identified during the January 23, 2008 audit visit											
Condition Not Changed in Fall 2010			SF		Assumed	MISC					
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC					
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
HA-1001	2'X4' white plain ceiling tile	960	SF	Teachers' Lunch Room	Assumed	MISC	Yes	None	0		
3YR Inspector Comments: 2008 - material identified during the January 23, 2008 audit visit											
Condition Not Changed in Fall 2010			SF		Assumed	MISC					
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC					
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
HA-1002	1'x1' white ceiling tile rand holes	1500	SF	Students' Lunch Room	Assumed	MISC	Yes	None	0		
3YR Inspector Comments: 2008 - material identified during the January 23, 2008 audit visit											
Condition Not Changed in Fall 2010			SF		Assumed	MISC					
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC					
Comments:											
Fall 2011											YES NO
Comment:											

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
HA-1003	Glue for 1'x1' white ceilingtile with holes	1500	SF	Students' Lunch Room	Assumed	MISC	No	None	0		
3YR Inspector Comments: 2008 - material identified during the January 23, 2008 audit visit											
Condition Not Changed in Fall 2010			SF		Assumed	MISC					
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC					
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
HA-1004	2'x2' white plain ceiling tile	1500	SF	Kitchen	Assumed	MISC	No	None	0		
3YR Inspector Comments: 2008 - material identified during the January 23, 2008 audit visit											
Condition Not Changed in Fall 2010			SF		Assumed	MISC					
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC					
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
HA-1005	1'x1' white CT with large holes	150	SF	Kitchen Manager Office	Assumed	MISC	Yes	None	0		
3YR Inspector Comments: 2008 - material identified during the January 23, 2008 audit visit											
Condition Not Changed in Fall 2010			SF		Assumed	MISC					
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC					
Comments:											
Fall 2011											YES NO
Comment:											

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
HA-1006	Glue for 1'x1' wh CT with large holes	150	SF	Kitchen Manager Office	Assumed	MISC	No	None	0		
3YR Inspector Comments: 2008 - material identified during the January 23, 2008 audit visit											
Condition Not Changed in Fall 2010			SF		Assumed	MISC					
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC					
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
HA-1007	1'x1' wh CT with random fissures	1680	SF	Rm. 301 on ceiling and walls	Assumed	MISC	Yes	None	0		
3YR Inspector Comments: 2008 - material identified during the January 23, 2008 audit visit											
Condition Not Changed in Fall 2010			SF		Assumed	MISC					
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC					
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
HA-1008	Glue for 1'x1' white CT with rand fiss	1680	SF	Room 301	Assumed	MISC	No	None	0		
3YR Inspector Comments: 2008 - material identified during the January 23, 2008 audit visit											
Condition Not Changed in Fall 2010			SF		Assumed	MISC					
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC					
Comments:											
Fall 2011											YES NO
Comment:											

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
HA-1010	12"x12" yellow VFT		SF		Assumed	MISC	No	None	0		
3YR Inspector Comments: 2008 - material identified during the January 23, 2008 audit visit. , installed in 2002											
Condition Not Changed in Fall 2010			SF		Assumed	MISC					
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC					
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
HA-1010m	Adhesive for 12"x12" yellow VFT		SF		Assumed	MISC	No	None	0		
3YR Inspector Comments: 2008 - material identified during the January 23, 2008 audit visit. , installed in 2002											
Condition Not Changed in Fall 2010			SF		Assumed	MISC					
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC					
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
HA-1011	Transite	30	SF	1st floor girl's r/r privacy wall	Chrysotile	MISC	No	None	0		
3YR Inspector Comments: Transite privacy wall in 1st fl. Girl's r/r abated in summer 2009.											
Condition Not Changed in Fall 2010			SF		Chrysotile	MISC					
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC					
Comments:											
Fall 2011											YES NO
Comment:											

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
HH	MJP E/F/V on Fiberglass Pipe Insulation	142	LF	Locker Room, 1st Floor Boy's Toilet, Hot & Cold Deck, & Wood Shop Area - 1923; Rms 219, 315, 319 under Classroom Sinks (12 LF); 2nd Floor Girls washroom (5 LF); 3rd Floor Girls Washroom (5 LF).	Chrysotile	TSI	Yes	None	0		
3YR Inspector Comments: 2007 - No change since last inspection (5 LF); 3rd Floor Girls Washroom (5 LF) were added in 2010.				2008 - Material was not observed on 1/23/08. Wood Shop Area - 1923; Rms 219, 315, 319 under Classroom Sinks (12 LF); 2nd Floor Girls washroom (5 LF); 3rd Floor Girls Washroom (5 LF) were added in 2010.							
Condition Not Changed in Fall 2010			LF		Chrysotile	TSI					
Comments:											
Condition Not Changed in Spring 2011			LF		Chrysotile	TSI					
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
II	Cardboard Pipe Insulation (Paper-Wrap Pipe Ins)	38	LF	Electrical Room Across from Stairway # 4 - 1908	Assumed	TSI	Yes	Loc	38		
3YR Inspector Comments: 2008 - during the 1/23/08 audit visit, inspector observed 38 l.f. of damaged material within Electrical room by stair #4											
Condition Not Changed in Fall 2010			LF		Assumed	TSI					
Comments:											
Condition Not Changed in Spring 2011			LF		Assumed	TSI					
Comments:											
Fall 2011											YES NO
Comment:											

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.


HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category		
JJ	MJP E/F/V on Cardboard Pipe Insulation(P.wrap PI)	10	LF	Electrical Room Across from Stairway # 4 - 1908	Chrysotile	TSI	Yes	None	0				
3YR Inspector Comments: 2007 - No change since last inspection												2008 - during the 1/23/08 audit visit, inspector observed 4 l.f. of damaged material within Electrical room by stair #4	
Condition Not Changed in Fall 2010			LF		Chrysotile	TSI							
Comments:													
Condition Not Changed in Spring 2011			LF		Chrysotile	TSI							
Comments:													
Fall 2011											YES	NO	
Comment:													

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

Please send a copy of this report to Lynn Crivello, 125 S. Clark St., 17th Floor, GSR #125

All LEA Responsibilities, for this school, will be met.



Lynn A. Crivello

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

Oracle Unit: 46281

Page 38

Please send a copy of this report to Lynn Crivello, 125 S. Clark St., 17th Floor, GSR #125

**NOTICE TO PARENTS AND STAFF REGARDING THE
ASBESTOS MANAGEMENT PLAN NOTIFICATION**

School: _____

Date: _____

This is to notify you in accordance with Illinois and Federal Asbestos Regulations, that a copy of the Asbestos Management Plan is available at each school during school hours by appointment. Requests to review the Asbestos Management Plan must be made at least 24 hours in advance.

Also please be advised that CPS conducts asbestos inspections of all schools every three years. The last inspection was completed in 2010. Asbestos surveillances are conducted every six months.

CHECK ONE

- A copy of this notice was sent home in each child's backpack.
- A copy of this notice was printed in the school's newsletter or calendar and sent home with each child.
- Other – Please indicate how this notice was delivered to parents and staff.

**A COPY OF THIS NOTICE MUST BE PLACED IN THE
SCHOOL'S ASBESTOS MANAGEMENT PLAN.**

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

Please send a copy of this report to Lynn Crivello, 125 S. Clark St., 17th Floor, GSR #125