

Chicago Public Schools

6 Month Asbestos Surveillance

Fall 2011

School Kenwood Academy
Address 5015 S. Blackstone

Oracle Unit 46361 **Building ID** 1710
Region 4 **General Services Route** 46

Asbestos Surveyor: _____

Survey Date: _____

E-mail Address: _____

CHECK HERE IF NO CHANGE TO ASBESTOS

A copy of the 2011/2012 notice to parents and staff regarding the asbestos management plan notification was distributed via:

Each child's backpack
 Notice printed in school's newsletter/calendar
 Other _____

Principal Signature _____

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
15	Tectum Tile	18200	SF	Building. C - Rooms 2nd Floor Boy's Gym, 1st Floor Girl's Gym. Building. A - Room 127	Assumed	MISC	No	None	0	SF	
<i>3YR Inspector Comments: No change</i>											
Condition Not Changed in Fall 2010			SF		Assumed	MISC				SF	
<i>Comments:</i>											
Condition Not Changed in Spring 2011			SF		Assumed	MISC				SF	
<i>Comments:</i>											
Fall 2011											YES NO
Comment:											

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

Oracle Unit: 46361

Page 1

Please send a copy of this report to Lynn Crivello, 125 S. Clark St., 17th Floor, GSR #125

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
16	Transite Table Tops	500	SF	Building B - Rooms 315, 301, 303, 325, 310	Assumed	MISC	No	None	0	SF	
3YR Inspector Comments: No change											
Condition Not Changed in Fall 2010			SF		Assumed	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC				SF	
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
17	Transite Counter Tops	500	SF	Building B Rooms 305, 315, 315 Storage, 301, 303, 303 Storage, 325, 325 Office, 306, 310	Assumed	MISC	No	None	0	SF	
3YR Inspector Comments: No change											
Condition Not Changed in Fall 2010			SF		Assumed	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC				SF	
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
38	Lab Table Tops	100	SF	Building B Rooms 305, 315, 301, 303, 303 Storage, 306, 310, 321 & 324	Assumed	MISC	No	None	0	SF	
3YR Inspector Comments: No change											
Condition Not Changed in Fall 2010			SF		Assumed	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC				SF	
Comments:											
Fall 2011											YES NO
Comment:											

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
39	Lab Hood	20	SF	Science Rooms (324, 321)	Assumed	MISC	No	None	0	SF	
3YR Inspector Comments: No change											
Condition Not Changed in Fall 2010			SF		Assumed	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC				SF	
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
40	Plaster Ceiling	90000	SF	Throughout Bathrooms	Assumed	MISC	No	None	0	SF	
3YR Inspector Comments: No change											
Condition Not Changed in Fall 2010			SF		Assumed	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC				SF	
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
43	Transite Ceiling	10	SF	Building D Stairwell 13	Assumed	MISC	No	None	0	SF	
3YR Inspector Comments: No change											
Condition Not Changed in Fall 2010			SF		Assumed	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC				SF	
Comments:											
Fall 2011											YES NO
Comment:											

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
44	Transite Walls, Chalkboard Masonite	800	SF	Building D Lunchroom, Weight Room	Assumed	MISC	No	None	0	SF	
3YR Inspector Comments: No change											
Condition Not Changed in Fall 2010			SF		Assumed	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC				SF	
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
45	Vibration Gasket	100	LF	Throughout Mechanical Rooms, MDF Room 123	Assumed	TSI	No	None	0	LF	
3YR Inspector Comments: No change											
Condition Not Changed in Fall 2010			LF		Assumed	TSI				LF	
Comments:											
Condition Not Changed in Spring 2011			LF		Assumed	TSI				LF	
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
46	Lab Hood	50	SF	Building B - Rooms 310, 305, and 315	Assumed	MISC	No	None	0	SF	
3YR Inspector Comments: No change											
Condition Not Changed in Fall 2010			SF		Assumed	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC				SF	
Comments:											
Fall 2011											YES NO
Comment:											

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
48	12" x 12" Cream w/Brown Specks Floor Tile	1500	SF	Building A Rooms 227 & 234, Building B	Assumed	MISC	No	None	0	SF	
3YR Inspector Comments: No change											
Condition Not Changed in Fall 2010			SF		Assumed	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC				SF	
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
49	12" x 12" Cream w/Brown Specks Floor Tile Mastic	1500	SF	Building A Rooms 227 & 234, Building B	Assumed	MISC	No	None	0	SF	
3YR Inspector Comments: No change											
Condition Not Changed in Fall 2010			SF		Assumed	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC				SF	
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
50	12" x 12" White w/Reddish Specks Floor Tile	132	SF	Building A Room 134	Assumed	MISC	No	None	0	SF	
3YR Inspector Comments: 2004 Comments - No 9" x 9" Floor Tile seen under this tile by the inspector. 2007 Comments - No change											
Condition Not Changed in Fall 2010			SF		Assumed	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC				SF	
Comments:											
Fall 2011											YES NO
Comment:											

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
51	12" x 12" White w/Reddish Specks Floor Tile Mastic	132	SF	Building A Room 134	Assumed	MISC	No	None	0	SF	
3YR Inspector Comments: 2004 Comments - No 9" x 9" Floor Tile associated with this mastic seen under this tile by the inspector. 2007 - No change											
Condition Not Changed in Fall 2010			SF		Assumed	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC				SF	
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
52	Sink Coating	43	SF	Building A Rooms 234 & 225	Assumed	MISC	No	None	0	SF	
3YR Inspector Comments: No change											
Condition Not Changed in Fall 2010			SF		Assumed	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC				SF	
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
53	12" x 12" Gray w/Gray Specks Floor Tile	900	SF	Building B Rooms 121	Assumed	MISC	No	None	0	SF	
3YR Inspector Comments: No change											
Condition Not Changed in Fall 2010			SF		Assumed	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC				SF	
Comments:											
Fall 2011											YES NO
Comment:											

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
54	12" x 12" Gray w/Gray Specks Floor Tile Mastic	900	SF	Building B Rooms 121	Assumed	MISC	No	None	0	SF	
3YR Inspector Comments: No change											
Condition Not Changed in Fall 2010			SF		Assumed	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC				SF	
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
55	Gray Carpet Mastic	500	SF	Building B 2nd Floor Faculty Commons	Assumed	MISC	No	None	0	SF	
3YR Inspector Comments: No change											
Condition Not Changed in Fall 2010			SF		Assumed	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC				SF	
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
56	12x12 Blue Floor Tile	1700	SF	ROOMS 321, 324	Assumed	MISC	No	None	0	SF	
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			SF		Assumed	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC				SF	
Comments:											
Fall 2011											YES NO
Comment:											

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
57	12x12 blue floor tile mastic	1700	SF	rm 321, 324	Assumed	MISC	No	None	0	SF	
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			SF		Assumed	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC				SF	
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
58	12x12 white ft w/ tan mottle	950	SF	rm 128, 128A	Assumed	MISC	No	None	0	SF	
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			SF		Assumed	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC				SF	
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
59	Mastic for 12x12 white floor tile w/ tan mottle	950	SF	rm 128, 128A	Assumed	MISC	No	None	0	SF	
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			SF		Assumed	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC				SF	
Comments:											
Fall 2011											YES NO
Comment:											

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
60	2x4 Ceiling tile w/ divots & dots	2100	SF	rm 128, 128A, 234	Assumed	MISC	No	None	0	SF	
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			SF		Assumed	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC				SF	
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
61	12x12 Brown Mottle floor tile	250	SF	rm 134 H	Assumed	MISC	No	None	0	SF	
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			SF		Assumed	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC				SF	
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
62	Mastic for 12x12 Brown mottle floor tile	250	SF	rm 134 H	Assumed	MISC	No	None	0	SF	
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			SF		Assumed	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC				SF	
Comments:											
Fall 2011											YES NO
Comment:											

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
63	12x12 Cream floor tile w/ brown specks	1200	SF	rm 234	Assumed	MISC	No	None	0	SF	
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			SF		Assumed	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC				SF	
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
64	Mastic for 12x12 Cream floor tile w/ brown specks	1200	SF	rm 234	Assumed	MISC	No	None	0	SF	
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			SF		Assumed	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC				SF	
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
A-1	2' x 4' Acoustical Ceiling Tiles	18400	SF	Throughout Building A - Offices, Hallways, Classrooms, 325 & 325 Office	Chrysotile	MISC	Yes	None	0	SF	
3YR Inspector Comments: 2004 Comment: 100 SF of damage/ discoloration caused by water is located in room 325. 2007 - No damage noted in room 325.											
Condition Not Changed in Fall 2010			SF		Chrysotile	MISC				SF	
Comments:											
Condition Changed in Spring 2011			SF		Chrysotile	MISC				SF	
Comments: Ceiling tiles still being damaged by leaks from boiler room											
Fall 2011											YES NO
Comment:											

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
A-3	Spray-on Fireproofing	10110	SF	Bldg. D- Rm224,223,Lunchroom,Kitchen,Halls,Boys/GirlsToilet,Bldg C-East Mech.Rm,237,238,Bldg.A Fan Rm	Assumed	SURFACE	No	None	0	SF	
3YR Inspector Comments: 2004 Comments - Damage is located in the Building A Fan Room. 2007 Comments - damage located in Building C Mech. Room. Fireproofing on floor. Seven samples collected by CCA in Jan. of 2007 from seven areas throughout the school were analyzed by TEM by Davis Environmental Labs and were determined to be negative for asbestos. Please refer to the letter report dated Jan. 25, 2007 from Peter F. Dennis of CCA to Lynn Crivello of the Chicago Public Schools for additional information regarding the sampling. 2010- Re-sampled by CCA determined NON-ACM											
Condition Not Changed in Fall 2010			SF		Assumed	SURFACE				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	SURFACE				SF	
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
A-7	12" x 12" Black Floor Tile Mastic	2160	SF	Building B - Passage ways 1 & 2	Chrysotile	MISC	No	None	0	SF	
3YR Inspector Comments: No change											
Condition Not Changed in Fall 2010			SF		Chrysotile	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC				SF	
Comments:											
Fall 2011											YES NO
Comment:											

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
A-7.1	12" x 12" Beige Floor Tile Mastic	1900	SF	Building D-District Superintendent's Office & Faculty Service Line	Chrysotile	MISC	No	None	0	SF	
3YR Inspector Comments: No change											
Condition Not Changed in Fall 2010			SF		Chrysotile	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC				SF	
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
A-7.3	12" x 12" Beige w/ Brown Specks Floor Tile Mastic	110	SF	Building D-Engineer's Office	Chrysotile	MISC	Yes	None	0	SF	
3YR Inspector Comments: No change											
Condition Not Changed in Fall 2010			SF		Chrysotile	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC				SF	
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
A-7.4	12" x 12" Tan Floor Tile Mastic	3885	SF	Building A - Halls, and Rooms 232 and 233	Chrysotile	MISC	No	None	0	SF	
3YR Inspector Comments: No change											
Condition Not Changed in Fall 2010			SF		Chrysotile	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC				SF	
Comments:											
Fall 2011											YES NO
Comment:											

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
A-8	9" x 9" Beige Floor Tile Mastic	21000	SF	Buildings D - Hall, A4 Building - Throughout Classrooms, Labs, Offices, Throughout Bldg.B Classrooms	Chrysotile	MISC	No	None	0	SF	

3YR Inspector Comments: 2007 Comments - Approx. 500 SF of missing tile and exposed Mastic is located in the hallways of the 1st floor of Building D. This area is not accessible to the students. This is a mech/storage area.

Condition Not Changed in Fall 2010		SF		Chrysotile	MISC					SF	
Comments:											
Condition Not Changed in Spring 2011		SF		Chrysotile	MISC					SF	
Comments:											

Fall 2011											YES NO
------------------	--	--	--	--	--	--	--	--	--	--	--------

Comment:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
A-8.1	9" x 9" Brown Floor Tile Mastic	21000	SF	Hallways Throughout Facility, Building A - Room 227	Chrysotile	MISC	Yes	None	0	SF	

3YR Inspector Comments: No change

Condition Not Changed in Fall 2010		SF		Chrysotile	MISC					SF	
Comments:											
Condition Changed in Spring 2011		SF		Chrysotile	MISC					SF	
Comments: Floortile in hallways has started to delaminate. Tile is curling and cracking. Areas in buildings A, B, C & D											

Fall 2011											YES NO
------------------	--	--	--	--	--	--	--	--	--	--	--------

Comment:

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
A-9	9" x 9" Beige Floor Tile	21000	SF	Building D-Hall, A4 Building-Throughout Facility Classrooms, Offices, Labs, Throughout Bldg, B Classrooms	Chrysotile	MISC	No	None	0	SF	
3YR Inspector Comments: 2007 Comments - Areas of damage or missing tiles have been repaired. 2004 Comments - Throughout Bldg, B Classrooms there are 80 SF of missing tiles. All water issues due to boiler room on the 4th floor; all ceiling tiles issues are located directly below boiler room. Damages are located in room 323 (8 SF damage/ 20 SF missing), 325 (12 SF damage/ 1 SF missing), and 316 (20 SF damage).											
Condition Not Changed in Fall 2010			SF		Chrysotile	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC				SF	
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
A-9.1	9" x 9" Brown Floor Tile	21000	SF	Hallways Throughout Facility, Building A - Room 227, Room 226	Chrysotile	MISC	No	None	0	SF	
3YR Inspector Comments: 2010 Comments: no damaged or missing tiles were observed. 2007 and 2004 Comments - Room 226 has 22 missing tiles. 5 SF of damaged FT are located on the 2nd and 3rd floor corridors.											
Condition Not Changed in Fall 2010			SF		Chrysotile	MISC				SF	
Comments:											
Condition Changed in Spring 2011			SF		Chrysotile	MISC				SF	
Comments: Floortile has started to delaminate. Loose, curling and cracked tiles in buildings A, B, C & D hallways											
Fall 2011											YES NO
Comment:											

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
A-C	Pipe Insulation	0	LF	Building A - Penthouse	Chrysotile	TSI	Yes	None	0	LF	
3YR Inspector Comments: No change 2010- Not observed. All fittings abated											
Condition Not Changed in Fall 2010			LF		Chrysotile	TSI				LF	
Comments:											
Condition Not Changed in Spring 2011			LF		Chrysotile	TSI				LF	
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
A-E	Pipe Insulation	0	LF	Building A - Pipe chases	Chrysotile	TSI	Yes	None	0	LF	
3YR Inspector Comments: Small areas of distributed damage. No change from 2004. 2010- Abated in 2008.											
Condition Not Changed in Fall 2010			LF		Chrysotile	TSI				LF	
Comments:											
Condition Not Changed in Spring 2011			LF		Chrysotile	TSI				LF	
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
B(A-2)	Tank Insulation	300	SF	Building B - 4th Floor Boiler Room	Chrysotile	TSI	Yes	None	0	LF	
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			SF		Chrysotile	TSI				LF	
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	TSI				LF	
Comments:											
Fall 2011											YES NO
Comment:											

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
B(A-3)	Cementitious Insulation (Joint)	250	SF	Building B - 4th Floor Boiler Room	Chrysotile	TSI	Yes	None	0	LF	
3YR Inspector Comments: No change											
Condition Not Changed in Fall 2010			SF		Chrysotile	TSI				LF	
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	TSI				LF	
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
B-1	2' x 4' Acoustical Ceiling Tile w/Pinholes	2250	SF	RM 234, 315, 325	Chrysotile	MISC	Yes	Dist	208	SF	
3YR Inspector Comments: 2010 Comments: Water damage observed in rooms 234, 315, and 325. not located in Rooms 123, 324, 301, 303 Storage & Main Office (these rooms contain metal tile).					2004 Comments - Damage located in rooms 315 (75 SF) and 311 (30 SF). Tile is listed as throughout, but is 2007 - Damage areas repaired. No new areas of damage.						
Condition Not Changed in Fall 2010			SF		Chrysotile	MISC				SF	
Comments:											
Condition Changed in Spring 2011			SF		Chrysotile	MISC				SF	
Comments: Floor in boiler room 4th floor continues to leak to ceiling tiles causing damage in 3rd floor classrooms											
Fall 2011											YES NO
Comment:											

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
B-D	Pipe Insulation	400	SF	Building B - Boiler Room	Chrysotile	TSI	Yes	None	0	LF	
3YR Inspector Comments: No change											
Condition Not Changed in Fall 2010			SF		Chrysotile	TSI				LF	
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	TSI				LF	
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
C-B	Cemetitious Insulation (Joint)	60	LF	Building C - Roof Drains	Chrysotile	TSI	Yes	None	0	LF	
3YR Inspector Comments: No change 2010- Partially abated in girls gym											
Condition Not Changed in Fall 2010			LF		Chrysotile	TSI				LF	
Comments:											
Condition Not Changed in Spring 2011			LF		Chrysotile	TSI				LF	
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
C-C	Pipe Insulation	700	LF	Building C - Throughout Building and Crawlspace	Chrysotile	TSI	Yes	None	0	LF	
3YR Inspector Comments: No change											
Condition Not Changed in Fall 2010			LF		Chrysotile	TSI				LF	
Comments:											
Condition Not Changed in Spring 2011			LF		Chrysotile	TSI				LF	
Comments:											
Fall 2011											YES NO
Comment:											

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
C-D	Cementitious Insulation on Pipe Joint	200	LF	Throughout Building C	Chrysotile	TSI	Yes	None	0	LF	
3YR Inspector Comments: No change											
Condition Not Changed in Fall 2010			LF		Chrysotile	TSI				LF	
Comments:											
Condition Not Changed in Spring 2011			LF		Chrysotile	TSI				LF	
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
C-E	Tank Insulation	245	SF	Building C - 3rd Floor Mechanical Room	Chrysotile	TSI	Yes	None	0	SF	
3YR Inspector Comments: No change 2010- Fiberglass with hard end-cap insulation											
Condition Not Changed in Fall 2010			SF		Chrysotile	TSI				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	TSI				SF	
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
CK-DC	Joint Insulation	500	LF	Building D - Equipment Room	Chrysotile	TSI	Yes	None	0	LF	
3YR Inspector Comments: No change											
Condition Not Changed in Fall 2010			LF		Chrysotile	TSI				LF	
Comments:											
Condition Not Changed in Spring 2011			LF		Chrysotile	TSI				LF	
Comments:											
Fall 2011											YES NO
Comment:											

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
CK-DE	Aircell Pipe Insulation	100	LF	Building D - Cafeteria Pipe Chase	Chrysotile	TSI	Yes	None	0	LF	
3YR Inspector Comments: 2010 Comments: No damaged observed											
Condition Not Changed in Fall 2010			LF		Chrysotile	TSI				LF	
Comments:											
Condition Not Changed in Spring 2011			LF		Chrysotile	TSI				LF	
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
CK-DF	Lag & Joint Cement	50	LF	Building D - Mechanical Room	Chrysotile	TSI	Yes	None	0	LF	
3YR Inspector Comments: No damage											
Condition Not Changed in Fall 2010			LF		Chrysotile	TSI				LF	
Comments:											
Condition Not Changed in Spring 2011			LF		Chrysotile	TSI				LF	
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
CK-DG	Tank Insulation	300	SF	Building D - Mechanical Room	Chrysotile	TSI	Yes	None	0	SF	
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			SF		Chrysotile	TSI				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	TSI				SF	
Comments:											
Fall 2011											YES NO
Comment:											

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
E-B	Fiberglass Pipe Insulation Hard Elbows	900	LF	Buildings A, B, C, D	Chrysotile	TSI	Yes	None	0	LF	
3YR Inspector Comments: NO change											
Condition Not Changed in Fall 2010			LF		Chrysotile	TSI				LF	
Comments:											
Condition Not Changed in Spring 2011			LF		Chrysotile	TSI				LF	
Comments:											
Fall 2011											YES NO
Comment:											


HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
E-C	Tank Insulation	400	SF	Building D - 1st Floor Mechanical Room	Chrysotile	TSI	Yes	None	0	SF	
3YR Inspector Comments: 2010 Comments: Possible same HA as described as CK-DG											
Condition Not Changed in Fall 2010			SF		Chrysotile	TSI				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	TSI				SF	
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
P	Incinerator Stack Insulation	40	LF	Building D - Mechanical Room	Assumed	TSI	Yes	None	40	LF	
3YR Inspector Comments: No change 2010- Incinerator removed 1995											
Condition Not Changed in Fall 2010			LF		Assumed	TSI				LF	
Comments:											
Condition Not Changed in Spring 2011			LF		Assumed	TSI				LF	
Comments:											
Fall 2011											YES NO
Comment:											

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

All LEA Responsibilities, for this school, will be met.



Lynn A. Crivello

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

**NOTICE TO PARENTS AND STAFF REGARDING THE
ASBESTOS MANAGEMENT PLAN NOTIFICATION**

School: _____

Date: _____

This is to notify you in accordance with Illinois and Federal Asbestos Regulations, that a copy of the Asbestos Management Plan is available at each school during school hours by appointment. Requests to review the Asbestos Management Plan must be made at least 24 hours in advance.

Also please be advised that CPS conducts asbestos inspections of all schools every three years. The last inspection was completed in 2010. Asbestos surveillances are conducted every six months.

CHECK ONE

- A copy of this notice was sent home in each child's backpack.
- A copy of this notice was printed in the school's newsletter or calendar and sent home with each child.
- Other – Please indicate how this notice was delivered to parents and staff.

**A COPY OF THIS NOTICE MUST BE PLACED IN THE
SCHOOL'S ASBESTOS MANAGEMENT PLAN.**

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.