

# Chicago Public Schools

## 6 Month Asbestos Surveillance

Fall 2011

**School** Marshall High School  
**Address** 3250 W. Adams

**Oracle Unit** 47041    **Building ID** 1470  
**Region** 3    **General Services Route** 38

**Asbestos Surveyor:** \_\_\_\_\_

**Survey Date:** \_\_\_\_\_

**E-mail Address:** \_\_\_\_\_

**CHECK HERE IF NO CHANGE TO ASBESTOS**

**A copy of the 2011/2012 notice to parents and staff regarding the asbestos management plan notification was distributed via:**

*Each child's backpack*   
  *Notice printed in school's newsletter/calendar*   
  *Other* \_\_\_\_\_

**Principal Signature** \_\_\_\_\_

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	<b>Change in Assessment Category</b>
10 M	Brown Linoleum Mastic	500	SF	Room 125-1	Assumed	MISC	No	None	0	SF	
<small>3YR Inspector Comments: 2007 COMMENTS=Material possibly covered by carpet, no record of abatement.            2010- Material not observed.</small>											
Condition Not Changed in Fall 2010			SF		Assumed	MISC				SF	
<small>Comments:</small>											
Condition Not Changed in Spring 2011			SF		Assumed	MISC				SF	
<small>Comments:</small>											
<b>Fall 2011</b>											<b>YES      NO</b>
<b>Comment:</b>											

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

Oracle Unit: 47041

Page 1

Please send a copy of this report to Lynn Crivello, 125 S. Clark St., 17th Floor, GSR #125

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
100	Beige Linoleum	750	SF	Room 323	Assumed	MISC	No	None	0	SF	
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			SF		Assumed	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC				SF	
Comments:											
<b>Fall 2011</b>											YES NO
<b>Comment:</b>											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
101	Beige Linoleum Adhesive	750	SF	Room 323	Assumed	MISC	No	None	0	SF	
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			SF		Assumed	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC				SF	
Comments:											
<b>Fall 2011</b>											YES NO
<b>Comment:</b>											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
102	Grey and Tan Terrazzo	41000	SF	Hallway borders, Lunchroom, Stairwells	Assumed	SURFAC E	No	None	0	SF	
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			SF		Assumed	SURFAC E				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	SURFAC E				SF	
Comments:											
<b>Fall 2011</b>											YES NO
<b>Comment:</b>											

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
103	Red 12" x 12" Floor Tile	400	SF	Rm 124	Assumed	MISC	No	None	0	SF	
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			SF		Assumed	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC				SF	
Comments:											
<b>Fall 2011</b>											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
104	Red 12" x 12" Floor Tile Mastic	400	SF	Rm 124	Assumed	MISC	No	None	0	SF	
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			SF		Assumed	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC				SF	
Comments:											
<b>Fall 2011</b>											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
17	Insulation Inside of Vault Door	24	SF	Rooms 125	Assumed	MISC	No	None	0	SF	
3YR Inspector Comments: 2007 COMMENTS=material not reachable, condition not attainable.											
Condition Not Changed in Fall 2010			SF		Assumed	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC				SF	
Comments:											
<b>Fall 2011</b>											YES NO
Comment:											

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
18	Carpet Mastic			Throughout Building	Assumed	MISC	No	None	0	SF	
3YR Inspector Comments: This Homogeneous Area has been separated into new areas by carpet colors. (see subsequent HA's '18 A to 18 K'											
Condition Not Changed in Fall 2010					Assumed	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011					Assumed	MISC				SF	
Comments:											
<b>Fall 2011</b>											YES NO
<b>Comment:</b>											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
18 A	Purple & White Mix Carpet Mastic	2100	SF	Room 130, 229, 225 & 227	Assumed	MISC	No	None	0	SF	
3YR Inspector Comments: 2004=Did not sample to avoid damaging carpet.											
Condition Not Changed in Fall 2010			SF		Assumed	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC				SF	
Comments:											
<b>Fall 2011</b>											YES NO
<b>Comment:</b>											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
18 B	Orange Carpet Mastic	700	SF	Room 228	Assumed	MISC	No	None	0	SF	
3YR Inspector Comments:											
Condition Changed in Fall 2010			SF		Assumed	MISC				SF	
Comments: Carpet has been removed. This room has hardwood floors.											
Condition Not Changed in Spring 2011			SF		Assumed	MISC				SF	
Comments:											
<b>Fall 2011</b>											YES NO
<b>Comment:</b>											

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
18 C	Brown Carpet Mastic	700	SF	Room 237	Assumed	MISC	No	None	0	SF	
3YR Inspector Comments:											
Condition Changed in Fall 2010			SF		Assumed	MISC				SF	
Comments: Carpet is blue with Gold specks.											
Condition Not Changed in Spring 2011			SF		Assumed	MISC				SF	
Comments:											
<b>Fall 2011</b>											YES NO
<b>Comment:</b>											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
18 D	Blue Carpet Mastic	4000	SF	Rooms 123, 129, 132, 136 and 137 and Assistant Principal's Office	Assumed	MISC	No	None	0	SF	
3YR Inspector Comments: 2004=Did not sample to avoid damaging carpet. 2007=Rm 124 had red carpet not blue as stated in 2004 inspection (see HA 18E).											
Condition Changed in Fall 2010			SF		Assumed	MISC				SF	
Comments: No Carpet in these room except 137											
Condition Not Changed in Spring 2011			SF		Assumed	MISC				SF	
Comments:											
<b>Fall 2011</b>											YES NO
<b>Comment:</b>											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
18 F	Lavender Carpet Mastic	700	SF	Room 125	Assumed	MISC	No	None	0	SF	
3YR Inspector Comments:											
Condition Changed in Fall 2010			SF		Assumed	MISC				SF	
Comments: Carpet has been replaced. Carpet is brown											
Condition Not Changed in Spring 2011			SF		Assumed	MISC				SF	
Comments:											
<b>Fall 2011</b>											YES NO
<b>Comment:</b>											

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
18 G	Black and Green Carpet Mastic	700	SF	Principal's Office	Assumed	MISC	No	None	0	SF	
3YR Inspector Comments:											
Condition Changed in Fall 2010			SF		Assumed	MISC				SF	
Comments: Carpet has been replaced											
Condition Not Changed in Spring 2011			SF		Assumed	MISC				SF	
Comments:											
<b>Fall 2011</b>											YES NO
<b>Comment:</b>											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
18 H	Blue Patterned Carpet Mastic	200	SF	Room 126	Assumed	MISC	No	None	0	SF	
3YR Inspector Comments:											
Condition Changed in Fall 2010			SF		Assumed	MISC				SF	
Comments: Carpet has been removed. Tile floor											
Condition Not Changed in Spring 2011			SF		Assumed	MISC				SF	
Comments:											
<b>Fall 2011</b>											YES NO
<b>Comment:</b>											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
18 I	Blue Mix Carpet Mastic	1000	SF	Conference Room	Assumed	MISC	No	None	0	SF	
3YR Inspector Comments:											
Condition Changed in Fall 2010			SF		Assumed	MISC				SF	
Comments: Carpet has been replaced											
Condition Not Changed in Spring 2011			SF		Assumed	MISC				SF	
Comments:											
<b>Fall 2011</b>											YES NO
<b>Comment:</b>											

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
18 J	Gray Carpet Mastic	700	SF	Room 136	Assumed	MISC	No	None	0	SF	
3YR Inspector Comments: 2004=Did not sample to avoid damaging carpet.											
Condition Changed in Fall 2010			SF		Assumed	MISC				SF	
Comments: Carpet removed. This room has hardwood floors.											
Condition Not Changed in Spring 2011			SF		Assumed	MISC				SF	
Comments:											
<b>Fall 2011</b>											YES NO
<b>Comment:</b>											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
18 K	Brown Mix Carpet Mastic	100	SF	Infant Toddler Center	Assumed	MISC	No	None	0	SF	
3YR Inspector Comments: 2004=Did not sample to avoid damaging carpet.											
Condition Changed in Fall 2010			SF		Assumed	MISC				SF	
Comments: All carpet has been replaced											
Condition Not Changed in Spring 2011			SF		Assumed	MISC				SF	
Comments:											
<b>Fall 2011</b>											YES NO
<b>Comment:</b>											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
19	Black Science Lab Tables	550	SF	Rooms 212, 214 & 343	Chrysotile	MISC	No	None	0	SF	
3YR Inspector Comments:											
Condition Changed in Fall 2010			SF		Chrysotile	MISC				SF	
Comments: Tables have been replaced.											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC				SF	
Comments:											
<b>Fall 2011</b>											YES NO
<b>Comment:</b>											

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
2	12"x12" Dark Brown Floor Tile w/White & Blk Strks	4200	SF	Rooms 210, 325, 344, 346, 347	Chrysotile	MISC	No	None	0	SF	
3YR Inspector Comments: 2001 Comments - This floor tile was sampled again in 2000, and was found to contain asbestos. 2004 Comments - Rooms 147 & 151 were abated 1-02, Room 323 now has linoleum covering the floor tile. Damage to floor tile is distributed throughout the rooms. 2007 Comments=Material not in Rm 147 & 151, see new HA 93, 94. Room 346 not found. 100 SF damage in Room 341, 260 SF serious damage in Rm 214(added to salient list)											
Condition Changed in Fall 2010			SF		Chrysotile	MISC				SF	
Comments: 347, 210, 325, remains. 214, 341 344 and 346 have been replaced											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC				SF	
Comments:											
<b>Fall 2011</b>											YES NO
<b>Comment:</b>											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
20	Gray Boiler Rope Gaskets	30	LF	Boiler Interiors	Chrysotile	TSI	No	None	0	LF	
3YR Inspector Comments: Gaskets are located inside the boiler. 2007 comments=material could not be assessed.											
Condition Not Changed in Fall 2010			LF		Chrysotile	TSI				LF	
Comments:											
Condition Not Changed in Spring 2011			LF		Chrysotile	TSI				LF	
Comments:											
<b>Fall 2011</b>											YES NO
<b>Comment:</b>											

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
21	Roofing Material - Not AHERA			Roof	Assumed						
3YR Inspector Comments: Material not observed, not AHERA											
Condition Changed in Fall 2010					Assumed						
Comments: Roof has been replaced											
Condition Not Changed in Spring 2011					Assumed						
Comments:											
<b>Fall 2011</b>											YES NO
<b>Comment:</b>											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
23	9" x 9" Green Floor Tile w/ White Specks Mastic	1100	SF	Room 127 Office Closet and Possibly Under the Carpet in Room 125 & Rm 125 closet.	Chrysotile	MISC	No	None	0	SF	
3YR Inspector Comments: Room 127 has carpeting laid over these floor tiles. 2007 comment=additional tile found in Rm 125 closet											
Condition Not Changed in Fall 2010			SF		Chrysotile	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC				SF	
Comments:											
<b>Fall 2011</b>											YES NO
<b>Comment:</b>											

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
24	Fire Door Lining		SF	Door #9	Chrysotile & Amosite	TSI	No	None	0	SF	
3YR Inspector Comments: Insulation is located inside the doors. 2007 comments=material inaccessible, could not be assessed. 2010- Material inaccessible.											
Condition Changed in Fall 2010			SF		Chrysotile & Amosite	TSI				SF	
Comments: Doors have been replaced											
Condition Not Changed in Spring 2011			SF		Chrysotile & Amosite	TSI				SF	
Comments:											
<b>Fall 2011</b>											YES NO
<b>Comment:</b>											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
25	9"x9" Tan Floor Tile w/ Brown & Beige Strks Mastic	800	SF	126 and 330 (Teacher's Lounge)	Chrysotile	MISC	No	None	0	SF	
3YR Inspector Comments: Material not observed in Rm 126, possibly under carpet. Material abated from Rm 330 (Teacher's Lounge) 2010- Material not observed.											
Condition Not Changed in Fall 2010			SF		Chrysotile	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC				SF	
Comments:											
<b>Fall 2011</b>											YES NO
<b>Comment:</b>											

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
26	9" x 9" Light Green Floor Tile Mastic	1100	SF	Rooms 127, Office Closet & Possibly Under the Carpet in 125 & Rm 125 closet	Assumed	MISC	No	None	0	SF	
3YR Inspector Comments: Room 127 has carpeting laid over these floor tiles. 2007 comment=additional tile found in Rm 125 closet											
Condition Not Changed in Fall 2010			SF		Assumed	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC				SF	
Comments:											
<b>Fall 2011</b>											<b>YES NO</b>
<b>Comment:</b>											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
2M	12"x12" Dk Brn Floor Tile w/ Wh & Blk Strks Mastic	4200	SF	Rooms 210, 325, 344, 346, 347	Chrysotile	MISC	No	None	0	SF	
3YR Inspector Comments: 2001 Comments - Room 344 has 100 SF of Delaminated/Broken Tiles. 2004 Comments - Rooms 147 & 151 were abated 1-02. Room 323 has beige linoleum. Room 346 not found. 100 SF damage in Room 341, 260 SF serious damage in Rm 214(added to salient list)											
Condition Changed in Fall 2010			SF		Chrysotile	MISC				SF	
Comments: 347, 210, 325 remain the same. 214, 341 344, 346 have been replaced											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC				SF	
Comments:											
<b>Fall 2011</b>											<b>YES NO</b>
<b>Comment:</b>											

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
31	Aircell Pipe Insulation	24	LF	Possibly in inaccessible areas of the building. See comments	Chrysotile	TSI	Yes	None	0	LF	
3YR Inspector Comments: 2001 Comments - Between November of 1991 and September 4, 1992 all accessible insulation was removed from this facility. This insulation may still remain in inaccessible areas such as pipe chases and between walls and floors. 2004 Comments - Room 216 has 1 LF of damage. 2007 COMMENTS=material not found (ABATEMENT date of 1/31/05) 2010- Material observed in vestibule of Exit 10											
Condition Not Changed in Fall 2010			LF		Chrysotile	TSI				LF	
Comments:											
Condition Not Changed in Spring 2011			LF		Chrysotile	TSI				LF	
Comments:											
<b>Fall 2011</b>											<b>YES NO</b>
<b>Comment:</b>											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
32	Hard Joint Compound on Aircell Pipe Insulation	4	LF	Possibly in Inaccessible Areas of the Building	Amosite & Chrysotile	TSI	Yes	None	0	LF	
3YR Inspector Comments: Between November of 1991 and September 4, 1992 all accessible insulation was removed from this facility. This insulation may still remain in inaccessible areas such as pipe chases and between walls and floors. 2007 COMMENTS=material was not visible 2010- Material not visible.											
Condition Not Changed in Fall 2010			LF		Amosite & Chrysotile	TSI				LF	
Comments:											
Condition Not Changed in Spring 2011			LF		Amosite & Chrysotile	TSI				LF	
Comments:											
<b>Fall 2011</b>											<b>YES NO</b>
<b>Comment:</b>											

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
33	Paperwrap Pipe Insulation		LF	Possibly in inaccessible areas of the building	Chrysotile	TSI	Yes	None	0	LF	
3YR Inspector Comments: Between November of 1991 and September 4, 1992 all accessible insulation was removed from this facility. This insulation may still remain in inaccessible areas such as pipe chases and between walls and floors. 2007 COMMENTS=material was not visible 2010- Material not visible.											
Condition Not Changed in Fall 2010			LF		Chrysotile	TSI					LF
Comments:											
Condition Not Changed in Spring 2011			LF		Chrysotile	TSI					LF
Comments:											
<b>Fall 2011</b>											YES NO
<b>Comment:</b>											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
34	Hard Joint Compound on Paperwrap Pipe Insulation			Throughout Basement	Chrysotile	TSI	Yes	None	0	LF	
3YR Inspector Comments: Between November of 1991 and September 4, 1992 all accessible insulation was removed from this facility. This insulation may still remain in inaccessible areas such as pipe chases and between walls and floors. 2007 COMMENTS=material was not visible 2010- Material observed throughout Boiler Room and Basement.											
Condition Not Changed in Fall 2010					Chrysotile	TSI					LF
Comments:											
Condition Not Changed in Spring 2011					Chrysotile	TSI					LF
Comments:											
<b>Fall 2011</b>											YES NO
<b>Comment:</b>											

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
35	Mag Block Pipe Insulation			Engine Room, Air Tunnel 3 & 8	Chrysotile	TSI	Yes				
3YR Inspector Comments: Between November of 1991 and September 4, 1992 all accessible insulation was removed from this facility. This insulation may still remain in inaccessible areas such as pipe chases and between walls and floors. 2007 COMMENTS=material was not visible 2010- Material not observed.											
Condition Not Changed in Fall 2010					Chrysotile	TSI					
Comments:											
Condition Not Changed in Spring 2011					Chrysotile	TSI					
Comments:											
<b>Fall 2011</b>											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
36	Mag Block Pipe Joint Insulation		LF	Engine Room, Air Tunnel 3 & 8	Chrysotile	TSI	Yes				
3YR Inspector Comments: Between November of 1991 and September 4, 1992 all accessible insulation was removed from this facility. This insulation may still remain in inaccessible areas such as pipe chases and between walls and floors. 2007 COMMENTS=material was not visible 2010- Material not observed.											
Condition Not Changed in Fall 2010			LF		Chrysotile	TSI					
Comments:											
Condition Not Changed in Spring 2011			LF		Chrysotile	TSI					
Comments:											
<b>Fall 2011</b>											YES NO
Comment:											

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
37	Hard Joint Compound on Fiberglass Pipe Insulation			Engine Room, Air Tunnels 3 & 8	Amosite & Chrysotile	TSI	Yes				
3YR Inspector Comments: Between November of 1991 and September 4, 1992 all accessible insulation was removed from this facility. This insulation may still remain in inaccessible areas such as pipe chases and between walls and floors. 2007 COMMENTS=material was not visible. (SEE ABATEMENT dates for Rooms 244, 248, 344, 348) 2010- Material not observed.											
Condition Not Changed in Fall 2010					Amosite & Chrysotile	TSI					
Comments:											
Condition Not Changed in Spring 2011					Amosite & Chrysotile	TSI					
Comments:											
<b>Fall 2011</b>											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
41	Gray Transite Counter Tops - ABATED		SF	Rooms 244, 246, 248, 344, 346, and 348	Chrysotile	MISC	No				
3YR Inspector Comments: Material abated 9/2006. 2010- Material not observed.											
Condition Not Changed in Fall 2010			SF		Chrysotile	MISC					
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC					
Comments:											
<b>Fall 2011</b>											YES NO
Comment:											

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
42	Mag Type Boiler Gasket	50	LF	Boiler Room	Chrysotile	TSI	Yes	None	0	LF	
3YR Inspector Comments: 2007 COMMENTS=material inaccessible, condition not assessable. 2010- Material not observed.											
Condition Not Changed in Fall 2010			LF		Chrysotile	TSI				LF	
Comments:											
Condition Not Changed in Spring 2011			LF		Chrysotile	TSI				LF	
Comments:											
<b>Fall 2011</b>											<b>YES      NO</b>
<b>Comment:</b>											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
43	Leather Like Boiler Gaskets	50	LF	Boiler Room	Chrysotile	TSI	No	None	0	LF	
3YR Inspector Comments: The gaskets are located inside the boiler. 2007 COMMENTS=material inaccessible, condition not assessable. 2010- Material not observed.											
Condition Not Changed in Fall 2010			LF		Chrysotile	TSI				LF	
Comments:											
Condition Not Changed in Spring 2011			LF		Chrysotile	TSI				LF	
Comments:											
<b>Fall 2011</b>											<b>YES      NO</b>
<b>Comment:</b>											

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
47	Aircell Duct Insulation	1200	SF	Crawlspace 3	Chrysotile	TSI		None	0	SF	
3YR Inspector Comments: All accessible insulation was abated in 1991, however, some material may exist in inaccessible areas such as above hard ceilings, in sealed pipe chases, etc. 2007 COMMENTS=material not visible 2010- Material observed in crawlspace near swimming pool.											
Condition Not Changed in Fall 2010			SF		Chrysotile	TSI				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	TSI				SF	
Comments:											
<b>Fall 2011</b>											YES NO
<b>Comment:</b>											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
4M	12" x 12" Black Floor Tile w/ Brown Streaks Mastic	750	SF	Rooms 132, 134, 143,145, 230 (Women's Washroom), 244, 246, 248, 254, and 310, Men's 3rd Flr RR	Chrysotile	MISC	No	None	0	SF	
3YR Inspector Comments: 2001 Comments - Room 244 has 34 Broken Floor Tile. 2004 Comments - Room 147 was abated 1-02. 2007 comments=only Rm 248 has this tile. Rm 132, 134 abatement date unknown, see HA 87, 88. Rm143, 145, 147 & 310: abatement date unknown.											
Condition Changed in Fall 2010			SF		Chrysotile	MISC				SF	
Comments: Tile has been replaced											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC				SF	
Comments:											
<b>Fall 2011</b>											YES NO
<b>Comment:</b>											

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
5	9" x 9" Tan Floor Tile w/ Brown & Beige Streaks	800	SF	Rooms 126	Chrysotile	MISC	No	None	0	SF	
3YR Inspector Comments: Tile possibly under carpet in Room 126. no record of abatement. Conditon was not assessed. 2010- Material not observed.											
Condition Changed in Fall 2010			SF		Chrysotile	MISC				SF	
Comments: Tile has been replaced											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC				SF	
Comments:											
<b>Fall 2011</b>											YES NO
<b>Comment:</b>											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
50	2' x 5' Black Transite Table Tops	5000	SF	Rooms 244, 246, 248, 344, 346, 348, 321, 325, and 327	Chrysotile	MISC	No	None	0	SF	
3YR Inspector Comments: Rm 346 not found. Newer table tops.											
Condition Not Changed in Fall 2010			SF		Chrysotile	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC				SF	
Comments:											
<b>Fall 2011</b>											YES NO
<b>Comment:</b>											

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
51	Gray Transite Table Tops	500	SF	Room 214	Chrysotile	MISC	No				
3YR Inspector Comments: Material not found in Rm 214, but HA 19 (black science lab tables) exist in this room. Possible that material was abated in 09/06 with all other science lab remodeling. 2010- Material not observed.											
Condition Changed in Fall 2010			SF		Chrysotile	MISC					
Comments: Tables have been removed											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC					
Comments:											
<b>Fall 2011</b>											YES NO
<b>Comment:</b>											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
58	Aircell Pipe Insulation	120	LF	Boiler Room, Gym 12, Exit 3B	Chrysotile	TSI	Yes	Dist	10	LF	
3YR Inspector Comments: Between November of 1991 and September 4, 1992 all accessible insulation was removed from this facility. This insulation may still remain in inaccessible areas such as pipe chases and between walls and floors. 2007 COMMENTS=material was not found, previous comment holds true. 2010- Material found throughout Boiler Room and Basement. Damaged material in Boiler Room.											
Condition Not Changed in Fall 2010			LF		Chrysotile	TSI				LF	
Comments:											
Condition Not Changed in Spring 2011			LF		Chrysotile	TSI				LF	
Comments:											
<b>Fall 2011</b>											YES NO
<b>Comment:</b>											

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
59	Hard Joint Compound on Aircell Pipe Insulation	25	LF	Boiler Room, Gym 12, Exit 3B	Chrysotile	TSI	Yes	None	0	LF	
3YR Inspector Comments: Between November of 1991 and September 4, 1992 all accessible insulation was removed from this facility. This insulation may still remain in inaccessible areas such as pipe chases and between walls and floors. 2007 COMMENTS=material was not found, previous comment holds true. 2010- Material observed throughout Boiler Room and Basement.											
Condition Not Changed in Fall 2010			LF		Chrysotile	TSI				LF	
Comments:											
Condition Not Changed in Spring 2011			LF		Chrysotile	TSI				LF	
Comments:											
<b>Fall 2011</b>											<b>YES NO</b>
<b>Comment:</b>											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
60	Paperwrap Pipe Insulation	70	LF	Boiler Room	Chrysotile	TSI	Yes	Dist	20	LF	
3YR Inspector Comments: All accessible insulation was abated in 1991, however, some material may exist in inaccessible areas such as above hard ceilings, in sealed pipe chases, etc. 2007 COMMENTS=material was not found, previous comment holds true. 2010- Material observed in Boiler Room.											
Condition Not Changed in Fall 2010			LF		Chrysotile	TSI				LF	
Comments:											
Condition Not Changed in Spring 2011			LF		Chrysotile	TSI				LF	
Comments:											
<b>Fall 2011</b>											<b>YES NO</b>
<b>Comment:</b>											

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
61	Hard Joint Compound on Paperwrap Pipe Insulation	5	LF	Boiler Room	Chrysotile	TSI	Yes	None	0	LF	
3YR Inspector Comments: All accessible insulation was abated in 1991, however, some material may exist in inaccessible areas such as above hard ceilings, in sealed pipe chases, etc. 2007 COMMENTS=material was not found, previous comment holds true. 2010- Material observed in the Boiler Room.											
Condition Not Changed in Fall 2010			LF		Chrysotile	TSI				LF	
Comments:											
Condition Not Changed in Spring 2011			LF		Chrysotile	TSI				LF	
Comments:											
<b>Fall 2011</b>											<b>YES NO</b>
<b>Comment:</b>											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
62	Mag Block Pipe Insulation	10	LF	Boiler Room, Gym 12, Auditorium	Chrysotile	TSI	Yes	Loc	1	LF	
3YR Inspector Comments: Between November of 1991 and September 4, 1992 all accessible insulation was removed from this facility. This insulation may still remain in inaccessible areas such as pipe chases and between walls and floors. 2007 COMMENTS=material was not found, previous comment holds true. 2010- Material found in Basement area. Damage found at the entrance to Basement tunnel.											
Condition Not Changed in Fall 2010			LF		Chrysotile	TSI				LF	
Comments:											
Condition Not Changed in Spring 2011			LF		Chrysotile	TSI				LF	
Comments:											
<b>Fall 2011</b>											<b>YES NO</b>
<b>Comment:</b>											

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
63	Mag Block Joint Insulation	2	SF	Boiler Room, Gym 12, Auditorium	Chrysotile	TSI	Yes	None	0	LF	
3YR Inspector Comments: Between November of 1991 and September 4, 1992 all accessible insulation was removed from this facility. This insulation may still remain in inaccessible areas such as pipe chases and between walls and floors. 2007 COMMENTS=material was not found, previous comment holds true.											
2010- Material found in Basement areas.											
Condition Not Changed in Fall 2010			SF		Chrysotile	TSI					LF
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	TSI					LF
Comments:											
<b>Fall 2011</b>											
<b>Comment:</b>											<b>YES</b> <b>NO</b>

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
64	Hard Joint Compound on Fiberglass Pipe Insulation	15	LF	Boiler Room and throughout basement	Chrysotile	TSI	Yes	Loc	2	LF	
3YR Inspector Comments: All accessible insulation was abated in 1992, however, some material may exist in inaccessible areas such as above hard ceilings, in sealed pipe chases, etc. 2007 COMMENTS=joints on fiberglass pipe insulation were not visibly damaged											
2010- Material observed in the Boiler Room and throughout basement. Damaged material observed in Boiler Room connected to storage tank.											
Condition Not Changed in Fall 2010			LF		Chrysotile	TSI					LF
Comments:											
Condition Not Changed in Spring 2011			LF		Chrysotile	TSI					LF
Comments:											
<b>Fall 2011</b>											
<b>Comment:</b>											<b>YES</b> <b>NO</b>

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
65	12" x12" Olive Floor Tile w/Brn & Wh Specks Mastic	500	SF	Room 130	Assumed	MISC	No	None	0	SF	
3YR Inspector Comments: These tiles are no longer in this room.											
Condition Not Changed in Fall 2010			SF		Assumed	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC				SF	
Comments:											
<b>Fall 2011</b>											<b>YES</b> <b>NO</b>
<b>Comment:</b>											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
78	12" x 12" Brown Floor Tile w/ White Streaks	50	SF	Room 337 Storage	Chrysotile	MISC	No	None	0	SF	
3YR Inspector Comments: 2007 COMMENTS=Material not found. No record of abatement. Wood flooring exist 2010- Material not observed.											
Condition Not Changed in Fall 2010			SF		Chrysotile	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC				SF	
Comments:											
<b>Fall 2011</b>											<b>YES</b> <b>NO</b>
<b>Comment:</b>											

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
79	12" x 12" Brown Floor Tile w/ White Streaks Mastic	50	SF	Room 337 Storage	Chrysotile	MISC	No	None	0	SF	
3YR Inspector Comments: 2007 COMMENTS=Material not found. No record of abatement. Wood flooring exist 2010- Material not observed.											
Condition Not Changed in Fall 2010			SF		Chrysotile	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC				SF	
Comments:											
<b>Fall 2011</b>											YES NO
<b>Comment:</b>											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
7M	12"x12" Gray Floor Tile w/ Brn & Wh Streaks Mastic	700	SF	Room 235	Assumed	MISC	No	None	0	SF	
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			SF		Assumed	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC				SF	
Comments:											
<b>Fall 2011</b>											YES NO
<b>Comment:</b>											

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
8	12"x12" Lt Brn Floor Tile w/Red & Wh Strks Mastic	1200	SF	Corridors, Rooms 109, 220 and 320	Assumed	MISC	No	None	0	SF	
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			SF		Assumed	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC				SF	
Comments:											
<b>Fall 2011</b>											YES NO
<b>Comment:</b>											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
80	9" x 9" Beige Floor Tile		SF	Room 246	Chrysotile	MISC	No	None	0	SF	
3YR Inspector Comments: Covered by 12" x 12" Floor Tile (see HA #4/4M). 2007 comments=New flooring is new HA 'A' & 'A-1'.											
2010- Material not observed.											
Condition Changed in Fall 2010			SF		Chrysotile	MISC				SF	
Comments: Tile has been removed											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC				SF	
Comments:											
<b>Fall 2011</b>											YES NO
<b>Comment:</b>											

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
81	9" x 9" Beige Floor Tile Mastic	0	SF	Room 246	Chrysotile	MISC	No	None	0	SF	
3YR Inspector Comments: Covered by 12" x 12" Floor Tile (see HA #4/4M). 2010- Material not observed.											
2007 comments=New flooring is new HA 'A' & 'A-1'.											
Condition Changed in Fall 2010			SF		Chrysotile	MISC				SF	
Comments: Tile has been replaced											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC				SF	
Comments:											
<b>Fall 2011</b>											YES NO
<b>Comment:</b>											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
82	Vault Door Liner	24	SF	Rooms 125	Assumed	TSI	No	None	0	SF	
3YR Inspector Comments: Did not sample to avoid damaging door. 2007 comments=material abated, only in Room 125 2010- Material not observed.											
Condition Not Changed in Fall 2010			SF		Assumed	TSI				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	TSI				SF	
Comments:											
<b>Fall 2011</b>											YES NO
<b>Comment:</b>											

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
83	12" x 12" Gray Floor Tile w/ Brown Specks	700	SF	Room 125	Assumed	MISC	No	None	0	SF	
3YR Inspector Comments: Did not sample to avoid damaging tile.											
Condition Changed in Fall 2010			SF		Assumed	MISC				SF	
Comments: Tile has been replaced											
Condition Not Changed in Spring 2011			SF		Assumed	MISC				SF	
Comments:											
<b>Fall 2011</b>											YES NO
<b>Comment:</b>											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
84	12" x 12" Gray Floor Tile w/Brown Specks Mastic	700	SF	Room 125	Assumed	MISC	No	None	0	SF	
3YR Inspector Comments: Did not sample to avoid damaging tile.											
Condition Changed in Fall 2010			SF		Assumed	MISC				SF	
Comments: Tile has been replaced											
Condition Not Changed in Spring 2011			SF		Assumed	MISC				SF	
Comments:											
<b>Fall 2011</b>											YES NO
<b>Comment:</b>											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
85	12" x 12" Beige Mix Floor Tile	150	SF	Room 130	Assumed	MISC	No	None	0	SF	
3YR Inspector Comments: Did not sample to avoid damaging tile.											
Condition Not Changed in Fall 2010			SF		Assumed	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC				SF	
Comments:											
<b>Fall 2011</b>											YES NO
<b>Comment:</b>											

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
86	12" x 12" Beige Mix Floor Tile Mastic	150	SF	Room 130	Assumed	MISC	No	None	0	SF	
3YR Inspector Comments: Did not sample to avoid damaging tile.											
Condition Not Changed in Fall 2010			SF		Assumed	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC				SF	
Comments:											
<b>Fall 2011</b>											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
87	12" x 12" White Floor Tile w/ Gray Streaks	1364	SF	Room 132 & 134	Assumed	MISC	No	None	0	SF	
3YR Inspector Comments: Did not sample to avoid damaging tile.											
Condition Not Changed in Fall 2010			SF		Assumed	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC				SF	
Comments:											
<b>Fall 2011</b>											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
88	12" x 12" White Floor Tile w/ Gray Streaks Mastic	1364	SF	Room 132 & 134	Assumed	MISC	No	None	0	SF	
3YR Inspector Comments: Did not sample to avoid damaging tile.											
Condition Not Changed in Fall 2010			SF		Assumed	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC				SF	
Comments:											
<b>Fall 2011</b>											YES NO
Comment:											

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
89	12" x 12" Gray Mix Floor Tile	1500	SF	Room 143, 145	Assumed	MISC	No	None	0	SF	
3YR Inspector Comments: Did not sample to avoid damaging tile.											
Condition Not Changed in Fall 2010			SF		Assumed	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC				SF	
Comments:											
<b>Fall 2011</b>											YES NO
<b>Comment:</b>											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
9 M	Orange Linoleum Mastic	750	SF	Room 101	Assumed	MISC	No	None	0	SF	
3YR Inspector Comments: Room 101 not found. 2007 COMMENTS=room 101 not found. 2010- Room not found.											
Condition Not Changed in Fall 2010			SF		Assumed	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC				SF	
Comments:											
<b>Fall 2011</b>											YES NO
<b>Comment:</b>											

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
90	12" x 12" Gray Mix Floor Tile Mastic	1500	SF	Room 143, 145	Assumed	MISC	No	None	0	SF	
3YR Inspector Comments: Did not sample to avoid damaging tile.											
Condition Not Changed in Fall 2010			SF		Assumed	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC				SF	
Comments:											
<b>Fall 2011</b>											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
91	12" x 12" White Floor Tile w/Gray Streaks	1500	SF	Infant/Toddler Center	Assumed	MISC	No	None	0	SF	
3YR Inspector Comments: Did not sample to avoid damaging tile.											
Condition Not Changed in Fall 2010			SF		Assumed	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC				SF	
Comments:											
<b>Fall 2011</b>											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
92	12" x 12" White Floor Tile w/ Gray Streaks Mastic	1500	SF	Infant/Toddler Center	Assumed	MISC	No	None	0	SF	
3YR Inspector Comments: Did not sample to avoid damaging tile.											
Condition Not Changed in Fall 2010			SF		Assumed	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC				SF	
Comments:											
<b>Fall 2011</b>											YES NO
Comment:											

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
93	12" x 12" Pink/Purple Speckled Floor Tile	1500	SF	Classrooms 147 & 151	Assumed	MISC	No	None	0	SF	
3YR Inspector Comments: 2010- Material not observed in 147. Flooring now linoleum											
Condition Not Changed in Fall 2010			SF		Assumed	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC				SF	
Comments:											
<b>Fall 2011</b>											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
94	12" x 12" Pink/Purple Speckled Floor Tile Mastic	1500	SF	Classrooms 147 151	Assumed	MISC	No	None	0	SF	
3YR Inspector Comments: 2010- Material not observed in 147. Flooring is linoleum.											
Condition Not Changed in Fall 2010			SF		Assumed	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC				SF	
Comments:											
<b>Fall 2011</b>											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
95	2' x 4' White Ceiling Tile	1500	SF	Classrooms 147 & 151	Assumed	MISC	Yes	None	0	SF	
3YR Inspector Comments:											
Condition Changed in Fall 2010			SF		Assumed	MISC				SF	
Comments: Replaced											
Condition Not Changed in Spring 2011			SF		Assumed	MISC				SF	
Comments:											
<b>Fall 2011</b>											YES NO
Comment:											

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
96	4" Brown Vinyl Baseboard	150	SF	Classrooms 147 & 151	Assumed	MISC	No	None	0	SF	
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			SF		Assumed	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC				SF	
Comments:											
<b>Fall 2011</b>											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
97	4" Brown Vinyl Baseboard Adhesive	150	SF	Classrooms 147 & 151	Assumed	MISC	No	None	0	SF	
3YR Inspector Comments:											
Condition Changed in Fall 2010			SF		Assumed	MISC				SF	
Comments: Replaced											
Condition Not Changed in Spring 2011			SF		Assumed	MISC				SF	
Comments:											
<b>Fall 2011</b>											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
98	Lavender Stage Curtain	500	SF	Auditorium	Assumed	MISC	No	None	0	SF	
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			SF		Assumed	MISC				SF	
Comments:											
Condition Changed in Spring 2011			SF		Assumed	MISC				SF	
Comments: All stage curtains have been replaced											
<b>Fall 2011</b>											YES NO
Comment:											

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
99	Orange Carpet Adhesive	1500	SF	Auditorium and Room 228	Assumed	MISC	No	None	0	SF	
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			SF		Assumed	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC				SF	
Comments:											
<b>Fall 2011</b>											YES NO
<b>Comment:</b>											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
A	BLUE LINOLEUM FLOORING	4200	SF	ROOMS 327, 344, 348, 314, 246, 244	Assumed	MISC	No	None	0	SF	
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			SF		Assumed	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC				SF	
Comments:											
<b>Fall 2011</b>											YES NO
<b>Comment:</b>											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
A-1	BLUE LINOLEUM FLOORING-MASTIC	4200	SF	ROOMS 327, 344, 348, 314, 246, 244	Assumed	MISC	No	None	0	SF	
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			SF		Assumed	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC				SF	
Comments:											
<b>Fall 2011</b>											YES NO
<b>Comment:</b>											

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
B	12x12 VFT BLUE	1150	SF	ROOMS 354, 230(TEACHERS LOUNGE) & 330(TEACHER'S LOUNGE)	Assumed	MISC	No	None	0	SF	
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			SF		Assumed	MISC					SF
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC					SF
Comments:											
<b>Fall 2011</b>											YES NO
<b>Comment:</b>											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
B-1	12x12 VFT BLUE-MASTIC	1150	SF	ROOMS 354, 230(TEACHERS LOUNGE) & 330(TEACHER'S LOUNGE)	Assumed	MISC	No	None	0	SF	
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			SF		Assumed	MISC					SF
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC					SF
Comments:											
<b>Fall 2011</b>											YES NO
<b>Comment:</b>											

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

*All LEA Responsibilities, for this school, will be met.*

  
\_\_\_\_\_

*Lynn A. Crivello*

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

Oracle Unit: 47041

Page 35

**Please send a copy of this report to Lynn Crivello, 125 S. Clark St., 17th Floor, GSR #125**

**NOTICE TO PARENTS AND STAFF REGARDING THE  
ASBESTOS MANAGEMENT PLAN NOTIFICATION**

School: \_\_\_\_\_

Date: \_\_\_\_\_

This is to notify you in accordance with Illinois and Federal Asbestos Regulations, that a copy of the Asbestos Management Plan is available at each school during school hours by appointment. Requests to review the Asbestos Management Plan must be made at least 24 hours in advance.

Also please be advised that CPS conducts asbestos inspections of all schools every three years. The last inspection was completed in 2010. Asbestos surveillances are conducted every six months.

CHECK ONE

- A copy of this notice was sent home in each child's backpack.
- A copy of this notice was printed in the school's newsletter or calendar and sent home with each child.
- Other – Please indicate how this notice was delivered to parents and staff.

**A COPY OF THIS NOTICE MUST BE PLACED IN THE  
SCHOOL'S ASBESTOS MANAGEMENT PLAN.**

*VFT = Vinyl Floor Tile*

*Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.*