

**ILLINOIS DEPARTMENT OF PUBLIC HEALTH  
AHERA THREE YEAR REINSPECTION  
ASBESTOS ABATEMENT PROGRAM  
SCHOOL INFORMATION FORM**

**SECTION I**

NAME OF SCHOOL DISTRICT: CHICAGO SCHOOL DIST 299  
SCHOOL ID NUMBER: 14-016-2990-2069  
SCHOOL NAME: Bass School  
ADDRESS OF SCHOOL: 1140 W. 66th  
CITY: Chicago, IL, 60621

DATE LAST THREE YEAR REINSPECTION WAS COMPLETED **2/9/2010**

**If the address on this form is different than the address of the building, submit a written explanation.**

---

**SECTION II** *(Please type or print)*

**PLEASE COMPLETE THE FOLLOWING FOR YOUR THREE YEAR REINSPECTION:**

DATE REINSPECTION COMPLETED: 4/1/2013 ENROLLMENT 333

IDPH INSPECTOR LICENSE NUMBER: 100-02865

IDPH LICENSED INSPECTOR NAME (Please Print): Steven Doran

IDPH MP LICENSE NUMBER: 100-09870

IDPH LICENSED MANAGEMENT PLANNER NAME (Please Print): Todd Huffer

DESIGNATED PERSON (Please Print): Ms. Lynn Crivello PHONE: (773) 553-3113



4/1/2013

*Signature of Designated Person*

*Date*

---

**SECTION III**

PLEASE COMPLETE THE FOLLOWING INFORMATION FOR ANY CHANGES WITHIN THE SCHOOL DISTRICT.

School building has been sold. Date of Sale: \_\_\_\_\_

School has been closed. Date closed: \_\_\_\_\_

School building has been demolished. Date: \_\_\_\_\_

School building is asbestos free since last reinspection: \_\_\_\_\_

**Please explain in writing why the school building is now asbestos free and include the supporting documentation.**

If a new school building has been added to the district, submit either an exclusionary statement or a management plan and inspection report. Include the complete name, address and city of school building.

**Explain in writing if the address of the building is different than the address on this form:**

---

---

**THREE-YEAR REINSPECTION**

**CHICAGO SCHOOL DIST 299**

**Bass School**

1140 W. 66th  
Chicago, IL, 60621

Unit: 22161  
Building ID: 2180

IDPH ID Number: 14-016-2990-2069

**REPORT DATE:**

Monday, April 01, 2013

**Prepared for:**

**Chicago Public Schools**  
**125 S. Clark Street**  
**Chicago, IL 60603**

**Prepared by:**

**Carnow, Conibear and Associates**

600 West Van Buren St., Ste 500

Phone (312) 762-2900

Fax (312) 782-5145

**DO NOT REMOVE FROM SCHOOL  
REQUIRED BY FEDERAL LAW**



## **Environmental Notification to Occupants**

To: Faculty, Staff and Parents  
From: Chicago Public Schools  
Date: March 08, 2013

RE: Bass School, Unit 22161  
1140 W. 66th  
Chicago, IL, 60621

Dear Faculty, Staff and Parents,

This letter is to notify you that the 2013 asbestos three year re-inspection has been completed at Bass School , following the Federal Asbestos Hazard Emergency Response Act (AHERA), 40 CFR Part 763, Subpart E and is available for your review at the main office of the school.

Although asbestos-containing materials have been identified at Bass School, there is no reason to believe that any threat to the health of students or staff exists at this time. CPS will continue to carefully monitor the condition of asbestos-containing materials and if conditions warrant, all appropriate steps will be taken to maintain the health and safety of all building occupants.

If you have any questions regarding this matter or require additional information, please feel free to contact Ms. Lynn Crivello, the designated Local Education Authority's Designated Person at (773) 553-3113 .

## **Table of Contents**

- I. School and Inspection Information
- II. Executive Summary
- III. Methodology
- IV. Abatement History
- V. Reassessments and Recommendations
- VI. Conclusions

Table I: Inspector's Reinspection Findings

Table II: Management Planner's Review

### **APPENDICES:**

- Appendix A: Assessment Sheets, Drawings and Photos
- Appendix B: Inspector and Management Planner Licenses
- Appendix C: Laboratory Accreditations
- Appendix D: Laboratory Results
- Appendix E: Chain of Custody Forms

## SCHOOL AND INSPECTION INFORMATION

### 1. School Information

School: Bass School Unit: 22161 Region: 05  
Address: 1140 W. 66th Chicago, IL, 60621  
IDPH ID: 14-016-2990-2069 Building ID: 2180  
Contact: Dixon, Charles Phone: 773-535-3277

### 2. Description of Facility

Original Construction: Additional Construction:  
Total Square Footage: 81300 No of Floors: 1  
Current Occupancy: 333

### 3. LEA Designated Person

Contact: Ms. Lynn Crivello Phone: (773) 553-3113  
Address: 125 South Clark Street, 17th Floor  
Chicago, IL 60603


### 4. Managing Environmental Consultant

MEC: Carnow, Conibear and Associates  
Contact: Dan Juneau  
Address 600 West Van Buren St., Ste 500  
Phone: (312) 762-2900 Fax: (312) 782-5145

### 5. Inspector

Inspector Name: Steven Doran


Inspector IDPH license # 100-02865

  
Signature:  
Date: 3/8/2013

### 6. Management Planner

Management Planner Name: Todd Huffer

Management Planner IDPH license # 100-09870

  
Signature:  
Date: 4/1/2013

### 7. Review Date: 4/1/2013

### 8. LEA Designated Person's Acknowledgement

The reinspection report and recommendations have been received by me and appropriate action will be taken by the School District.

Signature:



Date: 4/1/2013

Name: Ms. Lynn Crivello

## II. EXECUTIVE SUMMARY

Carnow, Conibear and Associates was retained by the Chicago Public Schools (CPS) to perform a three-year asbestos reinspection of the Bass School. This inspection was conducted in accordance with the United States Environmental Protection Agency (USEPA) Asbestos Hazard Emergency Response Act (AHERA) part 763.92 (b), and the ongoing Operations and Maintenance Program (O&M) originally designed in the School's Asbestos Management Plan. The purpose of this three-year reinspection is to record any condition changes in the asbestos-containing building material (ACBM) in the school since the previous three-year reinspection and the six-month periodic surveillance, to identify, assess, and include any Homogeneous Areas (HA) not identified in the Management Plan, and to recommend an appropriate response action to manage asbestos.

The inspector conducted a three-year reinspection of this facility under Illinois Department of Public Health (IDPH) school reinspection requirements and AHERA, sections 763.85 and 763.88. The main building and each addition to the main building, if constructed at different dates, were inspected separately. Laboratory accreditations are included in Appendix C, laboratory results are included in Appendix D, and chain of custody forms are included in Appendix E.

Note: During previous inspections, some of the HA(s) were identified together as 9" x 9" floor tile (FT), mastics assoc. with 9" x 9" FT, 12" x 12" FT, mastics assoc. with 12" x 12" FT, pipe insulation, etc. Some of these HA(s) have been re-identified by areas that are uniform in color, texture, construction date, application date, and general appearance.

The inspector has determined the following:

A. The following HAs have changed assessment categories for Building 2180:

10	9x9 floor tile mastic
FT-2	12x12 light brown w/white specks floor tile
FT-3	12x12 brown w/white flecks floor tile
FT-4	12x12 white w/thin flecks floor tile
FT-5	linoleum
FT-7	12x12 off white w/brown & gray flecks floor tile
FT-8	12x12 brown w/white specks floor tile
FTM-2	12x12 light brown w/white specks floor tile mastic
FTM-3	12x12 brown w/white flecks floor tile mastic

FTM-5

linoleum mastic

FTM-7

12x12 off wht w/brwn & gray flecks flr tile mastic



B. The following new homogenous areas have been identified for Building 2180:

- CT1                    2 X 4 Ceiling Tile
- CT2                    2 X 4 Ceiling Tile

C. This reinspection covered only physically accessible and visible areas and materials that were identified in the LEA's management plan. The following materials were concealed and/or contained in areas that were inaccessible for sampling and have been classified as Assumed:

04	hardcoat plaster
10	9x9 floor tile mastic
CM-1	blue carpet mastic
CM-2	light blue carpet mastic
CT1	2 X 4 Ceiling Tile
CT2	2 X 4 Ceiling Tile
FT-10	12x12 blue floor tile
FT-11	12x12 brown floor tile
FT-12	12x12 brown floor tile mastic
FT-2	12x12 light brown w/white specks floor tile
FT-3	12x12 brown w/white flecks floor tile
FT-4	12x12 white w/thin flecks floor tile
FT-5	linoleum
FT-7	12x12 off white w/brown & gray flecks floor tile
FT-8	12x12 brown w/white specks floor tile
FT-9	12x12 blue floor tile
FTM-2	12x12 light brown w/white specks floor tile mastic
FTM-3	12x12 brown w/white flecks floor tile mastic
FTM-5	linoleum mastic
FTM-7	12x12 off wht w/brwn & gray flecks flr tile mastic
FTM-9	12x12 blue floor tile mastic

The following areas were deemed to be inaccessible:

09	12x12 floor tile mastic
10	9x9 floor tile mastic
11	9x9 floor tile mastic
CM-1	blue carpet mastic
CM-2	light blue carpet mastic
FT-12	12x12 brown floor tile mastic
FTM-1	mastic beneath 9x9 tan floor tile
FTM-2	12x12 light brown w/white specks floor tile mastic
FTM-4	12x12 white w/thin flecks floor tile mastic
FTM-5	linoleum mastic
FTM-6	9x9 dark tan w/brown streaks floor tile mastic
FTM-7	12x12 off wht w/brwn & gray flecks flr tile mastic
FTM-8	12x12 brown w/white specks floor tile mastic
I	aircell pipe
J	aircell joints
K	cardboard pipe
L	cardboard joints
O	aircell pipe lag

P                      aircell pipe-1960 bldg  
Q                      aircell joints

Materials were also listed as "assumed" if they were in good condition and sampling was not conducted to avoid damage.

This reinspection was conducted by Steven Doran, IDPH License # 100-02865. The Management Plan was updated by Todd Huffer, IDPH License # 100-09870. Inspector and Management Planner Licenses are included in Appendix B.

### **III. METHODOLOGY**

Tasks performed on-site included the following:

1. Review current management plan, identify HA(s) and extract appropriate information.
2. Examine and verify abatement records.
3. Touch and visually and physically reinspect and reassess the condition of all friable known or assumed ACBM.
4. Touch and visually and physically reinspect all non-friable known or assumed ACBM to determine whether these materials have become friable since the last inspection or periodic surveillance.
5. Identify any condition changes that may affect Hazard Ranking of known ACBM or Assumed ACBM, as well as any HA(s) that have become friable since the last reinspection.
6. Collect bulk samples from each newly discovered friable HA or previously assumed and submit for laboratory analysis.
7. Tabulate reinspection findings and submit for management planner review and recommendations with appropriate response actions based on the AHERA Damage Category of the ACBM.
8. Submit reinspection findings and management planner recommendations to the LEA within thirty (30) days for inclusion into the management plan.

### **IV. ABATEMENT HISTORY**

The information collected from the existing management plan and inspection report(s) and from interviews with the school official revealed that the following asbestos abatement was conducted at the school since the previous Three year Reinspection.

Abatement Dates:

### **V. REASSESSMENTS AND RECOMMENDATIONS**

The reassessments and recommendations are summarized in Tables I and II on the following pages. Detailed Hazard Assessment Sheets and Drawings and Photos (if applicable) are included in Appendix A.

### **VI. CONCLUSIONS**

The Bass School Building 2180 Three-Year reinspection has been completed and response actions have been recommended for both friable and non-friable materials. A timely execution of the response actions recommended will enable the LEA and the Designated Person(s) to effectively manage the existing ACBM.

This three-year reinspection report should be inspected in the current Management plan at the CPS Central Office, and one (1) copy should be kept at the school for use when planning any renovation and/or demolition activities in areas where ACBM has been identified. Also, periodic surveillance documentation and any summary reports from any response actions that are executed at the school should be used to update the Management Plan.

**Table I**  
**Inspector's Reinspection Findings**

---

# Chicago Public Schools

School Bass School Unit 22161 Building ID 2180

Address 1140 W. 66th Region 05

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
01	hard coat plaster	75,000	SF	throughout 1894 building	AMO_CHR	SURFACE	Y	NONE	0		No	ACBM with the potential for damage		MODERATE
02	12x12 beige floor tile	6,500	SF	1894 - rm 08, 07, 01 & bsmnt crrdr & playrms, rm 106, 103, 104, 107 & 108 & 1st flr storage & wardrobes, rooms 303-307, counselor's office, and principals office closet	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
03	9x9 black with white streaks floor tile	200	SF	1894 bldg - engineer's office	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
04	hardcoat plaster	12,800	SF	1939 building- basement assembly hall & platform	ASSUMED	SURFACE	N	NONE	0		No	ACBM with the potential for damage		LOW
07	9x9 floor tile	3,000	SF	1960 bldg- 1st & 2nd floor west corridor	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
09	12x12 floor tile mastic	5,600	SF	1894 - rm 08,07,01 & bsmnt crrdr & playrms, rm 106,103, 104 & 1st flr strge & wardrobes, rm 303-307	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
10	9x9 floor tile mastic	200	SF	1894 bldg - engineer's office & toilet	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
11	9x9 floor tile mastic	3,000	SF	1960 bldg- 1st & 2nd floor west corridor	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
2	12x12 beige floor tile	0	SF	Various Rooms	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
BB-1	baseboard	900	LF	1st, 2nd, 3rd floor corridors - 1894 building	NO_ACBM	MISC								
BBM-1	baseboard mastic	900	LF	1st, 2nd, 3rd floor corridors - 1894 building	NO_ACBM	MISC								
CM-1	blue carpet mastic	1,750	SF	Room 303, 305, Art Room	ASSUMED	MISC	N	None	0		No	ACBM with the potential for damage		LOW
CM-2	light blue carpet mastic	180	SF	assistant principal's office	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW

# Chicago Public Schools

School Bass School Unit 22161 Building ID 2180

Address 1140 W. 66th Region 05

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
CT1	2 X 4 Ceiling Tile	800	SF	Kitchen	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
CT2	2 X 4 Ceiling Tile	2,730	SF	Room 303, 305, Art Room, Principal Office, Lunchroom	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
FT-1	9x9 tan floor tile	100	SF	basement bathroom, engineer's toilet	CHR	MISC	N	None	0		No	ACBM with the potential for damage		LOW
FT-10	12x12 blue floor tile	15	SF	Faculty room	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
FT-11	12x12 brown floor tile	75	SF	Principal rest room, storage closet, main office safe	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
FT-12	12x12 brown floor tile mastic	75	SF	Principal rest room, storage closet, main office safe	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
FT-2	12x12 light brown w/white specks floor tile	600	SF	stair case landing-1894	ASSUMED	MISC	N	NONE			Yes	ACBM with the potential for damage		LOW
FT-3	12x12 brown w/white flecks floor tile	750	SF	room 302 and Wardrobes	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
FT-4	12x12 white w/thin flecks floor tile	750	SF	room 308	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
FT-5	linoleum	2,400	SF	room 109, 113	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
FT-6	9x9 dark tan w/brown streaks floor tile	7,400	SF	room 110, 115, 212, 213, 214, 216, 208, 210,209,217,2nd floor faculty room	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
FT-7	12x12 off white w/brown & gray flecks floor tile	750	SF	room 211	ASSUMED	MISC	N	NONE			Yes	ACBM with the potential for damage		LOW
FT-8	12x12 brown w/white specks floor tile	300	SF	hall between 1939, 1960	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
FT-9	12x12 blue floor tile	2,400	SF	auditorium	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
FTM-1	mastic beneath 9x9 tan floor tile	100	SF	basement bathroom, engineer's office toilet	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
FTM-2	12x12 light brown w/white specks floor tile mastic	600	SF	stair case landing-1894	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
FTM-3	12x12 brown w/white flecks floor tile mastic	750	SF	room 302	ASSUMED	MISC	N	NONE			Yes	ACBM with the potential for damage		LOW
FTM-4	12x12 white w/thin flecks floor tile mastic	750	SF	room 308	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
FTM-5	linoleum mastic	2,400	SF	room 109, 114, 113	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW

# Chicago Public Schools

School Bass School Unit 22161 Building ID 2180

Address 1140 W. 66th Region 05

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
FTM-6	9x9 dark tan w/brown streaks floor tile mastic	7,385	SF	room 110, 115, 212, 213, 214, 216, 208, 210,209,217, 2nd floor faculty room	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
FTM-7	12x12 off wht w/brwn & gray flecks flr tile mastic	750	SF	room 211	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
FTM-8	12x12 brown w/white specks floor tile mastic	300	SF	hall between 1939, 1960	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
FTM-9	12x12 blue floor tile mastic	2,400	SF	Auditorium	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
G	Acoustical Plaster	15,000	SF	1960 building, rms 117,115,113,110,10 8,111,109, girls&boys rr, JC, stairs	NO_ACBM	SURFACE								
I	aircell pipe	200	LF	1894 bldg - boys playroom, storage, book room, girls playroom, fan room	CHR	TSI	N	NONE	0		No	ACBM with the potential for damage		LOW
J	aircell joints	30	LF	1894 bldg - boys playroom, storage, book room, girls playroom, fan room	CHR	TSI	N	NONE	0		No	ACBM with the potential for damage		LOW
K	cardboard pipe	200	LF	1894 bldg- basement boys & girls playroom, fan room, toilets, corridors	CHR	TSI	N	NONE	0		No	ACBM with the potential for damage		LOW
L	cardboard joints	20	LF	1894 bldg- basement boys & girls playroom, fan room, toilets, corridors	CHR	TSI	N	NONE	0		No	ACBM with the potential for damage		LOW
N	fiberglass joints	60	LF	1894 bldg-basement boys & girls toilets & playrooms, toilets, fan room	NO_ACBM	TSI								
O	aircell pipe lag	900	LF	1939 building- basement assembly room, platform, fan room	CHR	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW
P	aircell pipe-1960 bldg	100	LF	1960 bldg- 2nd floor stairwells (between room 217 & 210, between rooms 209 & mens bathroom)	CHR	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW
Q	aircell joints	50	LF	1939 bldg -	CHR	TSI	Y	NONE	0		No	ACBM with the		LOW





# Chicago Public Schools

School Bass School Unit 22161 Building ID 2180

Address 1140 W. 66th Region 05

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

*Inspector's Comments are Summarized at the End of the Report*

Reinspection Date <b>3/8/2013</b>
Inspector Name <b>Steven Doran</b>
<b>100-02865</b> <b>5/15/2013</b>
Inspector's IDPH License Number / Expiration Date

### Inspector's Comments

HA Number:	Inspector Comments:
01	
02	
03	
04	
07	
09	
10	
11	
2	
BB-1	
BBM-1	
CM-1	
CM-2	
CT1	
CT2	
FT-1	
FT-10	
FT-11	
FT-12	
FT-2	
FT-3	
FT-4	
FT-5	
FT-6	

# Chicago Public Schools

School Bass School Unit 22161 Building ID 2180

Address 1140 W. 66th Region 05

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

*Inspector's Comments are Summarized at the End of the Report*

---

HA Number:	Inspector Comments:
FT-7	
FT-8	
FT-9	
FTM-1	
FTM-2	
FTM-3	
FTM-4	
FTM-5	
FTM-6	
FTM-7	
FTM-8	
FTM-9	
G	
I	
J	
K	
L	
N	
O	
P	
Q	
R	

**Table II**

**Management Planner's Review**

---

# Chicago Public Schools

School Bass School  
Address 1140 W. 66th

Unit 22161  
Chicago, IL, 60621

Building ID 2180  
Region 05

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

### Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
01	hard coat plaster	75,000	SF	throughout 1894 building	Amosite, Chrysotile	SURFACE	Yes	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
02	12x12 beige floor tile	6,500	SF	1894 - rm 08, 07, 01 & bsmnt crdr & playrms, rm 106, 103, 104, 107 & 108 & 1st flr storage & wardrobes, rooms 303-307, counselor's office, and principals office closet	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
03	9x9 black with white streaks floor tile	200	SF	1894 bldg - engineer's office	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
04	hardcoat plaster	12,800	SF	1939 building- basement assembly hall & platform	Assumed	SURFACE	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
07	9x9 floor tile	3,000	SF	1960 bldg- 1st & 2nd floor west corridor	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
09	12x12 floor tile mastic	5,600	SF	1894 - rm 08,07,01 & bsmnt crdr & playrms, rm 106,103, 104 & 1st flr strge & wardrobes, rm 303-307	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
10	9x9 floor tile mastic	200	SF	1894 bldg - engineer's office & toilet	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
11	9x9 floor tile mastic	3,000	SF	1960 bldg- 1st & 2nd floor west corridor	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
2	12x12 beige floor tile	0	SF	Various Rooms	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
BB-1	baseboard	900	LF	1st, 2nd, 3rd floor corridors - 1894 building	No ACBM	MISC			LF		
BBM-1	baseboard mastic	900	LF	1st, 2nd, 3rd floor corridors - 1894 building	No ACBM	MISC			LF		
CM-1	blue carpet mastic	1,750	SF	Room 303, 305, Art Room	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
CM-2	light blue carpet mastic	180	SF	assistant principal's office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
CT1	2 X 4 Ceiling Tile	800	SF	Kitchen	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
CT2	2 X 4 Ceiling Tile	2,730	SF	Room 303, 305, Art Room, Principal Office, Lunchroom	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
FT-1	9x9 tan floor tile	100	SF	basement bathroom, engineer's toilet	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
FT-10	12x12 blue floor tile	15	SF	Faculty room	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
FT-11	12x12 brown floor tile	75	SF	Principal rest room, storage closet, main office safe	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
FT-12	12x12 brown floor tile mastic	75	SF	Principal rest room, storage closet, main office safe	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
FT-2	12x12 light brown w/white specks floor tile	600	SF	stair case landing-1894	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Operations and Maintenance
FT-3	12x12 brown w/white flecks floor tile	750	SF	room 302 and Wardrobes	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance

# Chicago Public Schools

School Bass School  
Address 1140 W. 66th

Unit 22161  
Chicago, IL, 60621

Building ID 2180  
Region 05

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

### Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
FT-4	12x12 white w/thin flecks floor tile	750	SF	room 308	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
FT-5	linoleum	2,400	SF	room 109, 113	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
FT-6	9x9 dark tan w/brown streaks floor tile	7,400	SF	room 110, 115, 212, 213, 214, 216, 208, 210,209,217,2nd floor faculty room	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
FT-7	12x12 off white w/brown & gray flecks floor tile	750	SF	room 211	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Operations and Maintenance
FT-8	12x12 brown w/white specks floor tile	300	SF	hall between 1939, 1960	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
FT-9	12x12 blue floor tile	2,400	SF	auditorium	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
FTM-1	mastic beneath 9x9 tan floor tile	100	SF	basement bathroom, engineer's office toilet	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
FTM-2	12x12 light brown w/white specks floor tile mastic	600	SF	stair case landing-1894	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
FTM-3	12x12 brown w/white flecks floor tile mastic	750	SF	room 302	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Operations and Maintenance
FTM-4	12x12 white w/thin flecks floor tile mastic	750	SF	room 308	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
FTM-5	linoleum mastic	2,400	SF	room 109, 114, 113	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
FTM-6	9x9 dark tan w/brown streaks floor tile mastic	7,385	SF	room 110, 115, 212, 213, 214, 216, 208, 210,209,217, 2nd floor faculty room	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
FTM-7	12x12 off wht w/brwn & gray flecks flr tile mastic	750	SF	room 211	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
FTM-8	12x12 brown w/white specks floor tile mastic	300	SF	hall between 1939, 1960	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
FTM-9	12x12 blue floor tile mastic	2,400	SF	Auditorium	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
G	Acoustical Plaster	15,000	SF	1960 building, rms 117,115,113,110,108,111,109, girls&boys rr, JC, stairs	No ACBM	SURFACE			SF		
I	aircell pipe	200	LF	1894 bldg - boys playroom, storage, book room, girls playroom, fan room	Chrysotile	TSI	No	0	LF	6 ACBM with the potential for damage	Operations and Maintenance
J	aircell joints	30	LF	1894 bldg - boys playroom, storage, book room, girls playroom, fan room	Chrysotile	TSI	No	0	LF	6 ACBM with the potential for damage	Operations and Maintenance
K	cardboard pipe	200	LF	1894 bldg- basement boys & girls playroom, fan room, toilets, corridors	Chrysotile	TSI	No	0	LF	6 ACBM with the potential for damage	Operations and Maintenance
L	cardboard joints	20	LF	1894 bldg- basement boys & girls playroom, fan room, toilets, corridors	Chrysotile	TSI	No	0	LF	6 ACBM with the potential for damage	Operations and Maintenance
N	fiberglass joints	60	LF	1894 bldg-basement boys & girls toilets & playrooms, toilets, fan room	No ACBM	TSI			LF		
O	aircell pipe lag	900	LF	1939 building- basement assembly room, platform, fan room	Chrysotile	TSI	Yes	0	LF	6 ACBM with the potential for damage	Operations and Maintenance
P	aircell pipe-1960 bldg	100	LF	1960 bldg- 2nd floor stairwells	Chrysotile	TSI	Yes	0	LF	6 ACBM with the potential for damage	Operations and Maintenance

# Chicago Public Schools

**School** Bass School  
**Address** 1140 W. 66th

**Unit** 22161  
 Chicago, IL, 60621

**Building ID** 2180  
**Region** 05

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

### *Management Planner's Comments Summarized at the End of the Report*

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
				(between room 217 & 210, between rooms 209 & mens bathroom)							
Q	aircell joints	50	LF	1939 bldg - plaform, fan room	Chrysotile	TSI	Yes	0	LF	6 ACBM with the potential for damage	Operations and Maintenance
R	fiberglass joints- ABATED	0	LF	1960 bldg- 2nd floor west corridor	Abated	MISC			LF		

Review Date 4/1/2013

HA Number	Management Comments
-----------	---------------------

# Chicago Public Schools

**School** Bass School  
**Address** 1140 W. 66th

**Unit** 22161  
 Chicago, IL, 60621

**Building ID** 2180  
**Region** 05

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

### *Management Planner's Comments Summarized at the End of the Report*

Manager Planner Name	Todd Huffer
100-09870	5/15/2013
Manager IDPH License No/Expiration	

HA Number	Management Comments
01	
02	
03	
04	
07	
09	
10	
11	
2	
BB-1	
BBM-1	
CM-1	
CM-2	
CT1	
CT2	
FT-1	
FT-10	
FT-11	
FT-12	
FT-2	
FT-3	
FT-4	
FT-5	
FT-6	
FT-7	
FT-8	
FT-9	



# Chicago Public Schools

**School** Bass School  
**Address** 1140 W. 66th

**Unit** 22161  
 Chicago, IL, 60621

**Building ID** 2180  
**Region** 05

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

### *Management Planner's Comments Summarized at the End of the Report*

HA Number	Management Comments
FTM-1	
FTM-2	
FTM-3	
FTM-4	
FTM-5	
FTM-6	
FTM-7	
FTM-8	
FTM-9	
G	
I	
J	
K	
L	
N	
O	
P	
Q	
R	

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22161** BUIDLING ID: **2180**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Steven Doran**  
SCHOOL NAME: **Bass School** INSPECTION DATE: **3/8/2013**  
ADDRESS: **1140 W. 66th** IDPH LICENSE NO: **100-02865**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **01**  
MATERIAL DESCRIPTION: **hard coat plaster**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**  
ASBESTOS TYPE: **Amosite, Chrysotile** FRIABLE: **Yes**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**

MATERIAL LOCATION: **throughout 1894 building**

MATERIAL QUANTITY: **75000**


MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/08/2013**

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22161** BUIDLING ID: **2180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Bass School** REVIEW DATE: **4/1/2013**  
ADDRESS: **1140 W. 66th** IDPH LICENSE NO: **100-02865**

---

HOMOGENEOUS AREA: **01**  
MATERIAL DESCRIPTION: **hard coat plaster**  
MATERIAL LOCATION: **throughout 1894 building**  
MATERIAL QUANTITY: **75000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Operations and Maintenance

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **04/01/2013**

# Chicago Public Schools

## Carnow, Conibear and Associates 2013 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22161** BUIDLING ID: **2180**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Steven Doran**  
SCHOOL NAME: **Bass School** INSPECTION DATE: **3/8/2013**  
ADDRESS: **1140 W. 66th** IDPH LICENSE NO: **100-02865**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **02**  
MATERIAL DESCRIPTION: **12x12 beige floor tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**


MATERIAL LOCATION: **1894 - rm 08, 07, 01 & bsmnt crrdr & playrms, rm 106, 103, 104, 107 & 108 & 1st flr storage & wardrobes, rooms 303-307, counselor's office, and principals office closet**

MATERIAL QUANTITY: **6500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/08/2013**

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22161** BUIDLING ID: **2180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Bass School** REVIEW DATE: **4/1/2013**  
ADDRESS: **1140 W. 66th** IDPH LICENSE NO: **100-02865**

---

HOMOGENEOUS AREA: **02**  
MATERIAL DESCRIPTION: **12x12 beige floor tile**  
MATERIAL LOCATION: **1894 - rm 08, 07, 01 & bsmnt crdr & playrms, rm 106, 103, 104, 107 & 108 & 1st flr storage & wardrobes, rooms 303-307, counselor's office, and principals office closet**  
MATERIAL QUANTITY: **6500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Operations and Maintenance

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: 04/01/2013

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22161** BUIDLING ID: **2180**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Steven Doran**  
SCHOOL NAME: **Bass School** INSPECTION DATE: **3/8/2013**  
ADDRESS: **1140 W. 66th** IDPH LICENSE NO: **100-02865**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **03**  
MATERIAL DESCRIPTION: **9x9 black with white streaks floor tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **1894 bldg - engineer's office**

MATERIAL QUANTITY: **200**


MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/08/2013**

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22161** BUIDLING ID: **2180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Bass School** REVIEW DATE: **4/1/2013**  
ADDRESS: **1140 W. 66th** IDPH LICENSE NO: **100-02865**

---

HOMOGENEOUS AREA: **03**  
MATERIAL DESCRIPTION: **9x9 black with white streaks floor tile**  
MATERIAL LOCATION: **1894 bldg - engineer's office**  
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Operations and Maintenance

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **04/01/2013**

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22161** BUIDLING ID: **2180**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Steven Doran**  
SCHOOL NAME: **Bass School** INSPECTION DATE: **3/8/2013**  
ADDRESS: **1140 W. 66th** IDPH LICENSE NO: **100-02865**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **04**  
MATERIAL DESCRIPTION: **hardcoat plaster**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1939 building- basement assembly hall & platform**  
MATERIAL QUANTITY: **12800** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/08/2013**



# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22161** BUIDLING ID: **2180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Bass School** REVIEW DATE: **4/1/2013**  
ADDRESS: **1140 W. 66th** IDPH LICENSE NO: **100-02865**

---

HOMOGENEOUS AREA: **04**  
MATERIAL DESCRIPTION: **hardcoat plaster**  
MATERIAL LOCATION: **1939 building- basement assembly hall & platform**  
MATERIAL QUANTITY: **12800** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Operations and Maintenance

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **04/01/2013**

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22161** BUIDLING ID: **2180**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Steven Doran**  
SCHOOL NAME: **Bass School** INSPECTION DATE: **3/8/2013**  
ADDRESS: **1140 W. 66th** IDPH LICENSE NO: **100-02865**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **07**  
MATERIAL DESCRIPTION: **9x9 floor tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1960 bldg- 1st & 2nd floor west corridor**  
MATERIAL QUANTITY: **3000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/08/2013**

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22161** BUIDLING ID: **2180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Bass School** REVIEW DATE: **4/1/2013**  
ADDRESS: **1140 W. 66th** IDPH LICENSE NO: **100-02865**

---

HOMOGENEOUS AREA: **07**  
MATERIAL DESCRIPTION: **9x9 floor tile**  
MATERIAL LOCATION: **1960 bldg- 1st & 2nd floor west corridor**  
MATERIAL QUANTITY: **3000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Operations and Maintenance

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **04/01/2013**

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22161** BUIDLING ID: **2180**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Steven Doran**  
SCHOOL NAME: **Bass School** INSPECTION DATE: **3/8/2013**  
ADDRESS: **1140 W. 66th** IDPH LICENSE NO: **100-02865**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **09**  
MATERIAL DESCRIPTION: **12x12 floor tile mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **1894 - rm 08,07,01 & bsmnt crdr & playrms, rm 106,103, 104 & 1st flr strge & wardrobes, rm 303-307**

MATERIAL QUANTITY: **5600**


MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/08/2013**

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22161** BUIDLING ID: **2180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Bass School** REVIEW DATE: **4/1/2013**  
ADDRESS: **1140 W. 66th** IDPH LICENSE NO: **100-02865**

---

HOMOGENEOUS AREA: **09**  
MATERIAL DESCRIPTION: **12x12 floor tile mastic**  
MATERIAL LOCATION: **1894 - rm 08,07,01 & bsmnt crrdr & playrms, rm 106,103, 104 & 1st flr strge & wardrobes, rm 303-307**  
MATERIAL QUANTITY: **5600** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Operations and Maintenance

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: 04/01/2013

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22161** BUIDLING ID: **2180**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Steven Doran**  
SCHOOL NAME: **Bass School** INSPECTION DATE: **3/8/2013**  
ADDRESS: **1140 W. 66th** IDPH LICENSE NO: **100-02865**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **10**  
MATERIAL DESCRIPTION: **9x9 floor tile mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT


This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1894 bldg - engineer's office & toilet**  
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 03/08/2013

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22161** BUIDLING ID: **2180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Bass School** REVIEW DATE: **4/1/2013**  
ADDRESS: **1140 W. 66th** IDPH LICENSE NO: **100-02865**

---

HOMOGENEOUS AREA: **10**  
MATERIAL DESCRIPTION: **9x9 floor tile mastic**  
MATERIAL LOCATION: **1894 bldg - engineer's office & toilet**  
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **04/01/2013**

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22161** BUIDLING ID: **2180**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Steven Doran**  
SCHOOL NAME: **Bass School** INSPECTION DATE: **3/8/2013**  
ADDRESS: **1140 W. 66th** IDPH LICENSE NO: **100-02865**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **11**  
MATERIAL DESCRIPTION: **9x9 floor tile mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **1960 bldg- 1st & 2nd floor west corridor**

MATERIAL QUANTITY: **3000**


MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/08/2013**



# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22161** BUIDLING ID: **2180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Bass School** REVIEW DATE: **4/1/2013**  
ADDRESS: **1140 W. 66th** IDPH LICENSE NO: **100-02865**

---

HOMOGENEOUS AREA: **11**  
MATERIAL DESCRIPTION: **9x9 floor tile mastic**  
MATERIAL LOCATION: **1960 bldg- 1st & 2nd floor west corridor**  
MATERIAL QUANTITY: **3000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Operations and Maintenance

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **04/01/2013**

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22161** BUIDLING ID: **2180**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Steven Doran**  
SCHOOL NAME: **Bass School** INSPECTION DATE: **3/8/2013**  
ADDRESS: **1140 W. 66th** IDPH LICENSE NO: **100-02865**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **2**  
MATERIAL DESCRIPTION: **12x12 beige floor tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Various Rooms**

MATERIAL QUANTITY: **0**


MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/08/2013**

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22161** BUIDLING ID: **2180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Bass School** REVIEW DATE: **4/1/2013**  
ADDRESS: **1140 W. 66th** IDPH LICENSE NO: **100-02865**

---

HOMOGENEOUS AREA: **2**

MATERIAL DESCRIPTION: **12x12 beige floor tile**

MATERIAL LOCATION: **Various Rooms**

MATERIAL QUANTITY: **0**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **04/01/2013**

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22161** BUIDLING ID: **2180**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Steven Doran**  
SCHOOL NAME: **Bass School** INSPECTION DATE: **3/8/2013**  
ADDRESS: **1140 W. 66th** IDPH LICENSE NO: **100-02865**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **BB-1**  
MATERIAL DESCRIPTION: **baseboard**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:


MATERIAL LOCATION: **1st, 2nd, 3rd floor corridors - 1894 building**

MATERIAL QUANTITY: **900** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature:



Date: **03/08/2013**

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22161** BUIDLING ID: **2180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Bass School** REVIEW DATE: **4/1/2013**  
ADDRESS: **1140 W. 66th** IDPH LICENSE NO: **100-02865**

---

HOMOGENEOUS AREA: **BB-1**  
MATERIAL DESCRIPTION: **baseboard**  
MATERIAL LOCATION: **1st, 2nd, 3rd floor corridors - 1894 building**  
MATERIAL QUANTITY: **900** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **04/01/2013**

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22161** BUIDLING ID: **2180**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Steven Doran**  
SCHOOL NAME: **Bass School** INSPECTION DATE: **3/8/2013**  
ADDRESS: **1140 W. 66th** IDPH LICENSE NO: **100-02865**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **BBM-1**  
MATERIAL DESCRIPTION: **baseboard mastic**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:


MATERIAL LOCATION: **1st, 2nd, 3rd floor corridors - 1894 building**

MATERIAL QUANTITY: **900** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature:



Date: **03/08/2013**

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22161** BUIDLING ID: **2180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Bass School** REVIEW DATE: **4/1/2013**  
ADDRESS: **1140 W. 66th** IDPH LICENSE NO: **100-02865**

---

HOMOGENEOUS AREA: **BBM-1**  
MATERIAL DESCRIPTION: **baseboard mastic**  
MATERIAL LOCATION: **1st, 2nd, 3rd floor corridors - 1894 building**  
MATERIAL QUANTITY: **900** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **04/01/2013**

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22161** BUIDLING ID: **2180**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Steven Doran**  
SCHOOL NAME: **Bass School** INSPECTION DATE: **3/8/2013**  
ADDRESS: **1140 W. 66th** IDPH LICENSE NO: **100-02865**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **CM-1**  
MATERIAL DESCRIPTION: **blue carpet mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Room 303, 305, Art Room**  
MATERIAL QUANTITY: **1750** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/08/2013**



# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22161** BUIDLING ID: **2180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Bass School** REVIEW DATE: **4/1/2013**  
ADDRESS: **1140 W. 66th** IDPH LICENSE NO: **100-02865**

---

HOMOGENEOUS AREA: **CM-1**  
MATERIAL DESCRIPTION: **blue carpet mastic**  
MATERIAL LOCATION: **Room 303, 305, Art Room**  
MATERIAL QUANTITY: **1750** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Operations and Maintenance

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **04/01/2013**

# Chicago Public Schools

## Carnow, Conibear and Associates 2013 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22161** BUIDLING ID: **2180**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Steven Doran**  
SCHOOL NAME: **Bass School** INSPECTION DATE: **3/8/2013**  
ADDRESS: **1140 W. 66th** IDPH LICENSE NO: **100-02865**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **CM-2**  
MATERIAL DESCRIPTION: **light blue carpet mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **assistant principal's office**

MATERIAL QUANTITY: **180**


MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 03/08/2013

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22161** BUIDLING ID: **2180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Bass School** REVIEW DATE: **4/1/2013**  
ADDRESS: **1140 W. 66th** IDPH LICENSE NO: **100-02865**

---

HOMOGENEOUS AREA: **CM-2**  
MATERIAL DESCRIPTION: **light blue carpet mastic**  
MATERIAL LOCATION: **assistant principal's office**  
MATERIAL QUANTITY: **180** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Operations and Maintenance

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **04/01/2013**

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22161** BUIDLING ID: **2180**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Steven Doran**  
SCHOOL NAME: **Bass School** INSPECTION DATE: **3/8/2013**  
ADDRESS: **1140 W. 66th** IDPH LICENSE NO: **100-02865**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **FT-1**  
MATERIAL DESCRIPTION: **9x9 tan floor tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **basement bathroom, engineer's toilet**

MATERIAL QUANTITY: **100**


MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/08/2013**

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22161** BUIDLING ID: **2180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Bass School** REVIEW DATE: **4/1/2013**  
ADDRESS: **1140 W. 66th** IDPH LICENSE NO: **100-02865**

---

HOMOGENEOUS AREA: **FT-1**  
MATERIAL DESCRIPTION: **9x9 tan floor tile**  
MATERIAL LOCATION: **basement bathroom, engineer's toilet**  
MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Operations and Maintenance

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **04/01/2013**

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22161** BUIDLING ID: **2180**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Steven Doran**  
SCHOOL NAME: **Bass School** INSPECTION DATE: **3/8/2013**  
ADDRESS: **1140 W. 66th** IDPH LICENSE NO: **100-02865**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **FT-10**  
MATERIAL DESCRIPTION: **12x12 blue floor tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Faculty room**

MATERIAL QUANTITY: **15**


MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/08/2013**

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22161** BUIDLING ID: **2180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Bass School** REVIEW DATE: **4/1/2013**  
ADDRESS: **1140 W. 66th** IDPH LICENSE NO: **100-02865**

---

HOMOGENEOUS AREA: **FT-10**  
MATERIAL DESCRIPTION: **12x12 blue floor tile**  
MATERIAL LOCATION: **Faculty room**  
MATERIAL QUANTITY: **15** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Operations and Maintenance

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **04/01/2013**

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22161** BUIDLING ID: **2180**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Steven Doran**  
SCHOOL NAME: **Bass School** INSPECTION DATE: **3/8/2013**  
ADDRESS: **1140 W. 66th** IDPH LICENSE NO: **100-02865**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **FT-11**  
MATERIAL DESCRIPTION: **12x12 brown floor tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**


MATERIAL LOCATION: **Principal rest room, storage closet, main office safe**

MATERIAL QUANTITY: **75** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 03/08/2013



# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22161** BUIDLING ID: **2180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Bass School** REVIEW DATE: **4/1/2013**  
ADDRESS: **1140 W. 66th** IDPH LICENSE NO: **100-02865**

---

HOMOGENEOUS AREA: **FT-11**  
MATERIAL DESCRIPTION: **12x12 brown floor tile**  
MATERIAL LOCATION: **Principal rest room, storage closet, main office safe**  
MATERIAL QUANTITY: **75** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Operations and Maintenance

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **04/01/2013**

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22161** BUIDLING ID: **2180**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Steven Doran**  
SCHOOL NAME: **Bass School** INSPECTION DATE: **3/8/2013**  
ADDRESS: **1140 W. 66th** IDPH LICENSE NO: **100-02865**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **FT-12**  
MATERIAL DESCRIPTION: **12x12 brown floor tile mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**


MATERIAL LOCATION: **Principal rest room, storage closet, main office safe**

MATERIAL QUANTITY: **75** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: **03/08/2013**

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22161** BUIDLING ID: **2180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Bass School** REVIEW DATE: **4/1/2013**  
ADDRESS: **1140 W. 66th** IDPH LICENSE NO: **100-02865**

---

HOMOGENEOUS AREA: **FT-12**  
MATERIAL DESCRIPTION: **12x12 brown floor tile mastic**  
MATERIAL LOCATION: **Principal rest room, storage closet, main office safe**  
MATERIAL QUANTITY: **75** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Operations and Maintenance

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: 04/01/2013

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22161** BUIDLING ID: **2180**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Steven Doran**  
SCHOOL NAME: **Bass School** INSPECTION DATE: **3/8/2013**  
ADDRESS: **1140 W. 66th** IDPH LICENSE NO: **100-02865**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **FT-2**  
MATERIAL DESCRIPTION: **12x12 light brown w/white specks floor tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **stair case landing-1894**

MATERIAL QUANTITY: **600**


MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 03/08/2013

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22161** BUIDLING ID: **2180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Bass School** REVIEW DATE: **4/1/2013**  
ADDRESS: **1140 W. 66th** IDPH LICENSE NO: **100-02865**

---

HOMOGENEOUS AREA: **FT-2**  
MATERIAL DESCRIPTION: **12x12 light brown w/white specks floor tile**  
MATERIAL LOCATION: **stair case landing-1894**  
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **04/01/2013**

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22161** BUIDLING ID: **2180**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Steven Doran**  
SCHOOL NAME: **Bass School** INSPECTION DATE: **3/8/2013**  
ADDRESS: **1140 W. 66th** IDPH LICENSE NO: **100-02865**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **FT-3**  
MATERIAL DESCRIPTION: **12x12 brown w/white flecks floor tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **room 302 and Wardrobes**  
MATERIAL QUANTITY: **750** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/08/2013**

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22161** BUIDLING ID: **2180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Bass School** REVIEW DATE: **4/1/2013**  
ADDRESS: **1140 W. 66th** IDPH LICENSE NO: **100-02865**

---

HOMOGENEOUS AREA: **FT-3**  
MATERIAL DESCRIPTION: **12x12 brown w/white flecks floor tile**  
MATERIAL LOCATION: **room 302 and Wardrobes**  
MATERIAL QUANTITY: **750** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **04/01/2013**

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22161** BUIDLING ID: **2180**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Steven Doran**  
SCHOOL NAME: **Bass School** INSPECTION DATE: **3/8/2013**  
ADDRESS: **1140 W. 66th** IDPH LICENSE NO: **100-02865**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **FT-4**  
MATERIAL DESCRIPTION: **12x12 white w/thin flecks floor tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **room 308**  
MATERIAL QUANTITY: **750** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 03/08/2013



# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22161** BUIDLING ID: **2180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Bass School** REVIEW DATE: **4/1/2013**  
ADDRESS: **1140 W. 66th** IDPH LICENSE NO: **100-02865**

---

HOMOGENEOUS AREA: **FT-4**  
MATERIAL DESCRIPTION: **12x12 white w/thin flecks floor tile**  
MATERIAL LOCATION: **room 308**  
MATERIAL QUANTITY: **750** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **04/01/2013**

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22161** BUIDLING ID: **2180**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Steven Doran**  
SCHOOL NAME: **Bass School** INSPECTION DATE: **3/8/2013**  
ADDRESS: **1140 W. 66th** IDPH LICENSE NO: **100-02865**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **FT-5**  
MATERIAL DESCRIPTION: **linoleum**  
HISTORICAL AHERA DAMAGE CATEGORY **6**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **room 109, 113**  
MATERIAL QUANTITY: **2400** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/08/2013**

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22161** BUIDLING ID: **2180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Bass School** REVIEW DATE: **4/1/2013**  
ADDRESS: **1140 W. 66th** IDPH LICENSE NO: **100-02865**

---

HOMOGENEOUS AREA: **FT-5**  
MATERIAL DESCRIPTION: **linoleum**  
MATERIAL LOCATION: **room 109, 113**  
MATERIAL QUANTITY: **2400** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **04/01/2013**

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22161** BUIDLING ID: **2180**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Steven Doran**  
SCHOOL NAME: **Bass School** INSPECTION DATE: **3/8/2013**  
ADDRESS: **1140 W. 66th** IDPH LICENSE NO: **100-02865**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **FT-6**  
MATERIAL DESCRIPTION: **9x9 dark tan w/brown streaks floor tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **room 110, 115, 212, 213, 214, 216, 208, 210,209,217,2nd floor faculty room**  
MATERIAL QUANTITY: **7400** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/08/2013**

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22161** BUIDLING ID: **2180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Bass School** REVIEW DATE: **4/1/2013**  
ADDRESS: **1140 W. 66th** IDPH LICENSE NO: **100-02865**

---

HOMOGENEOUS AREA: **FT-6**  
MATERIAL DESCRIPTION: **9x9 dark tan w/brown streaks floor tile**  
MATERIAL LOCATION: **room 110, 115, 212, 213, 214, 216, 208, 210,209,217,2nd floor faculty room**  
MATERIAL QUANTITY: **7400** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Operations and Maintenance

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **04/01/2013**

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22161** BUIDLING ID: **2180**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Steven Doran**  
SCHOOL NAME: **Bass School** INSPECTION DATE: **3/8/2013**  
ADDRESS: **1140 W. 66th** IDPH LICENSE NO: **100-02865**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **FT-7**  
MATERIAL DESCRIPTION: **12x12 off white w/brown & gray flecks floor tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **room 211**  
MATERIAL QUANTITY: **750** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: **03/08/2013**

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22161** BUIDLING ID: **2180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Bass School** REVIEW DATE: **4/1/2013**  
ADDRESS: **1140 W. 66th** IDPH LICENSE NO: **100-02865**

---

HOMOGENEOUS AREA: **FT-7**

MATERIAL DESCRIPTION: **12x12 off white w/brown & gray flecks floor tile**

MATERIAL LOCATION: **room 211**

MATERIAL QUANTITY: **750**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **04/01/2013**

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22161** BUIDLING ID: **2180**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Steven Doran**  
SCHOOL NAME: **Bass School** INSPECTION DATE: **3/8/2013**  
ADDRESS: **1140 W. 66th** IDPH LICENSE NO: **100-02865**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **FT-8**  
MATERIAL DESCRIPTION: **12x12 brown w/white specks floor tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **hall between 1939, 1960**

MATERIAL QUANTITY: **300**


MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/08/2013**



# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22161** BUIDLING ID: **2180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Bass School** REVIEW DATE: **4/1/2013**  
ADDRESS: **1140 W. 66th** IDPH LICENSE NO: **100-02865**

---

HOMOGENEOUS AREA: **FT-8**  
MATERIAL DESCRIPTION: **12x12 brown w/white specks floor tile**  
MATERIAL LOCATION: **hall between 1939, 1960**  
MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **04/01/2013**

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22161** BUIDLING ID: **2180**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Steven Doran**  
SCHOOL NAME: **Bass School** INSPECTION DATE: **3/8/2013**  
ADDRESS: **1140 W. 66th** IDPH LICENSE NO: **100-02865**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **FT-9**  
MATERIAL DESCRIPTION: **12x12 blue floor tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **auditorium**  
MATERIAL QUANTITY: **2400** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 03/08/2013

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22161** BUIDLING ID: **2180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Bass School** REVIEW DATE: **4/1/2013**  
ADDRESS: **1140 W. 66th** IDPH LICENSE NO: **100-02865**

---

HOMOGENEOUS AREA: **FT-9**  
MATERIAL DESCRIPTION: **12x12 blue floor tile**  
MATERIAL LOCATION: **auditorium**  
MATERIAL QUANTITY: **2400** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Operations and Maintenance

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **04/01/2013**

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22161** BUIDLING ID: **2180**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Steven Doran**  
SCHOOL NAME: **Bass School** INSPECTION DATE: **3/8/2013**  
ADDRESS: **1140 W. 66th** IDPH LICENSE NO: **100-02865**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **FTM-1**  
MATERIAL DESCRIPTION: **mastic beneath 9x9 tan floor tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **basement bathroom, engineer's office toilet**

MATERIAL QUANTITY: **100**


MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/08/2013**

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22161** BUIDLING ID: **2180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Bass School** REVIEW DATE: **4/1/2013**  
ADDRESS: **1140 W. 66th** IDPH LICENSE NO: **100-02865**

---

HOMOGENEOUS AREA: **FTM-1**  
MATERIAL DESCRIPTION: **mastic beneath 9x9 tan floor tile**  
MATERIAL LOCATION: **basement bathroom, engineer's office toilet**  
MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Operations and Maintenance

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **04/01/2013**

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22161** BUIDLING ID: **2180**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Steven Doran**  
SCHOOL NAME: **Bass School** INSPECTION DATE: **3/8/2013**  
ADDRESS: **1140 W. 66th** IDPH LICENSE NO: **100-02865**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **FTM-2**  
MATERIAL DESCRIPTION: **12x12 light brown w/white specks floor tile mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **stair case landing-1894**  
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/08/2013**

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22161** BUIDLING ID: **2180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Bass School** REVIEW DATE: **4/1/2013**  
ADDRESS: **1140 W. 66th** IDPH LICENSE NO: **100-02865**

---

HOMOGENEOUS AREA: **FTM-2**  
MATERIAL DESCRIPTION: **12x12 light brown w/white specks floor tile mastic**  
MATERIAL LOCATION: **stair case landing-1894**  
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **04/01/2013**

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22161** BUIDLING ID: **2180**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Steven Doran**  
SCHOOL NAME: **Bass School** INSPECTION DATE: **3/8/2013**  
ADDRESS: **1140 W. 66th** IDPH LICENSE NO: **100-02865**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **FTM-3**  
MATERIAL DESCRIPTION: **12x12 brown w/white flecks floor tile mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **room 302**  
MATERIAL QUANTITY: **750** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/08/2013**



# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22161** BUIDLING ID: **2180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Bass School** REVIEW DATE: **4/1/2013**  
ADDRESS: **1140 W. 66th** IDPH LICENSE NO: **100-02865**

---

HOMOGENEOUS AREA: **FTM-3**

MATERIAL DESCRIPTION: **12x12 brown w/white flecks floor tile mastic**

MATERIAL LOCATION: **room 302**

MATERIAL QUANTITY: **750**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **04/01/2013**

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22161** BUIDLING ID: **2180**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Steven Doran**  
SCHOOL NAME: **Bass School** INSPECTION DATE: **3/8/2013**  
ADDRESS: **1140 W. 66th** IDPH LICENSE NO: **100-02865**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **FTM-4**  
MATERIAL DESCRIPTION: **12x12 white w/thin flecks floor tile mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **room 308**

MATERIAL QUANTITY: **750**


MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/08/2013**

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22161** BUIDLING ID: **2180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Bass School** REVIEW DATE: **4/1/2013**  
ADDRESS: **1140 W. 66th** IDPH LICENSE NO: **100-02865**

---

HOMOGENEOUS AREA: **FTM-4**  
MATERIAL DESCRIPTION: **12x12 white w/thin flecks floor tile mastic**  
MATERIAL LOCATION: **room 308**  
MATERIAL QUANTITY: **750** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Operations and Maintenance

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **04/01/2013**

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22161** BUIDLING ID: **2180**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Steven Doran**  
SCHOOL NAME: **Bass School** INSPECTION DATE: **3/8/2013**  
ADDRESS: **1140 W. 66th** IDPH LICENSE NO: **100-02865**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **FTM-5**  
MATERIAL DESCRIPTION: **linoleum mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **room 109, 114, 113**  
MATERIAL QUANTITY: **2400** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/08/2013**

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22161** BUIDLING ID: **2180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Bass School** REVIEW DATE: **4/1/2013**  
ADDRESS: **1140 W. 66th** IDPH LICENSE NO: **100-02865**

---

HOMOGENEOUS AREA: **FTM-5**  
MATERIAL DESCRIPTION: **linoleum mastic**  
MATERIAL LOCATION: **room 109, 114, 113**  
MATERIAL QUANTITY: **2400** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **04/01/2013**

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22161** BUIDLING ID: **2180**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Steven Doran**  
SCHOOL NAME: **Bass School** INSPECTION DATE: **3/8/2013**  
ADDRESS: **1140 W. 66th** IDPH LICENSE NO: **100-02865**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **FTM-6**  
MATERIAL DESCRIPTION: **9x9 dark tan w/brown streaks floor tile mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **room 110, 115, 212, 213, 214, 216, 208, 210,209,217, 2nd floor faculty room**  
MATERIAL QUANTITY: **7385** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/08/2013**

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22161** BUIDLING ID: **2180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Bass School** REVIEW DATE: **4/1/2013**  
ADDRESS: **1140 W. 66th** IDPH LICENSE NO: **100-02865**

---

HOMOGENEOUS AREA: **FTM-6**  
MATERIAL DESCRIPTION: **9x9 dark tan w/brown streaks floor tile mastic**  
MATERIAL LOCATION: **room 110, 115, 212, 213, 214, 216, 208, 210,209,217, 2nd floor faculty room**  
MATERIAL QUANTITY: **7385** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Operations and Maintenance

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: 04/01/2013

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22161** BUIDLING ID: **2180**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Steven Doran**  
SCHOOL NAME: **Bass School** INSPECTION DATE: **3/8/2013**  
ADDRESS: **1140 W. 66th** IDPH LICENSE NO: **100-02865**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **FTM-7**  
MATERIAL DESCRIPTION: **12x12 off wht w/brwn & gray flecks flr tile mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **room 211**

MATERIAL QUANTITY: **750**


MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/08/2013**



# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22161** BUIDLING ID: **2180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Bass School** REVIEW DATE: **4/1/2013**  
ADDRESS: **1140 W. 66th** IDPH LICENSE NO: **100-02865**

---

HOMOGENEOUS AREA: **FTM-7**  
MATERIAL DESCRIPTION: **12x12 off wht w/brwn & gray flecks flr tile mastic**  
MATERIAL LOCATION: **room 211**  
MATERIAL QUANTITY: **750** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **04/01/2013**

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22161** BUIDLING ID: **2180**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Steven Doran**  
SCHOOL NAME: **Bass School** INSPECTION DATE: **3/8/2013**  
ADDRESS: **1140 W. 66th** IDPH LICENSE NO: **100-02865**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **FTM-8**  
MATERIAL DESCRIPTION: **12x12 brown w/white specks floor tile mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **hall between 1939, 1960**

MATERIAL QUANTITY: **300**


MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/08/2013**

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22161** BUIDLING ID: **2180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Bass School** REVIEW DATE: **4/1/2013**  
ADDRESS: **1140 W. 66th** IDPH LICENSE NO: **100-02865**

---

HOMOGENEOUS AREA: **FTM-8**  
MATERIAL DESCRIPTION: **12x12 brown w/white specks floor tile mastic**  
MATERIAL LOCATION: **hall between 1939, 1960**  
MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Operations and Maintenance

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **04/01/2013**

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22161** BUIDLING ID: **2180**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Steven Doran**  
SCHOOL NAME: **Bass School** INSPECTION DATE: **3/8/2013**  
ADDRESS: **1140 W. 66th** IDPH LICENSE NO: **100-02865**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **FTM-9**  
MATERIAL DESCRIPTION: **12x12 blue floor tile mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Auditorium**  
MATERIAL QUANTITY: **2400** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 03/08/2013

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22161** BUIDLING ID: **2180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Bass School** REVIEW DATE: **4/1/2013**  
ADDRESS: **1140 W. 66th** IDPH LICENSE NO: **100-02865**

---

HOMOGENEOUS AREA: **FTM-9**  
MATERIAL DESCRIPTION: **12x12 blue floor tile mastic**  
MATERIAL LOCATION: **Auditorium**  
MATERIAL QUANTITY: **2400** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Operations and Maintenance

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **04/01/2013**

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22161** BUIDLING ID: **2180**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Steven Doran**  
SCHOOL NAME: **Bass School** INSPECTION DATE: **3/8/2013**  
ADDRESS: **1140 W. 66th** IDPH LICENSE NO: **100-02865**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **G**  
MATERIAL DESCRIPTION: **Acoustical Plaster**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:


MATERIAL LOCATION: **1960 building, rms 117,115,113,110,108,111,109, girls&boys rr, JC, stairs**

MATERIAL QUANTITY: **15000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/08/2013**

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22161** BUIDLING ID: **2180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Bass School** REVIEW DATE: **4/1/2013**  
ADDRESS: **1140 W. 66th** IDPH LICENSE NO: **100-02865**

---

HOMOGENEOUS AREA: **G**  
MATERIAL DESCRIPTION: **Acoustical Plaster**  
MATERIAL LOCATION: **1960 building, rms 117,115,113,110,108,111,109, girls&boys rr, JC, stairs**  
MATERIAL QUANTITY: **15000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY:  DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **04/01/2013**

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22161** BUIDLING ID: **2180**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Steven Doran**  
SCHOOL NAME: **Bass School** INSPECTION DATE: **3/8/2013**  
ADDRESS: **1140 W. 66th** IDPH LICENSE NO: **100-02865**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **I**  
MATERIAL DESCRIPTION: **aircell pipe**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1894 bldg - boys playroom, storage, book room, girls playroom, fan room**  
MATERIAL QUANTITY: **200** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature:



Date: **03/08/2013**



# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22161** BUIDLING ID: **2180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Bass School** REVIEW DATE: **4/1/2013**  
ADDRESS: **1140 W. 66th** IDPH LICENSE NO: **100-02865**

---

HOMOGENEOUS AREA: **I**  
MATERIAL DESCRIPTION: **aircell pipe**  
MATERIAL LOCATION: **1894 bldg - boys playroom, storage, book room, girls playroom, fan room**  
MATERIAL QUANTITY: **200** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Operations and Maintenance

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **04/01/2013**

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22161** BUIDLING ID: **2180**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Steven Doran**  
SCHOOL NAME: **Bass School** INSPECTION DATE: **3/8/2013**  
ADDRESS: **1140 W. 66th** IDPH LICENSE NO: **100-02865**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **J**  
MATERIAL DESCRIPTION: **aircell joints**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1894 bldg - boys playroom, storage, book room, girls playroom, fan room**  
MATERIAL QUANTITY: **30** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature:



Date: **03/08/2013**

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22161** BUIDLING ID: **2180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Bass School** REVIEW DATE: **4/1/2013**  
ADDRESS: **1140 W. 66th** IDPH LICENSE NO: **100-02865**

---

HOMOGENEOUS AREA: **J**  
MATERIAL DESCRIPTION: **aircell joints**  
MATERIAL LOCATION: **1894 bldg - boys playroom, storage, book room, girls playroom, fan room**  
MATERIAL QUANTITY: **30** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Operations and Maintenance

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **04/01/2013**

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22161** BUIDLING ID: **2180**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Steven Doran**  
SCHOOL NAME: **Bass School** INSPECTION DATE: **3/8/2013**  
ADDRESS: **1140 W. 66th** IDPH LICENSE NO: **100-02865**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **K**  
MATERIAL DESCRIPTION: **cardboard pipe**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1894 bldg- basement boys & girls playroom, fan room, toilets, corridors**  
MATERIAL QUANTITY: **200** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: **03/08/2013**

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22161** BUIDLING ID: **2180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Bass School** REVIEW DATE: **4/1/2013**  
ADDRESS: **1140 W. 66th** IDPH LICENSE NO: **100-02865**

---

HOMOGENEOUS AREA: **K**  
MATERIAL DESCRIPTION: **cardboard pipe**  
MATERIAL LOCATION: **1894 bldg- basement boys & girls playroom, fan room, toilets, corridors**  
MATERIAL QUANTITY: **200** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Operations and Maintenance

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **04/01/2013**

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22161** BUIDLING ID: **2180**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Steven Doran**  
SCHOOL NAME: **Bass School** INSPECTION DATE: **3/8/2013**  
ADDRESS: **1140 W. 66th** IDPH LICENSE NO: **100-02865**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **L**  
MATERIAL DESCRIPTION: **cardboard joints**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1894 bldg- basement boys & girls playroom, fan room, toilets, corridors**  
MATERIAL QUANTITY: **20** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 03/08/2013

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22161** BUIDLING ID: **2180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Bass School** REVIEW DATE: **4/1/2013**  
ADDRESS: **1140 W. 66th** IDPH LICENSE NO: **100-02865**

---

HOMOGENEOUS AREA: **L**  
MATERIAL DESCRIPTION: **cardboard joints**  
MATERIAL LOCATION: **1894 bldg- basement boys & girls playroom, fan room, toilets, corridors**  
MATERIAL QUANTITY: **20** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Operations and Maintenance

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **04/01/2013**

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22161** BUIDLING ID: **2180**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Steven Doran**  
SCHOOL NAME: **Bass School** INSPECTION DATE: **3/8/2013**  
ADDRESS: **1140 W. 66th** IDPH LICENSE NO: **100-02865**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **N**  
MATERIAL DESCRIPTION: **fiberglass joints**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:


MATERIAL LOCATION: **1894 bldg-basement boys & girls toilets & playrooms, toilets, fan room**

MATERIAL QUANTITY: **60** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **60** DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature:



Date: **03/08/2013**



# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22161** BUIDLING ID: **2180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Bass School** REVIEW DATE: **4/1/2013**  
ADDRESS: **1140 W. 66th** IDPH LICENSE NO: **100-02865**

---

HOMOGENEOUS AREA: **N**  
MATERIAL DESCRIPTION: **fiberglass joints**  
MATERIAL LOCATION: **1894 bldg-basement boys & girls toilets & playrooms, toilets, fan room**  
MATERIAL QUANTITY: **60** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY:  DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **04/01/2013**

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22161** BUIDLING ID: **2180**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Steven Doran**  
SCHOOL NAME: **Bass School** INSPECTION DATE: **3/8/2013**  
ADDRESS: **1140 W. 66th** IDPH LICENSE NO: **100-02865**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **0**  
MATERIAL DESCRIPTION: **aircell pipe lag**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1939 building- basement assembly room, platform, fan room**  
MATERIAL QUANTITY: **900** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature:



Date: **03/08/2013**

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22161** BUIDLING ID: **2180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Bass School** REVIEW DATE: **4/1/2013**  
ADDRESS: **1140 W. 66th** IDPH LICENSE NO: **100-02865**

---

HOMOGENEOUS AREA: **0**  
MATERIAL DESCRIPTION: **aircell pipe lag**  
MATERIAL LOCATION: **1939 building- basement assembly room, platform, fan room**  
MATERIAL QUANTITY: **900** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Operations and Maintenance

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **04/01/2013**

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22161** BUIDLING ID: **2180**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Steven Doran**  
SCHOOL NAME: **Bass School** INSPECTION DATE: **3/8/2013**  
ADDRESS: **1140 W. 66th** IDPH LICENSE NO: **100-02865**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **P**  
MATERIAL DESCRIPTION: **aircell pipe-1960 bldg**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**


MATERIAL LOCATION: **1960 bldg- 2nd floor stairwells (between room 217 & 210, between rooms 209 & mens bathroom)**

MATERIAL QUANTITY: **100** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature:



Date: **03/08/2013**

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22161** BUIDLING ID: **2180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Bass School** REVIEW DATE: **4/1/2013**  
ADDRESS: **1140 W. 66th** IDPH LICENSE NO: **100-02865**

---

HOMOGENEOUS AREA: **P**  
MATERIAL DESCRIPTION: **aircell pipe-1960 bldg**  
MATERIAL LOCATION: **1960 bldg- 2nd floor stairwells (between room 217 & 210, between rooms 209 & mens bathroom)**  
MATERIAL QUANTITY: **100** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Operations and Maintenance

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **04/01/2013**

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22161** BUIDLING ID: **2180**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Steven Doran**  
SCHOOL NAME: **Bass School** INSPECTION DATE: **3/8/2013**  
ADDRESS: **1140 W. 66th** IDPH LICENSE NO: **100-02865**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **Q**  
MATERIAL DESCRIPTION: **aircell joints**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1939 bldg - plaform, fan room**  
MATERIAL QUANTITY: **50** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature:



Date: **03/08/2013**

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22161** BUIDLING ID: **2180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Bass School** REVIEW DATE: **4/1/2013**  
ADDRESS: **1140 W. 66th** IDPH LICENSE NO: **100-02865**

---

HOMOGENEOUS AREA: **Q**  
MATERIAL DESCRIPTION: **aircell joints**  
MATERIAL LOCATION: **1939 bldg - plaform, fan room**  
MATERIAL QUANTITY: **50** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Operations and Maintenance

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **04/01/2013**

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22161** BUIDLING ID: **2180**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Steven Doran**  
SCHOOL NAME: **Bass School** INSPECTION DATE: **3/8/2013**  
ADDRESS: **1140 W. 66th** IDPH LICENSE NO: **100-02865**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **R**  
MATERIAL DESCRIPTION: **fiberglass joints- ABATED**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:


MATERIAL LOCATION: **1960 bldg- 2nd floor west corridor**

MATERIAL QUANTITY: **0** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature:



Date: **03/08/2013**



# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22161** BUIDLING ID: **2180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Bass School** REVIEW DATE: **4/1/2013**  
ADDRESS: **1140 W. 66th** IDPH LICENSE NO: **100-02865**

---

HOMOGENEOUS AREA: **R**  
MATERIAL DESCRIPTION: **fiberglass joints- ABATED**  
MATERIAL LOCATION: **1960 bldg- 2nd floor west corridor**  
MATERIAL QUANTITY: **0** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY:  DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **04/01/2013**

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **22161**    BUILDING ID: **2180**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Steven Doran**  
SCHOOL NAME: **Bass School**    INSPECTION DATE: **3/8/2013**  
ADDRESS: **1140 W. 66th**    IDPH LICENSE NO: **100-02865**

---

### INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **CT1**  
MATERIAL DESCRIPTION: **2 X 4 Ceiling Tile**  
MATERIAL LOCATION: **Kitchen**  
MATERIAL QUANTITY: **800**    MATERIAL UNITS: **SF**  
MATERIAL CATEGORY: **MISC**    FRIABLE: **No**  
ASBESTOS TYPE: **Assumed**  
DISTURBANCE POTENTIAL: **LOW**    CONDITION:  
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
ACCESSIBILITY: **Within Reach**    DAMAGE REASON:  
DAMAGE QUANTITY: **0**    DAMAGE REASON:  
DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_

*Steven Doran*

Date: 03/08/2013

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22161** BUILDING ID: **2180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Bass School** REVIEW DATE: **4/1/2013**  
ADDRESS: **1140 W. 66th** IDPH LICENSE NO: **100-02865**

HOMOGENEOUS AREA: **CT1**  
MATERIAL DESCRIPTION: **2 X 4 Ceiling Tile**  
MATERIAL LOCATION: **Kitchen**  
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:


COMMENTS:

Management Planner's Signature: \_\_\_\_\_




Date: 04/01/2013


KCPSS 2011-2013 Three Year A-Cad Drawings\Region 5\Bass School\Bass School First Floor.dwg



**ASBESTOS REINSPECTION KEY NOTES:**

 HA-CT1 2' x 4' Ceiling Tile Type 1

Bass School First Floor  
2013 Asbestos Reinspection



CLIENT:  
Chicago Public Schools  
125 South Clark Street,  
Chicago, Illinois 60603

PROJECT NAME:  
2013 AHERA Reinspection  
Perkins Bass Elementary School  
1140 W 66th St  
Chicago, IL 60621

SHEET NAME:  
Bass School First Floor -  
HA-CT1

INSPECTED BY:  
Steve Doran

DRAWN BY: MJW	DATE: 5/6/2013	CHECKED BY:
REVISED BY:	DATE:	CHECKED BY:
REVISED BY:	DATE:	CHECKED BY:
REVISED BY:	DATE:	CHECKED BY:

IDPH License #:100- 02865

Carnow, Conibear & Assoc., Ltd.  
Environmental Consulting Services  
600 W. Van Buren St., Suite 500, Chicago, IL 60607  
t: 312.782.4486 f: 312.782.5145  
www.ccaatd.com

CCA PROJECT NUMBER  
A320130001-309

DATE  
03/08/2013

SHEET NUMBER

**CARNOW  
CONIBEAR** HA-CT1

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **22161**    BUILDING ID: **2180**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Steven Doran**  
SCHOOL NAME: **Bass School**    INSPECTION DATE: **3/8/2013**  
ADDRESS: **1140 W. 66th**    IDPH LICENSE NO: **100-02865**

---

### INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **CT2**  
MATERIAL DESCRIPTION: **2 X 4 Ceiling Tile**  
MATERIAL LOCATION: **Room 303, 305, Art Room, Principal Office, Lunchroom**  
MATERIAL QUANTITY: **2730**    MATERIAL UNITS: **SF**  
MATERIAL CATEGORY: **MISC**    FRIABLE: **No**  
ASBESTOS TYPE: **Assumed**  
DISTURBANCE POTENTIAL: **MODERATE**    CONDITION:  
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
ACCESSIBILITY: **Within Reach**    DAMAGE REASON:  
DAMAGE QUANTITY: **0**    DAMAGE REASON:  
DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_

*Steven Doran*

Date: 03/08/2013

# Chicago Public Schools

## Carnow, Conibear and Associates 2013 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **22161**      BUILDING ID: **2180**  
CITY/STATE: **Chicago, Illinois**      MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Bass School**      REVIEW DATE: **4/1/2013**  
ADDRESS: **1140 W. 66th**      IDPH LICENSE NO: **100-02865**

HOMOGENEOUS AREA: **CT2**  
MATERIAL DESCRIPTION: **2 X 4 Ceiling Tile**  
MATERIAL LOCATION: **Room 303, 305, Art Room, Principal Office, Lunchroom**  
MATERIAL QUANTITY: **2730**      MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0**      DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:


COMMENTS:

Management Planner's Signature: \_\_\_\_\_



Date: 04/01/2013


KCPSS 2011-2013 Three Year AHERA Region 533-Bass School/Bass School First Floor.dwg



**ASBESTOS REINSPECTION KEY NOTES:**

HA-CT2 2' x 4' Ceiling Tile Type 2

Bass School First Floor  
2013 Asbestos Reinspection



CLIENT:  
Chicago Public Schools  
125 South Clark Street,  
Chicago, Illinois 60603

PROJECT NAME:  
2013 AHERA Reinspection  
Perkins Bass Elementary School  
1140 W 66th St  
Chicago, IL 60621

SHEET NAME:  
Bass School First Floor -  
HA-CT2  
INSPECTED BY:  
Steve Doran

DRAWN BY: MJW	DATE: 5/6/2013	CHECKED BY:
REVISED BY:	DATE:	CHECKED BY:
REVISED BY:	DATE:	CHECKED BY:
REVISED BY:	DATE:	CHECKED BY:


INSPECTED BY:  
Steve Doran

IDPH License #:100- 02865


Carnow, Conibear & Assoc., Ltd.  
Environmental Consulting Services  
600 W. Van Buren St., Suite 500, Chicago, IL 60607  
t: 312.782.4486 f: 312.782.5145  
www.ccaatd.com

**CARNOW  
CONIBEAR**


CCA PROJECT NUMBER  
A320130001-309  
DATE  
03/08/2013  
SHEET NUMBER  
**HA-CT2**



**ASBESTOS REINSPECTION KEY NOTES:**

 HA-CT2 2' x 4' Ceiling Tile Type 2

Bass School Third Floor  
2013 Asbestos Reinspection



K:\CPS 2011\2013 Three Year\A\Cal Drawings\Region 5\Bass School\Bass School Third Floor.dwg

CLIENT:  
Chicago Public Schools  
125 South Clark Street,  
Chicago, Illinois 60603

PROJECT NAME:  
2013 AHERA Reinspection  
Perkins Bass Elementary School  
1140 W 66th St  
Chicago, IL 60621

SHEET NAME:  
Bass School Third Floor -  
HA-CT2  
INSPECTED BY:  
Steve Doran

DRAWN BY: MJW	DATE: 5/3/2013	CHECKED BY:
REVISED BY:	DATE:	CHECKED BY:
REVISED BY:	DATE:	CHECKED BY:
REVISED BY:	DATE:	CHECKED BY:

IDPH License #:100- 02865

Carnow, Conibeare & Assoc., Ltd.  
Environmental Consulting Services  
600 W. Van Buren St., Suite 500, Chicago, IL 60607  
t: 312.782.4486 f: 312.782.5145  
www.ccailld.com

**CARNOW  
CONIBEAR**

CCA PROJECT NUMBER  
A320130001-309  
DATE  
03/08/2013  
SHEET NUMBER  
**HA-CT2**



# APPENDIX B

## Inspector and Management Planner Licenses


---

Illinois Department of  
**PUBLIC HEALTH**

**ASBESTOS  
PROFESSIONAL  
LICENSE**

ID NUMBER	ISSUED	EXPIRES
100 - 02865	5/31/2012	05/15/2013

STEVEN DORAN  
3340 MAPLE ST  
EVERGREEN PARK, IL 60805



Environmental Health

Illinois Department of  
**PUBLIC HEALTH**


**LEAD RISK  
ASSESSOR LICENSE**

LEAD ID	ISSUED	EXPIRES
001193	1/31/2013	1/31/2014

Steven Doran  
3340 Maple Street  
Evergreen Park, IL 60805



ILLINOIS LEAD PROGRAM  
Environmental Health



# Occupational Training & Supply, Inc.

7233 Adams Street • Willowbrook, IL 60527 • (630) 655-3900

## Asbestos Building Inspector Refresher

Occupational Training and Supply, Inc. certifies that

### Steven Doran


has successfully completed the 4 hour Asbestos Building Inspector Refresher Course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 10 CFR 763 Asbestos Hazard Emergency Response Act (AHERA) and TSCA Title II.

Certificate: BIR1204180683

Exam Date: 4/18/2012

Course Date: 4/18/2012

Expiration Date: 4/18/2013

  
Kathy DeSalvo, Director

2012



# Occupational Training & Supply, Inc.

7233 Adams Street • Willowbrook, IL 60527 • (630) 655-3900

## Asbestos Building Inspector Refresher

Occupational Training and Supply, Inc. certifies that

# Todd Huffer

**has successfully completed the 4 hour Asbestos Building Inspector Refresher Course** and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 10 CFR 763 Asbestos Hazard Emergency Response Act (AHERA) and TSCA Title II.

Certificate: BIR1212042317

Exam Date: 12/4/2012

Course Date: 12/4/2012


Expiration Date: 12/4/2013

Kathy DeSalvo, Director

2012



# Todd Huffer

Illinois Licensed Asbestos Inspector, Management Planner,  
Project Manager, and Air Sampling Professional

 **ASBESTOS  
PROFESSIONAL  
LICENSE**

<b>ID NUMBER</b> 100 - 09870	<b>ISSUED</b> 4/4/2012	<b>EXPIRES</b> 05/15/2013
---------------------------------	---------------------------	------------------------------

**TODD T HUFFER**  
918 N WOLCOTT UNIT 6  
CHICAGO, IL 60622

   
Environmental Health

<b>ENDORSEMENTS</b>	<b>TC EXPIRES</b>
INSPECTOR	12/8/2012
MANAGEMENT PLANNER	1/19/2013
PROJECT MANAGER	9/8/2012
AIR SAMPLING PROFESSIONAL	

**Alteration of this license shall result in legal action**  
This license issued under authority of the State of Illinois  
Department of Public Health  
This license is valid only when accompanied by a valid  
training course certificate.

**CARNOW  
CONIBEAR**



# Occupational Training & Supply, Inc.

7233 Adams Street ♦ Willowbrook, IL 60527 ♦ (630) 655-3900

## Asbestos Management Planner Refresher

*Occupational Training and Supply, Inc. certifies that*

# Todd Huffer

**has successfully completed the 4 hour Asbestos Management Planner Refresher Course**  
and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 10 CFR 763 Asbestos Hazard Emergency Response Act (AHERA) and TSCA Title II.

Certificate: MPRI302250735

Exam Date: 2/25/2013

Course Date: 2/25/2013

Expiration Date: 2/25/2014

Kathy DeSalvo, Director

2013

# APPENDIX C

## Laboratory Accreditations

---

# APPENDIX D

## Laboratory Results

---



# APPENDIX E

## Chain of Custody Forms

---

## Three-Year Reinspection Key to Terms

	<b>CODE</b>	<b>KEY</b>
<b>MATERIAL</b>		
	ACBM	Asbestos Containing Building Materials
<b>MATERIAL CATEGORY</b>		
	MISC	Miscellaneous
	SURF	Surfacing
	TSI	Thermal System Insulation
<b>MATERIAL UNITS</b>		
	LF	Linear Feet
	SF	Square Feet
	CF	Cubic Feet
<b>DAMAGE TYPE</b>		
	Loc	Localized
	Dist	Distributed