

**ILLINOIS DEPARTMENT OF PUBLIC HEALTH
AHERA THREE YEAR REINSPECTION
ASBESTOS ABATEMENT PROGRAM
SCHOOL INFORMATION FORM**

SECTION I

NAME OF SCHOOL DISTRICT: CHICAGO SCHOOL DIST 299
SCHOOL ID NUMBER: 14-016-2990-2749
SCHOOL NAME: Mount Greenwood School
ADDRESS OF SCHOOL: 10841 S Homan
CITY: Chicago, IL, 60647

DATE LAST THREE YEAR REINSPECTION WAS COMPLETED **3/15/2010**

If the address on this form is different than the address of the building, submit a written explanation.

SECTION II *(Please type or print)*

PLEASE COMPLETE THE FOLLOWING FOR YOUR THREE YEAR REINSPECTION:

DATE REINSPECTION COMPLETED: 4/15/2013 ENROLLMENT 1013
IDPH INSPECTOR LICENSE NUMBER: 100-11255
IDPH LICENSED INSPECTOR NAME (Please Print): Esteban Nunez
IDPH MP LICENSE NUMBER: 100-06325
IDPH LICENSED MANAGEMENT PLANNER NAME (Please Print): Santiago Garcia

DESIGNATED PERSON (Please Print): Ms. Lynn Crivello PHONE: (773) 553-3113



4/15/2013

Signature of Designated Person

Date

SECTION III

PLEASE COMPLETE THE FOLLOWING INFORMATION FOR ANY CHANGES WITHIN THE SCHOOL DISTRICT.

School building has been sold. Date of Sale: _____

School has been closed. Date closed: _____

School building has been demolished. Date: _____

School building is asbestos free since last reinspection: _____

Please explain in writing why the school building is now asbestos free and include the supporting documentation.

If a new school building has been added to the district, submit either an exclusionary statement or a management plan and inspection report. Include the complete name, address and city of school building.

Explain in writing if the address of the building is different than the address on this form:

THREE-YEAR REINSPECTION

CHICAGO SCHOOL DIST 299

Mount Greenwood School

10841 S Homan
Chicago, IL, 60647

Unit: 24591
Building ID: 4940

IDPH ID Number: 14-016-2990-2749

REPORT DATE:

Monday, April 15, 2013

Prepared for:

Chicago Public Schools
125 S. Clark Street
Chicago, IL 60603

Prepared by:

GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone (312) 733-6262

Fax (312) 733-5612

**DO NOT REMOVE FROM SCHOOL
REQUIRED BY FEDERAL LAW**

February 19, 2013

Mr. R. Kent Cook
Asbestos Program
Illinois Department of Public Health
525 West Jefferson Street
Springfield, Illinois 62761

Re: Chicago Public Schools - 2013 Three-Year Reinspections

Dear Mr. Cook:

GSG Consultants, Inc., Managing Environmental Consultant (MEC), conducted the Three-Year Reinspections and performed management plan updates for the Chicago Public Schools (CPS) facilities in Region 1,2,6 Elementary Schools. Please update your records with the following information.

School District: 299 Unit: 24591 Region: 06 IDPH ID: 14-016-2990-2749

School: Mount Greenwood School Building ID: 4940

Address: 10841 S Homan
Chicago, IL, 60647

Building Contact: Killeen, Jeremiah Contact Phone: 773-535-2786

Current Building Owners: Chicago Public Schools

Review Date: 4/13/2013

Inspector: Esteban Nunez Inspector IDPH License: 100-11255
Management Planner: Santiago Garcia Management Planner IDPH License: 100-06325

If you have any questions or comments, please contact us at (312) 733-6262

Sincerely,
GSG Consultants, Inc.



Santiago Garcia
100-06325

Environmental Notification to Occupants

To: Faculty, Staff and Parents
From: Chicago Public Schools
Date: February 19, 2013

RE: Mount Greenwood School, Unit 24591
10841 S Homan
Chicago, IL, 60647

Dear Faculty, Staff and Parents,

This letter is to notify you that the 2013 asbestos three year re-inspection has been completed at Mount Greenwood School , following the Federal Asbestos Hazard Emergency Response Act (AHERA), 40 CFR Part 763, Subpart E and is available for your review at the main office of the school.

Although asbestos-containing materials have been identified at Mount Greenwood School, there is no reason to believe that any threat to the health of students or staff exists at this time. CPS will continue to carefully monitor the condition of asbestos-containing materials and if conditions warrant, all appropriate steps will be taken to maintain the health and safety of all building occupants.

If you have any questions regarding this matter or require additional information, please feel free to contact Ms. Lynn Crivello, the designated Local Education Authority's Designated Person at (773) 553-3113 .

Table of Contents

- I. School and Inspection Information
- II. Executive Summary
- III. Methodology
- IV. Abatement History
- V. Reassessments and Recommendations
- VI. Conclusions

Table I: Inspector's Reinspection Findings

Table II: Management Planner's Review

APPENDICES:

- Appendix A: Assessment Sheets, Drawings and Photos
- Appendix B: Inspector and Management Planner Licenses
- Appendix C: Laboratory Accreditations
- Appendix D: Laboratory Results
- Appendix E: Chain of Custody Forms

SCHOOL AND INSPECTION INFORMATION

1. School Information

School: Mount Greenwood School Unit: 24591 Region: 06
Address: 10841 S Homan Chicago, IL, 60647
IDPH ID: 14-016-2990-2749 Building ID: 4940
Contact: Killeen, Jeremiah Phone: 773-535-2786

2. Description of Facility

Original Construction: Additional Construction:
Total Square Footage: 63500 No of Floors:
Current Occupancy: 1013

3. LEA Designated Person

Contact: Ms. Lynn Crivello Phone: (773) 553-3113
Address: 125 South Clark Street, 17th Floor
Chicago, IL 60603

4. Managing Environmental Consultant

MEC: GSG Consultants, Inc.
Contact: Arturo Saenz
Address 855 W. Adams St., Ste. 200
Phone: (312) 733-6262 Fax: (312) 733-5612

5. Inspector

Inspector Name: Esteban Nunez

Inspector IDPH license # 100-11255

Signature: 
Date: 2/19/2013

6. Management Planner

Management Planner Name: Santiago Garcia

Management Planner IDPH license # 100-06325

Signature: 
Date: 4/13/2013

7. Review Date: 4/13/2013

8. LEA Designated Person's Acknowledgement

The reinspection report and recommendations have been received by me and appropriate action will be taken by the School District.

Signature: 

Date: 4/15/2013

Name: Ms. Lynn Crivello

II. EXECUTIVE SUMMARY

GSG Consultants, Inc. was retained by the Chicago Public Schools (CPS) to perform a three-year asbestos reinspection of the Mount Greenwood School. This inspection was conducted in accordance with the United States Environmental Protection Agency (USEPA) Asbestos Hazard Emergency Response Act (AHERA) part 763.92 (b), and the ongoing Operations and Maintenance Program (O&M) originally designed in the School's Asbestos Management Plan. The purpose of this three-year reinspection is to record any condition changes in the asbestos-containing building material (ACBM) in the school since the previous three-year reinspection and the six-month periodic surveillance, to identify, assess, and include any Homogeneous Areas (HA) not identified in the Management Plan, and to recommend an appropriate response action to manage asbestos.

The inspector conducted a three-year reinspection of this facility under Illinois Department of Public Health (IDPH) school reinspection requirements and AHERA, sections 763.85 and 763.88. The main building and each addition to the main building, if constructed at different dates, were inspected separately. Laboratory accreditations are included in Appendix C, laboratory results are included in Appendix D, and chain of custody forms are included in Appendix E.

Note: During previous inspections, some of the HA(s) were identified together as 9" x 9" floor tile (FT), mastics assoc. with 9" x 9" FT, 12" x 12" FT, mastics assoc. with 12" x 12" FT, pipe insulation, etc. Some of these HA(s) have been re-identified by areas that are uniform in color, texture, construction date, application date, and general appearance.

The inspector has determined the following:

A. The following HAs have changed assessment categories for Building 4940:

- | | |
|---|-------------------------------|
| E | holding tank - mag insulation |
| F | Cardboard pipe insulation |

B. The following new homogenous areas have been identified for Building 4940:

- | | |
|----|--|
| 15 | Multi-color Carpet Mastic |
| 16 | 12" x 12" White with Black Speckles Floor Tile |
| 17 | 12" x 12" White with Black Speckles Floor Tile Mastic |
| 18 | Boiler Gaskets |
| 19 | Incinerator Fire Birck |

C. This reinspection covered only physically accessible and visible areas and materials that were identified in the LEA's management plan. The following materials were concealed and/or contained in areas that were inaccessible for sampling and have been classified as Assumed:

| | |
|------|--|
| 03AA | 9x9 Tan Streaked Floor Tile Mastic |
| 04A | 12x12 off white w/brown specks floor tile |
| 04B | 12x12 gray w/specks floor tile |
| 04BB | 12x12 gray floor tile mastic |
| 04C | 12x12 tan w/specks floor tile |
| 04CC | 12x12 tan w/specks floor tile mastic |
| 04D | 12x12 gray w/white floor tile |
| 04E | 12x12 off white w/brown specks floor tile |
| 04EE | 12x12 off white w/brown specks floor tile mastic |
| 06 | transite duct |
| 10 | 12 x 12 White with Light Blue Speckled Floor Tile |
| 10M | 12 x 12 White with Light Blue Speckled Floor Tile Mastic |
| 11 | Tan and Brown Mosaic Ceramic Tile Grout |
| 11M | Tan and Brown Mosaic Ceramic Tile Adhesive |
| 12 | Brown and White Terrazzo |
| 13 | Multi Tan Color Mosaic Ceramic Tile Grout |
| 13M | Multi Tan Color Mosaic Ceramic Tile Adhesive |
| 14 | Smooth Plaster |
| 15 | Multi-color Carpet Mastic |
| 16 | 12" x 12" White with Black Speckles Floor Tile |
| 17 | 12" x 12" White with Black Speckles Floor Tile Mastic |
| 18 | Boiler Gaskets |
| 19 | Incinerator Fire Birck |
| 7 | Smooth Plaster |
| 8 | Black and White Terrazzo |
| 9 | Tan and Brown Mosaic Ceramic Tile Grout |
| 9M | Tan and Brown Mosaic Ceramic Tile Adhesive |
| CM-1 | blue carpet mastic (Not Observed) |
| CM-2 | Blue Carpet Mastic |
| H | 1'x1' Ceiling Tile |
| I | 1'x1' Ceiling Tile Mastic |

The following areas were deemed to be inaccessible:

| | |
|------|--|
| 03AA | 9x9 Tan Streaked Floor Tile Mastic |
| 04BB | 12x12 gray floor tile mastic |
| 10M | 12 x 12 White with Light Blue Speckled Floor Tile Mastic |
| 11M | Tan and Brown Mosaic Ceramic Tile Adhesive |
| 13M | Multi Tan Color Mosaic Ceramic Tile Adhesive |

Materials were also listed as "assumed" if they were in good condition and sampling was not conducted to avoid damage.

This reinspection was conducted by Esteban Nunez, IDPH License # 100-11255. The Management Plan was updated by Santiago Garcia, IDPH License # 100-06325. Inspector and Management Planner Licenses are included in Appendix B.

III. METHODOLOGY

Tasks performed on-site included the following:

1. Review current management plan, identify HA(s) and extract appropriate information.
2. Examine and verify abatement records.
3. Touch and visually and physically reinspect and reassess the condition of all friable known or assumed ACBM.
4. Touch and visually and physically reinspect all non-friable known or assumed ACBM to determine whether these materials have become friable since the last inspection or periodic surveillance.
5. Identify any condition changes that may affect Hazard Ranking of known ACBM or Assumed ACBM, as well as any HA(s) that have become friable since the last reinspection.
6. Collect bulk samples from each newly discovered friable HA or previously assumed and submit for laboratory analysis.
7. Tabulate reinspection findings and submit for management planner review and recommendations with appropriate response actions based on the AHERA Damage Category of the ACBM.
8. Submit reinspection findings and management planner recommendations to the LEA within thirty (30) days for inclusion into the management plan.

IV. ABATEMENT HISTORY

The information collected from the existing management plan and inspection report(s) and from interviews with the school official revealed that the following asbestos abatement was conducted at the school since the previous Three year Reinspection.

Abatement Dates:

V. REASSESSMENTS AND RECOMMENDATIONS

The reassessments and recommendations are summarized in Tables I and II on the following pages. Detailed Hazard Assessment Sheets and Drawings and Photos (if applicable) are included in Appendix A.

VI. CONCLUSIONS

The Mount Greenwood School Building 4940 Three-Year reinspection has been completed and response actions have been recommended for both friable and non-friable materials. A timely execution of the response actions recommended will enable the LEA and the Designated Person(s) to effectively manage the existing ACBM.

This three-year reinspection report should be inspected in the current Management plan at the CPS Central Office, and one (1) copy should be kept at the school for use when planning any renovation and/or demolition activities in areas where ACBM has been identified. Also, periodic surveillance documentation and any summary reports from any response actions that are executed at the school should be used to update the Management Plan.

Table I
Inspector's Reinspection Findings

Chicago Public Schools

School Mount Greenwood School Unit 24591 Building ID 4940

Address 10841 S Homan Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262 Fax: (312) 733-5612

Inspector's Comments are Summarized at the End of the Report

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category | Damage Category | Damage Reason | Disturbance Potential |
|-------|--|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|-------------------------------|------------------------------------|---------------|-----------------------|
| 03A | 9x9 Tan Streaked Floor Tile | 2,600 | SF | 1937 - 2nd Floor Corridor, Principal's Office & Closet, Classrooms, 2nd Floor Landing, Clinic | CHR | MISC | N | NONE | 0 | | No | ACBM with the potential for damage | | LOW |
| 03AA | 9x9 Tan Streaked Floor Tile Mastic | 2,600 | SF | 1937 - 2nd Floor Corridor, Principal's Office & Closet, Classrooms, 2nd Floor Landing, Clinic | ASSUMED | MISC | N | NONE | 0 | | No | ACBM with the potential for damage | | LOW |
| 03B | 9x9 tan floor tile w/streaks | 5,830 | SF | 1947 - room 200, 202, 2nd floor corridor | CHR | MISC | N | LOC | 0 | | No | ACBM with the potential for damage | | LOW |
| 03BB | 9x9 tan floor tile w/streaks mastic | 5,830 | SF | 1947 - room 200, 202, 2nd floor corridor | CHR | MISC | N | NONE | 0 | | No | ACBM with the potential for damage | | LOW |
| 03C | 9x9 olive green floor tile | 1,325 | SF | 1947 - assembly hall | CHR | MISC | N | NONE | 0 | | No | ACBM with the potential for damage | | LOW |
| 03CC | 9x9 olive green floor tile mastic | 1,325 | SF | 1947 - assembly hall | CHR | MISC | N | NONE | 0 | | No | ACBM with the potential for damage | | LOW |
| 04A | 12x12 off white w/brown specks floor tile | 11,545 | SF | 1937 - rms. 104,105,107,108,110,111,113,116,210,205,206,209,211,212,213,214,teachers lounge | ASSUMED | MISC | | NONE | 0 | | No | ACBM with the potential for damage | | LOW |
| 04AA | 12x12 off white w/brown specks floor tile mastic | 11,545 | SF | 1937 - rms. 104,105,107,108,110,111,113,116,210,205,206,209,211,212,213,214,teachers lounge | CHR | MISC | N | NONE | 0 | | No | ACBM with the potential for damage | | LOW |
| 04B | 12x12 gray w/specks floor tile | 380 | SF | 1937 - Room 114 | ASSUMED | MISC | N | NONE | 0 | | No | ACBM with the potential for damage | | LOW |
| 04BB | 12x12 gray floor tile mastic | 380 | SF | 1937 - Room 114 | ASSUMED | MISC | | NONE | 0 | | No | ACBM with the potential for damage | | LOW |
| 04C | 12x12 tan w/specks floor tile | 380 | SF | 1937 - Room 114 | ASSUMED | MISC | | NONE | 0 | | No | ACBM with the potential for damage | | LOW |
| 04CC | 12x12 tan w/specks floor tile mastic | 380 | SF | 1937 - Room 114 | ASSUMED | MISC | | NONE | 0 | | No | ACBM with the potential for damage | | LOW |
| 04D | 12x12 gray w/white floor tile | 780 | SF | 1937 - Room 112 | ASSUMED | MISC | | NONE | 0 | | No | ACBM with the potential for damage | | LOW |

Chicago Public Schools

School Mount Greenwood School Unit 24591 Building ID 4940

Address 10841 S Homan Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262 Fax: (312) 733-5612

Inspector's Comments are Summarized at the End of the Report

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category | Damage Category | Damage Reason | Disturbance Potential |
|-------|--|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|-------------------------------|------------------------------------|---------------|-----------------------|
| 04DD | 12x12 gray w/white floor tile mastic | 780 | SF | 1937 - room 112 | CHR | MISC | N | None | 0 | | No | ACBM with the potential for damage | | LOW |
| 04E | 12x12 off white w/brown specks floor tile | 5,310 | SF | 1947 - rm. 102,103,104,106,20 1,203,204 | ASSUMED | MISC | | NONE | 0 | | No | ACBM with the potential for damage | | LOW |
| 04EE | 12x12 off white w/brown specks floor tile mastic | 5,310 | SF | 1947 - rm. 102,103,104,106,20 1,203,204 | ASSUMED | MISC | | NONE | 0 | | No | ACBM with the potential for damage | | LOW |
| 04F | 12x12 dark burgandy floor tile | 475 | SF | 1947 - room 101 (part of checkerboard pattern) | CHR | MISC | N | NONE | 0 | | No | ACBM with the potential for damage | | LOW |
| 04FF | 12x12 dark burgandy floor tile mastic | 475 | SF | 1947 - room 101 | CHR | MISC | N | NONE | 0 | | No | ACBM with the potential for damage | | LOW |
| 04G | 12x12 light burgandy floor tile | 475 | SF | 1947 - room 101 (part of checkerboard) | CHR | MISC | N | NONE | 0 | | No | ACBM with the potential for damage | | LOW |
| 04GG | 12x12 light burgandy floor tile mastic | 475 | SF | 1947 - room 101 | CHR | MISC | N | NONE | 0 | | No | ACBM with the potential for damage | | LOW |
| 06 | transite duct | 600 | SF | tunnel | ASSUMED | MISC | N | NONE | 0 | | No | ACBM with the potential for damage | | LOW |
| 10 | 12 x 12 White with Light Blue Speckled Floor Tile | 5,000 | SF | 1st Floor Corridor | ASSUMED | MISC | N | NONE | 0 | | No | ACBM with the potential for damage | | LOW |
| 10M | 12 x 12 White with Light Blue Speckled Floor Tile Mastic | 5,000 | SF | 1st Floor Corridor | ASSUMED | MISC | N | NONE | 0 | | No | ACBM with the potential for damage | | LOW |
| 11 | Tan and Brown Mosaic Ceramic Tile Grout | 1,500 | SF | Boys Washrooms, Vestibule and Teachers Lounge Toilet | ASSUMED | MISC | Y | NONE | 0 | | No | ACBM with the potential for damage | | LOW |
| 11M | Tan and Brown Mosaic Ceramic Tile Adhesive | 1,500 | SF | Boys Washrooms, Vestibule and Teachers Lounge Toilet | ASSUMED | MISC | N | NONE | 0 | | No | ACBM with the potential for damage | | LOW |
| 12 | Brown and White Terrazzo | 2,400 | SF | 1947 Stairs | ASSUMED | MISC | N | NONE | 0 | | No | ACBM with the potential for damage | | LOW |
| 13 | Multi Tan Color Mosaic Ceramic Tile Grout | 1,800 | SF | 1947 - Girls Washrooms and Assembly Hall, West, East Vestibules | ASSUMED | MISC | Y | NONE | 0 | | No | ACBM with the potential for damage | | LOW |
| 13M | Multi Tan Color Mosaic Ceramic Tile Adhesive | 1,800 | SF | 1947 - Girls Washrooms and Assembly Hall, West, East | ASSUMED | MISC | N | NONE | 0 | | No | ACBM with the potential for damage | | LOW |

Chicago Public Schools

School Mount Greenwood School Unit 24591 Building ID 4940

Address 10841 S Homan Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262 Fax: (312) 733-5612

Inspector's Comments are Summarized at the End of the Report

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category | Damage Category | Damage Reason | Disturbance Potential |
|-------|---|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|-------------------------------|---|---------------|-----------------------|
| | | | | Vestibules | | | | | | | | | | |
| 14 | Smooth Plaster | 60,000 | SF | 1947 Bldg - Throughout | ASSUMED | SURFACE | Y | NONE | 0 | | No | ACBM with the potential for damage | | LOW |
| 15 | Multi-color Carpet Mastic | 800 | SF | Library | ASSUMED | MISC | N | NONE | | | | ACBM with the potential for damage | | LOW |
| 16 | 12" x 12" White with Black Speckles Floor Tile | 1,400 | SF | Book Room, Store Room and Hallway Outside Office | ASSUMED | MISC | N | NONE | 0 | | | ACBM with the potential for damage | | MODERATE |
| 17 | 12" x 12" White with Black Speckles Floor Tile Mastic | 1,400 | SF | Book Room, Store Room and Hallway Outside Engineer Office | ASSUMED | MISC | N | NONE | | | | ACBM with the potential for damage | | LOW |
| 18 | Boiler Gaskets | 160 | LF | Boiler Room | ASSUMED | TSI | Y | NONE | | | | ACBM with the potential for damage | | LOW |
| 19 | Incinerator Fire Birck | 400 | SF | Coal Room | ASSUMED | MISC | N | NONE | | | | ACBM with the potential for damage | | LOW |
| 7 | Smooth Plaster | 120,000 | SF | 1937 Bldg - Throughout bldg | ASSUMED | SURFACE | N | NONE | 0 | | No | ACBM with the potential for damage | | LOW |
| 8 | Black and White Terrazzo | 2,400 | SF | 1937 Stairs | ASSUMED | MISC | N | NONE | 0 | | No | ACBM with the potential for damage | | LOW |
| 9 | Tan and Brown Mosaic Ceramic Tile Grout | 3,200 | SF | 1937 Bldg - Washrooms and Vestibules | ASSUMED | MISC | Y | NONE | 0 | | No | ACBM with the potential for damage | | LOW |
| 9M | Tan and Brown Mosaic Ceramic Tile Adhesive | 3,200 | SF | 1937 Bldg - Washrooms and Vestibules | ASSUMED | MISC | N | NONE | 0 | | No | ACBM with the potential for damage | | LOW |
| A | aircell pipe insulation | 2,800 | LF | basement | CHR | TSI | Y | DIST | 31 | | No | Damaged or significantly damaged friable thermal system insulating ACBM | 5 | LOW |
| B | aircell cementitious fittings | 360 | LF | basement | CHR | MISC | Y | NONE | 0 | | No | ACBM with the potential for damage | | LOW |
| C | aircell duct | 1,600 | LF | unexcavated area | CHR | TSI | Y | DIST | 120 | | No | Damaged or significantly damaged friable thermal system insulating ACBM | 5 | LOW |
| CM-1 | blue carpet mastic (Not Observed) | 0 | SF | 1937 - library, engineer's office & part of office | ASSUMED | MISC | N | NONE | | | No | ACBM with the potential for damage | | LOW |
| CM-2 | Blue Carpet Mastic | 450 | SF | Principal's Office & Main Office | ASSUMED | MISC | N | NONE | 0 | | No | ACBM with the potential for damage | | LOW |
| E | holding tank - mag insulation | 300 | SF | boiler room | CHR | TSI | Y | LOC | 5 | | Yes | Damaged or significantly damaged friable thermal system | 3 | LOW |

Chicago Public Schools

School Mount Greenwood School Unit 24591 Building ID 4940

Address 10841 S Homan Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262 Fax: (312) 733-5612

Inspector's Comments are Summarized at the End of the Report

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category | Damage Category | Damage Reason | Disturbance Potential |
|-------|---|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|-------------------------------|---|---------------|-----------------------|
| | | | | | | | | | | | | insulating ACBM | | |
| F | Cardboard pipe insulation | 1,300 | LF | Basement and all 1st floor toilets | CHR | TSI | Y | LOC | 5 | | Yes | Damaged or significantly damaged friable thermal system insulating ACBM | | LOW |
| G | Cardboard cementitious fittings | 150 | LF | Basement and all 1st floor toilets | CHR | MISC | Y | NONE | 0 | | No | ACBM with the potential for damage | | LOW |
| H | 1'x1' Ceiling Tile | 2,000 | SF | Auditorium | ASSUMED | MISC | Y | NONE | 0 | | No | ACBM with the potential for damage | | LOW |
| I | 1'x1' Ceiling Tile Mastic | 2,000 | SF | Auditorium | ASSUMED | MISC | N | NONE | 0 | | No | ACBM with the potential for damage | | LOW |
| J | Mudded Fittings on Fiberglass Pipe Runs | 200 | LF | Basement, Unexcavated Area, Beneath Gym, Boiler Rm. | CHR | TSI | Y | NONE | 0 | | No | ACBM with the potential for damage | | LOW |

Chicago Public Schools

School Mount Greenwood School Unit 24591 Building ID 4940
Address 10841 S Homan Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262 Fax: (312) 733-5612

Inspector's Comments are Summarized at the End of the Report

| |
|---|
| Reinspection Date 2/19/2013 |
| Inspector Name Esteban Nunez |
| 100-11255 5/15/2013 |
| Inspector's IDPH License Number / Expiration Date |

Inspector's Comments

| HA Number: | Inspector Comments: |
|------------|---------------------|
| 03A | |
| 03AA | |
| 03B | |
| 03BB | |
| 03C | |
| 03CC | |
| 04A | |
| 04AA | |
| 04B | |
| 04BB | |
| 04C | |
| 04CC | |
| 04D | |
| 04DD | |
| 04E | |
| 04EE | |
| 04F | |
| 04FF | |
| 04G | |
| 04GG | |
| 06 | |
| 10 | |
| 10M | |
| 11 | |

Chicago Public Schools

School Mount Greenwood School Unit 24591 Building ID 4940

Address 10841 S Homan Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262 Fax: (312) 733-5612

Inspector's Comments are Summarized at the End of the Report

| HA Number: | Inspector Comments: |
|------------|---------------------|
| 11M | |
| 12 | |
| 13 | |
| 13M | |
| 14 | |
| 15 | |
| 16 | |
| 17 | |
| 18 | |
| 19 | |
| 7 | |
| 8 | |
| 9 | |
| 9M | |
| A | |
| B | |
| C | |
| CM-1 | |
| CM-2 | |
| E | |
| F | |
| G | |
| H | |
| I | |
| J | Add boiler room |

Chicago Public Schools

School Mount Greenwood School **Unit** 24591 **Building ID** 4940

Address 10841 S Homan **Region** 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262 Fax: (312) 733-5612

Inspector's Comments are Summarized at the End of the Report

Table II

Management Planner's Review

Chicago Public Schools

School Mount Greenwood School

Unit 24591

Building ID 4940

Address 10841 S Homan

Chicago, IL, 60647

Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262

Fax: (312) 733-5612

Management Planner's Comments Summarized at the End of the Report

| HA Num | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Quantity | Damage Units | Damage Category | Response |
|--------|--|-------------------|----------------|--|---------------|-------------------|---------|-----------------|--------------|--------------------------------------|----------------------------|
| 03A | 9x9 Tan Streaked Floor Tile | 2,600 | SF | 1937 - 2nd Floor Corridor, Principal's Office & Closet, Classrooms, 2nd Floor Landing, Clinic | Chrysotile | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Operations and Maintenance |
| 03AA | 9x9 Tan Streaked Floor Tile Mastic | 2,600 | SF | 1937 - 2nd Floor Corridor, Principal's Office & Closet, Classrooms, 2nd Floor Landing, Clinic | Assumed | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Operations and Maintenance |
| 03B | 9x9 tan floor tile w/streaks | 5,830 | SF | 1947 - room 200, 202, 2nd floor corridor | Chrysotile | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Operations and Maintenance |
| 03BB | 9x9 tan floor tile w/streaks mastic | 5,830 | SF | 1947 - room 200, 202, 2nd floor corridor | Chrysotile | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Operations and Maintenance |
| 03C | 9x9 olive green floor tile | 1,325 | SF | 1947 - assembly hall | Chrysotile | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Operations and Maintenance |
| 03CC | 9x9 olive green floor tile mastic | 1,325 | SF | 1947 - assembly hall | Chrysotile | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Operations and Maintenance |
| 04A | 12x12 off white w/brown specks floor tile | 11,545 | SF | 1937 - rms. 104,105,107,108,110,111,113,116,210,205,206,209,211,212,213,214,teachers lounge | Assumed | MISC | | 0 | SF | 6 ACBM with the potential for damage | Operations and Maintenance |
| 04AA | 12x12 off white w/brown specks floor tile mastic | 11,545 | SF | 1937 - rms. 104,105,107,108,110,111,113,116,210,205,206,209,211,212,213,214,teachers lounge | Chrysotile | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Operations and Maintenance |
| 04B | 12x12 gray w/specks floor tile | 380 | SF | 1937 - Room 114 | Assumed | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Operations and Maintenance |
| 04BB | 12x12 gray floor tile mastic | 380 | SF | 1937 - Room 114 | Assumed | MISC | | 0 | SF | 6 ACBM with the potential for damage | Operations and Maintenance |
| 04C | 12x12 tan w/specks floor tile | 380 | SF | 1937 - Room 114 | Assumed | MISC | | 0 | SF | 6 ACBM with the potential for damage | Operations and Maintenance |
| 04CC | 12x12 tan w/specks floor tile mastic | 380 | SF | 1937 - Room 114 | Assumed | MISC | | 0 | SF | 6 ACBM with the potential for damage | Operations and Maintenance |
| 04D | 12x12 gray w/white floor tile | 780 | SF | 1937 - Room 112 | Assumed | MISC | | 0 | SF | 6 ACBM with the potential for damage | Operations and Maintenance |
| 04DD | 12x12 gray w/white floor tile mastic | 780 | SF | 1937 - room 112 | Chrysotile | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Operations and Maintenance |
| 04E | 12x12 off white w/brown specks floor tile | 5,310 | SF | 1947 - rm. 102,103,104,106,201,203,204 | Assumed | MISC | | 0 | SF | 6 ACBM with the potential for damage | Operations and Maintenance |
| 04EE | 12x12 off white w/brown specks floor tile mastic | 5,310 | SF | 1947 - rm. 102,103,104,106,201,203,204 | Assumed | MISC | | 0 | SF | 6 ACBM with the potential for damage | Operations and Maintenance |
| 04F | 12x12 dark burgandy floor tile | 475 | SF | 1947 - room 101 (part of checkerboard pattern) | Chrysotile | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Operations and Maintenance |
| 04FF | 12x12 dark burgandy floor tile mastic | 475 | SF | 1947 - room 101 | Chrysotile | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Operations and Maintenance |
| 04G | 12x12 light burgandy floor tile | 475 | SF | 1947 - room 101 (part of checkerboard) | Chrysotile | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Operations and Maintenance |
| 04GG | 12x12 light burgandy floor tile mastic | 475 | SF | 1947 - room 101 | Chrysotile | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Operations and Maintenance |
| 06 | transite duct | 600 | SF | tunnel | Assumed | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Operations and Maintenance |

Chicago Public Schools

School Mount Greenwood School

Unit 24591

Building ID 4940

Address 10841 S Homan

Chicago, IL, 60647

Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262

Fax: (312) 733-5612

Management Planner's Comments Summarized at the End of the Report

| HA Num | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Quantity | Damage Units | Damage Category | Response |
|--------|--|-------------------|----------------|---|---------------|-------------------|---------|-----------------|--------------|---|----------------------------|
| 10 | 12 x 12 White with Light Blue Speckled Floor Tile | 5,000 | SF | 1st Floor Corridor | Assumed | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Operations and Maintenance |
| 10M | 12 x 12 White with Light Blue Speckled Floor Tile Mastic | 5,000 | SF | 1st Floor Corridor | Assumed | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Operations and Maintenance |
| 11 | Tan and Brown Mosaic Ceramic Tile Grout | 1,500 | SF | Boys Washrooms, Vestibule and Teachers Lounge Toilet | Assumed | MISC | Yes | 0 | SF | 6 ACBM with the potential for damage | Operations and Maintenance |
| 11M | Tan and Brown Mosaic Ceramic Tile Adhesive | 1,500 | SF | Boys Washrooms, Vestibule and Teachers Lounge Toilet | Assumed | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Operations and Maintenance |
| 12 | Brown and White Terrazzo | 2,400 | SF | 1947 Stairs | Assumed | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Operations and Maintenance |
| 13 | Multi Tan Color Mosaic Ceramic Tile Grout | 1,800 | SF | 1947 - Girls Washrooms and Assembly Hall, West, East Vestibules | Assumed | MISC | Yes | 0 | SF | 6 ACBM with the potential for damage | Operations and Maintenance |
| 13M | Multi Tan Color Mosaic Ceramic Tile Adhesive | 1,800 | SF | 1947 - Girls Washrooms and Assembly Hall, West, East Vestibules | Assumed | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Operations and Maintenance |
| 14 | Smooth Plaster | 60,000 | SF | 1947 Bldg - Throughout | Assumed | SURFACE | Yes | 0 | SF | 6 ACBM with the potential for damage | Operations and Maintenance |
| 15 | Multi-color Carpet Mastic | 800 | SF | Library | Assumed | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Operations and Maintenance |
| 16 | 12" x 12" White with Black Speckles Floor Tile | 1,400 | SF | Book Room, Store Room and Hallway Outside Office | Assumed | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Operations and Maintenance |
| 17 | 12" x 12" White with Black Speckles Floor Tile Mastic | 1,400 | SF | Book Room, Store Room and Hallway Outside Engineer Office | Assumed | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Operations and Maintenance |
| 18 | Boiler Gaskets | 160 | LF | Boiler Room | Assumed | TSI | Yes | 0 | LF | 6 ACBM with the potential for damage | Operations and Maintenance |
| 19 | Incinerator Fire Birck | 400 | SF | Coal Room | Assumed | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Operations and Maintenance |
| 7 | Smooth Plaster | 120,000 | SF | 1937 Bldg - Throughout bldg | Assumed | SURFACE | No | 0 | SF | 6 ACBM with the potential for damage | Operations and Maintenance |
| 8 | Black and White Terrazzo | 2,400 | SF | 1937 Stairs | Assumed | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Operations and Maintenance |
| 9 | Tan and Brown Mosaic Ceramic Tile Grout | 3,200 | SF | 1937 Bldg - Washrooms and Vestibules | Assumed | MISC | Yes | 0 | SF | 6 ACBM with the potential for damage | Operations and Maintenance |
| 9M | Tan and Brown Mosaic Ceramic Tile Adhesive | 3,200 | SF | 1937 Bldg - Washrooms and Vestibules | Assumed | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Operations and Maintenance |
| A | aircell pipe insulation | 2,800 | LF | basement | Chrysotile | TSI | Yes | 31 | LF | 1 Damaged or significantly damaged friable thermal system insulating ACBM | Repair |
| B | aircell cementitious fittings | 360 | LF | basement | Chrysotile | MISC | Yes | 0 | LF | 6 ACBM with the potential for damage | Operations and Maintenance |
| C | aircell duct | 1,600 | LF | unexcavated area | Chrysotile | TSI | Yes | 120 | LF | 1 Damaged or significantly damaged friable thermal system insulating ACBM | Repair |
| CM-1 | blue carpet mastic (Not Observed) | 0 | SF | 1937 - library, engineer's office & part of office | Assumed | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Operations and Maintenance |
| CM-2 | Blue Carpet Mastic | 450 | SF | Principal's Office & Main Office | Assumed | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Operations and Maintenance |
| E | holding tank - mag insulation | 300 | SF | boiler room | Chrysotile | TSI | Yes | 5 | SF | 1 Damaged or significantly damaged friable thermal system insulating ACBM | Repair |
| F | Cardboard pipe insulation | 1,300 | LF | Basement and all 1st floor toilets | Chrysotile | TSI | Yes | 5 | LF | 1 Damaged or significantly damaged friable thermal system insulating ACBM | Repair |

Chicago Public Schools

School Mount Greenwood School

Unit 24591

Building ID 4940

Address 10841 S Homan

Chicago, IL, 60647

Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262

Fax: (312) 733-5612

Management Planner's Comments Summarized at the End of the Report

| HA Num | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Quantity | Damage Units | Damage Category | Response |
|--------|---|-------------------|----------------|---|---------------|-------------------|---------|-----------------|--------------|--------------------------------------|----------------------------|
| G | Cardboard cementitious fittings | 150 | LF | Basement and all 1st floor toilets | Chrysotile | MISC | Yes | 0 | LF | 6 ACBM with the potential for damage | Operations and Maintenance |
| H | 1'x1' Ceiling Tile | 2,000 | SF | Auditorium | Assumed | MISC | Yes | 0 | SF | 6 ACBM with the potential for damage | Operations and Maintenance |
| I | 1'x1' Ceiling Tile Mastic | 2,000 | SF | Auditorium | Assumed | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Operations and Maintenance |
| J | Mudded Fittings on Fiberglass Pipe Runs | 200 | LF | Basement, Unexcavated Area, Beneath Gym, Boiler Rm. | Chrysotile | TSI | Yes | 0 | LF | 6 ACBM with the potential for damage | Operations and Maintenance |

| HA Number | Management Comments |
|-----------|---------------------|
|-----------|---------------------|

Chicago Public Schools

School Mount Greenwood School
Address 10841 S Homan

Unit 24591
 Chicago, IL, 60647

Building ID 4940
Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262

Fax: (312) 733-5612

Management Planner's Comments Summarized at the End of the Report

| | |
|------------------------------------|-----------------|
| Review Date | 4/13/2013 |
| Manager Planner Name | Santiago Garcia |
| 100-06325 | 5/15/2013 |
| Manager IDPH License No/Expiration | |

| HA Number | Management Comments |
|-----------|---------------------|
| 03A | |
| 03AA | |
| 03B | |
| 03BB | |
| 03C | |
| 03CC | |
| 04A | |
| 04AA | |
| 04B | |
| 04BB | |
| 04C | |
| 04CC | |
| 04D | |
| 04DD | |
| 04E | |
| 04EE | |
| 04F | |
| 04FF | |
| 04G | |
| 04GG | |
| 06 | |
| 10 | |
| 10M | |
| 11 | |
| 11M | |
| 12 | |
| 13 | |

Chicago Public Schools

School Mount Greenwood School

Unit 24591

Building ID 4940

Address 10841 S Homan

Chicago, IL, 60647

Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262

Fax: (312) 733-5612

Management Planner's Comments Summarized at the End of the Report

| HA Number | Management Comments |
|-----------|---------------------|
| 13M | |
| 14 | |
| 15 | |
| 16 | |
| 17 | |
| 18 | |
| 19 | |
| 7 | |
| 8 | |
| 9 | |
| 9M | |
| A | |
| B | |
| C | |
| CM-1 | |
| CM-2 | |
| E | |
| F | |
| G | |
| H | |
| I | |
| J | |

Chicago Public Schools

GSG Consultants, Inc.

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24591** BUIDLING ID: **4940**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Esteban Nunez**
SCHOOL NAME: **Mount Greenwood School** INSPECTION DATE: **2/19/2013**
ADDRESS: **10841 S Homan** IDPH LICENSE NO: **100-11255**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **03A**
MATERIAL DESCRIPTION: **9x9 Tan Streaked Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **1937 - 2nd Floor Corridor, Principal's Office & Closet, Classrooms, 2nd Floor Landing, Clinic**

MATERIAL QUANTITY: **2600** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **02/19/2013**

Chicago Public Schools

GSG Consultants, Inc.

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24591** BUIDLING ID: **4940**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Santiago Garcia**
SCHOOL NAME: **Mount Greenwood School** REVIEW DATE: **4/13/2013**
ADDRESS: **10841 S Homan** IDPH LICENSE NO: **100-11255**

HOMOGENEOUS AREA: **03A**
MATERIAL DESCRIPTION: **9x9 Tan Streaked Floor Tile**
MATERIAL LOCATION: **1937 - 2nd Floor Corridor, Principal's Office & Closet, Classrooms, 2nd Floor Landing, Clinic**
MATERIAL QUANTITY: **2600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: 04/13/2013

Chicago Public Schools

GSG Consultants, Inc.
2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24591** BUIDLING ID: **4940**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Esteban Nunez**
SCHOOL NAME: **Mount Greenwood School** INSPECTION DATE: **2/19/2013**
ADDRESS: **10841 S Homan** IDPH LICENSE NO: **100-11255**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **03AA**
MATERIAL DESCRIPTION: **9x9 Tan Streaked Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **1937 - 2nd Floor Corridor, Principal's Office & Closet, Classrooms, 2nd Floor Landing, Clinic**

MATERIAL QUANTITY: **2600**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **02/19/2013**

Chicago Public Schools

GSG Consultants, Inc.

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24591** BUILDING ID: **4940**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Santiago Garcia**
SCHOOL NAME: **Mount Greenwood School** REVIEW DATE: **4/13/2013**
ADDRESS: **10841 S Homan** IDPH LICENSE NO: **100-11255**

HOMOGENEOUS AREA: **03AA**
MATERIAL DESCRIPTION: **9x9 Tan Streaked Floor Tile Mastic**
MATERIAL LOCATION: **1937 - 2nd Floor Corridor, Principal's Office & Closet, Classrooms, 2nd Floor Landing, Clinic**
MATERIAL QUANTITY: **2600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: 04/13/2013

Chicago Public Schools

GSG Consultants, Inc.
2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24591** BUIDLING ID: **4940**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Esteban Nunez**
SCHOOL NAME: **Mount Greenwood School** INSPECTION DATE: **2/19/2013**
ADDRESS: **10841 S Homan** IDPH LICENSE NO: **100-11255**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **03B**
MATERIAL DESCRIPTION: **9x9 tan floor tile w/streaks**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1947 - room 200, 202, 2nd floor corridor**
MATERIAL QUANTITY: **5830** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **02/19/2013**

Chicago Public Schools

GSG Consultants, Inc.

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24591** BUIDLING ID: **4940**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Santiago Garcia**
SCHOOL NAME: **Mount Greenwood School** REVIEW DATE: **4/13/2013**
ADDRESS: **10841 S Homan** IDPH LICENSE NO: **100-11255**

HOMOGENEOUS AREA: **03B**
MATERIAL DESCRIPTION: **9x9 tan floor tile w/streaks**
MATERIAL LOCATION: **1947 - room 200, 202, 2nd floor corridor**
MATERIAL QUANTITY: **5830** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature:



Date: **04/13/2013**

Chicago Public Schools

GSG Consultants, Inc.
2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24591** BUIDLING ID: **4940**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Esteban Nunez**
SCHOOL NAME: **Mount Greenwood School** INSPECTION DATE: **2/19/2013**
ADDRESS: **10841 S Homan** IDPH LICENSE NO: **100-11255**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **03BB**
MATERIAL DESCRIPTION: **9x9 tan floor tile w/streaks mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1947 - room 200, 202, 2nd floor corridor**
MATERIAL QUANTITY: **5830** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **02/19/2013**

Chicago Public Schools

GSG Consultants, Inc.

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24591** BUILDING ID: **4940**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Santiago Garcia**
SCHOOL NAME: **Mount Greenwood School** REVIEW DATE: **4/13/2013**
ADDRESS: **10841 S Homan** IDPH LICENSE NO: **100-11255**

HOMOGENEOUS AREA: **03BB**
MATERIAL DESCRIPTION: **9x9 tan floor tile w/streaks mastic**
MATERIAL LOCATION: **1947 - room 200, 202, 2nd floor corridor**
MATERIAL QUANTITY: **5830** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature:



Date: **04/13/2013**

Chicago Public Schools

GSG Consultants, Inc.
2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24591** BUIDLING ID: **4940**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Esteban Nunez**
SCHOOL NAME: **Mount Greenwood School** INSPECTION DATE: **2/19/2013**
ADDRESS: **10841 S Homan** IDPH LICENSE NO: **100-11255**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **03C**
MATERIAL DESCRIPTION: **9x9 olive green floor tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1947 - assembly hall**
MATERIAL QUANTITY: **1325** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **02/19/2013**

Chicago Public Schools

GSG Consultants, Inc.

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24591** BUIDLING ID: **4940**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Santiago Garcia**
SCHOOL NAME: **Mount Greenwood School** REVIEW DATE: **4/13/2013**
ADDRESS: **10841 S Homan** IDPH LICENSE NO: **100-11255**

HOMOGENEOUS AREA: **03C**
MATERIAL DESCRIPTION: **9x9 olive green floor tile**
MATERIAL LOCATION: **1947 - assembly hall**
MATERIAL QUANTITY: **1325** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: 04/13/2013

Chicago Public Schools

GSG Consultants, Inc.
2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24591** BUIDLING ID: **4940**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Esteban Nunez**
SCHOOL NAME: **Mount Greenwood School** INSPECTION DATE: **2/19/2013**
ADDRESS: **10841 S Homan** IDPH LICENSE NO: **100-11255**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **03CC**
MATERIAL DESCRIPTION: **9x9 olive green floor tile mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1947 - assembly hall**
MATERIAL QUANTITY: **1325** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **02/19/2013**

Chicago Public Schools

GSG Consultants, Inc.

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24591** BUIDLING ID: **4940**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Santiago Garcia**
SCHOOL NAME: **Mount Greenwood School** REVIEW DATE: **4/13/2013**
ADDRESS: **10841 S Homan** IDPH LICENSE NO: **100-11255**

HOMOGENEOUS AREA: **03CC**
MATERIAL DESCRIPTION: **9x9 olive green floor tile mastic**
MATERIAL LOCATION: **1947 - assembly hall**
MATERIAL QUANTITY: **1325** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **04/13/2013**

Chicago Public Schools

GSG Consultants, Inc.
2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 24591 BUIDLING ID: 4940
CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Esteban Nunez
SCHOOL NAME: Mount Greenwood School INSPECTION DATE: 2/19/2013
ADDRESS: 10841 S Homan IDPH LICENSE NO: 100-11255

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 04A
MATERIAL DESCRIPTION: 12x12 off white w/brown specks floor tile
HISTORICAL AHERA DAMAGE CATEGORY 6
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: Assumed FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW

MATERIAL LOCATION: 1937 - rms. 104,105,107,108,110,111,113,116,210,205,206,209,211,212,213,214,teachers lounge

MATERIAL QUANTITY: 11545

MATERIAL UNITS: SF

DAMAGE QUANTITY:

DAMAGE UNITS: SF

COMMENTS:

Inspector's Signature:



Date: 02/19/2013

Chicago Public Schools

GSG Consultants, Inc.

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24591** BUILDING ID: **4940**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Santiago Garcia**
SCHOOL NAME: **Mount Greenwood School** REVIEW DATE: **4/13/2013**
ADDRESS: **10841 S Homan** IDPH LICENSE NO: **100-11255**

HOMOGENEOUS AREA: **04A**
MATERIAL DESCRIPTION: **12x12 off white w/brown specks floor tile**
MATERIAL LOCATION: **1937 - rms. 104,105,107,108,110,111,113,116,210,205,206,209,211,212,213,214,teachers lounge**
MATERIAL QUANTITY: **11545** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: 04/13/2013

Chicago Public Schools

GSG Consultants, Inc.
2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24591** BUIDLING ID: **4940**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Esteban Nunez**
SCHOOL NAME: **Mount Greenwood School** INSPECTION DATE: **2/19/2013**
ADDRESS: **10841 S Homan** IDPH LICENSE NO: **100-11255**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **04AA**
MATERIAL DESCRIPTION: **12x12 off white w/brown specks floor tile mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **1937 - rms. 104,105,107,108,110,111,113,116,210,205,206,209,211,212,213,214,teachers lounge**

MATERIAL QUANTITY: **11545**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **02/19/2013**

Chicago Public Schools

GSG Consultants, Inc.
2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24591** BUILDING ID: **4940**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Santiago Garcia**
SCHOOL NAME: **Mount Greenwood School** REVIEW DATE: **4/13/2013**
ADDRESS: **10841 S Homan** IDPH LICENSE NO: **100-11255**

HOMOGENEOUS AREA: **04AA**
MATERIAL DESCRIPTION: **12x12 off white w/brown specks floor tile mastic**
MATERIAL LOCATION: **1937 - rms. 104,105,107,108,110,111,113,116,210,205,206,209,211,212,213,214,teachers lounge**
MATERIAL QUANTITY: **11545** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: 04/13/2013

Chicago Public Schools

GSG Consultants, Inc.
2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 24591 BUIDLING ID: 4940
CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Esteban Nunez
SCHOOL NAME: Mount Greenwood School INSPECTION DATE: 2/19/2013
ADDRESS: 10841 S Homan IDPH LICENSE NO: 100-11255

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 04B
MATERIAL DESCRIPTION: 12x12 gray w/specks floor tile
HISTORICAL AHERA DAMAGE CATEGORY 6
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: Assumed FRIABLE: No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW
MATERIAL LOCATION: 1937 - Room 114
MATERIAL QUANTITY: 380 MATERIAL UNITS: SF
DAMAGE QUANTITY: DAMAGE UNITS: SF

COMMENTS:

Inspector's Signature:



Date: 02/19/2013

Chicago Public Schools

GSG Consultants, Inc. 2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24591** BUILDING ID: **4940**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Santiago Garcia**
SCHOOL NAME: **Mount Greenwood School** REVIEW DATE: **4/13/2013**
ADDRESS: **10841 S Homan** IDPH LICENSE NO: **100-11255**

HOMOGENEOUS AREA: **04B**
MATERIAL DESCRIPTION: **12x12 gray w/specks floor tile**
MATERIAL LOCATION: **1937 - Room 114**
MATERIAL QUANTITY: **380** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: 04/13/2013

Chicago Public Schools

GSG Consultants, Inc.
2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 24591 BUIDLING ID: 4940
CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Esteban Nunez
SCHOOL NAME: Mount Greenwood School INSPECTION DATE: 2/19/2013
ADDRESS: 10841 S Homan IDPH LICENSE NO: 100-11255

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 04BB
MATERIAL DESCRIPTION: 12x12 gray floor tile mastic
HISTORICAL AHERA DAMAGE CATEGORY 6
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: Assumed FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW
MATERIAL LOCATION: 1937 - Room 114
MATERIAL QUANTITY: 380 MATERIAL UNITS: SF
DAMAGE QUANTITY: DAMAGE UNITS: SF

COMMENTS:

Inspector's Signature:



Date: 02/19/2013

Chicago Public Schools

GSG Consultants, Inc. 2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24591** BUILDING ID: **4940**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Santiago Garcia**
SCHOOL NAME: **Mount Greenwood School** REVIEW DATE: **4/13/2013**
ADDRESS: **10841 S Homan** IDPH LICENSE NO: **100-11255**

HOMOGENEOUS AREA: **04BB**
MATERIAL DESCRIPTION: **12x12 gray floor tile mastic**
MATERIAL LOCATION: **1937 - Room 114**
MATERIAL QUANTITY: **380** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: 04/13/2013

Chicago Public Schools

GSG Consultants, Inc.
2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 24591 BUIDLING ID: 4940
CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Esteban Nunez
SCHOOL NAME: Mount Greenwood School INSPECTION DATE: 2/19/2013
ADDRESS: 10841 S Homan IDPH LICENSE NO: 100-11255

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 04C
MATERIAL DESCRIPTION: 12x12 tan w/specks floor tile
HISTORICAL AHERA DAMAGE CATEGORY 6
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: Assumed FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW
MATERIAL LOCATION: 1937 - Room 114
MATERIAL QUANTITY: 380 MATERIAL UNITS: SF
DAMAGE QUANTITY: DAMAGE UNITS: SF

COMMENTS:

Inspector's Signature:



Date: 02/19/2013

Chicago Public Schools

GSG Consultants, Inc.

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24591** BUIDLING ID: **4940**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Santiago Garcia**
SCHOOL NAME: **Mount Greenwood School** REVIEW DATE: **4/13/2013**
ADDRESS: **10841 S Homan** IDPH LICENSE NO: **100-11255**

HOMOGENEOUS AREA: **04C**
MATERIAL DESCRIPTION: **12x12 tan w/specks floor tile**
MATERIAL LOCATION: **1937 - Room 114**
MATERIAL QUANTITY: **380** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: 04/13/2013

Chicago Public Schools

GSG Consultants, Inc.
2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24591** BUIDLING ID: **4940**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Esteban Nunez**
SCHOOL NAME: **Mount Greenwood School** INSPECTION DATE: **2/19/2013**
ADDRESS: **10841 S Homan** IDPH LICENSE NO: **100-11255**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **04CC**
MATERIAL DESCRIPTION: **12x12 tan w/specks floor tile mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1937 - Room 114**
MATERIAL QUANTITY: **380** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **02/19/2013**

Chicago Public Schools

GSG Consultants, Inc. 2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24591** BUILDING ID: **4940**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Santiago Garcia**
SCHOOL NAME: **Mount Greenwood School** REVIEW DATE: **4/13/2013**
ADDRESS: **10841 S Homan** IDPH LICENSE NO: **100-11255**

HOMOGENEOUS AREA: **04CC**
MATERIAL DESCRIPTION: **12x12 tan w/specks floor tile mastic**
MATERIAL LOCATION: **1937 - Room 114**
MATERIAL QUANTITY: **380** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: 04/13/2013

Chicago Public Schools

GSG Consultants, Inc.
2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 24591 BUIDLING ID: 4940
CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Esteban Nunez
SCHOOL NAME: Mount Greenwood School INSPECTION DATE: 2/19/2013
ADDRESS: 10841 S Homan IDPH LICENSE NO: 100-11255

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 04D
MATERIAL DESCRIPTION: 12x12 gray w/white floor tile
HISTORICAL AHERA DAMAGE CATEGORY 6
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: Assumed FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW
MATERIAL LOCATION: 1937 - Room 112
MATERIAL QUANTITY: 780 MATERIAL UNITS: SF
DAMAGE QUANTITY: DAMAGE UNITS: SF
COMMENTS:

Inspector's Signature:



Date: 02/19/2013

Chicago Public Schools

GSG Consultants, Inc.
2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24591** BUIDLING ID: **4940**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Santiago Garcia**
SCHOOL NAME: **Mount Greenwood School** REVIEW DATE: **4/13/2013**
ADDRESS: **10841 S Homan** IDPH LICENSE NO: **100-11255**

HOMOGENEOUS AREA: **04D**
MATERIAL DESCRIPTION: **12x12 gray w/white floor tile**
MATERIAL LOCATION: **1937 - Room 112**
MATERIAL QUANTITY: **780** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: 04/13/2013

Chicago Public Schools

GSG Consultants, Inc.
2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24591** BUIDLING ID: **4940**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Esteban Nunez**
SCHOOL NAME: **Mount Greenwood School** INSPECTION DATE: **2/19/2013**
ADDRESS: **10841 S Homan** IDPH LICENSE NO: **100-11255**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **04DD**
MATERIAL DESCRIPTION: **12x12 gray w/white floor tile mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1937 - room 112**
MATERIAL QUANTITY: **780** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **02/19/2013**

Chicago Public Schools

GSG Consultants, Inc.

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24591** BUIDLING ID: **4940**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Santiago Garcia**
SCHOOL NAME: **Mount Greenwood School** REVIEW DATE: **4/13/2013**
ADDRESS: **10841 S Homan** IDPH LICENSE NO: **100-11255**

HOMOGENEOUS AREA: **04DD**
MATERIAL DESCRIPTION: **12x12 gray w/white floor tile mastic**
MATERIAL LOCATION: **1937 - room 112**
MATERIAL QUANTITY: **780** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature:



Date: **04/13/2013**

Chicago Public Schools

GSG Consultants, Inc.
2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 24591 BUIDLING ID: 4940
CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Esteban Nunez
SCHOOL NAME: Mount Greenwood School INSPECTION DATE: 2/19/2013
ADDRESS: 10841 S Homan IDPH LICENSE NO: 100-11255

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 04E
MATERIAL DESCRIPTION: 12x12 off white w/brown specks floor tile
HISTORICAL AHERA DAMAGE CATEGORY 6
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: Assumed FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW
MATERIAL LOCATION: 1947 - rm. 102,103,104,106,201,203,204
MATERIAL QUANTITY: 5310 MATERIAL UNITS: SF
DAMAGE QUANTITY: DAMAGE UNITS: SF
COMMENTS:

Inspector's Signature:



Date: 02/19/2013

Chicago Public Schools

GSG Consultants, Inc.

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24591** BUILDING ID: **4940**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Santiago Garcia**
SCHOOL NAME: **Mount Greenwood School** REVIEW DATE: **4/13/2013**
ADDRESS: **10841 S Homan** IDPH LICENSE NO: **100-11255**

HOMOGENEOUS AREA: **04E**
MATERIAL DESCRIPTION: **12x12 off white w/brown specks floor tile**
MATERIAL LOCATION: **1947 - rm. 102,103,104,106,201,203,204**
MATERIAL QUANTITY: **5310** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **04/13/2013**

Chicago Public Schools

GSG Consultants, Inc.
2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24591** BUIDLING ID: **4940**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Esteban Nunez**
SCHOOL NAME: **Mount Greenwood School** INSPECTION DATE: **2/19/2013**
ADDRESS: **10841 S Homan** IDPH LICENSE NO: **100-11255**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **04EE**
MATERIAL DESCRIPTION: **12x12 off white w/brown specks floor tile mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1947 - rm. 102,103,104,106,201,203,204**
MATERIAL QUANTITY: **5310** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **02/19/2013**

Chicago Public Schools

GSG Consultants, Inc. 2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24591** BUILDING ID: **4940**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Santiago Garcia**
SCHOOL NAME: **Mount Greenwood School** REVIEW DATE: **4/13/2013**
ADDRESS: **10841 S Homan** IDPH LICENSE NO: **100-11255**

HOMOGENEOUS AREA: **04EE**
MATERIAL DESCRIPTION: **12x12 off white w/brown specks floor tile mastic**
MATERIAL LOCATION: **1947 - rm. 102,103,104,106,201,203,204**
MATERIAL QUANTITY: **5310** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: 04/13/2013

Chicago Public Schools

GSG Consultants, Inc.
2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24591** BUIDLING ID: **4940**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Esteban Nunez**
SCHOOL NAME: **Mount Greenwood School** INSPECTION DATE: **2/19/2013**
ADDRESS: **10841 S Homan** IDPH LICENSE NO: **100-11255**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **04F**
MATERIAL DESCRIPTION: **12x12 dark burgandy floor tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1947 - room 101 (part of checkerboard pattern)**
MATERIAL QUANTITY: **475** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **02/19/2013**

Chicago Public Schools

GSG Consultants, Inc.
2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24591** BUIDLING ID: **4940**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Santiago Garcia**
SCHOOL NAME: **Mount Greenwood School** REVIEW DATE: **4/13/2013**
ADDRESS: **10841 S Homan** IDPH LICENSE NO: **100-11255**

HOMOGENEOUS AREA: **04F**
MATERIAL DESCRIPTION: **12x12 dark burgandy floor tile**
MATERIAL LOCATION: **1947 - room 101 (part of checkerboard pattern)**
MATERIAL QUANTITY: **475** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: 04/13/2013

Chicago Public Schools

GSG Consultants, Inc.
2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24591** BUIDLING ID: **4940**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Esteban Nunez**
SCHOOL NAME: **Mount Greenwood School** INSPECTION DATE: **2/19/2013**
ADDRESS: **10841 S Homan** IDPH LICENSE NO: **100-11255**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **04FF**
MATERIAL DESCRIPTION: **12x12 dark burgandy floor tile mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1947 - room 101**
MATERIAL QUANTITY: **475** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **02/19/2013**

Chicago Public Schools

GSG Consultants, Inc.

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24591** BUIDLING ID: **4940**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Santiago Garcia**
SCHOOL NAME: **Mount Greenwood School** REVIEW DATE: **4/13/2013**
ADDRESS: **10841 S Homan** IDPH LICENSE NO: **100-11255**

HOMOGENEOUS AREA: **04FF**
MATERIAL DESCRIPTION: **12x12 dark burgandy floor tile mastic**
MATERIAL LOCATION: **1947 - room 101**
MATERIAL QUANTITY: **475** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature:



Date: **04/13/2013**

Chicago Public Schools

GSG Consultants, Inc.
2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24591** BUIDLING ID: **4940**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Esteban Nunez**
SCHOOL NAME: **Mount Greenwood School** INSPECTION DATE: **2/19/2013**
ADDRESS: **10841 S Homan** IDPH LICENSE NO: **100-11255**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **04G**
MATERIAL DESCRIPTION: **12x12 light burgandy floor tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1947 - room 101 (part of checkerboard)**
MATERIAL QUANTITY: **475** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **02/19/2013**

Chicago Public Schools

GSG Consultants, Inc.

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24591** BUIDLING ID: **4940**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Santiago Garcia**
SCHOOL NAME: **Mount Greenwood School** REVIEW DATE: **4/13/2013**
ADDRESS: **10841 S Homan** IDPH LICENSE NO: **100-11255**

HOMOGENEOUS AREA: **04G**
MATERIAL DESCRIPTION: **12x12 light burgandy floor tile**
MATERIAL LOCATION: **1947 - room 101 (part of checkerboard)**
MATERIAL QUANTITY: **475** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: 04/13/2013

Chicago Public Schools

GSG Consultants, Inc.
2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24591** BUIDLING ID: **4940**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Esteban Nunez**
SCHOOL NAME: **Mount Greenwood School** INSPECTION DATE: **2/19/2013**
ADDRESS: **10841 S Homan** IDPH LICENSE NO: **100-11255**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **04GG**
MATERIAL DESCRIPTION: **12x12 light burgandy floor tile mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1947 - room 101**
MATERIAL QUANTITY: **475** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **02/19/2013**

Chicago Public Schools

GSG Consultants, Inc.

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24591** BUIDLING ID: **4940**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Santiago Garcia**
SCHOOL NAME: **Mount Greenwood School** REVIEW DATE: **4/13/2013**
ADDRESS: **10841 S Homan** IDPH LICENSE NO: **100-11255**

HOMOGENEOUS AREA: **04GG**
MATERIAL DESCRIPTION: **12x12 light burgandy floor tile mastic**
MATERIAL LOCATION: **1947 - room 101**
MATERIAL QUANTITY: **475** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: 04/13/2013

Chicago Public Schools

GSG Consultants, Inc.
2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24591** BUIDLING ID: **4940**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Esteban Nunez**
SCHOOL NAME: **Mount Greenwood School** INSPECTION DATE: **2/19/2013**
ADDRESS: **10841 S Homan** IDPH LICENSE NO: **100-11255**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **06**
MATERIAL DESCRIPTION: **transite duct**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **tunnel**
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 02/19/2013

Chicago Public Schools

GSG Consultants, Inc.

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24591** BUIDLING ID: **4940**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Santiago Garcia**
SCHOOL NAME: **Mount Greenwood School** REVIEW DATE: **4/13/2013**
ADDRESS: **10841 S Homan** IDPH LICENSE NO: **100-11255**

HOMOGENEOUS AREA: **06**
MATERIAL DESCRIPTION: **transite duct**
MATERIAL LOCATION: **tunnel**
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **04/13/2013**

Chicago Public Schools

GSG Consultants, Inc.
2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24591** BUIDLING ID: **4940**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Esteban Nunez**
SCHOOL NAME: **Mount Greenwood School** INSPECTION DATE: **2/19/2013**
ADDRESS: **10841 S Homan** IDPH LICENSE NO: **100-11255**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **10**
MATERIAL DESCRIPTION: **12 x 12 White with Light Blue Speckled Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1st Floor Corridor**
MATERIAL QUANTITY: **5000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **02/19/2013**

Chicago Public Schools

GSG Consultants, Inc.

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24591** BUIDLING ID: **4940**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Santiago Garcia**
SCHOOL NAME: **Mount Greenwood School** REVIEW DATE: **4/13/2013**
ADDRESS: **10841 S Homan** IDPH LICENSE NO: **100-11255**

HOMOGENEOUS AREA: **10**
MATERIAL DESCRIPTION: **12 x 12 White with Light Blue Speckled Floor Tile**
MATERIAL LOCATION: **1st Floor Corridor**
MATERIAL QUANTITY: **5000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: 04/13/2013

Chicago Public Schools

GSG Consultants, Inc.
2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24591** BUIDLING ID: **4940**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Esteban Nunez**
SCHOOL NAME: **Mount Greenwood School** INSPECTION DATE: **2/19/2013**
ADDRESS: **10841 S Homan** IDPH LICENSE NO: **100-11255**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **10M**
MATERIAL DESCRIPTION: **12 x 12 White with Light Blue Speckled Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1st Floor Corridor**
MATERIAL QUANTITY: **5000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **02/19/2013**

Chicago Public Schools

GSG Consultants, Inc.

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24591** BUIDLING ID: **4940**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Santiago Garcia**
SCHOOL NAME: **Mount Greenwood School** REVIEW DATE: **4/13/2013**
ADDRESS: **10841 S Homan** IDPH LICENSE NO: **100-11255**

HOMOGENEOUS AREA: **10M**
MATERIAL DESCRIPTION: **12 x 12 White with Light Blue Speckled Floor Tile Mastic**
MATERIAL LOCATION: **1st Floor Corridor**
MATERIAL QUANTITY: **5000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **04/13/2013**

Chicago Public Schools

GSG Consultants, Inc.
2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24591** BUIDLING ID: **4940**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Esteban Nunez**
SCHOOL NAME: **Mount Greenwood School** INSPECTION DATE: **2/19/2013**
ADDRESS: **10841 S Homan** IDPH LICENSE NO: **100-11255**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **11**
MATERIAL DESCRIPTION: **Tan and Brown Mosaic Ceramic Tile Grout**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Boys Washrooms, Vestibule and Teachers Lounge Toilet**
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **02/19/2013**

Chicago Public Schools

GSG Consultants, Inc.

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24591** BUIDLING ID: **4940**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Santiago Garcia**
SCHOOL NAME: **Mount Greenwood School** REVIEW DATE: **4/13/2013**
ADDRESS: **10841 S Homan** IDPH LICENSE NO: **100-11255**

HOMOGENEOUS AREA: **11**
MATERIAL DESCRIPTION: **Tan and Brown Mosaic Ceramic Tile Grout**
MATERIAL LOCATION: **Boys Washrooms, Vestibule and Teachers Lounge Toilet**
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **04/13/2013**

Chicago Public Schools

GSG Consultants, Inc.
2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24591** BUIDLING ID: **4940**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Esteban Nunez**
SCHOOL NAME: **Mount Greenwood School** INSPECTION DATE: **2/19/2013**
ADDRESS: **10841 S Homan** IDPH LICENSE NO: **100-11255**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **11M**
MATERIAL DESCRIPTION: **Tan and Brown Mosaic Ceramic Tile Adhesive**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Boys Washrooms, Vestibule and Teachers Lounge Toilet**
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **02/19/2013**

Chicago Public Schools

GSG Consultants, Inc.

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24591** BUIDLING ID: **4940**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Santiago Garcia**
SCHOOL NAME: **Mount Greenwood School** REVIEW DATE: **4/13/2013**
ADDRESS: **10841 S Homan** IDPH LICENSE NO: **100-11255**

HOMOGENEOUS AREA: **11M**
MATERIAL DESCRIPTION: **Tan and Brown Mosaic Ceramic Tile Adhesive**
MATERIAL LOCATION: **Boys Washrooms, Vestibule and Teachers Lounge Toilet**
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: 04/13/2013

Chicago Public Schools

GSG Consultants, Inc.
2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24591** BUIDLING ID: **4940**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Esteban Nunez**
SCHOOL NAME: **Mount Greenwood School** INSPECTION DATE: **2/19/2013**
ADDRESS: **10841 S Homan** IDPH LICENSE NO: **100-11255**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **12**
MATERIAL DESCRIPTION: **Brown and White Terrazzo**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1947 Stairs**
MATERIAL QUANTITY: **2400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **02/19/2013**

Chicago Public Schools

GSG Consultants, Inc.

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24591** BUIDLING ID: **4940**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Santiago Garcia**
SCHOOL NAME: **Mount Greenwood School** REVIEW DATE: **4/13/2013**
ADDRESS: **10841 S Homan** IDPH LICENSE NO: **100-11255**

HOMOGENEOUS AREA: **12**
MATERIAL DESCRIPTION: **Brown and White Terrazzo**
MATERIAL LOCATION: **1947 Stairs**
MATERIAL QUANTITY: **2400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: 04/13/2013

Chicago Public Schools

GSG Consultants, Inc.
2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24591** BUIDLING ID: **4940**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Esteban Nunez**
SCHOOL NAME: **Mount Greenwood School** INSPECTION DATE: **2/19/2013**
ADDRESS: **10841 S Homan** IDPH LICENSE NO: **100-11255**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **13**
MATERIAL DESCRIPTION: **Multi Tan Color Mosaic Ceramic Tile Grout**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1947 - Girls Washrooms and Assembly Hall, West, East Vestibules**
MATERIAL QUANTITY: **1800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **02/19/2013**

Chicago Public Schools

GSG Consultants, Inc.

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24591** BUILDING ID: **4940**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Santiago Garcia**
SCHOOL NAME: **Mount Greenwood School** REVIEW DATE: **4/13/2013**
ADDRESS: **10841 S Homan** IDPH LICENSE NO: **100-11255**

HOMOGENEOUS AREA: **13**
MATERIAL DESCRIPTION: **Multi Tan Color Mosaic Ceramic Tile Grout**
MATERIAL LOCATION: **1947 - Girls Washrooms and Assembly Hall, West, East Vestibules**
MATERIAL QUANTITY: **1800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **04/13/2013**

Chicago Public Schools

GSG Consultants, Inc.
2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24591** BUIDLING ID: **4940**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Esteban Nunez**
SCHOOL NAME: **Mount Greenwood School** INSPECTION DATE: **2/19/2013**
ADDRESS: **10841 S Homan** IDPH LICENSE NO: **100-11255**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **13M**
MATERIAL DESCRIPTION: **Multi Tan Color Mosaic Ceramic Tile Adhesive**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1947 - Girls Washrooms and Assembly Hall, West, East Vestibules**
MATERIAL QUANTITY: **1800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **02/19/2013**

Chicago Public Schools

GSG Consultants, Inc.

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24591** BUIDLING ID: **4940**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Santiago Garcia**
SCHOOL NAME: **Mount Greenwood School** REVIEW DATE: **4/13/2013**
ADDRESS: **10841 S Homan** IDPH LICENSE NO: **100-11255**

HOMOGENEOUS AREA: **13M**
MATERIAL DESCRIPTION: **Multi Tan Color Mosaic Ceramic Tile Adhesive**
MATERIAL LOCATION: **1947 - Girls Washrooms and Assembly Hall, West, East Vestibules**
MATERIAL QUANTITY: **1800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature:



Date: **04/13/2013**

Chicago Public Schools

GSG Consultants, Inc.
2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24591** BUIDLING ID: **4940**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Esteban Nunez**
SCHOOL NAME: **Mount Greenwood School** INSPECTION DATE: **2/19/2013**
ADDRESS: **10841 S Homan** IDPH LICENSE NO: **100-11255**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **14**
MATERIAL DESCRIPTION: **Smooth Plaster**
HISTORICAL AHERA DAMAGE CATEGORY **6**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1947 Bldg - Throughout**
MATERIAL QUANTITY: **60000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____



Date: 02/19/2013

Chicago Public Schools

GSG Consultants, Inc.

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24591** BUILDING ID: **4940**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Santiago Garcia**
SCHOOL NAME: **Mount Greenwood School** REVIEW DATE: **4/13/2013**
ADDRESS: **10841 S Homan** IDPH LICENSE NO: **100-11255**

HOMOGENEOUS AREA: **14**
MATERIAL DESCRIPTION: **Smooth Plaster**
MATERIAL LOCATION: **1947 Bldg - Throughout**
MATERIAL QUANTITY: **60000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **04/13/2013**

Chicago Public Schools

GSG Consultants, Inc.
2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 24591 BUILDING ID: 4940
CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Esteban Nunez
SCHOOL NAME: Mount Greenwood School INSPECTION DATE: 2/19/2013
ADDRESS: 10841 S Homan IDPH LICENSE NO: 100-11255

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 7
MATERIAL DESCRIPTION: Smooth Plaster
HISTORICAL AHERA DAMAGE CATEGORY 6
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: Assumed FRIABLE: No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW
MATERIAL LOCATION: 1937 Bldg - Throughout bldg
MATERIAL QUANTITY: 120000 MATERIAL UNITS: SF
DAMAGE QUANTITY: DAMAGE UNITS: SF

COMMENTS:

Inspector's Signature:



Date: 02/19/2013

Chicago Public Schools

GSG Consultants, Inc.

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24591** BUILDING ID: **4940**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Santiago Garcia**
SCHOOL NAME: **Mount Greenwood School** REVIEW DATE: **4/13/2013**
ADDRESS: **10841 S Homan** IDPH LICENSE NO: **100-11255**

HOMOGENEOUS AREA: **7**
MATERIAL DESCRIPTION: **Smooth Plaster**
MATERIAL LOCATION: **1937 Bldg - Throughout bldg**
MATERIAL QUANTITY: **120000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: 04/13/2013

Chicago Public Schools

GSG Consultants, Inc.
2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24591** BUIDLING ID: **4940**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Esteban Nunez**
SCHOOL NAME: **Mount Greenwood School** INSPECTION DATE: **2/19/2013**
ADDRESS: **10841 S Homan** IDPH LICENSE NO: **100-11255**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **8**
MATERIAL DESCRIPTION: **Black and White Terrazzo**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1937 Stairs**
MATERIAL QUANTITY: **2400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **02/19/2013**

Chicago Public Schools

GSG Consultants, Inc.

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24591** BUIDLING ID: **4940**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Santiago Garcia**
SCHOOL NAME: **Mount Greenwood School** REVIEW DATE: **4/13/2013**
ADDRESS: **10841 S Homan** IDPH LICENSE NO: **100-11255**

HOMOGENEOUS AREA: **8**
MATERIAL DESCRIPTION: **Black and White Terrazzo**
MATERIAL LOCATION: **1937 Stairs**
MATERIAL QUANTITY: **2400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature:



Date: **04/13/2013**

Chicago Public Schools

GSG Consultants, Inc.
2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24591** BUIDLING ID: **4940**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Esteban Nunez**
SCHOOL NAME: **Mount Greenwood School** INSPECTION DATE: **2/19/2013**
ADDRESS: **10841 S Homan** IDPH LICENSE NO: **100-11255**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **9**
MATERIAL DESCRIPTION: **Tan and Brown Mosaic Ceramic Tile Grout**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1937 Bldg - Washrooms and Vestibules**
MATERIAL QUANTITY: **3200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **02/19/2013**

Chicago Public Schools

GSG Consultants, Inc.

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24591** BUIDLING ID: **4940**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Santiago Garcia**
SCHOOL NAME: **Mount Greenwood School** REVIEW DATE: **4/13/2013**
ADDRESS: **10841 S Homan** IDPH LICENSE NO: **100-11255**

HOMOGENEOUS AREA: **9**
MATERIAL DESCRIPTION: **Tan and Brown Mosaic Ceramic Tile Grout**
MATERIAL LOCATION: **1937 Bldg - Washrooms and Vestibules**
MATERIAL QUANTITY: **3200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: 04/13/2013

Chicago Public Schools

GSG Consultants, Inc.
2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24591** BUIDLING ID: **4940**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Esteban Nunez**
SCHOOL NAME: **Mount Greenwood School** INSPECTION DATE: **2/19/2013**
ADDRESS: **10841 S Homan** IDPH LICENSE NO: **100-11255**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **9M**
MATERIAL DESCRIPTION: **Tan and Brown Mosaic Ceramic Tile Adhesive**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1937 Bldg - Washrooms and Vestibules**
MATERIAL QUANTITY: **3200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **02/19/2013**

Chicago Public Schools

GSG Consultants, Inc.

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24591** BUIDLING ID: **4940**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Santiago Garcia**
SCHOOL NAME: **Mount Greenwood School** REVIEW DATE: **4/13/2013**
ADDRESS: **10841 S Homan** IDPH LICENSE NO: **100-11255**

HOMOGENEOUS AREA: **9M**
MATERIAL DESCRIPTION: **Tan and Brown Mosaic Ceramic Tile Adhesive**
MATERIAL LOCATION: **1937 Bldg - Washrooms and Vestibules**
MATERIAL QUANTITY: **3200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: 04/13/2013

Chicago Public Schools

GSG Consultants, Inc.
2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24591** BUILDING ID: **4940**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Esteban Nunez**
SCHOOL NAME: **Mount Greenwood School** INSPECTION DATE: **2/19/2013**
ADDRESS: **10841 S Homan** IDPH LICENSE NO: **100-11255**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **A**
MATERIAL DESCRIPTION: **aircell pipe insulation**
HISTORICAL AHERA DAMAGE CATEGORY: **1 Damaged or significantly damaged friable thermal system insulating ACBM**
HISTORICAL DAMAGE REASON: **Physical Damage**
HISTORICAL RESPONSE ACTION: **Repair Operations and Maintenance**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **1. Damaged or significantly damaged friable thermal system insulating ACBM**

DAMAGE REASON: **Physical Damage**
DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **basement**
MATERIAL QUANTITY: **2800** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **LF** DAMAGE UNITS: **LF**
COMMENTS:

Inspector's Signature:



Date: **02/19/2013**

Chicago Public Schools

GSG Consultants, Inc.
2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24591** BUIDLING ID: **4940**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Santiago Garcia**
SCHOOL NAME: **Mount Greenwood School** REVIEW DATE: **4/13/2013**
ADDRESS: **10841 S Homan** IDPH LICENSE NO: **100-11255**

HOMOGENEOUS AREA: **A**
MATERIAL DESCRIPTION: **aircell pipe insulation**
MATERIAL LOCATION: **basement**
MATERIAL QUANTITY: **2800** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **31** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Repair
Operations and Maintenance**

Comments:

Management Planner's Signature: _____



Date: **04/13/2013**

Chicago Public Schools

GSG Consultants, Inc.
2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24591** BUIDLING ID: **4940**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Esteban Nunez**
SCHOOL NAME: **Mount Greenwood School** INSPECTION DATE: **2/19/2013**
ADDRESS: **10841 S Homan** IDPH LICENSE NO: **100-11255**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **B**
MATERIAL DESCRIPTION: **aircell cementitious fittings**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **basement**
MATERIAL QUANTITY: **360** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature:



Date: **02/19/2013**

Chicago Public Schools

GSG Consultants, Inc.
2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24591** BUIDLING ID: **4940**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Santiago Garcia**
SCHOOL NAME: **Mount Greenwood School** REVIEW DATE: **4/13/2013**
ADDRESS: **10841 S Homan** IDPH LICENSE NO: **100-11255**

HOMOGENEOUS AREA: **B**
MATERIAL DESCRIPTION: **aircell cementitious fittings**
MATERIAL LOCATION: **basement**
MATERIAL QUANTITY: **360** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: 04/13/2013

Chicago Public Schools

GSG Consultants, Inc.
2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24591** BUILDING ID: **4940**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Esteban Nunez**
SCHOOL NAME: **Mount Greenwood School** INSPECTION DATE: **2/19/2013**
ADDRESS: **10841 S Homan** IDPH LICENSE NO: **100-11255**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **C**
MATERIAL DESCRIPTION: **aircell duct**
HISTORICAL AHERA DAMAGE CATEGORY **1 Damaged or significantly damaged friable thermal system insulating ACBM**
HISTORICAL DAMAGE REASON: **Physical Damage**
HISTORICAL RESPONSE ACTION: **Repair Operations and Maintenance**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **1. Damaged or significantly damaged friable thermal system insulating ACBM**

DAMAGE REASON: **Physical Damage**
DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **unexcavated area**
MATERIAL QUANTITY: **1600** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **1600** DAMAGE UNITS: **LF**
COMMENTS:

Inspector's Signature:



Date: **02/19/2013**

Chicago Public Schools

GSG Consultants, Inc. 2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24591** BUIDLING ID: **4940**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Santiago Garcia**
SCHOOL NAME: **Mount Greenwood School** REVIEW DATE: **4/13/2013**
ADDRESS: **10841 S Homan** IDPH LICENSE NO: **100-11255**

HOMOGENEOUS AREA: **C**
MATERIAL DESCRIPTION: **aircell duct**
MATERIAL LOCATION: **unexcavated area**
MATERIAL QUANTITY: **1600** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **120** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Repair
Operations and Maintenance**

Comments:

Management Planner's Signature: _____



Date: **04/13/2013**

Chicago Public Schools

GSG Consultants, Inc.
2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24591** BUIDLING ID: **4940**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Esteban Nunez**
SCHOOL NAME: **Mount Greenwood School** INSPECTION DATE: **2/19/2013**
ADDRESS: **10841 S Homan** IDPH LICENSE NO: **100-11255**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **CM-1**
MATERIAL DESCRIPTION: **blue carpet mastic (Not Observed)**
HISTORICAL AHERA DAMAGE CATEGORY **6**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1937 - library, engineer's office & part of office**
MATERIAL QUANTITY: **0** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **02/19/2013**

Chicago Public Schools

GSG Consultants, Inc.

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24591** BUILDING ID: **4940**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Santiago Garcia**
SCHOOL NAME: **Mount Greenwood School** REVIEW DATE: **4/13/2013**
ADDRESS: **10841 S Homan** IDPH LICENSE NO: **100-11255**

HOMOGENEOUS AREA: **CM-1**
MATERIAL DESCRIPTION: **blue carpet mastic (Not Observed)**
MATERIAL LOCATION: **1937 - library, engineer's office & part of office**
MATERIAL QUANTITY: **0** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: 04/13/2013

Chicago Public Schools

GSG Consultants, Inc.
2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24591** BUIDLING ID: **4940**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Esteban Nunez**
SCHOOL NAME: **Mount Greenwood School** INSPECTION DATE: **2/19/2013**
ADDRESS: **10841 S Homan** IDPH LICENSE NO: **100-11255**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **CM-2**
MATERIAL DESCRIPTION: **Blue Carpet Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Principal's Office & Main Office**
MATERIAL QUANTITY: **450** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **02/19/2013**

Chicago Public Schools

GSG Consultants, Inc.

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24591** BUIDLING ID: **4940**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Santiago Garcia**
SCHOOL NAME: **Mount Greenwood School** REVIEW DATE: **4/13/2013**
ADDRESS: **10841 S Homan** IDPH LICENSE NO: **100-11255**

HOMOGENEOUS AREA: **CM-2**
MATERIAL DESCRIPTION: **Blue Carpet Mastic**
MATERIAL LOCATION: **Principal's Office & Main Office**
MATERIAL QUANTITY: **450** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: 04/13/2013

Chicago Public Schools

GSG Consultants, Inc.
2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24591** BUIDLING ID: **4940**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Esteban Nunez**
SCHOOL NAME: **Mount Greenwood School** INSPECTION DATE: **2/19/2013**
ADDRESS: **10841 S Homan** IDPH LICENSE NO: **100-11255**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **E**
MATERIAL DESCRIPTION: **holding tank - mag insulation**
HISTORICAL AHERA DAMAGE CATEGORY **1 Damaged or significantly damaged friable thermal system insulating ACBM**
HISTORICAL DAMAGE REASON: **Deterioration**
HISTORICAL RESPONSE ACTION: **Repair Operations and Maintenance**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **1. Damaged or significantly damaged friable thermal system insulating ACBM**

DAMAGE REASON: **Deterioration**
DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **boiler room**
MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature:



Date: **02/19/2013**

Chicago Public Schools

GSG Consultants, Inc.

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24591** BUIDLING ID: **4940**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Santiago Garcia**
SCHOOL NAME: **Mount Greenwood School** REVIEW DATE: **4/13/2013**
ADDRESS: **10841 S Homan** IDPH LICENSE NO: **100-11255**

HOMOGENEOUS AREA: **E**
MATERIAL DESCRIPTION: **holding tank - mag insulation**
MATERIAL LOCATION: **boiler room**
MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **5** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Repair
Operations and Maintenance**

Comments:

Management Planner's Signature: _____



Date: **04/13/2013**

Chicago Public Schools

GSG Consultants, Inc.
2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24591** BUILDING ID: **4940**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Esteban Nunez**
SCHOOL NAME: **Mount Greenwood School** INSPECTION DATE: **2/19/2013**
ADDRESS: **10841 S Homan** IDPH LICENSE NO: **100-11255**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **F**
MATERIAL DESCRIPTION: **Cardboard pipe insulation**
HISTORICAL AHERA DAMAGE CATEGORY: **1 Damaged or significantly damaged friable thermal system insulating ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Repair Operations and Maintenance**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and its condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **1. Damaged or significantly damaged friable thermal system insulating ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Basement and all 1st floor toilets**

MATERIAL QUANTITY: **1300**

MATERIAL UNITS: **LF**

DAMAGE QUANTITY:

DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature:



Date: **02/19/2013**

Chicago Public Schools

GSG Consultants, Inc.
2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24591** BUIDLING ID: **4940**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Santiago Garcia**
SCHOOL NAME: **Mount Greenwood School** REVIEW DATE: **4/13/2013**
ADDRESS: **10841 S Homan** IDPH LICENSE NO: **100-11255**

HOMOGENEOUS AREA: **F**
MATERIAL DESCRIPTION: **Cardboard pipe insulation**
MATERIAL LOCATION: **Basement and all 1st floor toilets**
MATERIAL QUANTITY: **1300** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **5** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Repair
Operations and Maintenance**

Comments:

Management Planner's Signature: _____



Date: **04/13/2013**

Chicago Public Schools

GSG Consultants, Inc.
2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24591** BUIDLING ID: **4940**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Esteban Nunez**
SCHOOL NAME: **Mount Greenwood School** INSPECTION DATE: **2/19/2013**
ADDRESS: **10841 S Homan** IDPH LICENSE NO: **100-11255**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **G**
MATERIAL DESCRIPTION: **Cardboard cementitious fittings**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Basement and all 1st floor toilets**
MATERIAL QUANTITY: **150** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: _____



Date: 02/19/2013

Chicago Public Schools

GSG Consultants, Inc.

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24591** BUIDLING ID: **4940**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Santiago Garcia**
SCHOOL NAME: **Mount Greenwood School** REVIEW DATE: **4/13/2013**
ADDRESS: **10841 S Homan** IDPH LICENSE NO: **100-11255**

HOMOGENEOUS AREA: **G**
MATERIAL DESCRIPTION: **Cardboard cementitious fittings**
MATERIAL LOCATION: **Basement and all 1st floor toilets**
MATERIAL QUANTITY: **150** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: 04/13/2013

Chicago Public Schools

GSG Consultants, Inc.
2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24591** BUIDLING ID: **4940**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Esteban Nunez**
SCHOOL NAME: **Mount Greenwood School** INSPECTION DATE: **2/19/2013**
ADDRESS: **10841 S Homan** IDPH LICENSE NO: **100-11255**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **H**
MATERIAL DESCRIPTION: **1'x1' Ceiling Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Auditorium**
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 02/19/2013

Chicago Public Schools

GSG Consultants, Inc.
2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24591** BUIDLING ID: **4940**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Santiago Garcia**
SCHOOL NAME: **Mount Greenwood School** REVIEW DATE: **4/13/2013**
ADDRESS: **10841 S Homan** IDPH LICENSE NO: **100-11255**

HOMOGENEOUS AREA: **H**
MATERIAL DESCRIPTION: **1'x1' Ceiling Tile**
MATERIAL LOCATION: **Auditorium**
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: 04/13/2013

Chicago Public Schools

GSG Consultants, Inc.
2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24591** BUIDLING ID: **4940**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Esteban Nunez**
SCHOOL NAME: **Mount Greenwood School** INSPECTION DATE: **2/19/2013**
ADDRESS: **10841 S Homan** IDPH LICENSE NO: **100-11255**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **I**
MATERIAL DESCRIPTION: **1'x1' Ceiling Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Auditorium**
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **02/19/2013**

Chicago Public Schools

GSG Consultants, Inc.
2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24591** BUILDING ID: **4940**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Santiago Garcia**
SCHOOL NAME: **Mount Greenwood School** REVIEW DATE: **4/13/2013**
ADDRESS: **10841 S Homan** IDPH LICENSE NO: **100-11255**

HOMOGENEOUS AREA: **I**
MATERIAL DESCRIPTION: **1'x1' Ceiling Tile Mastic**
MATERIAL LOCATION: **Auditorium**
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **04/13/2013**

Chicago Public Schools

GSG Consultants, Inc.
2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24591** BUIDLING ID: **4940**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Esteban Nunez**
SCHOOL NAME: **Mount Greenwood School** INSPECTION DATE: **2/19/2013**
ADDRESS: **10841 S Homan** IDPH LICENSE NO: **100-11255**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **J**
MATERIAL DESCRIPTION: **Mudded Fittings on Fiberglass Pipe Runs**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Basement, Unexcavated Area, Beneath Gym, Boiler Rm.**
MATERIAL QUANTITY: **200** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: DAMAGE UNITS: **LF**
COMMENTS: **Add boiler room**

Inspector's Signature: _____



Date: 02/19/2013

Chicago Public Schools

GSG Consultants, Inc.

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24591** BUIDLING ID: **4940**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Santiago Garcia**
SCHOOL NAME: **Mount Greenwood School** REVIEW DATE: **4/13/2013**
ADDRESS: **10841 S Homan** IDPH LICENSE NO: **100-11255**

HOMOGENEOUS AREA: **J**
MATERIAL DESCRIPTION: **Mudded Fittings on Fiberglass Pipe Runs**
MATERIAL LOCATION: **Basement, Unexcavated Area, Beneath Gym, Boiler Rm.**
MATERIAL QUANTITY: **200** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: 04/13/2013

Chicago Public Schools

GSG Consultants, Inc.
2013 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24591** BUILDING ID: **4940**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Esteban Nunez**
SCHOOL NAME: **Mount Greenwood School** INSPECTION DATE: **2/19/2013**
ADDRESS: **10841 S Homan** IDPH LICENSE NO: **100-11255**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **18**
MATERIAL DESCRIPTION: **Boiler Gaskets**
MATERIAL LOCATION: **Boiler Room**
MATERIAL QUANTITY: **160** MATERIAL UNITS: **LF**
MATERIAL CATEGORY: **TSI** FRIABLE: **Yes**
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **LOW** CONDITION:
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
ACCESSIBILITY: **Within Reach** DAMAGE REASON:
DAMAGE QUANTITY: DAMAGE REASON:
DAMAGE UNITS: **LF**
COMMENTS:

Inspector's Signature: _____



Date: 02/19/2013

Chicago Public Schools

GSG Consultants, Inc. 2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24591** BUILDING ID: **4940**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Santiago Garcia**
SCHOOL NAME: **Mount Greenwood School** REVIEW DATE: **4/13/2013**
ADDRESS: **10841 S Homan** IDPH LICENSE NO: **100-11255**

HOMOGENEOUS AREA: **18**

MATERIAL DESCRIPTION: **Boiler Gaskets**

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY: **160**

MATERIAL UNITS: **LF**

DAMAGE QUANTITY:

DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:


COMMENTS:

Management Planner's Signature:  Date: **04/13/2013**

DIST. 18

HA#18 Boiler Gaskets

NEW ADDITION 1947



BASEMENT PLAN
SCALE 1/8" = 1'-0"



MOUNT GREENWOOD ELEMENTARY SCHOOL
10851 S. HOMAN AVENUE

BOARD OF EDUCATION
CHICAGO ILL.

CLASS : SCHOOL
CONSTRUCTION : FIREPROOF
STORIES : 2
HEIGHT : 29'-4"

2/4

Chicago Public Schools

GSG Consultants, Inc.
2013 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24591** BUILDING ID: **4940**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Esteban Nunez**
SCHOOL NAME: **Mount Greenwood School** INSPECTION DATE: **2/19/2013**
ADDRESS: **10841 S Homan** IDPH LICENSE NO: **100-11255**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **16**
MATERIAL DESCRIPTION: **12" x 12" White with Black Speckles Floor Tile**
MATERIAL LOCATION: **Book Room, Store Room and Hallway Outside Office**
MATERIAL QUANTITY: **1400** MATERIAL UNITS: **SF**
MATERIAL CATEGORY: **MISC** FRIABLE: **No**
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **MODERATE** CONDITION:
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
ACCESSIBILITY: **Within Reach** DAMAGE REASON:
DAMAGE QUANTITY: **0** DAMAGE REASON:
DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____



Date: 02/19/2013

Chicago Public Schools

GSG Consultants, Inc.
2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24591** BUILDING ID: **4940**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Santiago Garcia**
SCHOOL NAME: **Mount Greenwood School** REVIEW DATE: **4/13/2013**
ADDRESS: **10841 S Homan** IDPH LICENSE NO: **100-11255**

HOMOGENEOUS AREA: **16**
MATERIAL DESCRIPTION: **12" x 12" White with Black Speckles Floor Tile**
MATERIAL LOCATION: **Book Room, Store Room and Hallway Outside Office**
MATERIAL QUANTITY: **1400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.


The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:  Date: 04/13/2013

HA# 16+17 White w/Black Spec VFT + Mastic

NEW ADDITION 1947



FIRST FLOOR PLAN
SCALE 1" = 50'-0"

MOUNT GREENWOOD ELEMENTARY SCHOOL
10851 S. HOMAN AVENUE

BOARD OF EDUCATION
CHICAGO ILL.

3/4

CLASS : SCHOOL
CONSTRUCTION : FIREPROOF
STORIES : 2
HEIGHT : 29'-4"

Chicago Public Schools

GSG Consultants, Inc.
2013 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24591** BUILDING ID: **4940**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Esteban Nunez**
SCHOOL NAME: **Mount Greenwood School** INSPECTION DATE: **2/19/2013**
ADDRESS: **10841 S Homan** IDPH LICENSE NO: **100-11255**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **19**
MATERIAL DESCRIPTION: **Incinerator Fire Birck**
MATERIAL LOCATION: **Coal Room**
MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**
MATERIAL CATEGORY: **MISC** FRIABLE: **No**
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **LOW** CONDITION:
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
ACCESSIBILITY: **Within Reach** DAMAGE REASON:
DAMAGE QUANTITY: DAMAGE REASON:
DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature:



Date: **02/19/2013**

Chicago Public Schools

GSG Consultants, Inc. 2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24591** BUILDING ID: **4940**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Santiago Garcia**
SCHOOL NAME: **Mount Greenwood School** REVIEW DATE: **4/13/2013**
ADDRESS: **10841 S Homan** IDPH LICENSE NO: **100-11255**

HOMOGENEOUS AREA: **19**
MATERIAL DESCRIPTION: **Incinerator Fire Birck**
MATERIAL LOCATION: **Coal Room**
MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.


The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:  Date: **04/13/2013**

HA# 19 Incinerator Fire
Bricks

NEW ADDITION 1947



BASEMENT PLAN
SCALE 1" = 50'-0"



DIST. 18

MOUNT GREENWOOD ELEMENTARY SCHOOL
10851 S. HOMAN AVENUE

CLASS : SCHOOL
CONSTRUCTION : FIREPROOF
STORIES : 2
HEIGHT : 29'-4"

BOARD OF EDUCATION
CHICAGO ILL.

2/4

Chicago Public Schools

GSG Consultants, Inc.
2013 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24591** BUILDING ID: **4940**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Esteban Nunez**
SCHOOL NAME: **Mount Greenwood School** INSPECTION DATE: **2/19/2013**
ADDRESS: **10841 S Homan** IDPH LICENSE NO: **100-11255**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **17**
MATERIAL DESCRIPTION: **12" x 12" White with Black Speckles Floor Tile Mastic**
MATERIAL LOCATION: **Book Room, Store Room and Hallway Outside Engineer Office**
MATERIAL QUANTITY: **1400** MATERIAL UNITS: **SF**
MATERIAL CATEGORY: **MISC** FRIABLE: **No**
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **LOW** CONDITION:
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
ACCESSIBILITY: **Within Reach** DAMAGE REASON:
DAMAGE QUANTITY: DAMAGE REASON:
DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____



Date: 02/19/2013

Chicago Public Schools

GSG Consultants, Inc. 2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24591** BUILDING ID: **4940**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Santiago Garcia**
SCHOOL NAME: **Mount Greenwood School** REVIEW DATE: **4/13/2013**
ADDRESS: **10841 S Homan** IDPH LICENSE NO: **100-11255**

HOMOGENEOUS AREA: **17**
MATERIAL DESCRIPTION: **12" x 12" White with Black Speckles Floor Tile Mastic**
MATERIAL LOCATION: **Book Room, Store Room and Hallway Outside Engineer Office**
MATERIAL QUANTITY: **1400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.


The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:  Date: **04/13/2013**

HA# 16+17 White w/Black Spec VFT + Mastic

NEW ADDITION 1947



FIRST FLOOR PLAN

SCALE 1" = 50'-0"

MOUNT GREENWOOD ELEMENTARY SCHOOL
10851 S. HOMAN AVENUE

BOARD OF EDUCATION
CHICAGO ILL.

CLASS : SCHOOL
CONSTRUCTION : FIREPROOF
STORIES : 2
HEIGHT : 29'-4"

3/4

Chicago Public Schools

GSG Consultants, Inc.
2013 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24591** BUILDING ID: **4940**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Esteban Nunez**
SCHOOL NAME: **Mount Greenwood School** INSPECTION DATE: **2/19/2013**
ADDRESS: **10841 S Homan** IDPH LICENSE NO: **100-11255**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **15**
MATERIAL DESCRIPTION: **Multi-color Carpet Mastic**
MATERIAL LOCATION: **Library**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**
MATERIAL CATEGORY: **MISC** FRIABLE: **No**
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **LOW** CONDITION:
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
ACCESSIBILITY: **Within Reach** DAMAGE REASON:
DAMAGE QUANTITY: DAMAGE REASON:
DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature:



Date: **02/19/2013**

Chicago Public Schools

GSG Consultants, Inc. 2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24591** BUILDING ID: **4940**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Santiago Garcia**
SCHOOL NAME: **Mount Greenwood School** REVIEW DATE: **4/13/2013**
ADDRESS: **10841 S Homan** IDPH LICENSE NO: **100-11255**

HOMOGENEOUS AREA: **15**

MATERIAL DESCRIPTION: **Multi-color Carpet Mastic**

MATERIAL LOCATION: **Library**

MATERIAL QUANTITY: **800**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:  Date: **04/13/2013**

NEW ADDITION 1947



SECOND FLOOR PLAN
SCALE 1/8" = 1'-0"

HAIR IS Milk Color Carpet Mastic



MOUNT GREENWOOD ELEMENTARY SCHOOL
10851 S. HOMAN AVENUE

BOARD OF EDUCATION
CHICAGO ILL

CLASS: SCHOOL
CONSTRUCTION: FIREPROOF
STORIES: 2
HEIGHT: 27'-4"

F. J. N. SEPT-11-1947

44

APPENDIX B

Inspector and Management Planner Licenses

CERTIFICATE OF ACHIEVEMENT ASBESTOS ABATEMENT

Accredited by the Illinois Department of Public Health

This is to certify that ESTEBAN NUNEZ
has completed the ASBESTOS INSPECTOR'S REFRESHER course and successfully passed the
examination on 02/16/2013 with a minimum score of 70% or better. Training was in accordance
with U.S. E.P.A. 40 CFR 763 Subpart E, Appendix C, Asbestos Containing Materials in Schools:
Model Accreditation Plan, TSCA II, Authorized by both AHERA & ASHARA.



Nicholas J. Penoff

02/16/2013

Course Dates: _____

02/16/2014

Expires: _____

1302BIR28

Certificate Number: _____

Phone Number: (312) 491-0081

Director of Training

Nicholas J. Penoff

Doctor of Public Health

FORM # A-010



**ASBESTOS
PROFESSIONAL
LICENSE**

ENDORSEMENTS

INSPECTOR

TC EXPIRES

3/16/2014

ID NUMBER
100 - 11238
ISSUED
3/21/2013
EXPIRES
05/16/2014

PROJECT MANAGER
3/20/2014
AIR SAMPLING PROFESSIONAL

ESTEBAN NUNEZ
855 WEST ADAMS ST, #200
CHICAGO, IL 60607



Environmental Health

Alteration of this license shall result in legal action
This license issued under authority of the State of Illinois
Department of Public Health
This license is valid only when accompanied by a valid
training course certificate.



ASBESTOS PROFESSIONAL LICENSE

| ENDORSEMENTS | TC EXPIRES |
|---------------------------|------------|
| INSPECTOR | 2/4/2014 |
| MANAGEMENT PLANNER | 2/28/2014 |
| PROJECT MANAGER | 2/9/2014 |
| AIR SAMPLING PROFESSIONAL | |

| ID NUMBER | ISSUED | EXPIRES |
|-------------|-----------|------------|
| 100 - 06325 | 3/21/2013 | 05/15/2014 |

SANTIAGO GARCIA
855 W ADAMS ST SUITE 200
CHICAGO, IL 60607



Environmental Health

Alteration of this license shall result in legal action
This license issued under authority of the State of Illinois
Department of Public Health
This license is valid only when accompanied by a valid
training course certificate.

CERTIFICATE OF ACHIEVEMENT ASBESTOS ABATEMENT

Approved by the Illinois Department of Public Health and Indiana Department of Environmental Management

This is to certify that SANTIAGO GARCIA
has completed the Contractor/Supervisor Recertification course and passed the examination
on 02/09/2013 with a minimum score of 70% or better. Training was in accordance with U.S.
E.P.A. 40 CFR 763 Subpart E, Appendix C, Asbestos Containing Materials in Schools: Model
Accreditation Plan, TSCA II, Authorized by both AHERA & ASHARA and Indiana Rule 326 IAC
18-2.



N. Penick

02/09/2013

Course Dates:

02/09/2014

Expires:

1302CSR24

Certificate Number:

Phone Number: (312) 491-0081

Director of Training

Nicholas J. Penick

Doctor of Public Health

FORM # A-008

APPENDIX C

Laboratory Accreditations

APPENDIX D

Laboratory Results

APPENDIX E

Chain of Custody Forms

Three-Year Reinspection Key to Terms

| | CODE | KEY |
|--------------------------|-------------|--|
| MATERIAL | | |
| | ACBM | Asbestos Containing Building Materials |
| MATERIAL CATEGORY | | |
| | MISC | Miscellaneous |
| | SURF | Surfacing |
| | TSI | Thermal System Insulation |
| MATERIAL UNITS | | |
| | LF | Linear Feet |
| | SF | Square Feet |
| | CF | Cubic Feet |
| DAMAGE TYPE | | |
| | Loc | Localized |
| | Dist | Distributed |