

ILLINOIS DEPARTMENT OF PUBLIC HEALTH
AHERA THREE YEAR REINSPECTION
ASBESTOS ABATEMENT PROGRAM
SCHOOL INFORMATION FORM

SECTION I

NAME OF SCHOOL DISTRICT: CHICAGO SCHOOL DIST 299
SCHOOL ID NUMBER: 14-016-2990-
SCHOOL NAME: Ruiz School
ADDRESS OF SCHOOL: 2410 S.Leavitt
CITY: Chicago, IL, 60608

DATE LAST THREE YEAR REINSPECTION WAS COMPLETED **3/2/2010**

If the address on this form is different than the address of the building, submit a written explanation.

SECTION II (Please type or print)

PLEASE COMPLETE THE FOLLOWING FOR YOUR THREE YEAR REINSPECTION:

DATE REINSPECTION COMPLETED: 3/31/2013 ENROLLMENT 960
IDPH INSPECTOR LICENSE NUMBER: 100-8785
IDPH LICENSED INSPECTOR NAME (Please Print): Kathy Yurks
IDPH MP LICENSE NUMBER: 100-03613
IDPH LICENSED MANAGEMENT PLANNER NAME (Please Print): Daniel Juneau

DESIGNATED PERSON (Please Print): Ms. Lynn Crivello PHONE: (773) 553-3113



3/31/2013

Signature of Designated Person

Date

SECTION III

PLEASE COMPLETE THE FOLLOWING INFORMATION FOR ANY CHANGES WITHIN THE SCHOOL DISTRICT.

School building has been sold. Date of Sale: _____

School has been closed. Date closed: _____

School building has been demolished. Date: _____

School building is asbestos free since last reinspection: _____

Please explain in writing why the school building is now asbestos free and include the supporting documentation.

If a new school building has been added to the district, submit either an exclusionary statement or a management plan and inspection report. Include the complete name, address and city of school building.

Explain in writing if the address of the building is different than the address on this form:

THREE-YEAR REINSPECTION

CHICAGO SCHOOL DIST 299

Ruiz School

2410 S.Leavitt
Chicago, IL, 60608

Unit: 24931
Building ID: 5390

IDPH ID Number: 14-016-2990-

REPORT DATE:

Sunday, March 31, 2013

Prepared for:

Chicago Public Schools
125 S. Clark Street
Chicago, IL 60603

Prepared by:

Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone (312) 762-2900

Fax (312) 782-5145

**DO NOT REMOVE FROM SCHOOL
REQUIRED BY FEDERAL LAW**

March 25, 2013

Mr. R. Kent Cook
Asbestos Program
Illinois Department of Public Health
525 West Jefferson Street
Springfield, Illinois 62761

Re: Chicago Public Schools - 2013 Three-Year Reinspections

Dear Mr. Cook:

Carnow, Conibear and Associates, Managing Environmental Consultant (MEC), conducted the Three-Year Reinspections and performed management plan updates for the Chicago Public Schools (CPS) facilities in Region 3,4,5 Elementary Schools. Please update your records with the following information.

School District: 299 Unit: 24931 Region: 03 IDPH ID: 14-016-2990-

School: Ruiz School Building ID: 5390

Address: 2410 S.Leavitt

Chicago, IL, 60608

Building Contact: Hawes, Cheryl

Contact Phone: 7732858137

Current Building Owners: Chicago Public Schools

Review Date: 3/31/2013

Inspector: Kathy Yurks

Inspector IDPH License: 100-8785

Management Planner: Daniel Juneau

Management Planner IDPH License: 100-03613

If you have any questions or comments, please contact us at (312) 762-2900

Sincerely,
Carnow, Conibear and Associates



Daniel Juneau
100-03613

Environmental Notification to Occupants

To: Faculty, Staff and Parents
From: Chicago Public Schools
Date: March 25, 2013

RE: Ruiz School, Unit 24931
2410 S.Leavitt
Chicago, IL, 60608

Dear Faculty, Staff and Parents,

This letter is to notify you that the 2013 asbestos three year re-inspection has been completed at Ruiz School , following the Federal Asbestos Hazard Emergency Response Act (AHERA), 40 CFR Part 763, Subpart E and is available for your review at the main office of the school.

Although asbestos-containing materials have been identified at Ruiz School, there is no reason to believe that any threat to the health of students or staff exists at this time. CPS will continue to carefully monitor the condition of asbestos-containing materials and if conditions warrant, all appropriate steps will be taken to maintain the health and safety of all building occupants.

If you have any questions regarding this matter or require additional information, please feel free to contact Ms. Lynn Crivello, the designated Local Education Authority's Designated Person at (773) 553-3113 .

Table of Contents

- I. School and Inspection Information
- II. Executive Summary
- III. Methodology
- IV. Abatement History
- V. Reassessments and Recommendations
- VI. Conclusions

Table I: Inspector's Reinspection Findings

Table II: Management Planner's Review

APPENDICES:

- Appendix A: Assessment Sheets, Drawings and Photos
- Appendix B: Inspector and Management Planner Licenses
- Appendix C: Laboratory Accreditations
- Appendix D: Laboratory Results
- Appendix E: Chain of Custody Forms

SCHOOL AND INSPECTION INFORMATION

1. School Information

School: Ruiz School Unit: 24931 Region: 03
Address: 2410 S.Leavitt Chicago, IL, 60608
IDPH ID: 14-016-2990- Building ID: 5390
Contact: Hawes, Cheryl Phone: 7732858137

2. Description of Facility

Original Construction: Additional Construction:
Total Square Footage: 72400 No of Floors:
Current Occupancy: 960

3. LEA Designated Person

Contact: Ms. Lynn Crivello Phone: (773) 553-3113
Address: 125 South Clark Street, 17th Floor
Chicago, IL 60603


4. Managing Environmental Consultant

MEC: Carnow, Conibear and Associates
Contact: Dan Juneau
Address 600 West Van Buren St., Ste 500
Phone: (312) 762-2900 Fax: (312) 782-5145

5. Inspector

Inspector Name: Kathy Yurks


Inspector IDPH license # 100-8785


Signature:
Date: 3/25/2013

6. Management Planner

Management Planner Name: Daniel Juneau

Management Planner IDPH license # 100-03613


Signature:
Date: 3/31/2013

7. Review Date: 3/31/2013

8. LEA Designated Person's Acknowledgement

The reinspection report and recommendations have been received by me and appropriate action will be taken by the School District.

Signature:



Date: 3/31/2013

Name: Ms. Lynn Crivello

II. EXECUTIVE SUMMARY

Carnow, Conibear and Associates was retained by the Chicago Public Schools (CPS) to perform a three-year asbestos reinspection of the Ruiz School. This inspection was conducted in accordance with the United States Environmental Protection Agency (USEPA) Asbestos Hazard Emergency Response Act (AHERA) part 763.92 (b), and the ongoing Operations and Maintenance Program (O&M) originally designed in the School's Asbestos Management Plan. The purpose of this three-year reinspection is to record any condition changes in the asbestos-containing building material (ACBM) in the school since the previous three-year reinspection and the six-month periodic surveillance, to identify, assess, and include any Homogeneous Areas (HA) not identified in the Management Plan, and to recommend an appropriate response action to manage asbestos.

The inspector conducted a three-year reinspection of this facility under Illinois Department of Public Health (IDPH) school reinspection requirements and AHERA, sections 763.85 and 763.88. The main building and each addition to the main building, if constructed at different dates, were inspected separately. Laboratory accreditations are included in Appendix C, laboratory results are included in Appendix D, and chain of custody forms are included in Appendix E.

Note: During previous inspections, some of the HA(s) were identified together as 9" x 9" floor tile (FT), mastics assoc. with 9" x 9" FT, 12" x 12" FT, mastics assoc. with 12" x 12" FT, pipe insulation, etc. Some of these HA(s) have been re-identified by areas that are uniform in color, texture, construction date, application date, and general appearance.

The inspector has determined the following:

A. The following HAs have changed assessment categories for Building 5390:

B. The following new homogenous areas have been identified for Building 5390:

| | |
|----|--------------------------|
| 56 | Blue Ceramic Tile |
| 57 | Blue Ceramic Grout |
| 58 | Tan Ceramic Tile |
| 59 | Tan Ceramic Grout |
| 60 | Gray Ceramic Tile |
| 61 | Gray Ceramic Grout |
| 62 | Dark Brown Ceramic Tile |
| 63 | Dark Brown Ceramic Grout |

C. This reinspection covered only physically accessible and visible areas and materials that were identified in the LEA's management plan. The following materials were concealed and/or contained in areas that were inaccessible for sampling and have been classified as Assumed:

| | |
|----|--|
| 1 | 12" x 12" White w/Gray Floor Tile |
| 10 | 12" x 12" Brown Mix Floor Tile Mastic |
| 11 | 12" x 12" Light Brown w/Gray Floor Tile |
| 12 | 12" x 12" Light Brown w/Gray Floor Tile Mastic |
| 13 | 12" x 12" Beige w/Brown Floor Tile |
| 14 | 12" x 12" Beige w/Brown Floor Tile Mastic |
| 15 | White Undercoating on Sinks |
| 16 | 4" Gray Vinyl Baseboard |
| 17 | 4" Gray Vinyl Baseboard Adhesive |
| 18 | 4" Brown Vinyl Baseboard |
| 19 | 4" Brown Vinyl Baseboard Adhesive |
| 2 | 12" x 12" White w/Gray Floor Tile Mastic |
| 20 | 2' x 4' Lay In Ceiling Panels |
| 21 | 2' x 2' Lay In Ceiling Panels |
| 22 | Duct Sealant |
| 23 | Vibration Collars |
| 24 | Window Caulk |
| 25 | Drywall |
| 26 | Drywall Compound |
| 27 | Blue Carpet Adhesive |
| 28 | Brown Carpet Adhesive |
| 29 | Lab Counter Tops and Sinks |
| 3 | 12" x 12" Gray Mix Floor Tile |
| 30 | Lab Table Tops |
| 31 | Spray on Insulation |
| 32 | Chalk Board/Poster Board Adhesive |
| 33 | 4" White Baseboard |
| 34 | 4" White Baseboard Adhesive |
| 35 | 12"X12" Blue w/White Floor Tile |
| 36 | 12"X12" Blue w/White Floor Tile mastic |
| 37 | 12"X12" Lt Pink Mix Floor Tile |
| 38 | 12"X12" Lt Pink Mix Floor Tile Mastic |
| 39 | 12"X12" White w/Gray Floor Tile |
| 4 | 12" x 12" Gray Mix Floor Tile Mastic |
| 40 | 12"X12" White w/Gray Floor Tile Mastic |
| 41 | 2'X2' Lay In Ceiling Tiles |
| 42 | 4" Tan Vinyl Baseboard |
| 43 | 4" Tan Vinyl Baseboard Adhesive |
| 44 | Drywall |
| 45 | Fire Door Insulation |
| 46 | Drywall Joint Compound |
| 47 | Beige Vinyl Flooring |
| 48 | Beige Vinyl Flooring Mastic |
| 49 | Drywall Joint Tape |

| | |
|------|---------------------------------------|
| 5 | 12" x 12" Pink Mix Floor Tile |
| 50 | 12x12 Brown & White Floor Tile |
| 51 | 12x12 Brown & White Floor Tile Mastic |
| 52 | 12x12 Brown & White Floor Tile |
| 53 | 12x12 Brown & White Floor Tile Mastic |
| 54 | Rubber Flooring Material |
| 55 | Rubber Flooring Material Mastic |
| 56 | Blue Ceramic Tile |
| 57 | Blue Ceramic Grout |
| 58 | Tan Ceramic Tile |
| 59 | Tan Ceramic Grout |
| 6 | 12" x 12" Pink Mix Floor Tile Mastic |
| 60 | Gray Ceramic Tile |
| 61 | Gray Ceramic Grout |
| 62 | Dark Brown Ceramic Tile |
| 63 | Dark Brown Ceramic Grout |
| 7 | 12" x 12" Beige Mix Floor Tile |
| 8 | 12" x 12" Beige Mix Floor Tile Mastic |
| 9 | 12" x 12" Brown Mix Floor Tile |
| MB-6 | Orange Sheet Flooring Adhesive |

The following areas were deemed to be inaccessible:

| | |
|------|--|
| 10 | 12" x 12" Brown Mix Floor Tile Mastic |
| 17 | 4" Gray Vinyl Baseboard Adhesive |
| 19 | 4" Brown Vinyl Baseboard Adhesive |
| 2 | 12" x 12" White w/Gray Floor Tile Mastic |
| 27 | Blue Carpet Adhesive |
| 32 | Chalk Board/Poster Board Adhesive |
| 34 | 4" White Baseboard Adhesive |
| 36 | 12"X12" Blue w/White Floor Tile mastic |
| 38 | 12"X12" Lt Pink Mix Floor Tile Mastic |
| 4 | 12" x 12" Gray Mix Floor Tile Mastic |
| 40 | 12"X12" White w/Gray Floor Tile Mastic |
| 43 | 4" Tan Vinyl Baseboard Adhesive |
| 51 | 12x12 Brown & White Floor Tile Mastic |
| 53 | 12x12 Brown & White Floor Tile Mastic |
| 55 | Rubber Flooring Material Mastic |
| 57 | Blue Ceramic Grout |
| 59 | Tan Ceramic Grout |
| 6 | 12" x 12" Pink Mix Floor Tile Mastic |
| 61 | Gray Ceramic Grout |
| MB-6 | Orange Sheet Flooring Adhesive |

Materials were also listed as "assumed" if they were in good condition and sampling was not conducted to avoid damage.

This reinspection was conducted by Kathy Yurks, IDPH License # 100-8785. The Management Plan was updated by Daniel Juneau, IDPH License # 100-03613. Inspector and Management Planner Licenses are included in Appendix B.

III. METHODOLOGY

Tasks performed on-site included the following:

1. Review current management plan, identify HA(s) and extract appropriate information.
2. Examine and verify abatement records.
3. Touch and visually and physically reinspect and reassess the condition of all friable known or assumed ACBM.
4. Touch and visually and physically reinspect all non-friable known or assumed ACBM to determine whether these materials have become friable since the last inspection or periodic surveillance.
5. Identify any condition changes that may affect Hazard Ranking of known ACBM or Assumed ACBM, as well as any HA(s) that have become friable since the last reinspection.
6. Collect bulk samples from each newly discovered friable HA or previously assumed and submit for laboratory analysis.
7. Tabulate reinspection findings and submit for management planner review and recommendations with appropriate response actions based on the AHERA Damage Category of the ACBM.
8. Submit reinspection findings and management planner recommendations to the LEA within thirty (30) days for inclusion into the management plan.

IV. ABATEMENT HISTORY

The information collected from the existing management plan and inspection report(s) and from interviews with the school official revealed that the following asbestos abatement was conducted at the school since the previous Three year Reinspection.

Abatement Dates:

V. REASSESSMENTS AND RECOMMENDATIONS

The reassessments and recommendations are summarized in Tables I and II on the following pages. Detailed Hazard Assessment Sheets and Drawings and Photos (if applicable) are included in Appendix A.

VI. CONCLUSIONS

The Ruiz School Building 5390 Three-Year reinspection has been completed and response actions have been recommended for both friable and non-friable materials. A timely execution of the response actions recommended will enable the LEA and the Designated Person(s) to effectively manage the existing ACBM.

This three-year reinspection report should be inspected in the current Management plan at the CPS Central Office, and one (1) copy should be kept at the school for use when planning any renovation and/or demolition activities in areas where ACBM has been identified. Also, periodic surveillance documentation and any summary reports from any response actions that are executed at the school should be used to update the Management Plan.

Table I
Inspector's Reinspection Findings

Chicago Public Schools

School Ruiz School Unit 24931 Building ID 5390

Address 2410 S.Leavitt Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category | Damage Category | Damage Reason | Disturbance Potential |
|-------|--|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|-------------------------------|--|---------------|-----------------------|
| 1 | 12" x 12" White w/Gray Floor Tile | 14,000 | SF | Classrooms 203, 208, 209 213,301-314 and 316 | ASSUMED | MISC | N | NONE | 0 | | No | ACBM with the potential for damage | | MODERATE |
| 10 | 12" x 12" Brown Mix Floor Tile Mastic | 2,500 | SF | 1st Floor Corridor, Cafeteria, Janitor's Closet, Storage | ASSUMED | MISC | N | NONE | 0 | | No | ACBM with the potential for damage | | MODERATE |
| 11 | 12" x 12" Light Brown w/Gray Floor Tile | 2,500 | SF | 102/104, 105, 110, 112, Demonstration room | ASSUMED | MISC | N | NONE | 0 | | No | ACBM with the potential for damage | | MODERATE |
| 12 | 12" x 12" Light Brown w/Gray Floor Tile Mastic | 2,500 | SF | 102/104, 105, 110, 112, Demonstration Room | ASSUMED | MISC | N | NONE | 0 | | No | ACBM with the potential for damage | | MODERATE |
| 13 | 12" x 12" Beige w/Brown Floor Tile | 800 | SF | Classroom 108 | ASSUMED | MISC | N | NONE | 0 | | No | ACBM with the potential for damage | | MODERATE |
| 14 | 12" x 12" Beige w/Brown Floor Tile Mastic | 800 | SF | Classroom 108 | ASSUMED | MISC | N | NONE | 0 | | No | ACBM with the potential for damage | | MODERATE |
| 15 | White Undercoating on Sinks | 10 | SF | Classrooms 108, 110, 112, Demonstration Room | ASSUMED | MISC | N | NONE | 0 | | No | ACBM with the potential for damage | | MODERATE |
| 16 | 4" Gray Vinyl Baseboard | 850 | LF | Classrooms 213, 313, 314, 2nd & 3rd Floor Corridors | ASSUMED | MISC | N | NONE | 0 | | No | ACBM with the potential for damage | | MODERATE |
| 17 | 4" Gray Vinyl Baseboard Adhesive | 800 | LF | 213, 313, 314, 2nd & 3rd Floor Corridors | ASSUMED | MISC | N | NONE | 0 | | No | ACBM with the potential for damage | | MODERATE |
| 18 | 4" Brown Vinyl Baseboard | 800 | LF | Stairways, 106, 108, 313, Gym, Cafeteria, 1st Floor Corridor | ASSUMED | MISC | N | NONE | 0 | | No | ACBM with the potential for damage | | MODERATE |
| 19 | 4" Brown Vinyl Baseboard Adhesive | 800 | LF | Stairways, 106, 108, 313, Gym, Cafeteria, 1st Floor Corridor | ASSUMED | MISC | N | NONE | 0 | | No | ACBM with the potential for damage | | MODERATE |
| 2 | 12" x 12" White w/Gray Floor Tile Mastic | 14,000 | SF | Classrooms 213,301-314 and 316 | ASSUMED | MISC | N | NONE | 0 | | No | ACBM with the potential for damage | | MODERATE |
| 20 | 2' x 4' Lay In Ceiling Panels | 48,000 | SF | Classrooms, Corridors, Library, Storage Rooms, Cafeteria, Demonstration Room | ASSUMED | MISC | Y | NONE | 0 | | No | Any remaining friable ACBM or friable suspect ACBM | | MODERATE |
| 21 | 2' x 2' Lay In Ceiling Panels | 1,000 | SF | Cafeteria and Demonstration Room | ASSUMED | MISC | Y | NONE | 0 | | No | Any remaining friable ACBM or friable suspect ACBM | | MODERATE |

Chicago Public Schools

School Ruiz School Unit 24931 Building ID 5390

Address 2410 S.Leavitt Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category | Damage Category | Damage Reason | Disturbance Potential |
|-------|--|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|-------------------------------|--|---------------|-----------------------|
| 22 | Duct Sealant | 80 | LF | Third Floor Mechanical Room | ASSUMED | MISC | N | NONE | 0 | | No | ACBM with the potential for damage | | MODERATE |
| 23 | Vibration Collars | 20 | LF | Third Floor Mechanical Room | ASSUMED | MISC | N | NONE | 0 | | No | ACBM with the potential for damage | | MODERATE |
| 24 | Window Caulk | 18,000 | LF | Throughout Facility | ASSUMED | MISC | N | NONE | 0 | | No | ACBM with the potential for damage | | MODERATE |
| 25 | Drywall | 50,000 | SF | Throughout Facility as Inside Walls Between Classrooms | ASSUMED | MISC | N | NONE | 0 | | No | ACBM with the potential for damage | | MODERATE |
| 26 | Drywall Compound | 50,000 | SF | Throughout Facility as Inside Walls Between Classrooms | ASSUMED | MISC | N | NONE | 0 | | No | ACBM with the potential for damage | | MODERATE |
| 27 | Blue Carpet Adhesive | 14,000 | SF | Classrooms 301-310, 312, 201, 202, 211, 214, 102/104, 110, 112, Main Office, Library | ASSUMED | MISC | N | NONE | 0 | | No | ACBM with the potential for damage | | MODERATE |
| 28 | Brown Carpet Adhesive | 400 | SF | Classroom 213 | ASSUMED | MISC | N | NONE | 0 | | No | ACBM with the potential for damage | | MODERATE |
| 29 | Lab Counter Tops and Sinks | 90 | SF | Classroom 311 | ASSUMED | MISC | N | NONE | 0 | | No | ACBM with the potential for damage | | MODERATE |
| 3 | 12" x 12" Gray Mix Floor Tile | 2,000 | SF | 3rd Floor Corridor & Janitor's Closet | ASSUMED | MISC | N | NONE | 0 | | No | ACBM with the potential for damage | | MODERATE |
| 30 | Lab Table Tops | 90 | SF | Classroom 311 | ASSUMED | MISC | N | NONE | 0 | | No | ACBM with the potential for damage | | MODERATE |
| 31 | Spray on Insualtion | 48,000 | SF | Throughout First and Second Floors on Metal Ceilings | ASSUMED | SURFACE | Y | NONE | 0 | | No | Any remaining friable ACBM or friable suspect ACBM | | MODERATE |
| 32 | Chalk Board/Poster Board Adhesive | 3,400 | SF | All Classrooms | ASSUMED | MISC | N | NONE | 0 | | No | ACBM with the potential for damage | | MODERATE |
| 33 | 4" White Baseboard | 90 | LF | Classroom 213 | ASSUMED | MISC | N | NONE | 0 | | No | ACBM with the potential for damage | | MODERATE |
| 34 | 4" White Baseboard Adhesive | 90 | LF | Classroom 213 | ASSUMED | MISC | N | NONE | 0 | | No | ACBM with the potential for damage | | MODERATE |
| 35 | 12"X12" Blue w/White Floor Tile | 500 | SF | Room 103 | ASSUMED | MISC | N | NONE | 0 | | No | ACBM with the potential for damage | | MODERATE |
| 36 | 12"X12" Blue w/White Floor Tile mastic | 500 | SF | Room 103 | ASSUMED | MISC | N | NONE | 0 | | No | ACBM with the potential for damage | | MODERATE |
| 37 | 12"X12" Lt Pink Mix Floor Tile | 1,500 | SF | 205, 206, 207 | ASSUMED | MISC | N | NONE | 0 | | No | ACBM with the potential for damage | | MODERATE |
| 38 | 12"X12" Lt Pink Mix Floor Tile Mastic | 1,500 | SF | 205, 206, 207 | ASSUMED | MISC | N | NONE | 0 | | No | ACBM with the potential for damage | | MODERATE |
| 39 | 12"X12" White w/Gray Floor Tile | 5,000 | SF | Modular Corridor, | ASSUMED | MISC | N | NONE | 0 | | No | ACBM with the | | MODERATE |

Chicago Public Schools

School Ruiz School Unit 24931 Building ID 5390

Address 2410 S.Leavitt Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category | Damage Category | Damage Reason | Disturbance Potential |
|-------|--|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|-------------------------------|--|---------------|-----------------------|
| | | | | 115, 116, 117, 118, 119, 120 | | | | | | | | potential for damage | | |
| 4 | 12" x 12" Gray Mix Floor Tile Mastic | 2,000 | SF | 3rd Floor Corridor & Janitor's Closet | ASSUMED | MISC | N | NONE | 0 | | No | ACBM with the potential for damage | | MODERATE |
| 40 | 12"X12" White w/Gray Floor Tile Mastic | 5,000 | SF | Modular Corridor, 115, 116, 117, 118, 119, 120 | ASSUMED | MISC | N | NONE | 0 | | No | ACBM with the potential for damage | | MODERATE |
| 41 | 2'X2' Lay In Ceiling Tiles | 5,200 | SF | Through-out Modular Unit | ASSUMED | MISC | Y | NONE | 0 | | No | Any remaining friable ACBM or friable suspect ACBM | | MODERATE |
| 42 | 4" Tan Vinyl Baseboard | 1,000 | LF | Modular corridor and classrooms | ASSUMED | MISC | N | NONE | 0 | | No | ACBM with the potential for damage | | MODERATE |
| 43 | 4" Tan Vinyl Baseboard Adhesive | 1,000 | LF | Modular corridor and classrooms | ASSUMED | MISC | N | NONE | 0 | | No | ACBM with the potential for damage | | MODERATE |
| 44 | Drywall | 5,200 | SF | Through-out Modular Unit | ASSUMED | MISC | N | NONE | 0 | | No | ACBM with the potential for damage | | MODERATE |
| 45 | Fire Door Insulation | 160 | SF | Entrances of Modular Unit | ASSUMED | MISC | N | NONE | 0 | | No | ACBM with the potential for damage | | MODERATE |
| 46 | Drywall Joint Compound | 1,500 | LF | Through-out Modular | ASSUMED | MISC | N | NONE | 0 | | No | ACBM with the potential for damage | | MODERATE |
| 47 | Beige Vinyl Flooring | 200 | SF | Men's and Women's Washrooms in Modular | ASSUMED | MISC | N | NONE | 0 | | No | ACBM with the potential for damage | | MODERATE |
| 48 | Beige Vinyl Flooring Mastic | 200 | SF | Men's and Women's Washrooms in Modular | ASSUMED | MISC | N | NONE | 0 | | No | ACBM with the potential for damage | | MODERATE |
| 49 | Drywall Joint Tape | 1,000 | LF | Through-out Modular | ASSUMED | MISC | N | NONE | 0 | | No | ACBM with the potential for damage | | MODERATE |
| 5 | 12" x 12" Pink Mix Floor Tile | 2,000 | SF | 2nd Floor Corridor & Storage and stairwells | ASSUMED | MISC | N | NONE | 0 | | No | ACBM with the potential for damage | | MODERATE |
| 50 | 12x12 Brown & White Floor Tile | 800 | SF | Rm 310 | ASSUMED | MISC | N | NONE | 0 | | No | ACBM with the potential for damage | | MODERATE |
| 51 | 12x12 Brown & White Floor Tile Mastic | 800 | SF | Rm 310 | ASSUMED | MISC | N | NONE | 0 | | No | ACBM with the potential for damage | | MODERATE |
| 52 | 12x12 Brown & White Floor Tile | 800 | SF | Rm 313 | ASSUMED | MISC | N | NONE | 0 | | No | ACBM with the potential for damage | | MODERATE |
| 53 | 12x12 Brown & White Floor Tile Mastic | 800 | SF | Rm 313 | ASSUMED | MISC | N | NONE | 0 | | No | ACBM with the potential for damage | | MODERATE |
| 54 | Rubber Flooring Material | 800 | SF | Gym | ASSUMED | MISC | N | NONE | 0 | | No | ACBM with the potential for damage | | MODERATE |
| 55 | Rubber Flooring Material Mastic | 800 | SF | Gym | ASSUMED | MISC | N | NONE | 0 | | No | ACBM with the potential for damage | | MODERATE |
| 56 | Blue Ceramic Tile | 700 | SF | 3rd Floor | ASSUMED | MISC | N | NONE | 0 | | No | ACBM with the | | MODERATE |

Chicago Public Schools

School Ruiz School Unit 24931 Building ID 5390

Address 2410 S.Leavitt Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category | Damage Category | Damage Reason | Disturbance Potential |
|-------|---------------------------------------|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|-------------------------------|------------------------------------|---------------|-----------------------|
| | | | | Boy's/girl/Teacher's Washroom | | | | | | | | potential for damage | | |
| 57 | Blue Ceramic Grout | 700 | SF | 3rd Floor Boy's/girl/Teacher's Washroom | ASSUMED | MISC | N | NONE | 0 | | No | ACBM with the potential for damage | | MODERATE |
| 58 | Tan Ceramic Tile | 700 | SF | 2nd Floor Boy's/girl/Teacher's Washroom | ASSUMED | MISC | N | NONE | 0 | | No | ACBM with the potential for damage | | MODERATE |
| 59 | Tan Ceramic Grout | 700 | SF | 2nd Floor Boy's/girl/Teacher's Washroom | ASSUMED | MISC | N | NONE | 0 | | No | ACBM with the potential for damage | | MODERATE |
| 6 | 12" x 12" Pink Mix Floor Tile Mastic | 2,000 | SF | 2nd Floor Corridor & Storage | ASSUMED | MISC | N | NONE | 0 | | No | ACBM with the potential for damage | | MODERATE |
| 60 | Gray Ceramic Tile | 700 | SF | 1st Floor Boy's/girl/Teacher's Washroom | ASSUMED | MISC | N | NONE | 0 | | No | ACBM with the potential for damage | | MODERATE |
| 61 | Gray Ceramic Grout | 700 | SF | 1st Floor Boy's/girl/Teacher's Washroom | ASSUMED | MISC | N | NONE | 0 | | No | ACBM with the potential for damage | | MODERATE |
| 62 | Dark Brown Ceramic Tile | 1,100 | SF | Kitchen/Service area | ASSUMED | MISC | N | NONE | 0 | | No | ACBM with the potential for damage | | MODERATE |
| 63 | Dark Brown Ceramic Grout | 1,100 | SF | Kitchen/Serving Area | ASSUMED | MISC | N | NONE | 0 | | | ACBM with the potential for damage | | LOW |
| 7 | 12" x 12" Beige Mix Floor Tile | 600 | SF | Classrooms 201-212, 213 Closet, and 218 | ASSUMED | MISC | N | NONE | 0 | | No | ACBM with the potential for damage | | MODERATE |
| 8 | 12" x 12" Beige Mix Floor Tile Mastic | 600 | SF | Classrooms 201-212, 213 Closet, and 218 | ASSUMED | MISC | N | NONE | 0 | | No | ACBM with the potential for damage | | MODERATE |
| 9 | 12" x 12" Brown Mix Floor Tile | 2,500 | SF | 1st Floor Corridor, Cafeteria, Janitor's Closet, Storage | ASSUMED | MISC | N | NONE | 0 | | No | ACBM with the potential for damage | | MODERATE |
| MB-6 | Orange Sheet Flooring Adhesive | 160 | SF | Girl's Washroom | ASSUMED | MISC | N | NONE | 0 | | No | ACBM with the potential for damage | | MODERATE |

Chicago Public Schools

School Ruiz School Unit 24931 Building ID 5390

Address 2410 S.Leavitt Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

| |
|---|
| Reinspection Date 3/25/2013 |
| Inspector Name Kathy Yurks |
| 100-8785 5/15/2013 |
| Inspector's IDPH License Number / Expiration Date |

Inspector's Comments

| HA Number: | Inspector Comments: |
|------------|--|
| 1 | |
| 10 | |
| 11 | |
| 12 | |
| 13 | |
| 14 | |
| 15 | |
| 16 | |
| 17 | |
| 18 | |
| 19 | |
| 2 | |
| 20 | |
| 21 | |
| 22 | |
| 23 | |
| 24 | |
| 25 | |
| 26 | |
| 27 | Material observed in room 103 and 202 - 2013 Re-inspection |
| 28 | |
| 29 | |
| 3 | |
| 30 | |

Chicago Public Schools

School Ruiz School Unit 24931 Building ID 5390

Address 2410 S.Leavitt Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

| HA Number: | Inspector Comments: |
|------------|---------------------|
| 31 | |
| 32 | |
| 33 | |
| 34 | |
| 35 | |
| 36 | |
| 37 | |
| 38 | |
| 39 | |
| 4 | |
| 40 | |
| 41 | |
| 42 | |
| 43 | |
| 44 | |
| 45 | |
| 46 | |
| 47 | |
| 48 | |
| 49 | |
| 5 | |
| 50 | |
| 51 | |
| 52 | |
| 53 | |
| 54 | |
| 55 | |
| 56 | |
| 57 | |

Chicago Public Schools

School Ruiz School Unit 24931 Building ID 5390

Address 2410 S.Leavitt Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

| HA Number: | Inspector Comments: |
|------------|---------------------|
| 58 | |
| 59 | |
| 6 | |
| 60 | |
| 61 | |
| 62 | |
| 63 | |
| 7 | |
| 8 | |
| 9 | |
| MB-6 | |

Table II

Management Planner's Review

Chicago Public Schools

School Ruiz School
Address 2410 S.Leavitt

Unit 24931
Chicago, IL, 60608

Building ID 5390
Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

| HA Num | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Quantity | Damage Units | Damage Category | Response |
|--------|--|-------------------|----------------|---|---------------|-------------------|---------|-----------------|--------------|--|----------------------------|
| 1 | 12" x 12" White w/Gray Floor Tile | 14,000 | SF | Classrooms 203, 208, 209 213,301-314 and 316 | Assumed | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Operations and Maintenance |
| 10 | 12" x 12" Brown Mix Floor Tile Mastic | 2,500 | SF | 1st Floor Corridor, Cafeteria, Janitor's Closet, Storage | Assumed | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Operations and Maintenance |
| 11 | 12" x 12" Light Brown w/Gray Floor Tile | 2,500 | SF | 102/104, 105, 110, 112, Demonstration room | Assumed | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Operations and Maintenance |
| 12 | 12" x 12" Light Brown w/Gray Floor Tile Mastic | 2,500 | SF | 102/104, 105, 110, 112, Demonstration Room | Assumed | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Operations and Maintenance |
| 13 | 12" x 12" Beige w/Brown Floor Tile | 800 | SF | Classroom 108 | Assumed | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Operations and Maintenance |
| 14 | 12" x 12" Beige w/Brown Floor Tile Mastic | 800 | SF | Classroom 108 | Assumed | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Operations and Maintenance |
| 15 | White Undercoating on Sinks | 10 | SF | Classrooms 108, 110, 112, Demonstration Room | Assumed | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Operations and Maintenance |
| 16 | 4" Gray Vinyl Baseboard | 850 | LF | Classrooms 213, 313, 314, 2nd & 3rd Floor Corridors | Assumed | MISC | No | 0 | LF | 6 ACBM with the potential for damage | Operations and Maintenance |
| 17 | 4" Gray Vinyl Baseboard Adhesive | 800 | LF | 213, 313, 314, 2nd & 3rd Floor Corridors | Assumed | MISC | No | 0 | LF | 6 ACBM with the potential for damage | Operations and Maintenance |
| 18 | 4" Brown Vinyl Baseboard | 800 | LF | Stairways, 106, 108, 313, Gym, Cafeteria, 1st Floor Corridor | Assumed | MISC | No | 0 | LF | 6 ACBM with the potential for damage | Operations and Maintenance |
| 19 | 4" Brown Vinyl Baseboard Adhesive | 800 | LF | Stairways, 106, 108, 313, Gym, Cafeteria, 1st Floor Corridor | Assumed | MISC | No | 0 | LF | 6 ACBM with the potential for damage | Operations and Maintenance |
| 2 | 12" x 12" White w/Gray Floor Tile Mastic | 14,000 | SF | Classrooms 213,301-314 and 316 | Assumed | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Operations and Maintenance |
| 20 | 2' x 4' Lay In Ceiling Panels | 48,000 | SF | Classrooms, Corridors, Library, Storage Rooms, Cafeteria, Demonstration Room | Assumed | MISC | Yes | 0 | SF | 7 Any remaining friable ACBM or friable suspect ACBM | Operations and Maintenance |
| 21 | 2' x 2' Lay In Ceiling Panels | 1,000 | SF | Cafeteria and Demonstration Room | Assumed | MISC | Yes | 0 | SF | 7 Any remaining friable ACBM or friable suspect ACBM | Operations and Maintenance |
| 22 | Duct Sealant | 80 | LF | Third Floor Mechanical Room | Assumed | MISC | No | 0 | LF | 6 ACBM with the potential for damage | Operations and Maintenance |
| 23 | Vibration Collars | 20 | LF | Third Floor Mechanical Room | Assumed | MISC | No | 0 | LF | 6 ACBM with the potential for damage | Operations and Maintenance |
| 24 | Window Caulk | 18,000 | LF | Throughout Facility | Assumed | MISC | No | 0 | LF | 6 ACBM with the potential for damage | Operations and Maintenance |
| 25 | Drywall | 50,000 | SF | Throughout Facility as Inside Walls Between Classrooms | Assumed | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Operations and Maintenance |
| 26 | Drywall Compound | 50,000 | SF | Throughout Facility as Inside Walls Between Classrooms | Assumed | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Operations and Maintenance |
| 27 | Blue Carpet Adhesive | 14,000 | SF | Classrooms 301-310, 312,201, 202, 211, 214, 102/104, 110, 112, Main Office, Library | Assumed | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Operations and Maintenance |

Chicago Public Schools

School Ruiz School
Address 2410 S.Leavitt

Unit 24931
Chicago, IL, 60608

Building ID 5390
Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

| HA Num | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Quantity | Damage Units | Damage Category | Response |
|--------|--|-------------------|----------------|--|---------------|-------------------|---------|-----------------|--------------|--|----------------------------|
| 28 | Brown Carpet Adhesive | 400 | SF | Classroom 213 | Assumed | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Operations and Maintenance |
| 29 | Lab Counter Tops and Sinks | 90 | SF | Classroom 311 | Assumed | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Operations and Maintenance |
| 3 | 12" x 12" Gray Mix Floor Tile | 2,000 | SF | 3rd Floor Corridor & Janitor's Closet | Assumed | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Operations and Maintenance |
| 30 | Lab Table Tops | 90 | SF | Classroom 311 | Assumed | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Operations and Maintenance |
| 31 | Spray on Insulation | 48,000 | SF | Throughout First and Second Floors on Metal Ceilings | Assumed | SURFACE | Yes | 0 | SF | 7 Any remaining friable ACBM or friable suspect ACBM | Operations and Maintenance |
| 32 | Chalk Board/Poster Board Adhesive | 3,400 | SF | All Classrooms | Assumed | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Operations and Maintenance |
| 33 | 4" White Baseboard | 90 | LF | Classroom 213 | Assumed | MISC | No | 0 | LF | 6 ACBM with the potential for damage | Operations and Maintenance |
| 34 | 4" White Baseboard Adhesive | 90 | LF | Classroom 213 | Assumed | MISC | No | 0 | LF | 6 ACBM with the potential for damage | Operations and Maintenance |
| 35 | 12"X12" Blue w/White Floor Tile | 500 | SF | Room 103 | Assumed | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Operations and Maintenance |
| 36 | 12"X12" Blue w/White Floor Tile mastic | 500 | SF | Room 103 | Assumed | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Operations and Maintenance |
| 37 | 12"X12" Lt Pink Mix Floor Tile | 1,500 | SF | 205, 206, 207 | Assumed | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Operations and Maintenance |
| 38 | 12"X12" Lt Pink Mix Floor Tile Mastic | 1,500 | SF | 205, 206, 207 | Assumed | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Operations and Maintenance |
| 39 | 12"X12" White w/Gray Floor Tile | 5,000 | SF | Modular Corridor, 115, 116, 117, 118, 119, 120 | Assumed | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Operations and Maintenance |
| 4 | 12" x 12" Gray Mix Floor Tile Mastic | 2,000 | SF | 3rd Floor Corridor & Janitor's Closet | Assumed | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Operations and Maintenance |
| 40 | 12"X12" White w/Gray Floor Tile Mastic | 5,000 | SF | Modular Corridor, 115, 116, 117, 118, 119, 120 | Assumed | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Operations and Maintenance |
| 41 | 2'X2' Lay In Ceiling Tiles | 5,200 | SF | Through-out Modular Unit | Assumed | MISC | Yes | 0 | SF | 7 Any remaining friable ACBM or friable suspect ACBM | Operations and Maintenance |
| 42 | 4" Tan Vinyl Baseboard | 1,000 | LF | Modular corridor and classrooms | Assumed | MISC | No | 0 | LF | 6 ACBM with the potential for damage | Operations and Maintenance |
| 43 | 4" Tan Vinyl Baseboard Adhesive | 1,000 | LF | Modular corridor and classrooms | Assumed | MISC | No | 0 | LF | 6 ACBM with the potential for damage | Operations and Maintenance |
| 44 | Drywall | 5,200 | SF | Through-out Modular Unit | Assumed | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Operations and Maintenance |
| 45 | Fire Door Insulation | 160 | SF | Entrances of Modular Unit | Assumed | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Operations and Maintenance |
| 46 | Drywall Joint Compound | 1,500 | LF | Through-out Modular | Assumed | MISC | No | 0 | LF | 6 ACBM with the potential for damage | Operations and Maintenance |
| 47 | Beige Vinyl Flooring | 200 | SF | Men's and Women's Washrooms in Modular | Assumed | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Operations and Maintenance |
| 48 | Beige Vinyl Flooring Mastic | 200 | SF | Men's and Women's Washrooms in Modular | Assumed | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Operations and Maintenance |
| 49 | Drywall Joint Tape | 1,000 | LF | Through-out Modular | Assumed | MISC | No | 0 | LF | 6 ACBM with the potential for damage | Operations and Maintenance |
| 5 | 12" x 12" Pink Mix Floor Tile | 2,000 | SF | 2nd Floor Corridor & Storage and stairwells | Assumed | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Operations and Maintenance |
| 50 | 12x12 Brown & White Floor Tile | 800 | SF | Rm 310 | Assumed | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Operations and Maintenance |
| 51 | 12x12 Brown & White Floor Tile Mastic | 800 | SF | Rm 310 | Assumed | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Operations and Maintenance |
| 52 | 12x12 Brown & White Floor Tile | 800 | SF | Rm 313 | Assumed | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Operations and Maintenance |

Chicago Public Schools

School Ruiz School
Address 2410 S.Leavitt

Unit 24931
Chicago, IL, 60608

Building ID 5390
Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

| HA Num | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Quantity | Damage Units | Damage Category | Response |
|--------|---------------------------------------|-------------------|----------------|--|---------------|-------------------|---------|-----------------|--------------|--------------------------------------|----------------------------|
| 53 | 12x12 Brown & White Floor Tile Mastic | 800 | SF | Rm 313 | Assumed | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Operations and Maintenance |
| 54 | Rubber Flooring Material | 800 | SF | Gym | Assumed | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Operations and Maintenance |
| 55 | Rubber Flooring Material Mastic | 800 | SF | Gym | Assumed | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Operations and Maintenance |
| 56 | Blue Ceramic Tile | 700 | SF | 3rd Floor Boy's/girl/Teacher's Washrroom | Assumed | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Operations and Maintenance |
| 57 | Blue Ceramic Grout | 700 | SF | 3rd Floor Boy's/girl/Teacher's Washrroom | Assumed | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Operations and Maintenance |
| 58 | Tan Ceramic Tile | 700 | SF | 2nd Floor Boy's/girl/Teacher's Washrroom | Assumed | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Operations and Maintenance |
| 59 | Tan Ceramic Grout | 700 | SF | 2nd Floor Boy's/girl/Teacher's Washrroom | Assumed | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Operations and Maintenance |
| 6 | 12" x 12" Pink Mix Floor Tile Mastic | 2,000 | SF | 2nd Floor Corridor & Storage | Assumed | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Operations and Maintenance |
| 60 | Gray Ceramic Tile | 700 | SF | 1st Floor Boy's/girl/Teacher's Washrroom | Assumed | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Operations and Maintenance |
| 61 | Gray Ceramic Grout | 700 | SF | 1st Floor Boy's/girl/Teacher's Washrroom | Assumed | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Operations and Maintenance |
| 62 | Dark Brown Ceramic Tile | 1,100 | SF | Kitchen/Service area | Assumed | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Operations and Maintenance |
| 63 | Dark Brown Ceramic Grout | 1,100 | SF | Kitchen/Serving Area | Assumed | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Operations and Maintenance |
| 7 | 12" x 12" Beige Mix Floor Tile | 600 | SF | Classrooms 201-212, 213 Closet, and 218 | Assumed | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Operations and Maintenance |
| 8 | 12" x 12" Beige Mix Floor Tile Mastic | 600 | SF | Classrooms 201-212, 213 Closet, and 218 | Assumed | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Operations and Maintenance |
| 9 | 12" x 12" Brown Mix Floor Tile | 2,500 | SF | 1st Floor Corridor, Cafeteria, Janitor's Closet, Storage | Assumed | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Operations and Maintenance |
| MB-6 | Orange Sheet Flooring Adhesive | 160 | SF | Girl's Washrroom | Assumed | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Operations and Maintenance |

Chicago Public Schools

School Ruiz School
Address 2410 S.Leavitt

Unit 24931
 Chicago, IL, 60608

Building ID 5390
Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

| | |
|------------------------------------|---------------|
| Review Date | 3/31/2013 |
| Manager Planner Name | Daniel Juneau |
| 100-03613 | 5/15/2014 |
| Manager IDPH License No/Expiration | |

| HA Number | Management Comments |
|-----------|---------------------|
| 1 | |
| 10 | |
| 11 | |
| 12 | |
| 13 | |
| 14 | |
| 15 | |
| 16 | |
| 17 | |
| 18 | |
| 19 | |
| 2 | |
| 20 | |

Chicago Public Schools

School Ruiz School
Address 2410 S.Leavitt

Unit 24931
Chicago, IL, 60608

Building ID 5390
Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates
600 West Van Buren St., Ste 500
Phone: (312) 762-2900 Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

| HA Number | Management Comments |
|-----------|---------------------|
| 21 | |
| 22 | |
| 23 | |
| 24 | |
| 25 | |
| 26 | |
| 27 | |
| 28 | |
| 29 | |
| 3 | |
| 30 | |
| 31 | |
| 32 | |
| 33 | |
| 34 | |
| 35 | |
| 36 | |
| 37 | |
| 38 | |
| 39 | |
| 4 | |
| 40 | |
| 41 | |
| 42 | |
| 43 | |
| 44 | |
| 45 | |

Chicago Public Schools

School Ruiz School
Address 2410 S.Leavitt

Unit 24931
 Chicago, IL, 60608

Building ID 5390
Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates
 600 West Van Buren St., Ste 500
 Phone: (312) 762-2900 Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

| HA Number | Management Comments |
|-----------|---------------------|
| 46 | |
| 47 | |
| 48 | |
| 49 | |
| 5 | |
| 50 | |
| 51 | |
| 52 | |
| 53 | |
| 54 | |
| 55 | |
| 56 | |
| 57 | |
| 58 | |
| 59 | |
| 6 | |
| 60 | |
| 61 | |
| 62 | |
| 63 | |
| 7 | |
| 8 | |
| 9 | |
| MB-6 | |

Chicago Public Schools

School Ruiz School
Address 2410 S.Leavitt

Unit 24931
Chicago, IL, 60608

Building ID 5390
Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates
600 West Van Buren St., Ste 500
Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24931** BUIDLING ID: **5390**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kathy Yurks**
SCHOOL NAME: **Ruiz School** INSPECTION DATE: **3/25/2013**
ADDRESS: **2410 S.Leavitt** IDPH LICENSE NO: **100-8785**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **1**
MATERIAL DESCRIPTION: **12" x 12"White w/Gray Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**

MATERIAL LOCATION: **Classrooms 203, 208, 209 213,301-314 and 316**

MATERIAL QUANTITY: **14000**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 03/25/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24931** BUIDLING ID: **5390**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Ruiz School** REVIEW DATE: **3/31/2013**
ADDRESS: **2410 S.Leavitt** IDPH LICENSE NO: **100-8785**

HOMOGENEOUS AREA: **1**
MATERIAL DESCRIPTION: **12" x 12"White w/Gray Floor Tile**
MATERIAL LOCATION: **Classrooms 203, 208, 209 213,301-314 and 316**
MATERIAL QUANTITY: **14000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **03/31/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24931** BUIDLING ID: **5390**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kathy Yurks**
SCHOOL NAME: **Ruiz School** INSPECTION DATE: **3/25/2013**
ADDRESS: **2410 S.Leavitt** IDPH LICENSE NO: **100-8785**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **10**
MATERIAL DESCRIPTION: **12" x 12" Brown Mix Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**


MATERIAL LOCATION: **1st Floor Corridor, Cafeteria, Janitor's Closet, Storage**

MATERIAL QUANTITY: **2500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 03/25/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24931** BUIDLING ID: **5390**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Ruiz School** REVIEW DATE: **3/31/2013**
ADDRESS: **2410 S.Leavitt** IDPH LICENSE NO: **100-8785**

HOMOGENEOUS AREA: **10**
MATERIAL DESCRIPTION: **12" x 12" Brown Mix Floor Tile Mastic**
MATERIAL LOCATION: **1st Floor Corridor, Cafeteria, Janitor's Closet, Storage**
MATERIAL QUANTITY: **2500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **03/31/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24931** BUIDLING ID: **5390**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kathy Yurks**
SCHOOL NAME: **Ruiz School** INSPECTION DATE: **3/25/2013**
ADDRESS: **2410 S.Leavitt** IDPH LICENSE NO: **100-8785**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **11**
MATERIAL DESCRIPTION: **12" x 12" Light Brown w/Gray Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **102/104, 105, 110, 112, Demonstration room**
MATERIAL QUANTITY: **2500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 03/25/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24931** BUIDLING ID: **5390**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Ruiz School** REVIEW DATE: **3/31/2013**
ADDRESS: **2410 S.Leavitt** IDPH LICENSE NO: **100-8785**

HOMOGENEOUS AREA: **11**
MATERIAL DESCRIPTION: **12" x 12" Light Brown w/Gray Floor Tile**
MATERIAL LOCATION: **102/104, 105, 110, 112, Demonstration room**
MATERIAL QUANTITY: **2500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **03/31/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24931** BUIDLING ID: **5390**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kathy Yurks**
SCHOOL NAME: **Ruiz School** INSPECTION DATE: **3/25/2013**
ADDRESS: **2410 S.Leavitt** IDPH LICENSE NO: **100-8785**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **12**
MATERIAL DESCRIPTION: **12" x 12" Light Brown w/Gray Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT


This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **102/104, 105, 110, 112, Demonstration Room**
MATERIAL QUANTITY: **2500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____



Date: 03/25/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24931** BUIDLING ID: **5390**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Ruiz School** REVIEW DATE: **3/31/2013**
ADDRESS: **2410 S.Leavitt** IDPH LICENSE NO: **100-8785**

HOMOGENEOUS AREA: **12**
MATERIAL DESCRIPTION: **12" x 12" Light Brown w/Gray Floor Tile Mastic**
MATERIAL LOCATION: **102/104, 105, 110, 112, Demonstration Room**
MATERIAL QUANTITY: **2500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **03/31/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24931** BUIDLING ID: **5390**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kathy Yurks**
SCHOOL NAME: **Ruiz School** INSPECTION DATE: **3/25/2013**
ADDRESS: **2410 S.Leavitt** IDPH LICENSE NO: **100-8785**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **13**
MATERIAL DESCRIPTION: **12" x 12" Beige w/Brown Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**

MATERIAL LOCATION: **Classroom 108**

MATERIAL QUANTITY: **800**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 03/25/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24931** BUIDLING ID: **5390**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Ruiz School** REVIEW DATE: **3/31/2013**
ADDRESS: **2410 S.Leavitt** IDPH LICENSE NO: **100-8785**

HOMOGENEOUS AREA: **13**
MATERIAL DESCRIPTION: **12" x 12" Beige w/Brown Floor Tile**
MATERIAL LOCATION: **Classroom 108**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **03/31/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24931** BUIDLING ID: **5390**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kathy Yurks**
SCHOOL NAME: **Ruiz School** INSPECTION DATE: **3/25/2013**
ADDRESS: **2410 S.Leavitt** IDPH LICENSE NO: **100-8785**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **14**
MATERIAL DESCRIPTION: **12" x 12" Beige w/Brown Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**

MATERIAL LOCATION: **Classroom 108**

MATERIAL QUANTITY: **800**


MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 03/25/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24931** BUIDLING ID: **5390**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Ruiz School** REVIEW DATE: **3/31/2013**
ADDRESS: **2410 S.Leavitt** IDPH LICENSE NO: **100-8785**

HOMOGENEOUS AREA: **14**
MATERIAL DESCRIPTION: **12" x 12" Beige w/Brown Floor Tile Mastic**
MATERIAL LOCATION: **Classroom 108**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **03/31/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24931** BUIDLING ID: **5390**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kathy Yurks**
SCHOOL NAME: **Ruiz School** INSPECTION DATE: **3/25/2013**
ADDRESS: **2410 S.Leavitt** IDPH LICENSE NO: **100-8785**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **15**
MATERIAL DESCRIPTION: **White Undercoating on Sinks**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Classrooms 108, 110, 112, Demonstration Room**
MATERIAL QUANTITY: **10** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 03/25/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24931** BUIDLING ID: **5390**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Ruiz School** REVIEW DATE: **3/31/2013**
ADDRESS: **2410 S.Leavitt** IDPH LICENSE NO: **100-8785**

HOMOGENEOUS AREA: **15**
MATERIAL DESCRIPTION: **White Undercoating on Sinks**
MATERIAL LOCATION: **Classrooms 108, 110, 112, Demonstration Room**
MATERIAL QUANTITY: **10** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **03/31/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24931** BUIDLING ID: **5390**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kathy Yurks**
SCHOOL NAME: **Ruiz School** INSPECTION DATE: **3/25/2013**
ADDRESS: **2410 S.Leavitt** IDPH LICENSE NO: **100-8785**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **16**
MATERIAL DESCRIPTION: **4" Gray Vinyl Baseboard**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT


This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Classrooms 213, 313, 314, 2nd & 3rd Floor Corridors**
MATERIAL QUANTITY: **850** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: DAMAGE UNITS: **LF**
COMMENTS:

Inspector's Signature: _____



Date: 03/25/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24931** BUIDLING ID: **5390**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Ruiz School** REVIEW DATE: **3/31/2013**
ADDRESS: **2410 S.Leavitt** IDPH LICENSE NO: **100-8785**

HOMOGENEOUS AREA: **16**
MATERIAL DESCRIPTION: **4" Gray Vinyl Baseboard**
MATERIAL LOCATION: **Classrooms 213, 313, 314, 2nd & 3rd Floor Corridors**
MATERIAL QUANTITY: **850** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **03/31/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24931** BUIDLING ID: **5390**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kathy Yurks**
SCHOOL NAME: **Ruiz School** INSPECTION DATE: **3/25/2013**
ADDRESS: **2410 S.Leavitt** IDPH LICENSE NO: **100-8785**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **17**
MATERIAL DESCRIPTION: **4" Gray Vinyl Baseboard Adhesive**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **213, 313, 314, 2nd & 3rd Floor Corridors**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: _____



Date: 03/25/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24931** BUIDLING ID: **5390**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Ruiz School** REVIEW DATE: **3/31/2013**
ADDRESS: **2410 S.Leavitt** IDPH LICENSE NO: **100-8785**

HOMOGENEOUS AREA: **17**
MATERIAL DESCRIPTION: **4" Gray Vinyl Baseboard Adhesive**
MATERIAL LOCATION: **213, 313, 314, 2nd & 3rd Floor Corridors**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **03/31/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24931** BUIDLING ID: **5390**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kathy Yurks**
SCHOOL NAME: **Ruiz School** INSPECTION DATE: **3/25/2013**
ADDRESS: **2410 S.Leavitt** IDPH LICENSE NO: **100-8785**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **18**
MATERIAL DESCRIPTION: **4" Brown Vinyl Baseboard**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Stairways, 106, 108, 313, Gym, Cafeteria, 1st Floor Corridor**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: _____



Date: 03/25/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24931** BUIDLING ID: **5390**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Ruiz School** REVIEW DATE: **3/31/2013**
ADDRESS: **2410 S.Leavitt** IDPH LICENSE NO: **100-8785**

HOMOGENEOUS AREA: **18**
MATERIAL DESCRIPTION: **4" Brown Vinyl Baseboard**
MATERIAL LOCATION: **Stairways, 106, 108, 313, Gym, Cafeteria, 1st Floor Corridor**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **03/31/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24931** BUIDLING ID: **5390**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kathy Yurks**
SCHOOL NAME: **Ruiz School** INSPECTION DATE: **3/25/2013**
ADDRESS: **2410 S.Leavitt** IDPH LICENSE NO: **100-8785**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **19**
MATERIAL DESCRIPTION: **4" Brown Vinyl Baseboard Adhesive**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**


MATERIAL LOCATION: **Stairways, 106, 108, 313, Gym, Cafeteria, 1st Floor Corridor**

MATERIAL QUANTITY: **800** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: _____



Date: 03/25/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24931** BUIDLING ID: **5390**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Ruiz School** REVIEW DATE: **3/31/2013**
ADDRESS: **2410 S.Leavitt** IDPH LICENSE NO: **100-8785**

HOMOGENEOUS AREA: **19**
MATERIAL DESCRIPTION: **4" Brown Vinyl Baseboard Adhesive**
MATERIAL LOCATION: **Stairways, 106, 108, 313, Gym, Cafeteria, 1st Floor Corridor**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **03/31/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24931** BUIDLING ID: **5390**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kathy Yurks**
SCHOOL NAME: **Ruiz School** INSPECTION DATE: **3/25/2013**
ADDRESS: **2410 S.Leavitt** IDPH LICENSE NO: **100-8785**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **2**
MATERIAL DESCRIPTION: **12" x 12" White w/Gray Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Classrooms 213,301-314 and 316**
MATERIAL QUANTITY: **14000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 03/25/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24931** BUIDLING ID: **5390**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Ruiz School** REVIEW DATE: **3/31/2013**
ADDRESS: **2410 S.Leavitt** IDPH LICENSE NO: **100-8785**

HOMOGENEOUS AREA: **2**
MATERIAL DESCRIPTION: **12" x 12" White w/Gray Floor Tile Mastic**
MATERIAL LOCATION: **Classrooms 213,301-314 and 316**
MATERIAL QUANTITY: **14000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **03/31/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24931** BUIDLING ID: **5390**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kathy Yurks**
SCHOOL NAME: **Ruiz School** INSPECTION DATE: **3/25/2013**
ADDRESS: **2410 S.Leavitt** IDPH LICENSE NO: **100-8785**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **20**
MATERIAL DESCRIPTION: **2' x 4' Lay In Ceiling Panels**
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Classrooms, Corridors, Library, Storage Rooms, Cafeteria, Demonstration Room**
MATERIAL QUANTITY: **48000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 03/25/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24931** BUIDLING ID: **5390**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Ruiz School** REVIEW DATE: **3/31/2013**
ADDRESS: **2410 S.Leavitt** IDPH LICENSE NO: **100-8785**

HOMOGENEOUS AREA: **20**
MATERIAL DESCRIPTION: **2' x 4' Lay In Ceiling Panels**
MATERIAL LOCATION: **Classrooms, Corridors, Library, Storage Rooms, Cafeteria, Demonstration Room**
MATERIAL QUANTITY: **48000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **03/31/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24931** BUIDLING ID: **5390**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kathy Yurks**
SCHOOL NAME: **Ruiz School** INSPECTION DATE: **3/25/2013**
ADDRESS: **2410 S.Leavitt** IDPH LICENSE NO: **100-8785**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **21**
MATERIAL DESCRIPTION: **2' x 2' Lay In Ceiling Panels**
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Cafeteria and Demonstration Room**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 03/25/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24931** BUIDLING ID: **5390**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Ruiz School** REVIEW DATE: **3/31/2013**
ADDRESS: **2410 S.Leavitt** IDPH LICENSE NO: **100-8785**

HOMOGENEOUS AREA: **21**
MATERIAL DESCRIPTION: **2' x 2' Lay In Ceiling Panels**
MATERIAL LOCATION: **Cafeteria and Demonstration Room**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **03/31/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24931** BUIDLING ID: **5390**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kathy Yurks**
SCHOOL NAME: **Ruiz School** INSPECTION DATE: **3/25/2013**
ADDRESS: **2410 S.Leavitt** IDPH LICENSE NO: **100-8785**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **22**
MATERIAL DESCRIPTION: **Duct Sealant**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**

MATERIAL LOCATION: **Third Floor Mechanical Room**

MATERIAL QUANTITY: **80**

MATERIAL UNITS: **LF**

DAMAGE QUANTITY:

DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: _____



Date: 03/25/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24931** BUIDLING ID: **5390**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Ruiz School** REVIEW DATE: **3/31/2013**
ADDRESS: **2410 S.Leavitt** IDPH LICENSE NO: **100-8785**

HOMOGENEOUS AREA: **22**
MATERIAL DESCRIPTION: **Duct Sealant**
MATERIAL LOCATION: **Third Floor Mechanical Room**
MATERIAL QUANTITY: **80** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **03/31/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24931** BUIDLING ID: **5390**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kathy Yurks**
SCHOOL NAME: **Ruiz School** INSPECTION DATE: **3/25/2013**
ADDRESS: **2410 S.Leavitt** IDPH LICENSE NO: **100-8785**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **23**
MATERIAL DESCRIPTION: **Vibration Collars**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**

MATERIAL LOCATION: **Third Floor Mechanical Room**

MATERIAL QUANTITY: **20**

MATERIAL UNITS: **LF**

DAMAGE QUANTITY:

DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: _____



Date: 03/25/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24931** BUIDLING ID: **5390**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Ruiz School** REVIEW DATE: **3/31/2013**
ADDRESS: **2410 S.Leavitt** IDPH LICENSE NO: **100-8785**

HOMOGENEOUS AREA: **23**

MATERIAL DESCRIPTION: **Vibration Collars**

MATERIAL LOCATION: **Third Floor Mechanical Room**

MATERIAL QUANTITY: **20**

MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **03/31/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24931** BUIDLING ID: **5390**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kathy Yurks**
SCHOOL NAME: **Ruiz School** INSPECTION DATE: **3/25/2013**
ADDRESS: **2410 S.Leavitt** IDPH LICENSE NO: **100-8785**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **24**
MATERIAL DESCRIPTION: **Window Caulk**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**

MATERIAL LOCATION: **Throughout Facility**

MATERIAL QUANTITY: **18000**


MATERIAL UNITS: **LF**

DAMAGE QUANTITY:

DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: _____



Date: 03/25/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24931** BUIDLING ID: **5390**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Ruiz School** REVIEW DATE: **3/31/2013**
ADDRESS: **2410 S.Leavitt** IDPH LICENSE NO: **100-8785**

HOMOGENEOUS AREA: **24**
MATERIAL DESCRIPTION: **Window Caulk**
MATERIAL LOCATION: **Throughout Facility**
MATERIAL QUANTITY: **18000** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **03/31/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24931** BUIDLING ID: **5390**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kathy Yurks**
SCHOOL NAME: **Ruiz School** INSPECTION DATE: **3/25/2013**
ADDRESS: **2410 S.Leavitt** IDPH LICENSE NO: **100-8785**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **25**
MATERIAL DESCRIPTION: **Drywall**
HISTORICAL AHERA DAMAGE CATEGORY **6 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Throughout Facility as Inside Walls Between Classrooms**
MATERIAL QUANTITY: **50000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 03/25/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24931** BUIDLING ID: **5390**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Ruiz School** REVIEW DATE: **3/31/2013**
ADDRESS: **2410 S.Leavitt** IDPH LICENSE NO: **100-8785**

HOMOGENEOUS AREA: **25**
MATERIAL DESCRIPTION: **Drywall**
MATERIAL LOCATION: **Throughout Facility as Inside Walls Between Classrooms**
MATERIAL QUANTITY: **50000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **03/31/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24931** BUIDLING ID: **5390**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kathy Yurks**
SCHOOL NAME: **Ruiz School** INSPECTION DATE: **3/25/2013**
ADDRESS: **2410 S.Leavitt** IDPH LICENSE NO: **100-8785**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **26**
MATERIAL DESCRIPTION: **Drywall Compound**
HISTORICAL AHERA DAMAGE CATEGORY **6 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT


This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Throughout Facility as Inside Walls Between Classrooms**
MATERIAL QUANTITY: **50000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____



Date: 03/25/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24931** BUIDLING ID: **5390**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Ruiz School** REVIEW DATE: **3/31/2013**
ADDRESS: **2410 S.Leavitt** IDPH LICENSE NO: **100-8785**

HOMOGENEOUS AREA: **26**
MATERIAL DESCRIPTION: **Drywall Compound**
MATERIAL LOCATION: **Throughout Facility as Inside Walls Between Classrooms**
MATERIAL QUANTITY: **50000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **03/31/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24931** BUIDLING ID: **5390**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kathy Yurks**
SCHOOL NAME: **Ruiz School** INSPECTION DATE: **3/25/2013**
ADDRESS: **2410 S.Leavitt** IDPH LICENSE NO: **100-8785**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **27**
MATERIAL DESCRIPTION: **Blue Carpet Adhesive**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**


MATERIAL LOCATION: **Classrooms 301-310, 312,201, 202, 211, 214, 102/104, 110, 112, Main Office, Library**

MATERIAL QUANTITY: **14000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS: **Material observed in room 103 and 202 - 2013 Re-inspection**

Inspector's Signature: _____



Date: 03/25/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24931** BUIDLING ID: **5390**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Ruiz School** REVIEW DATE: **3/31/2013**
ADDRESS: **2410 S.Leavitt** IDPH LICENSE NO: **100-8785**

HOMOGENEOUS AREA: **27**
MATERIAL DESCRIPTION: **Blue Carpet Adhesive**
MATERIAL LOCATION: **Classrooms 301-310, 312,201, 202, 211, 214, 102/104, 110, 112, Main Office, Library**
MATERIAL QUANTITY: **14000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **03/31/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24931** BUIDLING ID: **5390**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kathy Yurks**
SCHOOL NAME: **Ruiz School** INSPECTION DATE: **3/25/2013**
ADDRESS: **2410 S.Leavitt** IDPH LICENSE NO: **100-8785**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **28**
MATERIAL DESCRIPTION: **Brown Carpet Adhesive**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:


DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Classroom 213**

MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 03/25/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24931** BUIDLING ID: **5390**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Ruiz School** REVIEW DATE: **3/31/2013**
ADDRESS: **2410 S.Leavitt** IDPH LICENSE NO: **100-8785**

HOMOGENEOUS AREA: **28**
MATERIAL DESCRIPTION: **Brown Carpet Adhesive**
MATERIAL LOCATION: **Classroom 213**
MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **03/31/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24931** BUIDLING ID: **5390**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kathy Yurks**
SCHOOL NAME: **Ruiz School** INSPECTION DATE: **3/25/2013**
ADDRESS: **2410 S.Leavitt** IDPH LICENSE NO: **100-8785**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **29**
MATERIAL DESCRIPTION: **Lab Counter Tops and Sinks**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**

MATERIAL LOCATION: **Classroom 311**

MATERIAL QUANTITY: **90**


MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 03/25/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24931** BUIDLING ID: **5390**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Ruiz School** REVIEW DATE: **3/31/2013**
ADDRESS: **2410 S.Leavitt** IDPH LICENSE NO: **100-8785**

HOMOGENEOUS AREA: **29**

MATERIAL DESCRIPTION: **Lab Counter Tops and Sinks**

MATERIAL LOCATION: **Classroom 311**

MATERIAL QUANTITY: **90**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **03/31/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24931** BUIDLING ID: **5390**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kathy Yurks**
SCHOOL NAME: **Ruiz School** INSPECTION DATE: **3/25/2013**
ADDRESS: **2410 S.Leavitt** IDPH LICENSE NO: **100-8785**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **3**
MATERIAL DESCRIPTION: **12" x 12" Gray Mix Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **3rd Floor Corridor & Janitor's Closet**
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 03/25/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24931** BUIDLING ID: **5390**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Ruiz School** REVIEW DATE: **3/31/2013**
ADDRESS: **2410 S.Leavitt** IDPH LICENSE NO: **100-8785**

HOMOGENEOUS AREA: **3**
MATERIAL DESCRIPTION: **12" x 12" Gray Mix Floor Tile**
MATERIAL LOCATION: **3rd Floor Corridor & Janitor's Closet**
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **03/31/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24931** BUIDLING ID: **5390**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kathy Yurks**
SCHOOL NAME: **Ruiz School** INSPECTION DATE: **3/25/2013**
ADDRESS: **2410 S.Leavitt** IDPH LICENSE NO: **100-8785**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **30**
MATERIAL DESCRIPTION: **Lab Table Tops**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Classroom 311**
MATERIAL QUANTITY: **90** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 03/25/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24931** BUIDLING ID: **5390**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Ruiz School** REVIEW DATE: **3/31/2013**
ADDRESS: **2410 S.Leavitt** IDPH LICENSE NO: **100-8785**

HOMOGENEOUS AREA: **30**

MATERIAL DESCRIPTION: **Lab Table Tops**

MATERIAL LOCATION: **Classroom 311**

MATERIAL QUANTITY: **90**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **03/31/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24931** BUIDLING ID: **5390**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kathy Yurks**
SCHOOL NAME: **Ruiz School** INSPECTION DATE: **3/25/2013**
ADDRESS: **2410 S.Leavitt** IDPH LICENSE NO: **100-8785**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **31**
MATERIAL DESCRIPTION: **Spray on Insualtion**
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Throughout First and Second Floors on Metal Ceilings**
MATERIAL QUANTITY: **48000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 03/25/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24931** BUIDLING ID: **5390**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Ruiz School** REVIEW DATE: **3/31/2013**
ADDRESS: **2410 S.Leavitt** IDPH LICENSE NO: **100-8785**

HOMOGENEOUS AREA: **31**
MATERIAL DESCRIPTION: **Spray on Insualtion**
MATERIAL LOCATION: **Throughout First and Second Floors on Metal Ceilings**
MATERIAL QUANTITY: **48000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **03/31/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24931** BUIDLING ID: **5390**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kathy Yurks**
SCHOOL NAME: **Ruiz School** INSPECTION DATE: **3/25/2013**
ADDRESS: **2410 S.Leavitt** IDPH LICENSE NO: **100-8785**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **32**
MATERIAL DESCRIPTION: **Chalk Board/Poster Board Adhesive**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **All Classrooms**
MATERIAL QUANTITY: **3400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 03/25/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24931** BUIDLING ID: **5390**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Ruiz School** REVIEW DATE: **3/31/2013**
ADDRESS: **2410 S.Leavitt** IDPH LICENSE NO: **100-8785**

HOMOGENEOUS AREA: **32**
MATERIAL DESCRIPTION: **Chalk Board/Poster Board Adhesive**
MATERIAL LOCATION: **All Classrooms**
MATERIAL QUANTITY: **3400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **03/31/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24931** BUIDLING ID: **5390**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kathy Yurks**
SCHOOL NAME: **Ruiz School** INSPECTION DATE: **3/25/2013**
ADDRESS: **2410 S.Leavitt** IDPH LICENSE NO: **100-8785**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **33**
MATERIAL DESCRIPTION: **4" White Baseboard**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**

MATERIAL LOCATION: **Classroom 213**

MATERIAL QUANTITY: **90**

MATERIAL UNITS: **LF**

DAMAGE QUANTITY:

DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: _____



Date: 03/25/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24931** BUIDLING ID: **5390**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Ruiz School** REVIEW DATE: **3/31/2013**
ADDRESS: **2410 S.Leavitt** IDPH LICENSE NO: **100-8785**

HOMOGENEOUS AREA: **33**

MATERIAL DESCRIPTION: **4" White Baseboard**

MATERIAL LOCATION: **Classroom 213**

MATERIAL QUANTITY: **90**

MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **03/31/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24931** BUIDLING ID: **5390**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kathy Yurks**
SCHOOL NAME: **Ruiz School** INSPECTION DATE: **3/25/2013**
ADDRESS: **2410 S.Leavitt** IDPH LICENSE NO: **100-8785**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **34**
MATERIAL DESCRIPTION: **4" White Baseboard Adhesive**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**

MATERIAL LOCATION: **Classroom 213**

MATERIAL QUANTITY: **90**


MATERIAL UNITS: **LF**

DAMAGE QUANTITY:

DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: _____



Date: 03/25/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24931** BUIDLING ID: **5390**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Ruiz School** REVIEW DATE: **3/31/2013**
ADDRESS: **2410 S.Leavitt** IDPH LICENSE NO: **100-8785**

HOMOGENEOUS AREA: **34**
MATERIAL DESCRIPTION: **4" White Baseboard Adhesive**
MATERIAL LOCATION: **Classroom 213**
MATERIAL QUANTITY: **90** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **03/31/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24931** BUIDLING ID: **5390**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kathy Yurks**
SCHOOL NAME: **Ruiz School** INSPECTION DATE: **3/25/2013**
ADDRESS: **2410 S.Leavitt** IDPH LICENSE NO: **100-8785**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **35**
MATERIAL DESCRIPTION: **12"X12" Blue w/White Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Room 103**
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 03/25/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24931** BUIDLING ID: **5390**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Ruiz School** REVIEW DATE: **3/31/2013**
ADDRESS: **2410 S.Leavitt** IDPH LICENSE NO: **100-8785**

HOMOGENEOUS AREA: **35**
MATERIAL DESCRIPTION: **12"X12" Blue w/White Floor Tile**
MATERIAL LOCATION: **Room 103**
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **03/31/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24931** BUIDLING ID: **5390**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kathy Yurks**
SCHOOL NAME: **Ruiz School** INSPECTION DATE: **3/25/2013**
ADDRESS: **2410 S.Leavitt** IDPH LICENSE NO: **100-8785**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **36**
MATERIAL DESCRIPTION: **12"X12" Blue w/White Floor Tile mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**

MATERIAL LOCATION: **Room 103**

MATERIAL QUANTITY: **500**


MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 03/25/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24931** BUIDLING ID: **5390**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Ruiz School** REVIEW DATE: **3/31/2013**
ADDRESS: **2410 S.Leavitt** IDPH LICENSE NO: **100-8785**

HOMOGENEOUS AREA: **36**
MATERIAL DESCRIPTION: **12"X12" Blue w/White Floor Tile mastic**
MATERIAL LOCATION: **Room 103**
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **03/31/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24931** BUIDLING ID: **5390**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kathy Yurks**
SCHOOL NAME: **Ruiz School** INSPECTION DATE: **3/25/2013**
ADDRESS: **2410 S.Leavitt** IDPH LICENSE NO: **100-8785**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **37**
MATERIAL DESCRIPTION: **12"X12" Lt Pink Mix Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **205, 206, 207**
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 03/25/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24931** BUIDLING ID: **5390**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Ruiz School** REVIEW DATE: **3/31/2013**
ADDRESS: **2410 S.Leavitt** IDPH LICENSE NO: **100-8785**

HOMOGENEOUS AREA: **37**
MATERIAL DESCRIPTION: **12"X12" Lt Pink Mix Floor Tile**
MATERIAL LOCATION: **205, 206, 207**
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **03/31/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24931** BUIDLING ID: **5390**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kathy Yurks**
SCHOOL NAME: **Ruiz School** INSPECTION DATE: **3/25/2013**
ADDRESS: **2410 S.Leavitt** IDPH LICENSE NO: **100-8785**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **38**
MATERIAL DESCRIPTION: **12"X12" Lt Pink Mix Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **205, 206, 207**
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 03/25/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24931** BUIDLING ID: **5390**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Ruiz School** REVIEW DATE: **3/31/2013**
ADDRESS: **2410 S.Leavitt** IDPH LICENSE NO: **100-8785**

HOMOGENEOUS AREA: **38**
MATERIAL DESCRIPTION: **12"X12" Lt Pink Mix Floor Tile Mastic**
MATERIAL LOCATION: **205, 206, 207**
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **03/31/2013**

Chicago Public Schools

Carnow, Conibear and Associates 2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24931** BUIDLING ID: **5390**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kathy Yurks**
SCHOOL NAME: **Ruiz School** INSPECTION DATE: **3/25/2013**
ADDRESS: **2410 S.Leavitt** IDPH LICENSE NO: **100-8785**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **39**
MATERIAL DESCRIPTION: **12"X12" White w/Gray Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Modular Corridor, 115, 116, 117, 118, 119, 120**
MATERIAL QUANTITY: **5000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 03/25/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24931** BUIDLING ID: **5390**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Ruiz School** REVIEW DATE: **3/31/2013**
ADDRESS: **2410 S.Leavitt** IDPH LICENSE NO: **100-8785**

HOMOGENEOUS AREA: **39**
MATERIAL DESCRIPTION: **12"X12" White w/Gray Floor Tile**
MATERIAL LOCATION: **Modular Corridor, 115, 116, 117, 118, 119, 120**
MATERIAL QUANTITY: **5000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **03/31/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24931** BUIDLING ID: **5390**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kathy Yurks**
SCHOOL NAME: **Ruiz School** INSPECTION DATE: **3/25/2013**
ADDRESS: **2410 S.Leavitt** IDPH LICENSE NO: **100-8785**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **4**
MATERIAL DESCRIPTION: **12" x 12" Gray Mix Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**

MATERIAL LOCATION: **3rd Floor Corridor & Janitor's Closet**

MATERIAL QUANTITY: **2000**


MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 03/25/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24931** BUIDLING ID: **5390**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Ruiz School** REVIEW DATE: **3/31/2013**
ADDRESS: **2410 S.Leavitt** IDPH LICENSE NO: **100-8785**

HOMOGENEOUS AREA: **4**
MATERIAL DESCRIPTION: **12" x 12" Gray Mix Floor Tile Mastic**
MATERIAL LOCATION: **3rd Floor Corridor & Janitor's Closet**
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **03/31/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24931** BUIDLING ID: **5390**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kathy Yurks**
SCHOOL NAME: **Ruiz School** INSPECTION DATE: **3/25/2013**
ADDRESS: **2410 S.Leavitt** IDPH LICENSE NO: **100-8785**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **40**
MATERIAL DESCRIPTION: **12"X12" White w/Gray Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Modular Corridor, 115, 116, 117, 118, 119, 120**
MATERIAL QUANTITY: **5000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 03/25/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24931** BUIDLING ID: **5390**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Ruiz School** REVIEW DATE: **3/31/2013**
ADDRESS: **2410 S.Leavitt** IDPH LICENSE NO: **100-8785**

HOMOGENEOUS AREA: **40**
MATERIAL DESCRIPTION: **12"X12" White w/Gray Floor Tile Mastic**
MATERIAL LOCATION: **Modular Corridor, 115, 116, 117, 118, 119, 120**
MATERIAL QUANTITY: **5000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **03/31/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24931** BUIDLING ID: **5390**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kathy Yurks**
SCHOOL NAME: **Ruiz School** INSPECTION DATE: **3/25/2013**
ADDRESS: **2410 S.Leavitt** IDPH LICENSE NO: **100-8785**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **41**
MATERIAL DESCRIPTION: **2'X2' Lay In Ceiling Tiles**
HISTORICAL AHERA DAMAGE CATEGORY **7 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Through-out Modular Unit**
MATERIAL QUANTITY: **5200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 03/25/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24931** BUIDLING ID: **5390**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Ruiz School** REVIEW DATE: **3/31/2013**
ADDRESS: **2410 S.Leavitt** IDPH LICENSE NO: **100-8785**

HOMOGENEOUS AREA: **41**
MATERIAL DESCRIPTION: **2'X2' Lay In Ceiling Tiles**
MATERIAL LOCATION: **Through-out Modular Unit**
MATERIAL QUANTITY: **5200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **03/31/2013**

Chicago Public Schools

Carnow, Conibear and Associates 2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24931** BUIDLING ID: **5390**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kathy Yurks**
SCHOOL NAME: **Ruiz School** INSPECTION DATE: **3/25/2013**
ADDRESS: **2410 S.Leavitt** IDPH LICENSE NO: **100-8785**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **42**
MATERIAL DESCRIPTION: **4" Tan Vinyl Baseboard**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**

MATERIAL LOCATION: **Modular corridor and classrooms**

MATERIAL QUANTITY: **1000**


MATERIAL UNITS: **LF**

DAMAGE QUANTITY:

DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: _____



Date: 03/25/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24931** BUIDLING ID: **5390**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Ruiz School** REVIEW DATE: **3/31/2013**
ADDRESS: **2410 S.Leavitt** IDPH LICENSE NO: **100-8785**

HOMOGENEOUS AREA: **42**
MATERIAL DESCRIPTION: **4" Tan Vinyl Baseboard**
MATERIAL LOCATION: **Modular corridor and classrooms**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **03/31/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24931** BUIDLING ID: **5390**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kathy Yurks**
SCHOOL NAME: **Ruiz School** INSPECTION DATE: **3/25/2013**
ADDRESS: **2410 S.Leavitt** IDPH LICENSE NO: **100-8785**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **43**
MATERIAL DESCRIPTION: **4" Tan Vinyl Baseboard Adhesive**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**

MATERIAL LOCATION: **Modular corridor and classrooms**

MATERIAL QUANTITY: **1000**


MATERIAL UNITS: **LF**

DAMAGE QUANTITY:

DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: _____



Date: 03/25/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24931** BUIDLING ID: **5390**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Ruiz School** REVIEW DATE: **3/31/2013**
ADDRESS: **2410 S.Leavitt** IDPH LICENSE NO: **100-8785**

HOMOGENEOUS AREA: **43**

MATERIAL DESCRIPTION: **4" Tan Vinyl Baseboard Adhesive**

MATERIAL LOCATION: **Modular corridor and classrooms**

MATERIAL QUANTITY: **1000**

MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **03/31/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24931** BUIDLING ID: **5390**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kathy Yurks**
SCHOOL NAME: **Ruiz School** INSPECTION DATE: **3/25/2013**
ADDRESS: **2410 S.Leavitt** IDPH LICENSE NO: **100-8785**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **44**
MATERIAL DESCRIPTION: **Drywall**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT


This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Through-out Modular Unit**
MATERIAL QUANTITY: **5200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____



Date: 03/25/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24931** BUIDLING ID: **5390**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Ruiz School** REVIEW DATE: **3/31/2013**
ADDRESS: **2410 S.Leavitt** IDPH LICENSE NO: **100-8785**

HOMOGENEOUS AREA: **44**
MATERIAL DESCRIPTION: **Drywall**
MATERIAL LOCATION: **Through-out Modular Unit**
MATERIAL QUANTITY: **5200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **03/31/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24931** BUIDLING ID: **5390**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kathy Yurks**
SCHOOL NAME: **Ruiz School** INSPECTION DATE: **3/25/2013**
ADDRESS: **2410 S.Leavitt** IDPH LICENSE NO: **100-8785**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **45**
MATERIAL DESCRIPTION: **Fire Door Insulation**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**

MATERIAL LOCATION: **Entrances of Modular Unit**

MATERIAL QUANTITY: **160**


MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 03/25/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24931** BUIDLING ID: **5390**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Ruiz School** REVIEW DATE: **3/31/2013**
ADDRESS: **2410 S.Leavitt** IDPH LICENSE NO: **100-8785**

HOMOGENEOUS AREA: **45**

MATERIAL DESCRIPTION: **Fire Door Insulation**

MATERIAL LOCATION: **Entrances of Modular Unit**

MATERIAL QUANTITY: **160**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **03/31/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24931** BUIDLING ID: **5390**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kathy Yurks**
SCHOOL NAME: **Ruiz School** INSPECTION DATE: **3/25/2013**
ADDRESS: **2410 S.Leavitt** IDPH LICENSE NO: **100-8785**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **46**
MATERIAL DESCRIPTION: **Drywall Joint Compound**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**

MATERIAL LOCATION: **Through-out Modular**

MATERIAL QUANTITY: **1500**

MATERIAL UNITS: **LF**

DAMAGE QUANTITY:

DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: _____



Date: 03/25/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24931** BUIDLING ID: **5390**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Ruiz School** REVIEW DATE: **3/31/2013**
ADDRESS: **2410 S.Leavitt** IDPH LICENSE NO: **100-8785**

HOMOGENEOUS AREA: **46**
MATERIAL DESCRIPTION: **Drywall Joint Compound**
MATERIAL LOCATION: **Through-out Modular**
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **03/31/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24931** BUIDLING ID: **5390**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kathy Yurks**
SCHOOL NAME: **Ruiz School** INSPECTION DATE: **3/25/2013**
ADDRESS: **2410 S.Leavitt** IDPH LICENSE NO: **100-8785**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **47**
MATERIAL DESCRIPTION: **Beige Vinyl Flooring**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Men's and Women's Washrooms in Modular**
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 03/25/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24931** BUIDLING ID: **5390**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Ruiz School** REVIEW DATE: **3/31/2013**
ADDRESS: **2410 S.Leavitt** IDPH LICENSE NO: **100-8785**

HOMOGENEOUS AREA: **47**
MATERIAL DESCRIPTION: **Beige Vinyl Flooring**
MATERIAL LOCATION: **Men's and Women's Washrooms in Modular**
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **03/31/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24931** BUIDLING ID: **5390**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kathy Yurks**
SCHOOL NAME: **Ruiz School** INSPECTION DATE: **3/25/2013**
ADDRESS: **2410 S.Leavitt** IDPH LICENSE NO: **100-8785**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **48**
MATERIAL DESCRIPTION: **Beige Vinyl Flooring Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Men's and Women's Washrooms in Modular**
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 03/25/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24931** BUIDLING ID: **5390**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Ruiz School** REVIEW DATE: **3/31/2013**
ADDRESS: **2410 S.Leavitt** IDPH LICENSE NO: **100-8785**

HOMOGENEOUS AREA: **48**
MATERIAL DESCRIPTION: **Beige Vinyl Flooring Mastic**
MATERIAL LOCATION: **Men's and Women's Washrooms in Modular**
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **03/31/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24931** BUIDLING ID: **5390**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kathy Yurks**
SCHOOL NAME: **Ruiz School** INSPECTION DATE: **3/25/2013**
ADDRESS: **2410 S.Leavitt** IDPH LICENSE NO: **100-8785**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **49**
MATERIAL DESCRIPTION: **Drywall Joint Tape**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**

MATERIAL LOCATION: **Through-out Modular**

MATERIAL QUANTITY: **1000**


MATERIAL UNITS: **LF**

DAMAGE QUANTITY:

DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: _____



Date: 03/25/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24931** BUIDLING ID: **5390**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Ruiz School** REVIEW DATE: **3/31/2013**
ADDRESS: **2410 S.Leavitt** IDPH LICENSE NO: **100-8785**

HOMOGENEOUS AREA: **49**
MATERIAL DESCRIPTION: **Drywall Joint Tape**
MATERIAL LOCATION: **Through-out Modular**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **03/31/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24931** BUIDLING ID: **5390**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kathy Yurks**
SCHOOL NAME: **Ruiz School** INSPECTION DATE: **3/25/2013**
ADDRESS: **2410 S.Leavitt** IDPH LICENSE NO: **100-8785**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **5**
MATERIAL DESCRIPTION: **12" x 12" Pink Mix Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **2nd Floor Corridor & Storage and stairwells**
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____



Date: 03/25/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24931** BUIDLING ID: **5390**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Ruiz School** REVIEW DATE: **3/31/2013**
ADDRESS: **2410 S.Leavitt** IDPH LICENSE NO: **100-8785**

HOMOGENEOUS AREA: **5**
MATERIAL DESCRIPTION: **12" x 12" Pink Mix Floor Tile**
MATERIAL LOCATION: **2nd Floor Corridor & Storage and stairwells**
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **03/31/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24931** BUIDLING ID: **5390**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kathy Yurks**
SCHOOL NAME: **Ruiz School** INSPECTION DATE: **3/25/2013**
ADDRESS: **2410 S.Leavitt** IDPH LICENSE NO: **100-8785**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **50**
MATERIAL DESCRIPTION: **12x12 Brown & White Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Rm 310**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 03/25/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24931** BUIDLING ID: **5390**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Ruiz School** REVIEW DATE: **3/31/2013**
ADDRESS: **2410 S.Leavitt** IDPH LICENSE NO: **100-8785**

HOMOGENEOUS AREA: **50**

MATERIAL DESCRIPTION: **12x12 Brown & White Floor Tile**

MATERIAL LOCATION: **Rm 310**

MATERIAL QUANTITY: **800**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **03/31/2013**

Chicago Public Schools

Carnow, Conibear and Associates 2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24931** BUIDLING ID: **5390**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kathy Yurks**
SCHOOL NAME: **Ruiz School** INSPECTION DATE: **3/25/2013**
ADDRESS: **2410 S.Leavitt** IDPH LICENSE NO: **100-8785**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **51**
MATERIAL DESCRIPTION: **12x12 Brown & White Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Rm 310**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 03/25/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24931** BUIDLING ID: **5390**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Ruiz School** REVIEW DATE: **3/31/2013**
ADDRESS: **2410 S.Leavitt** IDPH LICENSE NO: **100-8785**

HOMOGENEOUS AREA: **51**
MATERIAL DESCRIPTION: **12x12 Brown & White Floor Tile Mastic**
MATERIAL LOCATION: **Rm 310**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **03/31/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24931** BUIDLING ID: **5390**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kathy Yurks**
SCHOOL NAME: **Ruiz School** INSPECTION DATE: **3/25/2013**
ADDRESS: **2410 S.Leavitt** IDPH LICENSE NO: **100-8785**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **52**
MATERIAL DESCRIPTION: **12x12 Brown & White Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Rm 313**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 03/25/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24931** BUIDLING ID: **5390**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Ruiz School** REVIEW DATE: **3/31/2013**
ADDRESS: **2410 S.Leavitt** IDPH LICENSE NO: **100-8785**

HOMOGENEOUS AREA: **52**
MATERIAL DESCRIPTION: **12x12 Brown & White Floor Tile**
MATERIAL LOCATION: **Rm 313**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **03/31/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24931** BUIDLING ID: **5390**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kathy Yurks**
SCHOOL NAME: **Ruiz School** INSPECTION DATE: **3/25/2013**
ADDRESS: **2410 S.Leavitt** IDPH LICENSE NO: **100-8785**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **53**
MATERIAL DESCRIPTION: **12x12 Brown & White Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Rm 313**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 03/25/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24931** BUIDLING ID: **5390**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Ruiz School** REVIEW DATE: **3/31/2013**
ADDRESS: **2410 S.Leavitt** IDPH LICENSE NO: **100-8785**

HOMOGENEOUS AREA: **53**
MATERIAL DESCRIPTION: **12x12 Brown & White Floor Tile Mastic**
MATERIAL LOCATION: **Rm 313**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **03/31/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24931** BUIDLING ID: **5390**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kathy Yurks**
SCHOOL NAME: **Ruiz School** INSPECTION DATE: **3/25/2013**
ADDRESS: **2410 S.Leavitt** IDPH LICENSE NO: **100-8785**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **54**
MATERIAL DESCRIPTION: **Rubber Flooring Material**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**


MATERIAL LOCATION: **Gym**

MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 03/25/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24931** BUIDLING ID: **5390**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Ruiz School** REVIEW DATE: **3/31/2013**
ADDRESS: **2410 S.Leavitt** IDPH LICENSE NO: **100-8785**

HOMOGENEOUS AREA: **54**
MATERIAL DESCRIPTION: **Rubber Flooring Material**
MATERIAL LOCATION: **Gym**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **03/31/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24931** BUIDLING ID: **5390**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kathy Yurks**
SCHOOL NAME: **Ruiz School** INSPECTION DATE: **3/25/2013**
ADDRESS: **2410 S.Leavitt** IDPH LICENSE NO: **100-8785**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **55**
MATERIAL DESCRIPTION: **Rubber Flooring Material Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Gym**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 03/25/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24931** BUIDLING ID: **5390**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Ruiz School** REVIEW DATE: **3/31/2013**
ADDRESS: **2410 S.Leavitt** IDPH LICENSE NO: **100-8785**

HOMOGENEOUS AREA: **55**
MATERIAL DESCRIPTION: **Rubber Flooring Material Mastic**
MATERIAL LOCATION: **Gym**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **03/31/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24931** BUIDLING ID: **5390**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kathy Yurks**
SCHOOL NAME: **Ruiz School** INSPECTION DATE: **3/25/2013**
ADDRESS: **2410 S.Leavitt** IDPH LICENSE NO: **100-8785**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **6**
MATERIAL DESCRIPTION: **12" x 12" Pink Mix Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**

MATERIAL LOCATION: **2nd Floor Corridor & Storage**

MATERIAL QUANTITY: **2000**


MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 03/25/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24931** BUIDLING ID: **5390**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Ruiz School** REVIEW DATE: **3/31/2013**
ADDRESS: **2410 S.Leavitt** IDPH LICENSE NO: **100-8785**

HOMOGENEOUS AREA: **6**
MATERIAL DESCRIPTION: **12" x 12" Pink Mix Floor Tile Mastic**
MATERIAL LOCATION: **2nd Floor Corridor & Storage**
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **03/31/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24931** BUIDLING ID: **5390**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kathy Yurks**
SCHOOL NAME: **Ruiz School** INSPECTION DATE: **3/25/2013**
ADDRESS: **2410 S.Leavitt** IDPH LICENSE NO: **100-8785**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **7**
MATERIAL DESCRIPTION: **12" x 12" Beige Mix Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**


MATERIAL LOCATION: **Classrooms 201-212, 213 Closet, and 218**

MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 03/25/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24931** BUIDLING ID: **5390**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Ruiz School** REVIEW DATE: **3/31/2013**
ADDRESS: **2410 S.Leavitt** IDPH LICENSE NO: **100-8785**

HOMOGENEOUS AREA: **7**
MATERIAL DESCRIPTION: **12" x 12" Beige Mix Floor Tile**
MATERIAL LOCATION: **Classrooms 201-212, 213 Closet, and 218**
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **03/31/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24931** BUIDLING ID: **5390**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kathy Yurks**
SCHOOL NAME: **Ruiz School** INSPECTION DATE: **3/25/2013**
ADDRESS: **2410 S.Leavitt** IDPH LICENSE NO: **100-8785**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **8**
MATERIAL DESCRIPTION: **12" x 12" Beige Mix Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**


MATERIAL LOCATION: **Classrooms 201-212, 213 Closet, and 218**

MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 03/25/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24931** BUIDLING ID: **5390**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Ruiz School** REVIEW DATE: **3/31/2013**
ADDRESS: **2410 S.Leavitt** IDPH LICENSE NO: **100-8785**

HOMOGENEOUS AREA: **8**
MATERIAL DESCRIPTION: **12" x 12" Beige Mix Floor Tile Mastic**
MATERIAL LOCATION: **Classrooms 201-212, 213 Closet, and 218**
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **03/31/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24931** BUIDLING ID: **5390**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kathy Yurks**
SCHOOL NAME: **Ruiz School** INSPECTION DATE: **3/25/2013**
ADDRESS: **2410 S.Leavitt** IDPH LICENSE NO: **100-8785**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **9**
MATERIAL DESCRIPTION: **12" x 12" Brown Mix Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**


MATERIAL LOCATION: **1st Floor Corridor, Cafeteria, Janitor's Closet, Storage**

MATERIAL QUANTITY: **2500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 03/25/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24931** BUIDLING ID: **5390**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Ruiz School** REVIEW DATE: **3/31/2013**
ADDRESS: **2410 S.Leavitt** IDPH LICENSE NO: **100-8785**

HOMOGENEOUS AREA: **9**
MATERIAL DESCRIPTION: **12" x 12" Brown Mix Floor Tile**
MATERIAL LOCATION: **1st Floor Corridor, Cafeteria, Janitor's Closet, Storage**
MATERIAL QUANTITY: **2500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **03/31/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24931** BUIDLING ID: **5390**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kathy Yurks**
SCHOOL NAME: **Ruiz School** INSPECTION DATE: **3/25/2013**
ADDRESS: **2410 S.Leavitt** IDPH LICENSE NO: **100-8785**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **MB-6**
MATERIAL DESCRIPTION: **Orange Sheet Flooring Adhesive**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**

MATERIAL LOCATION: **Girl's Washroom**

MATERIAL QUANTITY: **160**


MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 03/25/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24931** BUIDLING ID: **5390**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Ruiz School** REVIEW DATE: **3/31/2013**
ADDRESS: **2410 S.Leavitt** IDPH LICENSE NO: **100-8785**

HOMOGENEOUS AREA: **MB-6**
MATERIAL DESCRIPTION: **Orange Sheet Flooring Adhesive**
MATERIAL LOCATION: **Girl's Washroom**
MATERIAL QUANTITY: **160** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **03/31/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION


Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24931** BUILDING ID: **5390**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kathy Yurks**
SCHOOL NAME: **Ruiz School** INSPECTION DATE: **3/25/2013**
ADDRESS: **2410 S.Leavitt** IDPH LICENSE NO: **100-8785**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **56**
MATERIAL DESCRIPTION: **Blue Ceramic Tile**
MATERIAL LOCATION: **3rd Floor Boy's/girl'/Teacher's Washrroom**
MATERIAL QUANTITY: **700** MATERIAL UNITS: **SF**
MATERIAL CATEGORY: **MISC** FRIABLE: **No**
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **MODERATE** CONDITION:
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
ACCESSIBILITY: **Within Reach** DAMAGE REASON:
DAMAGE QUANTITY: **0** DAMAGE REASON:
DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____



Date: 03/25/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24931** BUILDING ID: **5390**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Ruiz School** REVIEW DATE: **3/31/2013**
ADDRESS: **2410 S.Leavitt** IDPH LICENSE NO: **100-8785**


HOMOGENEOUS AREA: **56**
MATERIAL DESCRIPTION: **Blue Ceramic Tile**
MATERIAL LOCATION: **3rd Floor Boy's/girl/Teacher's Washrroom**
MATERIAL QUANTITY: **700** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____



Date: **03/31/2013**



ASBESTOS REINSPECTION KEY NOTES:

 HA-56 Blue Ceramic Tile

Ruiz School Third Floor
2013 ASBESTOS REINSPECTION



CLIENT:
Chicago Public Schools
125 South Clark Street,
Chicago, Illinois 60603

PROJECT NAME:
2013 AHERA Reinspection
Ruiz Elementary School
2410 S. Leavitt St.
Chicago, IL 60608

SHEET NAME:
Ruiz School Third Floor -
HA-56

INSPECTED BY:
Kathy Yurks

| | | |
|--------------|----------------|-------------|
| DRAWN BY: JH | DATE: 4/3/2013 | CHECKED BY: |
| REVISED BY: | DATE: | CHECKED BY: |
| REVISED BY: | DATE: | CHECKED BY: |
| REVISED BY: | DATE: | CHECKED BY: |

IDPH License #:100- 08785

Carnow, Conibear & Assoc., Ltd.
Environmental Consulting Services
600 W. Van Buren St., Suite 500, Chicago, IL 60607
t: 312.782.4486 f: 312.782.5145
www.ccaatd.com



CCA PROJECT NUMBER
A320130001-236

DATE
3/25/2013

SHEET NUMBER
HA-56

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION


Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24931** BUILDING ID: **5390**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kathy Yurks**
SCHOOL NAME: **Ruiz School** INSPECTION DATE: **3/25/2013**
ADDRESS: **2410 S.Leavitt** IDPH LICENSE NO: **100-8785**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **60**
MATERIAL DESCRIPTION: **Gray Ceramic Tile**
MATERIAL LOCATION: **1st Floor Boy's/girl'/Teacher's Washrroom**
MATERIAL QUANTITY: **700** MATERIAL UNITS: **SF**
MATERIAL CATEGORY: **MISC** FRIABLE: **No**
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **MODERATE** CONDITION:
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
ACCESSIBILITY: **Within Reach** DAMAGE REASON:
DAMAGE QUANTITY: **0** DAMAGE REASON:
DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____



Date: 03/25/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24931** BUILDING ID: **5390**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Ruiz School** REVIEW DATE: **3/31/2013**
ADDRESS: **2410 S.Leavitt** IDPH LICENSE NO: **100-8785**


HOMOGENEOUS AREA: **60**
MATERIAL DESCRIPTION: **Gray Ceramic Tile**
MATERIAL LOCATION: **1st Floor Boy's/girl'/Teacher's Washrroom**
MATERIAL QUANTITY: **700** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:  _____ Date: **03/31/2013**



ASBESTOS REINSPECTION KEY NOTES:

 HA-60 Gray Ceramic Tile

Ruiz School First Floor
 2013 ASBESTOS REINSPECTION



CLIENT:
 Chicago Public Schools
 125 South Clark Street,
 Chicago, Illinois 60603

PROJECT NAME:
 2013 AHERA Reinspection
 Ruiz Elementary School
 2410 S. Leavitt St.
 Chicago, IL 60608

SHEET NAME:
 Ruiz School First Floor -
 HA-60

INSPECTED BY:
 Kathy Yurks

| | | |
|--------------|----------------|-------------|
| DRAWN BY: JH | DATE: 4/3/2013 | CHECKED BY: |
| REVISED BY: | DATE: | CHECKED BY: |
| REVISED BY: | DATE: | CHECKED BY: |
| REVISED BY: | DATE: | CHECKED BY: |

IDPH License #:100- 08785

Carnow, Conibear & Assoc., Ltd.
 Environmental Consulting Services
 600 W. Van Buren St., Suite 500, Chicago, IL 60607
 t: 312.782.4486 f: 312.782.5145
 www.ccaatd.com



CCA PROJECT NUMBER
 A320130001-236

DATE
 3/25/2013

SHEET NUMBER

KCPSS 2013/03/25 Three Year/Local Drinking Water AHERA Ruiz School First Floor.dwg

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION


Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24931** BUILDING ID: **5390**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kathy Yurks**
SCHOOL NAME: **Ruiz School** INSPECTION DATE: **3/25/2013**
ADDRESS: **2410 S.Leavitt** IDPH LICENSE NO: **100-8785**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **57**
MATERIAL DESCRIPTION: **Blue Ceramic Grout**
MATERIAL LOCATION: **3rd Floor Boy's/girl/Teacher's Washrroom**
MATERIAL QUANTITY: **700** MATERIAL UNITS: **SF**
MATERIAL CATEGORY: **MISC** FRIABLE: **No**
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **MODERATE** CONDITION:
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
ACCESSIBILITY: **Not Reachable** DAMAGE REASON:
DAMAGE QUANTITY: **0** DAMAGE REASON:
DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____



Date: 03/25/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24931** BUILDING ID: **5390**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Ruiz School** REVIEW DATE: **3/31/2013**
ADDRESS: **2410 S.Leavitt** IDPH LICENSE NO: **100-8785**


HOMOGENEOUS AREA: **57**
MATERIAL DESCRIPTION: **Blue Ceramic Grout**
MATERIAL LOCATION: **3rd Floor Boy's/girl/Teacher's Washrroom**
MATERIAL QUANTITY: **700** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____



Date: **03/31/2013**



ASBESTOS REINSPECTION KEY NOTES:

 HA-57 Blue Ceramic Grout

Ruiz School Third Floor

2013 ASBESTOS REINSPECTION



CLIENT:
Chicago Public Schools
125 South Clark Street,
Chicago, Illinois 60603

PROJECT NAME:
2013 AHERA Reinspection
Ruiz Elementary School
2410 S. Leavitt St.
Chicago, IL 60608

SHEET NAME:
Ruiz School Third Floor -
HA-57

INSPECTED BY:
Kathy Yurks

| | | |
|--------------|----------------|-------------|
| DRAWN BY: JH | DATE: 4/3/2013 | CHECKED BY: |
| REVISED BY: | DATE: | CHECKED BY: |
| REVISED BY: | DATE: | CHECKED BY: |
| REVISED BY: | DATE: | CHECKED BY: |

IDPH License #:100- 08785

Carnow, Conibear & Assoc., Ltd.
Environmental Consulting Services
600 W. Van Buren St., Suite 500, Chicago, IL 60607
t: 312.782.4486 f: 312.782.5145
www.ccaatd.com

CCA PROJECT NUMBER
A320130001-236

DATE
3/25/2013

SHEET NUMBER

**CARNOW
CONIBEAR** HA-57

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION


Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24931** BUILDING ID: **5390**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kathy Yurks**
SCHOOL NAME: **Ruiz School** INSPECTION DATE: **3/25/2013**
ADDRESS: **2410 S.Leavitt** IDPH LICENSE NO: **100-8785**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **61**
MATERIAL DESCRIPTION: **Gray Ceramic Grout**
MATERIAL LOCATION: **1st Floor Boy's/girl/Teacher's Washrroom**
MATERIAL QUANTITY: **700** MATERIAL UNITS: **SF**
MATERIAL CATEGORY: **MISC** FRIABLE: **No**
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **MODERATE** CONDITION:
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
ACCESSIBILITY: **Not Reachable** DAMAGE REASON:
DAMAGE QUANTITY: **0** DAMAGE REASON:
DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____



Date: 03/25/2013

Chicago Public Schools

Carnow, Conibear and Associates 2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24931** BUILDING ID: **5390**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Ruiz School** REVIEW DATE: **3/31/2013**
ADDRESS: **2410 S.Leavitt** IDPH LICENSE NO: **100-8785**


HOMOGENEOUS AREA: **61**
MATERIAL DESCRIPTION: **Gray Ceramic Grout**
MATERIAL LOCATION: **1st Floor Boy's/girl'/Teacher's Washrroom**
MATERIAL QUANTITY: **700** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.


The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____



Date: **03/31/2013**



ASBESTOS REINSPECTION KEY NOTES:

 HA-61 Gray Ceramic Grout

Ruiz School First Floor
2013 ASBESTOS REINSPECTION



CLIENT:
Chicago Public Schools
125 South Clark Street,
Chicago, Illinois 60603

PROJECT NAME:
2013 AHERA Reinspection
Ruiz Elementary School
2410 S. Leavitt St.
Chicago, IL 60608

SHEET NAME:
Ruiz School First Floor -
HA-61
INSPECTED BY:
Kathy Yurks

| | | |
|--------------|----------------|-------------|
| DRAWN BY: JH | DATE: 4/3/2013 | CHECKED BY: |
| REVISED BY: | DATE: | CHECKED BY: |
| REVISED BY: | DATE: | CHECKED BY: |
| REVISED BY: | DATE: | CHECKED BY: |

IDPH License #:100- 08785

Carnow, Conibear & Assoc., Ltd.
Environmental Consulting Services
600 W. Van Buren St., Suite 500, Chicago, IL 60607
t: 312.782.4486 f: 312.782.5145
www.ccaatd.com

CCA PROJECT NUMBER
A320130001-236
DATE
3/25/2013
SHEET NUMBER



KCPSS 2013/03/25 Three Year/Local Drinking Water/Regular AHERA/ Ruiz School/Elementary School/Floor/eng

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION


Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24931** BUILDING ID: **5390**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kathy Yurks**
SCHOOL NAME: **Ruiz School** INSPECTION DATE: **3/25/2013**
ADDRESS: **2410 S.Leavitt** IDPH LICENSE NO: **100-8785**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **59**
MATERIAL DESCRIPTION: **Tan Ceramic Grout**
MATERIAL LOCATION: **2nd Floor Boy's/girl'/Teacher's Washrroom**
MATERIAL QUANTITY: **700** MATERIAL UNITS: **SF**
MATERIAL CATEGORY: **MISC** FRIABLE: **No**
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **MODERATE** CONDITION:
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
ACCESSIBILITY: **Not Reachable** DAMAGE REASON:
DAMAGE QUANTITY: **0** DAMAGE REASON:
DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____



Date: 03/25/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24931** BUILDING ID: **5390**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Ruiz School** REVIEW DATE: **3/31/2013**
ADDRESS: **2410 S.Leavitt** IDPH LICENSE NO: **100-8785**

HOMOGENEOUS AREA: **59**

MATERIAL DESCRIPTION: **Tan Ceramic Grout**

MATERIAL LOCATION: **2nd Floor Boy's/girl'/Teacher's Washrroom**

MATERIAL QUANTITY: **700** MATERIAL UNITS: **SF**


DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____



Date: **03/31/2013**

IRMA RUIZ ELEMENTARY SCHOOL



Key: HA-59 Tan Ceramic Grout

SECOND FLOOR

ASBESTOS REINSPECTION KEY NOTES:

 HA-59 Tan Ceramic Grout

Ruiz School Second Floor
2013 ASBESTOS REINSPECTION



CLIENT:
Chicago Public Schools
125 South Clark Street,
Chicago, Illinois 60603

PROJECT NAME:
2013 AHERA Reinspection
Ruiz Elementary School
2410 S. Leavitt St.
Chicago, IL 60608

SHEET NAME:
Ruiz School Second Floor -
HA-59
INSPECTED BY:
Kathy Yurks

| | | |
|--------------|----------------|-------------|
| DRAWN BY: JH | DATE: 4/3/2013 | CHECKED BY: |
| REVISED BY: | DATE: | CHECKED BY: |
| REVISED BY: | DATE: | CHECKED BY: |
| REVISED BY: | DATE: | CHECKED BY: |

IDPH License #:100- 08785

Carnow, Conibear & Assoc., Ltd.
Environmental Consulting Services
600 W. Van Buren St., Suite 500, Chicago, IL 60607
t: 312.782.4486 f: 312.782.5145
www.ccaatd.com

**CARNOW
CONIBEAR**

CCA PROJECT NUMBER
A320130001-236
DATE
3/25/2013
SHEET NUMBER
HA-59

KCPSS 2013/03/25 These Yearbook Drawings/Plans are for Ruiz School Second Floor only

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION


Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24931** BUILDING ID: **5390**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kathy Yurks**
SCHOOL NAME: **Ruiz School** INSPECTION DATE: **3/25/2013**
ADDRESS: **2410 S.Leavitt** IDPH LICENSE NO: **100-8785**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **62**
MATERIAL DESCRIPTION: **Dark Brown Ceramic Tile**
MATERIAL LOCATION: **Kitchen/Service area**
MATERIAL QUANTITY: **1100** MATERIAL UNITS: **SF**
MATERIAL CATEGORY: **MISC** FRIABLE: **No**
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **MODERATE** CONDITION:
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
ACCESSIBILITY: **Within Reach** DAMAGE REASON:
DAMAGE QUANTITY: **0** DAMAGE REASON:
DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____



Date: 03/25/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24931** BUILDING ID: **5390**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Ruiz School** REVIEW DATE: **3/31/2013**
ADDRESS: **2410 S.Leavitt** IDPH LICENSE NO: **100-8785**


HOMOGENEOUS AREA: **62**
MATERIAL DESCRIPTION: **Dark Brown Ceramic Tile**
MATERIAL LOCATION: **Kitchen/Service area**
MATERIAL QUANTITY: **1100** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.


The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____



Date: **03/31/2013**



ASBESTOS REINSPECTION KEY NOTES:

 HA-62 Dark Brown Ceramic Tile

Ruiz School First Floor
2013 ASBESTOS REINSPECTION



CLIENT:
Chicago Public Schools
125 South Clark Street,
Chicago, Illinois 60603

PROJECT NAME:
2013 AHERA Reinspection
Ruiz Elementary School
2410 S. Leavitt St.
Chicago, IL 60608

SHEET NAME:
Ruiz School First Floor -
HA-62
INSPECTED BY:
Kathy Yurks

| | | |
|--------------|----------------|-------------|
| DRAWN BY: JH | DATE: 4/3/2013 | CHECKED BY: |
| REVISED BY: | DATE: | CHECKED BY: |
| REVISED BY: | DATE: | CHECKED BY: |
| REVISED BY: | DATE: | CHECKED BY: |

IDPH License #:100- 08785

Carnow, Conibear & Assoc., Ltd.
Environmental Consulting Services
600 W. Van Buren St., Suite 500, Chicago, IL 60607
t: 312.782.4486 f: 312.782.5145
www.ccaatd.com

**CARNOW
CONIBEAR**

CCA PROJECT NUMBER
A320130001-236
DATE
3/25/2013
SHEET NUMBER
HA-62

KCPSS 2011/2013 Three Year Local Drinking Water AHERA Ruiz School First Floor.dwg

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION


Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24931** BUILDING ID: **5390**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kathy Yurks**
SCHOOL NAME: **Ruiz School** INSPECTION DATE: **3/25/2013**
ADDRESS: **2410 S.Leavitt** IDPH LICENSE NO: **100-8785**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **58**
MATERIAL DESCRIPTION: **Tan Ceramic Tile**
MATERIAL LOCATION: **2nd Floor Boy's/girl'/Teacher's Washrroom**
MATERIAL QUANTITY: **700** MATERIAL UNITS: **SF**
MATERIAL CATEGORY: **MISC** FRIABLE: **No**
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **MODERATE** CONDITION:
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
ACCESSIBILITY: **Within Reach** DAMAGE REASON:
DAMAGE QUANTITY: **0** DAMAGE REASON:
DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____



Date: 03/25/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24931** BUILDING ID: **5390**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Ruiz School** REVIEW DATE: **3/31/2013**
ADDRESS: **2410 S.Leavitt** IDPH LICENSE NO: **100-8785**

HOMOGENEOUS AREA: **58**

MATERIAL DESCRIPTION: **Tan Ceramic Tile**

MATERIAL LOCATION: **2nd Floor Boy's/girl'/Teacher's Washrroom**

MATERIAL QUANTITY: **700** MATERIAL UNITS: **SF**


DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:


COMMENTS:

Management Planner's Signature: _____



Date: **03/31/2013**

IRMA RUIZ ELEMENTARY SCHOOL



Key: HA-58 Tan Ceramic Tile

SECOND FLOOR

ASBESTOS REINSPECTION KEY NOTES:

 HA-58 Tan Ceramic Tile

Ruiz School Second Floor
2013 ASBESTOS REINSPECTION



CLIENT:
Chicago Public Schools
125 South Clark Street,
Chicago, Illinois 60603

PROJECT NAME:
2013 AHERA Reinspection
Ruiz Elementary School
2410 S. Leavitt St.
Chicago, IL 60608

SHEET NAME:
Ruiz School Second Floor -
HA-58
INSPECTED BY:
Kathy Yurks

| | | |
|--------------|----------------|-------------|
| DRAWN BY: JH | DATE: 4/3/2013 | CHECKED BY: |
| REVISED BY: | DATE: | CHECKED BY: |
| REVISED BY: | DATE: | CHECKED BY: |
| REVISED BY: | DATE: | CHECKED BY: |

IDPH License #:100- 08785

Carnow, Conibear & Assoc., Ltd.
Environmental Consulting Services
600 W. Van Buren St., Suite 500, Chicago, IL 60607
t: 312.782.4486 f: 312.782.5145
www.ccaatd.com

**CARNOW
CONIBEAR**

CCA PROJECT NUMBER
A320130001-236
DATE
3/25/2013
SHEET NUMBER
HA-58

KCPSS 2013/03/25 These Yearbook Drawings/Plans are for Ruiz School Second Floor/2nd

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION


Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24931** BUILDING ID: **5390**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kathy Yurks**
SCHOOL NAME: **Ruiz School** INSPECTION DATE: **3/25/2013**
ADDRESS: **2410 S.Leavitt** IDPH LICENSE NO: **100-8785**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **63**
MATERIAL DESCRIPTION: **Dark Brown Ceramic Grout**
MATERIAL LOCATION: **Kitchen/Serving Area**
MATERIAL QUANTITY: **1100** MATERIAL UNITS: **SF**
MATERIAL CATEGORY: **MISC** FRIABLE: **No**
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **LOW** CONDITION:
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
ACCESSIBILITY: **Within Reach** DAMAGE REASON:
DAMAGE QUANTITY: **0** DAMAGE REASON:
DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____



Date: 03/25/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24931** BUILDING ID: **5390**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Ruiz School** REVIEW DATE: **3/31/2013**
ADDRESS: **2410 S.Leavitt** IDPH LICENSE NO: **100-8785**


HOMOGENEOUS AREA: **63**
MATERIAL DESCRIPTION: **Dark Brown Ceramic Grout**
MATERIAL LOCATION: **Kitchen/Serving Area**
MATERIAL QUANTITY: **1100** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:  _____ Date: **03/31/2013**



ASBESTOS REINSPECTION KEY NOTES:

 HA-63 Dark Brown Ceramic Grout

Ruiz School First Floor
2013 ASBESTOS REINSPECTION



CLIENT:
Chicago Public Schools
125 South Clark Street,
Chicago, Illinois 60603

PROJECT NAME:
2013 AHERA Reinspection
Ruiz Elementary School
2410 S. Leavitt St.
Chicago, IL 60608

SHEET NAME:
Ruiz School First Floor -
HA-63
INSPECTED BY:
Kathy Yurks

| | | |
|--------------|----------------|-------------|
| DRAWN BY: JH | DATE: 4/3/2013 | CHECKED BY: |
| REVISED BY: | DATE: | CHECKED BY: |
| REVISED BY: | DATE: | CHECKED BY: |
| REVISED BY: | DATE: | CHECKED BY: |

IDPH License #:100- 08785

Carnow, Conibear & Assoc., Ltd.
Environmental Consulting Services
600 W. Van Buren St., Suite 500, Chicago, IL 60607
t: 312.782.4486 f: 312.782.5145
www.ccaatd.com


CARNOW CONIBEAR
HA-63

CCA PROJECT NUMBER
A320130001-236
DATE
3/25/2013
SHEET NUMBER

KCPSS 2011/2013 Three Year/Local Drinking Water AHERA Ruiz School First Floor.dwg

APPENDIX B

Inspector and Management Planner Licenses



Occupational Training & Supply, Inc.

7233 Adams Street • Willowbrook, IL 60527 • (630) 655-3900

Asbestos Building Inspector

Occupational Training and Supply, Inc. certifies that

Kathy Yurks

has successfully completed the 24 hour Asbestos Building Inspector Course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 10 CFR 763 Asbestos Hazard Emergency Response Act (AHERA) and TSCA Title II.

Certificate: ABIL206201045

Exam Date: 6/20/2012

Course Date: 6/18/2012-6/20/2012

Expiration Date: 6/20/2013

Kathy DeSalvo, Director

2012



**ASBESTOS
PROFESSIONAL
LICENSE**

ID NUMBER
100 - 08785

ISSUED
1/24/2013

EXPIRES
05/15/2014

KATHY YURKS
101 ROHRER PO BOX 32
MUNCU, IL 61857

Environmental Health



ENDORSEMENTS

TC EXPIRES

INSPECTOR

6/20/2013

AIR SAMPLING PROFESSIONAL

Alteration of this license shall result in legal action
This license issued under authority of the State of Illinois
Department of Public Health
This license is valid only when accompanied by a valid
training course certificate.



Occupational Training & Supply, Inc.

7233 Adams Street • Willowbrook, IL 60527 • (630) 655-3900

Asbestos Building Inspector Refresher

Occupational Training and Supply, Inc. certifies that

Daniel Juneau

has successfully completed the 4 hour Asbestos Building Inspector Refresher Course
and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department
of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance
with EPA 10 CFR 763 Asbestos Hazard Emergency Response Act (AHERA) and TSCA Title II.

Certificate: BIR1212042319


Exam Date: 12/4/2012

Course Date: 12/4/2012

Expiration Date: 12/4/2013

Kathy DeSalvo, Director

2012



Occupational Training & Supply, Inc.

7233 Adams Street ♦ Willowbrook, IL 60527 ♦ (630) 655-3900

Asbestos Management Planner Refresher

Occupational Training and Supply, Inc. certifies that

Daniel Juneau


has successfully completed the 4 hour Asbestos Management Planner Refresher Course
and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 10 CFR 763 Asbestos Hazard Emergency Response Act (AHERA) and TSCA Title II.

Certificate: MPR1302250736


Exam Date: 2/25/2013

Course Date: 2/25/2013

Expiration Date: 2/25/2014


Kathy DeSalvo, Director

2013



Occupational Training & Supply, Inc.

7233 Adams Street ♦ Willowbrook, IL 60527 ♦ (630) 655-3900

Asbestos Management Planner Refresher

Occupational Training and Supply, Inc. certifies that

Daniel Juneau

has successfully completed the 4 hour Asbestos Management Planner Refresher Course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 10 CFR 763 Asbestos Hazard Emergency Response Act (AHERA) and TSCA Title II.

Certificate: MPR1302250736

Exam Date: 2/25/2013

Course Date: 2/25/2013

Expiration Date: 2/25/2014

Kathy DeSalvo, Director

2013

Daniel Juneau

Illinois Licensed Asbestos Inspector, Management Planner,
Project Manager, and Air Sampling Professional



ASBESTOS PROFESSIONAL LICENSE

ID NUMBER
100 - 03613

ISSUED
4/11/2013

EXPIRES
05/15/2014

DANIEL J JUNEAU
1408 OAKWOOD AVENUE
DES PLAINES, IL 60016

Environmental Health



ENDORSEMENTS

TC EXPIRES

INSPECTOR

12/4/2013

MANAGEMENT PLANNER

2/25/2014

PROJECT MANAGER

12/3/2013

AIR SAMPLING PROFESSIONAL

Alteration of this license shall result in legal action
This license issued under authority of the State of Illinois
Department of Public Health

This license is valid only when accompanied by a valid
training course certificate.

**CARNOW
CONIBEAR**

APPENDIX C

Laboratory Accreditations

APPENDIX D

Laboratory Results

APPENDIX E

Chain of Custody Forms

Three-Year Reinspection Key to Terms

| | CODE | KEY |
|--------------------------|-------------|--|
| MATERIAL | | |
| | ACBM | Asbestos Containing Building Materials |
| MATERIAL CATEGORY | | |
| | MISC | Miscellaneous |
| | SURF | Surfacing |
| | TSI | Thermal System Insulation |
| MATERIAL UNITS | | |
| | LF | Linear Feet |
| | SF | Square Feet |
| | CF | Cubic Feet |
| DAMAGE TYPE | | |
| | Loc | Localized |
| | Dist | Distributed |