

ILLINOIS DEPARTMENT OF PUBLIC HEALTH  
AHERA THREE YEAR REINSPECTION  
ASBESTOS ABATEMENT PROGRAM  
SCHOOL INFORMATION FORM

**SECTION I**

NAME OF SCHOOL DISTRICT: CHICAGO SCHOOL DIST 299  
SCHOOL ID NUMBER: 14-016-2990-2806  
SCHOOL NAME: Kanoon Magnet  
ADDRESS OF SCHOOL: 2233 S. Kedzie  
CITY: Chicago, IL, 60623

DATE LAST THREE YEAR REINSPECTION WAS COMPLETED **2/19/2010**

**If the address on this form is different than the address of the building, submit a written explanation.**

**SECTION II** (Please type or print)

PLEASE COMPLETE THE FOLLOWING FOR YOUR THREE YEAR REINSPECTION:

DATE REINSPECTION COMPLETED: 4/2/2013 ENROLLMENT 766  
IDPH INSPECTOR LICENSE NUMBER: 100-11170  
IDPH LICENSED INSPECTOR NAME (Please Print): Jesus Delgado  
IDPH MP LICENSE NUMBER: 100-03613  
IDPH LICENSED MANAGEMENT PLANNER NAME (Please Print): Daniel Juneau

DESIGNATED PERSON (Please Print): Ms. Lynn Crivello PHONE: (773) 553-3113



4/2/2013

*Signature of Designated Person*

*Date*

**SECTION III**

PLEASE COMPLETE THE FOLLOWING INFORMATION FOR ANY CHANGES WITHIN THE SCHOOL DISTRICT.

School building has been sold. Date of Sale: \_\_\_\_\_

School has been closed. Date closed: \_\_\_\_\_

School building has been demolished. Date: \_\_\_\_\_

School building is asbestos free since last reinspection: \_\_\_\_\_

**Please explain in writing why the school building is now asbestos free and include the supporting documentation.**

If a new school building has been added to the district, submit either an exclusionary statement or a management plan and inspection report. Include the complete name, address and city of school building.

**Explain in writing if the address of the building is different than the address on this form:**

**THREE-YEAR REINSPECTION**

**CHICAGO SCHOOL DIST 299**

**Kanoon Magnet**

2233 S. Kedzie  
Chicago, IL, 60623

Unit: 29071  
Building ID: 3370

IDPH ID Number: 14-016-2990-2806

**REPORT DATE:**

Tuesday, April 02, 2013

**Prepared for:**

**Chicago Public Schools**  
**125 S. Clark Street**  
**Chicago, IL 60603**

**Prepared by:**

**Carnow, Conibear and Associates**

600 West Van Buren St., Ste 500

Phone (312) 762-2900

Fax (312) 782-5145

**DO NOT REMOVE FROM SCHOOL  
REQUIRED BY FEDERAL LAW**



## **Environmental Notification to Occupants**

To: Faculty, Staff and Parents  
From: Chicago Public Schools  
Date: March 19, 2013

RE: Kanoon Magnet, Unit 29071  
2233 S. Kedzie  
Chicago, IL, 60623

Dear Faculty, Staff and Parents,

This letter is to notify you that the 2013 asbestos three year re-inspection has been completed at Kanoon Magnet , following the Federal Asbestos Hazard Emergency Response Act (AHERA), 40 CFR Part 763, Subpart E and is available for your review at the main office of the school.

Although asbestos-containing materials have been identified at Kanoon Magnet, there is no reason to believe that any threat to the health of students or staff exists at this time. CPS will continue to carefully monitor the condition of asbestos-containing materials and if conditions warrant, all appropriate steps will be taken to maintain the health and safety of all building occupants.

If you have any questions regarding this matter or require additional information, please feel free to contact Ms. Lynn Crivello, the designated Local Education Authority's Designated Person at (773) 553-3113 .

## **Table of Contents**

- I. School and Inspection Information
- II. Executive Summary
- III. Methodology
- IV. Abatement History
- V. Reassessments and Recommendations
- VI. Conclusions

Table I: Inspector's Reinspection Findings

Table II: Management Planner's Review

### **APPENDICES:**

- Appendix A: Assessment Sheets, Drawings and Photos
- Appendix B: Inspector and Management Planner Licenses
- Appendix C: Laboratory Accreditations
- Appendix D: Laboratory Results
- Appendix E: Chain of Custody Forms

## SCHOOL AND INSPECTION INFORMATION

### 1. School Information

School: Kanoon Magnet  
Address: 2233 S. Kedzie  
IDPH ID: 14-016-2990-2806  
Contact: Torres, Henry

Unit: 29071  
Chicago, IL, 60623  
Building ID: 3370  
Phone: 773-450-2721

Region: 03

### 2. Description of Facility

Original Construction: 1980  
Total Square Footage: 65300  
Current Occupancy: 766

Additional Construction:  
No of Floors: 1

### 3. LEA Designated Person

Contact: Ms. Lynn Crivello  
Address: 125 South Clark Street, 17th Floor  
Chicago, IL 60603

Phone: (773) 553-3113

### 4. Managing Environmental Consultant

MEC: Carnow, Conibear and Associates  
Contact: Dan Juneau  
Address 600 West Van Buren St., Ste 500  
Phone: (312) 762-2900

Fax: (312) 782-5145

### 5. Inspector

Inspector Name: Jesus Delgado

Inspector IDPH license # 100-11170




Signature:  
Date: 3/19/2013

### 6. Management Planner

Management Planner Name: Daniel Juneau

Management Planner IDPH license # 100-03613



Signature:  
Date: 4/2/2013

### 7. Review Date: 4/2/2013

### 8. LEA Designated Person's Acknowledgement

The reinspection report and recommendations have been received by me and appropriate action will be taken by the School District.

Signature: 

Date: 4/2/2013

Name: Ms. Lynn Crivello

## II. EXECUTIVE SUMMARY

Carnow, Conibear and Associates was retained by the Chicago Public Schools (CPS) to perform a three-year asbestos reinspection of the Kanoon Magnet. This inspection was conducted in accordance with the United States Environmental Protection Agency (USEPA) Asbestos Hazard Emergency Response Act (AHERA) part 763.92 (b), and the ongoing Operations and Maintenance Program (O&M) originally designed in the School's Asbestos Management Plan. The purpose of this three-year reinspection is to record any condition changes in the asbestos-containing building material (ACBM) in the school since the previous three-year reinspection and the six-month periodic surveillance, to identify, assess, and include any Homogeneous Areas (HA) not identified in the Management Plan, and to recommend an appropriate response action to manage asbestos.

The inspector conducted a three-year reinspection of this facility under Illinois Department of Public Health (IDPH) school reinspection requirements and AHERA, sections 763.85 and 763.88. The main building and each addition to the main building, if constructed at different dates, were inspected separately. Laboratory accreditations are included in Appendix C, laboratory results are included in Appendix D, and chain of custody forms are included in Appendix E.

Note: During previous inspections, some of the HA(s) were identified together as 9" x 9" floor tile (FT), mastics assoc. with 9" x 9" FT, 12" x 12" FT, mastics assoc. with 12" x 12" FT, pipe insulation, etc. Some of these HA(s) have been re-identified by areas that are uniform in color, texture, construction date, application date, and general appearance.

The inspector has determined the following:

A. The following HAs have changed assessment categories for Building 3370:

- |   |  |
|---|--|
| 3 | 12" x 12" Beige w/ Brown Specks Floor Tile       |
| 4 | 12" x 12" Beige w/Brown Specks Floor Tile Mastic |

B. The following new homogenous areas have been identified for Building 3370:

46	12"x12" Grey w/Dark Grey Streaks VFT
47	12"x12" Grey w/Dark Grey Streaks VFT Mastic
48	12"x12" Beige w/White Streaks VFT
49	12"x12" Beige w/White Streaks VFT Mastic
50	12"x12" Red VFT
51	12"x12" Red VFT Mastic
52	Grey Patterned Carpet Mastic

C. This reinspection covered only physically accessible and visible areas and materials that were identified in the LEA's management plan. The following materials were concealed and/or contained in areas that were inaccessible for sampling and have been classified as Assumed:

23	Stage Lights Electrical Insulation
24	Carpet Mastic
25	Sink Coating
26	12" x 12" White w/Blue Specks FT
27	12" x 12" White w/Blue Specks FT Mastic
28	12" x 12" Blue Speckled Floor Tile
29	12" x 12" Blue Speckled Floor Tile Mastic
30	Beige Ceramic Floor Tile Grout
31	Brown Ceramic Baseboard Grout
32	Interior Door Caulk
33	Burgandy Carpet Mastic
34	4" Black Vinyl Baseboard
35	4" Black Vinyl Baseboard Adhesive
36	Wall Expansion Joint Caulk
37	Drywall Ceiling
38	Drywall Ceiling Joint Compound
39	Drywall Ceiling Joint Tape
40	12" X 12" Beige Speckled Floor Tile (Patch)
41	12" X 12" Beige Speckled Floor Tile (Patch)
42	Gray Skid Pad Covering Adhesive
43	Ceramic Wall Tile Grout
44	Ceramic Wall Tile Adhesive
45	Gray Carpet Adhesive
46	12"x12" Grey w/Dark Grey Streaks VFT
47	12"x12" Grey w/Dark Grey Streaks VFT Mastic
48	12"x12" Beige w/White Streaks VFT
49	12"x12" Beige w/White Streaks VFT Mastic
50	12"x12" Red VFT
51	12"x12" Red VFT Mastic
52	Grey Patterned Carpet Mastic
7	Vault Door Insulation
8	Transite Counter Top
9	Vibration Collar (isolation cloth)

The following areas were deemed to be inaccessible:

23	Stage Lights Electrical Insulation
24	Carpet Mastic
27	12" x 12" White w/Blue Specks FT Mastic
29	12" x 12" Blue Speckled Floor Tile Mastic
33	Burgandy Carpet Mastic
35	4" Black Vinyl Baseboard Adhesive

4	12" x 12" Beige w/Brown Specks Floor Tile Mastic
42	Gray Skid Pad Covering Adhesive
44	Ceramic Wall Tile Adhesive
45	Gray Carpet Adhesive
47	12"x12" Grey w/Dark Grey Streaks VFT Mastic
49	12"x12" Beige w/White Streaks VFT Mastic
51	12"x12" Red VFT Mastic
52	Grey Patterned Carpet Mastic
7	Vault Door Insulation

Materials were also listed as "assumed" if they were in good condition and sampling was not conducted to avoid damage.

This reinspection was conducted by Jesus Delgado, IDPH License # 100-11170. The Management Plan was updated by Daniel Juneau, IDPH License # 100-03613. Inspector and Management Planner Licenses are included in Appendix B.

### **III. METHODOLOGY**

Tasks performed on-site included the following:

1. Review current management plan, identify HA(s) and extract appropriate information.
2. Examine and verify abatement records.
3. Touch and visually and physically reinspect and reassess the condition of all friable known or assumed ACBM.
4. Touch and visually and physically reinspect all non-friable known or assumed ACBM to determine whether these materials have become friable since the last inspection or periodic surveillance.
5. Identify any condition changes that may affect Hazard Ranking of known ACBM or Assumed ACBM, as well as any HA(s) that have become friable since the last reinspection.
6. Collect bulk samples from each newly discovered friable HA or previously assumed and submit for laboratory analysis.
7. Tabulate reinspection findings and submit for management planner review and recommendations with appropriate response actions based on the AHERA Damage Category of the ACBM.
8. Submit reinspection findings and management planner recommendations to the LEA within thirty (30) days for inclusion into the management plan.

### **IV. ABATEMENT HISTORY**

The information collected from the existing management plan and inspection report(s) and from interviews with the school official revealed that the following asbestos abatement was conducted at the school since the previous Three year Reinspection.

Abatement Dates:

### **V. REASSESSMENTS AND RECOMMENDATIONS**

The reassessments and recommendations are summarized in Tables I and II on the following pages. Detailed Hazard Assessment Sheets and Drawings and Photos (if applicable) are included in Appendix A.

### **VI. CONCLUSIONS**

The Kanoon Magnet Building 3370 Three-Year reinspection has been completed and response actions have been recommended for both friable and non-friable materials. A timely execution of the response actions recommended will enable the LEA and the Designated Person(s) to effectively manage the existing ACBM.

This three-year reinspection report should be inspected in the current Management plan at the CPS Central Office, and one (1) copy should be kept at the school for use when planning any renovation and/or demolition activities in areas where ACBM has been identified. Also, periodic surveillance documentation and any summary reports from any response actions that are executed at the school should be used to update the Management Plan.

**Table I**  
**Inspector's Reinspection Findings**

---

# Chicago Public Schools

School Kanoon Magnet Unit 29071 Building ID 3370

Address 2233 S. Kedzie Region 03

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
1	2' x 4' Ceiling tile			Throughout building	NO_ACBM	MISC								
10	Hard plaster on walls & ceiling			Small Gymnasium (Handball Court)	NO_ACBM	SURFACE								
11	2' x 4' Metal covered ceiling tile			Throughout classrooms on the 1st & 2nd floors	NO_ACBM	MISC								
12	Duct interior lining			Mechanical/Fan Rooms	NO_ACBM	MISC								
13	Folding Doors Cloth Cover			Rooms 120 & 122	NO_ACBM	MISC								
14	Black pipe insulation			Mechanical/Fan Rooms	NO_ACBM	TSI								
15	Duct Exterior Insulation			Mechanical/Fan Room	NO_ACBM	TSI								
16	Interior window caulk			Throughout school	NO_ACBM	MISC								
17	Exterior window caulk - not AHERA			Exterior of building	NO_ACBM	MISC								
18	Exterior window glaze - not AHERA			Exterior of building	NO_ACBM	MISC								
19	Lower Roof Field - not AHERA			Lower roof	NO_ACBM	MISC								
2	Spray-on Fire Proofing			Throughout school	NO_ACBM	SURFACE								
20	Lower Roof Flashing - not AHERA	990	SF	Lower roof	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
21	Upper Roof Field - not AHERA			Upper roof	NO_ACBM	MISC								
22	Upper Roof Flashing - not AHERA	140	SF	Upper roof	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
23	Stage Lights Electrical Insulation	20	LF	Auditorium	ASSUMED	TSI	N	NONE	0		No	ACBM with the potential for damage		LOW
24	Carpet Mastic	18,000	SF	108,110,114,200,202, 208,210,214,218,220-224,226,228,230,232,234	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
25	Sink Coating	135	SF	200, 201, 202, 204, 206, 208, 210, 212, 205, 214, 218, 220, 222,223, 224, 226,105,108, 110, 112, 114, 116, 118,120,122	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
26	12" x 12" White w/Blue Specks FT	2,400	SF	Room 105,112,118	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
27	12" x 12" White w/Blue Specks FT Mastic	2,400	SF	Room 105, 112, 118	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
28	12" x 12" Blue Speckled Floor Tile	225	SF	Room 105, 112, 118	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW

# Chicago Public Schools

School Kanoon Magnet Unit 29071 Building ID 3370

Address 2233 S. Kedzie Region 03

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
29	12" x 12" Blue Speckled Floor Tile Mastic	225	SF	Room 105, 112, 118, and 212	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
3	12" x 12" Beige w/ Brown Specks Floor Tile	30,000	SF	Throughout building in all classrooms and hallways except washrooms	CHR	MISC	N	NONE	0		Yes	ACBM with potential for significant damage		MODERATE
30	Beige Ceramic Floor Tile Grout	4,000	SF	All 1st and 2nd Floor Washrooms, 1st Floor Janitors Closets, and Kitchen Area	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
31	Brown Ceramic Baseboard Grout	600	LF	All 1st and 2nd Floor Washrooms, 1st Floor Janitors Closets, and Kitchen Area	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
32	Interior Door Caulk	1,280	LF	All door on 1st and 2nd floors	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
33	Burgandy Carpet Mastic	4,600	SF	Main Office, Conf Room, Faculty Lounge, Asst Prin Office, Rms 106C and D, Student Services,	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
34	4" Black Vinyl Baseboard	300	LF	Assembly Hall	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
35	4" Black Vinyl Baseboard Adhesive	300	LF	Assembly Hall	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
36	Wall Expansion Joint Caulk	300	LF	Assembly Hall	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
37	Drywall Ceiling			Room 221	ASSUMED	MISC		None						Low
38	Drywall Ceiling Joint Compound			Room 221	ASSUMED	MISC		None						Low
39	Drywall Ceiling Joint Tape			Room 221	ASSUMED	MISC		None						Low
4	12" x 12" Beige w/Brown Specks Floor Tile Mastic	30,000	SF	Throughout building	CHR	MISC	N	NONE	0		Yes	ACBM with potential for significant damage		LOW
40	12" X 12" Beige Speckled Floor Tile (Patch)	26	SF	2nd Floor Hall outside room 234 and Stairs	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
41	12" X 12" Beige Speckled Floor Tile (Patch)	26	SF	2nd Floor Hall outside room 234 and Stairs	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
42	Gray Skid Pad Covering Adhesive	25	SF	Elevator	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
43	Ceramic Wall Tile Grout	20	SF	Janitors Closets	ASSUMED	MISC	N	NONE	0		No	ACBM with the		LOW



# Chicago Public Schools

School Kanoon Magnet Unit 29071 Building ID 3370

Address 2233 S. Kedzie Region 03

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

*Inspector's Comments are Summarized at the End of the Report*

Reinspection Date <b>3/19/2013</b>
Inspector Name <b>Jesus Delgado</b>
<b>100-11170</b> <b>5/15/2013</b>
Inspector's IDPH License Number / Expiration Date

### Inspector's Comments

HA Number:	Inspector Comments:
1	
10	
11	
12	
13	
14	
15	
16	
17	
18	
19	
2	
20	
21	
22	
23	
24	Not Observed in 105,116,118,120,122,201
25	
26	Not Observed in 212
27	Not Observed in 212
28	Not Observed in 212
29	Not Observed in 212
3	
30	

# Chicago Public Schools

School Kanoon Magnet Unit 29071 Building ID 3370

Address 2233 S. Kedzie Region 03

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

*Inspector's Comments are Summarized at the End of the Report*

---

HA Number:	Inspector Comments:
31	
32	
33	Not Observed in Wk Room
34	
35	
36	
37	Material not observed or present in 2013 Re-Inspection
38	Material not observed or present in 2013 Re-Inspection
39	Material not observed or present in 2013 Re-Inspection
4	
40	
41	
42	
43	
44	
45	
46	
47	
48	
49	
5	
50	
51	
52	
6	
7	
8	
9	
B	

# Chicago Public Schools

**School** Kanoon Magnet **Unit** 29071 **Building ID** 3370

**Address** 2233 S. Kedzie **Region** 03

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

*Inspector's Comments are Summarized at the End of the Report*

---

**Table II**

**Management Planner's Review**

---

# Chicago Public Schools

**School** Kanoon Magnet  
**Address** 2233 S. Kedzie

**Unit** 29071  
Chicago, IL, 60623

**Building ID** 3370  
**Region** 03

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

### *Management Planner's Comments Summarized at the End of the Report*

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
1	2' x 4' Ceiling tile			Throughout building	No ACBM	MISC					
10	Hard plaster on walls & ceiling			Small Gymnasium (Handball Court)	No ACBM	SURFACE					
11	2' x 4' Metal covered ceiling tile			Throughout classrooms on the 1st & 2nd floors	No ACBM	MISC					
12	Duct interior lining			Mechanical/Fan Rooms	No ACBM	MISC					
13	Folding Doors Cloth Cover			Rooms 120 & 122	No ACBM	MISC					
14	Black pipe insulation			Mechanical/Fan Rooms	No ACBM	TSI					
15	Duct Exterior Insulation			Mechanical/Fan Room	No ACBM	TSI					
16	Interior window caulk			Throughout school	No ACBM	MISC					
17	Exterior window caulk - not AHERA			Exterior of building	No ACBM	MISC					
18	Exterior window glaze - not AHERA			Exterior of building	No ACBM	MISC					
19	Lower Roof Field - not AHERA			Lower roof	No ACBM	MISC					
2	Spray-on Fire Proofing			Throughout school	No ACBM	SURFACE					
20	Lower Roof Flashing - not AHERA	990	SF	Lower roof	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
21	Upper Roof Field - not AHERA			Upper roof	No ACBM	MISC					
22	Upper Roof Flashing - not AHERA	140	SF	Upper roof	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
23	Stage Lights Electrical Insulation	20	LF	Auditorium	Assumed	TSI	No	0	LF	6 ACBM with the potential for damage	Operations and Maintenance
24	Carpet Mastic	18,000	SF	108,110,114,200,202-208,210,214,218,220-224,226,228,230,232,234	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
25	Sink Coating	135	SF	200, 201, 202, 204, 206, 208, 210, 212, 205, 214, 218, 220, 222,223, 224, 226,105,108, 110, 112, 114, 116, 118,120,122	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
26	12" x 12" White w/Blue Specks FT	2,400	SF	Room 105,112,118	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
27	12" x 12" White w/Blue Specks FT Mastic	2,400	SF	Room 105, 112, 118	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
28	12" x 12" Blue Speckled Floor Tile	225	SF	Room 105, 112, 118	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
29	12" x 12" Blue Speckled Floor Tile Mastic	225	SF	Room 105, 112, 118, and 212	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
3	12" x 12" Beige w/ Brown Specks Floor Tile	30,000	SF	Throughout building in all classrooms and hallways except washrooms	Chrysotile	MISC	No	0	SF	5 ACBM with potential for significant damage	Operations and Maintenance
30	Beige Ceramic Floor Tile Grout	4,000	SF	All 1st and 2nd Floor Washrooms, 1st Floor Janitors Closets, and Kitchen Area	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
31	Brown Ceramic Baseboard Grout	600	LF	All 1st and 2nd Floor Washrooms, 1st Floor Janitors Closets, and Kitchen Area	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Operations and Maintenance

# Chicago Public Schools

**School** Kanoon Magnet  
**Address** 2233 S. Kedzie

**Unit** 29071  
Chicago, IL, 60623

**Building ID** 3370  
**Region** 03

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

### *Management Planner's Comments Summarized at the End of the Report*

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
32	Interior Door Caulk	1,280	LF	All door on 1st and 2nd floors	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Operations and Maintenance
33	Burgandy Carpet Mastic	4,600	SF	Main Office, Conf Room, Faculty Lounge, Asst Prin Office, Rms 106C and D, Student Services,	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
34	4" Black Vinyl Baseboard	300	LF	Assembly Hall	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Operations and Maintenance
35	4" Black Vinyl Baseboard Adhesive	300	LF	Assembly Hall	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Operations and Maintenance
36	Wall Expansion Joint Caulk	300	LF	Assembly Hall	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Operations and Maintenance
37	Drywall Ceiling			Room 221	Assumed	MISC					
38	Drywall Ceiling Joint Compound			Room 221	Assumed	MISC					
39	Drywall Ceiling Joint Tape			Room 221	Assumed	MISC					
4	12" x 12" Beige w/Brown Specks Floor Tile Mastic	30,000	SF	Throughout building	Chrysotile	MISC	No	0	SF	5 ACBM with potential for significant damage	Operations and Maintenance
40	12" X 12" Beige Speckled Floor Tile (Patch)	26	SF	2nd Floor Hall outside room 234 and Stairs	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
41	12" X 12" Beige Speckled Floor Tile (Patch)	26	SF	2nd Floor Hall outside room 234 and Stairs	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
42	Gray Skid Pad Covering Adhesive	25	SF	Elevator	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
43	Ceramic Wall Tile Grout	20	SF	Janitors Closets	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
44	Ceramic Wall Tile Adhesive	20	SF	Janitor's Closets	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
45	Gray Carpet Adhesive	4,000	SF	Assembly Hall	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
46	12"x12" Grey w/Dark Grey Streaks VFT	3,300	SF	Rooms 116,120,122	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
47	12"x12" Grey w/Dark Grey Streaks VFT Mastic	3,300	SF	Rooms 116,120,122	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
48	12"x12" Beige w/White Streaks VFT	740	SF	Room 212	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
49	12"x12" Beige w/White Streaks VFT Mastic	740	SF	Room 212	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
5	Baseboard			Throughout building	No ACBM	MISC					
50	12"x12" Red VFT	30	SF	Room 212	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
51	12"x12" Red VFT Mastic	30	SF	Room 212	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
52	Grey Patterned Carpet Mastic	1,430	SF	Room 225(Library)	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
6	Baseboard Mastic			Throughout building	No ACBM	MISC					
7	Vault Door Insulation	60	SF	Main Office (Room 100D/Storage), Room 218	Assumed	TSI	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
8	Transite Counter Top	150	SF	Science Lab (Room 201)	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
9	Vibration Collar (isolation cloth)	100	LF	Ductwork throughout building - mechanical areas	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Operations and Maintenance
B	Hard Joint Compound on Fiberglass Pipe Runs			Throughout school (above ceiling tiles)	No ACBM	MISC					

# Chicago Public Schools

**School** Kanoon Magnet  
**Address** 2233 S. Kedzie

**Unit** 29071  
 Chicago, IL, 60623

**Building ID** 3370  
**Region** 03

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

*Management Planner's Comments Summarized at the End of the Report*

Review Date	4/2/2013
Manager Planner Name	Daniel Juneau
100-03613	5/15/2014
Manager IDPH License No/Expiration	

HA Number	Management Comments
1	
10	
11	
12	
13	
14	
15	

# Chicago Public Schools

**School** Kanoon Magnet  
**Address** 2233 S. Kedzie

**Unit** 29071  
 Chicago, IL, 60623

**Building ID** 3370  
**Region** 03

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates  
 600 West Van Buren St., Ste 500  
 Phone: (312) 762-2900 Fax: (312) 782-5145

*Management Planner's Comments Summarized at the End of the Report*

HA Number	Management Comments
16	
17	
18	
19	
2	
20	
21	
22	
23	
24	
25	
26	
27	
28	
29	
3	
30	
31	
32	
33	
34	
35	
36	
37	
38	
39	
4	

# Chicago Public Schools

**School** Kanoon Magnet  
**Address** 2233 S. Kedzie

**Unit** 29071  
 Chicago, IL, 60623

**Building ID** 3370  
**Region** 03

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates  
 600 West Van Buren St., Ste 500  
 Phone: (312) 762-2900 Fax: (312) 782-5145

*Management Planner's Comments Summarized at the End of the Report*

HA Number	Management Comments
40	
41	
42	
43	
44	
45	
46	
47	
48	
49	
5	
50	
51	
52	
6	
7	
8	
9	
B	

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29071** BUILDING ID: **3370**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Jesus Delgado**  
SCHOOL NAME: **Kanoon Magnet** INSPECTION DATE: **3/19/2013**  
ADDRESS: **2233 S. Kedzie** IDPH LICENSE NO: **100-11170**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **1**  
MATERIAL DESCRIPTION: **2' x 4' Ceiling tile**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **03/19/2013**

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29071** BUIDLING ID: **3370**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Kanoon Magnet** REVIEW DATE: **4/2/2013**  
ADDRESS: **2233 S. Kedzie** IDPH LICENSE NO: **100-11170**

---

HOMOGENEOUS AREA: **1**

MATERIAL DESCRIPTION: **2' x 4' Ceiling tile**

MATERIAL LOCATION: **Throughout building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **04/02/2013**

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29071** BUIDLING ID: **3370**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Jesus Delgado**  
SCHOOL NAME: **Kanoon Magnet** INSPECTION DATE: **3/19/2013**  
ADDRESS: **2233 S. Kedzie** IDPH LICENSE NO: **100-11170**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **10**  
MATERIAL DESCRIPTION: **Hard plaster on walls & ceiling**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Small Gymnasium (Handball Court)**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **03/19/2013**

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29071** BUIDLING ID: **3370**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Kanoon Magnet** REVIEW DATE: **4/2/2013**  
ADDRESS: **2233 S. Kedzie** IDPH LICENSE NO: **100-11170**

---

HOMOGENEOUS AREA: **10**

MATERIAL DESCRIPTION: **Hard plaster on walls & ceiling**

MATERIAL LOCATION: **Small Gymnasium (Handball Court)**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **04/02/2013**

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29071** BUIDLING ID: **3370**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Jesus Delgado**  
SCHOOL NAME: **Kanoon Magnet** INSPECTION DATE: **3/19/2013**  
ADDRESS: **2233 S. Kedzie** IDPH LICENSE NO: **100-11170**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **11**  
MATERIAL DESCRIPTION: **2' x 4' Metal covered ceiling tile**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout classrooms on the 1st & 2nd floors**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **03/19/2013**

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29071** BUIDLING ID: **3370**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Kanoon Magnet** REVIEW DATE: **4/2/2013**  
ADDRESS: **2233 S. Kedzie** IDPH LICENSE NO: **100-11170**

---

HOMOGENEOUS AREA: **11**

MATERIAL DESCRIPTION: **2' x 4' Metal covered ceiling tile**

MATERIAL LOCATION: **Throughout classrooms on the 1st & 2nd floors**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **04/02/2013**

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29071** BUIDLING ID: **3370**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Jesus Delgado**  
SCHOOL NAME: **Kanoon Magnet** INSPECTION DATE: **3/19/2013**  
ADDRESS: **2233 S. Kedzie** IDPH LICENSE NO: **100-11170**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **12**  
MATERIAL DESCRIPTION: **Duct interior lining**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Mechanical/Fan Rooms**

MATERIAL QUANTITY:


MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **03/19/2013**

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29071** BUIDLING ID: **3370**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Kanoon Magnet** REVIEW DATE: **4/2/2013**  
ADDRESS: **2233 S. Kedzie** IDPH LICENSE NO: **100-11170**

---

HOMOGENEOUS AREA: **12**

MATERIAL DESCRIPTION: **Duct interior lining**

MATERIAL LOCATION: **Mechanical/Fan Rooms**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **04/02/2013**

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29071** BUIDLING ID: **3370**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Jesus Delgado**  
SCHOOL NAME: **Kanoon Magnet** INSPECTION DATE: **3/19/2013**  
ADDRESS: **2233 S. Kedzie** IDPH LICENSE NO: **100-11170**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **13**  
MATERIAL DESCRIPTION: **Folding Doors Cloth Cover**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Rooms 120 &122**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **03/19/2013**

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29071** BUIDLING ID: **3370**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Kanoon Magnet** REVIEW DATE: **4/2/2013**  
ADDRESS: **2233 S. Kedzie** IDPH LICENSE NO: **100-11170**

---

HOMOGENEOUS AREA: **13**

MATERIAL DESCRIPTION: **Folding Doors Cloth Cover**

MATERIAL LOCATION: **Rooms 120 &122**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **04/02/2013**

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29071** BUIDLING ID: **3370**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Jesus Delgado**  
SCHOOL NAME: **Kanoon Magnet** INSPECTION DATE: **3/19/2013**  
ADDRESS: **2233 S. Kedzie** IDPH LICENSE NO: **100-11170**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **14**  
MATERIAL DESCRIPTION: **Black pipe insulation**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Mechanical/Fan Rooms**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **03/19/2013**

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29071** BUIDLING ID: **3370**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Kanoon Magnet** REVIEW DATE: **4/2/2013**  
ADDRESS: **2233 S. Kedzie** IDPH LICENSE NO: **100-11170**

---

HOMOGENEOUS AREA: **14**

MATERIAL DESCRIPTION: **Black pipe insulation**

MATERIAL LOCATION: **Mechanical/Fan Rooms**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:


---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **04/02/2013**

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29071** BUIDLING ID: **3370**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Jesus Delgado**  
SCHOOL NAME: **Kanoon Magnet** INSPECTION DATE: **3/19/2013**  
ADDRESS: **2233 S. Kedzie** IDPH LICENSE NO: **100-11170**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **15**  
MATERIAL DESCRIPTION: **Duct Exterior Insulation**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Mechanical/Fan Room**

MATERIAL QUANTITY:


MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **03/19/2013**

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29071** BUIDLING ID: **3370**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Kanoon Magnet** REVIEW DATE: **4/2/2013**  
ADDRESS: **2233 S. Kedzie** IDPH LICENSE NO: **100-11170**

---

HOMOGENEOUS AREA: **15**

MATERIAL DESCRIPTION: **Duct Exterior Insulation**

MATERIAL LOCATION: **Mechanical/Fan Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **04/02/2013**

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29071** BUIDLING ID: **3370**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Jesus Delgado**  
SCHOOL NAME: **Kanoon Magnet** INSPECTION DATE: **3/19/2013**  
ADDRESS: **2233 S. Kedzie** IDPH LICENSE NO: **100-11170**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **16**  
MATERIAL DESCRIPTION: **Interior window caulk**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout school**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **03/19/2013**

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29071** BUIDLING ID: **3370**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Kanoon Magnet** REVIEW DATE: **4/2/2013**  
ADDRESS: **2233 S. Kedzie** IDPH LICENSE NO: **100-11170**

---

HOMOGENEOUS AREA: **16**

MATERIAL DESCRIPTION: **Interior window caulk**

MATERIAL LOCATION: **Throughout school**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **04/02/2013**

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29071** BUIDLING ID: **3370**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Jesus Delgado**  
SCHOOL NAME: **Kanoon Magnet** INSPECTION DATE: **3/19/2013**  
ADDRESS: **2233 S. Kedzie** IDPH LICENSE NO: **100-11170**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **17**  
MATERIAL DESCRIPTION: **Exterior window caulk - not AHERA**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Exterior of building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **03/19/2013**

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29071** BUIDLING ID: **3370**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Kanoon Magnet** REVIEW DATE: **4/2/2013**  
ADDRESS: **2233 S. Kedzie** IDPH LICENSE NO: **100-11170**

---

HOMOGENEOUS AREA: **17**

MATERIAL DESCRIPTION: **Exterior window caulk - not AHERA**

MATERIAL LOCATION: **Exterior of building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **04/02/2013**

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29071** BUIDLING ID: **3370**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Jesus Delgado**  
SCHOOL NAME: **Kanoon Magnet** INSPECTION DATE: **3/19/2013**  
ADDRESS: **2233 S. Kedzie** IDPH LICENSE NO: **100-11170**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **18**  
MATERIAL DESCRIPTION: **Exterior window glaze - not AHERA**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Exterior of building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **03/19/2013**

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29071** BUIDLING ID: **3370**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Kanoon Magnet** REVIEW DATE: **4/2/2013**  
ADDRESS: **2233 S. Kedzie** IDPH LICENSE NO: **100-11170**

---

HOMOGENEOUS AREA: **18**

MATERIAL DESCRIPTION: **Exterior window glaze - not AHERA**

MATERIAL LOCATION: **Exterior of building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **04/02/2013**

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29071** BUIDLING ID: **3370**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Jesus Delgado**  
SCHOOL NAME: **Kanoon Magnet** INSPECTION DATE: **3/19/2013**  
ADDRESS: **2233 S. Kedzie** IDPH LICENSE NO: **100-11170**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **19**  
MATERIAL DESCRIPTION: **Lower Roof Field - not AHERA**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Lower roof**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **03/19/2013**

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29071** BUIDLING ID: **3370**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Kanoon Magnet** REVIEW DATE: **4/2/2013**  
ADDRESS: **2233 S. Kedzie** IDPH LICENSE NO: **100-11170**

---

HOMOGENEOUS AREA: **19**

MATERIAL DESCRIPTION: **Lower Roof Field - not AHERA**

MATERIAL LOCATION: **Lower roof**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **04/02/2013**

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29071** BUIDLING ID: **3370**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Jesus Delgado**  
SCHOOL NAME: **Kanoon Magnet** INSPECTION DATE: **3/19/2013**  
ADDRESS: **2233 S. Kedzie** IDPH LICENSE NO: **100-11170**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **2**  
MATERIAL DESCRIPTION: **Spray-on Fire Proofing**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout school**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **03/19/2013**

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29071** BUIDLING ID: **3370**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Kanoon Magnet** REVIEW DATE: **4/2/2013**  
ADDRESS: **2233 S. Kedzie** IDPH LICENSE NO: **100-11170**

---

HOMOGENEOUS AREA: **2**

MATERIAL DESCRIPTION: **Spray-on Fire Proofing**

MATERIAL LOCATION: **Throughout school**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **04/02/2013**

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29071** BUIDLING ID: **3370**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Jesus Delgado**  
SCHOOL NAME: **Kanoon Magnet** INSPECTION DATE: **3/19/2013**  
ADDRESS: **2233 S. Kedzie** IDPH LICENSE NO: **100-11170**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **20**  
MATERIAL DESCRIPTION: **Lower Roof Flashing - not AHERA**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Lower roof**

MATERIAL QUANTITY: **990**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/19/2013**

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29071** BUIDLING ID: **3370**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Kanoon Magnet** REVIEW DATE: **4/2/2013**  
ADDRESS: **2233 S. Kedzie** IDPH LICENSE NO: **100-11170**

---

HOMOGENEOUS AREA: **20**

MATERIAL DESCRIPTION: **Lower Roof Flashing - not AHERA**

MATERIAL LOCATION: **Lower roof**

MATERIAL QUANTITY: **990**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **04/02/2013**

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29071** BUIDLING ID: **3370**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Jesus Delgado**  
SCHOOL NAME: **Kanoon Magnet** INSPECTION DATE: **3/19/2013**  
ADDRESS: **2233 S. Kedzie** IDPH LICENSE NO: **100-11170**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **21**  
MATERIAL DESCRIPTION: **Upper Roof Field - not AHERA**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:  
DISTURBANCE POTENTIAL:  
MATERIAL LOCATION: **Upper roof**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:  
COMMENTS:

Inspector's Signature:



Date: **03/19/2013**

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29071** BUIDLING ID: **3370**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Kanoon Magnet** REVIEW DATE: **4/2/2013**  
ADDRESS: **2233 S. Kedzie** IDPH LICENSE NO: **100-11170**

---

HOMOGENEOUS AREA: **21**

MATERIAL DESCRIPTION: **Upper Roof Field - not AHERA**

MATERIAL LOCATION: **Upper roof**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:


---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **04/02/2013**

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29071** BUIDLING ID: **3370**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Jesus Delgado**  
SCHOOL NAME: **Kanoon Magnet** INSPECTION DATE: **3/19/2013**  
ADDRESS: **2233 S. Kedzie** IDPH LICENSE NO: **100-11170**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **22**  
MATERIAL DESCRIPTION: **Upper Roof Flashing - not AHERA**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Upper roof**

MATERIAL QUANTITY: **140**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/19/2013**

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29071** BUIDLING ID: **3370**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Kanoon Magnet** REVIEW DATE: **4/2/2013**  
ADDRESS: **2233 S. Kedzie** IDPH LICENSE NO: **100-11170**

---

HOMOGENEOUS AREA: **22**  
MATERIAL DESCRIPTION: **Upper Roof Flashing - not AHERA**  
MATERIAL LOCATION: **Upper roof**  
MATERIAL QUANTITY: **140** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **04/02/2013**

# Chicago Public Schools

## Carnow, Conibear and Associates 2013 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29071** BUIDLING ID: **3370**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Jesus Delgado**  
SCHOOL NAME: **Kanoon Magnet** INSPECTION DATE: **3/19/2013**  
ADDRESS: **2233 S. Kedzie** IDPH LICENSE NO: **100-11170**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **23**  
MATERIAL DESCRIPTION: **Stage Lights Electrical Insulation**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Auditorium**

MATERIAL QUANTITY: **20**

MATERIAL UNITS: **LF**

DAMAGE QUANTITY:

DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature:



Date: **03/19/2013**

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29071** BUILDING ID: **3370**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Kanoon Magnet** REVIEW DATE: **4/2/2013**  
ADDRESS: **2233 S. Kedzie** IDPH LICENSE NO: **100-11170**

---

HOMOGENEOUS AREA: **23**

MATERIAL DESCRIPTION: **Stage Lights Electrical Insulation**

MATERIAL LOCATION: **Auditorium**

MATERIAL QUANTITY: **20**

MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Operations and Maintenance

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **04/02/2013**

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29071** BUIDLING ID: **3370**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Jesus Delgado**  
SCHOOL NAME: **Kanoon Magnet** INSPECTION DATE: **3/19/2013**  
ADDRESS: **2233 S. Kedzie** IDPH LICENSE NO: **100-11170**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **24**  
MATERIAL DESCRIPTION: **Carpet Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **108,110,114,200,202-208,210,214,218,220-224,226,228,230,232,234**  
MATERIAL QUANTITY: **18000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS: **Not Observed in 105,116,118,120,122,201**

Inspector's Signature:



Date: **03/19/2013**

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29071** BUIDLING ID: **3370**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Kanoon Magnet** REVIEW DATE: **4/2/2013**  
ADDRESS: **2233 S. Kedzie** IDPH LICENSE NO: **100-11170**

---

HOMOGENEOUS AREA: **24**  
MATERIAL DESCRIPTION: **Carpet Mastic**  
MATERIAL LOCATION: **108,110,114,200,202-208,210,214,218,220-224,226,228,230,232,234**  
MATERIAL QUANTITY: **18000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Operations and Maintenance

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **04/02/2013**

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29071** BUIDLING ID: **3370**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Jesus Delgado**  
SCHOOL NAME: **Kanoon Magnet** INSPECTION DATE: **3/19/2013**  
ADDRESS: **2233 S. Kedzie** IDPH LICENSE NO: **100-11170**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **25**  
MATERIAL DESCRIPTION: **Sink Coating**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**


MATERIAL LOCATION: **200, 201, 202, 204, 206, 208, 210, 212, 205, 214, 218, 220, 222,223, 224, 226,105,108, 110, 112, 114, 116, 118,120,122**

MATERIAL QUANTITY: **135** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/19/2013**

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29071** BUIDLING ID: **3370**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Kanoon Magnet** REVIEW DATE: **4/2/2013**  
ADDRESS: **2233 S. Kedzie** IDPH LICENSE NO: **100-11170**

---

HOMOGENEOUS AREA: **25**  
MATERIAL DESCRIPTION: **Sink Coating**  
MATERIAL LOCATION: **200, 201, 202, 204, 206, 208, 210, 212, 205, 214, 218, 220, 222,223, 224, 226,105,108, 110, 112, 114, 116, 118,120,122**  
MATERIAL QUANTITY: **135** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Operations and Maintenance

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: 04/02/2013

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29071** BUIDLING ID: **3370**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Jesus Delgado**  
SCHOOL NAME: **Kanoon Magnet** INSPECTION DATE: **3/19/2013**  
ADDRESS: **2233 S. Kedzie** IDPH LICENSE NO: **100-11170**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **26**  
MATERIAL DESCRIPTION: **12" x 12" White w/Blue Specks FT**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT


This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Room 105,112,118**  
MATERIAL QUANTITY: **2400** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS: **Not Observed in 212**

Inspector's Signature:



Date: **03/19/2013**

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29071** BUIDLING ID: **3370**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Kanoon Magnet** REVIEW DATE: **4/2/2013**  
ADDRESS: **2233 S. Kedzie** IDPH LICENSE NO: **100-11170**

---

HOMOGENEOUS AREA: **26**  
MATERIAL DESCRIPTION: **12" x 12" White w/Blue Specks FT**  
MATERIAL LOCATION: **Room 105,112,118**  
MATERIAL QUANTITY: **2400** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Operations and Maintenance

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **04/02/2013**

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29071** BUIDLING ID: **3370**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Jesus Delgado**  
SCHOOL NAME: **Kanoon Magnet** INSPECTION DATE: **3/19/2013**  
ADDRESS: **2233 S. Kedzie** IDPH LICENSE NO: **100-11170**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **27**  
MATERIAL DESCRIPTION: **12" x 12" White w/Blue Specks FT Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT


This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Room 105, 112, 118**  
MATERIAL QUANTITY: **2400** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS: **Not Observed in 212**

Inspector's Signature:



Date: **03/19/2013**

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29071** BUIDLING ID: **3370**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Kanoon Magnet** REVIEW DATE: **4/2/2013**  
ADDRESS: **2233 S. Kedzie** IDPH LICENSE NO: **100-11170**

---

HOMOGENEOUS AREA: **27**

MATERIAL DESCRIPTION: **12" x 12" White w/Blue Specks FT Mastic**

MATERIAL LOCATION: **Room 105, 112, 118**

MATERIAL QUANTITY: **2400**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Operations and Maintenance

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **04/02/2013**

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29071** BUIDLING ID: **3370**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Jesus Delgado**  
SCHOOL NAME: **Kanoon Magnet** INSPECTION DATE: **3/19/2013**  
ADDRESS: **2233 S. Kedzie** IDPH LICENSE NO: **100-11170**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **28**  
MATERIAL DESCRIPTION: **12" x 12" Blue Speckled Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Room 105, 112, 118**  
MATERIAL QUANTITY: **225** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS: **Not Observed in 212**

Inspector's Signature:



Date: **03/19/2013**

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29071** BUIDLING ID: **3370**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Kanoon Magnet** REVIEW DATE: **4/2/2013**  
ADDRESS: **2233 S. Kedzie** IDPH LICENSE NO: **100-11170**

---

HOMOGENEOUS AREA: **28**  
MATERIAL DESCRIPTION: **12" x 12" Blue Speckled Floor Tile**  
MATERIAL LOCATION: **Room 105, 112, 118**  
MATERIAL QUANTITY: **225** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Operations and Maintenance

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **04/02/2013**

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29071** BUIDLING ID: **3370**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Jesus Delgado**  
SCHOOL NAME: **Kanoon Magnet** INSPECTION DATE: **3/19/2013**  
ADDRESS: **2233 S. Kedzie** IDPH LICENSE NO: **100-11170**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **29**  
MATERIAL DESCRIPTION: **12" x 12" Blue Speckled Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Room 105, 112, 118, and 212**

MATERIAL QUANTITY: **225**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS: **Not Observed in 212**

Inspector's Signature:



Date: **03/19/2013**

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29071** BUIDLING ID: **3370**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Kanoon Magnet** REVIEW DATE: **4/2/2013**  
ADDRESS: **2233 S. Kedzie** IDPH LICENSE NO: **100-11170**

---

HOMOGENEOUS AREA: **29**  
MATERIAL DESCRIPTION: **12" x 12" Blue Speckled Floor Tile Mastic**  
MATERIAL LOCATION: **Room 105, 112, 118, and 212**  
MATERIAL QUANTITY: **225** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Operations and Maintenance

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **04/02/2013**

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29071** BUIDLING ID: **3370**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Jesus Delgado**  
SCHOOL NAME: **Kanoon Magnet** INSPECTION DATE: **3/19/2013**  
ADDRESS: **2233 S. Kedzie** IDPH LICENSE NO: **100-11170**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **3**  
MATERIAL DESCRIPTION: **12" x 12" Beige w/ Brown Specks Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **5 ACBM with potential for significant damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **5. ACBM with potential for significant damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **Throughout building in all classrooms and hallways except washrooms**  
MATERIAL QUANTITY: **30000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/19/2013**

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29071** BUIDLING ID: **3370**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Kanoon Magnet** REVIEW DATE: **4/2/2013**  
ADDRESS: **2233 S. Kedzie** IDPH LICENSE NO: **100-11170**

---

HOMOGENEOUS AREA: **3**  
MATERIAL DESCRIPTION: **12" x 12" Beige w/ Brown Specks Floor Tile**  
MATERIAL LOCATION: **Throughout building in all classrooms and hallways except washrooms**  
MATERIAL QUANTITY: **30000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Operations and Maintenance

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **04/02/2013**

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29071** BUIDLING ID: **3370**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Jesus Delgado**  
SCHOOL NAME: **Kanoon Magnet** INSPECTION DATE: **3/19/2013**  
ADDRESS: **2233 S. Kedzie** IDPH LICENSE NO: **100-11170**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **30**  
MATERIAL DESCRIPTION: **Beige Ceramic Floor Tile Grout**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **All 1st and 2nd Floor Washrooms, 1st Floor Janitors Closets, and Kitchen Area**  
MATERIAL QUANTITY: **4000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/19/2013**

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29071** BUIDLING ID: **3370**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Kanoon Magnet** REVIEW DATE: **4/2/2013**  
ADDRESS: **2233 S. Kedzie** IDPH LICENSE NO: **100-11170**

---

HOMOGENEOUS AREA: **30**  
MATERIAL DESCRIPTION: **Beige Ceramic Floor Tile Grout**  
MATERIAL LOCATION: **All 1st and 2nd Floor Washrooms, 1st Floor Janitors Closets, and Kitchen Area**  
MATERIAL QUANTITY: **4000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Operations and Maintenance

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **04/02/2013**

# Chicago Public Schools

## Carnow, Conibear and Associates 2013 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29071** BUIDLING ID: **3370**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Jesus Delgado**  
SCHOOL NAME: **Kanoon Magnet** INSPECTION DATE: **3/19/2013**  
ADDRESS: **2233 S. Kedzie** IDPH LICENSE NO: **100-11170**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **31**  
MATERIAL DESCRIPTION: **Brown Ceramic Baseboard Grout**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **All 1st and 2nd Floor Washrooms, 1st Floor Janitors Closets, and Kitchen Area**  
MATERIAL QUANTITY: **600** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature:



Date: **03/19/2013**

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29071** BUILDING ID: **3370**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Kanoon Magnet** REVIEW DATE: **4/2/2013**  
ADDRESS: **2233 S. Kedzie** IDPH LICENSE NO: **100-11170**

---

HOMOGENEOUS AREA: **31**  
MATERIAL DESCRIPTION: **Brown Ceramic Baseboard Grout**  
MATERIAL LOCATION: **All 1st and 2nd Floor Washrooms, 1st Floor Janitors Closets, and Kitchen Area**  
MATERIAL QUANTITY: **600** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Operations and Maintenance

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **04/02/2013**

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29071** BUIDLING ID: **3370**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Jesus Delgado**  
SCHOOL NAME: **Kanoon Magnet** INSPECTION DATE: **3/19/2013**  
ADDRESS: **2233 S. Kedzie** IDPH LICENSE NO: **100-11170**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **32**  
MATERIAL DESCRIPTION: **Interior Door Caulk**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **All door on 1st and 2nd floors**  
MATERIAL QUANTITY: **1280** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature:



Date: **03/19/2013**

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29071** BUIDLING ID: **3370**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Kanoon Magnet** REVIEW DATE: **4/2/2013**  
ADDRESS: **2233 S. Kedzie** IDPH LICENSE NO: **100-11170**

---

HOMOGENEOUS AREA: **32**  
MATERIAL DESCRIPTION: **Interior Door Caulk**  
MATERIAL LOCATION: **All door on 1st and 2nd floors**  
MATERIAL QUANTITY: **1280** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Operations and Maintenance

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **04/02/2013**

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29071** BUIDLING ID: **3370**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Jesus Delgado**  
SCHOOL NAME: **Kanoon Magnet** INSPECTION DATE: **3/19/2013**  
ADDRESS: **2233 S. Kedzie** IDPH LICENSE NO: **100-11170**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **33**  
MATERIAL DESCRIPTION: **Burgandy Carpet Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Main Office, Conf Room, Faculty Lounge, Asst Prin Office, Rms 106C and D, Student Services,**

MATERIAL QUANTITY: **4600**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS: **Not Observed in Wk Room**

Inspector's Signature:



Date: **03/19/2013**

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29071** BUIDLING ID: **3370**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Kanoon Magnet** REVIEW DATE: **4/2/2013**  
ADDRESS: **2233 S. Kedzie** IDPH LICENSE NO: **100-11170**

---

HOMOGENEOUS AREA: **33**  
MATERIAL DESCRIPTION: **Burgandy Carpet Mastic**  
MATERIAL LOCATION: **Main Office, Conf Room, Faculty Lounge, Asst Prin Office, Rms 106C and D, Student Services,**  
MATERIAL QUANTITY: **4600** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Operations and Maintenance

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **04/02/2013**

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29071** BUIDLING ID: **3370**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Jesus Delgado**  
SCHOOL NAME: **Kanoon Magnet** INSPECTION DATE: **3/19/2013**  
ADDRESS: **2233 S. Kedzie** IDPH LICENSE NO: **100-11170**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **34**  
MATERIAL DESCRIPTION: **4" Black Vinyl Baseboard**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Assembly Hall**  
MATERIAL QUANTITY: **300** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature:



Date: **03/19/2013**

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29071** BUIDLING ID: **3370**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Kanoon Magnet** REVIEW DATE: **4/2/2013**  
ADDRESS: **2233 S. Kedzie** IDPH LICENSE NO: **100-11170**

---

HOMOGENEOUS AREA: **34**

MATERIAL DESCRIPTION: **4" Black Vinyl Baseboard**

MATERIAL LOCATION: **Assembly Hall**

MATERIAL QUANTITY: **300**

MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Operations and Maintenance

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **04/02/2013**

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29071** BUIDLING ID: **3370**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Jesus Delgado**  
SCHOOL NAME: **Kanoon Magnet** INSPECTION DATE: **3/19/2013**  
ADDRESS: **2233 S. Kedzie** IDPH LICENSE NO: **100-11170**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **35**  
MATERIAL DESCRIPTION: **4" Black Vinyl Baseboard Adhesive**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Assembly Hall**  
MATERIAL QUANTITY: **300** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature:



Date: **03/19/2013**

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29071** BUIDLING ID: **3370**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Kanoon Magnet** REVIEW DATE: **4/2/2013**  
ADDRESS: **2233 S. Kedzie** IDPH LICENSE NO: **100-11170**

---

HOMOGENEOUS AREA: **35**

MATERIAL DESCRIPTION: **4" Black Vinyl Baseboard Adhesive**

MATERIAL LOCATION: **Assembly Hall**

MATERIAL QUANTITY: **300**

MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Operations and Maintenance

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **04/02/2013**

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29071** BUIDLING ID: **3370**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Jesus Delgado**  
SCHOOL NAME: **Kanoon Magnet** INSPECTION DATE: **3/19/2013**  
ADDRESS: **2233 S. Kedzie** IDPH LICENSE NO: **100-11170**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **36**  
MATERIAL DESCRIPTION: **Wall Expansion Joint Caulk**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Assembly Hall**  
MATERIAL QUANTITY: **300** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature:



Date: **03/19/2013**

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29071** BUIDLING ID: **3370**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Kanoon Magnet** REVIEW DATE: **4/2/2013**  
ADDRESS: **2233 S. Kedzie** IDPH LICENSE NO: **100-11170**

---

HOMOGENEOUS AREA: **36**

MATERIAL DESCRIPTION: **Wall Expansion Joint Caulk**

MATERIAL LOCATION: **Assembly Hall**

MATERIAL QUANTITY: **300**

MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Operations and Maintenance

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **04/02/2013**

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29071** BUIDLING ID: **3370**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Jesus Delgado**  
SCHOOL NAME: **Kanoon Magnet** INSPECTION DATE: **3/19/2013**  
ADDRESS: **2233 S. Kedzie** IDPH LICENSE NO: **100-11170**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **37**  
MATERIAL DESCRIPTION: **Drywall Ceiling**  
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**  
ASBESTOS TYPE: **Assumed** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **Low**

MATERIAL LOCATION: **Room 221**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Material not observed or present in 2013 Re-Inspection**

Inspector's Signature:



Date: **03/19/2013**

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29071** BUIDLING ID: **3370**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Kanoon Magnet** REVIEW DATE: **4/2/2013**  
ADDRESS: **2233 S. Kedzie** IDPH LICENSE NO: **100-11170**

---

HOMOGENEOUS AREA: **37**

MATERIAL DESCRIPTION: **Drywall Ceiling**

MATERIAL LOCATION: **Room 221**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Operations and Maintenance

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **04/02/2013**

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29071** BUIDLING ID: **3370**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Jesus Delgado**  
SCHOOL NAME: **Kanoon Magnet** INSPECTION DATE: **3/19/2013**  
ADDRESS: **2233 S. Kedzie** IDPH LICENSE NO: **100-11170**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **38**  
MATERIAL DESCRIPTION: **Drywall Ceiling Joint Compound**  
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**  
ASBESTOS TYPE: **Assumed** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **Low**

MATERIAL LOCATION: **Room 221**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Material not observed or present in 2013 Re-Inspection**

Inspector's Signature:



Date: **03/19/2013**

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29071** BUIDLING ID: **3370**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Kanoon Magnet** REVIEW DATE: **4/2/2013**  
ADDRESS: **2233 S. Kedzie** IDPH LICENSE NO: **100-11170**

---

HOMOGENEOUS AREA: **38**

MATERIAL DESCRIPTION: **Drywall Ceiling Joint Compound**

MATERIAL LOCATION: **Room 221**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Operations and Maintenance

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **04/02/2013**

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29071** BUIDLING ID: **3370**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Jesus Delgado**  
SCHOOL NAME: **Kanoon Magnet** INSPECTION DATE: **3/19/2013**  
ADDRESS: **2233 S. Kedzie** IDPH LICENSE NO: **100-11170**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **39**  
MATERIAL DESCRIPTION: **Drywall Ceiling Joint Tape**  
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**  
ASBESTOS TYPE: **Assumed** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **Low**

MATERIAL LOCATION: **Room 221**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Material not observed or present in 2013 Re-Inspection**

Inspector's Signature:



Date: **03/19/2013**

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29071** BUIDLING ID: **3370**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Kanoon Magnet** REVIEW DATE: **4/2/2013**  
ADDRESS: **2233 S. Kedzie** IDPH LICENSE NO: **100-11170**

---

HOMOGENEOUS AREA: **39**

MATERIAL DESCRIPTION: **Drywall Ceiling Joint Tape**

MATERIAL LOCATION: **Room 221**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Operations and Maintenance

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **04/02/2013**

# Chicago Public Schools

## Carnow, Conibear and Associates 2013 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29071** BUIDLING ID: **3370**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Jesus Delgado**  
SCHOOL NAME: **Kanoon Magnet** INSPECTION DATE: **3/19/2013**  
ADDRESS: **2233 S. Kedzie** IDPH LICENSE NO: **100-11170**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **4**  
MATERIAL DESCRIPTION: **12" x 12" Beige w/Brown Specks Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **5 ACBM with potential for significant damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **5. ACBM with potential for significant damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Throughout building**  
MATERIAL QUANTITY: **30000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/19/2013**

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29071** BUILDING ID: **3370**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Kanoon Magnet** REVIEW DATE: **4/2/2013**  
ADDRESS: **2233 S. Kedzie** IDPH LICENSE NO: **100-11170**

---

HOMOGENEOUS AREA: **4**  
MATERIAL DESCRIPTION: **12" x 12" Beige w/Brown Specks Floor Tile Mastic**  
MATERIAL LOCATION: **Throughout building**  
MATERIAL QUANTITY: **30000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Operations and Maintenance

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **04/02/2013**

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29071** BUIDLING ID: **3370**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Jesus Delgado**  
SCHOOL NAME: **Kanoon Magnet** INSPECTION DATE: **3/19/2013**  
ADDRESS: **2233 S. Kedzie** IDPH LICENSE NO: **100-11170**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **40**  
MATERIAL DESCRIPTION: **12" X 12" Beige Speckled Floor Tile (Patch)**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **2nd Floor Hall outside room 234 and Stairs**

MATERIAL QUANTITY: **26**


MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/19/2013**

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29071** BUIDLING ID: **3370**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Kanoon Magnet** REVIEW DATE: **4/2/2013**  
ADDRESS: **2233 S. Kedzie** IDPH LICENSE NO: **100-11170**

---

HOMOGENEOUS AREA: **40**  
MATERIAL DESCRIPTION: **12" X 12" Beige Speckled Floor Tile (Patch)**  
MATERIAL LOCATION: **2nd Floor Hall outside room 234 and Stairs**  
MATERIAL QUANTITY: **26** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Operations and Maintenance

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **04/02/2013**

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29071** BUIDLING ID: **3370**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Jesus Delgado**  
SCHOOL NAME: **Kanoon Magnet** INSPECTION DATE: **3/19/2013**  
ADDRESS: **2233 S. Kedzie** IDPH LICENSE NO: **100-11170**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **41**  
MATERIAL DESCRIPTION: **12" X 12" Beige Speckled Floor Tile (Patch)**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **2nd Floor Hall outside room 234 and Stairs**  
MATERIAL QUANTITY: **26** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/19/2013**

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29071** BUIDLING ID: **3370**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Kanoon Magnet** REVIEW DATE: **4/2/2013**  
ADDRESS: **2233 S. Kedzie** IDPH LICENSE NO: **100-11170**

---

HOMOGENEOUS AREA: **41**  
MATERIAL DESCRIPTION: **12" X 12" Beige Speckled Floor Tile (Patch)**  
MATERIAL LOCATION: **2nd Floor Hall outside room 234 and Stairs**  
MATERIAL QUANTITY: **26** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Operations and Maintenance

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **04/02/2013**

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29071** BUIDLING ID: **3370**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Jesus Delgado**  
SCHOOL NAME: **Kanoon Magnet** INSPECTION DATE: **3/19/2013**  
ADDRESS: **2233 S. Kedzie** IDPH LICENSE NO: **100-11170**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **42**  
MATERIAL DESCRIPTION: **Gray Skid Pad Covering Adhesive**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Elevator**  
MATERIAL QUANTITY: **25** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/19/2013**

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29071** BUIDLING ID: **3370**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Kanoon Magnet** REVIEW DATE: **4/2/2013**  
ADDRESS: **2233 S. Kedzie** IDPH LICENSE NO: **100-11170**

---

HOMOGENEOUS AREA: **42**  
MATERIAL DESCRIPTION: **Gray Skid Pad Covering Adhesive**  
MATERIAL LOCATION: **Elevator**  
MATERIAL QUANTITY: **25** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Operations and Maintenance

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **04/02/2013**

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29071** BUIDLING ID: **3370**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Jesus Delgado**  
SCHOOL NAME: **Kanoon Magnet** INSPECTION DATE: **3/19/2013**  
ADDRESS: **2233 S. Kedzie** IDPH LICENSE NO: **100-11170**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **43**  
MATERIAL DESCRIPTION: **Ceramic Wall Tile Grout**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Janitors Closets**  
MATERIAL QUANTITY: **20** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/19/2013**

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29071** BUILDING ID: **3370**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Kanoon Magnet** REVIEW DATE: **4/2/2013**  
ADDRESS: **2233 S. Kedzie** IDPH LICENSE NO: **100-11170**

---

HOMOGENEOUS AREA: **43**  
MATERIAL DESCRIPTION: **Ceramic Wall Tile Grout**  
MATERIAL LOCATION: **Janitors Closets**  
MATERIAL QUANTITY: **20** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Operations and Maintenance

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **04/02/2013**

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29071** BUIDLING ID: **3370**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Jesus Delgado**  
SCHOOL NAME: **Kanoon Magnet** INSPECTION DATE: **3/19/2013**  
ADDRESS: **2233 S. Kedzie** IDPH LICENSE NO: **100-11170**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **44**  
MATERIAL DESCRIPTION: **Ceramic Wall Tile Adhesive**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Janitor's Closets**  
MATERIAL QUANTITY: **20** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/19/2013**

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29071** BUIDLING ID: **3370**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Kanoon Magnet** REVIEW DATE: **4/2/2013**  
ADDRESS: **2233 S. Kedzie** IDPH LICENSE NO: **100-11170**

---

HOMOGENEOUS AREA: **44**  
MATERIAL DESCRIPTION: **Ceramic Wall Tile Adhesive**  
MATERIAL LOCATION: **Janitor's Closets**  
MATERIAL QUANTITY: **20** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Operations and Maintenance

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **04/02/2013**

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29071** BUIDLING ID: **3370**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Jesus Delgado**  
SCHOOL NAME: **Kanoon Magnet** INSPECTION DATE: **3/19/2013**  
ADDRESS: **2233 S. Kedzie** IDPH LICENSE NO: **100-11170**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **45**  
MATERIAL DESCRIPTION: **Gray Carpet Adhesive**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Assembly Hall**  
MATERIAL QUANTITY: **4000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/19/2013**

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29071** BUIDLING ID: **3370**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Kanoon Magnet** REVIEW DATE: **4/2/2013**  
ADDRESS: **2233 S. Kedzie** IDPH LICENSE NO: **100-11170**

---

HOMOGENEOUS AREA: **45**  
MATERIAL DESCRIPTION: **Gray Carpet Adhesive**  
MATERIAL LOCATION: **Assembly Hall**  
MATERIAL QUANTITY: **4000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Operations and Maintenance

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **04/02/2013**

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29071** BUIDLING ID: **3370**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Jesus Delgado**  
SCHOOL NAME: **Kanoon Magnet** INSPECTION DATE: **3/19/2013**  
ADDRESS: **2233 S. Kedzie** IDPH LICENSE NO: **100-11170**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **5**  
MATERIAL DESCRIPTION: **Baseboard**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **03/19/2013**

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29071** BUIDLING ID: **3370**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Kanoon Magnet** REVIEW DATE: **4/2/2013**  
ADDRESS: **2233 S. Kedzie** IDPH LICENSE NO: **100-11170**

---

HOMOGENEOUS AREA: **5**

MATERIAL DESCRIPTION: **Baseboard**

MATERIAL LOCATION: **Throughout building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **04/02/2013**

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29071** BUIDLING ID: **3370**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Jesus Delgado**  
SCHOOL NAME: **Kanoon Magnet** INSPECTION DATE: **3/19/2013**  
ADDRESS: **2233 S. Kedzie** IDPH LICENSE NO: **100-11170**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **6**  
MATERIAL DESCRIPTION: **Baseboard Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **03/19/2013**

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29071** BUIDLING ID: **3370**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Kanoon Magnet** REVIEW DATE: **4/2/2013**  
ADDRESS: **2233 S. Kedzie** IDPH LICENSE NO: **100-11170**

---

HOMOGENEOUS AREA: **6**

MATERIAL DESCRIPTION: **Baseboard Mastic**

MATERIAL LOCATION: **Throughout building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **04/02/2013**

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29071** BUIDLING ID: **3370**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Jesus Delgado**  
SCHOOL NAME: **Kanoon Magnet** INSPECTION DATE: **3/19/2013**  
ADDRESS: **2233 S. Kedzie** IDPH LICENSE NO: **100-11170**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **7**  
MATERIAL DESCRIPTION: **Vault Door Insulation**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Main Office (Room 100D/Storage), Room 218**  
MATERIAL QUANTITY: **60** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/19/2013**

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29071** BUIDLING ID: **3370**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Kanoon Magnet** REVIEW DATE: **4/2/2013**  
ADDRESS: **2233 S. Kedzie** IDPH LICENSE NO: **100-11170**

---

HOMOGENEOUS AREA: **7**  
MATERIAL DESCRIPTION: **Vault Door Insulation**  
MATERIAL LOCATION: **Main Office (Room 100D/Storage), Room 218**  
MATERIAL QUANTITY: **60** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Operations and Maintenance

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **04/02/2013**

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29071** BUIDLING ID: **3370**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Jesus Delgado**  
SCHOOL NAME: **Kanoon Magnet** INSPECTION DATE: **3/19/2013**  
ADDRESS: **2233 S. Kedzie** IDPH LICENSE NO: **100-11170**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **8**  
MATERIAL DESCRIPTION: **Transite Counter Top**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Science Lab (Room 201)**  
MATERIAL QUANTITY: **150** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/19/2013**

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29071** BUIDLING ID: **3370**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Kanoon Magnet** REVIEW DATE: **4/2/2013**  
ADDRESS: **2233 S. Kedzie** IDPH LICENSE NO: **100-11170**

---

HOMOGENEOUS AREA: **8**  
MATERIAL DESCRIPTION: **Transite Counter Top**  
MATERIAL LOCATION: **Science Lab (Room 201)**  
MATERIAL QUANTITY: **150** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Operations and Maintenance

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **04/02/2013**

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29071** BUIDLING ID: **3370**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Jesus Delgado**  
SCHOOL NAME: **Kanoon Magnet** INSPECTION DATE: **3/19/2013**  
ADDRESS: **2233 S. Kedzie** IDPH LICENSE NO: **100-11170**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **9**  
MATERIAL DESCRIPTION: **Vibration Collar (isolation cloth)**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Ductwork throughout building - mechanical areas**

MATERIAL QUANTITY: **100**

MATERIAL UNITS: **LF**

DAMAGE QUANTITY:

DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature:



Date: **03/19/2013**

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29071** BUIDLING ID: **3370**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Kanoon Magnet** REVIEW DATE: **4/2/2013**  
ADDRESS: **2233 S. Kedzie** IDPH LICENSE NO: **100-11170**

---

HOMOGENEOUS AREA: **9**

MATERIAL DESCRIPTION: **Vibration Collar (isolation cloth)**

MATERIAL LOCATION: **Ductwork throughout building - mechanical areas**

MATERIAL QUANTITY: **100** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Operations and Maintenance

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **04/02/2013**

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29071** BUIDLING ID: **3370**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Jesus Delgado**  
SCHOOL NAME: **Kanoon Magnet** INSPECTION DATE: **3/19/2013**  
ADDRESS: **2233 S. Kedzie** IDPH LICENSE NO: **100-11170**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **B**  
MATERIAL DESCRIPTION: **Hard Joint Compound on Fiberglass Pipe Runs**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:  
DISTURBANCE POTENTIAL:  
MATERIAL LOCATION: **Throughout school (above ceiling tiles)**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:  
COMMENTS:

Inspector's Signature:



Date: **03/19/2013**

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29071** BUIDLING ID: **3370**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Kanoon Magnet** REVIEW DATE: **4/2/2013**  
ADDRESS: **2233 S. Kedzie** IDPH LICENSE NO: **100-11170**

---

HOMOGENEOUS AREA: **B**

MATERIAL DESCRIPTION: **Hard Joint Compound on Fiberglass Pipe Runs**

MATERIAL LOCATION: **Throughout school (above ceiling tiles)**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **04/02/2013**



# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29071** BUILDING ID: **3370**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Kanoon Magnet** REVIEW DATE: **4/2/2013**  
ADDRESS: **2233 S. Kedzie** IDPH LICENSE NO: **100-11170**

HOMOGENEOUS AREA: **46**

MATERIAL DESCRIPTION: **12"x12" Grey w/Dark Grey Streaks VFT**

MATERIAL LOCATION: **Rooms 116,120,122**

MATERIAL QUANTITY: **3300**

MATERIAL UNITS:

**SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS:

**SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_



Date: **04/02/2013**

K:\CPS 2011\2013 Three Year\A\Gad Drawings\Region 4\K\Kanoon Magnet School\Kanoon Magnet First Floor.dwg



**ASBESTOS REINSPECTION KEY NOTES:**

 HA-46 12"x 12" Grey with dark Grey Streaks Floor Tile

Kanoon Magnet First Floor  
2013 Asbestos Reinspection



CLIENT:  
Chicago Public Schools  
125 South Clark Street,  
Chicago, Illinois 60603

PROJECT NAME:  
2013 AHERA Reinspection  
Gerald Delgado Kanoon Elementary  
Magnet School  
2233 S Kedzie Ave  
Chicago, IL 60623

SHEET NAME:  
Kanoon Magnet First Floor -  
HA-46

INSPECTED BY:  
Jesus Delgado

DRAWN BY: MJW	DATE: 3/27/2013	CHECKED BY:
REVISED BY:	DATE:	CHECKED BY:
REVISED BY:	DATE:	CHECKED BY:
REVISED BY:	DATE:	CHECKED BY:

IDPH License #:100- 11170

Carnow, Conibear & Assoc., Ltd.  
Environmental Consulting Services  
600 W. Van Buren St., Suite 500, Chicago, IL 60607  
t: 312.782.4486 f: 312.782.5145  
www.ccaatl.com



CCA PROJECT NUMBER  
A320130001-202

DATE  
03/19/2013

SHEET NUMBER  
**HA-46**



# Chicago Public Schools

## Carnow, Conibear and Associates 2013 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29071** BUILDING ID: **3370**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Kanoon Magnet** REVIEW DATE: **4/2/2013**  
ADDRESS: **2233 S. Kedzie** IDPH LICENSE NO: **100-11170**

HOMOGENEOUS AREA: **49**

MATERIAL DESCRIPTION: **12"x12" Beige w/White Streaks VFT Mastic**

MATERIAL LOCATION: **Room 212**

MATERIAL QUANTITY: **740** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.


The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_



Date: **04/02/2013**



**ASBESTOS REINSPECTION KEY NOTES:**



HA-49 Mastic Associated with 12"x 12" Beige with White Streaks Floor Tile

Kanoon Magnet Second Floor  
2013 Asbestos Reinspection



NOT TO SCALE

CLIENT:  
Chicago Public Schools  
125 South Clark Street,  
Chicago, Illinois 60603

PROJECT NAME:  
2013 AHERA Reinspection  
Gerald Delgado Kanoon Elementary  
Magnet School  
2233 S Kedzie Ave  
Chicago, IL 60623

SHEET NAME:  
Kanoon Magnet Second Floor  
- HA-49

INSPECTED BY:  
Jesus Delgado

DRAWN BY: MJW	DATE: 3/27/2013	CHECKED BY:
REVISED BY:	DATE:	CHECKED BY:
REVISED BY:	DATE:	CHECKED BY:
REVISED BY:	DATE:	CHECKED BY:

IDPH License #:100- 11170

Carnow, Conibeare & Assoc., Ltd.  
Environmental Consulting Services  
600 W. Van Buren St., Suite 500, Chicago, IL 60607  
t: 312.782.4486 f: 312.782.5145  
www.ccaatl.com



CCA PROJECT NUMBER  
A320130001-202

DATE  
03/19/2013

SHEET NUMBER

**HA-49**

KCPSS 03112013 Three Years/Case Drawings/Region 4/Kanoon Magnet School/Kanoon Magnet Second Floor.dwg



# Chicago Public Schools

## Carnow, Conibear and Associates 2013 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29071** BUILDING ID: **3370**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Kanoon Magnet** REVIEW DATE: **4/2/2013**  
ADDRESS: **2233 S. Kedzie** IDPH LICENSE NO: **100-11170**

HOMOGENEOUS AREA: **47**  
MATERIAL DESCRIPTION: **12"x12" Grey w/Dark Grey Streaks VFT Mastic**  
MATERIAL LOCATION: **Rooms 116,120,122**  
MATERIAL QUANTITY: **3300** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**


---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_



Date: 04/02/2013

K:\CPS 2011\2013 Three Year\A\Gad Drawings\Region 4\K\Kanoon Magnet School\Kanoon Magnet First Floor.dwg



**ASBESTOS REINSPECTION KEY NOTES:**



HA-47 Mastic Associated with 12"x 12" Grey with dark Grey Streaks Floor Tile

Kanoon Magnet First Floor  
2013 Asbestos Reinspection



CLIENT:  
Chicago Public Schools  
125 South Clark Street,  
Chicago, Illinois 60603

PROJECT NAME:  
2013 AHERA Reinspection  
Gerald Delgado Kanoon Elementary  
Magnet School  
2233 S Kedzie Ave  
Chicago, IL 60623

SHEET NAME:  
Kanoon Magnet First Floor -  
HA-47

INSPECTED BY:  
Jesus Delgado

DRAWN BY: MJW	DATE: 3/27/2013	CHECKED BY:
REVISED BY:	DATE:	CHECKED BY:
REVISED BY:	DATE:	CHECKED BY:
REVISED BY:	DATE:	CHECKED BY:

IDPH License #:100- 11170

Carnow, Conibear & Assoc., Ltd.  
Environmental Consulting Services  
600 W. Van Buren St., Suite 500, Chicago, IL 60607  
t: 312.782.4486 f: 312.782.5145  
www.ccaatl.com



CCA PROJECT NUMBER  
A320130001-202

DATE  
03/19/2013

SHEET NUMBER  
**HA-47**



# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29071** BUILDING ID: **3370**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Kanoon Magnet** REVIEW DATE: **4/2/2013**  
ADDRESS: **2233 S. Kedzie** IDPH LICENSE NO: **100-11170**

HOMOGENEOUS AREA: **48**

MATERIAL DESCRIPTION: **12"x12" Beige w/White Streaks VFT**

MATERIAL LOCATION: **Room 212**

MATERIAL QUANTITY: **740** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_



Date: **04/02/2013**



# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **29071**      BUILDING ID: **3370**  
CITY/STATE: **Chicago, Illinois**      AHERA INSPECTOR: **Jesus Delgado**  
SCHOOL NAME: **Kanoon Magnet**      INSPECTION DATE: **3/19/2013**  
ADDRESS: **2233 S. Kedzie**      IDPH LICENSE NO: **100-11170**

---

### INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **50**  
MATERIAL DESCRIPTION: **12"x12" Red VFT**  
MATERIAL LOCATION: **Room 212**  
MATERIAL QUANTITY: **30**      MATERIAL UNITS: **SF**  
MATERIAL CATEGORY: **MISC**      FRIABLE: **No**  
ASBESTOS TYPE: **Assumed**  
DISTURBANCE POTENTIAL: **LOW**      CONDITION:  
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
ACCESSIBILITY: **Within Reach**      DAMAGE REASON:  
DAMAGE QUANTITY: **0**      DAMAGE REASON:  
DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature:



Date: **03/19/2013**

# Chicago Public Schools

## Carnow, Conibear and Associates 2013 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **29071**      BUILDING ID: **3370**  
CITY/STATE: **Chicago, Illinois**      MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Kanoon Magnet**      REVIEW DATE: **4/2/2013**  
ADDRESS: **2233 S. Kedzie**      IDPH LICENSE NO: **100-11170**

HOMOGENEOUS AREA: **50**  
MATERIAL DESCRIPTION: **12"x12" Red VFT**  
MATERIAL LOCATION: **Room 212**  
MATERIAL QUANTITY: **30**      MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0**      DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_



Date: 04/02/2013





# Chicago Public Schools

## Carnow, Conibear and Associates 2013 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29071** BUILDING ID: **3370**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Kanoon Magnet** REVIEW DATE: **4/2/2013**  
ADDRESS: **2233 S. Kedzie** IDPH LICENSE NO: **100-11170**

HOMOGENEOUS AREA: **52**  
MATERIAL DESCRIPTION: **Grey Patterned Carpet Mastic**  
MATERIAL LOCATION: **Room 225(Library)**  
MATERIAL QUANTITY: **1430** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**


---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_



Date: 04/02/2013



**ASBESTOS REINSPECTION KEY NOTES:**



HA-52 Mastic Associated with Grey Patterned Carpet

Kanoon Magnet Second Floor  
2013 Asbestos Reinspection



NOT TO SCALE

CLIENT:  
Chicago Public Schools  
125 South Clark Street,  
Chicago, Illinois 60603

PROJECT NAME:  
2013 AHERA Reinspection  
Gerald Delgado Kanoon Elementary  
Magnet School  
2233 S Kedzie Ave  
Chicago, IL 60623

SHEET NAME:  
Kanoon Magnet Second Floor  
- HA-52

INSPECTED BY:  
Jesus Delgado

DRAWN BY: MJW	DATE: 3/27/2013	CHECKED BY:
REVISED BY:	DATE:	CHECKED BY:
REVISED BY:	DATE:	CHECKED BY:
REVISED BY:	DATE:	CHECKED BY:

IDPH License #:100- 11170

Carnow, Conibear & Assoc., Ltd.  
Environmental Consulting Services  
600 W. Van Buren St., Suite 500, Chicago, IL 60607  
t: 312.782.4486 f: 312.782.5145  
www.ccaatd.com



CCA PROJECT NUMBER  
A320130001-202

DATE  
03/19/2013

SHEET NUMBER

**HA-52**



# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29071** BUILDING ID: **3370**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Kanoon Magnet** REVIEW DATE: **4/2/2013**  
ADDRESS: **2233 S. Kedzie** IDPH LICENSE NO: **100-11170**

HOMOGENEOUS AREA: **51**  
MATERIAL DESCRIPTION: **12"x12" Red VFT Mastic**  
MATERIAL LOCATION: **Room 212**  
MATERIAL QUANTITY: **30** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**


---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.


The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_



Date: 04/02/2013



**ASBESTOS REINSPECTION KEY NOTES:**



HA-51 Mastic Associated with 12"x 12" Red Floor Tile

Kanoon Magnet Second Floor  
2013 Asbestos Reinspection



CLIENT:  
Chicago Public Schools  
125 South Clark Street,  
Chicago, Illinois 60603

PROJECT NAME:  
2013 AHERA Reinspection  
Gerald Delgado Kanoon Elementary  
Magnet School  
2233 S Kedzie Ave  
Chicago, IL 60623

SHEET NAME:  
Kanoon Magnet Second Floor  
- HA-51

INSPECTED BY:  
Jesus Delgado

DRAWN BY: MJW	DATE: 3/27/2013	CHECKED BY:
REVISED BY:	DATE:	CHECKED BY:
REVISED BY:	DATE:	CHECKED BY:
REVISED BY:	DATE:	CHECKED BY:

IDPH License #:100- 11170

Carnow, Conibear & Assoc., Ltd.  
Environmental Consulting Services  
600 W. Van Buren St., Suite 500, Chicago, IL 60607  
t: 312.782.4486 f: 312.782.5145  
www.ccaatd.com



CCA PROJECT NUMBER  
A320130001-202

DATE  
03/19/2013


SHEET NUMBER

**HA-51**

# APPENDIX B

## Inspector and Management Planner Licenses

---



# Occupational Training & Supply, Inc.

7233 Adams Street • Willowbrook, IL 60527 • (630) 655-3900

## Asbestos Building Inspector Refresher

Occupational Training and Supply, Inc. certifies that

### Jesus Delgado

has successfully completed the 4 hour Asbestos Building Inspector Refresher Course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 10 CFR 763 Asbestos Hazard Emergency Response Act (AHERA) and TSCA Title II.

Certificate: BIR1301040034

Exam Date: 1/4/2013

Course Date: 1/4/2013

Expiration Date: 1/4/2014

  
Kathy DeSalvo, Director

2013



525-535 West Jefferson Street • Springfield, Illinois 62761-0001 • [www.idph.state.il.us](http://www.idph.state.il.us)

Pat Quinn, Governor

2/7/2013

JESUS M DELGADO  
5256 HARCOURT ST  
OAK FOREST, IL 60452

ASBESTOS PROFESSIONAL LICENSE ID NUMBER: 11170


Enclosed is your Asbestos Professional License that expires 05/15/2014

CERTIFICATE EXPIRATION DATE

INSPECTOR 1/4/2014

PROJECT MANAGER 11/2/2013  
AIR SAMPLING PROFESSIONAL

If you have any questions or need further assistance, contact the Asbestos Program at (217)782-3517 or fax (217)785-5897.  
Our WEB address is <http://www.idph.state.il.us/envhealth/ehhome.htm>





# Occupational Training & Supply, Inc.

7233 Adams Street • Willowbrook, IL 60527 • (630) 655-3900

## Asbestos Building Inspector Refresher

*Occupational Training and Supply, Inc. certifies that*

# Daniel Juneau

**has successfully completed the 4 hour Asbestos Building Inspector Refresher Course**  
and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department  
of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance  
with EPA 10 CFR 763 Asbestos Hazard Emergency Response Act (AHERA) and TSCA Title II.

Certificate: BIR1212042319

Exam Date: 12/4/2012

Course Date: 12/4/2012

Expiration Date: 12/4/2013

Kathy DeSalvo, Director

2012



# Occupational Training & Supply, Inc.

7233 Adams Street ♦ Willowbrook, IL 60527 ♦ (630) 655-3900

## Asbestos Management Planner Refresher

*Occupational Training and Supply, Inc. certifies that*

# Daniel Juneau

**has successfully completed the 4 hour Asbestos Management Planner Refresher Course** and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 10 CFR 763 Asbestos Hazard Emergency Response Act (AHERA) and TSCA Title II.

Certificate: MPR1302250736

Exam Date: 2/25/2013

Course Date: 2/25/2013

Expiration Date: 2/25/2014

  
Kathy DeSalvo, Director

2013



# Occupational Training & Supply, Inc.

7233 Adams Street ♦ Willowbrook, IL 60527 ♦ (630) 655-3900

## Asbestos Management Planner Refresher

*Occupational Training and Supply, Inc. certifies that*

# Daniel Juneau

**has successfully completed the 4 hour Asbestos Management Planner Refresher Course** and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 10 CFR 763 Asbestos Hazard Emergency Response Act (AHERA) and TSCA Title II.

Certificate: MPR1302250736

Exam Date: 2/25/2013

Course Date: 2/25/2013

Expiration Date: 2/25/2014

Kathy DeSalvo, Director

2013

# Daniel Juneau

Illinois Licensed Asbestos Inspector, Management Planner,  
Project Manager, and Air Sampling Professional



## ASBESTOS PROFESSIONAL LICENSE

ID NUMBER  
**100 - 03613**

ISSUED  
**4/11/2013**

EXPIRES  
**05/15/2014**

DANIEL J JUNEAU  
1408 OAKWOOD AVENUE  
DES PLAINES, IL 60016

Environmental Health



### ENDORSEMENTS

### TC EXPIRES

INSPECTOR

12/4/2013

MANAGEMENT PLANNER

2/25/2014

PROJECT MANAGER

12/3/2013

AIR SAMPLING PROFESSIONAL

**Alteration of this license shall result in legal action**  
This license issued under authority of the State of Illinois  
Department of Public Health

This license is valid only when accompanied by a valid  
training course certificate.

**CARNOW  
CONIBEAR**

# APPENDIX C

## Laboratory Accreditations

---

# APPENDIX D

## Laboratory Results

---

# APPENDIX E

## Chain of Custody Forms

---

## Three-Year Reinspection Key to Terms

	<b>CODE</b>	<b>KEY</b>
<b>MATERIAL</b>		
	ACBM	Asbestos Containing Building Materials
<b>MATERIAL CATEGORY</b>		
	MISC	Miscellaneous
	SURF	Surfacing
	TSI	Thermal System Insulation
<b>MATERIAL UNITS</b>		
	LF	Linear Feet
	SF	Square Feet
	CF	Cubic Feet
<b>DAMAGE TYPE</b>		
	Loc	Localized
	Dist	Distributed