

**ILLINOIS DEPARTMENT OF PUBLIC HEALTH  
AHERA THREE YEAR REINSPECTION  
ASBESTOS ABATEMENT PROGRAM  
SCHOOL INFORMATION FORM**

**SECTION I**

NAME OF SCHOOL DISTRICT: CHICAGO SCHOOL DIST 299  
SCHOOL ID NUMBER: 14-016-2990-0053  
SCHOOL NAME: Lenart Center  
ADDRESS OF SCHOOL: 8101 S. LaSalle Street  
CITY: Chicago, IL, 60620

DATE LAST THREE YEAR REINSPECTION WAS COMPLETED

**If the address on this form is different than the address of the building, submit a written explanation.**

---

**SECTION II** *(Please type or print)*

**PLEASE COMPLETE THE FOLLOWING FOR YOUR THREE YEAR REINSPECTION:**

DATE REINSPECTION COMPLETED: 3/31/2013 ENROLLMENT 318  
IDPH INSPECTOR LICENSE NUMBER: 100-02950  
IDPH LICENSED INSPECTOR NAME (Please Print): Keith Clough  
IDPH MP LICENSE NUMBER: 100-03613  
IDPH LICENSED MANAGEMENT PLANNER NAME (Please Print): Daniel Juneau

DESIGNATED PERSON (Please Print): Ms. Lynn Crivello PHONE: (773) 553-3113



3/31/2013

*Signature of Designated Person*

*Date*

---

**SECTION III**

PLEASE COMPLETE THE FOLLOWING INFORMATION FOR ANY CHANGES WITHIN THE SCHOOL DISTRICT.

School building has been sold. Date of Sale: \_\_\_\_\_

School has been closed. Date closed: \_\_\_\_\_

School building has been demolished. Date: \_\_\_\_\_

School building is asbestos free since last reinspection: \_\_\_\_\_

**Please explain in writing why the school building is now asbestos free and include the supporting documentation.**

If a new school building has been added to the district, submit either an exclusionary statement or a management plan and inspection report. Include the complete name, address and city of school building.

**Explain in writing if the address of the building is different than the address on this form:**

**THREE-YEAR REINSPECTION**

**CHICAGO SCHOOL DIST 299**

**Lenart Center**

8101 S. LaSalle Street  
Chicago, IL, 60620

Unit: 29361  
Building ID: 7240

IDPH ID Number: 14-016-2990-0053

**REPORT DATE:**

Sunday, March 31, 2013

**Prepared for:**

**Chicago Public Schools**  
**125 S. Clark Street**  
**Chicago, IL 60603**

**Prepared by:**

**Carnow, Conibear and Associates**

600 West Van Buren St., Ste 500

Phone (312) 762-2900

Fax (312) 782-5145

**DO NOT REMOVE FROM SCHOOL  
REQUIRED BY FEDERAL LAW**

March 20, 2013

Mr. R. Kent Cook  
Asbestos Program  
Illinois Department of Public Health  
525 West Jefferson Street  
Springfield, Illinois 62761

Re: Chicago Public Schools - 2013 Three-Year Reinspections

Dear Mr. Cook:

Carnow, Conibear and Associates, Managing Environmental Consultant (MEC), conducted the Three-Year Reinspections and performed management plan updates for the Chicago Public Schools (CPS) facilities in Region 3,4,5 Elementary Schools. Please update your records with the following information.

School District: 299      Unit: 29361      Region: 05      IDPH ID: 14-016-2990-0053

School: Lenart Center      Building ID: 7240

Address: 8101 S. LaSalle Street  
Chicago, IL, 60620

Building Contact: Tucker, Jerome      Contact Phone: 773-978-3604


Current Building Owners: Chicago Public Schools

Review Date: 3/31/2013

Inspector: Keith Clough      Inspector IDPH License: 100-02950  
Management Planner: Daniel Juneau      Management Planner IDPH License: 100-03613

If you have any questions or comments, please contact us at (312) 762-2900

Sincerely,  
Carnow, Conibear and Associates



Daniel Juneau  
100-03613

## **Environmental Notification to Occupants**

To: Faculty, Staff and Parents  
From: Chicago Public Schools  
Date: March 20, 2013

RE: Lenart Center, Unit 29361  
8101 S. LaSalle Street  
Chicago, IL, 60620

Dear Faculty, Staff and Parents,

This letter is to notify you that the 2013 asbestos three year re-inspection has been completed at Lenart Center , following the Federal Asbestos Hazard Emergency Response Act (AHERA), 40 CFR Part 763, Subpart E and is available for your review at the main office of the school.

Although asbestos-containing materials have been identified at Lenart Center, there is no reason to believe that any threat to the health of students or staff exists at this time. CPS will continue to carefully monitor the condition of asbestos-containing materials and if conditions warrant, all appropriate steps will be taken to maintain the health and safety of all building occupants.

If you have any questions regarding this matter or require additional information, please feel free to contact Ms. Lynn Crivello, the designated Local Education Authority's Designated Person at (773) 553-3113 .

## **Table of Contents**

- I. School and Inspection Information
- II. Executive Summary
- III. Methodology
- IV. Abatement History
- V. Reassessments and Recommendations
- VI. Conclusions

Table I: Inspector's Reinspection Findings

Table II: Management Planner's Review

### **APPENDICES:**

- Appendix A: Assessment Sheets, Drawings and Photos
- Appendix B: Inspector and Management Planner Licenses
- Appendix C: Laboratory Accreditations
- Appendix D: Laboratory Results
- Appendix E: Chain of Custody Forms

## SCHOOL AND INSPECTION INFORMATION

### 1. School Information

School: Lenart Center Unit: 29361 Region: 05  
Address: 8101 S. LaSalle Street Chicago, IL, 60620  
IDPH ID: 14-016-2990-0053 Building ID: 7240  
Contact: Tucker, Jerome Phone: 773-978-3604

### 2. Description of Facility

Original Construction: Additional Construction:  
Total Square Footage: 59400 No of Floors:  
Current Occupancy: 318

### 3. LEA Designated Person

Contact: Ms. Lynn Crivello Phone: (773) 553-3113  
Address: 125 South Clark Street, 17th Floor  
Chicago, IL 60603

### 4. Managing Environmental Consultant

MEC: Carnow, Conibear and Associates  
Contact: Dan Juneau  
Address 600 West Van Buren St., Ste 500  
Phone: (312) 762-2900 Fax: (312) 782-5145

### 5. Inspector

Inspector Name: Keith Clough




Inspector IDPH license # 100-02950

Signature:  
Date: 3/20/2013

### 6. Management Planner

Management Planner Name: Daniel Juneau



Management Planner IDPH license # 100-03613

Signature:  
Date: 3/31/2013

### 7. Review Date: 3/31/2013

### 8. LEA Designated Person's Acknowledgement

The reinspection report and recommendations have been received by me and appropriate action will be taken by the School District.

Signature: 

Date: 3/31/2013

Name: Ms. Lynn Crivello

## II. EXECUTIVE SUMMARY

Carnow, Conibear and Associates was retained by the Chicago Public Schools (CPS) to perform a three-year asbestos reinspection of the Lenart Center. This inspection was conducted in accordance with the United States Environmental Protection Agency (USEPA) Asbestos Hazard Emergency Response Act (AHERA) part 763.92 (b), and the ongoing Operations and Maintenance Program (O&M) originally designed in the School's Asbestos Management Plan. The purpose of this three-year reinspection is to record any condition changes in the asbestos-containing building material (ACBM) in the school since the previous three-year reinspection and the six-month periodic surveillance, to identify, assess, and include any Homogeneous Areas (HA) not identified in the Management Plan, and to recommend an appropriate response action to manage asbestos.

The inspector conducted a three-year reinspection of this facility under Illinois Department of Public Health (IDPH) school reinspection requirements and AHERA, sections 763.85 and 763.88. The main building and each addition to the main building, if constructed at different dates, were inspected separately. Laboratory accreditations are included in Appendix C, laboratory results are included in Appendix D, and chain of custody forms are included in Appendix E.

Note: During previous inspections, some of the HA(s) were identified together as 9" x 9" floor tile (FT), mastics assoc. with 9" x 9" FT, 12" x 12" FT, mastics assoc. with 12" x 12" FT, pipe insulation, etc. Some of these HA(s) have been re-identified by areas that are uniform in color, texture, construction date, application date, and general appearance.

The inspector has determined the following:

A. The following HAs have changed assessment categories for Building 7240:

10	aircell pipe insulation
13	cardboard pipe insulation
CM-1	carpet mastic
FTM-7	blue linoleum mastic
FTM-8	12x12 white floor tile mastic

B. The following new homogenous areas have been identified for Building 7240:



C. This reinspection covered only physically accessible and visible areas and materials that were identified in the LEA's management plan. The following materials were concealed and/or contained in areas that were inaccessible for sampling and have been classified as Assumed:

16	Tank insulation
17	Aircell pipe insulation.
18	Plaster.
19	Braided Pipe Wrap
20	Green Linoleum Flooring Mastic
CM-1	carpet mastic
FT-2	cream/peach linoleum
FT-3	12x12 teal floor tile (part of checkerboard)
FT-4	12x12 caramel floor tile
FT-7	blue linoleum
FT-8	12x12 white floor tile
FT-9	brown linoleum
FTM-1	9x9 Brown floor tile mastic
FTM-7	blue linoleum mastic
FTM-8	12x12 white floor tile mastic
FTM-9	Green linoleum mastic (not observed)

The following areas were deemed to be inaccessible:

Materials were also listed as "assumed" if they were in good condition and sampling was not conducted to avoid damage.

This reinspection was conducted by Keith Clough, IDPH License # 100-02950. The Management Plan was updated by Daniel Juneau, IDPH License # 100-03613. Inspector and Management Planner Licenses are included in Appendix B.

### **III. METHODOLOGY**

Tasks performed on-site included the following:

1. Review current management plan, identify HA(s) and extract appropriate information.
2. Examine and verify abatement records.
3. Touch and visually and physically reinspect and reassess the condition of all friable known or assumed ACBM.
4. Touch and visually and physically reinspect all non-friable known or assumed ACBM to determine whether these materials have become friable since the last inspection or periodic surveillance.
5. Identify any condition changes that may affect Hazard Ranking of known ACBM or Assumed ACBM, as well as any HA(s) that have become friable since the last reinspection.
6. Collect bulk samples from each newly discovered friable HA or previously assumed and submit for laboratory analysis.
7. Tabulate reinspection findings and submit for management planner review and recommendations with appropriate response actions based on the AHERA Damage Category of the ACBM.
8. Submit reinspection findings and management planner recommendations to the LEA within thirty (30) days for inclusion into the management plan.

### **IV. ABATEMENT HISTORY**

The information collected from the existing management plan and inspection report(s) and from interviews with the school official revealed that the following asbestos abatement was conducted at the school since the previous Three year Reinspection.

Abatement Dates:

### **V. REASSESSMENTS AND RECOMMENDATIONS**

The reassessments and recommendations are summarized in Tables I and II on the following pages. Detailed Hazard Assessment Sheets and Drawings and Photos (if applicable) are included in Appendix A.

### **VI. CONCLUSIONS**

The Lenart Center Building 7240 Three-Year reinspection has been completed and response actions have been recommended for both friable and non-friable materials. A timely execution of the response actions recommended will enable the LEA and the Designated Person(s) to effectively manage the existing ACBM.

This three-year reinspection report should be inspected in the current Management plan at the CPS Central Office, and one (1) copy should be kept at the school for use when planning any renovation and/or demolition activities in areas where ACBM has been identified. Also, periodic surveillance documentation and any summary reports from any response actions that are executed at the school should be used to update the Management Plan.

**Table I**  
**Inspector's Reinspection Findings**

---

# Chicago Public Schools

School Lenart Center Unit 29361 Building ID 7240

Address 8101 S. LaSalle Street Region 05

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
10	aircell pipe insulation	1,000	LF	unexcavated areas. Heat plenums, pump room, supply room	CHR	TSI	Y	DIST	40		Yes	Damaged or significantly damaged friable thermal system insulating ACBM	3	HIGH
11	aircell fittings	200	SF	unexcavated areas. Heat plenums, pump room, supply room	CHR	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW
12	aircell duct wrap	300	SF	unexcavated areas	CHR	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW
13	cardboard pipe insulation	270	LF	unexcavated areas and south heat plenum	CHR	TSI	Y	DIST	30		Yes	Damaged or significantly damaged friable thermal system insulating ACBM		HIGH
14	cardboard pipe fittings	50	LF	unexcavated areas and south heat plenum	CHR	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW
15	rope pipe insulation	60	LF	North and South Fan Rooms	CHR	MISC	Y	NONE	0		No	ACBM with the potential for damage		LOW
16	Tank insulation	80	SF	upper tank rm. Boiler room	ASSUMED	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW
17	Aircell pipe insulation.	190	LF	below the upper tank.	ASSUMED	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW
18	Plaster.	80,000	SF	core walls of tunnel and throughout	ASSUMED	SURFACE	Y	NONE	0		No	ACBM with the potential for damage		LOW
19	Braided Pipe Wrap	10	LF	Auditorium stage stair area	ASSUMED	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW
20	Green Linoleum Flooring Mastic	2,000	SF	2nd Fl. SE Corridor and elevator Lobby on 1st, 2nd, & 3rd Fl.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
CM-1	carpet mastic	2,750	SF	Room 110, Principals office, main office, general office, copy/store room	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
FT-1	9x9 brown floor tile	2,600	SF	engineers office, restroom and auditorium	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
FT-2	cream/peach linoleum	1,300	SF	lunchroom & boys lockerroom	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
FT-3	12x12 teal floor tile (part of checkerboard)	1,385	SF	1st floor corridor	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
FT-4	12x12 caramel floor tile	3,025	SF	1st & 3rd floor corridor (1st floor	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW

# Chicago Public Schools

School Lenart Center Unit 29361 Building ID 7240

Address 8101 S. LaSalle Street Region 05

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				part of checkerboard)										
FT-5	9x9 green floor tile	725	SF	2nd floor corridor N/S (part of checkerboard)	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
FT-6	9x9 tan floor tile	725	SF	2nd floor corridor N/s-part of checkerboard	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
FT-7	blue linoleum	1,500	SF	2nd floor computer lab and 303	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
FT-8	12x12 white floor tile	250	SF	2nd floor MDF room next to computer lab	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
FT-9	brown linoleum	450	SF	2nd floor elevator lobby	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
FTM-1	9x9 Brown floor tile mastic	2,600	SF	engineers office, restroom, and auditorium	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
FTM-3	12x12 Teal floor tile mastic	1,385	SF	1st floor corridor-part of checkerboard	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
FTM-4	12x12 caramel floor tile mastic	3,025	SF	1st and 3rd floor corridor	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
FTM-5	9x9 green floor tile mastic	725	SF	2nd floor corridor N/S-part of checkerboard	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
FTM-6	9x9 tan floor tile mastic	725	SF	2nd floor corridor N/S-part of checkerboard	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
FTM-7	blue linoleum mastic	1,500	SF	2nd floor computer lab and 303	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
FTM-8	12x12 white floor tile mastic	250	SF	2nd floor MDF room next to computer lab	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
FTM-9	Green linoleum mastic (not observed)	450	SF	2nd floor elevator lobby	ASSUMED	MISC	N							

# Chicago Public Schools

School Lenart Center Unit 29361 Building ID 7240

Address 8101 S. LaSalle Street Region 05

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

*Inspector's Comments are Summarized at the End of the Report*

Reinspection Date <b>3/20/2013</b>
Inspector Name <b>Keith Clough</b>
<b>100-02950</b> <span style="float: right;"><b>5/15/2013</b></span>
Inspector's IDPH License Number / Expiration Date

#### Inspector's Comments

HA Number:	Inspector Comments:
10	
11	
12	
13	
14	
15	
16	
17	
18	
19	
20	
CM-1	
FT-1	
FT-2	
FT-3	
FT-4	
FT-5	
FT-6	
FT-7	
FT-8	
FT-9	
FTM-1	
FTM-3	
FTM-4	

# Chicago Public Schools

School Lenart Center Unit 29361 Building ID 7240

Address 8101 S. LaSalle Street Region 05

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

*Inspector's Comments are Summarized at the End of the Report*

---

HA Number:	Inspector Comments:
FTM-5	
FTM-6	
FTM-7	
FTM-8	
FTM-9	

**Table II**

**Management Planner's Review**

---



# Chicago Public Schools

**School** Lenart Center  
**Address** 8101 S. LaSalle Street

**Unit** 29361  
Chicago, IL, 60620

**Building ID** 7240  
**Region** 05

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

### Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
10	aircell pipe insulation	1,000	LF	unexcavated areas. Heat plenums, pump room, supply room	Chrysotile	TSI	Yes	40	LF	1 Damaged or significantly damaged friable thermal system insulating ACBM	Remove
11	aircell fittings	200	SF	unexcavated areas. Heat plenums, pump room, supply room	Chrysotile	TSI	Yes	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
12	aircell duct wrap	300	SF	unexcavated areas	Chrysotile	TSI	Yes	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
13	cardboard pipe insulation	270	LF	unexcavated areas and south heat plenum	Chrysotile	TSI	Yes	30	LF	1 Damaged or significantly damaged friable thermal system insulating ACBM	Remove
14	cardboard pipe fittings	50	LF	unexcavated areas and south heat plenum	Chrysotile	TSI	Yes	0	LF	6 ACBM with the potential for damage	Operations and Maintenance
15	rope pipe insulation	60	LF	North and South Fan Rooms	Chrysotile	MISC	Yes	0	LF	6 ACBM with the potential for damage	Operations and Maintenance
16	Tank insulation	80	SF	upper tank rm. Boiler room	Assumed	TSI	Yes	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
17	Aircell pipe insulation.	190	LF	below the upper tank.	Assumed	TSI	Yes	0	LF	6 ACBM with the potential for damage	Operations and Maintenance
18	Plaster.	80,000	SF	core walls of tunnel and throughout	Assumed	SURFACE	Yes	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
19	Braided Pipe Wrap	10	LF	Auditorium stage stair area	Assumed	TSI	Yes	0	LF	6 ACBM with the potential for damage	Operations and Maintenance
20	Green Linoleum Flooring Mastic	2,000	SF	2nd Fl. SE Corridor and elevator Lobby on 1st, 2nd, & 3rd Fl.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
CM-1	carpet mastic	2,750	SF	Room 110, Principals office, main office, general office, copy/store room	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
FT-1	9x9 brown floor tile	2,600	SF	engineers office, restroom and auditorium	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
FT-2	cream/peach linoleum	1,300	SF	lunchroom & boys lockerroom	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
FT-3	12x12 teal floor tile (part of checkerboard)	1,385	SF	1st floor corridor	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
FT-4	12x12 caramel floor tile	3,025	SF	1st & 3rd floor corridor (1st floor part of checkerboard)	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
FT-5	9x9 green floor tile	725	SF	2nd floor corridor N/S (part of checkerboard)	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
FT-6	9x9 tan floor tile	725	SF	2nd floor corridor N/s-part of checkerboard	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
FT-7	blue linoleum	1,500	SF	2nd floor computer lab and 303	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
FT-8	12x12 white floor tile	250	SF	2nd floor MDF room next to computer lab	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
FT-9	brown linoleum	450	SF	2nd floor elevator lobby	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
FTM-1	9x9 Brown floor tile mastic	2,600	SF	engineers office, restroom, and auditorium	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
FTM-3	12x12 Teal floor tile mastic	1,385	SF	1st floor corridor-part of checkerboard	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
FTM-4	12x12 caramel floor tile mastic	3,025	SF	1st and 3rd floor corridor	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance

# Chicago Public Schools

**School** Lenart Center  
**Address** 8101 S. LaSalle Street

**Unit** 29361  
 Chicago, IL, 60620

**Building ID** 7240  
**Region** 05

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

### *Management Planner's Comments Summarized at the End of the Report*

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
FTM-5	9x9 green floor tile mastic	725	SF	2nd floor corridor N/S-part of checkerboard	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
FTM-6	9x9 tan floor tile mastic	725	SF	2nd floor corridor N/S-part of checkerboard	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
FTM-7	blue linoleum mastic	1,500	SF	2nd floor computer lab and 303	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
FTM-8	12x12 white floor tile mastic	250	SF	2nd floor MDF room next to computer lab	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
FTM-9	Green linoleum mastic (not observed)	450	SF	2nd floor elevator lobby	Assumed	MISC	No		SF		

# Chicago Public Schools

**School** Lenart Center  
**Address** 8101 S. LaSalle Street

**Unit** 29361  
 Chicago, IL, 60620

**Building ID** 7240  
**Region** 05

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

### *Management Planner's Comments Summarized at the End of the Report*

Review Date	3/31/2013
Manager Planner Name	Daniel Juneau
100-03613	5/15/2014
Manager IDPH License No/Expiration	

HA Number	Management Comments
10	Unexcavated area shall be labeled as an asbestos hazard until response action can be implemented.
11	
12	
13	Unexcavated area shall be labeled as an asbestos hazard until response action can be implemented.
14	
15	
16	
17	
18	
19	
20	
CM-1	
FT-1	
FT-2	
FT-3	
FT-4	
FT-5	
FT-6	
FT-7	
FT-8	
FT-9	
FTM-1	
FTM-3	
FTM-4	
FTM-5	
FTM-6	

# Chicago Public Schools

**School** Lenart Center  
**Address** 8101 S. LaSalle Street

**Unit** 29361  
Chicago, IL, 60620

**Building ID** 7240  
**Region** 05

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates  
600 West Van Buren St., Ste 500  
Phone: (312) 762-2900

Fax: (312) 782-5145

### *Management Planner's Comments Summarized at the End of the Report*

HA Number	Management Comments
FTM-7	
FTM-8	
FTM-9	

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29361** BUIDLING ID: **7240**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Keith Clough**  
SCHOOL NAME: **Lenart Center** INSPECTION DATE: **3/20/2013**  
ADDRESS: **8101 S. LaSalle Street** IDPH LICENSE NO: **100-02950**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **10**  
MATERIAL DESCRIPTION: **aircell pipe insulation**  
HISTORICAL AHERA DAMAGE CATEGORY **1**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **1. Damaged or significantly damaged friable thermal system insulating ACBM**

DAMAGE REASON: **Deterioration**  
DISTURBANCE POTENTIAL: **HIGH**  
MATERIAL LOCATION: **unexcavated areas. Heat plenums, pump room, supply room**  
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: DAMAGE UNITS: **LF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 03/20/2013

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29361** BUIDLING ID: **7240**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Lenart Center** REVIEW DATE: **3/31/2013**  
ADDRESS: **8101 S. LaSalle Street** IDPH LICENSE NO: **100-02950**

---

HOMOGENEOUS AREA: **10**  
MATERIAL DESCRIPTION: **aircell pipe insulation**  
MATERIAL LOCATION: **unexcavated areas. Heat plenums, pump room, supply room**  
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **40** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Unexcavated area shall be labeled as an asbestos hazard until response action can be implemented.

Management Planner's Signature: \_\_\_\_\_



Date: **03/31/2013**

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29361** BUIDLING ID: **7240**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Keith Clough**  
SCHOOL NAME: **Lenart Center** INSPECTION DATE: **3/20/2013**  
ADDRESS: **8101 S. LaSalle Street** IDPH LICENSE NO: **100-02950**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **11**  
MATERIAL DESCRIPTION: **aircell fittings**  
HISTORICAL AHERA DAMAGE CATEGORY **6**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **unexcavated areas. Heat plenums, pump room, supply room**

MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 03/20/2013

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29361** BUILDING ID: **7240**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Lenart Center** REVIEW DATE: **3/31/2013**  
ADDRESS: **8101 S. LaSalle Street** IDPH LICENSE NO: **100-02950**

---

HOMOGENEOUS AREA: **11**  
MATERIAL DESCRIPTION: **aircell fittings**  
MATERIAL LOCATION: **unexcavated areas. Heat plenums, pump room, supply room**  
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**


---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **03/31/2013**



# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29361** BUIDLING ID: **7240**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Keith Clough**  
SCHOOL NAME: **Lenart Center** INSPECTION DATE: **3/20/2013**  
ADDRESS: **8101 S. LaSalle Street** IDPH LICENSE NO: **100-02950**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **12**  
MATERIAL DESCRIPTION: **aircell duct wrap**  
HISTORICAL AHERA DAMAGE CATEGORY **6**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **unexcavated areas**  
MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 03/20/2013

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29361** BUIDLING ID: **7240**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Lenart Center** REVIEW DATE: **3/31/2013**  
ADDRESS: **8101 S. LaSalle Street** IDPH LICENSE NO: **100-02950**

---

HOMOGENEOUS AREA: **12**  
MATERIAL DESCRIPTION: **aircell duct wrap**  
MATERIAL LOCATION: **unexcavated areas**  
MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**


---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **03/31/2013**

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 29361 BUIDLING ID: 7240  
CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Keith Clough  
SCHOOL NAME: Lenart Center INSPECTION DATE: 3/20/2013  
ADDRESS: 8101 S. LaSalle Street IDPH LICENSE NO: 100-02950

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 13  
MATERIAL DESCRIPTION: cardboard pipe insulation  
HISTORICAL AHERA DAMAGE CATEGORY 1  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: Chrysotile FRIABLE: Yes

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **1. Damaged or significantly damaged friable thermal system insulating ACM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: HIGH

MATERIAL LOCATION: unexcavated areas and south heat plenum

MATERIAL QUANTITY: 270

MATERIAL UNITS: LF

DAMAGE QUANTITY:

DAMAGE UNITS: LF

COMMENTS:

Inspector's Signature:



Date: 03/20/2013

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29361** BUIDLING ID: **7240**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Lenart Center** REVIEW DATE: **3/31/2013**  
ADDRESS: **8101 S. LaSalle Street** IDPH LICENSE NO: **100-02950**

---

HOMOGENEOUS AREA: **13**  
MATERIAL DESCRIPTION: **cardboard pipe insulation**  
MATERIAL LOCATION: **unexcavated areas and south heat plenum**  
MATERIAL QUANTITY: **270** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **30** DAMAGE UNITS: **LF**

---


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Unexcavated area shall be labeled as an asbestos hazard until response action can be implemented.

Management Planner's Signature: \_\_\_\_\_



Date: **03/31/2013**

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29361** BUIDLING ID: **7240**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Keith Clough**  
SCHOOL NAME: **Lenart Center** INSPECTION DATE: **3/20/2013**  
ADDRESS: **8101 S. LaSalle Street** IDPH LICENSE NO: **100-02950**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **14**  
MATERIAL DESCRIPTION: **cardboard pipe fittings**  
HISTORICAL AHERA DAMAGE CATEGORY **6**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **unexcavated areas and south heat plenum**

MATERIAL QUANTITY: **50** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: **03/20/2013**

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29361** BUIDLING ID: **7240**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Lenart Center** REVIEW DATE: **3/31/2013**  
ADDRESS: **8101 S. LaSalle Street** IDPH LICENSE NO: **100-02950**

---

HOMOGENEOUS AREA: **14**  
MATERIAL DESCRIPTION: **cardboard pipe fittings**  
MATERIAL LOCATION: **unexcavated areas and south heat plenum**  
MATERIAL QUANTITY: **50** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**


---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **03/31/2013**

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29361** BUIDLING ID: **7240**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Keith Clough**  
SCHOOL NAME: **Lenart Center** INSPECTION DATE: **3/20/2013**  
ADDRESS: **8101 S. LaSalle Street** IDPH LICENSE NO: **100-02950**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **15**  
MATERIAL DESCRIPTION: **rope pipe insulation**  
HISTORICAL AHERA DAMAGE CATEGORY **6**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **North and South Fan Rooms**

MATERIAL QUANTITY: **60**

MATERIAL UNITS: **LF**

DAMAGE QUANTITY:

DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 03/20/2013

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29361** BUIDLING ID: **7240**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Lenart Center** REVIEW DATE: **3/31/2013**  
ADDRESS: **8101 S. LaSalle Street** IDPH LICENSE NO: **100-02950**

---

HOMOGENEOUS AREA: **15**

MATERIAL DESCRIPTION: **rope pipe insulation**

MATERIAL LOCATION: **North and South Fan Rooms**

MATERIAL QUANTITY: **60**

MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **LF**


---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **03/31/2013**



# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29361** BUIDLING ID: **7240**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Keith Clough**  
SCHOOL NAME: **Lenart Center** INSPECTION DATE: **3/20/2013**  
ADDRESS: **8101 S. LaSalle Street** IDPH LICENSE NO: **100-02950**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **16**  
MATERIAL DESCRIPTION: **Tank insulation**  
HISTORICAL AHERA DAMAGE CATEGORY **6**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **upper tank rm. Boiler room**  
MATERIAL QUANTITY: **80** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 03/20/2013

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29361** BUIDLING ID: **7240**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Lenart Center** REVIEW DATE: **3/31/2013**  
ADDRESS: **8101 S. LaSalle Street** IDPH LICENSE NO: **100-02950**

---

HOMOGENEOUS AREA: **16**

MATERIAL DESCRIPTION: **Tank insulation**

MATERIAL LOCATION: **upper tank rm. Boiler room**

MATERIAL QUANTITY: **80**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**


---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **03/31/2013**

# Chicago Public Schools

## Carnow, Conibear and Associates 2013 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29361** BUIDLING ID: **7240**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Keith Clough**  
SCHOOL NAME: **Lenart Center** INSPECTION DATE: **3/20/2013**  
ADDRESS: **8101 S. LaSalle Street** IDPH LICENSE NO: **100-02950**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **17**  
MATERIAL DESCRIPTION: **Aircell pipe insulation.**  
HISTORICAL AHERA DAMAGE CATEGORY **6**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **below the upper tank.**

MATERIAL QUANTITY: **190**

MATERIAL UNITS: **LF**

DAMAGE QUANTITY:

DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: **03/20/2013**

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29361** BUIDLING ID: **7240**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Lenart Center** REVIEW DATE: **3/31/2013**  
ADDRESS: **8101 S. LaSalle Street** IDPH LICENSE NO: **100-02950**

---

HOMOGENEOUS AREA: **17**

MATERIAL DESCRIPTION: **Aircell pipe insulation.**

MATERIAL LOCATION: **below the upper tank.**

MATERIAL QUANTITY: **190**

MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **03/31/2013**

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29361** BUIDLING ID: **7240**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Keith Clough**  
SCHOOL NAME: **Lenart Center** INSPECTION DATE: **3/20/2013**  
ADDRESS: **8101 S. LaSalle Street** IDPH LICENSE NO: **100-02950**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **18**  
MATERIAL DESCRIPTION: **Plaster.**  
HISTORICAL AHERA DAMAGE CATEGORY **6**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **core walls of tunnel and throughout**  
MATERIAL QUANTITY: **80000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 03/20/2013

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29361** BUIDLING ID: **7240**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Lenart Center** REVIEW DATE: **3/31/2013**  
ADDRESS: **8101 S. LaSalle Street** IDPH LICENSE NO: **100-02950**

---

HOMOGENEOUS AREA: **18**  
MATERIAL DESCRIPTION: **Plaster.**  
MATERIAL LOCATION: **core walls of tunnel and throughout**  
MATERIAL QUANTITY: **80000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **03/31/2013**

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29361** BUIDLING ID: **7240**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Keith Clough**  
SCHOOL NAME: **Lenart Center** INSPECTION DATE: **3/20/2013**  
ADDRESS: **8101 S. LaSalle Street** IDPH LICENSE NO: **100-02950**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **19**  
MATERIAL DESCRIPTION: **Braided Pipe Wrap**  
HISTORICAL AHERA DAMAGE CATEGORY **6**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Auditorium stage stair area**  
MATERIAL QUANTITY: **10** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 03/20/2013

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29361** BUIDLING ID: **7240**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Lenart Center** REVIEW DATE: **3/31/2013**  
ADDRESS: **8101 S. LaSalle Street** IDPH LICENSE NO: **100-02950**

---

HOMOGENEOUS AREA: **19**

MATERIAL DESCRIPTION: **Braided Pipe Wrap**

MATERIAL LOCATION: **Auditorium stage stair area**

MATERIAL QUANTITY: **10**

MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **03/31/2013**



# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29361** BUIDLING ID: **7240**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Keith Clough**  
SCHOOL NAME: **Lenart Center** INSPECTION DATE: **3/20/2013**  
ADDRESS: **8101 S. LaSalle Street** IDPH LICENSE NO: **100-02950**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **20**  
MATERIAL DESCRIPTION: **Green Linoleum Flooring Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **2nd Fl. SE Corridor and elevator Lobby on 1st, 2nd, & 3rd Fl.**

MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 03/20/2013

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29361** BUIDLING ID: **7240**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Lenart Center** REVIEW DATE: **3/31/2013**  
ADDRESS: **8101 S. LaSalle Street** IDPH LICENSE NO: **100-02950**

---

HOMOGENEOUS AREA: **20**  
MATERIAL DESCRIPTION: **Green Linoleum Flooring Mastic**  
MATERIAL LOCATION: **2nd Fl. SE Corridor and elevator Lobby on 1st, 2nd, & 3rd Fl.**  
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**


---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **03/31/2013**

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29361** BUIDLING ID: **7240**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Keith Clough**  
SCHOOL NAME: **Lenart Center** INSPECTION DATE: **3/20/2013**  
ADDRESS: **8101 S. LaSalle Street** IDPH LICENSE NO: **100-02950**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **CM-1**  
MATERIAL DESCRIPTION: **carpet mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Room 110, Principals office, main office, general office, copy/store room**  
MATERIAL QUANTITY: **2750** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 03/20/2013

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29361** BUIDLING ID: **7240**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Lenart Center** REVIEW DATE: **3/31/2013**  
ADDRESS: **8101 S. LaSalle Street** IDPH LICENSE NO: **100-02950**

---

HOMOGENEOUS AREA: **CM-1**  
MATERIAL DESCRIPTION: **carpet mastic**  
MATERIAL LOCATION: **Room 110, Principals office, main office, general office, copy/store room**  
MATERIAL QUANTITY: **2750** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Operations and Maintenance

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **03/31/2013**

# Chicago Public Schools

## Carnow, Conibear and Associates 2013 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29361** BUIDLING ID: **7240**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Keith Clough**  
SCHOOL NAME: **Lenart Center** INSPECTION DATE: **3/20/2013**  
ADDRESS: **8101 S. LaSalle Street** IDPH LICENSE NO: **100-02950**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **FT-1**  
MATERIAL DESCRIPTION: **9x9 brown floor tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **engineers office, restroom and auditorium**

MATERIAL QUANTITY: **2600**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 03/20/2013

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29361** BUIDLING ID: **7240**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Lenart Center** REVIEW DATE: **3/31/2013**  
ADDRESS: **8101 S. LaSalle Street** IDPH LICENSE NO: **100-02950**

---

HOMOGENEOUS AREA: **FT-1**  
MATERIAL DESCRIPTION: **9x9 brown floor tile**  
MATERIAL LOCATION: **engineers office, restroom and auditorium**  
MATERIAL QUANTITY: **2600** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**


---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **03/31/2013**

# Chicago Public Schools

## Carnow, Conibear and Associates 2013 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29361** BUIDLING ID: **7240**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Keith Clough**  
SCHOOL NAME: **Lenart Center** INSPECTION DATE: **3/20/2013**  
ADDRESS: **8101 S. LaSalle Street** IDPH LICENSE NO: **100-02950**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **FT-2**  
MATERIAL DESCRIPTION: **cream/peach linoleum**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **lunchroom & boys lockerroom**  
MATERIAL QUANTITY: **1300** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 03/20/2013

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29361** BUIDLING ID: **7240**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Lenart Center** REVIEW DATE: **3/31/2013**  
ADDRESS: **8101 S. LaSalle Street** IDPH LICENSE NO: **100-02950**

---

HOMOGENEOUS AREA: **FT-2**  
MATERIAL DESCRIPTION: **cream/peach linoleum**  
MATERIAL LOCATION: **lunchroom & boys lockerroom**  
MATERIAL QUANTITY: **1300** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Operations and Maintenance

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **03/31/2013**



# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29361** BUIDLING ID: **7240**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Keith Clough**  
SCHOOL NAME: **Lenart Center** INSPECTION DATE: **3/20/2013**  
ADDRESS: **8101 S. LaSalle Street** IDPH LICENSE NO: **100-02950**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **FT-3**  
MATERIAL DESCRIPTION: **12x12 teal floor tile (part of checkerboard)**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1st floor corridor**  
MATERIAL QUANTITY: **1385** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 03/20/2013

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29361** BUIDLING ID: **7240**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Lenart Center** REVIEW DATE: **3/31/2013**  
ADDRESS: **8101 S. LaSalle Street** IDPH LICENSE NO: **100-02950**

---

HOMOGENEOUS AREA: **FT-3**  
MATERIAL DESCRIPTION: **12x12 teal floor tile (part of checkerboard)**  
MATERIAL LOCATION: **1st floor corridor**  
MATERIAL QUANTITY: **1385** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Operations and Maintenance

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **03/31/2013**

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29361** BUIDLING ID: **7240**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Keith Clough**  
SCHOOL NAME: **Lenart Center** INSPECTION DATE: **3/20/2013**  
ADDRESS: **8101 S. LaSalle Street** IDPH LICENSE NO: **100-02950**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **FT-4**  
MATERIAL DESCRIPTION: **12x12 caramel floor tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1st & 3rd floor corridor (1st floor part of checkerboard)**  
MATERIAL QUANTITY: **3025** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 03/20/2013

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29361** BUIDLING ID: **7240**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Lenart Center** REVIEW DATE: **3/31/2013**  
ADDRESS: **8101 S. LaSalle Street** IDPH LICENSE NO: **100-02950**

---

HOMOGENEOUS AREA: **FT-4**  
MATERIAL DESCRIPTION: **12x12 caramel floor tile**  
MATERIAL LOCATION: **1st & 3rd floor corridor (1st floor part of checkerboard)**  
MATERIAL QUANTITY: **3025** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Operations and Maintenance

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **03/31/2013**

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29361** BUIDLING ID: **7240**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Keith Clough**  
SCHOOL NAME: **Lenart Center** INSPECTION DATE: **3/20/2013**  
ADDRESS: **8101 S. LaSalle Street** IDPH LICENSE NO: **100-02950**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **FT-5**  
MATERIAL DESCRIPTION: **9x9 green floor tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **2nd floor corridor N/S (part of checkerboard)**  
MATERIAL QUANTITY: **725** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 03/20/2013

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29361** BUIDLING ID: **7240**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Lenart Center** REVIEW DATE: **3/31/2013**  
ADDRESS: **8101 S. LaSalle Street** IDPH LICENSE NO: **100-02950**

---

HOMOGENEOUS AREA: **FT-5**  
MATERIAL DESCRIPTION: **9x9 green floor tile**  
MATERIAL LOCATION: **2nd floor corridor N/S (part of checkerboard)**  
MATERIAL QUANTITY: **725** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **03/31/2013**

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29361** BUIDLING ID: **7240**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Keith Clough**  
SCHOOL NAME: **Lenart Center** INSPECTION DATE: **3/20/2013**  
ADDRESS: **8101 S. LaSalle Street** IDPH LICENSE NO: **100-02950**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **FT-6**  
MATERIAL DESCRIPTION: **9x9 tan floor tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **2nd floor corridor N/s-part of checkerboard**  
MATERIAL QUANTITY: **725** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 03/20/2013

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29361** BUIDLING ID: **7240**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Lenart Center** REVIEW DATE: **3/31/2013**  
ADDRESS: **8101 S. LaSalle Street** IDPH LICENSE NO: **100-02950**

---

HOMOGENEOUS AREA: **FT-6**  
MATERIAL DESCRIPTION: **9x9 tan floor tile**  
MATERIAL LOCATION: **2nd floor corridor N/s-part of checkerboard**  
MATERIAL QUANTITY: **725** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**


---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **03/31/2013**



# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29361** BUIDLING ID: **7240**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Keith Clough**  
SCHOOL NAME: **Lenart Center** INSPECTION DATE: **3/20/2013**  
ADDRESS: **8101 S. LaSalle Street** IDPH LICENSE NO: **100-02950**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **FT-7**  
MATERIAL DESCRIPTION: **blue linoleum**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **2nd floor computer lab and 303**  
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 03/20/2013

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29361** BUIDLING ID: **7240**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Lenart Center** REVIEW DATE: **3/31/2013**  
ADDRESS: **8101 S. LaSalle Street** IDPH LICENSE NO: **100-02950**

---

HOMOGENEOUS AREA: **FT-7**  
MATERIAL DESCRIPTION: **blue linoleum**  
MATERIAL LOCATION: **2nd floor computer lab and 303**  
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Operations and Maintenance

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **03/31/2013**

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29361** BUIDLING ID: **7240**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Keith Clough**  
SCHOOL NAME: **Lenart Center** INSPECTION DATE: **3/20/2013**  
ADDRESS: **8101 S. LaSalle Street** IDPH LICENSE NO: **100-02950**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **FT-8**  
MATERIAL DESCRIPTION: **12x12 white floor tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **2nd floor MDF room next to computer lab**  
MATERIAL QUANTITY: **250** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 03/20/2013

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29361** BUIDLING ID: **7240**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Lenart Center** REVIEW DATE: **3/31/2013**  
ADDRESS: **8101 S. LaSalle Street** IDPH LICENSE NO: **100-02950**

---

HOMOGENEOUS AREA: **FT-8**  
MATERIAL DESCRIPTION: **12x12 white floor tile**  
MATERIAL LOCATION: **2nd floor MDF room next to computer lab**  
MATERIAL QUANTITY: **250** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Operations and Maintenance

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **03/31/2013**

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29361** BUIDLING ID: **7240**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Keith Clough**  
SCHOOL NAME: **Lenart Center** INSPECTION DATE: **3/20/2013**  
ADDRESS: **8101 S. LaSalle Street** IDPH LICENSE NO: **100-02950**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **FT-9**  
MATERIAL DESCRIPTION: **brown linoleum**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **2nf floor elevator lobby**  
MATERIAL QUANTITY: **450** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 03/20/2013

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29361** BUIDLING ID: **7240**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Lenart Center** REVIEW DATE: **3/31/2013**  
ADDRESS: **8101 S. LaSalle Street** IDPH LICENSE NO: **100-02950**

---

HOMOGENEOUS AREA: **FT-9**  
MATERIAL DESCRIPTION: **brown linoleum**  
MATERIAL LOCATION: **2nf floor elevator lobby**  
MATERIAL QUANTITY: **450** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Operations and Maintenance

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **03/31/2013**

# Chicago Public Schools

## Carnow, Conibear and Associates 2013 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29361** BUIDLING ID: **7240**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Keith Clough**  
SCHOOL NAME: **Lenart Center** INSPECTION DATE: **3/20/2013**  
ADDRESS: **8101 S. LaSalle Street** IDPH LICENSE NO: **100-02950**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **FTM-1**  
MATERIAL DESCRIPTION: **9x9 Brown floor tile mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **engineers office, restroom, and ausitorium**

MATERIAL QUANTITY: **2600**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 03/20/2013

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29361** BUIDLING ID: **7240**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Lenart Center** REVIEW DATE: **3/31/2013**  
ADDRESS: **8101 S. LaSalle Street** IDPH LICENSE NO: **100-02950**

---

HOMOGENEOUS AREA: **FTM-1**  
MATERIAL DESCRIPTION: **9x9 Brown floor tile mastic**  
MATERIAL LOCATION: **engineers office, restroom, and ausitorium**  
MATERIAL QUANTITY: **2600** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Operations and Maintenance

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **03/31/2013**



# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29361** BUIDLING ID: **7240**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Keith Clough**  
SCHOOL NAME: **Lenart Center** INSPECTION DATE: **3/20/2013**  
ADDRESS: **8101 S. LaSalle Street** IDPH LICENSE NO: **100-02950**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **FTM-3**  
MATERIAL DESCRIPTION: **12x12 Teal floor tile mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1st floor corridor-part of checkerboard**  
MATERIAL QUANTITY: **1385** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 03/20/2013

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29361** BUIDLING ID: **7240**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Lenart Center** REVIEW DATE: **3/31/2013**  
ADDRESS: **8101 S. LaSalle Street** IDPH LICENSE NO: **100-02950**

---

HOMOGENEOUS AREA: **FTM-3**  
MATERIAL DESCRIPTION: **12x12 Teal floor tile mastic**  
MATERIAL LOCATION: **1st floor corridor-part of checkerboard**  
MATERIAL QUANTITY: **1385** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Operations and Maintenance

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **03/31/2013**

# Chicago Public Schools

## Carnow, Conibear and Associates 2013 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29361** BUIDLING ID: **7240**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Keith Clough**  
SCHOOL NAME: **Lenart Center** INSPECTION DATE: **3/20/2013**  
ADDRESS: **8101 S. LaSalle Street** IDPH LICENSE NO: **100-02950**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **FTM-4**  
MATERIAL DESCRIPTION: **12x12 caramel floor tile mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1st and 3rd floor corridor**  
MATERIAL QUANTITY: **3025** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 03/20/2013

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29361** BUIDLING ID: **7240**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Lenart Center** REVIEW DATE: **3/31/2013**  
ADDRESS: **8101 S. LaSalle Street** IDPH LICENSE NO: **100-02950**

---

HOMOGENEOUS AREA: **FTM-4**  
MATERIAL DESCRIPTION: **12x12 caramel floor tile mastic**  
MATERIAL LOCATION: **1st and 3rd floor corridor**  
MATERIAL QUANTITY: **3025** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**


---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **03/31/2013**

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29361** BUIDLING ID: **7240**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Keith Clough**  
SCHOOL NAME: **Lenart Center** INSPECTION DATE: **3/20/2013**  
ADDRESS: **8101 S. LaSalle Street** IDPH LICENSE NO: **100-02950**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **FTM-5**  
MATERIAL DESCRIPTION: **9x9 green floor tile mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **2nd floor corridor N/S-part of checkerboard**  
MATERIAL QUANTITY: **725** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 03/20/2013

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29361** BUIDLING ID: **7240**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Lenart Center** REVIEW DATE: **3/31/2013**  
ADDRESS: **8101 S. LaSalle Street** IDPH LICENSE NO: **100-02950**

---

HOMOGENEOUS AREA: **FTM-5**  
MATERIAL DESCRIPTION: **9x9 green floor tile mastic**  
MATERIAL LOCATION: **2nd floor corridor N/S-part of checkerboard**  
MATERIAL QUANTITY: **725** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **03/31/2013**

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29361** BUIDLING ID: **7240**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Keith Clough**  
SCHOOL NAME: **Lenart Center** INSPECTION DATE: **3/20/2013**  
ADDRESS: **8101 S. LaSalle Street** IDPH LICENSE NO: **100-02950**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **FTM-6**  
MATERIAL DESCRIPTION: **9x9 tan floor tile mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **2nd floor corridor N/S-part of checkerboard**  
MATERIAL QUANTITY: **725** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 03/20/2013

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29361** BUIDLING ID: **7240**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Lenart Center** REVIEW DATE: **3/31/2013**  
ADDRESS: **8101 S. LaSalle Street** IDPH LICENSE NO: **100-02950**

---

HOMOGENEOUS AREA: **FTM-6**  
MATERIAL DESCRIPTION: **9x9 tan floor tile mastic**  
MATERIAL LOCATION: **2nd floor corridor N/S-part of checkerboard**  
MATERIAL QUANTITY: **725** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**


---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **03/31/2013**



# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29361** BUIDLING ID: **7240**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Keith Clough**  
SCHOOL NAME: **Lenart Center** INSPECTION DATE: **3/20/2013**  
ADDRESS: **8101 S. LaSalle Street** IDPH LICENSE NO: **100-02950**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **FTM-7**  
MATERIAL DESCRIPTION: **blue linoleum mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **2nd floor computer lab and 303**

MATERIAL QUANTITY: **1500**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 03/20/2013

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29361** BUIDLING ID: **7240**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Lenart Center** REVIEW DATE: **3/31/2013**  
ADDRESS: **8101 S. LaSalle Street** IDPH LICENSE NO: **100-02950**

---

HOMOGENEOUS AREA: **FTM-7**  
MATERIAL DESCRIPTION: **blue linoleum mastic**  
MATERIAL LOCATION: **2nd floor computer lab and 303**  
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**


---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **03/31/2013**

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29361** BUIDLING ID: **7240**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Keith Clough**  
SCHOOL NAME: **Lenart Center** INSPECTION DATE: **3/20/2013**  
ADDRESS: **8101 S. LaSalle Street** IDPH LICENSE NO: **100-02950**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **FTM-8**  
MATERIAL DESCRIPTION: **12x12 white floor tile mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **2nd floor MDF room next to computer lab**  
MATERIAL QUANTITY: **250** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 03/20/2013

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29361** BUIDLING ID: **7240**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Lenart Center** REVIEW DATE: **3/31/2013**  
ADDRESS: **8101 S. LaSalle Street** IDPH LICENSE NO: **100-02950**

---

HOMOGENEOUS AREA: **FTM-8**  
MATERIAL DESCRIPTION: **12x12 white floor tile mastic**  
MATERIAL LOCATION: **2nd floor MDF room next to computer lab**  
MATERIAL QUANTITY: **250** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**


---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **03/31/2013**

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29361** BUIDLING ID: **7240**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Keith Clough**  
SCHOOL NAME: **Lenart Center** INSPECTION DATE: **3/20/2013**  
ADDRESS: **8101 S. LaSalle Street** IDPH LICENSE NO: **100-02950**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **FTM-9**  
MATERIAL DESCRIPTION: **Green linoleum mastic (not observed)**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **2nd floor elevator lobby**

MATERIAL QUANTITY: **450**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 03/20/2013

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29361** BUIDLING ID: **7240**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**  
SCHOOL NAME: **Lenart Center** REVIEW DATE: **3/31/2013**  
ADDRESS: **8101 S. LaSalle Street** IDPH LICENSE NO: **100-02950**

---

HOMOGENEOUS AREA: **FTM-9**  
MATERIAL DESCRIPTION: **Green linoleum mastic (not obseved)**  
MATERIAL LOCATION: **2nd floor elevator lobby**  
MATERIAL QUANTITY: **450** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**


---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **03/31/2013**

# **Chicago Public Schools**

**Carnow, Conibear and Associates**

***2013 AHERA REINSPECTION***

# APPENDIX B

## Inspector and Management Planner Licenses

---



# CERTIFICATE OF ACHIEVEMENT ASBESTOS ABATEMENT

Approved by the Illinois Department of Public Health and Indiana Department of Environmental Management

This is to certify that KEITH CLOUGH  
has completed the Contractor/Supervisor Recertification course and passed the examination  
on 04/30/2012 with a minimum score of 70% or better. Training was in accordance with U.S.  
E.P.A. 40 CFR 763 Subpart E, Appendix C, Asbestos Containing Materials in Schools: Model  
Accreditation Plan, TSCA II, Authorized by both AHERA & ASHARA and Indiana Rule 326 IAC  
18-2.



*Handwritten signature*

04/30/2012

Course Dates:

04/30/2013

Expires:

1204CSR19

Certificate Number:


Phone Number: (312) 491-0081

Director of Training

Nicholas J. Peneff

Director of Public Health

FORM # A-008



525-535 West Jefferson Street • Springfield, Illinois 62761-0001 • www.idph.state.il.us

Pat Quinn, Governor

4/10/2012

KEITH CLOUGH  
524 HOMELAND RD  
MATTESON, IL 60443

ASBESTOS PROFESSIONAL LICENSE ID NUMBER: 02950

Enclosed is your Asbestos Professional License that expires 05/15/2013

CERTIFICATE EXPIRATION DATE

INSPECTOR 3/21/2013

PROJECT MANAGER 4/29/2012  
AIR SAMPLING PROFESSIONAL

If you have any questions or need further assistance, contact the Asbestos Program at (217)782-3517 or fax (217)785-5897. Our WEB address is <http://www.idph.state.il.us/envhealth/ehhome.htm>



ASBESTOS PROFESSIONAL LICENSE

ID NUMBER ISSUED EXPIRES  
100 - 02950 4/10/2012 05/15/2013

KEITH CLOUGH  
524 HOMELAND RD  
MATTESON, IL 60443



Environmental Health

1003



# Occupational Training & Supply, Inc.

7233 Adams Street • Willowbrook, IL 60527 • (630) 655-3900

## Asbestos Building Inspector Refresher

*Occupational Training and Supply, Inc. certifies that*

# Daniel Juneau

**has successfully completed the 4 hour Asbestos Building Inspector Refresher Course**  
and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department  
of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance  
with EPA 10 CFR 763 Asbestos Hazard Emergency Response Act (AHERA) and TSCA Title II.

Certificate: BIR1212042319


Exam Date: 12/4/2012

Course Date: 12/4/2012

Expiration Date: 12/4/2013

Kathy DeSalvo, Director

2012



# Occupational Training & Supply, Inc.

7233 Adams Street ♦ Willowbrook, IL 60527 ♦ (630) 655-3900

## Asbestos Management Planner Refresher

*Occupational Training and Supply, Inc. certifies that*

# Daniel Juneau


**has successfully completed the 4 hour Asbestos Management Planner Refresher Course** and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 10 CFR 763 Asbestos Hazard Emergency Response Act (AHERA) and TSCA Title II.

Certificate: MPR1302250736

Exam Date: 2/25/2013


Course Date: 2/25/2013

Expiration Date: 2/25/2014



Kathy DeSalvo, Director

2013



# Occupational Training & Supply, Inc.

7233 Adams Street ♦ Willowbrook, IL 60527 ♦ (630) 655-3900

## Asbestos Management Planner Refresher

*Occupational Training and Supply, Inc. certifies that*

# Daniel Juneau


**has successfully completed the 4 hour Asbestos Management Planner Refresher Course**  
and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 10 CFR 763 Asbestos Hazard Emergency Response Act (AHERA) and TSCA Title II.

Certificate: MPR1302250736

Exam Date: 2/25/2013

Course Date: 2/25/2013

Expiration Date: 2/25/2014

  
Kathy DeSalvo, Director

2013

# Daniel Juneau

Illinois Licensed Asbestos Inspector, Management Planner,  
Project Manager, and Air Sampling Professional



## ASBESTOS PROFESSIONAL LICENSE

ID NUMBER  
**100 - 03613**

ISSUED  
**4/11/2013**

EXPIRES  
**05/15/2014**

DANIEL J JUNEAU  
1408 OAKWOOD AVENUE  
DES PLAINES, IL 60016

Environmental Health



### ENDORSEMENTS

### TC EXPIRES

INSPECTOR

12/4/2013

MANAGEMENT PLANNER

2/25/2014

PROJECT MANAGER

12/3/2013

AIR SAMPLING PROFESSIONAL

**Alteration of this license shall result in legal action**  
This license issued under authority of the State of Illinois  
Department of Public Health

This license is valid only when accompanied by a valid  
training course certificate.

**CARNOW  
CONIBEAR**

# APPENDIX C

## Laboratory Accreditations

---

# APPENDIX D

## Laboratory Results

---



# APPENDIX E

## Chain of Custody Forms

---

## Three-Year Reinspection Key to Terms

	<b>CODE</b>	<b>KEY</b>
<b>MATERIAL</b>		
	ACBM	Asbestos Containing Building Materials
<b>MATERIAL CATEGORY</b>		
	MISC	Miscellaneous
	SURF	Surfacing
	TSI	Thermal System Insulation
<b>MATERIAL UNITS</b>		
	LF	Linear Feet
	SF	Square Feet
	CF	Cubic Feet
<b>DAMAGE TYPE</b>		
	Loc	Localized
	Dist	Distributed