

**ILLINOIS DEPARTMENT OF PUBLIC HEALTH
AHERA THREE YEAR REINSPECTION
ASBESTOS ABATEMENT PROGRAM
SCHOOL INFORMATION FORM**

SECTION I

NAME OF SCHOOL DISTRICT: CHICAGO SCHOOL DIST 299
SCHOOL ID NUMBER: 14-016-2990-3725
SCHOOL NAME: Christopher School
ADDRESS OF SCHOOL: 5042 S. Artesian
CITY: Chicago, IL, 60632

DATE LAST THREE YEAR REINSPECTION WAS COMPLETED 2/9/2010

If the address on this form is different than the address of the building, submit a written explanation.

SECTION II *(Please type or print)*

PLEASE COMPLETE THE FOLLOWING FOR YOUR THREE YEAR REINSPECTION:

DATE REINSPECTION COMPLETED: 4/18/2013 ENROLLMENT 313
IDPH INSPECTOR LICENSE NUMBER: 100-11170
IDPH LICENSED INSPECTOR NAME (Please Print): Jesus Delgado
IDPH MP LICENSE NUMBER: 100-09870
IDPH LICENSED MANAGEMENT PLANNER NAME (Please Print): Todd Huffer

DESIGNATED PERSON (Please Print): Ms. Lynn Crivello PHONE: (773) 553-3113



4/18/2013

Signature of Designated Person

Date

SECTION III

PLEASE COMPLETE THE FOLLOWING INFORMATION FOR ANY CHANGES WITHIN THE SCHOOL DISTRICT.

School building has been sold. Date of Sale: _____

School has been closed. Date closed: _____

School building has been demolished. Date: _____

School building is asbestos free since last reinspection: _____

Please explain in writing why the school building is now asbestos free and include the supporting documentation.

If a new school building has been added to the district, submit either an exclusionary statement or a management plan and inspection report. Include the complete name, address and city of school building.

Explain in writing if the address of the building is different than the address on this form:

THREE-YEAR REINSPECTION

CHICAGO SCHOOL DIST 299

Christopher School

5042 S. Artesian
Chicago, IL, 60632

Unit: 30031
Building ID: 2780

IDPH ID Number: 14-016-2990-3725

REPORT DATE:

Thursday, April 18, 2013

Prepared for:

Chicago Public Schools
125 S. Clark Street
Chicago, IL 60603

Prepared by:

Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone (312) 762-2900

Fax (312) 782-5145

**DO NOT REMOVE FROM SCHOOL
REQUIRED BY FEDERAL LAW**

March 18, 2013

Mr. R. Kent Cook
Asbestos Program
Illinois Department of Public Health
525 West Jefferson Street
Springfield, Illinois 62761

Re: Chicago Public Schools - 2013 Three-Year Reinspections

Dear Mr. Cook:

Carnow, Conibear and Associates, Managing Environmental Consultant (MEC), conducted the Three-Year Reinspections and performed management plan updates for the Chicago Public Schools (CPS) facilities in Region 3,4,5 Elementary Schools. Please update your records with the following information.

School District: 299 Unit: 30031 Region: 04 IDPH ID: 14-016-2990-3725

School: Christopher School Building ID: 2780

Address: 5042 S. Artesian
Chicago, IL, 60632

Building Contact: Reynolds, Edward Contact Phone: 773-501-5324

Current Building Owners: Chicago Public Schools

Review Date: 4/18/2013

Inspector: Jesus Delgado Inspector IDPH License: 100-11170
Management Planner: Todd Huffer Management Planner IDPH License: 100-09870

If you have any questions or comments, please contact us at (312) 762-2900

Sincerely,
Carnow, Conibear and Associates



Todd Huffer
100-09870

Environmental Notification to Occupants

To: Faculty, Staff and Parents
From: Chicago Public Schools
Date: March 18, 2013

RE: Christopher School, Unit 30031
5042 S. Artesian
Chicago, IL, 60632

Dear Faculty, Staff and Parents,

This letter is to notify you that the 2013 asbestos three year re-inspection has been completed at Christopher School , following the Federal Asbestos Hazard Emergency Response Act (AHERA), 40 CFR Part 763, Subpart E and is available for your review at the main office of the school.

Although asbestos-containing materials have been identified at Christopher School, there is no reason to believe that any threat to the health of students or staff exists at this time. CPS will continue to carefully monitor the condition of asbestos-containing materials and if conditions warrant, all appropriate steps will be taken to maintain the health and safety of all building occupants.

If you have any questions regarding this matter or require additional information, please feel free to contact Ms. Lynn Crivello, the designated Local Education Authority's Designated Person at (773) 553-3113 .

Table of Contents

- I. School and Inspection Information
- II. Executive Summary
- III. Methodology
- IV. Abatement History
- V. Reassessments and Recommendations
- VI. Conclusions

Table I: Inspector's Reinspection Findings

Table II: Management Planner's Review

APPENDICES:

- Appendix A: Assessment Sheets, Drawings and Photos
- Appendix B: Inspector and Management Planner Licenses
- Appendix C: Laboratory Accreditations
- Appendix D: Laboratory Results
- Appendix E: Chain of Custody Forms

SCHOOL AND INSPECTION INFORMATION

1. School Information

School: Christopher School Unit: 30031 Region: 04
Address: 5042 S. Artesian Chicago, IL, 60632
IDPH ID: 14-016-2990-3725 Building ID: 2780
Contact: Reynolds, Edward Phone: 773-501-5324

2. Description of Facility

Original Construction: Additional Construction:
Total Square Footage: 54500 No of Floors:
Current Occupancy: 313

3. LEA Designated Person


Contact: Ms. Lynn Crivello Phone: (773) 553-3113
Address: 125 South Clark Street, 17th Floor
Chicago, IL 60603

4. Managing Environmental Consultant

MEC: Carnow, Conibear and Associates
Contact: Dan Juneau
Address 600 West Van Buren St., Ste 500
Phone: (312) 762-2900 Fax: (312) 782-5145

5. Inspector

Inspector Name: Jesus Delgado



Signature:
Date: 3/18/2013

Inspector IDPH license # 100-11170

6. Management Planner

Management Planner Name: Todd Huffer



Signature:
Date: 4/18/2013

Management Planner IDPH license # 100-09870

7. Review Date: 4/18/2013

8. LEA Designated Person's Acknowledgement

The reinspection report and recommendations have been received by me and appropriate action will be taken by the School District.



Signature:

Date: 4/18/2013

Name: Ms. Lynn Crivello

II. EXECUTIVE SUMMARY

Carnow, Conibear and Associates was retained by the Chicago Public Schools (CPS) to perform a three-year asbestos reinspection of the Christopher School. This inspection was conducted in accordance with the United States Environmental Protection Agency (USEPA) Asbestos Hazard Emergency Response Act (AHERA) part 763.92 (b), and the ongoing Operations and Maintenance Program (O&M) originally designed in the School's Asbestos Management Plan. The purpose of this three-year reinspection is to record any condition changes in the asbestos-containing building material (ACBM) in the school since the previous three-year reinspection and the six-month periodic surveillance, to identify, assess, and include any Homogeneous Areas (HA) not identified in the Management Plan, and to recommend an appropriate response action to manage asbestos.

The inspector conducted a three-year reinspection of this facility under Illinois Department of Public Health (IDPH) school reinspection requirements and AHERA, sections 763.85 and 763.88. The main building and each addition to the main building, if constructed at different dates, were inspected separately. Laboratory accreditations are included in Appendix C, laboratory results are included in Appendix D, and chain of custody forms are included in Appendix E.

Note: During previous inspections, some of the HA(s) were identified together as 9" x 9" floor tile (FT), mastics assoc. with 9" x 9" FT, 12" x 12" FT, mastics assoc. with 12" x 12" FT, pipe insulation, etc. Some of these HA(s) have been re-identified by areas that are uniform in color, texture, construction date, application date, and general appearance.

The inspector has determined the following:

A. The following HAs have changed assessment categories for Building 2780:

003	Plaster
004	2' x 2' Ceiling Panels - ABATED
007 A	12" x 12" Lt Brown FT w/Gray, Blue, & Rust Strks
007 B	12" x 12" Beige Floor Tile w/White & Brown Streaks
007 E	12" x 12" Black Floor Tile w/White Specks
007 F	12" x 12" White Floor Tile
009	12" x 12" Ceiling Tiles
01	Hard Coat Plaster
044	Cinder Block - New Construction

045	Cinder Block Mortar - New Construction
046	Rubber Flooring
047	4" Black Baseboard
048	4" Black Baseboard Mastic
049	6" Black Baseboard
050	6" Black Baseboard Mastic
053	Finished (Glazed) Brick Mortar
055	Non-skid Strips

B. The following new homogenous areas have been identified for Building 2780:

108	12"X12" Blue W/Gray White Streaks VFT
109	12"X12" Blue W/Gray & White Streaks VFT Mastic

C. This reinspection covered only physically accessible and visible areas and materials that were identified in the LEA's management plan. The following materials were concealed and/or contained in areas that were inaccessible for sampling and have been classified as Assumed:

002	Burlap
003	Plaster
004	2' x 2' Ceiling Panels - ABATED
007 A	12" x 12" Lt Brown FT w/Gray, Blue, & Rust Strks
007 B	12" x 12" Beige Floor Tile w/White & Brown Streaks
007 C	12" x 12" Black Floor Tile
007 D	12" x 12" Black Floor Tile w/White Streaks
007 E	12" x 12" Black Floor Tile w/White Specks
007 F	12" x 12" White Floor Tile
007 G	12" x 12" Dk Gray Floor Tile w/Brn & White Streaks
007 H	12" x 12" Light Gray Floor Tile w/White Streaks
007 J	12" x 12" Cream Floor Tile w/ Brown & Gray Streaks
007 K	12"x12" Dk Gray Floor Tile w/Black & Gray Streaks
009	12" x 12" Ceiling Tiles
01	Hard Coat Plaster
028	9" x 9" Gray Floor Tile w/Brn & Wh Streaks Mastic
040	12" x 12" Cream Floor Tile w/Brown & Gray Mastic
044	Cinder Block - New Construction
045	Cinder Block Mortar - New Construction
046	Rubber Flooring
047	4" Black Baseboard
048	4" Black Baseboard Mastic
049	6" Black Baseboard
050	6" Black Baseboard Mastic
053	Finished (Glazed) Brick Mortar
054	Terrazzo Wall Panels
055	Non-skid Strips
066	12" x 12" Dk Gray FT w/Black & Gray Streaks Mastic
067	Non - Skid Strips
068	Ceramic Tile Grout
069	Grout Between Floor & Wall
07 I	12" x 12" Off-White Floor Tile w/Brown Speckles
070	Ceramic Tile Grout in Pool
071	Gray Baseboard
072	Gray Baseboard Mastic
073	Ceiling Panel Material
074	Insulation Above Ceiling Panels
078	Terrazzo Sink
079	2' x 2' Ceiling Panels
080	Insulation in Safe Door
083	12" x 12" Multi-Brown Streaked Floor Tile
084	12" x 12" Multi-Brown Streaked Floor Tile Mastic

085	Dark Gray Linoleum
086	Dark Gray Linoleum Mastic
087	2' x 4' Lay-In Ceiling Panels
088	Dark Gray Baseboard
089	Dark Gray Baseboard Mastic
090	Drywall
091	White and Light Blue Linoleum
092	White and Light Blue Linoleum Mastic
093	Boiler Gaskets
094	Insulation Under Steel Shell of Incinerator
095	12" x 12" White w/Gray Specks Floor Tile
096	12" x 12" White w/Gray Specks Floor Tile Mastic
097	4" Beige Baseboard
098	4" Beige Baseboard Adhesive
099	2' x 2' White Fissured Ceiling Tile
100	12"x12" Gray and Cream Speckled Floor Tile
101	12"x12" Gray and Cream Speckled Floor Tile-Mastic
102	12"x12" Brown Floor Tile
103	12"x12" Brown Floor Tile Mastic
104	12x12 Light BrownFT with Dark Brown & White
105	Mastic associated with 12x12Light Brown FT with Dark Brown & White
106	Cream with Light Brown Linoleum
107	Adhesive associated with Cream with Light Brown Linoleum
108	12"X12" Blue W/Gray White Streaks VFT
109	12"X12" Blue W/Gray & White Streaks VFT Mastic
90A	Drywall Tape
90B	Drywall Compound

The following areas were deemed to be inaccessible:

018	9" x 9" Red w/White Streaks Floor Tile Mastic
019	9"x9" Lt Brn w/Blue, Red, Yel, & Wh Dots FT Mastic
020	9" x 9" Light Brown w/Brn & Wh Streaks FT Mastic
021	9" x 9" Light Brown Speckled Floor Tile Mastic
022	9" x 9" Medium Brown Speckled Floor Tile Mastic
023	9" x 9" Dark Brown Speckled Floor Tile Mastic
024	9" x 9" Lt Brn w/Dk Brown & White Spots FT Mastic
026	9" x 9" Rusty Brown Speckled Floor Tile Mastic
029	9"x9" Lt. Brn FT w/Dark Brown & White Spots Mastic
030	12"x12" Lt Brn FT w/ Gry, Blu, & Rust Strks Mastic
032	12" x 12" Black Floor Tile Mastic
034	12" x 12" Black Floor Tile w/White Specks Mastic
039	12"x12"Cream Floor Tile w/(Lt) Brown & Gray Mastic

040	12" x 12" Cream Floor Tile w/Brown & Gray Mastic
048	4" Black Baseboard Mastic
050	6" Black Baseboard Mastic
066	12" x 12" Dk Gray FT w/Black & Gray Streaks Mastic
072	Gray Baseboard Mastic
074	Insulation Above Ceiling Panels
076	Linoleum Like Material Mastic
079	2' x 2' Ceiling Panels
080	Insulation in Safe Door
084	12" x 12" Multi-Brown Streaked Floor Tile Mastic
086	Dark Gray Linoleum Mastic
088	Dark Gray Baseboard
089	Dark Gray Baseboard Mastic
093	Boiler Gaskets
094	Insulation Under Steel Shell of Incinerator
100	12"x12" Gray and Cream Speckled Floor Tile
101	12"x12" Gray and Cream Speckled Floor Tile- Mastic
103	12"x12" Brown Floor Tile Mastic
105	Mastic associated with 12x12Light Brown FT with Dark Brown & White
107	Adhesive associated with Cream with Light Brown Linoleum
109	12"X12" Blue W/Gray & White Streaks VFT Mastic

Materials were also listed as "assumed" if they were in good condition and sampling was not conducted to avoid damage.

This reinspection was conducted by Jesus Delgado, IDPH License # 100-11170. The Management Plan was updated by Todd Huffer, IDPH License # 100-09870. Inspector and Management Planner Licenses are included in Appendix B.

III. METHODOLOGY

Tasks performed on-site included the following:

1. Review current management plan, identify HA(s) and extract appropriate information.
2. Examine and verify abatement records.
3. Touch and visually and physically reinspect and reassess the condition of all friable known or assumed ACBM.
4. Touch and visually and physically reinspect all non-friable known or assumed ACBM to determine whether these materials have become friable since the last inspection or periodic surveillance.
5. Identify any condition changes that may affect Hazard Ranking of known ACBM or Assumed ACBM, as well as any HA(s) that have become friable since the last reinspection.
6. Collect bulk samples from each newly discovered friable HA or previously assumed and submit for laboratory analysis.
7. Tabulate reinspection findings and submit for management planner review and recommendations with appropriate response actions based on the AHERA Damage Category of the ACBM.
8. Submit reinspection findings and management planner recommendations to the LEA within thirty (30) days for inclusion into the management plan.

IV. ABATEMENT HISTORY

The information collected from the existing management plan and inspection report(s) and from interviews with the school official revealed that the following asbestos abatement was conducted at the school since the previous Three year Reinspection.

Abatement Dates:

V. REASSESSMENTS AND RECOMMENDATIONS

The reassessments and recommendations are summarized in Tables I and II on the following pages. Detailed Hazard Assessment Sheets and Drawings and Photos (if applicable) are included in Appendix A.

VI. CONCLUSIONS

The Christopher School Building 2780 Three-Year reinspection has been completed and response actions have been recommended for both friable and non-friable materials. A timely execution of the response actions recommended will enable the LEA and the Designated Person(s) to effectively manage the existing ACBM.

This three-year reinspection report should be inspected in the current Management plan at the CPS Central Office, and one (1) copy should be kept at the school for use when planning any renovation and/or demolition activities in areas where ACBM has been identified. Also, periodic surveillance documentation and any summary reports from any response actions that are executed at the school should be used to update the Management Plan.

Table I
Inspector's Reinspection Findings

Chicago Public Schools

School Christopher School Unit 30031 Building ID 2780

Address 5042 S. Artesian Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
001	2' x 4' Ceiling Panels			Throughout Facility	NO_ACBM	MISC								
002	Burlap	50,000	SF	On Walls Throughout Facility	ASSUMED	MISC	N	DIST	20		No	ACBM with the potential for damage		LOW
003	Plaster	100,000	SF	Throughout Original Construction	ASSUMED	SURFACE	N	LOC	30		Yes	ACBM with the potential for damage		LOW
004	2' x 2' Ceiling Panels - ABATED	3,550	SF	Gym	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
005	2' x 4' Ceiling Panels			Throughout Facility	NO_ACBM	MISC								
006 A	9"x9" Dark Brown Floor Tile w/ Red & White Streaks	2,500	SF	Computer Room, Science Lab (125-A), Office, 104, 133, 135, Principal's Office	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
006 B	9"x9" Light Brown Floor Tile w/ Dark Brown Streaks	700	SF	Science Lab and Office	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
006 C	9" x 9" Black Floor Tile w/ White Streaks	200	SF	Science Lab, Hall, Speech, Cafeteria, Rooms 104, 106, 116, 117, 126	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
006 D	9" x 9" Light Brown Floor Tile w/White Streaks	1,000	SF	Hallways on 1st Floor	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
006 E	9" x 9" Green Floor Tile w/ White Streaks	1,000	SF	Hallways	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
006 F	9" x 9" Gray FT w/Red, Yellow, Blue, & White Dots	1,400	SF	Rooms 116, 117, 125 and 127	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
006 G	9" x 9" Red Floor Tile w/White Streaks	1,000	SF	Hallways on 1st Floor and Rooms 104, 129	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
006 H	9"x9 Light Brown FT w/ Blue, Red, Yel & White Dots	1,400	SF	Room 123	CHR	MISC	N	None						
006 I	9" x 9" Light Brn w/Brn & White Streaks Floor Tile	20	SF	Rooms 122, 123, 126 and as Patches in the Cafeteria	CHR	MISC	N	NONE	0			ACBM with the potential for damage		LOW
006 K	9" x 9" Medium Brown Speckled Floor Tile	1,500	SF	Computer Room, Speech, Cafeteria, 103-110, 124, 126-128, 129, Office, Teachers Lounge	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
006 L	9" x 9" Dark Brown Speckled Floor Tile	800	SF	Computer Room, Speech, Cafeteria, 103-110, 124, 126-128, 129, Office, Teachers Lounge	CHR	MISC	N	None	0		No	ACBM with the potential for damage		LOW
006 M	9" x 9" Light Brown FT w/ Dark Brown &	700	SF	Women's Teacher's	CHR	MISC	N	NONE	0		No	ACBM with the		LOW

Chicago Public Schools

School Christopher School Unit 30031 Building ID 2780

Address 5042 S. Artesian Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
	White Spots			Lounge, Rooms 101, 113, 115, 122, 123, and 126								potential for damage		
006 N	9" x 9" Beige Floor Tile w/Brown & White Streaks	1,100	SF	Cafeteria, Hall between Mobile Units, 103, Physical Therapy, Office, 122, 123, 126, 133, 135	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
006 O	9" x 9" Rusty Brown Speckled Floor Tile	50	SF	Cafeteria, Rooms 103, 104, 124, and 126, Computer Lab	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
006 P	9" x 9" White Floor Tile w/ Black Streaks	800	SF	Kitchen	CHR	MISC	N	None	0					
006 Q	9" x 9" Gray Floor Tile w/White & Brown Streaks	200	SF	Room 130	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
006 R	9" x 9" Lt Brn Floor Tile w/Dk Brown & White Spots	100	SF	Room 113	CHR	MISC	N	None						High
006 S	9" x 9" Multi-Brown Specked Floor Tile	700	SF	Room 111	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
007 A	12" x 12" Lt Brown FT w/Gray, Blue, & Rust Strks	75	SF	Custodians Lounge	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
007 B	12" x 12" Beige Floor Tile w/White & Brown Streaks	750	SF	Assembly Hall	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
007 C	12" x 12" Black Floor Tile			Room 123	ASSUMED	MISC								
007 D	12" x 12" Black Floor Tile w/White Streaks			Speech, Entrance by 127, Room 126	ASSUMED	MISC								
007 E	12" x 12" Black Floor Tile w/White Specks	350	SF	Speech, Cafeteria, Assembly Hall	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
007 F	12" x 12" White Floor Tile	100	SF	Teachers Lounge, Speech	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
007 G	12" x 12" Dk Gray Floor Tile w/Brn & White Streaks	25	SF	Cafeteria	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
007 H	12" x 12" Light Gray Floor Tile w/White Streaks	100	SF	Cafeteria	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
007 J	12" x 12" Cream Floor Tile w/ Brown & Gray Streaks	300	SF	Boy's and Girl's Locker Room, Pool Office	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
007 K	12"x12" Dk Gray Floor Tile w/Black & Gray Streaks	900	SF	Room 130	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
008 A	Linoleum (Lt Green Patterned)	0	SF	Room 129 - NOT OBSERVED	CHR	MISC	N							
008 B	Linoleum (Lt Brown Patterned)	100	SF	Women's Washroom	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		HIGH
008 C	Beige Patterned Linoleum	100	SF	Physical Therapy	CHR	MISC	N	NONE	0		No	ACBM with the		HIGH

Chicago Public Schools

School Christopher School Unit 30031 Building ID 2780

Address 5042 S. Artesian Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				Room								potential for damage		
008 D	Linoleum (Yellow Patterned)	100	SF	Washroom Across From Office	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		HIGH
009	12" x 12" Ceiling Tiles	80	SF	Assembly Hall on Walls	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
01	Hard Coat Plaster	100,000	SF	Throughout	ASSUMED	SURFACE	N	NONE	0		Yes	ACBM with the potential for damage		LOW
010	Block			Boiler Room	NO_ACBM	MISC								
011	Block Mortar	250	SF	Boiler Room	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
012	9"x9" Dark Brown FT w/ Red & White Streaks Mastic	2,500	SF	Computer Room, Science Room (125-A), Office, Principal's Office, Rooms 133, 135	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
013	9" x 9" Light Brown FT w/Dk Brown Streaks Mastic	1,000	SF	Science Lab and Office	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
014	9" x 9" Black Floor Tile w/White Streaks Mastic	1,000	SF	Rooms 104, 106, 116, 117, 125-A, Hall, Speech and as Patches in the Cafeteria, Science Lab	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
015	9" x 9" Lt Brown FT w/White Streaks Mastic	1,000	SF	Hallways on 1st Floor	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
016	9" x 9" Green FT w/White Streaks Mastic	1,000	SF	Hallways on 1st Floor	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
017	9"x9" Gray w/Red, Yel, Blue & White Dots FT Mastic	1,400	SF	Rooms 116, 117 and 125/127	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
018	9" x 9" Red w/White Streaks Floor Tile Mastic	1,000	SF	Rooms 104 and 129 and Hallways on 1st Floor	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
019	9"x9" Lt Brn w/Blue, Red, Yel, & Wh Dots FT Mastic	1,400	SF	Room123	CHR	MISC	N	None						Low
020	9" x 9" Light Brown w/Brn & Wh Streaks FT Mastic	20	SF	Rooms 122, 123, 126 and as Patches in the Cafeteria	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
021	9" x 9" Light Brown Speckled Floor Tile Mastic	700	SF	Computer Room, Speech, Cafeteria, 103-110, 124, 126-128, 129, Office, Teachers Lounge	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
022	9" x 9" Medium Brown Speckled Floor Tile Mastic	1,500	SF	103-109, 124, 126, 127, 129,	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW

Chicago Public Schools

School Christopher School Unit 30031 Building ID 2780

Address 5042 S. Artesian Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				Technology, Speech, Office, T. Lounge, Social Worker, Physical Therapy										
023	9" x 9" Dark Brown Speckled Floor Tile Mastic	800	SF	103-109, 124, 126, 127, 129, Technology, Speech, Office, T. Lounge, Social Worker, Physical Therapy	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
024	9" x 9" Lt Brn w/Dk Brown & White Spots FT Mastic	700	SF	Rooms 113, 115, 122, 123, 126 and Women's Teacher's Lounge	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
025	9" x 9" Beige w/Brown & White Streaks FT Mastic	800	SF	Rooms 103, 122, and 126, 133, 135 Office, Physical Therapy, Cafeteria, and Hallways	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
026	9" x 9" Rusty Brown Speckled Floor Tile Mastic	150	SF	Rooms 103, 104, 124, and 126, Technology Room and the Cafeteria	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
027	9" x 9" White w/Black Streaks Floor Tile Mastic	800	SF	Kitchen	CHR	MISC	N	None						Low
028	9" x 9" Gray Floor Tile w/Brn & Wh Streaks Mastic			Room 128-(Number Has Been Changed From 130)	ASSUMED	MISC								
029	9"x9" Lt. Brn FT w/Dark Brown & White Spots Mastic	700	SF	Room 113	CHR	MISC	N	None						Low
030	12"x12" Lt Brn FT w/ Gry, Blu, & Rust Strks Mastic	200	SF	Custodian's Lounge	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
031	12" x 12" Beige FT w/ Wh & Brown Streaks Mastic	1,600	SF	Assembly Hall	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
032	12" x 12" Black Floor Tile Mastic	600	SF	Room 123	CHR	MISC	N	None						Low
033	12" x 12" Black Floor Tile w/ White Streaks Mastic	200	SF	Speech, Entrance by 127, Room 126	CHR	MISC	N	None						Low
034	12" x 12" Black Floor Tile w/White Specks Mastic	350	SF	Speech, Cafeteria, Assembly Hall	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
035	12" x 12" White Floor Tile Mastic	100	SF	Speech, Teacher's Lounge	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
036	12"x12" Dark Gray FT w/Brown & White Strks Mastic	25	SF	Cafeteria	CHR	MISC	N	None						Low
037	12" x 12" Light Gray FT w/White Streaks	100	SF	Cafeteria	CHR	MISC	N	None						Low

Chicago Public Schools

School Christopher School Unit 30031 Building ID 2780

Address 5042 S. Artesian Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				- Original Construction										
057	Exterior Brick Mortar - Not AHERA			Exterior of Building - Original Construction	NO_ACBM	MISC								
058	Exterior Door Caulk - Not AHERA)			Exterior of All Doors in Original Construction	CHR						No			
059	Cinder Block in Original Construction			Throughout Basement	NO_ACBM	MISC								
060	Cinderblock Mortar - Original Construction			Throughout Basement	NO_ACBM	MISC								
061	2' x 4' Ceiling Panels			Throughout Building	NO_ACBM	MISC								
062	Exterior Window Caulk - Not AHERA			Exterior of Building - Original Building	CHR	MISC					No			
063	Exterior Brick - Not AHERA			Exterior of New Addition	NO_ACBM	MISC					No			
064	Exterior Brick Mortar - Not AHERA			Exterior of New Addition	NO_ACBM	MISC					No			
065	Exterior Door Caulk - Not AHERA			Exterior of New Addition	CHR	MISC					No			
066	12" x 12" Dk Gray FT w/Black & Gray Streaks Mastic	900	SF	Room 130	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
067	Non - Skid Strips	100	SF	Boy's and Girl's Locker Room, Pool Office	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
068	Ceramic Tile Grout	800	SF	Pool Deck	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
069	Grout Between Floor & Wall	400	SF	Pool Deck	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
071	12" x 12" Off-White Floor Tile w/Brown Speckles	500	SF	Cafeteria, Boys Washroom, Room 108	ASSUMED	MISC	N	None						Low
070	Ceramic Tile Grout in Pool	1,000	SF	Pool	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
071	Gray Baseboard	100	LF	Room 130	ASSUMED	MISC	N	None						Low
072	Gray Baseboard Mastic	100	LF	Room 130	ASSUMED	MISC	N	None						Low
073	Ceiling Panel Material	900	SF	Room 130	ASSUMED	MISC	N	None						Low
074	Insulation Above Ceiling Panels	900	SF	Room 130	ASSUMED	MISC	N	None						Low
075	Linoleum Like Flooring Material	10	SF	Storage	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
076	Linoleum Like Material Mastic	10	SF	Storage	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW

Chicago Public Schools

School Christopher School Unit 30031 Building ID 2780

Address 5042 S. Artesian Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
077	Vibration Absorbers	20	LF	Attic	NO_ACBM	MISC	N	None						Moderate
078	Terrazzo Sink	40	SF	Boy's Washroom	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
079	2' x 2' Ceiling Panels	3,600	SF	Gym	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
080	Insulation in Safe Door	32	SF	Hallway Across From Assembly Hall	ASSUMED	TSI	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
081	9" x 9" Multi-Brown Specked Floor Tile	700	SF	Room 111	CHR	MISC	N	None						High
082	9" x 9" Multi-Brown Specked Floor Tile Mastic	700	SF	Room 111	CHR	MISC	N	None						Low
083	12" x 12" Multi-Brown Streaked Floor Tile	500	SF	Room 132	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		HIGH
084	12" x 12" Multi-Brown Streaked Floor Tile Mastic	500	SF	Room 132	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
085	Dark Gray Linoleum	400	SF	Outside Hall by Rooms 401, 403, 405, 407	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		HIGH
086	Dark Gray Linoleum Mastic	400	SF	Hall outside Rooms 401, 403, 405, 407	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
087	2' x 4' Lay-In Ceiling Panels	1,000	SF	Room 180/181 and as Patch in Exit by Gym	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
088	Dark Gray Baseboard	250	SF	Room 401, 403, 405, 407 and Hall	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
089	Dark Gray Baseboard Mastic	250	SF	Room 401, 403, 405, 407, Hall	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
090	Drywall	2,600	SF	New Building 401, 403, 405, 407 and Hall, Unisex Washroom	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
091	White and Light Blue Linoleum	1,600	SF	Rooms 401, 403, 405, 407	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		HIGH
092	White and Light Blue Linoleum Mastic	1,600	SF	Rooms 401, 403, 405, 407	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
093	Boiler Gaskets	50	LF	Boiler Room	ASSUMED	TSI	N	NONE	0		No	ACBM with the potential for damage		LOW
094	Insulation Under Steel Shell of Incinerator	100	SF	Boiler Room	ASSUMED	TSI	N	NONE	0		No	ACBM with the potential for damage		LOW
095	12" x 12" White w/Gray Specks Floor Tile	3,900	SF	New Annex - Rooms 302 - 309, Changing Room and Laundry Room, Halls on 1st Floor	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		HIGH

Chicago Public Schools

School Christopher School Unit 30031 Building ID 2780

Address 5042 S. Artesian Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
096	12" x 12" White w/Gray Specks Floor Tile Mastic	3,900	SF	New Annex - Rooms 302 - 309, Changing Room and Laundry Room, and Halls on 1st Floor	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
097	4" Beige Baseboard	800	LF	New Annex - All Rooms except Washroom	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
098	4" Beige Baseboard Adhesive	800	LF	New Annex - All Rooms except Washroom	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
099	2' x 2' White Fissured Ceiling Tile	4,000	SF	New Annex - All Rooms, 1st Floor Hall	ASSUMED	MISC	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		MODERATE
100	12"x12" Gray and Cream Speckled Floor Tile	3,600	SF	Auditorium	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		HIGH
101	12"x12" Gray and Cream Speckled Floor Tile-Mastic	3,600	SF	Auditorium	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
102	12"x12" Brown Floor Tile	120	SF	Auditorium, Stairs, Landing	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		HIGH
103	12"x12" Brown Floor Tile Mastic	300	SF	Auditorium, Stairs, Landing, Engineer	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
104	12x12 Light Brown FT with Dark Brown & White	3,000	SF	Rooms 111, 103, 132, 135, 136, 113	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		HIGH
105	Mastic associated with 12x12 Light Brown FT with Dark Brown & White	3,000	SF	Rooms 111, 103, 132, 135, 136, 113	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
106	Cream with Light Brown Linoleum	750	SF	Washrooms across from 129/131	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		HIGH
107	Adhesive associated with Cream with Light Brown Linoleum	750	SF	Washrooms across from room 129/131	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
108	12"X12" Blue W/Gray White Streaks VFT	11,000	SF	Room 113,116,117/119,121/123,143,101,105,107,109,125,127,128,137,141, cafeteria lounge	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
109	12"X12" Blue W/Gray & White Streaks VFT Mastic	11,000	SF	Room 113,116,117/119,121/123,143,101,105,107,109,125,127,128,137,141, cafeteria lounge	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
90A	Drywall Tape	250	SF	Addition for 401, 403, 405, 407	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE

Chicago Public Schools

School Christopher School Unit 30031 Building ID 2780

Address 5042 S. Artesian Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
90B	Drywall Compound	250	LF	Addition for 401, 403, 405, 407	ASSUMED	MISC	Y	NONE	0		No	Any remaining friable ACM or friable suspect ACM		MODERATE
B	Aircell Pipe Insulation	1,500	LF	Tunnel, Basement, Crawl Spaces	CHR	TSI	Y	LOC	100		No	Damaged or significantly damaged friable thermal system insulating ACM	5	LOW
C	Aircell Pipe Insulation Joints	50	LF	Basement, Tunnel, Crawl Spaces	CHR	TSI	Y	NONE	0		No	ACBM with the potential for damage		MODERATE
D	Cardboard Pipe Insulation	35	LF	Tunnel / Kitchen Storage Room	CHR	TSI	N	NONE	0		No	ACBM with the potential for damage		MODERATE
E	Cardboard Pipe Insulation Joints	4	LF	Tunnel/Kitchen Storage	NO_ACBM	MISC					No			
F	Pipe Joint Insulation off Fiberglass	10	LF	Tunnel, Kitchen Storage Room	CHR	TSI	N	NONE	0		No	ACBM with the potential for damage		MODERATE
G	Boiler Insulation - ABATED				ABATED	TSI					No			
H	Tank Insulation - ABATED				ABATED	TSI					No			
I	Aircell Pipe Wrap (Jacketing)	1,500	LF	Tunnel, Basement, Crawl Spaces, Maintenance Areas	CHR	TSI	N	LOC	100		No	Damaged or significantly damaged friable thermal system insulating ACM		MODERATE
J	Fiberglass Pipe Insulation			Tunnel	NO_ACBM	TSI					No			

Chicago Public Schools

School Christopher School Unit 30031 Building ID 2780

Address 5042 S. Artesian Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

Reinspection Date 3/18/2013
Inspector Name Jesus Delgado
100-11170 5/15/2013
Inspector's IDPH License Number / Expiration Date

Inspector's Comments

HA Number:	Inspector Comments:
001	
002	
003	
004	
005	
006 A	Not observed in 125, computer room
006 B	
006 C	Not observed in cafeteria, 116, 117, 126
006 D	
006 E	
006 F	Not observed in 116, 117, 126, 125/127
006 G	
006 H	Material was not observed - 2013 3 years re-inspection
006 I	Not observed in cafeteria, 122, 123, 126
006 K	Not observed in 127, 128, 103, computer room, 110, 124, 126, cafeteria
006 L	Not observed in 127, 128, 103, computer room, 110, 124, 126, cafeteria
006 M	Not observed in 113, 115, 122, 123, 126
006 N	Not observed in cafeteria, mobile unit, 103
006 O	Not observed in 103, 126, 126, 124, computer room
006 P	Material was not observed - 2013 3 years re-inspection
006 Q	
006 R	Material was not observed - 2013 3 years re-inspection
006 S	
007 A	

Chicago Public Schools

School Christopher School Unit 30031 Building ID 2780

Address 5042 S. Artesian Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
007 B	
007 C	Material was not observed - 2013 3 years re-inspection
007 D	Material was not observed - 2013 3 years re-inspection
007 E	Not observed in caferia
007 F	Not observed in teacher lounge
007 G	Not observed in caferia
007 H	
007 J	
007 K	
008 A	Material was not observed - 2013 3 years re-inspection
008 B	
008 C	
008 D	
009	
01	
010	
011	
012	Not observed in 124A and computer room
013	
014	Not observed in 124A and caferia
015	
016	
017	Not observed in 124/127
018	
019	Material was not observed - 2013 3 years re-inspection
020	Not observed in caferia
021	Not observed in 127, 128, 103, computer room, 110, 124, 126, caferia
022	Not observed in teach, 103, 105, 109
023	not observed in 127, teacher lounge, 103, 105, 109, Tech.

Chicago Public Schools

School Christopher School Unit 30031 Building ID 2780

Address 5042 S. Artesian Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
024	Not observed in 113, 115, 122, 123, 126
025	Not observed in cafeteria, 103.
026	Not observed in cafeteria, tech room, 103
027	Material was not observed - 2013 3 years re-inspection
028	Material was not observed - 2013 3 years re-inspection
029	Material was not observed - 2013 3 years re-inspection
030	
031	
032	Material was not observed - 2013 3 years re-inspection
033	Material was not observed - 2013 3 years re-inspection
034	Not observed in cafeteria
035	Not observed in teacher lounge
036	Material was not observed - 2013 3 years re-inspection
037	Material was not observed - 2013 3 years re-inspection
038	Material was not observed - 2013 3 years re-inspection
039	
040	
041	
042	
043	
044	
045	
046	
047	
048	
049	
050	
051	
052	

Chicago Public Schools

School Christopher School Unit 30031 Building ID 2780

Address 5042 S. Artesian Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
053	
054	Material not observed in room 129
055	
056	
057	
058	Not AHERA
059	
060	
061	
062	Not AHERA
063	
064	
065	Not AHERA
066	
067	
068	
069	
071	Material was not observed - 2013 3 years re-inspection
070	
071	Material was not observed - 2013 3 years re-inspection
072	Material was not observed - 2013 3 years re-inspection
073	Material was not observed - 2013 3 years re-inspection
074	Material was not observed - 2013 3 years re-inspection
075	
076	
077	
078	
079	
080	

Chicago Public Schools

School Christopher School Unit 30031 Building ID 2780

Address 5042 S. Artesian Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
081	Material was not observed - 2013 3 years re-inspection
082	Material was not observed - 2013 3 years re-inspection
083	
084	
085	
086	
087	
088	
089	
090	
091	
092	
093	
094	
095	
096	
097	
098	
099	
100	
101	
102	
103	
104	
105	
106	
107	
108	
109	

Chicago Public Schools

School Christopher School Unit 30031 Building ID 2780

Address 5042 S. Artesian Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
90A	
90B	
B	
C	
D	
E	
F	Not observed in kitchen storage
G	Material was not observed - 2013 3 years re-inspection
H	Material was not observed - 2013 3 years re-inspection
I	
J	

Table II

Management Planner's Review

Chicago Public Schools

School Christopher School

Unit 30031

Building ID 2780

Address 5042 S. Artesian

Chicago, IL, 60632

Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
001	2' x 4' Ceiling Panels			Throughout Facility	No ACBM	MISC					
002	Burlap	50,000	SF	On Walls Throughout Facility	Assumed	MISC	No	20	SF	6 ACBM with the potential for damage	Remove
003	Plaster	100,000	SF	Throughout Original Construction	Assumed	SURFACE	No	30	SF	6 ACBM with the potential for damage	Operations and Maintenance
004	2' x 2' Ceiling Panels - ABATED	3,550	SF	Gym	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
005	2' x 4' Ceiling Panels			Throughout Facility	No ACBM	MISC					
006 A	9"x9" Dark Brown Floor Tile w/ Red & White Streaks	2,500	SF	Computer Room, Science Lab (125-A), Office, 104, 133, 135, Principal's Office	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
006 B	9"x9" Light Brown Floor Tile w/ Dark Brown Streaks	700	SF	Science Lab and Office	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
006 C	9" x 9" Black Floor Tile w/ White Streaks	200	SF	Science Lab, Hall, Speech, Cafeteria, Rooms 104, 106, 116, 117, 126	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	
006 D	9" x 9" Light Brown Floor Tile w/White Streaks	1,000	SF	Hallways on 1st Floor	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
006 E	9" x 9" Green Floor Tile w/ White Streaks	1,000	SF	Hallways	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
006 F	9" x 9" Gray FT w/Red, Yellow, Blue, & White Dots	1,400	SF	Rooms 116, 117, 125 and 127	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
006 G	9" x 9" Red Floor Tile w/White Streaks	1,000	SF	Hallways on 1st Floor and Rooms 104, 129	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
006 H	9"x9 Light Brown FT w/ Blue, Red, Yel & White Dots	1,400	SF	Room 123	Chrysotile	MISC	No		SF		
006 I	9" x 9" Light Brn w/Brn & White Streaks Floor Tile	20	SF	Rooms 122, 123, 126 and as Patches in the Cafeteria	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
006 K	9" x 9" Medium Brown Speckled Floor Tile	1,500	SF	Computer Room, Speech, Cafeteria, 103-110, 124, 126-128, 129, Office, Teachers Lounge	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
006 L	9" x 9" Dark Brown Speckled Floor Tile	800	SF	Computer Room, Speech, Cafeteria, 103-110, 124, 126-128, 129, Office, Teachers Lounge	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
006 M	9" x 9" Light Brown FT w/ Dark Brown & White Spots	700	SF	Women's Teacher's Lounge, Rooms 101, 113, 115, 122, 123, and 126	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
006 N	9" x 9" Beige Floor Tile w/Brown & White Streaks	1,100	SF	Cafeteria, Hall between Mobile Units, 103, Physical Therapy, Office, 122, 123, 126, 133, 135	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
006 O	9" x 9" Rusty Brown Speckled Floor Tile	50	SF	Cafeteria, Rooms 103, 104, 124, and 126, Computer Lab	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
006 P	9" x 9" White Floor Tile w/ Black Streaks	800	SF	Kitchen	Chrysotile	MISC	No	0	SF		
006 Q	9" x 9" Gray Floor Tile w/White & Brown Streaks	200	SF	Room 130	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
006 R	9" x 9" Lt Brn Floor Tile w/Dk Brown & White Spots	100	SF	Room 113	Chrysotile	MISC	No		SF		
006 S	9" x 9" Multi-Brown Speckled Floor Tile	700	SF	Room 111	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance

Chicago Public Schools

School Christopher School

Unit 30031

Building ID 2780

Address 5042 S. Artesian

Chicago, IL, 60632

Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
007 A	12" x 12" Lt Brown FT w/Gray, Blue, & Rust Strks	75	SF	Custodians Lounge	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
007 B	12" x 12" Beige Floor Tile w/White & Brown Streaks	750	SF	Assembly Hall	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
007 C	12" x 12" Black Floor Tile			Room 123	Assumed	MISC					
007 D	12" x 12" Black Floor Tile w/White Streaks			Speech, Entrance by 127, Room 126	Assumed	MISC					
007 E	12" x 12" Black Floor Tile w/White Specks	350	SF	Speech, Cafeteria, Assembly Hall	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
007 F	12" x 12" White Floor Tile	100	SF	Teachers Lounge, Speech	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
007 G	12" x 12" Dk Gray Floor Tile w/Brn & White Streaks	25	SF	Cafeteria	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
007 H	12" x 12" Light Gray Floor Tile w/White Streaks	100	SF	Cafeteria	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
007 J	12" x 12" Cream Floor Tile w/ Brown & Gray Streaks	300	SF	Boy's and Girl's Locker Room, Pool Office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
007 K	12"x12" Dk Gray Floor Tile w/Black & Gray Streaks	900	SF	Room 130	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
008 A	Linoleum (Lt Green Patterned)	0	SF	Room 129 - NOT OBSERVED	Chrysotile	MISC	No		SF		
008 B	Linoleum (Lt Brown Patterned)	100	SF	Women's Washroom	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
008 C	Beige Patterned Linoleum	100	SF	Physical Therapy Room	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
008 D	Linoleum (Yellow Patterned)	100	SF	Washroom Across From Office	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
009	12" x 12" Ceiling Tiles	80	SF	Assembly Hall on Walls	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
01	Hard Coat Plaster	100,000	SF	Throughout	Assumed	SURFACE	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
010	Block			Boiler Room	No ACBM	MISC					
011	Block Mortar	250	SF	Boiler Room	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
012	9"x9" Dark Brown FT w/ Red & White Streaks Mastic	2,500	SF	Computer Room, Science Room (125-A), Office, Principal's Office, Rooms 133, 135	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
013	9" x 9" Light Brown FT w/Dk Brown Streaks Mastic	1,000	SF	Science Lab and Office	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
014	9" x 9" Black Floor Tile w/White Streaks Mastic	1,000	SF	Rooms 104, 106, 116, 117, 125-A, Hall, Speech and as Patches in the Cafeteria, Science Lab	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
015	9" x 9" Lt Brown FT w/White Streaks Mastic	1,000	SF	Hallways on 1st Floor	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
016	9" x 9" Green FT w/White Streaks Mastic	1,000	SF	Hallways on 1st Floor	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
017	9"x9" Gray w/Red,Yel, Blue & White Dots FT Mastic	1,400	SF	Rooms 116, 117 and 125/127	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
018	9" x 9" Red w/White Streaks Floor Tile Mastic	1,000	SF	Rooms 104 and 129 and Hallways on 1st Floor	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
019	9"x9" Lt Brn w/Blue, Red, Yel, & Wh Dots FT Mastic	1,400	SF	Room123	Chrysotile	MISC	No		SF		Operations and Maintenance
020	9" x 9" Light Brown w/Brn & Wh Streaks FT Mastic	20	SF	Rooms 122, 123, 126 and as Patches	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance

Chicago Public Schools

School Christopher School

Unit 30031

Building ID 2780

Address 5042 S. Artesian

Chicago, IL, 60632

Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
				in the Cafeteria							
021	9" x 9" Light Brown Speckled Floor Tile Mastic	700	SF	Computer Room, Speech, Cafeteria, 103-110, 124, 126-128, 129, Office, Teachers Lounge	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
022	9" x 9" Medium Brown Speckled Floor Tile Mastic	1,500	SF	103-109, 124, 126, 127, 129, Technology, Speech, Office, T. Lounge, Social Worker, Physical Therapy	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
023	9" x 9" Dark Brown Speckled Floor Tile Mastic	800	SF	103-109, 124, 126, 127, 129, Technology, Speech, Office, T. Lounge, Social Worker, Physical Therapy	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
024	9" x 9" Lt Brn w/Dk Brown & White Spots FT Mastic	700	SF	Rooms 113, 115, 122, 123, 126 and Women's Teacher's Lounge	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
025	9" x 9" Beige w/Brown & White Streaks FT Mastic	800	SF	Rooms 103, 122, and 126, 133, 135 Office, Physical Therapy, Cafeteria, and Hallways	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
026	9" x 9" Rusty Brown Speckled Floor Tile Mastic	150	SF	Rooms 103, 104, 124, and 126, Technology Room and the Cafeteria	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
027	9" x 9" White w/Black Streaks Floor Tile Mastic	800	SF	Kitchen	Chrysotile	MISC	No		SF		
028	9" x 9" Gray Floor Tile w/Brn & Wh Streaks Mastic			Room 128-(Number Has Been Changed From 130)	Assumed	MISC					
029	9"x9" Lt. Brn FT w/Dark Brown & White Spots Mastic	700	SF	Room 113	Chrysotile	MISC	No		SF		
030	12"x12" Lt Brn FT w/ Gry, Blu, & Rust Strks Mastic	200	SF	Custodian's Lounge	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
031	12" x 12" Beige FT w/ Wh & Brown Streaks Mastic	1,600	SF	Assembly Hall	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
032	12" x 12" Black Floor Tile Mastic	600	SF	Room 123	Chrysotile	MISC	No		SF		
033	12" x 12" Black Floor Tile w/ White Streaks Mastic	200	SF	Speech, Entrance by 127, Room 126	Chrysotile	MISC	No		SF		
034	12" x 12" Black Floor Tile w/White Specks Mastic	350	SF	Speech, Cafeteria, Assembly Hall	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
035	12" x 12" White Floor Tile Mastic	100	SF	Speech, Teacher's Lounge	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
036	12"x12" Dark Gray FT w/Brown & White Strks Mastic	25	SF	Cafeteria	Chrysotile	MISC	No		SF		
037	12" x 12" Light Gray FT w/White Streaks Mastic	100	SF	Cafeteria	Chrysotile	MISC	No		SF		
038	12" x 12" Off-White FT w/Brown Speckles Mastic	500	SF	Cafeteria, Boy's Washroom, Room 108	Chrysotile	MISC	No		SF		
039	12"x12" Cream Floor Tile w/(Lt) Brown & Gray Mastic	300	SF	Girl's and Boy's Locker Room, Pool Office	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
040	12" x 12" Cream Floor Tile w/Brown & Gray Mastic	300	SF	Girl's and Boy's Locker Room, Pool Office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance

Chicago Public Schools

School Christopher School
Address 5042 S. Artesian

Unit 30031
 Chicago, IL, 60632

Building ID 2780
Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
041	Interior Brick Mortar			Throughout Building	No ACBM	MISC					
042	Black Border Tiles	1,000	SF	Throughout Building halls on 1st Floor	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
043	Black Border Tile Mastic	1,000	SF	Throughout Building Halls on 1st Floor	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
044	Cinder Block - New Construction	4,000	SF	Throughout Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
045	Cinder Block Mortar - New Construction	40,000	SF	Throughout Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
046	Rubber Flooring	3,550	SF	Gym	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
047	4" Black Baseboard	1,000	LF	Gym, Boy's and Girl's Locker Room throughout	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Operations and Maintenance
048	4" Black Baseboard Mastic	1,000	SF	Gym, Boy's and Girl's Locker Room Throughout	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
049	6" Black Baseboard	250	LF	Gym	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Operations and Maintenance
050	6" Black Baseboard Mastic	250	LF	Gym	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Operations and Maintenance
051	Spray-on Material	1,250	SF	Attic	No ACBM	MISC			SF		
052	Plaster	200,000	SF	Attic	No ACBM	SURFACE			SF		
053	Finished (Glazed) Brick Mortar	200,000	LF	Throughout Building	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Operations and Maintenance
054	Terrazzo Wall Panels	400	SF	Boys and Women's Washroom, Room 129	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
055	Non-skid Strips	100	SF	Women's Washroom	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
056	Exterior Brick - Not AHERA			Exterior of Building - Original Construction	No ACBM	MISC					
057	Exterior Brick Mortar - Not AHERA			Exterior of Building - Original Construction	No ACBM	MISC					
058	Exterior Door Caulk - Not AHERA)			Exterior of All Doors in Original Construction	Chrysotile						
059	Cinder Block in Original Construction			Throughout Basement	No ACBM	MISC					
060	Cinderblock Mortar - Original Construction			Throughout Basement	No ACBM	MISC					
061	2' x 4' Ceiling Panels			Throughout Building	No ACBM	MISC					
062	Exterior Window Caulk - Not AHERA			Exterior of Building - Original Building	Chrysotile	MISC					
063	Exterior Brick - Not AHERA			Exterior of New Addition	No ACBM	MISC					
064	Exterior Brick Mortar - Not AHERA			Exterior of New Addition	No ACBM	MISC					
065	Exterior Door Caulk - Not AHERA			Exterior of New Addition	Chrysotile	MISC					
066	12" x 12" Dk Gray FT w/Black & Gray Streaks Mastic	900	SF	Room 130	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
067	Non - Skid Strips	100	SF	Boy's and Girl's Locker Room, Pool Office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance

Chicago Public Schools

School Christopher School
Address 5042 S. Artesian

Unit 30031
 Chicago, IL, 60632

Building ID 2780
Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
068	Ceramic Tile Grout	800	SF	Pool Deck	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
069	Grout Between Floor & Wall	400	SF	Pool Deck	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
070	12" x 12" Off-White Floor Tile w/Brown Speckles	500	SF	Cafeteria, Boys Washroom, Room 108	Assumed	MISC	No		SF		
071	Ceramic Tile Grout in Pool	1,000	SF	Pool	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
072	Gray Baseboard	100	LF	Room 130	Assumed	MISC	No		LF		
073	Gray Baseboard Mastic	100	LF	Room 130	Assumed	MISC	No		LF		
074	Ceiling Panel Material	900	SF	Room 130	Assumed	MISC	No		SF		
075	Insulation Above Ceiling Panels	900	SF	Room 130	Assumed	MISC	No		SF		
076	Linoleum Like Flooring Material	10	SF	Storage	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
077	Linoleum Like Material Mastic	10	SF	Storage	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
078	Vibration Absorbers	20	LF	Attic	No ACBM	MISC	No		LF		
079	Terrazzo Sink	40	SF	Boy's Washroom	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
080	2' x 2' Ceiling Panels	3,600	SF	Gym	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
081	Insulation in Safe Door	32	SF	Hallway Across From Assembly Hall	Assumed	TSI	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Operations and Maintenance
082	9" x 9" Multi-Brown Specked Floor Tile	700	SF	Room 111	Chrysotile	MISC	No		SF		
083	9" x 9" Multi-Brown Specked Floor Tile Mastic	700	SF	Room 111	Chrysotile	MISC	No		SF		
084	12" x 12" Multi-Brown Streaked Floor Tile	500	SF	Room 132	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
085	12" x 12" Multi-Brown Streaked Floor Tile Mastic	500	SF	Room 132	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
086	Dark Gray Linoleum	400	SF	Outside Hall by Rooms 401, 403, 405, 407	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
087	Dark Gray Linoleum Mastic	400	SF	Hall outside Rooms 401, 403, 405, 407	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
088	2' x 4' Lay-In Ceiling Panels	1,000	SF	Room 180/181 and as Patch in Exit by Gym	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
089	Dark Gray Baseboard	250	SF	Room 401, 403, 405, 407 and Hall	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
090	Dark Gray Baseboard Mastic	250	SF	Room 401, 403, 405, 407, Hall	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
091	Drywall	2,600	SF	New Building 401, 403, 405, 407 and Hall, Unisex Washroom	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
092	White and Light Blue Linoleum	1,600	SF	Rooms 401, 403, 405, 407	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
093	White and Light Blue Linoleum Mastic	1,600	SF	Rooms 401, 403, 405, 407	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
094	Boiler Gaskets	50	LF	Boiler Room	Assumed	TSI	No	0	LF	6 ACBM with the potential for damage	Operations and Maintenance
095	Insulation Under Steel Shell of Incinerator	100	SF	Boiler Room	Assumed	TSI	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
096	12" x 12" White w/Gray Specks Floor Tile	3,900	SF	New Annex - Rooms 302 - 309, Changing Room and Laundry Room, Halls on 1st Floor	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance

Chicago Public Schools

School Christopher School

Unit 30031

Building ID 2780

Address 5042 S. Artesian

Chicago, IL, 60632

Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
096	12" x 12" White w/Gray Specks Floor Tile Mastic	3,900	SF	New Annex - Rooms 302 - 309, Changing Room and Laundry Room, and Halls on 1st Floor	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
097	4" Beige Baseboard	800	LF	New Annex - All Rooms except Washroom	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Operations and Maintenance
098	4" Beige Baseboard Adhesive	800	LF	New Annex - All Rooms except Washroom	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Operations and Maintenance
099	2' x 2' White Fissured Ceiling Tile	4,000	SF	New Annex - All Rooms, 1st Floor Hall	Assumed	MISC	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Operations and Maintenance
100	12"x12" Gray and Cream Speckled Floor Tile	3,600	SF	Auditorium	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
101	12"x12" Gray and Cream Speckled Floor Tile-Mastic	3,600	SF	Auditorium	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
102	12"x12" Brown Floor Tile	120	SF	Auditorium, Stairs, Landing	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
103	12"x12" Brown Floor Tile Mastic	300	SF	Auditorium, Stairs, Landing, Engineer	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
104	12x12 Light Brown FT with Dark Brown & White	3,000	SF	Rooms 111, 103, 132, 135, 136, 113	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
105	Mastic associated with 12x12Light Brown FT with Dark Brown & White	3,000	SF	Rooms 111, 103, 132, 135, 136, 113	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
106	Cream with Light Brown Linoleum	750	SF	Washrooms across from 129/131	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
107	Adhesive associated with Cream with Light Brown Linoleum	750	SF	Washrooms across from room 129/131	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
108	12"X12" Blue W/Gray White Streaks VFT	11,000	SF	Room 113,116,117/119,121/123,143,101,105, 107,109,125, 127,128,137,141, cafeteria lounge	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
109	12"X12" Blue W/Gray & White Streaks VFT Mastic	11,000	SF	Room 113,116,117/119,121/123,143,101,105, 107,109,125, 127,128,137,141, cafeteria lounge	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
90A	Drywall Tape	250	SF	Addition for 401, 403, 405, 407	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
90B	Drywall Compound	250	LF	Addition for 401, 403, 405, 407	Assumed	MISC	Yes	0	LF	7 Any remaining friable ACBM or friable suspect ACBM	Operations and Maintenance
B	Aircell Pipe Insulation	1,500	LF	Tunnel, Basement, Crawl Spaces	Chrysotile	TSI	Yes	100	LF	1 Damaged or significantly damaged friable thermal system insulating ACBM	Remove
C	Aircell Pipe Insulation Joints	50	LF	Basement, Tunnel, Crawl Spaces	Chrysotile	TSI	Yes	0	LF	6 ACBM with the potential for damage	Operations and Maintenance
D	Cardboard Pipe Insulation	35	LF	Tunnel / Kitchen Storage Room	Chrysotile	TSI	No	0	LF	6 ACBM with the potential for damage	Operations and Maintenance
E	Cardboard Pipe Insulation Joints	4	LF	Tunnel/Kitchen Storage	No ACBM	MISC			LF		

Chicago Public Schools

School Christopher School
Address 5042 S. Artesian

Unit 30031
 Chicago, IL, 60632

Building ID 2780
Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
F	Pipe Joint Insulation off Fiberglass	10	LF	Tunnel, Kitchen Storage Room	Chrysotile	TSI	No	0	LF	6 ACBM with the potential for damage	Operations and Maintenance
G	Boiler Insulation - ABATED				Abated	TSI					
H	Tank Insulation - ABATED				Abated	TSI					
I	Aircell Pipe Wrap (Jacketing)	1,500	LF	Tunnel, Basement, Crawl Spaces, Maintenance Areas	Chrysotile	TSI	No	100	LF	1 Damaged or significantly damaged friable thermal system insulating ACBM	Remove
J	Fiberglass Pipe Insulation			Tunnel	No ACBM	TSI					

Chicago Public Schools

School Christopher School

Unit 30031

Building ID 2780

Address 5042 S. Artesian

Chicago, IL, 60632

Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

Review Date	4/18/2013
Manager Planner Name	Todd Huffer
100-09870	5/15/2013
Manager IDPH License No/Expiration	

HA Number	Management Comments
001	
002	Remove/Repair damaged material and maintain O&M
003	
004	
005	
006 A	Not observed in 125, computer room
006 B	
006 C	Not observed in cafeteria, 116, 117, 126
006 D	
006 E	
006 F	Not observed in 116, 117, 126, 125/127
006 G	
006 H	Material was not observed - 2013 3 years re-inspection
006 I	Not observed in cafeteria, 122, 123, 126
006 K	Not observed in 127, 128, 103, computer room, 110, 124, 126, cafeteria
006 L	Not observed in 127, 128, 103, computer room, 110, 124, 126, cafeteria
006 M	Not observed in 113, 115, 122, 123, 126
006 N	Not observed in cafeteria, mobile unit, 103
006 O	Not observed in 103, 126, 126, 124, computer room
006 P	Material was not observed - 2013 3 years re-inspection
006 Q	
006 R	Material was not observed - 2013 3 years re-inspection
006 S	
007 A	
007 B	
007 C	Material was not observed - 2013 3 years re-inspection
007 D	Material was not observed - 2013 3 years re-inspection

Chicago Public Schools

School Christopher School
Address 5042 S. Artesian

Unit 30031
 Chicago, IL, 60632

Building ID 2780
Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
007 E	Not observed in cafeteria
007 F	Not observed in teacher lounge
007 G	Not observed in cafeteria
007 H	
007 J	
007 K	
008 A	Material was not observed - 2013 3 years re-inspection
008 B	
008 C	
008 D	
009	
01	
010	
011	
012	Not observed in 124A and computer room
013	
014	Not observed in 124A and cafeteria
015	
016	
017	Not observed in 124/127
018	
019	Material was not observed - 2013 3 years re-inspection
020	Not observed in cafeteria
021	Not observed in 127, 128, 103, computer room, 110, 124, 126, cafeteria
022	Not observed in teach, 103, 105, 109
023	not observed in 127, teacher lounge, 103, 105, 109, Tech.
024	Not observed in 113, 115, 122, 123, 126

Chicago Public Schools

School Christopher School
Address 5042 S. Artesian

Unit 30031
 Chicago, IL, 60632

Building ID 2780
Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
025	Not observed in cafeteria, 103.
026	Not observed in cafeteria, tech room, 103
027	Material was not observed - 2013 3 years re-inspection
028	Material was not observed - 2013 3 years re-inspection
029	Material was not observed - 2013 3 years re-inspection
030	
031	
032	Material was not observed - 2013 3 years re-inspection
033	Material was not observed - 2013 3 years re-inspection
034	Not observed in cafeteria
035	Not observed in teacher lounge
036	Material was not observed - 2013 3 years re-inspection
037	Material was not observed - 2013 3 years re-inspection
038	Material was not observed - 2013 3 years re-inspection
039	
040	
041	
042	
043	
044	
045	
046	
047	
048	
049	
050	
051	

Chicago Public Schools

School Christopher School
Address 5042 S. Artesian

Unit 30031
 Chicago, IL, 60632

Building ID 2780
Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
052	
053	
054	Material not observed in room 129
055	
056	
057	
058	
059	
060	
061	
062	
063	
064	
065	
066	
067	
068	
069	
071	Material was not observed - 2013 3 years re-inspection
070	
071	Material was not observed - 2013 3 years re-inspection
072	Material was not observed - 2013 3 years re-inspection
073	Material was not observed - 2013 3 years re-inspection
074	Material was not observed - 2013 3 years re-inspection
075	
076	
077	

Chicago Public Schools

School Christopher School

Unit 30031

Building ID 2780

Address 5042 S. Artesian

Chicago, IL, 60632

Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
078	
079	
080	
081	Material was not observed - 2013 3 years re-inspection
082	Material was not observed - 2013 3 years re-inspection
083	
084	
085	
086	
087	
088	
089	
090	
091	
092	
093	
094	
095	
096	
097	
098	
099	
100	
101	
102	
103	
104	

Chicago Public Schools

School Christopher School
Address 5042 S. Artesian

Unit 30031
 Chicago, IL, 60632

Building ID 2780
Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
105	
106	
107	
108	
109	
90A	
90B	
B	Remove/Repair damaged material and maintain O&M
C	
D	
E	
F	Not observed in kitchen storage
G	
H	
I	Remove/Repair damaged material and maintain O&M
J	

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **30031** BUIDLING ID: **2780**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Jesus Delgado**
SCHOOL NAME: **Christopher School** INSPECTION DATE: **3/18/2013**
ADDRESS: **5042 S. Artesian** IDPH LICENSE NO: **100-11170**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **001**
MATERIAL DESCRIPTION: **2' x 4' Ceiling Panels**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout Facility**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **03/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **30031** BUIDLING ID: **2780**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Christopher School** REVIEW DATE: **4/18/2013**
ADDRESS: **5042 S. Artesian** IDPH LICENSE NO: **100-11170**

HOMOGENEOUS AREA: **001**

MATERIAL DESCRIPTION: **2' x 4' Ceiling Panels**

MATERIAL LOCATION: **Throughout Facility**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **04/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **30031** BUIDLING ID: **2780**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Jesus Delgado**
SCHOOL NAME: **Christopher School** INSPECTION DATE: **3/18/2013**
ADDRESS: **5042 S. Artesian** IDPH LICENSE NO: **100-11170**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **002**
MATERIAL DESCRIPTION: **Burlap**
HISTORICAL AHERA DAMAGE CATEGORY **6**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **On Walls Throughout Facility**
MATERIAL QUANTITY: **50000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **30031** BUIDLING ID: **2780**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Christopher School** REVIEW DATE: **4/18/2013**
ADDRESS: **5042 S. Artesian** IDPH LICENSE NO: **100-11170**

HOMOGENEOUS AREA: **002**
MATERIAL DESCRIPTION: **Burlap**
MATERIAL LOCATION: **On Walls Throughout Facility**
MATERIAL QUANTITY: **50000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **20** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Remove/Repair damaged material and maintain O&M

Management Planner's Signature: _____



Date: **04/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **30031** BUIDLING ID: **2780**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Jesus Delgado**
SCHOOL NAME: **Christopher School** INSPECTION DATE: **3/18/2013**
ADDRESS: **5042 S. Artesian** IDPH LICENSE NO: **100-11170**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **003**
MATERIAL DESCRIPTION: **Plaster**
HISTORICAL AHERA DAMAGE CATEGORY **6**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT


This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Throughout Original Construction**
MATERIAL QUANTITY: **100000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature:



Date: **03/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **30031** BUIDLING ID: **2780**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Christopher School** REVIEW DATE: **4/18/2013**
ADDRESS: **5042 S. Artesian** IDPH LICENSE NO: **100-11170**

HOMOGENEOUS AREA: **003**
MATERIAL DESCRIPTION: **Plaster**
MATERIAL LOCATION: **Throughout Original Construction**
MATERIAL QUANTITY: **100000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **30** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **04/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **30031** BUIDLING ID: **2780**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Jesus Delgado**
SCHOOL NAME: **Christopher School** INSPECTION DATE: **3/18/2013**
ADDRESS: **5042 S. Artesian** IDPH LICENSE NO: **100-11170**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **004**
MATERIAL DESCRIPTION: **2' x 2' Ceiling Panels - ABATED**
HISTORICAL AHERA DAMAGE CATEGORY **6**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Gym**
MATERIAL QUANTITY: **3550** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **30031** BUIDLING ID: **2780**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Christopher School** REVIEW DATE: **4/18/2013**
ADDRESS: **5042 S. Artesian** IDPH LICENSE NO: **100-11170**

HOMOGENEOUS AREA: **004**
MATERIAL DESCRIPTION: **2' x 2' Ceiling Panels - ABATED**
MATERIAL LOCATION: **Gym**
MATERIAL QUANTITY: **3550** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **04/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates
2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **30031** BUIDLING ID: **2780**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Jesus Delgado**
SCHOOL NAME: **Christopher School** INSPECTION DATE: **3/18/2013**
ADDRESS: **5042 S. Artesian** IDPH LICENSE NO: **100-11170**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **005**
MATERIAL DESCRIPTION: **2' x 4' Ceiling Panels**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout Facility**

MATERIAL QUANTITY:


MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **03/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **30031** BUIDLING ID: **2780**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Christopher School** REVIEW DATE: **4/18/2013**
ADDRESS: **5042 S. Artesian** IDPH LICENSE NO: **100-11170**

HOMOGENEOUS AREA: **005**
MATERIAL DESCRIPTION: **2' x 4' Ceiling Panels**
MATERIAL LOCATION: **Throughout Facility**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **04/18/2013** _____

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **30031** BUIDLING ID: **2780**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Jesus Delgado**
SCHOOL NAME: **Christopher School** INSPECTION DATE: **3/18/2013**
ADDRESS: **5042 S. Artesian** IDPH LICENSE NO: **100-11170**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **006 A**
MATERIAL DESCRIPTION: **9"x9" Dark Brown Floor Tile w/ Red & White Streaks**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Computer Room, Science Lab (125-A), Office, 104, 133, 135, Principal's Office**

MATERIAL QUANTITY: **2500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS: **Not observed in 125, computer room**

Inspector's Signature:



Date: **03/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **30031** BUIDLING ID: **2780**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Christopher School** REVIEW DATE: **4/18/2013**
ADDRESS: **5042 S. Artesian** IDPH LICENSE NO: **100-11170**

HOMOGENEOUS AREA: **006 A**
MATERIAL DESCRIPTION: **9"x9" Dark Brown Floor Tile w/ Red & White Streaks**
MATERIAL LOCATION: **Computer Room, Science Lab (125-A), Office, 104, 133, 135, Principal's Office**
MATERIAL QUANTITY: **2500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Not observed in 125, computer room

Management Planner's Signature: _____



Date: 04/18/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **30031** BUIDLING ID: **2780**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Jesus Delgado**
SCHOOL NAME: **Christopher School** INSPECTION DATE: **3/18/2013**
ADDRESS: **5042 S. Artesian** IDPH LICENSE NO: **100-11170**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **006 B**
MATERIAL DESCRIPTION: **9"x9" Light Brown Floor Tile w/ Dark Brown Streaks**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Science Lab and Office**

MATERIAL QUANTITY: **700**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **30031** BUIDLING ID: **2780**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Christopher School** REVIEW DATE: **4/18/2013**
ADDRESS: **5042 S. Artesian** IDPH LICENSE NO: **100-11170**

HOMOGENEOUS AREA: **006 B**
MATERIAL DESCRIPTION: **9"x9" Light Brown Floor Tile w/ Dark Brown Streaks**
MATERIAL LOCATION: **Science Lab and Office**
MATERIAL QUANTITY: **700** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **04/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates 2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **30031** BUIDLING ID: **2780**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Jesus Delgado**
SCHOOL NAME: **Christopher School** INSPECTION DATE: **3/18/2013**
ADDRESS: **5042 S. Artesian** IDPH LICENSE NO: **100-11170**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **006 C**
MATERIAL DESCRIPTION: **9" x 9" Black Floor Tile w/ White Streaks**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT


This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Science Lab, Hall, Speech, Cafeteria, Rooms 104, 106, 116, 117, 126**
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS: **Not observed in caferia, 116, 117, 126**

Inspector's Signature:



Date: **03/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **30031** BUIDLING ID: **2780**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Christopher School** REVIEW DATE: **4/18/2013**
ADDRESS: **5042 S. Artesian** IDPH LICENSE NO: **100-11170**

HOMOGENEOUS AREA: **006 C**
MATERIAL DESCRIPTION: **9" x 9" Black Floor Tile w/ White Streaks**
MATERIAL LOCATION: **Science Lab, Hall, Speech, Cafeteria, Rooms 104, 106, 116, 117, 126**
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Not observed in caferia, 116, 117, 126

Management Planner's Signature: _____



Date: **04/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **30031** BUIDLING ID: **2780**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Jesus Delgado**
SCHOOL NAME: **Christopher School** INSPECTION DATE: **3/18/2013**
ADDRESS: **5042 S. Artesian** IDPH LICENSE NO: **100-11170**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **006 D**
MATERIAL DESCRIPTION: **9" x 9" Light Brown Floor Tile w/White Streaks**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Hallways on 1st Floor**

MATERIAL QUANTITY: **1000**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **30031** BUIDLING ID: **2780**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Christopher School** REVIEW DATE: **4/18/2013**
ADDRESS: **5042 S. Artesian** IDPH LICENSE NO: **100-11170**

HOMOGENEOUS AREA: **006 D**
MATERIAL DESCRIPTION: **9" x 9" Light Brown Floor Tile w/White Streaks**
MATERIAL LOCATION: **Hallways on 1st Floor**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **04/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates 2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **30031** BUIDLING ID: **2780**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Jesus Delgado**
SCHOOL NAME: **Christopher School** INSPECTION DATE: **3/18/2013**
ADDRESS: **5042 S. Artesian** IDPH LICENSE NO: **100-11170**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **006 E**
MATERIAL DESCRIPTION: **9" x 9" Green Floor Tile w/ White Streaks**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Hallways**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **30031** BUIDLING ID: **2780**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Christopher School** REVIEW DATE: **4/18/2013**
ADDRESS: **5042 S. Artesian** IDPH LICENSE NO: **100-11170**

HOMOGENEOUS AREA: **006 E**

MATERIAL DESCRIPTION: **9" x 9" Green Floor Tile w/ White Streaks**

MATERIAL LOCATION: **Hallways**

MATERIAL QUANTITY: **1000**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **04/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **30031** BUIDLING ID: **2780**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Jesus Delgado**
SCHOOL NAME: **Christopher School** INSPECTION DATE: **3/18/2013**
ADDRESS: **5042 S. Artesian** IDPH LICENSE NO: **100-11170**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **006 F**
MATERIAL DESCRIPTION: **9" x 9" Gray FT w/Red, Yellow, Blue, & White Dots**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Rooms 116, 117, 125 and 127**

MATERIAL QUANTITY: **1400**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS: **Not observed in 116, 117, 126, 125/127**

Inspector's Signature:



Date: **03/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **30031** BUIDLING ID: **2780**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Christopher School** REVIEW DATE: **4/18/2013**
ADDRESS: **5042 S. Artesian** IDPH LICENSE NO: **100-11170**

HOMOGENEOUS AREA: **006 F**
MATERIAL DESCRIPTION: **9" x 9" Gray FT w/Red, Yellow, Blue, & White Dots**
MATERIAL LOCATION: **Rooms 116, 117, 125 and 127**
MATERIAL QUANTITY: **1400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Not observed in 116, 117, 126, 125/127

Management Planner's Signature: _____



Date: **04/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **30031** BUIDLING ID: **2780**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Jesus Delgado**
SCHOOL NAME: **Christopher School** INSPECTION DATE: **3/18/2013**
ADDRESS: **5042 S. Artesian** IDPH LICENSE NO: **100-11170**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **006 G**
MATERIAL DESCRIPTION: **9" x 9" Red Floor Tile w/White Streaks**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Hallways on 1st Floor and Rooms 104, 129**

MATERIAL QUANTITY: **1000**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **30031** BUIDLING ID: **2780**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Christopher School** REVIEW DATE: **4/18/2013**
ADDRESS: **5042 S. Artesian** IDPH LICENSE NO: **100-11170**

HOMOGENEOUS AREA: **006 G**
MATERIAL DESCRIPTION: **9" x 9" Red Floor Tile w/White Streaks**
MATERIAL LOCATION: **Hallways on 1st Floor and Rooms 104, 129**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **04/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **30031** BUIDLING ID: **2780**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Jesus Delgado**
SCHOOL NAME: **Christopher School** INSPECTION DATE: **3/18/2013**
ADDRESS: **5042 S. Artesian** IDPH LICENSE NO: **100-11170**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **006 H**
MATERIAL DESCRIPTION: **9"x9 Light Brown FT w/ Blue, Red, Yel & White Dots**
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 123**

MATERIAL QUANTITY: **1400**


MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS: **Material was not observed - 2013 3 years re-inspection**

Inspector's Signature:



Date: **03/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **30031** BUIDLING ID: **2780**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Christopher School** REVIEW DATE: **4/18/2013**
ADDRESS: **5042 S. Artesian** IDPH LICENSE NO: **100-11170**

HOMOGENEOUS AREA: **006 H**
MATERIAL DESCRIPTION: **9"x9 Light Brown FT w/ Blue, Red, Yel & White Dots**
MATERIAL LOCATION: **Room 123**
MATERIAL QUANTITY: **1400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Material was not observed - 2013 3 years re-inspection

Management Planner's Signature: _____



Date: **04/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **30031** BUIDLING ID: **2780**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Jesus Delgado**
SCHOOL NAME: **Christopher School** INSPECTION DATE: **3/18/2013**
ADDRESS: **5042 S. Artesian** IDPH LICENSE NO: **100-11170**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **006 I**
MATERIAL DESCRIPTION: **9" x 9" Light Brn w/Brn & White Streaks Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Rooms 122, 123, 126 and as Patches in the Cafeteria**

MATERIAL QUANTITY: **20** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS: **Not observed in caferia, 122, 123, 126**

Inspector's Signature:



Date: **03/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **30031** BUIDLING ID: **2780**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Christopher School** REVIEW DATE: **4/18/2013**
ADDRESS: **5042 S. Artesian** IDPH LICENSE NO: **100-11170**

HOMOGENEOUS AREA: **006 I**
MATERIAL DESCRIPTION: **9" x 9" Light Brn w/Brn & White Streaks Floor Tile**
MATERIAL LOCATION: **Rooms 122, 123, 126 and as Patches in the Cafeteria**
MATERIAL QUANTITY: **20** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Not observed in caferia, 122, 123, 126

Management Planner's Signature: _____



Date: **04/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **30031** BUIDLING ID: **2780**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Jesus Delgado**
SCHOOL NAME: **Christopher School** INSPECTION DATE: **3/18/2013**
ADDRESS: **5042 S. Artesian** IDPH LICENSE NO: **100-11170**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **006 K**
MATERIAL DESCRIPTION: **9" x 9" Medium Brown Speckled Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Computer Room, Speech, Cafeteria, 103-110, 124, 126-128, 129, Office, Teachers Lounge**

MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS: **Not observed in 127, 128, 103, computer room, 110, 124, 126, caferia**

Inspector's Signature:



Date: **03/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **30031** BUIDLING ID: **2780**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Christopher School** REVIEW DATE: **4/18/2013**
ADDRESS: **5042 S. Artesian** IDPH LICENSE NO: **100-11170**

HOMOGENEOUS AREA: **006 K**
MATERIAL DESCRIPTION: **9" x 9" Medium Brown Speckled Floor Tile**
MATERIAL LOCATION: **Computer Room, Speech, Cafeteria, 103-110, 124, 126-128, 129, Office, Teachers Lounge**
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Not observed in 127, 128, 103, computer room, 110, 124, 126, caferia

Management Planner's Signature: _____



Date: 04/18/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **30031** BUIDLING ID: **2780**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Jesus Delgado**
SCHOOL NAME: **Christopher School** INSPECTION DATE: **3/18/2013**
ADDRESS: **5042 S. Artesian** IDPH LICENSE NO: **100-11170**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **006 L**
MATERIAL DESCRIPTION: **9" x 9" Dark Brown Speckled Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Computer Room, Speech, Cafeteria, 103-110, 124, 126-128, 129, Office, Teachers Lounge**

MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS: **Not observed in 127, 128, 103, computer room, 110, 124, 126, caferia**

Inspector's Signature:



Date: **03/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **30031** BUIDLING ID: **2780**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Christopher School** REVIEW DATE: **4/18/2013**
ADDRESS: **5042 S. Artesian** IDPH LICENSE NO: **100-11170**

HOMOGENEOUS AREA: **006 L**
MATERIAL DESCRIPTION: **9" x 9" Dark Brown Speckled Floor Tile**
MATERIAL LOCATION: **Computer Room, Speech, Cafeteria, 103-110, 124, 126-128, 129, Office, Teachers Lounge**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Not observed in 127, 128, 103, computer room, 110, 124, 126, caferia

Management Planner's Signature: _____



Date: 04/18/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **30031** BUIDLING ID: **2780**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Jesus Delgado**
SCHOOL NAME: **Christopher School** INSPECTION DATE: **3/18/2013**
ADDRESS: **5042 S. Artesian** IDPH LICENSE NO: **100-11170**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **006 M**
MATERIAL DESCRIPTION: **9" x 9" Light Brown FT w/ Dark Brown & White Spots**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Women's Teacher's Lounge, Rooms 101, 113, 115, 122, 123, and 126**

MATERIAL QUANTITY: **700** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS: **Not observed in 113, 115, 122, 123, 126**

Inspector's Signature:



Date: **03/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **30031** BUIDLING ID: **2780**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Christopher School** REVIEW DATE: **4/18/2013**
ADDRESS: **5042 S. Artesian** IDPH LICENSE NO: **100-11170**

HOMOGENEOUS AREA: **006 M**
MATERIAL DESCRIPTION: **9" x 9" Light Brown FT w/ Dark Brown & White Spots**
MATERIAL LOCATION: **Women's Teacher's Lounge, Rooms 101, 113, 115, 122, 123, and 126**
MATERIAL QUANTITY: **700** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Not observed in 113, 115, 122, 123, 126

Management Planner's Signature: _____



Date: **04/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates 2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **30031** BUIDLING ID: **2780**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Jesus Delgado**
SCHOOL NAME: **Christopher School** INSPECTION DATE: **3/18/2013**
ADDRESS: **5042 S. Artesian** IDPH LICENSE NO: **100-11170**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **006 N**
MATERIAL DESCRIPTION: **9" x 9" Beige Floor Tile w/Brown & White Streaks**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Cafeteria, Hall between Mobile Units, 103, Physical Therapy, Office, 122, 123, 126, 133, 135**

MATERIAL QUANTITY: **1100**


MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS: **Not observed in caferia, mobile unit, 103**

Inspector's Signature:



Date: **03/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **30031** BUIDLING ID: **2780**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Christopher School** REVIEW DATE: **4/18/2013**
ADDRESS: **5042 S. Artesian** IDPH LICENSE NO: **100-11170**

HOMOGENEOUS AREA: **006 N**
MATERIAL DESCRIPTION: **9" x 9" Beige Floor Tile w/Brown & White Streaks**
MATERIAL LOCATION: **Cafeteria, Hall between Mobile Units, 103, Physical Therapy, Office, 122, 123, 126, 133, 135**
MATERIAL QUANTITY: **1100** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Not observed in caferia, mobile unit, 103

Management Planner's Signature: _____



Date: **04/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **30031** BUIDLING ID: **2780**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Jesus Delgado**
SCHOOL NAME: **Christopher School** INSPECTION DATE: **3/18/2013**
ADDRESS: **5042 S. Artesian** IDPH LICENSE NO: **100-11170**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **006 O**
MATERIAL DESCRIPTION: **9" x 9" Rusty Brown Speckled Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Cafeteria, Rooms 103, 104, 124, and 126, Computer Lab**

MATERIAL QUANTITY: **50** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS: **Not observed in 103, 126, 124, computer room**

Inspector's Signature:



Date: **03/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **30031** BUIDLING ID: **2780**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Christopher School** REVIEW DATE: **4/18/2013**
ADDRESS: **5042 S. Artesian** IDPH LICENSE NO: **100-11170**

HOMOGENEOUS AREA: **006 O**
MATERIAL DESCRIPTION: **9" x 9" Rusty Brown Speckled Floor Tile**
MATERIAL LOCATION: **Cafeteria, Rooms 103, 104, 124, and 126, Computer Lab**
MATERIAL QUANTITY: **50** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Not observed in 103, 126, 126, 124, computer room

Management Planner's Signature: _____



Date: **04/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **30031** BUIDLING ID: **2780**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Jesus Delgado**
SCHOOL NAME: **Christopher School** INSPECTION DATE: **3/18/2013**
ADDRESS: **5042 S. Artesian** IDPH LICENSE NO: **100-11170**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **006 P**
MATERIAL DESCRIPTION: **9" x 9" White Floor Tile w/ Black Streaks**
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Kitchen**

MATERIAL QUANTITY: **800**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS: **Material was not observed - 2013 3 years re-inspection**

Inspector's Signature:



Date: **03/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **30031** BUIDLING ID: **2780**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Christopher School** REVIEW DATE: **4/18/2013**
ADDRESS: **5042 S. Artesian** IDPH LICENSE NO: **100-11170**

HOMOGENEOUS AREA: **006 P**
MATERIAL DESCRIPTION: **9" x 9" White Floor Tile w/ Black Streaks**
MATERIAL LOCATION: **Kitchen**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Material was not observed - 2013 3 years re-inspection

Management Planner's Signature: _____



Date: **04/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **30031** BUIDLING ID: **2780**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Jesus Delgado**
SCHOOL NAME: **Christopher School** INSPECTION DATE: **3/18/2013**
ADDRESS: **5042 S. Artesian** IDPH LICENSE NO: **100-11170**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **006 Q**
MATERIAL DESCRIPTION: **9" x 9" Gray Floor Tile w/White & Brown Streaks**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Room 130**

MATERIAL QUANTITY: **200**


MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **30031** BUIDLING ID: **2780**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Christopher School** REVIEW DATE: **4/18/2013**
ADDRESS: **5042 S. Artesian** IDPH LICENSE NO: **100-11170**

HOMOGENEOUS AREA: **006 Q**

MATERIAL DESCRIPTION: **9" x 9" Gray Floor Tile w/White & Brown Streaks**

MATERIAL LOCATION: **Room 130**

MATERIAL QUANTITY: **200**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **04/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **30031** BUIDLING ID: **2780**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Jesus Delgado**
SCHOOL NAME: **Christopher School** INSPECTION DATE: **3/18/2013**
ADDRESS: **5042 S. Artesian** IDPH LICENSE NO: **100-11170**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **006 R**
MATERIAL DESCRIPTION: **9" x 9" Lt Brn Floor Tile w/Dk Brown & White Spots**
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **High**

MATERIAL LOCATION: **Room 113**

MATERIAL QUANTITY: **100**


MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS: **Material was not observed - 2013 3 years re-inspection**

Inspector's Signature:



Date: **03/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **30031** BUIDLING ID: **2780**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Christopher School** REVIEW DATE: **4/18/2013**
ADDRESS: **5042 S. Artesian** IDPH LICENSE NO: **100-11170**

HOMOGENEOUS AREA: **006 R**

MATERIAL DESCRIPTION: **9" x 9" Lt Brn Floor Tile w/Dk Brown & White Spots**

MATERIAL LOCATION: **Room 113**

MATERIAL QUANTITY: **100**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Material was not observed - 2013 3 years re-inspection

Management Planner's Signature: _____



Date: **04/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **30031** BUIDLING ID: **2780**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Jesus Delgado**
SCHOOL NAME: **Christopher School** INSPECTION DATE: **3/18/2013**
ADDRESS: **5042 S. Artesian** IDPH LICENSE NO: **100-11170**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **006 S**
MATERIAL DESCRIPTION: **9" x 9" Multi-Brown Specked Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 111**
MATERIAL QUANTITY: **700** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **30031** BUIDLING ID: **2780**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Christopher School** REVIEW DATE: **4/18/2013**
ADDRESS: **5042 S. Artesian** IDPH LICENSE NO: **100-11170**

HOMOGENEOUS AREA: **006 S**
MATERIAL DESCRIPTION: **9" x 9" Multi-Brown Specked Floor Tile**
MATERIAL LOCATION: **Room 111**
MATERIAL QUANTITY: **700** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **04/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **30031** BUIDLING ID: **2780**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Jesus Delgado**
SCHOOL NAME: **Christopher School** INSPECTION DATE: **3/18/2013**
ADDRESS: **5042 S. Artesian** IDPH LICENSE NO: **100-11170**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **007 A**
MATERIAL DESCRIPTION: **12" x 12" Lt Brown FT w/Gray, Blue, & Rust Strks**
HISTORICAL AHERA DAMAGE CATEGORY **6**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Custodians Lounge**

MATERIAL QUANTITY: **75**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **30031** BUIDLING ID: **2780**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Christopher School** REVIEW DATE: **4/18/2013**
ADDRESS: **5042 S. Artesian** IDPH LICENSE NO: **100-11170**

HOMOGENEOUS AREA: **007 A**

MATERIAL DESCRIPTION: **12" x 12" Lt Brown FT w/Gray, Blue, & Rust Strks**

MATERIAL LOCATION: **Custodians Lounge**

MATERIAL QUANTITY: **75**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **04/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates 2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **30031** BUIDLING ID: **2780**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Jesus Delgado**
SCHOOL NAME: **Christopher School** INSPECTION DATE: **3/18/2013**
ADDRESS: **5042 S. Artesian** IDPH LICENSE NO: **100-11170**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **007 B**
MATERIAL DESCRIPTION: **12" x 12" Beige Floor Tile w/White & Brown Streaks**
HISTORICAL AHERA DAMAGE CATEGORY **6**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Assembly Hall**

MATERIAL QUANTITY: **750**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **30031** BUIDLING ID: **2780**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Christopher School** REVIEW DATE: **4/18/2013**
ADDRESS: **5042 S. Artesian** IDPH LICENSE NO: **100-11170**

HOMOGENEOUS AREA: **007 B**

MATERIAL DESCRIPTION: **12" x 12" Beige Floor Tile w/White & Brown Streaks**

MATERIAL LOCATION: **Assembly Hall**

MATERIAL QUANTITY: **750**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **04/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **30031** BUIDLING ID: **2780**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Jesus Delgado**
SCHOOL NAME: **Christopher School** INSPECTION DATE: **3/18/2013**
ADDRESS: **5042 S. Artesian** IDPH LICENSE NO: **100-11170**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **007 C**
MATERIAL DESCRIPTION: **12" x 12" Black Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 123**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Material was not observed - 2013 3 years re-inspection**

Inspector's Signature:



Date: **03/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **30031** BUIDLING ID: **2780**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Christopher School** REVIEW DATE: **4/18/2013**
ADDRESS: **5042 S. Artesian** IDPH LICENSE NO: **100-11170**

HOMOGENEOUS AREA: **007 C**

MATERIAL DESCRIPTION: **12" x 12" Black Floor Tile**

MATERIAL LOCATION: **Room 123**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Material was not observed - 2013 3 years re-inspection

Management Planner's Signature: _____



Date: **04/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates 2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **30031** BUIDLING ID: **2780**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Jesus Delgado**
SCHOOL NAME: **Christopher School** INSPECTION DATE: **3/18/2013**
ADDRESS: **5042 S. Artesian** IDPH LICENSE NO: **100-11170**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **007 D**
MATERIAL DESCRIPTION: **12" x 12" Black Floor Tile w/White Streaks**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Speech, Entrance by 127, Room 126**

MATERIAL QUANTITY:


MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Material was not observed - 2013 3 years re-inspection**

Inspector's Signature:



Date: **03/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **30031** BUIDLING ID: **2780**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Christopher School** REVIEW DATE: **4/18/2013**
ADDRESS: **5042 S. Artesian** IDPH LICENSE NO: **100-11170**

HOMOGENEOUS AREA: **007 D**

MATERIAL DESCRIPTION: **12" x 12" Black Floor Tile w/White Streaks**

MATERIAL LOCATION: **Speech, Entrance by 127, Room 126**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Material was not observed - 2013 3 years re-inspection

Management Planner's Signature: _____



Date: **04/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **30031** BUIDLING ID: **2780**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Jesus Delgado**
SCHOOL NAME: **Christopher School** INSPECTION DATE: **3/18/2013**
ADDRESS: **5042 S. Artesian** IDPH LICENSE NO: **100-11170**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **007 E**
MATERIAL DESCRIPTION: **12" x 12" Black Floor Tile w/White Specks**
HISTORICAL AHERA DAMAGE CATEGORY **6**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Speech, Cafeteria, Assembly Hall**

MATERIAL QUANTITY: **350**


MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS: **Not observed in caferia**

Inspector's Signature:



Date: **03/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **30031** BUIDLING ID: **2780**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Christopher School** REVIEW DATE: **4/18/2013**
ADDRESS: **5042 S. Artesian** IDPH LICENSE NO: **100-11170**

HOMOGENEOUS AREA: **007 E**
MATERIAL DESCRIPTION: **12" x 12" Black Floor Tile w/White Specks**
MATERIAL LOCATION: **Speech, Cafeteria, Assembly Hall**
MATERIAL QUANTITY: **350** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Not observed in caferia

Management Planner's Signature: _____



Date: **04/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **30031** BUIDLING ID: **2780**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Jesus Delgado**
SCHOOL NAME: **Christopher School** INSPECTION DATE: **3/18/2013**
ADDRESS: **5042 S. Artesian** IDPH LICENSE NO: **100-11170**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **007 F**
MATERIAL DESCRIPTION: **12" x 12" White Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Teachers Lounge, Speech**

MATERIAL QUANTITY: **100**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS: **Not observed in teacher lounge**

Inspector's Signature:



Date: **03/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **30031** BUIDLING ID: **2780**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Christopher School** REVIEW DATE: **4/18/2013**
ADDRESS: **5042 S. Artesian** IDPH LICENSE NO: **100-11170**

HOMOGENEOUS AREA: **007 F**
MATERIAL DESCRIPTION: **12" x 12" White Floor Tile**
MATERIAL LOCATION: **Teachers Lounge, Speech**
MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Not observed in teacher lounge

Management Planner's Signature: _____



Date: **04/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **30031** BUIDLING ID: **2780**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Jesus Delgado**
SCHOOL NAME: **Christopher School** INSPECTION DATE: **3/18/2013**
ADDRESS: **5042 S. Artesian** IDPH LICENSE NO: **100-11170**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **007 G**
MATERIAL DESCRIPTION: **12" x 12" Dk Gray Floor Tile w/Brn & White Streaks**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Cafeteria**

MATERIAL QUANTITY: **25**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS: **Not observed in caferia**

Inspector's Signature:



Date: **03/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **30031** BUIDLING ID: **2780**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Christopher School** REVIEW DATE: **4/18/2013**
ADDRESS: **5042 S. Artesian** IDPH LICENSE NO: **100-11170**

HOMOGENEOUS AREA: **007 G**

MATERIAL DESCRIPTION: **12" x 12" Dk Gray Floor Tile w/Brn & White Streaks**

MATERIAL LOCATION: **Cafeteria**

MATERIAL QUANTITY: **25**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Not observed in caferia

Management Planner's Signature: _____



Date: **04/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **30031** BUIDLING ID: **2780**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Jesus Delgado**
SCHOOL NAME: **Christopher School** INSPECTION DATE: **3/18/2013**
ADDRESS: **5042 S. Artesian** IDPH LICENSE NO: **100-11170**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **007 H**
MATERIAL DESCRIPTION: **12" x 12" Light Gray Floor Tile w/White Streaks**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Cafeteria**

MATERIAL QUANTITY: **100**


MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **30031** BUIDLING ID: **2780**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Christopher School** REVIEW DATE: **4/18/2013**
ADDRESS: **5042 S. Artesian** IDPH LICENSE NO: **100-11170**

HOMOGENEOUS AREA: **007 H**

MATERIAL DESCRIPTION: **12" x 12" Light Gray Floor Tile w/White Streaks**

MATERIAL LOCATION: **Cafeteria**

MATERIAL QUANTITY: **100**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **04/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **30031** BUIDLING ID: **2780**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Jesus Delgado**
SCHOOL NAME: **Christopher School** INSPECTION DATE: **3/18/2013**
ADDRESS: **5042 S. Artesian** IDPH LICENSE NO: **100-11170**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **007 J**
MATERIAL DESCRIPTION: **12" x 12" Cream Floor Tile w/ Brown & Gray Streaks**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Boy's and Girl's Locker Room, Pool Office**

MATERIAL QUANTITY: **300**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **30031** BUIDLING ID: **2780**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Christopher School** REVIEW DATE: **4/18/2013**
ADDRESS: **5042 S. Artesian** IDPH LICENSE NO: **100-11170**

HOMOGENEOUS AREA: **007 J**
MATERIAL DESCRIPTION: **12" x 12" Cream Floor Tile w/ Brown & Gray Streaks**
MATERIAL LOCATION: **Boy's and Girl's Locker Room, Pool Office**
MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **04/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **30031** BUIDLING ID: **2780**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Jesus Delgado**
SCHOOL NAME: **Christopher School** INSPECTION DATE: **3/18/2013**
ADDRESS: **5042 S. Artesian** IDPH LICENSE NO: **100-11170**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **007 K**
MATERIAL DESCRIPTION: **12"x12" Dk Gray Floor Tile w/Black & Gray Streaks**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 130**
MATERIAL QUANTITY: **900** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **30031** BUIDLING ID: **2780**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Christopher School** REVIEW DATE: **4/18/2013**
ADDRESS: **5042 S. Artesian** IDPH LICENSE NO: **100-11170**

HOMOGENEOUS AREA: **007 K**

MATERIAL DESCRIPTION: **12"x12" Dk Gray Floor Tile w/Black & Gray Streaks**

MATERIAL LOCATION: **Room 130**

MATERIAL QUANTITY: **900**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **04/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **30031** BUIDLING ID: **2780**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Jesus Delgado**
SCHOOL NAME: **Christopher School** INSPECTION DATE: **3/18/2013**
ADDRESS: **5042 S. Artesian** IDPH LICENSE NO: **100-11170**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **008 A**
MATERIAL DESCRIPTION: **Linoleum (Lt Green Patterned)**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:


MATERIAL LOCATION: **Room 129 - NOT OBSERVED**

MATERIAL QUANTITY: **0** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS: **Material was not observed - 2013 3 years re-inspection**

Inspector's Signature:



Date: **03/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **30031** BUIDLING ID: **2780**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Christopher School** REVIEW DATE: **4/18/2013**
ADDRESS: **5042 S. Artesian** IDPH LICENSE NO: **100-11170**

HOMOGENEOUS AREA: **008 A**
MATERIAL DESCRIPTION: **Linoleum (Lt Green Patterned)**
MATERIAL LOCATION: **Room 129 - NOT OBSERVED**
MATERIAL QUANTITY: **0** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Material was not observed - 2013 3 years re-inspection

Management Planner's Signature: _____



Date: 04/18/2013

Chicago Public Schools

Carnow, Conibear and Associates 2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **30031** BUIDLING ID: **2780**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Jesus Delgado**
SCHOOL NAME: **Christopher School** INSPECTION DATE: **3/18/2013**
ADDRESS: **5042 S. Artesian** IDPH LICENSE NO: **100-11170**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **008 B**
MATERIAL DESCRIPTION: **Linoleum (Lt Brown Patterned)**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **HIGH**
MATERIAL LOCATION: **Women's Washroom**
MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **30031** BUIDLING ID: **2780**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Christopher School** REVIEW DATE: **4/18/2013**
ADDRESS: **5042 S. Artesian** IDPH LICENSE NO: **100-11170**

HOMOGENEOUS AREA: **008 B**

MATERIAL DESCRIPTION: **Linoleum (Lt Brown Patterned)**

MATERIAL LOCATION: **Women's Washroom**

MATERIAL QUANTITY: **100**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **04/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **30031** BUIDLING ID: **2780**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Jesus Delgado**
SCHOOL NAME: **Christopher School** INSPECTION DATE: **3/18/2013**
ADDRESS: **5042 S. Artesian** IDPH LICENSE NO: **100-11170**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **008 C**
MATERIAL DESCRIPTION: **Beige Patterned Linoleum**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **HIGH**
MATERIAL LOCATION: **Physical Therapy Room**
MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **30031** BUIDLING ID: **2780**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Christopher School** REVIEW DATE: **4/18/2013**
ADDRESS: **5042 S. Artesian** IDPH LICENSE NO: **100-11170**

HOMOGENEOUS AREA: **008 C**
MATERIAL DESCRIPTION: **Beige Patterned Linoleum**
MATERIAL LOCATION: **Physical Therapy Room**
MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **04/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **30031** BUIDLING ID: **2780**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Jesus Delgado**
SCHOOL NAME: **Christopher School** INSPECTION DATE: **3/18/2013**
ADDRESS: **5042 S. Artesian** IDPH LICENSE NO: **100-11170**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **008 D**
MATERIAL DESCRIPTION: **Linoleum (Yellow Patterned)**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **HIGH**

MATERIAL LOCATION: **Washroom Across From Office**

MATERIAL QUANTITY: **100**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **30031** BUIDLING ID: **2780**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Christopher School** REVIEW DATE: **4/18/2013**
ADDRESS: **5042 S. Artesian** IDPH LICENSE NO: **100-11170**

HOMOGENEOUS AREA: **008 D**
MATERIAL DESCRIPTION: **Linoleum (Yellow Patterned)**
MATERIAL LOCATION: **Washroom Across From Office**
MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **04/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **30031** BUIDLING ID: **2780**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Jesus Delgado**
SCHOOL NAME: **Christopher School** INSPECTION DATE: **3/18/2013**
ADDRESS: **5042 S. Artesian** IDPH LICENSE NO: **100-11170**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **009**
MATERIAL DESCRIPTION: **12" x 12" Ceiling Tiles**
HISTORICAL AHERA DAMAGE CATEGORY **6**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Assembly Hall on Walls**

MATERIAL QUANTITY: **80**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **30031** BUIDLING ID: **2780**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Christopher School** REVIEW DATE: **4/18/2013**
ADDRESS: **5042 S. Artesian** IDPH LICENSE NO: **100-11170**

HOMOGENEOUS AREA: **009**
MATERIAL DESCRIPTION: **12" x 12" Ceiling Tiles**
MATERIAL LOCATION: **Assembly Hall on Walls**
MATERIAL QUANTITY: **80** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **04/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates 2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **30031** BUIDLING ID: **2780**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Jesus Delgado**
SCHOOL NAME: **Christopher School** INSPECTION DATE: **3/18/2013**
ADDRESS: **5042 S. Artesian** IDPH LICENSE NO: **100-11170**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **01**
MATERIAL DESCRIPTION: **Hard Coat Plaster**
HISTORICAL AHERA DAMAGE CATEGORY **6**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Throughout**
MATERIAL QUANTITY: **100000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **30031** BUIDLING ID: **2780**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Christopher School** REVIEW DATE: **4/18/2013**
ADDRESS: **5042 S. Artesian** IDPH LICENSE NO: **100-11170**

HOMOGENEOUS AREA: **01**
MATERIAL DESCRIPTION: **Hard Coat Plaster**
MATERIAL LOCATION: **Throughout**
MATERIAL QUANTITY: **100000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **04/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **30031** BUIDLING ID: **2780**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Jesus Delgado**
SCHOOL NAME: **Christopher School** INSPECTION DATE: **3/18/2013**
ADDRESS: **5042 S. Artesian** IDPH LICENSE NO: **100-11170**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **010**
MATERIAL DESCRIPTION: **Block**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY:


MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **03/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **30031** BUIDLING ID: **2780**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Christopher School** REVIEW DATE: **4/18/2013**
ADDRESS: **5042 S. Artesian** IDPH LICENSE NO: **100-11170**

HOMOGENEOUS AREA: **010**

MATERIAL DESCRIPTION: **Block**

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **04/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **30031** BUIDLING ID: **2780**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Jesus Delgado**
SCHOOL NAME: **Christopher School** INSPECTION DATE: **3/18/2013**
ADDRESS: **5042 S. Artesian** IDPH LICENSE NO: **100-11170**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **011**
MATERIAL DESCRIPTION: **Block Mortar**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Boiler Room**
MATERIAL QUANTITY: **250** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **30031** BUIDLING ID: **2780**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Christopher School** REVIEW DATE: **4/18/2013**
ADDRESS: **5042 S. Artesian** IDPH LICENSE NO: **100-11170**

HOMOGENEOUS AREA: **011**
MATERIAL DESCRIPTION: **Block Mortar**
MATERIAL LOCATION: **Boiler Room**
MATERIAL QUANTITY: **250** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **04/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates 2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **30031** BUILDING ID: **2780**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Jesus Delgado**
SCHOOL NAME: **Christopher School** INSPECTION DATE: **3/18/2013**
ADDRESS: **5042 S. Artesian** IDPH LICENSE NO: **100-11170**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **012**
MATERIAL DESCRIPTION: **9"x9" Dark Brown FT w/ Red & White Streaks Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Computer Room, Science Room (125-A), Office, Principal's Office, Rooms 133, 135**

MATERIAL QUANTITY: **2500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS: **Not observed in 124A and computer room**

Inspector's Signature:



Date: **03/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **30031** BUIDLING ID: **2780**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Christopher School** REVIEW DATE: **4/18/2013**
ADDRESS: **5042 S. Artesian** IDPH LICENSE NO: **100-11170**

HOMOGENEOUS AREA: **012**
MATERIAL DESCRIPTION: **9"x9" Dark Brown FT w/ Red & White Streaks Mastic**
MATERIAL LOCATION: **Computer Room, Science Room (125-A), Office, Principal's Office, Rooms 133, 135**
MATERIAL QUANTITY: **2500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Not observed in 124A and computer room

Management Planner's Signature: _____



Date: 04/18/2013

Chicago Public Schools

Carnow, Conibear and Associates 2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **30031** BUIDLING ID: **2780**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Jesus Delgado**
SCHOOL NAME: **Christopher School** INSPECTION DATE: **3/18/2013**
ADDRESS: **5042 S. Artesian** IDPH LICENSE NO: **100-11170**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **013**
MATERIAL DESCRIPTION: **9" x 9" Light Brown FT w/Dk Brown Streaks Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Science Lab and Office**

MATERIAL QUANTITY: **1000**


MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **30031** BUIDLING ID: **2780**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Christopher School** REVIEW DATE: **4/18/2013**
ADDRESS: **5042 S. Artesian** IDPH LICENSE NO: **100-11170**

HOMOGENEOUS AREA: **013**
MATERIAL DESCRIPTION: **9" x 9" Light Brown FT w/Dk Brown Streaks Mastic**
MATERIAL LOCATION: **Science Lab and Office**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **04/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **30031** BUIDLING ID: **2780**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Jesus Delgado**
SCHOOL NAME: **Christopher School** INSPECTION DATE: **3/18/2013**
ADDRESS: **5042 S. Artesian** IDPH LICENSE NO: **100-11170**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **014**
MATERIAL DESCRIPTION: **9" x 9" Black Floor Tile w/White Streaks Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Rooms 104, 106, 116, 117, 125-A, Hall, Speech and as Patches in the Cafeteria, Science Lab**

MATERIAL QUANTITY: **1000**


MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS: **Not observed in 124A and caferia**

Inspector's Signature:



Date: **03/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **30031** BUIDLING ID: **2780**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Christopher School** REVIEW DATE: **4/18/2013**
ADDRESS: **5042 S. Artesian** IDPH LICENSE NO: **100-11170**

HOMOGENEOUS AREA: **014**
MATERIAL DESCRIPTION: **9" x 9" Black Floor Tile w/White Streaks Mastic**
MATERIAL LOCATION: **Rooms 104, 106, 116, 117, 125-A, Hall, Speech and as Patches in the Cafeteria, Science Lab**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Not observed in 124A and caferia

Management Planner's Signature: _____



Date: **04/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **30031** BUIDLING ID: **2780**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Jesus Delgado**
SCHOOL NAME: **Christopher School** INSPECTION DATE: **3/18/2013**
ADDRESS: **5042 S. Artesian** IDPH LICENSE NO: **100-11170**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **015**
MATERIAL DESCRIPTION: **9" x 9" Lt Brown FT w/White Streaks Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Hallways on 1st Floor**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **30031** BUIDLING ID: **2780**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Christopher School** REVIEW DATE: **4/18/2013**
ADDRESS: **5042 S. Artesian** IDPH LICENSE NO: **100-11170**

HOMOGENEOUS AREA: **015**
MATERIAL DESCRIPTION: **9" x 9" Lt Brown FT w/White Streaks Mastic**
MATERIAL LOCATION: **Hallways on 1st Floor**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **04/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **30031** BUIDLING ID: **2780**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Jesus Delgado**
SCHOOL NAME: **Christopher School** INSPECTION DATE: **3/18/2013**
ADDRESS: **5042 S. Artesian** IDPH LICENSE NO: **100-11170**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **016**
MATERIAL DESCRIPTION: **9" x 9" Green FT w/White Streaks Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Hallways on 1st Floor**

MATERIAL QUANTITY: **1000**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **30031** BUIDLING ID: **2780**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Christopher School** REVIEW DATE: **4/18/2013**
ADDRESS: **5042 S. Artesian** IDPH LICENSE NO: **100-11170**

HOMOGENEOUS AREA: **016**
MATERIAL DESCRIPTION: **9" x 9" Green FT w/White Streaks Mastic**
MATERIAL LOCATION: **Hallways on 1st Floor**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **04/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates 2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **30031** BUIDLING ID: **2780**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Jesus Delgado**
SCHOOL NAME: **Christopher School** INSPECTION DATE: **3/18/2013**
ADDRESS: **5042 S. Artesian** IDPH LICENSE NO: **100-11170**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **017**
MATERIAL DESCRIPTION: **9"x9" Gray w/Red,Yel, Blue & White Dots FT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Rooms 116, 117 and 125/127**

MATERIAL QUANTITY: **1400**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS: **Not observed in 124/127**

Inspector's Signature:



Date: **03/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **30031** BUIDLING ID: **2780**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Christopher School** REVIEW DATE: **4/18/2013**
ADDRESS: **5042 S. Artesian** IDPH LICENSE NO: **100-11170**

HOMOGENEOUS AREA: **017**
MATERIAL DESCRIPTION: **9"x9" Gray w/Red,Yel, Blue & White Dots FT Mastic**
MATERIAL LOCATION: **Rooms 116, 117 and 125/127**
MATERIAL QUANTITY: **1400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Not observed in 124/127

Management Planner's Signature: _____



Date: **04/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **30031** BUIDLING ID: **2780**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Jesus Delgado**
SCHOOL NAME: **Christopher School** INSPECTION DATE: **3/18/2013**
ADDRESS: **5042 S. Artesian** IDPH LICENSE NO: **100-11170**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **018**
MATERIAL DESCRIPTION: **9" x 9" Red w/White Streaks Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms 104 and 129 and Hallways on 1st Floor**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **30031** BUIDLING ID: **2780**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Christopher School** REVIEW DATE: **4/18/2013**
ADDRESS: **5042 S. Artesian** IDPH LICENSE NO: **100-11170**

HOMOGENEOUS AREA: **018**
MATERIAL DESCRIPTION: **9" x 9" Red w/White Streaks Floor Tile Mastic**
MATERIAL LOCATION: **Rooms 104 and 129 and Hallways on 1st Floor**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **04/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **30031** BUIDLING ID: **2780**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Jesus Delgado**
SCHOOL NAME: **Christopher School** INSPECTION DATE: **3/18/2013**
ADDRESS: **5042 S. Artesian** IDPH LICENSE NO: **100-11170**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **019**
MATERIAL DESCRIPTION: **9"x9" Lt Brn w/Blue, Red, Yel, & Wh Dots FT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **Low**

MATERIAL LOCATION: **Room123**

MATERIAL QUANTITY: **1400**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS: **Material was not observed - 2013 3 years re-inspection**

Inspector's Signature:



Date: **03/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **30031** BUIDLING ID: **2780**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Christopher School** REVIEW DATE: **4/18/2013**
ADDRESS: **5042 S. Artesian** IDPH LICENSE NO: **100-11170**

HOMOGENEOUS AREA: **019**
MATERIAL DESCRIPTION: **9"x9" Lt Brn w/Blue, Red, Yel, & Wh Dots FT Mastic**
MATERIAL LOCATION: **Room123**
MATERIAL QUANTITY: **1400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Material was not observed - 2013 3 years re-inspection

Management Planner's Signature: _____



Date: **04/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates 2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **30031** BUIDLING ID: **2780**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Jesus Delgado**
SCHOOL NAME: **Christopher School** INSPECTION DATE: **3/18/2013**
ADDRESS: **5042 S. Artesian** IDPH LICENSE NO: **100-11170**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **020**
MATERIAL DESCRIPTION: **9" x 9" Light Brown w/Brn & Wh Streaks FT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT


This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms 122, 123, 126 and as Patches in the Cafeteria**
MATERIAL QUANTITY: **20** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS: **Not observed in caferia**

Inspector's Signature:



Date: **03/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **30031** BUIDLING ID: **2780**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Christopher School** REVIEW DATE: **4/18/2013**
ADDRESS: **5042 S. Artesian** IDPH LICENSE NO: **100-11170**

HOMOGENEOUS AREA: **020**
MATERIAL DESCRIPTION: **9" x 9" Light Brown w/Brn & Wh Streaks FT Mastic**
MATERIAL LOCATION: **Rooms 122, 123, 126 and as Patches in the Cafeteria**
MATERIAL QUANTITY: **20** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Not observed in caferia

Management Planner's Signature: _____



Date: 04/18/2013

Chicago Public Schools

Carnow, Conibear and Associates 2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **30031** BUIDLING ID: **2780**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Jesus Delgado**
SCHOOL NAME: **Christopher School** INSPECTION DATE: **3/18/2013**
ADDRESS: **5042 S. Artesian** IDPH LICENSE NO: **100-11170**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **021**
MATERIAL DESCRIPTION: **9" x 9" Light Brown Speckled Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**


MATERIAL LOCATION: **Computer Room, Speech, Cafeteria, 103-110, 124, 126-128, 129, Office, Teachers Lounge**

MATERIAL QUANTITY: **700** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS: **Not observed in 127, 128, 103, computer room, 110, 124, 126, caferia**

Inspector's Signature:



Date: **03/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **30031** BUIDLING ID: **2780**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Christopher School** REVIEW DATE: **4/18/2013**
ADDRESS: **5042 S. Artesian** IDPH LICENSE NO: **100-11170**

HOMOGENEOUS AREA: **021**
MATERIAL DESCRIPTION: **9" x 9" Light Brown Speckled Floor Tile Mastic**
MATERIAL LOCATION: **Computer Room, Speech, Cafeteria, 103-110, 124, 126-128, 129, Office, Teachers Lounge**
MATERIAL QUANTITY: **700** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Not observed in 127, 128, 103, computer room, 110, 124, 126, caferia

Management Planner's Signature: _____



Date: 04/18/2013

Chicago Public Schools

Carnow, Conibear and Associates 2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **30031** BUIDLING ID: **2780**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Jesus Delgado**
SCHOOL NAME: **Christopher School** INSPECTION DATE: **3/18/2013**
ADDRESS: **5042 S. Artesian** IDPH LICENSE NO: **100-11170**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **022**
MATERIAL DESCRIPTION: **9" x 9" Medium Brown Speckled Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**


MATERIAL LOCATION: **103-109, 124, 126, 127, 129, Technology, Speech, Office, T. Lounge, Social Worker, Physical Therapy**

MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS: **Not observed in teach, 103, 105, 109**

Inspector's Signature:



Date: **03/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **30031** BUIDLING ID: **2780**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Christopher School** REVIEW DATE: **4/18/2013**
ADDRESS: **5042 S. Artesian** IDPH LICENSE NO: **100-11170**

HOMOGENEOUS AREA: **022**
MATERIAL DESCRIPTION: **9" x 9" Medium Brown Speckled Floor Tile Mastic**
MATERIAL LOCATION: **103-109, 124, 126, 127, 129, Technology, Speech, Office, T. Lounge, Social Worker, Physical Therapy**
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Not observed in teach, 103, 105, 109

Management Planner's Signature: _____



Date: 04/18/2013

Chicago Public Schools

Carnow, Conibear and Associates 2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **30031** BUIDLING ID: **2780**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Jesus Delgado**
SCHOOL NAME: **Christopher School** INSPECTION DATE: **3/18/2013**
ADDRESS: **5042 S. Artesian** IDPH LICENSE NO: **100-11170**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **023**
MATERIAL DESCRIPTION: **9" x 9" Dark Brown Speckled Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**


MATERIAL LOCATION: **103-109, 124, 126, 127, 129, Technology, Speech, Office, T. Lounge, Social Worker, Physical Therapy**

MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS: **not observed in 127, teacher lounge, 103, 105, 109, Tech.**

Inspector's Signature:



Date: **03/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **30031** BUIDLING ID: **2780**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Christopher School** REVIEW DATE: **4/18/2013**
ADDRESS: **5042 S. Artesian** IDPH LICENSE NO: **100-11170**

HOMOGENEOUS AREA: **023**
MATERIAL DESCRIPTION: **9" x 9" Dark Brown Speckled Floor Tile Mastic**
MATERIAL LOCATION: **103-109, 124, 126, 127, 129, Technology, Speech, Office, T. Lounge, Social Worker, Physical Therapy**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

not observed in 127, teacher lounge, 103, 105, 109, Tech.

Management Planner's Signature: _____



Date: 04/18/2013

Chicago Public Schools

Carnow, Conibear and Associates 2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **30031** BUIDLING ID: **2780**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Jesus Delgado**
SCHOOL NAME: **Christopher School** INSPECTION DATE: **3/18/2013**
ADDRESS: **5042 S. Artesian** IDPH LICENSE NO: **100-11170**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **024**
MATERIAL DESCRIPTION: **9" x 9" Lt Brn w/Dk Brown & White Spots FT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT


This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms 113, 115, 122, 123, 126 and Women's Teacher's Lounge**
MATERIAL QUANTITY: **700** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS: **Not observed in 113, 115, 122, 123, 126**

Inspector's Signature:



Date: **03/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **30031** BUIDLING ID: **2780**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Christopher School** REVIEW DATE: **4/18/2013**
ADDRESS: **5042 S. Artesian** IDPH LICENSE NO: **100-11170**

HOMOGENEOUS AREA: **024**
MATERIAL DESCRIPTION: **9" x 9" Lt Brn w/Dk Brown & White Spots FT Mastic**
MATERIAL LOCATION: **Rooms 113, 115, 122, 123, 126 and Women's Teacher's Lounge**
MATERIAL QUANTITY: **700** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Not observed in 113, 115, 122, 123, 126

Management Planner's Signature: _____



Date: 04/18/2013

Chicago Public Schools

Carnow, Conibear and Associates 2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **30031** BUIDLING ID: **2780**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Jesus Delgado**
SCHOOL NAME: **Christopher School** INSPECTION DATE: **3/18/2013**
ADDRESS: **5042 S. Artesian** IDPH LICENSE NO: **100-11170**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **025**
MATERIAL DESCRIPTION: **9" x 9" Beige w/Brown & White Streaks FT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Rooms 103, 122, and 126, 133, 135 Office, Physical Therapy, Cafeteria, and Hallways**

MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS: **Not observed in caferia, 103.**

Inspector's Signature:



Date: **03/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **30031** BUIDLING ID: **2780**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Christopher School** REVIEW DATE: **4/18/2013**
ADDRESS: **5042 S. Artesian** IDPH LICENSE NO: **100-11170**

HOMOGENEOUS AREA: **025**
MATERIAL DESCRIPTION: **9" x 9" Beige w/Brown & White Streaks FT Mastic**
MATERIAL LOCATION: **Rooms 103, 122, and 126, 133, 135 Office, Physical Therapy, Cafeteria, and Hallways**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Not observed in caferia, 103.

Management Planner's Signature: _____



Date: 04/18/2013

Chicago Public Schools

Carnow, Conibear and Associates 2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **30031** BUIDLING ID: **2780**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Jesus Delgado**
SCHOOL NAME: **Christopher School** INSPECTION DATE: **3/18/2013**
ADDRESS: **5042 S. Artesian** IDPH LICENSE NO: **100-11170**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **026**
MATERIAL DESCRIPTION: **9" x 9" Rusty Brown Speckled Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms 103, 104, 124, and 126, Technology Room and the Cafeteria**
MATERIAL QUANTITY: **150** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS: **Not observed in caferia, tech room, 103**

Inspector's Signature:



Date: **03/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **30031** BUIDLING ID: **2780**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Christopher School** REVIEW DATE: **4/18/2013**
ADDRESS: **5042 S. Artesian** IDPH LICENSE NO: **100-11170**

HOMOGENEOUS AREA: **026**
MATERIAL DESCRIPTION: **9" x 9" Rusty Brown Speckled Floor Tile Mastic**
MATERIAL LOCATION: **Rooms 103, 104, 124, and 126, Technology Room and the Cafeteria**
MATERIAL QUANTITY: **150** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Not observed in caferia, tech room, 103

Management Planner's Signature: _____



Date: **04/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates 2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **30031** BUIDLING ID: **2780**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Jesus Delgado**
SCHOOL NAME: **Christopher School** INSPECTION DATE: **3/18/2013**
ADDRESS: **5042 S. Artesian** IDPH LICENSE NO: **100-11170**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **027**
MATERIAL DESCRIPTION: **9" x 9" White w/Black Streaks Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **Low**

MATERIAL LOCATION: **Kitchen**

MATERIAL QUANTITY: **800**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS: **Material was not observed - 2013 3 years re-inspection**

Inspector's Signature:



Date: **03/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **30031** BUIDLING ID: **2780**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Christopher School** REVIEW DATE: **4/18/2013**
ADDRESS: **5042 S. Artesian** IDPH LICENSE NO: **100-11170**

HOMOGENEOUS AREA: **027**
MATERIAL DESCRIPTION: **9" x 9" White w/Black Streaks Floor Tile Mastic**
MATERIAL LOCATION: **Kitchen**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Material was not observed - 2013 3 years re-inspection

Management Planner's Signature: _____



Date: **04/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **30031** BUIDLING ID: **2780**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Jesus Delgado**
SCHOOL NAME: **Christopher School** INSPECTION DATE: **3/18/2013**
ADDRESS: **5042 S. Artesian** IDPH LICENSE NO: **100-11170**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **028**
MATERIAL DESCRIPTION: **9" x 9" Gray Floor Tile w/Brn & Wh Streaks Mastic**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:


MATERIAL LOCATION: **Room 128-(Number Has Been Changed From 130)**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Material was not observed - 2013 3 years re-inspection**

Inspector's Signature:



Date: **03/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **30031** BUIDLING ID: **2780**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Christopher School** REVIEW DATE: **4/18/2013**
ADDRESS: **5042 S. Artesian** IDPH LICENSE NO: **100-11170**

HOMOGENEOUS AREA: **028**
MATERIAL DESCRIPTION: **9" x 9" Gray Floor Tile w/Brn & Wh Streaks Mastic**
MATERIAL LOCATION: **Room 128-(Number Has Been Changed From 130)**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Material was not observed - 2013 3 years re-inspection

Management Planner's Signature: _____



Date: **04/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **30031** BUIDLING ID: **2780**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Jesus Delgado**
SCHOOL NAME: **Christopher School** INSPECTION DATE: **3/18/2013**
ADDRESS: **5042 S. Artesian** IDPH LICENSE NO: **100-11170**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **029**
MATERIAL DESCRIPTION: **9"x9" Lt. Brn FT w/Dark Brown & White Spots Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **Low**

MATERIAL LOCATION: **Room 113**

MATERIAL QUANTITY: **700**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS: **Material was not observed - 2013 3 years re-inspection**

Inspector's Signature:



Date: **03/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **30031** BUIDLING ID: **2780**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Christopher School** REVIEW DATE: **4/18/2013**
ADDRESS: **5042 S. Artesian** IDPH LICENSE NO: **100-11170**

HOMOGENEOUS AREA: **029**
MATERIAL DESCRIPTION: **9"x9" Lt. Brn FT w/Dark Brown & White Spots Mastic**
MATERIAL LOCATION: **Room 113**
MATERIAL QUANTITY: **700** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Material was not observed - 2013 3 years re-inspection

Management Planner's Signature: _____



Date: **04/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **30031** BUIDLING ID: **2780**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Jesus Delgado**
SCHOOL NAME: **Christopher School** INSPECTION DATE: **3/18/2013**
ADDRESS: **5042 S. Artesian** IDPH LICENSE NO: **100-11170**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **030**
MATERIAL DESCRIPTION: **12"x12" Lt Brn FT w/ Gry, Blu, & Rust Strks Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Custodian's Lounge**

MATERIAL QUANTITY: **200**


MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **30031** BUIDLING ID: **2780**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Christopher School** REVIEW DATE: **4/18/2013**
ADDRESS: **5042 S. Artesian** IDPH LICENSE NO: **100-11170**

HOMOGENEOUS AREA: **030**
MATERIAL DESCRIPTION: **12"x12" Lt Brn FT w/ Gry, Blu, & Rust Strks Mastic**
MATERIAL LOCATION: **Custodian's Lounge**
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **04/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates 2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **30031** BUIDLING ID: **2780**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Jesus Delgado**
SCHOOL NAME: **Christopher School** INSPECTION DATE: **3/18/2013**
ADDRESS: **5042 S. Artesian** IDPH LICENSE NO: **100-11170**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **031**
MATERIAL DESCRIPTION: **12" x 12" Beige FT w/ Wh & Brown Streaks Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Assembly Hall**
MATERIAL QUANTITY: **1600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **30031** BUIDLING ID: **2780**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Christopher School** REVIEW DATE: **4/18/2013**
ADDRESS: **5042 S. Artesian** IDPH LICENSE NO: **100-11170**

HOMOGENEOUS AREA: **031**
MATERIAL DESCRIPTION: **12" x 12" Beige FT w/ Wh & Brown Streaks Mastic**
MATERIAL LOCATION: **Assembly Hall**
MATERIAL QUANTITY: **1600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **04/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates 2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **30031** BUIDLING ID: **2780**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Jesus Delgado**
SCHOOL NAME: **Christopher School** INSPECTION DATE: **3/18/2013**
ADDRESS: **5042 S. Artesian** IDPH LICENSE NO: **100-11170**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **032**
MATERIAL DESCRIPTION: **12" x 12" Black Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **Low**

MATERIAL LOCATION: **Room 123**

MATERIAL QUANTITY: **600**


MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS: **Material was not observed - 2013 3 years re-inspection**

Inspector's Signature:



Date: **03/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **30031** BUIDLING ID: **2780**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Christopher School** REVIEW DATE: **4/18/2013**
ADDRESS: **5042 S. Artesian** IDPH LICENSE NO: **100-11170**

HOMOGENEOUS AREA: **032**
MATERIAL DESCRIPTION: **12" x 12" Black Floor Tile Mastic**
MATERIAL LOCATION: **Room 123**
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Material was not observed - 2013 3 years re-inspection

Management Planner's Signature: _____



Date: **04/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **30031** BUIDLING ID: **2780**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Jesus Delgado**
SCHOOL NAME: **Christopher School** INSPECTION DATE: **3/18/2013**
ADDRESS: **5042 S. Artesian** IDPH LICENSE NO: **100-11170**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **033**
MATERIAL DESCRIPTION: **12" x 12" Black Floor Tile w/ White Streaks Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **Low**

MATERIAL LOCATION: **Speech, Entrance by 127, Room 126**

MATERIAL QUANTITY: **200**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS: **Material was not observed - 2013 3 years re-inspection**

Inspector's Signature:



Date: **03/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **30031** BUIDLING ID: **2780**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Christopher School** REVIEW DATE: **4/18/2013**
ADDRESS: **5042 S. Artesian** IDPH LICENSE NO: **100-11170**

HOMOGENEOUS AREA: **033**
MATERIAL DESCRIPTION: **12" x 12" Black Floor Tile w/ White Streaks Mastic**
MATERIAL LOCATION: **Speech, Entrance by 127, Room 126**
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Material was not observed - 2013 3 years re-inspection

Management Planner's Signature: _____



Date: **04/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates 2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **30031** BUIDLING ID: **2780**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Jesus Delgado**
SCHOOL NAME: **Christopher School** INSPECTION DATE: **3/18/2013**
ADDRESS: **5042 S. Artesian** IDPH LICENSE NO: **100-11170**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **034**
MATERIAL DESCRIPTION: **12" x 12" Black Floor Tile w/White Specks Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Speech, Cafeteria, Assembly Hall**

MATERIAL QUANTITY: **350**


MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS: **Not observed in caferia**

Inspector's Signature:



Date: **03/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **30031** BUIDLING ID: **2780**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Christopher School** REVIEW DATE: **4/18/2013**
ADDRESS: **5042 S. Artesian** IDPH LICENSE NO: **100-11170**

HOMOGENEOUS AREA: **034**
MATERIAL DESCRIPTION: **12" x 12" Black Floor Tile w/White Specks Mastic**
MATERIAL LOCATION: **Speech, Cafeteria, Assembly Hall**
MATERIAL QUANTITY: **350** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Not observed in caferia

Management Planner's Signature: _____



Date: **04/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **30031** BUIDLING ID: **2780**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Jesus Delgado**
SCHOOL NAME: **Christopher School** INSPECTION DATE: **3/18/2013**
ADDRESS: **5042 S. Artesian** IDPH LICENSE NO: **100-11170**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **035**
MATERIAL DESCRIPTION: **12" x 12" White Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Speech, Teacher's Lounge**

MATERIAL QUANTITY: **100**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS: **Not observed in teacher lounge**

Inspector's Signature:



Date: **03/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **30031** BUIDLING ID: **2780**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Christopher School** REVIEW DATE: **4/18/2013**
ADDRESS: **5042 S. Artesian** IDPH LICENSE NO: **100-11170**

HOMOGENEOUS AREA: **035**
MATERIAL DESCRIPTION: **12" x 12" White Floor Tile Mastic**
MATERIAL LOCATION: **Speech, Teacher's Lounge**
MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Not observed in teacher lounge

Management Planner's Signature: _____



Date: 04/18/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **30031** BUIDLING ID: **2780**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Jesus Delgado**
SCHOOL NAME: **Christopher School** INSPECTION DATE: **3/18/2013**
ADDRESS: **5042 S. Artesian** IDPH LICENSE NO: **100-11170**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **036**
MATERIAL DESCRIPTION: **12"x12" Dark Gray FT w/Brown & White Strks Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **Low**

MATERIAL LOCATION: **Cafeteria**

MATERIAL QUANTITY: **25**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS: **Material was not observed - 2013 3 years re-inspection**

Inspector's Signature:



Date: **03/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **30031** BUIDLING ID: **2780**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Christopher School** REVIEW DATE: **4/18/2013**
ADDRESS: **5042 S. Artesian** IDPH LICENSE NO: **100-11170**

HOMOGENEOUS AREA: **036**
MATERIAL DESCRIPTION: **12"x12" Dark Gray FT w/Brown & White Strks Mastic**
MATERIAL LOCATION: **Cafeteria**
MATERIAL QUANTITY: **25** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Material was not observed - 2013 3 years re-inspection

Management Planner's Signature: _____



Date: **04/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **30031** BUIDLING ID: **2780**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Jesus Delgado**
SCHOOL NAME: **Christopher School** INSPECTION DATE: **3/18/2013**
ADDRESS: **5042 S. Artesian** IDPH LICENSE NO: **100-11170**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **037**
MATERIAL DESCRIPTION: **12" x 12" Light Gray FT w/White Streaks Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **Low**

MATERIAL LOCATION: **Cafeteria**

MATERIAL QUANTITY: **100**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS: **Material was not observed - 2013 3 years re-inspection**

Inspector's Signature:



Date: **03/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **30031** BUIDLING ID: **2780**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Christopher School** REVIEW DATE: **4/18/2013**
ADDRESS: **5042 S. Artesian** IDPH LICENSE NO: **100-11170**

HOMOGENEOUS AREA: **037**
MATERIAL DESCRIPTION: **12" x 12" Light Gray FT w/White Streaks Mastic**
MATERIAL LOCATION: **Cafeteria**
MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Material was not observed - 2013 3 years re-inspection

Management Planner's Signature: _____



Date: **04/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates 2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **30031** BUIDLING ID: **2780**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Jesus Delgado**
SCHOOL NAME: **Christopher School** INSPECTION DATE: **3/18/2013**
ADDRESS: **5042 S. Artesian** IDPH LICENSE NO: **100-11170**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **038**
MATERIAL DESCRIPTION: **12" x 12" Off-White FT w/Brown Speckles Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **Low**

MATERIAL LOCATION: **Cafeteria, Boy's Washroom, Room 108**

MATERIAL QUANTITY: **500**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS: **Material was not observed - 2013 3 years re-inspection**

Inspector's Signature:



Date: **03/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **30031** BUIDLING ID: **2780**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Christopher School** REVIEW DATE: **4/18/2013**
ADDRESS: **5042 S. Artesian** IDPH LICENSE NO: **100-11170**

HOMOGENEOUS AREA: **038**
MATERIAL DESCRIPTION: **12" x 12" Off-White FT w/Brown Speckles Mastic**
MATERIAL LOCATION: **Cafeteria, Boy's Washroom, Room 108**
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Material was not observed - 2013 3 years re-inspection

Management Planner's Signature: _____



Date: **04/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates 2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **30031** BUIDLING ID: **2780**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Jesus Delgado**
SCHOOL NAME: **Christopher School** INSPECTION DATE: **3/18/2013**
ADDRESS: **5042 S. Artesian** IDPH LICENSE NO: **100-11170**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **039**
MATERIAL DESCRIPTION: **12"x12" Cream Floor Tile w/(Lt) Brown & Gray Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Girl's and Boy's Locker Room, Pool Office**

MATERIAL QUANTITY: **300**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **30031** BUIDLING ID: **2780**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Christopher School** REVIEW DATE: **4/18/2013**
ADDRESS: **5042 S. Artesian** IDPH LICENSE NO: **100-11170**

HOMOGENEOUS AREA: **039**
MATERIAL DESCRIPTION: **12"x12"Cream Floor Tile w/(Lt) Brown & Gray Mastic**
MATERIAL LOCATION: **Girl's and Boy's Locker Room, Pool Office**
MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **04/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **30031** BUIDLING ID: **2780**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Jesus Delgado**
SCHOOL NAME: **Christopher School** INSPECTION DATE: **3/18/2013**
ADDRESS: **5042 S. Artesian** IDPH LICENSE NO: **100-11170**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **040**
MATERIAL DESCRIPTION: **12" x 12" Cream Floor Tile w/Brown & Gray Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Girl's and Boy's Locker Room, Pool Office**

MATERIAL QUANTITY: **300**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **30031** BUIDLING ID: **2780**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Christopher School** REVIEW DATE: **4/18/2013**
ADDRESS: **5042 S. Artesian** IDPH LICENSE NO: **100-11170**

HOMOGENEOUS AREA: **040**
MATERIAL DESCRIPTION: **12" x 12" Cream Floor Tile w/Brown & Gray Mastic**
MATERIAL LOCATION: **Girl's and Boy's Locker Room, Pool Office**
MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **04/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **30031** BUIDLING ID: **2780**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Jesus Delgado**
SCHOOL NAME: **Christopher School** INSPECTION DATE: **3/18/2013**
ADDRESS: **5042 S. Artesian** IDPH LICENSE NO: **100-11170**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **041**
MATERIAL DESCRIPTION: **Interior Brick Mortar**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **03/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **30031** BUIDLING ID: **2780**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Christopher School** REVIEW DATE: **4/18/2013**
ADDRESS: **5042 S. Artesian** IDPH LICENSE NO: **100-11170**

HOMOGENEOUS AREA: **041**

MATERIAL DESCRIPTION: **Interior Brick Mortar**

MATERIAL LOCATION: **Throughout Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **04/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **30031** BUILDING ID: **2780**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Jesus Delgado**
SCHOOL NAME: **Christopher School** INSPECTION DATE: **3/18/2013**
ADDRESS: **5042 S. Artesian** IDPH LICENSE NO: **100-11170**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **042**
MATERIAL DESCRIPTION: **Black Border Tiles**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **HIGH**
MATERIAL LOCATION: **Throughout Building halls on 1st Floor**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **30031** BUIDLING ID: **2780**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Christopher School** REVIEW DATE: **4/18/2013**
ADDRESS: **5042 S. Artesian** IDPH LICENSE NO: **100-11170**

HOMOGENEOUS AREA: **042**
MATERIAL DESCRIPTION: **Black Border Tiles**
MATERIAL LOCATION: **Throughout Building halls on 1st Floor**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **04/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **30031** BUIDLING ID: **2780**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Jesus Delgado**
SCHOOL NAME: **Christopher School** INSPECTION DATE: **3/18/2013**
ADDRESS: **5042 S. Artesian** IDPH LICENSE NO: **100-11170**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **043**
MATERIAL DESCRIPTION: **Black Border Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Throughout Building Halls on 1st Floor**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **30031** BUIDLING ID: **2780**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Christopher School** REVIEW DATE: **4/18/2013**
ADDRESS: **5042 S. Artesian** IDPH LICENSE NO: **100-11170**

HOMOGENEOUS AREA: **043**
MATERIAL DESCRIPTION: **Black Border Tile Mastic**
MATERIAL LOCATION: **Throughout Building Halls on 1st Floor**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: 04/18/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **30031** BUIDLING ID: **2780**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Jesus Delgado**
SCHOOL NAME: **Christopher School** INSPECTION DATE: **3/18/2013**
ADDRESS: **5042 S. Artesian** IDPH LICENSE NO: **100-11170**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **044**
MATERIAL DESCRIPTION: **Cinder Block - New Construction**
HISTORICAL AHERA DAMAGE CATEGORY **6**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Throughout Building**
MATERIAL QUANTITY: **4000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **30031** BUIDLING ID: **2780**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Christopher School** REVIEW DATE: **4/18/2013**
ADDRESS: **5042 S. Artesian** IDPH LICENSE NO: **100-11170**

HOMOGENEOUS AREA: **044**
MATERIAL DESCRIPTION: **Cinder Block - New Construction**
MATERIAL LOCATION: **Throughout Building**
MATERIAL QUANTITY: **4000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **04/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **30031** BUILDING ID: **2780**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Jesus Delgado**
SCHOOL NAME: **Christopher School** INSPECTION DATE: **3/18/2013**
ADDRESS: **5042 S. Artesian** IDPH LICENSE NO: **100-11170**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **045**
MATERIAL DESCRIPTION: **Cinder Block Mortar - New Construction**
HISTORICAL AHERA DAMAGE CATEGORY **6**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Throughout Building**
MATERIAL QUANTITY: **40000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature:



Date: **03/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **30031** BUIDLING ID: **2780**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Christopher School** REVIEW DATE: **4/18/2013**
ADDRESS: **5042 S. Artesian** IDPH LICENSE NO: **100-11170**

HOMOGENEOUS AREA: **045**
MATERIAL DESCRIPTION: **Cinder Block Mortar - New Construction**
MATERIAL LOCATION: **Throughout Building**
MATERIAL QUANTITY: **40000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **04/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **30031** BUIDLING ID: **2780**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Jesus Delgado**
SCHOOL NAME: **Christopher School** INSPECTION DATE: **3/18/2013**
ADDRESS: **5042 S. Artesian** IDPH LICENSE NO: **100-11170**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **046**
MATERIAL DESCRIPTION: **Rubber Flooring**
HISTORICAL AHERA DAMAGE CATEGORY **6**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Gym**
MATERIAL QUANTITY: **3550** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **30031** BUIDLING ID: **2780**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Christopher School** REVIEW DATE: **4/18/2013**
ADDRESS: **5042 S. Artesian** IDPH LICENSE NO: **100-11170**

HOMOGENEOUS AREA: **046**
MATERIAL DESCRIPTION: **Rubber Flooring**
MATERIAL LOCATION: **Gym**
MATERIAL QUANTITY: **3550** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **04/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **30031** BUIDLING ID: **2780**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Jesus Delgado**
SCHOOL NAME: **Christopher School** INSPECTION DATE: **3/18/2013**
ADDRESS: **5042 S. Artesian** IDPH LICENSE NO: **100-11170**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **047**
MATERIAL DESCRIPTION: **4" Black Baseboard**
HISTORICAL AHERA DAMAGE CATEGORY **6**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Gym, Boy's and Girl's Locker Room throughout**

MATERIAL QUANTITY: **1000**

MATERIAL UNITS: **LF**

DAMAGE QUANTITY:

DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature:



Date: **03/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **30031** BUIDLING ID: **2780**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Christopher School** REVIEW DATE: **4/18/2013**
ADDRESS: **5042 S. Artesian** IDPH LICENSE NO: **100-11170**

HOMOGENEOUS AREA: **047**
MATERIAL DESCRIPTION: **4" Black Baseboard**
MATERIAL LOCATION: **Gym, Boy's and Girl's Locker Room throughout**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **04/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **30031** BUIDLING ID: **2780**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Jesus Delgado**
SCHOOL NAME: **Christopher School** INSPECTION DATE: **3/18/2013**
ADDRESS: **5042 S. Artesian** IDPH LICENSE NO: **100-11170**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **048**
MATERIAL DESCRIPTION: **4" Black Baseboard Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Gym, Boy's and Girl's Locker Room Throughout**

MATERIAL QUANTITY: **1000**


MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **30031** BUIDLING ID: **2780**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Christopher School** REVIEW DATE: **4/18/2013**
ADDRESS: **5042 S. Artesian** IDPH LICENSE NO: **100-11170**

HOMOGENEOUS AREA: **048**
MATERIAL DESCRIPTION: **4" Black Baseboard Mastic**
MATERIAL LOCATION: **Gym, Boy's and Girl's Locker Room Throughout**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **04/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **30031** BUIDLING ID: **2780**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Jesus Delgado**
SCHOOL NAME: **Christopher School** INSPECTION DATE: **3/18/2013**
ADDRESS: **5042 S. Artesian** IDPH LICENSE NO: **100-11170**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **049**
MATERIAL DESCRIPTION: **6" Black Baseboard**
HISTORICAL AHERA DAMAGE CATEGORY **6**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Gym**
MATERIAL QUANTITY: **250** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature:



Date: **03/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **30031** BUIDLING ID: **2780**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Christopher School** REVIEW DATE: **4/18/2013**
ADDRESS: **5042 S. Artesian** IDPH LICENSE NO: **100-11170**

HOMOGENEOUS AREA: **049**
MATERIAL DESCRIPTION: **6" Black Baseboard**
MATERIAL LOCATION: **Gym**
MATERIAL QUANTITY: **250** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **04/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates 2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **30031** BUIDLING ID: **2780**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Jesus Delgado**
SCHOOL NAME: **Christopher School** INSPECTION DATE: **3/18/2013**
ADDRESS: **5042 S. Artesian** IDPH LICENSE NO: **100-11170**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **050**
MATERIAL DESCRIPTION: **6" Black Baseboard Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Gym**
MATERIAL QUANTITY: **250** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature:



Date: **03/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **30031** BUIDLING ID: **2780**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Christopher School** REVIEW DATE: **4/18/2013**
ADDRESS: **5042 S. Artesian** IDPH LICENSE NO: **100-11170**

HOMOGENEOUS AREA: **050**
MATERIAL DESCRIPTION: **6" Black Baseboard Mastic**
MATERIAL LOCATION: **Gym**
MATERIAL QUANTITY: **250** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **04/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **30031** BUIDLING ID: **2780**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Jesus Delgado**
SCHOOL NAME: **Christopher School** INSPECTION DATE: **3/18/2013**
ADDRESS: **5042 S. Artesian** IDPH LICENSE NO: **100-11170**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **051**
MATERIAL DESCRIPTION: **Spray-on Material**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Attic**

MATERIAL QUANTITY: **1250**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **30031** BUIDLING ID: **2780**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Christopher School** REVIEW DATE: **4/18/2013**
ADDRESS: **5042 S. Artesian** IDPH LICENSE NO: **100-11170**

HOMOGENEOUS AREA: **051**

MATERIAL DESCRIPTION: **Spray-on Material**

MATERIAL LOCATION: **Attic**

MATERIAL QUANTITY: **1250**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **04/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **30031** BUIDLING ID: **2780**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Jesus Delgado**
SCHOOL NAME: **Christopher School** INSPECTION DATE: **3/18/2013**
ADDRESS: **5042 S. Artesian** IDPH LICENSE NO: **100-11170**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **052**
MATERIAL DESCRIPTION: **Plaster**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Attic**

MATERIAL QUANTITY: **200000**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **30031** BUIDLING ID: **2780**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Christopher School** REVIEW DATE: **4/18/2013**
ADDRESS: **5042 S. Artesian** IDPH LICENSE NO: **100-11170**

HOMOGENEOUS AREA: **052**
MATERIAL DESCRIPTION: **Plaster**
MATERIAL LOCATION: **Attic**
MATERIAL QUANTITY: **200000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **04/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **30031** BUIDLING ID: **2780**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Jesus Delgado**
SCHOOL NAME: **Christopher School** INSPECTION DATE: **3/18/2013**
ADDRESS: **5042 S. Artesian** IDPH LICENSE NO: **100-11170**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **053**
MATERIAL DESCRIPTION: **Finished (Glazed) Brick Mortar**
HISTORICAL AHERA DAMAGE CATEGORY **6**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Throughout Building**
MATERIAL QUANTITY: **200000** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature:



Date: **03/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **30031** BUIDLING ID: **2780**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Christopher School** REVIEW DATE: **4/18/2013**
ADDRESS: **5042 S. Artesian** IDPH LICENSE NO: **100-11170**

HOMOGENEOUS AREA: **053**
MATERIAL DESCRIPTION: **Finished (Glazed) Brick Mortar**
MATERIAL LOCATION: **Throughout Building**
MATERIAL QUANTITY: **200000** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: 04/18/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **30031** BUIDLING ID: **2780**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Jesus Delgado**
SCHOOL NAME: **Christopher School** INSPECTION DATE: **3/18/2013**
ADDRESS: **5042 S. Artesian** IDPH LICENSE NO: **100-11170**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **054**
MATERIAL DESCRIPTION: **Terrazzo Wall Panels**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**


MATERIAL LOCATION: **Boys and Women's Washroom, Room 129**

MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS: **Material not observed in room 129**

Inspector's Signature:



Date: **03/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **30031** BUIDLING ID: **2780**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Christopher School** REVIEW DATE: **4/18/2013**
ADDRESS: **5042 S. Artesian** IDPH LICENSE NO: **100-11170**

HOMOGENEOUS AREA: **054**
MATERIAL DESCRIPTION: **Terrazzo Wall Panels**
MATERIAL LOCATION: **Boys and Women's Washroom, Room 129**
MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Material not observed in room 129

Management Planner's Signature: _____



Date: **04/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **30031** BUIDLING ID: **2780**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Jesus Delgado**
SCHOOL NAME: **Christopher School** INSPECTION DATE: **3/18/2013**
ADDRESS: **5042 S. Artesian** IDPH LICENSE NO: **100-11170**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **055**
MATERIAL DESCRIPTION: **Non-skid Strips**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Women's Washroom**
MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **30031** BUIDLING ID: **2780**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Christopher School** REVIEW DATE: **4/18/2013**
ADDRESS: **5042 S. Artesian** IDPH LICENSE NO: **100-11170**

HOMOGENEOUS AREA: **055**
MATERIAL DESCRIPTION: **Non-skid Strips**
MATERIAL LOCATION: **Women's Washroom**
MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **04/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **30031** BUIDLING ID: **2780**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Jesus Delgado**
SCHOOL NAME: **Christopher School** INSPECTION DATE: **3/18/2013**
ADDRESS: **5042 S. Artesian** IDPH LICENSE NO: **100-11170**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **056**
MATERIAL DESCRIPTION: **Exterior Brick - Not AHERA**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:


MATERIAL LOCATION: **Exterior of Building - Original Construction**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **03/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **30031** BUIDLING ID: **2780**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Christopher School** REVIEW DATE: **4/18/2013**
ADDRESS: **5042 S. Artesian** IDPH LICENSE NO: **100-11170**

HOMOGENEOUS AREA: **056**
MATERIAL DESCRIPTION: **Exterior Brick - Not AHERA**
MATERIAL LOCATION: **Exterior of Building - Original Construction**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **04/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **30031** BUIDLING ID: **2780**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Jesus Delgado**
SCHOOL NAME: **Christopher School** INSPECTION DATE: **3/18/2013**
ADDRESS: **5042 S. Artesian** IDPH LICENSE NO: **100-11170**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **057**
MATERIAL DESCRIPTION: **Exterior Brick Mortar - Not AHERA**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:


MATERIAL LOCATION: **Exterior of Building - Original Construction**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **03/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **30031** BUIDLING ID: **2780**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Christopher School** REVIEW DATE: **4/18/2013**
ADDRESS: **5042 S. Artesian** IDPH LICENSE NO: **100-11170**

HOMOGENEOUS AREA: **057**
MATERIAL DESCRIPTION: **Exterior Brick Mortar - Not AHERA**
MATERIAL LOCATION: **Exterior of Building - Original Construction**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **04/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates
2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **30031** BUIDLING ID: **2780**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Jesus Delgado**
SCHOOL NAME: **Christopher School** INSPECTION DATE: **3/18/2013**
ADDRESS: **5042 S. Artesian** IDPH LICENSE NO: **100-11170**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **058**
MATERIAL DESCRIPTION: **Exterior Door Caulk - Not AHERA)**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Chrysotile** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Exterior of All Doors in Original Construction**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Not AHERA**

Inspector's Signature:



Date: **03/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **30031** BUIDLING ID: **2780**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Christopher School** REVIEW DATE: **4/18/2013**
ADDRESS: **5042 S. Artesian** IDPH LICENSE NO: **100-11170**

HOMOGENEOUS AREA: **058**
MATERIAL DESCRIPTION: **Exterior Door Caulk - Not AHERA)**
MATERIAL LOCATION: **Exterior of All Doors in Original Construction**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **04/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **30031** BUIDLING ID: **2780**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Jesus Delgado**
SCHOOL NAME: **Christopher School** INSPECTION DATE: **3/18/2013**
ADDRESS: **5042 S. Artesian** IDPH LICENSE NO: **100-11170**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **059**
MATERIAL DESCRIPTION: **Cinder Block in Original Construction**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout Basement**

MATERIAL QUANTITY:


MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **03/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **30031** BUIDLING ID: **2780**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Christopher School** REVIEW DATE: **4/18/2013**
ADDRESS: **5042 S. Artesian** IDPH LICENSE NO: **100-11170**

HOMOGENEOUS AREA: **059**
MATERIAL DESCRIPTION: **Cinder Block in Original Construction**
MATERIAL LOCATION: **Throughout Basement**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **04/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **30031** BUIDLING ID: **2780**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Jesus Delgado**
SCHOOL NAME: **Christopher School** INSPECTION DATE: **3/18/2013**
ADDRESS: **5042 S. Artesian** IDPH LICENSE NO: **100-11170**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **060**
MATERIAL DESCRIPTION: **Cinderblock Mortar - Original Construction**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout Basement**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **03/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **30031** BUIDLING ID: **2780**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Christopher School** REVIEW DATE: **4/18/2013**
ADDRESS: **5042 S. Artesian** IDPH LICENSE NO: **100-11170**

HOMOGENEOUS AREA: **060**
MATERIAL DESCRIPTION: **Cinderblock Mortar - Original Construction**
MATERIAL LOCATION: **Throughout Basement**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **04/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **30031** BUIDLING ID: **2780**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Jesus Delgado**
SCHOOL NAME: **Christopher School** INSPECTION DATE: **3/18/2013**
ADDRESS: **5042 S. Artesian** IDPH LICENSE NO: **100-11170**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **061**
MATERIAL DESCRIPTION: **2' x 4' Ceiling Panels**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **03/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **30031** BUIDLING ID: **2780**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Christopher School** REVIEW DATE: **4/18/2013**
ADDRESS: **5042 S. Artesian** IDPH LICENSE NO: **100-11170**

HOMOGENEOUS AREA: **061**

MATERIAL DESCRIPTION: **2' x 4' Ceiling Panels**

MATERIAL LOCATION: **Throughout Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **04/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **30031** BUIDLING ID: **2780**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Jesus Delgado**
SCHOOL NAME: **Christopher School** INSPECTION DATE: **3/18/2013**
ADDRESS: **5042 S. Artesian** IDPH LICENSE NO: **100-11170**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **062**
MATERIAL DESCRIPTION: **Exterior Window Caulk - Not AHERA**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Chrysotile** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Exterior of Building - Original Building**

MATERIAL QUANTITY:


MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not AHERA**

Inspector's Signature:



Date: **03/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **30031** BUIDLING ID: **2780**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Christopher School** REVIEW DATE: **4/18/2013**
ADDRESS: **5042 S. Artesian** IDPH LICENSE NO: **100-11170**

HOMOGENEOUS AREA: **062**

MATERIAL DESCRIPTION: **Exterior Window Caulk - Not AHERA**

MATERIAL LOCATION: **Exterior of Building - Original Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **04/18/2013** _____

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **30031** BUIDLING ID: **2780**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Jesus Delgado**
SCHOOL NAME: **Christopher School** INSPECTION DATE: **3/18/2013**
ADDRESS: **5042 S. Artesian** IDPH LICENSE NO: **100-11170**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **063**
MATERIAL DESCRIPTION: **Exterior Brick - Not AHERA**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Exterior of New Addition**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **03/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **30031** BUIDLING ID: **2780**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Christopher School** REVIEW DATE: **4/18/2013**
ADDRESS: **5042 S. Artesian** IDPH LICENSE NO: **100-11170**

HOMOGENEOUS AREA: **063**

MATERIAL DESCRIPTION: **Exterior Brick - Not AHERA**

MATERIAL LOCATION: **Exterior of New Addition**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **04/18/2013** _____

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **30031** BUIDLING ID: **2780**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Jesus Delgado**
SCHOOL NAME: **Christopher School** INSPECTION DATE: **3/18/2013**
ADDRESS: **5042 S. Artesian** IDPH LICENSE NO: **100-11170**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **064**
MATERIAL DESCRIPTION: **Exterior Brick Mortar - Not AHERA**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:


MATERIAL LOCATION: **Exterior of New Addition**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **03/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **30031** BUIDLING ID: **2780**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Christopher School** REVIEW DATE: **4/18/2013**
ADDRESS: **5042 S. Artesian** IDPH LICENSE NO: **100-11170**

HOMOGENEOUS AREA: **064**

MATERIAL DESCRIPTION: **Exterior Brick Mortar - Not AHERA**

MATERIAL LOCATION: **Exterior of New Addition**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **04/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **30031** BUIDLING ID: **2780**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Jesus Delgado**
SCHOOL NAME: **Christopher School** INSPECTION DATE: **3/18/2013**
ADDRESS: **5042 S. Artesian** IDPH LICENSE NO: **100-11170**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **065**
MATERIAL DESCRIPTION: **Exterior Door Caulk - Not AHERA**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Chrysotile** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Exterior of New Addition**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not AHERA**

Inspector's Signature:



Date: **03/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **30031** BUIDLING ID: **2780**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Christopher School** REVIEW DATE: **4/18/2013**
ADDRESS: **5042 S. Artesian** IDPH LICENSE NO: **100-11170**

HOMOGENEOUS AREA: **065**

MATERIAL DESCRIPTION: **Exterior Door Caulk - Not AHERA**

MATERIAL LOCATION: **Exterior of New Addition**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **04/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **30031** BUIDLING ID: **2780**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Jesus Delgado**
SCHOOL NAME: **Christopher School** INSPECTION DATE: **3/18/2013**
ADDRESS: **5042 S. Artesian** IDPH LICENSE NO: **100-11170**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **066**
MATERIAL DESCRIPTION: **12" x 12" Dk Gray FT w/Black & Gray Streaks Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Room 130**

MATERIAL QUANTITY: **900**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **30031** BUIDLING ID: **2780**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Christopher School** REVIEW DATE: **4/18/2013**
ADDRESS: **5042 S. Artesian** IDPH LICENSE NO: **100-11170**

HOMOGENEOUS AREA: **066**
MATERIAL DESCRIPTION: **12" x 12" Dk Gray FT w/Black & Gray Streaks Mastic**
MATERIAL LOCATION: **Room 130**
MATERIAL QUANTITY: **900** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **04/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **30031** BUIDLING ID: **2780**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Jesus Delgado**
SCHOOL NAME: **Christopher School** INSPECTION DATE: **3/18/2013**
ADDRESS: **5042 S. Artesian** IDPH LICENSE NO: **100-11170**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **067**
MATERIAL DESCRIPTION: **Non - Skid Strips**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Boy's and Girl's Locker Room, Pool Office**
MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **30031** BUIDLING ID: **2780**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Christopher School** REVIEW DATE: **4/18/2013**
ADDRESS: **5042 S. Artesian** IDPH LICENSE NO: **100-11170**

HOMOGENEOUS AREA: **067**
MATERIAL DESCRIPTION: **Non - Skid Strips**
MATERIAL LOCATION: **Boy's and Girl's Locker Room, Pool Office**
MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **04/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **30031** BUIDLING ID: **2780**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Jesus Delgado**
SCHOOL NAME: **Christopher School** INSPECTION DATE: **3/18/2013**
ADDRESS: **5042 S. Artesian** IDPH LICENSE NO: **100-11170**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **068**
MATERIAL DESCRIPTION: **Ceramic Tile Grout**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Pool Deck**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **30031** BUIDLING ID: **2780**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Christopher School** REVIEW DATE: **4/18/2013**
ADDRESS: **5042 S. Artesian** IDPH LICENSE NO: **100-11170**

HOMOGENEOUS AREA: **068**
MATERIAL DESCRIPTION: **Ceramic Tile Grout**
MATERIAL LOCATION: **Pool Deck**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **04/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **30031** BUIDLING ID: **2780**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Jesus Delgado**
SCHOOL NAME: **Christopher School** INSPECTION DATE: **3/18/2013**
ADDRESS: **5042 S. Artesian** IDPH LICENSE NO: **100-11170**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **069**
MATERIAL DESCRIPTION: **Grout Between Floor & Wall**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Pool Deck**
MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **30031** BUIDLING ID: **2780**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Christopher School** REVIEW DATE: **4/18/2013**
ADDRESS: **5042 S. Artesian** IDPH LICENSE NO: **100-11170**

HOMOGENEOUS AREA: **069**
MATERIAL DESCRIPTION: **Grout Between Floor & Wall**
MATERIAL LOCATION: **Pool Deck**
MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **04/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **30031** BUIDLING ID: **2780**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Jesus Delgado**
SCHOOL NAME: **Christopher School** INSPECTION DATE: **3/18/2013**
ADDRESS: **5042 S. Artesian** IDPH LICENSE NO: **100-11170**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **07 I**
MATERIAL DESCRIPTION: **12" x 12" Off-White Floor Tile w/Brown Speckles**
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **Low**

MATERIAL LOCATION: **Cafeteria, Boys Washroom, Room 108**

MATERIAL QUANTITY: **500**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS: **Material was not observed - 2013 3 years re-inspection**

Inspector's Signature:



Date: **03/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **30031** BUIDLING ID: **2780**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Christopher School** REVIEW DATE: **4/18/2013**
ADDRESS: **5042 S. Artesian** IDPH LICENSE NO: **100-11170**

HOMOGENEOUS AREA: **07 I**
MATERIAL DESCRIPTION: **12" x 12" Off-White Floor Tile w/Brown Speckles**
MATERIAL LOCATION: **Cafeteria, Boys Washroom, Room 108**
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Material was not observed - 2013 3 years re-inspection

Management Planner's Signature: _____



Date: **04/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **30031** BUIDLING ID: **2780**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Jesus Delgado**
SCHOOL NAME: **Christopher School** INSPECTION DATE: **3/18/2013**
ADDRESS: **5042 S. Artesian** IDPH LICENSE NO: **100-11170**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **070**
MATERIAL DESCRIPTION: **Ceramic Tile Grout in Pool**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Pool**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **30031** BUIDLING ID: **2780**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Christopher School** REVIEW DATE: **4/18/2013**
ADDRESS: **5042 S. Artesian** IDPH LICENSE NO: **100-11170**

HOMOGENEOUS AREA: **070**
MATERIAL DESCRIPTION: **Ceramic Tile Grout in Pool**
MATERIAL LOCATION: **Pool**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **04/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **30031** BUIDLING ID: **2780**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Jesus Delgado**
SCHOOL NAME: **Christopher School** INSPECTION DATE: **3/18/2013**
ADDRESS: **5042 S. Artesian** IDPH LICENSE NO: **100-11170**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **071**
MATERIAL DESCRIPTION: **Gray Baseboard**
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **Low**

MATERIAL LOCATION: **Room 130**

MATERIAL QUANTITY: **100**

MATERIAL UNITS: **LF**

DAMAGE QUANTITY:

DAMAGE UNITS: **LF**

COMMENTS: **Material was not observed - 2013 3 years re-inspection**

Inspector's Signature:



Date: **03/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **30031** BUIDLING ID: **2780**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Christopher School** REVIEW DATE: **4/18/2013**
ADDRESS: **5042 S. Artesian** IDPH LICENSE NO: **100-11170**

HOMOGENEOUS AREA: **071**
MATERIAL DESCRIPTION: **Gray Baseboard**
MATERIAL LOCATION: **Room 130**
MATERIAL QUANTITY: **100** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Material was not observed - 2013 3 years re-inspection

Management Planner's Signature: _____



Date: **04/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **30031** BUIDLING ID: **2780**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Jesus Delgado**
SCHOOL NAME: **Christopher School** INSPECTION DATE: **3/18/2013**
ADDRESS: **5042 S. Artesian** IDPH LICENSE NO: **100-11170**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **072**
MATERIAL DESCRIPTION: **Gray Baseboard Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **Low**

MATERIAL LOCATION: **Room 130**

MATERIAL QUANTITY: **100**

MATERIAL UNITS: **LF**

DAMAGE QUANTITY:

DAMAGE UNITS: **LF**

COMMENTS: **Material was not observed - 2013 3 years re-inspection**

Inspector's Signature:



Date: **03/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **30031** BUIDLING ID: **2780**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Christopher School** REVIEW DATE: **4/18/2013**
ADDRESS: **5042 S. Artesian** IDPH LICENSE NO: **100-11170**

HOMOGENEOUS AREA: **072**
MATERIAL DESCRIPTION: **Gray Baseboard Mastic**
MATERIAL LOCATION: **Room 130**
MATERIAL QUANTITY: **100** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Material was not observed - 2013 3 years re-inspection

Management Planner's Signature: _____



Date: **04/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates 2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **30031** BUIDLING ID: **2780**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Jesus Delgado**
SCHOOL NAME: **Christopher School** INSPECTION DATE: **3/18/2013**
ADDRESS: **5042 S. Artesian** IDPH LICENSE NO: **100-11170**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **073**
MATERIAL DESCRIPTION: **Ceiling Panel Material**
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **Low**

MATERIAL LOCATION: **Room 130**

MATERIAL QUANTITY: **900**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS: **Material was not observed - 2013 3 years re-inspection**

Inspector's Signature:



Date: **03/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **30031** BUIDLING ID: **2780**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Christopher School** REVIEW DATE: **4/18/2013**
ADDRESS: **5042 S. Artesian** IDPH LICENSE NO: **100-11170**

HOMOGENEOUS AREA: **073**
MATERIAL DESCRIPTION: **Ceiling Panel Material**
MATERIAL LOCATION: **Room 130**
MATERIAL QUANTITY: **900** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Material was not observed - 2013 3 years re-inspection

Management Planner's Signature: _____



Date: 04/18/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **30031** BUIDLING ID: **2780**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Jesus Delgado**
SCHOOL NAME: **Christopher School** INSPECTION DATE: **3/18/2013**
ADDRESS: **5042 S. Artesian** IDPH LICENSE NO: **100-11170**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **074**
MATERIAL DESCRIPTION: **Insulation Above Ceiling Panels**
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **Low**

MATERIAL LOCATION: **Room 130**

MATERIAL QUANTITY: **900**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS: **Material was not observed - 2013 3 years re-inspection**

Inspector's Signature:



Date: **03/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **30031** BUIDLING ID: **2780**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Christopher School** REVIEW DATE: **4/18/2013**
ADDRESS: **5042 S. Artesian** IDPH LICENSE NO: **100-11170**

HOMOGENEOUS AREA: **074**
MATERIAL DESCRIPTION: **Insulation Above Ceiling Panels**
MATERIAL LOCATION: **Room 130**
MATERIAL QUANTITY: **900** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Material was not observed - 2013 3 years re-inspection

Management Planner's Signature: _____



Date: **04/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **30031** BUIDLING ID: **2780**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Jesus Delgado**
SCHOOL NAME: **Christopher School** INSPECTION DATE: **3/18/2013**
ADDRESS: **5042 S. Artesian** IDPH LICENSE NO: **100-11170**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **075**
MATERIAL DESCRIPTION: **Linoleum Like Flooring Material**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Storage**
MATERIAL QUANTITY: **10** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **30031** BUIDLING ID: **2780**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Christopher School** REVIEW DATE: **4/18/2013**
ADDRESS: **5042 S. Artesian** IDPH LICENSE NO: **100-11170**

HOMOGENEOUS AREA: **075**
MATERIAL DESCRIPTION: **Linoleum Like Flooring Material**
MATERIAL LOCATION: **Storage**
MATERIAL QUANTITY: **10** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **04/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **30031** BUIDLING ID: **2780**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Jesus Delgado**
SCHOOL NAME: **Christopher School** INSPECTION DATE: **3/18/2013**
ADDRESS: **5042 S. Artesian** IDPH LICENSE NO: **100-11170**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **076**
MATERIAL DESCRIPTION: **Linoleum Like Material Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Storage**

MATERIAL QUANTITY: **10**


MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **30031** BUIDLING ID: **2780**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Christopher School** REVIEW DATE: **4/18/2013**
ADDRESS: **5042 S. Artesian** IDPH LICENSE NO: **100-11170**

HOMOGENEOUS AREA: **076**
MATERIAL DESCRIPTION: **Linoleum Like Material Mastic**
MATERIAL LOCATION: **Storage**
MATERIAL QUANTITY: **10** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **04/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **30031** BUIDLING ID: **2780**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Jesus Delgado**
SCHOOL NAME: **Christopher School** INSPECTION DATE: **3/18/2013**
ADDRESS: **5042 S. Artesian** IDPH LICENSE NO: **100-11170**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **077**
MATERIAL DESCRIPTION: **Vibration Absorbers**
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **No ACBM** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **Moderate**

MATERIAL LOCATION: **Attic**

MATERIAL QUANTITY: **20**

MATERIAL UNITS: **LF**

DAMAGE QUANTITY:

DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature:



Date: **03/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **30031** BUIDLING ID: **2780**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Christopher School** REVIEW DATE: **4/18/2013**
ADDRESS: **5042 S. Artesian** IDPH LICENSE NO: **100-11170**

HOMOGENEOUS AREA: **077**
MATERIAL DESCRIPTION: **Vibration Absorbers**
MATERIAL LOCATION: **Attic**
MATERIAL QUANTITY: **20** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **04/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates 2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **30031** BUIDLING ID: **2780**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Jesus Delgado**
SCHOOL NAME: **Christopher School** INSPECTION DATE: **3/18/2013**
ADDRESS: **5042 S. Artesian** IDPH LICENSE NO: **100-11170**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **078**
MATERIAL DESCRIPTION: **Terrazzo Sink**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Boy's Washroom**
MATERIAL QUANTITY: **40** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **30031** BUIDLING ID: **2780**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Christopher School** REVIEW DATE: **4/18/2013**
ADDRESS: **5042 S. Artesian** IDPH LICENSE NO: **100-11170**

HOMOGENEOUS AREA: **078**
MATERIAL DESCRIPTION: **Terrazzo Sink**
MATERIAL LOCATION: **Boy's Washroom**
MATERIAL QUANTITY: **40** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: 04/18/2013

Chicago Public Schools

Carnow, Conibear and Associates 2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **30031** BUIDLING ID: **2780**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Jesus Delgado**
SCHOOL NAME: **Christopher School** INSPECTION DATE: **3/18/2013**
ADDRESS: **5042 S. Artesian** IDPH LICENSE NO: **100-11170**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **079**
MATERIAL DESCRIPTION: **2' x 2' Ceiling Panels**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Gym**
MATERIAL QUANTITY: **3600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **30031** BUIDLING ID: **2780**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Christopher School** REVIEW DATE: **4/18/2013**
ADDRESS: **5042 S. Artesian** IDPH LICENSE NO: **100-11170**

HOMOGENEOUS AREA: **079**
MATERIAL DESCRIPTION: **2' x 2' Ceiling Panels**
MATERIAL LOCATION: **Gym**
MATERIAL QUANTITY: **3600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **04/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **30031** BUIDLING ID: **2780**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Jesus Delgado**
SCHOOL NAME: **Christopher School** INSPECTION DATE: **3/18/2013**
ADDRESS: **5042 S. Artesian** IDPH LICENSE NO: **100-11170**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **080**
MATERIAL DESCRIPTION: **Insulation in Safe Door**
HISTORICAL AHERA DAMAGE CATEGORY **7 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Hallway Across From Assembly Hall**
MATERIAL QUANTITY: **32** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature:



Date: **03/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **30031** BUIDLING ID: **2780**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Christopher School** REVIEW DATE: **4/18/2013**
ADDRESS: **5042 S. Artesian** IDPH LICENSE NO: **100-11170**

HOMOGENEOUS AREA: **080**
MATERIAL DESCRIPTION: **Insulation in Safe Door**
MATERIAL LOCATION: **Hallway Across From Assembly Hall**
MATERIAL QUANTITY: **32** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **04/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **30031** BUIDLING ID: **2780**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Jesus Delgado**
SCHOOL NAME: **Christopher School** INSPECTION DATE: **3/18/2013**
ADDRESS: **5042 S. Artesian** IDPH LICENSE NO: **100-11170**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **081**
MATERIAL DESCRIPTION: **9" x 9" Multi-Brown Specked Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **High**

MATERIAL LOCATION: **Room 111**

MATERIAL QUANTITY: **700**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS: **Material was not observed - 2013 3 years re-inspection**

Inspector's Signature:



Date: **03/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **30031** BUIDLING ID: **2780**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Christopher School** REVIEW DATE: **4/18/2013**
ADDRESS: **5042 S. Artesian** IDPH LICENSE NO: **100-11170**

HOMOGENEOUS AREA: **081**
MATERIAL DESCRIPTION: **9" x 9" Multi-Brown Specked Floor Tile**
MATERIAL LOCATION: **Room 111**
MATERIAL QUANTITY: **700** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Material was not observed - 2013 3 years re-inspection

Management Planner's Signature: _____



Date: **04/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **30031** BUIDLING ID: **2780**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Jesus Delgado**
SCHOOL NAME: **Christopher School** INSPECTION DATE: **3/18/2013**
ADDRESS: **5042 S. Artesian** IDPH LICENSE NO: **100-11170**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **082**
MATERIAL DESCRIPTION: **9" x 9" Multi-Brown Specked Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **Low**

MATERIAL LOCATION: **Room 111**

MATERIAL QUANTITY: **700**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS: **Material was not observed - 2013 3 years re-inspection**

Inspector's Signature:



Date: **03/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **30031** BUIDLING ID: **2780**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Christopher School** REVIEW DATE: **4/18/2013**
ADDRESS: **5042 S. Artesian** IDPH LICENSE NO: **100-11170**

HOMOGENEOUS AREA: **082**
MATERIAL DESCRIPTION: **9" x 9" Multi-Brown Specked Floor Tile Mastic**
MATERIAL LOCATION: **Room 111**
MATERIAL QUANTITY: **700** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Material was not observed - 2013 3 years re-inspection

Management Planner's Signature: _____



Date: **04/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **30031** BUIDLING ID: **2780**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Jesus Delgado**
SCHOOL NAME: **Christopher School** INSPECTION DATE: **3/18/2013**
ADDRESS: **5042 S. Artesian** IDPH LICENSE NO: **100-11170**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **083**
MATERIAL DESCRIPTION: **12" x 12" Multi-Brown Streaked Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **HIGH**
MATERIAL LOCATION: **Room 132**
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **30031** BUIDLING ID: **2780**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Christopher School** REVIEW DATE: **4/18/2013**
ADDRESS: **5042 S. Artesian** IDPH LICENSE NO: **100-11170**

HOMOGENEOUS AREA: **083**
MATERIAL DESCRIPTION: **12" x 12" Multi-Brown Streaked Floor Tile**
MATERIAL LOCATION: **Room 132**
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: 04/18/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **30031** BUIDLING ID: **2780**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Jesus Delgado**
SCHOOL NAME: **Christopher School** INSPECTION DATE: **3/18/2013**
ADDRESS: **5042 S. Artesian** IDPH LICENSE NO: **100-11170**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **084**
MATERIAL DESCRIPTION: **12" x 12" Multi-Brown Streaked Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Room 132**

MATERIAL QUANTITY: **500**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **30031** BUIDLING ID: **2780**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Christopher School** REVIEW DATE: **4/18/2013**
ADDRESS: **5042 S. Artesian** IDPH LICENSE NO: **100-11170**

HOMOGENEOUS AREA: **084**
MATERIAL DESCRIPTION: **12" x 12" Multi-Brown Streaked Floor Tile Mastic**
MATERIAL LOCATION: **Room 132**
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **04/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **30031** BUIDLING ID: **2780**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Jesus Delgado**
SCHOOL NAME: **Christopher School** INSPECTION DATE: **3/18/2013**
ADDRESS: **5042 S. Artesian** IDPH LICENSE NO: **100-11170**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **085**
MATERIAL DESCRIPTION: **Dark Gray Linoleum**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **HIGH**

MATERIAL LOCATION: **Outside Hall by Rooms 401, 403, 405, 407**

MATERIAL QUANTITY: **400**


MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **30031** BUIDLING ID: **2780**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Christopher School** REVIEW DATE: **4/18/2013**
ADDRESS: **5042 S. Artesian** IDPH LICENSE NO: **100-11170**

HOMOGENEOUS AREA: **085**
MATERIAL DESCRIPTION: **Dark Gray Linoleum**
MATERIAL LOCATION: **Outside Hall by Rooms 401, 403, 405, 407**
MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **04/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **30031** BUIDLING ID: **2780**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Jesus Delgado**
SCHOOL NAME: **Christopher School** INSPECTION DATE: **3/18/2013**
ADDRESS: **5042 S. Artesian** IDPH LICENSE NO: **100-11170**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **086**
MATERIAL DESCRIPTION: **Dark Gray Linoleum Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Hall outside Rooms 401, 403, 405, 407**

MATERIAL QUANTITY: **400**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **30031** BUIDLING ID: **2780**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Christopher School** REVIEW DATE: **4/18/2013**
ADDRESS: **5042 S. Artesian** IDPH LICENSE NO: **100-11170**

HOMOGENEOUS AREA: **086**
MATERIAL DESCRIPTION: **Dark Gray Linoleum Mastic**
MATERIAL LOCATION: **Hall outside Rooms 401, 403, 405, 407**
MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **04/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates 2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **30031** BUIDLING ID: **2780**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Jesus Delgado**
SCHOOL NAME: **Christopher School** INSPECTION DATE: **3/18/2013**
ADDRESS: **5042 S. Artesian** IDPH LICENSE NO: **100-11170**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **087**
MATERIAL DESCRIPTION: **2' x 4' Lay-In Ceiling Panels**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 180/181 and as Patch in Exit by Gym**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **30031** BUIDLING ID: **2780**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Christopher School** REVIEW DATE: **4/18/2013**
ADDRESS: **5042 S. Artesian** IDPH LICENSE NO: **100-11170**

HOMOGENEOUS AREA: **087**
MATERIAL DESCRIPTION: **2' x 4' Lay-In Ceiling Panels**
MATERIAL LOCATION: **Room 180/181 and as Patch in Exit by Gym**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **04/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **30031** BUIDLING ID: **2780**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Jesus Delgado**
SCHOOL NAME: **Christopher School** INSPECTION DATE: **3/18/2013**
ADDRESS: **5042 S. Artesian** IDPH LICENSE NO: **100-11170**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **088**
MATERIAL DESCRIPTION: **Dark Gray Baseboard**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT


This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Room 401, 403, 405, 407 and Hall**
MATERIAL QUANTITY: **250** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature:



Date: **03/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **30031** BUIDLING ID: **2780**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Christopher School** REVIEW DATE: **4/18/2013**
ADDRESS: **5042 S. Artesian** IDPH LICENSE NO: **100-11170**

HOMOGENEOUS AREA: **088**
MATERIAL DESCRIPTION: **Dark Gray Baseboard**
MATERIAL LOCATION: **Room 401, 403, 405, 407 and Hall**
MATERIAL QUANTITY: **250** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **04/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **30031** BUIDLING ID: **2780**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Jesus Delgado**
SCHOOL NAME: **Christopher School** INSPECTION DATE: **3/18/2013**
ADDRESS: **5042 S. Artesian** IDPH LICENSE NO: **100-11170**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **089**
MATERIAL DESCRIPTION: **Dark Gray Baseboard Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Room 401, 403, 405, 407, Hall**

MATERIAL QUANTITY: **250**


MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **30031** BUIDLING ID: **2780**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Christopher School** REVIEW DATE: **4/18/2013**
ADDRESS: **5042 S. Artesian** IDPH LICENSE NO: **100-11170**

HOMOGENEOUS AREA: **089**
MATERIAL DESCRIPTION: **Dark Gray Baseboard Mastic**
MATERIAL LOCATION: **Room 401, 403, 405, 407, Hall**
MATERIAL QUANTITY: **250** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **04/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **30031** BUIDLING ID: **2780**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Jesus Delgado**
SCHOOL NAME: **Christopher School** INSPECTION DATE: **3/18/2013**
ADDRESS: **5042 S. Artesian** IDPH LICENSE NO: **100-11170**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **090**
MATERIAL DESCRIPTION: **Drywall**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **New Building 401, 403, 405, 407 and Hall, Unisex Washroom**
MATERIAL QUANTITY: **2600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **30031** BUIDLING ID: **2780**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Christopher School** REVIEW DATE: **4/18/2013**
ADDRESS: **5042 S. Artesian** IDPH LICENSE NO: **100-11170**

HOMOGENEOUS AREA: **090**
MATERIAL DESCRIPTION: **Drywall**
MATERIAL LOCATION: **New Building 401, 403, 405, 407 and Hall, Unisex Washroom**
MATERIAL QUANTITY: **2600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **04/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **30031** BUIDLING ID: **2780**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Jesus Delgado**
SCHOOL NAME: **Christopher School** INSPECTION DATE: **3/18/2013**
ADDRESS: **5042 S. Artesian** IDPH LICENSE NO: **100-11170**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **091**
MATERIAL DESCRIPTION: **White and Light Blue Linoleum**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **HIGH**
MATERIAL LOCATION: **Rooms 401, 403, 405, 407**
MATERIAL QUANTITY: **1600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **30031** BUIDLING ID: **2780**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Christopher School** REVIEW DATE: **4/18/2013**
ADDRESS: **5042 S. Artesian** IDPH LICENSE NO: **100-11170**

HOMOGENEOUS AREA: **091**
MATERIAL DESCRIPTION: **White and Light Blue Linoleum**
MATERIAL LOCATION: **Rooms 401, 403, 405, 407**
MATERIAL QUANTITY: **1600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **04/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **30031** BUIDLING ID: **2780**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Jesus Delgado**
SCHOOL NAME: **Christopher School** INSPECTION DATE: **3/18/2013**
ADDRESS: **5042 S. Artesian** IDPH LICENSE NO: **100-11170**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **092**
MATERIAL DESCRIPTION: **White and Light Blue Linoleum Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms 401, 403, 405, 407**
MATERIAL QUANTITY: **1600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **30031** BUIDLING ID: **2780**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Christopher School** REVIEW DATE: **4/18/2013**
ADDRESS: **5042 S. Artesian** IDPH LICENSE NO: **100-11170**

HOMOGENEOUS AREA: **092**
MATERIAL DESCRIPTION: **White and Light Blue Linoleum Mastic**
MATERIAL LOCATION: **Rooms 401, 403, 405, 407**
MATERIAL QUANTITY: **1600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **04/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **30031** BUIDLING ID: **2780**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Jesus Delgado**
SCHOOL NAME: **Christopher School** INSPECTION DATE: **3/18/2013**
ADDRESS: **5042 S. Artesian** IDPH LICENSE NO: **100-11170**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **093**
MATERIAL DESCRIPTION: **Boiler Gaskets**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Boiler Room**
MATERIAL QUANTITY: **50** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature:



Date: **03/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **30031** BUIDLING ID: **2780**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Christopher School** REVIEW DATE: **4/18/2013**
ADDRESS: **5042 S. Artesian** IDPH LICENSE NO: **100-11170**

HOMOGENEOUS AREA: **093**
MATERIAL DESCRIPTION: **Boiler Gaskets**
MATERIAL LOCATION: **Boiler Room**
MATERIAL QUANTITY: **50** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **04/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **30031** BUIDLING ID: **2780**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Jesus Delgado**
SCHOOL NAME: **Christopher School** INSPECTION DATE: **3/18/2013**
ADDRESS: **5042 S. Artesian** IDPH LICENSE NO: **100-11170**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **094**
MATERIAL DESCRIPTION: **Insulation Under Steel Shell of Incinerator**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Boiler Room**
MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **30031** BUIDLING ID: **2780**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Christopher School** REVIEW DATE: **4/18/2013**
ADDRESS: **5042 S. Artesian** IDPH LICENSE NO: **100-11170**

HOMOGENEOUS AREA: **094**
MATERIAL DESCRIPTION: **Insulation Under Steel Shell of Incinerator**
MATERIAL LOCATION: **Boiler Room**
MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **04/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **30031** BUIDLING ID: **2780**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Jesus Delgado**
SCHOOL NAME: **Christopher School** INSPECTION DATE: **3/18/2013**
ADDRESS: **5042 S. Artesian** IDPH LICENSE NO: **100-11170**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **095**
MATERIAL DESCRIPTION: **12" x 12" White w/Gray Specks Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **HIGH**
MATERIAL LOCATION: **New Annex - Rooms 302 - 309, Changing Room and Laundry Room, Halls on 1st Floor**
MATERIAL QUANTITY: **3900** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature:



Date: **03/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **30031** BUIDLING ID: **2780**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Christopher School** REVIEW DATE: **4/18/2013**
ADDRESS: **5042 S. Artesian** IDPH LICENSE NO: **100-11170**

HOMOGENEOUS AREA: **095**
MATERIAL DESCRIPTION: **12" x 12" White w/Gray Specks Floor Tile**
MATERIAL LOCATION: **New Annex - Rooms 302 - 309, Changing Room and Laundry Room, Halls on 1st Floor**
MATERIAL QUANTITY: **3900** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **04/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **30031** BUIDLING ID: **2780**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Jesus Delgado**
SCHOOL NAME: **Christopher School** INSPECTION DATE: **3/18/2013**
ADDRESS: **5042 S. Artesian** IDPH LICENSE NO: **100-11170**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **096**
MATERIAL DESCRIPTION: **12" x 12" White w/Gray Specks Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **New Annex - Rooms 302 - 309, Changing Room and Laundry Room, and Halls on 1st Floor**

MATERIAL QUANTITY: **3900**


MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **30031** BUIDLING ID: **2780**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Christopher School** REVIEW DATE: **4/18/2013**
ADDRESS: **5042 S. Artesian** IDPH LICENSE NO: **100-11170**

HOMOGENEOUS AREA: **096**
MATERIAL DESCRIPTION: **12" x 12" White w/Gray Specks Floor Tile Mastic**
MATERIAL LOCATION: **New Annex - Rooms 302 - 309, Changing Room and Laundry Room, and Halls on 1st Floor**
MATERIAL QUANTITY: **3900** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **04/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates 2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **30031** BUIDLING ID: **2780**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Jesus Delgado**
SCHOOL NAME: **Christopher School** INSPECTION DATE: **3/18/2013**
ADDRESS: **5042 S. Artesian** IDPH LICENSE NO: **100-11170**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **097**
MATERIAL DESCRIPTION: **4" Beige Baseboard**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT


This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **New Annex - All Rooms except Washroom**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: DAMAGE UNITS: **LF**
COMMENTS:

Inspector's Signature:



Date: **03/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **30031** BUIDLING ID: **2780**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Christopher School** REVIEW DATE: **4/18/2013**
ADDRESS: **5042 S. Artesian** IDPH LICENSE NO: **100-11170**

HOMOGENEOUS AREA: **097**
MATERIAL DESCRIPTION: **4" Beige Baseboard**
MATERIAL LOCATION: **New Annex - All Rooms except Washroom**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **04/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **30031** BUIDLING ID: **2780**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Jesus Delgado**
SCHOOL NAME: **Christopher School** INSPECTION DATE: **3/18/2013**
ADDRESS: **5042 S. Artesian** IDPH LICENSE NO: **100-11170**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **098**
MATERIAL DESCRIPTION: **4" Beige Baseboard Adhesive**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **New Annex - All Rooms except Washroom**

MATERIAL QUANTITY: **800**

MATERIAL UNITS: **LF**

DAMAGE QUANTITY:

DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature:



Date: **03/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **30031** BUIDLING ID: **2780**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Christopher School** REVIEW DATE: **4/18/2013**
ADDRESS: **5042 S. Artesian** IDPH LICENSE NO: **100-11170**

HOMOGENEOUS AREA: **098**
MATERIAL DESCRIPTION: **4" Beige Baseboard Adhesive**
MATERIAL LOCATION: **New Annex - All Rooms except Washroom**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **04/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **30031** BUIDLING ID: **2780**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Jesus Delgado**
SCHOOL NAME: **Christopher School** INSPECTION DATE: **3/18/2013**
ADDRESS: **5042 S. Artesian** IDPH LICENSE NO: **100-11170**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **099**
MATERIAL DESCRIPTION: **2' x 2' White Fissured Ceiling Tile**
HISTORICAL AHERA DAMAGE CATEGORY **7 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **New Annex - All Rooms, 1st Floor Hall**
MATERIAL QUANTITY: **4000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature:



Date: **03/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **30031** BUIDLING ID: **2780**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Christopher School** REVIEW DATE: **4/18/2013**
ADDRESS: **5042 S. Artesian** IDPH LICENSE NO: **100-11170**

HOMOGENEOUS AREA: **099**
MATERIAL DESCRIPTION: **2' x 2' White Fissured Ceiling Tile**
MATERIAL LOCATION: **New Annex - All Rooms, 1st Floor Hall**
MATERIAL QUANTITY: **4000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: 04/18/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **30031** BUIDLING ID: **2780**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Jesus Delgado**
SCHOOL NAME: **Christopher School** INSPECTION DATE: **3/18/2013**
ADDRESS: **5042 S. Artesian** IDPH LICENSE NO: **100-11170**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **100**
MATERIAL DESCRIPTION: **12"x12" Gray and Cream Speckled Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **HIGH**
MATERIAL LOCATION: **Auditorium**
MATERIAL QUANTITY: **3600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **30031** BUIDLING ID: **2780**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Christopher School** REVIEW DATE: **4/18/2013**
ADDRESS: **5042 S. Artesian** IDPH LICENSE NO: **100-11170**

HOMOGENEOUS AREA: **100**
MATERIAL DESCRIPTION: **12"x12" Gray and Cream Speckled Floor Tile**
MATERIAL LOCATION: **Auditorium**
MATERIAL QUANTITY: **3600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **04/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **30031** BUIDLING ID: **2780**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Jesus Delgado**
SCHOOL NAME: **Christopher School** INSPECTION DATE: **3/18/2013**
ADDRESS: **5042 S. Artesian** IDPH LICENSE NO: **100-11170**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **101**
MATERIAL DESCRIPTION: **12"x12" Gray and Cream Speckled Floor Tile-Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Auditorium**
MATERIAL QUANTITY: **3600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **30031** BUIDLING ID: **2780**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Christopher School** REVIEW DATE: **4/18/2013**
ADDRESS: **5042 S. Artesian** IDPH LICENSE NO: **100-11170**

HOMOGENEOUS AREA: **101**
MATERIAL DESCRIPTION: **12"x12" Gray and Cream Speckled Floor Tile-Mastic**
MATERIAL LOCATION: **Auditorium**
MATERIAL QUANTITY: **3600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **04/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **30031** BUIDLING ID: **2780**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Jesus Delgado**
SCHOOL NAME: **Christopher School** INSPECTION DATE: **3/18/2013**
ADDRESS: **5042 S. Artesian** IDPH LICENSE NO: **100-11170**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **102**
MATERIAL DESCRIPTION: **12"x12" Brown Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **HIGH**
MATERIAL LOCATION: **Auditorium, Stairs, Landing**
MATERIAL QUANTITY: **120** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **30031** BUIDLING ID: **2780**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Christopher School** REVIEW DATE: **4/18/2013**
ADDRESS: **5042 S. Artesian** IDPH LICENSE NO: **100-11170**

HOMOGENEOUS AREA: **102**
MATERIAL DESCRIPTION: **12"x12" Brown Floor Tile**
MATERIAL LOCATION: **Auditorium, Stairs, Landing**
MATERIAL QUANTITY: **120** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **04/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **30031** BUIDLING ID: **2780**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Jesus Delgado**
SCHOOL NAME: **Christopher School** INSPECTION DATE: **3/18/2013**
ADDRESS: **5042 S. Artesian** IDPH LICENSE NO: **100-11170**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **103**
MATERIAL DESCRIPTION: **12"x12" Brown Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Auditorium, Stairs, Landing, Engineer**
MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **30031** BUIDLING ID: **2780**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Christopher School** REVIEW DATE: **4/18/2013**
ADDRESS: **5042 S. Artesian** IDPH LICENSE NO: **100-11170**

HOMOGENEOUS AREA: **103**
MATERIAL DESCRIPTION: **12"x12" Brown Floor Tile Mastic**
MATERIAL LOCATION: **Auditorium, Stairs, Landing, Engineer**
MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **04/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **30031** BUIDLING ID: **2780**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Jesus Delgado**
SCHOOL NAME: **Christopher School** INSPECTION DATE: **3/18/2013**
ADDRESS: **5042 S. Artesian** IDPH LICENSE NO: **100-11170**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **104**
MATERIAL DESCRIPTION: **12x12 Light Brown FT with Dark Brown & White**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **HIGH**
MATERIAL LOCATION: **Rooms 111, 103, 132, 135, 136, 113**
MATERIAL QUANTITY: **3000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature:



Date: **03/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **30031** BUIDLING ID: **2780**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Christopher School** REVIEW DATE: **4/18/2013**
ADDRESS: **5042 S. Artesian** IDPH LICENSE NO: **100-11170**

HOMOGENEOUS AREA: **104**
MATERIAL DESCRIPTION: **12x12 Light Brown FT with Dark Brown & White**
MATERIAL LOCATION: **Rooms 111, 103, 132, 135, 136, 113**
MATERIAL QUANTITY: **3000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **04/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **30031** BUIDLING ID: **2780**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Jesus Delgado**
SCHOOL NAME: **Christopher School** INSPECTION DATE: **3/18/2013**
ADDRESS: **5042 S. Artesian** IDPH LICENSE NO: **100-11170**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **105**
MATERIAL DESCRIPTION: **Mastic associated with 12x12Light Brown FT with Dark Brown & White**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Rooms 111, 103, 132, 135, 136, 113**

MATERIAL QUANTITY: **3000**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **30031** BUIDLING ID: **2780**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Christopher School** REVIEW DATE: **4/18/2013**
ADDRESS: **5042 S. Artesian** IDPH LICENSE NO: **100-11170**

HOMOGENEOUS AREA: **105**
MATERIAL DESCRIPTION: **Mastic associated with 12x12Light Brown FT with Dark Brown & White**
MATERIAL LOCATION: **Rooms 111, 103, 132, 135, 136, 113**
MATERIAL QUANTITY: **3000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **04/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **30031** BUIDLING ID: **2780**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Jesus Delgado**
SCHOOL NAME: **Christopher School** INSPECTION DATE: **3/18/2013**
ADDRESS: **5042 S. Artesian** IDPH LICENSE NO: **100-11170**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **106**
MATERIAL DESCRIPTION: **Cream with Light Brown Linoleum**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **HIGH**
MATERIAL LOCATION: **Washrooms across from 129/131**
MATERIAL QUANTITY: **750** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **30031** BUIDLING ID: **2780**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Christopher School** REVIEW DATE: **4/18/2013**
ADDRESS: **5042 S. Artesian** IDPH LICENSE NO: **100-11170**

HOMOGENEOUS AREA: **106**
MATERIAL DESCRIPTION: **Cream with Light Brown Linoleum**
MATERIAL LOCATION: **Washrooms across from 129/131**
MATERIAL QUANTITY: **750** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **04/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates 2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **30031** BUIDLING ID: **2780**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Jesus Delgado**
SCHOOL NAME: **Christopher School** INSPECTION DATE: **3/18/2013**
ADDRESS: **5042 S. Artesian** IDPH LICENSE NO: **100-11170**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **107**
MATERIAL DESCRIPTION: **Adhesive associated with Cream with Light Brown Linoleum**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Washrooms across from room 129/131**

MATERIAL QUANTITY: **750**


MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **30031** BUIDLING ID: **2780**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Christopher School** REVIEW DATE: **4/18/2013**
ADDRESS: **5042 S. Artesian** IDPH LICENSE NO: **100-11170**

HOMOGENEOUS AREA: **107**
MATERIAL DESCRIPTION: **Adhesive associated with Cream with Light Brown Linoleum**
MATERIAL LOCATION: **Washrooms across from room 129/131**
MATERIAL QUANTITY: **750** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **04/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates 2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **30031** BUIDLING ID: **2780**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Jesus Delgado**
SCHOOL NAME: **Christopher School** INSPECTION DATE: **3/18/2013**
ADDRESS: **5042 S. Artesian** IDPH LICENSE NO: **100-11170**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **90A**
MATERIAL DESCRIPTION: **Drywall Tape**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT


This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Addition for 401, 403, 405, 407**
MATERIAL QUANTITY: **250** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature:



Date: **03/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **30031** BUIDLING ID: **2780**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Christopher School** REVIEW DATE: **4/18/2013**
ADDRESS: **5042 S. Artesian** IDPH LICENSE NO: **100-11170**

HOMOGENEOUS AREA: **90A**
MATERIAL DESCRIPTION: **Drywall Tape**
MATERIAL LOCATION: **Addition for 401, 403, 405, 407**
MATERIAL QUANTITY: **250** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **04/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **30031** BUIDLING ID: **2780**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Jesus Delgado**
SCHOOL NAME: **Christopher School** INSPECTION DATE: **3/18/2013**
ADDRESS: **5042 S. Artesian** IDPH LICENSE NO: **100-11170**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **90B**
MATERIAL DESCRIPTION: **Drywall Compound**
HISTORICAL AHERA DAMAGE CATEGORY **7 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Addition for 401, 403, 405, 407**
MATERIAL QUANTITY: **250** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: DAMAGE UNITS: **LF**
COMMENTS:

Inspector's Signature:



Date: **03/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **30031** BUIDLING ID: **2780**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Christopher School** REVIEW DATE: **4/18/2013**
ADDRESS: **5042 S. Artesian** IDPH LICENSE NO: **100-11170**

HOMOGENEOUS AREA: **90B**
MATERIAL DESCRIPTION: **Drywall Compound**
MATERIAL LOCATION: **Addition for 401, 403, 405, 407**
MATERIAL QUANTITY: **250** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **04/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **30031** BUIDLING ID: **2780**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Jesus Delgado**
SCHOOL NAME: **Christopher School** INSPECTION DATE: **3/18/2013**
ADDRESS: **5042 S. Artesian** IDPH LICENSE NO: **100-11170**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **B**
MATERIAL DESCRIPTION: **Aircell Pipe Insulation**
HISTORICAL AHERA DAMAGE CATEGORY **1 Damaged or significantly damaged friable thermal system insulating ACM**
HISTORICAL DAMAGE REASON: **Physical Damage**
HISTORICAL RESPONSE ACTION: **Enclose**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **1. Damaged or significantly damaged friable thermal system insulating ACM**

DAMAGE REASON: **Physical Damage**
DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Tunnel, Basement, Crawl Spaces**
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: DAMAGE UNITS: **LF**
COMMENTS:

Inspector's Signature:



Date: **03/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **30031** BUIDLING ID: **2780**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Christopher School** REVIEW DATE: **4/18/2013**
ADDRESS: **5042 S. Artesian** IDPH LICENSE NO: **100-11170**

HOMOGENEOUS AREA: **B**
MATERIAL DESCRIPTION: **Aircell Pipe Insulation**
MATERIAL LOCATION: **Tunnel, Basement, Crawl Spaces**
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **100** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Enclose

Comments:

Remove/Repair damaged material and maintain O&M

Management Planner's Signature: _____



Date: **04/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **30031** BUIDLING ID: **2780**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Jesus Delgado**
SCHOOL NAME: **Christopher School** INSPECTION DATE: **3/18/2013**
ADDRESS: **5042 S. Artesian** IDPH LICENSE NO: **100-11170**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **C**
MATERIAL DESCRIPTION: **Aircell Pipe Insulation Joints**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**

MATERIAL LOCATION: **Basement, Tunnel, Crawl Spaces**

MATERIAL QUANTITY: **50**

MATERIAL UNITS: **LF**

DAMAGE QUANTITY:

DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature:



Date: **03/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **30031** BUIDLING ID: **2780**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Christopher School** REVIEW DATE: **4/18/2013**
ADDRESS: **5042 S. Artesian** IDPH LICENSE NO: **100-11170**

HOMOGENEOUS AREA: **C**
MATERIAL DESCRIPTION: **Aircell Pipe Insulation Joints**
MATERIAL LOCATION: **Basement, Tunnel, Crawl Spaces**
MATERIAL QUANTITY: **50** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **04/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **30031** BUIDLING ID: **2780**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Jesus Delgado**
SCHOOL NAME: **Christopher School** INSPECTION DATE: **3/18/2013**
ADDRESS: **5042 S. Artesian** IDPH LICENSE NO: **100-11170**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **D**
MATERIAL DESCRIPTION: **Cardboard Pipe Insulation**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**

MATERIAL LOCATION: **Tunnel / Kitchen Storage Room**

MATERIAL QUANTITY: **35**

MATERIAL UNITS: **LF**

DAMAGE QUANTITY:

DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature:



Date: **03/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **30031** BUIDLING ID: **2780**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Christopher School** REVIEW DATE: **4/18/2013**
ADDRESS: **5042 S. Artesian** IDPH LICENSE NO: **100-11170**

HOMOGENEOUS AREA: **D**
MATERIAL DESCRIPTION: **Cardboard Pipe Insulation**
MATERIAL LOCATION: **Tunnel / Kitchen Storage Room**
MATERIAL QUANTITY: **35** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **04/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **30031** BUIDLING ID: **2780**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Jesus Delgado**
SCHOOL NAME: **Christopher School** INSPECTION DATE: **3/18/2013**
ADDRESS: **5042 S. Artesian** IDPH LICENSE NO: **100-11170**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **E**
MATERIAL DESCRIPTION: **Cardboard Pipe Insulation Joints**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Tunnel/Kitchen Storage**

MATERIAL QUANTITY: **4** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature:



Date: **03/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **30031** BUIDLING ID: **2780**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Christopher School** REVIEW DATE: **4/18/2013**
ADDRESS: **5042 S. Artesian** IDPH LICENSE NO: **100-11170**

HOMOGENEOUS AREA: **E**
MATERIAL DESCRIPTION: **Cardboard Pipe Insulation Joints**
MATERIAL LOCATION: **Tunnel/Kitchen Storage**
MATERIAL QUANTITY: **4** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: 04/18/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **30031** BUIDLING ID: **2780**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Jesus Delgado**
SCHOOL NAME: **Christopher School** INSPECTION DATE: **3/18/2013**
ADDRESS: **5042 S. Artesian** IDPH LICENSE NO: **100-11170**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **F**
MATERIAL DESCRIPTION: **Pipe Joint Insulation off Fiberglass**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**

MATERIAL LOCATION: **Tunnel, Kitchen Storage Room**

MATERIAL QUANTITY: **10**

MATERIAL UNITS: **LF**

DAMAGE QUANTITY:

DAMAGE UNITS: **LF**

COMMENTS: **Not observed in kitchen storage**

Inspector's Signature:



Date: **03/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **30031** BUIDLING ID: **2780**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Christopher School** REVIEW DATE: **4/18/2013**
ADDRESS: **5042 S. Artesian** IDPH LICENSE NO: **100-11170**

HOMOGENEOUS AREA: **F**
MATERIAL DESCRIPTION: **Pipe Joint Insulation off Fiberglass**
MATERIAL LOCATION: **Tunnel, Kitchen Storage Room**
MATERIAL QUANTITY: **10** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Not observed in kitchen storage

Management Planner's Signature: _____



Date: **04/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **30031** BUIDLING ID: **2780**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Jesus Delgado**
SCHOOL NAME: **Christopher School** INSPECTION DATE: **3/18/2013**
ADDRESS: **5042 S. Artesian** IDPH LICENSE NO: **100-11170**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **G**
MATERIAL DESCRIPTION: **Boiler Insulation - ABATED**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION:

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Material was not observed - 2013 3 years re-inspection**

Inspector's Signature:



Date: **03/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **30031** BUIDLING ID: **2780**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Christopher School** REVIEW DATE: **4/18/2013**
ADDRESS: **5042 S. Artesian** IDPH LICENSE NO: **100-11170**

HOMOGENEOUS AREA: **G**

MATERIAL DESCRIPTION: **Boiler Insulation - ABATED**

MATERIAL LOCATION:

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **04/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **30031** BUIDLING ID: **2780**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Jesus Delgado**
SCHOOL NAME: **Christopher School** INSPECTION DATE: **3/18/2013**
ADDRESS: **5042 S. Artesian** IDPH LICENSE NO: **100-11170**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **H**
MATERIAL DESCRIPTION: **Tank Insulation - ABATED**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION:

MATERIAL QUANTITY:


MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Material was not observed - 2013 3 years re-inspection**

Inspector's Signature:



Date: **03/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **30031** BUIDLING ID: **2780**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Christopher School** REVIEW DATE: **4/18/2013**
ADDRESS: **5042 S. Artesian** IDPH LICENSE NO: **100-11170**

HOMOGENEOUS AREA: **H**

MATERIAL DESCRIPTION: **Tank Insulation - ABATED**

MATERIAL LOCATION:

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **04/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **30031** BUIDLING ID: **2780**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Jesus Delgado**
SCHOOL NAME: **Christopher School** INSPECTION DATE: **3/18/2013**
ADDRESS: **5042 S. Artesian** IDPH LICENSE NO: **100-11170**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **I**
MATERIAL DESCRIPTION: **Aircell Pipe Wrap (Jacketing)**
HISTORICAL AHERA DAMAGE CATEGORY **1 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **1. Damaged or significantly damaged friable thermal system insulating ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**

MATERIAL LOCATION: **Tunnel, Basement, Crawl Spaces, Maintenance Areas**

MATERIAL QUANTITY: **1500** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature:



Date: **03/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **30031** BUIDLING ID: **2780**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Christopher School** REVIEW DATE: **4/18/2013**
ADDRESS: **5042 S. Artesian** IDPH LICENSE NO: **100-11170**

HOMOGENEOUS AREA: **I**
MATERIAL DESCRIPTION: **Aircell Pipe Wrap (Jacketing)**
MATERIAL LOCATION: **Tunnel, Basement, Crawl Spaces, Maintenance Areas**
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **100** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Remove/Repair damaged material and maintain O&M

Management Planner's Signature: _____



Date: **04/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **30031** BUIDLING ID: **2780**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Jesus Delgado**
SCHOOL NAME: **Christopher School** INSPECTION DATE: **3/18/2013**
ADDRESS: **5042 S. Artesian** IDPH LICENSE NO: **100-11170**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **J**
MATERIAL DESCRIPTION: **Fiberglass Pipe Insulation**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Tunnel**

MATERIAL QUANTITY:


MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **03/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **30031** BUIDLING ID: **2780**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Christopher School** REVIEW DATE: **4/18/2013**
ADDRESS: **5042 S. Artesian** IDPH LICENSE NO: **100-11170**

HOMOGENEOUS AREA: **J**

MATERIAL DESCRIPTION: **Fiberglass Pipe Insulation**

MATERIAL LOCATION: **Tunnel**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **04/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates 2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **30031** BUILDING ID: **2780**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Christopher School** REVIEW DATE: **4/18/2013**
ADDRESS: **5042 S. Artesian** IDPH LICENSE NO: **100-11170**


HOMOGENEOUS AREA: **108**
MATERIAL DESCRIPTION: **12"X12" Blue W/Gray White Streaks VFT**
MATERIAL LOCATION: **Room 113,116,117/119,121/123,143,101,105,107,109,125, 127,128,137,141, cafeteria lounge**
MATERIAL QUANTITY: **11000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:


COMMENTS:

Management Planner's Signature: _____




Date: 04/18/2013

Walter S. Christopher School Floor Plan



ASBESTOS REINSPECTION KEY NOTES:

 HA-108 12"x12" Blue w/ Gray & White Streaks Floor Tile

FIRST FLOOR

ASBESTOS REINSPECTION

NOT TO SCALE



CLIENT:
Chicago Public Schools
125 South Clark Street,
Chicago, Illinois 60603

PROJECT NAME:
2013 AHERA Reinspection
Christopher School
5042 S. Artesian
Chicago, Illinois 60632

SHEET NAME:
Asbestos CPS Reinspection 2013

DRAWN BY: DM	DATE: 3-29-13	CHECKED BY:
REVISED BY:	DATE:	CHECKED BY:
REVISED BY:	DATE:	CHECKED BY:
REVISED BY:	DATE:	CHECKED BY:

INSPECTED BY:
Jesus Delgado

IDPH License #:100-11170

Carnow, Conibear & Assoc., Ltd.
Environmental Consulting Services
600 W. Van Buren St., Suite 500, Chicago, IL 60607
t: 312.782.4486 f: 312.782.5145
www.ccaatltd.com

CCA PROJECT NUMBER
A320130001-158
DATE
March 18, 2013
SHEET NUMBER

**CARNOW
CONIBEAR** HA-108

20130313 Three Year Asbestos Reinspection Region: MC Christopher School CPS Year: Christopher Drawing: Any

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION


Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **30031** BUILDING ID: **2780**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Jesus Delgado**
SCHOOL NAME: **Christopher School** INSPECTION DATE: **3/18/2013**
ADDRESS: **5042 S. Artesian** IDPH LICENSE NO: **100-11170**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **109**
MATERIAL DESCRIPTION: **12"X12" Blue W/Gray & White Streaks VFT Mastic**
MATERIAL LOCATION: **Room 113,116,117/119,121/123,143,101,105,107,109,125, 127,128,137,141, cafeteria lounge**
MATERIAL QUANTITY: **11000** MATERIAL UNITS: **SF**
MATERIAL CATEGORY: **MISC** FRIABLE: **No**
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **LOW** CONDITION:
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
ACCESSIBILITY: **Not Reachable** DAMAGE REASON:
DAMAGE QUANTITY: **0** DAMAGE REASON:
DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature:



Date: **03/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates 2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **30031** BUILDING ID: **2780**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Christopher School** REVIEW DATE: **4/18/2013**
ADDRESS: **5042 S. Artesian** IDPH LICENSE NO: **100-11170**

HOMOGENEOUS AREA: **109**
MATERIAL DESCRIPTION: **12"X12" Blue W/Gray & White Streaks VFT Mastic**
MATERIAL LOCATION: **Room 113,116,117/119,121/123,143,101,105,107,109,125, 127,128,137,141, cafeteria lounge**
MATERIAL QUANTITY: **11000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____



Date: 04/18/2013

APPENDIX B

Inspector and Management Planner Licenses



Occupational Training & Supply, Inc.

7233 Adams Street • Willowbrook, IL 60527 • (630) 655-3900

Asbestos Building Inspector Refresher

Occupational Training and Supply, Inc. certifies that

Jesus Delgado


has successfully completed the 4 hour Asbestos Building Inspector Refresher Course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 10 CFR 763 Asbestos Hazard Emergency Response Act (AHERA) and TSCA Title II.

Certificate: BIR1301040034

Exam Date: 1/4/2013

Course Date: 1/4/2013

Expiration Date: 1/4/2014


Kathy DeSalvo, Director

2013



525-535 West Jefferson Street • Springfield, Illinois 62761-0001 • www.idph.state.il.us

Pat Quinn, Governor

2/7/2013

JESUS M DELGADO
5256 HARCOURT ST
OAK FOREST, IL 60452

ASBESTOS PROFESSIONAL LICENSE ID NUMBER: 11170


Enclosed is your Asbestos Professional License that expires 05/15/2014

CERTIFICATE EXPIRATION DATE

INSPECTOR 1/4/2014

PROJECT MANAGER 11/2/2013
AIR SAMPLING PROFESSIONAL

If you have any questions or need further assistance, contact the Asbestos Program at (217)782-3517 or fax (217)785-5897.
Our WEB address is <http://www.idph.state.il.us/envhealth/ehhome.htm>





Occupational Training & Supply, Inc.

7233 Adams Street • Willowbrook, IL 60527 • (630) 655-3900

Asbestos Building Inspector Refresher

Occupational Training and Supply, Inc. certifies that

Todd Huffer

has successfully completed the 4 hour Asbestos Building Inspector Refresher Course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 10 CFR 763 Asbestos Hazard Emergency Response Act (AHERA) and TSCA Title II.

Certificate: BIR1212042317

Exam Date: 12/4/2012

Course Date: 12/4/2012


Expiration Date: 12/4/2013

Kathy DeSalvo, Director

2012



Todd Huffer

Illinois Licensed Asbestos Inspector, Management Planner,
Project Manager, and Air Sampling Professional

 **ASBESTOS
PROFESSIONAL
LICENSE**

ID NUMBER 100 - 09870	ISSUED 4/4/2012	EXPIRES 05/15/2013
---------------------------------	---------------------------	------------------------------

TODD T HUFFER
918 N WOLCOTT UNIT 6
CHICAGO, IL 60622

Environmental Health

ENDORSEMENTS	TC EXPIRES
INSPECTOR	12/8/2012
MANAGEMENT PLANNER	1/19/2013
PROJECT MANAGER	9/8/2012
AIR SAMPLING PROFESSIONAL	

Alteration of this license shall result in legal action
This license issued under authority of the State of Illinois
Department of Public Health
This license is valid only when accompanied by a valid
training course certificate.

**CARNOW
CONIBEAR**



Occupational Training & Supply, Inc.

7233 Adams Street ♦ Willowbrook, IL 60527 ♦ (630) 655-3900

Asbestos Management Planner Refresher

Occupational Training and Supply, Inc. certifies that

Todd Huffer


has successfully completed the 4 hour Asbestos Management Planner Refresher Course
and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 10 CFR 763 Asbestos Hazard Emergency Response Act (AHERA) and TSCA Title II.

Certificate: MPRI302250735

Exam Date: 2/25/2013

Course Date: 2/25/2013

Expiration Date: 2/25/2014


Kathy DeSalvo, Director

2013

APPENDIX C

Laboratory Accreditations

APPENDIX D

Laboratory Results

APPENDIX E

Chain of Custody Forms

Three-Year Reinspection Key to Terms

	CODE	KEY
MATERIAL		
	ACBM	Asbestos Containing Building Materials
MATERIAL CATEGORY		
	MISC	Miscellaneous
	SURF	Surfacing
	TSI	Thermal System Insulation
MATERIAL UNITS		
	LF	Linear Feet
	SF	Square Feet
	CF	Cubic Feet
DAMAGE TYPE		
	Loc	Localized
	Dist	Distributed