

ILLINOIS DEPARTMENT OF PUBLIC HEALTH
AHERA THREE YEAR REINSPECTION
ASBESTOS ABATEMENT PROGRAM
SCHOOL INFORMATION FORM

SECTION I

NAME OF SCHOOL DISTRICT: CHICAGO SCHOOL DIST 299
SCHOOL ID NUMBER: 14-016-2990-0021
SCHOOL NAME: Hyde Park Academy
ADDRESS OF SCHOOL: 6220 S. Stony Island
CITY: Chicago, IL, 60637

DATE LAST THREE YEAR REINSPECTION WAS COMPLETED **3/19/2010**

If the address on this form is different than the address of the building, submit a written explanation.

SECTION II (Please type or print)

PLEASE COMPLETE THE FOLLOWING FOR YOUR THREE YEAR REINSPECTION:

DATE REINSPECTION COMPLETED: 3/31/2013 ENROLLMENT 1092
IDPH INSPECTOR LICENSE NUMBER: 100-02175
IDPH LICENSED INSPECTOR NAME (Please Print): Ethan Payne
IDPH MP LICENSE NUMBER: 100-03613
IDPH LICENSED MANAGEMENT PLANNER NAME (Please Print): Daniel Juneau

DESIGNATED PERSON (Please Print): Ms. Lynn Crivello PHONE: (773) 553-3113



3/31/2013

Signature of Designated Person

Date

SECTION III

PLEASE COMPLETE THE FOLLOWING INFORMATION FOR ANY CHANGES WITHIN THE SCHOOL DISTRICT.

School building has been sold. Date of Sale: _____

School has been closed. Date closed: _____

School building has been demolished. Date: _____

School building is asbestos free since last reinspection: _____

Please explain in writing why the school building is now asbestos free and include the supporting documentation.

If a new school building has been added to the district, submit either an exclusionary statement or a management plan and inspection report. Include the complete name, address and city of school building.

Explain in writing if the address of the building is different than the address on this form:

THREE-YEAR REINSPECTION

CHICAGO SCHOOL DIST 299

Hyde Park Academy

6220 S. Stony Island
Chicago, IL, 60637

Unit: 46171
Building ID: 1390

IDPH ID Number: 14-016-2990-0021

REPORT DATE:

Sunday, March 31, 2013

Prepared for:

Chicago Public Schools
125 S. Clark Street
Chicago, IL 60603

Prepared by:

Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone (312) 762-2900

Fax (312) 782-5145

**DO NOT REMOVE FROM SCHOOL
REQUIRED BY FEDERAL LAW**

Environmental Notification to Occupants

To: Faculty, Staff and Parents
From: Chicago Public Schools
Date: March 01, 2013

RE: Hyde Park Academy, Unit 46171
6220 S. Stony Island
Chicago, IL, 60637

Dear Faculty, Staff and Parents,

This letter is to notify you that the 2013 asbestos three year re-inspection has been completed at Hyde Park Academy , following the Federal Asbestos Hazard Emergency Response Act (AHERA), 40 CFR Part 763, Subpart E and is available for your review at the main office of the school.

Although asbestos-containing materials have been identified at Hyde Park Academy, there is no reason to believe that any threat to the health of students or staff exists at this time. CPS will continue to carefully monitor the condition of asbestos-containing materials and if conditions warrant, all appropriate steps will be taken to maintain the health and safety of all building occupants.

If you have any questions regarding this matter or require additional information, please feel free to contact Ms. Lynn Crivello, the designated Local Education Authority's Designated Person at (773) 553-3113 .

Table of Contents

- I. School and Inspection Information
- II. Executive Summary
- III. Methodology
- IV. Abatement History
- V. Reassessments and Recommendations
- VI. Conclusions

Table I: Inspector's Reinspection Findings

Table II: Management Planner's Review

APPENDICES:

- Appendix A: Assessment Sheets, Drawings and Photos
- Appendix B: Inspector and Management Planner Licenses
- Appendix C: Laboratory Accreditations
- Appendix D: Laboratory Results
- Appendix E: Chain of Custody Forms

SCHOOL AND INSPECTION INFORMATION

1. School Information

School: Hyde Park Academy Unit: 46171 Region: 05
Address: 6220 S. Stony Island Chicago, IL, 60637
IDPH ID: 14-016-2990-0021 Building ID: 1390
Contact: Williams, Jesse Phone: 7734699926

2. Description of Facility

Original Construction: Additional Construction:
Total Square Footage: 329400 No of Floors:
Current Occupancy: 1092

3. LEA Designated Person

Contact: Ms. Lynn Crivello Phone: (773) 553-3113
Address: 125 South Clark Street, 17th Floor
Chicago, IL 60603


4. Managing Environmental Consultant

MEC: Carnow, Conibear and Associates
Contact: Dan Juneau
Address 600 West Van Buren St., Ste 500
Phone: (312) 762-2900 Fax: (312) 782-5145

5. Inspector

Inspector Name: Ethan Payne


Inspector IDPH license # 100-02175


Signature:
Date: 3/1/2013

6. Management Planner

Management Planner Name: Daniel Juneau

Management Planner IDPH license # 100-03613


Signature:
Date: 3/31/2013

7. Review Date: 3/31/2013

8. LEA Designated Person's Acknowledgement

The reinspection report and recommendations have been received by me and appropriate action will be taken by the School District.


Signature:

Date: 3/31/2013

Name: Ms. Lynn Crivello

II. EXECUTIVE SUMMARY

Carnow, Conibear and Associates was retained by the Chicago Public Schools (CPS) to perform a three-year asbestos reinspection of the Hyde Park Academy. This inspection was conducted in accordance with the United States Environmental Protection Agency (USEPA) Asbestos Hazard Emergency Response Act (AHERA) part 763.92 (b), and the ongoing Operations and Maintenance Program (O&M) originally designed in the School's Asbestos Management Plan. The purpose of this three-year reinspection is to record any condition changes in the asbestos-containing building material (ACBM) in the school since the previous three-year reinspection and the six-month periodic surveillance, to identify, assess, and include any Homogeneous Areas (HA) not identified in the Management Plan, and to recommend an appropriate response action to manage asbestos.

The inspector conducted a three-year reinspection of this facility under Illinois Department of Public Health (IDPH) school reinspection requirements and AHERA, sections 763.85 and 763.88. The main building and each addition to the main building, if constructed at different dates, were inspected separately. Laboratory accreditations are included in Appendix C, laboratory results are included in Appendix D, and chain of custody forms are included in Appendix E.

Note: During previous inspections, some of the HA(s) were identified together as 9" x 9" floor tile (FT), mastics assoc. with 9" x 9" FT, 12" x 12" FT, mastics assoc. with 12" x 12" FT, pipe insulation, etc. Some of these HA(s) have been re-identified by areas that are uniform in color, texture, construction date, application date, and general appearance.

The inspector has determined the following:

A. The following HAs have changed assessment categories for Building 1390:

01	plaster
03	hard plaster
05	12x12 ceiling tile
07	2x4 pinhole ceiling tile
24	2' ceiling tile
25	2' ceiling tile
27	9x9 med.brn. F.T.
29	12x12 lt. Brn. F.T.
34	12x12 lt. Brn. F.T.

37	12x12 off-white F.T.
38	12x12 white F.T.
42	12x12 lt. Brn. F.T.
44	9x9 tan F.T.
52	12x12 dark tan F.T. mastic
55	12x12 white F.T. mastic
64	12x12 ceiling tile text
65	12x12 ceiling tile text mastic
66	ceiling/tile system
67	12x12 ceiling tile mastic
68	2'x4' ceiling tile
69	drop-in ceiling tile
70	2'x4' ceiling tile
71	black trim vinyl baseboard
73	blk. Trim vinyl baseboard
75	black trim vinyl baseboard
77	transite wind/sill
78	transite windowsill
79	grey carpet mastic
80	green carpet mastic
81	brown carpet mastic
82	dr. orange carpet mastic
83	orange carpet mastic

B. The following new homogenous areas have been identified for Building 1390:

C. This reinspection covered only physically accessible and visible areas and materials that were identified in the LEA's management plan. The following materials were concealed and/or contained in areas that were inaccessible for sampling and have been classified as Assumed:

01	plaster
03	hard plaster
05	12x12 ceiling tile
07	2x4 pinhole ceiling tile
08	2x4 perforated ceiling tile
09	ceiling tectum panels
12	12x12 metal ceiling tile
16	12x12 ceiling tile text (material not observed)
24	2' ceiling tile
25	2' ceiling tile
27	9x9 med.brn. F.T.
29	12x12 lt. Brn. F.T.
34	12x12 lt. Brn. F.T.
37	12x12 off-white F.T.
38	12x12 white F.T.
42	12x12 lt. Brn. F.T.
44	9x9 tan F.T.
52	12x12 dark tan F.T. mastic
55	12x12 white F.T. mastic
64	12x12 ceiling tile text
65	12x12 ceiling tile text mastic
66	ceiling/tile system
67	12x12 ceiling tile mastic
68	2'x4' ceiling tile
69	drop-in ceiling tile
70	2'x4' ceiling tile
71	black trim vinyl baseboard
75	black trim vinyl baseboard
77	transite wind/sill
78	transite windowsill
79	grey carpet mastic
80	green carpet mastic
81	brown carpet mastic
82	dr. orange carpet mastic
83	orange carpet mastic
84	12" x 12" Light gray with white floor tile
85	Mastic for 12" x 12" Light gray with white floor tile
86	Gray mix Terrazzo
87	12" x 12" White w/gray and black floor tile
88	Mastic for 12" x 12" white with gray and black floor tile
89	12" x 12" white with blue and red floor tile
90	Mastic for 12" x 12" white with Blue and Ref floor tile
91	Black Chalk boards

92	Black Chalk Board Adhesive
HA-1000	Glue for 1'x1' white ceiling tile with grooves
HA-1001	new 2'x2' white ceiling tile
HA-1002	new 2'x4' white ceiling tile
HA-1003	Black sink unsealing
P	2'x2' WHITE CEILING TILE
Q	LINOLEUM FLOORING Grey with white
Q-1	LINOLEUM FLOORING-MASTIC
R	12x12 BROWN VFT
R-1	12x12 BROWN VFT-MASTIC
S	12x12 BLUE VFT
S-1	12x12 BLUE VFT-MASTIC
T	12x12 ORANGE W/ GREEN VFT
T-1	12x12 ORANGE W/ GREEN VFT-MASTIC

The following areas were deemed to be inaccessible:

04	12x12 ceiling tile text
09	ceiling tectum panels
12	12x12 metal ceiling tile
18	9x9 light brown F.T. mastic
19	9x9 tan F.T. mastic
20	9x9 med. Brn. F.T. mastic
21	12x12 tan F.T. mastic
22	12x12 tan F.T. mastic
23	12x12 lt. Brn. Tile mastic
47	9x9 med. brn. F.T. mastic
48	9x9 tan F.T. mastic
49	12x12 beige F.T. Mastic
50	12x12 brown F.T. mastic
52	12x12 dark tan F.T. mastic
53	12x12 lt. Grn. F.T. mastic
54	12x12 off-white F.T. mastic
56	12x12 Tan speckled F.T. mastic
57	9x9 brown F.T. mastic
58	9x9 drk.brn. F.T. mastic
59	12x12 lt. Brn. F.T. mastic
60	9x9 med. Brn. F.T. mastic
61	9x9 tan F.T. mastic
62	9x9 brown F.T. mastic
65	12x12 ceiling tile text mastic
67	12x12 ceiling tile mastic
72	black trim vinyl baseboard mastic
74	blk. Trim vinyl baseboard mastic
76	black trim vinyl baseboard mastic
79	grey carpet mastic
80	green carpet mastic
81	brown carpet mastic

82	dr. orange carpet mastic
83	orange carpet mastic
85	Mastic for 12" x 12" Light gray with white floor tile
88	Mastic for 12" x 12" white with gray and black floor tile
90	Mastic for 12" x 12" white with Blue and Ref floor tile
92	Black Chalk Board Adhesive
I	cardboard fittings
J	fiberglass fittings
K	aircell duct insulation
L	aircell pipe insulation
N	fiber glass fittings
Q-1	LINOLEUM FLOORING-MASTIC
R-1	12x12 BROWN VFT-MASTIC
S-1	12x12 BLUE VFT-MASTIC
T-1	12x12 ORANGE W/ GREEN VFT-MASTIC

Materials were also listed as "assumed" if they were in good condition and sampling was not conducted to avoid damage.

This reinspection was conducted by Ethan Payne, IDPH License # 100-02175. The Management Plan was updated by Daniel Juneau, IDPH License # 100-03613. Inspector and Management Planner Licenses are included in Appendix B.

III. METHODOLOGY

Tasks performed on-site included the following:

1. Review current management plan, identify HA(s) and extract appropriate information.
2. Examine and verify abatement records.
3. Touch and visually and physically reinspect and reassess the condition of all friable known or assumed ACBM.
4. Touch and visually and physically reinspect all non-friable known or assumed ACBM to determine whether these materials have become friable since the last inspection or periodic surveillance.
5. Identify any condition changes that may affect Hazard Ranking of known ACBM or Assumed ACBM, as well as any HA(s) that have become friable since the last reinspection.
6. Collect bulk samples from each newly discovered friable HA or previously assumed and submit for laboratory analysis.
7. Tabulate reinspection findings and submit for management planner review and recommendations with appropriate response actions based on the AHERA Damage Category of the ACBM.
8. Submit reinspection findings and management planner recommendations to the LEA within thirty (30) days for inclusion into the management plan.

IV. ABATEMENT HISTORY

The information collected from the existing management plan and inspection report(s) and from interviews with the school official revealed that the following asbestos abatement was conducted at the school since the previous Three year Reinspection.

Abatement Dates:

V. REASSESSMENTS AND RECOMMENDATIONS

The reassessments and recommendations are summarized in Tables I and II on the following pages. Detailed Hazard Assessment Sheets and Drawings and Photos (if applicable) are included in Appendix A.

VI. CONCLUSIONS

The Hyde Park Academy Building 1390 Three-Year reinspection has been completed and response actions have been recommended for both friable and non-friable materials. A timely execution of the response actions recommended will enable the LEA and the Designated Person(s) to effectively manage the existing ACBM.

This three-year reinspection report should be inspected in the current Management plan at the CPS Central Office, and one (1) copy should be kept at the school for use when planning any renovation and/or demolition activities in areas where ACBM has been identified. Also, periodic surveillance documentation and any summary reports from any response actions that are executed at the school should be used to update the Management Plan.

Table I
Inspector's Reinspection Findings

Chicago Public Schools

School Hyde Park Academy Unit 46171 Building ID 1390

Address 6220 S. Stony Island Region 05

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
01	plaster	140,000	SF	building 1911	ASSUMED	SURFACE	N	NONE	0		Yes	ACBM with the potential for damage		MODERATE
02	hard plaster	140,000	SF	building 1937	CHR	SURFACE	Y	NONE	0		No	ACBM with the potential for damage		MODERATE
03	hard plaster	140,000	SF	building 1970	ASSUMED	SURFACE	N	NONE	0		Yes	ACBM with the potential for damage		MODERATE
04	12x12 ceiling tile text	700	SF	1937 building room 142	CHR	MISC	Y	NONE	0		No	ACBM with the potential for damage		MODERATE
05	12x12 ceiling tile	10,000	SF	1937 building	ASSUMED	MISC	Y	NONE	0		Yes	ACBM with the potential for damage		MODERATE
06	2x2 ceiling tile	34,500	SF	1911 building	AMO	MISC	Y	NONE	0		No	ACBM with potential for significant damage		MODERATE
07	2x4 pinhole ceiling tile	34,500	SF	1911 building	ASSUMED	MISC	Y	NONE	0		Yes	ACBM with the potential for damage		MODERATE
08	2x4 perforated ceiling tile	1,500	SF	1911 building	ASSUMED	MISC	Y	NONE	0		No	ACBM with the potential for damage		LOW
09	ceiling tectum panels	13,000	SF	1911 buildings (50 ft. in air inaccessible to sample)	ASSUMED	MISC	Y	NONE	0		No	ACBM with the potential for damage		LOW
10	9x9 light brown F.T.	16,800	SF	SEE COMMENTS FOR ROOM LOCATIONS	CHR	MISC	N	DIST	120		No	ACBM with the potential for damage		MODERATE
11	12x12 tan F.T.	99,000	SF	SEE COMMENTS FOR ROOM LOCATIONS	CHR	MISC	N	DIST	100		No	ACBM with the potential for damage		MODERATE
12	12x12 metal ceiling tile	3,750	SF	1911 natatorium (ceiling is inaccessible)	ASSUMED	MISC	Y	NONE	0		No	ACBM with the potential for damage		LOW
13	transite table tops	3,200	SF	Science labs	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
14	transite panel material	150	SF	Science labs 312, 316	CHR	MISC	Y	NONE	0		No	ACBM with the potential for damage		LOW
15	acoustical ceiling tile (no material)			1911 building	UNDEFINED									
16	12x12 ceiling tile text (material not observed)			1937 building	ASSUMED	MISC								
17	spray-on fireproofing	45,000	SF	BLDG 1911 above 2nd & 3rd floor ceiling tile	CHR	SURFACE	Y	NONE	0		No	ACBM with potential for significant damage		MODERATE
18	9x9 light brown F.T. mastic	16,800	SF	SEE COMMENTS FOR ROOM LOCATIONS	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
19	9x9 tan F.T. mastic	11,400	SF	1st, 2nd & 3rd floor south hallways	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW

Chicago Public Schools

School Hyde Park Academy Unit 46171 Building ID 1390

Address 6220 S. Stony Island Region 05

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
20	9x9 med. Brn. F.T. mastic	21,000	SF	SEE COMMENTS FOR ROOM LOCATIONS	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
21	12x12 tan F.T. mastic	99,000	SF	SEE COMMENTS FOR ROOM LOCATIONS	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
22	12x12 tan F.T. mastic	900	SF	1937 building, patched areas of 1st, 2nd flr hallway	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
23	12x12 lt. Brn. Tile mastic	1,700	SF	1970 building, weight room	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
24	2' ceiling tile	14,000	SF	1937 building	ASSUMED	MISC	Y	NONE	0		Yes	ACBM with the potential for damage		LOW
25	2' ceiling tile	1,200	SF	1970/ rear of rm. 143 2nd flr. S/W corridor	ASSUMED	MISC	Y	NONE	0		Yes	ACBM with the potential for damage		LOW
26	9x9 tan F.T.	11,400	SF	1st, 2nd & 3rd floor south hallways	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
27	9x9 med.brn. F.T.	21,000	SF	SEE COMMENTS FOR ROOM LOCATIONS	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
28	12x12 tan F.T.	900	SF	1937 building, patched areas of 1st, 2nd flr hallway	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
29	12x12 lt. Brn. F.T.	1,700	SF	1970 building, weight room	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
30	9x9 med. Brn. F.T.	2,500	SF	Room 246, southeastern hall on 2nd floor	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
31	9x9 tan F.T.	1,300	SF	Room 210, 311	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
32	12x12 beige F.T.	750	SF	Small hallways leading to library on 2nd and 3rd floors.	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
33	12x12 brown F.T.	4,000	SF	Locker rooms 1st floor	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
34	12x12 lt. Brn. F.T.	11,000	SF	1911 building	ASSUMED	MISC	N	NONE	0		Yes	Any remaining friable ACBM or friable suspect ACBM		MODERATE
35	12x12 dark tan F.T.	800	SF	1911 building, patched areas	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
36	12x12 lt. Grn. F.T.	1,600	SF	Room 133	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
37	12x12 off-white F.T.	1,825	SF	Engineer's office	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the		LOW

Chicago Public Schools

School Hyde Park Academy Unit 46171 Building ID 1390

Address 6220 S. Stony Island Region 05

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
												potential for damage		
38	12x12 white F.T.	2,500	SF	Rooms 135, 137	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		MODERATE
39	12x12 Tan speckled F.T.	490	SF	Patched areas of 1st flr north hallway	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
40	9x9 brown F.T.	950	SF	1937 building, patched areas of 1st, 2nd, 3rd flr hallways	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
41	9x9 drk.brn. F.T.	75	SF	1937 building, patched areas of 1st, 2nd, 3rd flr hallways	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
42	12x12 lt. Brn. F.T.	1,500	SF	1937 building, patched areas of 1st, 2nd & 3rd floor south hallways	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		MODERATE
43	9x9 med. Brn. F.T.	1,800	SF	Team, Visitor, Boy's & Girl's Locker Rooms	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
44	9x9 tan F.T.	425	SF	1937 building	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		MODERATE
45	9x9 brown F.T.	3,100	SF	SEE COMMENTS FOR ROOM LOCATIONS	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
46	9x9 brown F.T.	600	SF	Patched areas of 1st, 2nd & 3rd floor south hallways	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
47	9x9 med. brn. F.T. mastic	2,500	SF	Room 246, southeastern hall on 2nd floor	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
48	9x9 tan F.T. mastic	1,300	SF	Room 210, 311	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
49	12x12 beige F.T. Mastic	750	SF	Small hallways leading to library on 2nd and 3rd floors.	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
50	12x12 brown F.T. mastic	4,000	SF	Locker rooms 1st floor	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
51	12x12 lt. Brn. F.T. mastic			Auditorium	ABATED	MISC								
52	12x12 dark tan F.T. mastic	800	SF	1911 building, patched areas	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
53	12x12 lt. Grn. F.T. mastic	1,600	SF	Room 133	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
54	12x12 off-white F.T. mastic	1,825	SF	Engineer's office	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
55	12x12 white F.T. mastic	2,500	SF	Rooms 135, 137	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the		LOW

Chicago Public Schools

School Hyde Park Academy Unit 46171 Building ID 1390

Address 6220 S. Stony Island Region 05

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
												potential for damage		
56	12x12 Tan speckled F.T. mastic	490	SF	Patched areas of 1st flr north hallway	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
57	9x9 brown F.T. mastic	950	SF	1937 building, patched areas of 1st, 2nd, 3rd flr hallways	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
58	9x9 drk.brn. F.T. mastic	75	SF	1937 building, patched areas of 1st, 2nd, 3rd flr hallways	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
59	12x12 lt. Brn. F.T. mastic	1,500	SF	1937 building, patched areas of 1st, 2nd & 3rd floor south hallways	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
60	9x9 med. Brn. F.T. mastic	1,800	SF	Team, Visitor, Boy's & Girl's Locker Rooms	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
61	9x9 tan F.T. mastic	425	SF	1937 building	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
62	9x9 brown F.T. mastic	3,100	SF	SEE COMMENTS FOR ROOM LOCATIONS	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
63	9x9 lt. Brn. F.T. mastic	600	SF	Patched areas of 1st, 2nd & 3rd floor south hallways	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
64	12x12 ceiling tile text	25,000	SF	1911 building	ASSUMED	MISC	Y	NONE	0		Yes	ACBM with the potential for damage		LOW
65	12x12 ceiling tile text mastic	25,000	SF	1911 building	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
66	ceiling/tile system	15,000	SF	1911 building	ASSUMED	MISC	Y	NONE	0		Yes	Any remaining friable ACBM or friable suspect ACBM		LOW
67	12x12 ceiling tile mastic	1,300	SF	1937 building	ASSUMED	MISC	N	UNKNO WN	0		Yes	ACBM with the potential for damage		LOW
68	2'x4' ceiling tile	800	SF	1937 building	ASSUMED	MISC	Y	NONE	0		Yes	Any remaining friable ACBM or friable suspect ACBM		LOW
69	drop-in ceiling tile	8,500	SF	1937 building	ASSUMED	MISC	Y	NONE	0		Yes	Any remaining friable ACBM or friable suspect ACBM		LOW
70	2'x4' ceiling tile	1,200	SF	1970 building	ASSUMED	MISC	Y	NONE	0		Yes	Any remaining friable ACBM or friable suspect ACBM		LOW
71	black trim vinyl baseboard	18,000	LF	1911 building	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW

Chicago Public Schools

School Hyde Park Academy Unit 46171 Building ID 1390

Address 6220 S. Stony Island Region 05

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
72	black trim vinyl baseboard mastic	18,000	LF	1911 building	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
73	blk. Trim vinyl baseboard	275	LF	1937 building	CHR	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
74	blk. Trim vinyl baseboard mastic	275	LF	1937 building	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
75	black trim vinyl baseboard	300	LF	1970 building	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
76	black trim vinyl baseboard mastic	300	LF	1970 building	CHR	MISC	N	UNKNO WN	0		No	ACBM with the potential for damage		LOW
77	transite wind/sill	3,000	SF	1911 building	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
78	transite windowsill	550	SF	1937 building	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
79	grey carpet mastic	950	SF	1911 building	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
80	green carpet mastic	1,900	SF	1911 building	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
81	brown carpet mastic	1,200	SF	1911 building	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
82	dr. orange carpet mastic	15,000	SF	1911 building	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
83	orange carpet mastic	21,000	SF	1911 building	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
84	12" x 12" Light gray with white floor tile	3,000	SF	Auditorium	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
85	Mastic for 12" x 12" Light gray with white floor tile	3,000	SF	Auditorium	ASSUMED	MISC	N	UNKNO WN	0		No	ACBM with the potential for damage		LOW
86	Gray mix Terrazzo	5,000	SF	Entrance and stairwells	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
87	12" x 12" White w/gray and black floor tile	3,200	SF	Room 114 and patches in room 210	ASSUMED	MISC	N	UNKNO WN	0		No	ACBM with the potential for damage		MODERATE
88	Mastic for 12" x 12" white with gray and black floor tile	500	SF	Room 114 and patches in Room 210	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
89	12" x 12" white with blue and red floor tile	1,800	SF	Room 117	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
90	Mastic for 12" x 12" white with Blue and Ref floor tile	1,800	SF	Room 117	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
91	Black Chalk boards	13,000	SF	Classrooms	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
92	Black Chalk Board Adhesive	13,000	SF	Classrooms	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
A	Mag block			boiler	ABATED	TSI		None						

Chicago Public Schools

School Hyde Park Academy Unit 46171 Building ID 1390

Address 6220 S. Stony Island Region 05

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
B	mag block			garage	ABATED	TSI								
C	mag block			suspended in pump room	ABATED	TSI								
D	mag block ABATED			pump rm.	ABATED	TSI								
E	mag block			boiler room	ABATED	TSI								
F	preform pipe			boiler room & tunnel	ABATED	TSI		None						Moderate
G	preform fittings			basement & tunnels	ABATED	TSI		None						Moderate
H	cardboard pipe insulation			compressor rm./ pump rm. Absorption rm./ tunnels	ABATED	TSI								
HA-1000	Glue for 1'x1' white ceiling tile with grooves	34,500	SF	Rm. 301, 303, 305, 307, 309, 311	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
HA-1001	new 2'x2' white ceiling tile	35,000	SF	throughout 1st and 3rd floor	ASSUMED	MISC	Y	NONE	0		No	ACBM with the potential for damage		LOW
HA-1002	new 2'x4' white ceiling tile	35,000	SF	throughout 1st and 3rd floors	ASSUMED	MISC	Y	NONE	0		No	ACBM with the potential for damage		LOW
HA-1003	Black sink unsercoating	15	SF	Art rooms 401, 402, 406	ASSUMED	MISC	N	NONE	0		No			LOW
I	cardboard fittings	40	LF	tunnels/compressor rm.	CHR	TSI	Y	NONE	0		No	ACBM with the potential for damage		MODERATE
J	fiberglass fittings	1,800	LF	1911 building	CHR	TSI	Y	LOC	0		No	ACBM with the potential for damage		LOW
K	aircell duct insulation	30	SF	tunnels	CHR	TSI	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
L	aircell pipe insulation	2,240	LF	pump rm. Tunnels	CHR	TSI	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
M	fittings on aircell	140	LF	pump room 1911	CHR	TSI	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
N	fiber glass fittings	400	LF	1937 building	CHR	TSI	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		MODERATE
O	fiberglass fittings			1970bldg		MISC		None						Moderate
P	2'x2' WHITE CEILING TILE	69,000	SF	THROUGHOUT 1911 BLDG	ASSUMED	MISC	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
Q	LINOLEUM FLOORING Grey with white	2,000	SF	ROOM 245, and 343	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
Q-1	LINOLEUM FLOORING-MASTIC	950	SF	ROOM 245, and 343	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW

Chicago Public Schools

School Hyde Park Academy Unit 46171 Building ID 1390

Address 6220 S. Stony Island Region 05

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
R	12x12 BROWN VFT	2,300	SF	ROOMS 341, 333	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
R-1	12x12 BROWN VFT-MASTIC	2,300	SF	ROOMS 341, 333	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
S	12x12 BLUE VFT	3,250	SF	EAST STAIRWELL, FRONT OF AUDITORIUM & ALL OF AUDITORIUM	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
S-1	12x12 BLUE VFT-MASTIC	3,250	SF	EAST STAIRWELL, FRONT OF AUDITORIUM & ALL OF AUDITORIUM	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
T	12x12 ORANGE W/ GREEN VFT	450	SF	BACK STAGE OF AUDITORIUM W/ HALLWAY	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
T-1	12x12 ORANGE W/ GREEN VFT-MASTIC	450	SF	BACK STAGE OF AUDITORIUM W/ HALLWAY	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW

Chicago Public Schools

School Hyde Park Academy Unit 46171 Building ID 1390

Address 6220 S. Stony Island Region 05

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

Reinspection Date 3/1/2013
Inspector Name Ethan Payne
100-02175 5/15/2013
Inspector's IDPH License Number / Expiration Date

Inspector's Comments

HA Number:	Inspector Comments:
01	
02	
03	
04	
05	
06	
07	
08	
09	
10	
11	
12	
13	
14	
15	Material Removed 2013
16	Material Removed 2013
17	
18	142-145, 140,138,136,132,130,240,238,236,232,210,345,346,344,303,305,307,309,311,340,33 8,336,334,332
19	
20	
21	
22	

Chicago Public Schools

School Hyde Park Academy Unit 46171 Building ID 1390

Address 6220 S. Stony Island Region 05

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
23	
24	
25	
26	
27	
28	
29	
30	
31	
32	
33	
34	
35	
36	
37	
38	
39	
40	
41	
42	
43	
44	
45	142-145, 140,138,136,132,130,240,238,236,232,210,345,346,344,303,305,307,309,311,340,33 8,336,334,332
46	
47	
48	
49	

Chicago Public Schools

School Hyde Park Academy Unit 46171 Building ID 1390

Address 6220 S. Stony Island Region 05

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
50	
51	
52	
53	
54	
55	
56	
57	
58	
59	
60	
61	
62	142-145, 140,138,136,132,130,240,238,236,232,210,345,346,344,303,305,307,309,311,340,33 8,336,334,332
63	
64	
65	
66	
67	
68	
69	
70	
71	
72	
73	
74	
75	
76	

Chicago Public Schools

School Hyde Park Academy Unit 46171 Building ID 1390

Address 6220 S. Stony Island Region 05

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
77	
78	
79	
80	
81	
82	
83	
84	
85	
86	
87	
88	
89	
90	
91	
92	
A	
B	
C	
D	
E	
F	Material Abated, some material may exist in tunnels
G	
H	
HA-1000	
HA-1001	
HA-1002	
HA-1003	
I	

Chicago Public Schools

School Hyde Park Academy Unit 46171 Building ID 1390

Address 6220 S. Stony Island Region 05

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
J	
K	
L	
M	
N	
O	Fiberglass not suspect material
P	
Q	
Q-1	
R	
R-1	
S	
S-1	
T	
T-1	

Table II

Management Planner's Review

Chicago Public Schools

School Hyde Park Academy

Unit 46171

Building ID 1390

Address 6220 S. Stony Island

Chicago, IL, 60637

Region 05

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
01	plaster	140,000	SF	building 1911	Assumed	SURFACE	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
02	hard plaster	140,000	SF	building 1937	Chrysotile	SURFACE	Yes	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
03	hard plaster	140,000	SF	building 1970	Assumed	SURFACE	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
04	12x12 ceiling tile text	700	SF	1937 building room 142	Chrysotile	MISC	Yes	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
05	12x12 ceiling tile	10,000	SF	1937 building	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
06	2x2 ceiling tile	34,500	SF	1911 building	Amosite	MISC	Yes	0	SF	5 ACBM with potential for significant damage	Operations and Maintenance
07	2x4 pinhole ceiling tile	34,500	SF	1911 building	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
08	2x4 perforated ceiling tile	1,500	SF	1911 building	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
09	ceiling tectum panels	13,000	SF	1911 buildings (50 ft. in air inaccessible to sample)	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
10	9x9 light brown F.T.	16,800	SF	SEE COMMENTS FOR ROOM LOCATIONS	Chrysotile	MISC	No	120	SF	6 ACBM with the potential for damage	Operations and Maintenance
11	12x12 tan F.T.	99,000	SF	SEE COMMENTS FOR ROOM LOCATIONS	Chrysotile	MISC	No	100	SF	6 ACBM with the potential for damage	Operations and Maintenance
12	12x12 metal ceiling tile	3,750	SF	1911 natatorium (ceiling is inaccessible)	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
13	transite table tops	3,200	SF	Science labs	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
14	transite panel material	150	SF	Science labs 312, 316	Chrysotile	MISC	Yes	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
15	accoustical ceiling tile (no material)			1911 building	Undefined						
16	12x12 ceiling tile text (material not observed)			1937 building	Assumed	MISC					
17	spray-on fireproofing	45,000	SF	BLDG 1911 above 2nd & 3rd floor ceiling tile	Chrysotile	SURFACE	Yes	0	SF	5 ACBM with potential for significant damage	Operations and Maintenance
18	9x9 light brown F.T. mastic	16,800	SF	SEE COMMENTS FOR ROOM LOCATIONS	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
19	9x9 tan F.T. mastic	11,400	SF	1st, 2nd & 3rd floor south hallways	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
20	9x9 med. Brn. F.T. mastic	21,000	SF	SEE COMMENTS FOR ROOM LOCATIONS	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
21	12x12 tan F.T. mastic	99,000	SF	SEE COMMENTS FOR ROOM LOCATIONS	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
22	12x12 tan F.T. mastic	900	SF	1937 building, patched areas of 1st, 2nd flr hallway	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
23	12x12 lt. Brn. Tile mastic	1,700	SF	1970 building, weight room	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
24	2' ceiling tile	14,000	SF	1937 building	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
25	2' ceiling tile	1,200	SF	1970/ rear of rm. 143 2nd flr. S/W corridor	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Operations and Maintenance

Chicago Public Schools

School Hyde Park Academy
Address 6220 S. Stony Island

Unit 46171
 Chicago, IL, 60637

Building ID 1390
Region 05

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
26	9x9 tan F.T.	11,400	SF	1st, 2nd & 3rd floor south hallways	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
27	9x9 med.brn. F.T.	21,000	SF	SEE COMMENTS FOR ROOM LOCATIONS	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
28	12x12 tan F.T.	900	SF	1937 building, patched areas of 1st, 2nd flr hallway	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
29	12x12 lt. Brn. F.T.	1,700	SF	1970 building, weight room	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
30	9x9 med. Brn. F.T.	2,500	SF	Room 246, southeastern hall on 2nd floor	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
31	9x9 tan F.T.	1,300	SF	Room 210, 311	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
32	12x12 beige F.T.	750	SF	Small hallways leading to library on 2nd and 3rd floors.	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
33	12x12 brown F.T.	4,000	SF	Locker rooms 1st floor	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
34	12x12 lt. Brn. F.T.	11,000	SF	1911 building	Assumed	MISC	No	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Operations and Maintenance
35	12x12 dark tan F.T.	800	SF	1911 building, patched areas	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
36	12x12 lt. Grn. F.T.	1,600	SF	Room 133	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
37	12x12 off-white F.T.	1,825	SF	Engineer's office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
38	12x12 white F.T.	2,500	SF	Rooms 135, 137	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
39	12x12 Tan speckled F.T.	490	SF	Patched areas of 1st flr north hallway	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
40	9x9 brown F.T.	950	SF	1937 building, patched areas of 1st, 2nd, 3rd flr hallways	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
41	9x9 drk.brn. F.T.	75	SF	1937 building, patched areas of 1st, 2nd, 3rd flr hallways	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
42	12x12 lt. Brn. F.T.	1,500	SF	1937 building, patched areas of 1st, 2nd & 3rd floor south hallways	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
43	9x9 med. Brn. F.T.	1,800	SF	Team, Visitor, Boy's & Girl's Locker Rooms	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
44	9x9 tan F.T.	425	SF	1937 building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
45	9x9 brown F.T.	3,100	SF	SEE COMMENTS FOR ROOM LOCATIONS	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
46	9x9 brown F.T.	600	SF	Patched areas of 1st, 2nd & 3rd floor south hallways	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
47	9x9 med. brn. F.T. mastic	2,500	SF	Room 246, southeastern hall on 2nd floor	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
48	9x9 tan F.T. mastic	1,300	SF	Room 210, 311	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
49	12x12 beige F.T. Mastic	750	SF	Small hallways leading to library on 2nd	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance

Chicago Public Schools

School Hyde Park Academy
Address 6220 S. Stony Island

Unit 46171
Chicago, IL, 60637

Building ID 1390
Region 05

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
				and 3rd floors.							
50	12x12 brown F.T. mastic	4,000	SF	Locker rooms 1st floor	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
51	12x12 lt. Brn. F.T. mastic			Auditorium	Abated	MISC					
52	12x12 dark tan F.T. mastic	800	SF	1911 building, patched areas	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
53	12x12 lt. Grn. F.T. mastic	1,600	SF	Room 133	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
54	12x12 off-white F.T. mastic	1,825	SF	Engineer's office	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
55	12x12 white F.T. mastic	2,500	SF	Rooms 135, 137	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
56	12x12 Tan speckled F.T. mastic	490	SF	Patched areas of 1st flr north hallway	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
57	9x9 brown F.T. mastic	950	SF	1937 building, patched areas of 1st, 2nd, 3rd flr hallways	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
58	9x9 drk.brn. F.T. mastic	75	SF	1937 building, patched areas of 1st, 2nd, 3rd flr hallways	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
59	12x12 lt. Brn. F.T. mastic	1,500	SF	1937 building, patched areas of 1st, 2nd & 3rd floor south hallways	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
60	9x9 med. Brn. F.T. mastic	1,800	SF	Team, Visitor, Boy's & Girl's Locker Rooms	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
61	9x9 tan F.T. mastic	425	SF	1937 building	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
62	9x9 brown F.T. mastic	3,100	SF	SEE COMMENTS FOR ROOM LOCATIONS	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
63	9x9 lt. Brn. F.T. mastic	600	SF	Patched areas of 1st, 2nd & 3rd floor south hallways	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
64	12x12 ceiling tile text	25,000	SF	1911 building	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
65	12x12 ceiling tile text mastic	25,000	SF	1911 building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
66	ceiling/tile system	15,000	SF	1911 building	Assumed	MISC	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Operations and Maintenance
67	12x12 ceiling tile mastic	1,300	SF	1937 building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
68	2'x4' ceiling tile	800	SF	1937 building	Assumed	MISC	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Operations and Maintenance
69	drop-in ceiling tile	8,500	SF	1937 building	Assumed	MISC	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Operations and Maintenance
70	2'x4' ceiling tile	1,200	SF	1970 building	Assumed	MISC	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Operations and Maintenance
71	black trim vinyl baseboard	18,000	LF	1911 building	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Operations and Maintenance
72	black trim vinyl baseboard mastic	18,000	LF	1911 building	Chrysotile	MISC	No	0	LF	6 ACBM with the potential for damage	Operations and Maintenance
73	blk. Trim vinyl baseboard	275	LF	1937 building	Chrysotile	MISC	No	0	LF	6 ACBM with the potential for damage	Operations and Maintenance

Chicago Public Schools

School Hyde Park Academy
Address 6220 S. Stony Island

Unit 46171
 Chicago, IL, 60637

Building ID 1390
Region 05

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
74	blk. Trim vinyl baseboard mastic	275	LF	1937 building	Chrysotile	MISC	No	0	LF	6 ACBM with the potential for damage	Operations and Maintenance
75	black trim vinyl baseboard	300	LF	1970 building	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Operations and Maintenance
76	black trim vinyl baseboard mastic	300	LF	1970 building	Chrysotile	MISC	No	0	LF	6 ACBM with the potential for damage	Operations and Maintenance
77	transite wind/sill	3,000	SF	1911 building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
78	transite windowsill	550	SF	1937 building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
79	grey carpet mastic	950	SF	1911 building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
80	green carpet mastic	1,900	SF	1911 building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
81	brown carpet mastic	1,200	SF	1911 building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
82	dr. orange carpet mastic	15,000	SF	1911 building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
83	orange carpet mastic	21,000	SF	1911 building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
84	12" x 12" Light gray with white floor tile	3,000	SF	Auditorium	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
85	Mastic for 12" x 12" Light gray with white floor tile	3,000	SF	Auditorium	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
86	Gray mix Terrazzo	5,000	SF	Entrance and stairwells	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
87	12" x 12" White w/gray and black floor tile	3,200	SF	Room 114 and patches in room 210	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
88	Mastic for 12" x 12" white with gray and black floor tile	500	SF	Room 114 and patches in Room 210	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
89	12" x 12" white with blue and red floor tile	1,800	SF	Room 117	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
90	Mastic for 12" x 12" white with Blue and Ref floor tile	1,800	SF	Room 117	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
91	Black Chalk boards	13,000	SF	Classrooms	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
92	Black Chalk Board Adhesive	13,000	SF	Classrooms	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
A	Mag block			boiler	Abated	TSI					
B	mag block			garage	Abated	TSI					
C	mag block			suspended in pump room	Abated	TSI					
D	mag block ABATED			pump rm.	Abated	TSI					
E	mag block			boiler room	Abated	TSI					
F	preform pipe			boiler room & tunnel	Abated	TSI					
G	preform fittings			basement & tunnels	Abated	TSI					
H	cardboard pipe insulation			compressor rm./ pump rm. Absorption rm./ tunnels	Abated	TSI					
HA-1000	Glue for 1'x1' white ceiling tile with grooves	34,500	SF	Rm. 301, 303, 305, 307, 309, 311	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
HA-1001	new 2'x2' white ceiling tile	35,000	SF	throughout 1st and 3rd floor	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
HA-	new 2'x4' white ceiling tile	35,000	SF	throughout 1st and 3rd floors	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Operations and Maintenance

Chicago Public Schools

School Hyde Park Academy

Unit 46171

Building ID 1390

Address 6220 S. Stony Island

Chicago, IL, 60637

Region 05

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
1002											
HA-1003	Black sink unsercoating	15	SF	Art rooms 401, 402, 406	Assumed	MISC	No	0	SF		Operations and Maintenance
I	cardboard fittings	40	LF	tunnels/compressor rm.	Chrysotile	TSI	Yes	0	LF	6 ACBM with the potential for damage	Operations and Maintenance
J	fiberglass fittings	1,800	LF	1911 building	Chrysotile	TSI	Yes	0	LF	6 ACBM with the potential for damage	Operations and Maintenance
K	aircell duct insulation	30	SF	tunnels	Chrysotile	TSI	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Operations and Maintenance
L	aircell pipe insulation	2,240	LF	pump rm. Tunnels	Chrysotile	TSI	Yes	0	LF	7 Any remaining friable ACBM or friable suspect ACBM	Operations and Maintenance
M	fittings on aircell	140	LF	pump room 1911	Chrysotile	TSI	Yes	0	LF	7 Any remaining friable ACBM or friable suspect ACBM	Operations and Maintenance
N	fiber glass fittings	400	LF	1937 building	Chrysotile	TSI	Yes	0	LF	7 Any remaining friable ACBM or friable suspect ACBM	Operations and Maintenance
O	fiberglass fittings			1970bldg		MISC					
P	2'x2' WHITE CEILING TILE	69,000	SF	THROUGHOUT 1911 BLDG	Assumed	MISC	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Operations and Maintenance
Q	LINOLEUM FLOORING Grey with white	2,000	SF	ROOM 245, and 343	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
Q-1	LINOLEUM FLOORING-MASTIC	950	SF	ROOM 245, and 343	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
R	12x12 BROWN VFT	2,300	SF	ROOMS 341, 333	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
R-1	12x12 BROWN VFT-MASTIC	2,300	SF	ROOMS 341, 333	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
S	12x12 BLUE VFT	3,250	SF	EAST STAIRWELL, FRONT OF AUDITORIUM & ALL OF AUDITORIUM	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
S-1	12x12 BLUE VFT-MASTIC	3,250	SF	EAST STAIRWELL, FRONT OF AUDITORIUM & ALL OF AUDITORIUM	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
T	12x12 ORANGE W/ GREEN VFT	450	SF	BACK STAGE OF AUDITORIUM W/ HALLWAY	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
T-1	12x12 ORANGE W/ GREEN VFT-MASTIC	450	SF	BACK STAGE OF AUDITORIUM W/ HALLWAY	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance

Chicago Public Schools

School Hyde Park Academy
Address 6220 S. Stony Island

Unit 46171
 Chicago, IL, 60637

Building ID 1390
Region 05

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

Review Date	3/31/2013
Manager Planner Name	Daniel Juneau
100-03613	5/15/2014
Manager IDPH License No/Expiration	

HA Number	Management Comments
01	
02	
03	
04	
05	
06	
07	
08	
09	
10	
11	

Chicago Public Schools

School Hyde Park Academy
Address 6220 S. Stony Island

Unit 46171
Chicago, IL, 60637

Building ID 1390
Region 05

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
12	
13	
14	
15	
16	
17	
18	
19	
20	
21	
22	
23	
24	
25	
26	
27	
28	
29	
30	
31	
32	
33	
34	
35	
36	
37	
38	

Chicago Public Schools

School Hyde Park Academy

Unit 46171

Building ID 1390

Address 6220 S. Stony Island

Chicago, IL, 60637

Region 05

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
39	
40	
41	
42	
43	
44	
45	
46	
47	
48	
49	
50	
51	
52	
53	
54	
55	
56	
57	
58	
59	
60	
61	
62	
63	
64	
65	

Chicago Public Schools

School Hyde Park Academy

Unit 46171

Building ID 1390

Address 6220 S. Stony Island

Chicago, IL, 60637

Region 05

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
66	
67	
68	
69	
70	
71	
72	
73	
74	
75	
76	
77	
78	
79	
80	
81	
82	
83	
84	
85	
86	
87	
88	
89	
90	
91	
92	

Chicago Public Schools

School Hyde Park Academy

Unit 46171

Building ID 1390

Address 6220 S. Stony Island

Chicago, IL, 60637

Region 05

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
A	
B	
C	
D	
E	
F	
G	
H	
HA-1000	
HA-1001	
HA-1002	
HA-1003	
I	
J	
K	
L	
M	
N	
O	
P	
Q	
Q-1	
R	
R-1	
S	
S-1	
T	

Chicago Public Schools

School Hyde Park Academy

Unit 46171

Building ID 1390

Address 6220 S. Stony Island

Chicago, IL, 60637

Region 05

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
T-1	

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46171** BUILDING ID: **1390**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ethan Payne**
SCHOOL NAME: **Hyde Park Academy** INSPECTION DATE: **3/1/2013**
ADDRESS: **6220 S. Stony Island** IDPH LICENSE NO: **100-02175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **01**
MATERIAL DESCRIPTION: **plaster**
HISTORICAL AHERA DAMAGE CATEGORY **6**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **building 1911**
MATERIAL QUANTITY: **140000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature:



Date: **03/01/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46171** BUIDLING ID: **1390**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Hyde Park Academy** REVIEW DATE: **3/31/2013**
ADDRESS: **6220 S. Stony Island** IDPH LICENSE NO: **100-02175**


HOMOGENEOUS AREA: **01**
MATERIAL DESCRIPTION: **plaster**
MATERIAL LOCATION: **building 1911**
MATERIAL QUANTITY: **140000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **03/31/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46171** BUIDLING ID: **1390**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ethan Payne**
SCHOOL NAME: **Hyde Park Academy** INSPECTION DATE: **3/1/2013**
ADDRESS: **6220 S. Stony Island** IDPH LICENSE NO: **100-02175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **02**
MATERIAL DESCRIPTION: **hard plaster**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **building 1937**
MATERIAL QUANTITY: **140000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/01/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46171** BUIDLING ID: **1390**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Hyde Park Academy** REVIEW DATE: **3/31/2013**
ADDRESS: **6220 S. Stony Island** IDPH LICENSE NO: **100-02175**

HOMOGENEOUS AREA: **02**
MATERIAL DESCRIPTION: **hard plaster**
MATERIAL LOCATION: **building 1937**
MATERIAL QUANTITY: **140000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **03/31/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46171** BUILDING ID: **1390**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ethan Payne**
SCHOOL NAME: **Hyde Park Academy** INSPECTION DATE: **3/1/2013**
ADDRESS: **6220 S. Stony Island** IDPH LICENSE NO: **100-02175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **03**
MATERIAL DESCRIPTION: **hard plaster**
HISTORICAL AHERA DAMAGE CATEGORY **6**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **building 1970**
MATERIAL QUANTITY: **140000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/01/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46171** BUIDLING ID: **1390**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Hyde Park Academy** REVIEW DATE: **3/31/2013**
ADDRESS: **6220 S. Stony Island** IDPH LICENSE NO: **100-02175**


HOMOGENEOUS AREA: **03**
MATERIAL DESCRIPTION: **hard plaster**
MATERIAL LOCATION: **building 1970**
MATERIAL QUANTITY: **140000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **03/31/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46171** BUIDLING ID: **1390**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ethan Payne**
SCHOOL NAME: **Hyde Park Academy** INSPECTION DATE: **3/1/2013**
ADDRESS: **6220 S. Stony Island** IDPH LICENSE NO: **100-02175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **04**
MATERIAL DESCRIPTION: **12x12 ceiling tile text**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **1937 building room 142**
MATERIAL QUANTITY: **700** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/01/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46171** BUIDLING ID: **1390**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Hyde Park Academy** REVIEW DATE: **3/31/2013**
ADDRESS: **6220 S. Stony Island** IDPH LICENSE NO: **100-02175**

HOMOGENEOUS AREA: **04**
MATERIAL DESCRIPTION: **12x12 ceiling tile text**
MATERIAL LOCATION: **1937 building room 142**
MATERIAL QUANTITY: **700** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **03/31/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46171** BUIDLING ID: **1390**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ethan Payne**
SCHOOL NAME: **Hyde Park Academy** INSPECTION DATE: **3/1/2013**
ADDRESS: **6220 S. Stony Island** IDPH LICENSE NO: **100-02175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **05**
MATERIAL DESCRIPTION: **12x12 ceiling tile**
HISTORICAL AHERA DAMAGE CATEGORY **6**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **1937 building**
MATERIAL QUANTITY: **10000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/01/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46171** BUIDLING ID: **1390**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Hyde Park Academy** REVIEW DATE: **3/31/2013**
ADDRESS: **6220 S. Stony Island** IDPH LICENSE NO: **100-02175**


HOMOGENEOUS AREA: **05**
MATERIAL DESCRIPTION: **12x12 ceiling tile**
MATERIAL LOCATION: **1937 building**
MATERIAL QUANTITY: **10000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **03/31/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46171** BUIDLING ID: **1390**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ethan Payne**
SCHOOL NAME: **Hyde Park Academy** INSPECTION DATE: **3/1/2013**
ADDRESS: **6220 S. Stony Island** IDPH LICENSE NO: **100-02175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **06**
MATERIAL DESCRIPTION: **2x2 ceiling tile**
HISTORICAL AHERA DAMAGE CATEGORY **5 ACBM with potential for significant damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Amosite** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **5. ACBM with potential for significant damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **1911 building**
MATERIAL QUANTITY: **34500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/01/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46171** BUIDLING ID: **1390**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Hyde Park Academy** REVIEW DATE: **3/31/2013**
ADDRESS: **6220 S. Stony Island** IDPH LICENSE NO: **100-02175**

HOMOGENEOUS AREA: **06**
MATERIAL DESCRIPTION: **2x2 ceiling tile**
MATERIAL LOCATION: **1911 building**
MATERIAL QUANTITY: **34500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **03/31/2013**

Chicago Public Schools

Carnow, Conibear and Associates 2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46171** BUIDLING ID: **1390**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ethan Payne**
SCHOOL NAME: **Hyde Park Academy** INSPECTION DATE: **3/1/2013**
ADDRESS: **6220 S. Stony Island** IDPH LICENSE NO: **100-02175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **07**
MATERIAL DESCRIPTION: **2x4 pinhole ceiling tile**
HISTORICAL AHERA DAMAGE CATEGORY **6**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **1911 building**
MATERIAL QUANTITY: **34500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature:



Date: **03/01/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46171** BUIDLING ID: **1390**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Hyde Park Academy** REVIEW DATE: **3/31/2013**
ADDRESS: **6220 S. Stony Island** IDPH LICENSE NO: **100-02175**


HOMOGENEOUS AREA: **07**
MATERIAL DESCRIPTION: **2x4 pinhole ceiling tile**
MATERIAL LOCATION: **1911 building**
MATERIAL QUANTITY: **34500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **03/31/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46171** BUIDLING ID: **1390**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ethan Payne**
SCHOOL NAME: **Hyde Park Academy** INSPECTION DATE: **3/1/2013**
ADDRESS: **6220 S. Stony Island** IDPH LICENSE NO: **100-02175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **08**
MATERIAL DESCRIPTION: **2x4 perforated ceiling tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1911 building**
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/01/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46171** BUIDLING ID: **1390**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Hyde Park Academy** REVIEW DATE: **3/31/2013**
ADDRESS: **6220 S. Stony Island** IDPH LICENSE NO: **100-02175**

HOMOGENEOUS AREA: **08**

MATERIAL DESCRIPTION: **2x4 perforated ceiling tile**

MATERIAL LOCATION: **1911 building**

MATERIAL QUANTITY: **1500**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **03/31/2013**

Chicago Public Schools

Carnow, Conibear and Associates 2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46171** BUIDLING ID: **1390**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ethan Payne**
SCHOOL NAME: **Hyde Park Academy** INSPECTION DATE: **3/1/2013**
ADDRESS: **6220 S. Stony Island** IDPH LICENSE NO: **100-02175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **09**
MATERIAL DESCRIPTION: **ceiling tectum panels**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1911 buildings (50 ft. in air inaccessible to sample)**
MATERIAL QUANTITY: **13000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/01/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46171** BUIDLING ID: **1390**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Hyde Park Academy** REVIEW DATE: **3/31/2013**
ADDRESS: **6220 S. Stony Island** IDPH LICENSE NO: **100-02175**

HOMOGENEOUS AREA: **09**
MATERIAL DESCRIPTION: **ceiling tectum panels**
MATERIAL LOCATION: **1911 buildings (50 ft. in air inaccessible to sample)**
MATERIAL QUANTITY: **13000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **03/31/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46171** BUIDLING ID: **1390**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ethan Payne**
SCHOOL NAME: **Hyde Park Academy** INSPECTION DATE: **3/1/2013**
ADDRESS: **6220 S. Stony Island** IDPH LICENSE NO: **100-02175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **10**
MATERIAL DESCRIPTION: **9x9 light brown F.T.**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Repair
Operations and Maintenance**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**

MATERIAL LOCATION: **SEE COMMENTS FOR ROOM LOCATIONS**

MATERIAL QUANTITY: **16800** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/01/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46171** BUIDLING ID: **1390**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Hyde Park Academy** REVIEW DATE: **3/31/2013**
ADDRESS: **6220 S. Stony Island** IDPH LICENSE NO: **100-02175**

HOMOGENEOUS AREA: **10**
MATERIAL DESCRIPTION: **9x9 light brown F.T.**
MATERIAL LOCATION: **SEE COMMENTS FOR ROOM LOCATIONS**
MATERIAL QUANTITY: **16800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **120** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Repair
Operations and Maintenance**

Comments:

Management Planner's Signature: _____



Date: **03/31/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46171** BUIDLING ID: **1390**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ethan Payne**
SCHOOL NAME: **Hyde Park Academy** INSPECTION DATE: **3/1/2013**
ADDRESS: **6220 S. Stony Island** IDPH LICENSE NO: **100-02175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **11**
MATERIAL DESCRIPTION: **12x12 tan F.T.**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Enclose
Operations and Maintenance**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**

MATERIAL LOCATION: **SEE COMMENTS FOR ROOM LOCATIONS**

MATERIAL QUANTITY: **99000**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/01/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46171** BUIDLING ID: **1390**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Hyde Park Academy** REVIEW DATE: **3/31/2013**
ADDRESS: **6220 S. Stony Island** IDPH LICENSE NO: **100-02175**

HOMOGENEOUS AREA: **11**
MATERIAL DESCRIPTION: **12x12 tan F.T.**
MATERIAL LOCATION: **SEE COMMENTS FOR ROOM LOCATIONS**
MATERIAL QUANTITY: **99000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **100** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Enclose
Operations and Maintenance**

Comments:

Management Planner's Signature: _____



Date: **03/31/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46171** BUIDLING ID: **1390**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ethan Payne**
SCHOOL NAME: **Hyde Park Academy** INSPECTION DATE: **3/1/2013**
ADDRESS: **6220 S. Stony Island** IDPH LICENSE NO: **100-02175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **12**
MATERIAL DESCRIPTION: **12x12 metal ceiling tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1911 natatorium (ceiling is inaccessible)**
MATERIAL QUANTITY: **3750** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature:



Date: **03/01/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46171** BUIDLING ID: **1390**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Hyde Park Academy** REVIEW DATE: **3/31/2013**
ADDRESS: **6220 S. Stony Island** IDPH LICENSE NO: **100-02175**

HOMOGENEOUS AREA: **12**
MATERIAL DESCRIPTION: **12x12 metal ceiling tile**
MATERIAL LOCATION: **1911 natatorium (ceiling is inaccessible)**
MATERIAL QUANTITY: **3750** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **03/31/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46171** BUIDLING ID: **1390**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ethan Payne**
SCHOOL NAME: **Hyde Park Academy** INSPECTION DATE: **3/1/2013**
ADDRESS: **6220 S. Stony Island** IDPH LICENSE NO: **100-02175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **13**
MATERIAL DESCRIPTION: **transite table tops**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Science labs**
MATERIAL QUANTITY: **3200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/01/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46171** BUIDLING ID: **1390**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Hyde Park Academy** REVIEW DATE: **3/31/2013**
ADDRESS: **6220 S. Stony Island** IDPH LICENSE NO: **100-02175**

HOMOGENEOUS AREA: **13**
MATERIAL DESCRIPTION: **transite table tops**
MATERIAL LOCATION: **Science labs**
MATERIAL QUANTITY: **3200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **03/31/2013**

Chicago Public Schools

Carnow, Conibear and Associates 2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46171** BUIDLING ID: **1390**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ethan Payne**
SCHOOL NAME: **Hyde Park Academy** INSPECTION DATE: **3/1/2013**
ADDRESS: **6220 S. Stony Island** IDPH LICENSE NO: **100-02175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **14**
MATERIAL DESCRIPTION: **transite panel material**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Science labs 312, 316**
MATERIAL QUANTITY: **150** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature:



Date: **03/01/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46171** BUIDLING ID: **1390**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Hyde Park Academy** REVIEW DATE: **3/31/2013**
ADDRESS: **6220 S. Stony Island** IDPH LICENSE NO: **100-02175**

HOMOGENEOUS AREA: **14**
MATERIAL DESCRIPTION: **transite panel material**
MATERIAL LOCATION: **Science labs 312, 316**
MATERIAL QUANTITY: **150** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **03/31/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46171** BUIDLING ID: **1390**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ethan Payne**
SCHOOL NAME: **Hyde Park Academy** INSPECTION DATE: **3/1/2013**
ADDRESS: **6220 S. Stony Island** IDPH LICENSE NO: **100-02175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **15**
MATERIAL DESCRIPTION: **accoustical ceiling tile (no material)**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Undefined** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1911 building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Material Removed 2013**

Inspector's Signature:



Date: **03/01/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46171** BUIDLING ID: **1390**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Hyde Park Academy** REVIEW DATE: **3/31/2013**
ADDRESS: **6220 S. Stony Island** IDPH LICENSE NO: **100-02175**

HOMOGENEOUS AREA: **15**

MATERIAL DESCRIPTION: **accoustical ceiling tile (no material)**

MATERIAL LOCATION: **1911 building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **03/31/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46171** BUILDING ID: **1390**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ethan Payne**
SCHOOL NAME: **Hyde Park Academy** INSPECTION DATE: **3/1/2013**
ADDRESS: **6220 S. Stony Island** IDPH LICENSE NO: **100-02175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **16**
MATERIAL DESCRIPTION: **12x12 ceiling tile text (material not observed)**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1937 building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Material Removed 2013**

Inspector's Signature:



Date: **03/01/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46171** BUIDLING ID: **1390**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Hyde Park Academy** REVIEW DATE: **3/31/2013**
ADDRESS: **6220 S. Stony Island** IDPH LICENSE NO: **100-02175**

HOMOGENEOUS AREA: **16**

MATERIAL DESCRIPTION: **12x12 ceiling tile text (material not observed)**

MATERIAL LOCATION: **1937 building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **03/31/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46171** BUIDLING ID: **1390**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ethan Payne**
SCHOOL NAME: **Hyde Park Academy** INSPECTION DATE: **3/1/2013**
ADDRESS: **6220 S. Stony Island** IDPH LICENSE NO: **100-02175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **17**
MATERIAL DESCRIPTION: **spray-on fireproofing**
HISTORICAL AHERA DAMAGE CATEGORY **5 ACBM with potential for significant damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **5. ACBM with potential for significant damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **BLDG 1911 above 2nd & 3rd floor ceiling tile**
MATERIAL QUANTITY: **45000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/01/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46171** BUIDLING ID: **1390**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Hyde Park Academy** REVIEW DATE: **3/31/2013**
ADDRESS: **6220 S. Stony Island** IDPH LICENSE NO: **100-02175**

HOMOGENEOUS AREA: **17**
MATERIAL DESCRIPTION: **spray-on fireproofing**
MATERIAL LOCATION: **BLDG 1911 above 2nd & 3rd floor ceiling tile**
MATERIAL QUANTITY: **45000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **03/31/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46171** BUIDLING ID: **1390**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ethan Payne**
SCHOOL NAME: **Hyde Park Academy** INSPECTION DATE: **3/1/2013**
ADDRESS: **6220 S. Stony Island** IDPH LICENSE NO: **100-02175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **18**
MATERIAL DESCRIPTION: **9x9 light brown F.T. mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **SEE COMMENTS FOR ROOM LOCATIONS**

MATERIAL QUANTITY: **16800**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS: **142-145, 140,138,136,132,130,240,238,236,232,210,345,346,344,303,305,307,309,311,340,338,336,334,332**

Inspector's Signature:



Date: **03/01/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46171** BUIDLING ID: **1390**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Hyde Park Academy** REVIEW DATE: **3/31/2013**
ADDRESS: **6220 S. Stony Island** IDPH LICENSE NO: **100-02175**

HOMOGENEOUS AREA: **18**
MATERIAL DESCRIPTION: **9x9 light brown F.T. mastic**
MATERIAL LOCATION: **SEE COMMENTS FOR ROOM LOCATIONS**
MATERIAL QUANTITY: **16800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **03/31/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46171** BUIDLING ID: **1390**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ethan Payne**
SCHOOL NAME: **Hyde Park Academy** INSPECTION DATE: **3/1/2013**
ADDRESS: **6220 S. Stony Island** IDPH LICENSE NO: **100-02175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **19**
MATERIAL DESCRIPTION: **9x9 tan F.T. mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1st, 2nd & 3rd floor south hallways**
MATERIAL QUANTITY: **11400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature:



Date: **03/01/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46171** BUIDLING ID: **1390**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Hyde Park Academy** REVIEW DATE: **3/31/2013**
ADDRESS: **6220 S. Stony Island** IDPH LICENSE NO: **100-02175**

HOMOGENEOUS AREA: **19**
MATERIAL DESCRIPTION: **9x9 tan F.T. mastic**
MATERIAL LOCATION: **1st, 2nd & 3rd floor south hallways**
MATERIAL QUANTITY: **11400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **03/31/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46171** BUIDLING ID: **1390**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ethan Payne**
SCHOOL NAME: **Hyde Park Academy** INSPECTION DATE: **3/1/2013**
ADDRESS: **6220 S. Stony Island** IDPH LICENSE NO: **100-02175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **20**
MATERIAL DESCRIPTION: **9x9 med. Brn. F.T. mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **SEE COMMENTS FOR ROOM LOCATIONS**

MATERIAL QUANTITY: **21000**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/01/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46171** BUIDLING ID: **1390**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Hyde Park Academy** REVIEW DATE: **3/31/2013**
ADDRESS: **6220 S. Stony Island** IDPH LICENSE NO: **100-02175**

HOMOGENEOUS AREA: **20**
MATERIAL DESCRIPTION: **9x9 med. Brn. F.T. mastic**
MATERIAL LOCATION: **SEE COMMENTS FOR ROOM LOCATIONS**
MATERIAL QUANTITY: **21000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **03/31/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46171** BUIDLING ID: **1390**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ethan Payne**
SCHOOL NAME: **Hyde Park Academy** INSPECTION DATE: **3/1/2013**
ADDRESS: **6220 S. Stony Island** IDPH LICENSE NO: **100-02175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **21**
MATERIAL DESCRIPTION: **12x12 tan F.T. mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **SEE COMMENTS FOR ROOM LOCATIONS**

MATERIAL QUANTITY: **99000**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/01/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46171** BUIDLING ID: **1390**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Hyde Park Academy** REVIEW DATE: **3/31/2013**
ADDRESS: **6220 S. Stony Island** IDPH LICENSE NO: **100-02175**

HOMOGENEOUS AREA: **21**
MATERIAL DESCRIPTION: **12x12 tan F.T. mastic**
MATERIAL LOCATION: **SEE COMMENTS FOR ROOM LOCATIONS**
MATERIAL QUANTITY: **99000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **03/31/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46171** BUIDLING ID: **1390**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ethan Payne**
SCHOOL NAME: **Hyde Park Academy** INSPECTION DATE: **3/1/2013**
ADDRESS: **6220 S. Stony Island** IDPH LICENSE NO: **100-02175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **22**
MATERIAL DESCRIPTION: **12x12 tan F.T. mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **1937 building, patched areas of 1st, 2nd flr hallway**

MATERIAL QUANTITY: **900** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/01/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46171** BUIDLING ID: **1390**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Hyde Park Academy** REVIEW DATE: **3/31/2013**
ADDRESS: **6220 S. Stony Island** IDPH LICENSE NO: **100-02175**

HOMOGENEOUS AREA: **22**
MATERIAL DESCRIPTION: **12x12 tan F.T. mastic**
MATERIAL LOCATION: **1937 building, patched areas of 1st, 2nd flr hallway**
MATERIAL QUANTITY: **900** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **03/31/2013**

Chicago Public Schools

Carnow, Conibear and Associates 2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46171** BUIDLING ID: **1390**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ethan Payne**
SCHOOL NAME: **Hyde Park Academy** INSPECTION DATE: **3/1/2013**
ADDRESS: **6220 S. Stony Island** IDPH LICENSE NO: **100-02175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **23**
MATERIAL DESCRIPTION: **12x12 lt. Brn. Tile mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1970 building, weight room**
MATERIAL QUANTITY: **1700** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature:



Date: **03/01/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46171** BUIDLING ID: **1390**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Hyde Park Academy** REVIEW DATE: **3/31/2013**
ADDRESS: **6220 S. Stony Island** IDPH LICENSE NO: **100-02175**

HOMOGENEOUS AREA: **23**
MATERIAL DESCRIPTION: **12x12 lt. Brn. Tile mastic**
MATERIAL LOCATION: **1970 building, weight room**
MATERIAL QUANTITY: **1700** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **03/31/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46171** BUIDLING ID: **1390**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ethan Payne**
SCHOOL NAME: **Hyde Park Academy** INSPECTION DATE: **3/1/2013**
ADDRESS: **6220 S. Stony Island** IDPH LICENSE NO: **100-02175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **24**
MATERIAL DESCRIPTION: **2' ceiling tile**
HISTORICAL AHERA DAMAGE CATEGORY **6**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1937 building**
MATERIAL QUANTITY: **14000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/01/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46171** BUIDLING ID: **1390**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Hyde Park Academy** REVIEW DATE: **3/31/2013**
ADDRESS: **6220 S. Stony Island** IDPH LICENSE NO: **100-02175**


HOMOGENEOUS AREA: **24**
MATERIAL DESCRIPTION: **2' ceiling tile**
MATERIAL LOCATION: **1937 building**
MATERIAL QUANTITY: **14000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **03/31/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46171** BUIDLING ID: **1390**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ethan Payne**
SCHOOL NAME: **Hyde Park Academy** INSPECTION DATE: **3/1/2013**
ADDRESS: **6220 S. Stony Island** IDPH LICENSE NO: **100-02175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **25**
MATERIAL DESCRIPTION: **2' ceiling tile**
HISTORICAL AHERA DAMAGE CATEGORY **6**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1970/ rear of rm. 143 2nd flr. S/W corridor**
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature:



Date: **03/01/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46171** BUIDLING ID: **1390**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Hyde Park Academy** REVIEW DATE: **3/31/2013**
ADDRESS: **6220 S. Stony Island** IDPH LICENSE NO: **100-02175**


HOMOGENEOUS AREA: **25**
MATERIAL DESCRIPTION: **2' ceiling tile**
MATERIAL LOCATION: **1970/ rear of rm. 143 2nd flr. S/W corridor**
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **03/31/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46171** BUIDLING ID: **1390**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ethan Payne**
SCHOOL NAME: **Hyde Park Academy** INSPECTION DATE: **3/1/2013**
ADDRESS: **6220 S. Stony Island** IDPH LICENSE NO: **100-02175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **26**
MATERIAL DESCRIPTION: **9x9 tan F.T.**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1st, 2nd & 3rd floor south hallways**
MATERIAL QUANTITY: **11400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/01/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46171** BUIDLING ID: **1390**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Hyde Park Academy** REVIEW DATE: **3/31/2013**
ADDRESS: **6220 S. Stony Island** IDPH LICENSE NO: **100-02175**

HOMOGENEOUS AREA: **26**
MATERIAL DESCRIPTION: **9x9 tan F.T.**
MATERIAL LOCATION: **1st, 2nd & 3rd floor south hallways**
MATERIAL QUANTITY: **11400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **03/31/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46171** BUIDLING ID: **1390**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ethan Payne**
SCHOOL NAME: **Hyde Park Academy** INSPECTION DATE: **3/1/2013**
ADDRESS: **6220 S. Stony Island** IDPH LICENSE NO: **100-02175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **27**
MATERIAL DESCRIPTION: **9x9 med.brn. F.T.**
HISTORICAL AHERA DAMAGE CATEGORY **6**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **SEE COMMENTS FOR ROOM LOCATIONS**

MATERIAL QUANTITY: **21000**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/01/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46171** BUIDLING ID: **1390**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Hyde Park Academy** REVIEW DATE: **3/31/2013**
ADDRESS: **6220 S. Stony Island** IDPH LICENSE NO: **100-02175**

HOMOGENEOUS AREA: **27**

MATERIAL DESCRIPTION: **9x9 med.brn. F.T.**

MATERIAL LOCATION: **SEE COMMENTS FOR ROOM LOCATIONS**

MATERIAL QUANTITY: **21000**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **03/31/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46171** BUIDLING ID: **1390**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ethan Payne**
SCHOOL NAME: **Hyde Park Academy** INSPECTION DATE: **3/1/2013**
ADDRESS: **6220 S. Stony Island** IDPH LICENSE NO: **100-02175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **28**
MATERIAL DESCRIPTION: **12x12 tan F.T.**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1937 building, patched areas of 1st, 2nd flr hallway**
MATERIAL QUANTITY: **900** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature:



Date: **03/01/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46171** BUIDLING ID: **1390**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Hyde Park Academy** REVIEW DATE: **3/31/2013**
ADDRESS: **6220 S. Stony Island** IDPH LICENSE NO: **100-02175**

HOMOGENEOUS AREA: **28**
MATERIAL DESCRIPTION: **12x12 tan F.T.**
MATERIAL LOCATION: **1937 building, patched areas of 1st, 2nd flr hallway**
MATERIAL QUANTITY: **900** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **03/31/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46171** BUILDING ID: **1390**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ethan Payne**
SCHOOL NAME: **Hyde Park Academy** INSPECTION DATE: **3/1/2013**
ADDRESS: **6220 S. Stony Island** IDPH LICENSE NO: **100-02175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **29**
MATERIAL DESCRIPTION: **12x12 lt. Brn. F.T.**
HISTORICAL AHERA DAMAGE CATEGORY **6**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1970 building, weight room**
MATERIAL QUANTITY: **1700** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____



Date: **03/01/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46171** BUIDLING ID: **1390**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Hyde Park Academy** REVIEW DATE: **3/31/2013**
ADDRESS: **6220 S. Stony Island** IDPH LICENSE NO: **100-02175**

HOMOGENEOUS AREA: **29**
MATERIAL DESCRIPTION: **12x12 lt. Brn. F.T.**
MATERIAL LOCATION: **1970 building, weight room**
MATERIAL QUANTITY: **1700** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **03/31/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46171** BUIDLING ID: **1390**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ethan Payne**
SCHOOL NAME: **Hyde Park Academy** INSPECTION DATE: **3/1/2013**
ADDRESS: **6220 S. Stony Island** IDPH LICENSE NO: **100-02175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **30**
MATERIAL DESCRIPTION: **9x9 med. Brn. F.T.**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 246, southeastern hall on 2nd floor**
MATERIAL QUANTITY: **2500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/01/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46171** BUIDLING ID: **1390**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Hyde Park Academy** REVIEW DATE: **3/31/2013**
ADDRESS: **6220 S. Stony Island** IDPH LICENSE NO: **100-02175**

HOMOGENEOUS AREA: **30**
MATERIAL DESCRIPTION: **9x9 med. Brn. F.T.**
MATERIAL LOCATION: **Room 246, southeastern hall on 2nd floor**
MATERIAL QUANTITY: **2500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **03/31/2013**

Chicago Public Schools

Carnow, Conibear and Associates 2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46171** BUIDLING ID: **1390**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ethan Payne**
SCHOOL NAME: **Hyde Park Academy** INSPECTION DATE: **3/1/2013**
ADDRESS: **6220 S. Stony Island** IDPH LICENSE NO: **100-02175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **31**
MATERIAL DESCRIPTION: **9x9 tan F.T.**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Room 210, 311**
MATERIAL QUANTITY: **1300** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature:



Date: **03/01/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46171** BUIDLING ID: **1390**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Hyde Park Academy** REVIEW DATE: **3/31/2013**
ADDRESS: **6220 S. Stony Island** IDPH LICENSE NO: **100-02175**

HOMOGENEOUS AREA: **31**
MATERIAL DESCRIPTION: **9x9 tan F.T.**
MATERIAL LOCATION: **Room 210, 311**
MATERIAL QUANTITY: **1300** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **03/31/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46171** BUIDLING ID: **1390**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ethan Payne**
SCHOOL NAME: **Hyde Park Academy** INSPECTION DATE: **3/1/2013**
ADDRESS: **6220 S. Stony Island** IDPH LICENSE NO: **100-02175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **32**
MATERIAL DESCRIPTION: **12x12 beige F.T.**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Small hallways leading to library on 2nd and 3rd floors.**
MATERIAL QUANTITY: **750** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature:



Date: **03/01/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46171** BUIDLING ID: **1390**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Hyde Park Academy** REVIEW DATE: **3/31/2013**
ADDRESS: **6220 S. Stony Island** IDPH LICENSE NO: **100-02175**

HOMOGENEOUS AREA: **32**
MATERIAL DESCRIPTION: **12x12 beige F.T.**
MATERIAL LOCATION: **Small hallways leading to library on 2nd and 3rd floors.**
MATERIAL QUANTITY: **750** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **03/31/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46171** BUIDLING ID: **1390**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ethan Payne**
SCHOOL NAME: **Hyde Park Academy** INSPECTION DATE: **3/1/2013**
ADDRESS: **6220 S. Stony Island** IDPH LICENSE NO: **100-02175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **33**
MATERIAL DESCRIPTION: **12x12 brown F.T.**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**

MATERIAL LOCATION: **Locker rooms 1st floor**

MATERIAL QUANTITY: **4000**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/01/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46171** BUIDLING ID: **1390**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Hyde Park Academy** REVIEW DATE: **3/31/2013**
ADDRESS: **6220 S. Stony Island** IDPH LICENSE NO: **100-02175**

HOMOGENEOUS AREA: **33**
MATERIAL DESCRIPTION: **12x12 brown F.T.**
MATERIAL LOCATION: **Locker rooms 1st floor**
MATERIAL QUANTITY: **4000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **03/31/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46171** BUIDLING ID: **1390**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ethan Payne**
SCHOOL NAME: **Hyde Park Academy** INSPECTION DATE: **3/1/2013**
ADDRESS: **6220 S. Stony Island** IDPH LICENSE NO: **100-02175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **34**
MATERIAL DESCRIPTION: **12x12 lt. Brn. F.T.**
HISTORICAL AHERA DAMAGE CATEGORY **7**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **1911 building**
MATERIAL QUANTITY: **11000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/01/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46171** BUIDLING ID: **1390**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Hyde Park Academy** REVIEW DATE: **3/31/2013**
ADDRESS: **6220 S. Stony Island** IDPH LICENSE NO: **100-02175**

HOMOGENEOUS AREA: **34**
MATERIAL DESCRIPTION: **12x12 lt. Brn. F.T.**
MATERIAL LOCATION: **1911 building**
MATERIAL QUANTITY: **11000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **03/31/2013**

Chicago Public Schools

Carnow, Conibear and Associates 2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46171** BUIDLING ID: **1390**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ethan Payne**
SCHOOL NAME: **Hyde Park Academy** INSPECTION DATE: **3/1/2013**
ADDRESS: **6220 S. Stony Island** IDPH LICENSE NO: **100-02175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **35**
MATERIAL DESCRIPTION: **12x12 dark tan F.T.**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **1911 building, patched areas**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature:



Date: **03/01/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46171** BUIDLING ID: **1390**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Hyde Park Academy** REVIEW DATE: **3/31/2013**
ADDRESS: **6220 S. Stony Island** IDPH LICENSE NO: **100-02175**

HOMOGENEOUS AREA: **35**
MATERIAL DESCRIPTION: **12x12 dark tan F.T.**
MATERIAL LOCATION: **1911 building, patched areas**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **03/31/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46171** BUIDLING ID: **1390**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ethan Payne**
SCHOOL NAME: **Hyde Park Academy** INSPECTION DATE: **3/1/2013**
ADDRESS: **6220 S. Stony Island** IDPH LICENSE NO: **100-02175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **36**
MATERIAL DESCRIPTION: **12x12 lt. Grn. F.T.**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 133**
MATERIAL QUANTITY: **1600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/01/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46171** BUIDLING ID: **1390**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Hyde Park Academy** REVIEW DATE: **3/31/2013**
ADDRESS: **6220 S. Stony Island** IDPH LICENSE NO: **100-02175**

HOMOGENEOUS AREA: **36**

MATERIAL DESCRIPTION: **12x12 lt. Grn. F.T.**

MATERIAL LOCATION: **Room 133**

MATERIAL QUANTITY: **1600**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **03/31/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46171** BUIDLING ID: **1390**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ethan Payne**
SCHOOL NAME: **Hyde Park Academy** INSPECTION DATE: **3/1/2013**
ADDRESS: **6220 S. Stony Island** IDPH LICENSE NO: **100-02175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **37**
MATERIAL DESCRIPTION: **12x12 off-white F.T.**
HISTORICAL AHERA DAMAGE CATEGORY **6**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Engineer's office**

MATERIAL QUANTITY: **1825**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/01/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46171** BUIDLING ID: **1390**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Hyde Park Academy** REVIEW DATE: **3/31/2013**
ADDRESS: **6220 S. Stony Island** IDPH LICENSE NO: **100-02175**


HOMOGENEOUS AREA: **37**
MATERIAL DESCRIPTION: **12x12 off-white F.T.**
MATERIAL LOCATION: **Engineer's office**
MATERIAL QUANTITY: **1825** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **03/31/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46171** BUIDLING ID: **1390**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ethan Payne**
SCHOOL NAME: **Hyde Park Academy** INSPECTION DATE: **3/1/2013**
ADDRESS: **6220 S. Stony Island** IDPH LICENSE NO: **100-02175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **38**
MATERIAL DESCRIPTION: **12x12 white F.T.**
HISTORICAL AHERA DAMAGE CATEGORY **6**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Rooms 135, 137**
MATERIAL QUANTITY: **2500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/01/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46171** BUIDLING ID: **1390**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Hyde Park Academy** REVIEW DATE: **3/31/2013**
ADDRESS: **6220 S. Stony Island** IDPH LICENSE NO: **100-02175**


HOMOGENEOUS AREA: **38**
MATERIAL DESCRIPTION: **12x12 white F.T.**
MATERIAL LOCATION: **Rooms 135, 137**
MATERIAL QUANTITY: **2500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **03/31/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46171** BUIDLING ID: **1390**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ethan Payne**
SCHOOL NAME: **Hyde Park Academy** INSPECTION DATE: **3/1/2013**
ADDRESS: **6220 S. Stony Island** IDPH LICENSE NO: **100-02175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **39**
MATERIAL DESCRIPTION: **12x12 Tan speckled F.T.**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Patched areas of 1st flr north hallway**
MATERIAL QUANTITY: **490** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature:



Date: **03/01/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46171** BUIDLING ID: **1390**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Hyde Park Academy** REVIEW DATE: **3/31/2013**
ADDRESS: **6220 S. Stony Island** IDPH LICENSE NO: **100-02175**

HOMOGENEOUS AREA: **39**
MATERIAL DESCRIPTION: **12x12 Tan speckled F.T.**
MATERIAL LOCATION: **Patched areas of 1st flr north hallway**
MATERIAL QUANTITY: **490** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **03/31/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46171** BUIDLING ID: **1390**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ethan Payne**
SCHOOL NAME: **Hyde Park Academy** INSPECTION DATE: **3/1/2013**
ADDRESS: **6220 S. Stony Island** IDPH LICENSE NO: **100-02175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **40**
MATERIAL DESCRIPTION: **9x9 brown F.T.**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1937 building, patched areas of 1st, 2nd, 3rd flr hallways**
MATERIAL QUANTITY: **950** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/01/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46171** BUIDLING ID: **1390**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Hyde Park Academy** REVIEW DATE: **3/31/2013**
ADDRESS: **6220 S. Stony Island** IDPH LICENSE NO: **100-02175**

HOMOGENEOUS AREA: **40**
MATERIAL DESCRIPTION: **9x9 brown F.T.**
MATERIAL LOCATION: **1937 building, patched areas of 1st, 2nd, 3rd flr hallways**
MATERIAL QUANTITY: **950** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **03/31/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46171** BUIDLING ID: **1390**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ethan Payne**
SCHOOL NAME: **Hyde Park Academy** INSPECTION DATE: **3/1/2013**
ADDRESS: **6220 S. Stony Island** IDPH LICENSE NO: **100-02175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **41**
MATERIAL DESCRIPTION: **9x9 drk.brn. F.T.**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **1937 building, patched areas of 1st, 2nd, 3rd flr hallways**

MATERIAL QUANTITY: **75** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/01/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46171** BUIDLING ID: **1390**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Hyde Park Academy** REVIEW DATE: **3/31/2013**
ADDRESS: **6220 S. Stony Island** IDPH LICENSE NO: **100-02175**

HOMOGENEOUS AREA: **41**
MATERIAL DESCRIPTION: **9x9 drk.brn. F.T.**
MATERIAL LOCATION: **1937 building, patched areas of 1st, 2nd, 3rd flr hallways**
MATERIAL QUANTITY: **75** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **03/31/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46171** BUILDING ID: **1390**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ethan Payne**
SCHOOL NAME: **Hyde Park Academy** INSPECTION DATE: **3/1/2013**
ADDRESS: **6220 S. Stony Island** IDPH LICENSE NO: **100-02175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **42**
MATERIAL DESCRIPTION: **12x12 lt. Brn. F.T.**
HISTORICAL AHERA DAMAGE CATEGORY **6**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **1937 building, patched areas of 1st, 2nd & 3rd floor south hallways**
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/01/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46171** BUIDLING ID: **1390**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Hyde Park Academy** REVIEW DATE: **3/31/2013**
ADDRESS: **6220 S. Stony Island** IDPH LICENSE NO: **100-02175**

HOMOGENEOUS AREA: **42**
MATERIAL DESCRIPTION: **12x12 lt. Brn. F.T.**
MATERIAL LOCATION: **1937 building, patched areas of 1st, 2nd & 3rd floor south hallways**
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **03/31/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46171** BUIDLING ID: **1390**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ethan Payne**
SCHOOL NAME: **Hyde Park Academy** INSPECTION DATE: **3/1/2013**
ADDRESS: **6220 S. Stony Island** IDPH LICENSE NO: **100-02175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **43**
MATERIAL DESCRIPTION: **9x9 med. Brn. F.T.**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Team, Visitor, Boy's & Girl's Locker Rooms**

MATERIAL QUANTITY: **1800** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/01/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46171** BUIDLING ID: **1390**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Hyde Park Academy** REVIEW DATE: **3/31/2013**
ADDRESS: **6220 S. Stony Island** IDPH LICENSE NO: **100-02175**

HOMOGENEOUS AREA: **43**
MATERIAL DESCRIPTION: **9x9 med. Brn. F.T.**
MATERIAL LOCATION: **Team, Visitor, Boy's & Girl's Locker Rooms**
MATERIAL QUANTITY: **1800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **03/31/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46171** BUIDLING ID: **1390**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ethan Payne**
SCHOOL NAME: **Hyde Park Academy** INSPECTION DATE: **3/1/2013**
ADDRESS: **6220 S. Stony Island** IDPH LICENSE NO: **100-02175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **44**
MATERIAL DESCRIPTION: **9x9 tan F.T.**
HISTORICAL AHERA DAMAGE CATEGORY **6**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **1937 building**
MATERIAL QUANTITY: **425** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/01/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46171** BUIDLING ID: **1390**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Hyde Park Academy** REVIEW DATE: **3/31/2013**
ADDRESS: **6220 S. Stony Island** IDPH LICENSE NO: **100-02175**


HOMOGENEOUS AREA: **44**
MATERIAL DESCRIPTION: **9x9 tan F.T.**
MATERIAL LOCATION: **1937 building**
MATERIAL QUANTITY: **425** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **03/31/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46171** BUIDLING ID: **1390**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ethan Payne**
SCHOOL NAME: **Hyde Park Academy** INSPECTION DATE: **3/1/2013**
ADDRESS: **6220 S. Stony Island** IDPH LICENSE NO: **100-02175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **45**
MATERIAL DESCRIPTION: **9x9 brown F.T.**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**

MATERIAL LOCATION: **SEE COMMENTS FOR ROOM LOCATIONS**

MATERIAL QUANTITY: **3100** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS: **142-145, 140,138,136,132,130,240,238,236,232,210,345,346,344,303,305,307,309,311,340,338,336,334,332**

Inspector's Signature:



Date: **03/01/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46171** BUIDLING ID: **1390**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Hyde Park Academy** REVIEW DATE: **3/31/2013**
ADDRESS: **6220 S. Stony Island** IDPH LICENSE NO: **100-02175**

HOMOGENEOUS AREA: **45**

MATERIAL DESCRIPTION: **9x9 brown F.T.**

MATERIAL LOCATION: **SEE COMMENTS FOR ROOM LOCATIONS**

MATERIAL QUANTITY: **3100**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **03/31/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46171** BUIDLING ID: **1390**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ethan Payne**
SCHOOL NAME: **Hyde Park Academy** INSPECTION DATE: **3/1/2013**
ADDRESS: **6220 S. Stony Island** IDPH LICENSE NO: **100-02175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **46**
MATERIAL DESCRIPTION: **9x9 brown F.T.**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Patched areas of 1st, 2nd & 3rd floor south hallways**
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature:



Date: **03/01/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46171** BUIDLING ID: **1390**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Hyde Park Academy** REVIEW DATE: **3/31/2013**
ADDRESS: **6220 S. Stony Island** IDPH LICENSE NO: **100-02175**

HOMOGENEOUS AREA: **46**
MATERIAL DESCRIPTION: **9x9 brown F.T.**
MATERIAL LOCATION: **Patched areas of 1st, 2nd & 3rd floor south hallways**
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **03/31/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46171** BUIDLING ID: **1390**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ethan Payne**
SCHOOL NAME: **Hyde Park Academy** INSPECTION DATE: **3/1/2013**
ADDRESS: **6220 S. Stony Island** IDPH LICENSE NO: **100-02175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **47**
MATERIAL DESCRIPTION: **9x9 med. brn. F.T. mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 246, southeastern hall on 2nd floor**
MATERIAL QUANTITY: **2500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/01/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46171** BUIDLING ID: **1390**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Hyde Park Academy** REVIEW DATE: **3/31/2013**
ADDRESS: **6220 S. Stony Island** IDPH LICENSE NO: **100-02175**

HOMOGENEOUS AREA: **47**
MATERIAL DESCRIPTION: **9x9 med. brn. F.T. mastic**
MATERIAL LOCATION: **Room 246, southeastern hall on 2nd floor**
MATERIAL QUANTITY: **2500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **03/31/2013**

Chicago Public Schools

Carnow, Conibear and Associates 2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46171** BUIDLING ID: **1390**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ethan Payne**
SCHOOL NAME: **Hyde Park Academy** INSPECTION DATE: **3/1/2013**
ADDRESS: **6220 S. Stony Island** IDPH LICENSE NO: **100-02175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **48**
MATERIAL DESCRIPTION: **9x9 tan F.T. mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 210, 311**
MATERIAL QUANTITY: **1300** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/01/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46171** BUIDLING ID: **1390**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Hyde Park Academy** REVIEW DATE: **3/31/2013**
ADDRESS: **6220 S. Stony Island** IDPH LICENSE NO: **100-02175**

HOMOGENEOUS AREA: **48**
MATERIAL DESCRIPTION: **9x9 tan F.T. mastic**
MATERIAL LOCATION: **Room 210, 311**
MATERIAL QUANTITY: **1300** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **03/31/2013**

Chicago Public Schools

Carnow, Conibear and Associates 2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46171** BUIDLING ID: **1390**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ethan Payne**
SCHOOL NAME: **Hyde Park Academy** INSPECTION DATE: **3/1/2013**
ADDRESS: **6220 S. Stony Island** IDPH LICENSE NO: **100-02175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **49**
MATERIAL DESCRIPTION: **12x12 beige F.T. Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Small hallways leading to library on 2nd and 3rd floors.**
MATERIAL QUANTITY: **750** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/01/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46171** BUIDLING ID: **1390**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Hyde Park Academy** REVIEW DATE: **3/31/2013**
ADDRESS: **6220 S. Stony Island** IDPH LICENSE NO: **100-02175**

HOMOGENEOUS AREA: **49**
MATERIAL DESCRIPTION: **12x12 beige F.T. Mastic**
MATERIAL LOCATION: **Small hallways leading to library on 2nd and 3rd floors.**
MATERIAL QUANTITY: **750** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **03/31/2013**

Chicago Public Schools

Carnow, Conibear and Associates 2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46171** BUIDLING ID: **1390**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ethan Payne**
SCHOOL NAME: **Hyde Park Academy** INSPECTION DATE: **3/1/2013**
ADDRESS: **6220 S. Stony Island** IDPH LICENSE NO: **100-02175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **50**
MATERIAL DESCRIPTION: **12x12 brown F.T. mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Locker rooms 1st floor**
MATERIAL QUANTITY: **4000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/01/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46171** BUIDLING ID: **1390**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Hyde Park Academy** REVIEW DATE: **3/31/2013**
ADDRESS: **6220 S. Stony Island** IDPH LICENSE NO: **100-02175**

HOMOGENEOUS AREA: **50**
MATERIAL DESCRIPTION: **12x12 brown F.T. mastic**
MATERIAL LOCATION: **Locker rooms 1st floor**
MATERIAL QUANTITY: **4000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **03/31/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46171** BUIDLING ID: **1390**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ethan Payne**
SCHOOL NAME: **Hyde Park Academy** INSPECTION DATE: **3/1/2013**
ADDRESS: **6220 S. Stony Island** IDPH LICENSE NO: **100-02175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **51**
MATERIAL DESCRIPTION: **12x12 lt. Brn. F.T. mastic**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Auditorium**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **03/01/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46171** BUIDLING ID: **1390**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Hyde Park Academy** REVIEW DATE: **3/31/2013**
ADDRESS: **6220 S. Stony Island** IDPH LICENSE NO: **100-02175**

HOMOGENEOUS AREA: **51**

MATERIAL DESCRIPTION: **12x12 lt. Brn. F.T. mastic**

MATERIAL LOCATION: **Auditorium**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **03/31/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46171** BUIDLING ID: **1390**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ethan Payne**
SCHOOL NAME: **Hyde Park Academy** INSPECTION DATE: **3/1/2013**
ADDRESS: **6220 S. Stony Island** IDPH LICENSE NO: **100-02175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **52**
MATERIAL DESCRIPTION: **12x12 dark tan F.T. mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **1911 building, patched areas**

MATERIAL QUANTITY: **800**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/01/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46171** BUIDLING ID: **1390**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Hyde Park Academy** REVIEW DATE: **3/31/2013**
ADDRESS: **6220 S. Stony Island** IDPH LICENSE NO: **100-02175**

HOMOGENEOUS AREA: **52**
MATERIAL DESCRIPTION: **12x12 dark tan F.T. mastic**
MATERIAL LOCATION: **1911 building, patched areas**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **03/31/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46171** BUIDLING ID: **1390**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ethan Payne**
SCHOOL NAME: **Hyde Park Academy** INSPECTION DATE: **3/1/2013**
ADDRESS: **6220 S. Stony Island** IDPH LICENSE NO: **100-02175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **53**
MATERIAL DESCRIPTION: **12x12 lt. Grn. F.T. mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 133**
MATERIAL QUANTITY: **1600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/01/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46171** BUIDLING ID: **1390**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Hyde Park Academy** REVIEW DATE: **3/31/2013**
ADDRESS: **6220 S. Stony Island** IDPH LICENSE NO: **100-02175**

HOMOGENEOUS AREA: **53**
MATERIAL DESCRIPTION: **12x12 lt. Grn. F.T. mastic**
MATERIAL LOCATION: **Room 133**
MATERIAL QUANTITY: **1600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **03/31/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46171** BUIDLING ID: **1390**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ethan Payne**
SCHOOL NAME: **Hyde Park Academy** INSPECTION DATE: **3/1/2013**
ADDRESS: **6220 S. Stony Island** IDPH LICENSE NO: **100-02175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **54**
MATERIAL DESCRIPTION: **12x12 off-white F.T. mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Engineer's office**

MATERIAL QUANTITY: **1825**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/01/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46171** BUIDLING ID: **1390**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Hyde Park Academy** REVIEW DATE: **3/31/2013**
ADDRESS: **6220 S. Stony Island** IDPH LICENSE NO: **100-02175**

HOMOGENEOUS AREA: **54**
MATERIAL DESCRIPTION: **12x12 off-white F.T. mastic**
MATERIAL LOCATION: **Engineer's office**
MATERIAL QUANTITY: **1825** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **03/31/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46171** BUIDLING ID: **1390**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ethan Payne**
SCHOOL NAME: **Hyde Park Academy** INSPECTION DATE: **3/1/2013**
ADDRESS: **6220 S. Stony Island** IDPH LICENSE NO: **100-02175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **55**
MATERIAL DESCRIPTION: **12x12 white F.T. mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms 135, 137**
MATERIAL QUANTITY: **2500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/01/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46171** BUIDLING ID: **1390**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Hyde Park Academy** REVIEW DATE: **3/31/2013**
ADDRESS: **6220 S. Stony Island** IDPH LICENSE NO: **100-02175**


HOMOGENEOUS AREA: **55**
MATERIAL DESCRIPTION: **12x12 white F.T. mastic**
MATERIAL LOCATION: **Rooms 135, 137**
MATERIAL QUANTITY: **2500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **03/31/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46171** BUIDLING ID: **1390**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ethan Payne**
SCHOOL NAME: **Hyde Park Academy** INSPECTION DATE: **3/1/2013**
ADDRESS: **6220 S. Stony Island** IDPH LICENSE NO: **100-02175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **56**
MATERIAL DESCRIPTION: **12x12 Tan speckled F.T. mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Patched areas of 1st flr north hallway**

MATERIAL QUANTITY: **490** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/01/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46171** BUIDLING ID: **1390**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Hyde Park Academy** REVIEW DATE: **3/31/2013**
ADDRESS: **6220 S. Stony Island** IDPH LICENSE NO: **100-02175**

HOMOGENEOUS AREA: **56**
MATERIAL DESCRIPTION: **12x12 Tan speckled F.T. mastic**
MATERIAL LOCATION: **Patched areas of 1st flr north hallway**
MATERIAL QUANTITY: **490** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **03/31/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46171** BUIDLING ID: **1390**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ethan Payne**
SCHOOL NAME: **Hyde Park Academy** INSPECTION DATE: **3/1/2013**
ADDRESS: **6220 S. Stony Island** IDPH LICENSE NO: **100-02175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **57**
MATERIAL DESCRIPTION: **9x9 brown F.T. mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **1937 building, patched areas of 1st, 2nd, 3rd flr hallways**

MATERIAL QUANTITY: **950** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: **03/01/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46171** BUIDLING ID: **1390**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Hyde Park Academy** REVIEW DATE: **3/31/2013**
ADDRESS: **6220 S. Stony Island** IDPH LICENSE NO: **100-02175**

HOMOGENEOUS AREA: **57**
MATERIAL DESCRIPTION: **9x9 brown F.T. mastic**
MATERIAL LOCATION: **1937 building, patched areas of 1st, 2nd, 3rd flr hallways**
MATERIAL QUANTITY: **950** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **03/31/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46171** BUIDLING ID: **1390**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ethan Payne**
SCHOOL NAME: **Hyde Park Academy** INSPECTION DATE: **3/1/2013**
ADDRESS: **6220 S. Stony Island** IDPH LICENSE NO: **100-02175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **58**
MATERIAL DESCRIPTION: **9x9 drk.brn. F.T. mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1937 building, patched areas of 1st, 2nd, 3rd flr hallways**
MATERIAL QUANTITY: **75** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/01/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46171** BUIDLING ID: **1390**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Hyde Park Academy** REVIEW DATE: **3/31/2013**
ADDRESS: **6220 S. Stony Island** IDPH LICENSE NO: **100-02175**

HOMOGENEOUS AREA: **58**
MATERIAL DESCRIPTION: **9x9 drk.brn. F.T. mastic**
MATERIAL LOCATION: **1937 building, patched areas of 1st, 2nd, 3rd flr hallways**
MATERIAL QUANTITY: **75** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **03/31/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46171** BUIDLING ID: **1390**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ethan Payne**
SCHOOL NAME: **Hyde Park Academy** INSPECTION DATE: **3/1/2013**
ADDRESS: **6220 S. Stony Island** IDPH LICENSE NO: **100-02175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **59**
MATERIAL DESCRIPTION: **12x12 lt. Brn. F.T. mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1937 building, patched areas of 1st, 2nd & 3rd floor south hallways**
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/01/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46171** BUIDLING ID: **1390**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Hyde Park Academy** REVIEW DATE: **3/31/2013**
ADDRESS: **6220 S. Stony Island** IDPH LICENSE NO: **100-02175**

HOMOGENEOUS AREA: **59**
MATERIAL DESCRIPTION: **12x12 lt. Brn. F.T. mastic**
MATERIAL LOCATION: **1937 building, patched areas of 1st, 2nd & 3rd floor south hallways**
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **03/31/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46171** BUIDLING ID: **1390**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ethan Payne**
SCHOOL NAME: **Hyde Park Academy** INSPECTION DATE: **3/1/2013**
ADDRESS: **6220 S. Stony Island** IDPH LICENSE NO: **100-02175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **60**
MATERIAL DESCRIPTION: **9x9 med. Brn. F.T. mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Team, Visitor, Boy's & Girl's Locker Rooms**

MATERIAL QUANTITY: **1800**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/01/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46171** BUIDLING ID: **1390**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Hyde Park Academy** REVIEW DATE: **3/31/2013**
ADDRESS: **6220 S. Stony Island** IDPH LICENSE NO: **100-02175**

HOMOGENEOUS AREA: **60**
MATERIAL DESCRIPTION: **9x9 med. Brn. F.T. mastic**
MATERIAL LOCATION: **Team, Visitor, Boy's & Girl's Locker Rooms**
MATERIAL QUANTITY: **1800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **03/31/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46171** BUIDLING ID: **1390**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ethan Payne**
SCHOOL NAME: **Hyde Park Academy** INSPECTION DATE: **3/1/2013**
ADDRESS: **6220 S. Stony Island** IDPH LICENSE NO: **100-02175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **61**
MATERIAL DESCRIPTION: **9x9 tan F.T. mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1937 buildng**
MATERIAL QUANTITY: **425** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/01/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46171** BUIDLING ID: **1390**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Hyde Park Academy** REVIEW DATE: **3/31/2013**
ADDRESS: **6220 S. Stony Island** IDPH LICENSE NO: **100-02175**

HOMOGENEOUS AREA: **61**
MATERIAL DESCRIPTION: **9x9 tan F.T. mastic**
MATERIAL LOCATION: **1937 buildng**
MATERIAL QUANTITY: **425** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **03/31/2013**

Chicago Public Schools

Carnow, Conibear and Associates 2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46171** BUIDLING ID: **1390**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ethan Payne**
SCHOOL NAME: **Hyde Park Academy** INSPECTION DATE: **3/1/2013**
ADDRESS: **6220 S. Stony Island** IDPH LICENSE NO: **100-02175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **62**
MATERIAL DESCRIPTION: **9x9 brown F.T. mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **SEE COMMENTS FOR ROOM LOCATIONS**

MATERIAL QUANTITY: **3100** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS: **142-145, 140,138,136,132,130,240,238,236,232,210,345,346,344,303,305,307,309,311,340,338,336,334,332**

Inspector's Signature:



Date: **03/01/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46171** BUIDLING ID: **1390**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Hyde Park Academy** REVIEW DATE: **3/31/2013**
ADDRESS: **6220 S. Stony Island** IDPH LICENSE NO: **100-02175**

HOMOGENEOUS AREA: **62**
MATERIAL DESCRIPTION: **9x9 brown F.T. mastic**
MATERIAL LOCATION: **SEE COMMENTS FOR ROOM LOCATIONS**
MATERIAL QUANTITY: **3100** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **03/31/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46171** BUIDLING ID: **1390**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ethan Payne**
SCHOOL NAME: **Hyde Park Academy** INSPECTION DATE: **3/1/2013**
ADDRESS: **6220 S. Stony Island** IDPH LICENSE NO: **100-02175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **63**
MATERIAL DESCRIPTION: **9x9 lt. Brn. F.T. mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Patched areas of 1st, 2nd & 3rd floor south hallways**

MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/01/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46171** BUIDLING ID: **1390**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Hyde Park Academy** REVIEW DATE: **3/31/2013**
ADDRESS: **6220 S. Stony Island** IDPH LICENSE NO: **100-02175**

HOMOGENEOUS AREA: **63**
MATERIAL DESCRIPTION: **9x9 lt. Brn. F.T. mastic**
MATERIAL LOCATION: **Patched areas of 1st, 2nd & 3rd floor south hallways**
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **03/31/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46171** BUIDLING ID: **1390**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ethan Payne**
SCHOOL NAME: **Hyde Park Academy** INSPECTION DATE: **3/1/2013**
ADDRESS: **6220 S. Stony Island** IDPH LICENSE NO: **100-02175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **64**
MATERIAL DESCRIPTION: **12x12 ceiling tile text**
HISTORICAL AHERA DAMAGE CATEGORY **6**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1911 building**
MATERIAL QUANTITY: **25000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/01/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46171** BUIDLING ID: **1390**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Hyde Park Academy** REVIEW DATE: **3/31/2013**
ADDRESS: **6220 S. Stony Island** IDPH LICENSE NO: **100-02175**

HOMOGENEOUS AREA: **64**
MATERIAL DESCRIPTION: **12x12 ceiling tile text**
MATERIAL LOCATION: **1911 building**
MATERIAL QUANTITY: **25000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **03/31/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46171** BUIDLING ID: **1390**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ethan Payne**
SCHOOL NAME: **Hyde Park Academy** INSPECTION DATE: **3/1/2013**
ADDRESS: **6220 S. Stony Island** IDPH LICENSE NO: **100-02175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **65**
MATERIAL DESCRIPTION: **12x12 ceiling tile text mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1911 building**
MATERIAL QUANTITY: **25000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/01/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46171** BUIDLING ID: **1390**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Hyde Park Academy** REVIEW DATE: **3/31/2013**
ADDRESS: **6220 S. Stony Island** IDPH LICENSE NO: **100-02175**

HOMOGENEOUS AREA: **65**
MATERIAL DESCRIPTION: **12x12 ceiling tile text mastic**
MATERIAL LOCATION: **1911 building**
MATERIAL QUANTITY: **25000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **03/31/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46171** BUIDLING ID: **1390**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ethan Payne**
SCHOOL NAME: **Hyde Park Academy** INSPECTION DATE: **3/1/2013**
ADDRESS: **6220 S. Stony Island** IDPH LICENSE NO: **100-02175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **66**
MATERIAL DESCRIPTION: **ceiling/tile system**
HISTORICAL AHERA DAMAGE CATEGORY **7**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7**. **Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1911 building**
MATERIAL QUANTITY: **15000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/01/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46171** BUIDLING ID: **1390**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Hyde Park Academy** REVIEW DATE: **3/31/2013**
ADDRESS: **6220 S. Stony Island** IDPH LICENSE NO: **100-02175**


HOMOGENEOUS AREA: **66**
MATERIAL DESCRIPTION: **ceiling/tile system**
MATERIAL LOCATION: **1911 building**
MATERIAL QUANTITY: **15000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **03/31/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46171** BUIDLING ID: **1390**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ethan Payne**
SCHOOL NAME: **Hyde Park Academy** INSPECTION DATE: **3/1/2013**
ADDRESS: **6220 S. Stony Island** IDPH LICENSE NO: **100-02175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **67**
MATERIAL DESCRIPTION: **12x12 ceiling tile matsic**
HISTORICAL AHERA DAMAGE CATEGORY **6**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1937 building**
MATERIAL QUANTITY: **1300** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/01/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46171** BUIDLING ID: **1390**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Hyde Park Academy** REVIEW DATE: **3/31/2013**
ADDRESS: **6220 S. Stony Island** IDPH LICENSE NO: **100-02175**


HOMOGENEOUS AREA: **67**
MATERIAL DESCRIPTION: **12x12 ceiling tile matsic**
MATERIAL LOCATION: **1937 building**
MATERIAL QUANTITY: **1300** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **03/31/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46171** BUILDING ID: **1390**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ethan Payne**
SCHOOL NAME: **Hyde Park Academy** INSPECTION DATE: **3/1/2013**
ADDRESS: **6220 S. Stony Island** IDPH LICENSE NO: **100-02175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **68**
MATERIAL DESCRIPTION: **2'x4' ceiling tile**
HISTORICAL AHERA DAMAGE CATEGORY **7**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7**. **Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1937 building**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/01/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46171** BUIDLING ID: **1390**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Hyde Park Academy** REVIEW DATE: **3/31/2013**
ADDRESS: **6220 S. Stony Island** IDPH LICENSE NO: **100-02175**


HOMOGENEOUS AREA: **68**
MATERIAL DESCRIPTION: **2'x4' ceiling tile**
MATERIAL LOCATION: **1937 building**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **03/31/2013**

Chicago Public Schools

Carnow, Conibear and Associates 2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46171** BUILDING ID: **1390**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ethan Payne**
SCHOOL NAME: **Hyde Park Academy** INSPECTION DATE: **3/1/2013**
ADDRESS: **6220 S. Stony Island** IDPH LICENSE NO: **100-02175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **69**
MATERIAL DESCRIPTION: **drop-in ceiling tile**
HISTORICAL AHERA DAMAGE CATEGORY **7**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7**. **Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1937 building**
MATERIAL QUANTITY: **8500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/01/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46171** BUIDLING ID: **1390**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Hyde Park Academy** REVIEW DATE: **3/31/2013**
ADDRESS: **6220 S. Stony Island** IDPH LICENSE NO: **100-02175**


HOMOGENEOUS AREA: **69**
MATERIAL DESCRIPTION: **drop-in ceiling tile**
MATERIAL LOCATION: **1937 building**
MATERIAL QUANTITY: **8500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **03/31/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46171** BUILDING ID: **1390**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ethan Payne**
SCHOOL NAME: **Hyde Park Academy** INSPECTION DATE: **3/1/2013**
ADDRESS: **6220 S. Stony Island** IDPH LICENSE NO: **100-02175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **70**
MATERIAL DESCRIPTION: **2'x4' ceiling tile**
HISTORICAL AHERA DAMAGE CATEGORY **7**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7**. **Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1970 building**
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/01/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46171** BUIDLING ID: **1390**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Hyde Park Academy** REVIEW DATE: **3/31/2013**
ADDRESS: **6220 S. Stony Island** IDPH LICENSE NO: **100-02175**


HOMOGENEOUS AREA: **70**
MATERIAL DESCRIPTION: **2'x4' ceiling tile**
MATERIAL LOCATION: **1970 building**
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **03/31/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46171** BUIDLING ID: **1390**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ethan Payne**
SCHOOL NAME: **Hyde Park Academy** INSPECTION DATE: **3/1/2013**
ADDRESS: **6220 S. Stony Island** IDPH LICENSE NO: **100-02175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **71**
MATERIAL DESCRIPTION: **black trim vinyl baseboard**
HISTORICAL AHERA DAMAGE CATEGORY **6**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1911 building**
MATERIAL QUANTITY: **18000** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature:



Date: **03/01/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46171** BUIDLING ID: **1390**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Hyde Park Academy** REVIEW DATE: **3/31/2013**
ADDRESS: **6220 S. Stony Island** IDPH LICENSE NO: **100-02175**


HOMOGENEOUS AREA: **71**
MATERIAL DESCRIPTION: **black trim vinyl baseboard**
MATERIAL LOCATION: **1911 building**
MATERIAL QUANTITY: **18000** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **03/31/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46171** BUIDLING ID: **1390**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ethan Payne**
SCHOOL NAME: **Hyde Park Academy** INSPECTION DATE: **3/1/2013**
ADDRESS: **6220 S. Stony Island** IDPH LICENSE NO: **100-02175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **72**
MATERIAL DESCRIPTION: **black trim vinyl baseboard mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1911 building**
MATERIAL QUANTITY: **18000** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature:



Date: **03/01/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46171** BUIDLING ID: **1390**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Hyde Park Academy** REVIEW DATE: **3/31/2013**
ADDRESS: **6220 S. Stony Island** IDPH LICENSE NO: **100-02175**

HOMOGENEOUS AREA: **72**

MATERIAL DESCRIPTION: **black trim vinyl baseboard mastic**

MATERIAL LOCATION: **1911 building**

MATERIAL QUANTITY: **18000**

MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **LF**


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **03/31/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46171** BUILDING ID: **1390**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ethan Payne**
SCHOOL NAME: **Hyde Park Academy** INSPECTION DATE: **3/1/2013**
ADDRESS: **6220 S. Stony Island** IDPH LICENSE NO: **100-02175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **73**
MATERIAL DESCRIPTION: **blk. Trim vinyl baseboard**
HISTORICAL AHERA DAMAGE CATEGORY **6**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1937 building**
MATERIAL QUANTITY: **275** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: DAMAGE UNITS: **LF**
COMMENTS:

Inspector's Signature:



Date: **03/01/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46171** BUIDLING ID: **1390**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Hyde Park Academy** REVIEW DATE: **3/31/2013**
ADDRESS: **6220 S. Stony Island** IDPH LICENSE NO: **100-02175**


HOMOGENEOUS AREA: **73**
MATERIAL DESCRIPTION: **blk. Trim vinyl baseboard**
MATERIAL LOCATION: **1937 building**
MATERIAL QUANTITY: **275** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **03/31/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46171** BUIDLING ID: **1390**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ethan Payne**
SCHOOL NAME: **Hyde Park Academy** INSPECTION DATE: **3/1/2013**
ADDRESS: **6220 S. Stony Island** IDPH LICENSE NO: **100-02175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **74**
MATERIAL DESCRIPTION: **blk. Trim vinyl baseboard mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1937 building**
MATERIAL QUANTITY: **275** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature:



Date: **03/01/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46171** BUIDLING ID: **1390**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Hyde Park Academy** REVIEW DATE: **3/31/2013**
ADDRESS: **6220 S. Stony Island** IDPH LICENSE NO: **100-02175**

HOMOGENEOUS AREA: **74**
MATERIAL DESCRIPTION: **blk. Trim vinyl baseboard mastic**
MATERIAL LOCATION: **1937 building**
MATERIAL QUANTITY: **275** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **03/31/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46171** BUILDING ID: **1390**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ethan Payne**
SCHOOL NAME: **Hyde Park Academy** INSPECTION DATE: **3/1/2013**
ADDRESS: **6220 S. Stony Island** IDPH LICENSE NO: **100-02175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **75**
MATERIAL DESCRIPTION: **black trim vinyl baseboard**
HISTORICAL AHERA DAMAGE CATEGORY **6**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1970 building**
MATERIAL QUANTITY: **300** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature:



Date: **03/01/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46171** BUIDLING ID: **1390**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Hyde Park Academy** REVIEW DATE: **3/31/2013**
ADDRESS: **6220 S. Stony Island** IDPH LICENSE NO: **100-02175**

HOMOGENEOUS AREA: **75**

MATERIAL DESCRIPTION: **black trim vinyl baseboard**

MATERIAL LOCATION: **1970 building**

MATERIAL QUANTITY: **300**

MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0**


DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **03/31/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46171** BUIDLING ID: **1390**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ethan Payne**
SCHOOL NAME: **Hyde Park Academy** INSPECTION DATE: **3/1/2013**
ADDRESS: **6220 S. Stony Island** IDPH LICENSE NO: **100-02175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **76**
MATERIAL DESCRIPTION: **black trim vinyl baseboard mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1970 building**
MATERIAL QUANTITY: **300** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature:



Date: **03/01/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46171** BUIDLING ID: **1390**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Hyde Park Academy** REVIEW DATE: **3/31/2013**
ADDRESS: **6220 S. Stony Island** IDPH LICENSE NO: **100-02175**

HOMOGENEOUS AREA: **76**

MATERIAL DESCRIPTION: **black trim vinyl baseboard mastic**

MATERIAL LOCATION: **1970 building**

MATERIAL QUANTITY: **300**

MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **LF**


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **03/31/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46171** BUIDLING ID: **1390**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ethan Payne**
SCHOOL NAME: **Hyde Park Academy** INSPECTION DATE: **3/1/2013**
ADDRESS: **6220 S. Stony Island** IDPH LICENSE NO: **100-02175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **77**
MATERIAL DESCRIPTION: **transite wind/sill**
HISTORICAL AHERA DAMAGE CATEGORY **6**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1911 building**
MATERIAL QUANTITY: **3000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/01/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46171** BUIDLING ID: **1390**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Hyde Park Academy** REVIEW DATE: **3/31/2013**
ADDRESS: **6220 S. Stony Island** IDPH LICENSE NO: **100-02175**

HOMOGENEOUS AREA: **77**

MATERIAL DESCRIPTION: **transite wind/sill**

MATERIAL LOCATION: **1911 building**

MATERIAL QUANTITY: **3000**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **03/31/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46171** BUIDLING ID: **1390**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ethan Payne**
SCHOOL NAME: **Hyde Park Academy** INSPECTION DATE: **3/1/2013**
ADDRESS: **6220 S. Stony Island** IDPH LICENSE NO: **100-02175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **78**
MATERIAL DESCRIPTION: **transite windowsill**
HISTORICAL AHERA DAMAGE CATEGORY **6**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1937 building**
MATERIAL QUANTITY: **550** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/01/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46171** BUIDLING ID: **1390**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Hyde Park Academy** REVIEW DATE: **3/31/2013**
ADDRESS: **6220 S. Stony Island** IDPH LICENSE NO: **100-02175**


HOMOGENEOUS AREA: **78**
MATERIAL DESCRIPTION: **transite windowsill**
MATERIAL LOCATION: **1937 building**
MATERIAL QUANTITY: **550** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **03/31/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46171** BUILDING ID: **1390**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ethan Payne**
SCHOOL NAME: **Hyde Park Academy** INSPECTION DATE: **3/1/2013**
ADDRESS: **6220 S. Stony Island** IDPH LICENSE NO: **100-02175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **79**
MATERIAL DESCRIPTION: **grey carpet mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1911 building**
MATERIAL QUANTITY: **950** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/01/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46171** BUIDLING ID: **1390**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Hyde Park Academy** REVIEW DATE: **3/31/2013**
ADDRESS: **6220 S. Stony Island** IDPH LICENSE NO: **100-02175**


HOMOGENEOUS AREA: **79**
MATERIAL DESCRIPTION: **grey carpet mastic**
MATERIAL LOCATION: **1911 building**
MATERIAL QUANTITY: **950** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **03/31/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46171** BUIDLING ID: **1390**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ethan Payne**
SCHOOL NAME: **Hyde Park Academy** INSPECTION DATE: **3/1/2013**
ADDRESS: **6220 S. Stony Island** IDPH LICENSE NO: **100-02175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **80**
MATERIAL DESCRIPTION: **green carpet mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1911 building**
MATERIAL QUANTITY: **1900** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/01/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46171** BUIDLING ID: **1390**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Hyde Park Academy** REVIEW DATE: **3/31/2013**
ADDRESS: **6220 S. Stony Island** IDPH LICENSE NO: **100-02175**


HOMOGENEOUS AREA: **80**
MATERIAL DESCRIPTION: **green carpet mastic**
MATERIAL LOCATION: **1911 building**
MATERIAL QUANTITY: **1900** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **03/31/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46171** BUIDLING ID: **1390**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ethan Payne**
SCHOOL NAME: **Hyde Park Academy** INSPECTION DATE: **3/1/2013**
ADDRESS: **6220 S. Stony Island** IDPH LICENSE NO: **100-02175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **81**
MATERIAL DESCRIPTION: **brown carpet mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1911 building**
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/01/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46171** BUIDLING ID: **1390**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Hyde Park Academy** REVIEW DATE: **3/31/2013**
ADDRESS: **6220 S. Stony Island** IDPH LICENSE NO: **100-02175**

HOMOGENEOUS AREA: **81**
MATERIAL DESCRIPTION: **brown carpet mastic**
MATERIAL LOCATION: **1911 building**
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **03/31/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46171** BUILDING ID: **1390**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ethan Payne**
SCHOOL NAME: **Hyde Park Academy** INSPECTION DATE: **3/1/2013**
ADDRESS: **6220 S. Stony Island** IDPH LICENSE NO: **100-02175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **82**
MATERIAL DESCRIPTION: **dr. orange carpet mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1911 building**
MATERIAL QUANTITY: **15000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/01/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46171** BUIDLING ID: **1390**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Hyde Park Academy** REVIEW DATE: **3/31/2013**
ADDRESS: **6220 S. Stony Island** IDPH LICENSE NO: **100-02175**


HOMOGENEOUS AREA: **82**
MATERIAL DESCRIPTION: **dr. orange carpet mastic**
MATERIAL LOCATION: **1911 building**
MATERIAL QUANTITY: **15000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **03/31/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46171** BUILDING ID: **1390**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ethan Payne**
SCHOOL NAME: **Hyde Park Academy** INSPECTION DATE: **3/1/2013**
ADDRESS: **6220 S. Stony Island** IDPH LICENSE NO: **100-02175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **83**
MATERIAL DESCRIPTION: **orange carpet mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1911 building**
MATERIAL QUANTITY: **21000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/01/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46171** BUIDLING ID: **1390**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Hyde Park Academy** REVIEW DATE: **3/31/2013**
ADDRESS: **6220 S. Stony Island** IDPH LICENSE NO: **100-02175**


HOMOGENEOUS AREA: **83**
MATERIAL DESCRIPTION: **orange carpet mastic**
MATERIAL LOCATION: **1911 building**
MATERIAL QUANTITY: **21000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **03/31/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46171** BUIDLING ID: **1390**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ethan Payne**
SCHOOL NAME: **Hyde Park Academy** INSPECTION DATE: **3/1/2013**
ADDRESS: **6220 S. Stony Island** IDPH LICENSE NO: **100-02175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **84**
MATERIAL DESCRIPTION: **12" x 12" Light gray with white floor tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**

MATERIAL LOCATION: **Auditorium**

MATERIAL QUANTITY: **3000**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/01/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46171** BUIDLING ID: **1390**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Hyde Park Academy** REVIEW DATE: **3/31/2013**
ADDRESS: **6220 S. Stony Island** IDPH LICENSE NO: **100-02175**

HOMOGENEOUS AREA: **84**
MATERIAL DESCRIPTION: **12" x 12" Light gray with white floor tile**
MATERIAL LOCATION: **Auditorium**
MATERIAL QUANTITY: **3000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **03/31/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46171** BUIDLING ID: **1390**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ethan Payne**
SCHOOL NAME: **Hyde Park Academy** INSPECTION DATE: **3/1/2013**
ADDRESS: **6220 S. Stony Island** IDPH LICENSE NO: **100-02175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **85**
MATERIAL DESCRIPTION: **Mastic for 12" x 12" Light gray with white floor tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Auditorium**
MATERIAL QUANTITY: **3000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/01/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46171** BUIDLING ID: **1390**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Hyde Park Academy** REVIEW DATE: **3/31/2013**
ADDRESS: **6220 S. Stony Island** IDPH LICENSE NO: **100-02175**

HOMOGENEOUS AREA: **85**
MATERIAL DESCRIPTION: **Mastic for 12" x 12" Light gray with white floor tile**
MATERIAL LOCATION: **Auditorium**
MATERIAL QUANTITY: **3000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **03/31/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46171** BUILDING ID: **1390**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ethan Payne**
SCHOOL NAME: **Hyde Park Academy** INSPECTION DATE: **3/1/2013**
ADDRESS: **6220 S. Stony Island** IDPH LICENSE NO: **100-02175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **86**
MATERIAL DESCRIPTION: **Gray mix Terrazzo**
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Entrance and stairwells**
MATERIAL QUANTITY: **5000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/01/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46171** BUIDLING ID: **1390**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Hyde Park Academy** REVIEW DATE: **3/31/2013**
ADDRESS: **6220 S. Stony Island** IDPH LICENSE NO: **100-02175**

HOMOGENEOUS AREA: **86**
MATERIAL DESCRIPTION: **Gray mix Terrazzo**
MATERIAL LOCATION: **Entrance and stairwells**
MATERIAL QUANTITY: **5000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **03/31/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46171** BUIDLING ID: **1390**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ethan Payne**
SCHOOL NAME: **Hyde Park Academy** INSPECTION DATE: **3/1/2013**
ADDRESS: **6220 S. Stony Island** IDPH LICENSE NO: **100-02175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **87**
MATERIAL DESCRIPTION: **12" x 12" White w/gray and black floor tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Room 114 and patches in room 210**
MATERIAL QUANTITY: **3200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature:



Date: **03/01/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46171** BUIDLING ID: **1390**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Hyde Park Academy** REVIEW DATE: **3/31/2013**
ADDRESS: **6220 S. Stony Island** IDPH LICENSE NO: **100-02175**

HOMOGENEOUS AREA: **87**
MATERIAL DESCRIPTION: **12" x 12" White w/gray and black floor tile**
MATERIAL LOCATION: **Room 114 and patches in room 210**
MATERIAL QUANTITY: **3200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **03/31/2013**

Chicago Public Schools

Carnow, Conibear and Associates 2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46171** BUIDLING ID: **1390**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ethan Payne**
SCHOOL NAME: **Hyde Park Academy** INSPECTION DATE: **3/1/2013**
ADDRESS: **6220 S. Stony Island** IDPH LICENSE NO: **100-02175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **88**
MATERIAL DESCRIPTION: **Mastic for 12" x 12" white with gray and black floor tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 114 and patches in Room 210**
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature:



Date: **03/01/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46171** BUIDLING ID: **1390**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Hyde Park Academy** REVIEW DATE: **3/31/2013**
ADDRESS: **6220 S. Stony Island** IDPH LICENSE NO: **100-02175**

HOMOGENEOUS AREA: **88**
MATERIAL DESCRIPTION: **Mastic for 12" x 12" white with gray and black floor tile**
MATERIAL LOCATION: **Room 114 and patches in Room 210**
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **03/31/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46171** BUIDLING ID: **1390**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ethan Payne**
SCHOOL NAME: **Hyde Park Academy** INSPECTION DATE: **3/1/2013**
ADDRESS: **6220 S. Stony Island** IDPH LICENSE NO: **100-02175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **89**
MATERIAL DESCRIPTION: **12" x 12" white with blue and red floor tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**

MATERIAL LOCATION: **Room 117**

MATERIAL QUANTITY: **1800**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/01/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46171** BUIDLING ID: **1390**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Hyde Park Academy** REVIEW DATE: **3/31/2013**
ADDRESS: **6220 S. Stony Island** IDPH LICENSE NO: **100-02175**

HOMOGENEOUS AREA: **89**
MATERIAL DESCRIPTION: **12" x 12" white with blue and red floor tile**
MATERIAL LOCATION: **Room 117**
MATERIAL QUANTITY: **1800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **03/31/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46171** BUIDLING ID: **1390**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ethan Payne**
SCHOOL NAME: **Hyde Park Academy** INSPECTION DATE: **3/1/2013**
ADDRESS: **6220 S. Stony Island** IDPH LICENSE NO: **100-02175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **90**
MATERIAL DESCRIPTION: **Mastic for 12" x 12" white with Blue and Ref floor tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 117**
MATERIAL QUANTITY: **1800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/01/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46171** BUIDLING ID: **1390**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Hyde Park Academy** REVIEW DATE: **3/31/2013**
ADDRESS: **6220 S. Stony Island** IDPH LICENSE NO: **100-02175**

HOMOGENEOUS AREA: **90**
MATERIAL DESCRIPTION: **Mastic for 12" x 12" white with Blue and Ref floor tile**
MATERIAL LOCATION: **Room 117**
MATERIAL QUANTITY: **1800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **03/31/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46171** BUIDLING ID: **1390**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ethan Payne**
SCHOOL NAME: **Hyde Park Academy** INSPECTION DATE: **3/1/2013**
ADDRESS: **6220 S. Stony Island** IDPH LICENSE NO: **100-02175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **91**
MATERIAL DESCRIPTION: **Black Chalk boards**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Classrooms**
MATERIAL QUANTITY: **13000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/01/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46171** BUIDLING ID: **1390**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Hyde Park Academy** REVIEW DATE: **3/31/2013**
ADDRESS: **6220 S. Stony Island** IDPH LICENSE NO: **100-02175**

HOMOGENEOUS AREA: **91**
MATERIAL DESCRIPTION: **Black Chalk boards**
MATERIAL LOCATION: **Classrooms**
MATERIAL QUANTITY: **13000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **03/31/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46171** BUIDLING ID: **1390**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ethan Payne**
SCHOOL NAME: **Hyde Park Academy** INSPECTION DATE: **3/1/2013**
ADDRESS: **6220 S. Stony Island** IDPH LICENSE NO: **100-02175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **92**
MATERIAL DESCRIPTION: **Black Chalk Board Adhesive**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Classrooms**
MATERIAL QUANTITY: **13000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/01/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46171** BUIDLING ID: **1390**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Hyde Park Academy** REVIEW DATE: **3/31/2013**
ADDRESS: **6220 S. Stony Island** IDPH LICENSE NO: **100-02175**

HOMOGENEOUS AREA: **92**
MATERIAL DESCRIPTION: **Black Chalk Board Adhesive**
MATERIAL LOCATION: **Classrooms**
MATERIAL QUANTITY: **13000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **03/31/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46171** BUIDLING ID: **1390**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ethan Payne**
SCHOOL NAME: **Hyde Park Academy** INSPECTION DATE: **3/1/2013**
ADDRESS: **6220 S. Stony Island** IDPH LICENSE NO: **100-02175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **A**
MATERIAL DESCRIPTION: **Mag block**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **boiler**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **03/01/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46171** BUIDLING ID: **1390**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Hyde Park Academy** REVIEW DATE: **3/31/2013**
ADDRESS: **6220 S. Stony Island** IDPH LICENSE NO: **100-02175**

HOMOGENEOUS AREA: **A**

MATERIAL DESCRIPTION: **Mag block**

MATERIAL LOCATION: **boiler**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **03/31/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46171** BUIDLING ID: **1390**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ethan Payne**
SCHOOL NAME: **Hyde Park Academy** INSPECTION DATE: **3/1/2013**
ADDRESS: **6220 S. Stony Island** IDPH LICENSE NO: **100-02175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **B**
MATERIAL DESCRIPTION: **mag block**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **garage**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **03/01/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46171** BUIDLING ID: **1390**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Hyde Park Academy** REVIEW DATE: **3/31/2013**
ADDRESS: **6220 S. Stony Island** IDPH LICENSE NO: **100-02175**

HOMOGENEOUS AREA: **B**

MATERIAL DESCRIPTION: **mag block**

MATERIAL LOCATION: **garage**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **03/31/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46171** BUIDLING ID: **1390**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ethan Payne**
SCHOOL NAME: **Hyde Park Academy** INSPECTION DATE: **3/1/2013**
ADDRESS: **6220 S. Stony Island** IDPH LICENSE NO: **100-02175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **C**
MATERIAL DESCRIPTION: **mag block**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **suspended in pump room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **03/01/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46171** BUIDLING ID: **1390**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Hyde Park Academy** REVIEW DATE: **3/31/2013**
ADDRESS: **6220 S. Stony Island** IDPH LICENSE NO: **100-02175**

HOMOGENEOUS AREA: **C**

MATERIAL DESCRIPTION: **mag block**

MATERIAL LOCATION: **suspened in pump room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **03/31/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46171** BUIDLING ID: **1390**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ethan Payne**
SCHOOL NAME: **Hyde Park Academy** INSPECTION DATE: **3/1/2013**
ADDRESS: **6220 S. Stony Island** IDPH LICENSE NO: **100-02175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **D**
MATERIAL DESCRIPTION: **mag block ABATED**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **pump rm.**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **03/01/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46171** BUIDLING ID: **1390**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Hyde Park Academy** REVIEW DATE: **3/31/2013**
ADDRESS: **6220 S. Stony Island** IDPH LICENSE NO: **100-02175**

HOMOGENEOUS AREA: **D**

MATERIAL DESCRIPTION: **mag block ABATED**

MATERIAL LOCATION: **pump rm.**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **03/31/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46171** BUIDLING ID: **1390**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ethan Payne**
SCHOOL NAME: **Hyde Park Academy** INSPECTION DATE: **3/1/2013**
ADDRESS: **6220 S. Stony Island** IDPH LICENSE NO: **100-02175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **E**
MATERIAL DESCRIPTION: **mag block**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **boiler room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **03/01/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46171** BUIDLING ID: **1390**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Hyde Park Academy** REVIEW DATE: **3/31/2013**
ADDRESS: **6220 S. Stony Island** IDPH LICENSE NO: **100-02175**

HOMOGENEOUS AREA: **E**

MATERIAL DESCRIPTION: **mag block**

MATERIAL LOCATION: **boiler room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **03/31/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46171** BUIDLING ID: **1390**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ethan Payne**
SCHOOL NAME: **Hyde Park Academy** INSPECTION DATE: **3/1/2013**
ADDRESS: **6220 S. Stony Island** IDPH LICENSE NO: **100-02175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **F**
MATERIAL DESCRIPTION: **preform pipe**
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with potential for significant damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **Moderate**

MATERIAL LOCATION: **boiler room & tunnel**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Material Abated, some material may exist in tunnels**

Inspector's Signature:



Date: **03/01/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46171** BUIDLING ID: **1390**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Hyde Park Academy** REVIEW DATE: **3/31/2013**
ADDRESS: **6220 S. Stony Island** IDPH LICENSE NO: **100-02175**

HOMOGENEOUS AREA: **F**

MATERIAL DESCRIPTION: **preform pipe**

MATERIAL LOCATION: **boiler room & tunnel**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **03/31/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46171** BUIDLING ID: **1390**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ethan Payne**
SCHOOL NAME: **Hyde Park Academy** INSPECTION DATE: **3/1/2013**
ADDRESS: **6220 S. Stony Island** IDPH LICENSE NO: **100-02175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **G**
MATERIAL DESCRIPTION: **preform fittings**
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with potential for significant damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **Moderate**

MATERIAL LOCATION: **basement & tunnels**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **03/01/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46171** BUIDLING ID: **1390**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Hyde Park Academy** REVIEW DATE: **3/31/2013**
ADDRESS: **6220 S. Stony Island** IDPH LICENSE NO: **100-02175**

HOMOGENEOUS AREA: **G**

MATERIAL DESCRIPTION: **preform fittings**

MATERIAL LOCATION: **basement & tunnels**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **03/31/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46171** BUIDLING ID: **1390**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ethan Payne**
SCHOOL NAME: **Hyde Park Academy** INSPECTION DATE: **3/1/2013**
ADDRESS: **6220 S. Stony Island** IDPH LICENSE NO: **100-02175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **H**
MATERIAL DESCRIPTION: **cardboard pipe insulation**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **compressor rm./ pump rm. Absorption rm./ tunnels**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **03/01/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46171** BUIDLING ID: **1390**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Hyde Park Academy** REVIEW DATE: **3/31/2013**
ADDRESS: **6220 S. Stony Island** IDPH LICENSE NO: **100-02175**

HOMOGENEOUS AREA: **H**
MATERIAL DESCRIPTION: **cardboard pipe insulation**
MATERIAL LOCATION: **compressor rm./ pump rm. Absorption rm./ tunnels**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **03/31/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46171** BUIDLING ID: **1390**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ethan Payne**
SCHOOL NAME: **Hyde Park Academy** INSPECTION DATE: **3/1/2013**
ADDRESS: **6220 S. Stony Island** IDPH LICENSE NO: **100-02175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **HA-1000**
MATERIAL DESCRIPTION: **Glue for 1'x1' white ceiling tile with grooves**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Rm. 301, 303, 305, 307, 309, 311**
MATERIAL QUANTITY: **34500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature:



Date: **03/01/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46171** BUIDLING ID: **1390**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Hyde Park Academy** REVIEW DATE: **3/31/2013**
ADDRESS: **6220 S. Stony Island** IDPH LICENSE NO: **100-02175**

HOMOGENEOUS AREA: **HA-1000**
MATERIAL DESCRIPTION: **Glue for 1'x1' white ceiling tile with grooves**
MATERIAL LOCATION: **Rm. 301, 303, 305, 307, 309, 311**
MATERIAL QUANTITY: **34500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **03/31/2013**

Chicago Public Schools

Carnow, Conibear and Associates 2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46171** BUIDLING ID: **1390**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ethan Payne**
SCHOOL NAME: **Hyde Park Academy** INSPECTION DATE: **3/1/2013**
ADDRESS: **6220 S. Stony Island** IDPH LICENSE NO: **100-02175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **HA-1001**
MATERIAL DESCRIPTION: **new 2'x2' white ceiling tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **throughout 1st and 3rd floor**
MATERIAL QUANTITY: **35000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/01/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46171** BUIDLING ID: **1390**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Hyde Park Academy** REVIEW DATE: **3/31/2013**
ADDRESS: **6220 S. Stony Island** IDPH LICENSE NO: **100-02175**

HOMOGENEOUS AREA: **HA-1001**
MATERIAL DESCRIPTION: **new 2'x2' white ceiling tile**
MATERIAL LOCATION: **throughout 1st and 3rd floor**
MATERIAL QUANTITY: **35000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **03/31/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46171** BUIDLING ID: **1390**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ethan Payne**
SCHOOL NAME: **Hyde Park Academy** INSPECTION DATE: **3/1/2013**
ADDRESS: **6220 S. Stony Island** IDPH LICENSE NO: **100-02175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **HA-1002**
MATERIAL DESCRIPTION: **new 2'x4' white ceiling tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **throughout 1st and 3rd floors**

MATERIAL QUANTITY: **35000**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/01/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46171** BUIDLING ID: **1390**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Hyde Park Academy** REVIEW DATE: **3/31/2013**
ADDRESS: **6220 S. Stony Island** IDPH LICENSE NO: **100-02175**

HOMOGENEOUS AREA: **HA-1002**
MATERIAL DESCRIPTION: **new 2'x4' white ceiling tile**
MATERIAL LOCATION: **throughout 1st and 3rd floors**
MATERIAL QUANTITY: **35000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **03/31/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46171** BUIDLING ID: **1390**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ethan Payne**
SCHOOL NAME: **Hyde Park Academy** INSPECTION DATE: **3/1/2013**
ADDRESS: **6220 S. Stony Island** IDPH LICENSE NO: **100-02175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **HA-1003**
MATERIAL DESCRIPTION: **Black sink unsercoating**
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Art rooms 401, 402, 406**

MATERIAL QUANTITY: **15**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/01/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46171** BUILDING ID: **1390**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Hyde Park Academy** REVIEW DATE: **3/31/2013**
ADDRESS: **6220 S. Stony Island** IDPH LICENSE NO: **100-02175**

HOMOGENEOUS AREA: **HA-1003**
MATERIAL DESCRIPTION: **Black sink unsecoating**
MATERIAL LOCATION: **Art rooms 401, 402, 406**
MATERIAL QUANTITY: **15** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **03/31/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46171** BUIDLING ID: **1390**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ethan Payne**
SCHOOL NAME: **Hyde Park Academy** INSPECTION DATE: **3/1/2013**
ADDRESS: **6220 S. Stony Island** IDPH LICENSE NO: **100-02175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **I**
MATERIAL DESCRIPTION: **cardboard fittings**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**

MATERIAL LOCATION: **tunnels/compressor rm.**

MATERIAL QUANTITY: **40**

MATERIAL UNITS: **LF**

DAMAGE QUANTITY:

DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature:



Date: **03/01/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46171** BUIDLING ID: **1390**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Hyde Park Academy** REVIEW DATE: **3/31/2013**
ADDRESS: **6220 S. Stony Island** IDPH LICENSE NO: **100-02175**

HOMOGENEOUS AREA: **I**
MATERIAL DESCRIPTION: **cardboard fittings**
MATERIAL LOCATION: **tunnels/compressor rm.**
MATERIAL QUANTITY: **40** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **03/31/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46171** BUIDLING ID: **1390**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ethan Payne**
SCHOOL NAME: **Hyde Park Academy** INSPECTION DATE: **3/1/2013**
ADDRESS: **6220 S. Stony Island** IDPH LICENSE NO: **100-02175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **J**
MATERIAL DESCRIPTION: **fiberglass fittings**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1911 building**
MATERIAL QUANTITY: **1800** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature:



Date: **03/01/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46171** BUIDLING ID: **1390**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Hyde Park Academy** REVIEW DATE: **3/31/2013**
ADDRESS: **6220 S. Stony Island** IDPH LICENSE NO: **100-02175**

HOMOGENEOUS AREA: **J**
MATERIAL DESCRIPTION: **fiberglass fittings**
MATERIAL LOCATION: **1911 building**
MATERIAL QUANTITY: **1800** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **03/31/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46171** BUIDLING ID: **1390**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ethan Payne**
SCHOOL NAME: **Hyde Park Academy** INSPECTION DATE: **3/1/2013**
ADDRESS: **6220 S. Stony Island** IDPH LICENSE NO: **100-02175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **K**
MATERIAL DESCRIPTION: **aircell duct insulation**
HISTORICAL AHERA DAMAGE CATEGORY **7**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7**. **Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **tunnels**
MATERIAL QUANTITY: **30** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/01/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46171** BUIDLING ID: **1390**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Hyde Park Academy** REVIEW DATE: **3/31/2013**
ADDRESS: **6220 S. Stony Island** IDPH LICENSE NO: **100-02175**

HOMOGENEOUS AREA: **K**
MATERIAL DESCRIPTION: **aircell duct insulation**
MATERIAL LOCATION: **tunnels**
MATERIAL QUANTITY: **30** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **03/31/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46171** BUIDLING ID: **1390**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ethan Payne**
SCHOOL NAME: **Hyde Park Academy** INSPECTION DATE: **3/1/2013**
ADDRESS: **6220 S. Stony Island** IDPH LICENSE NO: **100-02175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **L**
MATERIAL DESCRIPTION: **aircell pipe insulation**
HISTORICAL AHERA DAMAGE CATEGORY **7 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **pump rm. Tunnels**
MATERIAL QUANTITY: **2240** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature:



Date: **03/01/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46171** BUIDLING ID: **1390**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Hyde Park Academy** REVIEW DATE: **3/31/2013**
ADDRESS: **6220 S. Stony Island** IDPH LICENSE NO: **100-02175**

HOMOGENEOUS AREA: **L**
MATERIAL DESCRIPTION: **aircell pipe insulation**
MATERIAL LOCATION: **pump rm. Tunnels**
MATERIAL QUANTITY: **2240** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **03/31/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46171** BUIDLING ID: **1390**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ethan Payne**
SCHOOL NAME: **Hyde Park Academy** INSPECTION DATE: **3/1/2013**
ADDRESS: **6220 S. Stony Island** IDPH LICENSE NO: **100-02175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **M**
MATERIAL DESCRIPTION: **fittings on aircell**
HISTORICAL AHERA DAMAGE CATEGORY **7**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7**. **Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **pump room 1911**
MATERIAL QUANTITY: **140** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature:



Date: **03/01/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46171** BUIDLING ID: **1390**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Hyde Park Academy** REVIEW DATE: **3/31/2013**
ADDRESS: **6220 S. Stony Island** IDPH LICENSE NO: **100-02175**


HOMOGENEOUS AREA: **M**
MATERIAL DESCRIPTION: **fittings on aircell**
MATERIAL LOCATION: **pump room 1911**
MATERIAL QUANTITY: **140** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **03/31/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46171** BUILDING ID: **1390**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ethan Payne**
SCHOOL NAME: **Hyde Park Academy** INSPECTION DATE: **3/1/2013**
ADDRESS: **6220 S. Stony Island** IDPH LICENSE NO: **100-02175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **N**
MATERIAL DESCRIPTION: **fiber glass fittings**
HISTORICAL AHERA DAMAGE CATEGORY **7 ACBM with potential for significant damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **1937 building**
MATERIAL QUANTITY: **400** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature:



Date: **03/01/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46171** BUIDLING ID: **1390**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Hyde Park Academy** REVIEW DATE: **3/31/2013**
ADDRESS: **6220 S. Stony Island** IDPH LICENSE NO: **100-02175**

HOMOGENEOUS AREA: **N**
MATERIAL DESCRIPTION: **fiber glass fittings**
MATERIAL LOCATION: **1937 building**
MATERIAL QUANTITY: **400** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **03/31/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46171** BUIDLING ID: **1390**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ethan Payne**
SCHOOL NAME: **Hyde Park Academy** INSPECTION DATE: **3/1/2013**
ADDRESS: **6220 S. Stony Island** IDPH LICENSE NO: **100-02175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **O**
MATERIAL DESCRIPTION: **fiberglass fittings**
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **Moderate**

MATERIAL LOCATION: **1970bldg**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Fiberglass not suspect material**

Inspector's Signature:



Date: **03/01/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46171** BUIDLING ID: **1390**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Hyde Park Academy** REVIEW DATE: **3/31/2013**
ADDRESS: **6220 S. Stony Island** IDPH LICENSE NO: **100-02175**

HOMOGENEOUS AREA: **0**

MATERIAL DESCRIPTION: **fiberglass fittings**

MATERIAL LOCATION: **1970bldg**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **03/31/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46171** BUIDLING ID: **1390**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ethan Payne**
SCHOOL NAME: **Hyde Park Academy** INSPECTION DATE: **3/1/2013**
ADDRESS: **6220 S. Stony Island** IDPH LICENSE NO: **100-02175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **P**
MATERIAL DESCRIPTION: **2'x2' WHITE CEILING TILE**
HISTORICAL AHERA DAMAGE CATEGORY **7 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **THROUGHOUT 1911 BLDG**
MATERIAL QUANTITY: **69000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/01/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46171** BUIDLING ID: **1390**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Hyde Park Academy** REVIEW DATE: **3/31/2013**
ADDRESS: **6220 S. Stony Island** IDPH LICENSE NO: **100-02175**

HOMOGENEOUS AREA: **P**
MATERIAL DESCRIPTION: **2'x2' WHITE CEILING TILE**
MATERIAL LOCATION: **THROUGHOUT 1911 BLDG**
MATERIAL QUANTITY: **69000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **03/31/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46171** BUIDLING ID: **1390**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ethan Payne**
SCHOOL NAME: **Hyde Park Academy** INSPECTION DATE: **3/1/2013**
ADDRESS: **6220 S. Stony Island** IDPH LICENSE NO: **100-02175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **Q**
MATERIAL DESCRIPTION: **LINOLEUM FLOORING Grey with white**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **ROOM 245, and 343**
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/01/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46171** BUIDLING ID: **1390**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Hyde Park Academy** REVIEW DATE: **3/31/2013**
ADDRESS: **6220 S. Stony Island** IDPH LICENSE NO: **100-02175**

HOMOGENEOUS AREA: **Q**
MATERIAL DESCRIPTION: **LINOLEUM FLOORING Grey with white**
MATERIAL LOCATION: **ROOM 245, and 343**
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **03/31/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46171** BUIDLING ID: **1390**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ethan Payne**
SCHOOL NAME: **Hyde Park Academy** INSPECTION DATE: **3/1/2013**
ADDRESS: **6220 S. Stony Island** IDPH LICENSE NO: **100-02175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **Q-1**
MATERIAL DESCRIPTION: **LINOLEUM FLOORING-MASTIC**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **ROOM 245, and 343**
MATERIAL QUANTITY: **950** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/01/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46171** BUIDLING ID: **1390**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Hyde Park Academy** REVIEW DATE: **3/31/2013**
ADDRESS: **6220 S. Stony Island** IDPH LICENSE NO: **100-02175**

HOMOGENEOUS AREA: **Q-1**
MATERIAL DESCRIPTION: **LINOLEUM FLOORING-MASTIC**
MATERIAL LOCATION: **ROOM 245, and 343**
MATERIAL QUANTITY: **950** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **03/31/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46171** BUIDLING ID: **1390**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ethan Payne**
SCHOOL NAME: **Hyde Park Academy** INSPECTION DATE: **3/1/2013**
ADDRESS: **6220 S. Stony Island** IDPH LICENSE NO: **100-02175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **R**
MATERIAL DESCRIPTION: **12x12 BROWN VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **ROOMS 341, 333**
MATERIAL QUANTITY: **2300** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/01/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46171** BUIDLING ID: **1390**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Hyde Park Academy** REVIEW DATE: **3/31/2013**
ADDRESS: **6220 S. Stony Island** IDPH LICENSE NO: **100-02175**

HOMOGENEOUS AREA: **R**
MATERIAL DESCRIPTION: **12x12 BROWN VFT**
MATERIAL LOCATION: **ROOMS 341, 333**
MATERIAL QUANTITY: **2300** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **03/31/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46171** BUIDLING ID: **1390**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ethan Payne**
SCHOOL NAME: **Hyde Park Academy** INSPECTION DATE: **3/1/2013**
ADDRESS: **6220 S. Stony Island** IDPH LICENSE NO: **100-02175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **R-1**
MATERIAL DESCRIPTION: **12x12 BROWN VFT-MASTIC**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **ROOMS 341, 333**
MATERIAL QUANTITY: **2300** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/01/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46171** BUIDLING ID: **1390**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Hyde Park Academy** REVIEW DATE: **3/31/2013**
ADDRESS: **6220 S. Stony Island** IDPH LICENSE NO: **100-02175**

HOMOGENEOUS AREA: **R-1**
MATERIAL DESCRIPTION: **12x12 BROWN VFT-MASTIC**
MATERIAL LOCATION: **ROOMS 341, 333**
MATERIAL QUANTITY: **2300** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **03/31/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46171** BUIDLING ID: **1390**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ethan Payne**
SCHOOL NAME: **Hyde Park Academy** INSPECTION DATE: **3/1/2013**
ADDRESS: **6220 S. Stony Island** IDPH LICENSE NO: **100-02175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **S**
MATERIAL DESCRIPTION: **12x12 BLUE VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **EAST STAIRWELL, FRONT OF AUDITORIUM & ALL OF AUDITORIUM**
MATERIAL QUANTITY: **3250** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/01/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46171** BUIDLING ID: **1390**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Hyde Park Academy** REVIEW DATE: **3/31/2013**
ADDRESS: **6220 S. Stony Island** IDPH LICENSE NO: **100-02175**

HOMOGENEOUS AREA: **S**
MATERIAL DESCRIPTION: **12x12 BLUE VFT**
MATERIAL LOCATION: **EAST STAIRWELL, FRONT OF AUDITORIUM & ALL OF AUDITORIUM**
MATERIAL QUANTITY: **3250** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **03/31/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46171** BUIDLING ID: **1390**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ethan Payne**
SCHOOL NAME: **Hyde Park Academy** INSPECTION DATE: **3/1/2013**
ADDRESS: **6220 S. Stony Island** IDPH LICENSE NO: **100-02175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **S-1**
MATERIAL DESCRIPTION: **12x12 BLUE VFT-MASTIC**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **EAST STAIRWELL, FRONT OF AUDITORIUM & ALL OF AUDITORIUM**
MATERIAL QUANTITY: **3250** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/01/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46171** BUIDLING ID: **1390**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Hyde Park Academy** REVIEW DATE: **3/31/2013**
ADDRESS: **6220 S. Stony Island** IDPH LICENSE NO: **100-02175**

HOMOGENEOUS AREA: **S-1**
MATERIAL DESCRIPTION: **12x12 BLUE VFT-MASTIC**
MATERIAL LOCATION: **EAST STAIRWELL, FRONT OF AUDITORIUM & ALL OF AUDITORIUM**
MATERIAL QUANTITY: **3250** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **03/31/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46171** BUIDLING ID: **1390**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ethan Payne**
SCHOOL NAME: **Hyde Park Academy** INSPECTION DATE: **3/1/2013**
ADDRESS: **6220 S. Stony Island** IDPH LICENSE NO: **100-02175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **T**
MATERIAL DESCRIPTION: **12x12 ORANGE W/ GREEN VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **BACK STAGE OF AUDITORIUM W/ HALLWAY**
MATERIAL QUANTITY: **450** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/01/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46171** BUIDLING ID: **1390**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Hyde Park Academy** REVIEW DATE: **3/31/2013**
ADDRESS: **6220 S. Stony Island** IDPH LICENSE NO: **100-02175**

HOMOGENEOUS AREA: **T**
MATERIAL DESCRIPTION: **12x12 ORANGE W/ GREEN VFT**
MATERIAL LOCATION: **BACK STAGE OF AUDITORIUM W/ HALLWAY**
MATERIAL QUANTITY: **450** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **03/31/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46171** BUIDLING ID: **1390**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ethan Payne**
SCHOOL NAME: **Hyde Park Academy** INSPECTION DATE: **3/1/2013**
ADDRESS: **6220 S. Stony Island** IDPH LICENSE NO: **100-02175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **T-1**
MATERIAL DESCRIPTION: **12x12 ORANGE W/ GREEN VFT-MASTIC**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **BACK STAGE OF AUDITORIUM W/ HALLWAY**
MATERIAL QUANTITY: **450** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/01/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46171** BUIDLING ID: **1390**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Hyde Park Academy** REVIEW DATE: **3/31/2013**
ADDRESS: **6220 S. Stony Island** IDPH LICENSE NO: **100-02175**

HOMOGENEOUS AREA: **T-1**
MATERIAL DESCRIPTION: **12x12 ORANGE W/ GREEN VFT-MASTIC**
MATERIAL LOCATION: **BACK STAGE OF AUDITORIUM W/ HALLWAY**
MATERIAL QUANTITY: **450** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **03/31/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

APPENDIX B

Inspector and Management Planner Licenses

CERTIFICATE OF ACHIEVEMENT ASBESTOS ABATEMENT

Accredited by the Illinois Department of Public Health

ETHAN PAYNE

This is to certify that _____
has completed the ASBESTOS INSPECTOR'S REFRESHER course and successfully passed the
examination on 03/21/2012 with a minimum score of 70% or better. Training was in accordance
with U.S. E.P.A. 40 CFR 763 Subpart E, Appendix C, Asbestos Containing Materials in Schools:
Model Accreditation Plan, TSCA II, Authorized by both AHERA & ASHARA.



Nicholas J. Peneff

03/21/2012

Course Dates:

03/21/2013

Expires:

1203BIR13

Certificate Number:

Phone Number: (312) 491-0081

Director of Training

Nicholas J. Peneff

Doctor of Public Health

FORM # A-010



Pat Quinn, Governor

525-535 West Jefferson Street • Springfield, Illinois 62761-0001 • www.idph.state.il.us

5/22/2012

ETHAN M PAYNE
11529 S. PEORIA
CHICAGO, IL 60643

ASBESTOS PROFESSIONAL LICENSE ID NUMBER: 02175

Enclosed is your Asbestos Professional License that expires 05/15/2013

CERTIFICATE EXPIRATION DATE


INSPECTOR

3/21/2013

PROJECT MANAGER
AIR SAMPLING PROFESSIONAL

~~7/29/2012~~

If you have any questions or need further assistance, contact the Asbestos Program at (217)782-3517 or fax (217)785-5897.
Our WEB address is <http://www.idph.state.il.us/envhealth/chhome.htm>





Occupational Training & Supply, Inc.

7233 Adams Street • Willowbrook, IL 60527 • (630) 655-3900

Asbestos Building Inspector Refresher

Occupational Training and Supply, Inc. certifies that

Daniel Juneau

has successfully completed the 4 hour Asbestos Building Inspector Refresher Course
and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 10 CFR 763 Asbestos Hazard Emergency Response Act (AHERA) and TSCA Title II.

Certificate: BIR1212042319


Exam Date: 12/4/2012

Course Date: 12/4/2012

Expiration Date: 12/4/2013

Kathy DeSalvo, Director

2012



Occupational Training & Supply, Inc.

7233 Adams Street ♦ Willowbrook, IL 60527 ♦ (630) 655-3900

Asbestos Management Planner Refresher

Occupational Training and Supply, Inc. certifies that

Daniel Juneau

has successfully completed the 4 hour Asbestos Management Planner Refresher Course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 10 CFR 763 Asbestos Hazard Emergency Response Act (AHERA) and TSCA Title II.

Certificate: MPR1302250736


Exam Date: 2/25/2013

Course Date: 2/25/2013

Expiration Date: 2/25/2014

Kathy DeSalvo, Director

2013



Occupational Training & Supply, Inc.

7233 Adams Street ♦ Willowbrook, IL 60527 ♦ (630) 655-3900

Asbestos Management Planner Refresher

Occupational Training and Supply, Inc. certifies that

Daniel Juneau

has successfully completed the 4 hour Asbestos Management Planner Refresher Course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 10 CFR 763 Asbestos Hazard Emergency Response Act (AHERA) and TSCA Title II.

Certificate: MPR1302250736

Exam Date: 2/25/2013

Course Date: 2/25/2013

Expiration Date: 2/25/2014

Kathy DeSalvo, Director

2013

Daniel Juneau

Illinois Licensed Asbestos Inspector, Management Planner,
Project Manager, and Air Sampling Professional



ASBESTOS PROFESSIONAL LICENSE

ID NUMBER
100 - 03613

ISSUED
4/11/2013

EXPIRES
05/15/2014

DANIEL J JUNEAU
1408 OAKWOOD AVENUE
DES PLAINES, IL 60016

Environmental Health



ENDORSEMENTS

TC EXPIRES

INSPECTOR

12/4/2013

MANAGEMENT PLANNER

2/25/2014

PROJECT MANAGER

12/3/2013

AIR SAMPLING PROFESSIONAL

Alteration of this license shall result in legal action
This license issued under authority of the State of Illinois
Department of Public Health

This license is valid only when accompanied by a valid
training course certificate.

**CARNOW
CONIBEAR**

APPENDIX C

Laboratory Accreditations

APPENDIX D

Laboratory Results

APPENDIX E

Chain of Custody Forms

Three-Year Reinspection Key to Terms

	CODE	KEY
MATERIAL		
	ACBM	Asbestos Containing Building Materials
MATERIAL CATEGORY		
	MISC	Miscellaneous
	SURF	Surfacing
	TSI	Thermal System Insulation
MATERIAL UNITS		
	LF	Linear Feet
	SF	Square Feet
	CF	Cubic Feet
DAMAGE TYPE		
	Loc	Localized
	Dist	Distributed