

**ILLINOIS DEPARTMENT OF PUBLIC HEALTH
AHERA THREE YEAR REINSPECTION
ASBESTOS ABATEMENT PROGRAM
SCHOOL INFORMATION FORM**

SECTION I

NAME OF SCHOOL DISTRICT: CHICAGO SCHOOL DIST 299
SCHOOL ID NUMBER: 14-016-2990-0050
SCHOOL NAME: Brooks College Prep (Southside College Prep)
ADDRESS OF SCHOOL: 250 E. 111th St.
CITY: Chicago, IL, 60628

DATE LAST THREE YEAR REINSPECTION WAS COMPLETED **3/15/2010**

If the address on this form is different than the address of the building, submit a written explanation.

SECTION II *(Please type or print)*

PLEASE COMPLETE THE FOLLOWING FOR YOUR THREE YEAR REINSPECTION:

DATE REINSPECTION COMPLETED: 5/13/2013 ENROLLMENT 793
IDPH INSPECTOR LICENSE NUMBER: 100-19036
IDPH LICENSED INSPECTOR NAME (Please Print): Ismael Hernandez
IDPH MP LICENSE NUMBER: 100-01786
IDPH LICENSED MANAGEMENT PLANNER NAME (Please Print): Guillermo Garcia

DESIGNATED PERSON (Please Print): Ms. Lynn Crivello PHONE: (773) 553-3113



5/13/2013

Signature of Designated Person

Date

SECTION III

PLEASE COMPLETE THE FOLLOWING INFORMATION FOR ANY CHANGES WITHIN THE SCHOOL DISTRICT.

School building has been sold. Date of Sale: _____

School has been closed. Date closed: _____

School building has been demolished. Date: _____

School building is asbestos free since last reinspection: _____

Please explain in writing why the school building is now asbestos free and include the supporting documentation.

If a new school building has been added to the district, submit either an exclusionary statement or a management plan and inspection report. Include the complete name, address and city of school building.

Explain in writing if the address of the building is different than the address on this form:

THREE-YEAR REINSPECTION

CHICAGO SCHOOL DIST 299

Brooks College Prep (Southside College Prep)

250 E. 111th St.
Chicago, IL, 60628

Unit: 47051
Building ID: 1500

IDPH ID Number: 14-016-2990-0050

REPORT DATE:

Monday, May 13, 2013

Prepared for:

**Chicago Public Schools
125 S. Clark Street
Chicago, IL 60603**

Prepared by:

GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone (312) 733-6262

Fax (312) 733-5612

**DO NOT REMOVE FROM SCHOOL
REQUIRED BY FEDERAL LAW**

April 17, 2013

Mr. R. Kent Cook
Asbestos Program
Illinois Department of Public Health
525 West Jefferson Street
Springfield, Illinois 62761

Re: Chicago Public Schools - 2013 Three-Year Reinspections

Dear Mr. Cook:

GSG Consultants, Inc., Managing Environmental Consultant (MEC), conducted the Three-Year Reinspections and performed management plan updates for the Chicago Public Schools (CPS) facilities in Region 1,2,6 Elementary Schools. Please update your records with the following information.

School District: 299 Unit: 47051 Region: 06 IDPH ID: 14-016-2990-0050

School: Brooks College Prep (Southside College Prep) Building ID: 1500

Address: 250 E. 111th St.

Chicago, IL, 60628

Building Contact: Ariola, Peter

Contact Phone: 773-553-1000

Current Building Owners: Chicago Public Schools

Review Date: 5/13/2013

Inspector: Ismael Hernandez

Inspector IDPH License: 100-19036

Management Planner: Guillermo Garcia

Management Planner IDPH License: 100-01786

If you have any questions or comments, please contact us at (312) 733-6262

Sincerely,
GSG Consultants, Inc.



Guillermo Garcia
100-01786

Environmental Notification to Occupants

To: Faculty, Staff and Parents
From: Chicago Public Schools
Date: April 17, 2013

RE: Brooks College Prep (Southside College Prep), Unit 47051
250 E. 111th St.
Chicago, IL, 60628

Dear Faculty, Staff and Parents,

This letter is to notify you that the 2013 asbestos three year re-inspection has been completed at Brooks College Prep (Southside College Prep) , following the Federal Asbestos Hazard Emergency Response Act (AHERA), 40 CFR Part 763, Subpart E and is available for your review at the main office of the school.

Although asbestos-containing materials have been identified at Brooks College Prep (Southside College Prep), there is no reason to believe that any threat to the health of students or staff exists at this time. CPS will continue to carefully monitor the condition of asbestos-containing materials and if conditions warrant, all appropriate steps will be taken to maintain the health and safety of all building occupants.

If you have any questions regarding this matter or require additional information, please feel free to contact Ms. Lynn Crivello, the designated Local Education Authority's Designated Person at (773) 553-3113 .

Table of Contents

- I. School and Inspection Information
- II. Executive Summary
- III. Methodology
- IV. Abatement History
- V. Reassessments and Recommendations
- VI. Conclusions

Table I: Inspector's Reinspection Findings

Table II: Management Planner's Review

APPENDICES:

- Appendix A: Assessment Sheets, Drawings and Photos
- Appendix B: Inspector and Management Planner Licenses
- Appendix C: Laboratory Accreditations
- Appendix D: Laboratory Results
- Appendix E: Chain of Custody Forms

SCHOOL AND INSPECTION INFORMATION

1. School Information

School: Brooks College Prep (Southside College Prep) Unit: 47051 Region: 06
Address: 250 E. 111th St. Chicago, IL, 60628
IDPH ID: 14-016-2990-0050 Building ID: 1500
Contact: Ariola, Peter Phone: 773-553-1000

2. Description of Facility

Original Construction: Additional Construction:
Total Square Footage: 173300 No of Floors:
Current Occupancy: 793

3. LEA Designated Person

Contact: Ms. Lynn Crivello Phone: (773) 553-3113
Address: 125 South Clark Street, 17th Floor
Chicago, IL 60603

4. Managing Environmental Consultant

MEC: GSG Consultants, Inc.
Contact: Arturo Saenz
Address 855 W. Adams St., Ste. 200
Phone: (312) 733-6262 Fax: (312) 733-5612

5. Inspector

Inspector Name: Ismael Hernandez



Signature:
Date: 4/17/2013

Inspector IDPH license # 100-19036

6. Management Planner

Management Planner Name: Guillermo Garcia



Signature:
Date: 5/13/2013

Management Planner IDPH license # 100-01786

7. Review Date: 5/13/2013

8. LEA Designated Person's Acknowledgement

The reinspection report and recommendations have been received by me and appropriate action will be taken by the School District.



Signature:

Date: 5/13/2013

Name: Ms. Lynn Crivello

II. EXECUTIVE SUMMARY

GSG Consultants, Inc. was retained by the Chicago Public Schools (CPS) to perform a three-year asbestos reinspection of the Brooks College Prep (Southside College Prep). This inspection was conducted in accordance with the United States Environmental Protection Agency (USEPA) Asbestos Hazard Emergency Response Act (AHERA) part 763.92 (b), and the ongoing Operations and Maintenance Program (O&M) originally designed in the School's Asbestos Management Plan. The purpose of this three-year reinspection is to record any condition changes in the asbestos-containing building material (ACBM) in the school since the previous three-year reinspection and the six-month periodic surveillance, to identify, assess, and include any Homogeneous Areas (HA) not identified in the Management Plan, and to recommend an appropriate response action to manage asbestos.

The inspector conducted a three-year reinspection of this facility under Illinois Department of Public Health (IDPH) school reinspection requirements and AHERA, sections 763.85 and 763.88. The main building and each addition to the main building, if constructed at different dates, were inspected separately. Laboratory accreditations are included in Appendix C, laboratory results are included in Appendix D, and chain of custody forms are included in Appendix E.

Note: During previous inspections, some of the HA(s) were identified together as 9" x 9" floor tile (FT), mastics assoc. with 9" x 9" FT, 12" x 12" FT, mastics assoc. with 12" x 12" FT, pipe insulation, etc. Some of these HA(s) have been re-identified by areas that are uniform in color, texture, construction date, application date, and general appearance.

The inspector has determined the following:

A. The following HAs have changed assessment categories for Building 1500:

012	Cardboard Pipe Insulation
151	NOT OBSERVED FLOOR TILE REPLACEMENT 12X12VFT/GREY/DARK BRN

B. The following new homogenous areas have been identified for Building 1500:

170	Carpet Mastic - Brown
171	Carpet Mastic Blue w/ white streaks
172	Carpet Mastic Brown w/ blue and orange streaks
30	Black Counter Tops

C. This reinspection covered only physically accessible and visible areas and materials that were identified in the LEA's management plan. The following materials were concealed and/or contained in areas that were inaccessible for sampling and have been classified as Assumed:

019	Beige Terrazzo
020	12 x 12 Yellow Floor Tile
025	12 x 12 Gray Floor Tile
080 (F25)	12x12 black floor tile not observed
080 (F27)	12x12 orange/brown floor tile NOT OBSERVED
081 (F25)	12x12 black floor tile mastic NOT OBSERVED
081 (F27)	12x12 orange/brown floor tile mastic NOT OBSERVED
082 (F31)	brown vinyl baseboard
082(F32)	black vinyl baseboard
082(F33)	wood grain baseboard mastic not observed
083 (F31)	mastic under baseboard
083 (F33)	wood grain baseboard not observed
083(F32)	black vinyl baseboard mastic not observed
084 (CM 45)	orange carpet mastic not observed
084 (CM53)	brown tweed carpet mastic not observed
084(42)	orange/brown carpet mastic not observed
084(43)	rust carpet mastic not observed
084(CM41)	brown/tweed carpet mastic not observed
087	12x12 Ceiling Tile- Not Observed
088	12x12 Ceiling Tile Mastic Not Observed
089	Plaster Not Observed
090M(F23)	12x12 white floor tile (BLDG DEMOLISHED)
091	12x12 off white floor tile
092	12x12 Off White Floor tile Mastic
100	1'x1' Ceiling Tile Mastic Not Observed
151	NOT OBSERVED FLOOR TILE REPLACEMENT 12X12VFT/GREY/DARK BRN MASTIC
152	MASTIC
153	2'x4' Speckled Pattern Ceiling Tile (w/ 2'x2' Sections)
154	4" Vinyl Baseboard - Grey
155	Mastic associated with 4" Vinyl Baseboard - Grey
156	12"x12" White with Grey Specs Floor Tile
157	12"x12" White with Grey Specs Floor Tile Mastic
158	2'x2' Smooth Pattern Ceiling Tile
159	Interior Window Caulk
160	Terrazzo Floor
161	12"x12" Grey Speckled Floor Tile
162	12"x12" Grey Speckled Floor Tile Mastic
163	Black Sink Undercoat
164	Black Counter Top
165	Drywall
166	Drywall Joint Compound

167	Sheet Flooring - Brown Multi-Color Pattern
168	Sheet Flooring - Brown Multi-Color Pattern Mastic
169	White Sink Undercoat
170	Carpet Mastic - Brown
171	Carpet Mastic Blue w/ white streaks
172	Carpet Mastic Brown w/ blue and orange streaks
21	12 x 12 Yellow Floor Tile Mastic
22	Brown Carpet Mastic
26	12 x 12 Gray Floor Tile Mastic
27	2 x 4 Lay-in Panels NOT OBSERVED
28	Spray-on Insulation
29	2 x 2 Lay-in Ceiling Panels
30	Black Counter Tops

The following areas were deemed to be inaccessible:

080 (F25)	12x12 black floor tile not observed
081 (F25)	12x12 black floor tile mastic NOT OBSERVED
21	12 x 12 Yellow Floor Tile Mastic
22	Brown Carpet Mastic
26	12 x 12 Gray Floor Tile Mastic

Materials were also listed as "assumed" if they were in good condition and sampling was not conducted to avoid damage.

This reinspection was conducted by Ismael Hernandez, IDPH License # 100-19036. The Management Plan was updated by Guillermo Garcia, IDPH License # 100-01786. Inspector and Management Planner Licenses are included in Appendix B.

III. METHODOLOGY

Tasks performed on-site included the following:

1. Review current management plan, identify HA(s) and extract appropriate information.
2. Examine and verify abatement records.
3. Touch and visually and physically reinspect and reassess the condition of all friable known or assumed ACBM.
4. Touch and visually and physically reinspect all non-friable known or assumed ACBM to determine whether these materials have become friable since the last inspection or periodic surveillance.
5. Identify any condition changes that may affect Hazard Ranking of known ACBM or Assumed ACBM, as well as any HA(s) that have become friable since the last reinspection.
6. Collect bulk samples from each newly discovered friable HA or previously assumed and submit for laboratory analysis.
7. Tabulate reinspection findings and submit for management planner review and recommendations with appropriate response actions based on the AHERA Damage Category of the ACBM.
8. Submit reinspection findings and management planner recommendations to the LEA within thirty (30) days for inclusion into the management plan.

IV. ABATEMENT HISTORY

The information collected from the existing management plan and inspection report(s) and from interviews with the school official revealed that the following asbestos abatement was conducted at the school since the previous Three year Reinspection.

Abatement Dates:

V. REASSESSMENTS AND RECOMMENDATIONS

The reassessments and recommendations are summarized in Tables I and II on the following pages. Detailed Hazard Assessment Sheets and Drawings and Photos (if applicable) are included in Appendix A.

VI. CONCLUSIONS

The Brooks College Prep (Southside College Prep) Building 1500 Three-Year reinspection has been completed and response actions have been recommended for both friable and non-friable materials. A timely execution of the response actions recommended will enable the LEA and the Designated Person(s) to effectively manage the existing ACBM.

This three-year reinspection report should be inspected in the current Management plan at the CPS Central Office, and one (1) copy should be kept at the school for use when planning any renovation and/or demolition activities in areas where ACBM has been identified. Also, periodic surveillance documentation and any summary reports from any response actions that are executed at the school should be used to update the Management Plan.

Table I
Inspector's Reinspection Findings

Chicago Public Schools

School Brooks College Prep (Southside College Prep) Unit 47051 Building ID 1500

Address 250 E. 111th St. Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262 Fax: (312) 733-5612

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
002	Aircell jacket (ABATED)			Main Building: Hot water tank in boiler room	ABATED	TSI					No			
004	Cardboard Pipe Insulation (ABATED)			Main Building: Boiler Rm. East	ABATED	TSI					No			
005	Mag. Jacket Boilers 1&2 (ABATED)			Main Building: Boiler Rm.	ABATED	TSI					No			
007	Cardboard Pipe Insulation (ABATED)			Main Building: Boiler Rm. East Perimeter	ABATED	TSI					No			
008	Joint compound on Cardboard Pipe Insul. (ABATED)			Main Building: Boiler Rm. Hot Water Pipe	ABATED	TSI					No			
009	Joint compound on aircell pipe insulation (ABATED)			Main Building: boiler room on east wall	ABATED	TSI					No			
010	Aircell Pipe Insulation	0	LF	Main Building: Attic (abated) and Tunnels (still present)	ABATED	TSI	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		MODERATE
011	Mag Block Pipe Insulation	800	LF	Main Building: Tunnel	CHR	TSI	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
012	Cardboard Pipe Insulation	500	LF	Main Building: Tunnels	CHR	TSI	Y	NONE	0		Yes	Any remaining friable ACBM or friable suspect ACBM		MODERATE
013(F18)	9x9 Brown Speckled Floor Tile (ABATED)			Main Building: West Wing Coaches Offices	ABATED	MISC					No			
014(C12)	2'x4' Ceiling Tile (ABATED)			Main Building: West Wing Coaches Office	ABATED	MISC					No			
014A	Red, black, brown, tan linoleum pattern (ABATED)			Main Building: auditorium 1st floor, 2nd floor foyer	ABATED	MISC					No			
015(C9)	1'x1' Glued on Ceiling (ABATED)			Main Building: Men's Bathroom	ABATED	MISC					No			
016	Plaster (ABATED)			Main Building: Throughout West Wing Building.	ABATED	SURFACE					No			
017(F1)	9x9 White Floor Tile (ABATED)			Main Building: East Wing Rooms 15, 19, and 306	ABATED	MISC					No			
018	9x9 Pink Floor Tile (ABATED)			Main Building: W Wing Foyer	ABATED	MISC					No			

Chicago Public Schools

School Brooks College Prep (Southside College Prep) Unit 47051 Building ID 1500

Address 250 E. 111th St. Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262 Fax: (312) 733-5612

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
018(F15)	9x9 pink floor tile mastic (ABATED)			Main Building: W. wing 1st floor foyer & 2nd floor foyer and lounge	ABATED	MISC					No			
019	Beige Terrazzo	20,000	SF	Main Office, Rooms 304, 310, 306, 303C, 317, 318, 116, Hallways and Bathrooms	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
020	12 x 12 Yellow Floor Tile	12,500	SF	Rooms 106, 200-205, 208, 209, 216, Library, Office, and Coach's Office	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
023	Light beige linoleum (ABATED)			Main Building: gym (room 251), room 253	ABATED	MISC		NONE			No			LOW
023(F2)	9x9 black floor tile (ABATED)			Main Building: east wing 2nd & 3rd floor rooms 15,19,306	ABATED	MISC					No			
024(F4)	9"x9" Maroon Floor Tile (ABATED)			Main Building: East Wing 2nd Floor, Library, and Guidance Office	ABATED	MISC					No			
025	12 x 12 Gray Floor Tile	5,000	SF	Band Room, 4th Floor, 403, 407, Office, Bathroom, West Side, 100, 101, Attendance Office	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
036 (C13)	2x4 lay in ceiling tile (ABATED)			Main Building: music room	ABATED	MISC					No			
040(F9)	9"x9" Gray Floor Tile (ABATED)			Main Building: Guidance and Xerox Offices	ABATED	MISC					No			
041(F3)	9"x9" Red Floor Tile (ABATED)			Main Building: Rm. 306 and Xerox Rm.	ABATED	MISC					No			
043(F11)	9x9 White Floor Tile (ABATED)			Main Building: Office	ABATED	MISC					No			
045 (F16)	9x9 grey floor tile (ABATED)			Main Building: west wing 2nd floor lounge	ABATED	MISC					No			
046(F20)	9"x9" Green Floor Tile (ABATED)			Main Building: Gym, Cafeteria	ABATED	MISC					No			
047(F19)	9"x9" Tan Floor Tile (ABATED)			Main Building:	ABATED	MISC					No			

Chicago Public Schools

School Brooks College Prep (Southside College Prep) Unit 47051 Building ID 1500

Address 250 E. 111th St. Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262 Fax: (312) 733-5612

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				Gym, Cafeteria Building										
049 (F5)	9x9 tan floor tile (ABATED)			Main Building: guidance office, east wing room 29 & library	ABATED	MISC					No			
051 (F12)	9x9 green & white floor tile (ABATED)			Main Building: east wing 2nd & 3rd floor hallway & room 31	ABATED	MISC					No			
052 (F17)	9x9 green & tan floor tile (ABATED)			Annex: office & storage 156A & 156B	ABATED	MISC					No			
052 (F21)	9x9 blue floor tile (ABATED)			Annex: room 151	ABATED	MISC					No			
052(F8)	Blue and White Linoleum (ABATED)			Main Building: 2nd Floor Teachers' Lounge Kitchen	ABATED	MISC					No			
053 (F13)	12x12 tan floor tile (ABATED)			Annex: boys & girls toilets & corridors	ABATED	MISC					No			
054	2x4 ceiling tile (ABATED)			Annex: chemistry lab room 252	ABATED	MISC					No			
055	Aircell (ABATED)			Annex: chemistry lab	ABATED	MISC					No			
059	Trim mastic on on tan baseboard (ABATED)			Annex: foyer/corridor	ABATED	MISC					No			
060	Trim tan baseboard (ABATED)			Annex: foyer/corridor	ABATED	MISC					No			
070 (F13)	12x12 tan floor tile mastic (ABATED)			Annex: boys & girls toilets & corridors	ABATED	MISC					No			
070 (F17)	9x9 green floor tile mastic (ABATED)			Annex: room 151	ABATED	MISC					No			
070 (F21)	9x9 blue floor tile mastic (ABATED)			Annex: room 151	ABATED	MISC					No			
072	paneling mastic (ABATED)			Annex: annex corridor	ABATED	MISC					No			
073 (C14)	12x12 ceiling tile mastic (ABATED)			Annex: rooms 155 A-D	ABATED	MISC					No			
078	Aircell pipe insulation	3,000	LF	Monastery: Crawl space tunnels, connecting tunnel from main bldg	CHR	TSI	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		MODERATE
079	Hard fittings on aircell pipe insulation	200	LF	Monastery: Crawl space tunnels,	CHR	TSI	Y	NONE	0		No	ACBM with the potential for damage		MODERATE

Chicago Public Schools

School Brooks College Prep (Southside College Prep) Unit 47051 Building ID 1500
 Address 250 E. 111th St. Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262 Fax: (312) 733-5612

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				connecting tunnel from main bldg										
080 (F25)	12x12 black floor tile not observed			Monastery: 2nd floor fireplace	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
080 (F26)	12x12 red floor tile not observed	260	SF	Monastery: 1st,2nd,3rd floor stairways	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		Low
080 (F27)	12x12 orange/brown floor tile NOT OBSERVED			Monastery: 2nd & 3rd floor monastery	ASSUMED	MISC		NONE	0		No	ACBM with the potential for damage		
081 (F25)	12x12 black floor tile mastic NOT OBSERVED			Monastery: 2nd floor fireplace	ASSUMED	MISC		NONE	0		No	ACBM with the potential for damage		
081 (F26)	12x12 red floor tile mastic NOT OBSERVED	260	SF	Monastery: 1st,2nd,3rd floor stairways	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
081 (F27)	12x12 orange/brown floor tile mastic NOT OBSERVED			Monastery: 2nd & 3rd floor monastery	ASSUMED	MISC		NONE	0		No	ACBM with the potential for damage		
082 (F31)	brown vinyl baseboard			Monastery: 2nd floor community room, monastery	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		
082(F32)	black vinyl baseboard			Monastery: 1st,2nd,3rd floor stairwells,315	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
082(F33)	wood grain baseboard mastic not observed			Monastery: room 210	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
083 (F31)	mastic under baseboard			Monastery: 2nd floor community room, monastery	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		
083 (F33)	wood grain baseboard not observed			Monastery: room 210	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		
083(F32)	black vinyl baseboard mastic not observed			Monastery: 1st,2nd,3rd floor stairwells,315	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		
084 (CM 45)	orange carpet mastic not observed			Monastery: 2nd floor corridor room 204 & 210	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		
084 (CM53)	brown tweed carpet mastic not observed			Monastery: room 306	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		
084(42)	orange/brown carpet mastic not observed			Monastery: 1st floor NW corner	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		
084(43)	rust carpet mastic not observed			Monastery: 1st floor NW corridor	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
084(CM4 1)	brown/tweed carpet mastic not observed			Monastery: 1st floor NW Corridor	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		
085(F28)	9x9 red/black border floor tile	600	SF	Monastery:	CHR	MISC	N	NONE	0		No	ACBM with the		LOW

Chicago Public Schools

School Brooks College Prep (Southside College Prep) Unit 47051 Building ID 1500

Address 250 E. 111th St. Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262 Fax: (312) 733-5612

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				stairwells 1st, 2nd, 3rd floor								potential for damage		
085(F29)	9x9 grey/red trim floor tile NOT OBSERVED	350	SF	Monastery:1st floor monastery	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
086(F28)	9x9 red/black border floor tile mastic not observed	600	SF	Monastery: stairwells 1st, 2nd, 3rd floor	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
086(F29)	9x9 grey/red trim floor tile mastic not observed	10	SF	Monastery:1st floor monastery	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		Low
087	12x12 Ceiling Tile- Not Observed			Monastery: 2nd,3rd floor	ASSUMED	MISC					No			
088	12x12 Ceiling Tile Mastic Not Observed			Monastery: 2nd 3rd floor	ASSUMED	MISC					No			
089	Plaster Not Observed			Monastery: throughout 1st,2nd ,3rd floors	ASSUMED	SURFACE					No			
090 (F23)	12x12 white floor tile mastic (BLDG DEMOLISHED)			Annex: physics lab	CHR	MISC					No			
090M(F23)	12x12 white floor tile (BLDG DEMOLISHED)			Annex: physics lab	ASSUMED	MISC					No			
091	12x12 off white floor tile			Gym	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
092	12x12 Off White Floor tile Mastic			Gym	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
093	Aircell pipe insulation (NOT OBSERVED)			Gym: Throughout bldg, locker rooms, showers	CHR	TSI					No			
094	Hard fittings on air cell pipe insulation (NOT OBSERVED)			Gym: Throughout bldg, locker rooms, showers	CHR	TSI					No			
100	1'x1' Ceiling Tile Mastic Not Observed			Monastery: confessionals	ASSUMED	MISC					No			
101 (F61)	12x12 light grey floor tile (ABATED)			Main Building: west wing far west corridor	ABATED	MISC					No			
101 (F62)	12x12 dark brown white/black speck floor tile (ABATED)			Main Building: west wing, north west corner	ABATED	MISC					No			
101(F60)	12x12 off white floor tile (ABATED)			Main Building: W wing 3rd floor, NW corner,west & east wing, north portion	ABATED	MISC					No			
102 (F61)	12x12 light grey floor tile mastic (ABATED)			Main Building: west wing far west	ABATED	MISC					No			

Chicago Public Schools

School Brooks College Prep (Southside College Prep) Unit 47051 Building ID 1500
 Address 250 E. 111th St. Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262 Fax: (312) 733-5612

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				corridor										
102(F60)	12x12 off white floor tile mastic (ABATED)			Main Building:W wing 3rd floor, NW corner,west & east wing, north portion	ABATED	MISC					No			
102(F62)	12x12 dark brown white/black speckled floor tile (ABATED)			Main Building:west wing, north west corner	ABATED	MISC					No			
103(F63)	9x9 light green floor tile (ABATED)			Main Building: west wing corridor, 2nd & 3rd floor east & west wing patches	ABATED	MISC					No			
103(F64)	9x9 light brown floor tile (ABATED)			Main Building: west wing 1st,2nd,3rd corridor patches & east end	ABATED	MISC					No			
103(F65)	9x9 medium brown floor tile (ABATED)			Main Building: west wing 1st & 3rd floor corridor patches & east wing	ABATED	MISC					No			
103(F66)	9x9 yellow floor tile (ABATED)			Main Building: 1st floor corridor patches	ABATED	MISC					No			
103(F7)	9x9 clay floor tile (ABATED)			Main Building: 1st floor corridor west wing	ABATED	MISC					No			
104 (F63)	9x9 light green floor tile mastic (ABATED)			Main Building: west wing corridor, 2nd & 3rd floor east & west wing patches	ABATED	MISC					No			
104 (F7)	9x9 clay floor tile mastic (ABATED)			Main Building: 1st floor corridor west wing	ABATED	MISC					No			
104(F1)	9x9 white floor tile mastic (ABATED)			Main Building: east wing room 15 & 19 & west wing music	ABATED	MISC					No			
104(F2)	9x9 black floor tile mastic (ABATED)			Main Building: east wing room 15 & 19	ABATED	MISC					No			
104(F3)	9x9 pink floor tile mastic (ABATED)			Main Building: west wing 1st,2nd floor foyer	ABATED	MISC					No			
104(F4)	9x9 maroon floor tile mastic (ABATED)			Main Building: 1st & 2nd floor west wing, 1st floor	ABATED	MISC					No			

Chicago Public Schools

School Brooks College Prep (Southside College Prep) Unit 47051 Building ID 1500

Address 250 E. 111th St. Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262 Fax: (312) 733-5612

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				throughout, 2nd flr west rooms										
104(F5)	9x9 tan abated mastic (ABATED)			Main Building: main BLDG: library, east wing throughout	ABATED	MISC					No			
104(F64)	9x9 light brown floor tile mastic (ABATED)			Main Building: west wing 1st,2nd,3rd corridor patches & east end	ABATED	MISC					No			
104(F65)	9x9 medium brown floor tile mastic (ABATED)			Main Building: west wing 1st & 3rd floor corridor patches & east wing	ABATED	MISC					No			
104(F66)	9x9 yellow floor tile mastic (ABATED)			Main Building: 1st floor corridor patches	ABATED	MISC					No			
104(F67)	9x9 green floor tile mastic (ABATED)			Main Building: 1st floor stairwell, east wing & 2nd & 3rd flr. Hallway	ABATED	MISC					No			
105 (F68)	Various size brown speckled floor tile (ABATED)	4,000	SF	Main Building: 1st,2nd,3rd floor patches in east & west wing	ABATED	MISC					No			
106(F68)	Various size brown speckled floor tile mastic (ABATED)			Main Building: 1st, 2nd,3 rd floor patches in east & west wing	ABATED	MISC					No			
107(CM7 0)	carpet mastic under multicolored (ABATED)			Main Building: 2nd floor west wing, far west wing	ABATED	MISC					No			
107(CM7 1)	grey carpet mastic (ABATED)			Main Building: 2nd floor office, 1st floor west corner	ABATED	MISC					No			
108	grey vinyl stair treads (ABATED)			Main Building: 1st, 2nd, 3rd floor east & west wings	ABATED	MISC		NONE	0		No	ACBM with the potential for damage		
109	vinyl stair track mastic (ABATED)			Main Building: 1st, 2nd, 3rd floor east & west wings	ABATED	MISC					No			
110 (F75)	4" brown vinyl base board (ABATED)	250	LF	Main Building: 1st floor corridor leading to west wing, 3rd floor NW corner	ABATED	MISC					No			

Chicago Public Schools

School Brooks College Prep (Southside College Prep) Unit 47051 Building ID 1500
 Address 250 E. 111th St. Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262 Fax: (312) 733-5612

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
110 (F76)	4" black baseboard (ABATED)			Main Bldg: 1st,2nd,3rd floor throughout east wing & corridor- e. wing 1st fl. NE. corner west wing	ABATED	MISC					No			
110 (F77)	4" tan baseboard (ABATED)			Main Building: 1st, 2nd floor main BLDG, NE. & NW. portion	ABATED	MISC					No			
111(F75)	4" brown vinyl base board mastic (ABATED)			Main Building: 1st floor corridor leading to west wing, 3rd floor NW corner	ABATED	MISC					No			
111(F76)	4" black baseboard (ABATED)			Main Building: 1st,2nd,3rd floor throughout	ABATED	MISC					No			
111(F77)	4" tan baseboard mastic (ABATED)			Main Building: 1st,2nd floor main BLDG, NE. & NW. portion	ABATED	MISC					No			
112 (F80)	6" black vinyl baseboard (ABATED)			Main Building: 2nd floor main bldg. SE corner	ABATED	MISC					No			
113 (F80)	6" black vinyl baseboard mastic (ABATED)			Main Building: 2nd floor main bldg. SE corner	ABATED	MISC					No			
114 (CT1)	12x12 ceiling tile (ABATED)			Main Building: 1st floor west wing near NW corner	ABATED	MISC					No			
114 (CTM1)	12x12 ceiling tile mastic (ABATED)			Main Building: 1st floor west wing near NW corner	ABATED	MISC					No			
116	12x12 cork tile (ABATED)			Main Building: 2nd floor west wing room NE. corner of bldg.	ABATED	MISC					No			
151	NOT OBSERVED FLOOR TILE REPLACEMENT 12X12VFT/GREY/DARK BRN	50,000	SF	1ST FL. 2ND FL. 3RD FLOORS HALLWAYS	ASSUMED	MISC		NONE	0		Yes	ACBM with the potential for damage		LOW
152	MASTIC	50,000	SF	1ST FL. 2ND FL. 3RD FL. THROUGHOUT BLD.BASE	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW

Chicago Public Schools

School Brooks College Prep (Southside College Prep) Unit 47051 Building ID 1500
 Address 250 E. 111th St. Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262 Fax: (312) 733-5612

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				BOARD										
153	2'x4' Speckled Pattern Ceiling Tile (w/ 2'x2' Sections)	1,350	SF	1st Floor: West Wing - Dining Room; 4th Floor: Center Building - Room 402 and 405	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
154	4" Vinyl Baseboard - Grey	1,100	LF	1st Floor: West Wing - Dining Room; 4th Floor: Center Building - Room 400, 400A, 400A-1, 402, 404, 404A, 404C, 404D, and 405	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
155	Mastic associated with 4" Vinyl Baseboard - Grey	1,100	LF	1st Floor: West Wing - Dining Room; 4th Floor: Center Building - Room 400, 400A, 400A-1, 402, 404, 404A, 404C, 404D, and 405	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
156	12"x12" White with Grey Specs Floor Tile	5,350	SF	1st Floor: East Wing - Rooms 131, 133, 135, 137, and 139	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
157	12"x12" White with Grey Specs Floor Tile Mastic	5,350	SF	1st Floor: East Wing - Rooms 131, 133, 135, 137, and 139	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
158	2'x2' Smooth Pattern Ceiling Tile	7,375	SF	1st Floor: East Wing - Rooms 131, 133, 135, 137, and 139, and North/South Corridor	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
159	Interior Window Caulk	400	LF	1st Floor: East Wing - Room 131, 133, 135, 137, and 139; 4th Floor: Center Building - Room 400, 400A, 400A-1, 402, 404, 404A, 404C, 404D, and 405	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
160	Terrazzo Floor	2,025	SF	1st Floor: East Wing - North/South Corridor	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW

Chicago Public Schools

School Brooks College Prep (Southside College Prep) Unit 47051 Building ID 1500
 Address 250 E. 111th St. Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262 Fax: (312) 733-5612

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
161	12"x12" Grey Speckled Floor Tile	2,600	SF	4th Floor: Center Building - Room 400, 400A, 400A-1, 402, 404, 404A, 404C, 404D, and 405	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
162	12"x12" Grey Speckled Floor Tile Mastic	2,600	SF	4th Floor: Center Building - Room 400, 400A, 400A-1, 402, 404, 404A, 404C, 404D, and 405	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
163	Black Sink Undercoat	1	EA	4th Floor: Center Building - Room 400	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
164	Black Counter Top	200	SF	4th Floor: Center Building - Room 400 and 400A	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
165	Drywall	4,600	SF	4th Floor: Center Building - Room 400, 400A, and 404	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
166	Drywall Joint Compound	4,600	SF	4th Floor: Center Building - Room 400, 400A, and 404	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
167	Sheet Flooring - Brown Multi-Color Pattern	1,350	SF	1st Floor: West Wing - Dining Room	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
168	Sheet Flooring - Brown Multi-Color Pattern Mastic	1,350	SF	1st Floor: West Wing - Dining Room	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
169	White Sink Undercoat	1	EA	4th Floor: Center Building - Room 404	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
170	Carpet Mastic - Brown	2,200	SF	Rooms 100 A, 100 C, 100 E, 100 F, 105, 111, 116A and 116B	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
171	Carpet Mastic Blue w/ white streaks	1,500	SF	Rooms 201, 201A, 201C and 201D	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
172	Carpet Mastic Brown w/ blue and orange streaks	10,300	SF	Rooms 147, 153A, 153C, 153D, 153E, 153F, 153F2, 235, 237A, 237D and Library	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
21	12 x 12 Yellow Floor Tile Mastic	12,500	SF	Rooms 106, 200-	ASSUMED	MISC	N	NONE	0		No	ACBM with the		LOW

Chicago Public Schools

School Brooks College Prep (Southside College Prep) Unit 47051 Building ID 1500
 Address 250 E. 111th St. Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262 Fax: (312) 733-5612

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				206, 208, 209, 210, 216, Library, Office, and Coach's Office								potential for damage		
22	Brown Carpet Mastic	6,000	SF	Library, Assistant Principals, Nurse Office, Side Office, 102, 103, 111, 117, and Office Hall	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
26	12 x 12 Gray Floor Tile Mastic	12,500	SF	Band Room, 4th Floor, 403, 407, Office, Bathroom, West Side, 100, 101, Attendance Office	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
27	2 x 4 Lay-in Panels NOT OBSERVED	1,000	SF	Kitchen-NOT OBSERVED	ASSUMED	MISC	Y	NONE	0		No	ACBM with the potential for damage		LOW
28	Spray-on Insulation	3,000	SF	Gymnasium	ASSUMED	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW
29	2 x 2 Lay-in Ceiling Panels	20,000	SF	Hallways	ASSUMED	MISC	Y	NONE	0		No	ACBM with the potential for damage		LOW
30	Black Counter Tops	26	SF	Rooms 307 and 307A	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW

Chicago Public Schools

School Brooks College Prep (Southside College Prep) Unit 47051 Building ID 1500
Address 250 E. 111th St. Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262 Fax: (312) 733-5612

Inspector's Comments are Summarized at the End of the Report

Reinspection Date 4/17/2013
Inspector Name Ismael Hernandez
100-19036 5/15/2014
Inspector's IDPH License Number / Expiration Date

Inspector's Comments

HA Number:	Inspector Comments:
002	
004	
005	
007	
008	
009	
010	
011	
012	
013(F18)	
014(C12)	
014A	
015(C9)	
016	
017(F1)	
018	
018(F15)	
019	
020	No Access to Rms 206 & 210
023	
023(F2)	
024(F4)	
025	
036 (C13)	

Chicago Public Schools

School Brooks College Prep (Southside College Prep) Unit 47051 Building ID 1500
Address 250 E. 111th St. Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262 Fax: (312) 733-5612

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
040(F9)	
041(F3)	
043(F11)	
045 (F16)	
046(F20)	
047(F19)	
049 (F5)	
051 (F12)	
052 (F17)	
052 (F21)	
052(F8)	
053 (F13)	
054	
055	
059	
060	
070 (F13)	
070 (F17)	
070 (F21)	
072	
073 (C14)	
078	
079	
080 (F25)	
080 (F26)	
080 (F27)	
081 (F25)	
081 (F26)	
081 (F27)	

Chicago Public Schools

School Brooks College Prep (Southside College Prep) Unit 47051 Building ID 1500
Address 250 E. 111th St. Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262 Fax: (312) 733-5612

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
082 (F31)	
082(F32)	
082(F33)	
083 (F31)	
083 (F33)	
083(F32)	
084 (CM 45)	
084 (CM53)	
084(42)	
084(43)	
084(CM41)	
085(F28)	
085(F29)	
086(F28)	
086(F29)	
087	
088	
089	
090 (F23)	
090M(F23)	
091	
092	
093	
094	
100	
101 (F61)	
101 (F62)	
101(F60)	
102 (F61)	

Chicago Public Schools

School Brooks College Prep (Southside College Prep) Unit 47051 Building ID 1500
Address 250 E. 111th St. Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262 Fax: (312) 733-5612

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
102(F60)	
102(F62)	
103(F63)	
103(F64)	
103(F65)	
103(F66)	
103(F7)	
104 (F63)	
104 (F7)	
104(F1)	
104(F2)	
104(F3)	
104(F4)	
104(F5)	
104(F64)	
104(F65)	
104(F66)	
104(F67)	
105 (F68)	
106(F68)	
107(CM70)	
107(CM71)	
108	
109	
110 (F75)	
110 (F76)	
110 (F77)	
111(F75)	
111(F76)	

Chicago Public Schools

School Brooks College Prep (Southside College Prep) Unit 47051 Building ID 1500
Address 250 E. 111th St. Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262 Fax: (312) 733-5612

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
111(F77)	
112 (F80)	
113 (F80)	
114 (CT1)	
114 (CTM1)	
116	
151	
152	
153	
154	
155	
156	
157	
158	
159	
160	
161	
162	
163	
164	
165	
166	
167	
168	
169	
170	
171	
172	
21	

Chicago Public Schools

School Brooks College Prep (Southside College Prep) **Unit** 47051 **Building ID** 1500

Address 250 E. 111th St. **Region** 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262 Fax: (312) 733-5612

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
22	
26	
27	
28	
29	
30	

Table II

Management Planner's Review

Chicago Public Schools

School Brooks College Prep
(Southside College Prep)

Unit 47051

Building ID 1500

Address 250 E. 111th St.

Chicago, IL, 60628

Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262

Fax: (312) 733-5612

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
002	Aircell jacket (ABATED)			Main Building: Hot water tank in boiler room	Abated	TSI					
004	Cardboard Pipe Insulation (ABATED)			Main Building: Boiler Rm. East	Abated	TSI					
005	Mag. Jacket Boilers 1&2 (ABATED)			Main Building: Boiler Rm.	Abated	TSI					
007	Cardboard Pipe Insulation (ABATED)			Main Building: Boiler Rm. East Perimeter	Abated	TSI					
008	Joint compound on Cardboard Pipe Insul. (ABATED)			Main Building: Boiler Rm. Hot Water Pipe	Abated	TSI					
009	Joint compound on aircell pipe insulation (ABATED)			Main Building: boiler room on east wall	Abated	TSI					
010	Aircell Pipe Insulation	0	LF	Main Building: Attic (abated) and Tunnels (still present)	Abated	TSI	Yes	0	LF	7 Any remaining friable ACBM or friable suspect ACBM	
011	Mag Block Pipe Insulation	800	LF	Main Building: Tunnel	Chrysotile	TSI	Yes	0	LF	7 Any remaining friable ACBM or friable suspect ACBM	Operations and Maintenance
012	Cardboard Pipe Insulation	500	LF	Main Building: Tunnels	Chrysotile	TSI	Yes	0	LF	7 Any remaining friable ACBM or friable suspect ACBM	Operations and Maintenance
013(F1 8)	9x9 Brown Speckled Floor Tile (ABATED)			Main Building: West Wind Coaches Offices	Abated	MISC					
014(C1 2)	2'x4' Ceiling Tile (ABATED)			Main Building: West Wing Coaches Office	Abated	MISC					
014A	Red, black, brown, tan linoleum pattern (ABATED)			Main Building: auditorium 1st floor, 2nd floor foyer	Abated	MISC					
015(C9)	1'x1' Glued on Ceiling (ABATED)			Main Building: Men's Bathroom	Abated	MISC					
016	Plaster (ABATED)			Main Building: Throughout West Wing Building.	Abated	SURFACE					
017(F1)	9x9 White Floor Tile (ABATED)			Main Building: East Wing Rooms 15, 19, and 306	Abated	MISC					
018	9x9 Pink Floor Tile (ABATED)			Main Building: W Wing Foyer	Abated	MISC					
018(F1 5)	9x9 pink floor tile mastic (ABATED)			Main Building: W. wing 1st floor foyer & 2nd floor foyer and lounge	Abated	MISC					
019	Beige Terrazzo	20,000	SF	Main Office, Rooms 304, 310, 306, 303C, 317, 318, 116, Hallways and Bathrooms	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
020	12 x 12 Yellow Floor Tile	12,500	SF	Rooms 106, 200-205, 208, 209, 216, Library, Office, and Coach's Office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance

Chicago Public Schools

School Brooks College Prep
(Southside College Prep)

Unit 47051

Building ID 1500

Address 250 E. 111th St.

Chicago, IL, 60628

Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262

Fax: (312) 733-5612

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
023	Light beige linoleum (ABATED)			Main Building: gym (room 251), room 253	Abated	MISC					
023(F2)	9x9 black floor tile (ABATED)			Main Building: east wing 2nd & 3rd floor rooms 15,19,306	Abated	MISC					
024(F4)	9"x9" Maroon Floor Tile (ABATED)			Main Building: East Wing 2nd Floor, Library, and Guidance Office	Abated	MISC					
025	12 x 12 Gray Floor Tile	5,000	SF	Band Room, 4th Floor, 403, 407, Office, Bathroom, West Side, 100, 101, Attendance Office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
036 (C13)	2x4 lay in ceiling tile (ABATED)			Main Building: music room	Abated	MISC					
040(F9)	9"x9" Gray Floor Tile (ABATED)			Main Building: Guidance and Xerox Offices	Abated	MISC					
041(F3)	9"x9" Red Floor Tile (ABATED)			Main Building: Rm. 306 and Xerox Rm.	Abated	MISC					
043(F11)	9x9 White Floor Tile (ABATED)			Main Building: Office	Abated	MISC					
045 (F16)	9x9 grey floor tile (ABATED)			Main Building: west wing 2nd floor lounge	Abated	MISC					
046(F20)	9"x9" Green Floor Tile (ABATED)			Main Building: Gym, Cafeteria	Abated	MISC					
047(F19)	9"x9" Tan Floor Tile (ABATED)			Main Building: Gym, Cafeteria Building	Abated	MISC					
049 (F5)	9x9 tan floor tile (ABATED)			Main Building: guidance office, east wing room 29 & library	Abated	MISC					
051 (F12)	9x9 green & white floor tile (ABATED)			Main Building: east wing 2nd & 3rd floor hallway & room 31	Abated	MISC					
052 (F17)	9x9 green & tan floor tile (ABATED)			Annex: office & storage 156A & 156B	Abated	MISC					
052 (F21)	9x9 blue floor tile (ABATED)			Annex: room 151	Abated	MISC					
052(F8)	Blue and White Linoleum (ABATED)			Main Building: 2nd Floor Teachers' Lounge Kitchen	Abated	MISC					
053 (F13)	12x12 tan floor tile (ABATED)			Annex: boys & girls toilets & corridors	Abated	MISC					
054	2x4 ceiling tile (ABATED)			Annex: chemistry lab room 252	Abated	MISC					

Chicago Public Schools

School Brooks College Prep
(Southside College Prep)

Unit 47051

Building ID 1500

Address 250 E. 111th St.

Chicago, IL, 60628

Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262

Fax: (312) 733-5612

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
055	Aircell (ABATED)			Annex: chemistry lab	Abated	MISC					
059	Trim mastic on on tan baseboard (ABATED)			Annex: foyer/corridor	Abated	MISC					
060	Trim tan baseboard (ABATED)			Annex: foyer/corridor	Abated	MISC					
070 (F13)	12x12 tan floor tile mastic (ABATED)			Annex: boys & girls toilets & corridors	Abated	MISC					
070 (F17)	9x9 green floor tile mastic (ABATED)			Annex: room 151	Abated	MISC					
070 (F21)	9x9 blue floor tile mastic (ABATED)			Annex: room 151	Abated	MISC					
072	paneling mastic (ABATED)			Annex: annex corridor	Abated	MISC					
073 (C14)	12x12 ceiling tile mastic (ABATED)			Annex: rooms 155 A-D	Abated	MISC					
078	Aircell pipe insulation	3,000	LF	Monastery: Crawl space tunnels, connecting tunnel from main bldg	Chrysotile	TSI	Yes	0	LF	7 Any remaining friable ACBM or friable suspect ACBM	Operations and Maintenance
079	Hard fittings on aircell pipe insulation	200	LF	Monastery: Crawl space tunnels, connecting tunnel from main bldg	Chrysotile	TSI	Yes	0	LF	6 ACBM with the potential for damage	Operations and Maintenance
080 (F25)	12x12 black floor tile not observed			Monastery: 2nd floor fireplace	Assumed	MISC	No	0		6 ACBM with the potential for damage	Operations and Maintenance
080 (F26)	12x12 red floor tile not observed	260	SF	Monastery: 1st,2nd,3rd floor stairways	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
080 (F27)	12x12 orange/brown floor tile NOT OBSERVED			Monastery: 2nd & 3rd floor monastery	Assumed	MISC		0		6 ACBM with the potential for damage	Operations and Maintenance
081 (F25)	12x12 black floor tile mastic NOT OBSERVED			Monastery: 2nd floor fireplace	Assumed	MISC		0		6 ACBM with the potential for damage	Operations and Maintenance
081 (F26)	12x12 red floor tile mastic NOT OBSERVED	260	SF	Monastery: 1st,2nd,3rd floor stairways	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
081 (F27)	12x12 orange/brown floor tile mastic NOT OBSERVED			Monastery: 2nd & 3rd floor monastery	Assumed	MISC		0		6 ACBM with the potential for damage	Operations and Maintenance
082 (F31)	brown vinyl baseboard			Monastery: 2nd floor community room, monastery	Assumed	MISC	No	0		6 ACBM with the potential for damage	Operations and Maintenance
082(F3 2)	black vinyl baseboard			Monastery: 1st,2nd,3rd floor stairwells,315	Assumed	MISC	No	0		6 ACBM with the potential for damage	Operations and Maintenance
082(F3 3)	wood grain baseboard mastic not observed			Monastery: room 210	Assumed	MISC	No	0		6 ACBM with the potential for damage	Operations and Maintenance
083	mastic under baseboard			Monastery: 2nd floor community room,	Assumed	MISC	No	0		6 ACBM with the potential for damage	Operations and Maintenance

Chicago Public Schools

School Brooks College Prep
(Southside College Prep)

Unit 47051

Building ID 1500

Address 250 E. 111th St.

Chicago, IL, 60628

Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262

Fax: (312) 733-5612

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
(F31)				monastery							
083 (F33)	wood grain baseboard not observed			Monastery: room 210	Assumed	MISC	No	0		6 ACBM with the potential for damage	Operations and Maintenance
083(F32)	black vinyl baseboard mastic not observed			Monastery: 1st,2nd,3rd floor stairwells,315	Assumed	MISC	No	0		6 ACBM with the potential for damage	Operations and Maintenance
084 (CM 45)	orange carpet mastic not observed			Monastery: 2nd floor corridor room 204 & 210	Assumed	MISC	No	0		6 ACBM with the potential for damage	Operations and Maintenance
084 (CM53)	brown tweed carpet mastic not observed			Monastery: room 306	Assumed	MISC	No	0		6 ACBM with the potential for damage	Operations and Maintenance
084(42)	orange/brown carpet mastic not observed			Monastery: 1st floor NW corner	Assumed	MISC	No	0		6 ACBM with the potential for damage	Operations and Maintenance
084(43)	rust carpet mastic not observed			Monastery: 1st floor NW corridor	Assumed	MISC	No	0		6 ACBM with the potential for damage	Operations and Maintenance
084(CM 41)	brown/tweed carpet mastic not observed			Monastery: 1st floor NW Corridor	Assumed	MISC	No	0		6 ACBM with the potential for damage	Operations and Maintenance
085(F28)	9x9 red/black border floor tile	600	SF	Monastery: stairwells 1st, 2nd, 3rd floor	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
085(F29)	9x9 grey/red trim floor tile NOT OBSERVED	350	SF	Monastery:1st floor monastery	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
086(F28)	9x9 red/black border floor tile mastic not observed	600	SF	Monastery: stairwells 1st, 2nd, 3rd floor	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
086(F29)	9x9 grey/red trim floor tile mastic not observed	10	SF	Monastery:1st floor monastery	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
087	12x12 Ceiling Tile- Not Observed			Monastery: 2nd,3rd floor	Assumed	MISC					Operations and Maintenance
088	12x12 Ceiling Tile Mastic Not Observed			Monastery: 2nd 3rd floor	Assumed	MISC					Operations and Maintenance
089	Plaster Not Observed			Monastery: throughout 1st,2nd ,3rd floors	Assumed	SURFACE					Operations and Maintenance
090 (F23)	12x12 white floor tile mastic (BLDG DEMOLISHED)			Annex: physics lab	Chrysotile	MISC					Operations and Maintenance
090M(F 23)	12x12 white floor tile (BLDG DEMOLISHED)			Annex: physics lab	Assumed	MISC					Operations and Maintenance
091	12x12 off white floor tile			Gym	Assumed	MISC	No	0		6 ACBM with the potential for damage	Operations and Maintenance
092	12x12 Off White Floor tile Mastic			Gym	Assumed	MISC	No	0		6 ACBM with the potential for damage	Operations and Maintenance
093	Aircell pipe insulation (NOT OBSERVED)			Gym: Throughout bldg, locker rooms, showers	Chrysotile	TSI					Operations and Maintenance
094	Hard fittings on air cell pipe insulation (NOT OBSERVED)			Gym: Throughout bldg, locker rooms, showers	Chrysotile	TSI					Operations and Maintenance

Chicago Public Schools

School Brooks College Prep
(Southside College Prep)

Unit 47051

Building ID 1500

Address 250 E. 111th St.

Chicago, IL, 60628

Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262

Fax: (312) 733-5612

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
100	1'x1' Ceiling Tile Mastic Not Observed			Monastery: confessionals	Assumed	MISC					Operations and Maintenance
101 (F61)	12x12 light grey floor tile (ABATED)			Main Building: west wing far west corridor	Abated	MISC					
101 (F62)	12x12 dark brown white/black speck floor tile (ABATED)			Main Building: west wing, north west corner	Abated	MISC					
101(F60)	12x12 off white floor tile (ABATED)			Main Building: W wing 3rd floor, NW corner,west & east wing, north portion	Abated	MISC					
102 (F61)	12x12 light grey floor tile mastic (ABATED)			Main Building: west wing far west corridor	Abated	MISC					
102(F60)	12x12 off white floor tile mastic (ABATED)			Main Building:W wing 3rd floor, NW corner,west & east wing, north portion	Abated	MISC					
102(F62)	12x12 dark brown white/black speckled floor tile (ABATED)			Main Building:west wing, north west corner	Abated	MISC					
103(F63)	9x9 light green floor tile (ABATED)			Main Building: west wing corridor, 2nd & 3rd floor east & west wing patches	Abated	MISC					
103(F64)	9x9 light brown floor tile (ABATED)			Main Building: west wing 1st,2nd,3rd corridor patches & east end	Abated	MISC					
103(F65)	9x9 medium brown floor tile (ABATED)			Main Building: west wing 1st & 3rd floor corridor patches & east wing	Abated	MISC					
103(F66)	9x9 yellow floor tile (ABATED)			Main Building: 1st floor corridor patches	Abated	MISC					
103(F7)	9x9 clay floor tile (ABATED)			Main Building: 1st floor corridor west wing	Abated	MISC					
104 (F63)	9x9 light green floor tile mastic (ABATED)			Main Building: west wing corridor, 2nd & 3rd floor east & west wing patches	Abated	MISC					
104 (F7)	9x9 clay floor tile mastic (ABATED)			Main Building: 1st floor corridor west wing	Abated	MISC					
104(F1)	9x9 white floor tile mastic (ABATED)			Main Building: east wing room 15 & 19 & west wing music	Abated	MISC					
104(F2)	9x9 black floor tile mastic (ABATED)			Main Building: east wing room 15 & 19	Abated	MISC					
104(F3)	9x9 pink floor tile mastic (ABATED)			Main Building: west wing 1st,2nd floor foyer	Abated	MISC					
104(F4)	9x9 maroon floor tile mastic (ABATED)			Main Building: 1st & 2nd floor west wing, 1st floor throughout, 2nd flr west rooms	Abated	MISC					

Chicago Public Schools

School Brooks College Prep
(Southside College Prep)

Unit 47051

Building ID 1500

Address 250 E. 111th St.

Chicago, IL, 60628

Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262

Fax: (312) 733-5612

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
104(F5)	9x9 tan abated mastic (ABATED)			Main Building: main BLDG: library, east wing throughout	Abated	MISC					
104(F64)	9x9 light brown floor tile mastic (ABATED)			Main Building: west wing 1st,2nd,3rd corridor patches & east end	Abated	MISC					
104(F65)	9x9 medium brown floor tile mastic (ABATED)			Main Building: west wing 1st & 3rd floor corridor patches & east wing	Abated	MISC					
104(F66)	9x9 yellow floor tile mastic (ABATED)			Main Building: 1st floor corridor patches	Abated	MISC					
104(F67)	9x9 green floor tile mastic (ABATED)			Main Building: 1st floor stairwell, east wing & 2nd & 3rd flr. Hallway	Abated	MISC					
105 (F68)	Various size brown speckled floor tile (ABATED)	4,000	SF	Main Building: 1st,2nd,3rd floor patches in east & west wing	Abated	MISC			SF		
106(F68)	Various size brown speckled floor tile mastic (ABATED)			Main Building: 1st, 2nd,3 rd floor patches in east & west wing	Abated	MISC					
107(CM70)	carpet mastic under multicolored (ABATED)			Main Building: 2nd floor west wing, far west wing	Abated	MISC					
107(CM71)	grey carpet mastic (ABATED)			Main Building: 2nd floor office, 1st floor west corner	Abated	MISC					
108	grey vinyl stair treads (ABATED)			Main Building: 1st, 2nd, 3rd floor east & west wings	Abated	MISC		0		6 ACBM with the potential for damage	
109	vinyl stair track mastic (ABATED)			Main Building: 1st, 2nd, 3rd floor east & west wings	Abated	MISC					
110 (F75)	4" brown vinyl base board (ABATED)	250	LF	Main Building: 1st floor corridor leading to west wing, 3rd floor NW corner	Abated	MISC			LF		
110 (F76)	4" black baseboard (ABATED)			Main Bldg: 1st,2nd,3rd floor throughout east wing & corridor- e. wing 1st flr. NE. corner west wing	Abated	MISC					
110 (F77)	4" tan baseboard (ABATED)			Main Building: 1st, 2nd floor main BLDG, NE. & NW. portion	Abated	MISC					
111(F75)	4" brown vinyl base board mastic (ABATED)			Main Building: 1st floor corridor leading to west wing, 3rd floor NW corner	Abated	MISC					
111(F76)	4" black baseboard (ABATED)			Main Building: 1st,2nd,3rd floor throughout	Abated	MISC					
111(F77)	4" tan baseboard mastic (ABATED)			Main Building: 1st,2nd floor main BLDG, NE. & NW. portion	Abated	MISC					

Chicago Public Schools

School Brooks College Prep
(Southside College Prep)

Unit 47051

Building ID 1500

Address 250 E. 111th St.

Chicago, IL, 60628

Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262

Fax: (312) 733-5612

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
112 (F80)	6" black vinyl baseboard (ABATED)			Main Building: 2nd floor main bldg. SE corner	Abated	MISC					
113 (F80)	6" black vinyl baseboard mastic (ABATED)			Main Building: 2nd floor main bldg. SE corner	Abated	MISC					
114 (CT1)	12x12 ceiling tile (ABATED)			Main Building: 1st floor west wing near NW corner	Abated	MISC					
114 (CTM1)	12x12 ceiling tile mastic (ABATED)			Main Building: 1st floor west wing near NW corner	Abated	MISC					
116	12x12 cork tile (ABATED)			Main Building: 2nd floor west wing room NE. corner of bldg.	Abated	MISC					
151	NOT OBSERVED FLOOR TILE REPLACEMENT 12X12VFT/GREY/DARK BRN	50,000	SF	1ST FL., 2ND FL., 3RD FLOORS HALLWAYS	Assumed	MISC		0	SF	6 ACBM with the potential for damage	Operations and Maintenance
152	MASTIC	50,000	SF	1ST FL., 2ND FL., 3RD FL. THROUGHOUT BLD.BASE BOARD	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
153	2'x4' Speckled Pattern Ceiling Tile (w/ 2'x2' Sections)	1,350	SF	1st Floor: West Wing - Dining Room: 4th Floor: Center Building - Room 402 and 405	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
154	4" Vinyl Baseboard - Grey	1,100	LF	1st Floor: West Wing - Dining Room; 4th Floor: Center Building - Room 400, 400A, 400A-1, 402, 404, 404A, 404C, 404D, and 405	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Operations and Maintenance
155	Mastic associated with 4" Vinyl Baseboard - Grey	1,100	LF	1st Floor: West Wing - Dining Room; 4th Floor: Center Building - Room 400, 400A, 400A-1, 402, 404, 404A, 404C, 404D, and 405	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Operations and Maintenance
156	12"x12" White with Grey Specs Floor Tile	5,350	SF	1st Floor: East Wing - Rooms 131, 133, 135, 137, and 139	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
157	12"x12" White with Grey Specs Floor Tile Mastic	5,350	SF	1st Floor: East Wing - Rooms 131, 133, 135, 137, and 139	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
158	2'x2' Smooth Pattern Ceiling Tile	7,375	SF	1st Floor: East Wing - Rooms 131, 133, 135, 137, and 139, and North/South Corridor	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
159	Interior Window Caulk	400	LF	1st Floor: East Wing - Room 131, 133, 135, 137, and 139; 4th Floor: Center Building - Room 400, 400A, 400A-1,	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Operations and Maintenance

Chicago Public Schools

School Brooks College Prep
(Southside College Prep)

Unit 47051

Building ID 1500

Address 250 E. 111th St.

Chicago, IL, 60628

Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262

Fax: (312) 733-5612

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
				402, 404, 404A, 404C, 404D, and 405							
160	Terrazzo Floor	2,025	SF	1st Floor: East Wing - North/South Corridor	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
161	12"x12" Grey Speckled Floor Tile	2,600	SF	4th Floor: Center Building - Room 400, 400A, 400A-1, 402, 404, 404A, 404C, 404D, and 405	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
162	12"x12" Grey Speckled Floor Tile Mastic	2,600	SF	4th Floor: Center Building - Room 400, 400A, 400A-1, 402, 404, 404A, 404C, 404D, and 405	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
163	Black Sink Undercoat	1	EA	4th Floor: Center Building - Room 400	Assumed	MISC	No	0	EA	6 ACBM with the potential for damage	Operations and Maintenance
164	Black Counter Top	200	SF	4th Floor: Center Building - Room 400 and 400A	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
165	Drywall	4,600	SF	4th Floor: Center Building - Room 400, 400A, and 404	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
166	Drywall Joint Compound	4,600	SF	4th Floor: Center Building - Room 400, 400A, and 404	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
167	Sheet Flooring - Brown Multi-Color Pattern	1,350	SF	1st Floor: West Wing - Dining Room	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
168	Sheet Flooring - Brown Multi-Color Pattern Mastic	1,350	SF	1st Floor: West Wing - Dining Room	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
169	White Sink Undercoat	1	EA	4th Floor: Center Building - Room 404	Assumed	MISC	No	0	EA	6 ACBM with the potential for damage	Operations and Maintenance
170	Carpet Mastic - Brown	2,200	SF	Rooms 100 A, 100 C, 100 E, 100 F, 105, 111, 116A and 116B	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
171	Carpet Mastic Blue w/ white streaks	1,500	SF	Rooms 201, 201A, 201C and 201D	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
172	Carpet Mastic Brown w/ blue and orange streaks	10,300	SF	Rooms 147, 153A, 153C, 153D, 153E, 153F, 153F2, 235, 237A, 237D and Library	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
21	12 x 12 Yellow Floor Tile Mastic	12,500	SF	Rooms 106, 200-206, 208, 209, 210, 216, Library, Office, and Coach's Office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
22	Brown Carpet Mastic	6,000	SF	Library, Assistant Principals, Nurse Office, Side Office, 102, 103, 111, 117, and Office Hall	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
26	12 x 12 Gray Floor Tile Mastic	12,500	SF	Band Room, 4th Floor, 403, 407, Office, Bathroom, West Side, 100, 101, Attendance Office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
27	2 x 4 Lay-in Panels NOT OBSERVED	1,000	SF	Kitchen-NOT OBSERVED	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
28	Spray-on Insulation	3,000	SF	Gymnasium	Assumed	TSI	Yes	0	SF	6 ACBM with the potential for damage	Operations and Maintenance

Chicago Public Schools

School Brooks College Prep
(Southside College Prep)

Unit 47051

Building ID 1500

Address 250 E. 111th St.

Chicago, IL, 60628

Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262

Fax: (312) 733-5612

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
29	2 x 2 Lay-in Ceiling Panels	20,000	SF	Hallways	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
30	Black Counter Tops	26	SF	Rooms 307 and 307A	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance

Review Date	5/13/2013
Manager Planner Name	Guillermo Garcia

HA Number	Management Comments
002	

Chicago Public Schools

School Brooks College Prep
(Southside College Prep)

Unit 47051

Building ID 1500

Address 250 E. 111th St.

Chicago, IL, 60628

Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262

Fax: (312) 733-5612

Management Planner's Comments Summarized at the End of the Report

100-01786	5/15/2013
Manager IDPH License No/Expiration	

HA Number	Management Comments
004	
005	
007	
008	
009	
010	
011	
012	
013(F18)	
014(C12)	
014A	
015(C9)	
016	
017(F1)	
018	
018(F15)	
019	
020	
023	
023(F2)	
024(F4)	
025	
036 (C13)	
040(F9)	
041(F3)	
043(F11)	

Chicago Public Schools

School Brooks College Prep
(Southside College Prep)

Unit 47051

Building ID 1500

Address 250 E. 111th St.

Chicago, IL, 60628

Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262

Fax: (312) 733-5612

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
045 (F16)	
046(F20)	
047(F19)	
049 (F5)	
051 (F12)	
052 (F17)	
052 (F21)	
052(F8)	
053 (F13)	
054	
055	
059	
060	
070 (F13)	
070 (F17)	
070 (F21)	
072	
073 (C14)	
078	
079	
080 (F25)	
080 (F26)	
080 (F27)	
081 (F25)	
081 (F26)	
081 (F27)	

Chicago Public Schools

School Brooks College Prep
(Southside College Prep)

Unit 47051

Building ID 1500

Address 250 E. 111th St.

Chicago, IL, 60628

Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262

Fax: (312) 733-5612

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
082 (F31)	
082(F32)	
082(F33)	
083 (F31)	
083 (F33)	
083(F32)	
084 (CM 45)	
084 (CM53)	
084(42)	
084(43)	
084(CM41)	
085(F28)	
085(F29)	
086(F28)	
086(F29)	
087	
088	
089	
090 (F23)	
090M(F23)	
091	
092	
093	
094	
100	
101 (F61)	

Chicago Public Schools

School Brooks College Prep
(Southside College Prep)

Unit 47051

Building ID 1500

Address 250 E. 111th St.

Chicago, IL, 60628

Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262

Fax: (312) 733-5612

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
101 (F62)	
101(F60)	
102 (F61)	
102(F60)	
102(F62)	
103(F63)	
103(F64)	
103(F65)	
103(F66)	
103(F7)	
104 (F63)	
104 (F7)	
104(F1)	
104(F2)	
104(F3)	
104(F4)	
104(F5)	
104(F64)	
104(F65)	
104(F66)	
104(F67)	
105 (F68)	
106(F68)	
107(CM70)	
107(CM71)	
108	

Chicago Public Schools

School Brooks College Prep
(Southside College Prep)

Unit 47051

Building ID 1500

Address 250 E. 111th St.

Chicago, IL, 60628

Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262

Fax: (312) 733-5612

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
109	
110 (F75)	
110 (F76)	
110 (F77)	
111(F75)	
111(F76)	
111(F77)	
112 (F80)	
113 (F80)	
114 (CT1)	
114 (CTM1)	
116	
151	
152	
153	
154	
155	
156	
157	
158	
159	
160	
161	
162	
163	
164	

Chicago Public Schools

School Brooks College Prep
(Southside College Prep)

Unit 47051

Building ID 1500

Address 250 E. 111th St.

Chicago, IL, 60628

Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262

Fax: (312) 733-5612

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
165	
166	
167	
168	
169	
170	
171	
172	
21	
22	
26	
27	
28	
29	
30	

Chicago Public Schools

GSG Consultants, Inc.

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47051** BUILDING ID: **1500**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ismael Hernandez**
SCHOOL NAME: **Brooks College Prep (Southside College Prep)** INSPECTION DATE: **4/17/2013**
ADDRESS: **250 E. 111th St.** IDPH LICENSE NO: **100-19036**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **002**
MATERIAL DESCRIPTION: **Aircell jacket (ABATED)**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Main Building: Hot water tank in boiler room**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **04/17/2013**

Chicago Public Schools

GSG Consultants, Inc. 2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47051** BUIDLING ID: **1500**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**
SCHOOL NAME: **Brooks College Prep
(Southside College
Prep)** REVIEW DATE: **5/13/2013**
ADDRESS: **250 E. 111th St.** IDPH LICENSE NO: **100-19036**

HOMOGENEOUS AREA: **002**
MATERIAL DESCRIPTION: **Aircell jacket (ABATED)**
MATERIAL LOCATION: **Main Building: Hot water tank in boiler room**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: 05/13/2013

Chicago Public Schools

GSG Consultants, Inc. 2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47051** BUIDLING ID: **1500**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ismael Hernandez**
SCHOOL NAME: **Brooks College Prep (Southside College Prep)** INSPECTION DATE: **4/17/2013**
ADDRESS: **250 E. 111th St.** IDPH LICENSE NO: **100-19036**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **004**
MATERIAL DESCRIPTION: **Cardboard Pipe Insulation (ABATED)**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:


MATERIAL LOCATION: **Main Building: Boiler Rm. East**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **04/17/2013**

Chicago Public Schools

GSG Consultants, Inc. 2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47051** BUILDING ID: **1500**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**
SCHOOL NAME: **Brooks College Prep
(Southside College
Prep)** REVIEW DATE: **5/13/2013**
ADDRESS: **250 E. 111th St.** IDPH LICENSE NO: **100-19036**

HOMOGENEOUS AREA: **004**
MATERIAL DESCRIPTION: **Cardboard Pipe Insulation (ABATED)**
MATERIAL LOCATION: **Main Building: Boiler Rm. East**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: 05/13/2013

Chicago Public Schools

GSG Consultants, Inc. 2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47051** BUIDLING ID: **1500**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ismael Hernandez**
SCHOOL NAME: **Brooks College Prep (Southside College Prep)** INSPECTION DATE: **4/17/2013**
ADDRESS: **250 E. 111th St.** IDPH LICENSE NO: **100-19036**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **005**
MATERIAL DESCRIPTION: **Mag. Jacket Boilers 1&2 (ABATED)**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Main Building: Boiler Rm.**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **04/17/2013**

Chicago Public Schools

GSG Consultants, Inc.

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47051** BUILDING ID: **1500**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**
SCHOOL NAME: **Brooks College Prep (Southside College Prep)** REVIEW DATE: **5/13/2013**
ADDRESS: **250 E. 111th St.** IDPH LICENSE NO: **100-19036**

HOMOGENEOUS AREA: **005**
MATERIAL DESCRIPTION: **Mag. Jacket Boilers 1&2 (ABATED)**
MATERIAL LOCATION: **Main Building: Boiler Rm.**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: 05/13/2013

Chicago Public Schools

GSG Consultants, Inc.
2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47051** BUIDLING ID: **1500**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ismael Hernandez**
SCHOOL NAME: **Brooks College Prep (Southside College Prep)** INSPECTION DATE: **4/17/2013**
ADDRESS: **250 E. 111th St.** IDPH LICENSE NO: **100-19036**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **007**
MATERIAL DESCRIPTION: **Cardboard Pipe Insulation (ABATED)**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:


MATERIAL LOCATION: **Main Building: Boiler Rm. East Perimeter**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **04/17/2013**

Chicago Public Schools

GSG Consultants, Inc.

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47051** BUILDING ID: **1500**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**
SCHOOL NAME: **Brooks College Prep (Southside College Prep)** REVIEW DATE: **5/13/2013**
ADDRESS: **250 E. 111th St.** IDPH LICENSE NO: **100-19036**

HOMOGENEOUS AREA: **007**
MATERIAL DESCRIPTION: **Cardboard Pipe Insulation (ABATED)**
MATERIAL LOCATION: **Main Building: Boiler Rm. East Perimeter**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: 05/13/2013

Chicago Public Schools

GSG Consultants, Inc. 2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47051** BUIDLING ID: **1500**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ismael Hernandez**
SCHOOL NAME: **Brooks College Prep (Southside College Prep)** INSPECTION DATE: **4/17/2013**
ADDRESS: **250 E. 111th St.** IDPH LICENSE NO: **100-19036**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **008**
MATERIAL DESCRIPTION: **Joint compound on Cardboard Pipe Insul. (ABATED)**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:


MATERIAL LOCATION: **Main Building: Boiler Rm. Hot Water Pipe**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **04/17/2013**

Chicago Public Schools

GSG Consultants, Inc. 2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47051** BUILDING ID: **1500**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**
SCHOOL NAME: **Brooks College Prep
(Southside College
Prep)** REVIEW DATE: **5/13/2013**
ADDRESS: **250 E. 111th St.** IDPH LICENSE NO: **100-19036**

HOMOGENEOUS AREA: **008**
MATERIAL DESCRIPTION: **Joint compound on Cardboard Pipe Insul. (ABATED)**
MATERIAL LOCATION: **Main Building: Boiler Rm. Hot Water Pipe**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: 05/13/2013

Chicago Public Schools

GSG Consultants, Inc. 2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47051** BUIDLING ID: **1500**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ismael Hernandez**
SCHOOL NAME: **Brooks College Prep (Southside College Prep)** INSPECTION DATE: **4/17/2013**
ADDRESS: **250 E. 111th St.** IDPH LICENSE NO: **100-19036**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **009**
MATERIAL DESCRIPTION: **Joint compound on aircell pipe insulation (ABATED)**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:


MATERIAL LOCATION: **Main Building: boiler room on east wall**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **04/17/2013**

Chicago Public Schools

GSG Consultants, Inc. 2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47051** BUILDING ID: **1500**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**
SCHOOL NAME: **Brooks College Prep
(Southside College
Prep)** REVIEW DATE: **5/13/2013**
ADDRESS: **250 E. 111th St.** IDPH LICENSE NO: **100-19036**

HOMOGENEOUS AREA: **009**
MATERIAL DESCRIPTION: **Joint compound on aircell pipe insulation (ABATED)**
MATERIAL LOCATION: **Main Building: boiler room on east wall**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: 05/13/2013

Chicago Public Schools

GSG Consultants, Inc.
2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47051** BUIDLING ID: **1500**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ismael Hernandez**
SCHOOL NAME: **Brooks College Prep (Southside College Prep)** INSPECTION DATE: **4/17/2013**
ADDRESS: **250 E. 111th St.** IDPH LICENSE NO: **100-19036**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **010**
MATERIAL DESCRIPTION: **Aircell Pipe Insulation**
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Abated** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Main Building: Attic (abated) and Tunnels (still present)**
MATERIAL QUANTITY: **0** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: DAMAGE UNITS: **LF**
COMMENTS:

Inspector's Signature: _____



Date: 04/17/2013

Chicago Public Schools

GSG Consultants, Inc. 2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47051** BUILDING ID: **1500**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**
SCHOOL NAME: **Brooks College Prep
(Southside College
Prep)** REVIEW DATE: **5/13/2013**
ADDRESS: **250 E. 111th St.** IDPH LICENSE NO: **100-19036**

HOMOGENEOUS AREA: **010**
MATERIAL DESCRIPTION: **Aircell Pipe Insulation**
MATERIAL LOCATION: **Main Building: Attic (abated) and Tunnels (still present)**
MATERIAL QUANTITY: **0** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **05/13/2013**

Chicago Public Schools

GSG Consultants, Inc. 2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47051** BUIDLING ID: **1500**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ismael Hernandez**
SCHOOL NAME: **Brooks College Prep (Southside College Prep)** INSPECTION DATE: **4/17/2013**
ADDRESS: **250 E. 111th St.** IDPH LICENSE NO: **100-19036**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **011**
MATERIAL DESCRIPTION: **Mag Block Pipe Insulation**
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Main Building: Tunnel**

MATERIAL QUANTITY: **800**


MATERIAL UNITS: **LF**

DAMAGE QUANTITY:

DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: _____



Date: 04/17/2013

Chicago Public Schools

GSG Consultants, Inc. 2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47051** BUILDING ID: **1500**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**
SCHOOL NAME: **Brooks College Prep
(Southside College
Prep)** REVIEW DATE: **5/13/2013**
ADDRESS: **250 E. 111th St.** IDPH LICENSE NO: **100-19036**

HOMOGENEOUS AREA: **011**
MATERIAL DESCRIPTION: **Mag Block Pipe Insulation**
MATERIAL LOCATION: **Main Building: Tunnel**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **05/13/2013**

Chicago Public Schools

GSG Consultants, Inc. 2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47051** BUIDLING ID: **1500**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ismael Hernandez**
SCHOOL NAME: **Brooks College Prep (Southside College Prep)** INSPECTION DATE: **4/17/2013**
ADDRESS: **250 E. 111th St.** IDPH LICENSE NO: **100-19036**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **012**
MATERIAL DESCRIPTION: **Cardboard Pipe Insulation**
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**

MATERIAL LOCATION: **Main Building: Tunnels**

MATERIAL QUANTITY: **500**


MATERIAL UNITS: **LF**

DAMAGE QUANTITY:

DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: _____



Date: 04/17/2013

Chicago Public Schools

GSG Consultants, Inc.
2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47051** BUILDING ID: **1500**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**
SCHOOL NAME: **Brooks College Prep
(Southside College
Prep)** REVIEW DATE: **5/13/2013**
ADDRESS: **250 E. 111th St.** IDPH LICENSE NO: **100-19036**

HOMOGENEOUS AREA: **012**
MATERIAL DESCRIPTION: **Cardboard Pipe Insulation**
MATERIAL LOCATION: **Main Building: Tunnels**
MATERIAL QUANTITY: **500** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **05/13/2013**

Chicago Public Schools

GSG Consultants, Inc. 2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47051** BUIDLING ID: **1500**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ismael Hernandez**
SCHOOL NAME: **Brooks College Prep (Southside College Prep)** INSPECTION DATE: **4/17/2013**
ADDRESS: **250 E. 111th St.** IDPH LICENSE NO: **100-19036**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **013(F18)**
MATERIAL DESCRIPTION: **9x9 Brown Speckled Floor Tile (ABATED)**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Main Building: West Wind Coaches Offices**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **04/17/2013**

Chicago Public Schools

GSG Consultants, Inc. 2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47051** BUILDING ID: **1500**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**
SCHOOL NAME: **Brooks College Prep
(Southside College
Prep)** REVIEW DATE: **5/13/2013**
ADDRESS: **250 E. 111th St.** IDPH LICENSE NO: **100-19036**

HOMOGENEOUS AREA: **013(F18)**
MATERIAL DESCRIPTION: **9x9 Brown Speckled Floor Tile (ABATED)**
MATERIAL LOCATION: **Main Building: West Wind Coaches Offices**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: 05/13/2013

Chicago Public Schools

GSG Consultants, Inc. 2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47051** BUIDLING ID: **1500**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ismael Hernandez**
SCHOOL NAME: **Brooks College Prep (Southside College Prep)** INSPECTION DATE: **4/17/2013**
ADDRESS: **250 E. 111th St.** IDPH LICENSE NO: **100-19036**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **014(C12)**
MATERIAL DESCRIPTION: **2'x4' Ceiling Tile (ABATED)**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Main Building: West Wing Coaches Office**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **04/17/2013**

Chicago Public Schools

GSG Consultants, Inc.

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47051** BUIDLING ID: **1500**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**
SCHOOL NAME: **Brooks College Prep
(Southside College
Prep)** REVIEW DATE: **5/13/2013**
ADDRESS: **250 E. 111th St.** IDPH LICENSE NO: **100-19036**

HOMOGENEOUS AREA: **014(C12)**
MATERIAL DESCRIPTION: **2'x4' Ceiling Tile (ABATED)**
MATERIAL LOCATION: **Main Building: West Wing Coaches Office**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: 05/13/2013

Chicago Public Schools

GSG Consultants, Inc.
2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47051** BUIDLING ID: **1500**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ismael Hernandez**
SCHOOL NAME: **Brooks College Prep (Southside College Prep)** INSPECTION DATE: **4/17/2013**
ADDRESS: **250 E. 111th St.** IDPH LICENSE NO: **100-19036**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **014A**
MATERIAL DESCRIPTION: **Red, black, brown, tan linoleum pattern (ABATED)**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:


MATERIAL LOCATION: **Main Building: auditorium 1st floor, 2nd floor foyer**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **04/17/2013**

Chicago Public Schools

GSG Consultants, Inc.
2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47051** BUILDING ID: **1500**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**
SCHOOL NAME: **Brooks College Prep
(Southside College
Prep)** REVIEW DATE: **5/13/2013**
ADDRESS: **250 E. 111th St.** IDPH LICENSE NO: **100-19036**

HOMOGENEOUS AREA: **014A**
MATERIAL DESCRIPTION: **Red, black, brown, tan linoleum pattern (ABATED)**
MATERIAL LOCATION: **Main Building: auditorium 1st floor, 2nd floor foyer**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: 05/13/2013

Chicago Public Schools

GSG Consultants, Inc. 2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47051** BUIDLING ID: **1500**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ismael Hernandez**
SCHOOL NAME: **Brooks College Prep (Southside College Prep)** INSPECTION DATE: **4/17/2013**
ADDRESS: **250 E. 111th St.** IDPH LICENSE NO: **100-19036**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **015(C9)**
MATERIAL DESCRIPTION: **1'x1' Glued on Ceiling (ABATED)**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:


MATERIAL LOCATION: **Main Building: Men's Bathroom**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **04/17/2013**

Chicago Public Schools

GSG Consultants, Inc.

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47051** BUILDING ID: **1500**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**
SCHOOL NAME: **Brooks College Prep (Southside College Prep)** REVIEW DATE: **5/13/2013**
ADDRESS: **250 E. 111th St.** IDPH LICENSE NO: **100-19036**

HOMOGENEOUS AREA: **015(C9)**

MATERIAL DESCRIPTION: **1'x1' Glued on Ceiling (ABATED)**

MATERIAL LOCATION: **Main Building: Men's Bathroom**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: 05/13/2013

Chicago Public Schools

GSG Consultants, Inc. 2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47051** BUIDLING ID: **1500**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ismael Hernandez**
SCHOOL NAME: **Brooks College Prep (Southside College Prep)** INSPECTION DATE: **4/17/2013**
ADDRESS: **250 E. 111th St.** IDPH LICENSE NO: **100-19036**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **016**
MATERIAL DESCRIPTION: **Plaster (ABATED)**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:


MATERIAL LOCATION: **Main Building: Throughout West Wing Building.**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **04/17/2013**

Chicago Public Schools

GSG Consultants, Inc. 2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47051** BUILDING ID: **1500**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**
SCHOOL NAME: **Brooks College Prep
(Southside College
Prep)** REVIEW DATE: **5/13/2013**
ADDRESS: **250 E. 111th St.** IDPH LICENSE NO: **100-19036**

HOMOGENEOUS AREA: **016**
MATERIAL DESCRIPTION: **Plaster (ABATED)**
MATERIAL LOCATION: **Main Building: Throughout West Wing Building.**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: 05/13/2013

Chicago Public Schools

GSG Consultants, Inc.
2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47051** BUIDLING ID: **1500**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ismael Hernandez**
SCHOOL NAME: **Brooks College Prep (Southside College Prep)** INSPECTION DATE: **4/17/2013**
ADDRESS: **250 E. 111th St.** IDPH LICENSE NO: **100-19036**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **017(F1)**
MATERIAL DESCRIPTION: **9x9 White Floor Tile (ABATED)**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:


MATERIAL LOCATION: **Main Building: East Wing Rooms 15, 19, and 306**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **04/17/2013**

Chicago Public Schools

GSG Consultants, Inc.
2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47051** BUILDING ID: **1500**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**
SCHOOL NAME: **Brooks College Prep
(Southside College
Prep)** REVIEW DATE: **5/13/2013**
ADDRESS: **250 E. 111th St.** IDPH LICENSE NO: **100-19036**

HOMOGENEOUS AREA: **017(F1)**
MATERIAL DESCRIPTION: **9x9 White Floor Tile (ABATED)**
MATERIAL LOCATION: **Main Building: East Wing Rooms 15, 19, and 306**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: 05/13/2013

Chicago Public Schools

GSG Consultants, Inc.
2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47051** BUIDLING ID: **1500**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ismael Hernandez**
SCHOOL NAME: **Brooks College Prep (Southside College Prep)** INSPECTION DATE: **4/17/2013**
ADDRESS: **250 E. 111th St.** IDPH LICENSE NO: **100-19036**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **018**
MATERIAL DESCRIPTION: **9x9 Pink Floor Tile (ABATED)**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:


MATERIAL LOCATION: **Main Building: W Wing Foyer**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **04/17/2013**

Chicago Public Schools

GSG Consultants, Inc.

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47051** BUILDING ID: **1500**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**
SCHOOL NAME: **Brooks College Prep (Southside College Prep)** REVIEW DATE: **5/13/2013**
ADDRESS: **250 E. 111th St.** IDPH LICENSE NO: **100-19036**

HOMOGENEOUS AREA: **018**
MATERIAL DESCRIPTION: **9x9 Pink Floor Tile (ABATED)**
MATERIAL LOCATION: **Main Building: W Wing Foyer**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: 05/13/2013

Chicago Public Schools

GSG Consultants, Inc. 2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47051** BUIDLING ID: **1500**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ismael Hernandez**
SCHOOL NAME: **Brooks College Prep (Southside College Prep)** INSPECTION DATE: **4/17/2013**
ADDRESS: **250 E. 111th St.** IDPH LICENSE NO: **100-19036**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **018(F15)**
MATERIAL DESCRIPTION: **9x9 pink floor tile mastic (ABATED)**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:


MATERIAL LOCATION: **Main Building: W. wing 1st floor foyer & 2nd floor foyer and lounge**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **04/17/2013**

Chicago Public Schools

GSG Consultants, Inc.
2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47051** BUILDING ID: **1500**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**
SCHOOL NAME: **Brooks College Prep
(Southside College
Prep)** REVIEW DATE: **5/13/2013**
ADDRESS: **250 E. 111th St.** IDPH LICENSE NO: **100-19036**

HOMOGENEOUS AREA: **018(F15)**
MATERIAL DESCRIPTION: **9x9 pink floor tile mastic (ABATED)**
MATERIAL LOCATION: **Main Building: W. wing 1st floor foyer & 2nd floor foyer and lounge**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: 05/13/2013

Chicago Public Schools

GSG Consultants, Inc.
2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47051** BUIDLING ID: **1500**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ismael Hernandez**
SCHOOL NAME: **Brooks College Prep (Southside College Prep)** INSPECTION DATE: **4/17/2013**
ADDRESS: **250 E. 111th St.** IDPH LICENSE NO: **100-19036**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **019**
MATERIAL DESCRIPTION: **Beige Terrazzo**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Main Office, Rooms 304, 310, 306, 303C, 317, 318, 116, Hallways and Bathrooms**
MATERIAL QUANTITY: **20000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____



Date: 04/17/2013

Chicago Public Schools

GSG Consultants, Inc.

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47051** BUILDING ID: **1500**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**
SCHOOL NAME: **Brooks College Prep (Southside College Prep)** REVIEW DATE: **5/13/2013**
ADDRESS: **250 E. 111th St.** IDPH LICENSE NO: **100-19036**

HOMOGENEOUS AREA: **019**
MATERIAL DESCRIPTION: **Beige Terrazzo**
MATERIAL LOCATION: **Main Office, Rooms 304, 310, 306, 303C, 317, 318, 116, Hallways and Bathrooms**
MATERIAL QUANTITY: **20000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **05/13/2013**

Chicago Public Schools

GSG Consultants, Inc.
2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47051** BUIDLING ID: **1500**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ismael Hernandez**
SCHOOL NAME: **Brooks College Prep (Southside College Prep)** INSPECTION DATE: **4/17/2013**
ADDRESS: **250 E. 111th St.** IDPH LICENSE NO: **100-19036**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **020**
MATERIAL DESCRIPTION: **12 x 12 Yellow Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms 106, 200-205, 208, 209, 216, Library, Office, and Coach's Office**
MATERIAL QUANTITY: **12500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS: **No Access to Rms 206 & 210**

Inspector's Signature: _____



Date: 04/17/2013

Chicago Public Schools

GSG Consultants, Inc.
2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47051** BUILDING ID: **1500**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**
SCHOOL NAME: **Brooks College Prep (Southside College Prep)** REVIEW DATE: **5/13/2013**
ADDRESS: **250 E. 111th St.** IDPH LICENSE NO: **100-19036**

HOMOGENEOUS AREA: **020**
MATERIAL DESCRIPTION: **12 x 12 Yellow Floor Tile**
MATERIAL LOCATION: **Rooms 106, 200-205, 208, 209, 216, Library, Office, and Coach's Office**
MATERIAL QUANTITY: **12500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **05/13/2013**

Chicago Public Schools

GSG Consultants, Inc.
2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47051** BUIDLING ID: **1500**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ismael Hernandez**
SCHOOL NAME: **Brooks College Prep (Southside College Prep)** INSPECTION DATE: **4/17/2013**
ADDRESS: **250 E. 111th St.** IDPH LICENSE NO: **100-19036**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **023**
MATERIAL DESCRIPTION: **Light beige linoleum (ABATED)**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Main Building: gym (room 251), room 253**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **04/17/2013**

Chicago Public Schools

GSG Consultants, Inc. 2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47051** BUILDING ID: **1500**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**
SCHOOL NAME: **Brooks College Prep
(Southside College
Prep)** REVIEW DATE: **5/13/2013**
ADDRESS: **250 E. 111th St.** IDPH LICENSE NO: **100-19036**

HOMOGENEOUS AREA: **023**
MATERIAL DESCRIPTION: **Light beige linoleum (ABATED)**
MATERIAL LOCATION: **Main Building: gym (room 251), room 253**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: 05/13/2013

Chicago Public Schools

GSG Consultants, Inc.
2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47051** BUIDLING ID: **1500**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ismael Hernandez**
SCHOOL NAME: **Brooks College Prep (Southside College Prep)** INSPECTION DATE: **4/17/2013**
ADDRESS: **250 E. 111th St.** IDPH LICENSE NO: **100-19036**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **023(F2)**
MATERIAL DESCRIPTION: **9x9 black floor tile (ABATED)**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:


MATERIAL LOCATION: **Main Building: east wing 2nd & 3rd floor rooms 15,19,306**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **04/17/2013**

Chicago Public Schools

GSG Consultants, Inc. 2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47051** BUIDLING ID: **1500**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**
SCHOOL NAME: **Brooks College Prep
(Southside College
Prep)** REVIEW DATE: **5/13/2013**
ADDRESS: **250 E. 111th St.** IDPH LICENSE NO: **100-19036**

HOMOGENEOUS AREA: **023(F2)**
MATERIAL DESCRIPTION: **9x9 black floor tile (ABATED)**
MATERIAL LOCATION: **Main Building: east wing 2nd & 3rd floor rooms 15,19,306**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: 05/13/2013

Chicago Public Schools

GSG Consultants, Inc. 2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47051** BUIDLING ID: **1500**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ismael Hernandez**
SCHOOL NAME: **Brooks College Prep (Southside College Prep)** INSPECTION DATE: **4/17/2013**
ADDRESS: **250 E. 111th St.** IDPH LICENSE NO: **100-19036**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **024(F4)**
MATERIAL DESCRIPTION: **9"x9" Maroon Floor Tile (ABATED)**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:


MATERIAL LOCATION: **Main Building: East Wing 2nd Floor, Library, and Guidance Office**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **04/17/2013**

Chicago Public Schools

GSG Consultants, Inc.

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47051** BUILDING ID: **1500**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**
SCHOOL NAME: **Brooks College Prep (Southside College Prep)** REVIEW DATE: **5/13/2013**
ADDRESS: **250 E. 111th St.** IDPH LICENSE NO: **100-19036**

HOMOGENEOUS AREA: **024(F4)**
MATERIAL DESCRIPTION: **9"x9" Maroon Floor Tile (ABATED)**
MATERIAL LOCATION: **Main Building: East Wing 2nd Floor, Library, and Guidance Office**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: 05/13/2013

Chicago Public Schools

GSG Consultants, Inc. 2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47051** BUIDLING ID: **1500**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ismael Hernandez**
SCHOOL NAME: **Brooks College Prep (Southside College Prep)** INSPECTION DATE: **4/17/2013**
ADDRESS: **250 E. 111th St.** IDPH LICENSE NO: **100-19036**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **025**
MATERIAL DESCRIPTION: **12 x 12 Gray Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Band Room, 4th Floor, 403, 407, Office, Bathroom, West Side, 100, 101, Attendance Office**

MATERIAL QUANTITY: **5000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 04/17/2013

Chicago Public Schools

GSG Consultants, Inc. 2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47051** BUILDING ID: **1500**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**
SCHOOL NAME: **Brooks College Prep (Southside College Prep)** REVIEW DATE: **5/13/2013**
ADDRESS: **250 E. 111th St.** IDPH LICENSE NO: **100-19036**

HOMOGENEOUS AREA: **025**
MATERIAL DESCRIPTION: **12 x 12 Gray Floor Tile**
MATERIAL LOCATION: **Band Room, 4th Floor, 403, 407, Office, Bathroom, West Side, 100, 101, Attendance Office**
MATERIAL QUANTITY: **5000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **05/13/2013**

Chicago Public Schools

GSG Consultants, Inc. 2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47051** BUIDLING ID: **1500**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ismael Hernandez**
SCHOOL NAME: **Brooks College Prep (Southside College Prep)** INSPECTION DATE: **4/17/2013**
ADDRESS: **250 E. 111th St.** IDPH LICENSE NO: **100-19036**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **036 (C13)**
MATERIAL DESCRIPTION: **2x4 lay in ceiling tile (ABATED)**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:


MATERIAL LOCATION: **Main Building: music room**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **04/17/2013**

Chicago Public Schools

GSG Consultants, Inc.

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47051** BUILDING ID: **1500**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**
SCHOOL NAME: **Brooks College Prep
(Southside College
Prep)** REVIEW DATE: **5/13/2013**
ADDRESS: **250 E. 111th St.** IDPH LICENSE NO: **100-19036**

HOMOGENEOUS AREA: **036 (C13)**
MATERIAL DESCRIPTION: **2x4 lay in ceiling tile (ABATED)**
MATERIAL LOCATION: **Main Building: music room**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: 05/13/2013

Chicago Public Schools

GSG Consultants, Inc. 2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47051** BUIDLING ID: **1500**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ismael Hernandez**
SCHOOL NAME: **Brooks College Prep (Southside College Prep)** INSPECTION DATE: **4/17/2013**
ADDRESS: **250 E. 111th St.** IDPH LICENSE NO: **100-19036**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **040(F9)**
MATERIAL DESCRIPTION: **9"x9" Gray Floor Tile (ABATED)**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:


MATERIAL LOCATION: **Main Building: Guidance and Xerox Offices**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **04/17/2013**

Chicago Public Schools

GSG Consultants, Inc.

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47051** BUIDLING ID: **1500**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**
SCHOOL NAME: **Brooks College Prep (Southside College Prep)** REVIEW DATE: **5/13/2013**
ADDRESS: **250 E. 111th St.** IDPH LICENSE NO: **100-19036**

HOMOGENEOUS AREA: **040(F9)**
MATERIAL DESCRIPTION: **9"x9" Gray Floor Tile (ABATED)**
MATERIAL LOCATION: **Main Building: Guidance and Xerox Offices**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: 05/13/2013

Chicago Public Schools

GSG Consultants, Inc. 2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47051** BUIDLING ID: **1500**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ismael Hernandez**
SCHOOL NAME: **Brooks College Prep (Southside College Prep)** INSPECTION DATE: **4/17/2013**
ADDRESS: **250 E. 111th St.** IDPH LICENSE NO: **100-19036**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **041(F3)**
MATERIAL DESCRIPTION: **9"x9" Red Floor Tile (ABATED)**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Main Building: Rm. 306 and Xerox Rm.**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **04/17/2013**

Chicago Public Schools

GSG Consultants, Inc.
2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47051** BUIDLING ID: **1500**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**
SCHOOL NAME: **Brooks College Prep
(Southside College
Prep)** REVIEW DATE: **5/13/2013**
ADDRESS: **250 E. 111th St.** IDPH LICENSE NO: **100-19036**

HOMOGENEOUS AREA: **041(F3)**
MATERIAL DESCRIPTION: **9"x9" Red Floor Tile (ABATED)**
MATERIAL LOCATION: **Main Building: Rm. 306 and Xerox Rm.**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: 05/13/2013

Chicago Public Schools

GSG Consultants, Inc.
2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47051** BUIDLING ID: **1500**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ismael Hernandez**
SCHOOL NAME: **Brooks College Prep (Southside College Prep)** INSPECTION DATE: **4/17/2013**
ADDRESS: **250 E. 111th St.** IDPH LICENSE NO: **100-19036**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **043(F11)**
MATERIAL DESCRIPTION: **9x9 White Floor Tile (ABATED)**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:


MATERIAL LOCATION: **Main Building: Office**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **04/17/2013**

Chicago Public Schools

GSG Consultants, Inc. 2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47051** BUILDING ID: **1500**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**
SCHOOL NAME: **Brooks College Prep
(Southside College
Prep)** REVIEW DATE: **5/13/2013**
ADDRESS: **250 E. 111th St.** IDPH LICENSE NO: **100-19036**

HOMOGENEOUS AREA: **043(F11)**
MATERIAL DESCRIPTION: **9x9 White Floor Tile (ABATED)**
MATERIAL LOCATION: **Main Building: Office**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: 05/13/2013

Chicago Public Schools

GSG Consultants, Inc.
2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47051** BUIDLING ID: **1500**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ismael Hernandez**
SCHOOL NAME: **Brooks College Prep (Southside College Prep)** INSPECTION DATE: **4/17/2013**
ADDRESS: **250 E. 111th St.** IDPH LICENSE NO: **100-19036**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **045 (F16)**
MATERIAL DESCRIPTION: **9x9 grey floor tile (ABATED)**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:


MATERIAL LOCATION: **Main Building: west wing 2nd floor lounge**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **04/17/2013**

Chicago Public Schools

GSG Consultants, Inc. 2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47051** BUILDING ID: **1500**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**
SCHOOL NAME: **Brooks College Prep
(Southside College
Prep)** REVIEW DATE: **5/13/2013**
ADDRESS: **250 E. 111th St.** IDPH LICENSE NO: **100-19036**

HOMOGENEOUS AREA: **045 (F16)**
MATERIAL DESCRIPTION: **9x9 grey floor tile (ABATED)**
MATERIAL LOCATION: **Main Building: west wing 2nd floor lounge**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: 05/13/2013

Chicago Public Schools

GSG Consultants, Inc. 2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47051** BUIDLING ID: **1500**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ismael Hernandez**
SCHOOL NAME: **Brooks College Prep (Southside College Prep)** INSPECTION DATE: **4/17/2013**
ADDRESS: **250 E. 111th St.** IDPH LICENSE NO: **100-19036**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **046(F20)**
MATERIAL DESCRIPTION: **9"x9" Green Floor Tile (ABATED)**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:


MATERIAL LOCATION: **Main Building: Gym, Cafeteria**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **04/17/2013**

Chicago Public Schools

GSG Consultants, Inc.

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47051** BUILDING ID: **1500**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**
SCHOOL NAME: **Brooks College Prep (Southside College Prep)** REVIEW DATE: **5/13/2013**
ADDRESS: **250 E. 111th St.** IDPH LICENSE NO: **100-19036**

HOMOGENEOUS AREA: **046(F20)**
MATERIAL DESCRIPTION: **9"x9" Green Floor Tile (ABATED)**
MATERIAL LOCATION: **Main Building: Gym, Cafeteria**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: 05/13/2013

Chicago Public Schools

GSG Consultants, Inc. 2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47051** BUIDLING ID: **1500**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ismael Hernandez**
SCHOOL NAME: **Brooks College Prep (Southside College Prep)** INSPECTION DATE: **4/17/2013**
ADDRESS: **250 E. 111th St.** IDPH LICENSE NO: **100-19036**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **047(F19)**
MATERIAL DESCRIPTION: **9"x9" Tan Floor Tile (ABATED)**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:


MATERIAL LOCATION: **Main Building: Gym, Cafeteria Building**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **04/17/2013**

Chicago Public Schools

GSG Consultants, Inc. 2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47051** BUILDING ID: **1500**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**
SCHOOL NAME: **Brooks College Prep
(Southside College
Prep)** REVIEW DATE: **5/13/2013**
ADDRESS: **250 E. 111th St.** IDPH LICENSE NO: **100-19036**

HOMOGENEOUS AREA: **047(F19)**
MATERIAL DESCRIPTION: **9"x9" Tan Floor Tile (ABATED)**
MATERIAL LOCATION: **Main Building: Gym, Cafeteria Building**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: 05/13/2013

Chicago Public Schools

GSG Consultants, Inc.
2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47051** BUIDLING ID: **1500**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ismael Hernandez**
SCHOOL NAME: **Brooks College Prep (Southside College Prep)** INSPECTION DATE: **4/17/2013**
ADDRESS: **250 E. 111th St.** IDPH LICENSE NO: **100-19036**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **049 (F5)**
MATERIAL DESCRIPTION: **9x9 tan floor tile (ABATED)**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:


MATERIAL LOCATION: **Main Building: guidance office,east wing room 29 & library**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **04/17/2013**

Chicago Public Schools

GSG Consultants, Inc.

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47051** BUIDLING ID: **1500**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**
SCHOOL NAME: **Brooks College Prep
(Southside College
Prep)** REVIEW DATE: **5/13/2013**
ADDRESS: **250 E. 111th St.** IDPH LICENSE NO: **100-19036**

HOMOGENEOUS AREA: **049 (F5)**

MATERIAL DESCRIPTION: **9x9 tan floor tile (ABATED)**

MATERIAL LOCATION: **Main Building: guidance office, east wing room 29 & library**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: 05/13/2013

Chicago Public Schools

GSG Consultants, Inc.
2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47051** BUIDLING ID: **1500**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ismael Hernandez**
SCHOOL NAME: **Brooks College Prep (Southside College Prep)** INSPECTION DATE: **4/17/2013**
ADDRESS: **250 E. 111th St.** IDPH LICENSE NO: **100-19036**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **051 (F12)**
MATERIAL DESCRIPTION: **9x9 green & white floor tile (ABATED)**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:


MATERIAL LOCATION: **Main Building: east wing 2nd & 3rd floor hallway & room 31**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **04/17/2013**

Chicago Public Schools

GSG Consultants, Inc. 2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47051** BUILDING ID: **1500**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**
SCHOOL NAME: **Brooks College Prep
(Southside College
Prep)** REVIEW DATE: **5/13/2013**
ADDRESS: **250 E. 111th St.** IDPH LICENSE NO: **100-19036**

HOMOGENEOUS AREA: **051 (F12)**
MATERIAL DESCRIPTION: **9x9 green & white floor tile (ABATED)**
MATERIAL LOCATION: **Main Building: east wing 2nd & 3rd floor hallway & room 31**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: 05/13/2013

Chicago Public Schools

GSG Consultants, Inc. 2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47051** BUIDLING ID: **1500**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ismael Hernandez**
SCHOOL NAME: **Brooks College Prep (Southside College Prep)** INSPECTION DATE: **4/17/2013**
ADDRESS: **250 E. 111th St.** IDPH LICENSE NO: **100-19036**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **052 (F17)**
MATERIAL DESCRIPTION: **9x9 green & tan floor tile (ABATED)**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:


MATERIAL LOCATION: **Annex: office & storage 156A & 156B**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **04/17/2013**

Chicago Public Schools

GSG Consultants, Inc.
2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47051** BUIDLING ID: **1500**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**
SCHOOL NAME: **Brooks College Prep
(Southside College
Prep)** REVIEW DATE: **5/13/2013**
ADDRESS: **250 E. 111th St.** IDPH LICENSE NO: **100-19036**

HOMOGENEOUS AREA: **052 (F17)**
MATERIAL DESCRIPTION: **9x9 green & tan floor tile (ABATED)**
MATERIAL LOCATION: **Annex: office & storage 156A & 156B**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: 05/13/2013

Chicago Public Schools

GSG Consultants, Inc. 2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47051** BUIDLING ID: **1500**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ismael Hernandez**
SCHOOL NAME: **Brooks College Prep (Southside College Prep)** INSPECTION DATE: **4/17/2013**
ADDRESS: **250 E. 111th St.** IDPH LICENSE NO: **100-19036**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **052 (F21)**
MATERIAL DESCRIPTION: **9x9 blue floor tile (ABATED)**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:


MATERIAL LOCATION: **Annex: room 151**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **04/17/2013**

Chicago Public Schools

GSG Consultants, Inc. 2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47051** BUIDLING ID: **1500**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**
SCHOOL NAME: **Brooks College Prep
(Southside College
Prep)** REVIEW DATE: **5/13/2013**
ADDRESS: **250 E. 111th St.** IDPH LICENSE NO: **100-19036**

HOMOGENEOUS AREA: **052 (F21)**
MATERIAL DESCRIPTION: **9x9 blue floor tile (ABATED)**
MATERIAL LOCATION: **Annex: room 151**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:  Date: **05/13/2013**

Chicago Public Schools

GSG Consultants, Inc.
2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47051** BUILDING ID: **1500**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ismael Hernandez**
SCHOOL NAME: **Brooks College Prep (Southside College Prep)** INSPECTION DATE: **4/17/2013**
ADDRESS: **250 E. 111th St.** IDPH LICENSE NO: **100-19036**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **052(F8)**
MATERIAL DESCRIPTION: **Blue and White Linoleum (ABATED)**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:


MATERIAL LOCATION: **Main Building: 2nd Floor Teachers' Lounge Kitchen**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **04/17/2013**

Chicago Public Schools

GSG Consultants, Inc.
2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47051** BUIDLING ID: **1500**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**
SCHOOL NAME: **Brooks College Prep
(Southside College
Prep)** REVIEW DATE: **5/13/2013**
ADDRESS: **250 E. 111th St.** IDPH LICENSE NO: **100-19036**

HOMOGENEOUS AREA: **052(F8)**
MATERIAL DESCRIPTION: **Blue and White Linoleum (ABATED)**
MATERIAL LOCATION: **Main Building: 2nd Floor Teachers' Lounge Kitchen**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: 05/13/2013

Chicago Public Schools

GSG Consultants, Inc.
2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47051** BUIDLING ID: **1500**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ismael Hernandez**
SCHOOL NAME: **Brooks College Prep (Southside College Prep)** INSPECTION DATE: **4/17/2013**
ADDRESS: **250 E. 111th St.** IDPH LICENSE NO: **100-19036**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **053 (F13)**
MATERIAL DESCRIPTION: **12x12 tan floor tile (ABATED)**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Annex: boys & girls toilets & corridors**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **04/17/2013**

Chicago Public Schools

GSG Consultants, Inc. 2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47051** BUILDING ID: **1500**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**
SCHOOL NAME: **Brooks College Prep
(Southside College
Prep)** REVIEW DATE: **5/13/2013**
ADDRESS: **250 E. 111th St.** IDPH LICENSE NO: **100-19036**

HOMOGENEOUS AREA: **053 (F13)**
MATERIAL DESCRIPTION: **12x12 tan floor tile (ABATED)**
MATERIAL LOCATION: **Annex: boys & girls toilets & corridors**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: 05/13/2013

Chicago Public Schools

GSG Consultants, Inc.
2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47051** BUIDLING ID: **1500**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ismael Hernandez**
SCHOOL NAME: **Brooks College Prep (Southside College Prep)** INSPECTION DATE: **4/17/2013**
ADDRESS: **250 E. 111th St.** IDPH LICENSE NO: **100-19036**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **054**
MATERIAL DESCRIPTION: **2x4 ceiling tile (ABATED)**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Annex: chemistry lab room 252**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **04/17/2013**

Chicago Public Schools

GSG Consultants, Inc.
2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47051** BUIDLING ID: **1500**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**
SCHOOL NAME: **Brooks College Prep
(Southside College
Prep)** REVIEW DATE: **5/13/2013**
ADDRESS: **250 E. 111th St.** IDPH LICENSE NO: **100-19036**

HOMOGENEOUS AREA: **054**
MATERIAL DESCRIPTION: **2x4 ceiling tile (ABATED)**
MATERIAL LOCATION: **Annex: chemistry lab room 252**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: 05/13/2013

Chicago Public Schools

GSG Consultants, Inc. 2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47051** BUIDLING ID: **1500**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ismael Hernandez**
SCHOOL NAME: **Brooks College Prep (Southside College Prep)** INSPECTION DATE: **4/17/2013**
ADDRESS: **250 E. 111th St.** IDPH LICENSE NO: **100-19036**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **055**
MATERIAL DESCRIPTION: **Aircell (ABATED)**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:


MATERIAL LOCATION: **Annex: chemistry lab**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **04/17/2013**

Chicago Public Schools

GSG Consultants, Inc. 2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47051** BUILDING ID: **1500**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**
SCHOOL NAME: **Brooks College Prep
(Southside College
Prep)** REVIEW DATE: **5/13/2013**
ADDRESS: **250 E. 111th St.** IDPH LICENSE NO: **100-19036**

HOMOGENEOUS AREA: **055**
MATERIAL DESCRIPTION: **Aircell (ABATED)**
MATERIAL LOCATION: **Annex: chemistry lab**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: 05/13/2013

Chicago Public Schools

GSG Consultants, Inc. 2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47051** BUIDLING ID: **1500**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ismael Hernandez**
SCHOOL NAME: **Brooks College Prep (Southside College Prep)** INSPECTION DATE: **4/17/2013**
ADDRESS: **250 E. 111th St.** IDPH LICENSE NO: **100-19036**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **059**
MATERIAL DESCRIPTION: **Trim mastic on on tan baseboard (ABATED)**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Annex: foyer/corridor**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **04/17/2013**

Chicago Public Schools

GSG Consultants, Inc. 2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47051** BUILDING ID: **1500**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**
SCHOOL NAME: **Brooks College Prep
(Southside College
Prep)** REVIEW DATE: **5/13/2013**
ADDRESS: **250 E. 111th St.** IDPH LICENSE NO: **100-19036**

HOMOGENEOUS AREA: **059**
MATERIAL DESCRIPTION: **Trim mastic on on tan baseboard (ABATED)**
MATERIAL LOCATION: **Annex: foyer/corridor**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: 05/13/2013

Chicago Public Schools

GSG Consultants, Inc. 2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47051** BUIDLING ID: **1500**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ismael Hernandez**
SCHOOL NAME: **Brooks College Prep (Southside College Prep)** INSPECTION DATE: **4/17/2013**
ADDRESS: **250 E. 111th St.** IDPH LICENSE NO: **100-19036**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **060**
MATERIAL DESCRIPTION: **Trim tan baseboard (ABATED)**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Annex: foyer/corridor**

MATERIAL QUANTITY:


MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **04/17/2013**

Chicago Public Schools

GSG Consultants, Inc.

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47051** BUILDING ID: **1500**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**
SCHOOL NAME: **Brooks College Prep
(Southside College
Prep)** REVIEW DATE: **5/13/2013**
ADDRESS: **250 E. 111th St.** IDPH LICENSE NO: **100-19036**

HOMOGENEOUS AREA: **060**
MATERIAL DESCRIPTION: **Trim tan baseboard (ABATED)**
MATERIAL LOCATION: **Annex: foyer/corridor**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: 05/13/2013

Chicago Public Schools

GSG Consultants, Inc.
2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47051** BUIDLING ID: **1500**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ismael Hernandez**
SCHOOL NAME: **Brooks College Prep (Southside College Prep)** INSPECTION DATE: **4/17/2013**
ADDRESS: **250 E. 111th St.** IDPH LICENSE NO: **100-19036**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **070 (F13)**
MATERIAL DESCRIPTION: **12x12 tan floor tile mastic (ABATED)**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:


MATERIAL LOCATION: **Annex: boys & girls toilets & corridors**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **04/17/2013**

Chicago Public Schools

GSG Consultants, Inc.

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47051** BUIDLING ID: **1500**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**
SCHOOL NAME: **Brooks College Prep
(Southside College
Prep)** REVIEW DATE: **5/13/2013**
ADDRESS: **250 E. 111th St.** IDPH LICENSE NO: **100-19036**

HOMOGENEOUS AREA: **070 (F13)**
MATERIAL DESCRIPTION: **12x12 tan floor tile mastic (ABATED)**
MATERIAL LOCATION: **Annex: boys & girls toilets & corridors**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: 05/13/2013

Chicago Public Schools

GSG Consultants, Inc. 2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47051** BUIDLING ID: **1500**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ismael Hernandez**
SCHOOL NAME: **Brooks College Prep (Southside College Prep)** INSPECTION DATE: **4/17/2013**
ADDRESS: **250 E. 111th St.** IDPH LICENSE NO: **100-19036**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **070 (F17)**
MATERIAL DESCRIPTION: **9x9 green floor tile mastic (ABATED)**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:


MATERIAL LOCATION: **Annex: room 151**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **04/17/2013**

Chicago Public Schools

GSG Consultants, Inc. 2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47051** BUILDING ID: **1500**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**
SCHOOL NAME: **Brooks College Prep
(Southside College
Prep)** REVIEW DATE: **5/13/2013**
ADDRESS: **250 E. 111th St.** IDPH LICENSE NO: **100-19036**

HOMOGENEOUS AREA: **070 (F17)**
MATERIAL DESCRIPTION: **9x9 green floor tile mastic (ABATED)**
MATERIAL LOCATION: **Annex: room 151**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: 05/13/2013

Chicago Public Schools

GSG Consultants, Inc.
2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47051** BUIDLING ID: **1500**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ismael Hernandez**
SCHOOL NAME: **Brooks College Prep (Southside College Prep)** INSPECTION DATE: **4/17/2013**
ADDRESS: **250 E. 111th St.** IDPH LICENSE NO: **100-19036**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **070 (F21)**
MATERIAL DESCRIPTION: **9x9 blue floor tile mastic (ABATED)**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Annex: room 151**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **04/17/2013**

Chicago Public Schools

GSG Consultants, Inc. 2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47051** BUIDLING ID: **1500**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**
SCHOOL NAME: **Brooks College Prep
(Southside College
Prep)** REVIEW DATE: **5/13/2013**
ADDRESS: **250 E. 111th St.** IDPH LICENSE NO: **100-19036**

HOMOGENEOUS AREA: **070 (F21)**
MATERIAL DESCRIPTION: **9x9 blue floor tile mastic (ABATED)**
MATERIAL LOCATION: **Annex: room 151**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:  Date: **05/13/2013**

Chicago Public Schools

GSG Consultants, Inc.
2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47051** BUIDLING ID: **1500**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ismael Hernandez**
SCHOOL NAME: **Brooks College Prep (Southside College Prep)** INSPECTION DATE: **4/17/2013**
ADDRESS: **250 E. 111th St.** IDPH LICENSE NO: **100-19036**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **072**
MATERIAL DESCRIPTION: **paneling mastic (ABATED)**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Annex: annex corridor**

MATERIAL QUANTITY:


MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **04/17/2013**

Chicago Public Schools

GSG Consultants, Inc. 2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47051** BUILDING ID: **1500**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**
SCHOOL NAME: **Brooks College Prep
(Southside College
Prep)** REVIEW DATE: **5/13/2013**
ADDRESS: **250 E. 111th St.** IDPH LICENSE NO: **100-19036**

HOMOGENEOUS AREA: **072**
MATERIAL DESCRIPTION: **paneling mastic (ABATED)**
MATERIAL LOCATION: **Annex: annex corridor**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: 05/13/2013

Chicago Public Schools

GSG Consultants, Inc. 2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47051** BUIDLING ID: **1500**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ismael Hernandez**
SCHOOL NAME: **Brooks College Prep (Southside College Prep)** INSPECTION DATE: **4/17/2013**
ADDRESS: **250 E. 111th St.** IDPH LICENSE NO: **100-19036**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **073 (C14)**
MATERIAL DESCRIPTION: **12x12 ceiling tile mastic (ABATED)**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Annex: rooms 155 A-D**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **04/17/2013**

Chicago Public Schools

GSG Consultants, Inc. 2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47051** BUIDLING ID: **1500**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**
SCHOOL NAME: **Brooks College Prep
(Southside College
Prep)** REVIEW DATE: **5/13/2013**
ADDRESS: **250 E. 111th St.** IDPH LICENSE NO: **100-19036**

HOMOGENEOUS AREA: **073 (C14)**
MATERIAL DESCRIPTION: **12x12 ceiling tile mastic (ABATED)**
MATERIAL LOCATION: **Annex: rooms 155 A-D**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: 05/13/2013

Chicago Public Schools

GSG Consultants, Inc.
2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47051** BUIDLING ID: **1500**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ismael Hernandez**
SCHOOL NAME: **Brooks College Prep (Southside College Prep)** INSPECTION DATE: **4/17/2013**
ADDRESS: **250 E. 111th St.** IDPH LICENSE NO: **100-19036**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **078**
MATERIAL DESCRIPTION: **Aircell pipe insulation**
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Monastery: Crawl space tunnels, connecting tunnel from main bldg**
MATERIAL QUANTITY: **3000** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: DAMAGE UNITS: **LF**
COMMENTS:

Inspector's Signature: _____



Date: 04/17/2013

Chicago Public Schools

GSG Consultants, Inc.
2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47051** BUILDING ID: **1500**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**
SCHOOL NAME: **Brooks College Prep
(Southside College
Prep)** REVIEW DATE: **5/13/2013**
ADDRESS: **250 E. 111th St.** IDPH LICENSE NO: **100-19036**

HOMOGENEOUS AREA: **078**
MATERIAL DESCRIPTION: **Aircell pipe insulation**
MATERIAL LOCATION: **Monastery: Crawl space tunnels, connecting tunnel from main bldg**
MATERIAL QUANTITY: **3000** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **05/13/2013**

Chicago Public Schools

GSG Consultants, Inc.
2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47051** BUIDLING ID: **1500**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ismael Hernandez**
SCHOOL NAME: **Brooks College Prep (Southside College Prep)** INSPECTION DATE: **4/17/2013**
ADDRESS: **250 E. 111th St.** IDPH LICENSE NO: **100-19036**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **079**
MATERIAL DESCRIPTION: **Hard fittings on aircell pipe insulation**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Monastery: Crawl space tunnels, connecting tunnel from main bldg**
MATERIAL QUANTITY: **200** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: DAMAGE UNITS: **LF**
COMMENTS:

Inspector's Signature: _____



Date: 04/17/2013

Chicago Public Schools

GSG Consultants, Inc.

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47051** BUILDING ID: **1500**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**
SCHOOL NAME: **Brooks College Prep
(Southside College
Prep)** REVIEW DATE: **5/13/2013**
ADDRESS: **250 E. 111th St.** IDPH LICENSE NO: **100-19036**

HOMOGENEOUS AREA: **079**
MATERIAL DESCRIPTION: **Hard fittings on aircell pipe insulation**
MATERIAL LOCATION: **Monastery: Crawl space tunnels, connecting tunnel from main bldg**
MATERIAL QUANTITY: **200** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **05/13/2013**

Chicago Public Schools

GSG Consultants, Inc.
2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 47051 BUIDLING ID: 1500
CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Ismael Hernandez
SCHOOL NAME: Brooks College Prep (Southside College Prep) INSPECTION DATE: 4/17/2013
ADDRESS: 250 E. 111th St. IDPH LICENSE NO: 100-19036

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 080 (F25)
MATERIAL DESCRIPTION: 12x12 black floor tile not observed
HISTORICAL AHERA DAMAGE CATEGORY 6
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: Assumed FRIABLE: No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Monastery: 2nd floor fireplace**

MATERIAL QUANTITY:


MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 04/17/2013

Chicago Public Schools

GSG Consultants, Inc. 2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47051** BUIDLING ID: **1500**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**
SCHOOL NAME: **Brooks College Prep
(Southside College
Prep)** REVIEW DATE: **5/13/2013**
ADDRESS: **250 E. 111th St.** IDPH LICENSE NO: **100-19036**

HOMOGENEOUS AREA: **080 (F25)**
MATERIAL DESCRIPTION: **12x12 black floor tile not observed**
MATERIAL LOCATION: **Monastery: 2nd floor fireplace**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: **0** DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **05/13/2013**

Chicago Public Schools

GSG Consultants, Inc.
2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47051** BUIDLING ID: **1500**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ismael Hernandez**
SCHOOL NAME: **Brooks College Prep (Southside College Prep)** INSPECTION DATE: **4/17/2013**
ADDRESS: **250 E. 111th St.** IDPH LICENSE NO: **100-19036**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **080 (F26)**
MATERIAL DESCRIPTION: **12x12 red floor tile not observed**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **Low**

MATERIAL LOCATION: **Monastery: 1st,2nd,3rd floor stairways**

MATERIAL QUANTITY: **260**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 04/17/2013

Chicago Public Schools

GSG Consultants, Inc. 2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47051** BUILDING ID: **1500**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**
SCHOOL NAME: **Brooks College Prep
(Southside College
Prep)** REVIEW DATE: **5/13/2013**
ADDRESS: **250 E. 111th St.** IDPH LICENSE NO: **100-19036**

HOMOGENEOUS AREA: **080 (F26)**
MATERIAL DESCRIPTION: **12x12 red floor tile not observed**
MATERIAL LOCATION: **Monastery: 1st,2nd,3rd floor stairways**
MATERIAL QUANTITY: **260** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **05/13/2013**

Chicago Public Schools

GSG Consultants, Inc.
2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 47051 BUIDLING ID: 1500
CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Ismael Hernandez
SCHOOL NAME: Brooks College Prep (Southside College Prep) INSPECTION DATE: 4/17/2013
ADDRESS: 250 E. 111th St. IDPH LICENSE NO: 100-19036

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 080 (F27)
MATERIAL DESCRIPTION: 12x12 orange/brown floor tile NOT OBSERVED
HISTORICAL AHERA DAMAGE CATEGORY 6
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: Assumed FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Monastery: 2nd & 3rd floor monastery**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 04/17/2013

Chicago Public Schools

GSG Consultants, Inc. 2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47051** BUIDLING ID: **1500**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**
SCHOOL NAME: **Brooks College Prep
(Southside College
Prep)** REVIEW DATE: **5/13/2013**
ADDRESS: **250 E. 111th St.** IDPH LICENSE NO: **100-19036**

HOMOGENEOUS AREA: **080 (F27)**
MATERIAL DESCRIPTION: **12x12 orange/brown floor tile NOT OBSERVED**
MATERIAL LOCATION: **Monastery: 2nd & 3rd floor monastery**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: **0** DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **05/13/2013**

Chicago Public Schools

GSG Consultants, Inc.
2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 47051 BUILDING ID: 1500
CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Ismael Hernandez
SCHOOL NAME: Brooks College Prep (Southside College Prep) INSPECTION DATE: 4/17/2013
ADDRESS: 250 E. 111th St. IDPH LICENSE NO: 100-19036

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 081 (F25)
MATERIAL DESCRIPTION: 12x12 black floor tile mastic NOT OBSERVED
HISTORICAL AHERA DAMAGE CATEGORY 6
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: Assumed FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Monastery: 2nd floor fireplace**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:  Date: 04/17/2013

Chicago Public Schools

GSG Consultants, Inc.

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47051** BUILDING ID: **1500**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**
SCHOOL NAME: **Brooks College Prep (Southside College Prep)** REVIEW DATE: **5/13/2013**
ADDRESS: **250 E. 111th St.** IDPH LICENSE NO: **100-19036**

HOMOGENEOUS AREA: **081 (F25)**
MATERIAL DESCRIPTION: **12x12 black floor tile mastic NOT OBSERVED**
MATERIAL LOCATION: **Monastery: 2nd floor fireplace**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: **0** DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **05/13/2013**

Chicago Public Schools

GSG Consultants, Inc.
2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47051** BUIDLING ID: **1500**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ismael Hernandez**
SCHOOL NAME: **Brooks College Prep (Southside College Prep)** INSPECTION DATE: **4/17/2013**
ADDRESS: **250 E. 111th St.** IDPH LICENSE NO: **100-19036**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **081 (F26)**
MATERIAL DESCRIPTION: **12x12 red floor tile mastic NOT OBSERVED**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Monastery: 1st,2nd,3rd floor stairways**

MATERIAL QUANTITY: **260**


MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 04/17/2013

Chicago Public Schools

GSG Consultants, Inc. 2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47051** BUIDLING ID: **1500**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**
SCHOOL NAME: **Brooks College Prep
(Southside College
Prep)** REVIEW DATE: **5/13/2013**
ADDRESS: **250 E. 111th St.** IDPH LICENSE NO: **100-19036**

HOMOGENEOUS AREA: **081 (F26)**
MATERIAL DESCRIPTION: **12x12 red floor tile mastic NOT OBSERVED**
MATERIAL LOCATION: **Monastery: 1st,2nd,3rd floor stairways**
MATERIAL QUANTITY: **260** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **05/13/2013**

Chicago Public Schools

GSG Consultants, Inc.
2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 47051 BUIDLING ID: 1500
CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Ismael Hernandez
SCHOOL NAME: Brooks College Prep (Southside College Prep) INSPECTION DATE: 4/17/2013
ADDRESS: 250 E. 111th St. IDPH LICENSE NO: 100-19036

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 081 (F27)
MATERIAL DESCRIPTION: 12x12 orange/brown floor tile mastic NOT OBSERVED
HISTORICAL AHERA DAMAGE CATEGORY 6
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: Assumed FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Monastery: 2nd & 3rd floor monastery**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 04/17/2013

Chicago Public Schools

GSG Consultants, Inc. 2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47051** BUIDLING ID: **1500**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**
SCHOOL NAME: **Brooks College Prep
(Southside College
Prep)** REVIEW DATE: **5/13/2013**
ADDRESS: **250 E. 111th St.** IDPH LICENSE NO: **100-19036**

HOMOGENEOUS AREA: **081 (F27)**
MATERIAL DESCRIPTION: **12x12 orange/brown floor tile mastic NOT OBSERVED**
MATERIAL LOCATION: **Monastery: 2nd & 3rd floor monastery**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: **0** DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **05/13/2013**

Chicago Public Schools

GSG Consultants, Inc. 2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47051** BUIDLING ID: **1500**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ismael Hernandez**
SCHOOL NAME: **Brooks College Prep (Southside College Prep)** INSPECTION DATE: **4/17/2013**
ADDRESS: **250 E. 111th St.** IDPH LICENSE NO: **100-19036**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **082 (F31)**
MATERIAL DESCRIPTION: **brown vinyl baseboard**
HISTORICAL AHERA DAMAGE CATEGORY **6**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Monastery: 2nd floor community room, monastery**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____



Date: 04/17/2013

Chicago Public Schools

GSG Consultants, Inc.

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47051** BUILDING ID: **1500**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**
SCHOOL NAME: **Brooks College Prep (Southside College Prep)** REVIEW DATE: **5/13/2013**
ADDRESS: **250 E. 111th St.** IDPH LICENSE NO: **100-19036**

HOMOGENEOUS AREA: **082 (F31)**
MATERIAL DESCRIPTION: **brown vinyl baseboard**
MATERIAL LOCATION: **Monastery: 2nd floor community room, monastery**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: **0** DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: 05/13/2013

Chicago Public Schools

GSG Consultants, Inc.
2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47051** BUIDLING ID: **1500**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ismael Hernandez**
SCHOOL NAME: **Brooks College Prep (Southside College Prep)** INSPECTION DATE: **4/17/2013**
ADDRESS: **250 E. 111th St.** IDPH LICENSE NO: **100-19036**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **082(F32)**
MATERIAL DESCRIPTION: **black vinyl baseboard**
HISTORICAL AHERA DAMAGE CATEGORY **6**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**


MATERIAL LOCATION: **Monastery: 1st,2nd,3rd floor stairwells,315**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____



Date: 04/17/2013

Chicago Public Schools

GSG Consultants, Inc. 2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47051** BUIDLING ID: **1500**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**
SCHOOL NAME: **Brooks College Prep
(Southside College
Prep)** REVIEW DATE: **5/13/2013**
ADDRESS: **250 E. 111th St.** IDPH LICENSE NO: **100-19036**

HOMOGENEOUS AREA: **082(F32)**
MATERIAL DESCRIPTION: **black vinyl baseboard**
MATERIAL LOCATION: **Monastery: 1st,2nd,3rd floor stairwells,315**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: **0** DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **05/13/2013**

Chicago Public Schools

GSG Consultants, Inc.
2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 47051 BUIDLING ID: 1500
CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Ismael Hernandez
SCHOOL NAME: Brooks College Prep (Southside College Prep) INSPECTION DATE: 4/17/2013
ADDRESS: 250 E. 111th St. IDPH LICENSE NO: 100-19036

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 082(F33)
MATERIAL DESCRIPTION: wood grain baseboard mastic not observed
HISTORICAL AHERA DAMAGE CATEGORY 6
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: Assumed FRIABLE: No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**


MATERIAL LOCATION: **Monastery: room 210**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 04/17/2013

Chicago Public Schools

GSG Consultants, Inc. 2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47051** BUILDING ID: **1500**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**
SCHOOL NAME: **Brooks College Prep
(Southside College
Prep)** REVIEW DATE: **5/13/2013**
ADDRESS: **250 E. 111th St.** IDPH LICENSE NO: **100-19036**

HOMOGENEOUS AREA: **082(F33)**
MATERIAL DESCRIPTION: **wood grain baseboard mastic not observed**
MATERIAL LOCATION: **Monastery: room 210**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: **0** DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: 05/13/2013

Chicago Public Schools

GSG Consultants, Inc.

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47051** BUIDLING ID: **1500**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ismael Hernandez**
SCHOOL NAME: **Brooks College Prep (Southside College Prep)** INSPECTION DATE: **4/17/2013**
ADDRESS: **250 E. 111th St.** IDPH LICENSE NO: **100-19036**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **083 (F31)**
MATERIAL DESCRIPTION: **mastic under baseboard**
HISTORICAL AHERA DAMAGE CATEGORY **6**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Monastery: 2nd floor community room, monastery**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____



Date: 04/17/2013

Chicago Public Schools

GSG Consultants, Inc. 2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47051** BUIDLING ID: **1500**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**
SCHOOL NAME: **Brooks College Prep
(Southside College
Prep)** REVIEW DATE: **5/13/2013**
ADDRESS: **250 E. 111th St.** IDPH LICENSE NO: **100-19036**

HOMOGENEOUS AREA: **083 (F31)**
MATERIAL DESCRIPTION: **mastic under baseboard**
MATERIAL LOCATION: **Monastery: 2nd floor community room, monastery**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: **0** DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **05/13/2013**

Chicago Public Schools

GSG Consultants, Inc.
2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 47051 BUILDING ID: 1500
CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Ismael Hernandez
SCHOOL NAME: Brooks College Prep (Southside College Prep) INSPECTION DATE: 4/17/2013
ADDRESS: 250 E. 111th St. IDPH LICENSE NO: 100-19036

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 083 (F33)
MATERIAL DESCRIPTION: wood grain baseboard not observed
HISTORICAL AHERA DAMAGE CATEGORY 6
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: Assumed FRIABLE: No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:


MATERIAL LOCATION: Monastery: room 210

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 04/17/2013

Chicago Public Schools

GSG Consultants, Inc. 2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47051** BUILDING ID: **1500**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**
SCHOOL NAME: **Brooks College Prep
(Southside College
Prep)** REVIEW DATE: **5/13/2013**
ADDRESS: **250 E. 111th St.** IDPH LICENSE NO: **100-19036**

HOMOGENEOUS AREA: **083 (F33)**
MATERIAL DESCRIPTION: **wood grain baseboard not observed**
MATERIAL LOCATION: **Monastery: room 210**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: **0** DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **05/13/2013**

Chicago Public Schools

GSG Consultants, Inc.
2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 47051 BUIDLING ID: 1500
CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Ismael Hernandez
SCHOOL NAME: Brooks College Prep (Southside College Prep) INSPECTION DATE: 4/17/2013
ADDRESS: 250 E. 111th St. IDPH LICENSE NO: 100-19036

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 083(F32)
MATERIAL DESCRIPTION: black vinyl baseboard mastic not observed
HISTORICAL AHERA DAMAGE CATEGORY 6
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: Assumed FRIABLE: No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Monastery: 1st,2nd,3rd floor stairwells,315

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 04/17/2013

Chicago Public Schools

GSG Consultants, Inc.

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47051** BUIDLING ID: **1500**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**
SCHOOL NAME: **Brooks College Prep (Southside College Prep)** REVIEW DATE: **5/13/2013**
ADDRESS: **250 E. 111th St.** IDPH LICENSE NO: **100-19036**

HOMOGENEOUS AREA: **083(F32)**
MATERIAL DESCRIPTION: **black vinyl baseboard mastic not observed**
MATERIAL LOCATION: **Monastery: 1st,2nd,3rd floor stairwells,315**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: **0** DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **05/13/2013**

Chicago Public Schools

GSG Consultants, Inc.
2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 47051 BUIDLING ID: 1500
CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Ismael Hernandez
SCHOOL NAME: Brooks College Prep (Southside College Prep) INSPECTION DATE: 4/17/2013
ADDRESS: 250 E. 111th St. IDPH LICENSE NO: 100-19036

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 084 (CM 45)
MATERIAL DESCRIPTION: orange carpet mastic not observed
HISTORICAL AHERA DAMAGE CATEGORY 6
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: Assumed FRIABLE: No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Monastery: 2nd floor corridor room 204 & 210**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 04/17/2013

Chicago Public Schools

GSG Consultants, Inc. 2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47051** BUIDLING ID: **1500**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**
SCHOOL NAME: **Brooks College Prep
(Southside College
Prep)** REVIEW DATE: **5/13/2013**
ADDRESS: **250 E. 111th St.** IDPH LICENSE NO: **100-19036**

HOMOGENEOUS AREA: **084 (CM 45)**
MATERIAL DESCRIPTION: **orange carpet mastic not observed**
MATERIAL LOCATION: **Monastery: 2nd floor corridor room 204 & 210**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: **0** DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **05/13/2013**

Chicago Public Schools

GSG Consultants, Inc.
2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 47051 BUIDLING ID: 1500
CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Ismael Hernandez
SCHOOL NAME: Brooks College Prep (Southside College Prep) INSPECTION DATE: 4/17/2013
ADDRESS: 250 E. 111th St. IDPH LICENSE NO: 100-19036

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 084 (CM53)
MATERIAL DESCRIPTION: brown tweed carpet mastic not observed
HISTORICAL AHERA DAMAGE CATEGORY 6
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: Assumed FRIABLE: No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Monastery: room 306

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 04/17/2013

Chicago Public Schools

GSG Consultants, Inc. 2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47051** BUIDLING ID: **1500**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**
SCHOOL NAME: **Brooks College Prep
(Southside College
Prep)** REVIEW DATE: **5/13/2013**
ADDRESS: **250 E. 111th St.** IDPH LICENSE NO: **100-19036**

HOMOGENEOUS AREA: **084 (CM53)**
MATERIAL DESCRIPTION: **brown tweed carpet mastic not observed**
MATERIAL LOCATION: **Monastery: room 306**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: **0** DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **05/13/2013**

Chicago Public Schools

GSG Consultants, Inc.
2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 47051 BUILDING ID: 1500
CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Ismael Hernandez
SCHOOL NAME: Brooks College Prep (Southside College Prep) INSPECTION DATE: 4/17/2013
ADDRESS: 250 E. 111th St. IDPH LICENSE NO: 100-19036

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 084(42)
MATERIAL DESCRIPTION: orange/brown carpet mastic not observed
HISTORICAL AHERA DAMAGE CATEGORY 6
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: Assumed FRIABLE: No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Monastery: 1st floor NW corner**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 04/17/2013

Chicago Public Schools

GSG Consultants, Inc. 2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47051** BUIDLING ID: **1500**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**
SCHOOL NAME: **Brooks College Prep
(Southside College
Prep)** REVIEW DATE: **5/13/2013**
ADDRESS: **250 E. 111th St.** IDPH LICENSE NO: **100-19036**

HOMOGENEOUS AREA: **084(42)**
MATERIAL DESCRIPTION: **orange/brown carpet mastic not observed**
MATERIAL LOCATION: **Monastery: 1st floor NW corner**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: **0** DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: 05/13/2013

Chicago Public Schools

GSG Consultants, Inc.
2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47051** BUIDLING ID: **1500**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ismael Hernandez**
SCHOOL NAME: **Brooks College Prep (Southside College Prep)** INSPECTION DATE: **4/17/2013**
ADDRESS: **250 E. 111th St.** IDPH LICENSE NO: **100-19036**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **084(43)**
MATERIAL DESCRIPTION: **rust carpet mastic not observed**
HISTORICAL AHERA DAMAGE CATEGORY **6**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**


MATERIAL LOCATION: **Monastery: 1st floor NW corridor**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **04/17/2013**

Chicago Public Schools

GSG Consultants, Inc. 2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47051** BUIDLING ID: **1500**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**
SCHOOL NAME: **Brooks College Prep
(Southside College
Prep)** REVIEW DATE: **5/13/2013**
ADDRESS: **250 E. 111th St.** IDPH LICENSE NO: **100-19036**

HOMOGENEOUS AREA: **084(43)**
MATERIAL DESCRIPTION: **rust carpet mastic not observed**
MATERIAL LOCATION: **Monastery: 1st floor NW corridor**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: **0** DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **05/13/2013**

Chicago Public Schools

GSG Consultants, Inc. 2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47051** BUIDLING ID: **1500**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ismael Hernandez**
SCHOOL NAME: **Brooks College Prep (Southside College Prep)** INSPECTION DATE: **4/17/2013**
ADDRESS: **250 E. 111th St.** IDPH LICENSE NO: **100-19036**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **084(CM41)**
MATERIAL DESCRIPTION: **brown/tweed carpet mastic not observed**
HISTORICAL AHERA DAMAGE CATEGORY **6**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Monastery: 1st floor NW Corridor**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **04/17/2013**

Chicago Public Schools

GSG Consultants, Inc. 2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47051** BUIDLING ID: **1500**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**
SCHOOL NAME: **Brooks College Prep
(Southside College
Prep)** REVIEW DATE: **5/13/2013**
ADDRESS: **250 E. 111th St.** IDPH LICENSE NO: **100-19036**

HOMOGENEOUS AREA: **084(CM41)**
MATERIAL DESCRIPTION: **brown/tweed carpet mastic not observed**
MATERIAL LOCATION: **Monastery: 1st floor NW Corridor**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: **0** DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **05/13/2013**

Chicago Public Schools

GSG Consultants, Inc.
2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47051** BUIDLING ID: **1500**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ismael Hernandez**
SCHOOL NAME: **Brooks College Prep (Southside College Prep)** INSPECTION DATE: **4/17/2013**
ADDRESS: **250 E. 111th St.** IDPH LICENSE NO: **100-19036**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **085(F28)**
MATERIAL DESCRIPTION: **9x9 red/black border floor tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Monastery: stairwells 1st, 2nd, 3rd floor**

MATERIAL QUANTITY: **600**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 04/17/2013

Chicago Public Schools

GSG Consultants, Inc.

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47051** BUIDLING ID: **1500**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**
SCHOOL NAME: **Brooks College Prep
(Southside College
Prep)** REVIEW DATE: **5/13/2013**
ADDRESS: **250 E. 111th St.** IDPH LICENSE NO: **100-19036**

HOMOGENEOUS AREA: **085(F28)**
MATERIAL DESCRIPTION: **9x9 red/black border floor tile**
MATERIAL LOCATION: **Monastery: stairwells 1st, 2nd, 3rd floor**
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **05/13/2013**

Chicago Public Schools

GSG Consultants, Inc.
2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47051** BUIDLING ID: **1500**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ismael Hernandez**
SCHOOL NAME: **Brooks College Prep (Southside College Prep)** INSPECTION DATE: **4/17/2013**
ADDRESS: **250 E. 111th St.** IDPH LICENSE NO: **100-19036**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **085(F29)**
MATERIAL DESCRIPTION: **9x9 grey/red trim floor tile NOT OBSERVED**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Monastery:1st floor monastery**

MATERIAL QUANTITY: **350**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **04/17/2013**

Chicago Public Schools

GSG Consultants, Inc.

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47051** BUIDLING ID: **1500**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**
SCHOOL NAME: **Brooks College Prep
(Southside College
Prep)** REVIEW DATE: **5/13/2013**
ADDRESS: **250 E. 111th St.** IDPH LICENSE NO: **100-19036**

HOMOGENEOUS AREA: **085(F29)**
MATERIAL DESCRIPTION: **9x9 grey/red trim floor tile NOT OBSERVED**
MATERIAL LOCATION: **Monastery:1st floor monastery**
MATERIAL QUANTITY: **350** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **05/13/2013**

Chicago Public Schools

GSG Consultants, Inc.
2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47051** BUIDLING ID: **1500**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ismael Hernandez**
SCHOOL NAME: **Brooks College Prep (Southside College Prep)** INSPECTION DATE: **4/17/2013**
ADDRESS: **250 E. 111th St.** IDPH LICENSE NO: **100-19036**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **086(F28)**
MATERIAL DESCRIPTION: **9x9 red/black border floor tile mastic not observed**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Monastery: stairwells 1st, 2nd, 3rd floor**

MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 04/17/2013

Chicago Public Schools

GSG Consultants, Inc. 2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47051** BUIDLING ID: **1500**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**
SCHOOL NAME: **Brooks College Prep
(Southside College
Prep)** REVIEW DATE: **5/13/2013**
ADDRESS: **250 E. 111th St.** IDPH LICENSE NO: **100-19036**

HOMOGENEOUS AREA: **086(F28)**
MATERIAL DESCRIPTION: **9x9 red/black border floor tile mastic not observed**
MATERIAL LOCATION: **Monastery: stairwells 1st, 2nd, 3rd floor**
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **05/13/2013**

Chicago Public Schools

GSG Consultants, Inc.
2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47051** BUIDLING ID: **1500**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ismael Hernandez**
SCHOOL NAME: **Brooks College Prep (Southside College Prep)** INSPECTION DATE: **4/17/2013**
ADDRESS: **250 E. 111th St.** IDPH LICENSE NO: **100-19036**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **086(F29)**
MATERIAL DESCRIPTION: **9x9 grey/red trim floor tile mastic not observed**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **Low**

MATERIAL LOCATION: **Monastery:1st floor monastery**

MATERIAL QUANTITY: **10**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **04/17/2013**

Chicago Public Schools

GSG Consultants, Inc.
2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47051** BUILDING ID: **1500**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**
SCHOOL NAME: **Brooks College Prep
(Southside College
Prep)** REVIEW DATE: **5/13/2013**
ADDRESS: **250 E. 111th St.** IDPH LICENSE NO: **100-19036**

HOMOGENEOUS AREA: **086(F29)**
MATERIAL DESCRIPTION: **9x9 grey/red trim floor tile mastic not observed**
MATERIAL LOCATION: **Monastery:1st floor monastery**
MATERIAL QUANTITY: **10** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **05/13/2013**

Chicago Public Schools

GSG Consultants, Inc.
2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47051** BUIDLING ID: **1500**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ismael Hernandez**
SCHOOL NAME: **Brooks College Prep (Southside College Prep)** INSPECTION DATE: **4/17/2013**
ADDRESS: **250 E. 111th St.** IDPH LICENSE NO: **100-19036**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **087**
MATERIAL DESCRIPTION: **12x12 Ceiling Tile- Not Observed**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Monastery: 2nd,3rd floor**

MATERIAL QUANTITY:


MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **04/17/2013**

Chicago Public Schools

GSG Consultants, Inc.

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47051** BUILDING ID: **1500**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**
SCHOOL NAME: **Brooks College Prep (Southside College Prep)** REVIEW DATE: **5/13/2013**
ADDRESS: **250 E. 111th St.** IDPH LICENSE NO: **100-19036**

HOMOGENEOUS AREA: **087**
MATERIAL DESCRIPTION: **12x12 Ceiling Tile- Not Observed**
MATERIAL LOCATION: **Monastery: 2nd,3rd floor**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: 05/13/2013

Chicago Public Schools

GSG Consultants, Inc.
2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47051** BUIDLING ID: **1500**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ismael Hernandez**
SCHOOL NAME: **Brooks College Prep (Southside College Prep)** INSPECTION DATE: **4/17/2013**
ADDRESS: **250 E. 111th St.** IDPH LICENSE NO: **100-19036**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **088**
MATERIAL DESCRIPTION: **12x12 Ceiling Tile Mastic Not Observed**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Monastery: 2nd 3rd floor**

MATERIAL QUANTITY:


MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **04/17/2013**

Chicago Public Schools

GSG Consultants, Inc.

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47051** BUILDING ID: **1500**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**
SCHOOL NAME: **Brooks College Prep (Southside College Prep)** REVIEW DATE: **5/13/2013**
ADDRESS: **250 E. 111th St.** IDPH LICENSE NO: **100-19036**

HOMOGENEOUS AREA: **088**
MATERIAL DESCRIPTION: **12x12 Ceiling Tile Mastic Not Observed**
MATERIAL LOCATION: **Monastery: 2nd 3rd floor**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: 05/13/2013

Chicago Public Schools

GSG Consultants, Inc.
2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47051** BUIDLING ID: **1500**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ismael Hernandez**
SCHOOL NAME: **Brooks College Prep (Southside College Prep)** INSPECTION DATE: **4/17/2013**
ADDRESS: **250 E. 111th St.** IDPH LICENSE NO: **100-19036**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **089**
MATERIAL DESCRIPTION: **Plaster Not Observed**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:


MATERIAL LOCATION: **Monastery: throughout 1st,2nd ,3rd floors**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **04/17/2013**

Chicago Public Schools

GSG Consultants, Inc.
2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47051** BUILDING ID: **1500**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**
SCHOOL NAME: **Brooks College Prep (Southside College Prep)** REVIEW DATE: **5/13/2013**
ADDRESS: **250 E. 111th St.** IDPH LICENSE NO: **100-19036**

HOMOGENEOUS AREA: **089**
MATERIAL DESCRIPTION: **Plaster Not Observed**
MATERIAL LOCATION: **Monastery: throughout 1st,2nd ,3rd floors**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: 05/13/2013

Chicago Public Schools

GSG Consultants, Inc. 2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47051** BUIDLING ID: **1500**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ismael Hernandez**
SCHOOL NAME: **Brooks College Prep (Southside College Prep)** INSPECTION DATE: **4/17/2013**
ADDRESS: **250 E. 111th St.** IDPH LICENSE NO: **100-19036**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **090 (F23)**
MATERIAL DESCRIPTION: **12x12 white floor tile mastic (BLDG DEMOLISHED)**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Chrysotile** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Annex: physics lab**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **04/17/2013**

Chicago Public Schools

GSG Consultants, Inc.
2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47051** BUIDLING ID: **1500**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**
SCHOOL NAME: **Brooks College Prep
(Southside College
Prep)** REVIEW DATE: **5/13/2013**
ADDRESS: **250 E. 111th St.** IDPH LICENSE NO: **100-19036**

HOMOGENEOUS AREA: **090 (F23)**
MATERIAL DESCRIPTION: **12x12 white floor tile mastic (BLDG DEMOLISHED)**
MATERIAL LOCATION: **Annex: physics lab**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: 05/13/2013

Chicago Public Schools

GSG Consultants, Inc.
2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47051** BUIDLING ID: **1500**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ismael Hernandez**
SCHOOL NAME: **Brooks College Prep (Southside College Prep)** INSPECTION DATE: **4/17/2013**
ADDRESS: **250 E. 111th St.** IDPH LICENSE NO: **100-19036**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **090M(F23)**
MATERIAL DESCRIPTION: **12x12 white floor tile (BLDG DEMOLISHED)**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Annex: physics lab**

MATERIAL QUANTITY:


MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **04/17/2013**

Chicago Public Schools

GSG Consultants, Inc. 2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47051** BUILDING ID: **1500**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**
SCHOOL NAME: **Brooks College Prep
(Southside College
Prep)** REVIEW DATE: **5/13/2013**
ADDRESS: **250 E. 111th St.** IDPH LICENSE NO: **100-19036**

HOMOGENEOUS AREA: **090M(F23)**
MATERIAL DESCRIPTION: **12x12 white floor tile (BLDG DEMOLISHED)**
MATERIAL LOCATION: **Annex: physics lab**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: 05/13/2013

Chicago Public Schools

GSG Consultants, Inc.
2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 47051 BUILDING ID: 1500
CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Ismael Hernandez
SCHOOL NAME: Brooks College Prep (Southside College Prep) INSPECTION DATE: 4/17/2013
ADDRESS: 250 E. 111th St. IDPH LICENSE NO: 100-19036

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 091
MATERIAL DESCRIPTION: 12x12 off white floor tile
HISTORICAL AHERA DAMAGE CATEGORY 6
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: Assumed FRIABLE: No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Gym**

MATERIAL QUANTITY:


MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 04/17/2013

Chicago Public Schools

GSG Consultants, Inc.

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47051** BUILDING ID: **1500**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**
SCHOOL NAME: **Brooks College Prep
(Southside College
Prep)** REVIEW DATE: **5/13/2013**
ADDRESS: **250 E. 111th St.** IDPH LICENSE NO: **100-19036**

HOMOGENEOUS AREA: **091**
MATERIAL DESCRIPTION: **12x12 off white floor tile**
MATERIAL LOCATION: **Gym**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: **0** DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **05/13/2013**

Chicago Public Schools

GSG Consultants, Inc.
2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 47051 BUILDING ID: 1500
CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Ismael Hernandez
SCHOOL NAME: Brooks College Prep (Southside College Prep) INSPECTION DATE: 4/17/2013
ADDRESS: 250 E. 111th St. IDPH LICENSE NO: 100-19036

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 092
MATERIAL DESCRIPTION: 12x12 Off White Floor tile Mastic
HISTORICAL AHERA DAMAGE CATEGORY 6
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: Assumed FRIABLE: No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Gym**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 04/17/2013

Chicago Public Schools

GSG Consultants, Inc. 2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47051** BUILDING ID: **1500**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**
SCHOOL NAME: **Brooks College Prep
(Southside College
Prep)** REVIEW DATE: **5/13/2013**
ADDRESS: **250 E. 111th St.** IDPH LICENSE NO: **100-19036**

HOMOGENEOUS AREA: **092**
MATERIAL DESCRIPTION: **12x12 Off White Floor tile Mastic**
MATERIAL LOCATION: **Gym**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: **0** DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **05/13/2013**

Chicago Public Schools

GSG Consultants, Inc. 2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47051** BUIDLING ID: **1500**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ismael Hernandez**
SCHOOL NAME: **Brooks College Prep (Southside College Prep)** INSPECTION DATE: **4/17/2013**
ADDRESS: **250 E. 111th St.** IDPH LICENSE NO: **100-19036**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **093**
MATERIAL DESCRIPTION: **Aircell pipe insulation (NOT OBSERVED)**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Chrysotile** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Gym: Throughout bldg, locker rooms, showers**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **04/17/2013**

Chicago Public Schools

GSG Consultants, Inc. 2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47051** BUILDING ID: **1500**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**
SCHOOL NAME: **Brooks College Prep
(Southside College
Prep)** REVIEW DATE: **5/13/2013**
ADDRESS: **250 E. 111th St.** IDPH LICENSE NO: **100-19036**

HOMOGENEOUS AREA: **093**
MATERIAL DESCRIPTION: **Aircell pipe insulation (NOT OBSERVED)**
MATERIAL LOCATION: **Gym: Throughout bldg, locker rooms, showers**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: 05/13/2013

Chicago Public Schools

GSG Consultants, Inc. 2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47051** BUIDLING ID: **1500**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ismael Hernandez**
SCHOOL NAME: **Brooks College Prep (Southside College Prep)** INSPECTION DATE: **4/17/2013**
ADDRESS: **250 E. 111th St.** IDPH LICENSE NO: **100-19036**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **094**
MATERIAL DESCRIPTION: **Hard fittings on air cell pipe insulation (NOT OBSERVED)**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Chrysotile** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:


MATERIAL LOCATION: **Gym: Throughout bldg, locker rooms, showers**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **04/17/2013**

Chicago Public Schools

GSG Consultants, Inc.
2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47051** BUILDING ID: **1500**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**
SCHOOL NAME: **Brooks College Prep
(Southside College
Prep)** REVIEW DATE: **5/13/2013**
ADDRESS: **250 E. 111th St.** IDPH LICENSE NO: **100-19036**

HOMOGENEOUS AREA: **094**
MATERIAL DESCRIPTION: **Hard fittings on air cell pipe insulation (NOT OBSERVED)**
MATERIAL LOCATION: **Gym: Throughout bldg, locker rooms, showers**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: 05/13/2013

Chicago Public Schools

GSG Consultants, Inc.
2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47051** BUIDLING ID: **1500**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ismael Hernandez**
SCHOOL NAME: **Brooks College Prep (Southside College Prep)** INSPECTION DATE: **4/17/2013**
ADDRESS: **250 E. 111th St.** IDPH LICENSE NO: **100-19036**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **100**
MATERIAL DESCRIPTION: **1'x1' Ceiling Tile Mastic Not Observed**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Monastery: confessionals**

MATERIAL QUANTITY:


MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **04/17/2013**

Chicago Public Schools

GSG Consultants, Inc. 2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47051** BUILDING ID: **1500**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**
SCHOOL NAME: **Brooks College Prep
(Southside College
Prep)** REVIEW DATE: **5/13/2013**
ADDRESS: **250 E. 111th St.** IDPH LICENSE NO: **100-19036**

HOMOGENEOUS AREA: **100**
MATERIAL DESCRIPTION: **1'x1' Ceiling Tile Mastic Not Observed**
MATERIAL LOCATION: **Monastery: confessionals**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:  Date: **05/13/2013**

Chicago Public Schools

GSG Consultants, Inc.
2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47051** BUIDLING ID: **1500**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ismael Hernandez**
SCHOOL NAME: **Brooks College Prep (Southside College Prep)** INSPECTION DATE: **4/17/2013**
ADDRESS: **250 E. 111th St.** IDPH LICENSE NO: **100-19036**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **101 (F61)**
MATERIAL DESCRIPTION: **12x12 light grey floor tile (ABATED)**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:


MATERIAL LOCATION: **Main Building: west wing far west corridor**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **04/17/2013**

Chicago Public Schools

GSG Consultants, Inc.

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47051** BUILDING ID: **1500**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**
SCHOOL NAME: **Brooks College Prep
(Southside College
Prep)** REVIEW DATE: **5/13/2013**
ADDRESS: **250 E. 111th St.** IDPH LICENSE NO: **100-19036**

HOMOGENEOUS AREA: **101 (F61)**
MATERIAL DESCRIPTION: **12x12 light grey floor tile (ABATED)**
MATERIAL LOCATION: **Main Building: west wing far west corridor**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: 05/13/2013

Chicago Public Schools

GSG Consultants, Inc.
2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47051** BUIDLING ID: **1500**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ismael Hernandez**
SCHOOL NAME: **Brooks College Prep (Southside College Prep)** INSPECTION DATE: **4/17/2013**
ADDRESS: **250 E. 111th St.** IDPH LICENSE NO: **100-19036**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **101 (F62)**
MATERIAL DESCRIPTION: **12x12 dark brown white/black speck floor tile (ABATED)**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:


MATERIAL LOCATION: **Main Building: west wing, north west corner**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **04/17/2013**

Chicago Public Schools

GSG Consultants, Inc.
2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47051** BUIDLING ID: **1500**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**
SCHOOL NAME: **Brooks College Prep
(Southside College
Prep)** REVIEW DATE: **5/13/2013**
ADDRESS: **250 E. 111th St.** IDPH LICENSE NO: **100-19036**

HOMOGENEOUS AREA: **101 (F62)**
MATERIAL DESCRIPTION: **12x12 dark brown white/black speck floor tile (ABATED)**
MATERIAL LOCATION: **Main Building: west wing, north west corner**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: 05/13/2013

Chicago Public Schools

GSG Consultants, Inc. 2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47051** BUIDLING ID: **1500**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ismael Hernandez**
SCHOOL NAME: **Brooks College Prep (Southside College Prep)** INSPECTION DATE: **4/17/2013**
ADDRESS: **250 E. 111th St.** IDPH LICENSE NO: **100-19036**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **101(F60)**
MATERIAL DESCRIPTION: **12x12 off white floor tile (ABATED)**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:


MATERIAL LOCATION: **Main Building: W wing 3rd floor, NW corner, west & east wing, north portion**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **04/17/2013**

Chicago Public Schools

GSG Consultants, Inc. 2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47051** BUILDING ID: **1500**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**
SCHOOL NAME: **Brooks College Prep
(Southside College
Prep)** REVIEW DATE: **5/13/2013**
ADDRESS: **250 E. 111th St.** IDPH LICENSE NO: **100-19036**

HOMOGENEOUS AREA: **101(F60)**
MATERIAL DESCRIPTION: **12x12 off white floor tile (ABATED)**
MATERIAL LOCATION: **Main Building: W wing 3rd floor, NW corner, west & east wing, north portion**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: 05/13/2013

Chicago Public Schools

GSG Consultants, Inc. 2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47051** BUIDLING ID: **1500**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ismael Hernandez**
SCHOOL NAME: **Brooks College Prep (Southside College Prep)** INSPECTION DATE: **4/17/2013**
ADDRESS: **250 E. 111th St.** IDPH LICENSE NO: **100-19036**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **102 (F61)**
MATERIAL DESCRIPTION: **12x12 light grey floor tile mastic (ABATED)**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:


MATERIAL LOCATION: **Main Building: west wing far west corridor**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **04/17/2013**

Chicago Public Schools

GSG Consultants, Inc. 2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47051** BUILDING ID: **1500**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**
SCHOOL NAME: **Brooks College Prep
(Southside College
Prep)** REVIEW DATE: **5/13/2013**
ADDRESS: **250 E. 111th St.** IDPH LICENSE NO: **100-19036**

HOMOGENEOUS AREA: **102 (F61)**
MATERIAL DESCRIPTION: **12x12 light grey floor tile mastic (ABATED)**
MATERIAL LOCATION: **Main Building: west wing far west corridor**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: 05/13/2013

Chicago Public Schools

GSG Consultants, Inc.
2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47051** BUIDLING ID: **1500**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ismael Hernandez**
SCHOOL NAME: **Brooks College Prep (Southside College Prep)** INSPECTION DATE: **4/17/2013**
ADDRESS: **250 E. 111th St.** IDPH LICENSE NO: **100-19036**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **102(F60)**
MATERIAL DESCRIPTION: **12x12 off white floor tile mastic (ABATED)**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:


MATERIAL LOCATION: **Main Building:W wing 3rd floor, NW corner,west & east wing, north portion**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **04/17/2013**

Chicago Public Schools

GSG Consultants, Inc. 2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47051** BUILDING ID: **1500**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**
SCHOOL NAME: **Brooks College Prep
(Southside College
Prep)** REVIEW DATE: **5/13/2013**
ADDRESS: **250 E. 111th St.** IDPH LICENSE NO: **100-19036**

HOMOGENEOUS AREA: **102(F60)**
MATERIAL DESCRIPTION: **12x12 off white floor tile mastic (ABATED)**
MATERIAL LOCATION: **Main Building:W wing 3rd floor, NW corner,west & east wing, north portion**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: 05/13/2013

Chicago Public Schools

GSG Consultants, Inc. 2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47051** BUIDLING ID: **1500**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ismael Hernandez**
SCHOOL NAME: **Brooks College Prep (Southside College Prep)** INSPECTION DATE: **4/17/2013**
ADDRESS: **250 E. 111th St.** IDPH LICENSE NO: **100-19036**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **102(F62)**
MATERIAL DESCRIPTION: **12x12 dark brown white/black speckled floor tile (ABATED)**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:


MATERIAL LOCATION: **Main Building:west wing, north west corner**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **04/17/2013**

Chicago Public Schools

GSG Consultants, Inc.

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47051** BUIDLING ID: **1500**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**
SCHOOL NAME: **Brooks College Prep
(Southside College
Prep)** REVIEW DATE: **5/13/2013**
ADDRESS: **250 E. 111th St.** IDPH LICENSE NO: **100-19036**

HOMOGENEOUS AREA: **102(F62)**

MATERIAL DESCRIPTION: **12x12 dark brown white/black speckled floor tile (ABATED)**

MATERIAL LOCATION: **Main Building:west wing, north west corner**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: 05/13/2013

Chicago Public Schools

GSG Consultants, Inc. 2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47051** BUIDLING ID: **1500**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ismael Hernandez**
SCHOOL NAME: **Brooks College Prep (Southside College Prep)** INSPECTION DATE: **4/17/2013**
ADDRESS: **250 E. 111th St.** IDPH LICENSE NO: **100-19036**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **103(F63)**
MATERIAL DESCRIPTION: **9x9 light green floor tile (ABATED)**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:


MATERIAL LOCATION: **Main Building: west wing corridor, 2nd & 3rd floor east & west wing patches**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **04/17/2013**

Chicago Public Schools

GSG Consultants, Inc.

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47051** BUILDING ID: **1500**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**
SCHOOL NAME: **Brooks College Prep (Southside College Prep)** REVIEW DATE: **5/13/2013**
ADDRESS: **250 E. 111th St.** IDPH LICENSE NO: **100-19036**

HOMOGENEOUS AREA: **103(F63)**
MATERIAL DESCRIPTION: **9x9 light green floor tile (ABATED)**
MATERIAL LOCATION: **Main Building: west wing corridor, 2nd & 3rd floor east & west wing patches**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: 05/13/2013

Chicago Public Schools

GSG Consultants, Inc.
2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47051** BUIDLING ID: **1500**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ismael Hernandez**
SCHOOL NAME: **Brooks College Prep (Southside College Prep)** INSPECTION DATE: **4/17/2013**
ADDRESS: **250 E. 111th St.** IDPH LICENSE NO: **100-19036**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **103(F64)**
MATERIAL DESCRIPTION: **9x9 light brown floor tile (ABATED)**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:


MATERIAL LOCATION: **Main Building: west wing 1st,2nd,3rd corridor patches & east end**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **04/17/2013**

Chicago Public Schools

GSG Consultants, Inc. 2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47051** BUILDING ID: **1500**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**
SCHOOL NAME: **Brooks College Prep
(Southside College
Prep)** REVIEW DATE: **5/13/2013**
ADDRESS: **250 E. 111th St.** IDPH LICENSE NO: **100-19036**

HOMOGENEOUS AREA: **103(F64)**
MATERIAL DESCRIPTION: **9x9 light brown floor tile (ABATED)**
MATERIAL LOCATION: **Main Building: west wing 1st,2nd,3rd corridor patches & east end**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: 05/13/2013

Chicago Public Schools

GSG Consultants, Inc.
2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47051** BUIDLING ID: **1500**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ismael Hernandez**
SCHOOL NAME: **Brooks College Prep (Southside College Prep)** INSPECTION DATE: **4/17/2013**
ADDRESS: **250 E. 111th St.** IDPH LICENSE NO: **100-19036**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **103(F65)**
MATERIAL DESCRIPTION: **9x9 medium brown floor tile (ABATED)**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:


MATERIAL LOCATION: **Main Building: west wing 1st & 3rd floor corridor patches & east wing**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **04/17/2013**

Chicago Public Schools

GSG Consultants, Inc.
2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47051** BUILDING ID: **1500**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**
SCHOOL NAME: **Brooks College Prep
(Southside College
Prep)** REVIEW DATE: **5/13/2013**
ADDRESS: **250 E. 111th St.** IDPH LICENSE NO: **100-19036**

HOMOGENEOUS AREA: **103(F65)**
MATERIAL DESCRIPTION: **9x9 medium brown floor tile (ABATED)**
MATERIAL LOCATION: **Main Building: west wing 1st & 3rd floor corridor patches & east wing**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: 05/13/2013

Chicago Public Schools

GSG Consultants, Inc.
2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47051** BUIDLING ID: **1500**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ismael Hernandez**
SCHOOL NAME: **Brooks College Prep (Southside College Prep)** INSPECTION DATE: **4/17/2013**
ADDRESS: **250 E. 111th St.** IDPH LICENSE NO: **100-19036**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **103(F66)**
MATERIAL DESCRIPTION: **9x9 yellow floor tile (ABATED)**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:


MATERIAL LOCATION: **Main Building: 1st floor corridor patches**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **04/17/2013**

Chicago Public Schools

GSG Consultants, Inc.
2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47051** BUILDING ID: **1500**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**
SCHOOL NAME: **Brooks College Prep
(Southside College
Prep)** REVIEW DATE: **5/13/2013**
ADDRESS: **250 E. 111th St.** IDPH LICENSE NO: **100-19036**

HOMOGENEOUS AREA: **103(F66)**
MATERIAL DESCRIPTION: **9x9 yellow floor tile (ABATED)**
MATERIAL LOCATION: **Main Building: 1st floor corridor patches**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: 05/13/2013

Chicago Public Schools

GSG Consultants, Inc. 2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47051** BUIDLING ID: **1500**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ismael Hernandez**
SCHOOL NAME: **Brooks College Prep (Southside College Prep)** INSPECTION DATE: **4/17/2013**
ADDRESS: **250 E. 111th St.** IDPH LICENSE NO: **100-19036**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **103(F7)**
MATERIAL DESCRIPTION: **9x9 clay floor tile (ABATED)**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:


MATERIAL LOCATION: **Main Building: 1st floor corridor west wing**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **04/17/2013**

Chicago Public Schools

GSG Consultants, Inc. 2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47051** BUILDING ID: **1500**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**
SCHOOL NAME: **Brooks College Prep
(Southside College
Prep)** REVIEW DATE: **5/13/2013**
ADDRESS: **250 E. 111th St.** IDPH LICENSE NO: **100-19036**

HOMOGENEOUS AREA: **103(F7)**
MATERIAL DESCRIPTION: **9x9 clay floor tile (ABATED)**
MATERIAL LOCATION: **Main Building: 1st floor corridor west wing**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: 05/13/2013

Chicago Public Schools

GSG Consultants, Inc.
2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47051** BUIDLING ID: **1500**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ismael Hernandez**
SCHOOL NAME: **Brooks College Prep (Southside College Prep)** INSPECTION DATE: **4/17/2013**
ADDRESS: **250 E. 111th St.** IDPH LICENSE NO: **100-19036**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **104 (F63)**
MATERIAL DESCRIPTION: **9x9 light green floor tile mastic (ABATED)**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:


MATERIAL LOCATION: **Main Building: west wing corridor, 2nd & 3rd floor east & west wing patches**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **04/17/2013**

Chicago Public Schools

GSG Consultants, Inc.
2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47051** BUILDING ID: **1500**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**
SCHOOL NAME: **Brooks College Prep
(Southside College
Prep)** REVIEW DATE: **5/13/2013**
ADDRESS: **250 E. 111th St.** IDPH LICENSE NO: **100-19036**

HOMOGENEOUS AREA: **104 (F63)**
MATERIAL DESCRIPTION: **9x9 light green floor tile mastic (ABATED)**
MATERIAL LOCATION: **Main Building: west wing corridor, 2nd & 3rd floor east & west wing patches**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: 05/13/2013

Chicago Public Schools

GSG Consultants, Inc. 2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47051** BUIDLING ID: **1500**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ismael Hernandez**
SCHOOL NAME: **Brooks College Prep (Southside College Prep)** INSPECTION DATE: **4/17/2013**
ADDRESS: **250 E. 111th St.** IDPH LICENSE NO: **100-19036**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **104 (F7)**
MATERIAL DESCRIPTION: **9x9 clay floor tile mastic (ABATED)**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:


MATERIAL LOCATION: **Main Building: 1st floor corridor west wing**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **04/17/2013**

Chicago Public Schools

GSG Consultants, Inc.

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47051** BUILDING ID: **1500**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**
SCHOOL NAME: **Brooks College Prep
(Southside College
Prep)** REVIEW DATE: **5/13/2013**
ADDRESS: **250 E. 111th St.** IDPH LICENSE NO: **100-19036**

HOMOGENEOUS AREA: **104 (F7)**

MATERIAL DESCRIPTION: **9x9 clay floor tile mastic (ABATED)**

MATERIAL LOCATION: **Main Building: 1st floor corridor west wing**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: 05/13/2013

Chicago Public Schools

GSG Consultants, Inc. 2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47051** BUIDLING ID: **1500**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ismael Hernandez**
SCHOOL NAME: **Brooks College Prep (Southside College Prep)** INSPECTION DATE: **4/17/2013**
ADDRESS: **250 E. 111th St.** IDPH LICENSE NO: **100-19036**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **104(F1)**
MATERIAL DESCRIPTION: **9x9 white floor tile mastic (ABATED)**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Main Building: east wing room 15 & 19 & west wing music**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **04/17/2013**

Chicago Public Schools

GSG Consultants, Inc.
2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47051** BUILDING ID: **1500**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**
SCHOOL NAME: **Brooks College Prep
(Southside College
Prep)** REVIEW DATE: **5/13/2013**
ADDRESS: **250 E. 111th St.** IDPH LICENSE NO: **100-19036**

HOMOGENEOUS AREA: **104(F1)**
MATERIAL DESCRIPTION: **9x9 white floor tile mastic (ABATED)**
MATERIAL LOCATION: **Main Building: east wing room 15 & 19 & west wing music**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: 05/13/2013

Chicago Public Schools

GSG Consultants, Inc.
2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47051** BUIDLING ID: **1500**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ismael Hernandez**
SCHOOL NAME: **Brooks College Prep (Southside College Prep)** INSPECTION DATE: **4/17/2013**
ADDRESS: **250 E. 111th St.** IDPH LICENSE NO: **100-19036**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **104(F2)**
MATERIAL DESCRIPTION: **9x9 black floor tile mastic (ABATED)**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:


MATERIAL LOCATION: **Main Building: east wing room 15 & 19**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **04/17/2013**

Chicago Public Schools

GSG Consultants, Inc. 2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47051** BUIDLING ID: **1500**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**
SCHOOL NAME: **Brooks College Prep
(Southside College
Prep)** REVIEW DATE: **5/13/2013**
ADDRESS: **250 E. 111th St.** IDPH LICENSE NO: **100-19036**

HOMOGENEOUS AREA: **104(F2)**
MATERIAL DESCRIPTION: **9x9 black floor tile mastic (ABATED)**
MATERIAL LOCATION: **Main Building: east wing room 15 & 19**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:  Date: **05/13/2013**

Chicago Public Schools

GSG Consultants, Inc.
2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47051** BUIDLING ID: **1500**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ismael Hernandez**
SCHOOL NAME: **Brooks College Prep (Southside College Prep)** INSPECTION DATE: **4/17/2013**
ADDRESS: **250 E. 111th St.** IDPH LICENSE NO: **100-19036**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **104(F3)**
MATERIAL DESCRIPTION: **9x9 pink floor tile mastic (ABATED)**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:


MATERIAL LOCATION: **Main Building: west wing 1st,2nd floor foyer**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **04/17/2013**

Chicago Public Schools

GSG Consultants, Inc.
2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47051** BUILDING ID: **1500**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**
SCHOOL NAME: **Brooks College Prep (Southside College Prep)** REVIEW DATE: **5/13/2013**
ADDRESS: **250 E. 111th St.** IDPH LICENSE NO: **100-19036**

HOMOGENEOUS AREA: **104(F3)**
MATERIAL DESCRIPTION: **9x9 pink floor tile mastic (ABATED)**
MATERIAL LOCATION: **Main Building: west wing 1st,2nd floor foyer**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: 05/13/2013

Chicago Public Schools

GSG Consultants, Inc. 2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47051** BUIDLING ID: **1500**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ismael Hernandez**
SCHOOL NAME: **Brooks College Prep (Southside College Prep)** INSPECTION DATE: **4/17/2013**
ADDRESS: **250 E. 111th St.** IDPH LICENSE NO: **100-19036**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **104(F4)**
MATERIAL DESCRIPTION: **9x9 maroon floor tile mastic (ABATED)**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:


MATERIAL LOCATION: **Main Building: 1st & 2nd floor west wing, 1st floor throughout, 2nd flr west rooms**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **04/17/2013**

Chicago Public Schools

GSG Consultants, Inc. 2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47051** BUILDING ID: **1500**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**
SCHOOL NAME: **Brooks College Prep
(Southside College
Prep)** REVIEW DATE: **5/13/2013**
ADDRESS: **250 E. 111th St.** IDPH LICENSE NO: **100-19036**

HOMOGENEOUS AREA: **104(F4)**
MATERIAL DESCRIPTION: **9x9 maroon floor tile mastic (ABATED)**
MATERIAL LOCATION: **Main Building: 1st & 2nd floor west wing, 1st floor throughout, 2nd flr west rooms**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: 05/13/2013

Chicago Public Schools

GSG Consultants, Inc.
2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47051** BUIDLING ID: **1500**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ismael Hernandez**
SCHOOL NAME: **Brooks College Prep (Southside College Prep)** INSPECTION DATE: **4/17/2013**
ADDRESS: **250 E. 111th St.** IDPH LICENSE NO: **100-19036**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **104(F5)**
MATERIAL DESCRIPTION: **9x9 tan abated mastic (ABATED)**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:


MATERIAL LOCATION: **Main Building: main BLDG: library, east wing throughout**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **04/17/2013**

Chicago Public Schools

GSG Consultants, Inc. 2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47051** BUIDLING ID: **1500**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**
SCHOOL NAME: **Brooks College Prep
(Southside College
Prep)** REVIEW DATE: **5/13/2013**
ADDRESS: **250 E. 111th St.** IDPH LICENSE NO: **100-19036**

HOMOGENEOUS AREA: **104(F5)**
MATERIAL DESCRIPTION: **9x9 tan abated mastic (ABATED)**
MATERIAL LOCATION: **Main Building: main BLDG: library, east wing throughout**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: 05/13/2013

Chicago Public Schools

GSG Consultants, Inc.
2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47051** BUIDLING ID: **1500**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ismael Hernandez**
SCHOOL NAME: **Brooks College Prep (Southside College Prep)** INSPECTION DATE: **4/17/2013**
ADDRESS: **250 E. 111th St.** IDPH LICENSE NO: **100-19036**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **104(F64)**
MATERIAL DESCRIPTION: **9x9 light brown floor tile mastic (ABATED)**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:


MATERIAL LOCATION: **Main Building: west wing 1st,2nd,3rd corridor patches & east end**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **04/17/2013**

Chicago Public Schools

GSG Consultants, Inc.
2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47051** BUILDING ID: **1500**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**
SCHOOL NAME: **Brooks College Prep
(Southside College
Prep)** REVIEW DATE: **5/13/2013**
ADDRESS: **250 E. 111th St.** IDPH LICENSE NO: **100-19036**

HOMOGENEOUS AREA: **104(F64)**
MATERIAL DESCRIPTION: **9x9 light brown floor tile mastic (ABATED)**
MATERIAL LOCATION: **Main Building: west wing 1st,2nd,3rd corridor patches & east end**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: 05/13/2013

Chicago Public Schools

GSG Consultants, Inc.
2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47051** BUIDLING ID: **1500**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ismael Hernandez**
SCHOOL NAME: **Brooks College Prep (Southside College Prep)** INSPECTION DATE: **4/17/2013**
ADDRESS: **250 E. 111th St.** IDPH LICENSE NO: **100-19036**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **104(F65)**
MATERIAL DESCRIPTION: **9x9 medium brown floor tile mastic (ABATED)**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:


MATERIAL LOCATION: **Main Building: west wing 1st & 3rd floor corridor patches & east wing**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **04/17/2013**

Chicago Public Schools

GSG Consultants, Inc. 2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47051** BUILDING ID: **1500**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**
SCHOOL NAME: **Brooks College Prep
(Southside College
Prep)** REVIEW DATE: **5/13/2013**
ADDRESS: **250 E. 111th St.** IDPH LICENSE NO: **100-19036**

HOMOGENEOUS AREA: **104(F65)**
MATERIAL DESCRIPTION: **9x9 medium brown floor tile mastic (ABATED)**
MATERIAL LOCATION: **Main Building: west wing 1st & 3rd floor corridor patches & east wing**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: 05/13/2013

Chicago Public Schools

GSG Consultants, Inc.
2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47051** BUIDLING ID: **1500**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ismael Hernandez**
SCHOOL NAME: **Brooks College Prep (Southside College Prep)** INSPECTION DATE: **4/17/2013**
ADDRESS: **250 E. 111th St.** IDPH LICENSE NO: **100-19036**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **104(F66)**
MATERIAL DESCRIPTION: **9x9 yellow floor tile mastic (ABATED)**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:


MATERIAL LOCATION: **Main Building: 1st floor corridor patches**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **04/17/2013**

Chicago Public Schools

GSG Consultants, Inc. 2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47051** BUILDING ID: **1500**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**
SCHOOL NAME: **Brooks College Prep
(Southside College
Prep)** REVIEW DATE: **5/13/2013**
ADDRESS: **250 E. 111th St.** IDPH LICENSE NO: **100-19036**

HOMOGENEOUS AREA: **104(F66)**
MATERIAL DESCRIPTION: **9x9 yellow floor tile mastic (ABATED)**
MATERIAL LOCATION: **Main Building: 1st floor corridor patches**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: 05/13/2013

Chicago Public Schools

GSG Consultants, Inc. 2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47051** BUIDLING ID: **1500**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ismael Hernandez**
SCHOOL NAME: **Brooks College Prep (Southside College Prep)** INSPECTION DATE: **4/17/2013**
ADDRESS: **250 E. 111th St.** IDPH LICENSE NO: **100-19036**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **104(F67)**
MATERIAL DESCRIPTION: **9x9 green floor tile mastic (ABATED)**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:


MATERIAL LOCATION: **Main Building: 1st floor stairwell, east wing & 2nd & 3rd flr. Hallway**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **04/17/2013**

Chicago Public Schools

GSG Consultants, Inc.

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47051** BUILDING ID: **1500**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**
SCHOOL NAME: **Brooks College Prep (Southside College Prep)** REVIEW DATE: **5/13/2013**
ADDRESS: **250 E. 111th St.** IDPH LICENSE NO: **100-19036**

HOMOGENEOUS AREA: **104(F67)**
MATERIAL DESCRIPTION: **9x9 green floor tile mastic (ABATED)**
MATERIAL LOCATION: **Main Building: 1st floor stairwell, east wing & 2nd & 3rd flr. Hallway**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: 05/13/2013

Chicago Public Schools

GSG Consultants, Inc.
2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47051** BUIDLING ID: **1500**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ismael Hernandez**
SCHOOL NAME: **Brooks College Prep (Southside College Prep)** INSPECTION DATE: **4/17/2013**
ADDRESS: **250 E. 111th St.** IDPH LICENSE NO: **100-19036**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **105 (F68)**
MATERIAL DESCRIPTION: **Various size brown speckled floor tile (ABATED)**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Main Building: 1st,2nd,3rd floor patches in east & west wing**

MATERIAL QUANTITY: **4000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **04/17/2013**

Chicago Public Schools

GSG Consultants, Inc.

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47051** BUILDING ID: **1500**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**
SCHOOL NAME: **Brooks College Prep
(Southside College
Prep)** REVIEW DATE: **5/13/2013**
ADDRESS: **250 E. 111th St.** IDPH LICENSE NO: **100-19036**

HOMOGENEOUS AREA: **105 (F68)**
MATERIAL DESCRIPTION: **Various size brown speckled floor tile (ABATED)**
MATERIAL LOCATION: **Main Building: 1st,2nd,3rd floor patches in east & west wing**
MATERIAL QUANTITY: **4000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **05/13/2013**

Chicago Public Schools

GSG Consultants, Inc.
2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47051** BUIDLING ID: **1500**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ismael Hernandez**
SCHOOL NAME: **Brooks College Prep (Southside College Prep)** INSPECTION DATE: **4/17/2013**
ADDRESS: **250 E. 111th St.** IDPH LICENSE NO: **100-19036**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **106(F68)**
MATERIAL DESCRIPTION: **Various size brown speckled floor tile mastic (ABATED)**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:


MATERIAL LOCATION: **Main Building: 1st, 2nd,3 rd floor patches in east & west wing**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **04/17/2013**

Chicago Public Schools

GSG Consultants, Inc.
2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47051** BUILDING ID: **1500**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**
SCHOOL NAME: **Brooks College Prep
(Southside College
Prep)** REVIEW DATE: **5/13/2013**
ADDRESS: **250 E. 111th St.** IDPH LICENSE NO: **100-19036**

HOMOGENEOUS AREA: **106(F68)**
MATERIAL DESCRIPTION: **Various size brown speckled floor tile mastic (ABATED)**
MATERIAL LOCATION: **Main Building: 1st, 2nd,3 rd floor patches in east & west wing**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: 05/13/2013

Chicago Public Schools

GSG Consultants, Inc.
2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47051** BUIDLING ID: **1500**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ismael Hernandez**
SCHOOL NAME: **Brooks College Prep (Southside College Prep)** INSPECTION DATE: **4/17/2013**
ADDRESS: **250 E. 111th St.** IDPH LICENSE NO: **100-19036**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **107(CM70)**
MATERIAL DESCRIPTION: **carpet mastic under multicolored (ABATED)**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:


MATERIAL LOCATION: **Main Building: 2nd floor west wing, far west wing**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **04/17/2013**

Chicago Public Schools

GSG Consultants, Inc.
2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47051** BUILDING ID: **1500**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**
SCHOOL NAME: **Brooks College Prep
(Southside College
Prep)** REVIEW DATE: **5/13/2013**
ADDRESS: **250 E. 111th St.** IDPH LICENSE NO: **100-19036**

HOMOGENEOUS AREA: **107(CM70)**
MATERIAL DESCRIPTION: **carpet mastic under multicolored (ABATED)**
MATERIAL LOCATION: **Main Building: 2nd floor west wing, far west wing**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: 05/13/2013

Chicago Public Schools

GSG Consultants, Inc.
2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47051** BUIDLING ID: **1500**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ismael Hernandez**
SCHOOL NAME: **Brooks College Prep (Southside College Prep)** INSPECTION DATE: **4/17/2013**
ADDRESS: **250 E. 111th St.** IDPH LICENSE NO: **100-19036**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **107(CM71)**
MATERIAL DESCRIPTION: **grey carpet mastic (ABATED)**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Main Building: 2nd floor office, 1st floor west corner**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **04/17/2013**

Chicago Public Schools

GSG Consultants, Inc.

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47051** BUIDLING ID: **1500**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**
SCHOOL NAME: **Brooks College Prep
(Southside College
Prep)** REVIEW DATE: **5/13/2013**
ADDRESS: **250 E. 111th St.** IDPH LICENSE NO: **100-19036**

HOMOGENEOUS AREA: **107(CM71)**

MATERIAL DESCRIPTION: **grey carpet mastic (ABATED)**

MATERIAL LOCATION: **Main Building: 2nd floor office, 1st floor west corner**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: 05/13/2013

Chicago Public Schools

GSG Consultants, Inc.
2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 47051 BUILDING ID: 1500
CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Ismael Hernandez
SCHOOL NAME: Brooks College Prep (Southside College Prep) INSPECTION DATE: 4/17/2013
ADDRESS: 250 E. 111th St. IDPH LICENSE NO: 100-19036

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 108
MATERIAL DESCRIPTION: grey vinyl stair treads (ABATED)
HISTORICAL AHERA DAMAGE CATEGORY 6
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: Abated FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Main Building: 1st, 2nd, 3rd floor east & west wings

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____



Date: 04/17/2013

Chicago Public Schools

GSG Consultants, Inc.
2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47051** BUILDING ID: **1500**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**
SCHOOL NAME: **Brooks College Prep (Southside College Prep)** REVIEW DATE: **5/13/2013**
ADDRESS: **250 E. 111th St.** IDPH LICENSE NO: **100-19036**

HOMOGENEOUS AREA: **108**
MATERIAL DESCRIPTION: **grey vinyl stair treads (ABATED)**
MATERIAL LOCATION: **Main Building: 1st, 2nd, 3rd floor east & west wings**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: **0** DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **05/13/2013**

Chicago Public Schools

GSG Consultants, Inc. 2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47051** BUIDLING ID: **1500**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ismael Hernandez**
SCHOOL NAME: **Brooks College Prep (Southside College Prep)** INSPECTION DATE: **4/17/2013**
ADDRESS: **250 E. 111th St.** IDPH LICENSE NO: **100-19036**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **109**
MATERIAL DESCRIPTION: **vinyl stair track mastic (ABATED)**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:


MATERIAL LOCATION: **Main Building: 1st, 2nd, 3rd floor east & west wings**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **04/17/2013**

Chicago Public Schools

GSG Consultants, Inc. 2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47051** BUILDING ID: **1500**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**
SCHOOL NAME: **Brooks College Prep
(Southside College
Prep)** REVIEW DATE: **5/13/2013**
ADDRESS: **250 E. 111th St.** IDPH LICENSE NO: **100-19036**

HOMOGENEOUS AREA: **109**
MATERIAL DESCRIPTION: **vinyl stair track mastic (ABATED)**
MATERIAL LOCATION: **Main Building: 1st, 2nd, 3rd floor east & west wings**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:  Date: **05/13/2013**

Chicago Public Schools

GSG Consultants, Inc.
2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47051** BUIDLING ID: **1500**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ismael Hernandez**
SCHOOL NAME: **Brooks College Prep (Southside College Prep)** INSPECTION DATE: **4/17/2013**
ADDRESS: **250 E. 111th St.** IDPH LICENSE NO: **100-19036**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **110 (F75)**
MATERIAL DESCRIPTION: **4" brown vinyl base board (ABATED)**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:


DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Main Building: 1st floor corridor leading to west wing, 3rd floor NW corner**

MATERIAL QUANTITY: **250** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: 

Date: **04/17/2013**

Chicago Public Schools

GSG Consultants, Inc.

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47051** BUILDING ID: **1500**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**
SCHOOL NAME: **Brooks College Prep (Southside College Prep)** REVIEW DATE: **5/13/2013**
ADDRESS: **250 E. 111th St.** IDPH LICENSE NO: **100-19036**

HOMOGENEOUS AREA: **110 (F75)**
MATERIAL DESCRIPTION: **4" brown vinyl base board (ABATED)**
MATERIAL LOCATION: **Main Building: 1st floor corridor leading to west wing, 3rd floor NW corner**
MATERIAL QUANTITY: **250** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **05/13/2013**

Chicago Public Schools

GSG Consultants, Inc. 2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47051** BUIDLING ID: **1500**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ismael Hernandez**
SCHOOL NAME: **Brooks College Prep (Southside College Prep)** INSPECTION DATE: **4/17/2013**
ADDRESS: **250 E. 111th St.** IDPH LICENSE NO: **100-19036**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **110 (F76)**
MATERIAL DESCRIPTION: **4" black baseboard (ABATED)**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Main Bldg: 1st,2nd,3rd floor throughout east wing & corridor- e. wing 1st flr. NE. corner west wing**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **04/17/2013**

Chicago Public Schools

GSG Consultants, Inc.
2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47051** BUILDING ID: **1500**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**
SCHOOL NAME: **Brooks College Prep (Southside College Prep)** REVIEW DATE: **5/13/2013**
ADDRESS: **250 E. 111th St.** IDPH LICENSE NO: **100-19036**

HOMOGENEOUS AREA: **110 (F76)**
MATERIAL DESCRIPTION: **4" black baseboard (ABATED)**
MATERIAL LOCATION: **Main Bldg: 1st,2nd,3rd floor throughout east wing & corridor- e. wing 1st flr. NE. corner west wing**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:  Date: 05/13/2013

Chicago Public Schools

GSG Consultants, Inc.
2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47051** BUIDLING ID: **1500**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ismael Hernandez**
SCHOOL NAME: **Brooks College Prep (Southside College Prep)** INSPECTION DATE: **4/17/2013**
ADDRESS: **250 E. 111th St.** IDPH LICENSE NO: **100-19036**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **110 (F77)**
MATERIAL DESCRIPTION: **4" tan baseboard (ABATED)**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:


MATERIAL LOCATION: **Main Building: 1st, 2nd floor main BLDG, NE. & NW. portion**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **04/17/2013**

Chicago Public Schools

GSG Consultants, Inc.
2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47051** BUILDING ID: **1500**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**
SCHOOL NAME: **Brooks College Prep
(Southside College
Prep)** REVIEW DATE: **5/13/2013**
ADDRESS: **250 E. 111th St.** IDPH LICENSE NO: **100-19036**

HOMOGENEOUS AREA: **110 (F77)**
MATERIAL DESCRIPTION: **4" tan baseboard (ABATED)**
MATERIAL LOCATION: **Main Building: 1st, 2nd floor main BLDG, NE. & NW. portion**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: 05/13/2013

Chicago Public Schools

GSG Consultants, Inc. 2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47051** BUIDLING ID: **1500**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ismael Hernandez**
SCHOOL NAME: **Brooks College Prep (Southside College Prep)** INSPECTION DATE: **4/17/2013**
ADDRESS: **250 E. 111th St.** IDPH LICENSE NO: **100-19036**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **111(F75)**
MATERIAL DESCRIPTION: **4" brown vinyl base board mastic (ABATED)**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:


MATERIAL LOCATION: **Main Building: 1st floor corridor leading to west wing, 3rd floor NW corner**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **04/17/2013**

Chicago Public Schools

GSG Consultants, Inc.

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47051** BUILDING ID: **1500**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**
SCHOOL NAME: **Brooks College Prep (Southside College Prep)** REVIEW DATE: **5/13/2013**
ADDRESS: **250 E. 111th St.** IDPH LICENSE NO: **100-19036**

HOMOGENEOUS AREA: **111(F75)**
MATERIAL DESCRIPTION: **4" brown vinyl base board mastic (ABATED)**
MATERIAL LOCATION: **Main Building: 1st floor corridor leading to west wing, 3rd floor NW corner**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: 05/13/2013

Chicago Public Schools

GSG Consultants, Inc. 2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47051** BUIDLING ID: **1500**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ismael Hernandez**
SCHOOL NAME: **Brooks College Prep (Southside College Prep)** INSPECTION DATE: **4/17/2013**
ADDRESS: **250 E. 111th St.** IDPH LICENSE NO: **100-19036**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **111(F76)**
MATERIAL DESCRIPTION: **4" black baseboard (ABATED)**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:


MATERIAL LOCATION: **Main Building: 1st,2nd,3rd floor throughout**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **04/17/2013**

Chicago Public Schools

GSG Consultants, Inc.

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47051** BUILDING ID: **1500**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**
SCHOOL NAME: **Brooks College Prep (Southside College Prep)** REVIEW DATE: **5/13/2013**
ADDRESS: **250 E. 111th St.** IDPH LICENSE NO: **100-19036**

HOMOGENEOUS AREA: **111(F76)**

MATERIAL DESCRIPTION: **4" black baseboard (ABATED)**

MATERIAL LOCATION: **Main Building: 1st,2nd,3rd floor throughout**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: 05/13/2013

Chicago Public Schools

GSG Consultants, Inc. 2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47051** BUIDLING ID: **1500**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ismael Hernandez**
SCHOOL NAME: **Brooks College Prep (Southside College Prep)** INSPECTION DATE: **4/17/2013**
ADDRESS: **250 E. 111th St.** IDPH LICENSE NO: **100-19036**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **111(F77)**
MATERIAL DESCRIPTION: **4" tan baseboard mastic (ABATED)**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Main Building: 1st,2nd floor main BLDG, NE. & NW. portion**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **04/17/2013**

Chicago Public Schools

GSG Consultants, Inc. 2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47051** BUIDLING ID: **1500**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**
SCHOOL NAME: **Brooks College Prep
(Southside College
Prep)** REVIEW DATE: **5/13/2013**
ADDRESS: **250 E. 111th St.** IDPH LICENSE NO: **100-19036**

HOMOGENEOUS AREA: **111(F77)**
MATERIAL DESCRIPTION: **4" tan baseboard mastic (ABATED)**
MATERIAL LOCATION: **Main Building: 1st,2nd floor main BLDG, NE. & NW. portion**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: 05/13/2013

Chicago Public Schools

GSG Consultants, Inc.
2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47051** BUIDLING ID: **1500**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ismael Hernandez**
SCHOOL NAME: **Brooks College Prep (Southside College Prep)** INSPECTION DATE: **4/17/2013**
ADDRESS: **250 E. 111th St.** IDPH LICENSE NO: **100-19036**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **112 (F80)**
MATERIAL DESCRIPTION: **6" black vinyl baseboard (ABATED)**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:


MATERIAL LOCATION: **Main Building: 2nd floor main bldg. SE corner**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **04/17/2013**

Chicago Public Schools

GSG Consultants, Inc.

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47051** BUILDING ID: **1500**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**
SCHOOL NAME: **Brooks College Prep
(Southside College
Prep)** REVIEW DATE: **5/13/2013**
ADDRESS: **250 E. 111th St.** IDPH LICENSE NO: **100-19036**

HOMOGENEOUS AREA: **112 (F80)**
MATERIAL DESCRIPTION: **6" black vinyl baseboard (ABATED)**
MATERIAL LOCATION: **Main Building: 2nd floor main bldg. SE corner**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: 05/13/2013

Chicago Public Schools

GSG Consultants, Inc. 2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47051** BUIDLING ID: **1500**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ismael Hernandez**
SCHOOL NAME: **Brooks College Prep (Southside College Prep)** INSPECTION DATE: **4/17/2013**
ADDRESS: **250 E. 111th St.** IDPH LICENSE NO: **100-19036**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **113 (F80)**
MATERIAL DESCRIPTION: **6" black vinyl baseboard mastic (ABATED)**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:


MATERIAL LOCATION: **Main Building: 2nd floor main bldg. SE corner**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **04/17/2013**

Chicago Public Schools

GSG Consultants, Inc.

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47051** BUILDING ID: **1500**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**
SCHOOL NAME: **Brooks College Prep
(Southside College
Prep)** REVIEW DATE: **5/13/2013**
ADDRESS: **250 E. 111th St.** IDPH LICENSE NO: **100-19036**

HOMOGENEOUS AREA: **113 (F80)**
MATERIAL DESCRIPTION: **6" black vinyl baseboard mastic (ABATED)**
MATERIAL LOCATION: **Main Building: 2nd floor main bldg. SE corner**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: 05/13/2013

Chicago Public Schools

GSG Consultants, Inc. 2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47051** BUIDLING ID: **1500**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ismael Hernandez**
SCHOOL NAME: **Brooks College Prep (Southside College Prep)** INSPECTION DATE: **4/17/2013**
ADDRESS: **250 E. 111th St.** IDPH LICENSE NO: **100-19036**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **114 (CT1)**
MATERIAL DESCRIPTION: **12x12 ceiling tile (ABATED)**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Main Building: 1st floor west wing near NW corner**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **04/17/2013**

Chicago Public Schools

GSG Consultants, Inc.
2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47051** BUILDING ID: **1500**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**
SCHOOL NAME: **Brooks College Prep
(Southside College
Prep)** REVIEW DATE: **5/13/2013**
ADDRESS: **250 E. 111th St.** IDPH LICENSE NO: **100-19036**

HOMOGENEOUS AREA: **114 (CT1)**
MATERIAL DESCRIPTION: **12x12 ceiling tile (ABATED)**
MATERIAL LOCATION: **Main Building: 1st floor west wing near NW corner**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: 05/13/2013

Chicago Public Schools

GSG Consultants, Inc. 2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47051** BUIDLING ID: **1500**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ismael Hernandez**
SCHOOL NAME: **Brooks College Prep (Southside College Prep)** INSPECTION DATE: **4/17/2013**
ADDRESS: **250 E. 111th St.** IDPH LICENSE NO: **100-19036**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **114 (CTM1)**
MATERIAL DESCRIPTION: **12x12 ceiling tile mastic (ABATED)**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:


MATERIAL LOCATION: **Main Building: 1st floor west wing near NW corner**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **04/17/2013**

Chicago Public Schools

GSG Consultants, Inc.
2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47051** BUILDING ID: **1500**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**
SCHOOL NAME: **Brooks College Prep
(Southside College
Prep)** REVIEW DATE: **5/13/2013**
ADDRESS: **250 E. 111th St.** IDPH LICENSE NO: **100-19036**

HOMOGENEOUS AREA: **114 (CTM1)**
MATERIAL DESCRIPTION: **12x12 ceiling tile mastic (ABATED)**
MATERIAL LOCATION: **Main Building: 1st floor west wing near NW corner**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: 05/13/2013

Chicago Public Schools

GSG Consultants, Inc. 2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47051** BUIDLING ID: **1500**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ismael Hernandez**
SCHOOL NAME: **Brooks College Prep (Southside College Prep)** INSPECTION DATE: **4/17/2013**
ADDRESS: **250 E. 111th St.** IDPH LICENSE NO: **100-19036**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **116**
MATERIAL DESCRIPTION: **12x12 cork tile (ABATED)**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:


MATERIAL LOCATION: **Main Building: 2nd floor west wing room NE. corner of bldg.**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **04/17/2013**

Chicago Public Schools

GSG Consultants, Inc. 2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47051** BUILDING ID: **1500**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**
SCHOOL NAME: **Brooks College Prep
(Southside College
Prep)** REVIEW DATE: **5/13/2013**
ADDRESS: **250 E. 111th St.** IDPH LICENSE NO: **100-19036**

HOMOGENEOUS AREA: **116**
MATERIAL DESCRIPTION: **12x12 cork tile (ABATED)**
MATERIAL LOCATION: **Main Building: 2nd floor west wing room NE. corner of bldg.**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: 05/13/2013

Chicago Public Schools

GSG Consultants, Inc. 2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47051** BUIDLING ID: **1500**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ismael Hernandez**
SCHOOL NAME: **Brooks College Prep (Southside College Prep)** INSPECTION DATE: **4/17/2013**
ADDRESS: **250 E. 111th St.** IDPH LICENSE NO: **100-19036**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **151**
MATERIAL DESCRIPTION: **NOT OBSERVED FLOOR TILE REPLACEMENT 12X12VFT/GREY/DARK BRN**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1ST FL., 2ND FL., 3RD FLOORS HALLWAYS**
MATERIAL QUANTITY: **50000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature:



Date: **04/17/2013**

Chicago Public Schools

GSG Consultants, Inc.

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47051** BUIDLING ID: **1500**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**
SCHOOL NAME: **Brooks College Prep
(Southside College
Prep)** REVIEW DATE: **5/13/2013**
ADDRESS: **250 E. 111th St.** IDPH LICENSE NO: **100-19036**

HOMOGENEOUS AREA: **151**
MATERIAL DESCRIPTION: **NOT OBSERVED FLOOR TILE REPLACEMENT12X12VFT/GREY/DARK BRN**
MATERIAL LOCATION: **1ST FL. ,2ND FL.,3RD FLOORS HALLWAYS**
MATERIAL QUANTITY: **50000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **05/13/2013**

Chicago Public Schools

GSG Consultants, Inc.
2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47051** BUIDLING ID: **1500**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ismael Hernandez**
SCHOOL NAME: **Brooks College Prep (Southside College Prep)** INSPECTION DATE: **4/17/2013**
ADDRESS: **250 E. 111th St.** IDPH LICENSE NO: **100-19036**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **152**
MATERIAL DESCRIPTION: **MASTIC**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1ST FL., 2ND FL., 3RD FL. THROUGHOUT BLD. BASE BOARD**
MATERIAL QUANTITY: **50000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____



Date: 04/17/2013

Chicago Public Schools

GSG Consultants, Inc.

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47051** BUILDING ID: **1500**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**
SCHOOL NAME: **Brooks College Prep (Southside College Prep)** REVIEW DATE: **5/13/2013**
ADDRESS: **250 E. 111th St.** IDPH LICENSE NO: **100-19036**

HOMOGENEOUS AREA: **152**
MATERIAL DESCRIPTION: **MASTIC**
MATERIAL LOCATION: **1ST FL., 2ND FL., 3RD FL. THROUGHOUT BLD. BASE BOARD**
MATERIAL QUANTITY: **50000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **05/13/2013**

Chicago Public Schools

GSG Consultants, Inc.
2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47051** BUIDLING ID: **1500**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ismael Hernandez**
SCHOOL NAME: **Brooks College Prep (Southside College Prep)** INSPECTION DATE: **4/17/2013**
ADDRESS: **250 E. 111th St.** IDPH LICENSE NO: **100-19036**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **153**
MATERIAL DESCRIPTION: **2'x4' Speckled Pattern Ceiling Tile (w/ 2'x2' Sections)**
HISTORICAL AHERA DAMAGE CATEGORY **6**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **1st Floo: West Wing - Dining Room: 4th Floor: Center Building - Room 402 and 405**

MATERIAL QUANTITY: **1350** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 04/17/2013

Chicago Public Schools

GSG Consultants, Inc.
2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47051** BUILDING ID: **1500**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**
SCHOOL NAME: **Brooks College Prep (Southside College Prep)** REVIEW DATE: **5/13/2013**
ADDRESS: **250 E. 111th St.** IDPH LICENSE NO: **100-19036**

HOMOGENEOUS AREA: **153**
MATERIAL DESCRIPTION: **2'x4' Speckled Pattern Ceiling Tile (w/ 2'x2' Sections)**
MATERIAL LOCATION: **1st Floor: West Wing - Dining Room: 4th Floor: Center Building - Room 402 and 405**
MATERIAL QUANTITY: **1350** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **05/13/2013**

Chicago Public Schools

GSG Consultants, Inc. 2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47051** BUIDLING ID: **1500**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ismael Hernandez**
SCHOOL NAME: **Brooks College Prep (Southside College Prep)** INSPECTION DATE: **4/17/2013**
ADDRESS: **250 E. 111th St.** IDPH LICENSE NO: **100-19036**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **154**
MATERIAL DESCRIPTION: **4" Vinyl Baseboard - Grey**
HISTORICAL AHERA DAMAGE CATEGORY **6**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **1st Floor: West Wing - Dining Room; 4th Floor: Center Building - Room 400, 400A, 400A-1, 402, 404, 404A, 404C, 404D, and 405**

MATERIAL QUANTITY: **1100** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: _____



Date: 04/17/2013

Chicago Public Schools

GSG Consultants, Inc.
2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47051** BUILDING ID: **1500**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**
SCHOOL NAME: **Brooks College Prep (Southside College Prep)** REVIEW DATE: **5/13/2013**
ADDRESS: **250 E. 111th St.** IDPH LICENSE NO: **100-19036**

HOMOGENEOUS AREA: **154**
MATERIAL DESCRIPTION: **4" Vinyl Baseboard - Grey**
MATERIAL LOCATION: **1st Floor: West Wing - Dining Room; 4th Floor: Center Building - Room 400, 400A, 400A-1, 402, 404, 404A, 404C, 404D, and 405**
MATERIAL QUANTITY: **1100** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **05/13/2013**

Chicago Public Schools

GSG Consultants, Inc.
2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47051** BUIDLING ID: **1500**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ismael Hernandez**
SCHOOL NAME: **Brooks College Prep (Southside College Prep)** INSPECTION DATE: **4/17/2013**
ADDRESS: **250 E. 111th St.** IDPH LICENSE NO: **100-19036**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **155**
MATERIAL DESCRIPTION: **Mastic associated with 4" Vinyl Baseboard - Grey**
HISTORICAL AHERA DAMAGE CATEGORY **6**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **1st Floor: West Wing - Dining Room; 4th Floor: Center Building - Room 400, 400A, 400A-1, 402, 404, 404A, 404C, 404D, and 405**

MATERIAL QUANTITY: **1100** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: _____



Date: 04/17/2013

Chicago Public Schools

GSG Consultants, Inc.

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47051** BUILDING ID: **1500**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**
SCHOOL NAME: **Brooks College Prep (Southside College Prep)** REVIEW DATE: **5/13/2013**
ADDRESS: **250 E. 111th St.** IDPH LICENSE NO: **100-19036**

HOMOGENEOUS AREA: **155**
MATERIAL DESCRIPTION: **Mastic associated with 4" Vinyl Baseboard - Grey**
MATERIAL LOCATION: **1st Floor: West Wing - Dining Room; 4th Floor: Center Building - Room 400, 400A, 400A-1, 402, 404, 404A, 404C, 404D, and 405**
MATERIAL QUANTITY: **1100** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **05/13/2013**

Chicago Public Schools

GSG Consultants, Inc. 2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47051** BUIDLING ID: **1500**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ismael Hernandez**
SCHOOL NAME: **Brooks College Prep (Southside College Prep)** INSPECTION DATE: **4/17/2013**
ADDRESS: **250 E. 111th St.** IDPH LICENSE NO: **100-19036**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **156**
MATERIAL DESCRIPTION: **12"x12" White with Grey Specs Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **1st Floor: East Wing - Rooms 131, 133, 135, 137, and 139**

MATERIAL QUANTITY: **5350**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 04/17/2013

Chicago Public Schools

GSG Consultants, Inc.

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47051** BUILDING ID: **1500**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**
SCHOOL NAME: **Brooks College Prep
(Southside College
Prep)** REVIEW DATE: **5/13/2013**
ADDRESS: **250 E. 111th St.** IDPH LICENSE NO: **100-19036**

HOMOGENEOUS AREA: **156**
MATERIAL DESCRIPTION: **12"x12" White with Grey Specs Floor Tile**
MATERIAL LOCATION: **1st Floor: East Wing - Rooms 131, 133, 135, 137, and 139**
MATERIAL QUANTITY: **5350** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **05/13/2013**

Chicago Public Schools

GSG Consultants, Inc.
2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47051** BUIDLING ID: **1500**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ismael Hernandez**
SCHOOL NAME: **Brooks College Prep (Southside College Prep)** INSPECTION DATE: **4/17/2013**
ADDRESS: **250 E. 111th St.** IDPH LICENSE NO: **100-19036**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **157**
MATERIAL DESCRIPTION: **12"x12" White with Grey Specs Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1st Floor: East Wing - Rooms 131, 133, 135, 137, and 139**
MATERIAL QUANTITY: **5350** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____



Date: 04/17/2013

Chicago Public Schools

GSG Consultants, Inc.

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47051** BUILDING ID: **1500**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**
SCHOOL NAME: **Brooks College Prep
(Southside College
Prep)** REVIEW DATE: **5/13/2013**
ADDRESS: **250 E. 111th St.** IDPH LICENSE NO: **100-19036**

HOMOGENEOUS AREA: **157**
MATERIAL DESCRIPTION: **12"x12" White with Grey Specs Floor Tile Mastic**
MATERIAL LOCATION: **1st Floor: East Wing - Rooms 131, 133, 135, 137, and 139**
MATERIAL QUANTITY: **5350** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **05/13/2013**

Chicago Public Schools

GSG Consultants, Inc.
2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47051** BUIDLING ID: **1500**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ismael Hernandez**
SCHOOL NAME: **Brooks College Prep (Southside College Prep)** INSPECTION DATE: **4/17/2013**
ADDRESS: **250 E. 111th St.** IDPH LICENSE NO: **100-19036**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **158**
MATERIAL DESCRIPTION: **2'x2' Smooth Pattern Ceiling Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **1st Floor: East Wing - Rooms 131, 133, 135, 137, and 139, and North/South Corridor**

MATERIAL QUANTITY: **7375** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 04/17/2013

Chicago Public Schools

GSG Consultants, Inc.

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47051** BUILDING ID: **1500**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**
SCHOOL NAME: **Brooks College Prep
(Southside College
Prep)** REVIEW DATE: **5/13/2013**
ADDRESS: **250 E. 111th St.** IDPH LICENSE NO: **100-19036**

HOMOGENEOUS AREA: **158**
MATERIAL DESCRIPTION: **2'x2' Smooth Pattern Ceiling Tile**
MATERIAL LOCATION: **1st Floor: East Wing - Rooms 131, 133, 135, 137, and 139, and North/South Corridor**
MATERIAL QUANTITY: **7375** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **05/13/2013**

Chicago Public Schools

GSG Consultants, Inc. 2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47051** BUIDLING ID: **1500**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ismael Hernandez**
SCHOOL NAME: **Brooks College Prep (Southside College Prep)** INSPECTION DATE: **4/17/2013**
ADDRESS: **250 E. 111th St.** IDPH LICENSE NO: **100-19036**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **159**
MATERIAL DESCRIPTION: **Interior Window Caulk**
HISTORICAL AHERA DAMAGE CATEGORY **6**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **1st Floor: East Wing - Room 131, 133, 135, 137, and 139; 4th Floor: Center Building - Room 400, 400A, 400A-1, 402, 404, 404A, 404C, 404D, and 405**

MATERIAL QUANTITY: **400** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: _____



Date: 04/17/2013

Chicago Public Schools

GSG Consultants, Inc.

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47051** BUILDING ID: **1500**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**
SCHOOL NAME: **Brooks College Prep (Southside College Prep)** REVIEW DATE: **5/13/2013**
ADDRESS: **250 E. 111th St.** IDPH LICENSE NO: **100-19036**

HOMOGENEOUS AREA: **159**
MATERIAL DESCRIPTION: **Interior Window Caulk**
MATERIAL LOCATION: **1st Floor: East Wing - Room 131, 133, 135, 137, and 139; 4th Floor: Center Building - Room 400, 400A, 400A-1, 402, 404, 404A, 404C, 404D, and 405**
MATERIAL QUANTITY: **400** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **05/13/2013**

Chicago Public Schools

GSG Consultants, Inc.
2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 47051 BUILDING ID: 1500
CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Ismael Hernandez
SCHOOL NAME: Brooks College Prep (Southside College Prep) INSPECTION DATE: 4/17/2013
ADDRESS: 250 E. 111th St. IDPH LICENSE NO: 100-19036

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 160
MATERIAL DESCRIPTION: Terrazzo Floor
HISTORICAL AHERA DAMAGE CATEGORY 6
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: Operations and Maintenance
ASBESTOS TYPE: Assumed FRIABLE: No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW
MATERIAL LOCATION: 1st Floor: East Wing - North/South Corridor
MATERIAL QUANTITY: 2025 MATERIAL UNITS: SF
DAMAGE QUANTITY: DAMAGE UNITS: SF
COMMENTS:

Inspector's Signature: _____



Date: 04/17/2013

Chicago Public Schools

GSG Consultants, Inc.
2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47051** BUIDLING ID: **1500**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**
SCHOOL NAME: **Brooks College Prep
(Southside College
Prep)** REVIEW DATE: **5/13/2013**
ADDRESS: **250 E. 111th St.** IDPH LICENSE NO: **100-19036**

HOMOGENEOUS AREA: **160**
MATERIAL DESCRIPTION: **Terrazzo Floor**
MATERIAL LOCATION: **1st Floor: East Wing - North/South Corridor**
MATERIAL QUANTITY: **2025** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **05/13/2013**

Chicago Public Schools

GSG Consultants, Inc. 2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47051** BUIDLING ID: **1500**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ismael Hernandez**
SCHOOL NAME: **Brooks College Prep (Southside College Prep)** INSPECTION DATE: **4/17/2013**
ADDRESS: **250 E. 111th St.** IDPH LICENSE NO: **100-19036**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **161**
MATERIAL DESCRIPTION: **12"x12" Grey Speckled Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **4th Floor: Center Building - Room 400, 400A, 400A-1, 402, 404, 404A, 404C, 404D, and 405**

MATERIAL QUANTITY: **2600** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 04/17/2013

Chicago Public Schools

GSG Consultants, Inc. 2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47051** BUILDING ID: **1500**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**
SCHOOL NAME: **Brooks College Prep
(Southside College
Prep)** REVIEW DATE: **5/13/2013**
ADDRESS: **250 E. 111th St.** IDPH LICENSE NO: **100-19036**

HOMOGENEOUS AREA: **161**
MATERIAL DESCRIPTION: **12"x12" Grey Speckled Floor Tile**
MATERIAL LOCATION: **4th Floor: Center Building - Room 400, 400A, 400A-1, 402, 404, 404A, 404C, 404D, and 405**
MATERIAL QUANTITY: **2600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **05/13/2013**

Chicago Public Schools

GSG Consultants, Inc. 2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47051** BUIDLING ID: **1500**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ismael Hernandez**
SCHOOL NAME: **Brooks College Prep (Southside College Prep)** INSPECTION DATE: **4/17/2013**
ADDRESS: **250 E. 111th St.** IDPH LICENSE NO: **100-19036**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **162**
MATERIAL DESCRIPTION: **12"x12" Grey Speckled Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **4th Floor: Center Building - Room 400, 400A, 400A-1, 402, 404, 404A, 404C, 404D, and 405**

MATERIAL QUANTITY: **2600** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 04/17/2013

Chicago Public Schools

GSG Consultants, Inc.
2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47051** BUILDING ID: **1500**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**
SCHOOL NAME: **Brooks College Prep
(Southside College
Prep)** REVIEW DATE: **5/13/2013**
ADDRESS: **250 E. 111th St.** IDPH LICENSE NO: **100-19036**

HOMOGENEOUS AREA: **162**
MATERIAL DESCRIPTION: **12"x12" Grey Speckled Floor Tile Mastic**
MATERIAL LOCATION: **4th Floor: Center Building - Room 400, 400A, 400A-1, 402, 404, 404A, 404C, 404D, and 405**
MATERIAL QUANTITY: **2600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **05/13/2013**

Chicago Public Schools

GSG Consultants, Inc.
2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 47051 BUILDING ID: 1500
CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Ismael Hernandez
SCHOOL NAME: Brooks College Prep (Southside College Prep) INSPECTION DATE: 4/17/2013
ADDRESS: 250 E. 111th St. IDPH LICENSE NO: 100-19036

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 163
MATERIAL DESCRIPTION: Black Sink Undercoat
HISTORICAL AHERA DAMAGE CATEGORY 6
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: Operations and Maintenance
ASBESTOS TYPE: Assumed FRIABLE: No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **4th Floor: Center Building - Room 400**

MATERIAL QUANTITY: **1** MATERIAL UNITS: **EA**

DAMAGE QUANTITY: DAMAGE UNITS: **EA**

COMMENTS:

Inspector's Signature: _____



Date: 04/17/2013

Chicago Public Schools

GSG Consultants, Inc. 2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47051** BUILDING ID: **1500**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**
SCHOOL NAME: **Brooks College Prep
(Southside College
Prep)** REVIEW DATE: **5/13/2013**
ADDRESS: **250 E. 111th St.** IDPH LICENSE NO: **100-19036**

HOMOGENEOUS AREA: **163**
MATERIAL DESCRIPTION: **Black Sink Undercoat**
MATERIAL LOCATION: **4th Floor: Center Building - Room 400**
MATERIAL QUANTITY: **1** MATERIAL UNITS: **EA**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **EA**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **05/13/2013**

Chicago Public Schools

GSG Consultants, Inc.
2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47051** BUIDLING ID: **1500**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ismael Hernandez**
SCHOOL NAME: **Brooks College Prep (Southside College Prep)** INSPECTION DATE: **4/17/2013**
ADDRESS: **250 E. 111th St.** IDPH LICENSE NO: **100-19036**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **164**
MATERIAL DESCRIPTION: **Black Counter Top**
HISTORICAL AHERA DAMAGE CATEGORY **6**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **4th Floor: Center Building - Room 400 and 400A**
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____



Date: 04/17/2013

Chicago Public Schools

GSG Consultants, Inc. 2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47051** BUILDING ID: **1500**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**
SCHOOL NAME: **Brooks College Prep
(Southside College
Prep)** REVIEW DATE: **5/13/2013**
ADDRESS: **250 E. 111th St.** IDPH LICENSE NO: **100-19036**

HOMOGENEOUS AREA: **164**
MATERIAL DESCRIPTION: **Black Counter Top**
MATERIAL LOCATION: **4th Floor: Center Building - Room 400 and 400A**
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **05/13/2013**

Chicago Public Schools

GSG Consultants, Inc.
2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47051** BUIDLING ID: **1500**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ismael Hernandez**
SCHOOL NAME: **Brooks College Prep (Southside College Prep)** INSPECTION DATE: **4/17/2013**
ADDRESS: **250 E. 111th St.** IDPH LICENSE NO: **100-19036**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **165**
MATERIAL DESCRIPTION: **Drywall**
HISTORICAL AHERA DAMAGE CATEGORY **6**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **4th Floor: Center Building - Room 400, 400A, and 404**

MATERIAL QUANTITY: **4600** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 04/17/2013

Chicago Public Schools

GSG Consultants, Inc. 2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47051** BUILDING ID: **1500**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**
SCHOOL NAME: **Brooks College Prep
(Southside College
Prep)** REVIEW DATE: **5/13/2013**
ADDRESS: **250 E. 111th St.** IDPH LICENSE NO: **100-19036**

HOMOGENEOUS AREA: **165**
MATERIAL DESCRIPTION: **Drywall**
MATERIAL LOCATION: **4th Floor: Center Building - Room 400, 400A, and 404**
MATERIAL QUANTITY: **4600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **05/13/2013**

Chicago Public Schools

GSG Consultants, Inc.

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47051** BUIDLING ID: **1500**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ismael Hernandez**
SCHOOL NAME: **Brooks College Prep (Southside College Prep)** INSPECTION DATE: **4/17/2013**
ADDRESS: **250 E. 111th St.** IDPH LICENSE NO: **100-19036**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **166**
MATERIAL DESCRIPTION: **Drywall Joint Compound**
HISTORICAL AHERA DAMAGE CATEGORY **6**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **4th Floor: Center Building - Room 400, 400A, and 404**

MATERIAL QUANTITY: **4600** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 04/17/2013

Chicago Public Schools

GSG Consultants, Inc.

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47051** BUILDING ID: **1500**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**
SCHOOL NAME: **Brooks College Prep
(Southside College
Prep)** REVIEW DATE: **5/13/2013**
ADDRESS: **250 E. 111th St.** IDPH LICENSE NO: **100-19036**

HOMOGENEOUS AREA: **166**
MATERIAL DESCRIPTION: **Drywall Joint Compound**
MATERIAL LOCATION: **4th Floor: Center Building - Room 400, 400A, and 404**
MATERIAL QUANTITY: **4600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **05/13/2013**

Chicago Public Schools

GSG Consultants, Inc.
2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47051** BUIDLING ID: **1500**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ismael Hernandez**
SCHOOL NAME: **Brooks College Prep (Southside College Prep)** INSPECTION DATE: **4/17/2013**
ADDRESS: **250 E. 111th St.** IDPH LICENSE NO: **100-19036**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **167**
MATERIAL DESCRIPTION: **Sheet Flooring - Brown Multi-Color Pattern**
HISTORICAL AHERA DAMAGE CATEGORY **6**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **1st Floor: West Wing - Dining Room**

MATERIAL QUANTITY: **1350**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 04/17/2013

Chicago Public Schools

GSG Consultants, Inc. 2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47051** BUILDING ID: **1500**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**
SCHOOL NAME: **Brooks College Prep
(Southside College
Prep)** REVIEW DATE: **5/13/2013**
ADDRESS: **250 E. 111th St.** IDPH LICENSE NO: **100-19036**

HOMOGENEOUS AREA: **167**
MATERIAL DESCRIPTION: **Sheet Flooring - Brown Multi-Color Pattern**
MATERIAL LOCATION: **1st Floor: West Wing - Dining Room**
MATERIAL QUANTITY: **1350** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **05/13/2013**

Chicago Public Schools

GSG Consultants, Inc.
2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47051** BUIDLING ID: **1500**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ismael Hernandez**
SCHOOL NAME: **Brooks College Prep (Southside College Prep)** INSPECTION DATE: **4/17/2013**
ADDRESS: **250 E. 111th St.** IDPH LICENSE NO: **100-19036**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **168**
MATERIAL DESCRIPTION: **Sheet Flooring - Brown Multi-Color Pattern Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **1st Floor: West Wing - Dining Room**

MATERIAL QUANTITY: **1350**


MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 04/17/2013

Chicago Public Schools

GSG Consultants, Inc.

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47051** BUILDING ID: **1500**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**
SCHOOL NAME: **Brooks College Prep
(Southside College
Prep)** REVIEW DATE: **5/13/2013**
ADDRESS: **250 E. 111th St.** IDPH LICENSE NO: **100-19036**

HOMOGENEOUS AREA: **168**
MATERIAL DESCRIPTION: **Sheet Flooring - Brown Multi-Color Pattern Mastic**
MATERIAL LOCATION: **1st Floor: West Wing - Dining Room**
MATERIAL QUANTITY: **1350** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **05/13/2013**

Chicago Public Schools

GSG Consultants, Inc.
2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47051** BUIDLING ID: **1500**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ismael Hernandez**
SCHOOL NAME: **Brooks College Prep (Southside College Prep)** INSPECTION DATE: **4/17/2013**
ADDRESS: **250 E. 111th St.** IDPH LICENSE NO: **100-19036**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **169**
MATERIAL DESCRIPTION: **White Sink Undercoat**
HISTORICAL AHERA DAMAGE CATEGORY **6**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **4th Floor: Center Building - Room 404**

MATERIAL QUANTITY: **1**


MATERIAL UNITS: **EA**

DAMAGE QUANTITY:

DAMAGE UNITS: **EA**

COMMENTS:

Inspector's Signature: _____



Date: 04/17/2013

Chicago Public Schools

GSG Consultants, Inc.
2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47051** BUILDING ID: **1500**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**
SCHOOL NAME: **Brooks College Prep
(Southside College
Prep)** REVIEW DATE: **5/13/2013**
ADDRESS: **250 E. 111th St.** IDPH LICENSE NO: **100-19036**

HOMOGENEOUS AREA: **169**
MATERIAL DESCRIPTION: **White Sink Undercoat**
MATERIAL LOCATION: **4th Floor: Center Building - Room 404**
MATERIAL QUANTITY: **1** MATERIAL UNITS: **EA**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **EA**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **05/13/2013**

Chicago Public Schools

GSG Consultants, Inc.
2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47051** BUIDLING ID: **1500**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ismael Hernandez**
SCHOOL NAME: **Brooks College Prep (Southside College Prep)** INSPECTION DATE: **4/17/2013**
ADDRESS: **250 E. 111th St.** IDPH LICENSE NO: **100-19036**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **21**
MATERIAL DESCRIPTION: **12 x 12 Yellow Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms 106, 200-206, 208, 209, 210, 216, Library, Office, and Coach's Office**
MATERIAL QUANTITY: **12500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____



Date: 04/17/2013

Chicago Public Schools

GSG Consultants, Inc.

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47051** BUILDING ID: **1500**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**
SCHOOL NAME: **Brooks College Prep (Southside College Prep)** REVIEW DATE: **5/13/2013**
ADDRESS: **250 E. 111th St.** IDPH LICENSE NO: **100-19036**

HOMOGENEOUS AREA: **21**
MATERIAL DESCRIPTION: **12 x 12 Yellow Floor Tile Mastic**
MATERIAL LOCATION: **Rooms 106, 200-206, 208, 209, 210, 216, Library, Office, and Coach's Office**
MATERIAL QUANTITY: **12500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **05/13/2013**

Chicago Public Schools

GSG Consultants, Inc.
2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47051** BUIDLING ID: **1500**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ismael Hernandez**
SCHOOL NAME: **Brooks College Prep (Southside College Prep)** INSPECTION DATE: **4/17/2013**
ADDRESS: **250 E. 111th St.** IDPH LICENSE NO: **100-19036**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **22**
MATERIAL DESCRIPTION: **Brown Carpet Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**


MATERIAL LOCATION: **Library, Assistant Principals, Nurse Office, Side Office, 102, 103, 111, 117, and Office Hall**

MATERIAL QUANTITY: **6000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 04/17/2013

Chicago Public Schools

GSG Consultants, Inc.

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47051** BUILDING ID: **1500**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**
SCHOOL NAME: **Brooks College Prep (Southside College Prep)** REVIEW DATE: **5/13/2013**
ADDRESS: **250 E. 111th St.** IDPH LICENSE NO: **100-19036**

HOMOGENEOUS AREA: **22**
MATERIAL DESCRIPTION: **Brown Carpet Mastic**
MATERIAL LOCATION: **Library, Assistant Principals, Nurse Office, Side Office, 102, 103, 111, 117, and Office Hall**
MATERIAL QUANTITY: **6000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **05/13/2013**

Chicago Public Schools

GSG Consultants, Inc. 2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47051** BUIDLING ID: **1500**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ismael Hernandez**
SCHOOL NAME: **Brooks College Prep (Southside College Prep)** INSPECTION DATE: **4/17/2013**
ADDRESS: **250 E. 111th St.** IDPH LICENSE NO: **100-19036**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **26**
MATERIAL DESCRIPTION: **12 x 12 Gray Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Band Room, 4th Floor, 403, 407, Office, Bathroom, West Side, 100, 101, Attendance Office**

MATERIAL QUANTITY: **12500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 04/17/2013

Chicago Public Schools

GSG Consultants, Inc. 2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47051** BUILDING ID: **1500**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**
SCHOOL NAME: **Brooks College Prep
(Southside College
Prep)** REVIEW DATE: **5/13/2013**
ADDRESS: **250 E. 111th St.** IDPH LICENSE NO: **100-19036**

HOMOGENEOUS AREA: **26**
MATERIAL DESCRIPTION: **12 x 12 Gray Floor Tile Mastic**
MATERIAL LOCATION: **Band Room, 4th Floor, 403, 407, Office, Bathroom, West Side, 100, 101, Attendance Office**
MATERIAL QUANTITY: **12500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **05/13/2013**

Chicago Public Schools

GSG Consultants, Inc.
2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47051** BUIDLING ID: **1500**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ismael Hernandez**
SCHOOL NAME: **Brooks College Prep (Southside College Prep)** INSPECTION DATE: **4/17/2013**
ADDRESS: **250 E. 111th St.** IDPH LICENSE NO: **100-19036**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **27**
MATERIAL DESCRIPTION: **2 x 4 Lay-in Panels NOT OBSERVED**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Kitchen-NOT OBSERVED**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____



Date: 04/17/2013

Chicago Public Schools

GSG Consultants, Inc. 2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47051** BUILDING ID: **1500**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**
SCHOOL NAME: **Brooks College Prep
(Southside College
Prep)** REVIEW DATE: **5/13/2013**
ADDRESS: **250 E. 111th St.** IDPH LICENSE NO: **100-19036**

HOMOGENEOUS AREA: **27**
MATERIAL DESCRIPTION: **2 x 4 Lay-in Panels NOT OBSERVED**
MATERIAL LOCATION: **Kitchen-NOT OBSERVED**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **05/13/2013**

Chicago Public Schools

GSG Consultants, Inc.
2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47051** BUIDLING ID: **1500**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ismael Hernandez**
SCHOOL NAME: **Brooks College Prep (Southside College Prep)** INSPECTION DATE: **4/17/2013**
ADDRESS: **250 E. 111th St.** IDPH LICENSE NO: **100-19036**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **28**
MATERIAL DESCRIPTION: **Spray-on Insulation**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Gymnasium**

MATERIAL QUANTITY: **3000**


MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 04/17/2013

Chicago Public Schools

GSG Consultants, Inc.
2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47051** BUILDING ID: **1500**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**
SCHOOL NAME: **Brooks College Prep
(Southside College
Prep)** REVIEW DATE: **5/13/2013**
ADDRESS: **250 E. 111th St.** IDPH LICENSE NO: **100-19036**

HOMOGENEOUS AREA: **28**
MATERIAL DESCRIPTION: **Spray-on Insulation**
MATERIAL LOCATION: **Gymnasium**
MATERIAL QUANTITY: **3000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **05/13/2013**

Chicago Public Schools

GSG Consultants, Inc.
2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47051** BUIDLING ID: **1500**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ismael Hernandez**
SCHOOL NAME: **Brooks College Prep (Southside College Prep)** INSPECTION DATE: **4/17/2013**
ADDRESS: **250 E. 111th St.** IDPH LICENSE NO: **100-19036**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **29**
MATERIAL DESCRIPTION: **2 x 2 Lay-in Ceiling Panels**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Hallways**

MATERIAL QUANTITY: **20000**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 04/17/2013

Chicago Public Schools

GSG Consultants, Inc.

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47051** BUILDING ID: **1500**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**
SCHOOL NAME: **Brooks College Prep
(Southside College
Prep)** REVIEW DATE: **5/13/2013**
ADDRESS: **250 E. 111th St.** IDPH LICENSE NO: **100-19036**

HOMOGENEOUS AREA: **29**
MATERIAL DESCRIPTION: **2 x 2 Lay-in Ceiling Panels**
MATERIAL LOCATION: **Hallways**
MATERIAL QUANTITY: **20000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **05/13/2013**

Chicago Public Schools

GSG Consultants, Inc.
2013 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47051** BUILDING ID: **1500**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ismael Hernandez**
SCHOOL NAME: **Brooks College Prep
(Southside College Prep)** INSPECTION DATE: **4/17/2013**
ADDRESS: **250 E. 111th St.** IDPH LICENSE NO: **100-19036**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **172**
MATERIAL DESCRIPTION: **Carpet Mastic Brown w/ blue and orange streaks**
MATERIAL LOCATION: **Rooms 147, 153A, 153C, 153D, 153E, 153F, 153F2, 235, 237A, 237D and Library**
MATERIAL QUANTITY: **10300** MATERIAL UNITS: **SF**
MATERIAL CATEGORY: **MISC** FRIABLE: **No**
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **LOW** CONDITION:
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
ACCESSIBILITY: **Barely Reachable** DAMAGE REASON:
DAMAGE QUANTITY: **0** DAMAGE REASON:
DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____



Date: 04/17/2013

Chicago Public Schools

GSG Consultants, Inc. 2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47051** BUILDING ID: **1500**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**
SCHOOL NAME: **Brooks College Prep** REVIEW DATE: **5/13/2013**
(Southside College Prep)
ADDRESS: **250 E. 111th St.** IDPH LICENSE NO: **100-19036**

HOMOGENEOUS AREA: **172**
MATERIAL DESCRIPTION: **Carpet Mastic Brown w/ blue and orange streaks**
MATERIAL LOCATION: **Rooms 147, 153A, 153C, 153D, 153E, 153F, 153F2, 235, 237A, 237D and Library**
MATERIAL QUANTITY: **10300** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:  Date: 05/13/2013

Chicago Public Schools

GSG Consultants, Inc.
2013 AHERA REINSPECTION


Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47051** BUILDING ID: **1500**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ismael Hernandez**
SCHOOL NAME: **Brooks College Prep** INSPECTION DATE: **4/17/2013**
(Southside College Prep)
ADDRESS: **250 E. 111th St.** IDPH LICENSE NO: **100-19036**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **30**
MATERIAL DESCRIPTION: **Black Counter Tops**
MATERIAL LOCATION: **Rooms 307 and 307A**
MATERIAL QUANTITY: **26** MATERIAL UNITS: **SF**
MATERIAL CATEGORY: **MISC** FRIABLE: **No**
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **LOW** CONDITION:
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
ACCESSIBILITY: **Within Reach** DAMAGE REASON:
DAMAGE QUANTITY: **0** DAMAGE REASON:
DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____



Date: 04/17/2013

Chicago Public Schools

GSG Consultants, Inc. 2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47051** BUILDING ID: **1500**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**
SCHOOL NAME: **Brooks College Prep** REVIEW DATE: **5/13/2013**
(Southside College Prep)
ADDRESS: **250 E. 111th St.** IDPH LICENSE NO: **100-19036**

HOMOGENEOUS AREA: **30**
MATERIAL DESCRIPTION: **Black Counter Tops**
MATERIAL LOCATION: **Rooms 307 and 307A**
MATERIAL QUANTITY: **26** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:  Date: **05/13/2013**

HA-30



BUILDING B
FLOOR 3

Chicago Public Schools

GSG Consultants, Inc.
2013 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47051** BUILDING ID: **1500**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ismael Hernandez**
SCHOOL NAME: **Brooks College Prep
(Southside College Prep)** INSPECTION DATE: **4/17/2013**
ADDRESS: **250 E. 111th St.** IDPH LICENSE NO: **100-19036**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **170**
MATERIAL DESCRIPTION: **Carpet Mastic - Brown**
MATERIAL LOCATION: **Rooms 100 A, 100 C, 100 E, 100 F, 105, 111, 116A and 116B**
MATERIAL QUANTITY: **2200** MATERIAL UNITS: **SF**
MATERIAL CATEGORY: **MISC** FRIABLE: **No**
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **LOW** CONDITION:
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
ACCESSIBILITY: **Within Reach** DAMAGE REASON:
DAMAGE QUANTITY: **0** DAMAGE REASON:
DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____



Date: 04/17/2013

Chicago Public Schools

GSG Consultants, Inc. 2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47051** BUILDING ID: **1500**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**
SCHOOL NAME: **Brooks College Prep** REVIEW DATE: **5/13/2013**
(Southside College Prep)
ADDRESS: **250 E. 111th St.** IDPH LICENSE NO: **100-19036**

HOMOGENEOUS AREA: **170**
MATERIAL DESCRIPTION: **Carpet Mastic - Brown**
MATERIAL LOCATION: **Rooms 100 A, 100 C, 100 E, 100 F, 105, 111, 116A and 116B**
MATERIAL QUANTITY: **2200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.


The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:  Date: **05/13/2013**

HA170

4-15-2013 P.M. all outside doors 1st floor



Chicago Public Schools

GSG Consultants, Inc.
2013 AHERA REINSPECTION


Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47051** BUILDING ID: **1500**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ismael Hernandez**
SCHOOL NAME: **Brooks College Prep** INSPECTION DATE: **4/17/2013**
(Southside College Prep)
ADDRESS: **250 E. 111th St.** IDPH LICENSE NO: **100-19036**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **171**
MATERIAL DESCRIPTION: **Carpet Mastic Blue w/ white streaks**
MATERIAL LOCATION: **Rooms 201, 201A, 201C and 201D**
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**
MATERIAL CATEGORY: **MISC** FRIABLE: **No**
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **LOW** CONDITION:
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
ACCESSIBILITY: **Barely Reachable** DAMAGE REASON:
DAMAGE QUANTITY: **0** DAMAGE REASON:
DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____



Date: 04/17/2013

Chicago Public Schools

GSG Consultants, Inc. 2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **47051** BUILDING ID: **1500**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**
SCHOOL NAME: **Brooks College Prep** REVIEW DATE: **5/13/2013**
(Southside College Prep)
ADDRESS: **250 E. 111th St.** IDPH LICENSE NO: **100-19036**

HOMOGENEOUS AREA: **171**
MATERIAL DESCRIPTION: **Carpet Mastic Blue w/ white streaks**
MATERIAL LOCATION: **Rooms 201, 201A, 201C and 201D**
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:  Date: **05/13/2013**

HA-171



BUILDING B
FLOOR 2

APPENDIX B

Inspector and Management Planner Licenses



Occupational Training & Supply, Inc.

7233 Adams Street • Willowbrook, IL 60527 • (630) 655-3900

Asbestos Building Inspector

Occupational Training and Supply, Inc. certifies that

Ismael Hernandez

has successfully completed the 24 hour Asbestos Building Inspector Course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of recertification in accordance with EPA 10 CFR 763 Asbestos Hazard Emergency Response Act (AHERA) and TSCA Title II.

Certificate: ABII201100109

Exam Date: 1/10/2013

Course Date: 1/8/2013-1/10/2013

Expiration Date: 1/10/2014


Kathy Desolar, Director

2013

ENDORSEMENTS

TO EXPIRES

PROJECT MANAGER 2/1/2018
AIR SAMPLING PROFESSIONAL

*Alteration of this license shall result in legal action
This license issued under authority of the State of Illinois
Department of Public Health
This license is valid only when accompanied by a valid
training course certificate.*



**ASBESTOS
PROFESSIONAL
LICENSE**

ID NUMBER	ISSUED	EXPIRES
100 - 19038	1/31/2013	05/15/2014

ISMAEL HERNANDEZ
2835 N NAGLE AVE
CHICAGO, IL 60634

Environmental Health



CERTIFICATE OF ACHIEVEMENT ASBESTOS ABATEMENT

Approved by the Illinois Department of Public Health and Indiana Department of Environmental Management

This is to certify that GUILLERMO GARCIA
has completed the Contractor/Supervisor Recertification course and passed the examination
on 06/22/2012 with a minimum score of 70% or better. Training was in accordance with U.S.
E.P.A. 40 CFR 763 Subpart E, Appendix C, Asbestos Containing Materials in Schools; Model
Accreditation Plan, TSCA II, Authorized by both AHERA & ASHARA and Indiana Rule 326 IAC
18-2.



Nicholas J. Penneff

06/22/2012

Course Dates:

06/22/2013

Expires:

1206CSR01

Certificate Number:

Phone Number: (312) 491-0081

Director of Training

Nicholas J. Penneff

Doctor of Public Health

FORM # A-008



ASBESTOS PROFESSIONAL LICENSE

ID NUMBER
100 - 01786

ISSUED
7/24/2012

EXPIRES
09/15/2013

GUILLERMO GARCIA
855 W ADAMS ST SUITE 100
CHICAGO, IL 60607

Environmental Health



ENDORSEMENTS	TC EXPIRES
INSPECTOR	03/30/13
MANAGEMENT PLANNER	03/30/13
PROJECT MANAGER	02/28/13
AIR SAMPLING PROFESSIONAL	

Alteration of this license shall result in legal action
 This license issued under authority of the State of Illinois
 Department of Public Health
 This license is valid only when accompanied by a valid
 training course certificate.

APPENDIX C

Laboratory Accreditations

APPENDIX D

Laboratory Results

APPENDIX E

Chain of Custody Forms

Three-Year Reinspection Key to Terms

	CODE	KEY
MATERIAL		
	ACBM	Asbestos Containing Building Materials
MATERIAL CATEGORY		
	MISC	Miscellaneous
	SURF	Surfacing
	TSI	Thermal System Insulation
MATERIAL UNITS		
	LF	Linear Feet
	SF	Square Feet
	CF	Cubic Feet
DAMAGE TYPE		
	Loc	Localized
	Dist	Distributed