

ILLINOIS DEPARTMENT OF PUBLIC HEALTH
AHERA THREE YEAR REINSPECTION
ASBESTOS ABATEMENT PROGRAM
SCHOOL INFORMATION FORM

SECTION I

NAME OF SCHOOL DISTRICT: CHICAGO SCHOOL DIST 299
SCHOOL ID NUMBER: 14-016-2990-0531
SCHOOL NAME: Dunbar High School
ADDRESS OF SCHOOL: 3000 S. King Dr.
CITY: Chicago, IL, 60616

DATE LAST THREE YEAR REINSPECTION WAS COMPLETED **3/3/2010**

If the address on this form is different than the address of the building, submit a written explanation.

SECTION II (Please type or print)

PLEASE COMPLETE THE FOLLOWING FOR YOUR THREE YEAR REINSPECTION:

DATE REINSPECTION COMPLETED: 4/14/2013 ENROLLMENT 1162
IDPH INSPECTOR LICENSE NUMBER: 100-8785
IDPH LICENSED INSPECTOR NAME (Please Print): Kathy Yurks
IDPH MP LICENSE NUMBER: 100-09870
IDPH LICENSED MANAGEMENT PLANNER NAME (Please Print): Todd Huffer

DESIGNATED PERSON (Please Print): Ms. Lynn Crivello PHONE: (773) 553-3113



4/14/2013

Signature of Designated Person

Date

SECTION III

PLEASE COMPLETE THE FOLLOWING INFORMATION FOR ANY CHANGES WITHIN THE SCHOOL DISTRICT.

School building has been sold. Date of Sale: _____

School has been closed. Date closed: _____

School building has been demolished. Date: _____

School building is asbestos free since last reinspection: _____

Please explain in writing why the school building is now asbestos free and include the supporting documentation.

If a new school building has been added to the district, submit either an exclusionary statement or a management plan and inspection report. Include the complete name, address and city of school building.

Explain in writing if the address of the building is different than the address on this form:

THREE-YEAR REINSPECTION

CHICAGO SCHOOL DIST 299

Dunbar High School

3000 S. King Dr.
Chicago, IL, 60616

Unit: 53021
Building ID: 1030

IDPH ID Number: 14-016-2990-0531

REPORT DATE:

Sunday, April 14, 2013

Prepared for:

Chicago Public Schools
125 S. Clark Street
Chicago, IL 60603

Prepared by:

Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone (312) 762-2900

Fax (312) 782-5145

**DO NOT REMOVE FROM SCHOOL
REQUIRED BY FEDERAL LAW**

Environmental Notification to Occupants

To: Faculty, Staff and Parents
From: Chicago Public Schools
Date: March 14, 2013

RE: Dunbar High School, Unit 53021
3000 S. King Dr.
Chicago, IL, 60616

Dear Faculty, Staff and Parents,

This letter is to notify you that the 2013 asbestos three year re-inspection has been completed at Dunbar High School , following the Federal Asbestos Hazard Emergency Response Act (AHERA), 40 CFR Part 763, Subpart E and is available for your review at the main office of the school.

Although asbestos-containing materials have been identified at Dunbar High School, there is no reason to believe that any threat to the health of students or staff exists at this time. CPS will continue to carefully monitor the condition of asbestos-containing materials and if conditions warrant, all appropriate steps will be taken to maintain the health and safety of all building occupants.

If you have any questions regarding this matter or require additional information, please feel free to contact Ms. Lynn Crivello, the designated Local Education Authority's Designated Person at (773) 553-3113 .

Table of Contents

- I. School and Inspection Information
- II. Executive Summary
- III. Methodology
- IV. Abatement History
- V. Reassessments and Recommendations
- VI. Conclusions

Table I: Inspector's Reinspection Findings

Table II: Management Planner's Review

APPENDICES:

- Appendix A: Assessment Sheets, Drawings and Photos
- Appendix B: Inspector and Management Planner Licenses
- Appendix C: Laboratory Accreditations
- Appendix D: Laboratory Results
- Appendix E: Chain of Custody Forms

SCHOOL AND INSPECTION INFORMATION

1. School Information

School: Dunbar High School Unit: 53021 Region: 04
Address: 3000 S. King Dr. Chicago, IL, 60616
IDPH ID: 14-016-2990-0531 Building ID: 1030
Contact: Bishop, Antonio Phone: 7735349251

2. Description of Facility

Original Construction: Additional Construction:
Total Square Footage: 328800 No of Floors:
Current Occupancy: 1162

3. LEA Designated Person

Contact: Ms. Lynn Crivello Phone: (773) 553-3113
Address: 125 South Clark Street, 17th Floor
Chicago, IL 60603


4. Managing Environmental Consultant

MEC: Carnow, Conibear and Associates
Contact: Dan Juneau
Address 600 West Van Buren St., Ste 500
Phone: (312) 762-2900 Fax: (312) 782-5145

5. Inspector

Inspector Name: Kathy Yurks


Inspector IDPH license # 100-8785


Signature:
Date: 3/14/2013

6. Management Planner

Management Planner Name: Todd Huffer

Management Planner IDPH license # 100-09870


Signature:
Date: 4/14/2013

7. Review Date: 4/14/2013

8. LEA Designated Person's Acknowledgement

The reinspection report and recommendations have been received by me and appropriate action will be taken by the School District.


Signature:

Date: 4/14/2013

Name: Ms. Lynn Crivello

II. EXECUTIVE SUMMARY

Carnow, Conibear and Associates was retained by the Chicago Public Schools (CPS) to perform a three-year asbestos reinspection of the Dunbar High School. This inspection was conducted in accordance with the United States Environmental Protection Agency (USEPA) Asbestos Hazard Emergency Response Act (AHERA) part 763.92 (b), and the ongoing Operations and Maintenance Program (O&M) originally designed in the School's Asbestos Management Plan. The purpose of this three-year reinspection is to record any condition changes in the asbestos-containing building material (ACBM) in the school since the previous three-year reinspection and the six-month periodic surveillance, to identify, assess, and include any Homogeneous Areas (HA) not identified in the Management Plan, and to recommend an appropriate response action to manage asbestos.

The inspector conducted a three-year reinspection of this facility under Illinois Department of Public Health (IDPH) school reinspection requirements and AHERA, sections 763.85 and 763.88. The main building and each addition to the main building, if constructed at different dates, were inspected separately. Laboratory accreditations are included in Appendix C, laboratory results are included in Appendix D, and chain of custody forms are included in Appendix E.

Note: During previous inspections, some of the HA(s) were identified together as 9" x 9" floor tile (FT), mastics assoc. with 9" x 9" FT, 12" x 12" FT, mastics assoc. with 12" x 12" FT, pipe insulation, etc. Some of these HA(s) have been re-identified by areas that are uniform in color, texture, construction date, application date, and general appearance.

The inspector has determined the following:

A. The following HAs have changed assessment categories for Building 1030:

2 J	9" x 9" Brown Floor Tile w/ White Streaks
3 B	12"x12" Gray Floor Tile w/ White & Black Streaks
3 C	12"x12" Dark Gray Floor Tile w/ Black Streaks
3 F	12"x12" Light Brown Floor Tile w/ White Streaks
3 H	12"x12" Beige Floor Tile w/ White Streaks
3 I	12"x12" Brown Floor Tile
3 J	12"x12" Beige Floor Tile
3 N	12" x 12" Gray Floor Tile w/White Streaks
3 O	12" x 12" White Floor Tile

3 P

12" x 12" Blue Floor Tile

3A

12" x12" White Floor Tile w/ Blue and Gray Streaks

B. The following new homogenous areas have been identified for Building 1030:

1 A	Blue Carpet Mastic
85	12" X 12" Blotted Blue VFT
86	12" X 12" Light Blue VFT
87	Mastic for HA 85 and 86

C. This reinspection covered only physically accessible and visible areas and materials that were identified in the LEA's management plan. The following materials were concealed and/or contained in areas that were inaccessible for sampling and have been classified as Assumed:

1 B	Beige Carpet Mastic
1 C	Gold Carpet Mastic
1030	12" x 12" White Floor Tile w/ Blue Streaks Mastic
14 AA	12" x 12" Gray Floor Tile Mastic
14 AB	12" x 12" Multi-Blue Floor Tile Mastic
14 AC	12" x 12" Beige Floor Tile Mastic - Replaced
14 AD	12" x 12" Blue Floor Tile Mastic - Replaced
14 AE	12" x 12" White Floor Tile w/ Blue Streaks Mastic
14 AF	12" x 12" Gray Floor Tile w/ Black Streaks Mastic
14 Q	12" x 12" Black Floor Tile Mastic
14 R	12" x 12" White Floor Tile Mastic
14 S	12" x 12" Light Blue Floor Tile Mastic
14 T	12" x 12" Light Brown Floor Tile Mastic
14 U	12" x 12" Beige Floor Tile Mastic
16 C	4" Beige Baseboard
16 D	4" Dark Gray Baseboard
17 C	4" Beige Baseboard Mastic
17 D	4" Dark Gray Baseboard Mastic
2 J	9" x 9" Brown Floor Tile w/ White Streaks
251	Gray Carpet Adhesive
3 AA	12" x 12" Gray Floor Tile
3 AB	12" x 12" Multi-Blue Floor Tile
3 AC	12" x 12" Beige Floor Tile - Removed
3 AD	12" x 12" Gray Floor Tile - Removed
3 AE	12" x 12" White Floor Tile w/ Blue Streaks
3 AF	12" x 12" Gray Floor Tile w/ Black Streaks
3 B	12"x12" Gray Floor Tile w/ White & Black Streaks
3 C	12"x12" Dark Gray Floor Tile w/ Black Streaks
3 D	12"x12" Brown Floor Tile w/ Dk Brn & Wh Streaks (Removed)
3 E	12"x12" White Floor Tile w/ Brown Streaks
3 F	12"x12" Light Brown Floor Tile w/ White Streaks
3 H	12"x12" Beige Floor Tile w/ White Streaks
3 I	12"x12" Brown Floor Tile
3 J	12"x12" Beige Floor Tile
3 N	12" x 12" Gray Floor Tile w/White Streaks
3 O	12" x 12" White Floor Tile
3 P	12" x 12" Blue Floor Tile
3 Q	12" x 12" Black Floor Tile
3 R	12" x 12" White Floor Tile
3 S	12" x 12" Light Blue Floor Tile
3 T	12" x 12" Light Brown Floor Tile
3 V	12" x 12" Dark Brown w/Dk Brn & Lt Brn Streak FT (Removed)

3 W	12" x 12" Gray Floor Tile w/ Light Gray Streaks (Removed)
3 X	12" x 12" Multi-Brown Floor Tile
3 Y	12" x 12" Beige Floor Tile
3 Z	12" x 12" Light Green Floor Tile
3A	12" x12" White Floor Tile w/ Blue and Gray Streaks
53	Lab Tops and Sinks
55	Vibration Collars
57	Insulation Inside Firedoors
66	Roof - Not AHERA
67	Roof Flashing - Not AHERA
68	Roof - Not AHERA
69	Roof Flashing - Not AHERA
71	1' x 1' Fissured Ceiling Tile Mastic
72	2' x 4' Ceiling Panels
73	Drywall
74	Drywall Compound
75	Boiler Gaskets
76	12" x 12" Multi-Gray Floor Tile
77	12" x 12" Multi-Gray Floor Tile Mastic
78	1' x 1' White Small Fissured Ceiling Tile
8	Plaster Above Ceiling Tiles
80	12 x 12 gold and beige pattern FT
80M	12 x 12 gold and beige pattern VFT mastic
81	12x12 Blueish Grey w/ Dark Grey & White Floor Tile
82	12x12 Blueish Grey w/Dark Grey & White Floor Tile Mastic
83	12x12 Lt Grey w/Dark Grey & White Floor Tile
84	12x12 Lt Grey w/Dark Grey & White Floor Tile Mastic
85	12" X 12" Blotted Blue VFT
86	12" X 12" Light Blue VFT
87	Mastic for HA 85 and 86
G	Fittings on Fiberglass Pipe Insulation
J	Cementitious Pipe Joint Insulation on Aircell Pipe

The following areas were deemed to be inaccessible:

1 B	Beige Carpet Mastic
1 C	Gold Carpet Mastic
13 A	9"x9" Dk Green Floor Tile w/ White Streaks Mastic (REMOVED)
13 F	9"x9" Gray FloorTile w/Lt. Gray & Blk Strks Mastic
13 G	9" x 9" Lt Gray VFT w/ Gray & Blk Strks Mastic
13 H	9"x9" Lt Brn Floor Tile w/Wh & Blk Streaks Mastic
13C	9" x 9" Bright Grn Floor Tile w/ Wh Streaks Mastic
14 A	12" x 12" White FT w/Blue & Grey Streaks Mastic
14 AA	12" x 12" Gray Floor Tile Mastic

14 AB	12" x 12" Multi-Blue Floor Tile Mastic
14 AE	12" x 12" White Floor Tile w/ Blue Streaks Mastic
14 AF	12" x 12" Gray Floor Tile w/ Black Streaks Mastic
14 B	12" x 12" Gray VFT w/ Wh & Blk Streaks Mastic
14 C	12" x 12" Dk Gray Floor Tile w/Blk Streaks Mastic
14 F	12"x12" Lt Brown Floor Tile w/White Streaks Mastic
14 G	12"x12"Gray Floor Tile w/Dk Gray/Wh Streaks Mastic
14 H	12" x 12" Beige Floor Tile w/White Streaks Mastic
14 I	12" x 12" Brown Floor Tile Mastic
14 J	12" x 12" Beige Floor Tile Mastic
14 L	12" x 12" Light Green Floor Tile Mastic
14 M	12" x 12" Gray Floor Tile Mastic
14 Q	12" x 12" Black Floor Tile Mastic
14 R	12" x 12" White Floor Tile Mastic
14 S	12" x 12" Light Blue Floor Tile Mastic
14 T	12" x 12" Light Brown Floor Tile Mastic
14 U	12" x 12" Beige Floor Tile Mastic
14 V	12"x12" Dk Brn Floor Tile w/Dk Brn & Lt Brn Mastic
14 W	12"x12" Gray Floor Tile w/Lt. Gray Streaks Mastic
14 X	12" x 12" Multi-Brown Floor Tile Mastic
14 Y	12" x 12" Beige Floor Tile Mastic
14 Z	12" x 12" Light Green Floor Tile Mastic
17 C	4" Beige Baseboard Mastic
17 D	4" Dark Gray Baseboard Mastic
251	Gray Carpet Adhesive
71	1' x 1' Fissured Ceiling Tile Mastic
75	Boiler Gaskets
82	12x12 Blueish Grey w/Dark Grey & White Floor Tile Mastic
84	12x12 Lt Grey w/Dark Grey & White Floor Tile Mastic
87	Mastic for HA 85 and 86
13 I	9"x 9" White Floor Tile w/Brn & Blk Streaks Mastic

Materials were also listed as "assumed" if they were in good condition and sampling was not conducted to avoid damage.

This reinspection was conducted by Kathy Yurks, IDPH License # 100-8785. The Management Plan was updated by Todd Huffer, IDPH License # 100-09870. Inspector and Management Planner Licenses are included in Appendix B.

III. METHODOLOGY

Tasks performed on-site included the following:

1. Review current management plan, identify HA(s) and extract appropriate information.
2. Examine and verify abatement records.
3. Touch and visually and physically reinspect and reassess the condition of all friable known or assumed ACBM.
4. Touch and visually and physically reinspect all non-friable known or assumed ACBM to determine whether these materials have become friable since the last inspection or periodic surveillance.
5. Identify any condition changes that may affect Hazard Ranking of known ACBM or Assumed ACBM, as well as any HA(s) that have become friable since the last reinspection.
6. Collect bulk samples from each newly discovered friable HA or previously assumed and submit for laboratory analysis.
7. Tabulate reinspection findings and submit for management planner review and recommendations with appropriate response actions based on the AHERA Damage Category of the ACBM.
8. Submit reinspection findings and management planner recommendations to the LEA within thirty (30) days for inclusion into the management plan.

IV. ABATEMENT HISTORY

The information collected from the existing management plan and inspection report(s) and from interviews with the school official revealed that the following asbestos abatement was conducted at the school since the previous Three year Reinspection.

Abatement Dates:

V. REASSESSMENTS AND RECOMMENDATIONS

The reassessments and recommendations are summarized in Tables I and II on the following pages. Detailed Hazard Assessment Sheets and Drawings and Photos (if applicable) are included in Appendix A.

VI. CONCLUSIONS

The Dunbar High School Building 1030 Three-Year reinspection has been completed and response actions have been recommended for both friable and non-friable materials. A timely execution of the response actions recommended will enable the LEA and the Designated Person(s) to effectively manage the existing ACBM.

This three-year reinspection report should be inspected in the current Management plan at the CPS Central Office, and one (1) copy should be kept at the school for use when planning any renovation and/or demolition activities in areas where ACBM has been identified. Also, periodic surveillance documentation and any summary reports from any response actions that are executed at the school should be used to update the Management Plan.

Table I
Inspector's Reinspection Findings

Chicago Public Schools

School Dunbar High School Unit 53021 Building ID 1030

Address 3000 S. King Dr. Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
1 A	Blue Carpet Mastic			Office Complex, 101, 106, 132	NO_ACBM									
1 B	Beige Carpet Mastic	200	SF	Engineer's Office	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
1 C	Gold Carpet Mastic	600	SF	Room 9-C	ASSUMED	MISC	N	None						Moderate
10	Ceramic Floor Tile Grout			Washrooms	NO_ACBM	MISC								
1030	12" x 12" White Floor Tile w/ Blue Streaks Mastic	600	SF	208	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
11	Peg Board	2,000	SF	Auditorium Walls	CHR	MISC	N	NONE	0		No	ACBM with potential for significant damage		MODERATE
12	Terrazzo			Foyer	NO_ACBM	MISC								
13 A	9"x9" Dk Green Floor Tile w/ White Streaks Mastic (REMOVED)	6,100	SF	1st, 2nd & 3rd Floor Corridors	CHR	MISC	N	None						Moderate
13 B	9" x 9" White Floor Tile w/Dark Grn Streaks Mastic	6,100	SF	1st, 2nd & 3rd Floor Corridors	ABATED	MISC	N	None						Moderate
13 D	9" x 9" White Floor Tile w/ Lt Grn Streaks Mastic	400	SF	As Patches in the 1st & 3rd Floor Corridors	ABATED	MISC	N	None						Moderate
13 E	9" x 9" Brown Floor Tile w/ Brown Streaks Mastic	500	SF	1st Floor Corridor, Rooms 100	ABATED	MISC	N	None						Moderate
13 F	9"x9" Gray FloorTile w/Lt. Gray & Blk Strks Mastic	10,692	SF	13A&B, Dressing Rms,100,103-105,119,120,128,140,200,208,211,212,214,217,221A&B,225,300, 301,etc.	ABATED	MISC	N	None						Moderate
13 G	9" x 9" Lt Gray VFT w/ Gray & Blk Strks Mastic	10,692	SF	3 A&B, Dressing Rooms, and Various Classrooms Throughout Building	CHR	MISC	N	NONE	0		No	ACBM with potential for significant damage		MODERATE
13 H	9"x9" Lt Brn Floor Tile w/Wh & Blk Streaks Mastic	200	SF	Rooms 212 & 311	ABATED	MISC	N	None						Moderate
13 J	9" x 9" Brown Floor Tile w/White Streaks Mastic			Auditorium	NO_ACBM	MISC								
13C	9" x 9" Bright Grn Floor Tile w/ Wh Streaks Mastic	400	SF	As Patches in the 1st & 3rd Floor Corridors	ABATED	MISC	N	None						Moderate
14 A	12" x 12" White FT w/Blue & Grey Streaks Mastic	5,600	SF	Rooms 222, 224, 310, and 312	ABATED	MISC	N	None						Moderate
14 AA	12" x 12" Gray Floor Tile Mastic	1,200	SF	Band Room Hall, Chorus Room, Foyer & Practice Room	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW

Chicago Public Schools

School Dunbar High School Unit 53021 Building ID 1030

Address 3000 S. King Dr. Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
14 AB	12" x 12" Multi-Blue Floor Tile Mastic	1,600	SF	Room 208	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
14 AC	12" x 12" Beige Floor Tile Mastic - Replaced			Room 128	ASSUMED	MISC								
14 AD	12" x 12" Blue Floor Tile Mastic - Replaced			Room 128	ASSUMED	MISC								
14 AE	12" x 12" White Floor Tile w/ Blue Streaks Mastic	600	SF	Room 208	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
14 AF	12" x 12" Gray Floor Tile w/ Black Streaks Mastic	20	SF	Room 208	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
14 B	12" x 12" Gray VFT w/ Wh & Blk Streaks Mastic	200	SF	Men's Lounge	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
14 C	12" x 12" Dk Gray Floor Tile w/Blk Streaks Mastic	5,400	SF	Rooms 140, 211, 214, 217, 305, 308, and 313	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
14 D	12" x 12" Brown VFT w/ Dk Brn & White Strks Mastic	25,000	SF	Boys Gym, Lunchroom, 1st and 2nd Floor Corridors, 114, 201, 213, 215, 216, 218-220, 223, 227, 303	CHR	MISC	N	LOC	20		No	ACBM with potential for significant damage		MODERATE
14 E	12" x 12" White Floor Tile w/Brown Streaks Mastic	25,000	SF	Boys Gym, Lunchroom, 1st and 2nd Floor Corridors, 114, 201, 213, 215, 216, 218-220, 223, 227, 303	CHR	MISC	N	LOC	20		No	ACBM with potential for significant damage		MODERATE
14 F	12"x12" Lt Brown Floor Tile w/White Streaks Mastic	750	SF	1st Floor Corridor by Ramps and as a Patch in the 2nd Floor Corridor	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
14 G	12"x12" Gray Floor Tile w/Dk Gray/Wh Streaks Mastic	8,300	SF	Rooms 100, 119, 121, 140, 305, 306, 308, 313, 209 Library	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
14 H	12" x 12" Beige Floor Tile w/White Streaks Mastic	250	SF	1st Floor Corridor by Ramps and as a Patch in the 2nd Floor Corridor	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
14 I	12" x 12" Brown Floor Tile Mastic	250	SF	Room 138	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
14 J	12" x 12" Beige Floor Tile Mastic	432	SF	Room 138	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
14 K	12" x 12" Green Floor Tile Mastic	150	SF	1st, 2nd & 3rd Floor	ABATED	MISC	N	None						Moderate

Chicago Public Schools

School Dunbar High School Unit 53021 Building ID 1030

Address 3000 S. King Dr. Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				Building										
17 B	Blue Baseboard Mastic			Office Complex and Room 310	NO_ACBM	MISC								
17 C	4" Beige Baseboard Mastic	300	LF	Band Room, Chorus Room, Hall and Foyer	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
17 D	4" Dark Gray Baseboard Mastic	150	LF	Room 208	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
18	Tank # 1 Insulation Jacket (Closest to Door)			Boiler House	NO_ACBM	TSI								
19	Tank Insulation Jacket (Middle Tank)			Boiler House	NO_ACBM	TSI								
2 A	9" x 9" Dark Green Floor Tiles w/White Streaks	2,000	SF	1st, 2nd and 3rd Floor Corridors and Gym Balcony, Closet	CHR	MISC	N	LOC	30		No	ACBM with potential for significant damage	5	MODERATE
2 B	9" x 9" White Floor Tile w/Dark Green Streaks	2,000	SF	Various 1st, 2nd, and 3rd Floor Corridors and Gym Balcony, Closet	CHR	MISC	N	LOC	30		No	ACBM with potential for significant damage	5	MODERATE
2 C	9" x 9" Bright Green Floor Tile w/ White Streaks	400	SF	As Patches in the 1st and 3rd Floor Corridors	ABATED	MISC	N	None						Moderate
2 D	9" x 9" White Floor Tile w/Bright Green Streaks	400	SF	1st, 2nd, and 3rd Floor Corridors	CHR	MISC	N	None						Moderate
2 E	9" x 9" Brown w/Brown Floor Tile	50	SF	Rooms 100 & 140 and the 1st Floor Corridor	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
2 F	9"x9" Gray w/Lt. Gray & Black Streaks Floor Tile	10,692	SF	13 A & B, Dressing Rooms, and Various Classrooms Throughout Building	CHR	MISC	N	DIST	50		No	ACBM with potential for significant damage		MODERATE
2 G	9" x 9" Lt. Gray Floor Tile w/Gray & Black Streaks	10,692	SF	13 A & B, Dressing Rooms, and Various Classrooms Throughout Building	CHR	MISC	N	DIST	50		No	ACBM with potential for significant damage		MODERATE
2 H	9" x 9" Light Brn Floor Tile w/White & Blk Streaks	200	SF	Rooms 311 and 212	ABATED	MISC	N	None						Moderate
2 I	9" x 9" White Floor Tile w/Lt Brn & Blk Streaks	200	SF	Rooms 212 and 311	CHR	MISC	N	NONE			No	ACBM with the potential for damage		MODERATE
2 J	9" x 9" Brown Floor Tile w/ White Streaks	3,800	SF	Auditorium	ASSUMED	MISC	Y	NONE	0		Yes	Any remaining friable ACBM or friable suspect ACBM		MODERATE

Chicago Public Schools

School Dunbar High School Unit 53021 Building ID 1030

Address 3000 S. King Dr. Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
	White Streaks			121, 140, 305, 306, 308, and 313										
3 H	12"x12" Beige Floor Tile w/ White Streaks			1st Floor Corridor by Ramps and as a Patch in 2nd Floor Corridor, 114, 207, 307	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		MODERATE
3 I	12"x12" Brown Floor Tile			Room 138	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		MODERATE
3 J	12"x12" Beige Floor Tile			Room 138	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
3 K	12"x12" Green Floor Tiles			As Patches in the 1st and 3rd Floor Corridors	ABATED	MISC								
3 L	12"x12" Light Green Floor Tiles			As Patches in the 1st and 3rd Floor Corridors	ABATED	MISC								
3 M	12" x 12" Gray Floor Tile			1st Floor Corridor Ramps	NO_ACBM	MISC								
3 N	12" x 12" Gray Floor Tile w/White Streaks			Room 104	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		MODERATE
3 O	12" x 12" White Floor Tile	900	SF	Room 132,106	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		MODERATE
3 P	12" x 12" Blue Floor Tile			Room 132	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		MODERATE
3 Q	12" x 12" Black Floor Tile	1,100	SF	Room 105	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
3 R	12" x 12" White Floor Tile	1,100	SF	Room 105	ASSUMED	MISC	N	None	0		No	ACBM with the potential for damage		MODERATE
3 S	12" x 12" Light Blue Floor Tile	175	SF	Room 104, 134, Social Room, 300B	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
3 T	12" x 12" Light Brown Floor Tile	2,400	SF	Rooms 114, 116, 117, 119, 130, and 206	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
3 U	12" x 12" Beige Floor Tile	2,400	SF	Rooms 114, 116, 117, 119, 130, and 206	ANT	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
3 V	12" x 12" Dark Brown w/Dk Brn & Lt Brn Streak FT (Removed)			On Cabinets in Various Classrooms	ASSUMED	MISC								
3 W	12" x 12" Gray Floor Tile w/ Light Gray Streaks (Removed)			On Cabinets in Various Classrooms	ASSUMED	MISC								
3 X	12" x 12" Multi-Brown Floor Tile	600	SF	Rooms 201 and 203	ASSUMED	MISC								
3 Y	12" x 12" Beige Floor Tile	300	SF	Rooms 201	ASSUMED	MISC								
3 Z	12" x 12" Light Green Floor Tile			Band Room, Chorus	ASSUMED	MISC	N	NONE	0		No	ACBM with the		MODERATE

Chicago Public Schools

School Dunbar High School Unit 53021 Building ID 1030

Address 3000 S. King Dr. Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
5	Insulation on Suspended HVAC Unit			Room 122	NO_ACBM	TSI								
50	2' x 8' Smooth Ceiling Tile			Shop Wing	NO_ACBM	MISC								
51	Insulation Behind Pegboard Walls			Auditorium	NO_ACBM	TSI								
52	Roof Flashing - Not AHERA			Shop Roof	NO_ACBM	MISC								
53	Lab Tops and Sinks	500	SF	Rooms 117, 310, 312, 222, and 224	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
54	Fiberglass Insulation on Suspended HVAC Unit			Room 122	NO_ACBM	TSI								
55	Vibration Collars	50	LF	Dressing Room, Janitor's Closet in Girl's Locker Room, Room 310 & Electrical Room in Room 206	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
56	Terrazzo Sinks			Washrooms	NO_ACBM	MISC								
57	Insulation Inside Firedoors	160	SF	Exits and Boiler Room	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
58	Exterior Dark Brick - Not AHERA			Exterior of Main Building	NO_ACBM	MISC								
59	Exterior Dark Brick Mortar - Not AHERA			Exterior of Main Building	NO_ACBM	MISC								
6	Fiberglass Insulation Backing on HVAC Unit			Room 122- ABATED	ABATED	TSI					No			
60	Exterior Light Face Brick - Not AHERA			Exterior of Main Building	NO_ACBM	MISC								
61	Exterior Light Face Brick Mortar - Not AHERA			Exterior of Main Building	NO_ACBM	MISC								
62	Exterior Door Grout - Not AHERA			Exterior of Main Building	NO_ACBM	MISC								
63	Exterior Blue Brick - Not AHERA			Exterior of Main Building	NO_ACBM	MISC								
64	Exterior Blue Brick Mortar - Not AHERA			Exterior of Main Building	NO_ACBM	MISC								
65	Exterior Window Grout - Not AHERA			Exterior of Main Building	NO_ACBM	MISC								
66	Roof - Not AHERA			Boiler House	ASSUMED						No			
67	Roof Flashing - Not AHERA			Boiler House	ASSUMED									
68	Roof - Not AHERA			Main Building	ASSUMED	MISC	N				No			
69	Roof Flashing - Not AHERA			Main Building	ASSUMED	MISC	N				No			
7	Plaster			Throughout Building	NO_ACBM	SURFACE								
70	Mastic on Wall	0	SF	Room 128 - Material not observed	CHR	MISC	N							

Chicago Public Schools

School Dunbar High School Unit 53021 Building ID 1030

Address 3000 S. King Dr. Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
71	1' x 1' Fissured Ceiling Tile Mastic	10,000	SF	Throughout Building, Cafeteria	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
72	2' x 4' Ceiling Panels	2,400	SF	Room 208, 117	ASSUMED	MISC	Y	NONE	0		No	ACBM with the potential for damage		MODERATE
73	Drywall	1,600	SF	Room 208	ASSUMED	MISC	Y	NONE	0		No	ACBM with the potential for damage		MODERATE
74	Drywall Compound	200	LF	Room 208	ASSUMED	MISC	Y	NONE	0		No	ACBM with the potential for damage		MODERATE
75	Boiler Gaskets	10	SF	Bryan Boiler in Basement	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
76	12" x 12" Multi-Gray Floor Tile	2,000	SF	Rooms 203 & 205	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
77	12" x 12" Multi-Gray Floor Tile Mastic	2,000	SF	Rooms 203 & 205	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
78	1' x 1' White Small Fissured Ceiling Tile	4,700	SF	Lunchroom	ASSUMED	MISC	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		MODERATE
8	Plaster Above Ceiling Tiles			Shop Wing	ASSUMED	SURFACE								
80	12 x 12 gold and beige pattern FT	2,000	SF	114, 207, 206, 204, 107	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
80M	12 x 12 gold and beige pattern VFT mastic	2,000	SF	114, 207, 206, 204, 107	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
81	12x12 Blueish Grey w/ Dark Grey & White Floor Tile	800	SF	Rm 128, 100	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
82	12x12 Blueish Grey w/Dark Grey & White Floor Tile Mastic	800	SF	Rm 128, 100	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
83	12x12 Lt Grey w/Dark Grey & White Floor Tile	3,200	SF	Rm 100, 128, 203, 301, 300, 308	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
84	12x12 Lt Grey w/Dark Grey & White Floor Tile Mastic	3,200	SF	Rm 100, 128, 203, 301, 300, 308	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
85	12" X 12" Blotted Blue VFT	26,000	SF	Throughout Hallways and Various Rooms	ASSUMED	MISC	N	NONE	0			ACBM with the potential for damage		MODERATE
86	12" X 12" Light Blue VFT	4,000	SF	Throughout Hallways and Various Classrooms	ASSUMED	MISC	N	NONE	0			ACBM with the potential for damage		MODERATE
87	Mastic for HA 85 and 86	30,000	SF	Throughout Hallways and Various Classrooms	ASSUMED	MISC	N	NONE	0			ACBM with the potential for damage		LOW
9	Drywall Joint Compound			Room 108	NO_ACBM	MISC								
A	Aircell Pipe Insulation	500	LF	Pipe Chases, Boiler Room and Throughout Building	CHR	TSI	Y	DIST	15		No	Any remaining friable ACBM or friable suspect ACBM		MODERATE

Chicago Public Schools

School Dunbar High School Unit 53021 Building ID 1030

Address 3000 S. King Dr. Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
B	(Cardboard) Paperwrap Pipe Insulation	600	LF	Boiler Room and Throughout Building, rm 115, 125	CHR	TSI	Y	LOC	1		No	Any remaining friable ACBM or friable suspect ACBM		MODERATE
C	Aircell Duct Insulation			Abated in 1992 - See 2004 Comments	ABATED	TSI								
D	Mag Block Insulation			Boilers in Boiler House - Abated 1992	ABATED	TSI								
E	Mag Block Pipe Insulation			Boiler House - Abated 1992	ABATED	TSI								
F	Mag Block Duct Insulation			Boiler House - Abated 1992	ABATED	TSI								
G	Fittings on Fiberglass Pipe Insulation	60	LF	Main Building	ASSUMED	TSI	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		MODERATE
HA-1000	White woven electrical wire insulation	50	LF	Auditorium stage light fixtures	CHR	MISC	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		MODERATE
131	9"x 9" White Floor Tile w/Brn & Blk Streaks Mastic	1,500	SF	Rooms 212 and 311	CHR	MISC	N							Moderate
J	Cementitious Pipe Joint Insulation on Aircell Pipe	50	LF	Pipe Chases, Boiler Room and Throughout Building	ASSUMED	TSI	N	NONE	0		No	ACBM with the potential for damage		MODERATE
K	Cementitious Pipe Joint Insulation on Paperwrap	20	LF	Boiler Room, Pipe Chases and Throughout Building	CHR	TSI	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		MODERATE

Chicago Public Schools

School Dunbar High School Unit 53021 Building ID 1030

Address 3000 S. King Dr. Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

Reinspection Date 3/14/2013
Inspector Name Kathy Yurks
100-8785 5/15/2013
Inspector's IDPH License Number / Expiration Date

Inspector's Comments

HA Number:	Inspector Comments:
1 A	
1 B	
1 C	Material was not observed - 2013 3 years re-inspection
10	
1030	
11	
12	
13 A	Material was not observed - 2013 3 years re-inspection
13 B	Material was not observed - 2013 3 years re-inspection
13 D	Material was not observed - 2013 3 years re-inspection
13 E	Material was not observed - 2013 3 years re-inspection
13 F	Material was not observed - 2013 3 years re-inspection
13 G	
13 H	Material was not observed - 2013 3 years re-inspection
13 J	
13C	Material was not observed - 2013 3 years re-inspection
14 A	Material was not observed - 2013 3 years re-inspection
14 AA	
14 AB	
14 AC	Material was not observed - 2013 3 years re-inspection
14 AD	Material was not observed - 2013 3 years re-inspection
14 AE	
14 AF	
14 B	

Chicago Public Schools

School Dunbar High School Unit 53021 Building ID 1030

Address 3000 S. King Dr. Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
14 C	
14 D	
14 E	
14 F	
14 G	
14 H	
14 I	
14 J	
14 K	Material was not observed - 2013 3 years re-inspection
14 L	Material was not observed - 2013 3 years re-inspection
14 M	
14 N	
14 O	
14 P	
14 Q	
14 R	
14 S	
14 T	
14 U	
14 V	Material was not observed - 2013 3 years re-inspection
14 W	Material was not observed - 2013 3 years re-inspection
14 X	Material was not observed - 2013 3 years re-inspection
14 Y	Material was not observed - 2013 3 years re-inspection
14 Z	
15	
16 A	
16 B	
16 C	
16 D	

Chicago Public Schools

School Dunbar High School Unit 53021 Building ID 1030

Address 3000 S. King Dr. Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
17 A	
17 B	
17 C	
17 D	
18	
19	
2 A	Material was not observed in all corridors- 2013 3 years re-inspection
2 B	Material was not observed in corridors - 2013 3 years re-inspection
2 C	Material was not observed - 2013 3 years re-inspection
2 D	Material was not observed - 2013 3 years re-inspection
2 E	
2 F	
2 G	
2 H	Material was not observed - 2013 3 years re-inspection
2 I	
2 J	
20	
21	
22	
23	
24	
25	
251	Material was not observed - 2013 3 years re-inspection
26	
27	
28	
29	
3 AA	
3 AB	

Chicago Public Schools

School Dunbar High School Unit 53021 Building ID 1030

Address 3000 S. King Dr. Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
3 AC	Material was not observed - 2013 3 years re-inspection
3 AD	Material was not observed - 2013 3 years re-inspection
3 AE	Not observed in room 208
3 AF	Not observed in room 208
3 B	
3 C	
3 D	Material was not observed - 2013 3 years re-inspection
3 E	Material was not observed - 2013 3 years re-inspection
3 F	Not observed in 1st floor corridor
3 G	Material was not observed - 2013 3 years re-inspection
3 H	Not observed in 1st corridor
3 I	
3 J	
3 K	Material was not observed - 2013 3 years re-inspection
3 L	Material was not observed - 2013 3 years re-inspection
3 M	
3 N	
3 O	
3 P	
3 Q	
3 R	Material may exist under new material (not observed)
3 S	
3 T	
3 U	
3 V	Material was not observed - 2013 3 years re-inspection
3 W	Material was not observed - 2013 3 years re-inspection
3 X	Material was not observed - 2013 3 years re-inspection
3 Y	Material was not observed - 2013 3 years re-inspection
3 Z	

Chicago Public Schools

School Dunbar High School Unit 53021 Building ID 1030

Address 3000 S. King Dr. Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
30	
31	
32	
33	
34	
35	
36	
37	
38	
39	
3A	
4	Material was not observed - 2013 3 years re-inspection
40	
41	
42	
43	
44	
45	
46	
47	
48	
49	
5	
50	
51	
52	
53	
54	
55	

Chicago Public Schools

School Dunbar High School Unit 53021 Building ID 1030

Address 3000 S. King Dr. Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
56	
57	
58	
59	
6	Material was not observed - 2013 3 years re-inspection
60	
61	
62	
63	
64	
65	
66	Not AHERA
67	Not AHERA
68	Not AHERA
69	Not AHERA
7	
70	Material was not observed - 2013 3 years re-inspection (couldn't find it)
71	
72	
73	
74	
75	
76	
77	
78	
8	Material was not observed - 2013 3 years re-inspection
80	
80M	
81	

Chicago Public Schools

School Dunbar High School Unit 53021 Building ID 1030

Address 3000 S. King Dr. Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
82	
83	
84	
85	
86	
87	
9	
A	
B	
C	Material was not observed - 2013 3 years re-inspection
D	Material was not observed - 2013 3 years re-inspection
E	Material was not observed - 2013 3 years re-inspection
F	Material was not observed - 2013 3 years re-inspection
G	
HA-1000	
I3 I	Material was not observed - 2013 3 years re-inspection
J	
K	

Table II

Management Planner's Review

Chicago Public Schools

School Dunbar High School

Unit 53021

Building ID 1030

Address 3000 S. King Dr.

Chicago, IL, 60616

Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
1 A	Blue Carpet Mastic			Office Complex, 101, 106, 132	No ACBM						
1 B	Beige Carpet Mastic	200	SF	Engineer's Office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
1 C	Gold Carpet Mastic	600	SF	Room 9-C	Assumed	MISC	No		SF		
10	Ceramic Floor Tile Grout			Washrooms	No ACBM	MISC					
1030	12" x 12" White Floor Tile w/ Blue Streaks Mastic	600	SF	208	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
11	Peg Board	2,000	SF	Auditorium Walls	Chrysotile	MISC	No	0	SF	5 ACBM with potential for significant damage	Operations and Maintenance
12	Terrazzo			Foyer	No ACBM	MISC					
13 A	9"x9" Dk Green Floor Tile w/ White Streaks Mastic (REMOVED)	6,100	SF	1st, 2nd & 3rd Floor Corridors	Chrysotile	MISC	No		SF		
13 B	9" x 9" White Floor Tile w/Dark Grn Streaks Mastic	6,100	SF	1st, 2nd & 3rd Floor Corridors	Abated	MISC	No		SF		
13 D	9" x 9" White Floor Tile w/ Lt Grn Streaks Mastic	400	SF	As Patches in the 1st & 3rd Floor Corridors	Abated	MISC	No		SF		
13 E	9" x 9" Brown Floor Tile w/ Brown Streaks Mastic	500	SF	1st Floor Corridor, Rooms 100	Abated	MISC	No		SF		
13 F	9"x9" Gray FloorTile w/Lt. Gray & Blk Strks Mastic	10,692	SF	13A&B, Dressing Rms,100,103-105,119,120,128,140,200,208,211,212, 214,217,221A&B,225,300, 301,etc.	Abated	MISC	No		SF		
13 G	9" x 9" Lt Gray VFT w/ Gray & Blk Strks Mastic	10,692	SF	3 A&B, Dressing Rooms, and Various Classrooms Throughout Building	Chrysotile	MISC	No	0	SF	5 ACBM with potential for significant damage	Operations and Maintenance
13 H	9"x9" Lt Brn Floor Tile w/Wh & Blk Streaks Mastic	200	SF	Rooms 212 & 311	Abated	MISC	No		SF		
13 J	9" x 9" Brown Floor Tile w/White Streaks Mastic			Auditorium	No ACBM	MISC					
13 C	9" x 9" Bright Grn Floor Tile w/ Wh Streaks Mastic	400	SF	As Patches in the 1st & 3rd Floor Corridors	Abated	MISC	No		SF		
14 A	12" x 12" White FT w/Blue & Grey Streaks Mastic	5,600	SF	Rooms 222, 224, 310, and 312	Abated	MISC	No		SF		
14 AA	12" x 12" Gray Floor Tile Mastic	1,200	SF	Band Room Hall, Chorus Room, Foyer & Practice Room	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
14 AB	12" x 12" Multi-Blue Floor Tile Mastic	1,600	SF	Room 208	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
14 AC	12" x 12" Beige Floor Tile Mastic - Replaced			Room 128	Assumed	MISC					
14 AD	12" x 12" Blue Floor Tile Mastic - Replaced			Room 128	Assumed	MISC					
14 AE	12" x 12" White Floor Tile w/ Blue Streaks Mastic	600	SF	Room 208	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
14 AF	12" x 12" Gray Floor Tile w/ Black Streaks Mastic	20	SF	Room 208	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
14 B	12" x 12" Gray VFT w/ Wh & Blk Streaks Mastic	200	SF	Men's Lounge	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
14 C	12" x 12" Dk Gray Floor Tile w/Blk Streaks Mastic	5,400	SF	Rooms 140, 211, 214, 217, 305, 308, and 313	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
14 D	12" x12" Brown VFT w/ Dk Brn & White Strks	25,000	SF	Boys Gym, Lunchroom, 1st and 2nd	Chrysotile	MISC	No	20	SF	5 ACBM with potential for significant	Operations and Maintenance

Chicago Public Schools

School Dunbar High School
Address 3000 S. King Dr.

Unit 53021
 Chicago, IL, 60616

Building ID 1030
Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
	Mastic			Floor Corridors, 114, 201, 213, 215, 216, 218-220, 223, 227, 303						damage	
14 E	12" x 12" White Floor Tile w/Brown Streaks Mastic	25,000	SF	Boys Gym, Lunchroom, 1st and 2nd Floor Corridors, 114, 201, 213, 215, 216, 218-220, 223, 227, 303	Chrysotile	MISC	No	20	SF	5 ACBM with potential for significant damage	Operations and Maintenance
14 F	12"x12" Lt Brown Floor Tile w/White Streaks Mastic	750	SF	1st Floor Corridor by Ramps and as a Patch in the 2nd Floor Corridor	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
14 G	12"x12" Gray Floor Tile w/Dk Gray/Wh Streaks Mastic	8,300	SF	Rooms 100, 119, 121, 140, 305, 306, 308, 313, 209 Library	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
14 H	12" x 12" Beige Floor Tile w/White Streaks Mastic	250	SF	1st Floor Corridor by Ramps and as a Patch in the 2nd Floor Corridor	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
14 I	12" x 12" Brown Floor Tile Mastic	250	SF	Room 138	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
14 J	12" x 12" Beige Floor Tile Mastic	432	SF	Room 138	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
14 K	12" x 12" Green Floor Tile Mastic	150	SF	1st, 2nd & 3rd Floor Corridors as Patches	Abated	MISC	No		SF		
14 L	12" x 12" Light Green Floor Tile Mastic	150	SF	1st, 2nd & 3rd Floor Corridors as Patches	Abated	MISC	No		SF		
14 M	12" x 12" Gray Floor Tile Mastic	550	SF	1st Floor Corridor Ramps	Chrysotile	MISC	No	0	SF	5 ACBM with potential for significant damage	Operations and Maintenance
14 N	12" x 12" Gray Floor Tile w/White Streaks Mastic			Room 104	No ACBM	MISC					
14 O	12" x 12" White Floor Tile Mastic			Room 132	No ACBM	MISC					
14 P	12" x 12" Blue Floor Tile Mastic			Room 132	No ACBM	MISC					
14 Q	12" x 12" Black Floor Tile Mastic	1,100	SF	Room 105	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
14 R	12" x 12" White Floor Tile Mastic	1,500	SF	Room 105	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
14 S	12" x 12" Light Blue Floor Tile Mastic	600	SF	Room 104, 221B, 223	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
14 T	12" x 12" Light Brown Floor Tile Mastic	700	SF	Rooms 114, 117, 119, 130, 206, & 207	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
14 U	12" x 12" Beige Floor Tile Mastic	700	SF	Rooms 114, 117, 119, 130, 206, & 207	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
14 V	12"x12" Dk Brn Floor Tile w/Dk Brn & Lt Brn Mastic	300	SF	On Cabinets in Various Classrooms	Abated	MISC	No		SF		
14 W	12"x12" Gray Floor Tile w/Lt. Gray Streaks Mastic	300	SF	On Cabinets in Various Classrooms	Abated	MISC	No		SF		
14 X	12" x 12" Multi-Brown Floor Tile Mastic	1,150	SF	Room 201 and 203	Chrysotile	MISC	No		SF	6 ACBM with the potential for damage	Operations and Maintenance
14 Y	12" x 12" Beige Floor Tile Mastic	1,150	SF	Rooms 201 and 203	Chrysotile	MISC	No		SF		
14 Z	12" x 12" Light Green Floor Tile Mastic	2,400	SF	Band Room, Chorus Room, Hall and Foyer	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
15	Drywall			Rooms 132 & 303 and the Office Complex	No ACBM	MISC					
16 A	Black Baseboard			Throughout Building	No ACBM	MISC					

Chicago Public Schools

School Dunbar High School

Unit 53021

Building ID 1030

Address 3000 S. King Dr.

Chicago, IL, 60616

Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
16 B	Blue Baseboard			Office Complex and Room 310	No ACBM	MISC					
16 C	4" Beige Baseboard	300	LF	Band Room, Hall, Foyer and Chorus Room	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Operations and Maintenance
16 D	4" Dark Gray Baseboard	150	LF	Room 208	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Operations and Maintenance
17 A	Black Baseboard Mastic			Throughout Building	No ACBM	MISC					
17 B	Blue Baseboard Mastic			Office Complex and Room 310	No ACBM	MISC					
17 C	4" Beige Baseboard Mastic	300	LF	Band Room, Chorus Room, Hall and Foyer	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Operations and Maintenance
17 D	4" Dark Gray Baseboard Mastic	150	LF	Room 208	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Operations and Maintenance
18	Tank # 1 Insulation Jacket (Closest to Door)			Boiler House	No ACBM	TSI					
19	Tank Insulation Jacket (Middle Tank)			Boiler House	No ACBM	TSI					
2 A	9" x 9" Dark Green Floor Tiles w/White Streaks	2,000	SF	1st, 2nd and 3rd Floor Corridors and Gym Balcony, Closet	Chrysotile	MISC	No	30	SF	5 ACBM with potential for significant damage	Operations and Maintenance
2 B	9" x 9" White Floor Tile w/Dark Green Streaks	2,000	SF	Various 1st, 2nd, and 3rd Floor Corridors and Gym Balcony, Closet	Chrysotile	MISC	No	30	SF	5 ACBM with potential for significant damage	Operations and Maintenance
2 C	9" x 9" Bright Green Floor Tile w/ White Streaks	400	SF	As Patches in the 1st and 3rd Floor Corridors	Abated	MISC	No		SF		
2 D	9" x 9" White Floor Tile w/Bright Green Streaks	400	SF	1st, 2nd, and 3rd Floor Corridors	Chrysotile	MISC	No		SF		
2 E	9" x 9" Brown w/Brown Floor Tile	50	SF	Rooms 100 & 140 and the 1st Floor Corridor	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
2 F	9"x9" Gray w/Lt. Gray & Black Streaks Floor Tile	10,692	SF	13 A & B, Dressing Rooms, and Various Classrooms Throughout Building	Chrysotile	MISC	No	50	SF	5 ACBM with potential for significant damage	Operations and Maintenance
2 G	9" x 9" Lt. Gray Floor Tile w/Gray & Black Streaks	10,692	SF	13 A & B, Dressing Rooms, and Various Classrooms Throughout Building	Chrysotile	MISC	No	50	SF	5 ACBM with potential for significant damage	Operations and Maintenance
2 H	9" x 9" Light Brn Floor Tile w/White & Blk Streaks	200	SF	Rooms 311 and 212	Abated	MISC	No		SF		
2 I	9" x 9" White Floor Tile w/Lt Brn & Blk Streaks	200	SF	Rooms 212 and 311	Chrysotile	MISC	No		SF	6 ACBM with the potential for damage	Operations and Maintenance
2 J	9" x 9" Brown Floor Tile w/ White Streaks	3,800	SF	Auditorium	Assumed	MISC	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Operations and Maintenance
20	Tank Insulation Jacket (Farthest From Door)			Boiler House	No ACBM	TSI					
21	Tank Insulation Jacket (Lower Level)			Boiler House	No ACBM	TSI					
22	Linear Pipe Insulation			Boiler House	No ACBM	TSI					
23	Steam Line Joints			Boiler House	No ACBM	TSI					
24	Cinder Block			Boiler House	No ACBM	MISC					
25	Cinder Block Mortar			Boiler House	No ACBM	MISC					

Chicago Public Schools

School Dunbar High School
Address 3000 S. King Dr.

Unit 53021
 Chicago, IL, 60616

Building ID 1030
Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
251	Gray Carpet Adhesive	0	SF	1st Floor Corridor, CPS ID	Assumed	MISC	No		SF		
26	Finished Brick (Glazed)			Boiler House Washroom	No ACBM	MISC					
27	Finished (Glazed) Brick Mortar			Boiler House Washroom	No ACBM	MISC					
28	Terrazzo Stall Panels			Boiler House Washroom	No ACBM	MISC					
29	Aircell Pipe Insulation	10	LF	Boiler House Washroom Behind Wall-In Chase	Chrysotile	TSI	Yes	0	LF	7 Any remaining friable ACBM or friable suspect ACBM	Operations and Maintenance
3 AA	12" x 12" Gray Floor Tile	1,200	SF	Band Room, Chorus Room, Hall, Foyer & Practice Room	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
3 AB	12" x 12" Multi-Blue Floor Tile	1,000	SF	Room 208	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
3 AC	12" x 12" Beige Floor Tile - Removed			Room 128	Assumed	MISC					
3 AD	12" x 12" Gray Floor Tile - Removed			Room 128	Assumed	MISC					
3 AE	12" x 12" White Floor Tile w/ Blue Streaks	600	SF	Room 208, 100, 128	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
3 AF	12" x 12" Gray Floor Tile w/ Black Streaks	20	SF	Room 208, 100, 128	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
3 B	12"x12" Gray Floor Tile w/ White & Black Streaks			Men's Lounge	Assumed	MISC	No	0		6 ACBM with the potential for damage	Operations and Maintenance
3 C	12"x12" Dark Gray Floor Tile w/ Black Streaks			Rooms 100, 140, 305, 308, and 313	Assumed	MISC	No	0		6 ACBM with the potential for damage	Operations and Maintenance
3 D	12"x12" Brown Floor Tile w/ Dk Brn & Wh Streaks (Removed)			Boys Gym, Lunch Room, Classrooms and Corridors	Assumed	MISC					
3 E	12"x12" White Floor Tile w/ Brown Streaks			Boys Gym, Lunch Room, Classrooms and Corridors	Assumed	MISC					
3 F	12"x12" Light Brown Floor Tile w/ White Streaks			1st Floor Corridor by Ramps and as a Patch in 2nd Floor Corridor, 114, 207	Assumed	MISC	No	0		6 ACBM with the potential for damage	Operations and Maintenance
3 G	12"x12" Gray Floor Tile w/ Dk Gray & White Streaks			Rooms 100, 119, 121, 140, 305, 306, 308, and 313	Abated	MISC					
3 H	12"x12" Beige Floor Tile w/ White Streaks			1st Floor Corridor by Ramps and as a Patch in 2nd Floor Corridor, 114, 207, 307	Assumed	MISC	No	0		6 ACBM with the potential for damage	Operations and Maintenance
3 I	12"x12" Brown Floor Tile			Room 138	Assumed	MISC	No	0		6 ACBM with the potential for damage	Operations and Maintenance
3 J	12"x12" Beige Floor Tile			Room 138	Assumed	MISC	No	0		6 ACBM with the potential for damage	Operations and Maintenance
3 K	12"x12" Green Floor Tiles			As Patches in the 1st and 3rd Floor Corridors	Abated	MISC					
3 L	12"x12" Light Green Floor Tiles			As Patches in the 1st and 3rd Floor Corridors	Abated	MISC					
3 M	12" x 12" Gray Floor Tile			1st Floor Corridor Ramps	No ACBM	MISC					
3 N	12" x 12" Gray Floor Tile w/White Streaks			Room 104	Assumed	MISC	No	0		6 ACBM with the potential for damage	Operations and Maintenance
3 O	12" x 12" White Floor Tile	900	SF	Room 132,106	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance

Chicago Public Schools

School Dunbar High School
Address 3000 S. King Dr.

Unit 53021
 Chicago, IL, 60616

Building ID 1030
Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
3 P	12" x 12" Blue Floor Tile			Room 132	Assumed	MISC	No	0		6 ACBM with the potential for damage	Operations and Maintenance
3 Q	12" x 12" Black Floor Tile	1,100	SF	Room 105	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
3 R	12" x 12" White Floor Tile	1,100	SF	Room 105	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
3 S	12" x 12" Light Blue Floor Tile	175	SF	Room 104, 134, Social Room, 300B	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
3 T	12" x 12" Light Brown Floor Tile	2,400	SF	Rooms 114, 116, 117, 119, 130, and 206	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
3 U	12" x 12" Beige Floor Tile	2,400	SF	Rooms 114, 116, 117, 119, 130, and 206	Anthophyllite	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
3 V	12" x 12" Dark Brown w/Dk Brn & Lt Brn Streak FT (Removed)			On Cabinets in Various Classrooms	Assumed	MISC					
3 W	12" x 12" Gray Floor Tile w/ Light Gray Streaks (Removed)			On Cabinets in Various Classrooms	Assumed	MISC					
3 X	12" x 12" Multi-Brown Floor Tile	600	SF	Rooms 201 and 203	Assumed	MISC			SF		
3 Y	12" x 12" Beige Floor Tile	300	SF	Rooms 201	Assumed	MISC			SF		
3 Z	12" x 12" Light Green Floor Tile			Band Room, Chorus Room, Hall and Foyer	Assumed	MISC	No	0		6 ACBM with the potential for damage	Operations and Maintenance
30	Tank Insulation			Basement	No ACBM	TSI					
31	Cinder Block Mortar			Throughout Building	No ACBM	MISC					
32	Interior Brick			Throughout Building	No ACBM	MISC					
33	Interior Brick Mortar			Throughout Building	No ACBM	MISC					
34	Ceiling Material			Basement Boiler Room	No ACBM	MISC					
35	Terrazzo Stairs and Landings/foyers			Throughout Stairways	No ACBM	MISC					
36	Clay Tile			Entrances and Exits	No ACBM	MISC					
37	Clay Tile Mortar			Entrances and Exits	No ACBM	MISC					
38	Window Glazing			Throughout Building	No ACBM	MISC					
39	Window Caulk (Grout)			Throughout Building	No ACBM	MISC					
3A	12" x 12" White Floor Tile w/ Blue and Gray Streaks	2,700	SF	Rms 224, 222, 310, 225, 221A, 217, 211, 207, 306 and 312	Assumed	MISC		0	SF	6 ACBM with the potential for damage	Operations and Maintenance
4	Outer Wrap Over Fiberglass Insulation on HVAC Unit			Room 122- ABATED	Abated	TSI					
40	Window Sill Mortar			Throughout Classrooms	No ACBM	MISC					
41	Finished (Glazed) Brick			Throughout Building	No ACBM	MISC					
42	Finished (Glazed) Brick Mortar			Throughout Building	No ACBM	MISC					
43	Terrazzo Stall Panels			All Washrooms	No ACBM	MISC					
44	1' x 1' Ceiling Tile (Acoustical)			As Patches in Foyer and Corridors	No ACBM	MISC					

Chicago Public Schools

School Dunbar High School

Unit 53021

Building ID 1030

Address 3000 S. King Dr.

Chicago, IL, 60616

Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
45	1' x 1' Ceiling Tiles			1st, 2nd, and 3rd Floor Corridors	No ACBM	MISC					
46	1' x 1' (Spline) Ceiling Tiles with Holes			1st, 2nd, and 3rd Floor Corridors	No ACBM	MISC					
47	2' x 4' Lay-In Ceiling Panels	1,500	SF	Rooms 311 and 110	Amosite	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
48	1' x 2' Slotted Ceiling Tile			Shop Wing and Gym	No ACBM	MISC					
49	2' x 8' Textured Ceiling Panels			Rms 122, 124, and 126	No ACBM	MISC					
5	Insulation on Suspended HVAC Unit			Room 122	No ACBM	TSI					
50	2' x 8' Smooth Ceiling Tile			Shop Wing	No ACBM	MISC					
51	Insulation Behind Pegboard Walls			Auditorium	No ACBM	TSI					
52	Roof Flashing - Not AHERA			Shop Roof	No ACBM	MISC					
53	Lab Tops and Sinks	500	SF	Rooms 117, 310, 312, 222, and 224	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
54	Fiberglass Insulation on Suspended HVAC Unit			Room 122	No ACBM	TSI					
55	Vibration Collars	50	LF	Dressing Room, Janitor's Closet in Girl's Locker Room, Room 310 & Electrical Room in Room 206	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Operations and Maintenance
56	Terrazzo Sinks			Washrooms	No ACBM	MISC					
57	Insulation Inside Firedoors	160	SF	Exits and Boiler Room	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
58	Exterior Dark Brick - Not AHERA			Exterior of Main Building	No ACBM	MISC					
59	Exterior Dark Brick Mortar - Not AHERA			Exterior of Main Building	No ACBM	MISC					
6	Fiberglass Insulation Backing on HVAC Unit			Room 122- ABATED	Abated	TSI					
60	Exterior Light Face Brick - Not AHERA			Exterior of Main Building	No ACBM	MISC					
61	Exterior Light Face Brick Mortar - Not AHERA			Exterior of Main Building	No ACBM	MISC					
62	Exterior Door Grout - Not AHERA			Exterior of Main Building	No ACBM	MISC					
63	Exterior Blue Brick - Not AHERA			Exterior of Main Building	No ACBM	MISC					
64	Exterior Blue Brick Mortar - Not AHERA			Exterior of Main Building	No ACBM	MISC					
65	Exterior Window Grout - Not AHERA			Exterior of Main Building	No ACBM	MISC					
66	Roof - Not AHERA			Boiler House	Assumed						
67	Roof Flashing - Not AHERA			Boiler House	Assumed						
68	Roof - Not AHERA			Main Building	Assumed	MISC	No				
69	Roof Flashing - Not AHERA			Main Building	Assumed	MISC	No				
7	Plaster			Throughout Building	No ACBM	SURFACE					
70	Mastic on Wall	0	SF	Room 128 - Material not observed	Chrysotile	MISC	No		SF		
71	1' x 1' Fissured Ceiling Tile Mastic	10,000	SF	Throughout Building, Cafeteria	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
72	2' x 4' Ceiling Panels	2,400	SF	Room 208, 117	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
73	Drywall	1,600	SF	Room 208	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
74	Drywall Compound	200	LF	Room 208	Assumed	MISC	Yes	0	LF	6 ACBM with the potential for damage	Operations and Maintenance

Chicago Public Schools

School Dunbar High School

Unit 53021

Building ID 1030

Address 3000 S. King Dr.

Chicago, IL, 60616

Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
75	Boiler Gaskets	10	SF	Bryan Boiler in Basement	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
76	12" x 12" Multi-Gray Floor Tile	2,000	SF	Rooms 203 & 205	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
77	12" x 12" Multi-Gray Floor Tile Mastic	2,000	SF	Rooms 203 & 205	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
78	1' x 1' White Small Fissured Ceiling Tile	4,700	SF	Lunchroom	Assumed	MISC	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Operations and Maintenance
8	Plaster Above Ceiling Tiles			Shop Wing	Assumed	SURFACE					
80	12 x 12 gold and beige pattern FT	2,000	SF	114, 207, 206, 204, 107	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
80M	12 x 12 gold and beige pattern VFT mastic	2,000	SF	114, 207, 206, 204, 107	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
81	12x12 Blueish Grey w/ Dark Grey & White Floor Tile	800	SF	Rm 128, 100	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
82	12x12 Blueish Grey w/Dark Grey & White Floor Tile Mastic	800	SF	Rm 128, 100	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
83	12x12 Lt Grey w/Dark Grey & White Floor Tile	3,200	SF	Rm 100, 128, 203, 301, 300, 308	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
84	12x12 Lt Grey w/Dark Grey & White Floor Tile Mastic	3,200	SF	Rm 100, 128, 203, 301, 300, 308	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
85	12" X 12" Blotted Blue VFT	26,000	SF	Throughout Hallways and Various Rooms	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	
86	12" X 12" Light Blue VFT	4,000	SF	Throughout Hallways and Various Classrooms	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	
87	Mastic for HA 85 and 86	30,000	SF	Throughout Hallways and Various Classrooms	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	
9	Drywall Joint Compound			Room 108	No ACBM	MISC					
A	Aircell Pipe Insulation	500	LF	Pipe Chases, Boiler Room and Throughout Building	Chrysotile	TSI	Yes	15	LF	7 Any remaining friable ACBM or friable suspect ACBM	Remove
B	(Cardboard) Paperwrap Pipe Insulation	600	LF	Boiler Room and Throughout Building, rm 115, 125	Chrysotile	TSI	Yes	1	LF	7 Any remaining friable ACBM or friable suspect ACBM	Repair
C	Aircell Duct Insulation			Abated in 1992 - See 2004 Comments	Abated	TSI					
D	Mag Block Insulation			Boilers in Boiler House - Abated 1992	Abated	TSI					
E	Mag Block Pipe Insulation			Boiler House - Abated 1992	Abated	TSI					
F	Mag Block Duct Insulation			Boiler House - Abated 1992	Abated	TSI					
G	Fittings on Fiberglass Pipe Insulation	60	LF	Main Building	Assumed	TSI	Yes	0	LF	7 Any remaining friable ACBM or friable suspect ACBM	Operations and Maintenance
HA-1000	White woven electrical wire insulation	50	LF	Auditorium stage light fixtures	Chrysotile	MISC	Yes	0	LF	7 Any remaining friable ACBM or friable suspect ACBM	Operations and Maintenance
I3 I	9"x 9" White Floor Tile w/Brn & Blk Streaks Mastic	1,500	SF	Rooms 212 and 311	Chrysotile	MISC	No		SF		
J	Cementitious Pipe Joint Insulation on Aircell Pipe	50	LF	Pipe Chases, Boiler Room and	Assumed	TSI	No	0	LF	6 ACBM with the potential for damage	Operations and Maintenance

Chicago Public Schools

School Dunbar High School

Unit 53021

Building ID 1030

Address 3000 S. King Dr.

Chicago, IL, 60616

Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
K	Cementitious Pipe Joint Insulation on Paperwrap	20	LF	Throughout Building Boiler Room, Pipe Chases and Throughout Building	Chrysotile	TSI	Yes	0	LF	7 Any remaining friable ACBM or friable suspect ACBM	Operations and Maintenance

Review Date	4/14/2013
Manager Planner Name	Todd Huffer

HA Number	Management Comments
1 A	

Chicago Public Schools

School Dunbar High School
Address 3000 S. King Dr.

Unit 53021
 Chicago, IL, 60616

Building ID 1030
Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

100-09870	5/15/2013
Manager IDPH License No/Expiration	

HA Number	Management Comments
1 B	
1 C	Material was not observed - 2013 3 years re-inspection
10	
1030	
11	
12	
13 A	
13 B	
13 D	
13 E	
13 F	
13 G	
13 H	
13 J	
13C	
14 A	
14 AA	
14 AB	
14 AC	Material was not observed - 2013 3 years re-inspection
14 AD	Material was not observed - 2013 3 years re-inspection
14 AE	
14 AF	
14 B	
14 C	
14 D	
14 E	
14 F	

Chicago Public Schools

School Dunbar High School
Address 3000 S. King Dr.

Unit 53021
 Chicago, IL, 60616

Building ID 1030
Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
14 G	
14 H	
14 I	
14 J	
14 K	
14 L	
14 M	
14 N	
14 O	
14 P	
14 Q	
14 R	
14 S	
14 T	
14 U	
14 V	
14 W	
14 X	
14 Y	Material was not observed - 2013 3 years re-inspection
14 Z	
15	
16 A	
16 B	
16 C	
16 D	
17 A	
17 B	

Chicago Public Schools

School Dunbar High School

Unit 53021

Building ID 1030

Address 3000 S. King Dr.

Chicago, IL, 60616

Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
17 C	
17 D	
18	
19	
2 A	Material was not observed in all corridors- 2013 3 years re-inspection
2 B	Material was not observed in corridors - 2013 3 years re-inspection
2 C	
2 D	Material was not observed - 2013 3 years re-inspection
2 E	
2 F	
2 G	
2 H	
2 I	
2 J	
20	
21	
22	
23	
24	
25	
251	Material was not observed - 2013 3 years re-inspection
26	
27	
28	
29	
3 AA	
3 AB	

Chicago Public Schools

School Dunbar High School
Address 3000 S. King Dr.

Unit 53021
 Chicago, IL, 60616

Building ID 1030
Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
3 AC	Material was not observed - 2013 3 years re-inspectio
3 AD	Material was not observed - 2013 3 years re-inspection
3 AE	Not observed in room 208
3 AF	Not observed in room 208
3 B	
3 C	
3 D	Material was not observed - 2013 3 years re-inspection
3 E	Material was not observed - 2013 3 years re-inspection
3 F	
3 G	
3 H	
3 I	
3 J	
3 K	
3 L	
3 M	
3 N	
3 O	
3 P	
3 Q	
3 R	Material may exist under new material (not observed)
3 S	
3 T	
3 U	
3 V	Material was not observed - 2013 3 years re-inspection
3 W	Material was not observed - 2013 3 years re-inspection
3 X	Material was not observed - 2013 3 years re-inspection

Chicago Public Schools

School Dunbar High School
Address 3000 S. King Dr.

Unit 53021
 Chicago, IL, 60616

Building ID 1030
Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
3 Y	Material was not observed - 2013 3 years re-inspection
3 Z	
30	
31	
32	
33	
34	
35	
36	
37	
38	
39	
3A	
4	
40	
41	
42	
43	
44	
45	
46	
47	
48	
49	
5	
50	
51	

Chicago Public Schools

School Dunbar High School
Address 3000 S. King Dr.

Unit 53021
 Chicago, IL, 60616

Building ID 1030
Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
52	
53	
54	
55	
56	
57	
58	
59	
6	
60	
61	
62	
63	
64	
65	
66	
67	
68	
69	
7	
70	
71	
72	
73	
74	
75	
76	

Chicago Public Schools

School Dunbar High School

Unit 53021

Building ID 1030

Address 3000 S. King Dr.

Chicago, IL, 60616

Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
77	
78	
8	Material was not observed - 2013 3 years re-inspection
80	
80M	
81	
82	
83	
84	
85	
86	
87	
9	
A	Remove/Repair Damaged area and maintain O&M on remaining HA
B	Remove/Repair Damaged area and maintain O&M on remaining HA
C	
D	
E	
F	
G	
HA-1000	
I3 I	
J	
K	

Chicago Public Schools

School Dunbar High School

Unit 53021

Building ID 1030

Address 3000 S. King Dr.

Chicago, IL, 60616

Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kathy Yurks**
SCHOOL NAME: **Dunbar High School** INSPECTION DATE: **3/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **1 B**
MATERIAL DESCRIPTION: **Beige Carpet Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**

MATERIAL LOCATION: **Engineer's Office**

MATERIAL QUANTITY: **200**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 03/14/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Dunbar High School** REVIEW DATE: **4/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

HOMOGENEOUS AREA: **1 B**
MATERIAL DESCRIPTION: **Beige Carpet Mastic**
MATERIAL LOCATION: **Engineer's Office**
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **04/14/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kathy Yurks**
SCHOOL NAME: **Dunbar High School** INSPECTION DATE: **3/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **1 C**
MATERIAL DESCRIPTION: **Gold Carpet Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **Moderate**

MATERIAL LOCATION: **Room 9-C**

MATERIAL QUANTITY: **600**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS: **Material was not observed - 2013 3 years re-inspection**

Inspector's Signature: _____



Date: 03/14/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Dunbar High School** REVIEW DATE: **4/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

HOMOGENEOUS AREA: **1 C**
MATERIAL DESCRIPTION: **Gold Carpet Mastic**
MATERIAL LOCATION: **Room 9-C**
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Material was not observed - 2013 3 years re-inspection

Management Planner's Signature: _____



Date: 04/14/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kathy Yurks**
SCHOOL NAME: **Dunbar High School** INSPECTION DATE: **3/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **10**
MATERIAL DESCRIPTION: **Ceramic Floor Tile Grout**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Washrooms**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **03/14/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Dunbar High School** REVIEW DATE: **4/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

HOMOGENEOUS AREA: **10**

MATERIAL DESCRIPTION: **Ceramic Floor Tile Grout**

MATERIAL LOCATION: **Washrooms**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **04/14/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kathy Yurks**
SCHOOL NAME: **Dunbar High School** INSPECTION DATE: **3/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **1030**
MATERIAL DESCRIPTION: **12" x 12" White Floor Tile w/ Blue Streaks Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**

MATERIAL LOCATION: **208**

MATERIAL QUANTITY: **600**


MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 03/14/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Dunbar High School** REVIEW DATE: **4/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

HOMOGENEOUS AREA: **1030**

MATERIAL DESCRIPTION: **12" x 12" White Floor Tile w/ Blue Streaks Mastic**

MATERIAL LOCATION: **208**

MATERIAL QUANTITY: **600**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **04/14/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kathy Yurks**
SCHOOL NAME: **Dunbar High School** INSPECTION DATE: **3/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **11**
MATERIAL DESCRIPTION: **Peg Board**
HISTORICAL AHERA DAMAGE CATEGORY **5 ACBM with potential for significant damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **5. ACBM with potential for significant damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Auditorium Walls**
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 03/14/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Dunbar High School** REVIEW DATE: **4/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

HOMOGENEOUS AREA: **11**
MATERIAL DESCRIPTION: **Peg Board**
MATERIAL LOCATION: **Auditorium Walls**
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **04/14/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kathy Yurks**
SCHOOL NAME: **Dunbar High School** INSPECTION DATE: **3/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **12**
MATERIAL DESCRIPTION: **Terrazzo**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Foyer**

MATERIAL QUANTITY:


MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **03/14/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Dunbar High School** REVIEW DATE: **4/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

HOMOGENEOUS AREA: **12**

MATERIAL DESCRIPTION: **Terrazzo**

MATERIAL LOCATION: **Foyer**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **04/14/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kathy Yurks**
SCHOOL NAME: **Dunbar High School** INSPECTION DATE: **3/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **13 A**
MATERIAL DESCRIPTION: **9"x9" Dk Green Floor Tile w/ White Streaks Mastic (REMOVED)**
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **Moderate**

MATERIAL LOCATION: **1st, 2nd & 3rd Floor Corridors**

MATERIAL QUANTITY: **6100**


MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS: **Material was not observed - 2013 3 years re-inspection**

Inspector's Signature: _____



Date: **03/14/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Dunbar High School** REVIEW DATE: **4/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

HOMOGENEOUS AREA: **13 A**
MATERIAL DESCRIPTION: **9"x9" Dk Green Floor Tile w/ White Streaks Mastic (REMOVED)**
MATERIAL LOCATION: **1st, 2nd & 3rd Floor Corridors**
MATERIAL QUANTITY: **6100** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **04/14/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kathy Yurks**
SCHOOL NAME: **Dunbar High School** INSPECTION DATE: **3/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **13 B**
MATERIAL DESCRIPTION: **9" x 9" White Floor Tile w/Dark Grn Streaks Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Abated** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **Moderate**

MATERIAL LOCATION: **1st, 2nd & 3rd Floor Corridors**

MATERIAL QUANTITY: **6100**


MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS: **Material was not observed - 2013 3 years re-inspection**

Inspector's Signature: _____



Date: 03/14/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Dunbar High School** REVIEW DATE: **4/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

HOMOGENEOUS AREA: **13 B**
MATERIAL DESCRIPTION: **9" x 9" White Floor Tile w/Dark Grn Streaks Mastic**
MATERIAL LOCATION: **1st, 2nd & 3rd Floor Corridors**
MATERIAL QUANTITY: **6100** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: 04/14/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kathy Yurks**
SCHOOL NAME: **Dunbar High School** INSPECTION DATE: **3/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **13 D**
MATERIAL DESCRIPTION: **9" x 9" White Floor Tile w/ Lt Grn Streaks Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Abated** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **Moderate**

MATERIAL LOCATION: **As Patches in the 1st & 3rd Floor Corridors**

MATERIAL QUANTITY: **400**


MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS: **Material was not observed - 2013 3 years re-inspection**

Inspector's Signature: _____



Date: 03/14/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Dunbar High School** REVIEW DATE: **4/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

HOMOGENEOUS AREA: **13 D**

MATERIAL DESCRIPTION: **9" x 9" White Floor Tile w/ Lt Grn Streaks Mastic**

MATERIAL LOCATION: **As Patches in the 1st & 3rd Floor Corridors**

MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **04/14/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kathy Yurks**
SCHOOL NAME: **Dunbar High School** INSPECTION DATE: **3/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **13 E**
MATERIAL DESCRIPTION: **9" x 9" Brown Floor Tile w/ Brown Streaks Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Abated** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **Moderate**

MATERIAL LOCATION: **1st Floor Corridor, Rooms 100**

MATERIAL QUANTITY: **500**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS: **Material was not observed - 2013 3 years re-inspection**

Inspector's Signature: _____



Date: **03/14/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Dunbar High School** REVIEW DATE: **4/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

HOMOGENEOUS AREA: **13 E**
MATERIAL DESCRIPTION: **9" x 9" Brown Floor Tile w/ Brown Streaks Mastic**
MATERIAL LOCATION: **1st Floor Corridor, Rooms 100**
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: 04/14/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kathy Yurks**
SCHOOL NAME: **Dunbar High School** INSPECTION DATE: **3/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **13 F**
MATERIAL DESCRIPTION: **9"x9" Gray FloorTile w/Lt. Gray & Blk Strks Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Abated** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **Moderate**


MATERIAL LOCATION: **13A&B, Dressing Rms,100,103-105,119,120,128,140,200,208,211,212,214,217,221A&B,225,300, 301,etc.**

MATERIAL QUANTITY: **10692** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS: **Material was not observed - 2013 3 years re-inspection**

Inspector's Signature: _____



Date: 03/14/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Dunbar High School** REVIEW DATE: **4/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

HOMOGENEOUS AREA: **13 F**
MATERIAL DESCRIPTION: **9"x9" Gray FloorTile w/Lt. Gray & Blk Strks Mastic**
MATERIAL LOCATION: **13A&B, Dressing Rms,100,103-105,119,120,128,140,200,208,211,212,214,217,221A&B,225,300,301,etc.**
MATERIAL QUANTITY: **10692** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: 04/14/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kathy Yurks**
SCHOOL NAME: **Dunbar High School** INSPECTION DATE: **3/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **13 G**
MATERIAL DESCRIPTION: **9" x 9" Lt Gray VFT w/ Gray & Blk Strks Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **5 ACBM with potential for significant damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **5. ACBM with potential for significant damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **3 A&B, Dressing Rooms, and Various Classrooms Throughout Building**
MATERIAL QUANTITY: **10692** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 03/14/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Dunbar High School** REVIEW DATE: **4/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

HOMOGENEOUS AREA: **13 G**
MATERIAL DESCRIPTION: **9" x 9" Lt Gray VFT w/ Gray & Blk Strks Mastic**
MATERIAL LOCATION: **3 A&B, Dressing Rooms, and Various Classrooms Throughout Building**
MATERIAL QUANTITY: **10692** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **04/14/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kathy Yurks**
SCHOOL NAME: **Dunbar High School** INSPECTION DATE: **3/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **13 H**
MATERIAL DESCRIPTION: **9"x9" Lt Brn Floor Tile w/Wh & Blk Streaks Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Abated** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **Moderate**

MATERIAL LOCATION: **Rooms 212 & 311**

MATERIAL QUANTITY: **200**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS: **Material was not observed - 2013 3 years re-inspection**

Inspector's Signature: _____



Date: 03/14/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Dunbar High School** REVIEW DATE: **4/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

HOMOGENEOUS AREA: **13 H**

MATERIAL DESCRIPTION: **9"x9" Lt Brn Floor Tile w/Wh & Blk Streaks Mastic**

MATERIAL LOCATION: **Rooms 212 & 311**

MATERIAL QUANTITY: **200**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **04/14/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kathy Yurks**
SCHOOL NAME: **Dunbar High School** INSPECTION DATE: **3/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **13 J**
MATERIAL DESCRIPTION: **9" x 9" Brown Floor Tile w/White Streaks Mastic**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Auditorium**

MATERIAL QUANTITY:


MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **03/14/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Dunbar High School** REVIEW DATE: **4/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

HOMOGENEOUS AREA: **13 J**

MATERIAL DESCRIPTION: **9" x 9" Brown Floor Tile w/White Streaks Mastic**

MATERIAL LOCATION: **Auditorium**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **04/14/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kathy Yurks**
SCHOOL NAME: **Dunbar High School** INSPECTION DATE: **3/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **13C**
MATERIAL DESCRIPTION: **9" x 9" Bright Grn Floor Tile w/ Wh Streaks Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Abated** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **Moderate**

MATERIAL LOCATION: **As Patches in the 1st & 3rd Floor Corridors**

MATERIAL QUANTITY: **400**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS: **Material was not observed - 2013 3 years re-inspection**

Inspector's Signature: _____



Date: 03/14/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUILDING ID: **1030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Dunbar High School** REVIEW DATE: **4/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

HOMOGENEOUS AREA: **13C**
MATERIAL DESCRIPTION: **9" x 9" Bright Grn Floor Tile w/ Wh Streaks Mastic**
MATERIAL LOCATION: **As Patches in the 1st & 3rd Floor Corridors**
MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: 04/14/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kathy Yurks**
SCHOOL NAME: **Dunbar High School** INSPECTION DATE: **3/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **14 A**
MATERIAL DESCRIPTION: **12" x 12" White FT w/Blue & Grey Streaks Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Abated** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **Moderate**

MATERIAL LOCATION: **Rooms 222, 224, 310, and 312**

MATERIAL QUANTITY: **5600**


MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS: **Material was not observed - 2013 3 years re-inspection**

Inspector's Signature: _____



Date: 03/14/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Dunbar High School** REVIEW DATE: **4/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

HOMOGENEOUS AREA: **14 A**
MATERIAL DESCRIPTION: **12" x 12" White FT w/Blue & Grey Streaks Mastic**
MATERIAL LOCATION: **Rooms 222, 224, 310, and 312**
MATERIAL QUANTITY: **5600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **04/14/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kathy Yurks**
SCHOOL NAME: **Dunbar High School** INSPECTION DATE: **3/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **14 AA**
MATERIAL DESCRIPTION: **12" x 12" Gray Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Band Room Hall, Chorus Room, Foyer & Practice Room**
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 03/14/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Dunbar High School** REVIEW DATE: **4/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

HOMOGENEOUS AREA: **14 AA**
MATERIAL DESCRIPTION: **12" x 12" Gray Floor Tile Mastic**
MATERIAL LOCATION: **Band Room Hall, Chorus Room, Foyer & Practice Room**
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **04/14/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kathy Yurks**
SCHOOL NAME: **Dunbar High School** INSPECTION DATE: **3/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **14 AB**
MATERIAL DESCRIPTION: **12" x 12" Multi-Blue Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Room 208**
MATERIAL QUANTITY: **1600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 03/14/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Dunbar High School** REVIEW DATE: **4/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

HOMOGENEOUS AREA: **14 AB**

MATERIAL DESCRIPTION: **12" x 12" Multi-Blue Floor Tile Mastic**

MATERIAL LOCATION: **Room 208**

MATERIAL QUANTITY: **1600**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **04/14/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kathy Yurks**
SCHOOL NAME: **Dunbar High School** INSPECTION DATE: **3/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **14 AC**
MATERIAL DESCRIPTION: **12" x 12" Beige Floor Tile Mastic - Replaced**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 128**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Material was not observed - 2013 3 years re-inspection**

Inspector's Signature:



Date: **03/14/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Dunbar High School** REVIEW DATE: **4/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

HOMOGENEOUS AREA: **14 AC**

MATERIAL DESCRIPTION: **12" x 12" Beige Floor Tile Mastic - Replaced**

MATERIAL LOCATION: **Room 128**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Material was not observed - 2013 3 years re-inspection

Management Planner's Signature: _____



Date: **04/14/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kathy Yurks**
SCHOOL NAME: **Dunbar High School** INSPECTION DATE: **3/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **14 AD**
MATERIAL DESCRIPTION: **12" x 12" Blue Floor Tile Mastic - Replaced**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 128**

MATERIAL QUANTITY:


MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Material was not observed - 2013 3 years re-inspection**

Inspector's Signature:



Date: **03/14/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Dunbar High School** REVIEW DATE: **4/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

HOMOGENEOUS AREA: **14 AD**

MATERIAL DESCRIPTION: **12" x 12" Blue Floor Tile Mastic - Replaced**

MATERIAL LOCATION: **Room 128**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Material was not observed - 2013 3 years re-inspection

Management Planner's Signature: _____



Date: **04/14/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kathy Yurks**
SCHOOL NAME: **Dunbar High School** INSPECTION DATE: **3/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **14 AE**
MATERIAL DESCRIPTION: **12" x 12" White Floor Tile w/ Blue Streaks Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Room 208**
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 03/14/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Dunbar High School** REVIEW DATE: **4/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

HOMOGENEOUS AREA: **14 AE**

MATERIAL DESCRIPTION: **12" x 12" White Floor Tile w/ Blue Streaks Mastic**

MATERIAL LOCATION: **Room 208**

MATERIAL QUANTITY: **600**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **04/14/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kathy Yurks**
SCHOOL NAME: **Dunbar High School** INSPECTION DATE: **3/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **14 AF**
MATERIAL DESCRIPTION: **12" x 12" Gray Floor Tile w/ Black Streaks Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**

MATERIAL LOCATION: **Room 208**

MATERIAL QUANTITY: **20**


MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 03/14/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Dunbar High School** REVIEW DATE: **4/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

HOMOGENEOUS AREA: **14 AF**

MATERIAL DESCRIPTION: **12" x 12" Gray Floor Tile w/ Black Streaks Mastic**

MATERIAL LOCATION: **Room 208**

MATERIAL QUANTITY: **20**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: 04/14/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kathy Yurks**
SCHOOL NAME: **Dunbar High School** INSPECTION DATE: **3/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **14 B**
MATERIAL DESCRIPTION: **12" x 12" Gray VFT w/ Wh & Blk Streaks Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Men's Lounge**
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 03/14/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Dunbar High School** REVIEW DATE: **4/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

HOMOGENEOUS AREA: **14 B**
MATERIAL DESCRIPTION: **12" x 12" Gray VFT w/ Wh & Blk Streaks Mastic**
MATERIAL LOCATION: **Men's Lounge**
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **04/14/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kathy Yurks**
SCHOOL NAME: **Dunbar High School** INSPECTION DATE: **3/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **14 C**
MATERIAL DESCRIPTION: **12" x 12" Dk Gray Floor Tile w/Blk Streaks Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Rooms 140, 211, 214, 217, 305, 308, and 313**
MATERIAL QUANTITY: **5400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 03/14/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Dunbar High School** REVIEW DATE: **4/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

HOMOGENEOUS AREA: **14 C**
MATERIAL DESCRIPTION: **12" x 12" Dk Gray Floor Tile w/Blk Streaks Mastic**
MATERIAL LOCATION: **Rooms 140, 211, 214, 217, 305, 308, and 313**
MATERIAL QUANTITY: **5400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **04/14/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kathy Yurks**
SCHOOL NAME: **Dunbar High School** INSPECTION DATE: **3/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **14 D**
MATERIAL DESCRIPTION: **12" x12" Brown VFT w/ Dk Brn & White Strks Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **5 ACBM with potential for significant damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Enclose
Operations and Maintenance**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **5. ACBM with potential for significant damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**

MATERIAL LOCATION: **Boys Gym, Lunchroom, 1st and 2nd Floor Corridors, 114, 201, 213, 215, 216, 218-220, 223, 227, 303**

MATERIAL QUANTITY: **25000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 03/14/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Dunbar High School** REVIEW DATE: **4/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

HOMOGENEOUS AREA: **14 D**
MATERIAL DESCRIPTION: **12" x12" Brown VFT w/ Dk Brn & White Strks Mastic**
MATERIAL LOCATION: **Boys Gym, Lunchroom, 1st and 2nd Floor Corridors, 114, 201, 213, 215, 216, 218-220, 223, 227, 303**
MATERIAL QUANTITY: **25000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **20** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Enclose
Operations and Maintenance**

Comments:

Management Planner's Signature: _____



Date: **04/14/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kathy Yurks**
SCHOOL NAME: **Dunbar High School** INSPECTION DATE: **3/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **14 E**
MATERIAL DESCRIPTION: **12" x 12" White Floor Tile w/Brown Streaks Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **5 ACBM with potential for significant damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Enclose
Operations and Maintenance**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **5. ACBM with potential for significant damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**

MATERIAL LOCATION: **Boys Gym, Lunchroom, 1st and 2nd Floor Corridors, 114, 201, 213, 215, 216, 218-220, 223, 227, 303**

MATERIAL QUANTITY: **25000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 03/14/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Dunbar High School** REVIEW DATE: **4/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

HOMOGENEOUS AREA: **14 E**
MATERIAL DESCRIPTION: **12" x 12" White Floor Tile w/Brown Streaks Mastic**
MATERIAL LOCATION: **Boys Gym, Lunchroom, 1st and 2nd Floor Corridors, 114, 201, 213, 215, 216, 218-220, 223, 227, 303**
MATERIAL QUANTITY: **25000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **20** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Enclose
Operations and Maintenance**

Comments:

Management Planner's Signature: _____



Date: **04/14/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kathy Yurks**
SCHOOL NAME: **Dunbar High School** INSPECTION DATE: **3/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **14 F**
MATERIAL DESCRIPTION: **12"x12" Lt Brown Floor Tile w/White Streaks Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT


This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **1st Floor Corridor by Ramps and as a Patch in the 2nd Floor Corridor**
MATERIAL QUANTITY: **750** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____



Date: 03/14/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Dunbar High School** REVIEW DATE: **4/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

HOMOGENEOUS AREA: **14 F**
MATERIAL DESCRIPTION: **12"x12" Lt Brown Floor Tile w/White Streaks Mastic**
MATERIAL LOCATION: **1st Floor Corridor by Ramps and as a Patch in the 2nd Floor Corridor**
MATERIAL QUANTITY: **750** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **04/14/2013**

Chicago Public Schools

Carnow, Conibear and Associates 2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kathy Yurks**
SCHOOL NAME: **Dunbar High School** INSPECTION DATE: **3/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **14 G**
MATERIAL DESCRIPTION: **12"x12" Gray Floor Tile w/Dk Gray/Wh Streaks Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Rooms 100, 119, 121, 140, 305, 306, 308, 313, 209 Library**
MATERIAL QUANTITY: **8300** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 03/14/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Dunbar High School** REVIEW DATE: **4/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

HOMOGENEOUS AREA: **14 G**
MATERIAL DESCRIPTION: **12"x12"Gray Floor Tile w/Dk Gray/Wh Streaks Mastic**
MATERIAL LOCATION: **Rooms 100, 119, 121, 140, 305, 306, 308, 313, 209 Library**
MATERIAL QUANTITY: **8300** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **04/14/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kathy Yurks**
SCHOOL NAME: **Dunbar High School** INSPECTION DATE: **3/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **14 H**
MATERIAL DESCRIPTION: **12" x 12" Beige Floor Tile w/White Streaks Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **1st Floor Corridor by Ramps and as a Patch in the 2nd Floor Corridor**
MATERIAL QUANTITY: **250** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____



Date: 03/14/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Dunbar High School** REVIEW DATE: **4/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

HOMOGENEOUS AREA: **14 H**
MATERIAL DESCRIPTION: **12" x 12" Beige Floor Tile w/White Streaks Mastic**
MATERIAL LOCATION: **1st Floor Corridor by Ramps and as a Patch in the 2nd Floor Corridor**
MATERIAL QUANTITY: **250** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **04/14/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kathy Yurks**
SCHOOL NAME: **Dunbar High School** INSPECTION DATE: **3/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **14 I**
MATERIAL DESCRIPTION: **12" x 12" Brown Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**

MATERIAL LOCATION: **Room 138**

MATERIAL QUANTITY: **250**


MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 03/14/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Dunbar High School** REVIEW DATE: **4/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

HOMOGENEOUS AREA: **14 I**
MATERIAL DESCRIPTION: **12" x 12" Brown Floor Tile Mastic**
MATERIAL LOCATION: **Room 138**
MATERIAL QUANTITY: **250** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **04/14/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kathy Yurks**
SCHOOL NAME: **Dunbar High School** INSPECTION DATE: **3/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **14 J**
MATERIAL DESCRIPTION: **12" x 12" Beige Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Room 138**

MATERIAL QUANTITY: **432**


MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 03/14/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Dunbar High School** REVIEW DATE: **4/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

HOMOGENEOUS AREA: **14 J**
MATERIAL DESCRIPTION: **12" x 12" Beige Floor Tile Mastic**
MATERIAL LOCATION: **Room 138**
MATERIAL QUANTITY: **432** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **04/14/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kathy Yurks**
SCHOOL NAME: **Dunbar High School** INSPECTION DATE: **3/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **14 K**
MATERIAL DESCRIPTION: **12" x 12" Green Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Abated** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **Moderate**

MATERIAL LOCATION: **1st, 2nd & 3rd Floor Corridors as Patches**

MATERIAL QUANTITY: **150**


MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS: **Material was not observed - 2013 3 years re-inspection**

Inspector's Signature: _____



Date: 03/14/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Dunbar High School** REVIEW DATE: **4/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

HOMOGENEOUS AREA: **14 K**
MATERIAL DESCRIPTION: **12" x 12" Green Floor Tile Mastic**
MATERIAL LOCATION: **1st, 2nd & 3rd Floor Corridors as Patches**
MATERIAL QUANTITY: **150** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: 04/14/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kathy Yurks**
SCHOOL NAME: **Dunbar High School** INSPECTION DATE: **3/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **14 L**
MATERIAL DESCRIPTION: **12" x 12" Light Green Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Abated** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **Moderate**

MATERIAL LOCATION: **1st, 2nd & 3rd Floor Corridors as Patches**

MATERIAL QUANTITY: **150**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS: **Material was not observed - 2013 3 years re-inspection**

Inspector's Signature: _____



Date: 03/14/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Dunbar High School** REVIEW DATE: **4/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

HOMOGENEOUS AREA: **14 L**
MATERIAL DESCRIPTION: **12" x 12" Light Green Floor Tile Mastic**
MATERIAL LOCATION: **1st, 2nd & 3rd Floor Corridors as Patches**
MATERIAL QUANTITY: **150** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **04/14/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kathy Yurks**
SCHOOL NAME: **Dunbar High School** INSPECTION DATE: **3/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **14 M**
MATERIAL DESCRIPTION: **12" x 12" Gray Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **5 ACBM with potential for significant damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **5. ACBM with potential for significant damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **1st Floor Corridor Ramps**
MATERIAL QUANTITY: **550** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 03/14/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Dunbar High School** REVIEW DATE: **4/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

HOMOGENEOUS AREA: **14 M**
MATERIAL DESCRIPTION: **12" x 12" Gray Floor Tile Mastic**
MATERIAL LOCATION: **1st Floor Corridor Ramps**
MATERIAL QUANTITY: **550** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **04/14/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kathy Yurks**
SCHOOL NAME: **Dunbar High School** INSPECTION DATE: **3/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **14 N**
MATERIAL DESCRIPTION: **12" x 12" Gray Floor Tile w/White Streaks Mastic**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 104**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **03/14/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Dunbar High School** REVIEW DATE: **4/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

HOMOGENEOUS AREA: **14 N**

MATERIAL DESCRIPTION: **12" x 12" Gray Floor Tile w/White Streaks Mastic**

MATERIAL LOCATION: **Room 104**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **04/14/2013** _____

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kathy Yurks**
SCHOOL NAME: **Dunbar High School** INSPECTION DATE: **3/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **14 O**
MATERIAL DESCRIPTION: **12" x 12" White Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 132**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **03/14/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Dunbar High School** REVIEW DATE: **4/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

HOMOGENEOUS AREA: **14 O**

MATERIAL DESCRIPTION: **12" x 12" White Floor Tile Mastic**

MATERIAL LOCATION: **Room 132**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **04/14/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kathy Yurks**
SCHOOL NAME: **Dunbar High School** INSPECTION DATE: **3/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **14 P**
MATERIAL DESCRIPTION: **12" x 12" Blue Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 132**

MATERIAL QUANTITY:


MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **03/14/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Dunbar High School** REVIEW DATE: **4/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

HOMOGENEOUS AREA: **14 P**

MATERIAL DESCRIPTION: **12" x 12" Blue Floor Tile Mastic**

MATERIAL LOCATION: **Room 132**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **04/14/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kathy Yurks**
SCHOOL NAME: **Dunbar High School** INSPECTION DATE: **3/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **14 Q**
MATERIAL DESCRIPTION: **12" x 12" Black Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Room 105**
MATERIAL QUANTITY: **1100** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 03/14/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Dunbar High School** REVIEW DATE: **4/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

HOMOGENEOUS AREA: **14 Q**
MATERIAL DESCRIPTION: **12" x 12" Black Floor Tile Mastic**
MATERIAL LOCATION: **Room 105**
MATERIAL QUANTITY: **1100** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **04/14/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kathy Yurks**
SCHOOL NAME: **Dunbar High School** INSPECTION DATE: **3/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **14 R**
MATERIAL DESCRIPTION: **12" x 12" White Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Room 105**
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 03/14/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Dunbar High School** REVIEW DATE: **4/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

HOMOGENEOUS AREA: **14 R**
MATERIAL DESCRIPTION: **12" x 12" White Floor Tile Mastic**
MATERIAL LOCATION: **Room 105**
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **04/14/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kathy Yurks**
SCHOOL NAME: **Dunbar High School** INSPECTION DATE: **3/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **14 S**
MATERIAL DESCRIPTION: **12" x 12" Light Blue Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Room 104, 221B, 223**
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 03/14/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Dunbar High School** REVIEW DATE: **4/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

HOMOGENEOUS AREA: **14 S**

MATERIAL DESCRIPTION: **12" x 12" Light Blue Floor Tile Mastic**

MATERIAL LOCATION: **Room 104, 221B, 223**

MATERIAL QUANTITY: **600**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **04/14/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kathy Yurks**
SCHOOL NAME: **Dunbar High School** INSPECTION DATE: **3/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **14 T**
MATERIAL DESCRIPTION: **12" x 12" Light Brown Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms 114, 117, 119, 130, 206, & 207**
MATERIAL QUANTITY: **700** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 03/14/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Dunbar High School** REVIEW DATE: **4/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

HOMOGENEOUS AREA: **14 T**
MATERIAL DESCRIPTION: **12" x 12" Light Brown Floor Tile Mastic**
MATERIAL LOCATION: **Rooms 114, 117, 119, 130, 206, & 207**
MATERIAL QUANTITY: **700** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **04/14/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kathy Yurks**
SCHOOL NAME: **Dunbar High School** INSPECTION DATE: **3/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **14 U**
MATERIAL DESCRIPTION: **12" x 12" Beige Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Rooms 114, 117, 119, 130, 206, & 207**

MATERIAL QUANTITY: **700**


MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 03/14/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Dunbar High School** REVIEW DATE: **4/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

HOMOGENEOUS AREA: **14 U**
MATERIAL DESCRIPTION: **12" x 12" Beige Floor Tile Mastic**
MATERIAL LOCATION: **Rooms 114, 117, 119, 130, 206, & 207**
MATERIAL QUANTITY: **700** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **04/14/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kathy Yurks**
SCHOOL NAME: **Dunbar High School** INSPECTION DATE: **3/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **14 V**
MATERIAL DESCRIPTION: **12"x12" Dk Brn Floor Tile w/Dk Brn & Lt Brn Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Abated** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **Moderate**

MATERIAL LOCATION: **On Cabinets in Various Classrooms**

MATERIAL QUANTITY: **300**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS: **Material was not observed - 2013 3 years re-inspection**

Inspector's Signature: _____



Date: 03/14/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Dunbar High School** REVIEW DATE: **4/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

HOMOGENEOUS AREA: **14 V**
MATERIAL DESCRIPTION: **12"x12" Dk Brn Floor Tile w/Dk Brn & Lt Brn Mastic**
MATERIAL LOCATION: **On Cabinets in Various Classrooms**
MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **04/14/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kathy Yurks**
SCHOOL NAME: **Dunbar High School** INSPECTION DATE: **3/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **14 W**
MATERIAL DESCRIPTION: **12"x12" Gray Floor Tile w/Lt. Gray Streaks Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Abated** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **Moderate**

MATERIAL LOCATION: **On Cabinets in Various Classrooms**

MATERIAL QUANTITY: **300**


MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS: **Material was not observed - 2013 3 years re-inspection**

Inspector's Signature: _____



Date: **03/14/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Dunbar High School** REVIEW DATE: **4/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

HOMOGENEOUS AREA: **14 W**
MATERIAL DESCRIPTION: **12"x12" Gray Floor Tile w/Lt. Gray Streaks Mastic**
MATERIAL LOCATION: **On Cabinets in Various Classrooms**
MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **04/14/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kathy Yurks**
SCHOOL NAME: **Dunbar High School** INSPECTION DATE: **3/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **14 X**
MATERIAL DESCRIPTION: **12" x 12" Multi-Brown Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**

MATERIAL LOCATION: **Room 201 and 203**

MATERIAL QUANTITY: **1150**


MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS: **Material was not observed - 2013 3 years re-inspection**

Inspector's Signature: _____



Date: 03/14/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Dunbar High School** REVIEW DATE: **4/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

HOMOGENEOUS AREA: **14 X**
MATERIAL DESCRIPTION: **12" x 12" Multi-Brown Floor Tile Mastic**
MATERIAL LOCATION: **Room 201 and 203**
MATERIAL QUANTITY: **1150** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **04/14/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kathy Yurks**
SCHOOL NAME: **Dunbar High School** INSPECTION DATE: **3/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **14 Y**
MATERIAL DESCRIPTION: **12" x 12" Beige Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **Moderate**

MATERIAL LOCATION: **Rooms 201 and 203**

MATERIAL QUANTITY: **1150**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS: **Material was not observed - 2013 3 years re-inspection**

Inspector's Signature: _____



Date: 03/14/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Dunbar High School** REVIEW DATE: **4/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

HOMOGENEOUS AREA: **14 Y**
MATERIAL DESCRIPTION: **12" x 12" Beige Floor Tile Mastic**
MATERIAL LOCATION: **Rooms 201 and 203**
MATERIAL QUANTITY: **1150** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Material was not observed - 2013 3 years re-inspection

Management Planner's Signature: _____



Date: 04/14/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kathy Yurks**
SCHOOL NAME: **Dunbar High School** INSPECTION DATE: **3/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **14 Z**
MATERIAL DESCRIPTION: **12" x 12" Light Green Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Band Room, Chorus Room, Hall and Foyer**

MATERIAL QUANTITY: **2400**


MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 03/14/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Dunbar High School** REVIEW DATE: **4/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

HOMOGENEOUS AREA: **14 Z**
MATERIAL DESCRIPTION: **12" x 12" Light Green Floor Tile Mastic**
MATERIAL LOCATION: **Band Room, Chorus Room, Hall and Foyer**
MATERIAL QUANTITY: **2400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **04/14/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kathy Yurks**
SCHOOL NAME: **Dunbar High School** INSPECTION DATE: **3/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **15**
MATERIAL DESCRIPTION: **Drywall**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Rooms 132 & 303 and the Office Complex**

MATERIAL QUANTITY:


MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **03/14/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Dunbar High School** REVIEW DATE: **4/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

HOMOGENEOUS AREA: **15**

MATERIAL DESCRIPTION: **Drywall**

MATERIAL LOCATION: **Rooms 132 & 303 and the Office Complex**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **04/14/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kathy Yurks**
SCHOOL NAME: **Dunbar High School** INSPECTION DATE: **3/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **16 A**
MATERIAL DESCRIPTION: **Black Baseboard**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout Building**

MATERIAL QUANTITY:


MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **03/14/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Dunbar High School** REVIEW DATE: **4/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

HOMOGENEOUS AREA: **16 A**

MATERIAL DESCRIPTION: **Black Baseboard**

MATERIAL LOCATION: **Throughout Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **04/14/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kathy Yurks**
SCHOOL NAME: **Dunbar High School** INSPECTION DATE: **3/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **16 B**
MATERIAL DESCRIPTION: **Blue Baseboard**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Office Complex and Room 310**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **03/14/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Dunbar High School** REVIEW DATE: **4/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

HOMOGENEOUS AREA: **16 B**

MATERIAL DESCRIPTION: **Blue Baseboard**

MATERIAL LOCATION: **Office Complex and Room 310**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **04/14/2013** _____

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kathy Yurks**
SCHOOL NAME: **Dunbar High School** INSPECTION DATE: **3/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **16 C**
MATERIAL DESCRIPTION: **4" Beige Baseboard**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Band Room, Hall, Foyer and Chorus Room**
MATERIAL QUANTITY: **300** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: _____



Date: 03/14/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Dunbar High School** REVIEW DATE: **4/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

HOMOGENEOUS AREA: **16 C**
MATERIAL DESCRIPTION: **4" Beige Baseboard**
MATERIAL LOCATION: **Band Room, Hall, Foyer and Chorus Room**
MATERIAL QUANTITY: **300** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **04/14/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kathy Yurks**
SCHOOL NAME: **Dunbar High School** INSPECTION DATE: **3/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **16 D**
MATERIAL DESCRIPTION: **4" Dark Gray Baseboard**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Room 208**
MATERIAL QUANTITY: **150** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: _____



Date: 03/14/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Dunbar High School** REVIEW DATE: **4/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

HOMOGENEOUS AREA: **16 D**
MATERIAL DESCRIPTION: **4" Dark Gray Baseboard**
MATERIAL LOCATION: **Room 208**
MATERIAL QUANTITY: **150** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: 04/14/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kathy Yurks**
SCHOOL NAME: **Dunbar High School** INSPECTION DATE: **3/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **17 A**
MATERIAL DESCRIPTION: **Black Baseboard Mastic**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout Building**

MATERIAL QUANTITY:


MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **03/14/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Dunbar High School** REVIEW DATE: **4/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

HOMOGENEOUS AREA: **17 A**

MATERIAL DESCRIPTION: **Black Baseboard Mastic**

MATERIAL LOCATION: **Throughout Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **04/14/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kathy Yurks**
SCHOOL NAME: **Dunbar High School** INSPECTION DATE: **3/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **17 B**
MATERIAL DESCRIPTION: **Blue Baseboard Mastic**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:


MATERIAL LOCATION: **Office Complex and Room 310**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **03/14/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Dunbar High School** REVIEW DATE: **4/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

HOMOGENEOUS AREA: **17 B**
MATERIAL DESCRIPTION: **Blue Baseboard Mastic**
MATERIAL LOCATION: **Office Complex and Room 310**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **04/14/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kathy Yurks**
SCHOOL NAME: **Dunbar High School** INSPECTION DATE: **3/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **17 C**
MATERIAL DESCRIPTION: **4" Beige Baseboard Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**


MATERIAL LOCATION: **Band Room, Chorus Room, Hall and Foyer**

MATERIAL QUANTITY: **300** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: _____



Date: 03/14/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Dunbar High School** REVIEW DATE: **4/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

HOMOGENEOUS AREA: **17 C**
MATERIAL DESCRIPTION: **4" Beige Baseboard Mastic**
MATERIAL LOCATION: **Band Room, Chorus Room, Hall and Foyer**
MATERIAL QUANTITY: **300** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: 04/14/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kathy Yurks**
SCHOOL NAME: **Dunbar High School** INSPECTION DATE: **3/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **17 D**
MATERIAL DESCRIPTION: **4" Dark Gray Baseboard Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Room 208**
MATERIAL QUANTITY: **150** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: _____



Date: 03/14/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Dunbar High School** REVIEW DATE: **4/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

HOMOGENEOUS AREA: **17 D**
MATERIAL DESCRIPTION: **4" Dark Gray Baseboard Mastic**
MATERIAL LOCATION: **Room 208**
MATERIAL QUANTITY: **150** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **04/14/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kathy Yurks**
SCHOOL NAME: **Dunbar High School** INSPECTION DATE: **3/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **18**
MATERIAL DESCRIPTION: **Tank # 1 Insulation Jacket (Closest to Door)**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Boiler House**

MATERIAL QUANTITY:


MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **03/14/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Dunbar High School** REVIEW DATE: **4/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

HOMOGENEOUS AREA: **18**

MATERIAL DESCRIPTION: **Tank # 1 Insulation Jacket (Closest to Door)**

MATERIAL LOCATION: **Boiler House**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **04/14/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kathy Yurks**
SCHOOL NAME: **Dunbar High School** INSPECTION DATE: **3/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **19**
MATERIAL DESCRIPTION: **Tank Insulation Jacket (Middle Tank)**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Boiler House**

MATERIAL QUANTITY:


MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **03/14/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Dunbar High School** REVIEW DATE: **4/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

HOMOGENEOUS AREA: **19**

MATERIAL DESCRIPTION: **Tank Insulation Jacket (Middle Tank)**

MATERIAL LOCATION: **Boiler House**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **04/14/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kathy Yurks**
SCHOOL NAME: **Dunbar High School** INSPECTION DATE: **3/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **2 A**
MATERIAL DESCRIPTION: **9" x 9' Dark Green Floor Tiles w/White Streaks**
HISTORICAL AHERA DAMAGE CATEGORY **5 ACBM with potential for significant damage**
HISTORICAL DAMAGE REASON: **Physical Damage**
HISTORICAL RESPONSE ACTION: **Operations and Maintenance Repair**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**


RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **5. ACBM with potential for significant damage**

DAMAGE REASON: **Physical Damage**
DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **1st, 2nd and 3rd Floor Corridors and Gym Balcony, Closet**
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **2000** DAMAGE UNITS: **SF**
COMMENTS: **Material was not observed in all corridors- 2013 3 years re-inspection**

Inspector's Signature: _____



Date: 03/14/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Dunbar High School** REVIEW DATE: **4/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

HOMOGENEOUS AREA: **2 A**
MATERIAL DESCRIPTION: **9" x 9' Dark Green Floor Tiles w/White Streaks**
MATERIAL LOCATION: **1st, 2nd and 3rd Floor Corridors and Gym Balcony, Closet**
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **30** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance Repair

Comments:

Material was not observed in all corridors- 2013 3 years re-inspection

Management Planner's Signature: _____



Date: **04/14/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kathy Yurks**
SCHOOL NAME: **Dunbar High School** INSPECTION DATE: **3/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **2 B**
MATERIAL DESCRIPTION: **9" x 9" White Floor Tile w/Dark Green Streaks**
HISTORICAL AHERA DAMAGE CATEGORY **5 ACBM with potential for significant damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Repair
Operations and Maintenance**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**


RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **5. ACBM with potential for significant damage**

DAMAGE REASON: **Physical Damage**
DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Various 1st, 2nd, and 3rd Floor Corridors and Gym Balcony, Closet**
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS: **Material was not observed in corridors - 2013 3 years re-inspection**

Inspector's Signature: _____



Date: 03/14/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Dunbar High School** REVIEW DATE: **4/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

HOMOGENEOUS AREA: **2 B**
MATERIAL DESCRIPTION: **9" x 9" White Floor Tile w/Dark Green Streaks**
MATERIAL LOCATION: **Various 1st, 2nd, and 3rd Floor Corridors and Gym Balcony, Closet**
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **30** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Repair
Operations and Maintenance**

Comments:

Material was not observed in corridors - 2013 3 years re-inspection

Management Planner's Signature: _____



Date: **04/14/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kathy Yurks**
SCHOOL NAME: **Dunbar High School** INSPECTION DATE: **3/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **2 C**
MATERIAL DESCRIPTION: **9" x 9" Bright Green Floor Tile w/ White Streaks**
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with potential for significant damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Abated** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **Moderate**

MATERIAL LOCATION: **As Patches in the 1st and 3rd Floor Corridors**

MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS: **Material was not observed - 2013 3 years re-inspection**

Inspector's Signature: _____



Date: 03/14/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Dunbar High School** REVIEW DATE: **4/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

HOMOGENEOUS AREA: **2 C**
MATERIAL DESCRIPTION: **9" x 9" Bright Green Floor Tile w/ White Streaks**
MATERIAL LOCATION: **As Patches in the 1st and 3rd Floor Corridors**
MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: 04/14/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kathy Yurks**
SCHOOL NAME: **Dunbar High School** INSPECTION DATE: **3/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **2 D**
MATERIAL DESCRIPTION: **9" x 9" White Floor Tile w/Bright Green Streaks**
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **Moderate**

MATERIAL LOCATION: **1st, 2nd, and 3rd Floor Corridors**

MATERIAL QUANTITY: **400**


MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS: **Material was not observed - 2013 3 years re-inspection**

Inspector's Signature: _____



Date: 03/14/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Dunbar High School** REVIEW DATE: **4/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

HOMOGENEOUS AREA: **2 D**
MATERIAL DESCRIPTION: **9" x 9" White Floor Tile w/Bright Green Streaks**
MATERIAL LOCATION: **1st, 2nd, and 3rd Floor Corridors**
MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Material was not observed - 2013 3 years re-inspection

Management Planner's Signature: _____



Date: **04/14/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kathy Yurks**
SCHOOL NAME: **Dunbar High School** INSPECTION DATE: **3/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **2 E**
MATERIAL DESCRIPTION: **9" x 9" Brown w/Brown Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Rooms 100 & 140 and the 1st Floor Corridor**
MATERIAL QUANTITY: **50** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 03/14/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Dunbar High School** REVIEW DATE: **4/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

HOMOGENEOUS AREA: **2 E**
MATERIAL DESCRIPTION: **9" x 9" Brown w/Brown Floor Tile**
MATERIAL LOCATION: **Rooms 100 & 140 and the 1st Floor Corridor**
MATERIAL QUANTITY: **50** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **04/14/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kathy Yurks**
SCHOOL NAME: **Dunbar High School** INSPECTION DATE: **3/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **2 F**
MATERIAL DESCRIPTION: **9"x9" Gray w/Lt. Gray & Black Streaks Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **5 ACBM with potential for significant damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Repair
Operations and Maintenance**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **5. ACBM with potential for significant damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **13 A & B, Dressing Rooms, and Various Classrooms Throughout Building**
MATERIAL QUANTITY: **10692** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____



Date: 03/14/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUILDING ID: **1030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Dunbar High School** REVIEW DATE: **4/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

HOMOGENEOUS AREA: **2 F**
MATERIAL DESCRIPTION: **9"x9" Gray w/Lt. Gray & Black Streaks Floor Tile**
MATERIAL LOCATION: **13 A & B, Dressing Rooms, and Various Classrooms Throughout Building**
MATERIAL QUANTITY: **10692** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **50** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Repair
Operations and Maintenance**

Comments:

Management Planner's Signature: _____



Date: **04/14/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kathy Yurks**
SCHOOL NAME: **Dunbar High School** INSPECTION DATE: **3/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **2 G**
MATERIAL DESCRIPTION: **9" x 9" Lt. Gray Floor Tile w/Gray & Black Streaks**
HISTORICAL AHERA DAMAGE CATEGORY **5 ACBM with potential for significant damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance Repair**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT


This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **5. ACBM with potential for significant damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **13 A & B, Dressing Rooms, and Various Classrooms Throughout Building**
MATERIAL QUANTITY: **10692** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____



Date: 03/14/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUILDING ID: **1030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Dunbar High School** REVIEW DATE: **4/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

HOMOGENEOUS AREA: **2 G**
MATERIAL DESCRIPTION: **9" x 9" Lt. Gray Floor Tile w/Gray & Black Streaks**
MATERIAL LOCATION: **13 A & B, Dressing Rooms, and Various Classrooms Throughout Building**
MATERIAL QUANTITY: **10692** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **50** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Operations and Maintenance
Repair**

Comments:

Management Planner's Signature: _____



Date: **04/14/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kathy Yurks**
SCHOOL NAME: **Dunbar High School** INSPECTION DATE: **3/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **2 H**
MATERIAL DESCRIPTION: **9" x 9" Light Brn Floor Tile w/White & Blk Streaks**
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Abated** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **Moderate**

MATERIAL LOCATION: **Rooms 311 and 212**

MATERIAL QUANTITY: **200**


MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS: **Material was not observed - 2013 3 years re-inspection**

Inspector's Signature: _____



Date: 03/14/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Dunbar High School** REVIEW DATE: **4/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

HOMOGENEOUS AREA: **2 H**
MATERIAL DESCRIPTION: **9" x 9" Light Brn Floor Tile w/White & Blk Streaks**
MATERIAL LOCATION: **Rooms 311 and 212**
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **04/14/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kathy Yurks**
SCHOOL NAME: **Dunbar High School** INSPECTION DATE: **3/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **21**
MATERIAL DESCRIPTION: **9" x 9" White Floor Tile w/Lt Brn & Blk Streaks**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**

MATERIAL LOCATION: **Rooms 212 and 311**

MATERIAL QUANTITY: **200**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 03/14/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Dunbar High School** REVIEW DATE: **4/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

HOMOGENEOUS AREA: **2 I**
MATERIAL DESCRIPTION: **9" x 9" White Floor Tile w/Lt Brn & Blk Streaks**
MATERIAL LOCATION: **Rooms 212 and 311**
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **04/14/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kathy Yurks**
SCHOOL NAME: **Dunbar High School** INSPECTION DATE: **3/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **2 J**
MATERIAL DESCRIPTION: **9" x 9" Brown Floor Tile w/ White Streaks**
HISTORICAL AHERA DAMAGE CATEGORY **7**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7**. **Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Auditorium**
MATERIAL QUANTITY: **3800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____



Date: 03/14/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Dunbar High School** REVIEW DATE: **4/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

HOMOGENEOUS AREA: **2 J**
MATERIAL DESCRIPTION: **9" x 9" Brown Floor Tile w/ White Streaks**
MATERIAL LOCATION: **Auditorium**
MATERIAL QUANTITY: **3800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: 04/14/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kathy Yurks**
SCHOOL NAME: **Dunbar High School** INSPECTION DATE: **3/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **20**
MATERIAL DESCRIPTION: **Tank Insulation Jacket (Farthest From Door)**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Boiler House**

MATERIAL QUANTITY:


MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **03/14/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Dunbar High School** REVIEW DATE: **4/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

HOMOGENEOUS AREA: **20**

MATERIAL DESCRIPTION: **Tank Insulation Jacket (Farthest From Door)**

MATERIAL LOCATION: **Boiler House**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **04/14/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kathy Yurks**
SCHOOL NAME: **Dunbar High School** INSPECTION DATE: **3/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **21**
MATERIAL DESCRIPTION: **Tank Insulation Jacket (Lower Level)**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Boiler House**

MATERIAL QUANTITY:


MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **03/14/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Dunbar High School** REVIEW DATE: **4/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

HOMOGENEOUS AREA: **21**

MATERIAL DESCRIPTION: **Tank Insulation Jacket (Lower Level)**

MATERIAL LOCATION: **Boiler House**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **04/14/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kathy Yurks**
SCHOOL NAME: **Dunbar High School** INSPECTION DATE: **3/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **22**
MATERIAL DESCRIPTION: **Linear Pipe Insulation**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Boiler House**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **03/14/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Dunbar High School** REVIEW DATE: **4/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

HOMOGENEOUS AREA: **22**

MATERIAL DESCRIPTION: **Linear Pipe Insulation**

MATERIAL LOCATION: **Boiler House**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **04/14/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kathy Yurks**
SCHOOL NAME: **Dunbar High School** INSPECTION DATE: **3/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **23**
MATERIAL DESCRIPTION: **Steam Line Joints**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Boiler House**

MATERIAL QUANTITY:


MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **03/14/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Dunbar High School** REVIEW DATE: **4/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

HOMOGENEOUS AREA: **23**

MATERIAL DESCRIPTION: **Steam Line Joints**

MATERIAL LOCATION: **Boiler House**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **04/14/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kathy Yurks**
SCHOOL NAME: **Dunbar High School** INSPECTION DATE: **3/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **24**
MATERIAL DESCRIPTION: **Cinder Block**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Boiler House**

MATERIAL QUANTITY:


MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **03/14/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Dunbar High School** REVIEW DATE: **4/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

HOMOGENEOUS AREA: **24**

MATERIAL DESCRIPTION: **Cinder Block**

MATERIAL LOCATION: **Boiler House**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **04/14/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kathy Yurks**
SCHOOL NAME: **Dunbar High School** INSPECTION DATE: **3/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **25**
MATERIAL DESCRIPTION: **Cinder Block Mortar**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Boiler House**

MATERIAL QUANTITY:


MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **03/14/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Dunbar High School** REVIEW DATE: **4/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

HOMOGENEOUS AREA: **25**

MATERIAL DESCRIPTION: **Cinder Block Mortar**

MATERIAL LOCATION: **Boiler House**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **04/14/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kathy Yurks**
SCHOOL NAME: **Dunbar High School** INSPECTION DATE: **3/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **251**
MATERIAL DESCRIPTION: **Gray Carpet Adhesive**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1st Floor Corridor, CPS ID**

MATERIAL QUANTITY: **0** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS: **Material was not observed - 2013 3 years re-inspection**

Inspector's Signature:



Date: **03/14/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Dunbar High School** REVIEW DATE: **4/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

HOMOGENEOUS AREA: **251**
MATERIAL DESCRIPTION: **Gray Carpet Adhesive**
MATERIAL LOCATION: **1st Floor Corridor, CPS ID**
MATERIAL QUANTITY: **0** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Material was not observed - 2013 3 years re-inspection

Management Planner's Signature: _____



Date: **04/14/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kathy Yurks**
SCHOOL NAME: **Dunbar High School** INSPECTION DATE: **3/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **26**
MATERIAL DESCRIPTION: **Finished Brick (Glazed)**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Boiler House Washroom**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **03/14/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Dunbar High School** REVIEW DATE: **4/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

HOMOGENEOUS AREA: **26**

MATERIAL DESCRIPTION: **Finished Brick (Glazed)**

MATERIAL LOCATION: **Boiler House Washroom**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **04/14/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kathy Yurks**
SCHOOL NAME: **Dunbar High School** INSPECTION DATE: **3/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **27**
MATERIAL DESCRIPTION: **Finished (Glazed) Brick Mortar**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Boiler House Washroom**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **03/14/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Dunbar High School** REVIEW DATE: **4/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

HOMOGENEOUS AREA: **27**

MATERIAL DESCRIPTION: **Finished (Glazed) Brick Mortar**

MATERIAL LOCATION: **Boiler House Washroom**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **04/14/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kathy Yurks**
SCHOOL NAME: **Dunbar High School** INSPECTION DATE: **3/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **28**
MATERIAL DESCRIPTION: **Terrazzo Stall Panels**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:


MATERIAL LOCATION: **Boiler House Washroom**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **03/14/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Dunbar High School** REVIEW DATE: **4/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

HOMOGENEOUS AREA: **28**

MATERIAL DESCRIPTION: **Terrazzo Stall Panels**

MATERIAL LOCATION: **Boiler House Washroom**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **04/14/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kathy Yurks**
SCHOOL NAME: **Dunbar High School** INSPECTION DATE: **3/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **29**
MATERIAL DESCRIPTION: **Aircell Pipe Insulation**
HISTORICAL AHERA DAMAGE CATEGORY **7 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Boiler House Washroom Behind Wall- In Chase**
MATERIAL QUANTITY: **10** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: _____



Date: 03/14/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Dunbar High School** REVIEW DATE: **4/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

HOMOGENEOUS AREA: **29**
MATERIAL DESCRIPTION: **Aircell Pipe Insulation**
MATERIAL LOCATION: **Boiler House Washroom Behind Wall- In Chase**
MATERIAL QUANTITY: **10** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **04/14/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kathy Yurks**
SCHOOL NAME: **Dunbar High School** INSPECTION DATE: **3/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **3 AA**
MATERIAL DESCRIPTION: **12" x 12" Gray Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Band Room, Chorus Room, Hall, Foyer & Practice Room**
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 03/14/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Dunbar High School** REVIEW DATE: **4/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

HOMOGENEOUS AREA: **3 AA**
MATERIAL DESCRIPTION: **12" x 12" Gray Floor Tile**
MATERIAL LOCATION: **Band Room, Chorus Room, Hall, Foyer & Practice Room**
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **04/14/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kathy Yurks**
SCHOOL NAME: **Dunbar High School** INSPECTION DATE: **3/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **3 AB**
MATERIAL DESCRIPTION: **12" x 12" Multi-Blue Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Room 208**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 03/14/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Dunbar High School** REVIEW DATE: **4/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

HOMOGENEOUS AREA: **3 AB**

MATERIAL DESCRIPTION: **12" x 12" Multi-Blue Floor Tile**

MATERIAL LOCATION: **Room 208**

MATERIAL QUANTITY: **1000**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **04/14/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kathy Yurks**
SCHOOL NAME: **Dunbar High School** INSPECTION DATE: **3/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **3 AC**
MATERIAL DESCRIPTION: **12" x 12" Beige Floor Tile - Removed**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 128**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Material was not observed - 2013 3 years re-inspection**

Inspector's Signature:



Date: **03/14/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Dunbar High School** REVIEW DATE: **4/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

HOMOGENEOUS AREA: **3 AC**

MATERIAL DESCRIPTION: **12" x 12" Beige Floor Tile - Removed**

MATERIAL LOCATION: **Room 128**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Material was not observed - 2013 3 years re-inspectio

Management Planner's Signature: _____



Date: **04/14/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kathy Yurks**
SCHOOL NAME: **Dunbar High School** INSPECTION DATE: **3/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **3 AD**
MATERIAL DESCRIPTION: **12" x 12" Gray Floor Tile - Removed**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 128**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Material was not observed - 2013 3 years re-inspection**

Inspector's Signature:



Date: **03/14/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Dunbar High School** REVIEW DATE: **4/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

HOMOGENEOUS AREA: **3 AD**

MATERIAL DESCRIPTION: **12" x 12" Gray Floor Tile - Removed**

MATERIAL LOCATION: **Room 128**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Material was not observed - 2013 3 years re-inspection

Management Planner's Signature: _____



Date: **04/14/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kathy Yurks**
SCHOOL NAME: **Dunbar High School** INSPECTION DATE: **3/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **3 AE**
MATERIAL DESCRIPTION: **12" x 12" White Floor Tile w/ Blue Streaks**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Room 208, 100, 128**
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS: **Not observed in room 208**

Inspector's Signature: _____



Date: 03/14/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Dunbar High School** REVIEW DATE: **4/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

HOMOGENEOUS AREA: **3 AE**
MATERIAL DESCRIPTION: **12" x 12" White Floor Tile w/ Blue Streaks**
MATERIAL LOCATION: **Room 208, 100, 128**
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Not observed in room 208

Management Planner's Signature: _____



Date: **04/14/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kathy Yurks**
SCHOOL NAME: **Dunbar High School** INSPECTION DATE: **3/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **3 AF**
MATERIAL DESCRIPTION: **12" x 12" Gray Floor Tile w/ Black Streaks**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Room 208, 100, 128**
MATERIAL QUANTITY: **20** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS: **Not observed in room 208**

Inspector's Signature: _____



Date: 03/14/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Dunbar High School** REVIEW DATE: **4/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

HOMOGENEOUS AREA: **3 AF**
MATERIAL DESCRIPTION: **12" x 12" Gray Floor Tile w/ Black Streaks**
MATERIAL LOCATION: **Room 208, 100, 128**
MATERIAL QUANTITY: **20** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Not observed in room 208

Management Planner's Signature: _____



Date: **04/14/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kathy Yurks**
SCHOOL NAME: **Dunbar High School** INSPECTION DATE: **3/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **3 B**
MATERIAL DESCRIPTION: **12"x12" Gray Floor Tile w/ White & Black Streaks**
HISTORICAL AHERA DAMAGE CATEGORY **6**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Men's Lounge**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____



Date: **03/14/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Dunbar High School** REVIEW DATE: **4/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

HOMOGENEOUS AREA: **3 B**

MATERIAL DESCRIPTION: **12"x12" Gray Floor Tile w/ White & Black Streaks**

MATERIAL LOCATION: **Men's Lounge**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY: **0**

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **04/14/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kathy Yurks**
SCHOOL NAME: **Dunbar High School** INSPECTION DATE: **3/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **3 C**
MATERIAL DESCRIPTION: **12"x12" Dark Gray Floor Tile w/ Black Streaks**
HISTORICAL AHERA DAMAGE CATEGORY **6**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**

MATERIAL LOCATION: **Rooms 100, 140, 305, 308, and 313**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____



Date: 03/14/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Dunbar High School** REVIEW DATE: **4/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

HOMOGENEOUS AREA: **3 C**
MATERIAL DESCRIPTION: **12"x12" Dark Gray Floor Tile w/ Black Streaks**
MATERIAL LOCATION: **Rooms 100, 140, 305, 308, and 313**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: **0** DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **04/14/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kathy Yurks**
SCHOOL NAME: **Dunbar High School** INSPECTION DATE: **3/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **3 D**
MATERIAL DESCRIPTION: **12"x12" Brown Floor Tile w/ Dk Brn & Wh Streaks (Removed)**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:


MATERIAL LOCATION: **Boys Gym, Lunch Room, Classrooms and Corridors**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Material was not observed - 2013 3 years re-inspection**

Inspector's Signature:



Date: **03/14/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Dunbar High School** REVIEW DATE: **4/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

HOMOGENEOUS AREA: **3 D**
MATERIAL DESCRIPTION: **12"x12" Brown Floor Tile w/ Dk Brn & Wh Streaks (Removed)**
MATERIAL LOCATION: **Boys Gym, Lunch Room, Classrooms and Corridors**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Material was not observed - 2013 3 years re-inspection

Management Planner's Signature: _____



Date: **04/14/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kathy Yurks**
SCHOOL NAME: **Dunbar High School** INSPECTION DATE: **3/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **3 E**
MATERIAL DESCRIPTION: **12"x12" White Floor Tile w/ Brown Streaks**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Boys Gym, Lunch Room, Classrooms and Corridors**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Material was not observed - 2013 3 years re-inspection**

Inspector's Signature:



Date: **03/14/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Dunbar High School** REVIEW DATE: **4/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

HOMOGENEOUS AREA: **3 E**

MATERIAL DESCRIPTION: **12"x12" White Floor Tile w/ Brown Streaks**

MATERIAL LOCATION: **Boys Gym, Lunch Room, Classrooms and Corridors**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Material was not observed - 2013 3 years re-inspection

Management Planner's Signature: _____



Date: **04/14/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kathy Yurks**
SCHOOL NAME: **Dunbar High School** INSPECTION DATE: **3/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **3 F**
MATERIAL DESCRIPTION: **12"x12" Light Brown Floor Tile w/ White Streaks**
HISTORICAL AHERA DAMAGE CATEGORY **6**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**

MATERIAL LOCATION: **1st Floor Corridor by Ramps and as a Patch in 2nd Floor Corridor, 114, 207**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Not observed in 1st floor corridor**

Inspector's Signature: _____



Date: 03/14/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Dunbar High School** REVIEW DATE: **4/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

HOMOGENEOUS AREA: **3 F**
MATERIAL DESCRIPTION: **12"x12" Light Brown Floor Tile w/ White Streaks**
MATERIAL LOCATION: **1st Floor Corridor by Ramps and as a Patch in 2nd Floor Corridor, 114, 207**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: **0** DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **04/14/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kathy Yurks**
SCHOOL NAME: **Dunbar High School** INSPECTION DATE: **3/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **3 G**
MATERIAL DESCRIPTION: **12"x12" Gray Floor Tile w/ Dk Gray & White Streaks**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Rooms 100, 119, 121, 140, 305, 306, 308, and 313**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Material was not observed - 2013 3 years re-inspection**

Inspector's Signature:



Date: **03/14/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Dunbar High School** REVIEW DATE: **4/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

HOMOGENEOUS AREA: **3 G**

MATERIAL DESCRIPTION: **12"x12" Gray Floor Tile w/ Dk Gray & White Streaks**

MATERIAL LOCATION: **Rooms 100, 119, 121, 140, 305, 306, 308, and 313**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **04/14/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kathy Yurks**
SCHOOL NAME: **Dunbar High School** INSPECTION DATE: **3/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **3 H**
MATERIAL DESCRIPTION: **12"x12" Beige Floor Tile w/ White Streaks**
HISTORICAL AHERA DAMAGE CATEGORY **6**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**


MATERIAL LOCATION: **1st Floor Corridor by Ramps and as a Patch in 2nd Floor Corridor, 114, 207, 307**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Not observed in 1st corridor**

Inspector's Signature: _____



Date: **03/14/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Dunbar High School** REVIEW DATE: **4/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

HOMOGENEOUS AREA: **3 H**
MATERIAL DESCRIPTION: **12"x12" Beige Floor Tile w/ White Streaks**
MATERIAL LOCATION: **1st Floor Corridor by Ramps and as a Patch in 2nd Floor Corridor, 114, 207, 307**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: **0** DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **04/14/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kathy Yurks**
SCHOOL NAME: **Dunbar High School** INSPECTION DATE: **3/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **31**
MATERIAL DESCRIPTION: **12"x12" Brown Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**

MATERIAL LOCATION: **Room 138**

MATERIAL QUANTITY:


MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____



Date: 03/14/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Dunbar High School** REVIEW DATE: **4/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

HOMOGENEOUS AREA: **3 I**

MATERIAL DESCRIPTION: **12"x12" Brown Floor Tile**

MATERIAL LOCATION: **Room 138**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY: **0**

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **04/14/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kathy Yurks**
SCHOOL NAME: **Dunbar High School** INSPECTION DATE: **3/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **3 J**
MATERIAL DESCRIPTION: **12"x12" Beige Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Room 138**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____



Date: 03/14/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Dunbar High School** REVIEW DATE: **4/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

HOMOGENEOUS AREA: **3 J**

MATERIAL DESCRIPTION: **12"x12" Beige Floor Tile**

MATERIAL LOCATION: **Room 138**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY: **0**

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **04/14/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kathy Yurks**
SCHOOL NAME: **Dunbar High School** INSPECTION DATE: **3/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **3 K**
MATERIAL DESCRIPTION: **12"x12" Green Floor Tiles**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **As Patches in the 1st and 3rd Floor Corridors**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Material was not observed - 2013 3 years re-inspection**

Inspector's Signature:



Date: **03/14/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Dunbar High School** REVIEW DATE: **4/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

HOMOGENEOUS AREA: **3 K**
MATERIAL DESCRIPTION: **12"x12" Green Floor Tiles**
MATERIAL LOCATION: **As Patches in the 1st and 3rd Floor Corridors**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **04/14/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kathy Yurks**
SCHOOL NAME: **Dunbar High School** INSPECTION DATE: **3/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **3 L**
MATERIAL DESCRIPTION: **12"x12" Light Green Floor Tiles**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **As Patches in the 1st and 3rd Floor Corridors**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Material was not observed - 2013 3 years re-inspection**

Inspector's Signature:



Date: **03/14/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Dunbar High School** REVIEW DATE: **4/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

HOMOGENEOUS AREA: **3 L**

MATERIAL DESCRIPTION: **12"x12" Light Green Floor Tiles**

MATERIAL LOCATION: **As Patches in the 1st and 3rd Floor Corridors**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **04/14/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kathy Yurks**
SCHOOL NAME: **Dunbar High School** INSPECTION DATE: **3/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **3 M**
MATERIAL DESCRIPTION: **12" x 12" Gray Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1st Floor Corridor Ramps**

MATERIAL QUANTITY:


MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **03/14/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Dunbar High School** REVIEW DATE: **4/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

HOMOGENEOUS AREA: **3 M**
MATERIAL DESCRIPTION: **12" x 12" Gray Floor Tile**
MATERIAL LOCATION: **1st Floor Corridor Ramps**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **04/14/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kathy Yurks**
SCHOOL NAME: **Dunbar High School** INSPECTION DATE: **3/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **3 N**
MATERIAL DESCRIPTION: **12" x 12" Gray Floor Tile w/White Streaks**
HISTORICAL AHERA DAMAGE CATEGORY **6**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**

MATERIAL LOCATION: **Room 104**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____



Date: 03/14/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Dunbar High School** REVIEW DATE: **4/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

HOMOGENEOUS AREA: **3 N**
MATERIAL DESCRIPTION: **12" x 12" Gray Floor Tile w/White Streaks**
MATERIAL LOCATION: **Room 104**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: **0** DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **04/14/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kathy Yurks**
SCHOOL NAME: **Dunbar High School** INSPECTION DATE: **3/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **3 0**
MATERIAL DESCRIPTION: **12" x 12" White Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Room 132,106**
MATERIAL QUANTITY: **900** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 03/14/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Dunbar High School** REVIEW DATE: **4/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

HOMOGENEOUS AREA: **3 O**
MATERIAL DESCRIPTION: **12" x 12" White Floor Tile**
MATERIAL LOCATION: **Room 132,106**
MATERIAL QUANTITY: **900** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **04/14/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kathy Yurks**
SCHOOL NAME: **Dunbar High School** INSPECTION DATE: **3/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **3 P**
MATERIAL DESCRIPTION: **12" x 12" Blue Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**

MATERIAL LOCATION: **Room 132**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____



Date: 03/14/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Dunbar High School** REVIEW DATE: **4/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

HOMOGENEOUS AREA: **3 P**
MATERIAL DESCRIPTION: **12" x 12" Blue Floor Tile**
MATERIAL LOCATION: **Room 132**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: **0** DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **04/14/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kathy Yurks**
SCHOOL NAME: **Dunbar High School** INSPECTION DATE: **3/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **3 Q**
MATERIAL DESCRIPTION: **12" x 12" Black Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Room 105**
MATERIAL QUANTITY: **1100** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 03/14/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Dunbar High School** REVIEW DATE: **4/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

HOMOGENEOUS AREA: **3 Q**
MATERIAL DESCRIPTION: **12" x 12" Black Floor Tile**
MATERIAL LOCATION: **Room 105**
MATERIAL QUANTITY: **1100** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **04/14/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kathy Yurks**
SCHOOL NAME: **Dunbar High School** INSPECTION DATE: **3/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **3 R**
MATERIAL DESCRIPTION: **12" x 12" White Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT


This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Room 105**
MATERIAL QUANTITY: **1100** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS: **Material may exist under new material (not observed)**

Inspector's Signature: _____



Date: 03/14/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Dunbar High School** REVIEW DATE: **4/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

HOMOGENEOUS AREA: **3 R**
MATERIAL DESCRIPTION: **12" x 12" White Floor Tile**
MATERIAL LOCATION: **Room 105**
MATERIAL QUANTITY: **1100** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Material may exist under new material (not observed)

Management Planner's Signature: _____



Date: **04/14/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kathy Yurks**
SCHOOL NAME: **Dunbar High School** INSPECTION DATE: **3/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **3 S**
MATERIAL DESCRIPTION: **12" x 12" Light Blue Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Room 104, 134, Social Room, 300B**
MATERIAL QUANTITY: **175** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 03/14/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Dunbar High School** REVIEW DATE: **4/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

HOMOGENEOUS AREA: **3 S**
MATERIAL DESCRIPTION: **12" x 12" Light Blue Floor Tile**
MATERIAL LOCATION: **Room 104, 134, Social Room, 300B**
MATERIAL QUANTITY: **175** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **04/14/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kathy Yurks**
SCHOOL NAME: **Dunbar High School** INSPECTION DATE: **3/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **3 T**
MATERIAL DESCRIPTION: **12" x 12" Light Brown Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms 114, 116, 117, 119, 130, and 206**
MATERIAL QUANTITY: **2400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 03/14/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Dunbar High School** REVIEW DATE: **4/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

HOMOGENEOUS AREA: **3 T**
MATERIAL DESCRIPTION: **12" x 12" Light Brown Floor Tile**
MATERIAL LOCATION: **Rooms 114, 116, 117, 119, 130, and 206**
MATERIAL QUANTITY: **2400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **04/14/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kathy Yurks**
SCHOOL NAME: **Dunbar High School** INSPECTION DATE: **3/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **3 U**
MATERIAL DESCRIPTION: **12" x 12" Beige Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Anthophyllite** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms 114, 116, 117, 119, 130, and 206**
MATERIAL QUANTITY: **2400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 03/14/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Dunbar High School** REVIEW DATE: **4/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

HOMOGENEOUS AREA: **3 U**
MATERIAL DESCRIPTION: **12" x 12" Beige Floor Tile**
MATERIAL LOCATION: **Rooms 114, 116, 117, 119, 130, and 206**
MATERIAL QUANTITY: **2400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **04/14/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kathy Yurks**
SCHOOL NAME: **Dunbar High School** INSPECTION DATE: **3/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **3 V**
MATERIAL DESCRIPTION: **12" x 12" Dark Brown w/Dk Brn & Lt Brn Streak FT (Removed)**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **On Cabinets in Various Classrooms**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Material was not observed - 2013 3 years re-inspection**

Inspector's Signature:



Date: **03/14/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Dunbar High School** REVIEW DATE: **4/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

HOMOGENEOUS AREA: **3 V**

MATERIAL DESCRIPTION: **12" x 12" Dark Brown w/Dk Brn & Lt Brn Streak FT (Removed)**

MATERIAL LOCATION: **On Cabinets in Various Classrooms**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Material was not observed - 2013 3 years re-inspection

Management Planner's Signature: _____



Date: **04/14/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kathy Yurks**
SCHOOL NAME: **Dunbar High School** INSPECTION DATE: **3/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **3 W**
MATERIAL DESCRIPTION: **12" x 12" Gray Floor Tile w/ Light Gray Streaks (Removed)**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **On Cabinets in Various Classrooms**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Material was not observed - 2013 3 years re-inspection**

Inspector's Signature:



Date: **03/14/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Dunbar High School** REVIEW DATE: **4/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

HOMOGENEOUS AREA: **3 W**
MATERIAL DESCRIPTION: **12" x 12" Gray Floor Tile w/ Light Gray Streaks (Removed)**
MATERIAL LOCATION: **On Cabinets in Various Classrooms**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Material was not observed - 2013 3 years re-inspection

Management Planner's Signature: _____



Date: **04/14/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kathy Yurks**
SCHOOL NAME: **Dunbar High School** INSPECTION DATE: **3/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **3 X**
MATERIAL DESCRIPTION: **12" x 12" Multi-Brown Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Rooms 201 and 203**

MATERIAL QUANTITY: **600**


MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS: **Material was not observed - 2013 3 years re-inspection**

Inspector's Signature:



Date: **03/14/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Dunbar High School** REVIEW DATE: **4/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

HOMOGENEOUS AREA: **3 X**
MATERIAL DESCRIPTION: **12" x 12" Multi-Brown Floor Tile**
MATERIAL LOCATION: **Rooms 201 and 203**
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Material was not observed - 2013 3 years re-inspection

Management Planner's Signature: _____



Date: **04/14/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kathy Yurks**
SCHOOL NAME: **Dunbar High School** INSPECTION DATE: **3/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **3 Y**
MATERIAL DESCRIPTION: **12" x 12" Beige Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Rooms 201**

MATERIAL QUANTITY: **300**


MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS: **Material was not observed - 2013 3 years re-inspection**

Inspector's Signature:



Date: **03/14/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Dunbar High School** REVIEW DATE: **4/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

HOMOGENEOUS AREA: **3 Y**
MATERIAL DESCRIPTION: **12" x 12" Beige Floor Tile**
MATERIAL LOCATION: **Rooms 201**
MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Material was not observed - 2013 3 years re-inspection

Management Planner's Signature: _____



Date: **04/14/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kathy Yurks**
SCHOOL NAME: **Dunbar High School** INSPECTION DATE: **3/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **3 Z**
MATERIAL DESCRIPTION: **12" x 12" Light Green Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**


MATERIAL LOCATION: **Band Room, Chorus Room, Hall and Foyer**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____



Date: 03/14/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Dunbar High School** REVIEW DATE: **4/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

HOMOGENEOUS AREA: **3 Z**
MATERIAL DESCRIPTION: **12" x 12" Light Green Floor Tile**
MATERIAL LOCATION: **Band Room, Chorus Room, Hall and Foyer**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: **0** DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: 04/14/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kathy Yurks**
SCHOOL NAME: **Dunbar High School** INSPECTION DATE: **3/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **30**
MATERIAL DESCRIPTION: **Tank Insulation**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Basement**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **03/14/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Dunbar High School** REVIEW DATE: **4/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

HOMOGENEOUS AREA: **30**

MATERIAL DESCRIPTION: **Tank Insulation**

MATERIAL LOCATION: **Basement**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **04/14/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kathy Yurks**
SCHOOL NAME: **Dunbar High School** INSPECTION DATE: **3/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **31**
MATERIAL DESCRIPTION: **Cinder Block Mortar**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout Building**

MATERIAL QUANTITY:


MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **03/14/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Dunbar High School** REVIEW DATE: **4/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

HOMOGENEOUS AREA: **31**

MATERIAL DESCRIPTION: **Cinder Block Mortar**

MATERIAL LOCATION: **Throughout Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **04/14/2013** _____

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUILDING ID: **1030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kathy Yurks**
SCHOOL NAME: **Dunbar High School** INSPECTION DATE: **3/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **32**
MATERIAL DESCRIPTION: **Interior Brick**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout Building**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **03/14/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Dunbar High School** REVIEW DATE: **4/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

HOMOGENEOUS AREA: **32**

MATERIAL DESCRIPTION: **Interior Brick**

MATERIAL LOCATION: **Throughout Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **04/14/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kathy Yurks**
SCHOOL NAME: **Dunbar High School** INSPECTION DATE: **3/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **33**
MATERIAL DESCRIPTION: **Interior Brick Mortar**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout Building**

MATERIAL QUANTITY:


MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **03/14/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Dunbar High School** REVIEW DATE: **4/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

HOMOGENEOUS AREA: **33**

MATERIAL DESCRIPTION: **Interior Brick Mortar**

MATERIAL LOCATION: **Throughout Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **04/14/2013** _____

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kathy Yurks**
SCHOOL NAME: **Dunbar High School** INSPECTION DATE: **3/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **34**
MATERIAL DESCRIPTION: **Ceiling Material**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Basement Boiler Room**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **03/14/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Dunbar High School** REVIEW DATE: **4/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

HOMOGENEOUS AREA: **34**

MATERIAL DESCRIPTION: **Ceiling Material**

MATERIAL LOCATION: **Basement Boiler Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **04/14/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kathy Yurks**
SCHOOL NAME: **Dunbar High School** INSPECTION DATE: **3/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **35**
MATERIAL DESCRIPTION: **Terrazzo Stairs and Landings/foyers**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout Stairways**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **03/14/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Dunbar High School** REVIEW DATE: **4/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

HOMOGENEOUS AREA: **35**

MATERIAL DESCRIPTION: **Terrazzo Stairs and Landings/foyers**

MATERIAL LOCATION: **Throughout Stairways**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **04/14/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kathy Yurks**
SCHOOL NAME: **Dunbar High School** INSPECTION DATE: **3/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **36**
MATERIAL DESCRIPTION: **Clay Tile**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Entrances and Exits**

MATERIAL QUANTITY:


MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **03/14/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Dunbar High School** REVIEW DATE: **4/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

HOMOGENEOUS AREA: **36**

MATERIAL DESCRIPTION: **Clay Tile**

MATERIAL LOCATION: **Entrances and Exits**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **04/14/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kathy Yurks**
SCHOOL NAME: **Dunbar High School** INSPECTION DATE: **3/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **37**
MATERIAL DESCRIPTION: **Clay Tile Mortar**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Entrances and Exits**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **03/14/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Dunbar High School** REVIEW DATE: **4/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

HOMOGENEOUS AREA: **37**

MATERIAL DESCRIPTION: **Clay Tile Mortar**

MATERIAL LOCATION: **Entrances and Exits**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **04/14/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kathy Yurks**
SCHOOL NAME: **Dunbar High School** INSPECTION DATE: **3/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **38**
MATERIAL DESCRIPTION: **Window Glazing**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:


MATERIAL LOCATION: **Throughout Building**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **03/14/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Dunbar High School** REVIEW DATE: **4/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

HOMOGENEOUS AREA: **38**

MATERIAL DESCRIPTION: **Window Glazing**

MATERIAL LOCATION: **Throughout Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **04/14/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kathy Yurks**
SCHOOL NAME: **Dunbar High School** INSPECTION DATE: **3/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **39**
MATERIAL DESCRIPTION: **Window Caulk (Grout)**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout Building**

MATERIAL QUANTITY:


MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **03/14/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Dunbar High School** REVIEW DATE: **4/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

HOMOGENEOUS AREA: **39**

MATERIAL DESCRIPTION: **Window Caulk (Grout)**

MATERIAL LOCATION: **Throughout Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **04/14/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kathy Yurks**
SCHOOL NAME: **Dunbar High School** INSPECTION DATE: **3/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **3A**
MATERIAL DESCRIPTION: **12" x12" White Floor Tile w/ Blue and Gray Streaks**
HISTORICAL AHERA DAMAGE CATEGORY **6**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT


This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Rms 224, 222, 310, 225, 221A, 217, 211, 207, 306and 312**
MATERIAL QUANTITY: **2700** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____



Date: 03/14/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Dunbar High School** REVIEW DATE: **4/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

HOMOGENEOUS AREA: **3A**
MATERIAL DESCRIPTION: **12" x12" White Floor Tile w/ Blue and Gray Streaks**
MATERIAL LOCATION: **Rms 224, 222, 310, 225, 221A, 217, 211, 207, 306and 312**
MATERIAL QUANTITY: **2700** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **04/14/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kathy Yurks**
SCHOOL NAME: **Dunbar High School** INSPECTION DATE: **3/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **4**
MATERIAL DESCRIPTION: **Outer Wrap Over Fiberglass Insulation on HVAC Unit**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 122- ABATED**

MATERIAL QUANTITY:


MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Material was not observed - 2013 3 years re-inspection**

Inspector's Signature:



Date: **03/14/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Dunbar High School** REVIEW DATE: **4/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

HOMOGENEOUS AREA: **4**

MATERIAL DESCRIPTION: **Outer Wrap Over Fiberglass Insulation on HVAC Unit**

MATERIAL LOCATION: **Room 122- ABATED**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **04/14/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kathy Yurks**
SCHOOL NAME: **Dunbar High School** INSPECTION DATE: **3/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **40**
MATERIAL DESCRIPTION: **Window Sill Mortar**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout Classrooms**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **03/14/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Dunbar High School** REVIEW DATE: **4/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

HOMOGENEOUS AREA: **40**

MATERIAL DESCRIPTION: **Window Sill Mortar**

MATERIAL LOCATION: **Throughout Classrooms**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **04/14/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kathy Yurks**
SCHOOL NAME: **Dunbar High School** INSPECTION DATE: **3/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **41**
MATERIAL DESCRIPTION: **Finished (Glazed) Brick**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout Building**

MATERIAL QUANTITY:


MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **03/14/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Dunbar High School** REVIEW DATE: **4/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

HOMOGENEOUS AREA: **41**

MATERIAL DESCRIPTION: **Finished (Glazed) Brick**

MATERIAL LOCATION: **Throughout Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **04/14/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kathy Yurks**
SCHOOL NAME: **Dunbar High School** INSPECTION DATE: **3/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **42**
MATERIAL DESCRIPTION: **Finished (Glazed) Brick Mortar**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout Building**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **03/14/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Dunbar High School** REVIEW DATE: **4/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

HOMOGENEOUS AREA: **42**

MATERIAL DESCRIPTION: **Finished (Glazed) Brick Mortar**

MATERIAL LOCATION: **Throughout Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **04/14/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kathy Yurks**
SCHOOL NAME: **Dunbar High School** INSPECTION DATE: **3/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **43**
MATERIAL DESCRIPTION: **Terrazzo Stall Panels**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **All Washrooms**

MATERIAL QUANTITY:


MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **03/14/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Dunbar High School** REVIEW DATE: **4/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

HOMOGENEOUS AREA: **43**

MATERIAL DESCRIPTION: **Terrazzo Stall Panels**

MATERIAL LOCATION: **All Washrooms**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **04/14/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kathy Yurks**
SCHOOL NAME: **Dunbar High School** INSPECTION DATE: **3/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **44**
MATERIAL DESCRIPTION: **1' x 1' Ceiling Tile (Acoustical)**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **As Patches in Foyer and Corridors**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **03/14/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Dunbar High School** REVIEW DATE: **4/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

HOMOGENEOUS AREA: **44**

MATERIAL DESCRIPTION: **1' x 1' Ceiling Tile (Acoustical)**

MATERIAL LOCATION: **As Patches in Foyer and Corridors**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **04/14/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kathy Yurks**
SCHOOL NAME: **Dunbar High School** INSPECTION DATE: **3/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **45**
MATERIAL DESCRIPTION: **1' x 1' Ceiling Tiles**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1st, 2nd, and 3rd Floor Corridors**

MATERIAL QUANTITY:


MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **03/14/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Dunbar High School** REVIEW DATE: **4/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

HOMOGENEOUS AREA: **45**

MATERIAL DESCRIPTION: **1' x 1' Ceiling Tiles**

MATERIAL LOCATION: **1st, 2nd, and 3rd Floor Corridors**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **04/14/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kathy Yurks**
SCHOOL NAME: **Dunbar High School** INSPECTION DATE: **3/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **46**
MATERIAL DESCRIPTION: **1' x 1' (Spline) Ceiling Tiles with Holes**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1st, 2nd, and 3rd Floor Corridors**

MATERIAL QUANTITY:


MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **03/14/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Dunbar High School** REVIEW DATE: **4/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

HOMOGENEOUS AREA: **46**

MATERIAL DESCRIPTION: **1' x 1' (Spline) Ceiling Tiles with Holes**

MATERIAL LOCATION: **1st, 2nd, and 3rd Floor Corridors**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **04/14/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kathy Yurks**
SCHOOL NAME: **Dunbar High School** INSPECTION DATE: **3/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **47**
MATERIAL DESCRIPTION: **2' x 4' Lay-In Ceiling Panels**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Amosite** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Rooms 311 and 110**
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 03/14/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Dunbar High School** REVIEW DATE: **4/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

HOMOGENEOUS AREA: **47**
MATERIAL DESCRIPTION: **2' x 4' Lay-In Ceiling Panels**
MATERIAL LOCATION: **Rooms 311 and 110**
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **04/14/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kathy Yurks**
SCHOOL NAME: **Dunbar High School** INSPECTION DATE: **3/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **48**
MATERIAL DESCRIPTION: **1' x 2' Slotted Ceiling Tile**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:


MATERIAL LOCATION: **Shop Wing and Gym**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **03/14/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Dunbar High School** REVIEW DATE: **4/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

HOMOGENEOUS AREA: **48**

MATERIAL DESCRIPTION: **1' x 2' Slotted Ceiling Tile**

MATERIAL LOCATION: **Shop Wing and Gym**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **04/14/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kathy Yurks**
SCHOOL NAME: **Dunbar High School** INSPECTION DATE: **3/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **49**
MATERIAL DESCRIPTION: **2' x 8' Textured Ceiling Panels**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Rms 122, 124, and 126**

MATERIAL QUANTITY:


MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **03/14/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Dunbar High School** REVIEW DATE: **4/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

HOMOGENEOUS AREA: **49**

MATERIAL DESCRIPTION: **2' x 8' Textured Ceiling Panels**

MATERIAL LOCATION: **Rms 122, 124, and 126**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **04/14/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kathy Yurks**
SCHOOL NAME: **Dunbar High School** INSPECTION DATE: **3/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **5**
MATERIAL DESCRIPTION: **Insulation on Suspended HVAC Unit**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 122**

MATERIAL QUANTITY:


MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **03/14/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Dunbar High School** REVIEW DATE: **4/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

HOMOGENEOUS AREA: **5**

MATERIAL DESCRIPTION: **Insulation on Suspended HVAC Unit**

MATERIAL LOCATION: **Room 122**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **04/14/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kathy Yurks**
SCHOOL NAME: **Dunbar High School** INSPECTION DATE: **3/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **50**
MATERIAL DESCRIPTION: **2' x 8' Smooth Ceiling Tile**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:


MATERIAL LOCATION: **Shop Wing**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **03/14/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Dunbar High School** REVIEW DATE: **4/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

HOMOGENEOUS AREA: **50**

MATERIAL DESCRIPTION: **2' x 8' Smooth Ceiling Tile**

MATERIAL LOCATION: **Shop Wing**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **04/14/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kathy Yurks**
SCHOOL NAME: **Dunbar High School** INSPECTION DATE: **3/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **51**
MATERIAL DESCRIPTION: **Insulation Behind Pegboard Walls**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Auditorium**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **03/14/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Dunbar High School** REVIEW DATE: **4/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

HOMOGENEOUS AREA: **51**

MATERIAL DESCRIPTION: **Insulation Behind Pegboard Walls**

MATERIAL LOCATION: **Auditorium**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **04/14/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kathy Yurks**
SCHOOL NAME: **Dunbar High School** INSPECTION DATE: **3/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **52**
MATERIAL DESCRIPTION: **Roof Flashing - Not AHERA**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Shop Roof**

MATERIAL QUANTITY:


MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **03/14/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Dunbar High School** REVIEW DATE: **4/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

HOMOGENEOUS AREA: **52**

MATERIAL DESCRIPTION: **Roof Flashing - Not AHERA**

MATERIAL LOCATION: **Shop Roof**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **04/14/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kathy Yurks**
SCHOOL NAME: **Dunbar High School** INSPECTION DATE: **3/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **53**
MATERIAL DESCRIPTION: **Lab Tops and Sinks**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Rooms 117, 310, 312, 222, and 224**
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 03/14/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Dunbar High School** REVIEW DATE: **4/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

HOMOGENEOUS AREA: **53**
MATERIAL DESCRIPTION: **Lab Tops and Sinks**
MATERIAL LOCATION: **Rooms 117, 310, 312, 222, and 224**
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **04/14/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kathy Yurks**
SCHOOL NAME: **Dunbar High School** INSPECTION DATE: **3/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **54**
MATERIAL DESCRIPTION: **Fiberglass Insulation on Suspended HVAC Unit**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 122**

MATERIAL QUANTITY:


MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **03/14/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Dunbar High School** REVIEW DATE: **4/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

HOMOGENEOUS AREA: **54**

MATERIAL DESCRIPTION: **Fiberglass Insulation on Suspended HVAC Unit**

MATERIAL LOCATION: **Room 122**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **04/14/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kathy Yurks**
SCHOOL NAME: **Dunbar High School** INSPECTION DATE: **3/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **55**
MATERIAL DESCRIPTION: **Vibration Collars**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**


MATERIAL LOCATION: **Dressing Room, Janitor's Closet in Girl's Locker Room, Room 310 & Electrical Room in Room 206**

MATERIAL QUANTITY: **50** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: _____



Date: 03/14/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Dunbar High School** REVIEW DATE: **4/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

HOMOGENEOUS AREA: **55**
MATERIAL DESCRIPTION: **Vibration Collars**
MATERIAL LOCATION: **Dressing Room, Janitor's Closet in Girl's Locker Room, Room 310 & Electrical Room in Room 206**
MATERIAL QUANTITY: **50** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: 04/14/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kathy Yurks**
SCHOOL NAME: **Dunbar High School** INSPECTION DATE: **3/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **56**
MATERIAL DESCRIPTION: **Terrazzo Sinks**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Washrooms**

MATERIAL QUANTITY:


MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **03/14/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Dunbar High School** REVIEW DATE: **4/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

HOMOGENEOUS AREA: **56**

MATERIAL DESCRIPTION: **Terrazzo Sinks**

MATERIAL LOCATION: **Washrooms**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **04/14/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kathy Yurks**
SCHOOL NAME: **Dunbar High School** INSPECTION DATE: **3/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **57**
MATERIAL DESCRIPTION: **Insulation Inside Firedoors**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**

MATERIAL LOCATION: **Exits and Boiler Room**

MATERIAL QUANTITY: **160**


MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 03/14/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Dunbar High School** REVIEW DATE: **4/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

HOMOGENEOUS AREA: **57**

MATERIAL DESCRIPTION: **Insulation Inside Firedoors**

MATERIAL LOCATION: **Exits and Boiler Room**

MATERIAL QUANTITY: **160**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **04/14/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kathy Yurks**
SCHOOL NAME: **Dunbar High School** INSPECTION DATE: **3/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **58**
MATERIAL DESCRIPTION: **Exterior Dark Brick - Not AHERA**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Exterior of Main Building**

MATERIAL QUANTITY:


MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **03/14/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Dunbar High School** REVIEW DATE: **4/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

HOMOGENEOUS AREA: **58**

MATERIAL DESCRIPTION: **Exterior Dark Brick - Not AHERA**

MATERIAL LOCATION: **Exterior of Main Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **04/14/2013** _____

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kathy Yurks**
SCHOOL NAME: **Dunbar High School** INSPECTION DATE: **3/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **59**
MATERIAL DESCRIPTION: **Exterior Dark Brick Mortar - Not AHERA**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Exterior of Main Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **03/14/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Dunbar High School** REVIEW DATE: **4/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

HOMOGENEOUS AREA: **59**

MATERIAL DESCRIPTION: **Exterior Dark Brick Mortar - Not AHERA**

MATERIAL LOCATION: **Exterior of Main Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **04/14/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kathy Yurks**
SCHOOL NAME: **Dunbar High School** INSPECTION DATE: **3/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **6**
MATERIAL DESCRIPTION: **Fiberglass Insulation Backing on HVAC Unit**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 122- ABATED**

MATERIAL QUANTITY:


MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Material was not observed - 2013 3 years re-inspection**

Inspector's Signature:



Date: **03/14/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Dunbar High School** REVIEW DATE: **4/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

HOMOGENEOUS AREA: **6**

MATERIAL DESCRIPTION: **Fiberglass Insulation Backing on HVAC Unit**

MATERIAL LOCATION: **Room 122- ABATED**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **04/14/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kathy Yurks**
SCHOOL NAME: **Dunbar High School** INSPECTION DATE: **3/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **60**
MATERIAL DESCRIPTION: **Exterior Light Face Brick - Not AHERA**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Exterior of Main Building**

MATERIAL QUANTITY:


MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **03/14/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Dunbar High School** REVIEW DATE: **4/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

HOMOGENEOUS AREA: **60**

MATERIAL DESCRIPTION: **Exterior Light Face Brick - Not AHERA**

MATERIAL LOCATION: **Exterior of Main Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **04/14/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kathy Yurks**
SCHOOL NAME: **Dunbar High School** INSPECTION DATE: **3/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **61**
MATERIAL DESCRIPTION: **Exterior Light Face Brick Mortar - Not AHERA**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Exterior of Main Building**

MATERIAL QUANTITY:


MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **03/14/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Dunbar High School** REVIEW DATE: **4/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

HOMOGENEOUS AREA: **61**

MATERIAL DESCRIPTION: **Exterior Light Face Brick Mortar - Not AHERA**

MATERIAL LOCATION: **Exterior of Main Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **04/14/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kathy Yurks**
SCHOOL NAME: **Dunbar High School** INSPECTION DATE: **3/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **62**
MATERIAL DESCRIPTION: **Exterior Door Grout - Not AHERA**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Exterior of Main Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **03/14/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Dunbar High School** REVIEW DATE: **4/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

HOMOGENEOUS AREA: **62**

MATERIAL DESCRIPTION: **Exterior Door Grout - Not AHERA**

MATERIAL LOCATION: **Exterior of Main Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **04/14/2013** _____

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kathy Yurks**
SCHOOL NAME: **Dunbar High School** INSPECTION DATE: **3/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **63**
MATERIAL DESCRIPTION: **Exterior Blue Brick - Not AHERA**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Exterior of Main Building**

MATERIAL QUANTITY:


MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **03/14/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Dunbar High School** REVIEW DATE: **4/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

HOMOGENEOUS AREA: **63**

MATERIAL DESCRIPTION: **Exterior Blue Brick - Not AHERA**

MATERIAL LOCATION: **Exterior of Main Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **04/14/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kathy Yurks**
SCHOOL NAME: **Dunbar High School** INSPECTION DATE: **3/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **64**
MATERIAL DESCRIPTION: **Exterior Blue Brick Mortar - Not AHERA**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Exterior of Main Building**

MATERIAL QUANTITY:


MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **03/14/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Dunbar High School** REVIEW DATE: **4/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

HOMOGENEOUS AREA: **64**

MATERIAL DESCRIPTION: **Exterior Blue Brick Mortar - Not AHERA**

MATERIAL LOCATION: **Exterior of Main Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **04/14/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kathy Yurks**
SCHOOL NAME: **Dunbar High School** INSPECTION DATE: **3/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **65**
MATERIAL DESCRIPTION: **Exterior Window Grout - Not AHERA**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Exterior of Main Building**

MATERIAL QUANTITY:


MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **03/14/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Dunbar High School** REVIEW DATE: **4/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

HOMOGENEOUS AREA: **65**

MATERIAL DESCRIPTION: **Exterior Window Grout - Not AHERA**

MATERIAL LOCATION: **Exterior of Main Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **04/14/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kathy Yurks**
SCHOOL NAME: **Dunbar High School** INSPECTION DATE: **3/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **66**
MATERIAL DESCRIPTION: **Roof - Not AHERA**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Boiler House**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not AHERA**

Inspector's Signature:



Date: **03/14/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Dunbar High School** REVIEW DATE: **4/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

HOMOGENEOUS AREA: **66**

MATERIAL DESCRIPTION: **Roof - Not AHERA**

MATERIAL LOCATION: **Boiler House**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **04/14/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kathy Yurks**
SCHOOL NAME: **Dunbar High School** INSPECTION DATE: **3/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **67**
MATERIAL DESCRIPTION: **Roof Flashing - Not AHERA**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Boiler House**

MATERIAL QUANTITY:


MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not AHERA**

Inspector's Signature:



Date: **03/14/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Dunbar High School** REVIEW DATE: **4/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

HOMOGENEOUS AREA: **67**

MATERIAL DESCRIPTION: **Roof Flashing - Not AHERA**

MATERIAL LOCATION: **Boiler House**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **04/14/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kathy Yurks**
SCHOOL NAME: **Dunbar High School** INSPECTION DATE: **3/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **68**
MATERIAL DESCRIPTION: **Roof - Not AHERA**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Main Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not AHERA**

Inspector's Signature:



Date: **03/14/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Dunbar High School** REVIEW DATE: **4/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

HOMOGENEOUS AREA: **68**

MATERIAL DESCRIPTION: **Roof - Not AHERA**

MATERIAL LOCATION: **Main Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **04/14/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kathy Yurks**
SCHOOL NAME: **Dunbar High School** INSPECTION DATE: **3/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **69**
MATERIAL DESCRIPTION: **Roof Flashing - Not AHERA**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Main Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not AHERA**

Inspector's Signature:



Date: **03/14/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Dunbar High School** REVIEW DATE: **4/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

HOMOGENEOUS AREA: **69**

MATERIAL DESCRIPTION: **Roof Flashing - Not AHERA**

MATERIAL LOCATION: **Main Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **04/14/2013** _____

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kathy Yurks**
SCHOOL NAME: **Dunbar High School** INSPECTION DATE: **3/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **7**
MATERIAL DESCRIPTION: **Plaster**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:


MATERIAL LOCATION: **Throughout Building**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____



Date: 03/14/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Dunbar High School** REVIEW DATE: **4/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

HOMOGENEOUS AREA: **7**

MATERIAL DESCRIPTION: **Plaster**

MATERIAL LOCATION: **Throughout Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **04/14/2013** _____

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kathy Yurks**
SCHOOL NAME: **Dunbar High School** INSPECTION DATE: **3/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **70**
MATERIAL DESCRIPTION: **Mastic on Wall**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:


MATERIAL LOCATION: **Room 128 - Material not observed**

MATERIAL QUANTITY: **0** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS: **Material was not observed - 2013 3 years re-inspection (couldn't find it)**

Inspector's Signature: _____



Date: 03/14/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Dunbar High School** REVIEW DATE: **4/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

HOMOGENEOUS AREA: **70**
MATERIAL DESCRIPTION: **Mastic on Wall**
MATERIAL LOCATION: **Room 128 - Material not observed**
MATERIAL QUANTITY: **0** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: 04/14/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUILDING ID: **1030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kathy Yurks**
SCHOOL NAME: **Dunbar High School** INSPECTION DATE: **3/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **71**
MATERIAL DESCRIPTION: **1' x 1' Fissured Ceiling Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Throughout Building, Cafeteria**

MATERIAL QUANTITY: **10000**


MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 03/14/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Dunbar High School** REVIEW DATE: **4/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

HOMOGENEOUS AREA: **71**
MATERIAL DESCRIPTION: **1' x 1' Fissured Ceiling Tile Mastic**
MATERIAL LOCATION: **Throughout Building, Cafeteria**
MATERIAL QUANTITY: **10000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **04/14/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kathy Yurks**
SCHOOL NAME: **Dunbar High School** INSPECTION DATE: **3/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **72**
MATERIAL DESCRIPTION: **2' x 4' Ceiling Panels**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Room 208, 117**
MATERIAL QUANTITY: **2400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 03/14/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Dunbar High School** REVIEW DATE: **4/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

HOMOGENEOUS AREA: **72**
MATERIAL DESCRIPTION: **2' x 4' Ceiling Panels**
MATERIAL LOCATION: **Room 208, 117**
MATERIAL QUANTITY: **2400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **04/14/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kathy Yurks**
SCHOOL NAME: **Dunbar High School** INSPECTION DATE: **3/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **73**
MATERIAL DESCRIPTION: **Drywall**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Room 208**
MATERIAL QUANTITY: **1600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 03/14/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Dunbar High School** REVIEW DATE: **4/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

HOMOGENEOUS AREA: **73**
MATERIAL DESCRIPTION: **Drywall**
MATERIAL LOCATION: **Room 208**
MATERIAL QUANTITY: **1600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **04/14/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kathy Yurks**
SCHOOL NAME: **Dunbar High School** INSPECTION DATE: **3/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **74**
MATERIAL DESCRIPTION: **Drywall Compound**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Room 208**
MATERIAL QUANTITY: **200** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: _____



Date: 03/14/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Dunbar High School** REVIEW DATE: **4/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

HOMOGENEOUS AREA: **74**
MATERIAL DESCRIPTION: **Drywall Compound**
MATERIAL LOCATION: **Room 208**
MATERIAL QUANTITY: **200** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **04/14/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kathy Yurks**
SCHOOL NAME: **Dunbar High School** INSPECTION DATE: **3/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **75**
MATERIAL DESCRIPTION: **Boiler Gaskets**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Bryan Boiler in Basement**
MATERIAL QUANTITY: **10** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 03/14/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Dunbar High School** REVIEW DATE: **4/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

HOMOGENEOUS AREA: **75**
MATERIAL DESCRIPTION: **Boiler Gaskets**
MATERIAL LOCATION: **Bryan Boiler in Basement**
MATERIAL QUANTITY: **10** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **04/14/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kathy Yurks**
SCHOOL NAME: **Dunbar High School** INSPECTION DATE: **3/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **76**
MATERIAL DESCRIPTION: **12" x 12" Multi-Gray Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**

MATERIAL LOCATION: **Rooms 203 & 205**

MATERIAL QUANTITY: **2000**


MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 03/14/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Dunbar High School** REVIEW DATE: **4/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

HOMOGENEOUS AREA: **76**
MATERIAL DESCRIPTION: **12" x 12" Multi-Gray Floor Tile**
MATERIAL LOCATION: **Rooms 203 & 205**
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **04/14/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kathy Yurks**
SCHOOL NAME: **Dunbar High School** INSPECTION DATE: **3/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **77**
MATERIAL DESCRIPTION: **12" x 12" Multi-Gray Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**

MATERIAL LOCATION: **Rooms 203 & 205**

MATERIAL QUANTITY: **2000**


MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 03/14/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Dunbar High School** REVIEW DATE: **4/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

HOMOGENEOUS AREA: **77**
MATERIAL DESCRIPTION: **12" x 12" Multi-Gray Floor Tile Mastic**
MATERIAL LOCATION: **Rooms 203 & 205**
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **04/14/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kathy Yurks**
SCHOOL NAME: **Dunbar High School** INSPECTION DATE: **3/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **78**
MATERIAL DESCRIPTION: **1' x 1' White Small Fissured Ceiling Tile**
HISTORICAL AHERA DAMAGE CATEGORY **7 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Lunchroom**
MATERIAL QUANTITY: **4700** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 03/14/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Dunbar High School** REVIEW DATE: **4/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

HOMOGENEOUS AREA: **78**
MATERIAL DESCRIPTION: **1' x 1' White Small Fissured Ceiling Tile**
MATERIAL LOCATION: **Lunchroom**
MATERIAL QUANTITY: **4700** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **04/14/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kathy Yurks**
SCHOOL NAME: **Dunbar High School** INSPECTION DATE: **3/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **8**
MATERIAL DESCRIPTION: **Plaster Above Ceiling Tiles**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Shop Wing**

MATERIAL QUANTITY:


MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Material was not observed - 2013 3 years re-inspection**

Inspector's Signature:



Date: **03/14/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Dunbar High School** REVIEW DATE: **4/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

HOMOGENEOUS AREA: **8**

MATERIAL DESCRIPTION: **Plaster Above Ceiling Tiles**

MATERIAL LOCATION: **Shop Wing**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Material was not observed - 2013 3 years re-inspection

Management Planner's Signature: _____



Date: **04/14/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kathy Yurks**
SCHOOL NAME: **Dunbar High School** INSPECTION DATE: **3/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **80**
MATERIAL DESCRIPTION: **12 x 12 gold and beige pattern FT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**

MATERIAL LOCATION: **114, 207, 206, 204, 107**

MATERIAL QUANTITY: **2000**


MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 03/14/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Dunbar High School** REVIEW DATE: **4/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

HOMOGENEOUS AREA: **80**
MATERIAL DESCRIPTION: **12 x 12 gold and beige pattern FT**
MATERIAL LOCATION: **114, 207, 206, 204, 107**
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **04/14/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kathy Yurks**
SCHOOL NAME: **Dunbar High School** INSPECTION DATE: **3/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **80M**
MATERIAL DESCRIPTION: **12 x 12 gold and beige pattern VFT mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **114, 207, 206, 204, 107**
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 03/14/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Dunbar High School** REVIEW DATE: **4/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

HOMOGENEOUS AREA: **80M**
MATERIAL DESCRIPTION: **12 x 12 gold and beige pattern VFT mastic**
MATERIAL LOCATION: **114, 207, 206, 204, 107**
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **04/14/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kathy Yurks**
SCHOOL NAME: **Dunbar High School** INSPECTION DATE: **3/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **81**
MATERIAL DESCRIPTION: **12x12 Blueish Grey w/ Dark Grey & White Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Rm 128, 100**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 03/14/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Dunbar High School** REVIEW DATE: **4/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

HOMOGENEOUS AREA: **81**
MATERIAL DESCRIPTION: **12x12 Blueish Grey w/ Dark Grey & White Floor Tile**
MATERIAL LOCATION: **Rm 128, 100**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **04/14/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kathy Yurks**
SCHOOL NAME: **Dunbar High School** INSPECTION DATE: **3/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **82**
MATERIAL DESCRIPTION: **12x12 Blueish Grey w/Dark Grey & White Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Rm 128, 100**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 03/14/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Dunbar High School** REVIEW DATE: **4/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

HOMOGENEOUS AREA: **82**
MATERIAL DESCRIPTION: **12x12 Blueish Grey w/Dark Grey & White Floor Tile Mastic**
MATERIAL LOCATION: **Rm 128, 100**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: 04/14/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kathy Yurks**
SCHOOL NAME: **Dunbar High School** INSPECTION DATE: **3/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **83**
MATERIAL DESCRIPTION: **12x12 Lt Grey w/Dark Grey & White Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Rm 100, 128, 203, 301, 300, 308**
MATERIAL QUANTITY: **3200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 03/14/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Dunbar High School** REVIEW DATE: **4/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

HOMOGENEOUS AREA: **83**
MATERIAL DESCRIPTION: **12x12 Lt Grey w/Dark Grey & White Floor Tile**
MATERIAL LOCATION: **Rm 100, 128, 203, 301, 300, 308**
MATERIAL QUANTITY: **3200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **04/14/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kathy Yurks**
SCHOOL NAME: **Dunbar High School** INSPECTION DATE: **3/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **84**
MATERIAL DESCRIPTION: **12x12 Lt Grey w/Dark Grey & White Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Rm 100, 128, 203, 301, 300, 308**
MATERIAL QUANTITY: **3200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 03/14/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Dunbar High School** REVIEW DATE: **4/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

HOMOGENEOUS AREA: **84**
MATERIAL DESCRIPTION: **12x12 Lt Grey w/Dark Grey & White Floor Tile Mastic**
MATERIAL LOCATION: **Rm 100, 128, 203, 301, 300, 308**
MATERIAL QUANTITY: **3200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **04/14/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kathy Yurks**
SCHOOL NAME: **Dunbar High School** INSPECTION DATE: **3/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **9**
MATERIAL DESCRIPTION: **Drywall Joint Compound**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 108**

MATERIAL QUANTITY:


MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **03/14/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Dunbar High School** REVIEW DATE: **4/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

HOMOGENEOUS AREA: **9**

MATERIAL DESCRIPTION: **Drywall Joint Compound**

MATERIAL LOCATION: **Room 108**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **04/14/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kathy Yurks**
SCHOOL NAME: **Dunbar High School** INSPECTION DATE: **3/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **A**
MATERIAL DESCRIPTION: **Aircell Pipe Insulation**
HISTORICAL AHERA DAMAGE CATEGORY **7 ACBM with potential for significant damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Repair
Operations and Maintenance**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT


This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Pipe Chases, Boiler Room and Throughout Building**
MATERIAL QUANTITY: **500** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: DAMAGE UNITS: **LF**
COMMENTS:

Inspector's Signature: _____



Date: 03/14/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Dunbar High School** REVIEW DATE: **4/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

HOMOGENEOUS AREA: **A**
MATERIAL DESCRIPTION: **Aircell Pipe Insulation**
MATERIAL LOCATION: **Pipe Chases, Boiler Room and Throughout Building**
MATERIAL QUANTITY: **500** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **15** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Repair
Operations and Maintenance**

Comments:

Remove/Repair Damaged area and maintain O&M on remaining HA

Management Planner's Signature: _____



Date: **04/14/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kathy Yurks**
SCHOOL NAME: **Dunbar High School** INSPECTION DATE: **3/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **B**
MATERIAL DESCRIPTION: **(Cardboard) Paperwrap Pipe Insulation**
HISTORICAL AHERA DAMAGE CATEGORY **7 ACBM with potential for significant damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Repair
Operations and Maintenance
See Comments**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Boiler Room and Throughout Building, rm 115, 125**
MATERIAL QUANTITY: **600** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: DAMAGE UNITS: **LF**
COMMENTS:

Inspector's Signature: _____



Date: 03/14/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Dunbar High School** REVIEW DATE: **4/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

HOMOGENEOUS AREA: **B**
MATERIAL DESCRIPTION: **(Cardboard) Paperwrap Pipe Insulation**
MATERIAL LOCATION: **Boiler Room and Throughout Building, rm 115, 125**
MATERIAL QUANTITY: **600** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **1** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Repair
Operations and Maintenance
See Comments

Comments:

Remove/Repair Damaged area and maintain O&M on remaining HA

Management Planner's Signature: _____



Date: **04/14/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kathy Yurks**
SCHOOL NAME: **Dunbar High School** INSPECTION DATE: **3/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **C**
MATERIAL DESCRIPTION: **Aircell Duct Insulation**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:


MATERIAL LOCATION: **Abated in 1992 - See 2004 Comments**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Material was not observed - 2013 3 years re-inspection**

Inspector's Signature:



Date: **03/14/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Dunbar High School** REVIEW DATE: **4/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

HOMOGENEOUS AREA: **C**

MATERIAL DESCRIPTION: **Aircell Duct Insulation**

MATERIAL LOCATION: **Abated in 1992 - See 2004 Comments**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **04/14/2013** _____

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kathy Yurks**
SCHOOL NAME: **Dunbar High School** INSPECTION DATE: **3/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **D**
MATERIAL DESCRIPTION: **Mag Block Insulation**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Boilers in Boiler House - Abated 1992**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Material was not observed - 2013 3 years re-inspection**

Inspector's Signature:



Date: **03/14/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Dunbar High School** REVIEW DATE: **4/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

HOMOGENEOUS AREA: **D**

MATERIAL DESCRIPTION: **Mag Block Insulation**

MATERIAL LOCATION: **Boilers in Boiler House - Abated 1992**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **04/14/2013** _____

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kathy Yurks**
SCHOOL NAME: **Dunbar High School** INSPECTION DATE: **3/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **E**
MATERIAL DESCRIPTION: **Mag Block Pipe Insulation**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Boiler House - Abated 1992**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Material was not observed - 2013 3 years re-inspection**

Inspector's Signature:



Date: **03/14/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Dunbar High School** REVIEW DATE: **4/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

HOMOGENEOUS AREA: **E**

MATERIAL DESCRIPTION: **Mag Block Pipe Insulation**

MATERIAL LOCATION: **Boiler House - Abated 1992**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **04/14/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kathy Yurks**
SCHOOL NAME: **Dunbar High School** INSPECTION DATE: **3/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **F**
MATERIAL DESCRIPTION: **Mag Block Duct Insulation**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Boiler House - Abated 1992**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Material was not observed - 2013 3 years re-inspection**

Inspector's Signature:



Date: **03/14/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Dunbar High School** REVIEW DATE: **4/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

HOMOGENEOUS AREA: **F**

MATERIAL DESCRIPTION: **Mag Block Duct Insulation**

MATERIAL LOCATION: **Boiler House - Abated 1992**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **04/14/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kathy Yurks**
SCHOOL NAME: **Dunbar High School** INSPECTION DATE: **3/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **G**
MATERIAL DESCRIPTION: **Fittings on Fiberglass Pipe Insulation**
HISTORICAL AHERA DAMAGE CATEGORY **7 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Main Building**
MATERIAL QUANTITY: **60** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: _____



Date: 03/14/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Dunbar High School** REVIEW DATE: **4/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

HOMOGENEOUS AREA: **G**

MATERIAL DESCRIPTION: **Fittings on Fiberglass Pipe Insulation**

MATERIAL LOCATION: **Main Building**

MATERIAL QUANTITY: **60**

MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **04/14/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kathy Yurks**
SCHOOL NAME: **Dunbar High School** INSPECTION DATE: **3/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **HA-1000**
MATERIAL DESCRIPTION: **White woven electrical wire insulation**
HISTORICAL AHERA DAMAGE CATEGORY **7 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Auditorium stage light fixtures**
MATERIAL QUANTITY: **50** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: _____



Date: 03/14/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Dunbar High School** REVIEW DATE: **4/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

HOMOGENEOUS AREA: **HA-1000**
MATERIAL DESCRIPTION: **White woven electrical wire insulation**
MATERIAL LOCATION: **Auditorium stage light fixtures**
MATERIAL QUANTITY: **50** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **04/14/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kathy Yurks**
SCHOOL NAME: **Dunbar High School** INSPECTION DATE: **3/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **I3 I**
MATERIAL DESCRIPTION: **9"x 9" White Floor Tile w/Brn & Blk Streaks Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **Moderate**

MATERIAL LOCATION: **Rooms 212 and 311**

MATERIAL QUANTITY: **1500**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS: **Material was not observed - 2013 3 years re-inspection**

Inspector's Signature: _____



Date: 03/14/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Dunbar High School** REVIEW DATE: **4/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

HOMOGENEOUS AREA: **I 3 I**
MATERIAL DESCRIPTION: **9"x 9" White Floor Tile w/Brn & Blk Streaks Mastic**
MATERIAL LOCATION: **Rooms 212 and 311**
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **04/14/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kathy Yurks**
SCHOOL NAME: **Dunbar High School** INSPECTION DATE: **3/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **J**
MATERIAL DESCRIPTION: **Cementitious Pipe Joint Insulation on Aircell Pipe**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT


This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Pipe Chases, Boiler Room and Throughout Building**
MATERIAL QUANTITY: **50** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: DAMAGE UNITS: **LF**
COMMENTS:

Inspector's Signature: _____



Date: 03/14/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUILDING ID: **1030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Dunbar High School** REVIEW DATE: **4/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

HOMOGENEOUS AREA: **J**
MATERIAL DESCRIPTION: **Cementitious Pipe Joint Insulation on Aircell Pipe**
MATERIAL LOCATION: **Pipe Chases, Boiler Room and Throughout Building**
MATERIAL QUANTITY: **50** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: 04/14/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kathy Yurks**
SCHOOL NAME: **Dunbar High School** INSPECTION DATE: **3/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **K**
MATERIAL DESCRIPTION: **Cementitious Pipe Joint Insulation on Paperwrap**
HISTORICAL AHERA DAMAGE CATEGORY **7 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Boiler Room, Pipe Chases and Throughout Building**
MATERIAL QUANTITY: **20** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: _____



Date: 03/14/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUIDLING ID: **1030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Dunbar High School** REVIEW DATE: **4/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

HOMOGENEOUS AREA: **K**
MATERIAL DESCRIPTION: **Cementitious Pipe Joint Insulation on Paperwrap**
MATERIAL LOCATION: **Boiler Room, Pipe Chases and Throughout Building**
MATERIAL QUANTITY: **20** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **04/14/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION


Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUILDING ID: **1030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kathy Yurks**
SCHOOL NAME: **Dunbar High School** INSPECTION DATE: **3/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **87**
MATERIAL DESCRIPTION: **Mastic for HA 85 and 86**
MATERIAL LOCATION: **Throughout Hallways and Various Classrooms**
MATERIAL QUANTITY: **30000** MATERIAL UNITS: **SF**
MATERIAL CATEGORY: **MISC** FRIABLE: **No**
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **LOW** CONDITION:
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
ACCESSIBILITY: **Not Reachable** DAMAGE REASON:
DAMAGE QUANTITY: **0** DAMAGE REASON:
DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____



Date: 03/14/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUILDING ID: **1030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Dunbar High School** REVIEW DATE: **4/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

HOMOGENEOUS AREA: **87**
MATERIAL DESCRIPTION: **Mastic for HA 85 and 86**
MATERIAL LOCATION: **Throughout Hallways and Various Classrooms**
MATERIAL QUANTITY: **30000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:


COMMENTS:

Management Planner's Signature: _____



Date: 04/14/2013

K:\CPS 2011\2013 Three Year\A\Gad Drawings\Region 4\13\1303 Dunbar High School\2013 Asbestos Reinspection\2013 Asbestos Reinspection Key Notes




First Floor

ASBESTOS REINSPECTION KEY NOTES:

HA-87 Mastic Associated with 12"x 12" Floor Tile, HA-85 and HA-86

Dunbar High School First Floor
2013 Asbestos Reinspection



CLIENT:
Chicago Public Schools
125 South Clark Street,
Chicago, Illinois 60603

PROJECT NAME:
2013 AHERA Reinspection
Paul Laurence Dunbar Career
Academy High School
3000 S King Dr
Chicago, IL 60616

SHEET NAME:
Dunbar High School First
Floor - HA-87

INSPECTED BY:
Kathy Yurks

DRAWN BY: MJW	DATE: 4/30/2013	CHECKED BY:
REVISED BY:	DATE:	CHECKED BY:
REVISED BY:	DATE:	CHECKED BY:
REVISED BY:	DATE:	CHECKED BY:


IDPH License #:100- 08785

Carnow, Conibear & Assoc., Ltd.
Environmental Consulting Services
600 W. Van Buren St., Suite 500, Chicago, IL 60607
t: 312.782.4486 f: 312.782.5145
www.ccaatd.com

**CARNOW
CONIBEAR**


CCA PROJECT NUMBER
A320130001-173
DATE
03/14/2013
SHEET NUMBER
HA-87

K:\CPS 2011\2013 Three Years\Cad Drawings\Region 4\10\Dunbar High School\Dunbar High School Second Floor.dwg



Second Floor

ASBESTOS REINSPECTION KEY NOTES:

 HA-87 Mastic Associated with 12"x 12" Floor Tile, HA-85 and HA-86

Dunbar High School Second Floor
2013 Asbestos Reinspection



CLIENT:
Chicago Public Schools
125 South Clark Street,
Chicago, Illinois 60603

PROJECT NAME:
2013 AHERA Reinspection
Paul Laurence Dunbar Career
Academy High School
3000 S King Dr
Chicago, IL 60616

SHEET NAME:
Dunbar High School Second
Floor - HA-87
INSPECTED BY:
Kathy Yurks


DRAWN BY: MJW	DATE: 4/30/2013	CHECKED BY:
REVISED BY:	DATE:	CHECKED BY:
REVISED BY:	DATE:	CHECKED BY:
REVISED BY:	DATE:	CHECKED BY:

INSPECTED BY:
Kathy Yurks
IDPH License #:100- 08785


Carnow, Conibear & Assoc., Ltd.
Environmental Consulting Services
600 W. Van Buren St., Suite 500, Chicago, IL 60607
t: 312.782.4486 f: 312.782.5145
www.ccaatd.com

**CARNOW
CONIBEAR**


CCA PROJECT NUMBER
A320130001-173
DATE
03/14/2013
SHEET NUMBER
HA-87



ASBESTOS REINSPECTION KEY NOTES:

 HA-87 Mastic Associated with 12"x 12" Floor Tile, HA-85 and HA-86

Dunbar High School Third Floor
2013 Asbestos Reinspection



CLIENT:
Chicago Public Schools
125 South Clark Street,
Chicago, Illinois 60603

PROJECT NAME:
2013 AHERA Reinspection
Paul Laurence Dunbar Career
Academy High School
3000 S King Dr
Chicago, IL 60616

SHEET NAME:
Dunbar High School Third
Floor - HA-87

INSPECTED BY:
Kathy Yurks

DRAWN BY: MJW	DATE: 4/30/2013	CHECKED BY:
REVISED BY:	DATE:	CHECKED BY:
REVISED BY:	DATE:	CHECKED BY:
REVISED BY:	DATE:	CHECKED BY:

IDPH License #:100- 08785

Carnow, Conibear & Assoc., Ltd.
Environmental Consulting Services
600 W. Van Buren St., Suite 500, Chicago, IL 60607
t: 312.782.4486 f: 312.782.5145
www.ccaatd.com



CCA PROJECT NUMBER
A320130001-173

DATE
03/14/2013

SHEET NUMBER
HA-87

K:\CPS 2011\2013 Three Years\CAD Drawings\Region 4\10\Dunbar High School\Dunbar High School Third Floor.dwg

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION


Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUILDING ID: **1030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kathy Yurks**
SCHOOL NAME: **Dunbar High School** INSPECTION DATE: **3/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **85**
MATERIAL DESCRIPTION: **12" X 12" Blotted Blue VFT**
MATERIAL LOCATION: **Throughout Hallways and Various Rooms**
MATERIAL QUANTITY: **26000** MATERIAL UNITS: **SF**
MATERIAL CATEGORY: **MISC** FRIABLE: **No**
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **MODERATE** CONDITION:
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
ACCESSIBILITY: **Within Reach** DAMAGE REASON:
DAMAGE QUANTITY: **0** DAMAGE REASON:
DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____



Date: 03/14/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUILDING ID: **1030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Dunbar High School** REVIEW DATE: **4/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

HOMOGENEOUS AREA: **85**
MATERIAL DESCRIPTION: **12" X 12" Blotted Blue VFT**
MATERIAL LOCATION: **Throughout Hallways and Various Rooms**
MATERIAL QUANTITY: **26000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:


COMMENTS:

Management Planner's Signature: _____



Date: 04/14/2013

K:\CPS 2011\2013 Three Year\A\Asst Drawings\Region 4\13\1303 Dunbar High School\2013 Asbestos Reinspection\2013 Asbestos Reinspection First Floor.dwg




First Floor

ASBESTOS REINSPECTION KEY NOTES:

 HA-85 12"x 12" Blotted Blue Floor Tile (mixed with HA-86)

Dunbar High School First Floor
2013 Asbestos Reinspection



CLIENT:
Chicago Public Schools
125 South Clark Street,
Chicago, Illinois 60603

PROJECT NAME:
2013 AHERA Reinspection
Paul Laurence Dunbar Career
Academy High School
3000 S King Dr
Chicago, IL 60616

SHEET NAME:
Dunbar High School First
Floor - HA-85
INSPECTED BY:
Kathy Yurks

DRAWN BY: MJW	DATE: 4/30/2013	CHECKED BY:
REVISED BY:	DATE:	CHECKED BY:
REVISED BY:	DATE:	CHECKED BY:
REVISED BY:	DATE:	CHECKED BY:


IDPH License #:100- 08785

Carnow, Conibear & Assoc., Ltd.
Environmental Consulting Services
600 W. Van Buren St., Suite 500, Chicago, IL 60607
t: 312.782.4486 f: 312.782.5145
www.ccaatd.com

**CARNOW
CONIBEAR**


CCA PROJECT NUMBER
A320130001-173
DATE
03/14/2013
SHEET NUMBER
HA-85

K:\CPS 2011\2013 Three Year\A\CAD Drawings\Region 4\10\Dunbar High School\Dunbar High School Second Floor.dwg




Second Floor

ASBESTOS REINSPECTION KEY NOTES:

 HA-85 12"x 12" Blotted Blue Floor Tile (mixed with HA-86)

Dunbar High School Second Floor
2013 Asbestos Reinspection



CLIENT:
Chicago Public Schools
125 South Clark Street,
Chicago, Illinois 60603

PROJECT NAME:
2013 AHERA Reinspection
Paul Laurence Dunbar Career
Academy High School
3000 S King Dr
Chicago, IL 60616

SHEET NAME:
Dunbar High School Second
Floor - HA-85
INSPECTED BY:
Kathy Yurks


DRAWN BY: MJW	DATE: 4/30/2013	CHECKED BY:
REVISED BY:	DATE:	CHECKED BY:
REVISED BY:	DATE:	CHECKED BY:
REVISED BY:	DATE:	CHECKED BY:

INSPECTED BY:
Kathy Yurks
IDPH License #:100- 08785

Carnow, Conibear & Assoc., Ltd.
Environmental Consulting Services
600 W. Van Buren St., Suite 500, Chicago, IL 60607
t: 312.782.4486 f: 312.782.5145
www.ccaatd.com

**CARNOW
CONIBEAR**


CCA PROJECT NUMBER
A320130001-173
DATE
03/14/2013
SHEET NUMBER
HA-85



ASBESTOS REINSPECTION KEY NOTES:

 HA-85 12"x 12" Blotted Blue Floor Tile (mixed with HA-86)

Dunbar High School Third Floor
2013 Asbestos Reinspection



CLIENT:
Chicago Public Schools
125 South Clark Street,
Chicago, Illinois 60603

PROJECT NAME:
2013 AHERA Reinspection
Paul Laurence Dunbar Career
Academy High School
3000 S King Dr
Chicago, IL 60616

SHEET NAME:
Dunbar High School Third
Floor - HA-85

INSPECTED BY:
Kathy Yurks

DRAWN BY: MJW	DATE: 4/30/2013	CHECKED BY:
REVISED BY:	DATE:	CHECKED BY:
REVISED BY:	DATE:	CHECKED BY:
REVISED BY:	DATE:	CHECKED BY:

IDPH License #:100- 08785

Carnow, Conibear & Assoc., Ltd.
Environmental Consulting Services
600 W. Van Buren St., Suite 500, Chicago, IL 60607
t: 312.782.4486 f: 312.782.5145
www.ccaatd.com



CCA PROJECT NUMBER
A320130001-173

DATE
03/14/2013

SHEET NUMBER
HA-85

K:\CPS 2011\2013 Three Years\Cad Drawings\Region 4\10\Dunbar High School\Dunbar High School Third Floor.dwg

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUILDING ID: **1030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Dunbar High School** REVIEW DATE: **4/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

HOMOGENEOUS AREA: **1 A**
MATERIAL DESCRIPTION: **Blue Carpet Mastic**
MATERIAL LOCATION: **Office Complex, 101, 106, 132**

MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____



Date: **04/14/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUILDING ID: **1030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kathy Yurks**
SCHOOL NAME: **Dunbar High School** INSPECTION DATE: **3/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **86**
MATERIAL DESCRIPTION: **12" X 12" Light Blue VFT**
MATERIAL LOCATION: **Throughout Hallways and Various Classrooms**
MATERIAL QUANTITY: **4000** MATERIAL UNITS: **SF**
MATERIAL CATEGORY: **MISC** FRIABLE: **No**
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **MODERATE** CONDITION:
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
ACCESSIBILITY: **Within Reach** DAMAGE REASON:
DAMAGE QUANTITY: **0** DAMAGE REASON:
DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____



Date: 03/14/2013

Chicago Public Schools

Carnow, Conibear and Associates 2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53021** BUILDING ID: **1030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Dunbar High School** REVIEW DATE: **4/14/2013**
ADDRESS: **3000 S. King Dr.** IDPH LICENSE NO: **100-8785**

HOMOGENEOUS AREA: **86**
MATERIAL DESCRIPTION: **12" X 12" Light Blue VFT**
MATERIAL LOCATION: **Throughout Hallways and Various Classrooms**
MATERIAL QUANTITY: **4000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:


COMMENTS:

Management Planner's Signature: _____



Date: 04/14/2013

K:\CPS 2011\2013 Three Year\A\Asst Drawings\Region 4\13\1303 Dunbar High School\1303 Dunbar High School First Floor




First Floor

ASBESTOS REINSPECTION KEY NOTES:

HA-86 12"x 12" Light Blue Floor Tile (mixed with HA-85)

Dunbar High School First Floor
2013 Asbestos Reinspection



CLIENT:
Chicago Public Schools
125 South Clark Street,
Chicago, Illinois 60603

PROJECT NAME:
2013 AHERA Reinspection
Paul Laurence Dunbar Career
Academy High School
3000 S King Dr
Chicago, IL 60616

SHEET NAME:
Dunbar High School First
Floor - HA-86

INSPECTED BY:
Kathy Yurks

DRAWN BY: MJW	DATE: 4/30/2013	CHECKED BY:
REVISED BY:	DATE:	CHECKED BY:
REVISED BY:	DATE:	CHECKED BY:
REVISED BY:	DATE:	CHECKED BY:


IDPH License #:100- 08785

Carnow, Conibeat & Assoc., Ltd.
Environmental Consulting Services
600 W. Van Buren St., Suite 500, Chicago, IL 60607
t: 312.782.4486 f: 312.782.5145
www.ccaatd.com

**CARNOW
CONIBEAR**

CCA PROJECT NUMBER
A320130001-173
DATE
03/14/2013
SHEET NUMBER
HA-86

K:\CPS 2011\2013 Three Years\Asd Drawings\Region 4\JD\Dunbar High School\Dunbar High School Second Floor.dwg



Second Floor

ASBESTOS REINSPECTION KEY NOTES:

HA-86 12"x 12" Light Blue Floor Tile (mixed with HA-85)

Dunbar High School Second Floor
2013 Asbestos Reinspection



CLIENT:
Chicago Public Schools
125 South Clark Street,
Chicago, Illinois 60603

PROJECT NAME:
2013 AHERA Reinspection
Paul Laurence Dunbar Career
Academy High School
3000 S King Dr
Chicago, IL 60616

SHEET NAME:
Dunbar High School Second
Floor - HA-86
INSPECTED BY:
Kathy Yurks


DRAWN BY: MJW	DATE: 4/30/2013	CHECKED BY:
REVISED BY:	DATE:	CHECKED BY:
REVISED BY:	DATE:	CHECKED BY:
REVISED BY:	DATE:	CHECKED BY:

INSPECTED BY:
Kathy Yurks
IDPH License #:100- 08785

Carnow, Conibear & Assoc., Ltd.
Environmental Consulting Services
600 W. Van Buren St., Suite 500, Chicago, IL 60607
t: 312.782.4486 f: 312.782.5145
www.ccaatd.com

**CARNOW
CONIBEAR**

CCA PROJECT NUMBER
A320130001-173
DATE
03/14/2013
SHEET NUMBER
HA-86



ASBESTOS REINSPECTION KEY NOTES:

 HA-86 12"x 12" Light Blue Floor Tile (mixed with HA-85)

Dunbar High School Third Floor
2013 Asbestos Reinspection



CLIENT:
Chicago Public Schools
125 South Clark Street,
Chicago, Illinois 60603

PROJECT NAME:
2013 AHERA Reinspection
Paul Laurence Dunbar Career
Academy High School
3000 S King Dr
Chicago, IL 60616

SHEET NAME:
Dunbar High School Third
Floor - HA-86

INSPECTED BY:
Kathy Yurks

DRAWN BY: MJW	DATE: 4/30/2013	CHECKED BY:
REVISED BY:	DATE:	CHECKED BY:
REVISED BY:	DATE:	CHECKED BY:
REVISED BY:	DATE:	CHECKED BY:

IDPH License #:100- 08785

Carnow, Conibear & Assoc., Ltd.
Environmental Consulting Services
600 W. Van Buren St., Suite 500, Chicago, IL 60607
t: 312.782.4486 f: 312.782.5145
www.ccaatd.com



CCA PROJECT NUMBER
A320130001-173


DATE
03/14/2013

SHEET NUMBER
HA-86

K:\CPS 2011\2013 Three Years\Cad Drawings\Region 4\10\Dunbar High School\Dunbar High School Third Floor.dwg

APPENDIX B

Inspector and Management Planner Licenses



Occupational Training & Supply, Inc.

7233 Adams Street • Willowbrook, IL 60527 • (630) 655-3900

Asbestos Building Inspector

Occupational Training and Supply, Inc. certifies that

Kathy Yurks

has successfully completed the 24 hour Asbestos Building Inspector Course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 10 CFR 763 Asbestos Hazard Emergency Response Act (AHERA) and TSCA Title II.

Certificate: ABIL206201045

Exam Date: 6/20/2012

Course Date: 6/18/2012-6/20/2012

Expiration Date: 6/20/2013

Kathy DeSalvo, Director

2012



**ASBESTOS
PROFESSIONAL
LICENSE**

ID NUMBER
100 - 08785

ISSUED
1/24/2013

EXPIRES
05/15/2014

KATHY YURKS
101 ROHRER PO BOX 32
MUNCU, IL 61857

Environmental Health



ENDORSEMENTS

TC EXPIRES

INSPECTOR

6/20/2013

AIR SAMPLING PROFESSIONAL

Alteration of this license shall result in legal action
This license issued under authority of the State of Illinois
Department of Public Health
This license is valid only when accompanied by a valid
training course certificate.



Occupational Training & Supply, Inc.

7233 Adams Street • Willowbrook, IL 60527 • (630) 655-3900

Asbestos Building Inspector Refresher

Occupational Training and Supply, Inc. certifies that

Todd Huffer

has successfully completed the 4 hour Asbestos Building Inspector Refresher Course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 10 CFR 763 Asbestos Hazard Emergency Response Act (AHERA) and TSCA Title II.

Certificate: BIR1212042317

Exam Date: 12/4/2012

Course Date: 12/4/2012


Expiration Date: 12/4/2013

Kathy DeSalvo, Director

2012



Todd Huffer

Illinois Licensed Asbestos Inspector, Management Planner,
Project Manager, and Air Sampling Professional

 **ASBESTOS PROFESSIONAL LICENSE**

ID NUMBER 100 - 09870	ISSUED 4/4/2012	EXPIRES 05/15/2013
---------------------------------	---------------------------	------------------------------

TODD T HUFFER
918 N WOLCOTT UNIT 6
CHICAGO, IL 60622

 
Environmental Health

ENDORSEMENTS	TC EXPIRES
INSPECTOR	12/8/2012
MANAGEMENT PLANNER	1/19/2013
PROJECT MANAGER	9/8/2012
AIR SAMPLING PROFESSIONAL	

Alteration of this license shall result in legal action
This license issued under authority of the State of Illinois
Department of Public Health
This license is valid only when accompanied by a valid
training course certificate.

**CARNOW
CONIBEAR**



Occupational Training & Supply, Inc.

7233 Adams Street ♦ Willowbrook, IL 60527 ♦ (630) 655-3900

Asbestos Management Planner Refresher

Occupational Training and Supply, Inc. certifies that

Todd Huffer

has successfully completed the 4 hour Asbestos Management Planner Refresher Course
and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 10 CFR 763 Asbestos Hazard Emergency Response Act (AHERA) and TSCA Title II.

Certificate: MPRI302250735

Exam Date: 2/25/2013

Course Date: 2/25/2013

Expiration Date: 2/25/2014

Kathy DeSalvo, Director

2013

APPENDIX C

Laboratory Accreditations

APPENDIX D

Laboratory Results

APPENDIX E

Chain of Custody Forms

Three-Year Reinspection Key to Terms

	CODE	KEY
MATERIAL		
	ACBM	Asbestos Containing Building Materials
MATERIAL CATEGORY		
	MISC	Miscellaneous
	SURF	Surfacing
	TSI	Thermal System Insulation
MATERIAL UNITS		
	LF	Linear Feet
	SF	Square Feet
	CF	Cubic Feet
DAMAGE TYPE		
	Loc	Localized
	Dist	Distributed