

**ILLINOIS DEPARTMENT OF PUBLIC HEALTH
AHERA THREE YEAR REINSPECTION
ASBESTOS ABATEMENT PROGRAM
SCHOOL INFORMATION FORM**

SECTION I

NAME OF SCHOOL DISTRICT: CHICAGO SCHOOL DIST 299
SCHOOL ID NUMBER: 14-016-2990-0529
SCHOOL NAME: Noble Street Charter - Chicago Bulls College
ADDRESS OF SCHOOL: 2040 W. Adams
CITY: Chicago, IL, 60612

DATE LAST THREE YEAR REINSPECTION WAS COMPLETED **3/12/2010**

If the address on this form is different than the address of the building, submit a written explanation.

SECTION II (Please type or print)

PLEASE COMPLETE THE FOLLOWING FOR YOUR THREE YEAR REINSPECTION:

DATE REINSPECTION COMPLETED: 5/3/2013 ENROLLMENT 0
IDPH INSPECTOR LICENSE NUMBER: 100-11460
IDPH LICENSED INSPECTOR NAME (Please Print): Marcus Tsilimos
IDPH MP LICENSE NUMBER: 100-05171
IDPH LICENSED MANAGEMENT PLANNER NAME (Please Print): Stephen Diblik

DESIGNATED PERSON (Please Print): Ms. Lynn Crivello PHONE: (773) 553-3113



5/3/2013

Signature of Designated Person

Date

SECTION III

PLEASE COMPLETE THE FOLLOWING INFORMATION FOR ANY CHANGES WITHIN THE SCHOOL DISTRICT.

School building has been sold. Date of Sale: _____

School has been closed. Date closed: _____

School building has been demolished. Date: _____

School building is asbestos free since last reinspection: _____

Please explain in writing why the school building is now asbestos free and include the supporting documentation.

If a new school building has been added to the district, submit either an exclusionary statement or a management plan and inspection report. Include the complete name, address and city of school building.

Explain in writing if the address of the building is different than the address on this form:

THREE-YEAR REINSPECTION

CHICAGO SCHOOL DIST 299

Noble Street Charter - Chicago Bulls College

2040 W. Adams
Chicago, IL, 60612

Unit: 26661
Building ID: 4040

IDPH ID Number: 14-016-2990-0529

REPORT DATE:

Friday, May 03, 2013

Prepared for:

Chicago Public Schools
125 S. Clark Street
Chicago, IL 60603

Prepared by:

Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone (312) 762-2900

Fax (312) 782-5145

**DO NOT REMOVE FROM SCHOOL
REQUIRED BY FEDERAL LAW**

April 26, 2013

Mr. R. Kent Cook
Asbestos Program
Illinois Department of Public Health
525 West Jefferson Street
Springfield, Illinois 62761

Re: Chicago Public Schools - 2013 Three-Year Reinspections

Dear Mr. Cook:

Carnow, Conibear and Associates, Managing Environmental Consultant (MEC), conducted the Three-Year Reinspections and performed management plan updates for the Chicago Public Schools (CPS) facilities in Region 3,4,5 Elementary Schools. Please update your records with the following information.

School District: 299 Unit: 26661 Region: 03 IDPH ID: 14-016-2990-0529

School: Noble Street Charter - Chicago Bulls College Building ID: 4040

Address: 2040 W. Adams
Chicago, IL, 60612

Building Contact: Contact Phone:

Current Building Owners: Chicago Public Schools

Review Date: 5/3/2013

Inspector: Marcus Tsilimos Inspector IDPH License: 100-11460
Management Planner: Stephen Diblik Management Planner IDPH License: 100-05171

If you have any questions or comments, please contact us at (312) 762-2900

Sincerely,
Carnow, Conibear and Associates



Stephen Diblik
100-05171

Environmental Notification to Occupants

To: Faculty, Staff and Parents
From: Chicago Public Schools
Date: April 26, 2013

RE: Noble Street Charter - Chicago Bulls College, Unit 26661
2040 W. Adams
Chicago, IL, 60612

Dear Faculty, Staff and Parents,

This letter is to notify you that the 2013 asbestos three year re-inspection has been completed at Noble Street Charter - Chicago Bulls College , following the Federal Asbestos Hazard Emergency Response Act (AHERA), 40 CFR Part 763, Subpart E and is available for your review at the main office of the school.

Although asbestos-containing materials have been identified at Noble Street Charter - Chicago Bulls College, there is no reason to believe that any threat to the health of students or staff exists at this time. CPS will continue to carefully monitor the condition of asbestos-containing materials and if conditions warrant, all appropriate steps will be taken to maintain the health and safety of all building occupants.

If you have any questions regarding this matter or require additional information, please feel free to contact Ms. Lynn Crivello, the designated Local Education Authority's Designated Person at (773) 553-3113 .

Table of Contents

- I. School and Inspection Information
- II. Executive Summary
- III. Methodology
- IV. Abatement History
- V. Reassessments and Recommendations
- VI. Conclusions

Table I: Inspector's Reinspection Findings

Table II: Management Planner's Review

APPENDICES:

- Appendix A: Assessment Sheets, Drawings and Photos
- Appendix B: Inspector and Management Planner Licenses
- Appendix C: Laboratory Accreditations
- Appendix D: Laboratory Results
- Appendix E: Chain of Custody Forms

SCHOOL AND INSPECTION INFORMATION

1. School Information

School: Noble Street Charter - Chicago Bulls College Unit: 26661 Region: 03
Address: 2040 W. Adams Chicago, IL, 60612
IDPH ID: 14-016-2990-0529 Building ID: 4040
Contact: Phone:

2. Description of Facility

Original Construction: Additional Construction:
Total Square Footage: 114200 No of Floors:
Current Occupancy: 0

3. LEA Designated Person

Contact: Ms. Lynn Crivello Phone: (773) 553-3113
Address: 125 South Clark Street, 17th Floor
Chicago, IL 60603


4. Managing Environmental Consultant

MEC: Carnow, Conibear and Associates
Contact: Dan Juneau
Address 600 West Van Buren St., Ste 500
Phone: (312) 762-2900 Fax: (312) 782-5145

5. Inspector

Inspector Name: Marcus Tsilimos


Inspector IDPH license # 100-11460

Signature: 
Date: 4/26/2013

6. Management Planner

Management Planner Name: Stephen Diblik


Management Planner IDPH license # 100-05171

Signature: 
Date: 5/3/2013

7. Review Date: 5/3/2013

8. LEA Designated Person's Acknowledgement

The reinspection report and recommendations have been received by me and appropriate action will be taken by the School District.

Signature: 

Date: 5/3/2013

Name: Ms. Lynn Crivello

II. EXECUTIVE SUMMARY

Carnow, Conibear and Associates was retained by the Chicago Public Schools (CPS) to perform a three-year asbestos reinspection of the Noble Street Charter - Chicago Bulls College. This inspection was conducted in accordance with the United States Environmental Protection Agency (USEPA) Asbestos Hazard Emergency Response Act (AHERA) part 763.92 (b), and the ongoing Operations and Maintenance Program (O&M) originally designed in the School's Asbestos Management Plan. The purpose of this three-year reinspection is to record any condition changes in the asbestos-containing building material (ACBM) in the school since the previous three-year reinspection and the six-month periodic surveillance, to identify, assess, and include any Homogeneous Areas (HA) not identified in the Management Plan, and to recommend an appropriate response action to manage asbestos.

The inspector conducted a three-year reinspection of this facility under Illinois Department of Public Health (IDPH) school reinspection requirements and AHERA, sections 763.85 and 763.88. The main building and each addition to the main building, if constructed at different dates, were inspected separately. Laboratory accreditations are included in Appendix C, laboratory results are included in Appendix D, and chain of custody forms are included in Appendix E.

Note: During previous inspections, some of the HA(s) were identified together as 9" x 9" floor tile (FT), mastics assoc. with 9" x 9" FT, 12" x 12" FT, mastics assoc. with 12" x 12" FT, pipe insulation, etc. Some of these HA(s) have been re-identified by areas that are uniform in color, texture, construction date, application date, and general appearance.

The inspector has determined the following:

A. The following HAs have changed assessment categories for Building 4040:

1	Hard Coat Plaster
10	Canvas Wall Covering
12	Ceramic Tile Mortar
14.1	Common Brick Mortar
15.1	Common Brick
16	Insulation Beneath Boiler Shells
17	Boiler Gaskets - Front Door
19	Fire Brick
2	1' x 1' Ceiling Tile (Thick)

20	Drywall & Compound
21	Insulation Inside of Vault Door
22	Floor Tile Beneath 12" x 12" Floor Tile
23	Mastic Beneath 1st Layer of Floor Tiles
24	Lab Counter Tops, Sinks & Tables
25	2' x 4' Lay In Ceiling Panels
26	Material Beneath 12" x 12" Floor Tile
27	Mastic for Material Beneath 12" x 12" Floor Tile
33	Drywall
34	Drywall Tape/Compound
4	1' x 1' Smooth Ceiling Tile (Thin)
5.3	12"x12" Brn/Yellow FT w/ White-Brown Specks
5.5	12" x 12" Beige Mix Floor Tile
60	Vault Door Insulation
8.5	12" x 12" Beige Mix Floor Tile Mastic
B	Water Tank Insulation
C	Tank Insulation
G	Cardboard Pipe Insulation

B. The following new homogenous areas have been identified for Building 4040:

C. This reinspection covered only physically accessible and visible areas and materials that were identified in the LEA's management plan. The following materials were concealed and/or contained in areas that were inaccessible for sampling and have been classified as Assumed:

06A	12"x12" Off-White Speckled Floor Tile Adhesive
1	Hard Coat Plaster
10	Canvas Wall Covering
11.2	Interior Window Glaze
12	Ceramic Tile Mortar
13 A	Blue/Maroon Mix Carpet Mastic
13 B	Green Mix Carpet Mastic
13 C	Dark Blue Carpet Mastic
13 D	Blue Carpet Mastic
13 E	Blue/Purple Mix Carpet Mastic
14.1	Common Brick Mortar
14.2	Brown Brick Mortar - not AHERA
14.3	New Brown Brick Mortar - not AHERA
15.1	Common Brick
15.2	Original Brown Brick - not AHERA
15.3	New Brown Brick - not AHERA
16	Insulation Beneath Boiler Shells
18	Boiler Gaskets
19	Fire Brick
2	1' x 1' Ceiling Tile (Thick)
20	Drywall & Compound
21	Insulation Inside of Vault Door
22	Floor Tile Beneath 12" x 12" Floor Tile
23	Mastic Beneath 1st Layer of Floor Tiles
24	Lab Counter Tops, Sinks & Tables
25	2' x 4' Lay In Ceiling Panels
26	Material Beneath 12" x 12" Floor Tile
27	Mastic for Material Beneath 12" x 12" Floor Tile
28	4" Gray Vinyl Baseboard
29	4" Gray Vinyl Baseboard Mastic
30	Gray Linoleum
31	Gray Linoleum Mastic
32	2' x 4' Lay in Ceiling Tile
33	Drywall
34	Drywall Tape/Compound
35	Sink Undercoating
36	White w/Gold Countertop Laminate
37	Vinyl Running Track Surface
38	Vinyl Running Track Surface Adhesive
39	Drywall
4	1' x 1' Smooth Ceiling Tile (Thin)
40	Drywall Joint Compound
41	Fire doors
42	4" Black Vinyl Baseboard

43	4" Black Vinyl Baseboard Adhesive
44	12" X 12" Gray w/White and Gray Floor Tile
45	12" X 12" Gray w/White and Gray Floor Tile Mastic
46	12" X 12" Gray w/Black and White Floor tile
47	12" X 12" Gray w/Black and White Floor tile Mastic
48	12" X 12" Beige w/ Lt Brown Floor Tile
49	12" X 12" Beige w/ Lt Brown Floor Tile Mastic
5.1	12"x12" Light Brown Floor Tile w/White Speckles
5.3	12"x12" Brn/Yellow FT w/ White-Brown Specks
5.4	12" x 12" Brown Floor Tile
5.5	12" x 12" Beige Mix Floor Tile
50	Peg Board
51	Peg Board Adhesive
52	Chalk Boards
53	Marker Board Adhesive
54	Duct Vibration Absorber
55	Gray Carpet Adhesive
56	Green/Orange/Yellow Carpet Adhesive.
57	Purple Carpet Adhesive
58	Gray and Blue Carpet Adhesive
59	Blue w/White Carpet Adhesive
60	Vault Door Insulation
61	12" x 12" tan floor tile with light brown
62	Mastic for 12" x 12" tan floor tile with light brown
63	Green Terrazzo
7.1	Linoleum
7.2	Linoleum
8.2	12"x12" White/Yellow FT w/Brown Specks Mastic
8.4	12" x 12" Brown Floor Tile Mastic
8.5	12" x 12" Beige Mix Floor Tile Mastic
9.1	9" x 9" Brown Floor Tile Mastic
B	Water Tank Insulation
K	Aircell Pipe Insulation
L	Hard Joint Compound on Aircell Pipe Insulation

The following areas were deemed to be inaccessible:

12	Ceramic Tile Mortar
14.1	Common Brick Mortar
16	Insulation Beneath Boiler Shells
21	Insulation Inside of Vault Door
22	Floor Tile Beneath 12" x 12" Floor Tile
23	Mastic Beneath 1st Layer of Floor Tiles
26	Material Beneath 12" x 12" Floor Tile
27	Mastic for Material Beneath 12" x 12" Floor Tile
29	4" Gray Vinyl Baseboard Mastic
31	Gray Linoleum Mastic
41	Fire doors

43	4" Black Vinyl Baseboard Adhesive
45	12" X 12" Gray w/White and Gray Floor Tile Mastic
47	12" X 12" Gray w/Black and White Floor tile Mastic
49	12" X 12" Beige w/ Lt Brown Floor Tile Mastic
51	Peg Board Adhesive
53	Marker Board Adhesive
55	Gray Carpet Adhesive
56	Green/Orange/Yellow Carpet Adhesive.
57	Purple Carpet Adhesive
58	Gray and Blue Carpet Adhesive
59	Blue w/White Carpet Adhesive
6.2	9" x 9" Brown/Black/Red/Green Mix Floor Tile
60	Vault Door Insulation
62	Mastic for 12" x 12" tan floor tile with light brown
8.2	12"x12" White/Yellow FT w/Brown Specks Mastic
8.3	12" x 12" Brown Floor Tile Mastic
8.4	12" x 12" Brown Floor Tile Mastic
8.5	12" x 12" Beige Mix Floor Tile Mastic
9.1	9" x 9" Brown Floor Tile Mastic
9.2	9"x9"Brown/Black/Red/Green Mix Floor Tile Mastic
9.3	9" x 9" Yellow & Green Floor Tile Mastic

Materials were also listed as "assumed" if they were in good condition and sampling was not conducted to avoid damage.

This reinspection was conducted by Marcus Tsilimos, IDPH License # 100-11460. The Management Plan was updated by Stephen Diblik, IDPH License # 100-05171. Inspector and Management Planner Licenses are included in Appendix B.

III. METHODOLOGY

Tasks performed on-site included the following:

1. Review current management plan, identify HA(s) and extract appropriate information.
2. Examine and verify abatement records.
3. Touch and visually and physically reinspect and reassess the condition of all friable known or assumed ACBM.
4. Touch and visually and physically reinspect all non-friable known or assumed ACBM to determine whether these materials have become friable since the last inspection or periodic surveillance.
5. Identify any condition changes that may affect Hazard Ranking of known ACBM or Assumed ACBM, as well as any HA(s) that have become friable since the last reinspection.
6. Collect bulk samples from each newly discovered friable HA or previously assumed and submit for laboratory analysis.
7. Tabulate reinspection findings and submit for management planner review and recommendations with appropriate response actions based on the AHERA Damage Category of the ACBM.
8. Submit reinspection findings and management planner recommendations to the LEA within thirty (30) days for inclusion into the management plan.

IV. ABATEMENT HISTORY

The information collected from the existing management plan and inspection report(s) and from interviews with the school official revealed that the following asbestos abatement was conducted at the school since the previous Three year Reinspection.

Abatement Dates:

V. REASSESSMENTS AND RECOMMENDATIONS

The reassessments and recommendations are summarized in Tables I and II on the following pages. Detailed Hazard Assessment Sheets and Drawings and Photos (if applicable) are included in Appendix A.

VI. CONCLUSIONS

The Noble Street Charter - Chicago Bulls College Building 4040 Three-Year reinspection has been completed and response actions have been recommended for both friable and non-friable materials. A timely execution of the response actions recommended will enable the LEA and the Designated Person(s) to effectively manage the existing ACBM.

This three-year reinspection report should be inspected in the current Management plan at the CPS Central Office, and one (1) copy should be kept at the school for use when planning any renovation and/or demolition activities in areas where ACBM has been identified. Also, periodic surveillance documentation and any summary reports from any response actions that are executed at the school should be used to update the Management Plan.

Table I
Inspector's Reinspection Findings

Chicago Public Schools

School Noble Street Charter - Chicago Bulls College Unit 26661 Building ID 4040

Address 2040 W. Adams Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
30	Gray Linoleum	1,200	SF	Room 315	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
31	Gray Linoleum Mastic	1,200	SF	Room 315	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
32	2' x 4' Lay in Ceiling Tile	1,050	SF	Rooms 102, 115, and Engineer's Office	ASSUMED	MISC	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
33	Drywall	320	SF	Tank Room	ASSUMED	MISC	Y	NONE	0		Yes	Any remaining friable ACBM or friable suspect ACBM		LOW
34	Drywall Tape/Compound	268	LF	Tank Room	ASSUMED	MISC	Y	NONE	0		Yes	Any remaining friable ACBM or friable suspect ACBM		LOW
35	Sink Undercoating	32	SF	Room 115, 202, 203, 306	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
36	White w/Gold Countertop Laminate	30	SF	Room 203	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
37	Vinyl Running Track Surface	1,902	SF	2nd floor above Gym	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
38	Vinyl Running Track Surface Adhesive	1,902	SF	2nd floor above Gym	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
39	Drywall	34,000	SF	Electric Vault, Girl's Basement Washroom, Teachers Lounge, 207, 3rd Fl Hall, 302, 303, 307, 310, 311, 313A	ASSUMED	MISC	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
4	1' x 1' Smooth Ceiling Tile (Thin)	300	SF	Room 013A	ASSUMED	MISC	N	NONE	0		Yes	Any remaining friable ACBM or friable suspect ACBM		LOW
40	Drywall Joint Compound	3,400	SF	Electric Vault, Girl's Basement Washroom, Teachers Lounge, 207, 3rd Fl Hall, 302, 303, 307, 310, 311, 313A	ASSUMED	MISC	Y	NONE	0		No	ACBM with the potential for damage		LOW
41	Fire doors	224	SF	Boiler Room, Kitchen, Gym and Exterior Doors	ASSUMED	TSI	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
42	4" Black Vinyl Baseboard	722	LF	Basement Hall, 1st Floor Boys Washroom, 2nd	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW

Chicago Public Schools

School Noble Street Charter - Chicago Bulls College Unit 26661 Building ID 4040

Address 2040 W. Adams Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				Floor Girls Washroom, 3rd Floor Hall, 3rd Floor Boys Washroom, Rooms 2 16, 201, 202, 203, 204, 300A, 300T, 302, 303, 313A.										
43	4" Black Vinyl Baseboard Adhesive	722	LF	Basement Hall, 1st Floor Boys Washroom, 2nd Floor Girls Washroom, 3rd Floor Hall, 3rd Floor Boys Washroom, Rooms 2 16, 201, 202, 203, 204, 300A, 300T, 302, 303, 313A.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
44	12" X 12" Gray w/White and Gray Floor Tile	3,072	SF	Rooms 300A, 305, 310, 311, 216, 215, 211, 208, 205, 206, 201, 111	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
45	12" X 12" Gray w/White and Gray Floor Tile Mastic	3,072	SF	Rooms 300A, 305, 310, 311, 216, 215, 211, 208, 205, 206, 201, and 111	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
46	12" X 12" Gray w/Black and White Floor tile	624	SF	102	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
47	12" X 12" Gray w/Black and White Floor tile Mastic	624	SF	102	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
48	12" X 12" Beige w/ Lt Brown Floor Tile	616	SF	Lunchroom	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
49	12" X 12" Beige w/ Lt Brown Floor Tile Mastic	616	SF	Lunchroom	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
5.1	12"x12" Light Brown Floor Tile w/White Speckles	1,100	SF	Classrooms 203, 211	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
5.2	12"x12" White/Yellow Floor Tile w/Brown Speckles	315	SF	Room 101A (Gym Office), Adjacent Hall and Coaches Office	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
5.3	12"x12" Brn/Yellow FT w/ White-Brown Specks	800	SF	Teacher's Lunch Room	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
5.4	12" x 12" Brown Floor Tile	40	SF	Engineer's Storage	ASSUMED	MISC	N	None						Low

Chicago Public Schools

School Noble Street Charter - Chicago Bulls College Unit 26661 Building ID 4040

Address 2040 W. Adams Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
5.5	12" x 12" Beige Mix Floor Tile	20,000	SF	Library, Storage Room Basement, Rooms 008,011,013,111,112,116,203,207,209,210,213,214,300,301,304-307,313,318	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
50	Peg Board	33	SF	Girl's Basement Washroom and Library	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
51	Peg Board Adhesive	33	SF	Girl's Basement Washroom and Library	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
52	Chalk Boards	4,720	SF	Basement Lab, Industrial Arts, Rooms: 103-106,111-113,A&B,205-211,214-216,300-305,307,312-315 Library,307,313A	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
53	Marker Board Adhesive	240	SF	Library, 307, 313A	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
54	Duct Vibration Absorber	4	LF	Room 011	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
55	Gray Carpet Adhesive	800	SF	Teachers Lounge on 1st and 209	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
56	Green/Orange/Yellow Carpet Adhesive.	768	SF	Room 108 and Principal's Office	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
57	Purple Carpet Adhesive	384	SF	Room 109	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
58	Gray and Blue Carpet Adhesive	936	SF	Rooms 112, 210, 212, 214	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
59	Blue w/White Carpet Adhesive	836	SF	Rooms 104, 204	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
6.1	9" x 9" Brown Floor Tile	112	SF	Room 109	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
6.2	9" x 9" Brown/Black/Red/Green Mix Floor Tile	430	SF	Rooms 004A & 004B	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
6.3	9"x9" Yellow & Green Floor Tiles in a Checkerboard	4,420	SF	Lunch Room	CHR	MISC	N	LOC	10		No	ACBM with the potential for damage		LOW
60	Vault Door Insulation	28	SF	Main Office (109)	ASSUMED	TSI	Y	NONE	0		Yes	Any remaining friable ACBM or friable suspect ACBM		LOW

Chicago Public Schools

School Noble Street Charter - Chicago Bulls College Unit 26661 Building ID 4040

Address 2040 W. Adams Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
61	12" x 12" tan floor tile with light brown	2,000	SF	Rooms 006, 006B and 008	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
62	Mastic for 12" x 12" tan floor tile with light brown	2,000	SF	Rooms 006, 006B, and 008	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
63	Green Terrazzo	4,000	SF	Stairwells and washroom adjacent to 315	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
7.1	Linoleum			Gym	ASSUMED	MISC								
7.2	Linoleum			Basement NW, NE Stairway	ASSUMED	MISC								
8.1	12"x12"Lt Brown Floor Tile w/White Specks Mastic	1,100	SF	Classrooms 203, 211	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
8.2	12"x12" White/Yellow FT w/Brown Specks Mastic	426	SF	Room 101A Gym Office, Adjacent Hall and Coach Office	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
8.3	12" x 12" Brown Floor Tile Mastic	900	SF	014	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
8.4	12" x 12" Brown Floor Tile Mastic	40	SF	Engineer's Storage Hallway	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
8.5	12" x 12" Beige Mix Floor Tile Mastic	20,000	SF	Bsmt. Clsrms, Found. Library, 102-104, 109, 111, 112, 115, 116, 203-207, 209-215, 301, 302, 304, 307, 308, 312-314	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
9.1	9" x 9" Brown Floor Tile Mastic	112	SF	109	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
9.2	9"x9" Brown/Black/Red/Green Mix Floor Tile Mastic	430	SF	Rooms 004A & 004B	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
9.3	9" x 9" Yellow & Green Floor Tile Mastic	4,420	SF	Lunch Room & Kitchen	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
A	Fiberglass Boiler Insulation			Boiler Room	NOT_TESTED									
B	Water Tank Insulation	100	SF	Boiler Room	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
C	Tank Insulation	125	SF	Tank Room	CHR	TSI	Y	NONE	0		Yes	Any remaining friable ACBM or friable suspect ACBM		LOW
D	Water Meter Packing			Sprinkler Room - Abated 1996	ABATED	MISC								
E	Preformed Pipe Insulation	550	LF	Basement, Boiler Room, Lunchroom,	CHR	TSI	Y	NONE	0		No	ACBM with potential for significant damage		LOW

Chicago Public Schools

School Noble Street Charter - Chicago Bulls College Unit 26661 Building ID 4040

Address 2040 W. Adams Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				Air Chamber, Elect. Room, Room 4A										
F	Preformed Pipe Joint Insulation	56	SF	Basement, Boiler Room, Lunchroom, Air Chamber, Elect. Room, Room 4A	CHR	TSI	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
G	Cardboard Pipe Insulation	1,830	LF	Engineers's Office, Storage, Pump Rooms, Fan rooms, Lunchroom, 011, Boiler Room, 002, Through Out, 015	CHR	TSI	Y	NONE	0		Yes	Damaged or significantly damaged friable thermal system insulating ACBM		LOW
H	Hard Joint Cmpd. On Cardboard Pipe Insulation	250	SF	Engineers's Office, Storage, Pump Rooms, Fan rooms, Lunchroom, 011, Boiler Room, 002, Through Out	CHR	TSI	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
J.1	Hard Joint Cmpd.- Orig. Fiberglass Pipe Insulation	270	SF	Engineers's Office, Storage, Pump Rooms, Fan rooms, Lunchroom, 011, Boiler Room, 002, Through Out	CHR	TSI	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
J.2	Hard Joint Cmpd.- New Fiberglass Pipe Insulation			Throughout Facility	NOT_TEST ED									
K	Aircell Pipe Insulation	300	LF	Basement, 2nd Floor, 1st fl washroom, Attic	ASSUMED	TSI	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
L	Hard Joint Compound on Aircell Pipe Insulation	70	SF	Basement & Second Floor, 1st fl washroom, Attic	ASSUMED	TSI	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
M	Duct Insulation	50	SF	Kitchen	CHR	TSI	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW

Chicago Public Schools

School Noble Street Charter - Chicago Bulls College Unit 26661 Building ID 4040
Address 2040 W. Adams Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

Reinspection Date 4/26/2013
Inspector Name Marcus Tsilimos
100-11460 5/15/2013
Inspector's IDPH License Number / Expiration Date

Inspector's Comments

HA Number:	Inspector Comments:
06	Not Observed, Gone or Underneath
06A	
1	
10	
11.1	
11.2	
12	
13 A	Not Observed, Gone.
13 B	Not Observed, Gone.
13 C	Not Observed, Gone.
13 D	Not Observed, Gone.
13 E	Not Observed, Gone.
14.1	
14.2	
14.3	
15.1	
15.2	
15.3	
16	
17	
18	
19	
2	
20	

Chicago Public Schools

School Noble Street Charter - Chicago Bulls College **Unit** 26661 **Building ID** 4040
Address 2040 W. Adams **Region** 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
21	
22	
23	
24	
25	
26	
27	
28	
29	
3	Not Observed, has been removed.
30	
31	
32	
33	
34	
35	
36	
37	
38	
39	
4	
40	
41	
42	
43	
44	
45	
46	
47	

Chicago Public Schools

School Noble Street Charter - Chicago Bulls College **Unit** 26661 **Building ID** 4040
Address 2040 W. Adams **Region** 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
48	
49	
5.1	
5.2	
5.3	
5.4	Not Observed.
5.5	
50	
51	
52	
53	
54	
55	
56	
57	
58	
59	
6.1	
6.2	
6.3	
60	
61	
62	
63	
7.1	Not Observed.
7.2	Not Observed.
8.1	
8.2	
8.3	

Chicago Public Schools

School Noble Street Charter - Chicago Bulls College **Unit** 26661 **Building ID** 4040

Address 2040 W. Adams **Region** 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
8.4	
8.5	
9.1	
9.2	
9.3	
A	Fiberglass not a suspect material.
B	
C	
D	
E	
F	
G	
H	
J.1	
J.2	Fiberglass not a suspect material.
K	
L	
M	

Table II

Management Planner's Review

Chicago Public Schools

School Noble Street Charter -
Chicago Bulls College

Unit 26661

Building ID 4040

Address 2040 W. Adams

Chicago, IL, 60612

Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
06	12"x12" Off-White Speckled Floor Tile			washroom #202	Chrysotile	MISC	No				
06A	12"x12" Off-White Speckled Floor Tile Adhesive	27,000	SF	1890 Building: 1st, 2nd, & 3rd Floor Corridors, Women's Washroom, Third Floor Teacher's Lounge and Classrooms; 006, 006B, 008, 013A, 103, 107, 110, 111, 112, 201, 207, 209, 210, 212, 213, 214, 307, 309, 311, 312, 313, and 314	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
1	Hard Coat Plaster	30,000	SF	Throughout Facility	Assumed	SURFACE	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Operations and Maintenance
10	Canvas Wall Covering	8,000	SF	Hallway by Rooms 210, 104, 105, Men's WR by 210, Teacher's WR by 206, 214-216	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
11.1	Exterior Window Glaze - Not AHERA			Throughout Facility	Undefined	MISC					
11.2	Interior Window Glaze	50	LF	Throughout Facility	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Operations and Maintenance
12	Ceramic Tile Mortar	200	SF	Gym, 1st Floor S. Central, 2nd Floor N Central, 2nd Floor W. Central	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
13 A	Blue/Maroon Mix Carpet Mastic			Rooms 013,107,108,201,202,208,210,211,212, 213,214,216,300A,302,303,308-311	Assumed	MISC					
13 B	Green Mix Carpet Mastic			Foundation Library, 111, 112, 114, 123A	Assumed	MISC					
13 C	Dark Blue Carpet Mastic	2,016	SF	Rooms 103, 104, 105, 204 B	Assumed	MISC	No		SF		
13 D	Blue Carpet Mastic			113A	Assumed	MISC	No				
13 E	Blue/Purple Mix Carpet Mastic	1,000	SF	109	Assumed	MISC	No		SF		
14.1	Common Brick Mortar	20,000	SF	Throughout Facility	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
14.2	Brown Brick Mortar - not AHERA			Exterior of Building	Assumed	MISC					
14.3	New Brown Brick Mortar - not AHERA			Exterior of Building	Assumed	MISC					
15.1	Common Brick	200,000	SF	Throughout Facility	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
15.2	Original Brown Brick - not AHERA			Exterior of Building	Assumed	MISC					
15.3	New Brown Brick - not AHERA			Exterior of Building	Assumed	MISC					
16	Insulation Beneath Boiler Shells	100	SF	Boiler Room	Assumed	TSI	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
17	Boiler Gaskets - Front Door	25	LF	Boiler #1	Chrysotile	MISC	Yes	0	LF	7 Any remaining friable ACBM or friable suspect ACBM	Operations and Maintenance
18	Boiler Gaskets	25	LF	Boiler #2	Assumed	MISC	Yes	0	LF	7 Any remaining friable ACBM or friable	Operations and Maintenance

Chicago Public Schools

School Noble Street Charter -
Chicago Bulls College

Unit 26661

Building ID 4040

Address 2040 W. Adams

Chicago, IL, 60612

Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
										suspect ACBM	
19	Fire Brick	100	SF	Incinerator	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
2	1' x 1' Ceiling Tile (Thick)	2,000	SF	Lunch Room	Assumed	MISC	No	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Operations and Maintenance
20	Drywall & Compound	5,000	SF	Rooms 004, 204 and 203	Assumed	MISC	No	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Operations and Maintenance
21	Insulation Inside of Vault Door	28	SF	Near room 314	Assumed	TSI	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Operations and Maintenance
22	Floor Tile Beneath 12" x 12" Floor Tile	800	SF	Room 112	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
23	Mastic Beneath 1st Layer of Floor Tiles	800	SF	Room 112	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
24	Lab Counter Tops, Sinks & Tables	500	SF	Rooms 214, 215, 313B,313C, 315, Basement Lab	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
25	2' x 4' Lay In Ceiling Panels	800	SF	315	Assumed	MISC	No	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Operations and Maintenance
26	Material Beneath 12" x 12" Floor Tile	1,000	SF	Rooms 313B & 314	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
27	Mastic for Material Beneath 12" x 12" Floor Tile	1,000	SF	Rooms 314 & 313B	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
28	4" Gray Vinyl Baseboard	190	LF	Room 315, 311, 310	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Operations and Maintenance
29	4" Gray Vinyl Baseboard Mastic	190	LF	Room 315, 311, 310	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Operations and Maintenance
3	2' x 4' Lay In Ceiling Panels - REMOVED			Basement Boy's Locker Room		MISC					
30	Gray Linoleum	1,200	SF	Room 315	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
31	Gray Linoleum Mastic	1,200	SF	Room 315	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
32	2' x 4' Lay in Ceiling Tile	1,050	SF	Rooms 102, 115, and Engineer's Office	Assumed	MISC	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Operations and Maintenance
33	Drywall	320	SF	Tank Room	Assumed	MISC	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Operations and Maintenance
34	Drywall Tape/Compound	268	LF	Tank Room	Assumed	MISC	Yes	0	LF	7 Any remaining friable ACBM or friable suspect ACBM	Operations and Maintenance
35	Sink Undercoating	32	SF	Room 115, 202, 203, 306	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
36	White w/Gold Countertop Laminate	30	SF	Room 203	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
37	Vinyl Running Track Surface	1,902	SF	2nd floor above Gym	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
38	Vinyl Running Track Surface Adhesive	1,902	SF	2nd floor above Gym	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
39	Drywall	34,000	SF	Electric Vault, Girl's Basement Washroom, Teachers Lounge, 207, 3rd FI Hall, 302, 303, 307, 310, 311, 313A	Assumed	MISC	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Operations and Maintenance

Chicago Public Schools

School Noble Street Charter -
Chicago Bulls College

Unit 26661

Building ID 4040

Address 2040 W. Adams

Chicago, IL, 60612

Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
4	1' x 1' Smooth Ceiling Tile (Thin)	300	SF	Room 013A	Assumed	MISC	No	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Operations and Maintenance
40	Drywall Joint Compound	3,400	SF	Electric Vault, Girl's Basement Washroom, Teachers Lounge, 207, 3rd FI Hall, 302, 303, 307, 310, 311, 313A	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
41	Fire doors	224	SF	Boiler Room, Kitchen, Gym and Exterior Doors	Assumed	TSI	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Operations and Maintenance
42	4" Black Vinyl Baseboard	722	LF	Basement Hall, 1st Floor Boys Washroom, 2nd Floor Girls Washroom, 3rd Floor Hall, 3rd Floor Boys Washroom, Rooms 216, 201, 202, 203, 204, 300A, 300T, 302, 303, 313A.	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Operations and Maintenance
43	4" Black Vinyl Baseboard Adhesive	722	LF	Basement Hall, 1st Floor Boys Washroom, 2nd Floor Girls Washroom, 3rd Floor Hall, 3rd Floor Boys Washroom, Rooms 216, 201, 202, 203, 204, 300A, 300T, 302, 303, 313A.	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Operations and Maintenance
44	12" X 12" Gray w/White and Gray Floor Tile	3,072	SF	Rooms 300A, 305, 310, 311, 216, 215, 211, 208, 205, 206, 201, 111	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
45	12" X 12" Gray w/White and Gray Floor Tile Mastic	3,072	SF	Rooms 300A, 305, 310, 311, 216, 215, 211, 208, 205, 206, 201, and 111	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
46	12" X 12" Gray w/Black and White Floor tile	624	SF	102	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
47	12" X 12" Gray w/Black and White Floor tile Mastic	624	SF	102	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
48	12" X 12" Beige w/ Lt Brown Floor Tile	616	SF	Lunchroom	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
49	12" X 12" Beige w/ Lt Brown Floor Tile Mastic	616	SF	Lunchroom	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
5.1	12"x12" Light Brown Floor Tile w/White Speckles	1,100	SF	Classrooms 203, 211	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
5.2	12"x12" White/Yellow Floor Tile w/Brown Speckles	315	SF	Room 101A (Gym Office), Adjacent Hall and Coaches Office	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
5.3	12"x12" Brn/Yellow FT w/ White-Brown Specks	800	SF	Teacher's Lunch Room	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
5.4	12" x 12" Brown Floor Tile	40	SF	Engineer's Storage	Assumed	MISC	No		SF		
5.5	12" x 12" Beige Mix Floor Tile	20,000	SF	Library, Storage Room Basement, Rooms 008, 011, 013, 111, 112, 116, 203, 207, 209, 210, 213, 214, 300, 301, 304-307, 313, 318	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
50	Peg Board	33	SF	Girl's Basement Washroom and Library	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance

Chicago Public Schools

School Noble Street Charter -
Chicago Bulls College

Unit 26661

Building ID 4040

Address 2040 W. Adams

Chicago, IL, 60612

Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
51	Peg Board Adhesive	33	SF	Girl's Basement Washroom and Library	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
52	Chalk Boards	4,720	SF	Basement Lab, Industrial Arts, Rooms: 103-106,111-113,A&B,205-211,214-216,300-305,307,312-315 Library,307,313A	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
53	Marker Board Adhesive	240	SF	Library, 307, 313A	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
54	Duct Vibration Absorber	4	LF	Room 011	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Operations and Maintenance
55	Gray Carpet Adhesive	800	SF	Teachers Lounge on 1st and 209	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
56	Green/Orange/Yellow Carpet Adhesive.	768	SF	Room 108 and Principal's Office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
57	Purple Carpet Adhesive	384	SF	Room 109	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
58	Gray and Blue Carpet Adhesive	936	SF	Rooms 112, 210, 212, 214	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
59	Blue w/White Carpet Adhesive	836	SF	Rooms 104, 204	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
6.1	9" x 9" Brown Floor Tile	112	SF	Room 109	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
6.2	9" x 9" Brown/Black/Red/Green Mix Floor Tile	430	SF	Rooms 004A & 004B	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
6.3	9"x9" Yellow & Green Floor Tiles in a Checkerboard	4,420	SF	Lunch Room	Chrysotile	MISC	No	10	SF	6 ACBM with the potential for damage	Operations and Maintenance
60	Vault Door Insulation	28	SF	Main Office (109)	Assumed	TSI	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Operations and Maintenance
61	12" x 12" tan floor tile with light brown	2,000	SF	Rooms 006, 006B and 008	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
62	Mastic for 12" x 12" tan floor tile with light brown	2,000	SF	Rooms 006, 006B, and 008	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
63	Green Terrazzo	4,000	SF	Stairwells and washroom adjacent to 315	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
7.1	Linoleum			Gym	Assumed	MISC					
7.2	Linoleum			Basement NW, NE Stairway	Assumed	MISC					
8.1	12"x12"Lt Brown Floor Tile w/White Specks Mastic	1,100	SF	Classrooms 203, 211	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
8.2	12"x12" White/Yellow FT w/Brown Specks Mastic	426	SF	Room 101A Gym Office, Adjacent Hall and Coach Office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
8.3	12" x 12" Brown Floor Tile Mastic	900	SF	014	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
8.4	12" x 12" Brown Floor Tile Mastic	40	SF	Engineer's Storage Hallway	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
8.5	12" x 12" Beige Mix Floor Tile Mastic	20,000	SF	Bsmt. Clrms,Found. Library,102-104,109,111,112,115,116,203-207,209-215,301,302,304,307,308,312-314	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
9.1	9" x 9" Brown Floor Tile Mastic	112	SF	109	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
9.2	9"x9"Brown/Black/Red/Green Mix Floor Tile Mastic	430	SF	Rooms 004A & 004B	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance

Chicago Public Schools

School Noble Street Charter -
Chicago Bulls College

Unit 26661

Building ID 4040

Address 2040 W. Adams

Chicago, IL, 60612

Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
9.3	9" x 9" Yellow & Green Floor Tile Mastic	4,420	SF	Lunch Room & Kitchen	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
A	Fiberglass Boiler Insulation			Boiler Room	Not Tested						
B	Water Tank Insulation	100	SF	Boiler Room	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
C	Tank Insulation	125	SF	Tank Room	Chrysotile	TSI	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Operations and Maintenance
D	Water Meter Packing			Sprinkler Room - Abated 1996	Abated	MISC					
E	Preformed Pipe Insulation	550	LF	Basement, Boiler Room, Lunchroom, Air Chamber, Elect. Room, Room 4A	Chrysotile	TSI	Yes	0	LF	5 ACBM with potential for significant damage	Operations and Maintenance
F	Preformed Pipe Joint Insulation	56	SF	Basement, Boiler Room, Lunchroom, Air Chamber, Elect. Room, Room 4A	Chrysotile	TSI	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Operations and Maintenance
G	Cardboard Pipe Insulation	1,830	LF	Engineers's Office, Storage, Pump Rooms, Fan rooms, Lunchroom, 011, Boiler Room, 002, Through Out, 015	Chrysotile	TSI	Yes	0	LF	1 Damaged or significantly damaged friable thermal system insulating ACBM	Repair
H	Hard Joint Cmpd. On Cardboard Pipe Insulation	250	SF	Engineers's Office, Storage, Pump Rooms, Fan rooms, Lunchroom, 011, Boiler Room, 002, Through Out	Chrysotile	TSI	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Operations and Maintenance
J.1	Hard Joint Cmpd.- Orig. Fiberglass Pipe Insulation	270	SF	Engineers's Office, Storage, Pump Rooms, Fan rooms, Lunchroom, 011, Boiler Room, 002, Through Out	Chrysotile	TSI	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Operations and Maintenance
J.2	Hard Joint Cmpd.- New Fiberglass Pipe Insulation			Throughout Facility	Not Tested						
K	Aircell Pipe Insulation	300	LF	Basement, 2nd Floor, 1st fl washroom, Attic	Assumed	TSI	Yes	0	LF	7 Any remaining friable ACBM or friable suspect ACBM	Operations and Maintenance
L	Hard Joint Compound on Aircell Pipe Insulation	70	SF	Basement & Second Floor, 1st fl washroom, Attic	Assumed	TSI	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Operations and Maintenance
M	Duct Insulation	50	SF	Kitchen	Chrysotile	TSI	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Operations and Maintenance

Chicago Public Schools

School Noble Street Charter -
Chicago Bulls College

Unit 26661

Building ID 4040

Address 2040 W. Adams

Chicago, IL, 60612

Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

Review Date	5/3/2013
Manager Planner Name	Stephen Diblik
100-05171	5/15/2013
Manager IDPH License No/Expiration	

HA Number	Management Comments
06	
06A	
1	
10	
11.1	
11.2	
12	
13 A	
13 B	
13 C	
13 D	
13 E	
14.1	

Chicago Public Schools

School Noble Street Charter -
Chicago Bulls College

Unit 26661

Building ID 4040

Address 2040 W. Adams

Chicago, IL, 60612

Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
14.2	
14.3	
15.1	
15.2	
15.3	
16	
17	
18	
19	
2	
20	
21	
22	
23	
24	
25	
26	
27	
28	
29	
3	
30	
31	
32	
33	
34	

Chicago Public Schools

School Noble Street Charter -
Chicago Bulls College

Unit 26661

Building ID 4040

Address 2040 W. Adams

Chicago, IL, 60612

Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
35	
36	
37	
38	
39	
4	
40	
41	
42	
43	
44	
45	
46	
47	
48	
49	
5.1	
5.2	
5.3	
5.4	
5.5	
50	
51	
52	
53	
54	

Chicago Public Schools

School Noble Street Charter -
Chicago Bulls College

Unit 26661

Building ID 4040

Address 2040 W. Adams

Chicago, IL, 60612

Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
55	
56	
57	
58	
59	
6.1	
6.2	
6.3	
60	
61	
62	
63	
7.1	
7.2	
8.1	
8.2	
8.3	
8.4	
8.5	
9.1	
9.2	
9.3	
A	
B	
C	
D	

Chicago Public Schools

School Noble Street Charter -
Chicago Bulls College

Unit 26661

Building ID 4040

Address 2040 W. Adams

Chicago, IL, 60612

Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
E	
F	
G	Repair damaged material and continue O&M
H	
J.1	
J.2	
K	
L	
M	

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26661** BUIDLING ID: **4040**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcus Tsilimos**
SCHOOL NAME: **Noble Street Charter - Chicago Bulls College** INSPECTION DATE: **4/26/2013**
ADDRESS: **2040 W. Adams** IDPH LICENSE NO: **100-11460**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **06**
MATERIAL DESCRIPTION: **12"x12" Off-White Speckled Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **washroom #202**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not Observed, Gone or Underneath**

Inspector's Signature:



Date: **04/26/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26661** BUIDLING ID: **4040**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**
SCHOOL NAME: **Noble Street Charter - Chicago Bulls College** REVIEW DATE: **5/3/2013**
ADDRESS: **2040 W. Adams** IDPH LICENSE NO: **100-11460**

HOMOGENEOUS AREA: **06**

MATERIAL DESCRIPTION: **12"x12" Off-White Speckled Floor Tile**

MATERIAL LOCATION: **washroom #202**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____

Stephen Diblik

Date: 05/03/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26661** BUIDLING ID: **4040**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcus Tsilimos**
SCHOOL NAME: **Noble Street Charter - Chicago Bulls College** INSPECTION DATE: **4/26/2013**
ADDRESS: **2040 W. Adams** IDPH LICENSE NO: **100-11460**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **06A**
MATERIAL DESCRIPTION: **12"x12" Off-White Speckled Floor Tile Adhesive**
HISTORICAL AHERA DAMAGE CATEGORY **6**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **1890 Building: 1st, 2nd, & 3rd Floor Corridors, Women's Washroom, Third Floor Teacher's Lounge and Classrooms; 006, 006B, 008, 013A, 103, 107, 110, 111, 112, 201, 207, 209, 210, 212, 213, 214, 307, 309, 311, 312, 313, and 314**

MATERIAL QUANTITY: **27000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 04/26/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26661** BUIDLING ID: **4040**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**
SCHOOL NAME: **Noble Street Charter - Chicago Bulls College** REVIEW DATE: **5/3/2013**
ADDRESS: **2040 W. Adams** IDPH LICENSE NO: **100-11460**

HOMOGENEOUS AREA: **06A**
MATERIAL DESCRIPTION: **12"x12" Off-White Speckled Floor Tile Adhesive**
MATERIAL LOCATION: **1890 Building: 1st, 2nd, & 3rd Floor Corridors, Women's Washroom, Third Floor Teacher's Lounge and Classrooms; 006, 006B, 008, 013A, 103, 107, 110, 111, 112, 201, 207, 209 ,210, 212, 213, 214, 307, 309, 311, 312, 313, and 314**
MATERIAL QUANTITY: **27000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____

Stephen Diblik

Date: **05/03/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26661** BUIDLING ID: **4040**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcus Tsilimos**
SCHOOL NAME: **Noble Street Charter - Chicago Bulls College** INSPECTION DATE: **4/26/2013**
ADDRESS: **2040 W. Adams** IDPH LICENSE NO: **100-11460**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **1**
MATERIAL DESCRIPTION: **Hard Coat Plaster**
HISTORICAL AHERA DAMAGE CATEGORY **7**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Throughout Facility**
MATERIAL QUANTITY: **30000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____



Date: 04/26/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26661** BUIDLING ID: **4040**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**
SCHOOL NAME: **Noble Street Charter - Chicago Bulls College** REVIEW DATE: **5/3/2013**
ADDRESS: **2040 W. Adams** IDPH LICENSE NO: **100-11460**

HOMOGENEOUS AREA: **1**
MATERIAL DESCRIPTION: **Hard Coat Plaster**
MATERIAL LOCATION: **Throughout Facility**
MATERIAL QUANTITY: **30000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____

Stephen Diblik

Date: **05/03/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26661** BUIDLING ID: **4040**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcus Tsilimos**
SCHOOL NAME: **Noble Street Charter - Chicago Bulls College** INSPECTION DATE: **4/26/2013**
ADDRESS: **2040 W. Adams** IDPH LICENSE NO: **100-11460**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **10**
MATERIAL DESCRIPTION: **Canvas Wall Covering**
HISTORICAL AHERA DAMAGE CATEGORY **6**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Hallway by Rooms 210, 104, 105, Men's WR by 210, Teacher's WR by 206, 214-216**

MATERIAL QUANTITY: **8000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 04/26/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26661** BUIDLING ID: **4040**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**
SCHOOL NAME: **Noble Street Charter - Chicago Bulls College** REVIEW DATE: **5/3/2013**
ADDRESS: **2040 W. Adams** IDPH LICENSE NO: **100-11460**

HOMOGENEOUS AREA: **10**
MATERIAL DESCRIPTION: **Canvas Wall Covering**
MATERIAL LOCATION: **Hallway by Rooms 210, 104, 105, Men's WR by 210, Teacher's WR by 206, 214-216**
MATERIAL QUANTITY: **8000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____

Stephen Diblik

Date: **05/03/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26661** BUIDLING ID: **4040**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcus Tsilimos**
SCHOOL NAME: **Noble Street Charter - Chicago Bulls College** INSPECTION DATE: **4/26/2013**
ADDRESS: **2040 W. Adams** IDPH LICENSE NO: **100-11460**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **11.1**
MATERIAL DESCRIPTION: **Exterior Window Glaze - Not AHERA**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Undefined** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout Facility**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **04/26/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26661** BUIDLING ID: **4040**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**
SCHOOL NAME: **Noble Street Charter - Chicago Bulls College** REVIEW DATE: **5/3/2013**
ADDRESS: **2040 W. Adams** IDPH LICENSE NO: **100-11460**

HOMOGENEOUS AREA: **11.1**

MATERIAL DESCRIPTION: **Exterior Window Glaze - Not AHERA**

MATERIAL LOCATION: **Throughout Facility**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____

Stephen Diblik

Date: 05/03/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26661** BUIDLING ID: **4040**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcus Tsilimos**
SCHOOL NAME: **Noble Street Charter - Chicago Bulls College** INSPECTION DATE: **4/26/2013**
ADDRESS: **2040 W. Adams** IDPH LICENSE NO: **100-11460**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **11.2**
MATERIAL DESCRIPTION: **Interior Window Glaze**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Throughout Facility**

MATERIAL QUANTITY: **50**

MATERIAL UNITS: **LF**

DAMAGE QUANTITY:

DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature:



Date: **04/26/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26661** BUIDLING ID: **4040**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**
SCHOOL NAME: **Noble Street Charter - Chicago Bulls College** REVIEW DATE: **5/3/2013**
ADDRESS: **2040 W. Adams** IDPH LICENSE NO: **100-11460**

HOMOGENEOUS AREA: **11.2**
MATERIAL DESCRIPTION: **Interior Window Glaze**
MATERIAL LOCATION: **Throughout Facility**
MATERIAL QUANTITY: **50** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____

Stephen Diblik

Date: **05/03/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26661** BUIDLING ID: **4040**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcus Tsilimos**
SCHOOL NAME: **Noble Street Charter - Chicago Bulls College** INSPECTION DATE: **4/26/2013**
ADDRESS: **2040 W. Adams** IDPH LICENSE NO: **100-11460**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **12**
MATERIAL DESCRIPTION: **Ceramic Tile Mortar**
HISTORICAL AHERA DAMAGE CATEGORY **6**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Gym, 1st Floor S. Central, 2nd Floor N Central, 2nd Floor W. Central**
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____



Date: 04/26/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26661** BUIDLING ID: **4040**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**
SCHOOL NAME: **Noble Street Charter - Chicago Bulls College** REVIEW DATE: **5/3/2013**
ADDRESS: **2040 W. Adams** IDPH LICENSE NO: **100-11460**

HOMOGENEOUS AREA: **12**
MATERIAL DESCRIPTION: **Ceramic Tile Mortar**
MATERIAL LOCATION: **Gym, 1st Floor S. Central, 2nd Floor N Central, 2nd Floor W. Central**
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____

Stephen Diblik

Date: 05/03/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26661** BUIDLING ID: **4040**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcus Tsilimos**
SCHOOL NAME: **Noble Street Charter - Chicago Bulls College** INSPECTION DATE: **4/26/2013**
ADDRESS: **2040 W. Adams** IDPH LICENSE NO: **100-11460**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **13 A**
MATERIAL DESCRIPTION: **Blue/Maroon Mix Carpet Mastic**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Rooms 013,107,108,201,202,208,210,211,212,213,214,216,300A,302,303,308-311**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Not Observed, Gone.**

Inspector's Signature:



Date: **04/26/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26661** BUIDLING ID: **4040**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**
SCHOOL NAME: **Noble Street Charter - Chicago Bulls College** REVIEW DATE: **5/3/2013**
ADDRESS: **2040 W. Adams** IDPH LICENSE NO: **100-11460**

HOMOGENEOUS AREA: **13 A**
MATERIAL DESCRIPTION: **Blue/Maroon Mix Carpet Mastic**
MATERIAL LOCATION: **Rooms 013,107,108,201,202,208,210,211,212,213,214,216,300A,302,303,308-311**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____

Stephen Diblik

Date: **05/03/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26661** BUIDLING ID: **4040**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcus Tsilimos**
SCHOOL NAME: **Noble Street Charter - Chicago Bulls College** INSPECTION DATE: **4/26/2013**
ADDRESS: **2040 W. Adams** IDPH LICENSE NO: **100-11460**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **13 B**
MATERIAL DESCRIPTION: **Green Mix Carpet Mastic**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Foundation Library, 111, 112, 114, 123A**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not Observed, Gone.**

Inspector's Signature:



Date: **04/26/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26661** BUIDLING ID: **4040**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**
SCHOOL NAME: **Noble Street Charter - Chicago Bulls College** REVIEW DATE: **5/3/2013**
ADDRESS: **2040 W. Adams** IDPH LICENSE NO: **100-11460**

HOMOGENEOUS AREA: **13 B**
MATERIAL DESCRIPTION: **Green Mix Carpet Mastic**
MATERIAL LOCATION: **Foundation Library, 111, 112, 114, 123A**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:  Date: **05/03/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26661** BUIDLING ID: **4040**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcus Tsilimos**
SCHOOL NAME: **Noble Street Charter - Chicago Bulls College** INSPECTION DATE: **4/26/2013**
ADDRESS: **2040 W. Adams** IDPH LICENSE NO: **100-11460**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **13 C**
MATERIAL DESCRIPTION: **Dark Blue Carpet Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **Low**

MATERIAL LOCATION: **Rooms 103, 104, 105, 204 B**

MATERIAL QUANTITY: **2016**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS: **Not Observed, Gone.**

Inspector's Signature:



Date: **04/26/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26661** BUIDLING ID: **4040**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**
SCHOOL NAME: **Noble Street Charter - Chicago Bulls College** REVIEW DATE: **5/3/2013**
ADDRESS: **2040 W. Adams** IDPH LICENSE NO: **100-11460**

HOMOGENEOUS AREA: **13 C**
MATERIAL DESCRIPTION: **Dark Blue Carpet Mastic**
MATERIAL LOCATION: **Rooms 103, 104, 105, 204 B**
MATERIAL QUANTITY: **2016** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature:

Stephen Diblik

Date: **05/03/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26661** BUIDLING ID: **4040**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcus Tsilimos**
SCHOOL NAME: **Noble Street Charter - Chicago Bulls College** INSPECTION DATE: **4/26/2013**
ADDRESS: **2040 W. Adams** IDPH LICENSE NO: **100-11460**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **13 D**
MATERIAL DESCRIPTION: **Blue Carpet Mastic**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **113A**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not Observed, Gone.**

Inspector's Signature:



Date: **04/26/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26661** BUIDLING ID: **4040**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**
SCHOOL NAME: **Noble Street Charter - Chicago Bulls College** REVIEW DATE: **5/3/2013**
ADDRESS: **2040 W. Adams** IDPH LICENSE NO: **100-11460**

HOMOGENEOUS AREA: **13 D**
MATERIAL DESCRIPTION: **Blue Carpet Mastic**
MATERIAL LOCATION: **113A**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____

Stephen Diblik

Date: **05/03/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26661** BUIDLING ID: **4040**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcus Tsilimos**
SCHOOL NAME: **Noble Street Charter - Chicago Bulls College** INSPECTION DATE: **4/26/2013**
ADDRESS: **2040 W. Adams** IDPH LICENSE NO: **100-11460**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **13 E**
MATERIAL DESCRIPTION: **Blue/Purple Mix Carpet Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **Low**

MATERIAL LOCATION: **109**

MATERIAL QUANTITY: **1000**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS: **Not Observed, Gone.**

Inspector's Signature:



Date: **04/26/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26661** BUIDLING ID: **4040**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**
SCHOOL NAME: **Noble Street Charter - Chicago Bulls College** REVIEW DATE: **5/3/2013**
ADDRESS: **2040 W. Adams** IDPH LICENSE NO: **100-11460**

HOMOGENEOUS AREA: **13 E**
MATERIAL DESCRIPTION: **Blue/Purple Mix Carpet Mastic**
MATERIAL LOCATION: **109**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____

Stephen Diblik

Date: **05/03/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26661** BUIDLING ID: **4040**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcus Tsilimos**
SCHOOL NAME: **Noble Street Charter - Chicago Bulls College** INSPECTION DATE: **4/26/2013**
ADDRESS: **2040 W. Adams** IDPH LICENSE NO: **100-11460**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **14.1**
MATERIAL DESCRIPTION: **Common Brick Mortar**
HISTORICAL AHERA DAMAGE CATEGORY **6**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Throughout Facility**
MATERIAL QUANTITY: **20000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **04/26/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26661** BUIDLING ID: **4040**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**
SCHOOL NAME: **Noble Street Charter - Chicago Bulls College** REVIEW DATE: **5/3/2013**
ADDRESS: **2040 W. Adams** IDPH LICENSE NO: **100-11460**

HOMOGENEOUS AREA: **14.1**
MATERIAL DESCRIPTION: **Common Brick Mortar**
MATERIAL LOCATION: **Throughout Facility**
MATERIAL QUANTITY: **20000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____

Stephen Diblik

Date: **05/03/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26661** BUIDLING ID: **4040**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcus Tsilimos**
SCHOOL NAME: **Noble Street Charter - Chicago Bulls College** INSPECTION DATE: **4/26/2013**
ADDRESS: **2040 W. Adams** IDPH LICENSE NO: **100-11460**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **14.2**
MATERIAL DESCRIPTION: **Brown Brick Mortar - not AHERA**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Exterior of Building**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **04/26/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26661** BUILDING ID: **4040**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**
SCHOOL NAME: **Noble Street Charter - Chicago Bulls College** REVIEW DATE: **5/3/2013**
ADDRESS: **2040 W. Adams** IDPH LICENSE NO: **100-11460**

HOMOGENEOUS AREA: **14.2**
MATERIAL DESCRIPTION: **Brown Brick Mortar - not AHERA**
MATERIAL LOCATION: **Exterior of Building**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____

Stephen Diblik

Date: 05/03/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26661** BUIDLING ID: **4040**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcus Tsilimos**
SCHOOL NAME: **Noble Street Charter - Chicago Bulls College** INSPECTION DATE: **4/26/2013**
ADDRESS: **2040 W. Adams** IDPH LICENSE NO: **100-11460**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **14.3**
MATERIAL DESCRIPTION: **New Brown Brick Mortar - not AHERA**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Exterior of Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **04/26/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26661** BUILDING ID: **4040**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**
SCHOOL NAME: **Noble Street Charter - Chicago Bulls College** REVIEW DATE: **5/3/2013**
ADDRESS: **2040 W. Adams** IDPH LICENSE NO: **100-11460**

HOMOGENEOUS AREA: **14.3**
MATERIAL DESCRIPTION: **New Brown Brick Mortar - not AHERA**
MATERIAL LOCATION: **Exterior of Building**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____

Stephen Diblik

Date: **05/03/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26661** BUIDLING ID: **4040**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcus Tsilimos**
SCHOOL NAME: **Noble Street Charter - Chicago Bulls College** INSPECTION DATE: **4/26/2013**
ADDRESS: **2040 W. Adams** IDPH LICENSE NO: **100-11460**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **15.1**
MATERIAL DESCRIPTION: **Common Brick**
HISTORICAL AHERA DAMAGE CATEGORY **6**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Throughout Facility**
MATERIAL QUANTITY: **200000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____



Date: 04/26/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26661** BUIDLING ID: **4040**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**
SCHOOL NAME: **Noble Street Charter - Chicago Bulls College** REVIEW DATE: **5/3/2013**
ADDRESS: **2040 W. Adams** IDPH LICENSE NO: **100-11460**

HOMOGENEOUS AREA: **15.1**
MATERIAL DESCRIPTION: **Common Brick**
MATERIAL LOCATION: **Throughout Facility**
MATERIAL QUANTITY: **200000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:

Stephen Diblik

Date: **05/03/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26661** BUIDLING ID: **4040**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcus Tsilimos**
SCHOOL NAME: **Noble Street Charter - Chicago Bulls College** INSPECTION DATE: **4/26/2013**
ADDRESS: **2040 W. Adams** IDPH LICENSE NO: **100-11460**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **15.2**
MATERIAL DESCRIPTION: **Original Brown Brick - not AHERA**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Exterior of Building**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **04/26/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26661** BUILDING ID: **4040**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**
SCHOOL NAME: **Noble Street Charter - Chicago Bulls College** REVIEW DATE: **5/3/2013**
ADDRESS: **2040 W. Adams** IDPH LICENSE NO: **100-11460**

HOMOGENEOUS AREA: **15.2**

MATERIAL DESCRIPTION: **Original Brown Brick - not AHERA**

MATERIAL LOCATION: **Exterior of Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____

Stephen Diblik

Date: **05/03/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26661** BUIDLING ID: **4040**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcus Tsilimos**
SCHOOL NAME: **Noble Street Charter - Chicago Bulls College** INSPECTION DATE: **4/26/2013**
ADDRESS: **2040 W. Adams** IDPH LICENSE NO: **100-11460**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **15.3**
MATERIAL DESCRIPTION: **New Brown Brick - not AHERA**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Exterior of Building**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **04/26/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26661** BUIDLING ID: **4040**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**
SCHOOL NAME: **Noble Street Charter - Chicago Bulls College** REVIEW DATE: **5/3/2013**
ADDRESS: **2040 W. Adams** IDPH LICENSE NO: **100-11460**

HOMOGENEOUS AREA: **15.3**
MATERIAL DESCRIPTION: **New Brown Brick - not AHERA**
MATERIAL LOCATION: **Exterior of Building**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____

Stephen Diblik

Date: 05/03/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26661** BUIDLING ID: **4040**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcus Tsilimos**
SCHOOL NAME: **Noble Street Charter - Chicago Bulls College** INSPECTION DATE: **4/26/2013**
ADDRESS: **2040 W. Adams** IDPH LICENSE NO: **100-11460**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **16**
MATERIAL DESCRIPTION: **Insulation Beneath Boiler Shells**
HISTORICAL AHERA DAMAGE CATEGORY **6**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Boiler Room**
MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **04/26/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26661** BUIDLING ID: **4040**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**
SCHOOL NAME: **Noble Street Charter - Chicago Bulls College** REVIEW DATE: **5/3/2013**
ADDRESS: **2040 W. Adams** IDPH LICENSE NO: **100-11460**

HOMOGENEOUS AREA: **16**
MATERIAL DESCRIPTION: **Insulation Beneath Boiler Shells**
MATERIAL LOCATION: **Boiler Room**
MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____

Stephen Diblik

Date: **05/03/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26661** BUIDLING ID: **4040**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcus Tsilimos**
SCHOOL NAME: **Noble Street Charter - Chicago Bulls College** INSPECTION DATE: **4/26/2013**
ADDRESS: **2040 W. Adams** IDPH LICENSE NO: **100-11460**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **17**
MATERIAL DESCRIPTION: **Boiler Gaskets - Front Door**
HISTORICAL AHERA DAMAGE CATEGORY **7 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Boiler #1**
MATERIAL QUANTITY: **25** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: DAMAGE UNITS: **LF**
COMMENTS:

Inspector's Signature: _____



Date: 04/26/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26661** BUIDLING ID: **4040**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**
SCHOOL NAME: **Noble Street Charter - Chicago Bulls College** REVIEW DATE: **5/3/2013**
ADDRESS: **2040 W. Adams** IDPH LICENSE NO: **100-11460**

HOMOGENEOUS AREA: **17**
MATERIAL DESCRIPTION: **Boiler Gaskets - Front Door**
MATERIAL LOCATION: **Boiler #1**
MATERIAL QUANTITY: **25** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____

Stephen Diblik

Date: **05/03/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26661** BUIDLING ID: **4040**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcus Tsilimos**
SCHOOL NAME: **Noble Street Charter - Chicago Bulls College** INSPECTION DATE: **4/26/2013**
ADDRESS: **2040 W. Adams** IDPH LICENSE NO: **100-11460**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **18**
MATERIAL DESCRIPTION: **Boiler Gaskets**
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Boiler #2**

MATERIAL QUANTITY: **25**

MATERIAL UNITS: **LF**

DAMAGE QUANTITY:

DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: _____



Date: 04/26/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26661** BUIDLING ID: **4040**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**
SCHOOL NAME: **Noble Street Charter - Chicago Bulls College** REVIEW DATE: **5/3/2013**
ADDRESS: **2040 W. Adams** IDPH LICENSE NO: **100-11460**

HOMOGENEOUS AREA: **18**
MATERIAL DESCRIPTION: **Boiler Gaskets**
MATERIAL LOCATION: **Boiler #2**
MATERIAL QUANTITY: **25** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____

Stephen Diblik

Date: 05/03/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26661** BUIDLING ID: **4040**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcus Tsilimos**
SCHOOL NAME: **Noble Street Charter - Chicago Bulls College** INSPECTION DATE: **4/26/2013**
ADDRESS: **2040 W. Adams** IDPH LICENSE NO: **100-11460**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **19**
MATERIAL DESCRIPTION: **Fire Brick**
HISTORICAL AHERA DAMAGE CATEGORY **6**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Incinerator**
MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **04/26/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26661** BUIDLING ID: **4040**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**
SCHOOL NAME: **Noble Street Charter - Chicago Bulls College** REVIEW DATE: **5/3/2013**
ADDRESS: **2040 W. Adams** IDPH LICENSE NO: **100-11460**

HOMOGENEOUS AREA: **19**
MATERIAL DESCRIPTION: **Fire Brick**
MATERIAL LOCATION: **Incinerator**
MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:

Stephen Diblik

Date: **05/03/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26661** BUIDLING ID: **4040**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcus Tsilimos**
SCHOOL NAME: **Noble Street Charter - Chicago Bulls College** INSPECTION DATE: **4/26/2013**
ADDRESS: **2040 W. Adams** IDPH LICENSE NO: **100-11460**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **2**
MATERIAL DESCRIPTION: **1' x 1' Ceiling Tile (Thick)**
HISTORICAL AHERA DAMAGE CATEGORY **7**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Lunch Room**
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **04/26/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26661** BUIDLING ID: **4040**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**
SCHOOL NAME: **Noble Street Charter - Chicago Bulls College** REVIEW DATE: **5/3/2013**
ADDRESS: **2040 W. Adams** IDPH LICENSE NO: **100-11460**

HOMOGENEOUS AREA: **2**
MATERIAL DESCRIPTION: **1' x 1' Ceiling Tile (Thick)**
MATERIAL LOCATION: **Lunch Room**
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____

Stephen Diblik

Date: **05/03/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26661** BUIDLING ID: **4040**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcus Tsilimos**
SCHOOL NAME: **Noble Street Charter - Chicago Bulls College** INSPECTION DATE: **4/26/2013**
ADDRESS: **2040 W. Adams** IDPH LICENSE NO: **100-11460**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **20**
MATERIAL DESCRIPTION: **Drywall & Compound**
HISTORICAL AHERA DAMAGE CATEGORY **7**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms 004, 204 and 203**
MATERIAL QUANTITY: **5000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____



Date: 04/26/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26661** BUIDLING ID: **4040**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**
SCHOOL NAME: **Noble Street Charter - Chicago Bulls College** REVIEW DATE: **5/3/2013**
ADDRESS: **2040 W. Adams** IDPH LICENSE NO: **100-11460**

HOMOGENEOUS AREA: **20**
MATERIAL DESCRIPTION: **Drywall & Compound**
MATERIAL LOCATION: **Rooms 004, 204 and 203**
MATERIAL QUANTITY: **5000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____

Stephen Diblik

Date: **05/03/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26661** BUIDLING ID: **4040**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcus Tsilimos**
SCHOOL NAME: **Noble Street Charter - Chicago Bulls College** INSPECTION DATE: **4/26/2013**
ADDRESS: **2040 W. Adams** IDPH LICENSE NO: **100-11460**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **21**
MATERIAL DESCRIPTION: **Insulation Inside of Vault Door**
HISTORICAL AHERA DAMAGE CATEGORY **7 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Near room 314**

MATERIAL QUANTITY: **28**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **04/26/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26661** BUIDLING ID: **4040**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**
SCHOOL NAME: **Noble Street Charter - Chicago Bulls College** REVIEW DATE: **5/3/2013**
ADDRESS: **2040 W. Adams** IDPH LICENSE NO: **100-11460**

HOMOGENEOUS AREA: **21**
MATERIAL DESCRIPTION: **Insulation Inside of Vault Door**
MATERIAL LOCATION: **Near room 314**
MATERIAL QUANTITY: **28** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____

Stephen Diblik

Date: **05/03/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26661** BUIDLING ID: **4040**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcus Tsilimos**
SCHOOL NAME: **Noble Street Charter - Chicago Bulls College** INSPECTION DATE: **4/26/2013**
ADDRESS: **2040 W. Adams** IDPH LICENSE NO: **100-11460**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **22**
MATERIAL DESCRIPTION: **Floor Tile Beneath 12" x 12" Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 112**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **04/26/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26661** BUIDLING ID: **4040**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**
SCHOOL NAME: **Noble Street Charter - Chicago Bulls College** REVIEW DATE: **5/3/2013**
ADDRESS: **2040 W. Adams** IDPH LICENSE NO: **100-11460**

HOMOGENEOUS AREA: **22**
MATERIAL DESCRIPTION: **Floor Tile Beneath 12" x 12" Floor Tile**
MATERIAL LOCATION: **Room 112**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____

Stephen Diblik

Date: **05/03/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26661** BUIDLING ID: **4040**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcus Tsilimos**
SCHOOL NAME: **Noble Street Charter - Chicago Bulls College** INSPECTION DATE: **4/26/2013**
ADDRESS: **2040 W. Adams** IDPH LICENSE NO: **100-11460**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **23**
MATERIAL DESCRIPTION: **Mastic Beneath 1st Layer of Floor Tiles**
HISTORICAL AHERA DAMAGE CATEGORY **6**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 112**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **04/26/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26661** BUIDLING ID: **4040**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**
SCHOOL NAME: **Noble Street Charter - Chicago Bulls College** REVIEW DATE: **5/3/2013**
ADDRESS: **2040 W. Adams** IDPH LICENSE NO: **100-11460**

HOMOGENEOUS AREA: **23**
MATERIAL DESCRIPTION: **Mastic Beneath 1st Layer of Floor Tiles**
MATERIAL LOCATION: **Room 112**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:

Stephen Diblik

Date: **05/03/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26661** BUIDLING ID: **4040**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcus Tsilimos**
SCHOOL NAME: **Noble Street Charter - Chicago Bulls College** INSPECTION DATE: **4/26/2013**
ADDRESS: **2040 W. Adams** IDPH LICENSE NO: **100-11460**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **24**
MATERIAL DESCRIPTION: **Lab Counter Tops, Sinks & Tables**
HISTORICAL AHERA DAMAGE CATEGORY **6**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms 214, 215, 313B,313C, 315, Basement Lab**
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **04/26/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26661** BUIDLING ID: **4040**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**
SCHOOL NAME: **Noble Street Charter - Chicago Bulls College** REVIEW DATE: **5/3/2013**
ADDRESS: **2040 W. Adams** IDPH LICENSE NO: **100-11460**

HOMOGENEOUS AREA: **24**
MATERIAL DESCRIPTION: **Lab Counter Tops, Sinks & Tables**
MATERIAL LOCATION: **Rooms 214, 215, 313B,313C, 315, Basement Lab**
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____

Stephen Diblik

Date: **05/03/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26661** BUIDLING ID: **4040**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcus Tsilimos**
SCHOOL NAME: **Noble Street Charter - Chicago Bulls College** INSPECTION DATE: **4/26/2013**
ADDRESS: **2040 W. Adams** IDPH LICENSE NO: **100-11460**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **25**
MATERIAL DESCRIPTION: **2' x 4' Lay In Ceiling Panels**
HISTORICAL AHERA DAMAGE CATEGORY **7**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **315**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 04/26/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26661** BUIDLING ID: **4040**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**
SCHOOL NAME: **Noble Street Charter - Chicago Bulls College** REVIEW DATE: **5/3/2013**
ADDRESS: **2040 W. Adams** IDPH LICENSE NO: **100-11460**

HOMOGENEOUS AREA: **25**
MATERIAL DESCRIPTION: **2' x 4' Lay In Ceiling Panels**
MATERIAL LOCATION: **315**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____

Stephen Diblik

Date: **05/03/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26661** BUIDLING ID: **4040**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcus Tsilimos**
SCHOOL NAME: **Noble Street Charter - Chicago Bulls College** INSPECTION DATE: **4/26/2013**
ADDRESS: **2040 W. Adams** IDPH LICENSE NO: **100-11460**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **26**
MATERIAL DESCRIPTION: **Material Beneath 12" x 12" Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms 313B & 314**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **04/26/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26661** BUILDING ID: **4040**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**
SCHOOL NAME: **Noble Street Charter - Chicago Bulls College** REVIEW DATE: **5/3/2013**
ADDRESS: **2040 W. Adams** IDPH LICENSE NO: **100-11460**

HOMOGENEOUS AREA: **26**
MATERIAL DESCRIPTION: **Material Beneath 12" x 12" Floor Tile**
MATERIAL LOCATION: **Rooms 313B & 314**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____

Stephen Diblik

Date: **05/03/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26661** BUIDLING ID: **4040**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcus Tsilimos**
SCHOOL NAME: **Noble Street Charter - Chicago Bulls College** INSPECTION DATE: **4/26/2013**
ADDRESS: **2040 W. Adams** IDPH LICENSE NO: **100-11460**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **27**
MATERIAL DESCRIPTION: **Mastic for Material Beneath 12" x 12" Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms 314 & 313B**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **04/26/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26661** BUIDLING ID: **4040**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**
SCHOOL NAME: **Noble Street Charter - Chicago Bulls College** REVIEW DATE: **5/3/2013**
ADDRESS: **2040 W. Adams** IDPH LICENSE NO: **100-11460**

HOMOGENEOUS AREA: **27**
MATERIAL DESCRIPTION: **Mastic for Material Beneath 12" x 12" Floor Tile**
MATERIAL LOCATION: **Rooms 314 & 313B**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:

Stephen Diblik

Date: **05/03/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26661** BUIDLING ID: **4040**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcus Tsilimos**
SCHOOL NAME: **Noble Street Charter - Chicago Bulls College** INSPECTION DATE: **4/26/2013**
ADDRESS: **2040 W. Adams** IDPH LICENSE NO: **100-11460**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **28**
MATERIAL DESCRIPTION: **4" Gray Vinyl Baseboard**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Room 315, 311, 310**

MATERIAL QUANTITY: **190**

MATERIAL UNITS: **LF**

DAMAGE QUANTITY:

DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature:



Date: **04/26/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26661** BUIDLING ID: **4040**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**
SCHOOL NAME: **Noble Street Charter - Chicago Bulls College** REVIEW DATE: **5/3/2013**
ADDRESS: **2040 W. Adams** IDPH LICENSE NO: **100-11460**

HOMOGENEOUS AREA: **28**
MATERIAL DESCRIPTION: **4" Gray Vinyl Baseboard**
MATERIAL LOCATION: **Room 315, 311, 310**
MATERIAL QUANTITY: **190** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____

Stephen Diblik

Date: **05/03/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26661** BUIDLING ID: **4040**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcus Tsilimos**
SCHOOL NAME: **Noble Street Charter - Chicago Bulls College** INSPECTION DATE: **4/26/2013**
ADDRESS: **2040 W. Adams** IDPH LICENSE NO: **100-11460**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **29**
MATERIAL DESCRIPTION: **4" Gray Vinyl Baseboard Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Room 315, 311, 310**

MATERIAL QUANTITY: **190**

MATERIAL UNITS: **LF**

DAMAGE QUANTITY:

DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature:



Date: **04/26/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26661** BUIDLING ID: **4040**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**
SCHOOL NAME: **Noble Street Charter - Chicago Bulls College** REVIEW DATE: **5/3/2013**
ADDRESS: **2040 W. Adams** IDPH LICENSE NO: **100-11460**

HOMOGENEOUS AREA: **29**
MATERIAL DESCRIPTION: **4" Gray Vinyl Baseboard Mastic**
MATERIAL LOCATION: **Room 315, 311, 310**
MATERIAL QUANTITY: **190** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____

Stephen Diblik

Date: **05/03/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26661** BUIDLING ID: **4040**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcus Tsilimos**
SCHOOL NAME: **Noble Street Charter - Chicago Bulls College** INSPECTION DATE: **4/26/2013**
ADDRESS: **2040 W. Adams** IDPH LICENSE NO: **100-11460**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **3**
MATERIAL DESCRIPTION: **2' x 4' Lay In Ceiling Panels - REMOVED**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Basement Boy's Locker Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not Observed, has been removed.**

Inspector's Signature:



Date: **04/26/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26661** BUIDLING ID: **4040**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**
SCHOOL NAME: **Noble Street Charter - Chicago Bulls College** REVIEW DATE: **5/3/2013**
ADDRESS: **2040 W. Adams** IDPH LICENSE NO: **100-11460**

HOMOGENEOUS AREA: **3**

MATERIAL DESCRIPTION: **2' x 4' Lay In Ceiling Panels - REMOVED**

MATERIAL LOCATION: **Basement Boy's Locker Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____

Stephen Diblik

Date: 05/03/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26661** BUIDLING ID: **4040**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcus Tsilimos**
SCHOOL NAME: **Noble Street Charter - Chicago Bulls College** INSPECTION DATE: **4/26/2013**
ADDRESS: **2040 W. Adams** IDPH LICENSE NO: **100-11460**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **30**
MATERIAL DESCRIPTION: **Gray Linoleum**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Room 315**

MATERIAL QUANTITY: **1200**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **04/26/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26661** BUIDLING ID: **4040**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**
SCHOOL NAME: **Noble Street Charter - Chicago Bulls College** REVIEW DATE: **5/3/2013**
ADDRESS: **2040 W. Adams** IDPH LICENSE NO: **100-11460**

HOMOGENEOUS AREA: **30**
MATERIAL DESCRIPTION: **Gray Linoleum**
MATERIAL LOCATION: **Room 315**
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____

Stephen Diblik

Date: **05/03/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26661** BUIDLING ID: **4040**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcus Tsilimos**
SCHOOL NAME: **Noble Street Charter - Chicago Bulls College** INSPECTION DATE: **4/26/2013**
ADDRESS: **2040 W. Adams** IDPH LICENSE NO: **100-11460**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **31**
MATERIAL DESCRIPTION: **Gray Linoleum Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Room 315**

MATERIAL QUANTITY: **1200**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 04/26/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26661** BUIDLING ID: **4040**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**
SCHOOL NAME: **Noble Street Charter - Chicago Bulls College** REVIEW DATE: **5/3/2013**
ADDRESS: **2040 W. Adams** IDPH LICENSE NO: **100-11460**

HOMOGENEOUS AREA: **31**
MATERIAL DESCRIPTION: **Gray Linoleum Mastic**
MATERIAL LOCATION: **Room 315**
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____

Stephen Diblik

Date: **05/03/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26661** BUIDLING ID: **4040**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcus Tsilimos**
SCHOOL NAME: **Noble Street Charter - Chicago Bulls College** INSPECTION DATE: **4/26/2013**
ADDRESS: **2040 W. Adams** IDPH LICENSE NO: **100-11460**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **32**
MATERIAL DESCRIPTION: **2' x 4' Lay in Ceiling Tile**
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Rooms 102, 115, and Engineer's Office**

MATERIAL QUANTITY: **1050**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 04/26/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26661** BUIDLING ID: **4040**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**
SCHOOL NAME: **Noble Street Charter - Chicago Bulls College** REVIEW DATE: **5/3/2013**
ADDRESS: **2040 W. Adams** IDPH LICENSE NO: **100-11460**

HOMOGENEOUS AREA: **32**
MATERIAL DESCRIPTION: **2' x 4' Lay in Ceiling Tile**
MATERIAL LOCATION: **Rooms 102, 115, and Engineer's Office**
MATERIAL QUANTITY: **1050** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____

Stephen Diblik

Date: **05/03/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26661** BUIDLING ID: **4040**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcus Tsilimos**
SCHOOL NAME: **Noble Street Charter - Chicago Bulls College** INSPECTION DATE: **4/26/2013**
ADDRESS: **2040 W. Adams** IDPH LICENSE NO: **100-11460**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **33**
MATERIAL DESCRIPTION: **Drywall**
HISTORICAL AHERA DAMAGE CATEGORY **7 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Tank Room**

MATERIAL QUANTITY: **320**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **04/26/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26661** BUIDLING ID: **4040**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**
SCHOOL NAME: **Noble Street Charter - Chicago Bulls College** REVIEW DATE: **5/3/2013**
ADDRESS: **2040 W. Adams** IDPH LICENSE NO: **100-11460**

HOMOGENEOUS AREA: **33**
MATERIAL DESCRIPTION: **Drywall**
MATERIAL LOCATION: **Tank Room**
MATERIAL QUANTITY: **320** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____

Stephen Diblik

Date: **05/03/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26661** BUIDLING ID: **4040**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcus Tsilimos**
SCHOOL NAME: **Noble Street Charter - Chicago Bulls College** INSPECTION DATE: **4/26/2013**
ADDRESS: **2040 W. Adams** IDPH LICENSE NO: **100-11460**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **34**
MATERIAL DESCRIPTION: **Drywall Tape/Compound**
HISTORICAL AHERA DAMAGE CATEGORY **7 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Tank Room**

MATERIAL QUANTITY: **268**

MATERIAL UNITS: **LF**

DAMAGE QUANTITY:

DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature:



Date: **04/26/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26661** BUIDLING ID: **4040**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**
SCHOOL NAME: **Noble Street Charter - Chicago Bulls College** REVIEW DATE: **5/3/2013**
ADDRESS: **2040 W. Adams** IDPH LICENSE NO: **100-11460**

HOMOGENEOUS AREA: **34**
MATERIAL DESCRIPTION: **Drywall Tape/Compound**
MATERIAL LOCATION: **Tank Room**
MATERIAL QUANTITY: **268** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____

Stephen Diblik

Date: **05/03/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26661** BUIDLING ID: **4040**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcus Tsilimos**
SCHOOL NAME: **Noble Street Charter - Chicago Bulls College** INSPECTION DATE: **4/26/2013**
ADDRESS: **2040 W. Adams** IDPH LICENSE NO: **100-11460**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **35**
MATERIAL DESCRIPTION: **Sink Undercoating**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Room 115, 202, 203, 306**

MATERIAL QUANTITY: **32**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 04/26/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26661** BUIDLING ID: **4040**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**
SCHOOL NAME: **Noble Street Charter - Chicago Bulls College** REVIEW DATE: **5/3/2013**
ADDRESS: **2040 W. Adams** IDPH LICENSE NO: **100-11460**

HOMOGENEOUS AREA: **35**
MATERIAL DESCRIPTION: **Sink Undercoating**
MATERIAL LOCATION: **Room 115, 202, 203, 306**
MATERIAL QUANTITY: **32** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____

Stephen Diblik

Date: **05/03/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26661** BUIDLING ID: **4040**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcus Tsilimos**
SCHOOL NAME: **Noble Street Charter - Chicago Bulls College** INSPECTION DATE: **4/26/2013**
ADDRESS: **2040 W. Adams** IDPH LICENSE NO: **100-11460**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **36**
MATERIAL DESCRIPTION: **White w/Gold Countertop Laminate**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Room 203**

MATERIAL QUANTITY: **30**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **04/26/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26661** BUIDLING ID: **4040**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**
SCHOOL NAME: **Noble Street Charter - Chicago Bulls College** REVIEW DATE: **5/3/2013**
ADDRESS: **2040 W. Adams** IDPH LICENSE NO: **100-11460**

HOMOGENEOUS AREA: **36**
MATERIAL DESCRIPTION: **White w/Gold Countertop Laminate**
MATERIAL LOCATION: **Room 203**
MATERIAL QUANTITY: **30** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature:

Stephen Diblik

Date: **05/03/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26661** BUIDLING ID: **4040**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcus Tsilimos**
SCHOOL NAME: **Noble Street Charter - Chicago Bulls College** INSPECTION DATE: **4/26/2013**
ADDRESS: **2040 W. Adams** IDPH LICENSE NO: **100-11460**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **37**
MATERIAL DESCRIPTION: **Vinyl Running Track Surface**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **2nd floor above Gym**

MATERIAL QUANTITY: **1902**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 04/26/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26661** BUIDLING ID: **4040**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**
SCHOOL NAME: **Noble Street Charter - Chicago Bulls College** REVIEW DATE: **5/3/2013**
ADDRESS: **2040 W. Adams** IDPH LICENSE NO: **100-11460**

HOMOGENEOUS AREA: **37**
MATERIAL DESCRIPTION: **Vinyl Running Track Surface**
MATERIAL LOCATION: **2nd floor above Gym**
MATERIAL QUANTITY: **1902** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature:

Stephen Diblik

Date: **05/03/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26661** BUIDLING ID: **4040**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcus Tsilimos**
SCHOOL NAME: **Noble Street Charter - Chicago Bulls College** INSPECTION DATE: **4/26/2013**
ADDRESS: **2040 W. Adams** IDPH LICENSE NO: **100-11460**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **38**
MATERIAL DESCRIPTION: **Vinyl Running Track Surface Adhesive**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **2nd floor above Gym**

MATERIAL QUANTITY: **1902**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **04/26/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26661** BUIDLING ID: **4040**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**
SCHOOL NAME: **Noble Street Charter - Chicago Bulls College** REVIEW DATE: **5/3/2013**
ADDRESS: **2040 W. Adams** IDPH LICENSE NO: **100-11460**

HOMOGENEOUS AREA: **38**
MATERIAL DESCRIPTION: **Vinyl Running Track Surface Adhesive**
MATERIAL LOCATION: **2nd floor above Gym**
MATERIAL QUANTITY: **1902** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature:

Stephen Diblik

Date: **05/03/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26661** BUIDLING ID: **4040**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcus Tsilimos**
SCHOOL NAME: **Noble Street Charter - Chicago Bulls College** INSPECTION DATE: **4/26/2013**
ADDRESS: **2040 W. Adams** IDPH LICENSE NO: **100-11460**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **39**
MATERIAL DESCRIPTION: **Drywall**
HISTORICAL AHERA DAMAGE CATEGORY **7 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Electric Vault, Girl's Basement Washroom, Teachers Lounge, 207, 3rd FI Hall, 302, 303, 307, 310, 311, 313A**

MATERIAL QUANTITY: **34000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 04/26/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26661** BUILDING ID: **4040**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**
SCHOOL NAME: **Noble Street Charter - Chicago Bulls College** REVIEW DATE: **5/3/2013**
ADDRESS: **2040 W. Adams** IDPH LICENSE NO: **100-11460**

HOMOGENEOUS AREA: **39**
MATERIAL DESCRIPTION: **Drywall**
MATERIAL LOCATION: **Electric Vault, Girl's Basement Washroom, Teachers Lounge, 207, 3rd Fl Hall, 302, 303, 307, 310, 311, 313A**
MATERIAL QUANTITY: **34000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____

Stephen Diblik

Date: **05/03/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26661** BUIDLING ID: **4040**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcus Tsilimos**
SCHOOL NAME: **Noble Street Charter - Chicago Bulls College** INSPECTION DATE: **4/26/2013**
ADDRESS: **2040 W. Adams** IDPH LICENSE NO: **100-11460**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **4**
MATERIAL DESCRIPTION: **1' x 1' Smooth Ceiling Tile (Thin)**
HISTORICAL AHERA DAMAGE CATEGORY **7**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 013A**
MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **04/26/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26661** BUIDLING ID: **4040**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**
SCHOOL NAME: **Noble Street Charter - Chicago Bulls College** REVIEW DATE: **5/3/2013**
ADDRESS: **2040 W. Adams** IDPH LICENSE NO: **100-11460**

HOMOGENEOUS AREA: **4**
MATERIAL DESCRIPTION: **1' x 1' Smooth Ceiling Tile (Thin)**
MATERIAL LOCATION: **Room 013A**
MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____

Stephen Diblik

Date: **05/03/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26661** BUIDLING ID: **4040**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcus Tsilimos**
SCHOOL NAME: **Noble Street Charter - Chicago Bulls College** INSPECTION DATE: **4/26/2013**
ADDRESS: **2040 W. Adams** IDPH LICENSE NO: **100-11460**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **40**
MATERIAL DESCRIPTION: **Drywall Joint Compound**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Electric Vault, Girl's Basement Washroom, Teachers Lounge, 207, 3rd FI Hall, 302, 303, 307, 310, 311, 313A**

MATERIAL QUANTITY: **3400** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 04/26/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26661** BUILDING ID: **4040**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**
SCHOOL NAME: **Noble Street Charter - Chicago Bulls College** REVIEW DATE: **5/3/2013**
ADDRESS: **2040 W. Adams** IDPH LICENSE NO: **100-11460**

HOMOGENEOUS AREA: **40**
MATERIAL DESCRIPTION: **Drywall Joint Compound**
MATERIAL LOCATION: **Electric Vault, Girl's Basement Washroom, Teachers Lounge, 207, 3rd Fl Hall, 302, 303, 307, 310, 311, 313A**
MATERIAL QUANTITY: **3400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____

Stephen Diblik

Date: 05/03/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26661** BUIDLING ID: **4040**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcus Tsilimos**
SCHOOL NAME: **Noble Street Charter - Chicago Bulls College** INSPECTION DATE: **4/26/2013**
ADDRESS: **2040 W. Adams** IDPH LICENSE NO: **100-11460**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **41**
MATERIAL DESCRIPTION: **Fire doors**
HISTORICAL AHERA DAMAGE CATEGORY **7 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Boiler Room, Kitchen, Gym and Exterior Doors**

MATERIAL QUANTITY: **224** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 04/26/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26661** BUIDLING ID: **4040**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**
SCHOOL NAME: **Noble Street Charter - Chicago Bulls College** REVIEW DATE: **5/3/2013**
ADDRESS: **2040 W. Adams** IDPH LICENSE NO: **100-11460**

HOMOGENEOUS AREA: **41**
MATERIAL DESCRIPTION: **Fire doors**
MATERIAL LOCATION: **Boiler Room, Kitchen, Gym and Exterior Doors**
MATERIAL QUANTITY: **224** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____

Stephen Diblik

Date: **05/03/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26661** BUIDLING ID: **4040**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcus Tsilimos**
SCHOOL NAME: **Noble Street Charter - Chicago Bulls College** INSPECTION DATE: **4/26/2013**
ADDRESS: **2040 W. Adams** IDPH LICENSE NO: **100-11460**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **42**
MATERIAL DESCRIPTION: **4" Black Vinyl Baseboard**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Basement Hall, 1st Floor Boys Washroom, 2nd Floor Girls Washroom, 3rd Floor Hall, 3rd Floor Boys Washroom, Rooms 216, 201, 202, 203, 204, 300A, 300T, 302, 303, 313A.**

MATERIAL QUANTITY: **722** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: _____



Date: **04/26/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26661** BUIDLING ID: **4040**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**
SCHOOL NAME: **Noble Street Charter - Chicago Bulls College** REVIEW DATE: **5/3/2013**
ADDRESS: **2040 W. Adams** IDPH LICENSE NO: **100-11460**

HOMOGENEOUS AREA: **42**
MATERIAL DESCRIPTION: **4" Black Vinyl Baseboard**
MATERIAL LOCATION: **Basement Hall, 1st Floor Boys Washroom, 2nd Floor Girls Washroom, 3rd Floor Hall, 3rd Floor Boys Washroom, Rooms 216, 201, 202, 203, 204, 300A, 300T, 302, 303, 313A.**
MATERIAL QUANTITY: **722** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____

Stephen Diblik

Date: **05/03/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26661** BUIDLING ID: **4040**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcus Tsilimos**
SCHOOL NAME: **Noble Street Charter - Chicago Bulls College** INSPECTION DATE: **4/26/2013**
ADDRESS: **2040 W. Adams** IDPH LICENSE NO: **100-11460**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **43**
MATERIAL DESCRIPTION: **4" Black Vinyl Baseboard Adhesive**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Basement Hall, 1st Floor Boys Washroom, 2nd Floor Girls Washroom, 3rd Floor Hall, 3rd Floor Boys Washroom, Rooms 216, 201, 202, 203, 204, 300A, 300T, 302, 303, 313A.**

MATERIAL QUANTITY: **722** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature:



Date: **04/26/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26661** BUIDLING ID: **4040**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**
SCHOOL NAME: **Noble Street Charter - Chicago Bulls College** REVIEW DATE: **5/3/2013**
ADDRESS: **2040 W. Adams** IDPH LICENSE NO: **100-11460**

HOMOGENEOUS AREA: **43**
MATERIAL DESCRIPTION: **4" Black Vinyl Baseboard Adhesive**
MATERIAL LOCATION: **Basement Hall, 1st Floor Boys Washroom, 2nd Floor Girls Washroom, 3rd Floor Hall, 3rd Floor Boys Washroom, Rooms 216, 201, 202, 203, 204, 300A, 300T, 302, 303, 313A.**
MATERIAL QUANTITY: **722** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____

Stephen Diblik

Date: 05/03/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26661** BUIDLING ID: **4040**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcus Tsilimos**
SCHOOL NAME: **Noble Street Charter - Chicago Bulls College** INSPECTION DATE: **4/26/2013**
ADDRESS: **2040 W. Adams** IDPH LICENSE NO: **100-11460**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **44**
MATERIAL DESCRIPTION: **12" X 12" Gray w/White and Gray Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Rooms 300A, 305, 310, 311, 216,215,211,208, 205, 206, 201, 111**

MATERIAL QUANTITY: **3072** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 04/26/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26661** BUIDLING ID: **4040**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**
SCHOOL NAME: **Noble Street Charter - Chicago Bulls College** REVIEW DATE: **5/3/2013**
ADDRESS: **2040 W. Adams** IDPH LICENSE NO: **100-11460**

HOMOGENEOUS AREA: **44**
MATERIAL DESCRIPTION: **12" X 12" Gray w/White and Gray Floor Tile**
MATERIAL LOCATION: **Rooms 300A, 305, 310, 311, 216,215,211,208, 205, 206, 201, 111**
MATERIAL QUANTITY: **3072** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____

Stephen Diblik

Date: **05/03/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26661** BUIDLING ID: **4040**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcus Tsilimos**
SCHOOL NAME: **Noble Street Charter - Chicago Bulls College** INSPECTION DATE: **4/26/2013**
ADDRESS: **2040 W. Adams** IDPH LICENSE NO: **100-11460**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **45**
MATERIAL DESCRIPTION: **12" X 12" Gray w/White and Gray Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Rooms 300A, 305, 310, 311, 216, 215, 211, 208, 205, 206, 201, and 111**

MATERIAL QUANTITY: **3072** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 04/26/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26661** BUIDLING ID: **4040**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**
SCHOOL NAME: **Noble Street Charter - Chicago Bulls College** REVIEW DATE: **5/3/2013**
ADDRESS: **2040 W. Adams** IDPH LICENSE NO: **100-11460**

HOMOGENEOUS AREA: **45**
MATERIAL DESCRIPTION: **12" X 12" Gray w/White and Gray Floor Tile Mastic**
MATERIAL LOCATION: **Rooms 300A, 305, 310, 311, 216, 215, 211, 208, 205, 206, 201, and 111**
MATERIAL QUANTITY: **3072** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____

Stephen Diblik

Date: **05/03/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26661** BUIDLING ID: **4040**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcus Tsilimos**
SCHOOL NAME: **Noble Street Charter - Chicago Bulls College** INSPECTION DATE: **4/26/2013**
ADDRESS: **2040 W. Adams** IDPH LICENSE NO: **100-11460**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **46**
MATERIAL DESCRIPTION: **12" X 12" Gray w/Black and White Floor tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Repair Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **102**

MATERIAL QUANTITY: **624**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **04/26/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26661** BUIDLING ID: **4040**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**
SCHOOL NAME: **Noble Street Charter - Chicago Bulls College** REVIEW DATE: **5/3/2013**
ADDRESS: **2040 W. Adams** IDPH LICENSE NO: **100-11460**

HOMOGENEOUS AREA: **46**
MATERIAL DESCRIPTION: **12" X 12" Gray w/Black and White Floor tile**
MATERIAL LOCATION: **102**
MATERIAL QUANTITY: **624** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Repair
Operations and Maintenance**

Comments:

Management Planner's Signature: _____

Stephen Diblik

Date: **05/03/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26661** BUIDLING ID: **4040**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcus Tsilimos**
SCHOOL NAME: **Noble Street Charter - Chicago Bulls College** INSPECTION DATE: **4/26/2013**
ADDRESS: **2040 W. Adams** IDPH LICENSE NO: **100-11460**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **47**
MATERIAL DESCRIPTION: **12" X 12" Gray w/Black and White Floor tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **102**

MATERIAL QUANTITY: **624**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 04/26/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26661** BUIDLING ID: **4040**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**
SCHOOL NAME: **Noble Street Charter - Chicago Bulls College** REVIEW DATE: **5/3/2013**
ADDRESS: **2040 W. Adams** IDPH LICENSE NO: **100-11460**

HOMOGENEOUS AREA: **47**
MATERIAL DESCRIPTION: **12" X 12" Gray w/Black and White Floor tile Mastic**
MATERIAL LOCATION: **102**
MATERIAL QUANTITY: **624** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____

Stephen Diblik

Date: **05/03/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26661** BUIDLING ID: **4040**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcus Tsilimos**
SCHOOL NAME: **Noble Street Charter - Chicago Bulls College** INSPECTION DATE: **4/26/2013**
ADDRESS: **2040 W. Adams** IDPH LICENSE NO: **100-11460**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **48**
MATERIAL DESCRIPTION: **12" X 12" Beige w/ Lt Brown Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Lunchroom**

MATERIAL QUANTITY: **616**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **04/26/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26661** BUIDLING ID: **4040**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**
SCHOOL NAME: **Noble Street Charter - Chicago Bulls College** REVIEW DATE: **5/3/2013**
ADDRESS: **2040 W. Adams** IDPH LICENSE NO: **100-11460**

HOMOGENEOUS AREA: **48**
MATERIAL DESCRIPTION: **12" X 12" Beige w/ Lt Brown Floor Tile**
MATERIAL LOCATION: **Lunchroom**
MATERIAL QUANTITY: **616** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____

Stephen Diblik

Date: **05/03/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26661** BUIDLING ID: **4040**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcus Tsilimos**
SCHOOL NAME: **Noble Street Charter - Chicago Bulls College** INSPECTION DATE: **4/26/2013**
ADDRESS: **2040 W. Adams** IDPH LICENSE NO: **100-11460**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **49**
MATERIAL DESCRIPTION: **12" X 12" Beige w/ Lt Brown Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Lunchroom**

MATERIAL QUANTITY: **616**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 04/26/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26661** BUIDLING ID: **4040**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**
SCHOOL NAME: **Noble Street Charter - Chicago Bulls College** REVIEW DATE: **5/3/2013**
ADDRESS: **2040 W. Adams** IDPH LICENSE NO: **100-11460**

HOMOGENEOUS AREA: **49**
MATERIAL DESCRIPTION: **12" X 12" Beige w/ Lt Brown Floor Tile Mastic**
MATERIAL LOCATION: **Lunchroom**
MATERIAL QUANTITY: **616** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____

Stephen Diblik

Date: **05/03/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26661** BUIDLING ID: **4040**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcus Tsilimos**
SCHOOL NAME: **Noble Street Charter - Chicago Bulls College** INSPECTION DATE: **4/26/2013**
ADDRESS: **2040 W. Adams** IDPH LICENSE NO: **100-11460**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **5.1**
MATERIAL DESCRIPTION: **12"x12" Light Brown Floor Tile w/White Speckles**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Classrooms 203, 211**

MATERIAL QUANTITY: **1100**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **04/26/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26661** BUIDLING ID: **4040**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**
SCHOOL NAME: **Noble Street Charter - Chicago Bulls College** REVIEW DATE: **5/3/2013**
ADDRESS: **2040 W. Adams** IDPH LICENSE NO: **100-11460**

HOMOGENEOUS AREA: **5.1**
MATERIAL DESCRIPTION: **12"x12" Light Brown Floor Tile w/White Speckles**
MATERIAL LOCATION: **Classrooms 203, 211**
MATERIAL QUANTITY: **1100** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____

Stephen Diblik

Date: **05/03/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26661** BUIDLING ID: **4040**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcus Tsilimos**
SCHOOL NAME: **Noble Street Charter - Chicago Bulls College** INSPECTION DATE: **4/26/2013**
ADDRESS: **2040 W. Adams** IDPH LICENSE NO: **100-11460**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **5.2**
MATERIAL DESCRIPTION: **12"x12" White/Yellow Floor Tile w/Brown Speckles**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Repair Operations and Maintenance**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Room 101A (Gym Office), Adjacent Hall and Coaches Office**

MATERIAL QUANTITY: **315** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 04/26/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26661** BUIDLING ID: **4040**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**
SCHOOL NAME: **Noble Street Charter - Chicago Bulls College** REVIEW DATE: **5/3/2013**
ADDRESS: **2040 W. Adams** IDPH LICENSE NO: **100-11460**

HOMOGENEOUS AREA: **5.2**
MATERIAL DESCRIPTION: **12"x12" White/Yellow Floor Tile w/Brown Speckles**
MATERIAL LOCATION: **Room 101A (Gym Office), Adjacent Hall and Coaches Office**
MATERIAL QUANTITY: **315** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Repair
Operations and Maintenance**

Comments:

Management Planner's Signature: _____

Stephen Diblik

Date: **05/03/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26661** BUIDLING ID: **4040**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcus Tsilimos**
SCHOOL NAME: **Noble Street Charter - Chicago Bulls College** INSPECTION DATE: **4/26/2013**
ADDRESS: **2040 W. Adams** IDPH LICENSE NO: **100-11460**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **5.3**
MATERIAL DESCRIPTION: **12"x12" Brn/Yellow FT w/ White-Brown Specks**
HISTORICAL AHERA DAMAGE CATEGORY **6**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Teacher's Lunch Room**

MATERIAL QUANTITY: **800**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **04/26/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26661** BUIDLING ID: **4040**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**
SCHOOL NAME: **Noble Street Charter - Chicago Bulls College** REVIEW DATE: **5/3/2013**
ADDRESS: **2040 W. Adams** IDPH LICENSE NO: **100-11460**

HOMOGENEOUS AREA: **5.3**
MATERIAL DESCRIPTION: **12"x12" Brn/Yellow FT w/ White-Brown Specks**
MATERIAL LOCATION: **Teacher's Lunch Room**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____

Stephen Diblik

Date: **05/03/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26661** BUIDLING ID: **4040**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcus Tsilimos**
SCHOOL NAME: **Noble Street Charter - Chicago Bulls College** INSPECTION DATE: **4/26/2013**
ADDRESS: **2040 W. Adams** IDPH LICENSE NO: **100-11460**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **5.4**
MATERIAL DESCRIPTION: **12" x 12" Brown Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **Low**

MATERIAL LOCATION: **Engineer's Storage**

MATERIAL QUANTITY: **40**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS: **Not Observed.**

Inspector's Signature:



Date: **04/26/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26661** BUIDLING ID: **4040**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**
SCHOOL NAME: **Noble Street Charter - Chicago Bulls College** REVIEW DATE: **5/3/2013**
ADDRESS: **2040 W. Adams** IDPH LICENSE NO: **100-11460**

HOMOGENEOUS AREA: **5.4**
MATERIAL DESCRIPTION: **12" x 12" Brown Floor Tile**
MATERIAL LOCATION: **Engineer's Storage**
MATERIAL QUANTITY: **40** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature:

Stephen Diblik

Date: **05/03/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26661** BUIDLING ID: **4040**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcus Tsilimos**
SCHOOL NAME: **Noble Street Charter - Chicago Bulls College** INSPECTION DATE: **4/26/2013**
ADDRESS: **2040 W. Adams** IDPH LICENSE NO: **100-11460**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **5.5**
MATERIAL DESCRIPTION: **12" x 12" Beige Mix Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Library, Storage Room Basement, Rooms
008,011,013,111,112,116,203,207,209,210,213,214,300,301,304-307,313,318**

MATERIAL QUANTITY: **20000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 04/26/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26661** BUIDLING ID: **4040**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**
SCHOOL NAME: **Noble Street Charter - Chicago Bulls College** REVIEW DATE: **5/3/2013**
ADDRESS: **2040 W. Adams** IDPH LICENSE NO: **100-11460**

HOMOGENEOUS AREA: **5.5**
MATERIAL DESCRIPTION: **12" x 12" Beige Mix Floor Tile**
MATERIAL LOCATION: **Library, Storage Room Basement, Rooms 008,011,013,111,112,116,203,207,209,210,213,214,300,301,304-307,313,318**
MATERIAL QUANTITY: **20000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____

Stephen Diblik

Date: **05/03/2013**

Chicago Public Schools

Carnow, Conibear and Associates 2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26661** BUIDLING ID: **4040**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcus Tsilimos**
SCHOOL NAME: **Noble Street Charter - Chicago Bulls College** INSPECTION DATE: **4/26/2013**
ADDRESS: **2040 W. Adams** IDPH LICENSE NO: **100-11460**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **50**
MATERIAL DESCRIPTION: **Peg Board**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**

MATERIAL LOCATION: **Girl's Basement Washroom and Library**

MATERIAL QUANTITY: **33** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 04/26/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26661** BUIDLING ID: **4040**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**
SCHOOL NAME: **Noble Street Charter - Chicago Bulls College** REVIEW DATE: **5/3/2013**
ADDRESS: **2040 W. Adams** IDPH LICENSE NO: **100-11460**

HOMOGENEOUS AREA: **50**
MATERIAL DESCRIPTION: **Peg Board**
MATERIAL LOCATION: **Girl's Basement Washroom and Library**
MATERIAL QUANTITY: **33** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____

Stephen Diblik

Date: **05/03/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26661** BUIDLING ID: **4040**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcus Tsilimos**
SCHOOL NAME: **Noble Street Charter - Chicago Bulls College** INSPECTION DATE: **4/26/2013**
ADDRESS: **2040 W. Adams** IDPH LICENSE NO: **100-11460**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **51**
MATERIAL DESCRIPTION: **Peg Board Adhesive**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Girl's Basement Washroom and Library**

MATERIAL QUANTITY: **33**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **04/26/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26661** BUIDLING ID: **4040**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**
SCHOOL NAME: **Noble Street Charter - Chicago Bulls College** REVIEW DATE: **5/3/2013**
ADDRESS: **2040 W. Adams** IDPH LICENSE NO: **100-11460**

HOMOGENEOUS AREA: **51**
MATERIAL DESCRIPTION: **Peg Board Adhesive**
MATERIAL LOCATION: **Girl's Basement Washroom and Library**
MATERIAL QUANTITY: **33** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____

Stephen Diblik

Date: **05/03/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26661** BUIDLING ID: **4040**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcus Tsilimos**
SCHOOL NAME: **Noble Street Charter - Chicago Bulls College** INSPECTION DATE: **4/26/2013**
ADDRESS: **2040 W. Adams** IDPH LICENSE NO: **100-11460**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **52**
MATERIAL DESCRIPTION: **Chalk Boards**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Basement Lab, Industrial Arts, Rooms: 103-106,111-113,A&B,205-211,214-216,300-305,307,312-315 Library,307,313A**

MATERIAL QUANTITY: **4720** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 04/26/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26661** BUIDLING ID: **4040**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**
SCHOOL NAME: **Noble Street Charter - Chicago Bulls College** REVIEW DATE: **5/3/2013**
ADDRESS: **2040 W. Adams** IDPH LICENSE NO: **100-11460**

HOMOGENEOUS AREA: **52**
MATERIAL DESCRIPTION: **Chalk Boards**
MATERIAL LOCATION: **Basement Lab, Industrial Arts, Rooms: 103-106,111-113,A&B,205-211,214-216,300-305,307,312-315 Library,307,313A**
MATERIAL QUANTITY: **4720** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature:

Stephen Diblik

Date: **05/03/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26661** BUIDLING ID: **4040**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcus Tsilimos**
SCHOOL NAME: **Noble Street Charter - Chicago Bulls College** INSPECTION DATE: **4/26/2013**
ADDRESS: **2040 W. Adams** IDPH LICENSE NO: **100-11460**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **53**
MATERIAL DESCRIPTION: **Marker Board Adhesive**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Library, 307, 313A**

MATERIAL QUANTITY: **240**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 04/26/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26661** BUIDLING ID: **4040**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**
SCHOOL NAME: **Noble Street Charter - Chicago Bulls College** REVIEW DATE: **5/3/2013**
ADDRESS: **2040 W. Adams** IDPH LICENSE NO: **100-11460**

HOMOGENEOUS AREA: **53**
MATERIAL DESCRIPTION: **Marker Board Adhesive**
MATERIAL LOCATION: **Library, 307, 313A**
MATERIAL QUANTITY: **240** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____

Stephen Diblik

Date: **05/03/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26661** BUIDLING ID: **4040**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcus Tsilimos**
SCHOOL NAME: **Noble Street Charter - Chicago Bulls College** INSPECTION DATE: **4/26/2013**
ADDRESS: **2040 W. Adams** IDPH LICENSE NO: **100-11460**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **54**
MATERIAL DESCRIPTION: **Duct Vibration Absorber**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Room 011**

MATERIAL QUANTITY: **4**

MATERIAL UNITS: **LF**

DAMAGE QUANTITY:

DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature:



Date: **04/26/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26661** BUIDLING ID: **4040**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**
SCHOOL NAME: **Noble Street Charter - Chicago Bulls College** REVIEW DATE: **5/3/2013**
ADDRESS: **2040 W. Adams** IDPH LICENSE NO: **100-11460**

HOMOGENEOUS AREA: **54**
MATERIAL DESCRIPTION: **Duct Vibration Absorber**
MATERIAL LOCATION: **Room 011**
MATERIAL QUANTITY: **4** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____

Stephen Diblik

Date: **05/03/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26661** BUIDLING ID: **4040**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcus Tsilimos**
SCHOOL NAME: **Noble Street Charter - Chicago Bulls College** INSPECTION DATE: **4/26/2013**
ADDRESS: **2040 W. Adams** IDPH LICENSE NO: **100-11460**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **55**
MATERIAL DESCRIPTION: **Gray Carpet Adhesive**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Teachers Lounge on 1st and 209**

MATERIAL QUANTITY: **800**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 04/26/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26661** BUIDLING ID: **4040**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**
SCHOOL NAME: **Noble Street Charter - Chicago Bulls College** REVIEW DATE: **5/3/2013**
ADDRESS: **2040 W. Adams** IDPH LICENSE NO: **100-11460**

HOMOGENEOUS AREA: **55**
MATERIAL DESCRIPTION: **Gray Carpet Adhesive**
MATERIAL LOCATION: **Teachers Lounge on 1st and 209**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____

Stephen Diblik

Date: 05/03/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26661** BUIDLING ID: **4040**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcus Tsilimos**
SCHOOL NAME: **Noble Street Charter - Chicago Bulls College** INSPECTION DATE: **4/26/2013**
ADDRESS: **2040 W. Adams** IDPH LICENSE NO: **100-11460**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **56**
MATERIAL DESCRIPTION: **Green/Orange/Yellow Carpet Adhesive.**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Room 108 and Principal's Office**

MATERIAL QUANTITY: **768**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **04/26/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26661** BUIDLING ID: **4040**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**
SCHOOL NAME: **Noble Street Charter - Chicago Bulls College** REVIEW DATE: **5/3/2013**
ADDRESS: **2040 W. Adams** IDPH LICENSE NO: **100-11460**

HOMOGENEOUS AREA: **56**
MATERIAL DESCRIPTION: **Green/Orange/Yellow Carpet Adhesive.**
MATERIAL LOCATION: **Room 108 and Principal's Office**
MATERIAL QUANTITY: **768** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____

Stephen Diblik

Date: **05/03/2013**

Chicago Public Schools

Carnow, Conibear and Associates 2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26661** BUIDLING ID: **4040**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcus Tsilimos**
SCHOOL NAME: **Noble Street Charter - Chicago Bulls College** INSPECTION DATE: **4/26/2013**
ADDRESS: **2040 W. Adams** IDPH LICENSE NO: **100-11460**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **57**
MATERIAL DESCRIPTION: **Purple Carpet Adhesive**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Room 109**

MATERIAL QUANTITY: **384**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **04/26/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26661** BUIDLING ID: **4040**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**
SCHOOL NAME: **Noble Street Charter - Chicago Bulls College** REVIEW DATE: **5/3/2013**
ADDRESS: **2040 W. Adams** IDPH LICENSE NO: **100-11460**

HOMOGENEOUS AREA: **57**
MATERIAL DESCRIPTION: **Purple Carpet Adhesive**
MATERIAL LOCATION: **Room 109**
MATERIAL QUANTITY: **384** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____

Stephen Diblik

Date: **05/03/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26661** BUIDLING ID: **4040**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcus Tsilimos**
SCHOOL NAME: **Noble Street Charter - Chicago Bulls College** INSPECTION DATE: **4/26/2013**
ADDRESS: **2040 W. Adams** IDPH LICENSE NO: **100-11460**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **58**
MATERIAL DESCRIPTION: **Gray and Blue Carpet Adhesive**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Rooms 112, 210, 212, 214**

MATERIAL QUANTITY: **936**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 04/26/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26661** BUIDLING ID: **4040**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**
SCHOOL NAME: **Noble Street Charter - Chicago Bulls College** REVIEW DATE: **5/3/2013**
ADDRESS: **2040 W. Adams** IDPH LICENSE NO: **100-11460**

HOMOGENEOUS AREA: **58**
MATERIAL DESCRIPTION: **Gray and Blue Carpet Adhesive**
MATERIAL LOCATION: **Rooms 112, 210, 212, 214**
MATERIAL QUANTITY: **936** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____

Stephen Diblik

Date: **05/03/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26661** BUIDLING ID: **4040**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcus Tsilimos**
SCHOOL NAME: **Noble Street Charter - Chicago Bulls College** INSPECTION DATE: **4/26/2013**
ADDRESS: **2040 W. Adams** IDPH LICENSE NO: **100-11460**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **59**
MATERIAL DESCRIPTION: **Blue w/White Carpet Adhesive**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Rooms 104, 204**

MATERIAL QUANTITY: **836**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **04/26/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26661** BUIDLING ID: **4040**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**
SCHOOL NAME: **Noble Street Charter - Chicago Bulls College** REVIEW DATE: **5/3/2013**
ADDRESS: **2040 W. Adams** IDPH LICENSE NO: **100-11460**

HOMOGENEOUS AREA: **59**
MATERIAL DESCRIPTION: **Blue w/White Carpet Adhesive**
MATERIAL LOCATION: **Rooms 104, 204**
MATERIAL QUANTITY: **836** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____

Stephen Diblik

Date: **05/03/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26661** BUIDLING ID: **4040**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcus Tsilimos**
SCHOOL NAME: **Noble Street Charter - Chicago Bulls College** INSPECTION DATE: **4/26/2013**
ADDRESS: **2040 W. Adams** IDPH LICENSE NO: **100-11460**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **6.1**
MATERIAL DESCRIPTION: **9" x 9" Brown Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Room 109**

MATERIAL QUANTITY: **112**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **04/26/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26661** BUIDLING ID: **4040**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**
SCHOOL NAME: **Noble Street Charter - Chicago Bulls College** REVIEW DATE: **5/3/2013**
ADDRESS: **2040 W. Adams** IDPH LICENSE NO: **100-11460**

HOMOGENEOUS AREA: **6.1**
MATERIAL DESCRIPTION: **9" x 9" Brown Floor Tile**
MATERIAL LOCATION: **Room 109**
MATERIAL QUANTITY: **112** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____

Stephen Diblik

Date: **05/03/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26661** BUIDLING ID: **4040**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcus Tsilimos**
SCHOOL NAME: **Noble Street Charter - Chicago Bulls College** INSPECTION DATE: **4/26/2013**
ADDRESS: **2040 W. Adams** IDPH LICENSE NO: **100-11460**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **6.2**
MATERIAL DESCRIPTION: **9" x 9" Brown/Black/Red/Green Mix Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Rooms 004A & 004B**

MATERIAL QUANTITY: **430**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **04/26/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26661** BUIDLING ID: **4040**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**
SCHOOL NAME: **Noble Street Charter - Chicago Bulls College** REVIEW DATE: **5/3/2013**
ADDRESS: **2040 W. Adams** IDPH LICENSE NO: **100-11460**

HOMOGENEOUS AREA: **6.2**
MATERIAL DESCRIPTION: **9" x 9" Brown/Black/Red/Green Mix Floor Tile**
MATERIAL LOCATION: **Rooms 004A & 004B**
MATERIAL QUANTITY: **430** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____

Stephen Diblik

Date: **05/03/2013**

Chicago Public Schools

Carnow, Conibear and Associates 2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26661** BUIDLING ID: **4040**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcus Tsilimos**
SCHOOL NAME: **Noble Street Charter - Chicago Bulls College** INSPECTION DATE: **4/26/2013**
ADDRESS: **2040 W. Adams** IDPH LICENSE NO: **100-11460**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **6.3**
MATERIAL DESCRIPTION: **9"x9" Yellow & Green Floor Tiles in a Checkerboard**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Remove Operations and Maintenance**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Lunch Room**

MATERIAL QUANTITY: **4420**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **04/26/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26661** BUIDLING ID: **4040**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**
SCHOOL NAME: **Noble Street Charter - Chicago Bulls College** REVIEW DATE: **5/3/2013**
ADDRESS: **2040 W. Adams** IDPH LICENSE NO: **100-11460**

HOMOGENEOUS AREA: **6.3**
MATERIAL DESCRIPTION: **9"x9" Yellow & Green Floor Tiles in a Checkerboard**
MATERIAL LOCATION: **Lunch Room**
MATERIAL QUANTITY: **4420** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **10** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Remove
Operations and Maintenance**

Comments:

Management Planner's Signature: _____

Stephen Diblik

Date: **05/03/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26661** BUIDLING ID: **4040**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcus Tsilimos**
SCHOOL NAME: **Noble Street Charter - Chicago Bulls College** INSPECTION DATE: **4/26/2013**
ADDRESS: **2040 W. Adams** IDPH LICENSE NO: **100-11460**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **60**
MATERIAL DESCRIPTION: **Vault Door Insulation**
HISTORICAL AHERA DAMAGE CATEGORY **7 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Main Office (109)**

MATERIAL QUANTITY: **28**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **04/26/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26661** BUIDLING ID: **4040**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**
SCHOOL NAME: **Noble Street Charter - Chicago Bulls College** REVIEW DATE: **5/3/2013**
ADDRESS: **2040 W. Adams** IDPH LICENSE NO: **100-11460**

HOMOGENEOUS AREA: **60**
MATERIAL DESCRIPTION: **Vault Door Insulation**
MATERIAL LOCATION: **Main Office (109)**
MATERIAL QUANTITY: **28** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____

Stephen Diblik

Date: **05/03/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26661** BUIDLING ID: **4040**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcus Tsilimos**
SCHOOL NAME: **Noble Street Charter - Chicago Bulls College** INSPECTION DATE: **4/26/2013**
ADDRESS: **2040 W. Adams** IDPH LICENSE NO: **100-11460**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **61**
MATERIAL DESCRIPTION: **12" x 12" tan floor tile with light brown**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Rooms 006, 006B and 008**

MATERIAL QUANTITY: **2000**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 04/26/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26661** BUIDLING ID: **4040**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**
SCHOOL NAME: **Noble Street Charter - Chicago Bulls College** REVIEW DATE: **5/3/2013**
ADDRESS: **2040 W. Adams** IDPH LICENSE NO: **100-11460**

HOMOGENEOUS AREA: **61**
MATERIAL DESCRIPTION: **12" x 12" tan floor tile with light brown**
MATERIAL LOCATION: **Rooms 006, 006B and 008**
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____

Stephen Diblik

Date: **05/03/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26661** BUIDLING ID: **4040**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcus Tsilimos**
SCHOOL NAME: **Noble Street Charter - Chicago Bulls College** INSPECTION DATE: **4/26/2013**
ADDRESS: **2040 W. Adams** IDPH LICENSE NO: **100-11460**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **62**
MATERIAL DESCRIPTION: **Mastic for 12" x 12" tan floor tile with light brown**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Rooms 006, 006B, and 008**

MATERIAL QUANTITY: **2000**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **04/26/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26661** BUIDLING ID: **4040**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**
SCHOOL NAME: **Noble Street Charter - Chicago Bulls College** REVIEW DATE: **5/3/2013**
ADDRESS: **2040 W. Adams** IDPH LICENSE NO: **100-11460**

HOMOGENEOUS AREA: **62**
MATERIAL DESCRIPTION: **Mastic for 12" x 12" tan floor tile with light brown**
MATERIAL LOCATION: **Rooms 006, 006B, and 008**
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____

Stephen Diblik

Date: **05/03/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26661** BUIDLING ID: **4040**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcus Tsilimos**
SCHOOL NAME: **Noble Street Charter - Chicago Bulls College** INSPECTION DATE: **4/26/2013**
ADDRESS: **2040 W. Adams** IDPH LICENSE NO: **100-11460**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **63**
MATERIAL DESCRIPTION: **Green Terrazzo**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Stairwells and washroom adjacent to 315**

MATERIAL QUANTITY: **4000**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 04/26/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26661** BUIDLING ID: **4040**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**
SCHOOL NAME: **Noble Street Charter - Chicago Bulls College** REVIEW DATE: **5/3/2013**
ADDRESS: **2040 W. Adams** IDPH LICENSE NO: **100-11460**

HOMOGENEOUS AREA: **63**
MATERIAL DESCRIPTION: **Green Terrazzo**
MATERIAL LOCATION: **Stairwells and washroom adjacent to 315**
MATERIAL QUANTITY: **4000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____

Stephen Diblik

Date: **05/03/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26661** BUIDLING ID: **4040**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcus Tsilimos**
SCHOOL NAME: **Noble Street Charter - Chicago Bulls College** INSPECTION DATE: **4/26/2013**
ADDRESS: **2040 W. Adams** IDPH LICENSE NO: **100-11460**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **7.1**
MATERIAL DESCRIPTION: **Linoleum**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Gym**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not Observed.**

Inspector's Signature:



Date: **04/26/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26661** BUIDLING ID: **4040**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**
SCHOOL NAME: **Noble Street Charter - Chicago Bulls College** REVIEW DATE: **5/3/2013**
ADDRESS: **2040 W. Adams** IDPH LICENSE NO: **100-11460**

HOMOGENEOUS AREA: **7.1**

MATERIAL DESCRIPTION: **Linoleum**

MATERIAL LOCATION: **Gym**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____

Stephen Diblik

Date: 05/03/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26661** BUIDLING ID: **4040**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcus Tsilimos**
SCHOOL NAME: **Noble Street Charter - Chicago Bulls College** INSPECTION DATE: **4/26/2013**
ADDRESS: **2040 W. Adams** IDPH LICENSE NO: **100-11460**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **7.2**
MATERIAL DESCRIPTION: **Linoleum**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Basement NW, NE Stairway**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Not Observed.**

Inspector's Signature:



Date: **04/26/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26661** BUIDLING ID: **4040**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**
SCHOOL NAME: **Noble Street Charter - Chicago Bulls College** REVIEW DATE: **5/3/2013**
ADDRESS: **2040 W. Adams** IDPH LICENSE NO: **100-11460**

HOMOGENEOUS AREA: **7.2**
MATERIAL DESCRIPTION: **Linoleum**
MATERIAL LOCATION: **Basement NW, NE Stairway**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:  Date: **05/03/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26661** BUIDLING ID: **4040**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcus Tsilimos**
SCHOOL NAME: **Noble Street Charter - Chicago Bulls College** INSPECTION DATE: **4/26/2013**
ADDRESS: **2040 W. Adams** IDPH LICENSE NO: **100-11460**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **8.1**
MATERIAL DESCRIPTION: **12"x12"Lt Brown Floor Tile w/White Specks Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Classrooms 203, 211**

MATERIAL QUANTITY: **1100**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 04/26/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26661** BUIDLING ID: **4040**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**
SCHOOL NAME: **Noble Street Charter - Chicago Bulls College** REVIEW DATE: **5/3/2013**
ADDRESS: **2040 W. Adams** IDPH LICENSE NO: **100-11460**

HOMOGENEOUS AREA: **8.1**
MATERIAL DESCRIPTION: **12"x12"Lt Brown Floor Tile w/White Specks Mastic**
MATERIAL LOCATION: **Classrooms 203, 211**
MATERIAL QUANTITY: **1100** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____

Stephen Diblik

Date: **05/03/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26661** BUIDLING ID: **4040**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcus Tsilimos**
SCHOOL NAME: **Noble Street Charter - Chicago Bulls College** INSPECTION DATE: **4/26/2013**
ADDRESS: **2040 W. Adams** IDPH LICENSE NO: **100-11460**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **8.2**
MATERIAL DESCRIPTION: **12"x12" White/Yellow FT w/Brown Specks Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Room 101A Gym Office, Adjacent Hall and Coach Office**

MATERIAL QUANTITY: **426** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 04/26/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26661** BUIDLING ID: **4040**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**
SCHOOL NAME: **Noble Street Charter - Chicago Bulls College** REVIEW DATE: **5/3/2013**
ADDRESS: **2040 W. Adams** IDPH LICENSE NO: **100-11460**

HOMOGENEOUS AREA: **8.2**
MATERIAL DESCRIPTION: **12"x12" White/Yellow FT w/Brown Specks Mastic**
MATERIAL LOCATION: **Room 101A Gym Office, Adjacent Hall and Coach Office**
MATERIAL QUANTITY: **426** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____

Stephen Diblik

Date: **05/03/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26661** BUIDLING ID: **4040**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcus Tsilimos**
SCHOOL NAME: **Noble Street Charter - Chicago Bulls College** INSPECTION DATE: **4/26/2013**
ADDRESS: **2040 W. Adams** IDPH LICENSE NO: **100-11460**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **8.3**
MATERIAL DESCRIPTION: **12" x 12" Brown Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **014**

MATERIAL QUANTITY: **900**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **04/26/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26661** BUIDLING ID: **4040**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**
SCHOOL NAME: **Noble Street Charter - Chicago Bulls College** REVIEW DATE: **5/3/2013**
ADDRESS: **2040 W. Adams** IDPH LICENSE NO: **100-11460**

HOMOGENEOUS AREA: **8.3**
MATERIAL DESCRIPTION: **12" x 12" Brown Floor Tile Mastic**
MATERIAL LOCATION: **014**
MATERIAL QUANTITY: **900** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____

Stephen Diblik

Date: **05/03/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26661** BUIDLING ID: **4040**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcus Tsilimos**
SCHOOL NAME: **Noble Street Charter - Chicago Bulls College** INSPECTION DATE: **4/26/2013**
ADDRESS: **2040 W. Adams** IDPH LICENSE NO: **100-11460**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **8.4**
MATERIAL DESCRIPTION: **12" x 12" Brown Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Engineer's Storage Hallway**

MATERIAL QUANTITY: **40**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **04/26/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26661** BUIDLING ID: **4040**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**
SCHOOL NAME: **Noble Street Charter - Chicago Bulls College** REVIEW DATE: **5/3/2013**
ADDRESS: **2040 W. Adams** IDPH LICENSE NO: **100-11460**

HOMOGENEOUS AREA: **8.4**
MATERIAL DESCRIPTION: **12" x 12" Brown Floor Tile Mastic**
MATERIAL LOCATION: **Engineer's Storage Hallway**
MATERIAL QUANTITY: **40** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____

Stephen Diblik

Date: **05/03/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26661** BUIDLING ID: **4040**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcus Tsilimos**
SCHOOL NAME: **Noble Street Charter - Chicago Bulls College** INSPECTION DATE: **4/26/2013**
ADDRESS: **2040 W. Adams** IDPH LICENSE NO: **100-11460**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **8.5**
MATERIAL DESCRIPTION: **12" x 12" Beige Mix Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Bsmt. Clsrms, Found. Library, 102-104, 109, 111, 112, 115, 116, 203-207, 209-215, 301, 302, 304, 307, 308, 312-314**

MATERIAL QUANTITY: **20000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 04/26/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26661** BUIDLING ID: **4040**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**
SCHOOL NAME: **Noble Street Charter - Chicago Bulls College** REVIEW DATE: **5/3/2013**
ADDRESS: **2040 W. Adams** IDPH LICENSE NO: **100-11460**

HOMOGENEOUS AREA: **8.5**
MATERIAL DESCRIPTION: **12" x 12" Beige Mix Floor Tile Mastic**
MATERIAL LOCATION: **Bsmt. Clsrms, Found. Library, 102-104, 109, 111, 112, 115, 116, 203-207, 209-215, 301, 302, 304, 307, 308, 312-314**
MATERIAL QUANTITY: **20000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____

Stephen Diblik

Date: 05/03/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26661** BUIDLING ID: **4040**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcus Tsilimos**
SCHOOL NAME: **Noble Street Charter - Chicago Bulls College** INSPECTION DATE: **4/26/2013**
ADDRESS: **2040 W. Adams** IDPH LICENSE NO: **100-11460**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **9.1**
MATERIAL DESCRIPTION: **9" x 9" Brown Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **109**

MATERIAL QUANTITY: **112**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **04/26/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26661** BUIDLING ID: **4040**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**
SCHOOL NAME: **Noble Street Charter - Chicago Bulls College** REVIEW DATE: **5/3/2013**
ADDRESS: **2040 W. Adams** IDPH LICENSE NO: **100-11460**

HOMOGENEOUS AREA: **9.1**
MATERIAL DESCRIPTION: **9" x 9" Brown Floor Tile Mastic**
MATERIAL LOCATION: **109**
MATERIAL QUANTITY: **112** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____

Stephen Diblik

Date: **05/03/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26661** BUIDLING ID: **4040**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcus Tsilimos**
SCHOOL NAME: **Noble Street Charter - Chicago Bulls College** INSPECTION DATE: **4/26/2013**
ADDRESS: **2040 W. Adams** IDPH LICENSE NO: **100-11460**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **9.2**
MATERIAL DESCRIPTION: **9"x9"Brown/Black/Red/Green Mix Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Rooms 004A & 004B**

MATERIAL QUANTITY: **430**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **04/26/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26661** BUIDLING ID: **4040**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**
SCHOOL NAME: **Noble Street Charter - Chicago Bulls College** REVIEW DATE: **5/3/2013**
ADDRESS: **2040 W. Adams** IDPH LICENSE NO: **100-11460**

HOMOGENEOUS AREA: **9.2**
MATERIAL DESCRIPTION: **9"x9"Brown/Black/Red/Green Mix Floor Tile Mastic**
MATERIAL LOCATION: **Rooms 004A & 004B**
MATERIAL QUANTITY: **430** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____

Stephen Diblik

Date: **05/03/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26661** BUIDLING ID: **4040**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcus Tsilimos**
SCHOOL NAME: **Noble Street Charter - Chicago Bulls College** INSPECTION DATE: **4/26/2013**
ADDRESS: **2040 W. Adams** IDPH LICENSE NO: **100-11460**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **9.3**
MATERIAL DESCRIPTION: **9" x 9" Yellow & Green Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Lunch Room & Kitchen**

MATERIAL QUANTITY: **4420**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 04/26/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26661** BUIDLING ID: **4040**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**
SCHOOL NAME: **Noble Street Charter - Chicago Bulls College** REVIEW DATE: **5/3/2013**
ADDRESS: **2040 W. Adams** IDPH LICENSE NO: **100-11460**

HOMOGENEOUS AREA: **9.3**
MATERIAL DESCRIPTION: **9" x 9" Yellow & Green Floor Tile Mastic**
MATERIAL LOCATION: **Lunch Room & Kitchen**
MATERIAL QUANTITY: **4420** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____

Stephen Diblik

Date: **05/03/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26661** BUIDLING ID: **4040**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcus Tsilimos**
SCHOOL NAME: **Noble Street Charter - Chicago Bulls College** INSPECTION DATE: **4/26/2013**
ADDRESS: **2040 W. Adams** IDPH LICENSE NO: **100-11460**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **A**
MATERIAL DESCRIPTION: **Fiberglass Boiler Insulation**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Not Tested** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Fiberglass not a suspect material.**

Inspector's Signature:



Date: **04/26/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26661** BUIDLING ID: **4040**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**
SCHOOL NAME: **Noble Street Charter - Chicago Bulls College** REVIEW DATE: **5/3/2013**
ADDRESS: **2040 W. Adams** IDPH LICENSE NO: **100-11460**

HOMOGENEOUS AREA: **A**

MATERIAL DESCRIPTION: **Fiberglass Boiler Insulation**

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____

Stephen Diblik

Date: **05/03/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26661** BUIDLING ID: **4040**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcus Tsilimos**
SCHOOL NAME: **Noble Street Charter - Chicago Bulls College** INSPECTION DATE: **4/26/2013**
ADDRESS: **2040 W. Adams** IDPH LICENSE NO: **100-11460**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **B**
MATERIAL DESCRIPTION: **Water Tank Insulation**
HISTORICAL AHERA DAMAGE CATEGORY **6**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Boiler Room**
MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____



Date: 04/26/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26661** BUIDLING ID: **4040**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**
SCHOOL NAME: **Noble Street Charter - Chicago Bulls College** REVIEW DATE: **5/3/2013**
ADDRESS: **2040 W. Adams** IDPH LICENSE NO: **100-11460**

HOMOGENEOUS AREA: **B**
MATERIAL DESCRIPTION: **Water Tank Insulation**
MATERIAL LOCATION: **Boiler Room**
MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____

Stephen Diblik

Date: **05/03/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26661** BUIDLING ID: **4040**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcus Tsilimos**
SCHOOL NAME: **Noble Street Charter - Chicago Bulls College** INSPECTION DATE: **4/26/2013**
ADDRESS: **2040 W. Adams** IDPH LICENSE NO: **100-11460**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **C**
MATERIAL DESCRIPTION: **Tank Insulation**
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Tank Room**

MATERIAL QUANTITY: **125**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 04/26/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26661** BUIDLING ID: **4040**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**
SCHOOL NAME: **Noble Street Charter - Chicago Bulls College** REVIEW DATE: **5/3/2013**
ADDRESS: **2040 W. Adams** IDPH LICENSE NO: **100-11460**

HOMOGENEOUS AREA: **C**
MATERIAL DESCRIPTION: **Tank Insulation**
MATERIAL LOCATION: **Tank Room**
MATERIAL QUANTITY: **125** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____

Stephen Diblik

Date: **05/03/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26661** BUIDLING ID: **4040**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcus Tsilimos**
SCHOOL NAME: **Noble Street Charter - Chicago Bulls College** INSPECTION DATE: **4/26/2013**
ADDRESS: **2040 W. Adams** IDPH LICENSE NO: **100-11460**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **D**
MATERIAL DESCRIPTION: **Water Meter Packing**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Sprinkler Room - Abated 1996**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **04/26/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26661** BUIDLING ID: **4040**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**
SCHOOL NAME: **Noble Street Charter - Chicago Bulls College** REVIEW DATE: **5/3/2013**
ADDRESS: **2040 W. Adams** IDPH LICENSE NO: **100-11460**

HOMOGENEOUS AREA: **D**
MATERIAL DESCRIPTION: **Water Meter Packing**
MATERIAL LOCATION: **Sprinkler Room - Abated 1996**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____

Stephen Diblik

Date: 05/03/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26661** BUIDLING ID: **4040**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcus Tsilimos**
SCHOOL NAME: **Noble Street Charter - Chicago Bulls College** INSPECTION DATE: **4/26/2013**
ADDRESS: **2040 W. Adams** IDPH LICENSE NO: **100-11460**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **E**
MATERIAL DESCRIPTION: **Preformed Pipe Insulation**
HISTORICAL AHERA DAMAGE CATEGORY **5 ACBM with potential for significant damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **5. ACBM with potential for significant damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Basement, Boiler Room, Lunchroom, Air Chamber, Elect. Room, Room 4A**

MATERIAL QUANTITY: **550** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: _____



Date: 04/26/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26661** BUIDLING ID: **4040**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**
SCHOOL NAME: **Noble Street Charter - Chicago Bulls College** REVIEW DATE: **5/3/2013**
ADDRESS: **2040 W. Adams** IDPH LICENSE NO: **100-11460**

HOMOGENEOUS AREA: **E**
MATERIAL DESCRIPTION: **Preformed Pipe Insulation**
MATERIAL LOCATION: **Basement, Boiler Room, Lunchroom, Air Chamber, Elect. Room, Room 4A**
MATERIAL QUANTITY: **550** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____

Stephen Diblik

Date: **05/03/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26661** BUIDLING ID: **4040**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcus Tsilimos**
SCHOOL NAME: **Noble Street Charter - Chicago Bulls College** INSPECTION DATE: **4/26/2013**
ADDRESS: **2040 W. Adams** IDPH LICENSE NO: **100-11460**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **F**
MATERIAL DESCRIPTION: **Preformed Pipe Joint Insulation**
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Basement, Boiler Room, Lunchroom, Air Chamber, Elect. Room, Room 4A**
MATERIAL QUANTITY: **56** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____



Date: 04/26/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26661** BUIDLING ID: **4040**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**
SCHOOL NAME: **Noble Street Charter - Chicago Bulls College** REVIEW DATE: **5/3/2013**
ADDRESS: **2040 W. Adams** IDPH LICENSE NO: **100-11460**

HOMOGENEOUS AREA: **F**
MATERIAL DESCRIPTION: **Preformed Pipe Joint Insulation**
MATERIAL LOCATION: **Basement, Boiler Room, Lunchroom, Air Chamber, Elect. Room, Room 4A**
MATERIAL QUANTITY: **56** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____

Stephen Diblik

Date: **05/03/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26661** BUIDLING ID: **4040**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcus Tsilimos**
SCHOOL NAME: **Noble Street Charter - Chicago Bulls College** INSPECTION DATE: **4/26/2013**
ADDRESS: **2040 W. Adams** IDPH LICENSE NO: **100-11460**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **G**
MATERIAL DESCRIPTION: **Cardboard Pipe Insulation**
HISTORICAL AHERA DAMAGE CATEGORY **1 Damaged or significantly damaged friable thermal system insulating ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Repair Operations and Maintenance**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **1. Damaged or significantly damaged friable thermal system insulating ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Engineers's Office, Storage, Pump Rooms, Fan rooms, Lunchroom, 011, Boiler Room, 002, Through Out, 015**

MATERIAL QUANTITY: **1830** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature:



Date: **04/26/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26661** BUIDLING ID: **4040**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**
SCHOOL NAME: **Noble Street Charter - Chicago Bulls College** REVIEW DATE: **5/3/2013**
ADDRESS: **2040 W. Adams** IDPH LICENSE NO: **100-11460**

HOMOGENEOUS AREA: **G**
MATERIAL DESCRIPTION: **Cardboard Pipe Insulation**
MATERIAL LOCATION: **Engineers's Office, Storage, Pump Rooms, Fan rooms, Lunchroom, 011, Boiler Room, 002, Through Out, 015**
MATERIAL QUANTITY: **1830** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Repair
Operations and Maintenance**

Comments:

Repair damaged material and continue O&M

Management Planner's Signature: Stephen Diblik Date: 05/03/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26661** BUIDLING ID: **4040**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcus Tsilimos**
SCHOOL NAME: **Noble Street Charter - Chicago Bulls College** INSPECTION DATE: **4/26/2013**
ADDRESS: **2040 W. Adams** IDPH LICENSE NO: **100-11460**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **H**
MATERIAL DESCRIPTION: **Hard Joint Cmpd. On Cardboard Pipe Insulation**
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Engineers's Office, Storage, Pump Rooms, Fan rooms, Lunchroom, 011, Boiler Room, 002, Through Out**

MATERIAL QUANTITY: **250** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 04/26/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26661** BUIDLING ID: **4040**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**
SCHOOL NAME: **Noble Street Charter - Chicago Bulls College** REVIEW DATE: **5/3/2013**
ADDRESS: **2040 W. Adams** IDPH LICENSE NO: **100-11460**

HOMOGENEOUS AREA: **H**
MATERIAL DESCRIPTION: **Hard Joint Cmpd. On Cardboard Pipe Insulation**
MATERIAL LOCATION: **Engineers's Office, Storage, Pump Rooms, Fan rooms, Lunchroom, 011, Boiler Room, 002, Through Out**
MATERIAL QUANTITY: **250** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature:

Stephen Diblik

Date: **05/03/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26661** BUIDLING ID: **4040**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcus Tsilimos**
SCHOOL NAME: **Noble Street Charter - Chicago Bulls College** INSPECTION DATE: **4/26/2013**
ADDRESS: **2040 W. Adams** IDPH LICENSE NO: **100-11460**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **J.1**
MATERIAL DESCRIPTION: **Hard Joint Cmpd.- Orig. Fiberglass Pipe Insulation**
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Engineers's Office, Storage, Pump Rooms, Fan rooms, Lunchroom, 011, Boiler Room, 002, Through Out**

MATERIAL QUANTITY: **270** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 04/26/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26661** BUIDLING ID: **4040**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**
SCHOOL NAME: **Noble Street Charter - Chicago Bulls College** REVIEW DATE: **5/3/2013**
ADDRESS: **2040 W. Adams** IDPH LICENSE NO: **100-11460**

HOMOGENEOUS AREA: **J.1**
MATERIAL DESCRIPTION: **Hard Joint Cmpd.- Orig. Fiberglass Pipe Insulation**
MATERIAL LOCATION: **Engineers's Office, Storage, Pump Rooms, Fan rooms, Lunchroom, 011, Boiler Room, 002, Through Out**
MATERIAL QUANTITY: **270** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____

Stephen Diblik

Date: **05/03/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26661** BUIDLING ID: **4040**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcus Tsilimos**
SCHOOL NAME: **Noble Street Charter - Chicago Bulls College** INSPECTION DATE: **4/26/2013**
ADDRESS: **2040 W. Adams** IDPH LICENSE NO: **100-11460**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **J.2**
MATERIAL DESCRIPTION: **Hard Joint Cmpd.- New Fiberglass Pipe Insulation**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Not Tested** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout Facility**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Fiberglass not a suspect material.**

Inspector's Signature:



Date: **04/26/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26661** BUIDLING ID: **4040**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**
SCHOOL NAME: **Noble Street Charter - Chicago Bulls College** REVIEW DATE: **5/3/2013**
ADDRESS: **2040 W. Adams** IDPH LICENSE NO: **100-11460**

HOMOGENEOUS AREA: **J.2**

MATERIAL DESCRIPTION: **Hard Joint Cmpd.- New Fiberglass Pipe Insulation**

MATERIAL LOCATION: **Throughout Facility**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____

Stephen Diblik

Date: **05/03/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26661** BUIDLING ID: **4040**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcus Tsilimos**
SCHOOL NAME: **Noble Street Charter - Chicago Bulls College** INSPECTION DATE: **4/26/2013**
ADDRESS: **2040 W. Adams** IDPH LICENSE NO: **100-11460**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **K**
MATERIAL DESCRIPTION: **Aircell Pipe Insulation**
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Basement, 2nd Floor, 1st fl washroom, Attic**

MATERIAL QUANTITY: **300**

MATERIAL UNITS: **LF**

DAMAGE QUANTITY:

DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature:



Date: **04/26/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26661** BUIDLING ID: **4040**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**
SCHOOL NAME: **Noble Street Charter - Chicago Bulls College** REVIEW DATE: **5/3/2013**
ADDRESS: **2040 W. Adams** IDPH LICENSE NO: **100-11460**

HOMOGENEOUS AREA: **K**
MATERIAL DESCRIPTION: **Aircell Pipe Insulation**
MATERIAL LOCATION: **Basement, 2nd Floor, 1st fl washroom, Attic**
MATERIAL QUANTITY: **300** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____

Stephen Diblik

Date: **05/03/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26661** BUIDLING ID: **4040**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcus Tsilimos**
SCHOOL NAME: **Noble Street Charter - Chicago Bulls College** INSPECTION DATE: **4/26/2013**
ADDRESS: **2040 W. Adams** IDPH LICENSE NO: **100-11460**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **L**
MATERIAL DESCRIPTION: **Hard Joint Compound on Aircell Pipe Insulation**
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Basement & Second Floor, 1st fl washroom, Attic**

MATERIAL QUANTITY: **70** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 04/26/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26661** BUIDLING ID: **4040**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**
SCHOOL NAME: **Noble Street Charter - Chicago Bulls College** REVIEW DATE: **5/3/2013**
ADDRESS: **2040 W. Adams** IDPH LICENSE NO: **100-11460**

HOMOGENEOUS AREA: **L**
MATERIAL DESCRIPTION: **Hard Joint Compound on Aircell Pipe Insulation**
MATERIAL LOCATION: **Basement & Second Floor, 1st fl washroom, Attic**
MATERIAL QUANTITY: **70** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____

Stephen Diblik

Date: **05/03/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26661** BUIDLING ID: **4040**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcus Tsilimos**
SCHOOL NAME: **Noble Street Charter - Chicago Bulls College** INSPECTION DATE: **4/26/2013**
ADDRESS: **2040 W. Adams** IDPH LICENSE NO: **100-11460**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **M**
MATERIAL DESCRIPTION: **Duct Insulation**
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Kitchen**

MATERIAL QUANTITY: **50**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **04/26/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26661** BUIDLING ID: **4040**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**
SCHOOL NAME: **Noble Street Charter - Chicago Bulls College** REVIEW DATE: **5/3/2013**
ADDRESS: **2040 W. Adams** IDPH LICENSE NO: **100-11460**

HOMOGENEOUS AREA: **M**
MATERIAL DESCRIPTION: **Duct Insulation**
MATERIAL LOCATION: **Kitchen**
MATERIAL QUANTITY: **50** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____

Stephen Diblik

Date: **05/03/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

APPENDIX B

Inspector and Management Planner Licenses

Marcus Tsilimos

Illinois Licensed Asbestos Inspector, Project Manager, and
Air Sampling Professional


Illinois Department of
PUBLIC HEALTH

**ASBESTOS
PROFESSIONAL
LICENSE**

ID NUMBER	ISSUED	EXPIRES
100 - 11460	4/4/2012	05/15/2013

MARCUS J TSILIMOS
2126 WEST CHICAGO AVE, 1R
CHICAGO, IL 60622

Environmental Health



ENDORSEMENTS	TC EXPIRES
INSPECTOR	12/8/2012
PROJECT MANAGER AIR SAMPLING PROFESSIONAL	12/15/2012

Alteration of this license shall result in legal action
This license issued under authority of the State of Illinois
Department of Public Health
This license is valid only when accompanied by a valid
training course certificate.

**CARNOW
CONIBEAR**



Occupational Training & Supply, Inc.

7233 Adams Street • Willowbrook, IL 60527 • (630) 655-3900

Marcus Tsilimos

has successfully completed the 4 hour Asbestos Building Inspector Refresher Course and has passed the competency exam with a minimum score of 70%. This course is accredited by the Illinois Department of Public Health and the Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR763, Asbestos Hazard Emergency Response Act (AHERA) and TSCA Title II. This training course complies with the requirements of TSCA Title II and is accredited by the state of Wisconsin Department of Health Services under CH.DHS159, Wisconsin Administration Code.

Asbestos Abatement Building Inspector Refresher

Certificate: BIRWI1301110188

Location: 12304 75th Street Kenosha, WI 53142

Course Date: 1/11/2013

Examination Date: 1/11/2013

Expiration Date: 1/11/2014



Kathy DeSalvo/Director

2013



Occupational Training & Supply, Inc.

7233 Adams Street • Willowbrook, IL 60527 • (630) 655-3900

Steve Diblik

has successfully completed the 4 hour Asbestos Building Inspector Refresher Course and has passed the competency exam with a minimum score of 70%. This course is accredited by the **Illinois Department of Public Health** and the **Indiana Department of Environmental Management** for purposes of accreditation in accordance with EPA 40 CFR763, Asbestos Hazard Emergency Response Act (AHERA) and TSCA Title II. This training course complies with the requirements of TSCA Title II and is accredited by the state of Wisconsin **Department of Health Services** under CH.DHS159, Wisconsin Administration Code.

Asbestos Abatement Building Inspector Refresher

Certificate: BIRWI1301110170

Location: 12304 75th Street Kenosha, WI 53142

Course Date: 1/11/2013

Examination Date: 1/11/2013

Expiration Date: 1/11/2014

Issue Date: 1/11/2013



Duplicate Original

Kathy DeSalvo, Director

2013

Stephen Diblik

Illinois Licensed Asbestos Inspector, Management Planner,
Project Manager and Air Sampling Professional



ASBESTOS PROFESSIONAL LICENSE

ID NUMBER
100 - 05171

ISSUED
4/4/2012

EXPIRES
05/15/2013

STEPHEN C DIBLIK
300 W. Adams Street, Suite 120
Chicago, IL 60606

Environmental Health



ENDORSEMENTS

TC EXPIRES

INSPECTOR

1/13/2013

MANAGEMENT PLANNER

1/19/2013

PROJECT MANAGER

12/15/2012

AIR SAMPLING PROFESSIONAL

Alteration of this license shall result in legal action
This license issued under authority of the State of Illinois
Department of Public Health
This license is valid only when accompanied by a valid
training course certificate.

**CARNOW
CONIBEAR**



Occupational Training & Supply, Inc.

7233 Adams Street • Willowbrook, IL 60527 • (630) 655-3900

Asbestos Management Planner Refresher

Occupational Training and Supply, Inc. certifies that

Stephen Diblik

has successfully completed the 4 hour Asbestos Management Planner Refresher Course
and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department
of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance
with EPA 10 CFR 763 Asbestos Hazard Emergency Response Act (AHERA) and TSCA Title II.

Certificate: MPR1302250732

Exam Date: 2/25/2013

Course Date: 2/25/2013

Expiration Date: 2/25/2014


Kathy DeSalvo
Director

2013

APPENDIX C

Laboratory Accreditations

APPENDIX D

Laboratory Results

APPENDIX E

Chain of Custody Forms

Three-Year Reinspection Key to Terms

	CODE	KEY
MATERIAL		
	ACBM	Asbestos Containing Building Materials
MATERIAL CATEGORY		
	MISC	Miscellaneous
	SURF	Surfacing
	TSI	Thermal System Insulation
MATERIAL UNITS		
	LF	Linear Feet
	SF	Square Feet
	CF	Cubic Feet
DAMAGE TYPE		
	Loc	Localized
	Dist	Distributed