

**ILLINOIS DEPARTMENT OF PUBLIC HEALTH
AHERA THREE YEAR REINSPECTION
ASBESTOS ABATEMENT PROGRAM
SCHOOL INFORMATION FORM**

SECTION I

NAME OF SCHOOL DISTRICT: CHICAGO SCHOOL DIST 299
SCHOOL ID NUMBER: 14-016-2990-
SCHOOL NAME: Chicago Military Academy at Bronzeville
ADDRESS OF SCHOOL: 3516 South Giles Avenue
CITY: Chicago, IL, 60653

DATE LAST THREE YEAR REINSPECTION WAS COMPLETED **4/14/2010**

If the address on this form is different than the address of the building, submit a written explanation.

SECTION II *(Please type or print)*

PLEASE COMPLETE THE FOLLOWING FOR YOUR THREE YEAR REINSPECTION:

DATE REINSPECTION COMPLETED: 4/6/2013 ENROLLMENT 425
IDPH INSPECTOR LICENSE NUMBER: 100-04437
IDPH LICENSED INSPECTOR NAME (Please Print): Mary Hicks
IDPH MP LICENSE NUMBER: 100-05171
IDPH LICENSED MANAGEMENT PLANNER NAME (Please Print): Stephen Diblik

DESIGNATED PERSON (Please Print): Ms. Lynn Crivello PHONE: (773) 553-3113



4/6/2013

Signature of Designated Person

Date

SECTION III

PLEASE COMPLETE THE FOLLOWING INFORMATION FOR ANY CHANGES WITHIN THE SCHOOL DISTRICT.

School building has been sold. Date of Sale: _____

School has been closed. Date closed: _____

School building has been demolished. Date: _____

School building is asbestos free since last reinspection: _____

Please explain in writing why the school building is now asbestos free and include the supporting documentation.

If a new school building has been added to the district, submit either an exclusionary statement or a management plan and inspection report. Include the complete name, address and city of school building.

Explain in writing if the address of the building is different than the address on this form:

THREE-YEAR REINSPECTION

CHICAGO SCHOOL DIST 299

Chicago Military Academy at Bronzeville

3516 South Giles Avenue
Chicago, IL, 60653

Unit: 70070
Building ID: 1800

IDPH ID Number: 14-016-2990-

REPORT DATE:

Saturday, April 06, 2013

Prepared for:

Chicago Public Schools
125 S. Clark Street
Chicago, IL 60603

Prepared by:

Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone (312) 762-2900

Fax (312) 782-5145

**DO NOT REMOVE FROM SCHOOL
REQUIRED BY FEDERAL LAW**

March 25, 2013

Mr. R. Kent Cook
Asbestos Program
Illinois Department of Public Health
525 West Jefferson Street
Springfield, Illinois 62761

Re: Chicago Public Schools - 2013 Three-Year Reinspections

Dear Mr. Cook:

Carnow, Conibear and Associates, Managing Environmental Consultant (MEC), conducted the Three-Year Reinspections and performed management plan updates for the Chicago Public Schools (CPS) facilities in Region 3,4,5 Elementary Schools. Please update your records with the following information.

School District: 299 Unit: 70070 Region: 04 IDPH ID: 14-016-2990-

School: Chicago Military Academy at Bronzeville Building ID: 1800

Address: 3516 South Giles Avenue
Chicago, IL, 60653

Building Contact: Sutton Jr., Jonathan Contact Phone: 773-310-1536

Current Building Owners: Chicago Public Schools

Review Date: 4/6/2013

Inspector: Mary Hicks Inspector IDPH License: 100-04437
Management Planner: Stephen Diblik Management Planner IDPH License: 100-05171

If you have any questions or comments, please contact us at (312) 762-2900

Sincerely,
Carnow, Conibear and Associates



Stephen Diblik
100-05171

Environmental Notification to Occupants

To: Faculty, Staff and Parents
From: Chicago Public Schools
Date: March 25, 2013

RE: Chicago Military Academy at Bronzeville, Unit 70070
3516 South Giles Avenue
Chicago, IL, 60653

Dear Faculty, Staff and Parents,

This letter is to notify you that the 2013 asbestos three year re-inspection has been completed at Chicago Military Academy at Bronzeville , following the Federal Asbestos Hazard Emergency Response Act (AHERA), 40 CFR Part 763, Subpart E and is available for your review at the main office of the school.

Although asbestos-containing materials have been identified at Chicago Military Academy at Bronzeville, there is no reason to believe that any threat to the health of students or staff exists at this time. CPS will continue to carefully monitor the condition of asbestos-containing materials and if conditions warrant, all appropriate steps will be taken to maintain the health and safety of all building occupants.

If you have any questions regarding this matter or require additional information, please feel free to contact Ms. Lynn Crivello, the designated Local Education Authority's Designated Person at (773) 553-3113 .

Table of Contents

- I. School and Inspection Information
- II. Executive Summary
- III. Methodology
- IV. Abatement History
- V. Reassessments and Recommendations
- VI. Conclusions

Table I: Inspector's Reinspection Findings

Table II: Management Planner's Review

APPENDICES:

- Appendix A: Assessment Sheets, Drawings and Photos
- Appendix B: Inspector and Management Planner Licenses
- Appendix C: Laboratory Accreditations
- Appendix D: Laboratory Results
- Appendix E: Chain of Custody Forms

SCHOOL AND INSPECTION INFORMATION

1. School Information

School: Chicago Military Academy at Bronzeville Unit: 70070 Region: 04
Address: 3516 South Giles Avenue Chicago, IL, 60653
IDPH ID: 14-016-2990- Building ID: 1800
Contact: Sutton Jr., Jonathan Phone: 773-310-1536

2. Description of Facility

Original Construction: Additional Construction:
Total Square Footage: 127900 No of Floors:
Current Occupancy: 425

3. LEA Designated Person

Contact: Ms. Lynn Crivello Phone: (773) 553-3113
Address: 125 South Clark Street, 17th Floor
Chicago, IL 60603


4. Managing Environmental Consultant

MEC: Carnow, Conibear and Associates
Contact: Dan Juneau
Address 600 West Van Buren St., Ste 500
Phone: (312) 762-2900 Fax: (312) 782-5145

5. Inspector

Inspector Name: Mary Hicks


Inspector IDPH license # 100-04437

Signature: 
Date: 3/25/2013

6. Management Planner

Management Planner Name: Stephen Diblik


Management Planner IDPH license # 100-05171

Signature: 
Date: 4/6/2013

7. Review Date: 4/6/2013

8. LEA Designated Person's Acknowledgement

The reinspection report and recommendations have been received by me and appropriate action will be taken by the School District.

Signature: 

Date: 4/6/2013

Name: Ms. Lynn Crivello

II. EXECUTIVE SUMMARY

Carnow, Conibear and Associates was retained by the Chicago Public Schools (CPS) to perform a three-year asbestos reinspection of the Chicago Military Academy at Bronzeville. This inspection was conducted in accordance with the United States Environmental Protection Agency (USEPA) Asbestos Hazard Emergency Response Act (AHERA) part 763.92 (b), and the ongoing Operations and Maintenance Program (O&M) originally designed in the School's Asbestos Management Plan. The purpose of this three-year reinspection is to record any condition changes in the asbestos-containing building material (ACBM) in the school since the previous three-year reinspection and the six-month periodic surveillance, to identify, assess, and include any Homogeneous Areas (HA) not identified in the Management Plan, and to recommend an appropriate response action to manage asbestos.

The inspector conducted a three-year reinspection of this facility under Illinois Department of Public Health (IDPH) school reinspection requirements and AHERA, sections 763.85 and 763.88. The main building and each addition to the main building, if constructed at different dates, were inspected separately. Laboratory accreditations are included in Appendix C, laboratory results are included in Appendix D, and chain of custody forms are included in Appendix E.

Note: During previous inspections, some of the HA(s) were identified together as 9" x 9" floor tile (FT), mastics assoc. with 9" x 9" FT, 12" x 12" FT, mastics assoc. with 12" x 12" FT, pipe insulation, etc. Some of these HA(s) have been re-identified by areas that are uniform in color, texture, construction date, application date, and general appearance.

The inspector has determined the following:

A. The following HAs have changed assessment categories for Building 1800:

001	2' x 2' Lay In Ceiling Panels
002	4" Green Vinyl Baseboard
003	4" Green Vinyl Baseboard Adhesive
004	4" Blue Vinyl Baseboard
005	4" Blue Vinyl Baseboard Adhesive
006	4" Gray Vinyl Baseboard
007	4" Gray Vinyl Baseboard Adhesive
008	4" Blond Vinyl Baseboard
009	4" Blond Vinyl Baseboard Adhesive

010	1" Light Brown Ceramic Tile Grout
011	1" Light Brown Ceramic Tile Grout Adhesive
012	Drywall
013	Drywall Compound
014	12" x 12" Blue/Gray Streaked Floor Tile
015	12" x 12" Blue/Gray Streaked Floor Tile Mastic
016	12" x 12" Green Mix Floor Tile
017	12" x 12" Green Mix Floor Tile Mastic
019	12" x 12" Blond Floor Tile Mastic
020	12" x 12" Gray Mix Floor Tile
021	12" x 12" Gray Mix Floor Tile Mastic
022	Quarry Tile Grout
023	Duct Sealant
024	Adhesive
25	Carpet Adhesive

B. The following new homogenous areas have been identified for Building 1800:

C. This reinspection covered only physically accessible and visible areas and materials that were identified in the LEA's management plan. The following materials were concealed and/or contained in areas that were inaccessible for sampling and have been classified as Assumed:

001	2' x 2' Lay In Ceiling Panels
002	4" Green Vinyl Baseboard
003	4" Green Vinyl Baseboard Adhesive
004	4" Blue Vinyl Baseboard
005	4" Blue Vinyl Baseboard Adhesive
006	4" Gray Vinyl Baseboard
007	4" Gray Vinyl Baseboard Adhesive
008	4" Blond Vinyl Baseboard
009	4" Blond Vinyl Baseboard Adhesive
010	1" Light Brown Ceramic Tile Grout
011	1" Light Brown Ceramic Tile Grout Adhesive
012	Drywall
013	Drywall Compound
014	12" x 12" Blue/Gray Streaked Floor Tile
015	12" x 12" Blue/Gray Streaked Floor Tile Mastic
016	12" x 12" Green Mix Floor Tile
017	12" x 12" Green Mix Floor Tile Mastic
018	12" x 12" Blond Floor Tile
019	12" x 12" Blond Floor Tile Mastic
020	12" x 12" Gray Mix Floor Tile
021	12" x 12" Gray Mix Floor Tile Mastic
022	Quarry Tile Grout
023	Duct Sealant
024	Adhesive
25	Carpet Adhesive
26	Green, Red and Gray Terrazzo
27	12"x12" White w/Blue Floor Tile
28	12"x12" White w/Blue Floor Tile Mastic
HA-100	2'x4' white ceiling tile

The following areas were deemed to be inaccessible:

003	4" Green Vinyl Baseboard Adhesive
005	4" Blue Vinyl Baseboard Adhesive
007	4" Gray Vinyl Baseboard Adhesive
009	4" Blond Vinyl Baseboard Adhesive
010	1" Light Brown Ceramic Tile Grout
011	1" Light Brown Ceramic Tile Grout Adhesive
013	Drywall Compound
015	12" x 12" Blue/Gray Streaked Floor Tile Mastic
017	12" x 12" Green Mix Floor Tile Mastic
019	12" x 12" Blond Floor Tile Mastic

021	12" x 12" Gray Mix Floor Tile Mastic
022	Quarry Tile Grout
023	Duct Sealant
024	Adhesive
28	12"x12" White w/Blue Floor Tile Mastic

Materials were also listed as "assumed" if they were in good condition and sampling was not conducted to avoid damage.

This reinspection was conducted by Mary Hicks, IDPH License # 100-04437. The Management Plan was updated by Stephen Diblik, IDPH License # 100-05171. Inspector and Management Planner Licenses are included in Appendix B.

III. METHODOLOGY

Tasks performed on-site included the following:

1. Review current management plan, identify HA(s) and extract appropriate information.
2. Examine and verify abatement records.
3. Touch and visually and physically reinspect and reassess the condition of all friable known or assumed ACBM.
4. Touch and visually and physically reinspect all non-friable known or assumed ACBM to determine whether these materials have become friable since the last inspection or periodic surveillance.
5. Identify any condition changes that may affect Hazard Ranking of known ACBM or Assumed ACBM, as well as any HA(s) that have become friable since the last reinspection.
6. Collect bulk samples from each newly discovered friable HA or previously assumed and submit for laboratory analysis.
7. Tabulate reinspection findings and submit for management planner review and recommendations with appropriate response actions based on the AHERA Damage Category of the ACBM.
8. Submit reinspection findings and management planner recommendations to the LEA within thirty (30) days for inclusion into the management plan.

IV. ABATEMENT HISTORY

The information collected from the existing management plan and inspection report(s) and from interviews with the school official revealed that the following asbestos abatement was conducted at the school since the previous Three year Reinspection.

Abatement Dates:

V. REASSESSMENTS AND RECOMMENDATIONS

The reassessments and recommendations are summarized in Tables I and II on the following pages. Detailed Hazard Assessment Sheets and Drawings and Photos (if applicable) are included in Appendix A.

VI. CONCLUSIONS

The Chicago Military Academy at Bronzeville Building 1800 Three-Year reinspection has been completed and response actions have been recommended for both friable and non-friable materials. A timely execution of the response actions recommended will enable the LEA and the Designated Person(s) to effectively manage the existing ACBM.

This three-year reinspection report should be inspected in the current Management plan at the CPS Central Office, and one (1) copy should be kept at the school for use when planning any renovation and/or demolition activities in areas where ACBM has been identified. Also, periodic surveillance documentation and any summary reports from any response actions that are executed at the school should be used to update the Management Plan.

Table I
Inspector's Reinspection Findings

Chicago Public Schools

School Chicago Military Academy at Bronzeville Unit 70070 Building ID 1800
 Address 3516 South Giles Avenue Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
001	2' x 2' Lay In Ceiling Panels	80,000	SF	Throughout Facility	ASSUMED	MISC	N	NONE	0		Yes	Any remaining friable ACBM or friable suspect ACBM		LOW
002	4" Green Vinyl Baseboard	700	LF	1st Floor Corridors, Classrooms, Alcoves & Offices	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
003	4" Green Vinyl Baseboard Adhesive	700	LF	1st Floor Corridors, Classrooms, Alcoves & Offices	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
004	4" Blue Vinyl Baseboard	400	LF	1st Floor Southeast and Southwest Stairways	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
005	4" Blue Vinyl Baseboard Adhesive	400	SF	1st Floor Southeast and Southwest Stairways	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
006	4" Gray Vinyl Baseboard	800	LF	3rd Floor Corridors, Classrooms, Alcoves & Offices	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
007	4" Gray Vinyl Baseboard Adhesive	800	SF	3rd Floor Corridors, Classrooms, Alcoves & Offices	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
008	4" Blond Vinyl Baseboard	500	LF	2nd Floor Corridors, Lunchroom, Kitchen, Classrooms, Alcoves & Offices	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
009	4" Blond Vinyl Baseboard Adhesive	500	SF	2nd Floor Corridors, Lunchroom, Kitchen, Classrooms, Alcoves & Offices	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
01	9" x 9" Black Vinyl Floor Tile - REMOVED					MISC								
010	1" Light Brown Ceramic Tile Grout	1,800	SF	1st, 2nd & 3rd Floor Washrooms	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
011	1" Light Brown Ceramic Tile Grout Adhesive	1,800	SF	1st, 2nd & 3rd Floor Washrooms	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
012	Drywall	30,000	SF	Throughout Facility	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
013	Drywall Compound	30,000	SF	Throughout Facility	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
014	12" x 12" Blue/Gray Streaked Floor Tile	2,000	SF	1st Floor SE & SW Stairways and Kitchen	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW

Chicago Public Schools

School Chicago Military Academy at Bronzeville Unit 70070 Building ID 1800
 Address 3516 South Giles Avenue Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
015	12" x 12" Blue/Gray Streaked Floor Tile Mastic	2,000	SF	1st Floor SE & SW Stairways and Kitchen	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
016	12" x 12" Green Mix Floor Tile	3,000	SF	Classrooms 110, 111, 112 & 113	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
017	12" x 12" Green Mix Floor Tile Mastic	3,000	SF	Classrooms 110, 111, 112 & 113	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
018	12" x 12" Blond Floor Tile	4,000	SF	2nd Floor Corridors, Lunchroom, Kitchen, Classrooms, Alcoves & Offices	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
019	12" x 12" Blond Floor Tile Mastic	4,000	SF	2nd Floor Corridors, Lunchroom, Kitchen, Classrooms, Alcoves & Offices	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
020	12" x 12" Gray Mix Floor Tile	10,800	SF	2nd & 3rd Floor Classrooms, Corridors, Stairways, Alcoves, Kitchen, Kitchen Office & Cafeteria	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
021	12" x 12" Gray Mix Floor Tile Mastic	10,800	SF	2nd & 3rd Floor Classrooms, Corridors, Stairways, Alcoves, Kitchen, Kitchen Office & Cafeteria	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
022	Quarry Tile Grout	500	SF	1st Floor Corridor	ASSUMED	MISC	Y	NONE	0		Yes	ACBM with the potential for damage		LOW
023	Duct Sealant	2,000	SF	Basement	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
024	Adhesive	700	SF	Beneath All Marker Boards in the Facility	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
25	Carpet Adhesive	2,400	SF	Offices, Media Center, Conference Room, 204, 304	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
26	Green, Red and Gray Terrazzo	10,000	SF	Entrance, stairwells, and hallways	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
27	12"x12" White w/Blue Floor Tile	40	SF	Elevator	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
28	12"x12" White w/Blue Floor Tile Mastic	40	SF	Elevator	ASSUMED	MISC	N	NONE	0		No	ACBM with the		LOW

Chicago Public Schools

School Chicago Military Academy at Bronzeville Unit 70070 Building ID 1800
 Address 3516 South Giles Avenue Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
HA-100	2'x4' white ceiling tile	5,000	SF	throughout the building	ASSUMED	MISC	Y	NONE	0		No	potential for damage Any remaining friable ACBM or friable suspect ACBM		LOW

Chicago Public Schools

School Chicago Military Academy at Bronzeville Unit 70070 Building ID 1800
Address 3516 South Giles Avenue Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

Reinspection Date 3/25/2013
Inspector Name Mary Hicks
100-04437 5/15/2013
Inspector's IDPH License Number / Expiration Date

Inspector's Comments

HA Number:	Inspector Comments:
001	
002	
003	
004	
005	
006	
007	
008	
009	
01	Removed.
010	
011	
012	
013	
014	
015	
016	
017	
018	
019	
020	
021	
022	
023	

Chicago Public Schools

School Chicago Military Academy at Bronzeville **Unit** 70070 **Building ID** 1800
Address 3516 South Giles Avenue **Region** 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
024	
25	Room 304 has Gray Floor Tile
26	
27	
28	
HA-100	

Table II

Management Planner's Review

Chicago Public Schools

School Chicago Military Academy
at Bronzeville

Unit 70070

Building ID 1800

Address 3516 South Giles Avenue

Chicago, IL, 60653

Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
001	2' x 2' Lay In Ceiling Panels	80,000	SF	Throughout Facility	Assumed	MISC	No	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Operations and Maintenance
002	4" Green Vinyl Baseboard	700	LF	1st Floor Corridors, Classrooms, Alcoves & Offices	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Operations and Maintenance
003	4" Green Vinyl Baseboard Adhesive	700	LF	1st Floor Corridors, Classrooms, Alcoves & Offices	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Operations and Maintenance
004	4" Blue Vinyl Baseboard	400	LF	1st Floor Southeast and Southwest Stairways	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Operations and Maintenance
005	4" Blue Vinyl Baseboard Adhesive	400	SF	1st Floor Southeast and Southwest Stairways	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
006	4" Gray Vinyl Baseboard	800	LF	3rd Floor Corridors, Classrooms, Alcoves & Offices	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Operations and Maintenance
007	4" Gray Vinyl Baseboard Adhesive	800	SF	3rd Floor Corridors, Classrooms, Alcoves & Offices	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
008	4" Blond Vinyl Baseboard	500	LF	2nd Floor Corridors, Lunchroom, Kitchen, Classrooms, Alcoves & Offices	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Operations and Maintenance
009	4" Blond Vinyl Baseboard Adhesive	500	SF	2nd Floor Corridors, Lunchroom, Kitchen, Classrooms, Alcoves & Offices	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
01	9" x 9" Black Vinyl Floor Tile - REMOVED					MISC					
010	1" Light Brown Ceramic Tile Grout	1,800	SF	1st, 2nd & 3rd Floor Washrooms	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
011	1" Light Brown Ceramic Tile Grout Adhesive	1,800	SF	1st, 2nd & 3rd Floor Washrooms	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
012	Drywall	30,000	SF	Throughout Facility	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
013	Drywall Compound	30,000	SF	Throughout Facility	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
014	12" x 12" Blue/Gray Streaked Floor Tile	2,000	SF	1st Floor SE & SW Stairways and Kitchen	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
015	12" x 12" Blue/Gray Streaked Floor Tile Mastic	2,000	SF	1st Floor SE & SW Stairways and Kitchen	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
016	12" x 12" Green Mix Floor Tile	3,000	SF	Classrooms 110, 111, 112 & 113	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
017	12" x 12" Green Mix Floor Tile Mastic	3,000	SF	Classrooms 110, 111, 112 & 113	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
018	12" x 12" Blond Floor Tile	4,000	SF	2nd Floor Corridors, Lunchroom, Kitchen, Classrooms, Alcoves & Offices	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
019	12" x 12" Blond Floor Tile Mastic	4,000	SF	2nd Floor Corridors, Lunchroom, Kitchen, Classrooms, Alcoves & Offices	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
020	12" x 12" Gray Mix Floor Tile	10,800	SF	2nd & 3rd Floor Classrooms, Corridors, Stairways, Alcoves, Kitchen, Kitchen	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance

Chicago Public Schools

School Chicago Military Academy
at Bronzeville

Unit 70070

Building ID 1800

Address 3516 South Giles Avenue

Chicago, IL, 60653

Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
				Office & Cafeteria							
021	12" x 12" Gray Mix Floor Tile Mastic	10,800	SF	2nd & 3rd Floor Classrooms, Corridors, Stairways, Alcoves, Kitchen, Kitchen Office & Cafeteria	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
022	Quarry Tile Grout	500	SF	1st Floor Corridor	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
023	Duct Sealant	2,000	SF	Basement	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
024	Adhesive	700	SF	Beneath All Marker Boards in the Facility	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
25	Carpet Adhesive	2,400	SF	Offices, Media Center, Conference Room, 204, 304	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
26	Green, Red and Gray Terrazzo	10,000	SF	Entrance, stairwells, and hallways	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
27	12"x12" White w/Blue Floor Tile	40	SF	Elevator	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
28	12"x12" White w/Blue Floor Tile Mastic	40	SF	Elevator	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
HA-100	2'x4' white ceiling tile	5,000	SF	throughout the building	Assumed	MISC	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Operations and Maintenance

Chicago Public Schools

School Chicago Military Academy
at Bronzeville

Unit 70070

Building ID 1800

Address 3516 South Giles Avenue

Chicago, IL, 60653

Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

Review Date	4/6/2013
Manager Planner Name	Stephen Diblik
100-05171	5/15/2013
Manager IDPH License No/Expiration	

HA Number	Management Comments
001	
002	
003	
004	
005	
006	
007	
008	
009	
01	
010	
011	
012	
013	
014	
015	
016	
017	
018	
019	
020	

Chicago Public Schools

School Chicago Military Academy
at Bronzeville

Unit 70070

Building ID 1800

Address 3516 South Giles Avenue

Chicago, IL, 60653

Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
021	
022	
023	
024	
25	
26	
27	
28	
HA-100	

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **70070** BUIDLING ID: **1800**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mary Hicks**
SCHOOL NAME: **Chicago Military Academy at
Bronzeville** INSPECTION DATE: **3/25/2013**
ADDRESS: **3516 South Giles Avenue** IDPH LICENSE NO: **100-04437**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **001**
MATERIAL DESCRIPTION: **2' x 2' Lay In Ceiling Panels**
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Throughout Facility**

MATERIAL QUANTITY: **80000**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/25/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **70070** BUIDLING ID: **1800**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**
SCHOOL NAME: **Chicago Military Academy at Bronzeville** REVIEW DATE: **4/6/2013**
ADDRESS: **3516 South Giles Avenue** IDPH LICENSE NO: **100-04437**

HOMOGENEOUS AREA: **001**
MATERIAL DESCRIPTION: **2' x 2' Lay In Ceiling Panels**
MATERIAL LOCATION: **Throughout Facility**
MATERIAL QUANTITY: **80000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____

Stephen Diblik

Date: **04/06/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **70070** BUIDLING ID: **1800**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mary Hicks**
SCHOOL NAME: **Chicago Military Academy at
Bronzeville** INSPECTION DATE: **3/25/2013**
ADDRESS: **3516 South Giles Avenue** IDPH LICENSE NO: **100-04437**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **002**
MATERIAL DESCRIPTION: **4" Green Vinyl Baseboard**
HISTORICAL AHERA DAMAGE CATEGORY **6**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1st Floor Corridors, Classrooms, Alcoves & Offices**
MATERIAL QUANTITY: **700** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature:



Date: **03/25/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **70070** BUIDLING ID: **1800**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**
SCHOOL NAME: **Chicago Military Academy at Bronzeville** REVIEW DATE: **4/6/2013**
ADDRESS: **3516 South Giles Avenue** IDPH LICENSE NO: **100-04437**

HOMOGENEOUS AREA: **002**
MATERIAL DESCRIPTION: **4" Green Vinyl Baseboard**
MATERIAL LOCATION: **1st Floor Corridors, Classrooms, Alcoves & Offices**
MATERIAL QUANTITY: **700** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____

Stephen Diblik

Date: **04/06/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **70070** BUIDLING ID: **1800**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mary Hicks**
SCHOOL NAME: **Chicago Military Academy at
Bronzeville** INSPECTION DATE: **3/25/2013**
ADDRESS: **3516 South Giles Avenue** IDPH LICENSE NO: **100-04437**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **003**
MATERIAL DESCRIPTION: **4" Green Vinyl Baseboard Adhesive**
HISTORICAL AHERA DAMAGE CATEGORY **6**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **1st Floor Corridors, Classrooms, Alcoves & Offices**

MATERIAL QUANTITY: **700** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature:



Date: **03/25/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **70070** BUIDLING ID: **1800**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**
SCHOOL NAME: **Chicago Military Academy at Bronzeville** REVIEW DATE: **4/6/2013**
ADDRESS: **3516 South Giles Avenue** IDPH LICENSE NO: **100-04437**

HOMOGENEOUS AREA: **003**
MATERIAL DESCRIPTION: **4" Green Vinyl Baseboard Adhesive**
MATERIAL LOCATION: **1st Floor Corridors, Classrooms, Alcoves & Offices**
MATERIAL QUANTITY: **700** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____

Stephen Diblik

Date: **04/06/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **70070** BUIDLING ID: **1800**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mary Hicks**
SCHOOL NAME: **Chicago Military Academy at
Bronzeville** INSPECTION DATE: **3/25/2013**
ADDRESS: **3516 South Giles Avenue** IDPH LICENSE NO: **100-04437**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **004**
MATERIAL DESCRIPTION: **4" Blue Vinyl Baseboard**
HISTORICAL AHERA DAMAGE CATEGORY **6**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **1st Floor Southeast and Southwest Stairways**

MATERIAL QUANTITY: **400** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature:

Mary Hicks

Date: **03/25/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **70070** BUIDLING ID: **1800**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**
SCHOOL NAME: **Chicago Military Academy at Bronzeville** REVIEW DATE: **4/6/2013**
ADDRESS: **3516 South Giles Avenue** IDPH LICENSE NO: **100-04437**

HOMOGENEOUS AREA: **004**
MATERIAL DESCRIPTION: **4" Blue Vinyl Baseboard**
MATERIAL LOCATION: **1st Floor Southeast and Southwest Stairways**
MATERIAL QUANTITY: **400** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____

Stephen Diblik

Date: **04/06/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **70070** BUIDLING ID: **1800**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mary Hicks**
SCHOOL NAME: **Chicago Military Academy at
Bronzeville** INSPECTION DATE: **3/25/2013**
ADDRESS: **3516 South Giles Avenue** IDPH LICENSE NO: **100-04437**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **005**
MATERIAL DESCRIPTION: **4" Blue Vinyl Baseboard Adhesive**
HISTORICAL AHERA DAMAGE CATEGORY **6**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1st Floor Southeast and Southwest Stairways**
MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/25/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **70070** BUIDLING ID: **1800**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**
SCHOOL NAME: **Chicago Military Academy at Bronzeville** REVIEW DATE: **4/6/2013**
ADDRESS: **3516 South Giles Avenue** IDPH LICENSE NO: **100-04437**

HOMOGENEOUS AREA: **005**
MATERIAL DESCRIPTION: **4" Blue Vinyl Baseboard Adhesive**
MATERIAL LOCATION: **1st Floor Southeast and Southwest Stairways**
MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____

Stephen Diblik

Date: **04/06/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **70070** BUIDLING ID: **1800**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mary Hicks**
SCHOOL NAME: **Chicago Military Academy at
Bronzeville** INSPECTION DATE: **3/25/2013**
ADDRESS: **3516 South Giles Avenue** IDPH LICENSE NO: **100-04437**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **006**
MATERIAL DESCRIPTION: **4" Gray Vinyl Baseboard**
HISTORICAL AHERA DAMAGE CATEGORY **6**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **3rd Floor Corridors, Classrooms, Alcoves & Offices**

MATERIAL QUANTITY: **800** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature:

Mary Hicks

Date: **03/25/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **70070** BUILDING ID: **1800**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**
SCHOOL NAME: **Chicago Military Academy at Bronzeville** REVIEW DATE: **4/6/2013**
ADDRESS: **3516 South Giles Avenue** IDPH LICENSE NO: **100-04437**

HOMOGENEOUS AREA: **006**
MATERIAL DESCRIPTION: **4" Gray Vinyl Baseboard**
MATERIAL LOCATION: **3rd Floor Corridors, Classrooms, Alcoves & Offices**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____

Stephen Diblik

Date: **04/06/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **70070** BUIDLING ID: **1800**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mary Hicks**
SCHOOL NAME: **Chicago Military Academy at
Bronzeville** INSPECTION DATE: **3/25/2013**
ADDRESS: **3516 South Giles Avenue** IDPH LICENSE NO: **100-04437**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **007**
MATERIAL DESCRIPTION: **4" Gray Vinyl Baseboard Adhesive**
HISTORICAL AHERA DAMAGE CATEGORY **6**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **3rd Floor Corridors, Classrooms, Alcoves & Offices**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature:



Date: **03/25/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **70070** BUIDLING ID: **1800**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**
SCHOOL NAME: **Chicago Military Academy at Bronzeville** REVIEW DATE: **4/6/2013**
ADDRESS: **3516 South Giles Avenue** IDPH LICENSE NO: **100-04437**

HOMOGENEOUS AREA: **007**
MATERIAL DESCRIPTION: **4" Gray Vinyl Baseboard Adhesive**
MATERIAL LOCATION: **3rd Floor Corridors, Classrooms, Alcoves & Offices**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____

Stephen Diblik

Date: **04/06/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **70070** BUIDLING ID: **1800**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mary Hicks**
SCHOOL NAME: **Chicago Military Academy at
Bronzeville** INSPECTION DATE: **3/25/2013**
ADDRESS: **3516 South Giles Avenue** IDPH LICENSE NO: **100-04437**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **008**
MATERIAL DESCRIPTION: **4" Blond Vinyl Baseboard**
HISTORICAL AHERA DAMAGE CATEGORY **6**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **2nd Floor Corridors, Lunchroom, Kitchen, Classrooms, Alcoves & Offices**
MATERIAL QUANTITY: **500** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature:



Date: **03/25/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **70070** BUIDLING ID: **1800**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**
SCHOOL NAME: **Chicago Military Academy at Bronzeville** REVIEW DATE: **4/6/2013**
ADDRESS: **3516 South Giles Avenue** IDPH LICENSE NO: **100-04437**

HOMOGENEOUS AREA: **008**
MATERIAL DESCRIPTION: **4" Blond Vinyl Baseboard**
MATERIAL LOCATION: **2nd Floor Corridors, Lunchroom, Kitchen, Classrooms, Alcoves & Offices**
MATERIAL QUANTITY: **500** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____

Stephen Diblik

Date: **04/06/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **70070** BUIDLING ID: **1800**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mary Hicks**
SCHOOL NAME: **Chicago Military Academy at
Bronzeville** INSPECTION DATE: **3/25/2013**
ADDRESS: **3516 South Giles Avenue** IDPH LICENSE NO: **100-04437**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **009**
MATERIAL DESCRIPTION: **4" Blond Vinyl Baseboard Adhesive**
HISTORICAL AHERA DAMAGE CATEGORY **6**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **2nd Floor Corridors, Lunchroom, Kitchen, Classrooms, Alcoves & Offices**
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:

Mary Hicks

Date: **03/25/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **70070** BUIDLING ID: **1800**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**
SCHOOL NAME: **Chicago Military Academy at Bronzeville** REVIEW DATE: **4/6/2013**
ADDRESS: **3516 South Giles Avenue** IDPH LICENSE NO: **100-04437**

HOMOGENEOUS AREA: **009**
MATERIAL DESCRIPTION: **4" Blond Vinyl Baseboard Adhesive**
MATERIAL LOCATION: **2nd Floor Corridors, Lunchroom, Kitchen, Classrooms, Alcoves & Offices**
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____

Stephen Diblik

Date: **04/06/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **70070** BUIDLING ID: **1800**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mary Hicks**
SCHOOL NAME: **Chicago Military Academy at
Bronzeville** INSPECTION DATE: **3/25/2013**
ADDRESS: **3516 South Giles Avenue** IDPH LICENSE NO: **100-04437**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **01**
MATERIAL DESCRIPTION: **9" x 9" Black Vinyl Floor Tile - REMOVED**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION:

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Removed.**

Inspector's Signature:

Mary Hicks

Date: **03/25/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **70070** BUIDLING ID: **1800**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**
SCHOOL NAME: **Chicago Military Academy at Bronzeville** REVIEW DATE: **4/6/2013**
ADDRESS: **3516 South Giles Avenue** IDPH LICENSE NO: **100-04437**

HOMOGENEOUS AREA: **01**

MATERIAL DESCRIPTION: **9" x 9" Black Vinyl Floor Tile - REMOVED**

MATERIAL LOCATION:

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____

Stephen Diblik

Date: **04/06/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **70070** BUIDLING ID: **1800**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mary Hicks**
SCHOOL NAME: **Chicago Military Academy at
Bronzeville** INSPECTION DATE: **3/25/2013**
ADDRESS: **3516 South Giles Avenue** IDPH LICENSE NO: **100-04437**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **010**
MATERIAL DESCRIPTION: **1" Light Brown Ceramic Tile Grout**
HISTORICAL AHERA DAMAGE CATEGORY **6**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **1st, 2nd & 3rd Floor Washrooms**

MATERIAL QUANTITY: **1800**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/25/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **70070** BUIDLING ID: **1800**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**
SCHOOL NAME: **Chicago Military Academy at Bronzeville** REVIEW DATE: **4/6/2013**
ADDRESS: **3516 South Giles Avenue** IDPH LICENSE NO: **100-04437**

HOMOGENEOUS AREA: **010**
MATERIAL DESCRIPTION: **1" Light Brown Ceramic Tile Grout**
MATERIAL LOCATION: **1st, 2nd & 3rd Floor Washrooms**
MATERIAL QUANTITY: **1800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:

Stephen Diblik

Date: **04/06/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **70070** BUIDLING ID: **1800**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mary Hicks**
SCHOOL NAME: **Chicago Military Academy at
Bronzeville** INSPECTION DATE: **3/25/2013**
ADDRESS: **3516 South Giles Avenue** IDPH LICENSE NO: **100-04437**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **011**
MATERIAL DESCRIPTION: **1" Light Brown Ceramic Tile Grout Adhesive**
HISTORICAL AHERA DAMAGE CATEGORY **6**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1st, 2nd & 3rd Floor Washrooms**
MATERIAL QUANTITY: **1800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature:



Date: **03/25/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **70070** BUIDLING ID: **1800**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**
SCHOOL NAME: **Chicago Military Academy at Bronzeville** REVIEW DATE: **4/6/2013**
ADDRESS: **3516 South Giles Avenue** IDPH LICENSE NO: **100-04437**

HOMOGENEOUS AREA: **011**
MATERIAL DESCRIPTION: **1" Light Brown Ceramic Tile Grout Adhesive**
MATERIAL LOCATION: **1st, 2nd & 3rd Floor Washrooms**
MATERIAL QUANTITY: **1800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____

Stephen Diblik

Date: **04/06/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **70070** BUIDLING ID: **1800**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mary Hicks**
SCHOOL NAME: **Chicago Military Academy at
Bronzeville** INSPECTION DATE: **3/25/2013**
ADDRESS: **3516 South Giles Avenue** IDPH LICENSE NO: **100-04437**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **012**
MATERIAL DESCRIPTION: **Drywall**
HISTORICAL AHERA DAMAGE CATEGORY **6**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Throughout Facility**
MATERIAL QUANTITY: **30000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature:



Date: **03/25/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **70070** BUILDING ID: **1800**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**
SCHOOL NAME: **Chicago Military Academy at Bronzeville** REVIEW DATE: **4/6/2013**
ADDRESS: **3516 South Giles Avenue** IDPH LICENSE NO: **100-04437**

HOMOGENEOUS AREA: **012**
MATERIAL DESCRIPTION: **Drywall**
MATERIAL LOCATION: **Throughout Facility**
MATERIAL QUANTITY: **30000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____

Stephen Diblik

Date: **04/06/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **70070** BUIDLING ID: **1800**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mary Hicks**
SCHOOL NAME: **Chicago Military Academy at
Bronzeville** INSPECTION DATE: **3/25/2013**
ADDRESS: **3516 South Giles Avenue** IDPH LICENSE NO: **100-04437**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **013**
MATERIAL DESCRIPTION: **Drywall Compound**
HISTORICAL AHERA DAMAGE CATEGORY **6**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Throughout Facility**
MATERIAL QUANTITY: **30000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____

Mary Hicks

Date: 03/25/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **70070** BUIDLING ID: **1800**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**
SCHOOL NAME: **Chicago Military Academy at Bronzeville** REVIEW DATE: **4/6/2013**
ADDRESS: **3516 South Giles Avenue** IDPH LICENSE NO: **100-04437**

HOMOGENEOUS AREA: **013**
MATERIAL DESCRIPTION: **Drywall Compound**
MATERIAL LOCATION: **Throughout Facility**
MATERIAL QUANTITY: **30000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____

Stephen Diblik

Date: **04/06/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **70070** BUIDLING ID: **1800**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mary Hicks**
SCHOOL NAME: **Chicago Military Academy at
Bronzeville** INSPECTION DATE: **3/25/2013**
ADDRESS: **3516 South Giles Avenue** IDPH LICENSE NO: **100-04437**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **014**
MATERIAL DESCRIPTION: **12" x 12" Blue/Gray Streaked Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1st Floor SE & SW Stairways and Kitchen**
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature:



Date: **03/25/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **70070** BUILDING ID: **1800**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**
SCHOOL NAME: **Chicago Military Academy at Bronzeville** REVIEW DATE: **4/6/2013**
ADDRESS: **3516 South Giles Avenue** IDPH LICENSE NO: **100-04437**

HOMOGENEOUS AREA: **014**
MATERIAL DESCRIPTION: **12" x 12" Blue/Gray Streaked Floor Tile**
MATERIAL LOCATION: **1st Floor SE & SW Stairways and Kitchen**
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____

Stephen Diblik

Date: **04/06/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **70070** BUIDLING ID: **1800**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mary Hicks**
SCHOOL NAME: **Chicago Military Academy at
Bronzeville** INSPECTION DATE: **3/25/2013**
ADDRESS: **3516 South Giles Avenue** IDPH LICENSE NO: **100-04437**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **015**
MATERIAL DESCRIPTION: **12" x 12" Blue/Gray Streaked Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1st Floor SE & SW Stairways and Kitchen**
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature:



Date: **03/25/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **70070** BUIDLING ID: **1800**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**
SCHOOL NAME: **Chicago Military Academy at Bronzeville** REVIEW DATE: **4/6/2013**
ADDRESS: **3516 South Giles Avenue** IDPH LICENSE NO: **100-04437**

HOMOGENEOUS AREA: **015**
MATERIAL DESCRIPTION: **12" x 12" Blue/Gray Streaked Floor Tile Mastic**
MATERIAL LOCATION: **1st Floor SE & SW Stairways and Kitchen**
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____

Stephen Diblik

Date: **04/06/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **70070** BUIDLING ID: **1800**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mary Hicks**
SCHOOL NAME: **Chicago Military Academy at
Bronzeville** INSPECTION DATE: **3/25/2013**
ADDRESS: **3516 South Giles Avenue** IDPH LICENSE NO: **100-04437**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **016**
MATERIAL DESCRIPTION: **12" x 12" Green Mix Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Classrooms 110, 111, 112 & 113**

MATERIAL QUANTITY: **3000**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/25/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **70070** BUIDLING ID: **1800**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**
SCHOOL NAME: **Chicago Military Academy at Bronzeville** REVIEW DATE: **4/6/2013**
ADDRESS: **3516 South Giles Avenue** IDPH LICENSE NO: **100-04437**

HOMOGENEOUS AREA: **016**
MATERIAL DESCRIPTION: **12" x 12" Green Mix Floor Tile**
MATERIAL LOCATION: **Classrooms 110, 111, 112 & 113**
MATERIAL QUANTITY: **3000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____

Stephen Diblik

Date: **04/06/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **70070** BUIDLING ID: **1800**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mary Hicks**
SCHOOL NAME: **Chicago Military Academy at
Bronzeville** INSPECTION DATE: **3/25/2013**
ADDRESS: **3516 South Giles Avenue** IDPH LICENSE NO: **100-04437**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **017**
MATERIAL DESCRIPTION: **12" x 12" Green Mix Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Classrooms 110, 111, 112 & 113**
MATERIAL QUANTITY: **3000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature:



Date: **03/25/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **70070** BUIDLING ID: **1800**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**
SCHOOL NAME: **Chicago Military Academy at Bronzeville** REVIEW DATE: **4/6/2013**
ADDRESS: **3516 South Giles Avenue** IDPH LICENSE NO: **100-04437**

HOMOGENEOUS AREA: **017**
MATERIAL DESCRIPTION: **12" x 12" Green Mix Floor Tile Mastic**
MATERIAL LOCATION: **Classrooms 110, 111, 112 & 113**
MATERIAL QUANTITY: **3000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____

Stephen Diblik

Date: **04/06/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **70070** BUIDLING ID: **1800**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mary Hicks**
SCHOOL NAME: **Chicago Military Academy at
Bronzeville** INSPECTION DATE: **3/25/2013**
ADDRESS: **3516 South Giles Avenue** IDPH LICENSE NO: **100-04437**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **018**
MATERIAL DESCRIPTION: **12" x 12" Blond Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **2nd Floor Corridors, Lunchroom, Kitchen, Classrooms, Alcoves & Offices**
MATERIAL QUANTITY: **4000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature:



Date: **03/25/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **70070** BUIDLING ID: **1800**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**
SCHOOL NAME: **Chicago Military Academy at Bronzeville** REVIEW DATE: **4/6/2013**
ADDRESS: **3516 South Giles Avenue** IDPH LICENSE NO: **100-04437**

HOMOGENEOUS AREA: **018**
MATERIAL DESCRIPTION: **12" x 12" Blond Floor Tile**
MATERIAL LOCATION: **2nd Floor Corridors, Lunchroom, Kitchen, Classrooms, Alcoves & Offices**
MATERIAL QUANTITY: **4000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____

Stephen Diblik

Date: **04/06/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **70070** BUIDLING ID: **1800**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mary Hicks**
SCHOOL NAME: **Chicago Military Academy at
Bronzeville** INSPECTION DATE: **3/25/2013**
ADDRESS: **3516 South Giles Avenue** IDPH LICENSE NO: **100-04437**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **019**
MATERIAL DESCRIPTION: **12" x 12" Blond Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **2nd Floor Corridors, Lunchroom, Kitchen, Classrooms, Alcoves & Offices**
MATERIAL QUANTITY: **4000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature:



Date: **03/25/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **70070** BUIDLING ID: **1800**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**
SCHOOL NAME: **Chicago Military Academy at Bronzeville** REVIEW DATE: **4/6/2013**
ADDRESS: **3516 South Giles Avenue** IDPH LICENSE NO: **100-04437**

HOMOGENEOUS AREA: **019**
MATERIAL DESCRIPTION: **12" x 12" Blond Floor Tile Mastic**
MATERIAL LOCATION: **2nd Floor Corridors, Lunchroom, Kitchen, Classrooms, Alcoves & Offices**
MATERIAL QUANTITY: **4000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:

Stephen Diblik

Date: **04/06/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 70070 BUIDLING ID: 1800
CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Mary Hicks
SCHOOL NAME: Chicago Military Academy at Bronzeville INSPECTION DATE: 3/25/2013
ADDRESS: 3516 South Giles Avenue IDPH LICENSE NO: 100-04437

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 020
MATERIAL DESCRIPTION: 12" x 12" Gray Mix Floor Tile
HISTORICAL AHERA DAMAGE CATEGORY 6
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: Assumed FRIABLE: No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW

MATERIAL LOCATION: 2nd & 3rd Floor Classrooms, Corridors, Stairways, Alcoves, Kitchen, Kitchen Office & Cafeteria

MATERIAL QUANTITY: 10800 MATERIAL UNITS: SF

DAMAGE QUANTITY: DAMAGE UNITS: SF

COMMENTS:

Inspector's Signature:



Date: 03/25/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **70070** BUIDLING ID: **1800**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**
SCHOOL NAME: **Chicago Military Academy at Bronzeville** REVIEW DATE: **4/6/2013**
ADDRESS: **3516 South Giles Avenue** IDPH LICENSE NO: **100-04437**

HOMOGENEOUS AREA: **020**
MATERIAL DESCRIPTION: **12" x 12" Gray Mix Floor Tile**
MATERIAL LOCATION: **2nd & 3rd Floor Classrooms, Corridors, Stairways, Alcoves, Kitchen, Kitchen Office & Cafeteria**
MATERIAL QUANTITY: **10800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____

Stephen Diblik

Date: **04/06/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **70070** BUIDLING ID: **1800**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mary Hicks**
SCHOOL NAME: **Chicago Military Academy at
Bronzeville** INSPECTION DATE: **3/25/2013**
ADDRESS: **3516 South Giles Avenue** IDPH LICENSE NO: **100-04437**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **021**
MATERIAL DESCRIPTION: **12" x 12" Gray Mix Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **2nd & 3rd Floor Classrooms, Corridors, Stairways, Alcoves, Kitchen, Kitchen Office & Cafeteria**
MATERIAL QUANTITY: **10800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature:



Date: **03/25/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **70070** BUIDLING ID: **1800**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**
SCHOOL NAME: **Chicago Military Academy at Bronzeville** REVIEW DATE: **4/6/2013**
ADDRESS: **3516 South Giles Avenue** IDPH LICENSE NO: **100-04437**

HOMOGENEOUS AREA: **021**
MATERIAL DESCRIPTION: **12" x 12" Gray Mix Floor Tile Mastic**
MATERIAL LOCATION: **2nd & 3rd Floor Classrooms, Corridors, Stairways, Alcoves, Kitchen, Kitchen Office & Cafeteria**
MATERIAL QUANTITY: **10800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____

Stephen Diblik

Date: **04/06/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **70070** BUIDLING ID: **1800**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mary Hicks**
SCHOOL NAME: **Chicago Military Academy at
Bronzeville** INSPECTION DATE: **3/25/2013**
ADDRESS: **3516 South Giles Avenue** IDPH LICENSE NO: **100-04437**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **022**
MATERIAL DESCRIPTION: **Quarry Tile Grout**
HISTORICAL AHERA DAMAGE CATEGORY **6**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1st Floor Corridor**
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/25/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **70070** BUIDLING ID: **1800**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**
SCHOOL NAME: **Chicago Military Academy at Bronzeville** REVIEW DATE: **4/6/2013**
ADDRESS: **3516 South Giles Avenue** IDPH LICENSE NO: **100-04437**

HOMOGENEOUS AREA: **022**
MATERIAL DESCRIPTION: **Quarry Tile Grout**
MATERIAL LOCATION: **1st Floor Corridor**
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____

Stephen Diblik

Date: **04/06/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **70070** BUIDLING ID: **1800**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mary Hicks**
SCHOOL NAME: **Chicago Military Academy at
Bronzeville** INSPECTION DATE: **3/25/2013**
ADDRESS: **3516 South Giles Avenue** IDPH LICENSE NO: **100-04437**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **023**
MATERIAL DESCRIPTION: **Duct Sealant**
HISTORICAL AHERA DAMAGE CATEGORY **6**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Basement**
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature:



Date: **03/25/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **70070** BUILDING ID: **1800**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**
SCHOOL NAME: **Chicago Military Academy at Bronzeville** REVIEW DATE: **4/6/2013**
ADDRESS: **3516 South Giles Avenue** IDPH LICENSE NO: **100-04437**

HOMOGENEOUS AREA: **023**
MATERIAL DESCRIPTION: **Duct Sealant**
MATERIAL LOCATION: **Basement**
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____

Stephen Diblik

Date: **04/06/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **70070** BUIDLING ID: **1800**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mary Hicks**
SCHOOL NAME: **Chicago Military Academy at
Bronzeville** INSPECTION DATE: **3/25/2013**
ADDRESS: **3516 South Giles Avenue** IDPH LICENSE NO: **100-04437**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **024**
MATERIAL DESCRIPTION: **Adhesive**
HISTORICAL AHERA DAMAGE CATEGORY **6**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Beneath All Marker Boards in the Facility**

MATERIAL QUANTITY: **700**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/25/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **70070** BUILDING ID: **1800**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**
SCHOOL NAME: **Chicago Military Academy at Bronzeville** REVIEW DATE: **4/6/2013**
ADDRESS: **3516 South Giles Avenue** IDPH LICENSE NO: **100-04437**

HOMOGENEOUS AREA: **024**
MATERIAL DESCRIPTION: **Adhesive**
MATERIAL LOCATION: **Beneath All Marker Boards in the Facility**
MATERIAL QUANTITY: **700** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____

Stephen Diblik

Date: **04/06/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **70070** BUIDLING ID: **1800**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mary Hicks**
SCHOOL NAME: **Chicago Military Academy at
Bronzeville** INSPECTION DATE: **3/25/2013**
ADDRESS: **3516 South Giles Avenue** IDPH LICENSE NO: **100-04437**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **25**
MATERIAL DESCRIPTION: **Carpet Adhesive**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Offices, Media Center, Conference Room, 204, 304**

MATERIAL QUANTITY: **2400**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS: **Room 304 has Gray Floor Tile**

Inspector's Signature:



Date: **03/25/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **70070** BUILDING ID: **1800**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**
SCHOOL NAME: **Chicago Military Academy at Bronzeville** REVIEW DATE: **4/6/2013**
ADDRESS: **3516 South Giles Avenue** IDPH LICENSE NO: **100-04437**

HOMOGENEOUS AREA: **25**
MATERIAL DESCRIPTION: **Carpet Adhesive**
MATERIAL LOCATION: **Offices, Media Center, Conference Room, 204, 304**
MATERIAL QUANTITY: **2400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____

Stephen Diblik

Date: **04/06/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **70070** BUIDLING ID: **1800**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mary Hicks**
SCHOOL NAME: **Chicago Military Academy at
Bronzeville** INSPECTION DATE: **3/25/2013**
ADDRESS: **3516 South Giles Avenue** IDPH LICENSE NO: **100-04437**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **26**
MATERIAL DESCRIPTION: **Green, Red and Gray Terrazzo**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Entrance, stairwells, and hallways**

MATERIAL QUANTITY: **10000**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/25/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **70070** BUIDLING ID: **1800**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**
SCHOOL NAME: **Chicago Military Academy at Bronzeville** REVIEW DATE: **4/6/2013**
ADDRESS: **3516 South Giles Avenue** IDPH LICENSE NO: **100-04437**

HOMOGENEOUS AREA: **26**
MATERIAL DESCRIPTION: **Green, Red and Gray Terrazzo**
MATERIAL LOCATION: **Entrance, stairwells, and hallways**
MATERIAL QUANTITY: **10000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____

Stephen Diblik

Date: **04/06/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **70070** BUIDLING ID: **1800**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mary Hicks**
SCHOOL NAME: **Chicago Military Academy at
Bronzeville** INSPECTION DATE: **3/25/2013**
ADDRESS: **3516 South Giles Avenue** IDPH LICENSE NO: **100-04437**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **27**
MATERIAL DESCRIPTION: **12"x12" White w/Blue Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Elevator**

MATERIAL QUANTITY: **40**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/25/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **70070** BUIDLING ID: **1800**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**
SCHOOL NAME: **Chicago Military Academy at Bronzeville** REVIEW DATE: **4/6/2013**
ADDRESS: **3516 South Giles Avenue** IDPH LICENSE NO: **100-04437**

HOMOGENEOUS AREA: **27**
MATERIAL DESCRIPTION: **12"x12" White w/Blue Floor Tile**
MATERIAL LOCATION: **Elevator**
MATERIAL QUANTITY: **40** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____

Stephen Diblik

Date: **04/06/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **70070** BUIDLING ID: **1800**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mary Hicks**
SCHOOL NAME: **Chicago Military Academy at
Bronzeville** INSPECTION DATE: **3/25/2013**
ADDRESS: **3516 South Giles Avenue** IDPH LICENSE NO: **100-04437**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **28**
MATERIAL DESCRIPTION: **12"x12" White w/Blue Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Elevator**

MATERIAL QUANTITY: **40**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:

Mary Hicks

Date: **03/25/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **70070** BUIDLING ID: **1800**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**
SCHOOL NAME: **Chicago Military Academy at Bronzeville** REVIEW DATE: **4/6/2013**
ADDRESS: **3516 South Giles Avenue** IDPH LICENSE NO: **100-04437**

HOMOGENEOUS AREA: **28**
MATERIAL DESCRIPTION: **12"x12" White w/Blue Floor Tile Mastic**
MATERIAL LOCATION: **Elevator**
MATERIAL QUANTITY: **40** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____

Stephen Diblik

Date: **04/06/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **70070** BUIDLING ID: **1800**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mary Hicks**
SCHOOL NAME: **Chicago Military Academy at
Bronzeville** INSPECTION DATE: **3/25/2013**
ADDRESS: **3516 South Giles Avenue** IDPH LICENSE NO: **100-04437**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **HA-100**
MATERIAL DESCRIPTION: **2'x4' white ceiling tile**
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **throughout the building**

MATERIAL QUANTITY: **5000**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____

Mary Hicks

Date: 03/25/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **70070** BUIDLING ID: **1800**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**
SCHOOL NAME: **Chicago Military Academy at Bronzeville** REVIEW DATE: **4/6/2013**
ADDRESS: **3516 South Giles Avenue** IDPH LICENSE NO: **100-04437**

HOMOGENEOUS AREA: **HA-100**
MATERIAL DESCRIPTION: **2'x4' white ceiling tile**
MATERIAL LOCATION: **throughout the building**
MATERIAL QUANTITY: **5000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____

Stephen Diblik

Date: **04/06/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

APPENDIX B

Inspector and Management Planner Licenses



**ASBESTOS
PROFESSIONAL
LICENSE**

ID NUMBER
100 - 04437

ISSUED
8/14/2012

EXPIRES
05/15/2013

MARY H HICKS
9558 SOUTH LOOMIS
CHICAGO, IL 60643



Environmental Health

ENDORSEMENTS	TC EXPIRES
INSPECTOR	2/3/2013
MANAGEMENT PLANNER	2/3/2013
PROJECT MANAGER	4/30/2013
AIR SAMPLING PROFESSIONAL	

Alteration of this license shall result in legal action
This license issued under authority of the State of Illinois
Department of Public Health
This license is valid only when accompanied by a valid
training course certificate.

CERTIFICATE OF ACHIEVEMENT ASBESTOS ABATEMENT

Accredited by the Illinois Department of Public Health

This is to certify that MARY HICKS
has completed the ASBESTOS INSPECTOR'S REFRESHER course and successfully passed the
examination on 02/04/2013 with a minimum score of 70% or better. Training was in accordance
with U.S. E.P.A. 40 CFR 763 Subpart E, Appendix C, Asbestos Containing Materials in Schools:
Model Accreditation Plan, TSCA II, Authorized by both AHERA & ASHARA.



Nicholas J. Penell

02/04/2013

Course Dates:

02/04/2014

Expires:

1302BR12

Certificate Number:

Phone Number: (312) 491-0081

Director of Training

Nicholas J. Penell

Doctor of Public Health

FORM # A-010



Occupational Training & Supply, Inc.

7233 Adams Street • Willowbrook, IL 60527 • (630) 655-3900

Steve Diblik

has successfully completed the 4 hour Asbestos Building Inspector Refresher Course and has passed the competency exam with a minimum score of 70%. This course is accredited by the **Illinois Department of Public Health** and the **Indiana Department of Environmental Management** for purposes of accreditation in accordance with EPA 40 CFR763, Asbestos Hazard Emergency Response Act (AHERA) and TSCA Title II. This training course complies with the requirements of TSCA Title II and is accredited by the state of Wisconsin **Department of Health Services** under CH.DHS159, Wisconsin Administration Code.

Asbestos Abatement Building Inspector Refresher

Certificate: BIRWI1301110170

Location: 12304 75th Street Kenosha, WI 53142

Course Date: 1/11/2013

Examination Date: 1/11/2013

Expiration Date: 1/11/2014

Issue Date: 1/11/2013



Duplicate Original

Kathy DeSalvo, Director

2013

Stephen Diblik

Illinois Licensed Asbestos Inspector, Management Planner,
Project Manager and Air Sampling Professional



ASBESTOS PROFESSIONAL LICENSE

ID NUMBER
100 - 05171

ISSUED
4/4/2012

EXPIRES
05/15/2013

STEPHEN C DIBLIK
300 W. Adams Street, Suite 120
Chicago, IL 60606

Environmental Health



ENDORSEMENTS

TC EXPIRES

INSPECTOR

1/13/2013

MANAGEMENT PLANNER

1/19/2013

PROJECT MANAGER

12/15/2012

AIR SAMPLING PROFESSIONAL

Alteration of this license shall result in legal action
This license issued under authority of the State of Illinois
Department of Public Health
This license is valid only when accompanied by a valid
training course certificate.

**CARNOW
CONIBEAR**



Occupational Training & Supply, Inc.

7233 Adams Street • Willowbrook, IL 60527 • (630) 655-3900

Asbestos Management Planner Refresher

Occupational Training and Supply, Inc. certifies that

Stephen Diblik


has successfully completed the 4 hour Asbestos Management Planner Refresher Course
and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department
of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance
with EPA 10 CFR 763 Asbestos Hazard Emergency Response Act (AHERA) and TSCA Title II.

Certificate: MPR1302250732

Exam Date: 2/25/2013

Course Date: 2/25/2013

Expiration Date: 2/25/2014


Kathy DeSalvo
Director

2013

APPENDIX C

Laboratory Accreditations

APPENDIX D

Laboratory Results

APPENDIX E

Chain of Custody Forms

Three-Year Reinspection Key to Terms

	CODE	KEY
MATERIAL		
	ACBM	Asbestos Containing Building Materials
MATERIAL CATEGORY		
	MISC	Miscellaneous
	SURF	Surfacing
	TSI	Thermal System Insulation
MATERIAL UNITS		
	LF	Linear Feet
	SF	Square Feet
	CF	Cubic Feet
DAMAGE TYPE		
	Loc	Localized
	Dist	Distributed