

**ILLINOIS DEPARTMENT OF PUBLIC HEALTH
AHERA THREE YEAR REINSPECTION
ASBESTOS ABATEMENT PROGRAM
SCHOOL INFORMATION FORM**

SECTION I

NAME OF SCHOOL DISTRICT: CHICAGO SCHOOL DIST 299
SCHOOL ID NUMBER: 14-016-2990-3520
SCHOOL NAME: South Loop School Branch
ADDRESS OF SCHOOL: 1915 South Federal Street
CITY: Chicago, IL, 60616

DATE LAST THREE YEAR REINSPECTION WAS COMPLETED **3/17/2010**

If the address on this form is different than the address of the building, submit a written explanation.

SECTION II *(Please type or print)*

PLEASE COMPLETE THE FOLLOWING FOR YOUR THREE YEAR REINSPECTION:

DATE REINSPECTION COMPLETED: 3/18/2013 ENROLLMENT 136
IDPH INSPECTOR LICENSE NUMBER: 100-11170
IDPH LICENSED INSPECTOR NAME (Please Print): Jesus Delgado
IDPH MP LICENSE NUMBER: 100-09870
IDPH LICENSED MANAGEMENT PLANNER NAME (Please Print): Todd Huffer

DESIGNATED PERSON (Please Print): Ms. Lynn Crivello PHONE: (773) 553-3113



3/18/2013

Signature of Designated Person

Date

SECTION III

PLEASE COMPLETE THE FOLLOWING INFORMATION FOR ANY CHANGES WITHIN THE SCHOOL DISTRICT.

School building has been sold. Date of Sale: _____

School has been closed. Date closed: _____

School building has been demolished. Date: _____

School building is asbestos free since last reinspection: _____

Please explain in writing why the school building is now asbestos free and include the supporting documentation.

If a new school building has been added to the district, submit either an exclusionary statement or a management plan and inspection report. Include the complete name, address and city of school building.

Explain in writing if the address of the building is different than the address on this form:

THREE-YEAR REINSPECTION

CHICAGO SCHOOL DIST 299

South Loop School Branch

1915 South Federal Street
Chicago, IL, 60616

Unit: 23752
Building ID: 3961

IDPH ID Number: 14-016-2990-3520

REPORT DATE:

Monday, March 18, 2013

Prepared for:

Chicago Public Schools
125 S. Clark Street
Chicago, IL 60603

Prepared by:

Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone (312) 762-2900

Fax (312) 782-5145

**DO NOT REMOVE FROM SCHOOL
REQUIRED BY FEDERAL LAW**

March 13, 2013

Mr. R. Kent Cook
Asbestos Program
Illinois Department of Public Health
525 West Jefferson Street
Springfield, Illinois 62761

Re: Chicago Public Schools - 2013 Three-Year Reinspections

Dear Mr. Cook:

Carnow, Conibear and Associates, Managing Environmental Consultant (MEC), conducted the Three-Year Reinspections and performed management plan updates for the Chicago Public Schools (CPS) facilities in Region 3,4,5 Elementary Schools. Please update your records with the following information.

School District: 299 Unit: 23752 Region: 03 IDPH ID: 14-016-2990-3520

School: South Loop School Branch Building ID: 3961

Address: 1915 South Federal Street
Chicago, IL, 60616

Building Contact: Contact Phone:

Current Building Owners: Chicago Public Schools

Review Date: 3/18/2013

Inspector: Jesus Delgado Inspector IDPH License: 100-11170
Management Planner: Todd Huffer Management Planner IDPH License: 100-09870

If you have any questions or comments, please contact us at (312) 762-2900

Sincerely,
Carnow, Conibear and Associates



Todd Huffer
100-09870

Environmental Notification to Occupants

To: Faculty, Staff and Parents
From: Chicago Public Schools
Date: March 13, 2013

RE: South Loop School Branch, Unit 23752
1915 South Federal Street
Chicago, IL, 60616

Dear Faculty, Staff and Parents,

This letter is to notify you that the 2013 asbestos three year re-inspection has been completed at South Loop School Branch , following the Federal Asbestos Hazard Emergency Response Act (AHERA), 40 CFR Part 763, Subpart E and is available for your review at the main office of the school.

Although asbestos-containing materials have been identified at South Loop School Branch, there is no reason to believe that any threat to the health of students or staff exists at this time. CPS will continue to carefully monitor the condition of asbestos-containing materials and if conditions warrant, all appropriate steps will be taken to maintain the health and safety of all building occupants.

If you have any questions regarding this matter or require additional information, please feel free to contact Ms. Lynn Crivello, the designated Local Education Authority's Designated Person at (773) 553-3113 .

Table of Contents

- I. School and Inspection Information
- II. Executive Summary
- III. Methodology
- IV. Abatement History
- V. Reassessments and Recommendations
- VI. Conclusions

Table I: Inspector's Reinspection Findings

Table II: Management Planner's Review

APPENDICES:

- Appendix A: Assessment Sheets, Drawings and Photos
- Appendix B: Inspector and Management Planner Licenses
- Appendix C: Laboratory Accreditations
- Appendix D: Laboratory Results
- Appendix E: Chain of Custody Forms

SCHOOL AND INSPECTION INFORMATION

1. School Information

School: South Loop School Branch Unit: 23752 Region: 03
Address: 1915 South Federal Street Chicago, IL, 60616
IDPH ID: 14-016-2990-3520 Building ID: 3961
Contact: Phone:

2. Description of Facility

Original Construction: Additional Construction:
Total Square Footage: No of Floors:
Current Occupancy: 136

3. LEA Designated Person


Contact: Ms. Lynn Crivello Phone: (773) 553-3113
Address: 125 South Clark Street, 17th Floor
Chicago, IL 60603

4. Managing Environmental Consultant

MEC: Carnow, Conibear and Associates
Contact: Dan Juneau
Address 600 West Van Buren St., Ste 500
Phone: (312) 762-2900 Fax: (312) 782-5145

5. Inspector

Inspector Name: Jesus Delgado



Signature:
Date: 3/13/2013

Inspector IDPH license # 100-11170

6. Management Planner

Management Planner Name: Todd Huffer



Signature:
Date: 3/18/2013

Management Planner IDPH license # 100-09870

7. Review Date: 3/18/2013

8. LEA Designated Person's Acknowledgement

The reinspection report and recommendations have been received by me and appropriate action will be taken by the School District.



Signature:

Date: 3/18/2013

Name: Ms. Lynn Crivello

II. EXECUTIVE SUMMARY

Carnow, Conibear and Associates was retained by the Chicago Public Schools (CPS) to perform a three-year asbestos reinspection of the South Loop School Branch. This inspection was conducted in accordance with the United States Environmental Protection Agency (USEPA) Asbestos Hazard Emergency Response Act (AHERA) part 763.92 (b), and the ongoing Operations and Maintenance Program (O&M) originally designed in the School's Asbestos Management Plan. The purpose of this three-year reinspection is to record any condition changes in the asbestos-containing building material (ACBM) in the school since the previous three-year reinspection and the six-month periodic surveillance, to identify, assess, and include any Homogeneous Areas (HA) not identified in the Management Plan, and to recommend an appropriate response action to manage asbestos.

The inspector conducted a three-year reinspection of this facility under Illinois Department of Public Health (IDPH) school reinspection requirements and AHERA, sections 763.85 and 763.88. The main building and each addition to the main building, if constructed at different dates, were inspected separately. Laboratory accreditations are included in Appendix C, laboratory results are included in Appendix D, and chain of custody forms are included in Appendix E.

Note: During previous inspections, some of the HA(s) were identified together as 9" x 9" floor tile (FT), mastics assoc. with 9" x 9" FT, 12" x 12" FT, mastics assoc. with 12" x 12" FT, pipe insulation, etc. Some of these HA(s) have been re-identified by areas that are uniform in color, texture, construction date, application date, and general appearance.

The inspector has determined the following:

A. The following HAs have changed assessment categories for Building 3961:

B. The following new homogenous areas have been identified for Building 3961:

C. This reinspection covered only physically accessible and visible areas and materials that were identified in the LEA's management plan. The following materials were concealed and/or contained in areas that were inaccessible for sampling and have been classified as Assumed:

001	1'x1' White Ceiling Tile - Abated During Rehab
002	12x12 Beige Floor Tile - Abated During Rehab
004	1'x1' Acoustical Ceiling Adhesive
005	Drywall - Removed during rehab
006	Drywall Joint Compound - Removed during rehab
007	Vinyl Baseboard - Removed during rehab
008	Vinyl Baseboard Mastic - removed during rehab
009	Carpet Adhesive - Removed during rehab
010	12"x12" Tan Floor Tile - Abated during rehab
012	Ceramic Grout - Removed during rehab
013	Vinyl Base w/Carpet - Removed during rehab
014	Vinyl Base Mastic w/Carpet - removed during rehab
015	Roof Deck Panel - Non AHERA
016	Vault Door Liner - Abated during rehab
17	Gray Linoleum
18	Gray Linoleum Adhesive
19	Drywall
20	Drywall Joint Compound
21	1'X1' Ceiling Tiles
22	12"X12" Gray w/White/Gray Floor Tile
23	12"X12" Gray w/White/Gray Floor Tile Mastic
24	Ceramic Tile Grout
25	Ceramic Tile Adhesive
26	Whiteboard (Markerboard) Adhesive
27	4" Gray Vinyl Baseboard
28	4" Gray Vinyl Baseboard Adhesive
29	Posterboard Adhesive

The following areas were deemed to be inaccessible:

18	Gray Linoleum Adhesive
23	12"X12" Gray w/White/Gray Floor Tile Mastic
25	Ceramic Tile Adhesive
26	Whiteboard (Markerboard) Adhesive
28	4" Gray Vinyl Baseboard Adhesive
29	Posterboard Adhesive

Materials were also listed as "assumed" if they were in good condition and sampling was not conducted to avoid damage.

This reinspection was conducted by Jesus Delgado, IDPH License # 100-11170. The

Management Plan was updated by Todd Huffer, IDPH License # 100-09870. Inspector and Management Planner Licenses are included in Appendix B.

III. METHODOLOGY

Tasks performed on-site included the following:

1. Review current management plan, identify HA(s) and extract appropriate information.
2. Examine and verify abatement records.
3. Touch and visually and physically reinspect and reassess the condition of all friable known or assumed ACBM.
4. Touch and visually and physically reinspect all non-friable known or assumed ACBM to determine whether these materials have become friable since the last inspection or periodic surveillance.
5. Identify any condition changes that may affect Hazard Ranking of known ACBM or Assumed ACBM, as well as any HA(s) that have become friable since the last reinspection.
6. Collect bulk samples from each newly discovered friable HA or previously assumed and submit for laboratory analysis.
7. Tabulate reinspection findings and submit for management planner review and recommendations with appropriate response actions based on the AHERA Damage Category of the ACBM.
8. Submit reinspection findings and management planner recommendations to the LEA within thirty (30) days for inclusion into the management plan.

IV. ABATEMENT HISTORY

The information collected from the existing management plan and inspection report(s) and from interviews with the school official revealed that the following asbestos abatement was conducted at the school since the previous Three year Reinspection.

Abatement Dates:

V. REASSESSMENTS AND RECOMMENDATIONS

The reassessments and recommendations are summarized in Tables I and II on the following pages. Detailed Hazard Assessment Sheets and Drawings and Photos (if applicable) are included in Appendix A.

VI. CONCLUSIONS

The South Loop School Branch Building 3961 Three-Year reinspection has been completed and response actions have been recommended for both friable and non-friable materials. A timely execution of the response actions recommended will enable the LEA and the Designated Person(s) to effectively manage the existing ACBM.

This three-year reinspection report should be inspected in the current Management plan at the CPS Central Office, and one (1) copy should be kept at the school for use when planning any renovation and/or demolition activities in areas where ACBM has been identified. Also, periodic surveillance documentation and any summary reports from any response actions that are executed at the school should be used to update the Management Plan.

Table I
Inspector's Reinspection Findings

Chicago Public Schools

School South Loop School Branch Unit 23752 Building ID 3961

Address 1915 South Federal Street Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
001	1'x1' White Ceiling Tile - Abated During Rehab	0	SF	Throughout Building except Lunchroom, All Purpose Room and Rm 119	ASSUMED	MISC	Y							
002	12x12 Beige Floor Tile - Abated During Rehab	0	SF	Corridors & Lunchroom	ASSUMED	MISC	N							
003	12"x12" Beige FT Mastic - Abated During Rehab	0	SF	Throughout Bldg. Lunchroom & Corridor	CHR	MISC	N							
004	1'x1' Acoustical Ceiling Adhesive	0	SF	Throughout Bldg. - Abated During Rehab	ASSUMED	MISC	N							
005	Drywall - Removed during rehab	0	SF	Throughout Bldg.	ASSUMED	MISC								
006	Drywall Joint Compound - Removed during rehab	0	SF	Throughout Bldg.	ASSUMED	MISC								
007	Vinyl Baseboard - Removed during rehab	0	LF	Throughout Bldg.	ASSUMED	MISC								
008	Vinyl Baseboard Mastic - removed during rehab	0	LF	Throughout Bldg.	ASSUMED	MISC								
009	Carpet Adhesive - Removed during rehab	0	SF	Throughout Building	ASSUMED	MISC								
010	12"x12" Tan Floor Tile - Abated during rehab	0	SF	Room 102 Washroom & Room 116 small area HWH	ASSUMED	MISC								
011	12"x12" Tan Floor Tile Mastic - Abated during rehab	0	SF	Room 102 Washroom & Room 116 small area HWH	CHR	MISC	N							
012	Ceramic Grout - Removed during rehab	0	SF	Boys & Girls Washrooms Throughout Bldg.	ASSUMED	SURFACE								
013	Vinyl Base w/Carpet - Removed during rehab	0	SF	Throughout various classrooms 101, 102, 103, 104, 105, 106 etc.	ASSUMED	MISC								
014	Vinyl Base Mastic w/Carpet - removed during rehab	0	SF	Throughout various classrooms 101, 102, 103, 104, 105, 106 etc.	ASSUMED	MISC								
015	Roof Deck Panel - Non AHERA	0		Exterior - Non AHERA	ASSUMED	MISC	N							
016	Vault Door Liner - Abated during rehab	0	SF	Office	ASSUMED	MISC	N							
17	Gray Linoleum	2,340	SF	APR (106) and 109	ASSUMED	MISC	N	NONE	0		No	ACBM with the		LOW

Chicago Public Schools

School South Loop School Branch Unit 23752 Building ID 3961
 Address 1915 South Federal Street Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
												potential for damage		
18	Gray Linoleum Adhesive	2,340	SF	APR (106) and 109	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
19	Drywall	19,115	SF	All Rooms Ceilings	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
20	Drywall Joint Compound	13,115	SF	All Rooms Ceilings	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
21	1'X1' Ceiling Tiles	8,750	SF	Corridors, Classrooms and Offices	ASSUMED	MISC	Y	NONE	0		No	ACBM with the potential for damage		LOW
22	12"X12" Gray w/White/Gray Floor Tile	10,700	SF	101 - 105, 107, Corridors, Staff Rooms, Offices, Kitchen	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
23	12"X12" Gray w/White/Gray Floor Tile Mastic	10,700	SF	101 - 105, 107, Corridors, Staff Rooms, Offices, Kitchen	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
24	Ceramic Tile Grout	350	SF	All Washrooms	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
25	Ceramic Tile Adhesive	350	SF	All Washrooms	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
26	Whiteboard (Markerboard) Adhesive	400	SF	101, 102, 103, 104 and 105	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
27	4" Gray Vinyl Baseboard	1,100	LF	All Rooms except Washrooms	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
28	4" Gray Vinyl Baseboard Adhesive	1,100	LF	All Rooms except Washrooms	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
29	Posterboard Adhesive	420	SF	101, 102, 103, 104, 105 and All Purpose Room	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW

Chicago Public Schools

School South Loop School Branch Unit 23752 Building ID 3961
Address 1915 South Federal Street Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

Reinspection Date 3/13/2013
Inspector Name Jesus Delgado
100-11170 5/15/2013
Inspector's IDPH License Number / Expiration Date

Inspector's Comments

HA Number:	Inspector Comments:
001	Material Not Observed - 2013
002	Material Not Observed - 2013
003	Material Not Observed - 2013
004	Material Not Observed - 2013
005	Material Not Observed - 2013
006	Material Not Observed - 2013
007	Material Not Observed - 2013
008	Material Not Observed - 2013
009	Material Not Observed - 2013
010	Material Not Observed - 2013
011	Material Not Observed - 2013
012	Material Not Observed - 2013
013	Material Not Observed - 2013
014	Material Not Observed - 2013
015	Material Not Observed - 2013
016	Material Not Observed - 2013
17	
18	
19	
20	
21	
22	
23	
24	

Chicago Public Schools

School South Loop School Branch **Unit** 23752 **Building ID** 3961

Address 1915 South Federal Street **Region** 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
25	
26	
27	
28	
29	

Table II

Management Planner's Review

Chicago Public Schools

School South Loop School Branch

Unit 23752

Building ID 3961

Address 1915 South Federal Street

Chicago, IL, 60616

Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
001	1'x1' White Ceiling Tile - Abated During Rehab	0	SF	Throughout Building except Lunchroom, All Purpose Room and Rm 119	Assumed	MISC	Yes		SF		
002	12x12 Beige Floor Tile - Abated During Rehab	0	SF	Corridors & Lunchroom	Assumed	MISC	No		SF		
003	12"x12" Beige FT Mastic - Abated During Rehab	0	SF	Throughout Bldg. Lunchroom & Corridor	Chrysotile	MISC	No		SF		
004	1'x1' Acoustical Ceiling Adhesive	0	SF	Throughout Bldg. - Abated During Rehab	Assumed	MISC	No		SF		
005	Drywall - Removed during rehab	0	SF	Throughout Bldg.	Assumed	MISC			SF		
006	Drywall Joint Compound - Removed during rehab	0	SF	Throughout Bldg.	Assumed	MISC			SF		
007	Vinyl Baseboard - Removed during rehab	0	LF	Throughout Bldg.	Assumed	MISC			LF		
008	Vinyl Baseboard Mastic - removed during rehab	0	LF	Throughout Bldg.	Assumed	MISC			LF		
009	Carpet Adhesive - Removed during rehab	0	SF	Throughout Building	Assumed	MISC			SF		
010	12"x12" Tan Floor Tile - Abated during rehab	0	SF	Room 102 Washroom & Room 116 small area HWH	Assumed	MISC			SF		
011	12"x12" Tan Floor Tile Mastic - Abated during rehab	0	SF	Room 102 Washroom & Room 116 small area HWH	Chrysotile	MISC	No		SF		
012	Ceramic Grout - Removed during rehab	0	SF	Boys & Girls Washrooms Throughout Bldg.	Assumed	SURFACE			SF		
013	Vinyl Base w/Carpet - Removed during rehab	0	SF	Throughout various classrooms 101, 102, 103, 104, 105, 106 etc.	Assumed	MISC			SF		
014	Vinyl Base Mastic w/Carpet - removed during rehab	0	SF	Throughout various classrooms 101, 102, 103, 104, 105, 106 etc.	Assumed	MISC			SF		
015	Roof Deck Panel - Non AHERA	0		Exterior - Non AHERA	Assumed	MISC	No				
016	Vault Door Liner - Abated during rehab	0	SF	Office	Assumed	MISC	No		SF		
17	Gray Linoleum	2,340	SF	APR (106) and 109	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
18	Gray Linoleum Adhesive	2,340	SF	APR (106) and 109	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
19	Drywall	19,115	SF	All Rooms Ceilings	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
20	Drywall Joint Compound	13,115	SF	All Rooms Ceilings	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
21	1'X1' Ceiling Tiles	8,750	SF	Corridors, Classrooms and Offices	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
22	12"X12" Gray w/White/Gray Floor Tile	10,700	SF	101 - 105, 107, Corridors, Staff Rooms, Offices, Kitchen	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
23	12"X12" Gray w/White/Gray Floor Tile Mastic	10,700	SF	101 - 105, 107, Corridors, Staff Rooms, Offices, Kitchen	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
24	Ceramic Tile Grout	350	SF	All Washrooms	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
25	Ceramic Tile Adhesive	350	SF	All Washrooms	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance

Chicago Public Schools

School South Loop School Branch
Address 1915 South Federal Street

Unit 23752
 Chicago, IL, 60616

Building ID 3961
Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
26	Whiteboard (Markerboard) Adhesive	400	SF	101, 102, 103, 104 and 105	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
27	4" Gray Vinyl Baseboard	1,100	LF	All Rooms except Washrooms	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Operations and Maintenance
28	4" Gray Vinyl Baseboard Adhesive	1,100	LF	All Rooms except Washrooms	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Operations and Maintenance
29	Posterboard Adhesive	420	SF	101, 102, 103, 104, 105 and All Purpose Room	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance

HA Number	Management Comments
-----------	---------------------

Chicago Public Schools

School South Loop School Branch
Address 1915 South Federal Street

Unit 23752
 Chicago, IL, 60616

Building ID 3961
Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

Review Date	3/18/2013
Manager Planner Name	Todd Huffer
100-09870	5/15/2013
Manager IDPH License No/Expiration	

HA Number	Management Comments
001	material not observed by Inspector in 2013
002	material not observed by Inspector in 2013
003	material not observed by Inspector in 2013
004	material not observed by Inspector in 2013
005	material not observed by Inspector in 2013
006	material not observed by Inspector in 2013
007	material not observed by Inspector in 2013
008	
009	material not observed by Inspector in 2013
010	material not observed by Inspector in 2013
011	material not observed by Inspector in 2013
012	material not observed by Inspector in 2013
013	material not observed by Inspector in 2013
014	material not observed by Inspector in 2013
015	
016	material not observed by Inspector in 2013
17	
18	
19	
20	
21	
22	
23	
24	
25	
26	
27	

Chicago Public Schools

School South Loop School Branch

Unit 23752

Building ID 3961

Address 1915 South Federal Street

Chicago, IL, 60616

Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
28	
29	

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23752** BUILDING ID: **3961**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Jesus Delgado**
SCHOOL NAME: **South Loop School Branch** INSPECTION DATE: **3/13/2013**
ADDRESS: **1915 South Federal Street** IDPH LICENSE NO: **100-11170**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **001**
MATERIAL DESCRIPTION: **1'x1' White Ceiling Tile - Abated During Rehab**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:


MATERIAL LOCATION: **Throughout Building except Lunchroom, All Purpose Room and Rm 119**

MATERIAL QUANTITY: **0** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS: **Material Not Observed - 2013**

Inspector's Signature:



Date: **03/13/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23752** BUIDLING ID: **3961**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **South Loop School Branch** REVIEW DATE: **3/18/2013**
ADDRESS: **1915 South Federal Street** IDPH LICENSE NO: **100-11170**

HOMOGENEOUS AREA: **001**
MATERIAL DESCRIPTION: **1'x1' White Ceiling Tile - Abated During Rehab**
MATERIAL LOCATION: **Throughout Building except Lunchroom, All Purpose Room and Rm 119**
MATERIAL QUANTITY: **0** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

material not observed by Inspector in 2013

Management Planner's Signature: _____



Date: **03/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23752** BUIDLING ID: **3961**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Jesus Delgado**
SCHOOL NAME: **South Loop School Branch** INSPECTION DATE: **3/13/2013**
ADDRESS: **1915 South Federal Street** IDPH LICENSE NO: **100-11170**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **002**
MATERIAL DESCRIPTION: **12x12 Beige Floor Tile - Abated During Rehab**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Corridors & Lunchroom**

MATERIAL QUANTITY: **0** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS: **Material Not Observed - 2013**

Inspector's Signature:



Date: **03/13/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23752** BUILDING ID: **3961**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **South Loop School Branch** REVIEW DATE: **3/18/2013**
ADDRESS: **1915 South Federal Street** IDPH LICENSE NO: **100-11170**

HOMOGENEOUS AREA: **002**
MATERIAL DESCRIPTION: **12x12 Beige Floor Tile - Abated During Rehab**
MATERIAL LOCATION: **Corridors & Lunchroom**
MATERIAL QUANTITY: **0** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

material not observed by Inspector in 2013

Management Planner's Signature: _____



Date: **03/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23752** BUIDLING ID: **3961**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Jesus Delgado**
SCHOOL NAME: **South Loop School Branch** INSPECTION DATE: **3/13/2013**
ADDRESS: **1915 South Federal Street** IDPH LICENSE NO: **100-11170**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **003**
MATERIAL DESCRIPTION: **12"x12" Beige FT Mastic - Abated During Rehab**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout Bldg. Lunchroom & Corridor**

MATERIAL QUANTITY: **0** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS: **Material Not Observed - 2013**

Inspector's Signature:



Date: **03/13/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23752** BUIDLING ID: **3961**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **South Loop School Branch** REVIEW DATE: **3/18/2013**
ADDRESS: **1915 South Federal Street** IDPH LICENSE NO: **100-11170**

HOMOGENEOUS AREA: **003**
MATERIAL DESCRIPTION: **12"x12" Beige FT Mastic - Abated During Rehab**
MATERIAL LOCATION: **Throughout Bldg. Lunchroom & Corridor**
MATERIAL QUANTITY: **0** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

material not observed by Inspector in 2013

Management Planner's Signature: _____



Date: **03/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23752** BUIDLING ID: **3961**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Jesus Delgado**
SCHOOL NAME: **South Loop School Branch** INSPECTION DATE: **3/13/2013**
ADDRESS: **1915 South Federal Street** IDPH LICENSE NO: **100-11170**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **004**
MATERIAL DESCRIPTION: **1'x1' Acoustical Ceiling Adhesive**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:


MATERIAL LOCATION: **Throughout Bldg. - Abated During Rehab**

MATERIAL QUANTITY: **0** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS: **Material Not Observed - 2013**

Inspector's Signature:



Date: **03/13/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23752** BUIDLING ID: **3961**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **South Loop School Branch** REVIEW DATE: **3/18/2013**
ADDRESS: **1915 South Federal Street** IDPH LICENSE NO: **100-11170**

HOMOGENEOUS AREA: **004**
MATERIAL DESCRIPTION: **1'x1' Acoustical Ceiling Adhesive**
MATERIAL LOCATION: **Throughout Bldg. - Abated During Rehab**
MATERIAL QUANTITY: **0** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

material not observed by Inspector in 2013

Management Planner's Signature: _____



Date: **03/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23752** BUIDLING ID: **3961**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Jesus Delgado**
SCHOOL NAME: **South Loop School Branch** INSPECTION DATE: **3/13/2013**
ADDRESS: **1915 South Federal Street** IDPH LICENSE NO: **100-11170**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **005**
MATERIAL DESCRIPTION: **Drywall - Removed during rehab**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:


MATERIAL LOCATION: **Throughout Bldg.**

MATERIAL QUANTITY: **0** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS: **Material Not Observed - 2013**

Inspector's Signature:



Date: **03/13/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23752** BUIDLING ID: **3961**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **South Loop School Branch** REVIEW DATE: **3/18/2013**
ADDRESS: **1915 South Federal Street** IDPH LICENSE NO: **100-11170**

HOMOGENEOUS AREA: **005**
MATERIAL DESCRIPTION: **Drywall - Removed during rehab**
MATERIAL LOCATION: **Throughout Bldg.**
MATERIAL QUANTITY: **0** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

material not observed by Inspector in 2013

Management Planner's Signature: _____



Date: **03/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23752** BUIDLING ID: **3961**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Jesus Delgado**
SCHOOL NAME: **South Loop School Branch** INSPECTION DATE: **3/13/2013**
ADDRESS: **1915 South Federal Street** IDPH LICENSE NO: **100-11170**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **006**
MATERIAL DESCRIPTION: **Drywall Joint Compound - Removed during rehab**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout Bldg.**

MATERIAL QUANTITY: **0**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS: **Material Not Observed - 2013**

Inspector's Signature:



Date: **03/13/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23752** BUIDLING ID: **3961**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **South Loop School Branch** REVIEW DATE: **3/18/2013**
ADDRESS: **1915 South Federal Street** IDPH LICENSE NO: **100-11170**

HOMOGENEOUS AREA: **006**
MATERIAL DESCRIPTION: **Drywall Joint Compound - Removed during rehab**
MATERIAL LOCATION: **Throughout Bldg.**
MATERIAL QUANTITY: **0** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

material not observed by Inspector in 2013

Management Planner's Signature: _____



Date: **03/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates 2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23752** BUIDLING ID: **3961**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Jesus Delgado**
SCHOOL NAME: **South Loop School Branch** INSPECTION DATE: **3/13/2013**
ADDRESS: **1915 South Federal Street** IDPH LICENSE NO: **100-11170**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **007**
MATERIAL DESCRIPTION: **Vinyl Baseboard - Removed during rehab**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout Bldg.**

MATERIAL QUANTITY: **0**

MATERIAL UNITS: **LF**

DAMAGE QUANTITY:

DAMAGE UNITS: **LF**

COMMENTS: **Material Not Observed - 2013**

Inspector's Signature:



Date: **03/13/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23752** BUIDLING ID: **3961**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **South Loop School Branch** REVIEW DATE: **3/18/2013**
ADDRESS: **1915 South Federal Street** IDPH LICENSE NO: **100-11170**

HOMOGENEOUS AREA: **007**
MATERIAL DESCRIPTION: **Vinyl Baseboard - Removed during rehab**
MATERIAL LOCATION: **Throughout Bldg.**
MATERIAL QUANTITY: **0** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

material not observed by Inspector in 2013

Management Planner's Signature: _____



Date: **03/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23752** BUIDLING ID: **3961**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Jesus Delgado**
SCHOOL NAME: **South Loop School Branch** INSPECTION DATE: **3/13/2013**
ADDRESS: **1915 South Federal Street** IDPH LICENSE NO: **100-11170**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **008**
MATERIAL DESCRIPTION: **Vinyl Baseboard Mastic - removed during rehab**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout Bldg.**

MATERIAL QUANTITY: **0** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS: **Material Not Observed - 2013**

Inspector's Signature:



Date: **03/13/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23752** BUIDLING ID: **3961**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **South Loop School Branch** REVIEW DATE: **3/18/2013**
ADDRESS: **1915 South Federal Street** IDPH LICENSE NO: **100-11170**

HOMOGENEOUS AREA: **008**
MATERIAL DESCRIPTION: **Vinyl Baseboard Mastic - removed during rehab**
MATERIAL LOCATION: **Throughout Bldg.**
MATERIAL QUANTITY: **0** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **03/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23752** BUIDLING ID: **3961**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Jesus Delgado**
SCHOOL NAME: **South Loop School Branch** INSPECTION DATE: **3/13/2013**
ADDRESS: **1915 South Federal Street** IDPH LICENSE NO: **100-11170**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **009**
MATERIAL DESCRIPTION: **Carpet Adhesive - Removed during rehab**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout Building**

MATERIAL QUANTITY: **0** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS: **Material Not Observed - 2013**

Inspector's Signature:



Date: **03/13/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23752** BUIDLING ID: **3961**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **South Loop School Branch** REVIEW DATE: **3/18/2013**
ADDRESS: **1915 South Federal Street** IDPH LICENSE NO: **100-11170**

HOMOGENEOUS AREA: **009**
MATERIAL DESCRIPTION: **Carpet Adhesive - Removed during rehab**
MATERIAL LOCATION: **Throughout Building**
MATERIAL QUANTITY: **0** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

material not observed by Inspector in 2013

Management Planner's Signature: _____



Date: **03/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23752** BUIDLING ID: **3961**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Jesus Delgado**
SCHOOL NAME: **South Loop School Branch** INSPECTION DATE: **3/13/2013**
ADDRESS: **1915 South Federal Street** IDPH LICENSE NO: **100-11170**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **010**
MATERIAL DESCRIPTION: **12"x12" Tan Floor Tile - Abated during rehab**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 102 Washroom & Room 116 small area HWH**

MATERIAL QUANTITY: **0** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS: **Material Not Observed - 2013**

Inspector's Signature:



Date: **03/13/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23752** BUIDLING ID: **3961**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **South Loop School Branch** REVIEW DATE: **3/18/2013**
ADDRESS: **1915 South Federal Street** IDPH LICENSE NO: **100-11170**

HOMOGENEOUS AREA: **010**
MATERIAL DESCRIPTION: **12"x12" Tan Floor Tile - Abated during rehab**
MATERIAL LOCATION: **Room 102 Washroom & Room 116 small area HWH**
MATERIAL QUANTITY: **0** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

material not observed by Inspector in 2013

Management Planner's Signature: _____



Date: **03/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23752** BUIDLING ID: **3961**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Jesus Delgado**
SCHOOL NAME: **South Loop School Branch** INSPECTION DATE: **3/13/2013**
ADDRESS: **1915 South Federal Street** IDPH LICENSE NO: **100-11170**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **011**
MATERIAL DESCRIPTION: **12"x12"Tan Floor Tile Mastic - Abated during rehab**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 102 Washroom & Room 116 small area HWH**

MATERIAL QUANTITY: **0** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS: **Material Not Observed - 2013**

Inspector's Signature:



Date: **03/13/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23752** BUIDLING ID: **3961**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **South Loop School Branch** REVIEW DATE: **3/18/2013**
ADDRESS: **1915 South Federal Street** IDPH LICENSE NO: **100-11170**

HOMOGENEOUS AREA: **011**
MATERIAL DESCRIPTION: **12"x12"Tan Floor Tile Mastic - Abated during rehab**
MATERIAL LOCATION: **Room 102 Washroom & Room 116 small area HWH**
MATERIAL QUANTITY: **0** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

material not observed by Inspector in 2013

Management Planner's Signature: _____



Date: **03/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23752** BUIDLING ID: **3961**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Jesus Delgado**
SCHOOL NAME: **South Loop School Branch** INSPECTION DATE: **3/13/2013**
ADDRESS: **1915 South Federal Street** IDPH LICENSE NO: **100-11170**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **012**
MATERIAL DESCRIPTION: **Ceramic Grout - Removed during rehab**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Boys & Girls Washrooms Throughout Bldg.**

MATERIAL QUANTITY: **0** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS: **Material Not Observed - 2013**

Inspector's Signature:



Date: **03/13/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23752** BUIDLING ID: **3961**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **South Loop School Branch** REVIEW DATE: **3/18/2013**
ADDRESS: **1915 South Federal Street** IDPH LICENSE NO: **100-11170**

HOMOGENEOUS AREA: **012**
MATERIAL DESCRIPTION: **Ceramic Grout - Removed during rehab**
MATERIAL LOCATION: **Boys & Girls Washrooms Throughout Bldg.**
MATERIAL QUANTITY: **0** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

material not observed by Inspector in 2013

Management Planner's Signature: _____



Date: **03/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23752** BUIDLING ID: **3961**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Jesus Delgado**
SCHOOL NAME: **South Loop School Branch** INSPECTION DATE: **3/13/2013**
ADDRESS: **1915 South Federal Street** IDPH LICENSE NO: **100-11170**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **013**
MATERIAL DESCRIPTION: **Vinyl Base w/Carpet - Removed during rehab**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:


MATERIAL LOCATION: **Throughout various classrooms 101, 102, 103, 104, 105, 106 etc.**

MATERIAL QUANTITY: **0** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS: **Material Not Observed - 2013**

Inspector's Signature:



Date: **03/13/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23752** BUIDLING ID: **3961**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **South Loop School Branch** REVIEW DATE: **3/18/2013**
ADDRESS: **1915 South Federal Street** IDPH LICENSE NO: **100-11170**

HOMOGENEOUS AREA: **013**
MATERIAL DESCRIPTION: **Vinyl Base w/Carpet - Removed during rehab**
MATERIAL LOCATION: **Throughout various classrooms 101, 102, 103, 104, 105, 106 etc.**
MATERIAL QUANTITY: **0** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

material not observed by Inspector in 2013

Management Planner's Signature: _____



Date: **03/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23752** BUIDLING ID: **3961**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Jesus Delgado**
SCHOOL NAME: **South Loop School Branch** INSPECTION DATE: **3/13/2013**
ADDRESS: **1915 South Federal Street** IDPH LICENSE NO: **100-11170**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **014**
MATERIAL DESCRIPTION: **Vinyl Base Mastic w/Carpet - removed during rehab**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout various classrooms 101, 102, 103, 104, 105, 106 etc.**

MATERIAL QUANTITY: **0** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS: **Material Not Observed - 2013**

Inspector's Signature:



Date: **03/13/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23752** BUIDLING ID: **3961**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **South Loop School Branch** REVIEW DATE: **3/18/2013**
ADDRESS: **1915 South Federal Street** IDPH LICENSE NO: **100-11170**

HOMOGENEOUS AREA: **014**
MATERIAL DESCRIPTION: **Vinyl Base Mastic w/Carpet - removed during rehab**
MATERIAL LOCATION: **Throughout various classrooms 101, 102, 103, 104, 105, 106 etc.**
MATERIAL QUANTITY: **0** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

material not observed by Inspector in 2013

Management Planner's Signature: _____



Date: **03/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23752** BUIDLING ID: **3961**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Jesus Delgado**
SCHOOL NAME: **South Loop School Branch** INSPECTION DATE: **3/13/2013**
ADDRESS: **1915 South Federal Street** IDPH LICENSE NO: **100-11170**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **015**
MATERIAL DESCRIPTION: **Roof Deck Panel - Non AHERA**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Exterior - Non AHERA**

MATERIAL QUANTITY: **0** MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Material Not Observed - 2013**

Inspector's Signature:



Date: **03/13/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23752** BUILDING ID: **3961**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **South Loop School Branch** REVIEW DATE: **3/18/2013**
ADDRESS: **1915 South Federal Street** IDPH LICENSE NO: **100-11170**

HOMOGENEOUS AREA: **015**
MATERIAL DESCRIPTION: **Roof Deck Panel - Non AHERA**
MATERIAL LOCATION: **Exterior - Non AHERA**
MATERIAL QUANTITY: **0** MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **03/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23752** BUIDLING ID: **3961**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Jesus Delgado**
SCHOOL NAME: **South Loop School Branch** INSPECTION DATE: **3/13/2013**
ADDRESS: **1915 South Federal Street** IDPH LICENSE NO: **100-11170**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **016**
MATERIAL DESCRIPTION: **Vault Door Liner - Abated during rehab**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Office**

MATERIAL QUANTITY: **0**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS: **Material Not Observed - 2013**

Inspector's Signature:



Date: **03/13/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23752** BUIDLING ID: **3961**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **South Loop School Branch** REVIEW DATE: **3/18/2013**
ADDRESS: **1915 South Federal Street** IDPH LICENSE NO: **100-11170**

HOMOGENEOUS AREA: **016**
MATERIAL DESCRIPTION: **Vault Door Liner - Abated during rehab**
MATERIAL LOCATION: **Office**
MATERIAL QUANTITY: **0** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

material not observed by Inspector in 2013

Management Planner's Signature: _____



Date: **03/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23752** BUIDLING ID: **3961**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Jesus Delgado**
SCHOOL NAME: **South Loop School Branch** INSPECTION DATE: **3/13/2013**
ADDRESS: **1915 South Federal Street** IDPH LICENSE NO: **100-11170**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **17**
MATERIAL DESCRIPTION: **Gray Linoleum**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **APR (106) and 109**
MATERIAL QUANTITY: **2340** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/13/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23752** BUIDLING ID: **3961**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **South Loop School Branch** REVIEW DATE: **3/18/2013**
ADDRESS: **1915 South Federal Street** IDPH LICENSE NO: **100-11170**

HOMOGENEOUS AREA: **17**
MATERIAL DESCRIPTION: **Gray Linoleum**
MATERIAL LOCATION: **APR (106) and 109**
MATERIAL QUANTITY: **2340** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **03/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23752** BUIDLING ID: **3961**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Jesus Delgado**
SCHOOL NAME: **South Loop School Branch** INSPECTION DATE: **3/13/2013**
ADDRESS: **1915 South Federal Street** IDPH LICENSE NO: **100-11170**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **18**
MATERIAL DESCRIPTION: **Gray Linoleum Adhesive**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **APR (106) and 109**
MATERIAL QUANTITY: **2340** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/13/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23752** BUIDLING ID: **3961**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **South Loop School Branch** REVIEW DATE: **3/18/2013**
ADDRESS: **1915 South Federal Street** IDPH LICENSE NO: **100-11170**

HOMOGENEOUS AREA: **18**
MATERIAL DESCRIPTION: **Gray Linoleum Adhesive**
MATERIAL LOCATION: **APR (106) and 109**
MATERIAL QUANTITY: **2340** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **03/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23752** BUIDLING ID: **3961**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Jesus Delgado**
SCHOOL NAME: **South Loop School Branch** INSPECTION DATE: **3/13/2013**
ADDRESS: **1915 South Federal Street** IDPH LICENSE NO: **100-11170**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **19**
MATERIAL DESCRIPTION: **Drywall**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **All Rooms Ceilings**
MATERIAL QUANTITY: **19115** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/13/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23752** BUIDLING ID: **3961**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **South Loop School Branch** REVIEW DATE: **3/18/2013**
ADDRESS: **1915 South Federal Street** IDPH LICENSE NO: **100-11170**

HOMOGENEOUS AREA: **19**
MATERIAL DESCRIPTION: **Drywall**
MATERIAL LOCATION: **All Rooms Ceilings**
MATERIAL QUANTITY: **19115** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **03/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23752** BUIDLING ID: **3961**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Jesus Delgado**
SCHOOL NAME: **South Loop School Branch** INSPECTION DATE: **3/13/2013**
ADDRESS: **1915 South Federal Street** IDPH LICENSE NO: **100-11170**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **20**
MATERIAL DESCRIPTION: **Drywall Joint Compound**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **All Rooms Ceilings**
MATERIAL QUANTITY: **13115** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/13/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23752** BUIDLING ID: **3961**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **South Loop School Branch** REVIEW DATE: **3/18/2013**
ADDRESS: **1915 South Federal Street** IDPH LICENSE NO: **100-11170**

HOMOGENEOUS AREA: **20**
MATERIAL DESCRIPTION: **Drywall Joint Compound**
MATERIAL LOCATION: **All Rooms Ceilings**
MATERIAL QUANTITY: **13115** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **03/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23752** BUIDLING ID: **3961**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Jesus Delgado**
SCHOOL NAME: **South Loop School Branch** INSPECTION DATE: **3/13/2013**
ADDRESS: **1915 South Federal Street** IDPH LICENSE NO: **100-11170**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **21**
MATERIAL DESCRIPTION: **1'X1' Ceiling Tiles**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Corridors, Classrooms and Offices**

MATERIAL QUANTITY: **8750**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/13/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23752** BUIDLING ID: **3961**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **South Loop School Branch** REVIEW DATE: **3/18/2013**
ADDRESS: **1915 South Federal Street** IDPH LICENSE NO: **100-11170**

HOMOGENEOUS AREA: **21**
MATERIAL DESCRIPTION: **1'X1' Ceiling Tiles**
MATERIAL LOCATION: **Corridors, Classrooms and Offices**
MATERIAL QUANTITY: **8750** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **03/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23752** BUIDLING ID: **3961**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Jesus Delgado**
SCHOOL NAME: **South Loop School Branch** INSPECTION DATE: **3/13/2013**
ADDRESS: **1915 South Federal Street** IDPH LICENSE NO: **100-11170**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **22**
MATERIAL DESCRIPTION: **12"X12" Gray w/White/Gray Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **101 - 105, 107, Corridors, Staff Rooms, Offices, Kitchen**
MATERIAL QUANTITY: **10700** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/13/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23752** BUIDLING ID: **3961**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **South Loop School Branch** REVIEW DATE: **3/18/2013**
ADDRESS: **1915 South Federal Street** IDPH LICENSE NO: **100-11170**

HOMOGENEOUS AREA: **22**
MATERIAL DESCRIPTION: **12"X12" Gray w/White/Gray Floor Tile**
MATERIAL LOCATION: **101 - 105, 107, Corridors, Staff Rooms, Offices, Kitchen**
MATERIAL QUANTITY: **10700** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **03/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23752** BUIDLING ID: **3961**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Jesus Delgado**
SCHOOL NAME: **South Loop School Branch** INSPECTION DATE: **3/13/2013**
ADDRESS: **1915 South Federal Street** IDPH LICENSE NO: **100-11170**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **23**
MATERIAL DESCRIPTION: **12"X12" Gray w/White/Gray Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **101 - 105, 107, Corridors, Staff Rooms, Offices, Kitchen**
MATERIAL QUANTITY: **10700** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/13/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23752** BUILDING ID: **3961**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **South Loop School Branch** REVIEW DATE: **3/18/2013**
ADDRESS: **1915 South Federal Street** IDPH LICENSE NO: **100-11170**

HOMOGENEOUS AREA: **23**
MATERIAL DESCRIPTION: **12"X12" Gray w/White/Gray Floor Tile Mastic**
MATERIAL LOCATION: **101 - 105, 107, Corridors, Staff Rooms, Offices, Kitchen**
MATERIAL QUANTITY: **10700** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **03/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23752** BUIDLING ID: **3961**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Jesus Delgado**
SCHOOL NAME: **South Loop School Branch** INSPECTION DATE: **3/13/2013**
ADDRESS: **1915 South Federal Street** IDPH LICENSE NO: **100-11170**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **24**
MATERIAL DESCRIPTION: **Ceramic Tile Grout**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **All Washrooms**
MATERIAL QUANTITY: **350** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/13/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23752** BUIDLING ID: **3961**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **South Loop School Branch** REVIEW DATE: **3/18/2013**
ADDRESS: **1915 South Federal Street** IDPH LICENSE NO: **100-11170**

HOMOGENEOUS AREA: **24**
MATERIAL DESCRIPTION: **Ceramic Tile Grout**
MATERIAL LOCATION: **All Washrooms**
MATERIAL QUANTITY: **350** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **03/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23752** BUIDLING ID: **3961**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Jesus Delgado**
SCHOOL NAME: **South Loop School Branch** INSPECTION DATE: **3/13/2013**
ADDRESS: **1915 South Federal Street** IDPH LICENSE NO: **100-11170**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **25**
MATERIAL DESCRIPTION: **Ceramic Tile Adhesive**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **All Washrooms**
MATERIAL QUANTITY: **350** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/13/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23752** BUIDLING ID: **3961**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **South Loop School Branch** REVIEW DATE: **3/18/2013**
ADDRESS: **1915 South Federal Street** IDPH LICENSE NO: **100-11170**

HOMOGENEOUS AREA: **25**
MATERIAL DESCRIPTION: **Ceramic Tile Adhesive**
MATERIAL LOCATION: **All Washrooms**
MATERIAL QUANTITY: **350** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **03/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23752** BUIDLING ID: **3961**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Jesus Delgado**
SCHOOL NAME: **South Loop School Branch** INSPECTION DATE: **3/13/2013**
ADDRESS: **1915 South Federal Street** IDPH LICENSE NO: **100-11170**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **26**
MATERIAL DESCRIPTION: **Whiteboard (Markerboard) Adhesive**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **101, 102, 103, 104 and 105**

MATERIAL QUANTITY: **400**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/13/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23752** BUIDLING ID: **3961**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **South Loop School Branch** REVIEW DATE: **3/18/2013**
ADDRESS: **1915 South Federal Street** IDPH LICENSE NO: **100-11170**

HOMOGENEOUS AREA: **26**
MATERIAL DESCRIPTION: **Whiteboard (Markerboard) Adhesive**
MATERIAL LOCATION: **101, 102, 103, 104 and 105**
MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **03/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23752** BUIDLING ID: **3961**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Jesus Delgado**
SCHOOL NAME: **South Loop School Branch** INSPECTION DATE: **3/13/2013**
ADDRESS: **1915 South Federal Street** IDPH LICENSE NO: **100-11170**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **27**
MATERIAL DESCRIPTION: **4" Gray Vinyl Baseboard**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **All Rooms except Washrooms**
MATERIAL QUANTITY: **1100** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature:



Date: **03/13/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23752** BUILDING ID: **3961**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **South Loop School Branch** REVIEW DATE: **3/18/2013**
ADDRESS: **1915 South Federal Street** IDPH LICENSE NO: **100-11170**

HOMOGENEOUS AREA: **27**
MATERIAL DESCRIPTION: **4" Gray Vinyl Baseboard**
MATERIAL LOCATION: **All Rooms except Washrooms**
MATERIAL QUANTITY: **1100** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **03/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23752** BUIDLING ID: **3961**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Jesus Delgado**
SCHOOL NAME: **South Loop School Branch** INSPECTION DATE: **3/13/2013**
ADDRESS: **1915 South Federal Street** IDPH LICENSE NO: **100-11170**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **28**
MATERIAL DESCRIPTION: **4" Gray Vinyl Baseboard Adhesive**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **All Rooms except Washrooms**

MATERIAL QUANTITY: **1100**


MATERIAL UNITS: **LF**

DAMAGE QUANTITY:

DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature:



Date: **03/13/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23752** BUILDING ID: **3961**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **South Loop School Branch** REVIEW DATE: **3/18/2013**
ADDRESS: **1915 South Federal Street** IDPH LICENSE NO: **100-11170**

HOMOGENEOUS AREA: **28**
MATERIAL DESCRIPTION: **4" Gray Vinyl Baseboard Adhesive**
MATERIAL LOCATION: **All Rooms except Washrooms**
MATERIAL QUANTITY: **1100** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **03/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23752** BUIDLING ID: **3961**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Jesus Delgado**
SCHOOL NAME: **South Loop School Branch** INSPECTION DATE: **3/13/2013**
ADDRESS: **1915 South Federal Street** IDPH LICENSE NO: **100-11170**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **29**
MATERIAL DESCRIPTION: **Posterboard Adhesive**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **101, 102, 103, 104, 105 and All Purpose Room**

MATERIAL QUANTITY: **420**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/13/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23752** BUIDLING ID: **3961**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **South Loop School Branch** REVIEW DATE: **3/18/2013**
ADDRESS: **1915 South Federal Street** IDPH LICENSE NO: **100-11170**

HOMOGENEOUS AREA: **29**
MATERIAL DESCRIPTION: **Posterboard Adhesive**
MATERIAL LOCATION: **101, 102, 103, 104, 105 and All Purpose Room**
MATERIAL QUANTITY: **420** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **03/18/2013**


Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

APPENDIX B

Inspector and Management Planner Licenses



Occupational Training & Supply, Inc.

7233 Adams Street • Willowbrook, IL 60527 • (630) 655-3900

Asbestos Building Inspector Refresher

Occupational Training and Supply, Inc. certifies that

Jesus Delgado


has successfully completed the 4 hour Asbestos Building Inspector Refresher Course
and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 10 CFR 763 Asbestos Hazard Emergency Response Act (AHERA) and TSCA Title II.

Certificate: BIR1301040034

Exam Date: 1/4/2013

Course Date: 1/4/2013

Expiration Date: 1/4/2014


Kathy DeSalvo, Director

2013



525-535 West Jefferson Street • Springfield, Illinois 62761-0001 • www.idph.state.il.us

Pat Quinn, Governor

2/7/2013

JESUS M DELGADO
5256 HARCOURT ST
OAK FOREST, IL 60452

ASBESTOS PROFESSIONAL LICENSE ID NUMBER: 11170


Enclosed is your Asbestos Professional License that expires 05/15/2014

CERTIFICATE EXPIRATION DATE

INSPECTOR 1/4/2014

PROJECT MANAGER 11/2/2013
AIR SAMPLING PROFESSIONAL

If you have any questions or need further assistance, contact the Asbestos Program at (217)782-3517 or fax (217)785-5897.
Our WEB address is <http://www.idph.state.il.us/envhealth/ehhome.htm>





Occupational Training & Supply, Inc.

7233 Adams Street • Willowbrook, IL 60527 • (630) 655-3900

Asbestos Building Inspector Refresher

Occupational Training and Supply, Inc. certifies that

Todd Huffer

has successfully completed the 4 hour Asbestos Building Inspector Refresher Course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 10 CFR 763 Asbestos Hazard Emergency Response Act (AHERA) and TSCA Title II.

Certificate: BIR1212042317

Exam Date: 12/4/2012

Course Date: 12/4/2012


Expiration Date: 12/4/2013

Kathy DeSalvo, Director

2012



Todd Huffer

Illinois Licensed Asbestos Inspector, Management Planner,
Project Manager, and Air Sampling Professional

 **ASBESTOS
PROFESSIONAL
LICENSE**

ID NUMBER **ISSUED** **EXPIRES**
100 - 09870 **4/4/2012** **05/15/2013**

TODD T HUFFER
918 N WOLCOTT UNIT 6
CHICAGO, IL 60622

Environmental Health

ENDORSEMENTS	TC EXPIRES
INSPECTOR	12/8/2012
MANAGEMENT PLANNER	1/19/2013
PROJECT MANAGER	9/8/2012
AIR SAMPLING PROFESSIONAL	

Alteration of this license shall result in legal action
This license issued under authority of the State of Illinois
Department of Public Health
This license is valid only when accompanied by a valid
training course certificate.

**CARNOW
CONIBEAR**



Occupational Training & Supply, Inc.

7233 Adams Street ♦ Willowbrook, IL 60527 ♦ (630) 655-3900

Asbestos Management Planner Refresher

Occupational Training and Supply, Inc. certifies that

Todd Huffer


has successfully completed the 4 hour Asbestos Management Planner Refresher Course
and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 10 CFR 763 Asbestos Hazard Emergency Response Act (AHERA) and TSCA Title II.

Certificate: MPRI302250735

Exam Date: 2/25/2013

Course Date: 2/25/2013

Expiration Date: 2/25/2014


Kathy DeSalvo, Director

2013

APPENDIX C

Laboratory Accreditations

APPENDIX D

Laboratory Results

APPENDIX E

Chain of Custody Forms

Three-Year Reinspection Key to Terms

	CODE	KEY
MATERIAL		
	ACBM	Asbestos Containing Building Materials
MATERIAL CATEGORY		
	MISC	Miscellaneous
	SURF	Surfacing
	TSI	Thermal System Insulation
MATERIAL UNITS		
	LF	Linear Feet
	SF	Square Feet
	CF	Cubic Feet
DAMAGE TYPE		
	Loc	Localized
	Dist	Distributed