

**ILLINOIS DEPARTMENT OF PUBLIC HEALTH  
AHERA THREE YEAR REINSPECTION  
ASBESTOS ABATEMENT PROGRAM  
SCHOOL INFORMATION FORM**

**SECTION I**

NAME OF SCHOOL DISTRICT: CHICAGO SCHOOL DIST 299  
SCHOOL ID NUMBER: 14-016-2990-2756  
SCHOOL NAME: McCutcheon School Branch  
ADDRESS OF SCHOOL: 4850 N Kenmore Avenue  
CITY: Chicago, IL, 60640

DATE LAST THREE YEAR REINSPECTION WAS COMPLETED **3/19/2010**

**If the address on this form is different than the address of the building, submit a written explanation.**

---

**SECTION II** *(Please type or print)*

**PLEASE COMPLETE THE FOLLOWING FOR YOUR THREE YEAR REINSPECTION:**

DATE REINSPECTION COMPLETED: 4/27/2013 ENROLLMENT 125  
IDPH INSPECTOR LICENSE NUMBER: 100-06327  
IDPH LICENSED INSPECTOR NAME (Please Print): Roberto Rivera  
IDPH MP LICENSE NUMBER: 100-06325  
IDPH LICENSED MANAGEMENT PLANNER NAME (Please Print): Santiago Garcia

DESIGNATED PERSON (Please Print): Ms. Lynn Crivello PHONE: (773) 553-3113



4/27/2013

*Signature of Designated Person*

*Date*

---

**SECTION III**

PLEASE COMPLETE THE FOLLOWING INFORMATION FOR ANY CHANGES WITHIN THE SCHOOL DISTRICT.

School building has been sold. Date of Sale: \_\_\_\_\_

School has been closed. Date closed: \_\_\_\_\_

School building has been demolished. Date: \_\_\_\_\_

School building is asbestos free since last reinspection: \_\_\_\_\_

**Please explain in writing why the school building is now asbestos free and include the supporting documentation.**

If a new school building has been added to the district, submit either an exclusionary statement or a management plan and inspection report. Include the complete name, address and city of school building.

**Explain in writing if the address of the building is different than the address on this form:**

**THREE-YEAR REINSPECTION**

**CHICAGO SCHOOL DIST 299**

**McCutcheon School Branch**

4850 N Kenmore Avenue  
Chicago, IL, 60640

Unit: 26202  
Building ID: 6911

IDPH ID Number: 14-016-2990-2756

**REPORT DATE:**

Saturday, April 27, 2013

**Prepared for:**

**Chicago Public Schools**  
**125 S. Clark Street**  
**Chicago, IL 60603**

**Prepared by:**

**GSG Consultants, Inc.**

855 W. Adams St., Ste. 200

Phone (312) 733-6262

Fax (312) 733-5612

**DO NOT REMOVE FROM SCHOOL  
REQUIRED BY FEDERAL LAW**

March 22, 2013

Mr. R. Kent Cook  
Asbestos Program  
Illinois Department of Public Health  
525 West Jefferson Street  
Springfield, Illinois 62761

Re: Chicago Public Schools - 2013 Three-Year Reinspections

Dear Mr. Cook:

GSG Consultants, Inc., Managing Environmental Consultant (MEC), conducted the Three-Year Reinspections and performed management plan updates for the Chicago Public Schools (CPS) facilities in Region 1,2,6 Elementary Schools. Please update your records with the following information.

School District: 299                      Unit: 26202                      Region: 01                      IDPH ID: 14-016-2990-2756

School: McCutcheon School Branch                      Building ID: 6911

Address: 4850 N Kenmore Avenue  
Chicago, IL, 60640

Building Contact:                      Contact Phone:

Current Building Owners: Chicago Public Schools

Review Date: 4/27/2013

Inspector: Roberto Rivera                      Inspector IDPH License: 100-06327  
Management Planner: Santiago Garcia                      Management Planner IDPH License: 100-06325

If you have any questions or comments, please contact us at (312) 733-6262

Sincerely,  
GSG Consultants, Inc.



Santiago Garcia  
100-06325

## **Environmental Notification to Occupants**

To: Faculty, Staff and Parents  
From: Chicago Public Schools  
Date: March 22, 2013

RE: McCutcheon School Branch, Unit 26202  
4850 N Kenmore Avenue  
Chicago, IL, 60640

Dear Faculty, Staff and Parents,

This letter is to notify you that the 2013 asbestos three year re-inspection has been completed at McCutcheon School Branch , following the Federal Asbestos Hazard Emergency Response Act (AHERA), 40 CFR Part 763, Subpart E and is available for your review at the main office of the school.

Although asbestos-containing materials have been identified at McCutcheon School Branch, there is no reason to believe that any threat to the health of students or staff exists at this time. CPS will continue to carefully monitor the condition of asbestos-containing materials and if conditions warrant, all appropriate steps will be taken to maintain the health and safety of all building occupants.

If you have any questions regarding this matter or require additional information, please feel free to contact Ms. Lynn Crivello, the designated Local Education Authority's Designated Person at (773) 553-3113 .

## **Table of Contents**

- I. School and Inspection Information
- II. Executive Summary
- III. Methodology
- IV. Abatement History
- V. Reassessments and Recommendations
- VI. Conclusions

Table I: Inspector's Reinspection Findings

Table II: Management Planner's Review

### **APPENDICES:**

- Appendix A: Assessment Sheets, Drawings and Photos
- Appendix B: Inspector and Management Planner Licenses
- Appendix C: Laboratory Accreditations
- Appendix D: Laboratory Results
- Appendix E: Chain of Custody Forms

## SCHOOL AND INSPECTION INFORMATION

### 1. School Information

School: McCutcheon School                      Unit: 26202                      Region: 01  
Branch  
Address: 4850 N Kenmore Avenue              Chicago, IL, 60640  
IDPH ID: 14-016-2990-2756                      Building ID: 6911  
Contact:    Phone:

### 2. Description of Facility

Original Construction:                                      Additional Construction:  
Total Square Footage:                                      No of Floors:  
Current Occupancy: 125

### 3. LEA Designated Person

Contact: Ms. Lynn Crivello                                      Phone: (773) 553-3113  
Address: 125 South Clark Street, 17th Floor  
Chicago, IL 60603

### 4. Managing Environmental Consultant

MEC: GSG Consultants, Inc.  
Contact: Arturo Saenz  
Address 855 W. Adams St., Ste. 200  
Phone: (312) 733-6262                                      Fax: (312) 733-5612

### 5. Inspector

Inspector Name: Roberto Rivera

Inspector IDPH license # 100-06327

  
Signature:  
Date: 3/22/2013

### 6. Management Planner

Management Planner Name: Santiago Garcia

Management Planner IDPH license # 100-06325

  
Signature:  
Date: 4/27/2013

### 7. Review Date: 4/27/2013

### 8. LEA Designated Person's Acknowledgement

The reinspection report and recommendations have been received by me and appropriate action will be taken by the School District.

  
Signature:

Date: 4/27/2013

Name: Ms. Lynn Crivello

## II. EXECUTIVE SUMMARY

GSG Consultants, Inc. was retained by the Chicago Public Schools (CPS) to perform a three-year asbestos reinspection of the McCutcheon School Branch. This inspection was conducted in accordance with the United States Environmental Protection Agency (USEPA) Asbestos Hazard Emergency Response Act (AHERA) part 763.92 (b), and the ongoing Operations and Maintenance Program (O&M) originally designed in the School's Asbestos Management Plan. The purpose of this three-year reinspection is to record any condition changes in the asbestos-containing building material (ACBM) in the school since the previous three-year reinspection and the six-month periodic surveillance, to identify, assess, and include any Homogeneous Areas (HA) not identified in the Management Plan, and to recommend an appropriate response action to manage asbestos.

The inspector conducted a three-year reinspection of this facility under Illinois Department of Public Health (IDPH) school reinspection requirements and AHERA, sections 763.85 and 763.88. The main building and each addition to the main building, if constructed at different dates, were inspected separately. Laboratory accreditations are included in Appendix C, laboratory results are included in Appendix D, and chain of custody forms are included in Appendix E.

Note: During previous inspections, some of the HA(s) were identified together as 9" x 9" floor tile (FT), mastics assoc. with 9" x 9" FT, 12" x 12" FT, mastics assoc. with 12" x 12" FT, pipe insulation, etc. Some of these HA(s) have been re-identified by areas that are uniform in color, texture, construction date, application date, and general appearance.

The inspector has determined the following:

A. The following HAs have changed assessment categories for Building 6911:

B. The following new homogenous areas have been identified for Building 6911:

08

Carpet Mastic



C. This reinspection covered only physically accessible and visible areas and materials that were identified in the LEA's management plan. The following materials were concealed and/or contained in areas that were inaccessible for sampling and have been classified as Assumed:

02	12"x12" White w/Brown Speckles VFT
07	2' x 4' Ceiling Tile w/Dots
08	Carpet Mastic

The following areas were deemed to be inaccessible:

07	2' x 4' Ceiling Tile w/Dots
08	Carpet Mastic

Materials were also listed as "assumed" if they were in good condition and sampling was not conducted to avoid damage.

This reinspection was conducted by Roberto Rivera, IDPH License # 100-06327. The Management Plan was updated by Santiago Garcia, IDPH License # 100-06325. Inspector and Management Planner Licenses are included in Appendix B.

### **III. METHODOLOGY**

Tasks performed on-site included the following:

1. Review current management plan, identify HA(s) and extract appropriate information.
2. Examine and verify abatement records.
3. Touch and visually and physically reinspect and reassess the condition of all friable known or assumed ACBM.
4. Touch and visually and physically reinspect all non-friable known or assumed ACBM to determine whether these materials have become friable since the last inspection or periodic surveillance.
5. Identify any condition changes that may affect Hazard Ranking of known ACBM or Assumed ACBM, as well as any HA(s) that have become friable since the last reinspection.
6. Collect bulk samples from each newly discovered friable HA or previously assumed and submit for laboratory analysis.
7. Tabulate reinspection findings and submit for management planner review and recommendations with appropriate response actions based on the AHERA Damage Category of the ACBM.
8. Submit reinspection findings and management planner recommendations to the LEA within thirty (30) days for inclusion into the management plan.

### **IV. ABATEMENT HISTORY**

The information collected from the existing management plan and inspection report(s) and from interviews with the school official revealed that the following asbestos abatement was conducted at the school since the previous Three year Reinspection.

Abatement Dates:

### **V. REASSESSMENTS AND RECOMMENDATIONS**

The reassessments and recommendations are summarized in Tables I and II on the following pages. Detailed Hazard Assessment Sheets and Drawings and Photos (if applicable) are included in Appendix A.

### **VI. CONCLUSIONS**

The McCutcheon School Branch Building 6911 Three-Year reinspection has been completed and response actions have been recommended for both friable and non-friable materials. A timely execution of the response actions recommended will enable the LEA and the Designated Person(s) to effectively manage the existing ACBM.

This three-year reinspection report should be inspected in the current Management plan at the CPS Central Office, and one (1) copy should be kept at the school for use when planning any renovation and/or demolition activities in areas where ACBM has been identified. Also, periodic surveillance documentation and any summary reports from any response actions that are executed at the school should be used to update the Management Plan.

**Table I**  
**Inspector's Reinspection Findings**

---

# Chicago Public Schools

**School** McCutcheon School Branch **Unit** 26202 **Building ID** 6911

**Address** 4850 N Kenmore Avenue **Region** 01

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

**Managing Environmental Consultant (MEC)** GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262 Fax: (312) 733-5612

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
01	9"x9" White w/Brown Speckles VFT	2,000	SF	Gym / Lunchroom	CHR	MISC	N	LOC	120		No	ACBM with the potential for damage		LOW
02	12"x12" White w/Brown Speckles VFT	160	SF	North & South Vestibules	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
04	12"x12" White w/Brown Speckles VFT Mastic	160	SF	North & South Vestibules	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
05	9"x9" White w/Brown Speckles VFT Mastic	2,000	SF	Gym / Lunchroom	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
06	Baseboard Mastic	1,800	LF	Throughout	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
07	2' x 4' Ceiling Tile w/Dots	15,000	SF	Throughout	ASSUMED	MISC	Y	NONE	0		No	ACBM with the potential for damage		LOW
08	Carpet Mastic	9,000	SF	Throughout classrooms, corridors & offices	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
B	MJP E/F/V on Fiberglass Pipe Insulation	120	LF	Chases & Engineer's Office (above ceiling tiles)	CHR	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW
C	Pre-Formed Insulation on Water Main - Not Observed	5	SF	Lunchroom Office Storage	AMO	TSI	Y	None	0		No	ACBM with potential for significant damage		LOW

# Chicago Public Schools

School McCutcheon School Branch Unit 26202 Building ID 6911  
Address 4850 N Kenmore Avenue Region 01

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262 Fax: (312) 733-5612

*Inspector's Comments are Summarized at the End of the Report*

Reinspection Date <b>3/22/2013</b>
Inspector Name <b>Roberto Rivera</b>
<b>100-06327</b> <b>5/15/2013</b>
Inspector's IDPH License Number / Expiration Date

### Inspector's Comments

HA Number:	Inspector Comments:
01	This building was vacant at the time of the inspection
02	This building was vacant at the time of the inspection
04	This building was vacant at the time of the inspection
05	This building was vacant at the time of the inspection
06	This building was vacant at the time of the inspection
07	This building was vacant at the time of the inspection
08	This building was vacant at the time of the inspection
B	This building was vacant at the time of the inspection
C	This building was vacant at the time of the inspection

**Table II**

**Management Planner's Review**

---

# Chicago Public Schools

**School** McCutcheon School  
Branch  
**Address** 4850 N Kenmore Avenue

**Unit** 26202  
Chicago, IL, 60640

**Building ID** 6911  
**Region** 01

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262

Fax: (312) 733-5612

### Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
01	9"x9" White w/Brown Speckles VFT	2,000	SF	Gym / Lunchroom	Chrysotile	MISC	No	120	SF	6 ACBM with the potential for damage	Repair
02	12"x12" White w/Brown Speckles VFT	160	SF	North & South Vestibules	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
04	12"x12" White w/Brown Speckles VFT Mastic	160	SF	North & South Vestibules	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
05	9"x9" White w/Brown Speckles VFT Mastic	2,000	SF	Gym / Lunchroom	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
06	Baseboard Mastic	1,800	LF	Throughout	Chrysotile	MISC	No	0	LF	6 ACBM with the potential for damage	Operations and Maintenance
07	2' x 4' Ceiling Tile w/Dots	15,000	SF	Throughout	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
08	Carpet Mastic	9,000	SF	Throughout classrooms, corridors & offices	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
B	MJP E/F/V on Fiberglass Pipe Insulation	120	LF	Chases & Engineer's Office (above ceiling tiles)	Chrysotile	TSI	Yes	0	LF	6 ACBM with the potential for damage	Operations and Maintenance
C	Pre-Formed Insulation on Water Main - Not Observed	5	SF	Lunchroom Office Storage	Amosite	TSI	Yes	0	SF	5 ACBM with potential for significant damage	Operations and Maintenance

# Chicago Public Schools

**School** McCutcheon School  
Branch  
**Address** 4850 N Kenmore Avenue

**Unit** 26202  
Chicago, IL, 60640

**Building ID** 6911  
**Region** 01

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262

Fax: (312) 733-5612

### *Management Planner's Comments Summarized at the End of the Report*

Review Date	4/27/2013
Manager Planner Name	Santiago Garcia
100-06325	5/15/2013
Manager IDPH License No/Expiration	

HA Number	Management Comments
01	Repair Damage as soon as possible
02	
04	
05	
06	
07	
08	
B	
C	



# Chicago Public Schools

GSG Consultants, Inc.

## 2013 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26202** BUIDLING ID: **6911**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roberto Rivera**  
SCHOOL NAME: **McCutcheon School Branch** INSPECTION DATE: **3/22/2013**  
ADDRESS: **4850 N Kenmore Avenue** IDPH LICENSE NO: **100-06327**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **01**  
MATERIAL DESCRIPTION: **9"x9" White w/Brown Speckles VFT**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Gym / Lunchroom**

MATERIAL QUANTITY: **2000**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS: **This building was vacant at the time of the inspection**

Inspector's Signature:



Date: **03/22/2013**

# Chicago Public Schools

## GSG Consultants, Inc. 2013 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26202** BUILDING ID: **6911**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Santiago Garcia**  
SCHOOL NAME: **McCutcheon School Branch** REVIEW DATE: **4/27/2013**  
ADDRESS: **4850 N Kenmore Avenue** IDPH LICENSE NO: **100-06327**

---

HOMOGENEOUS AREA: **01**  
MATERIAL DESCRIPTION: **9"x9" White w/Brown Speckles VFT**  
MATERIAL LOCATION: **Gym / Lunchroom**  
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **120** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### **Operations and Maintenance**

Comments:

Repair Damage as soon as possible

Management Planner's Signature: \_\_\_\_\_



Date: **04/27/2013**

# Chicago Public Schools

GSG Consultants, Inc.  
2013 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26202** BUIDLING ID: **6911**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roberto Rivera**  
SCHOOL NAME: **McCutcheon School Branch** INSPECTION DATE: **3/22/2013**  
ADDRESS: **4850 N Kenmore Avenue** IDPH LICENSE NO: **100-06327**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **02**  
MATERIAL DESCRIPTION: **12"x12" White w/Brown Speckles VFT**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **North & South Vestibules**  
MATERIAL QUANTITY: **160** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS: **This building was vacant at the time of the inspection**

Inspector's Signature: \_\_\_\_\_

*Roberto Rivera*

Date: 03/22/2013

# Chicago Public Schools

## GSG Consultants, Inc. 2013 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26202** BUILDING ID: **6911**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Santiago Garcia**  
SCHOOL NAME: **McCutcheon School Branch** REVIEW DATE: **4/27/2013**  
ADDRESS: **4850 N Kenmore Avenue** IDPH LICENSE NO: **100-06327**

---

HOMOGENEOUS AREA: **02**  
MATERIAL DESCRIPTION: **12"x12" White w/Brown Speckles VFT**  
MATERIAL LOCATION: **North & South Vestibules**  
MATERIAL QUANTITY: **160** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### Operations and Maintenance

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **04/27/2013**

# Chicago Public Schools

GSG Consultants, Inc.  
2013 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26202** BUIDLING ID: **6911**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roberto Rivera**  
SCHOOL NAME: **McCutcheon School Branch** INSPECTION DATE: **3/22/2013**  
ADDRESS: **4850 N Kenmore Avenue** IDPH LICENSE NO: **100-06327**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **04**  
MATERIAL DESCRIPTION: **12"x12" White w/Brown Speckles VFT Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **North & South Vestibules**  
MATERIAL QUANTITY: **160** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS: **This building was vacant at the time of the inspection**

Inspector's Signature: \_\_\_\_\_

*Roberto Rivera*

Date: 03/22/2013

# Chicago Public Schools

GSG Consultants, Inc.  
2013 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26202** BUILDING ID: **6911**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Santiago Garcia**  
SCHOOL NAME: **McCutcheon School Branch** REVIEW DATE: **4/27/2013**  
ADDRESS: **4850 N Kenmore Avenue** IDPH LICENSE NO: **100-06327**

---

HOMOGENEOUS AREA: **04**  
MATERIAL DESCRIPTION: **12"x12" White w/Brown Speckles VFT Mastic**  
MATERIAL LOCATION: **North & South Vestibules**  
MATERIAL QUANTITY: **160** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Operations and Maintenance

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **04/27/2013**

# Chicago Public Schools

GSG Consultants, Inc.  
2013 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26202** BUIDLING ID: **6911**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roberto Rivera**  
SCHOOL NAME: **McCutcheon School Branch** INSPECTION DATE: **3/22/2013**  
ADDRESS: **4850 N Kenmore Avenue** IDPH LICENSE NO: **100-06327**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **05**  
MATERIAL DESCRIPTION: **9"x9" White w/Brown Speckles VFT Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Gym / Lunchroom**  
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS: **This building was vacant at the time of the inspection**

Inspector's Signature: \_\_\_\_\_

*Roberto Rivera*

Date: 03/22/2013

# Chicago Public Schools

## GSG Consultants, Inc. 2013 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26202** BUILDING ID: **6911**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Santiago Garcia**  
SCHOOL NAME: **McCutcheon School Branch** REVIEW DATE: **4/27/2013**  
ADDRESS: **4850 N Kenmore Avenue** IDPH LICENSE NO: **100-06327**

---

HOMOGENEOUS AREA: **05**  
MATERIAL DESCRIPTION: **9"x9" White w/Brown Speckles VFT Mastic**  
MATERIAL LOCATION: **Gym / Lunchroom**  
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### **Operations and Maintenance**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **04/27/2013**



# Chicago Public Schools

GSG Consultants, Inc.  
2013 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26202** BUIDLING ID: **6911**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roberto Rivera**  
SCHOOL NAME: **McCutcheon School Branch** INSPECTION DATE: **3/22/2013**  
ADDRESS: **4850 N Kenmore Avenue** IDPH LICENSE NO: **100-06327**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **06**  
MATERIAL DESCRIPTION: **Baseboard Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Throughout**  
MATERIAL QUANTITY: **1800** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS: **This building was vacant at the time of the inspection**

Inspector's Signature: \_\_\_\_\_

*Roberto Rivera*

Date: 03/22/2013

# Chicago Public Schools

## GSG Consultants, Inc. 2013 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26202** BUILDING ID: **6911**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Santiago Garcia**  
SCHOOL NAME: **McCutcheon School Branch** REVIEW DATE: **4/27/2013**  
ADDRESS: **4850 N Kenmore Avenue** IDPH LICENSE NO: **100-06327**

---

HOMOGENEOUS AREA: **06**  
MATERIAL DESCRIPTION: **Baseboard Mastic**  
MATERIAL LOCATION: **Throughout**  
MATERIAL QUANTITY: **1800** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### **Operations and Maintenance**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **04/27/2013**

# Chicago Public Schools

GSG Consultants, Inc.  
2013 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26202** BUIDLING ID: **6911**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roberto Rivera**  
SCHOOL NAME: **McCutcheon School Branch** INSPECTION DATE: **3/22/2013**  
ADDRESS: **4850 N Kenmore Avenue** IDPH LICENSE NO: **100-06327**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **07**  
MATERIAL DESCRIPTION: **2' x 4' Ceiling Tile w/Dots**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with potential for significant damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Throughout**  
MATERIAL QUANTITY: **15000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS: **This building was vacant at the time of the inspection**

Inspector's Signature: \_\_\_\_\_

*Roberto Rivera*

Date: 03/22/2013

# Chicago Public Schools

## GSG Consultants, Inc. 2013 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26202** BUILDING ID: **6911**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Santiago Garcia**  
SCHOOL NAME: **McCutcheon School Branch** REVIEW DATE: **4/27/2013**  
ADDRESS: **4850 N Kenmore Avenue** IDPH LICENSE NO: **100-06327**

---

HOMOGENEOUS AREA: **07**  
MATERIAL DESCRIPTION: **2' x 4' Ceiling Tile w/Dots**  
MATERIAL LOCATION: **Throughout**  
MATERIAL QUANTITY: **15000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### **Operations and Maintenance**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **04/27/2013**

# Chicago Public Schools

GSG Consultants, Inc.  
2013 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26202** BUIDLING ID: **6911**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roberto Rivera**  
SCHOOL NAME: **McCutcheon School Branch** INSPECTION DATE: **3/22/2013**  
ADDRESS: **4850 N Kenmore Avenue** IDPH LICENSE NO: **100-06327**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **B**  
MATERIAL DESCRIPTION: **MJP E/F/V on Fiberglass Pipe Insulation**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with potential for significant damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Chases & Engineer's Office (above ceiling tiles)**  
MATERIAL QUANTITY: **120** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS: **This building was vacant at the time of the inspection**

Inspector's Signature:



Date: **03/22/2013**

# Chicago Public Schools

GSG Consultants, Inc.

2013 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26202** BUILDING ID: **6911**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Santiago Garcia**  
SCHOOL NAME: **McCutcheon School Branch** REVIEW DATE: **4/27/2013**  
ADDRESS: **4850 N Kenmore Avenue** IDPH LICENSE NO: **100-06327**

---

HOMOGENEOUS AREA: **B**  
MATERIAL DESCRIPTION: **MJP E/F/V on Fiberglass Pipe Insulation**  
MATERIAL LOCATION: **Chases & Engineer's Office (above ceiling tiles)**  
MATERIAL QUANTITY: **120** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Operations and Maintenance

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **04/27/2013**

# Chicago Public Schools

GSG Consultants, Inc.  
2013 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26202** BUIDLING ID: **6911**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roberto Rivera**  
SCHOOL NAME: **McCutcheon School Branch** INSPECTION DATE: **3/22/2013**  
ADDRESS: **4850 N Kenmore Avenue** IDPH LICENSE NO: **100-06327**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **C**  
MATERIAL DESCRIPTION: **Pre-Formed Insulation on Water Main - Not Observed**  
HISTORICAL AHERA DAMAGE CATEGORY **5 ACBM with potential for significant damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**  
ASBESTOS TYPE: **Amosite** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **5. ACBM with potential for significant damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Lunchroom Office Storage**  
MATERIAL QUANTITY: **5** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS: **This building was vacant at the time of the inspection**

Inspector's Signature: \_\_\_\_\_

*Roberto Rivera*

Date: 03/22/2013

# Chicago Public Schools

## GSG Consultants, Inc. 2013 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26202** BUILDING ID: **6911**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Santiago Garcia**  
SCHOOL NAME: **McCutcheon School Branch** REVIEW DATE: **4/27/2013**  
ADDRESS: **4850 N Kenmore Avenue** IDPH LICENSE NO: **100-06327**

---

HOMOGENEOUS AREA: **C**  
MATERIAL DESCRIPTION: **Pre-Formed Insulation on Water Main - Not Observed**  
MATERIAL LOCATION: **Lunchroom Office Storage**  
MATERIAL QUANTITY: **5** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### **Operations and Maintenance**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **04/27/2013**



# Chicago Public Schools

GSG Consultants, Inc.  
2013 AHERA REINSPECTION

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **26202**    BUILDING ID: **6911**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Roberto Rivera**  
SCHOOL NAME: **McCutcheon School Branch**    INSPECTION DATE: **3/22/2013**  
ADDRESS: **4850 N Kenmore Avenue**    IDPH LICENSE NO: **100-06327**

---

### INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **08**  
MATERIAL DESCRIPTION: **Carpet Mastic**  
MATERIAL LOCATION: **Throughout classrooms, corridors & offices**  
MATERIAL QUANTITY: **9000**    MATERIAL UNITS: **SF**  
MATERIAL CATEGORY: **MISC**    FRIABLE: **No**  
ASBESTOS TYPE: **Assumed**  
DISTURBANCE POTENTIAL: **LOW**    CONDITION:  
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
ACCESSIBILITY: **Not Reachable**    DAMAGE REASON:  
DAMAGE QUANTITY: **0**    DAMAGE REASON:  
DAMAGE UNITS: **SF**

COMMENTS:  
This building was vacant at the time of the inspection

Inspector's Signature: \_\_\_\_\_

*Roberto Rivera*

Date: 03/22/2013

# Chicago Public Schools

## GSG Consultants, Inc. 2013 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26202** BUILDING ID: **6911**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Santiago Garcia**  
SCHOOL NAME: **McCutcheon School Branch** REVIEW DATE: **4/27/2013**  
ADDRESS: **4850 N Kenmore Avenue** IDPH LICENSE NO: **100-06327**

HOMOGENEOUS AREA: **08**  
MATERIAL DESCRIPTION: **Carpet Mastic**  
MATERIAL LOCATION: **Throughout classrooms, corridors & offices**  
MATERIAL QUANTITY: **9000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:  Date: 04/27/2013

# APPENDIX B

## Inspector and Management Planner Licenses

---



## Occupational Training & Supply, Inc.

7233 Adams Street • Willowbrook, IL 60527 • (630) 655-3900

# Asbestos Building Inspector Refresher

*Occupational Training and Supply, Inc. certifies that*

## Roberto Rivera


**has successfully completed the 4 hour Asbestos Building Inspector Refresher Course** and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 10 CFR 763 Asbestos Hazard Emergency Response Act (AHERA) and TSCA Title II.

Certificate: BR1302150506

Exam Date: 2/15/2013

Course Date: 2/15/2013

Expiration Date: 2/15/2014

  
Kathy Desjardis, Director

2013



**ASBESTOS  
PROFESSIONAL  
LICENSE**

**ID NUMBER**

**100 - 06327**

**ISSUED**

**3/21/2013**

**EXPIRES**

**05/15/2014**

**ROBERTO RIVERA**

**88 WEST ADAMS STREET, S  
CHICAGO, IL 60607**

**Environmental Health**



**ENDORSEMENTS**

**SUPERVISOR/OWNER**

**TC EXPIRES**

**2/22/2014**

**INSPECTOR**

**2/19/2014**

**PROJECT MANAGER**

**2/22/2014**

**AIR SAMPLING PROFESSIONAL**

**Alteration of this license shall result in legal action  
This license issued under authority of the State of Illinois  
Department of Public Health**

**This license is valid only when accompanied by a valid  
training course certificate**



# ASBESTOS PROFESSIONAL LICENSE

ENDORSEMENTS	TC EXPIRES
INSPECTOR	2/4/2014
MANAGEMENT PLANNER	2/28/2014
PROJECT MANAGER	2/9/2014
AIR SAMPLING PROFESSIONAL	

ID NUMBER	ISSUED	EXPIRES
100 - 06325	3/21/2013	05/15/2014

SANTIAGO GARCIA  
855 W ADAMS ST SUITE 200  
CHICAGO, IL 60607



Environmental Health

**Alteration of this license shall result in legal action**  
This license issued under authority of the State of Illinois  
Department of Public Health  
This license is valid only when accompanied by a valid  
training course certificate.

# CERTIFICATE OF ACHIEVEMENT ASBESTOS ABATEMENT

Approved by the Illinois Department of Public Health and Indiana Department of Environmental Management

This is to certify that SANTIAGO GARCIA  
has completed the Contractor/Supervisor Recertification course and passed the examination  
on 02/09/2013 with a minimum score of 70% or better. Training was in accordance with U.S.  
E.P.A. 40 CFR 763 Subpart E, Appendix C, Asbestos Containing Materials in Schools: Model  
Accreditation Plan, TSCA II, Authorized by both AHERA & ASHARA and Indiana Rule 326 IAC  
18-2.



*N. Penick*

02/09/2013

Course Dates:

02/09/2014

Expires:

1302CSR24

Certificate Number:

Phone Number: (312) 491-0081

Director of Training

Nicholas J. Penick

Doctor of Public Health

FORM # A-008

# APPENDIX C

## Laboratory Accreditations

---



# APPENDIX D

## Laboratory Results

---

# APPENDIX E

## Chain of Custody Forms

---

## Three-Year Reinspection Key to Terms

	<b>CODE</b>	<b>KEY</b>
<b>MATERIAL</b>		
	ACBM	Asbestos Containing Building Materials
<b>MATERIAL CATEGORY</b>		
	MISC	Miscellaneous
	SURF	Surfacing
	TSI	Thermal System Insulation
<b>MATERIAL UNITS</b>		
	LF	Linear Feet
	SF	Square Feet
	CF	Cubic Feet
<b>DAMAGE TYPE</b>		
	Loc	Localized
	Dist	Distributed