

ILLINOIS DEPARTMENT OF PUBLIC HEALTH  
AHERA THREE YEAR REINSPECTION  
ASBESTOS ABATEMENT PROGRAM  
SCHOOL INFORMATION FORM

**SECTION I**

NAME OF SCHOOL DISTRICT: CHICAGO SCHOOL DIST 299  
SCHOOL ID NUMBER: 14-016-2990-2792  
SCHOOL NAME: Beasley CPC  
ADDRESS OF SCHOOL: 5165 S. State Street  
CITY: Chicago, IL, 60609

DATE LAST THREE YEAR REINSPECTION WAS COMPLETED 2/23/2010

**If the address on this form is different than the address of the building, submit a written explanation.**

**SECTION II** (Please type or print)

PLEASE COMPLETE THE FOLLOWING FOR YOUR THREE YEAR REINSPECTION:

DATE REINSPECTION COMPLETED: 4/11/2013 ENROLLMENT 185  
IDPH INSPECTOR LICENSE NUMBER: 100-03175  
IDPH LICENSED INSPECTOR NAME (Please Print): Marcos Iwankiw  
IDPH MP LICENSE NUMBER: 100-05171  
IDPH LICENSED MANAGEMENT PLANNER NAME (Please Print): Stephen Diblik

DESIGNATED PERSON (Please Print): Ms. Lynn Crivello PHONE: (773) 553-3113



4/11/2013

Signature of Designated Person

Date

**SECTION III**

PLEASE COMPLETE THE FOLLOWING INFORMATION FOR ANY CHANGES WITHIN THE SCHOOL DISTRICT.

School building has been sold. Date of Sale: \_\_\_\_\_

School has been closed. Date closed: \_\_\_\_\_

School building has been demolished. Date: \_\_\_\_\_

School building is asbestos free since last reinspection: \_\_\_\_\_

**Please explain in writing why the school building is now asbestos free and include the supporting documentation.**

If a new school building has been added to the district, submit either an exclusionary statement or a management plan and inspection report. Include the complete name, address and city of school building.

**Explain in writing if the address of the building is different than the address on this form:**

**THREE-YEAR REINSPECTION**

**CHICAGO SCHOOL DIST 299**

**Beasley CPC**

5165 S. State Street  
Chicago, IL, 60609

Unit: 29322  
Building ID: 6661

IDPH ID Number: 14-016-2990-2792

**REPORT DATE:**

Thursday, April 11, 2013

**Prepared for:**

**Chicago Public Schools**  
**125 S. Clark Street**  
**Chicago, IL 60603**

**Prepared by:**

**Carnow, Conibear and Associates**

600 West Van Buren St., Ste 500

Phone (312) 762-2900

Fax (312) 782-5145

**DO NOT REMOVE FROM SCHOOL  
REQUIRED BY FEDERAL LAW**

April 2, 2013

Mr. R. Kent Cook  
Asbestos Program  
Illinois Department of Public Health  
525 West Jefferson Street  
Springfield, Illinois 62761

Re: Chicago Public Schools - 2013 Three-Year Reinspections

Dear Mr. Cook:

Carnow, Conibear and Associates, Managing Environmental Consultant (MEC), conducted the Three-Year Reinspections and performed management plan updates for the Chicago Public Schools (CPS) facilities in Region 3,4,5 Elementary Schools. Please update your records with the following information.

School District: 299                      Unit: 29322                      Region: 04                      IDPH ID: 14-016-2990-2792

School: Beasley CPC                      Building ID: 6661

Address: 5165 S. State Street  
Chicago, IL, 60609

Building Contact:                      Contact Phone:

Current Building Owners: Chicago Public Schools

Review Date: 4/11/2013

Inspector: Marcos Iwankiw                      Inspector IDPH License: 100-03175  
Management Planner: Stephen Diblik                      Management Planner IDPH License: 100-05171

If you have any questions or comments, please contact us at (312) 762-2900

Sincerely,  
Carnow, Conibear and Associates



Stephen Diblik  
100-05171

## **Environmental Notification to Occupants**

To: Faculty, Staff and Parents  
From: Chicago Public Schools  
Date: April 02, 2013

RE: Beasley CPC, Unit 29322  
5165 S. State Street  
Chicago, IL, 60609

Dear Faculty, Staff and Parents,

This letter is to notify you that the 2013 asbestos three year re-inspection has been completed at Beasley CPC , following the Federal Asbestos Hazard Emergency Response Act (AHERA), 40 CFR Part 763, Subpart E and is available for your review at the main office of the school.

Although asbestos-containing materials have been identified at Beasley CPC, there is no reason to believe that any threat to the health of students or staff exists at this time. CPS will continue to carefully monitor the condition of asbestos-containing materials and if conditions warrant, all appropriate steps will be taken to maintain the health and safety of all building occupants.

If you have any questions regarding this matter or require additional information, please feel free to contact Ms. Lynn Crivello, the designated Local Education Authority's Designated Person at (773) 553-3113 .

## **Table of Contents**

- I. School and Inspection Information
- II. Executive Summary
- III. Methodology
- IV. Abatement History
- V. Reassessments and Recommendations
- VI. Conclusions

Table I: Inspector's Reinspection Findings

Table II: Management Planner's Review

### **APPENDICES:**

- Appendix A: Assessment Sheets, Drawings and Photos
- Appendix B: Inspector and Management Planner Licenses
- Appendix C: Laboratory Accreditations
- Appendix D: Laboratory Results
- Appendix E: Chain of Custody Forms

## SCHOOL AND INSPECTION INFORMATION

### 1. School Information

School: Beasley CPC  
Address: 5165 S. State Street  
IDPH ID: 14-016-2990-2792  
Contact:

Unit: 29322  
Chicago, IL, 60609  
Building ID: 6661  
Phone:

Region: 04

### 2. Description of Facility

Original Construction:  
Total Square Footage: 14250  
Current Occupancy: 185

Additional Construction:  
No of Floors:

### 3. LEA Designated Person

Contact: Ms. Lynn Crivello  
Address: 125 South Clark Street, 17th Floor  
Chicago, IL 60603

Phone: (773) 553-3113

### 4. Managing Environmental Consultant


MEC: Carnow, Conibear and Associates  
Contact: Dan Juneau  
Address 600 West Van Buren St., Ste 500  
Phone: (312) 762-2900

Fax: (312) 782-5145

### 5. Inspector

Inspector Name: Marcos Iwankiw


Inspector IDPH license # 100-03175

Signature:   
Date: 4/2/2013

### 6. Management Planner

Management Planner Name: Stephen Diblik

Management Planner IDPH license # 100-05171

Signature:   
Date: 4/11/2013

### 7. Review Date: 4/11/2013

### 8. LEA Designated Person's Acknowledgement

The reinspection report and recommendations have been received by me and appropriate action will be taken by the School District.

Signature: 

Date: 4/11/2013

Name: Ms. Lynn Crivello

## II. EXECUTIVE SUMMARY

Carnow, Conibear and Associates was retained by the Chicago Public Schools (CPS) to perform a three-year asbestos reinspection of the Beasley CPC. This inspection was conducted in accordance with the United States Environmental Protection Agency (USEPA) Asbestos Hazard Emergency Response Act (AHERA) part 763.92 (b), and the ongoing Operations and Maintenance Program (O&M) originally designed in the School's Asbestos Management Plan. The purpose of this three-year reinspection is to record any condition changes in the asbestos-containing building material (ACBM) in the school since the previous three-year reinspection and the six-month periodic surveillance, to identify, assess, and include any Homogeneous Areas (HA) not identified in the Management Plan, and to recommend an appropriate response action to manage asbestos.

The inspector conducted a three-year reinspection of this facility under Illinois Department of Public Health (IDPH) school reinspection requirements and AHERA, sections 763.85 and 763.88. The main building and each addition to the main building, if constructed at different dates, were inspected separately. Laboratory accreditations are included in Appendix C, laboratory results are included in Appendix D, and chain of custody forms are included in Appendix E.

Note: During previous inspections, some of the HA(s) were identified together as 9" x 9" floor tile (FT), mastics assoc. with 9" x 9" FT, 12" x 12" FT, mastics assoc. with 12" x 12" FT, pipe insulation, etc. Some of these HA(s) have been re-identified by areas that are uniform in color, texture, construction date, application date, and general appearance.

The inspector has determined the following:

A. The following HAs have changed assessment categories for Building 6661:

B. The following new homogenous areas have been identified for Building 6661:



C. This reinspection covered only physically accessible and visible areas and materials that were identified in the LEA's management plan. The following materials were concealed and/or contained in areas that were inaccessible for sampling and have been classified as Assumed:

15	Vault Door Interior Insulation
16	Roof and Flashing - Not AHERA
18	2' x 4' White Ceiling Tile
19	12" x 12" White Floor Tile
20	Mastic associated with 12" x 12" White Floor Tile
A	Water Meter Packing Insulation

The following areas were deemed to be inaccessible:

15	Vault Door Interior Insulation
5	12"x12" Gray Green Mix w/Beige Specks FT Mastic

Materials were also listed as "assumed" if they were in good condition and sampling was not conducted to avoid damage.

This reinspection was conducted by Marcos Iwankiw, IDPH License # 100-03175. The Management Plan was updated by Stephen Diblik, IDPH License # 100-05171. Inspector and Management Planner Licenses are included in Appendix B.

### **III. METHODOLOGY**

Tasks performed on-site included the following:

1. Review current management plan, identify HA(s) and extract appropriate information.
2. Examine and verify abatement records.
3. Touch and visually and physically reinspect and reassess the condition of all friable known or assumed ACBM.
4. Touch and visually and physically reinspect all non-friable known or assumed ACBM to determine whether these materials have become friable since the last inspection or periodic surveillance.
5. Identify any condition changes that may affect Hazard Ranking of known ACBM or Assumed ACBM, as well as any HA(s) that have become friable since the last reinspection.
6. Collect bulk samples from each newly discovered friable HA or previously assumed and submit for laboratory analysis.
7. Tabulate reinspection findings and submit for management planner review and recommendations with appropriate response actions based on the AHERA Damage Category of the ACBM.
8. Submit reinspection findings and management planner recommendations to the LEA within thirty (30) days for inclusion into the management plan.

### **IV. ABATEMENT HISTORY**

The information collected from the existing management plan and inspection report(s) and from interviews with the school official revealed that the following asbestos abatement was conducted at the school since the previous Three year Reinspection.

Abatement Dates:

### **V. REASSESSMENTS AND RECOMMENDATIONS**

The reassessments and recommendations are summarized in Tables I and II on the following pages. Detailed Hazard Assessment Sheets and Drawings and Photos (if applicable) are included in Appendix A.

### **VI. CONCLUSIONS**

The Beasley CPC Building 6661 Three-Year reinspection has been completed and response actions have been recommended for both friable and non-friable materials. A timely execution of the response actions recommended will enable the LEA and the Designated Person(s) to effectively manage the existing ACBM.

This three-year reinspection report should be inspected in the current Management plan at the CPS Central Office, and one (1) copy should be kept at the school for use when planning any renovation and/or demolition activities in areas where ACBM has been identified. Also, periodic surveillance documentation and any summary reports from any response actions that are executed at the school should be used to update the Management Plan.

**Table I**  
**Inspector's Reinspection Findings**

---





# Chicago Public Schools

School Beasley CPC Unit 29322 Building ID 6661

Address 5165 S. State Street Region 04

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

*Inspector's Comments are Summarized at the End of the Report*

Reinspection Date <b>4/2/2013</b>
Inspector Name <b><u>Marcos Iwankiw</u></b>
<b>100-03175</b> <b>5/15/2013</b>
Inspector's IDPH License Number / Expiration Date

### Inspector's Comments

HA Number:	Inspector Comments:
1	
10	
11	
12	
13	
14	
15	
16	
17	
18	
19	
1A	
2	
20	
2A	
3	
5	
6	
7	
8	
9	
A	
B	

# Chicago Public Schools

**School** Beasley CPC **Unit** 29322 **Building ID** 6661

**Address** 5165 S. State Street **Region** 04

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

*Inspector's Comments are Summarized at the End of the Report*

---

**Table II**

**Management Planner's Review**

---



# Chicago Public Schools

School Beasley CPC  
Address 5165 S. State Street

Unit 29322  
Chicago, IL, 60609

Building ID 6661  
Region 04

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

### Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
1	Rough Plaster Material			Washroom of Rooms 1-6, Head teacher storage, 3 electrical closets, water meter room		SURFACE					
10	Brown Baseboard Adhesive			Front desk and bench in office		MISC					
11	Exterior Metal Window Caulking - Not AHERA			Exterior of Building	Chrysotile	MISC					
12	Exterior Door Caulking - Not AHERA			Exterior of Building	No ACBM	MISC					
13	Exterior Brick - Not AHERA			Exterior of Building	No ACBM	MISC					
14	Exterior Brick Mortar - Not AHERA			Exterior of Building	No ACBM	MISC					
15	Vault Door Interior Insulation	40	SF	Vault	Assumed	TSI	Yes	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
16	Roof and Flashing - Not AHERA			Roof	Assumed	MISC					
17	Soundproofing on Sink Bottoms	30	SF	Classrooms 1-6, Parent Room and Lunchroom	Chrysotile	SURFACE	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
18	2' x 4' White Ceiling Tile	250	SF	Principal's Office and Entrance Foyer	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
19	12" x 12" White Floor Tile	3,900	SF	Room 1, 2, 3, 4, 5, 6	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
1A	Smooth Plaster Material			Kitchen & Vault	No ACBM	SURFACE					
2	2'x4' Long Pressed Wormy Pinhole Ceiling Tiles			Throughout School	No ACBM	MISC					
20	Mastic associated with 12" x 12" White Floor Tile	3,900	SF	Room 1, 2, 3, 4, 5, 6	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
2A	2'x4' Short Pressed Wormy Pinhole Ceiling Tiles			In Corridor	No ACBM	MISC					
3	12" x 12" Gray Green Mix w/Beige Specks Floor Tile	4,100	SF	All-Purpose Rm, Hallways, Offices, Vault and Storage.	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
5	12"x12" Gray Green Mix w/Beige Specks FT Mastic	4,100	SF	All-Purpose Rm, Hallways, Offices, Vault and Storage.	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
6	Light Gray Green Mix Vinyl Baseboard			Throughout Facility	No ACBM	MISC					
7	Light Gray Green Mix Vinyl Baseboard Adhesive			Throughout Facility	No ACBM	MISC					
8	Light Green & Pink Mix Carpet Adhesive			Throughout Facility	No ACBM	MISC					
9	Brown Baseboard			Main Office Corridor	No ACBM	MISC					
A	Water Meter Packing Insulation	4	SF	Mechanical Room	Assumed	TSI	Yes	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
B	Joint Compound of Fiberglass Pipe Insulation			Throughout Facility	No ACBM	TSI					

# Chicago Public Schools

**School** Beasley CPC  
**Address** 5165 S. State Street

**Unit** 29322  
 Chicago, IL, 60609

**Building ID** 6661  
**Region** 04

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

*Management Planner's Comments Summarized at the End of the Report*

Review Date	4/11/2013
Manager Planner Name	Stephen Diblik
100-05171	5/15/2013
Manager IDPH License No/Expiration	

HA Number	Management Comments
1	
10	
11	
12	
13	
14	
15	
16	
17	
18	
19	

# Chicago Public Schools

**School** Beasley CPC  
**Address** 5165 S. State Street

**Unit** 29322  
Chicago, IL, 60609

**Building ID** 6661  
**Region** 04

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates  
600 West Van Buren St., Ste 500  
Phone: (312) 762-2900 Fax: (312) 782-5145

### *Management Planner's Comments Summarized at the End of the Report*

HA Number	Management Comments
1A	
2	
20	
2A	
3	
5	
6	
7	
8	
9	
A	
B	

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29322** BUIDLING ID: **6661**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**  
SCHOOL NAME: **Beasley CPC** INSPECTION DATE: **4/2/2013**  
ADDRESS: **5165 S. State Street** IDPH LICENSE NO: **100-03175**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **1**  
MATERIAL DESCRIPTION: **Rough Plaster Material**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: FRIABLE:

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Washroom of Rooms 1-6, Head teacher storage, 3 electrical closets, water meter room**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **04/02/2013**

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29322** BUIDLING ID: **6661**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**  
SCHOOL NAME: **Beasley CPC** REVIEW DATE: **4/11/2013**  
ADDRESS: **5165 S. State Street** IDPH LICENSE NO: **100-03175**

---

HOMOGENEOUS AREA: **1**  
MATERIAL DESCRIPTION: **Rough Plaster Material**  
MATERIAL LOCATION: **Washroom of Rooms 1-6, Head teacher storage, 3 electrical closets, water meter room**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_

*Stephen Diblik*

Date: 04/11/2013

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29322** BUIDLING ID: **6661**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**  
SCHOOL NAME: **Beasley CPC** INSPECTION DATE: **4/2/2013**  
ADDRESS: **5165 S. State Street** IDPH LICENSE NO: **100-03175**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **10**  
MATERIAL DESCRIPTION: **Brown Baseboard Adhesive**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Front desk and bench in office**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **04/02/2013**

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29322** BUIDLING ID: **6661**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**  
SCHOOL NAME: **Beasley CPC** REVIEW DATE: **4/11/2013**  
ADDRESS: **5165 S. State Street** IDPH LICENSE NO: **100-03175**

---

HOMOGENEOUS AREA: **10**

MATERIAL DESCRIPTION: **Brown Baseboard Adhesive**

MATERIAL LOCATION: **Front desk and bench in office**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_

*Stephen Diblik*

Date: 04/11/2013

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29322** BUIDLING ID: **6661**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**  
SCHOOL NAME: **Beasley CPC** INSPECTION DATE: **4/2/2013**  
ADDRESS: **5165 S. State Street** IDPH LICENSE NO: **100-03175**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **11**  
MATERIAL DESCRIPTION: **Exterior Metal Window Caulking - Not AHERA**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Chrysotile** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Exterior of Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **04/02/2013**



# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29322** BUILDING ID: **6661**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**  
SCHOOL NAME: **Beasley CPC** REVIEW DATE: **4/11/2013**  
ADDRESS: **5165 S. State Street** IDPH LICENSE NO: **100-03175**

---

HOMOGENEOUS AREA: **11**

MATERIAL DESCRIPTION: **Exterior Metal Window Caulking - Not AHERA**

MATERIAL LOCATION: **Exterior of Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_

*Stephen Diblik*

Date: **04/11/2013**

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29322** BUIDLING ID: **6661**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**  
SCHOOL NAME: **Beasley CPC** INSPECTION DATE: **4/2/2013**  
ADDRESS: **5165 S. State Street** IDPH LICENSE NO: **100-03175**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **12**  
MATERIAL DESCRIPTION: **Exterior Door Caulking - Not AHERA**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Exterior of Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **04/02/2013**

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29322** BUIDLING ID: **6661**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**  
SCHOOL NAME: **Beasley CPC** REVIEW DATE: **4/11/2013**  
ADDRESS: **5165 S. State Street** IDPH LICENSE NO: **100-03175**

---

HOMOGENEOUS AREA: **12**

MATERIAL DESCRIPTION: **Exterior Door Caulking - Not AHERA**

MATERIAL LOCATION: **Exterior of Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_

*Stephen Diblik*

Date: 04/11/2013

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29322** BUIDLING ID: **6661**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**  
SCHOOL NAME: **Beasley CPC** INSPECTION DATE: **4/2/2013**  
ADDRESS: **5165 S. State Street** IDPH LICENSE NO: **100-03175**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **13**  
MATERIAL DESCRIPTION: **Exterior Brick - Not AHERA**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Exterior of Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **04/02/2013**

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29322** BUIDLING ID: **6661**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**  
SCHOOL NAME: **Beasley CPC** REVIEW DATE: **4/11/2013**  
ADDRESS: **5165 S. State Street** IDPH LICENSE NO: **100-03175**

---

HOMOGENEOUS AREA: **13**

MATERIAL DESCRIPTION: **Exterior Brick - Not AHERA**

MATERIAL LOCATION: **Exterior of Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_

*Stephen Diblik*

Date: **04/11/2013**

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29322** BUIDLING ID: **6661**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**  
SCHOOL NAME: **Beasley CPC** INSPECTION DATE: **4/2/2013**  
ADDRESS: **5165 S. State Street** IDPH LICENSE NO: **100-03175**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **14**  
MATERIAL DESCRIPTION: **Exterior Brick Mortor - Not AHERA**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Exterior of Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **04/02/2013**

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29322** BUIDLING ID: **6661**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**  
SCHOOL NAME: **Beasley CPC** REVIEW DATE: **4/11/2013**  
ADDRESS: **5165 S. State Street** IDPH LICENSE NO: **100-03175**

---

HOMOGENEOUS AREA: **14**

MATERIAL DESCRIPTION: **Exterior Brick Mortor - Not AHERA**

MATERIAL LOCATION: **Exterior of Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_

*Stephen Diblik*

Date: 04/11/2013

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29322** BUIDLING ID: **6661**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**  
SCHOOL NAME: **Beasley CPC** INSPECTION DATE: **4/2/2013**  
ADDRESS: **5165 S. State Street** IDPH LICENSE NO: **100-03175**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **15**  
MATERIAL DESCRIPTION: **Vault Door Interior Insulation**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Vault**  
MATERIAL QUANTITY: **40** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 04/02/2013



# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29322** BUIDLING ID: **6661**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**  
SCHOOL NAME: **Beasley CPC** REVIEW DATE: **4/11/2013**  
ADDRESS: **5165 S. State Street** IDPH LICENSE NO: **100-03175**

---

HOMOGENEOUS AREA: **15**

MATERIAL DESCRIPTION: **Vault Door Interior Insulation**

MATERIAL LOCATION: **Vault**

MATERIAL QUANTITY: **40**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Operations and Maintenance

Comments:

Management Planner's Signature: \_\_\_\_\_

*Stephen Diblik*

Date: 04/11/2013

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29322** BUIDLING ID: **6661**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**  
SCHOOL NAME: **Beasley CPC** INSPECTION DATE: **4/2/2013**  
ADDRESS: **5165 S. State Street** IDPH LICENSE NO: **100-03175**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **16**  
MATERIAL DESCRIPTION: **Roof and Flashing - Not AHERA**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Assumed** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Roof**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **04/02/2013**

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29322** BUIDLING ID: **6661**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**  
SCHOOL NAME: **Beasley CPC** REVIEW DATE: **4/11/2013**  
ADDRESS: **5165 S. State Street** IDPH LICENSE NO: **100-03175**

---

HOMOGENEOUS AREA: **16**

MATERIAL DESCRIPTION: **Roof and Flashing - Not AHERA**

MATERIAL LOCATION: **Roof**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_

*Stephen Diblik*

Date: 04/11/2013

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29322** BUIDLING ID: **6661**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**  
SCHOOL NAME: **Beasley CPC** INSPECTION DATE: **4/2/2013**  
ADDRESS: **5165 S. State Street** IDPH LICENSE NO: **100-03175**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **17**  
MATERIAL DESCRIPTION: **Soundproofing on Sink Bottoms**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**


MATERIAL LOCATION: **Classrooms 1-6, Parent Room and Lunchroom**

MATERIAL QUANTITY: **30** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: **04/02/2013**

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29322** BUIDLING ID: **6661**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**  
SCHOOL NAME: **Beasley CPC** REVIEW DATE: **4/11/2013**  
ADDRESS: **5165 S. State Street** IDPH LICENSE NO: **100-03175**

---

HOMOGENEOUS AREA: **17**  
MATERIAL DESCRIPTION: **Soundproofing on Sink Bottoms**  
MATERIAL LOCATION: **Classrooms 1-6, Parent Room and Lunchroom**  
MATERIAL QUANTITY: **30** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Operations and Maintenance

Comments:

Management Planner's Signature: \_\_\_\_\_

*Stephen Diblik*

Date: 04/11/2013

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29322** BUIDLING ID: **6661**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**  
SCHOOL NAME: **Beasley CPC** INSPECTION DATE: **4/2/2013**  
ADDRESS: **5165 S. State Street** IDPH LICENSE NO: **100-03175**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **18**  
MATERIAL DESCRIPTION: **2' x 4' White Ceiling Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**

MATERIAL LOCATION: **Principal's Office and Entrance Foyer**

MATERIAL QUANTITY: **250**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **04/02/2013**

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29322** BUIDLING ID: **6661**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**  
SCHOOL NAME: **Beasley CPC** REVIEW DATE: **4/11/2013**  
ADDRESS: **5165 S. State Street** IDPH LICENSE NO: **100-03175**

---

HOMOGENEOUS AREA: **18**  
MATERIAL DESCRIPTION: **2' x 4' White Ceiling Tile**  
MATERIAL LOCATION: **Principal's Office and Entrance Foyer**  
MATERIAL QUANTITY: **250** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Operations and Maintenance

Comments:

Management Planner's Signature: \_\_\_\_\_

*Stephen Diblik*

Date: 04/11/2013

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29322** BUIDLING ID: **6661**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**  
SCHOOL NAME: **Beasley CPC** INSPECTION DATE: **4/2/2013**  
ADDRESS: **5165 S. State Street** IDPH LICENSE NO: **100-03175**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **19**  
MATERIAL DESCRIPTION: **12" x 12" White Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT


This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **HIGH**  
MATERIAL LOCATION: **Room 1, 2, 3, 4, 5, 6**  
MATERIAL QUANTITY: **3900** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 04/02/2013



# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29322** BUIDLING ID: **6661**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**  
SCHOOL NAME: **Beasley CPC** REVIEW DATE: **4/11/2013**  
ADDRESS: **5165 S. State Street** IDPH LICENSE NO: **100-03175**

---

HOMOGENEOUS AREA: **19**  
MATERIAL DESCRIPTION: **12" x 12" White Floor Tile**  
MATERIAL LOCATION: **Room 1, 2, 3, 4, 5, 6**  
MATERIAL QUANTITY: **3900** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Operations and Maintenance

Comments:

Management Planner's Signature: \_\_\_\_\_

*Stephen Diblik*

Date: 04/11/2013

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29322** BUIDLING ID: **6661**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**  
SCHOOL NAME: **Beasley CPC** INSPECTION DATE: **4/2/2013**  
ADDRESS: **5165 S. State Street** IDPH LICENSE NO: **100-03175**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **1A**  
MATERIAL DESCRIPTION: **Smooth Plaster Material**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Kitchen & Vault**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **04/02/2013**

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29322** BUIDLING ID: **6661**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**  
SCHOOL NAME: **Beasley CPC** REVIEW DATE: **4/11/2013**  
ADDRESS: **5165 S. State Street** IDPH LICENSE NO: **100-03175**

---

HOMOGENEOUS AREA: **1A**

MATERIAL DESCRIPTION: **Smooth Plaster Material**

MATERIAL LOCATION: **Kitchen & Vault**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_

*Stephen Diblik*

Date: 04/11/2013

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29322** BUIDLING ID: **6661**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**  
SCHOOL NAME: **Beasley CPC** INSPECTION DATE: **4/2/2013**  
ADDRESS: **5165 S. State Street** IDPH LICENSE NO: **100-03175**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **2**  
MATERIAL DESCRIPTION: **2'x4' Long Pressed Wormy Pinhole Ceiling Tiles**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout School**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **04/02/2013**

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29322** BUIDLING ID: **6661**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**  
SCHOOL NAME: **Beasley CPC** REVIEW DATE: **4/11/2013**  
ADDRESS: **5165 S. State Street** IDPH LICENSE NO: **100-03175**

---

HOMOGENEOUS AREA: **2**

MATERIAL DESCRIPTION: **2'x4' Long Pressed Wormy Pinhole Ceiling Tiles**

MATERIAL LOCATION: **Throughout School**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_

*Stephen Diblik*

Date: **04/11/2013**

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29322** BUIDLING ID: **6661**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**  
SCHOOL NAME: **Beasley CPC** INSPECTION DATE: **4/2/2013**  
ADDRESS: **5165 S. State Street** IDPH LICENSE NO: **100-03175**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **20**  
MATERIAL DESCRIPTION: **Mastic associated with 12" x 12" White Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Room 1, 2, 3, 4 ,5 ,6**  
MATERIAL QUANTITY: **3900** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 04/02/2013

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29322** BUIDLING ID: **6661**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**  
SCHOOL NAME: **Beasley CPC** REVIEW DATE: **4/11/2013**  
ADDRESS: **5165 S. State Street** IDPH LICENSE NO: **100-03175**

---

HOMOGENEOUS AREA: **20**  
MATERIAL DESCRIPTION: **Mastic associated with 12" x 12" White Floor Tile**  
MATERIAL LOCATION: **Room 1, 2, 3, 4 ,5 ,6**  
MATERIAL QUANTITY: **3900** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Operations and Maintenance

Comments:

Management Planner's Signature: \_\_\_\_\_

*Stephen Diblik*

Date: 04/11/2013

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29322** BUIDLING ID: **6661**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**  
SCHOOL NAME: **Beasley CPC** INSPECTION DATE: **4/2/2013**  
ADDRESS: **5165 S. State Street** IDPH LICENSE NO: **100-03175**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **2A**  
MATERIAL DESCRIPTION: **2'x4' Short Pressed Wormy Pinhole Ceiling Tiles**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **In Corridor**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **04/02/2013**



# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29322** BUIDLING ID: **6661**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**  
SCHOOL NAME: **Beasley CPC** REVIEW DATE: **4/11/2013**  
ADDRESS: **5165 S. State Street** IDPH LICENSE NO: **100-03175**

---

HOMOGENEOUS AREA: **2A**

MATERIAL DESCRIPTION: **2'x4' Short Pressed Wormy Pinhole Ceiling Tiles**

MATERIAL LOCATION: **In Corridor**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_

*Stephen Diblik*

Date: 04/11/2013

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29322** BUIDLING ID: **6661**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**  
SCHOOL NAME: **Beasley CPC** INSPECTION DATE: **4/2/2013**  
ADDRESS: **5165 S. State Street** IDPH LICENSE NO: **100-03175**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **3**  
MATERIAL DESCRIPTION: **12" x 12" Gray Green Mix w/Beige Specks Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **HIGH**

MATERIAL LOCATION: **All-Purpose Rm, Hallways, Offices, Vault and Storage.**

MATERIAL QUANTITY: **4100**


MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **04/02/2013**

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29322** BUIDLING ID: **6661**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**  
SCHOOL NAME: **Beasley CPC** REVIEW DATE: **4/11/2013**  
ADDRESS: **5165 S. State Street** IDPH LICENSE NO: **100-03175**

---

HOMOGENEOUS AREA: **3**  
MATERIAL DESCRIPTION: **12" x 12" Gray Green Mix w/Beige Specks Floor Tile**  
MATERIAL LOCATION: **All-Purpose Rm, Hallways, Offices, Vault and Storage.**  
MATERIAL QUANTITY: **4100** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Operations and Maintenance

Comments:

Management Planner's Signature: \_\_\_\_\_

*Stephen Diblik*

Date: 04/11/2013

# Chicago Public Schools

## Carnow, Conibear and Associates 2013 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29322** BUIDLING ID: **6661**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**  
SCHOOL NAME: **Beasley CPC** INSPECTION DATE: **4/2/2013**  
ADDRESS: **5165 S. State Street** IDPH LICENSE NO: **100-03175**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **5**  
MATERIAL DESCRIPTION: **12"x12" Gray Green Mix w/Beige Specks FT Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**


MATERIAL LOCATION: **All-Purpose Rm, Hallways, Offices, Vault and Storage.**

MATERIAL QUANTITY: **4100** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: **04/02/2013**

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29322** BUIDLING ID: **6661**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**  
SCHOOL NAME: **Beasley CPC** REVIEW DATE: **4/11/2013**  
ADDRESS: **5165 S. State Street** IDPH LICENSE NO: **100-03175**

---

HOMOGENEOUS AREA: **5**  
MATERIAL DESCRIPTION: **12"x12" Gray Green Mix w/Beige Specks FT Mastic**  
MATERIAL LOCATION: **All-Purpose Rm, Hallways, Offices, Vault and Storage.**  
MATERIAL QUANTITY: **4100** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Operations and Maintenance

Comments:

Management Planner's Signature: \_\_\_\_\_

*Stephen Diblik*

Date: 04/11/2013

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29322** BUIDLING ID: **6661**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**  
SCHOOL NAME: **Beasley CPC** INSPECTION DATE: **4/2/2013**  
ADDRESS: **5165 S. State Street** IDPH LICENSE NO: **100-03175**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **6**  
MATERIAL DESCRIPTION: **Light Gray Green Mix Vinyl Baseboard**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout Facility**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **04/02/2013**

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29322** BUILDING ID: **6661**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**  
SCHOOL NAME: **Beasley CPC** REVIEW DATE: **4/11/2013**  
ADDRESS: **5165 S. State Street** IDPH LICENSE NO: **100-03175**

---

HOMOGENEOUS AREA: **6**

MATERIAL DESCRIPTION: **Light Gray Green Mix Vinyl Baseboard**

MATERIAL LOCATION: **Throughout Facility**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_

*Stephen Diblik*

Date: 04/11/2013

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29322** BUIDLING ID: **6661**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**  
SCHOOL NAME: **Beasley CPC** INSPECTION DATE: **4/2/2013**  
ADDRESS: **5165 S. State Street** IDPH LICENSE NO: **100-03175**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **7**  
MATERIAL DESCRIPTION: **Light Gray Green Mix Vinyl Baseboard Adhesive**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout Facility**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **04/02/2013**



# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29322** BUILDING ID: **6661**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**  
SCHOOL NAME: **Beasley CPC** REVIEW DATE: **4/11/2013**  
ADDRESS: **5165 S. State Street** IDPH LICENSE NO: **100-03175**

---

HOMOGENEOUS AREA: **7**

MATERIAL DESCRIPTION: **Light Gray Green Mix Vinyl Baseboard Adhesive**

MATERIAL LOCATION: **Throughout Facility**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_

*Stephen Diblik*

Date: 04/11/2013

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29322** BUIDLING ID: **6661**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**  
SCHOOL NAME: **Beasley CPC** INSPECTION DATE: **4/2/2013**  
ADDRESS: **5165 S. State Street** IDPH LICENSE NO: **100-03175**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **8**  
MATERIAL DESCRIPTION: **Light Green & Pink Mix Carpet Adhesive**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout Facility**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **04/02/2013**

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29322** BUIDLING ID: **6661**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**  
SCHOOL NAME: **Beasley CPC** REVIEW DATE: **4/11/2013**  
ADDRESS: **5165 S. State Street** IDPH LICENSE NO: **100-03175**

---

HOMOGENEOUS AREA: **8**

MATERIAL DESCRIPTION: **Light Green & Pink Mix Carpet Adhesive**

MATERIAL LOCATION: **Throughout Facility**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_

*Stephen Diblik*

Date: 04/11/2013

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29322** BUIDLING ID: **6661**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**  
SCHOOL NAME: **Beasley CPC** INSPECTION DATE: **4/2/2013**  
ADDRESS: **5165 S. State Street** IDPH LICENSE NO: **100-03175**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **9**  
MATERIAL DESCRIPTION: **Brown Baseboard**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Main Office Corridor**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **04/02/2013**

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29322** BUIDLING ID: **6661**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**  
SCHOOL NAME: **Beasley CPC** REVIEW DATE: **4/11/2013**  
ADDRESS: **5165 S. State Street** IDPH LICENSE NO: **100-03175**

---

HOMOGENEOUS AREA: **9**

MATERIAL DESCRIPTION: **Brown Baseboard**

MATERIAL LOCATION: **Main Office Corridor**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_

*Stephen Diblik*

Date: 04/11/2013

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29322** BUIDLING ID: **6661**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**  
SCHOOL NAME: **Beasley CPC** INSPECTION DATE: **4/2/2013**  
ADDRESS: **5165 S. State Street** IDPH LICENSE NO: **100-03175**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **A**  
MATERIAL DESCRIPTION: **Water Meter Packing Insulation**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Mechanical Room**  
MATERIAL QUANTITY: **4** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **04/02/2013**

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29322** BUILDING ID: **6661**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**  
SCHOOL NAME: **Beasley CPC** REVIEW DATE: **4/11/2013**  
ADDRESS: **5165 S. State Street** IDPH LICENSE NO: **100-03175**

---

HOMOGENEOUS AREA: **A**  
MATERIAL DESCRIPTION: **Water Meter Packing Insulation**  
MATERIAL LOCATION: **Mechanical Room**  
MATERIAL QUANTITY: **4** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Operations and Maintenance

Comments:

Management Planner's Signature: \_\_\_\_\_

*Stephen Diblik*

Date: 04/11/2013

# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29322** BUIDLING ID: **6661**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**  
SCHOOL NAME: **Beasley CPC** INSPECTION DATE: **4/2/2013**  
ADDRESS: **5165 S. State Street** IDPH LICENSE NO: **100-03175**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **B**  
MATERIAL DESCRIPTION: **Joint Compound of Fiberglass Pipe Insulation**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout Facility**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **04/02/2013**



# Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29322** BUIDLING ID: **6661**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**  
SCHOOL NAME: **Beasley CPC** REVIEW DATE: **4/11/2013**  
ADDRESS: **5165 S. State Street** IDPH LICENSE NO: **100-03175**

---

HOMOGENEOUS AREA: **B**

MATERIAL DESCRIPTION: **Joint Compound of Fiberglass Pipe Insulation**

MATERIAL LOCATION: **Throughout Facility**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_

*Stephen Diblik*

Date: 04/11/2013

# **Chicago Public Schools**

**Carnow, Conibear and Associates**

***2013 AHERA REINSPECTION***

# APPENDIX B

## **Inspector and Management Planner Licenses**

---

# Marcos Iwankiw


Licensed Illinois Asbestos Inspector, Project Manager, and  
Air Sampling Professional

Illinois Department of  
**PUBLIC HEALTH**

**ASBESTOS  
PROFESSIONAL  
LICENSE**

<b>ID NUMBER</b> 100 - 03175	<b>ISSUED</b> 6/5/2012	<b>EXPIRES</b> 05/15/2013
---------------------------------	---------------------------	------------------------------

**MARCOS IWANKIW**  
600 W. VAN BUREN STREET,  
CHICAGO, IL 60607



Environmental Health

<b>ENDORSEMENTS</b>	<b>TC EXPIRES</b>
INSPECTOR	12/8/2012
PROJECT MANAGER AIR SAMPLING PROFESSIONAL	1/23/2013

**Alteration of this license shall result in legal action**  
This license issued under authority of the State of Illinois  
Department of Public Health  
This license is valid only when accompanied by a valid  
training course certificate.

**CARNOW  
CONIBEAR**



# Occupational Training & Supply, Inc.

7233 Adams Street • Willowbrook, IL 60527 • (630) 655-3900

## Asbestos Building Inspector Refresher

Occupational Training and Supply, Inc. certifies that

### Marcos Iwankiw

**has successfully completed the 4 hour Asbestos Building Inspector Refresher Course**  
and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 10 CFR 763 Asbestos Hazard Emergency Response Act (AHERA) and TSCA Title II.

Certificate: BIR1212042318

Exam Date: 12/4/2012

Course Date: 12/4/2012

Expiration Date: 12/4/2013

Kathy DeSalvo, Director

2012



# Occupational Training & Supply, Inc.

7233 Adams Street • Willowbrook, IL 60527 • (630) 655-3900

## Steve Diblik

**has successfully completed the 4 hour Asbestos Building Inspector Refresher Course** and has passed the competency exam with a minimum score of 70%. This course is accredited by the **Illinois Department of Public Health** and the **Indiana Department of Environmental Management** for purposes of accreditation in accordance with EPA 40 CFR763, Asbestos Hazard Emergency Response Act (AHERA) and TSCA Title II. This training course complies with the requirements of TSCA Title II and is accredited by the state of Wisconsin **Department of Health Services** under CH.DHS159, Wisconsin Administration Code.

### ***Asbestos Abatement Building Inspector Refresher***

Certificate: BIRWI1301110170

Location: 12304 75<sup>th</sup> Street Kenosha, WI 53142

Course Date: 1/11/2013

Examination Date: 1/11/2013

Expiration Date: 1/11/2014

Issue Date: 1/11/2013



Duplicate Original

Kathy DeSalvo, Director

2013

# Stephen Diblik

Illinois Licensed Asbestos Inspector, Management Planner,  
Project Manager and Air Sampling Professional



## ASBESTOS PROFESSIONAL LICENSE

ID NUMBER  
**100 - 05171**

ISSUED  
**4/4/2012**

EXPIRES  
**05/15/2013**

**STEPHEN C DIBLIK**  
300 W. Adams Street, Suite 120  
Chicago, IL 60606

Environmental Health



### ENDORSEMENTS

### TC EXPIRES

INSPECTOR

1/13/2013

MANAGEMENT PLANNER

1/19/2013

PROJECT MANAGER

12/15/2012

AIR SAMPLING PROFESSIONAL

**Alteration of this license shall result in legal action**  
This license issued under authority of the State of Illinois  
Department of Public Health  
This license is valid only when accompanied by a valid  
training course certificate.

**CARNOW  
CONIBEAR**





# Occupational Training & Supply, Inc.

7233 Adams Street • Willowbrook, IL 60527 • (630) 655-3900

## Asbestos Management Planner Refresher

*Occupational Training and Supply, Inc. certifies that*

# Stephen Diblik

**has successfully completed the 4 hour Asbestos Management Planner Refresher Course** and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 10 CFR 763 Asbestos Hazard Emergency Response Act (AHERA) and TSCA Title II.

Certificate: MPR1302250732

Exam Date: 2/25/2013

Course Date: 2/25/2013

Expiration Date: 2/25/2014

  
Kathy DeSalvo  
Director

2013



# APPENDIX C

## Laboratory Accreditations

---

# APPENDIX D

## Laboratory Results

---

# APPENDIX E

## Chain of Custody Forms

---

## Three-Year Reinspection Key to Terms

	<b>CODE</b>	<b>KEY</b>
<b>MATERIAL</b>		
	ACBM	Asbestos Containing Building Materials
<b>MATERIAL CATEGORY</b>		
	MISC	Miscellaneous
	SURF	Surfacing
	TSI	Thermal System Insulation
<b>MATERIAL UNITS</b>		
	LF	Linear Feet
	SF	Square Feet
	CF	Cubic Feet
<b>DAMAGE TYPE</b>		
	Loc	Localized
	Dist	Distributed