

ILLINOIS DEPARTMENT OF PUBLIC HEALTH
AHERA THREE YEAR REINSPECTION
ASBESTOS ABATEMENT PROGRAM
SCHOOL INFORMATION FORM

SECTION I

NAME OF SCHOOL DISTRICT: CHICAGO SCHOOL DIST 299
SCHOOL ID NUMBER: 14-016-2990-2069
SCHOOL NAME: Bass School
ADDRESS OF SCHOOL: 1140 W. 66th
CITY: Chicago, IL, 60621

DATE LAST THREE YEAR REINSPECTION WAS COMPLETED **3/8/2013**

If the address on this form is different than the address of the building, submit a written explanation.

SECTION II (Please type or print)

PLEASE COMPLETE THE FOLLOWING FOR YOUR THREE YEAR REINSPECTION:

DATE REINSPECTION COMPLETED: 4/4/2016 ENROLLMENT 446
IDPH INSPECTOR LICENSE NUMBER: 100-02865
IDPH LICENSED INSPECTOR NAME (Please Print): Steven Doran
IDPH MP LICENSE NUMBER: 100-19466
IDPH LICENSED MANAGEMENT PLANNER NAME (Please Print): Evan Christian

DESIGNATED PERSON (Please Print): Robert Christlieb PHONE: (773) 553-3197



4/4/2016

Signature of Designated Person

Date

SECTION III

PLEASE COMPLETE THE FOLLOWING INFORMATION FOR ANY CHANGES WITHIN THE SCHOOL DISTRICT.

School building has been sold. Date of Sale: _____

School has been closed. Date closed: _____

School building has been demolished. Date: _____

School building is asbestos free since last reinspection: _____

Please explain in writing why the school building is now asbestos free and include the supporting documentation.

If a new school building has been added to the district, submit either an exclusionary statement or a management plan and inspection report. Include the complete name, address and city of school building.

Explain in writing if the address of the building is different than the address on this form:

THREE-YEAR REINSPECTION

CHICAGO SCHOOL DIST 299

Bass School

1140 W. 66th
Chicago, IL, 60621

Unit: 22161
Building ID: 2180

IDPH ID Number: 14-016-2990-2069

REPORT DATE:

Monday, April 04, 2016

Prepared for:

Chicago Public Schools
125 S. Clark Street
Chicago, IL 60603

Prepared by:

Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone (312) 762-2900

Fax (312) 782-5145

**DO NOT REMOVE FROM SCHOOL
REQUIRED BY FEDERAL LAW**

March 21, 2016

Mr. R. Kent Cook
Asbestos Program
Illinois Department of Public Health
525 West Jefferson Street
Springfield, Illinois 62761

Re: Chicago Public Schools - 2016 Three-Year Reinspections

Dear Mr. Cook:

Carnow, Conibear and Associates, Managing Environmental Consultant (MEC), conducted the Three-Year Reinspections and performed management plan updates for the Chicago Public Schools (CPS) facilities in Region 3,4,5 Elementary Schools. Please update your records with the following information.

School District: 299 Unit: 22161 Region: 05 IDPH ID: 14-016-2990-2069

School: Bass School Building ID: 2180

Address: 1140 W. 66th

Chicago, IL, 60621

Building Contact: Dixon, Charles Contact Phone: 773-416-2354

Current Building Owners: Chicago Public Schools

Review Date: 04/04/2016

Inspector: Steven Doran Inspector IDPH License: 100-02865
Management Planner: Evan Christian Management Planner IDPH License: 100-19466

If you have any questions or comments, please contact us at (312) 762-2900

Sincerely,
Carnow, Conibear and Associates

Evan Christian
100-19466

Environmental Notification to Occupants

To: Faculty, Staff and Parents
From: Chicago Public Schools
Date: March 21, 2016

RE: Bass School, Unit 22161
1140 W. 66th
Chicago, IL, 60621

Dear Faculty, Staff and Parents,

This letter is to notify you that the 2016 asbestos three year re-inspection has been completed at Bass School , following the Federal Asbestos Hazard Emergency Response Act (AHERA), 40 CFR Part 763, Subpart E and is available for your review at the main office of the school.

Although asbestos-containing materials have been identified at Bass School, there is no reason to believe that any threat to the health of students or staff exists at this time. CPS will continue to carefully monitor the condition of asbestos-containing materials and if conditions warrant, all appropriate steps will be taken to maintain the health and safety of all building occupants.

If you have any questions regarding this matter or require additional information, please feel free to contact Robert Christlieb, the designated Local Education Authority's Designated Person at (773) 553-3197 .

Table of Contents

- I. School and Inspection Information
- II. Executive Summary
- III. Methodology
- IV. Abatement History
- V. Reassessments and Recommendations
- VI. Conclusions

Table I: Inspector's Reinspection Findings

Table II: Management Planner's Review

APPENDICES:

- Appendix A: Assessment Sheets, Drawings and Photos
- Appendix B: Inspector and Management Planner Licenses
- Appendix C: Laboratory Accreditations
- Appendix D: Laboratory Results
- Appendix E: Chain of Custody Forms

SCHOOL AND INSPECTION INFORMATION

1. School Information

School: Bass School
Address: 1140 W. 66th
IDPH ID: 14-016-2990-2069
Contact: Dixon, Charles

Unit: 22161
Chicago, IL, 60621
Building ID: 2180
Phone: 773-416-2354

Region: 05

2. Description of Facility

Original Construction: 1939
Total Square Footage: 7009
Current Occupancy: 446

Additional Construction: 1894,1961
No of Floors: 1

3. LEA Designated Person

Contact: Robert Christlieb
Address: 125 South Clark Street, 17th Floor
Chicago, IL 60603

Phone: (773) 553-3197

4. Managing Environmental Consultant


MEC: Carnow, Conibear and Associates
Contact: Dan Juneau
Address 600 West Van Buren St., Ste 500
Phone: (312) 762-2900

Fax: (312) 782-5145

5. Inspector

Inspector Name: Steven Doran

Inspector IDPH license # 100-02865

Signature: 
Date: 3/21/2016

6. Management Planner

Management Planner Name: Evan Christian

Management Planner IDPH license # 100-19466

Signature:
Date: 04/04/2016

7. Review Date: 04/04/2016

8. LEA Designated Person's Acknowledgement

The reinspection report and recommendations have been received by me and appropriate action will be taken by the School District.

Signature: 

Date: 4/4/2016

Name: Robert Christlieb

II. EXECUTIVE SUMMARY

Carnow, Conibear and Associates was retained by the Chicago Public Schools (CPS) to perform a three-year asbestos reinspection of the Bass School. This inspection was conducted in accordance with the United States Environmental Protection Agency (USEPA) Asbestos Hazard Emergency Response Act (AHERA) part 763.92 (b), and the ongoing Operations and Maintenance Program (O&M) originally designed in the School's Asbestos Management Plan. The purpose of this three-year reinspection is to record any condition changes in the asbestos-containing building material (ACBM) in the school since the previous three-year reinspection and the six-month periodic surveillance, to identify, assess, and include any Homogeneous Areas (HA) not identified in the Management Plan, and to recommend an appropriate response action to manage asbestos.

The inspector conducted a three-year reinspection of this facility under Illinois Department of Public Health (IDPH) school reinspection requirements and AHERA, sections 763.85 and 763.88. The main building and each addition to the main building, if constructed at different dates, were inspected separately. Laboratory accreditations are included in Appendix C, laboratory results are included in Appendix D, and chain of custody forms are included in Appendix E.

Note: During previous inspections, some of the HA(s) were identified together as 9" x 9" floor tile (FT), mastics assoc. with 9" x 9" FT, 12" x 12" FT, mastics assoc. with 12" x 12" FT, pipe insulation, etc. Some of these HA(s) have been re-identified by areas that are uniform in color, texture, construction date, application date, and general appearance.

The inspector has determined the following:

A. The following HAs have changed assessment categories for Building 2180:

02	12x12 beige floor tile
12	2' x 2' Speckled Ceiling Tile
13	Spray-on Insulation
14	Brown Ceramic Floor Tile w/ Grout
15	Adhesive Associated w/ Brown Ceramic Floor Tile w/ Grout
CT1	2 X 4 Smooth Ceiling Tile
CT2	2 X 4 Ceiling Tile
FT-3	12x12 brown w/white flecks floor tile
I	aircell pipe

J	aircell joints
K	cardboard pipe
L	cardboard joints
O	aircell pipe lag
P	aircell pipe-1960 bldg
Q	aircell joints

B. The following new homogenous areas have been identified for Building 2180:

- | | |
|----|---|
| 12 | 2' x 2' Speckled Ceiling Tile |
| 13 | Spray-on Insulation |
| 14 | Brown Ceramic Floor Tile w/ Grout |
| 15 | Adhesive Associated w/ Brown Ceramic Floor Tile
w/ Grout |

C. This reinspection covered only physically accessible and visible areas and materials that were identified in the LEA's management plan. The following materials were concealed and/or contained in areas that were inaccessible for sampling and have been classified as Assumed:

04	hardcoat plaster
10	9x9 floor tile mastic
12	2' x 2' Speckled Ceiling Tile
13	Spray-on Insulation
14	Brown Ceramic Floor Tile w/ Grout
15	Adhesive Associated w/ Brown Ceramic Floor Tile w/ Grout
CM-1	blue carpet mastic
CM-2	light blue carpet mastic
CT1	2 X 4 Smooth Ceiling Tile
CT2	2 X 4 Ceiling Tile
FT-10	12x12 blue floor tile
FT-11	12x12 brown floor tile
FT-12	12x12 brown floor tile mastic
FT-2	12x12 light brown w/white specks floor tile
FT-3	12x12 brown w/white flecks floor tile
FT-4	12x12 white w/ tan and gray flecks floor tile
FT-5	linoleum
FT-7	12x12 off white w/brown & gray flecks floor tile
FT-8	12x12 brown w/white specks floor tile
FT-9	12x12 blue floor tile
FTM-2	12x12 light brown w/white specks floor tile mastic
FTM-3	12x12 brown w/white flecks floor tile mastic
FTM-5	linoleum mastic
FTM-7	12x12 off wht w/brwn & gray flecks flr tile mastic
FTM-9	12x12 blue floor tile mastic

The following areas were deemed to be inaccessible:

09	Mastic Associated w/ 12x12 beige floor tile
10	9x9 floor tile mastic
11	mastic Associated w/ 9x9 Dark and light brown floor tile
15	Adhesive Associated w/ Brown Ceramic Floor Tile w/ Grout
CM-2	light blue carpet mastic
FT-12	12x12 brown floor tile mastic
FTM-1	mastic beneath 9x9 tan floor tile
FTM-2	12x12 light brown w/white specks floor tile mastic
FTM-4	12x12 white w/ tan and gray flecks floor tile mastic

FTM-6	9x9 dark tan w/ light brown streaks floor tile mastic
FTM-8	12x12 brown w/white specks floor tile mastic
I	aircell pipe
J	aircell joints
K	cardboard pipe
L	cardboard joints
O	aircell pipe lag
P	aircell pipe-1960 bldg
Q	aircell joints

Materials were also listed as "assumed" if they were in good condition and sampling was not conducted to avoid damage.

This reinspection was conducted by Steven Doran, IDPH License # 100-02865. The Management Plan was updated by Evan Christian, IDPH License # 100-19466. Inspector and Management Planner Licenses are included in Appendix B.

III. METHODOLOGY

Tasks performed on-site included the following:

1. Review current management plan, identify HA(s) and extract appropriate information.
2. Examine and verify abatement records.
3. Touch and visually and physically reinspect and reassess the condition of all friable known or assumed ACBM.
4. Touch and visually and physically reinspect all non-friable known or assumed ACBM to determine whether these materials have become friable since the last inspection or periodic surveillance.
5. Identify any condition changes that may affect Hazard Ranking of known ACBM or Assumed ACBM, as well as any HA(s) that have become friable since the last reinspection.
6. Collect bulk samples from each newly discovered friable HA or previously assumed and submit for laboratory analysis.
7. Tabulate reinspection findings and submit for management planner review and recommendations with appropriate response actions based on the AHERA Damage Category of the ACBM.
8. Submit reinspection findings and management planner recommendations to the LEA within thirty (30) days for inclusion into the management plan.

IV. ABATEMENT HISTORY

The information collected from the existing management plan and inspection report(s) and from interviews with the school official revealed that the following asbestos abatement was conducted at the school since the previous Three year Reinspection.

Abatement Dates:

V. REASSESSMENTS AND RECOMMENDATIONS

The reassessments and recommendations are summarized in Tables I and II on the following pages. Detailed Hazard Assessment Sheets and Drawings and Photos (if applicable) are included in Appendix A.

VI. CONCLUSIONS

The Bass School Building 2180 Three-Year reinspection has been completed and response actions have been recommended for both friable and non-friable materials. A timely execution of the response actions recommended will enable the LEA and the Designated Person(s) to effectively manage the existing ACBM.

This three-year reinspection report should be inspected in the current Management plan at the CPS Central Office, and one (1) copy should be kept at the school for use when planning any renovation and/or demolition activities in areas where ACBM has been identified. Also, periodic surveillance documentation and any summary reports from any response actions that are executed at the school should be used to update the Management Plan.

Table I
Inspector's Reinspection Findings

Chicago Public Schools

School Bass School Unit 22161 Building ID 2180

Address 1140 W. 66th Region 05

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
01	hard coat plaster	75,000	SF	throughout 1894 building	AMO_CHR	SURFACE	N	NONE	0		No	ACBM with the potential for damage		LOW
02	12x12 beige floor tile	6,000	SF	1894 - rm 08, 07, 01 & bsmnt crrdr & playrms, rm 106, 103, 104, 107 & 108 & 1st flr storage & wardrobes, rooms 303-306, counselor's office, and principals office closet	CHR	MISC	N	DIST	20		Yes	ACBM with the potential for damage	5	LOW
03	9x9 black with white streaks floor tile	100	SF	1894 bldg - engineer's office, toilet	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
04	hardcoat plaster	10,400	SF	1939 building-basement assembly hall & platform	ASSUMED	SURFACE	N	NONE	0		No	ACBM with the potential for damage		LOW
07	9x9 Dark and Light Brown floor tile	3,000	SF	1960 bldg- 1st & 2nd floor west and north corridor	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
09	Mastic Associated w/ 12x12 beige floor tile	6,000	SF	1894 - rm 08,07,01 & bsmnt crrdr & playrms, rm 106,103, 104 & 1st flr strge & wardrobes, rm 303-306	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
10	9x9 floor tile mastic	100	SF	1894 bldg - engineer's office & toilet	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
11	mastic Associated w/ 9x9 Dark and light brown floor tile	3,000	SF	1960 bldg- 1st & 2nd floor west and north corridor	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
12	2' x 2' Speckled Ceiling Tile	1,500	SF	1st Floor Lunch Room and Adjacent Corridor	ASSUMED	MISC	Y	NONE	0		Yes	Any remaining friable ACBM or friable suspect ACBM		LOW
13	Spray-on Insulation	300	SF	Metal Pan Ceiling in Kitchen (N)	ASSUMED	TSI	Y	NONE	0		Yes	Any remaining friable ACBM or friable suspect ACBM		LOW
14	Brown Ceramic Floor Tile w/ Grout	600	SF	Door #8 and #5, North Entrance Foyer, Boy's and Girl's Bathrooms on 1st and 2nd Floor of	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW

Chicago Public Schools

School Bass School Unit 22161 Building ID 2180

Address 1140 W. 66th Region 05

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
FT-6	9x9 dark tan w/brown streaks floor tile	5,950	SF	room 115, 213, 214, 216, 208, 210,209,217,2nd floor faculty room	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
FT-7	12x12 off white w/brown & gray flecks floor tile			room 211	ASSUMED	MISC								
FT-8	12x12 brown w/white specks floor tile	300	SF	hall between 1939, 1960	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
FT-9	12x12 blue floor tile	3,200	SF	N. Entrance Foyer, Room 210, 2nd Floor Corridor, Engineer's Office, Auditorium	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
FTM-1	mastic beneath 9x9 tan floor tile	100	SF	basement bathroom, engineer's office toilet	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
FTM-2	12x12 light brown w/white specks floor tile mastic	600	SF	stair case landing-1894	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
FTM-3	12x12 brown w/white flecks floor tile mastic	750	SF	room 302	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
FTM-4	12x12 white w/ tan and gray flecks floor tile mastic	750	SF	room 308	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
FTM-5	linoleum mastic			room 109, 114, 113	ASSUMED	MISC								
FTM-6	9x9 dark tan w/ light brown streaks floor tile mastic	5,950	SF	room 115, 213, 214, 216, 208, 210,209,217, 2nd floor faculty room	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
FTM-7	12x12 off wht w/brwn & gray flecks flr tile mastic			room 211	ASSUMED	MISC								
FTM-8	12x12 brown w/white specks floor tile mastic	300	SF	hall between 1939, 1960	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
FTM-9	12x12 blue floor tile mastic	3,200	SF	N. Entrance Foyer, Room 210, 2nd Floor Corridor, Engineer's Office, Auditorium	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
G	Acoustical Plaster			1960 building, rms 117,115,113,110,108,111,109, girls&boys rr, JC, stairs	NO_ACBM	SURFACE								
I	aircell pipe	200	LF	1894 bldg - boys playroom, storage, book room, girls	CHR	TSI	Y	NONE	0		Yes	Any remaining friable ACBM or friable suspect ACBM		LOW

Chicago Public Schools

School Bass School Unit 22161 Building ID 2180

Address 1140 W. 66th Region 05

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

Reinspection Date 3/21/2016
Inspector Name Steven Doran
100-02865 5/15/2016
Inspector's IDPH License Number / Expiration Date

Inspector's Comments

HA Number:	Inspector Comments:
01	
02	Damage located in Rm. 108 - Tiles are "Off-white w/ streaks".
03	
04	
07	
09	Tile is "off-white w/ streaks"
10	Not observed in engineer's office.
11	
12	
13	
14	
15	
2	
BB-1	
BBM-1	
CM-1	Not observed 2016
CM-2	
CT1	
CT2	
FT-1	
FT-10	
FT-11	
FT-12	
FT-2	

Chicago Public Schools

School Bass School Unit 22161 Building ID 2180

Address 1140 W. 66th Region 05

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
FT-3	Damage is located in Rm. 302
FT-4	
FT-5	Not observed 2016 - Floors are now painted cement
FT-6	Not observed in room 209
FT-7	Not observed 2016 - Now carpet
FT-8	
FT-9	Not observed in the Auditorium
FTM-1	
FTM-2	
FTM-3	
FTM-4	
FTM-5	Not observed 2016 - Now painted cement floor
FTM-6	Not observed in room 209
FTM-7	Not observed 2016 - Now carpet
FTM-8	
FTM-9	Not observed in the Auditorium
G	
I	
J	
K	
L	
N	
O	
P	
Q	
R	

Chicago Public Schools

School Bass School **Unit** 22161 **Building ID** 2180

Address 1140 W. 66th **Region** 05

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

Table II

Management Planner's Review

Chicago Public Schools

School Bass School
Address 1140 W. 66th

Unit 22161
Chicago, IL, 60621

Building ID 2180
Region 05

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
01	hard coat plaster	75,000	SF	throughout 1894 building	Amosite, Chrysotile	SURFACE	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
02	12x12 beige floor tile	6,000	SF	1894 - rm 08, 07, 01 & bsmnt crdr & playrms, rm 106, 103, 104, 107 & 108 & 1st flr storage & wardrobes, rooms 303-306, counselor's office, and principals office closet	Chrysotile	MISC	No	20	SF	6 ACBM with the potential for damage	Repair
03	9x9 black with white streaks floor tile	100	SF	1894 bldg - engineer's office, toilet	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
04	hardcoat plaster	10,400	SF	1939 building- basement assembly hall & platform	Assumed	SURFACE	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
07	9x9 Dark and Light Brown floor tile	3,000	SF	1960 bldg- 1st & 2nd floor west and north corridor	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
09	Mastic Associated w/ 12x12 beige floor tile	6,000	SF	1894 - rm 08,07,01 & bsmnt crdr & playrms, rm 106,103, 104 & 1st flr strge & wardrobes, rm 303-306	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
10	9x9 floor tile mastic	100	SF	1894 bldg - engineer's office & toilet	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
11	mastic Associated w/ 9x9 Dark and light brown floor tile	3,000	SF	1960 bldg- 1st & 2nd floor west and north corridor	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
12	2' x 2' Speckled Ceiling Tile	1,500	SF	1st Floor Lunch Room and Adjacent Corridor	Assumed	MISC	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
13	Spray-on Insulation	300	SF	Metal Pan Ceiling in Kitchen (N)	Assumed	TSI	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
14	Brown Ceramic Floor Tile w/ Grout	600	SF	Door #8 and #5, North Entrance Foyer, Boy's and Girl's Bathrooms on 1st and 2nd Floor of 1960 Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
15	Adhesive Associated w/ Brown Ceramic Floor Tile w/ Grout	600	SF	Door #8 and #5, North Entrance Foyer, Boy's and Girl's Bathrooms on 1st and 2nd Floor of 1960 Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
2	12x12 beige floor tile	2,850	SF	Rms. 301, 302, and 308	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
BB-1	baseboard			1st, 2nd, 3rd floor corridors - 1894 building	No ACBM	MISC					
BBM-1	baseboard mastic			1st, 2nd, 3rd floor corridors - 1894 building	No ACBM	MISC					
CM-1	blue carpet mastic			Room 303, 305, Art Room	Assumed	MISC					Follow O&M Plan
CM-2	light blue carpet mastic	180	SF	assistant principal's office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
CT1	2 X 4 Smooth Ceiling Tile	1,000	SF	Kitchen	Assumed	MISC	Yes	0	SF	7 Any remaining friable ACBM or friable	Follow O&M Plan

Chicago Public Schools

School Bass School
Address 1140 W. 66th

Unit 22161
Chicago, IL, 60621

Building ID 2180
Region 05

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
CT2	2 X 4 Ceiling Tile	2,730	SF	Room 303, 305, Art Room, Principal Office, Assistant Principal's Office, Lunchroom	Assumed	MISC	Yes	0	SF	suspect ACBM 7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
FT-1	9x9 tan floor tile	100	SF	basement bathroom, engineer's toilet	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
FT-10	12x12 blue floor tile	15	SF	Faculty room	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
FT-11	12x12 brown floor tile	75	SF	Principal rest room, storage closet, main office safe	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
FT-12	12x12 brown floor tile mastic	75	SF	Principal rest room, storage closet, main office safe	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
FT-2	12x12 light brown w/white specks floor tile	600	SF	stair case landing-1894	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
FT-3	12x12 brown w/white flecks floor tile	750	SF	room 302 and Wardrobes	Assumed	MISC	No	40	SF	6 ACBM with the potential for damage	Repair
FT-4	12x12 white w/ tan and gray flecks floor tile	750	SF	Room 308	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
FT-5	linoleum			room 109, 113	Assumed	MISC					Follow O&M Plan
FT-6	9x9 dark tan w/brown streaks floor tile	5,950	SF	room 115, 213, 214, 216, 208, 210,209,217,2nd floor faculty room	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
FT-7	12x12 off white w/brown & gray flecks floor tile			room 211	Assumed	MISC					Follow O&M Plan
FT-8	12x12 brown w/white specks floor tile	300	SF	hall between 1939, 1960	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
FT-9	12x12 blue floor tile	3,200	SF	N. Entrance Foyer, Room 210, 2nd Floor Corridor, Engineer's Office, Auditorium	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
FTM-1	mastic beneath 9x9 tan floor tile	100	SF	basement bathroom, engineer's office toilet	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
FTM-2	12x12 light brown w/white specks floor tile mastic	600	SF	stair case landing-1894	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
FTM-3	12x12 brown w/white flecks floor tile mastic	750	SF	room 302	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
FTM-4	12x12 white w/ tan and gray flecks floor tile mastic	750	SF	room 308	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
FTM-5	linoleum mastic			room 109, 114, 113	Assumed	MISC					Follow O&M Plan
FTM-6	9x9 dark tan w/ light brown streaks floor tile mastic	5,950	SF	room 115, 213, 214, 216, 208, 210,209,217, 2nd floor faculty room	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
FTM-7	12x12 off wht w/brwn & gray flecks flr tile mastic			room 211	Assumed	MISC					Follow O&M Plan
FTM-8	12x12 brown w/white specks floor tile mastic	300	SF	hall between 1939, 1960	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
FTM-9	12x12 blue floor tile mastic	3,200	SF	N. Entrance Foyer, Room 210, 2nd Floor Corridor, Engineer's Office, Auditorium	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
G	Acoustical Plaster			1960 building, rms 117,115,113,110,108,111,109,	No ACBM	SURFACE					

Chicago Public Schools

School Bass School
Address 1140 W. 66th

Unit 22161
Chicago, IL, 60621

Building ID 2180
Region 05

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
				girls&boys rr, JC, stairs							
I	aircell pipe	200	LF	1894 bldg - boys playroom, storage, book room, girls playroom, fan room	Chrysotile	TSI	Yes	0	LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
J	aircell joints	30	LF	1894 bldg - boys playroom, storage, book room, girls playroom, fan room	Chrysotile	TSI	Yes	0	LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
K	cardboard pipe	200	LF	1894 bldg- basement boys & girls playroom, fan room, toilets, corridors	Chrysotile	TSI	Yes	0	LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
L	cardboard joints	20	LF	1894 bldg- basement boys & girls playroom, fan room, toilets, corridors	Chrysotile	TSI	Yes	1	LF	1 Damaged or significantly damaged friable thermal system insulating ACBM	Repair
N	fiberglass joints			1894 bldg-basement boys & girls toilets & playrooms, toilets, fan room	No ACBM	TSI					
O	aircell pipe lag	900	LF	1939 building- basement assembly room, platform, fan room	Chrysotile	TSI	Yes	1	LF	1 Damaged or significantly damaged friable thermal system insulating ACBM	Repair
P	aircell pipe-1960 bldg	100	LF	1960 bldg- 2nd floor stairwells (between room 217 & 210, between rooms 209 & mens bathroom)	Chrysotile	TSI	Yes	0	LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
Q	aircell joints	50	LF	1939 bldg - plaform, fan room	Chrysotile	TSI	Yes	0	LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
R	fiberglass joints- ABATED			1960 bldg- 2nd floor west corridor	Abated	MISC					

Chicago Public Schools

School Bass School
Address 1140 W. 66th

Unit 22161
 Chicago, IL, 60621

Building ID 2180
Region 05

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

Review Date	4/4/2016
Manager Planner Name	Evan Christian
100-19466	5/15/2016
Manager IDPH License No/Expiration	

HA Number	Management Comments
01	
02	Repair as needed then follow O&M plan.
03	
04	
07	
09	
10	If identified follow O&M procedure.
11	
12	
13	
14	
15	
2	
BB-1	
BBM-1	
CM-1	If identified follow O&M procedure.
CM-2	
CT1	
CT2	
FT-1	

Chicago Public Schools

School Bass School
Address 1140 W. 66th

Unit 22161
 Chicago, IL, 60621

Building ID 2180
Region 05

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
FT-10	
FT-11	
FT-12	
FT-2	
FT-3	Repair as needed then follow O&M plan.
FT-4	
FT-5	If identified follow O&M procedure.
FT-6	If identified follow O&M procedure.
FT-7	If identified follow O&M procedure.
FT-8	
FT-9	
FTM-1	
FTM-2	
FTM-3	
FTM-4	
FTM-5	If identified follow O&M procedure.
FTM-6	If identified follow O&M procedure.
FTM-7	If identified follow O&M procedure.
FTM-8	
FTM-9	If identified follow O&M procedure.
G	
I	
J	
K	
L	Patch and repair as needed then follow O&M plan.
N	
O	Patch and repair as needed then follow O&M plan.

Chicago Public Schools

School Bass School

Unit 22161

Building ID 2180

Address 1140 W. 66th

Chicago, IL, 60621

Region 05

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
P	
Q	
R	If identified follow O&M procedure.

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22161** BUIDLING ID: **2180**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Steven Doran**
SCHOOL NAME: **Bass School** INSPECTION DATE: **3/21/2016**
ADDRESS: **1140 W. 66th** IDPH LICENSE NO: **100-02865**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **01**
MATERIAL DESCRIPTION: **hard coat plaster**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Amosite, Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **throughout 1894 building**

MATERIAL QUANTITY: **75000**


MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/21/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22161** BUIDLING ID: **2180**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Bass School** REVIEW DATE: **4/4/2016**
ADDRESS: **1140 W. 66th** IDPH LICENSE NO: **100-02865**

HOMOGENEOUS AREA: **01**
MATERIAL DESCRIPTION: **hard coat plaster**
MATERIAL LOCATION: **throughout 1894 building**
MATERIAL QUANTITY: **75000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **04/04/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22161** BUIDLING ID: **2180**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Steven Doran**
SCHOOL NAME: **Bass School** INSPECTION DATE: **3/21/2016**
ADDRESS: **1140 W. 66th** IDPH LICENSE NO: **100-02865**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **02**
MATERIAL DESCRIPTION: **12x12 beige floor tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON: **Physical Damage
Deterioration**
DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1894 - rm 08, 07, 01 & bsmnt crrdr & playrms, rm 106, 103, 104, 107 & 108 & 1st flr storage & wardrobes, rooms 303-306, counselor's office, and principals office closet**
MATERIAL QUANTITY: **6000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS: **Damage located in Rm. 108 - Tiles are "Off-white w/ streaks".**

Inspector's Signature: _____

Steven Doran

Date: 03/21/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22161** BUIDLING ID: **2180**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Bass School** REVIEW DATE: **4/4/2016**
ADDRESS: **1140 W. 66th** IDPH LICENSE NO: **100-02865**

HOMOGENEOUS AREA: **02**
MATERIAL DESCRIPTION: **12x12 beige floor tile**
MATERIAL LOCATION: **1894 - rm 08, 07, 01 & bsmnt crdr & playrms, rm 106, 103, 104, 107 & 108 & 1st flr storage & wardrobes, rooms 303-306, counselor's office, and principals office closet**
MATERIAL QUANTITY: **6000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **20** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Repair as needed then follow O&M plan.

Management Planner's Signature: _____ Date: **04/04/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22161** BUIDLING ID: **2180**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Steven Doran**
SCHOOL NAME: **Bass School** INSPECTION DATE: **3/21/2016**
ADDRESS: **1140 W. 66th** IDPH LICENSE NO: **100-02865**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **03**
MATERIAL DESCRIPTION: **9x9 black with white streaks floor tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1894 bldg - engineer's office, toilet**
MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 03/21/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22161** BUIDLING ID: **2180**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Bass School** REVIEW DATE: **4/4/2016**
ADDRESS: **1140 W. 66th** IDPH LICENSE NO: **100-02865**

HOMOGENEOUS AREA: **03**
MATERIAL DESCRIPTION: **9x9 black with white streaks floor tile**
MATERIAL LOCATION: **1894 bldg - engineer's office, toilet**
MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **04/04/2016**

Chicago Public Schools

Carnow, Conibear and Associates 2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22161** BUIDLING ID: **2180**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Steven Doran**
SCHOOL NAME: **Bass School** INSPECTION DATE: **3/21/2016**
ADDRESS: **1140 W. 66th** IDPH LICENSE NO: **100-02865**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **04**
MATERIAL DESCRIPTION: **hardcoat plaster**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1939 building- basement assembly hall & platform**
MATERIAL QUANTITY: **10400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/21/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22161** BUIDLING ID: **2180**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Bass School** REVIEW DATE: **4/4/2016**
ADDRESS: **1140 W. 66th** IDPH LICENSE NO: **100-02865**

HOMOGENEOUS AREA: **04**

MATERIAL DESCRIPTION: **hardcoat plaster**

MATERIAL LOCATION: **1939 building- basement assembly hall & platform**

MATERIAL QUANTITY: **10400**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **04/04/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22161** BUIDLING ID: **2180**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Steven Doran**
SCHOOL NAME: **Bass School** INSPECTION DATE: **3/21/2016**
ADDRESS: **1140 W. 66th** IDPH LICENSE NO: **100-02865**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **07**
MATERIAL DESCRIPTION: **9x9 Dark and Light Brown floor tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1960 bldg- 1st & 2nd floor west and north corridor**
MATERIAL QUANTITY: **3000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 03/21/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22161** BUIDLING ID: **2180**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Bass School** REVIEW DATE: **4/4/2016**
ADDRESS: **1140 W. 66th** IDPH LICENSE NO: **100-02865**

HOMOGENEOUS AREA: **07**
MATERIAL DESCRIPTION: **9x9 Dark and Light Brown floor tile**
MATERIAL LOCATION: **1960 bldg- 1st & 2nd floor west and north corridor**
MATERIAL QUANTITY: **3000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **04/04/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22161** BUIDLING ID: **2180**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Steven Doran**
SCHOOL NAME: **Bass School** INSPECTION DATE: **3/21/2016**
ADDRESS: **1140 W. 66th** IDPH LICENSE NO: **100-02865**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **09**
MATERIAL DESCRIPTION: **Mastic Associated w/ 12x12 beige floor tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**


MATERIAL LOCATION: **1894 - rm 08,07,01 & bsmnt crdr & playrms, rm 106,103, 104 & 1st flr strge & wardrobes, rm 303-306**

MATERIAL QUANTITY: **6000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS: **Tile is "off-white w/ streaks"**

Inspector's Signature:



Date: **03/21/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22161** BUIDLING ID: **2180**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Bass School** REVIEW DATE: **4/4/2016**
ADDRESS: **1140 W. 66th** IDPH LICENSE NO: **100-02865**

HOMOGENEOUS AREA: **09**
MATERIAL DESCRIPTION: **Mastic Associated w/ 12x12 beige floor tile**
MATERIAL LOCATION: **1894 - rm 08,07,01 & bsmnt crrdr & playrms, rm 106,103, 104 & 1st flr strge & wardrobes, rm 303-306**
MATERIAL QUANTITY: **6000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **04/04/2016**

Chicago Public Schools

Carnow, Conibear and Associates 2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22161** BUIDLING ID: **2180**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Steven Doran**
SCHOOL NAME: **Bass School** INSPECTION DATE: **3/21/2016**
ADDRESS: **1140 W. 66th** IDPH LICENSE NO: **100-02865**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **10**
MATERIAL DESCRIPTION: **9x9 floor tile mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT


This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1894 bldg - engineer's office & toilet**
MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS: **Not observed in engineer's office.**

Inspector's Signature: _____



Date: 03/21/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22161** BUIDLING ID: **2180**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Bass School** REVIEW DATE: **4/4/2016**
ADDRESS: **1140 W. 66th** IDPH LICENSE NO: **100-02865**

HOMOGENEOUS AREA: **10**
MATERIAL DESCRIPTION: **9x9 floor tile mastic**
MATERIAL LOCATION: **1894 bldg - engineer's office & toilet**
MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

If identified follow O&M procedure.

Management Planner's Signature: _____ Date: **04/04/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22161** BUIDLING ID: **2180**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Steven Doran**
SCHOOL NAME: **Bass School** INSPECTION DATE: **3/21/2016**
ADDRESS: **1140 W. 66th** IDPH LICENSE NO: **100-02865**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **11**
MATERIAL DESCRIPTION: **mastic Associated w/ 9x9 Dark and light brown floor tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1960 bldg- 1st & 2nd floor west and north corridor**
MATERIAL QUANTITY: **3000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/21/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22161** BUIDLING ID: **2180**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Bass School** REVIEW DATE: **4/4/2016**
ADDRESS: **1140 W. 66th** IDPH LICENSE NO: **100-02865**

HOMOGENEOUS AREA: **11**
MATERIAL DESCRIPTION: **mastic Associated w/ 9x9 Dark and light brown floor tile**
MATERIAL LOCATION: **1960 bldg- 1st & 2nd floor west and north corridor**
MATERIAL QUANTITY: **3000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **04/04/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22161** BUIDLING ID: **2180**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Steven Doran**
SCHOOL NAME: **Bass School** INSPECTION DATE: **3/21/2016**
ADDRESS: **1140 W. 66th** IDPH LICENSE NO: **100-02865**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **2**
MATERIAL DESCRIPTION: **12x12 beige floor tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rms. 301, 302, and 308**
MATERIAL QUANTITY: **2850** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/21/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22161** BUIDLING ID: **2180**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Bass School** REVIEW DATE: **4/4/2016**
ADDRESS: **1140 W. 66th** IDPH LICENSE NO: **100-02865**

HOMOGENEOUS AREA: **2**
MATERIAL DESCRIPTION: **12x12 beige floor tile**
MATERIAL LOCATION: **Rms. 301, 302, and 308**
MATERIAL QUANTITY: **2850** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **04/04/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22161** BUIDLING ID: **2180**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Steven Doran**
SCHOOL NAME: **Bass School** INSPECTION DATE: **3/21/2016**
ADDRESS: **1140 W. 66th** IDPH LICENSE NO: **100-02865**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **BB-1**
MATERIAL DESCRIPTION: **baseboard**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:


MATERIAL LOCATION: **1st, 2nd, 3rd floor corridors - 1894 building**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **03/21/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22161** BUIDLING ID: **2180**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Bass School** REVIEW DATE: **4/4/2016**
ADDRESS: **1140 W. 66th** IDPH LICENSE NO: **100-02865**

HOMOGENEOUS AREA: **BB-1**

MATERIAL DESCRIPTION: **baseboard**

MATERIAL LOCATION: **1st, 2nd, 3rd floor corridors - 1894 building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **04/04/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22161** BUIDLING ID: **2180**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Steven Doran**
SCHOOL NAME: **Bass School** INSPECTION DATE: **3/21/2016**
ADDRESS: **1140 W. 66th** IDPH LICENSE NO: **100-02865**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **BBM-1**
MATERIAL DESCRIPTION: **baseboard mastic**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:


MATERIAL LOCATION: **1st, 2nd, 3rd floor corridors - 1894 building**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **03/21/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22161** BUIDLING ID: **2180**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Bass School** REVIEW DATE: **4/4/2016**
ADDRESS: **1140 W. 66th** IDPH LICENSE NO: **100-02865**

HOMOGENEOUS AREA: **BBM-1**

MATERIAL DESCRIPTION: **baseboard mastic**

MATERIAL LOCATION: **1st, 2nd, 3rd floor corridors - 1894 building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **04/04/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22161** BUIDLING ID: **2180**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Steven Doran**
SCHOOL NAME: **Bass School** INSPECTION DATE: **3/21/2016**
ADDRESS: **1140 W. 66th** IDPH LICENSE NO: **100-02865**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **CM-1**
MATERIAL DESCRIPTION: **blue carpet mastic**
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 303, 305, Art Room**

MATERIAL QUANTITY:


MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed 2016**

Inspector's Signature:



Date: **03/21/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22161** BUIDLING ID: **2180**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Bass School** REVIEW DATE: **4/4/2016**
ADDRESS: **1140 W. 66th** IDPH LICENSE NO: **100-02865**

HOMOGENEOUS AREA: **CM-1**

MATERIAL DESCRIPTION: **blue carpet mastic**

MATERIAL LOCATION: **Room 303, 305, Art Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

If identified follow O&M procedure.

Management Planner's Signature: _____ Date: **04/04/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22161** BUIDLING ID: **2180**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Steven Doran**
SCHOOL NAME: **Bass School** INSPECTION DATE: **3/21/2016**
ADDRESS: **1140 W. 66th** IDPH LICENSE NO: **100-02865**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **CM-2**
MATERIAL DESCRIPTION: **light blue carpet mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **assistant principal's office**

MATERIAL QUANTITY: **180**


MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/21/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22161** BUIDLING ID: **2180**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Bass School** REVIEW DATE: **4/4/2016**
ADDRESS: **1140 W. 66th** IDPH LICENSE NO: **100-02865**

HOMOGENEOUS AREA: **CM-2**
MATERIAL DESCRIPTION: **light blue carpet mastic**
MATERIAL LOCATION: **assistant principal's office**
MATERIAL QUANTITY: **180** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **04/04/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22161** BUIDLING ID: **2180**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Steven Doran**
SCHOOL NAME: **Bass School** INSPECTION DATE: **3/21/2016**
ADDRESS: **1140 W. 66th** IDPH LICENSE NO: **100-02865**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **CT1**
MATERIAL DESCRIPTION: **2 X 4 Smooth Ceiling Tile**
HISTORICAL AHERA DAMAGE CATEGORY **7 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Kitchen**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 03/21/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22161** BUIDLING ID: **2180**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Bass School** REVIEW DATE: **4/4/2016**
ADDRESS: **1140 W. 66th** IDPH LICENSE NO: **100-02865**

HOMOGENEOUS AREA: **CT1**
MATERIAL DESCRIPTION: **2 X 4 Smooth Ceiling Tile**
MATERIAL LOCATION: **Kitchen**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **04/04/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22161** BUIDLING ID: **2180**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Steven Doran**
SCHOOL NAME: **Bass School** INSPECTION DATE: **3/21/2016**
ADDRESS: **1140 W. 66th** IDPH LICENSE NO: **100-02865**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **CT2**
MATERIAL DESCRIPTION: **2 X 4 Ceiling Tile**
HISTORICAL AHERA DAMAGE CATEGORY **7 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 303, 305, Art Room, Principal Office, Assistant Principal's Office, Lunchroom**
MATERIAL QUANTITY: **2730** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/21/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22161** BUIDLING ID: **2180**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Bass School** REVIEW DATE: **4/4/2016**
ADDRESS: **1140 W. 66th** IDPH LICENSE NO: **100-02865**

HOMOGENEOUS AREA: **CT2**
MATERIAL DESCRIPTION: **2 X 4 Ceiling Tile**
MATERIAL LOCATION: **Room 303, 305, Art Room, Principal Office, Assistant Principal's Office, Lunchroom**
MATERIAL QUANTITY: **2730** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **04/04/2016**

Chicago Public Schools

Carnow, Conibear and Associates 2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22161** BUIDLING ID: **2180**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Steven Doran**
SCHOOL NAME: **Bass School** INSPECTION DATE: **3/21/2016**
ADDRESS: **1140 W. 66th** IDPH LICENSE NO: **100-02865**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **FT-1**
MATERIAL DESCRIPTION: **9x9 tan floor tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **basement bathroom, engineer's toilet**

MATERIAL QUANTITY: **100**


MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 03/21/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22161** BUIDLING ID: **2180**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Bass School** REVIEW DATE: **4/4/2016**
ADDRESS: **1140 W. 66th** IDPH LICENSE NO: **100-02865**

HOMOGENEOUS AREA: **FT-1**
MATERIAL DESCRIPTION: **9x9 tan floor tile**
MATERIAL LOCATION: **basement bathroom, engineer's toilet**
MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **04/04/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22161** BUIDLING ID: **2180**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Steven Doran**
SCHOOL NAME: **Bass School** INSPECTION DATE: **3/21/2016**
ADDRESS: **1140 W. 66th** IDPH LICENSE NO: **100-02865**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **FT-10**
MATERIAL DESCRIPTION: **12x12 blue floor tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Faculty room**
MATERIAL QUANTITY: **15** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/21/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22161** BUIDLING ID: **2180**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Bass School** REVIEW DATE: **4/4/2016**
ADDRESS: **1140 W. 66th** IDPH LICENSE NO: **100-02865**

HOMOGENEOUS AREA: **FT-10**

MATERIAL DESCRIPTION: **12x12 blue floor tile**

MATERIAL LOCATION: **Faculty room**

MATERIAL QUANTITY: **15**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **04/04/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22161** BUIDLING ID: **2180**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Steven Doran**
SCHOOL NAME: **Bass School** INSPECTION DATE: **3/21/2016**
ADDRESS: **1140 W. 66th** IDPH LICENSE NO: **100-02865**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **FT-11**
MATERIAL DESCRIPTION: **12x12 brown floor tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**


MATERIAL LOCATION: **Principal rest room, storage closet, main office safe**

MATERIAL QUANTITY: **75** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/21/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22161** BUIDLING ID: **2180**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Bass School** REVIEW DATE: **4/4/2016**
ADDRESS: **1140 W. 66th** IDPH LICENSE NO: **100-02865**

HOMOGENEOUS AREA: **FT-11**

MATERIAL DESCRIPTION: **12x12 brown floor tile**

MATERIAL LOCATION: **Principal rest room, storage closet, main office safe**

MATERIAL QUANTITY: **75**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **04/04/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22161** BUIDLING ID: **2180**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Steven Doran**
SCHOOL NAME: **Bass School** INSPECTION DATE: **3/21/2016**
ADDRESS: **1140 W. 66th** IDPH LICENSE NO: **100-02865**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **FT-12**
MATERIAL DESCRIPTION: **12x12 brown floor tile mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**


MATERIAL LOCATION: **Principal rest room, storage closet, main office safe**

MATERIAL QUANTITY: **75** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 03/21/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22161** BUIDLING ID: **2180**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Bass School** REVIEW DATE: **4/4/2016**
ADDRESS: **1140 W. 66th** IDPH LICENSE NO: **100-02865**

HOMOGENEOUS AREA: **FT-12**

MATERIAL DESCRIPTION: **12x12 brown floor tile mastic**

MATERIAL LOCATION: **Principal rest room, storage closet, main office safe**

MATERIAL QUANTITY: **75**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **04/04/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22161** BUIDLING ID: **2180**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Steven Doran**
SCHOOL NAME: **Bass School** INSPECTION DATE: **3/21/2016**
ADDRESS: **1140 W. 66th** IDPH LICENSE NO: **100-02865**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **FT-2**
MATERIAL DESCRIPTION: **12x12 light brown w/white specks floor tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **stair case landing-1894**

MATERIAL QUANTITY: **600**


MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/21/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22161** BUIDLING ID: **2180**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Bass School** REVIEW DATE: **4/4/2016**
ADDRESS: **1140 W. 66th** IDPH LICENSE NO: **100-02865**

HOMOGENEOUS AREA: **FT-2**
MATERIAL DESCRIPTION: **12x12 light brown w/white specks floor tile**
MATERIAL LOCATION: **stair case landing-1894**
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **04/04/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22161** BUIDLING ID: **2180**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Steven Doran**
SCHOOL NAME: **Bass School** INSPECTION DATE: **3/21/2016**
ADDRESS: **1140 W. 66th** IDPH LICENSE NO: **100-02865**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **FT-3**
MATERIAL DESCRIPTION: **12x12 brown w/white flecks floor tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**


RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON: **Deterioration
Physical Damage**
DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **room 302 and Wardrobes**
MATERIAL QUANTITY: **750** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS: **Damage is located in Rm. 302**

Inspector's Signature:



Date: **03/21/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22161** BUIDLING ID: **2180**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Bass School** REVIEW DATE: **4/4/2016**
ADDRESS: **1140 W. 66th** IDPH LICENSE NO: **100-02865**

HOMOGENEOUS AREA: **FT-3**
MATERIAL DESCRIPTION: **12x12 brown w/white flecks floor tile**
MATERIAL LOCATION: **room 302 and Wardrobes**
MATERIAL QUANTITY: **750** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **40** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Repair as needed then follow O&M plan.

Management Planner's Signature: _____ Date: **04/04/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22161** BUIDLING ID: **2180**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Steven Doran**
SCHOOL NAME: **Bass School** INSPECTION DATE: **3/21/2016**
ADDRESS: **1140 W. 66th** IDPH LICENSE NO: **100-02865**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **FT-4**
MATERIAL DESCRIPTION: **12x12 white w/ tan and gray flecks floor tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Room 308**

MATERIAL QUANTITY: **750**


MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/21/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22161** BUIDLING ID: **2180**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Bass School** REVIEW DATE: **4/4/2016**
ADDRESS: **1140 W. 66th** IDPH LICENSE NO: **100-02865**

HOMOGENEOUS AREA: **FT-4**

MATERIAL DESCRIPTION: **12x12 white w/ tan and gray flecks floor tile**

MATERIAL LOCATION: **Room 308**

MATERIAL QUANTITY: **750**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **04/04/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22161** BUIDLING ID: **2180**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Steven Doran**
SCHOOL NAME: **Bass School** INSPECTION DATE: **3/21/2016**
ADDRESS: **1140 W. 66th** IDPH LICENSE NO: **100-02865**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **FT-5**
MATERIAL DESCRIPTION: **linoleum**
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **room 109, 113**

MATERIAL QUANTITY:


MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed 2016 - Floors are now painted cement**

Inspector's Signature:



Date: **03/21/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22161** BUIDLING ID: **2180**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Bass School** REVIEW DATE: **4/4/2016**
ADDRESS: **1140 W. 66th** IDPH LICENSE NO: **100-02865**

HOMOGENEOUS AREA: **FT-5**

MATERIAL DESCRIPTION: **linoleum**

MATERIAL LOCATION: **room 109, 113**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

If identified follow O&M procedure.

Management Planner's Signature: _____ Date: **04/04/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22161** BUIDLING ID: **2180**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Steven Doran**
SCHOOL NAME: **Bass School** INSPECTION DATE: **3/21/2016**
ADDRESS: **1140 W. 66th** IDPH LICENSE NO: **100-02865**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **FT-6**
MATERIAL DESCRIPTION: **9x9 dark tan w/brown streaks floor tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT


This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **room 115, 213, 214, 216, 208, 210,209,217,2nd floor faculty room**
MATERIAL QUANTITY: **5950** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS: **Not observed in room 209**

Inspector's Signature:



Date: **03/21/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22161** BUIDLING ID: **2180**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Bass School** REVIEW DATE: **4/4/2016**
ADDRESS: **1140 W. 66th** IDPH LICENSE NO: **100-02865**

HOMOGENEOUS AREA: **FT-6**
MATERIAL DESCRIPTION: **9x9 dark tan w/brown streaks floor tile**
MATERIAL LOCATION: **room 115, 213, 214, 216, 208, 210,209,217,2nd floor faculty room**
MATERIAL QUANTITY: **5950** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

If identified follow O&M procedure.

Management Planner's Signature: _____ Date: **04/04/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22161** BUIDLING ID: **2180**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Steven Doran**
SCHOOL NAME: **Bass School** INSPECTION DATE: **3/21/2016**
ADDRESS: **1140 W. 66th** IDPH LICENSE NO: **100-02865**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **FT-7**
MATERIAL DESCRIPTION: **12x12 off white w/brown & gray flecks floor tile**
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **room 211**

MATERIAL QUANTITY:


MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed 2016 - Now carpet**

Inspector's Signature:



Date: **03/21/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22161** BUIDLING ID: **2180**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Bass School** REVIEW DATE: **4/4/2016**
ADDRESS: **1140 W. 66th** IDPH LICENSE NO: **100-02865**

HOMOGENEOUS AREA: **FT-7**

MATERIAL DESCRIPTION: **12x12 off white w/brown & gray flecks floor tile**

MATERIAL LOCATION: **room 211**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

If identified follow O&M procedure.

Management Planner's Signature: _____ Date: **04/04/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22161** BUIDLING ID: **2180**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Steven Doran**
SCHOOL NAME: **Bass School** INSPECTION DATE: **3/21/2016**
ADDRESS: **1140 W. 66th** IDPH LICENSE NO: **100-02865**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **FT-8**
MATERIAL DESCRIPTION: **12x12 brown w/white specks floor tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **hall between 1939, 1960**

MATERIAL QUANTITY: **300**


MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/21/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22161** BUIDLING ID: **2180**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Bass School** REVIEW DATE: **4/4/2016**
ADDRESS: **1140 W. 66th** IDPH LICENSE NO: **100-02865**

HOMOGENEOUS AREA: **FT-8**
MATERIAL DESCRIPTION: **12x12 brown w/white specks floor tile**
MATERIAL LOCATION: **hall between 1939, 1960**
MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **04/04/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22161** BUIDLING ID: **2180**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Steven Doran**
SCHOOL NAME: **Bass School** INSPECTION DATE: **3/21/2016**
ADDRESS: **1140 W. 66th** IDPH LICENSE NO: **100-02865**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **FT-9**
MATERIAL DESCRIPTION: **12x12 blue floor tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT


This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **N. Entrance Foyer, Room 210, 2nd Floor Corridor, Engineer's Office, Auditorium**
MATERIAL QUANTITY: **3200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS: **Not observed in the Auditorium**

Inspector's Signature:



Date: **03/21/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22161** BUILDING ID: **2180**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Bass School** REVIEW DATE: **4/4/2016**
ADDRESS: **1140 W. 66th** IDPH LICENSE NO: **100-02865**

HOMOGENEOUS AREA: **FT-9**
MATERIAL DESCRIPTION: **12x12 blue floor tile**
MATERIAL LOCATION: **N. Entrance Foyer, Room 210, 2nd Floor Corridor, Engineer's Office, Auditorium**
MATERIAL QUANTITY: **3200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **04/04/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22161** BUIDLING ID: **2180**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Steven Doran**
SCHOOL NAME: **Bass School** INSPECTION DATE: **3/21/2016**
ADDRESS: **1140 W. 66th** IDPH LICENSE NO: **100-02865**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **FTM-1**
MATERIAL DESCRIPTION: **mastic beneath 9x9 tan floor tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **basement bathroom, engineer's office toilet**

MATERIAL QUANTITY: **100**


MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 03/21/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22161** BUIDLING ID: **2180**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Bass School** REVIEW DATE: **4/4/2016**
ADDRESS: **1140 W. 66th** IDPH LICENSE NO: **100-02865**

HOMOGENEOUS AREA: **FTM-1**
MATERIAL DESCRIPTION: **mastic beneath 9x9 tan floor tile**
MATERIAL LOCATION: **basement bathroom, engineer's office toilet**
MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **04/04/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22161** BUIDLING ID: **2180**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Steven Doran**
SCHOOL NAME: **Bass School** INSPECTION DATE: **3/21/2016**
ADDRESS: **1140 W. 66th** IDPH LICENSE NO: **100-02865**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **FTM-2**
MATERIAL DESCRIPTION: **12x12 light brown w/white specks floor tile mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **stair case landing-1894**

MATERIAL QUANTITY: **600**


MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/21/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22161** BUIDLING ID: **2180**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Bass School** REVIEW DATE: **4/4/2016**
ADDRESS: **1140 W. 66th** IDPH LICENSE NO: **100-02865**

HOMOGENEOUS AREA: **FTM-2**
MATERIAL DESCRIPTION: **12x12 light brown w/white specks floor tile mastic**
MATERIAL LOCATION: **stair case landing-1894**
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **04/04/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22161** BUIDLING ID: **2180**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Steven Doran**
SCHOOL NAME: **Bass School** INSPECTION DATE: **3/21/2016**
ADDRESS: **1140 W. 66th** IDPH LICENSE NO: **100-02865**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **FTM-3**
MATERIAL DESCRIPTION: **12x12 brown w/white flecks floor tile mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **room 302**

MATERIAL QUANTITY: **750**


MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/21/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22161** BUIDLING ID: **2180**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Bass School** REVIEW DATE: **4/4/2016**
ADDRESS: **1140 W. 66th** IDPH LICENSE NO: **100-02865**

HOMOGENEOUS AREA: **FTM-3**
MATERIAL DESCRIPTION: **12x12 brown w/white flecks floor tile mastic**
MATERIAL LOCATION: **room 302**
MATERIAL QUANTITY: **750** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **04/04/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22161** BUIDLING ID: **2180**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Steven Doran**
SCHOOL NAME: **Bass School** INSPECTION DATE: **3/21/2016**
ADDRESS: **1140 W. 66th** IDPH LICENSE NO: **100-02865**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **FTM-4**
MATERIAL DESCRIPTION: **12x12 white w/ tan and gray flecks floor tile mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **room 308**

MATERIAL QUANTITY: **750**


MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 03/21/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22161** BUIDLING ID: **2180**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Bass School** REVIEW DATE: **4/4/2016**
ADDRESS: **1140 W. 66th** IDPH LICENSE NO: **100-02865**

HOMOGENEOUS AREA: **FTM-4**

MATERIAL DESCRIPTION: **12x12 white w/ tan and gray flecks floor tile mastic**

MATERIAL LOCATION: **room 308**

MATERIAL QUANTITY: **750**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **04/04/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22161** BUIDLING ID: **2180**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Steven Doran**
SCHOOL NAME: **Bass School** INSPECTION DATE: **3/21/2016**
ADDRESS: **1140 W. 66th** IDPH LICENSE NO: **100-02865**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **FTM-5**
MATERIAL DESCRIPTION: **linoleum mastic**
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **room 109, 114, 113**

MATERIAL QUANTITY:


MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed 2016 - Now painted cement floor**

Inspector's Signature:



Date: **03/21/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22161** BUIDLING ID: **2180**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Bass School** REVIEW DATE: **4/4/2016**
ADDRESS: **1140 W. 66th** IDPH LICENSE NO: **100-02865**

HOMOGENEOUS AREA: **FTM-5**

MATERIAL DESCRIPTION: **linoleum mastic**

MATERIAL LOCATION: **room 109, 114, 113**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

If identified follow O&M procedure.

Management Planner's Signature: _____ Date: **04/04/2016**

Chicago Public Schools

Carnow, Conibear and Associates 2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22161** BUIDLING ID: **2180**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Steven Doran**
SCHOOL NAME: **Bass School** INSPECTION DATE: **3/21/2016**
ADDRESS: **1140 W. 66th** IDPH LICENSE NO: **100-02865**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **FTM-6**
MATERIAL DESCRIPTION: **9x9 dark tan w/ light brown streaks floor tile mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT


This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **room 115, 213, 214, 216, 208, 210,209,217, 2nd floor faculty room**
MATERIAL QUANTITY: **5950** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS: **Not observed in room 209**

Inspector's Signature:



Date: **03/21/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22161** BUIDLING ID: **2180**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Bass School** REVIEW DATE: **4/4/2016**
ADDRESS: **1140 W. 66th** IDPH LICENSE NO: **100-02865**

HOMOGENEOUS AREA: **FTM-6**
MATERIAL DESCRIPTION: **9x9 dark tan w/ light brown streaks floor tile mastic**
MATERIAL LOCATION: **room 115, 213, 214, 216, 208, 210,209,217, 2nd floor faculty room**
MATERIAL QUANTITY: **5950** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

If identified follow O&M procedure.

Management Planner's Signature: _____ Date: **04/04/2016**

Chicago Public Schools

Carnow, Conibear and Associates 2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22161** BUIDLING ID: **2180**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Steven Doran**
SCHOOL NAME: **Bass School** INSPECTION DATE: **3/21/2016**
ADDRESS: **1140 W. 66th** IDPH LICENSE NO: **100-02865**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **FTM-7**
MATERIAL DESCRIPTION: **12x12 off wht w/brwn & gray flecks flr tile mastic**
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **room 211**

MATERIAL QUANTITY:


MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed 2016 - Now carpet**

Inspector's Signature:



Date: **03/21/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22161** BUIDLING ID: **2180**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Bass School** REVIEW DATE: **4/4/2016**
ADDRESS: **1140 W. 66th** IDPH LICENSE NO: **100-02865**

HOMOGENEOUS AREA: **FTM-7**

MATERIAL DESCRIPTION: **12x12 off wht w/brwn & gray flecks flr tile mastic**

MATERIAL LOCATION: **room 211**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

If identified follow O&M procedure.

Management Planner's Signature: _____ Date: **04/04/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22161** BUIDLING ID: **2180**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Steven Doran**
SCHOOL NAME: **Bass School** INSPECTION DATE: **3/21/2016**
ADDRESS: **1140 W. 66th** IDPH LICENSE NO: **100-02865**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **FTM-8**
MATERIAL DESCRIPTION: **12x12 brown w/white specks floor tile mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **hall between 1939, 1960**

MATERIAL QUANTITY: **300**


MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/21/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22161** BUIDLING ID: **2180**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Bass School** REVIEW DATE: **4/4/2016**
ADDRESS: **1140 W. 66th** IDPH LICENSE NO: **100-02865**

HOMOGENEOUS AREA: **FTM-8**
MATERIAL DESCRIPTION: **12x12 brown w/white specks floor tile mastic**
MATERIAL LOCATION: **hall between 1939, 1960**
MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **04/04/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22161** BUIDLING ID: **2180**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Steven Doran**
SCHOOL NAME: **Bass School** INSPECTION DATE: **3/21/2016**
ADDRESS: **1140 W. 66th** IDPH LICENSE NO: **100-02865**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **FTM-9**
MATERIAL DESCRIPTION: **12x12 blue floor tile mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT


This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **N. Entrance Foyer, Room 210, 2nd Floor Corridor, Engineer's Office, Auditorium**
MATERIAL QUANTITY: **3200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS: **Not observed in the Auditorium**

Inspector's Signature:



Date: **03/21/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22161** BUILDING ID: **2180**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Bass School** REVIEW DATE: **4/4/2016**
ADDRESS: **1140 W. 66th** IDPH LICENSE NO: **100-02865**

HOMOGENEOUS AREA: **FTM-9**
MATERIAL DESCRIPTION: **12x12 blue floor tile mastic**
MATERIAL LOCATION: **N. Entrance Foyer, Room 210, 2nd Floor Corridor, Engineer's Office, Auditorium**
MATERIAL QUANTITY: **3200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

If identified follow O&M procedure.

Management Planner's Signature: _____ Date: **04/04/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22161** BUIDLING ID: **2180**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Steven Doran**
SCHOOL NAME: **Bass School** INSPECTION DATE: **3/21/2016**
ADDRESS: **1140 W. 66th** IDPH LICENSE NO: **100-02865**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **G**
MATERIAL DESCRIPTION: **Acoustical Plaster**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:


MATERIAL LOCATION: **1960 building, rms 117,115,113,110,108,111,109, girls&boys rr, JC, stairs**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **03/21/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22161** BUIDLING ID: **2180**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Bass School** REVIEW DATE: **4/4/2016**
ADDRESS: **1140 W. 66th** IDPH LICENSE NO: **100-02865**

HOMOGENEOUS AREA: **G**

MATERIAL DESCRIPTION: **Acoustical Plaster**

MATERIAL LOCATION: **1960 building, rms 117,115,113,110,108,111,109, girls&boys rr, JC, stairs**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **04/04/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22161** BUIDLING ID: **2180**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Steven Doran**
SCHOOL NAME: **Bass School** INSPECTION DATE: **3/21/2016**
ADDRESS: **1140 W. 66th** IDPH LICENSE NO: **100-02865**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **I**
MATERIAL DESCRIPTION: **aircell pipe**
HISTORICAL AHERA DAMAGE CATEGORY **7 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1894 bldg - boys playroom, storage, book room, girls playroom, fan room**
MATERIAL QUANTITY: **200** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: _____



Date: 03/21/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22161** BUIDLING ID: **2180**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Bass School** REVIEW DATE: **4/4/2016**
ADDRESS: **1140 W. 66th** IDPH LICENSE NO: **100-02865**

HOMOGENEOUS AREA: **I**
MATERIAL DESCRIPTION: **aircell pipe**
MATERIAL LOCATION: **1894 bldg - boys playroom, storage, book room, girls playroom, fan room**
MATERIAL QUANTITY: **200** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **04/04/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22161** BUIDLING ID: **2180**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Steven Doran**
SCHOOL NAME: **Bass School** INSPECTION DATE: **3/21/2016**
ADDRESS: **1140 W. 66th** IDPH LICENSE NO: **100-02865**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **J**
MATERIAL DESCRIPTION: **aircell joints**
HISTORICAL AHERA DAMAGE CATEGORY **7 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1894 bldg - boys playroom, storage, book room, girls playroom, fan room**
MATERIAL QUANTITY: **30** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: _____



Date: 03/21/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22161** BUIDLING ID: **2180**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Bass School** REVIEW DATE: **4/4/2016**
ADDRESS: **1140 W. 66th** IDPH LICENSE NO: **100-02865**

HOMOGENEOUS AREA: **J**
MATERIAL DESCRIPTION: **aircell joints**
MATERIAL LOCATION: **1894 bldg - boys playroom, storage, book room, girls playroom, fan room**
MATERIAL QUANTITY: **30** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **04/04/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22161** BUIDLING ID: **2180**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Steven Doran**
SCHOOL NAME: **Bass School** INSPECTION DATE: **3/21/2016**
ADDRESS: **1140 W. 66th** IDPH LICENSE NO: **100-02865**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **K**
MATERIAL DESCRIPTION: **cardboard pipe**
HISTORICAL AHERA DAMAGE CATEGORY **7 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1894 bldg- basement boys & girls playroom, fan room, toilets, corridors**
MATERIAL QUANTITY: **200** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: _____



Date: 03/21/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22161** BUIDLING ID: **2180**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Bass School** REVIEW DATE: **4/4/2016**
ADDRESS: **1140 W. 66th** IDPH LICENSE NO: **100-02865**

HOMOGENEOUS AREA: **K**
MATERIAL DESCRIPTION: **cardboard pipe**
MATERIAL LOCATION: **1894 bldg- basement boys & girls playroom, fan room, toilets, corridors**
MATERIAL QUANTITY: **200** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **04/04/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22161** BUIDLING ID: **2180**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Steven Doran**
SCHOOL NAME: **Bass School** INSPECTION DATE: **3/21/2016**
ADDRESS: **1140 W. 66th** IDPH LICENSE NO: **100-02865**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **L**
MATERIAL DESCRIPTION: **cardboard joints**
HISTORICAL AHERA DAMAGE CATEGORY **1 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **1. Damaged or significantly damaged friable thermal system insulating ACBM**

DAMAGE REASON: **Deterioration
Physical Damage**
DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1894 bldg- basement boys & girls playroom, fan room, toilets, corridors**
MATERIAL QUANTITY: **20** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: DAMAGE UNITS: **LF**
COMMENTS:

Inspector's Signature: _____

Steven Doran

Date: 03/21/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22161** BUIDLING ID: **2180**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Bass School** REVIEW DATE: **4/4/2016**
ADDRESS: **1140 W. 66th** IDPH LICENSE NO: **100-02865**

HOMOGENEOUS AREA: **L**
MATERIAL DESCRIPTION: **cardboard joints**
MATERIAL LOCATION: **1894 bldg- basement boys & girls playroom, fan room, toilets, corridors**
MATERIAL QUANTITY: **20** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **1** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Patch and repair as needed then follow O&M plan.

Management Planner's Signature: _____ Date: **04/04/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22161** BUIDLING ID: **2180**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Steven Doran**
SCHOOL NAME: **Bass School** INSPECTION DATE: **3/21/2016**
ADDRESS: **1140 W. 66th** IDPH LICENSE NO: **100-02865**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **N**
MATERIAL DESCRIPTION: **fiberglass joints**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:


MATERIAL LOCATION: **1894 bldg-basement boys & girls toilets & playrooms, toilets, fan room**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **03/21/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22161** BUIDLING ID: **2180**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Bass School** REVIEW DATE: **4/4/2016**
ADDRESS: **1140 W. 66th** IDPH LICENSE NO: **100-02865**

HOMOGENEOUS AREA: **N**

MATERIAL DESCRIPTION: **fiberglass joints**

MATERIAL LOCATION: **1894 bldg-basement boys & girls toilets & playrooms, toilets, fan room**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **04/04/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22161** BUIDLING ID: **2180**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Steven Doran**
SCHOOL NAME: **Bass School** INSPECTION DATE: **3/21/2016**
ADDRESS: **1140 W. 66th** IDPH LICENSE NO: **100-02865**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **0**
MATERIAL DESCRIPTION: **aircell pipe lag**
HISTORICAL AHERA DAMAGE CATEGORY **1 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **1. Damaged or significantly damaged friable thermal system insulating ACBM**

DAMAGE REASON: **Deterioration
Physical Damage**
DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1939 building- basement assembly room, platform, fan room**
MATERIAL QUANTITY: **900** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: DAMAGE UNITS: **LF**
COMMENTS:

Inspector's Signature: _____

Steven Doran

Date: 03/21/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22161** BUIDLING ID: **2180**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Bass School** REVIEW DATE: **4/4/2016**
ADDRESS: **1140 W. 66th** IDPH LICENSE NO: **100-02865**

HOMOGENEOUS AREA: **0**
MATERIAL DESCRIPTION: **aircell pipe lag**
MATERIAL LOCATION: **1939 building- basement assembly room, platform, fan room**
MATERIAL QUANTITY: **900** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **1** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Patch and repair as needed then follow O&M plan.

Management Planner's Signature: _____ Date: **04/04/2016**

Chicago Public Schools

Carnow, Conibear and Associates 2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22161** BUIDLING ID: **2180**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Steven Doran**
SCHOOL NAME: **Bass School** INSPECTION DATE: **3/21/2016**
ADDRESS: **1140 W. 66th** IDPH LICENSE NO: **100-02865**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **P**
MATERIAL DESCRIPTION: **aircell pipe-1960 bldg**
HISTORICAL AHERA DAMAGE CATEGORY **7 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **1960 bldg- 2nd floor stairwells (between room 217 & 210, between rooms 209 & mens bathroom)**

MATERIAL QUANTITY: **100** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: _____

Steven Doran

Date: 03/21/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22161** BUIDLING ID: **2180**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Bass School** REVIEW DATE: **4/4/2016**
ADDRESS: **1140 W. 66th** IDPH LICENSE NO: **100-02865**

HOMOGENEOUS AREA: **P**
MATERIAL DESCRIPTION: **aircell pipe-1960 bldg**
MATERIAL LOCATION: **1960 bldg- 2nd floor stairwells (between room 217 & 210, between rooms 209 & mens bathroom)**
MATERIAL QUANTITY: **100** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **04/04/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22161** BUIDLING ID: **2180**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Steven Doran**
SCHOOL NAME: **Bass School** INSPECTION DATE: **3/21/2016**
ADDRESS: **1140 W. 66th** IDPH LICENSE NO: **100-02865**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **Q**
MATERIAL DESCRIPTION: **aircell joints**
HISTORICAL AHERA DAMAGE CATEGORY **7 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1939 bldg - plaform, fan room**
MATERIAL QUANTITY: **50** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature:



Date: **03/21/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22161** BUIDLING ID: **2180**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Bass School** REVIEW DATE: **4/4/2016**
ADDRESS: **1140 W. 66th** IDPH LICENSE NO: **100-02865**

HOMOGENEOUS AREA: **Q**
MATERIAL DESCRIPTION: **aircell joints**
MATERIAL LOCATION: **1939 bldg - plaform, fan room**
MATERIAL QUANTITY: **50** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **04/04/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22161** BUIDLING ID: **2180**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Steven Doran**
SCHOOL NAME: **Bass School** INSPECTION DATE: **3/21/2016**
ADDRESS: **1140 W. 66th** IDPH LICENSE NO: **100-02865**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **R**
MATERIAL DESCRIPTION: **fiberglass joints- ABATED**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1960 bldg- 2nd floor west corridor**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **03/21/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22161** BUIDLING ID: **2180**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Bass School** REVIEW DATE: **4/4/2016**
ADDRESS: **1140 W. 66th** IDPH LICENSE NO: **100-02865**

HOMOGENEOUS AREA: **R**

MATERIAL DESCRIPTION: **fiberglass joints- ABATED**

MATERIAL LOCATION: **1960 bldg- 2nd floor west corridor**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

If identified follow O&M procedure.

Management Planner's Signature: _____ Date: **04/04/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION


Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22161** BUILDING ID: **2180**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Steven Doran**
SCHOOL NAME: **Bass School** INSPECTION DATE: **3/21/2016**
ADDRESS: **1140 W. 66th** IDPH LICENSE NO: **100-02865**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **12**
MATERIAL DESCRIPTION: **2' x 2' Speckled Ceiling Tile**
MATERIAL LOCATION: **1st Floor Lunch Room and Adjacent Corridor**
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**
MATERIAL CATEGORY: **MISC** FRIABLE: **Yes**
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **LOW** CONDITION:
AHERA DAMAGE CATEGORY: **7 Any remaining friable ACBM or friable suspect ACBM**
ACCESSIBILITY: **Barely Reachable** DAMAGE REASON:
DAMAGE QUANTITY: **0** DAMAGE REASON:
DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature:



Date: **03/21/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22161** BUILDING ID: **2180**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Bass School** REVIEW DATE: **4/4/2016**
ADDRESS: **1140 W. 66th** IDPH LICENSE NO: **100-02865**

HOMOGENEOUS AREA: **12**

MATERIAL DESCRIPTION: **2' x 2' Speckled Ceiling Tile**

MATERIAL LOCATION: **1st Floor Lunch Room and Adjacent Corridor**

MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____ Date: **04/04/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22161** BUILDING ID: **2180**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Steven Doran**
SCHOOL NAME: **Bass School** INSPECTION DATE: **3/21/2016**
ADDRESS: **1140 W. 66th** IDPH LICENSE NO: **100-02865**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **13**
MATERIAL DESCRIPTION: **Spray-on Insulation**
MATERIAL LOCATION: **Metal Pan Ceiling in Kitchen (N)**
MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**
MATERIAL CATEGORY: **TSI** FRIABLE: **Yes**
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **LOW** CONDITION:
AHERA DAMAGE CATEGORY: **7 Any remaining friable ACBM or friable suspect ACBM**
ACCESSIBILITY: **Within Reach** DAMAGE REASON:
DAMAGE QUANTITY: **0** DAMAGE REASON:
DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____



Date: 03/21/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22161** BUILDING ID: **2180**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Bass School** REVIEW DATE: **4/4/2016**
ADDRESS: **1140 W. 66th** IDPH LICENSE NO: **100-02865**

HOMOGENEOUS AREA: **13**

MATERIAL DESCRIPTION: **Spray-on Insulation**

MATERIAL LOCATION: **Metal Pan Ceiling in Kitchen (N)**

MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____ Date: **04/04/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22161** BUILDING ID: **2180**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Steven Doran**
SCHOOL NAME: **Bass School** INSPECTION DATE: **3/21/2016**
ADDRESS: **1140 W. 66th** IDPH LICENSE NO: **100-02865**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **14**

MATERIAL DESCRIPTION: **Brown Ceramic Floor Tile w/ Grout**

MATERIAL LOCATION: **Door #8 and #5, North Entrance Foyer, Boy's and Girl's Bathrooms on 1st and 2nd Floor of 1960 Building**

MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**

MATERIAL CATEGORY: **MISC** FRIABLE: **No**

ASBESTOS TYPE: **Assumed**

DISTURBANCE POTENTIAL: **LOW** CONDITION:

AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**

ACCESSIBILITY: **Within Reach** DAMAGE REASON:
DAMAGE REASON:
DAMAGE REASON:

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____

Steven Doran

Date: 03/21/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22161** BUILDING ID: **2180**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Bass School** REVIEW DATE: **4/4/2016**
ADDRESS: **1140 W. 66th** IDPH LICENSE NO: **100-02865**

HOMOGENEOUS AREA: **14**

MATERIAL DESCRIPTION: **Brown Ceramic Floor Tile w/ Grout**

MATERIAL LOCATION: **Door #8 and #5, North Entrance Foyer, Boy's and Girl's Bathrooms on 1st and 2nd Floor of 1960 Building**

MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____ Date: **04/04/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22161** BUILDING ID: **2180**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Steven Doran**
SCHOOL NAME: **Bass School** INSPECTION DATE: **3/21/2016**
ADDRESS: **1140 W. 66th** IDPH LICENSE NO: **100-02865**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **15**

MATERIAL DESCRIPTION: **Adhesive Associated w/ Brown Ceramic Floor Tile w/ Grout**

MATERIAL LOCATION: **Door #8 and #5, North Entrance Foyer, Boy's and Girl's Bathrooms on 1st and 2nd Floor of 1960 Building**

MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**

MATERIAL CATEGORY: **MISC** FRIABLE: **No**

ASBESTOS TYPE: **Assumed**

DISTURBANCE POTENTIAL: **LOW** CONDITION:

AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**


ACCESSIBILITY: **Not Reachable** DAMAGE REASON:

DAMAGE QUANTITY: **0** DAMAGE REASON:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 03/21/2016

Chicago Public Schools

Carnow, Conibear and Associates 2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22161** BUILDING ID: **2180**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Bass School** REVIEW DATE: **4/4/2016**
ADDRESS: **1140 W. 66th** IDPH LICENSE NO: **100-02865**

HOMOGENEOUS AREA: **15**

MATERIAL DESCRIPTION: **Adhesive Associated w/ Brown Ceramic Floor Tile w/ Grout**

MATERIAL LOCATION: **Door #8 and #5, North Entrance Foyer, Boy's and Girl's Bathrooms on 1st and 2nd Floor of 1960 Building**

MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:


COMMENTS:

Management Planner's Signature: _____ Date: **04/04/2016**

APPENDIX B

Inspector and Management Planner Licenses

2015



OCCUPATIONAL TRAINING & SUPPLY, INC.

7233 S. Adams Street ♦ Willowbrook, IL 60527 ♦ (630) 655-3900

Asbestos Abatement Supervisor Refresher

Occupational Training & Supply, Inc. certifies that

Steven Doran

has successfully completed the Asbestos Abatement Supervisor Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency Response Act (AHERA) and TSCA Title II.

Course Date: 4/13/2015

Exam Date: 4/13/2015

Expiration Date: 4/13/2016

Certificate Number: ASR1504131973

Kathy DeSalvo, Director

IDPH ASBESTOS PROFESSIONAL LICENSE

ID NUMBER 100 - 02865 ISSUED 5/4/2015 EXPIRES 05/15/2016

STEVEN DORAN
3340 MAPLE ST.
EVERGREEN PARK, IL 60805



Environmental Health

ENDORSEMENTS

TC EXPIRES

INSPECTOR	2/14/2016
MANAGEMENT PLANNER	5/1/2015
PROJECT MANAGER	3/31/2015
AIR SAMPLING PROFESSIONAL	

Alteration of this license shall result in legal action.
This license issued under authority of the State of Illinois
Department of Public Health
This license is valid only when accompanied by a valid
training course certificate.

CERTIFICATE OF ACHIEVEMENT ASBESTOS ABATEMENT

Accredited by the Illinois Department of Public Health

This is to certify that STEVEN DORAN
has completed the ASBESTOS INSPECTOR'S REFRESHER course and successfully passed the examination on 02/14/2015 with a minimum score of 70% or better. Training was in accordance with U.S. E.P.A. 40 CFR 763 Subpart E, Appendix C, Asbestos Containing Materials in Schools. Model Accreditation Plan, TSCA II, Authorized by both AHERA & ASHARA.



02/14/2015

Course Dates:

02/14/2016

Expires:

1502BIR12

Certificate Number:


Phone: 312-491-0081

Director of Training
Nicholas J. Penff
Doctor of Public Health

FORM # A-010B

Evan Christian

Illinois Licensed Project Manager, and Air Sampling Professional



ENDORSEMENTS	TC EXPIRES
PROJECT MANAGER AIR SAMPLING PROFESSIONAL	12/12/2015
Alteration of this license shall result in legal action This license issued under authority of the State of Illinois Department of Public Health This license is valid only when accompanied by a valid training course certificate.	

**CARNOW
CONIBEAR**

2015



OCCUPATIONAL TRAINING & SUPPLY, INC.

7233 S. Adams Street ♦ Willowbrook, IL 60527 ♦ (630) 655-3900

Asbestos Building Inspector Refresher

Occupational Training & Supply, Inc. certifies that

Evan Christian

has successfully completed the Asbestos Building Inspector Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 12/2/2015

Exam Date: 12/2/2015

Expiration Date: 12/2/2016

Certificate Number: BIR1512024159



Katy DeSalvo, Director

Reliable
Environmental
Solutions, Inc. **RES**

This is to certify that **Evan Christian**

*has on January 28 & 29, 2016, in Springfield, Illinois,
completed the requirements for asbestos accreditation under Section 206 of TSCA Title II*

Asbestos Management Planner Initial Training

*as accredited by the State of Illinois and approved by the U.S.E.P.A. under 40 CFR 763 (AHERA)
and passed the associated examination with a score of 70% or higher*

Course Date: January 28 & 29, 2016

Examination Date: January 29, 2016

Expiration Date: January 29, 2017

Certificate Number: MP/0103

William S. Williams

Training Program Manager, William S. Williams

4211 Westgate Drive, Springfield, Illinois ☐ 217.787.9800 ☐ 217.787.9801 FAX ☐ www.ReliableEnv.com

APPENDIX C

Laboratory Accreditations

APPENDIX D

Laboratory Results

APPENDIX E

Chain of Custody Forms

Three-Year Reinspection Key to Terms

	CODE	KEY
MATERIAL		
	ACBM	Asbestos Containing Building Materials
MATERIAL CATEGORY		
	MISC	Miscellaneous
	SURF	Surfacing
	TSI	Thermal System Insulation
MATERIAL UNITS		
	LF	Linear Feet
	SF	Square Feet
	CF	Cubic Feet
DAMAGE TYPE		
	Loc	Localized
	Dist	Distributed