

ILLINOIS DEPARTMENT OF PUBLIC HEALTH  
AHERA THREE YEAR REINSPECTION  
ASBESTOS ABATEMENT PROGRAM  
SCHOOL INFORMATION FORM

**SECTION I**

NAME OF SCHOOL DISTRICT: CHICAGO SCHOOL DIST 299  
SCHOOL ID NUMBER: 14-016-2990-2101  
SCHOOL NAME: Budlong School  
ADDRESS OF SCHOOL: 2701 W Foster Avenue  
CITY: Chicago, IL, 60625

DATE LAST THREE YEAR REINSPECTION WAS COMPLETED **3/26/2013**

**If the address on this form is different than the address of the building, submit a written explanation.**

**SECTION II** (Please type or print)

PLEASE COMPLETE THE FOLLOWING FOR YOUR THREE YEAR REINSPECTION:

DATE REINSPECTION COMPLETED: 5/4/2016 ENROLLMENT 804  
IDPH INSPECTOR LICENSE NUMBER: 100-07210  
IDPH LICENSED INSPECTOR NAME (Please Print): Michael Holvay  
IDPH MP LICENSE NUMBER: 100-04019  
IDPH LICENSED MANAGEMENT PLANNER NAME (Please Print): Arturo Saenz

DESIGNATED PERSON (Please Print): Robert Christlieb PHONE: (773) 553-3197



5/4/2016

Signature of Designated Person

Date

**SECTION III**

PLEASE COMPLETE THE FOLLOWING INFORMATION FOR ANY CHANGES WITHIN THE SCHOOL DISTRICT.

School building has been sold. Date of Sale: \_\_\_\_\_

School has been closed. Date closed: \_\_\_\_\_

School building has been demolished. Date: \_\_\_\_\_

School building is asbestos free since last reinspection: \_\_\_\_\_

**Please explain in writing why the school building is now asbestos free and include the supporting documentation.**

If a new school building has been added to the district, submit either an exclusionary statement or a management plan and inspection report. Include the complete name, address and city of school building.

**Explain in writing if the address of the building is different than the address on this form:**

**THREE-YEAR REINSPECTION**

**CHICAGO SCHOOL DIST 299**

**Budlong School**

2701 W Foster Avenue  
Chicago, IL, 60625

Unit: 22391  
Building ID: 2440

IDPH ID Number: 14-016-2990-2101

**REPORT DATE:**

Wednesday, May 04, 2016

**Prepared for:**

**Chicago Public Schools**  
**125 S. Clark Street**  
**Chicago, IL 60603**

**Prepared by:**

**GSG Consultants, Inc.**

855 W. Adams St., Ste. 200

Phone (312) 733-6262

Fax (312) 733-5612

**DO NOT REMOVE FROM SCHOOL  
REQUIRED BY FEDERAL LAW**

March 8, 2016

Mr. R. Kent Cook  
Asbestos Program  
Illinois Department of Public Health  
525 West Jefferson Street  
Springfield, Illinois 62761

Re: Chicago Public Schools - 2016 Three-Year Reinspections

Dear Mr. Cook:

GSG Consultants, Inc., Managing Environmental Consultant (MEC), conducted the Three-Year Reinspections and performed management plan updates for the Chicago Public Schools (CPS) facilities in Region 1,2,6 Elementary Schools. Please update your records with the following information.

School District: 299                      Unit: 22391                      Region: 01                      IDPH ID: 14-016-2990-2101

School: Budlong School                      Building ID: 2440

Address: 2701 W Foster Avenue  
Chicago, IL, 60625

Building Contact: Gorder, Erik                      Contact Phone: 773-914-5327

Current Building Owners: Chicago Public Schools

Review Date: 03/28/2016

Inspector: Michael Holvay                      Inspector IDPH License: 100-07210  
Management Planner: Arturo Saenz                      Management Planner IDPH License: 100-04019

If you have any questions or comments, please contact us at (312) 733-6262

Sincerely,  
GSG Consultants, Inc.



Arturo Saenz  
100-04019

## **Environmental Notification to Occupants**

To: Faculty, Staff and Parents  
From: Chicago Public Schools  
Date: March 08, 2016

RE: Budlong School, Unit 22391  
2701 W Foster Avenue  
Chicago, IL, 60625

Dear Faculty, Staff and Parents,

This letter is to notify you that the 2016 asbestos three year re-inspection has been completed at Budlong School , following the Federal Asbestos Hazard Emergency Response Act (AHERA), 40 CFR Part 763, Subpart E and is available for your review at the main office of the school.

Although asbestos-containing materials have been identified at Budlong School, there is no reason to believe that any threat to the health of students or staff exists at this time. CPS will continue to carefully monitor the condition of asbestos-containing materials and if conditions warrant, all appropriate steps will be taken to maintain the health and safety of all building occupants.

If you have any questions regarding this matter or require additional information, please feel free to contact Robert Christlieb, the designated Local Education Authority's Designated Person at (773) 553-3197 .

## **Table of Contents**

- I. School and Inspection Information
- II. Executive Summary
- III. Methodology
- IV. Abatement History
- V. Reassessments and Recommendations
- VI. Conclusions

Table I: Inspector's Reinspection Findings

Table II: Management Planner's Review

### **APPENDICES:**

- Appendix A: Assessment Sheets, Drawings and Photos
- Appendix B: Inspector and Management Planner Licenses
- Appendix C: Laboratory Accreditations
- Appendix D: Laboratory Results
- Appendix E: Chain of Custody Forms

## SCHOOL AND INSPECTION INFORMATION

### 1. School Information

School:	Budlong School	Unit: 22391	Region: 01
Address:	2701 W Foster Avenue	Chicago, IL, 60625	
IDPH ID:	14-016-2990-2101	Building ID: 2440	
Contact:	Gorder, Erik	Phone: 773-914-5327	

### 2. Description of Facility

Original Construction:	1907	Additional Construction:	1955, 1996, 1996
Total Square Footage:	75773	No of Floors:	3
Current Occupancy:	804		

### 3. LEA Designated Person

Contact:	Robert Christlieb	Phone:	(773) 553-3197
Address:	125 South Clark Street, 17th Floor		
	Chicago, IL 60603		


### 4. Managing Environmental Consultant

MEC:	GSG Consultants, Inc.		
Contact:	Arturo Saenz		
Address:	855 W. Adams St., Ste. 200		
Phone:	(312) 733-6262	Fax:	(312) 733-5612

### 5. Inspector

Inspector Name: Michael Holvay

Inspector IDPH license # 100-07210




Michael Holvay  
Project Manager

Signature:  
Date: 3/8/2016

### 6. Management Planner

Management Planner Name: Arturo Saenz

Management Planner IDPH license # 100-04019



Signature:  
Date: 03/28/2016

### 7. Review Date: 03/28/2016

### 8. LEA Designated Person's Acknowledgement

The reinspection report and recommendations have been received by me and appropriate action will be taken by the School District.

Signature:



Date: 5/4/2016

Name: Robert Christlieb

## II. EXECUTIVE SUMMARY

GSG Consultants, Inc. was retained by the Chicago Public Schools (CPS) to perform a three-year asbestos reinspection of the Budlong School. This inspection was conducted in accordance with the United States Environmental Protection Agency (USEPA) Asbestos Hazard Emergency Response Act (AHERA) part 763.92 (b), and the ongoing Operations and Maintenance Program (O&M) originally designed in the School's Asbestos Management Plan. The purpose of this three-year reinspection is to record any condition changes in the asbestos-containing building material (ACBM) in the school since the previous three-year reinspection and the six-month periodic surveillance, to identify, assess, and include any Homogeneous Areas (HA) not identified in the Management Plan, and to recommend an appropriate response action to manage asbestos.

The inspector conducted a three-year reinspection of this facility under Illinois Department of Public Health (IDPH) school reinspection requirements and AHERA, sections 763.85 and 763.88. The main building and each addition to the main building, if constructed at different dates, were inspected separately. Laboratory accreditations are included in Appendix C, laboratory results are included in Appendix D, and chain of custody forms are included in Appendix E.

Note: During previous inspections, some of the HA(s) were identified together as 9" x 9" floor tile (FT), mastics assoc. with 9" x 9" FT, 12" x 12" FT, mastics assoc. with 12" x 12" FT, pipe insulation, etc. Some of these HA(s) have been re-identified by areas that are uniform in color, texture, construction date, application date, and general appearance.

The inspector has determined the following:

A. The following HAs have changed assessment categories for Building 2440:

B. The following new homogenous areas have been identified for Building 2440:

49	Tank Insulation
50	2x4 White Smooth Ceiling Tile
51	Textured Paint on Drywall ceiling
52	Carpet Mastic
53	Drywall System



C. This reinspection covered only physically accessible and visible areas and materials that were identified in the LEA's management plan. The following materials were concealed and/or contained in areas that were inaccessible for sampling and have been classified as Assumed:

04	12"x12" Blue with Speckles VFT
06	12"x12" Blue with Speckles VFT Mastic
11	12"x12' Light Blue VFT
11A	12"x12" Light Blue VFT Mastic
12	12"x12" Off White w/ Tan Streaks VFT
12A	12"x12" Off White w/ Tan Streaks VFT Mastic
13	12"x12" Off White w/ Gray Streaks VFT
13A	12"x12" Off White w/ Gray Streaks VFT Mastic
15	12"x12" Light Brown w/ wht/brwn specks VFT
15A	12"x12" Light Brown w/ wht/brwn specks VFT Mastic
16	12"x12" Cream VFT
16A	12"x12" Cream VFT Mastic
17	12"x12" White VFT - Not observed
17A	12"x12" White VFT Mastic - Not observed
22	12"x12" Beige w/ White Speckles VFT
22A	12"x12" Beige w/ White Speckles VFT Mastic
25	12"x12" Grey VFT
25A	12"x12" Grey VFT Mastic
33	12"x12" coffee w/ cream streaks VFT
33A	12"x12" coffee w/ cream streaks VFT Mastic
34	12"X 12" White w/Black Specks Floor Tile
35	12"X 12' White w/Black Specks Floor Tile MASTIC
36	Terrazzo -NOT OBSERVED
37	Mastic Under Rubber Stair Tread
38	Carpet Mastic
39	12"X12" White w/ Gray Specks VFT
39A	12"X12" White w/ Gray Specks VFT Mastic
40	2' x 4' Ceiling Tile
41	12" x 12" White with Brown Streaks VFT
41A	12" x 12" White with Brown Streaks VFT Mastic
42	12" x 12" Blue VFT -- NOT OBSERVED
42A	12" x 12" Blue VFT Mastic-- NOT OBSERVED
43	12" x 12" Red VFT-- NOT OBSERVED
43A	12" X 12" Red VFT Mastic-- NOT OBSERVED
44	1' x 1' White Groove Ceiling Tile
45	12" x 12" Aqua Green VFT
45A	12" x 12" Aqua Green VFT Mastic
46	12" x 12" Beige VFT
46A	12" x 12" Beige VFT Mastic
47	12" x 12" Blue VFT

47A	12" x 12" Blue VFT Mastic
48	12" x 12" Off White VFT
48A	12" x 12" Off White VFT Mastic
49	Tank Insulation
50	2x4 White Smooth Ceiling Tile
51	Textured Paint on Drywall ceiling
52	Carpet Mastic
53	Drywall System
K	White Spray Applied Fireproofing

The following areas were deemed to be inaccessible:

K	White Spray Applied Fireproofing
---	----------------------------------

Materials were also listed as "assumed" if they were in good condition and sampling was not conducted to avoid damage.

This reinspection was conducted by Michael Holvay, IDPH License # 100-07210. The Management Plan was updated by Arturo Saenz, IDPH License # 100-04019. Inspector and Management Planner Licenses are included in Appendix B.

### **III. METHODOLOGY**

Tasks performed on-site included the following:

1. Review current management plan, identify HA(s) and extract appropriate information.
2. Examine and verify abatement records.
3. Touch and visually and physically reinspect and reassess the condition of all friable known or assumed ACBM.
4. Touch and visually and physically reinspect all non-friable known or assumed ACBM to determine whether these materials have become friable since the last inspection or periodic surveillance.
5. Identify any condition changes that may affect Hazard Ranking of known ACBM or Assumed ACBM, as well as any HA(s) that have become friable since the last reinspection.
6. Collect bulk samples from each newly discovered friable HA or previously assumed and submit for laboratory analysis.
7. Tabulate reinspection findings and submit for management planner review and recommendations with appropriate response actions based on the AHERA Damage Category of the ACBM.
8. Submit reinspection findings and management planner recommendations to the LEA within thirty (30) days for inclusion into the management plan.

### **IV. ABATEMENT HISTORY**

The information collected from the existing management plan and inspection report(s) and from interviews with the school official revealed that the following asbestos abatement was conducted at the school since the previous Three year Reinspection.

Abatement Dates:

### **V. REASSESSMENTS AND RECOMMENDATIONS**

The reassessments and recommendations are summarized in Tables I and II on the following pages. Detailed Hazard Assessment Sheets and Drawings and Photos (if applicable) are included in Appendix A.

### **VI. CONCLUSIONS**

The Budlong School Building 2440 Three-Year reinspection has been completed and response actions have been recommended for both friable and non-friable materials. A timely execution of the response actions recommended will enable the LEA and the Designated Person(s) to effectively manage the existing ACBM.

This three-year reinspection report should be inspected in the current Management plan at the CPS Central Office, and one (1) copy should be kept at the school for use when planning any renovation and/or demolition activities in areas where ACBM has been identified. Also, periodic surveillance documentation and any summary reports from any response actions that are executed at the school should be used to update the Management Plan.

**Table I**  
**Inspector's Reinspection Findings**

---

# Chicago Public Schools

School Budlong School Unit 22391 Building ID 2440

Address 2701 W Foster Avenue Region 01

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262 Fax: (312) 733-5612

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
04	12"x12" Blue with Speckles VFT	1,100	SF	Room 101, closet & toilet and Room 103 - 1907	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
05	9"x9" Red w/ yellow streaks VFT	410	SF	Main Office & Storage (Under the Carpet) - 1907	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
06	12"x12" Blue with Speckles VFT Mastic	1,100	SF	Room 101, closet & toilet and Room 103 - 1907	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
07	9"x9" Red w/Yellow Streaks VFT Mastic	410	SF	Main Office & Storage (Under carpet)- 1907	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
08	12"x12" Tan w/ Brown Speckles VFT	2,330	SF	Basement E-W & Adjac., N-S Corridors & Room 109 (under existing VFT) - 1955	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
09	12"x12" Tan w/ Brown Speckles VFT Mastic	2,330	SF	Basement E-W & Adjac., N-S Corridors & Room 109 (under existing VFT) - 1955	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
10	9"x9" Brown VFT (ABATED)			Toilet in 1st Floor Main Office - 1907	ABATED	MISC								
10A	9"x9" Brown VFT Mastic (ABATED)			Toilet in 1st Floor Main Office - 1907	ABATED	MISC								
11	12"x12" Light Blue VFT	600	SF	Room 102 - 1907	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
11A	12"x12" Light Blue VFT Mastic	600	SF	Room 102 - 1907	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
12	12"x12" Off White w/ Tan Streaks VFT	2,600	SF	1st Floor Corridor and Room 101 and Toilet - 1907	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
12A	12"x12" Off White w/ Tan Streaks VFT Mastic	2,600	SF	1st Floor Corridor and Room 101 and Toilet- 1907	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
13	12"x12" Off White w/ Gray Streaks VFT	1,100	SF	Rooms 105, 118 and Hallway by 118 - 1907	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
13A	12"x12" Off White w/ Gray Streaks VFT Mastic	1,100	SF	Rooms 105, 118 and Hallway by 118 - 1907	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
14	9"x9" Brown w/ White Streaks VFT	760	SF	Room 118b (under carpet) & 118C	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE

# Chicago Public Schools

School Budlong School Unit 22391 Building ID 2440

Address 2701 W Foster Avenue Region 01

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262 Fax: (312) 733-5612

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				(under HA #13) - 1907										
14A	9"x9" Brown w/ White Streaks VFT Mastic - NOT OBSERVED	760	SF	Room 118b (under carpet) & 118C (under HA #13) - 1907	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
15	12"x12" Light Brown w/ wht/brwn specks VFT	200	SF	Engineer's old office - 1907	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
15A	12"x12" Light Brown w/ wht/brwn specks VFT Mastic	200	SF	Engineer's old office - 1907	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
16	12"x12" Cream VFT	20	SF	Janitor's closet by Principal's office - 1907	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
16A	12"x12" Cream VFT Mastic	20	SF	Janitor's closet by Principal's office - 1907	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
17	12"x12" White VFT - Not observed			Room 111 - 1955 - Not observed	ASSUMED	MISC	N							
17A	12"x12" White VFT Mastic - Not observed			Room 111 - 1955 - Not observed	ASSUMED	MISC	N							
18	9"x9" Peach VFT (ABATED)			1st Floor Middle Hallway - 1955 (ABATED)	ABATED	MISC								
18A	9"x9" Peach VFT Mastic - (ABATED)			1st Floor Middle Hallway - 1955 (ABATED)	ABATED	MISC								
19	9"x9" Tan VFT (ABATED)			1st Floor NW Corridor Hallway - 1955	ABATED	MISC								
19A	9"x9" Tan VFT Mastic (ABATED)			1st Floor NW Corridor Hallway - 1955	ABATED	MISC								
20	9"x9" Tan Spotted VFT (ABATED)			1st Floor NW Corridor Hallway - 1955	ABATED	MISC								
20A	9"x9" Tan Spotted VFT Mastic (ABATED)			1st Floor NW Corridor Hallway - 1955	ABATED	MISC								
21	12"x12" Gray w/ Pink & White Streaks VFT	850	SF	Room 112 - 1955	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
21A	12"x12" Gray w/ Pink & White Streaks VFT Mastic	850	SF	Room 112 - 1955	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
22	12"x12" Beige w/ White Speckles VFT	1,500	SF	Exit Door, Rooms 113, 114 (under	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE



# Chicago Public Schools

School Budlong School Unit 22391 Building ID 2440

Address 2701 W Foster Avenue Region 01

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262 Fax: (312) 733-5612

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				from school property										
32	Vinyl Baseboard Mastic			Throughout 2000 Mobile - Removed from school property	ABATED									
33	12"x12" cofee w/ cream streaks VFT	300	SF	Room 117	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
33A	12"x12" coffee w/ cream streaks VFT Mastic	300	SF	Room 117	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
34	12"X 12" White w/Black Specks Floor Tile	3,200	SF	Lunchroom, Kitchen Office and Corridor - 1955 Bldg	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
35	12"X 12" White w/Black Specks Floor Tile MASTIC	3,200	SF	Lunchroom, Kitchen Office and Corridor - 1955 Bldg	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
36	Terrazzo -NOT OBSERVED	1,200	SF	3rd Floor Boys and Mens Toilet and 2nd Floor Girls and Women'sToilet (1907 Bldg)	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
37	Mastic Under Rubber Stair Tread	800	SF	Stairwell (1907 Bldg)	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
38	Carpet Mastic	3,000	SF	Assembly Hall Balcony, Assistant Principal's Office, Room 101, 104, 106, 204, 102 ward, Main office, Principal's Office Basement Rm 116 (Old Library) - Bldg 1907	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
39	12"X12" White w/ Gray Specks VFT	800	SF	Basement Rm 115 - 1907	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
39A	12"X12" White w/ Gray Specks VFT Mastic	800	SF	Basement Rm 115 - 1907	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
40	2' x 4' Ceiling Tile	9,500	SF	3rd, 2nd and 1st Floor Corridors, Room 204, Main Office, Room 107, Basement Room 116, 117, 115, Basement Engineer Office, Room 119, 118B, 118C, Corridor by 118C & 118B - 1907	ASSUMED	MISC	Y	NONE	0		No	ACBM with the potential for damage		LOW



# Chicago Public Schools

School Budlong School Unit 22391 Building ID 2440

Address 2701 W Foster Avenue Region 01

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262 Fax: (312) 733-5612

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				Building										
41	12" x 12" White with Brown Streaks VFT	300	SF	Basement Room 117 - Building 1907	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
41A	12" x 12" White with Brown Streaks VFT Mastic	300	SF	Basement Room 117 - Building 1907	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
42	12" x 12" Blue VFT -- NOT OBSERVED	41	SF	Lunch Room - 1955 Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
42A	12" x 12" Blue VFT Mastic-- NOT OBSERVED	41	SF	Lunch Room - 1955 Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
43	12" x 12" Red VFT-- NOT OBSERVED	41	SF	Lunch Room - 1955 Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
43A	12" X 12" Red VFT Mastic-- NOT OBSERVED	41	SF	Lunch Room - 1955 Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
44	1' x 1' White Groove Ceiling Tile	5,000	SF	Throughout 1955 Building	ASSUMED	MISC	Y	NONE	0		No	ACBM with the potential for damage		LOW
45	12" x 12" Aqua Green VFT	160	SF	Classrooms and Corridor - 1997 Annex	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
45A	12" x 12" Aqua Green VFT Mastic	160	SF	Classrooms and Corridor - 1997 Annex	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
46	12" x 12" Beige VFT	160	SF	Classrooms and Corridor - 1997 Annex	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
46A	12" x 12" Beige VFT Mastic	160	SF	Classrooms and Corridor - 1997 Annex	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
47	12" x 12" Blue VFT	160	SF	Classroom and Corridor - 1997 Annex	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
47A	12" x 12" Blue VFT Mastic	160	SF	Classroom and Corridor - 1997 Annex	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
48	12" x 12" Off White VFT	160	SF	Classrooms and Corridor - 1997 Annex	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
48A	12" x 12" Off White VFT Mastic	160	SF	Classrooms and Corridor - 1997 Annex	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
49	Tank Insulation	20	SF	Tank Room (1907 Bldg)	ASSUMED	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW
50	2x4 White Smooth Ceiling Tile	800	SF	Old Girls Playroom (1907 Bldg)	ASSUMED	MISC	Y	NONE	0		No	ACBM with the potential for damage		MODERATE
51	Textured Paint on Drywall ceiling	700	SF	Basement- Girls and	ASSUMED	MISC	N	NONE	0		No	ACBM with the		LOW

# Chicago Public Schools

School Budlong School Unit 22391 Building ID 2440

Address 2701 W Foster Avenue Region 01

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262 Fax: (312) 733-5612

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				boys Toilet (1907) Bldg								potential for damage		
52	Carpet Mastic	1,200	SF	Room 114 (1955 Bldg)	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
53	Drywall System	4,000	SF	All Restrooms (1907) Bldg	ASSUMED	MISC	Y	NONE	0		No	ACBM with the potential for damage		MODERATE
A	MJP E/F/V on Fiberglass Pipe Insulation	430	LF	Boiler, Tank & Fan Rooms, Room Facing 119, Basement Boys & Girls Toilets - 1907	CHR	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW
B	Cardboard Pipe Insulation	1,148	LF	Throughout - 1907 (See Hatching Maps)	CHR	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW
C	MJP E/F/V on Cardboard Pipe Insulation	91	LF	Throughout - 1907 (See Hatching Maps)	CHR	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW
D	Aircell Pipe Insulation	492	LF	Tank Room, Rm 115B, 117, Hall to 115, Teachers Lounge Rm, 118C, Bsmt Boys & Girls Toilet - 1907	CHR	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW
E	MJP E/F/V on Aircell Pipe Insulation	45	LF	Tank Room, Rm 115B, 117, Hall to 115, Teachers Lounge Rm, 118C, Bsmt Boys & Girls Toilet - 1907	CHR	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW
G	Cardboard Pipe Insulation	80	LF	Chase Behind Teachers Toilet, Behind Walls & Above Drop Ceilings - 1955	CHR	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW
H	MJP E/F/V on Cardboard Pipe Insulation	70	LF	Chase Behind Teachers Toilet, Behind Walls & Above Drop Ceilings - 1955	CHR	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW
I	Aircell Pipe Insulation	30	LF	Chase Behind Teachers Toilet, Behind Walls & Above Drop Ceilings - 1955	CHR	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW
J	MJP E/F/V on Aircell Pipe Insulation	80	LF	Chase Behind	CHR	TSI	Y	NONE	0		No	ACBM with the		LOW



# Chicago Public Schools

School Budlong School Unit 22391 Building ID 2440

Address 2701 W Foster Avenue Region 01

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262 Fax: (312) 733-5612

*Inspector's Comments are Summarized at the End of the Report*

Reinspection Date <b>3/8/2016</b>
Inspector Name <b><u>Michael Holvay</u></b>
<b>100-07210</b> <b>1/18/2017</b>
Inspector's IDPH License Number / Expiration Date

### Inspector's Comments

HA Number:	Inspector Comments:
04	
05	
06	
07	
08	
09	
10	
10A	
11	
11A	
12	
12A	
13	
13A	
14	NOT OBSERVED
14A	- NOT OBSERVED
15	
15A	
16	
16A	
17	
17A	
18	
18A	

# Chicago Public Schools

School Budlong School Unit 22391 Building ID 2440

Address 2701 W Foster Avenue Region 01

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262 Fax: (312) 733-5612

*Inspector's Comments are Summarized at the End of the Report*

---

HA Number:	Inspector Comments:
19	
19A	
20	
20A	
21	
21A	
22	
22A	
23	Now HA#34+35
23A	Now HA#34+35
24	Now HA#34+35
24A	Now HA#34+35
25	
25A	
26	
26A	
27	
28	
29	
30	
31	2000 Mobile Unit Not on Site
32	2000 Mobile Unit not on site
33	
33A	
34	
35	
36	-NOT OBSERVED
37	
38	

# Chicago Public Schools

School Budlong School Unit 22391 Building ID 2440

Address 2701 W Foster Avenue Region 01

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262 Fax: (312) 733-5612

*Inspector's Comments are Summarized at the End of the Report*

---

HA Number:	Inspector Comments:
39	
39A	
40	
41	
41A	
42	-- NOT OBSERVED
42A	-- NOT OBSERVED
43	-- NOT OBSERVED
43A	-- NOT OBSERVED
44	
45	
45A	
46	
46A	
47	
47A	
48	
48A	
49	
50	
51	
52	
53	
A	
B	
C	
D	
E	
G	

# Chicago Public Schools

School Budlong School Unit 22391 Building ID 2440

Address 2701 W Foster Avenue Region 01

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262 Fax: (312) 733-5612

*Inspector's Comments are Summarized at the End of the Report*

---

HA Number:	Inspector Comments:
H	
I	
J	
K	
L	
M	
N	
O	
P	
Q	
R	

**Table II**

**Management Planner's Review**

---



# Chicago Public Schools

**School** Budlong School  
**Address** 2701 W Foster Avenue

**Unit** 22391  
Chicago, IL, 60625

**Building ID** 2440  
**Region** 01

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262

Fax: (312) 733-5612

### Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
04	12"x12" Blue with Speckles VFT	1,100	SF	Room 101, closet & toilet and Room 103 - 1907	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
05	9"x9" Red w/ yellow streaks VFT	410	SF	Main Office & Storage (Under the Carpet) - 1907	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
06	12"x12" Blue with Speckles VFT Mastic	1,100	SF	Room 101, closet & toilet and Room 103 - 1907	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
07	9"x9" Red w/Yellow Streaks VFT Mastic	410	SF	Main Office & Storage (Under carpet)- 1907	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
08	12"x12" Tan w/ Brown Speckles VFT	2,330	SF	Basement E-W & Adjac., N-S Corridors & Room 109 (under existing VFT) - 1955	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
09	12"x12" Tan w/ Brown Speckles VFT Mastic	2,330	SF	Basement E-W & Adjac., N-S Corridors & Room 109 (under existing VFT) - 1955	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
10	9"x9" Brown VFT (ABATED)			Toilet in 1st Floor Main Office - 1907	Abated	MISC					
10A	9"x9" Brown VFT Mastic (ABATED)			Toilet in 1st Floor Main Office - 1907	Abated	MISC					
11	12"x12' Light Blue VFT	600	SF	Room 102 - 1907	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
11A	12"x12" Light Blue VFT Mastic	600	SF	Room 102 - 1907	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
12	12"x12" Off White w/ Tan Streaks VFT	2,600	SF	1st Floor Corridor and Room 101 and Toilet - 1907	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
12A	12"x12" Off White w/ Tan Streaks VFT Mastic	2,600	SF	1st Floor Corridor and Room 101 and Toilet- 1907	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
13	12"x12" Off White w/ Gray Streaks VFT	1,100	SF	Rooms 105, 118 and Hallway by 118 - 1907	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
13A	12"x12" Off White w/ Gray Streaks VFT Mastic	1,100	SF	Rooms 105, 118 and Hallway by 118 - 1907	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
14	9"x9" Brown w/ White Streaks VFT	760	SF	Room 118b (under carpet) & 118C (under HA #13) - 1907	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
14A	9"x9" Brown w/ White Streaks VFT Mastic - NOT OBSERVED	760	SF	Room 118b (under carpet) & 118C (under HA #13) - 1907	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
15	12"x12" Light Brown w/ wht/brwn specks VFT	200	SF	Engineer's old office - 1907	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
15A	12"x12" Light Brown w/ wht/brwn specks VFT Mastic	200	SF	Engineer's old office - 1907	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
16	12"x12" Cream VFT	20	SF	Janitor's closet by Principal's office - 1907	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
16A	12"x12" Cream VFT Mastic	20	SF	Janitor's closet by Principal's office -	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

# Chicago Public Schools

**School** Budlong School  
**Address** 2701 W Foster Avenue

**Unit** 22391  
Chicago, IL, 60625

**Building ID** 2440  
**Region** 01

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262

Fax: (312) 733-5612

### *Management Planner's Comments Summarized at the End of the Report*

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
				1907							
17	12"x12" White VFT - Not observed			Room 111 - 1955 - Not observed	Assumed	MISC	No				Follow O&M Plan
17A	12"x12" White VFT Mastic - Not observed			Room 111 - 1955 - Not observed	Assumed	MISC	No				Follow O&M Plan
18	9"x9" Peach VFT (ABATED)			1st Floor Middle Hallway - 1955 (ABATED)	Abated	MISC					
18A	9"x9" Peach VFT Mastic - (ABATED)			1st Floor Middle Hallway - 1955 (ABATED)	Abated	MISC					
19	9"x9" Tan VFT (ABATED)			1st Floor NW Corridor Hallway - 1955	Abated	MISC					
19A	9"x9" Tan VFT Mastic (ABATED)			1st Floor NW Corridor Hallway - 1955	Abated	MISC					
20	9"x9" Tan Spotted VFT (ABATED)			1st Floor NW Corridor Hallway - 1955	Abated	MISC					
20A	9"x9" Tan Spotted VFT Mastic (ABATED)			1st Floor NW Corridor Hallway - 1955	Abated	MISC					
21	12"x12" Gray w/ Pink & White Streaks VFT	850	SF	Room 112 - 1955	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
21A	12"x12" Gray w/ Pink & White Streaks VFT Mastic	850	SF	Room 112 - 1955	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
22	12"x12" Beige w/ White Speckles VFT	1,500	SF	Exit Door, Rooms 113, 114 (under carpet) - 1955	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
22A	12"x12" Beige w/ White Speckles VFT Mastic	1,500	SF	Exit Door, Rooms 113, 114 (under carpet) - 1955	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
23	12"x12" Green w/ Black & White VFT (ABATED)			Room 111 - 1955 (now HA34+35)	Abated	MISC					
23A	12"x12" Green w/ White & Black VFT Mastic - (ABATED)			Room 111 - 1955	Abated	MISC					
24	12"x12" Rust Brown w/ White & Brown Streaks VFT - (ABATED)			Room 110 - 1955	Abated	MISC					
24A	12"x12" Rust Brn w/ White & Brn Streaks VFT Mastic - (ABATED)			Room 110 - 1955	Abated	MISC					
25	12"x12" Grey VFT	8,800	SF	All Rooms Except Boiler Rm, Electrical Rms, Gym and toilets - 1997 Annex	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
25A	12"x12" Grey VFT Mastic	8,800	SF	All Rooms Except Boiler Rm, Electrical Rms, Gym and Toilets - 1997 Annex	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
26	Vinyl Baseboard			All Rooms Except Boiler Rm, Electrical Rms & Gym - 1997 Annex	No ACBM						
26A	Vinyl Baseboard Mastic			All Rooms Except Boiler Rm, Electrical Rms & Gym - 1997 Annex	No ACBM						
27	2'x4' Ceiling Tile			All Rooms Except Boiler Rm, Electrical Rms & Gym - 1997 Annex	No ACBM						
28	2'x4' Ceiling Tile			All Rooms Except Bathrooms & Mechanical Rooms - 1998 Fieldhouse	No ACBM						

# Chicago Public Schools

**School** Budlong School  
**Address** 2701 W Foster Avenue

**Unit** 22391  
Chicago, IL, 60625

**Building ID** 2440  
**Region** 01

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262

Fax: (312) 733-5612

### Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
29	Vinyl Baseboard			Throughout 1998 Fieldhouse	No ACBM						
30	Vinyl Baseboard Mastic			Throughout 1998 Fieldhouse	No ACBM						
31	Vinyl Baseboard			Throughout 2000 Mobile - Removed from school property	Abated						
32	Vinyl Baseboard Mastic			Throughout 2000 Mobile - Removed from school property	Abated						
33	12"x12" coffee w/ cream streaks VFT	300	SF	Room 117	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
33A	12"x12" coffee w/ cream streaks VFT Mastic	300	SF	Room 117	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
34	12"X 12" White w/Black Specks Floor Tile	3,200	SF	Lunchroom, Kitchen Office and Corridor - 1955 Bldg	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
35	12"X 12" White w/Black Specks Floor Tile MASTIC	3,200	SF	Lunchroom, Kitchen Office and Corridor - 1955 Bldg	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
36	Terrazzo -NOT OBSERVED	1,200	SF	3rd Floor Boys and Mens Toilet and 2nd Floor Girls and Women'sToilet (1907 Bldg)	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
37	Mastic Under Rubber Stair Tread	800	SF	Stairwell (1907 Bldg)	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
38	Carpet Mastic	3,000	SF	Assembly Hall Balcony, Assistant Principal's Office, Room 101, 104, 106, 204, 102 ward, Main office, Principal's Office Basement Rm 116 (Old Library) - Bldg 1907	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
39	12"X12" White w/ Gray Specks VFT	800	SF	Basement Rm 115 - 1907	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
39A	12"X12" White w/ Gray Specks VFT Mastic	800	SF	Basement Rm 115 - 1907	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
40	2' x 4' Ceiling Tile	9,500	SF	3rd, 2nd and 1st Floor Corridors, Room 204, Main Office, Room 107, Basement Room 116, 117, 115, Basement Engineer Office, Room 119, 118B, 118C, Corridor by 118C & 118B - 1907 Building	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
41	12" x 12" White with Brown Streaks VFT	300	SF	Basement Room 117 - Building 1907	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
41A	12" x 12" White with Brown Streaks VFT Mastic	300	SF	Basement Room 117 - Building 1907	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
42	12" x 12" Blue VFT -- NOT OBSERVED	41	SF	Lunch Room - 1955 Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
42A	12" x 12" Blue VFT Mastic-- NOT OBSERVED	41	SF	Lunch Room - 1955 Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
43	12" x 12" Red VFT-- NOT OBSERVED	41	SF	Lunch Room - 1955 Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
43A	12" X 12" Red VFT Mastic-- NOT OBSERVED	41	SF	Lunch Room - 1955 Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
44	1' x 1' White Groove Ceiling Tile	5,000	SF	Throughout 1955 Building	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

# Chicago Public Schools

**School** Budlong School  
**Address** 2701 W Foster Avenue

**Unit** 22391  
Chicago, IL, 60625

**Building ID** 2440  
**Region** 01

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262

Fax: (312) 733-5612

### Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
45	12" x 12" Aqua Green VFT	160	SF	Classrooms and Corridor - 1997 Annex	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
45A	12" x 12" Aqua Green VFT Mastic	160	SF	Classrooms and Corridor - 1997 Annex	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
46	12" x 12" Beige VFT	160	SF	Classrooms and Corridor - 1997 Annex	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
46A	12" x 12" Beige VFT Mastic	160	SF	Classrooms and Corridor - 1997 Annex	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
47	12" x 12" Blue VFT	160	SF	Classroom and Corridor - 1997 Annex	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
47A	12" x 12" Blue VFT Mastic	160	SF	Classroom and Corridor - 1997 Annex	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
48	12" x 12" Off White VFT	160	SF	Classrooms and Corridor - 1997 Annex	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
48A	12" x 12" Off White VFT Mastic	160	SF	Classrooms and Corridor - 1997 Annex	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
49	Tank Insulation	20	SF	Tank Room (1907 Bldg)	Assumed	TSI	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
50	2x4 White Smooth Ceiling Tile	800	SF	Old Girls Playroom (1907 Bldg)	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
51	Textured Paint on Drywall ceiling	700	SF	Basement- Girls and boys Toilet (1907) Bldg	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
52	Carpet Mastic	1,200	SF	Room 114 (1955 Bldg)	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
53	Drywall System	4,000	SF	All Restrooms (1907) Bldg	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
A	MJP E/F/V on Fiberglass Pipe Insulation	430	LF	Boiler, Tank & Fan Rooms, Room Facing 119, Basement Boys & Girls Toilets - 1907	Chrysotile	TSI	Yes	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
B	Cardboard Pipe Insulation	1,148	LF	Throughout - 1907 (See Hatching Maps)	Chrysotile	TSI	Yes	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
C	MJP E/F/V on Cardboard Pipe Insulation	91	LF	Throughout - 1907 (See Hatching Maps)	Chrysotile	TSI	Yes	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
D	Aircell Pipe Insulation	492	LF	Tank Room, Rm 115B, 117, Hall to 115, Teachers Lounge Rm, 118C, Bsmt Boys & Girls Toilet - 1907	Chrysotile	TSI	Yes	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
E	MJP E/F/V on Aircell Pipe Insulation	45	LF	Tank Room, Rm 115B, 117, Hall to 115, Teachers Lounge Rm, 118C, Bsmt Boys & Girls Toilet - 1907	Chrysotile	TSI	Yes	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
G	Cardboard Pipe Insulation	80	LF	Chase Behind Teachers Toilet, Behind Walls & Above Drop Ceilings - 1955	Chrysotile	TSI	Yes	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
H	MJP E/F/V on Cardboard Pipe Insulation	70	LF	Chase Behind Teachers Toilet, Behind Walls & Above Drop Ceilings - 1955	Chrysotile	TSI	Yes	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
I	Aircell Pipe Insulation	30	LF	Chase Behind Teachers Toilet, Behind Walls & Above Drop Ceilings - 1955	Chrysotile	TSI	Yes	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
J	MJP E/F/V on Aircell Pipe Insulation	80	LF	Chase Behind Teachers Toilet, Behind Walls & Above Drop Ceilings - 1955	Chrysotile	TSI	Yes	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
K	White Spray Applied Fireproofing	5,000	SF	Gym - 1997 Annex	Assumed	SURFACE	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

# Chicago Public Schools

**School** Budlong School  
**Address** 2701 W Foster Avenue

**Unit** 22391  
 Chicago, IL, 60625

**Building ID** 2440  
**Region** 01

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262

Fax: (312) 733-5612

### *Management Planner's Comments Summarized at the End of the Report*

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
L	Drywall	0		Corridors Above CT, Bathroom Ceilings, Boiler & Electrical Room Ceilings - 1997 Annex	No ACBM						
M	Drywall Tape	0		Corridors Above CT, Bathroom Ceilings, Boiler & Electrical Room Ceilings - 1997 Annex	No ACBM						
N	Drywall Joint Compound	0		Corridors Above CT, Bathroom Ceilings, Boiler & Electrical Room Ceilings - 1997 Annex	No ACBM						
O	Drywall	0		Men & Womens Bathrooms, Mechanical Room - 1998 Fieldhouse	No ACBM						
P	Drywall Joint Compound	0		Mens & Womens Bathrooms, Mechanical Room - 1998 Fieldhouse	No ACBM						
Q	Vinyl Covered Drywall			Throughout 2000 Mobile - Removed from school property	Abated						
R	Textured Covered Drywall			Throughout 2000 Mobile - Removed from school property	Abated						

# Chicago Public Schools

**School** Budlong School  
**Address** 2701 W Foster Avenue

**Unit** 22391  
 Chicago, IL, 60625

**Building ID** 2440  
**Region** 01

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262

Fax: (312) 733-5612

### *Management Planner's Comments Summarized at the End of the Report*

Review Date	3/28/2016
Manager Planner Name	Arturo Saenz
100-04019	1/19/2017
Manager IDPH License No/Expiration	

HA Number	Management Comments
04	
05	
06	
07	
08	
09	
10	
10A	
11	
11A	
12	
12A	
13	
13A	
14	
14A	
15	
15A	
16	
16A	

# Chicago Public Schools

**School** Budlong School  
**Address** 2701 W Foster Avenue

**Unit** 22391  
 Chicago, IL, 60625

**Building ID** 2440  
**Region** 01

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262 Fax: (312) 733-5612

***Management Planner's Comments Summarized at the End of the Report***

HA Number	Management Comments
17	
17A	
18	
18A	
19	
19A	
20	
20A	
21	
21A	
22	
22A	
23	
23A	
24	
24A	
25	
25A	
26	
26A	
27	
28	
29	
30	
31	
32	
33	

# Chicago Public Schools

**School** Budlong School  
**Address** 2701 W Foster Avenue

**Unit** 22391  
Chicago, IL, 60625

**Building ID** 2440  
**Region** 01

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262

Fax: (312) 733-5612

### *Management Planner's Comments Summarized at the End of the Report*

HA Number	Management Comments
33A	
34	
35	
36	
37	
38	
39	
39A	
40	
41	
41A	
42	
42A	
43	
43A	
44	
45	
45A	
46	
46A	
47	
47A	
48	
48A	
49	
50	
51	



# Chicago Public Schools

**School** Budlong School  
**Address** 2701 W Foster Avenue

**Unit** 22391  
 Chicago, IL, 60625

**Building ID** 2440  
**Region** 01

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262 Fax: (312) 733-5612

***Management Planner's Comments Summarized at the End of the Report***

HA Number	Management Comments
52	
53	
A	
B	
C	
D	
E	
G	
H	
I	
J	
K	
L	
M	
N	
O	
P	
Q	
R	

# Chicago Public Schools

GSG Consultants, Inc.

## 2016 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22391** BUIDLING ID: **2440**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Holvay**  
SCHOOL NAME: **Budlong School** INSPECTION DATE: **3/8/2016**  
ADDRESS: **2701 W Foster Avenue** IDPH LICENSE NO: **100-07210**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **04**  
MATERIAL DESCRIPTION: **12"x12" Blue with Speckles VFT**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **Room 101, closet & toilet and Room 103 - 1907**  
MATERIAL QUANTITY: **1100** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature:

  
Michael Holvay  
Project Manager

Date: **03/08/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22391** BUILDING ID: **2440**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Budlong School** REVIEW DATE: **3/28/2016**  
ADDRESS: **2701 W Foster Avenue** IDPH LICENSE NO: **100-07210**

---

HOMOGENEOUS AREA: **04**  
MATERIAL DESCRIPTION: **12"x12" Blue with Speckles VFT**  
MATERIAL LOCATION: **Room 101, closet & toilet and Room 103 - 1907**  
MATERIAL QUANTITY: **1100** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **03/28/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22391** BUIDLING ID: **2440**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Holvay**  
SCHOOL NAME: **Budlong School** INSPECTION DATE: **3/8/2016**  
ADDRESS: **2701 W Foster Avenue** IDPH LICENSE NO: **100-07210**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **05**  
MATERIAL DESCRIPTION: **9"x9" Red w/ yellow streaks VFT**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **Main Office & Storage (Under the Carpet) - 1907**  
MATERIAL QUANTITY: **410** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature:

  
Michael Holvay  
Project Manager

Date: **03/08/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22391** BUIDLING ID: **2440**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Budlong School** REVIEW DATE: **3/28/2016**  
ADDRESS: **2701 W Foster Avenue** IDPH LICENSE NO: **100-07210**

---

HOMOGENEOUS AREA: **05**  
MATERIAL DESCRIPTION: **9"x9" Red w/ yellow streaks VFT**  
MATERIAL LOCATION: **Main Office & Storage (Under the Carpet) - 1907**  
MATERIAL QUANTITY: **410** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **03/28/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22391** BUIDLING ID: **2440**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Holvay**  
SCHOOL NAME: **Budlong School** INSPECTION DATE: **3/8/2016**  
ADDRESS: **2701 W Foster Avenue** IDPH LICENSE NO: **100-07210**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **06**  
MATERIAL DESCRIPTION: **12"x12" Blue with Speckles VFT Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **Room 101, closet & toilet and Room 103 - 1907**  
MATERIAL QUANTITY: **1100** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:

  
Michael Holvay  
Project Manager

Date: **03/08/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22391** BUIDLING ID: **2440**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Budlong School** REVIEW DATE: **3/28/2016**  
ADDRESS: **2701 W Foster Avenue** IDPH LICENSE NO: **100-07210**

---

HOMOGENEOUS AREA: **06**  
MATERIAL DESCRIPTION: **12"x12" Blue with Speckles VFT Mastic**  
MATERIAL LOCATION: **Room 101, closet & toilet and Room 103 - 1907**  
MATERIAL QUANTITY: **1100** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **03/28/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22391** BUIDLING ID: **2440**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Holvay**  
SCHOOL NAME: **Budlong School** INSPECTION DATE: **3/8/2016**  
ADDRESS: **2701 W Foster Avenue** IDPH LICENSE NO: **100-07210**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **07**  
MATERIAL DESCRIPTION: **9"x9" Red w/Yellow Streaks VFT Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Main Office & Storage (Under carpet)- 1907**  
MATERIAL QUANTITY: **410** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature:

  
Michael Holvay  
Project Manager

Date: **03/08/2016**



# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22391** BUIDLING ID: **2440**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Budlong School** REVIEW DATE: **3/28/2016**  
ADDRESS: **2701 W Foster Avenue** IDPH LICENSE NO: **100-07210**

---

HOMOGENEOUS AREA: **07**  
MATERIAL DESCRIPTION: **9"x9" Red w/Yellow Streaks VFT Mastic**  
MATERIAL LOCATION: **Main Office & Storage (Under carpet)- 1907**  
MATERIAL QUANTITY: **410** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **03/28/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22391** BUIDLING ID: **2440**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Holvay**  
SCHOOL NAME: **Budlong School** INSPECTION DATE: **3/8/2016**  
ADDRESS: **2701 W Foster Avenue** IDPH LICENSE NO: **100-07210**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **08**  
MATERIAL DESCRIPTION: **12"x12" Tan w/ Brown Speckles VFT**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **Basement E-W & Adjac., N-S Corridors & Room 109 (under existing VFT) - 1955**

MATERIAL QUANTITY: **2330** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:

  
Michael Holvay  
Project Manager

Date: **03/08/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22391** BUIDLING ID: **2440**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Budlong School** REVIEW DATE: **3/28/2016**  
ADDRESS: **2701 W Foster Avenue** IDPH LICENSE NO: **100-07210**

---

HOMOGENEOUS AREA: **08**  
MATERIAL DESCRIPTION: **12"x12" Tan w/ Brown Speckles VFT**  
MATERIAL LOCATION: **Basement E-W & Adjac., N-S Corridors & Room 109 (under existing VFT) - 1955**  
MATERIAL QUANTITY: **2330** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **03/28/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22391** BUIDLING ID: **2440**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Holvay**  
SCHOOL NAME: **Budlong School** INSPECTION DATE: **3/8/2016**  
ADDRESS: **2701 W Foster Avenue** IDPH LICENSE NO: **100-07210**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **09**  
MATERIAL DESCRIPTION: **12"x12" Tan w/ Brown Speckles VFT Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Basement E-W & Adjac., N-S Corridors & Room 109 (under existing VFT) - 1955**  
MATERIAL QUANTITY: **2330** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:

  
Michael Holvay  
Project Manager

Date: **03/08/2016**

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22391** BUIDLING ID: **2440**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Budlong School** REVIEW DATE: **3/28/2016**  
ADDRESS: **2701 W Foster Avenue** IDPH LICENSE NO: **100-07210**

---

HOMOGENEOUS AREA: **09**  
MATERIAL DESCRIPTION: **12"x12" Tan w/ Brown Speckles VFT Mastic**  
MATERIAL LOCATION: **Basement E-W & Adjac., N-S Corridors & Room 109 (under existing VFT) - 1955**  
MATERIAL QUANTITY: **2330** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **03/28/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22391** BUIDLING ID: **2440**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Holvay**  
SCHOOL NAME: **Budlong School** INSPECTION DATE: **3/8/2016**  
ADDRESS: **2701 W Foster Avenue** IDPH LICENSE NO: **100-07210**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **10**  
MATERIAL DESCRIPTION: **9"x9" Brown VFT (ABATED)**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Toilet in 1st Floor Main Office - 1907**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:

  
Michael Holvay  
Project Manager

Date: **03/08/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22391** BUIDLING ID: **2440**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Budlong School** REVIEW DATE: **3/28/2016**  
ADDRESS: **2701 W Foster Avenue** IDPH LICENSE NO: **100-07210**

---

HOMOGENEOUS AREA: **10**

MATERIAL DESCRIPTION: **9"x9" Brown VFT (ABATED)**

MATERIAL LOCATION: **Toilet in 1st Floor Main Office - 1907**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **03/28/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22391** BUIDLING ID: **2440**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Holvay**  
SCHOOL NAME: **Budlong School** INSPECTION DATE: **3/8/2016**  
ADDRESS: **2701 W Foster Avenue** IDPH LICENSE NO: **100-07210**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **10A**  
MATERIAL DESCRIPTION: **9"x9" Brown VFT Mastic (ABATED)**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Toilet in 1st Floor Main Office - 1907**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:

  
Michael Holvay  
Project Manager

Date: **03/08/2016**

---



# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22391** BUIDLING ID: **2440**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Budlong School** REVIEW DATE: **3/28/2016**  
ADDRESS: **2701 W Foster Avenue** IDPH LICENSE NO: **100-07210**

---

HOMOGENEOUS AREA: **10A**  
MATERIAL DESCRIPTION: **9"x9" Brown VFT Mastic (ABATED)**  
MATERIAL LOCATION: **Toilet in 1st Floor Main Office - 1907**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **03/28/2016**

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22391** BUIDLING ID: **2440**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Holvay**  
SCHOOL NAME: **Budlong School** INSPECTION DATE: **3/8/2016**  
ADDRESS: **2701 W Foster Avenue** IDPH LICENSE NO: **100-07210**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **11**  
MATERIAL DESCRIPTION: **12"x12' Light Blue VFT**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **Room 102 - 1907**  
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:

  
Michael Holvay  
Project Manager

Date: **03/08/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22391** BUILDING ID: **2440**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Budlong School** REVIEW DATE: **3/28/2016**  
ADDRESS: **2701 W Foster Avenue** IDPH LICENSE NO: **100-07210**

---

HOMOGENEOUS AREA: **11**  
MATERIAL DESCRIPTION: **12"x12' Light Blue VFT**  
MATERIAL LOCATION: **Room 102 - 1907**  
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **03/28/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22391** BUIDLING ID: **2440**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Holvay**  
SCHOOL NAME: **Budlong School** INSPECTION DATE: **3/8/2016**  
ADDRESS: **2701 W Foster Avenue** IDPH LICENSE NO: **100-07210**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **11A**  
MATERIAL DESCRIPTION: **12"x12" Light Blue VFT Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Room 102 - 1907**  
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:

  
Michael Holvay  
Project Manager

Date: **03/08/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22391** BUIDLING ID: **2440**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Budlong School** REVIEW DATE: **3/28/2016**  
ADDRESS: **2701 W Foster Avenue** IDPH LICENSE NO: **100-07210**

---

HOMOGENEOUS AREA: **11A**  
MATERIAL DESCRIPTION: **12"x12" Light Blue VFT Mastic**  
MATERIAL LOCATION: **Room 102 - 1907**  
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **03/28/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22391** BUIDLING ID: **2440**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Holvay**  
SCHOOL NAME: **Budlong School** INSPECTION DATE: **3/8/2016**  
ADDRESS: **2701 W Foster Avenue** IDPH LICENSE NO: **100-07210**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **12**  
MATERIAL DESCRIPTION: **12"x12" Off White w/ Tan Streaks VFT**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **1st Floor Corridor and Room 101 and Toilet - 1907**  
MATERIAL QUANTITY: **2600** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature:

  
Michael Holvay  
Project Manager

Date: **03/08/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22391** BUIDLING ID: **2440**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Budlong School** REVIEW DATE: **3/28/2016**  
ADDRESS: **2701 W Foster Avenue** IDPH LICENSE NO: **100-07210**

---

HOMOGENEOUS AREA: **12**  
MATERIAL DESCRIPTION: **12"x12" Off White w/ Tan Streaks VFT**  
MATERIAL LOCATION: **1st Floor Corridor and Room 101 and Toilet - 1907**  
MATERIAL QUANTITY: **2600** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **03/28/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22391** BUIDLING ID: **2440**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Holvay**  
SCHOOL NAME: **Budlong School** INSPECTION DATE: **3/8/2016**  
ADDRESS: **2701 W Foster Avenue** IDPH LICENSE NO: **100-07210**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **12A**  
MATERIAL DESCRIPTION: **12"x12" Off White w/ Tan Streaks VFT Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1st Floor Corridor and Room 101 and Toilet- 1907**  
MATERIAL QUANTITY: **2600** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:

  
Michael Holvay  
Project Manager

Date: **03/08/2016**



# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22391** BUILDING ID: **2440**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Budlong School** REVIEW DATE: **3/28/2016**  
ADDRESS: **2701 W Foster Avenue** IDPH LICENSE NO: **100-07210**

---

HOMOGENEOUS AREA: **12A**  
MATERIAL DESCRIPTION: **12"x12" Off White w/ Tan Streaks VFT Mastic**  
MATERIAL LOCATION: **1st Floor Corridor and Room 101 and Toilet- 1907**  
MATERIAL QUANTITY: **2600** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **03/28/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22391** BUIDLING ID: **2440**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Holvay**  
SCHOOL NAME: **Budlong School** INSPECTION DATE: **3/8/2016**  
ADDRESS: **2701 W Foster Avenue** IDPH LICENSE NO: **100-07210**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **13**  
MATERIAL DESCRIPTION: **12"x12" Off White w/ Gray Streaks VFT**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **Rooms 105, 118 and Hallway by 118 - 1907**  
MATERIAL QUANTITY: **1100** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_

  
Michael Holvay  
Project Manager

Date: 03/08/2016

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22391** BUIDLING ID: **2440**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Budlong School** REVIEW DATE: **3/28/2016**  
ADDRESS: **2701 W Foster Avenue** IDPH LICENSE NO: **100-07210**

---

HOMOGENEOUS AREA: **13**  
MATERIAL DESCRIPTION: **12"x12" Off White w/ Gray Streaks VFT**  
MATERIAL LOCATION: **Rooms 105, 118 and Hallway by 118 - 1907**  
MATERIAL QUANTITY: **1100** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **03/28/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22391** BUIDLING ID: **2440**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Holvay**  
SCHOOL NAME: **Budlong School** INSPECTION DATE: **3/8/2016**  
ADDRESS: **2701 W Foster Avenue** IDPH LICENSE NO: **100-07210**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **13A**  
MATERIAL DESCRIPTION: **12"x12" Off White w/ Gray Streaks VFT Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Rooms 105, 118 and Hallway by 118 - 1907**  
MATERIAL QUANTITY: **1100** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:

  
Michael Holvay  
Project Manager

Date: **03/08/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22391** BUIDLING ID: **2440**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Budlong School** REVIEW DATE: **3/28/2016**  
ADDRESS: **2701 W Foster Avenue** IDPH LICENSE NO: **100-07210**

---

HOMOGENEOUS AREA: **13A**  
MATERIAL DESCRIPTION: **12"x12" Off White w/ Gray Streaks VFT Mastic**  
MATERIAL LOCATION: **Rooms 105, 118 and Hallway by 118 - 1907**  
MATERIAL QUANTITY: **1100** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **03/28/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 22391 BUIDLING ID: 2440  
CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Michael Holvay  
SCHOOL NAME: Budlong School INSPECTION DATE: 3/8/2016  
ADDRESS: 2701 W Foster Avenue IDPH LICENSE NO: 100-07210

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 14  
MATERIAL DESCRIPTION: 9"x9" Brown w/ White Streaks VFT  
HISTORICAL AHERA DAMAGE CATEGORY 6 ACBM with the potential for damage  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: Follow O&M Plan  
ASBESTOS TYPE: Chrysotile FRIABLE: No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: MODERATE  
MATERIAL LOCATION: Room 118b (under carpet) & 118C (under HA #13) - 1907  
MATERIAL QUANTITY: 760 MATERIAL UNITS: SF  
DAMAGE QUANTITY: DAMAGE UNITS: SF  
COMMENTS: NOT OBSERVED

Inspector's Signature:

  
Michael Holvay  
Project Manager

Date: 03/08/2016

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22391** BUIDLING ID: **2440**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Budlong School** REVIEW DATE: **3/28/2016**  
ADDRESS: **2701 W Foster Avenue** IDPH LICENSE NO: **100-07210**

---

HOMOGENEOUS AREA: **14**  
MATERIAL DESCRIPTION: **9"x9" Brown w/ White Streaks VFT**  
MATERIAL LOCATION: **Room 118b (under carpet) & 118C (under HA #13) - 1907**  
MATERIAL QUANTITY: **760** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **03/28/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22391** BUIDLING ID: **2440**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Holvay**  
SCHOOL NAME: **Budlong School** INSPECTION DATE: **3/8/2016**  
ADDRESS: **2701 W Foster Avenue** IDPH LICENSE NO: **100-07210**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **14A**  
MATERIAL DESCRIPTION: **9"x9" Brown w/ White Streaks VFT Mastic - NOT OBSERVED**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Room 118b (under carpet) & 118C (under HA #13) - 1907**  
MATERIAL QUANTITY: **760** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS: **- NOT OBSERVED**

Inspector's Signature: \_\_\_\_\_

  
Michael Holvay  
Project Manager

Date: 03/08/2016



# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22391** BUILDING ID: **2440**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Budlong School** REVIEW DATE: **3/28/2016**  
ADDRESS: **2701 W Foster Avenue** IDPH LICENSE NO: **100-07210**

---

HOMOGENEOUS AREA: **14A**  
MATERIAL DESCRIPTION: **9"x9" Brown w/ White Streaks VFT Mastic - NOT OBSERVED**  
MATERIAL LOCATION: **Room 118b (under carpet) & 118C (under HA #13) - 1907**  
MATERIAL QUANTITY: **760** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **03/28/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22391** BUIDLING ID: **2440**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Holvay**  
SCHOOL NAME: **Budlong School** INSPECTION DATE: **3/8/2016**  
ADDRESS: **2701 W Foster Avenue** IDPH LICENSE NO: **100-07210**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **15**  
MATERIAL DESCRIPTION: **12"x12" Light Brown w/ wht/brwn specks VFT**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **Engineer's old office - 1907**  
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature:

  
Michael Holvay  
Project Manager

Date: **03/08/2016**

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22391** BUILDING ID: **2440**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Budlong School** REVIEW DATE: **3/28/2016**  
ADDRESS: **2701 W Foster Avenue** IDPH LICENSE NO: **100-07210**

---

HOMOGENEOUS AREA: **15**  
MATERIAL DESCRIPTION: **12"x12" Light Brown w/ wht/brwn specks VFT**  
MATERIAL LOCATION: **Engineer's old office - 1907**  
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **03/28/2016**

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22391** BUIDLING ID: **2440**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Holvay**  
SCHOOL NAME: **Budlong School** INSPECTION DATE: **3/8/2016**  
ADDRESS: **2701 W Foster Avenue** IDPH LICENSE NO: **100-07210**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **15A**  
MATERIAL DESCRIPTION: **12"x12" Light Brown w/ wht/brwn specks VFT Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Engineer's old office - 1907**  
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_

  
Michael Holvay  
Project Manager

Date: 03/08/2016

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22391** BUIDLING ID: **2440**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Budlong School** REVIEW DATE: **3/28/2016**  
ADDRESS: **2701 W Foster Avenue** IDPH LICENSE NO: **100-07210**

---

HOMOGENEOUS AREA: **15A**  
MATERIAL DESCRIPTION: **12"x12" Light Brown w/ wht/brwn specks VFT Mastic**  
MATERIAL LOCATION: **Engineer's old office - 1907**  
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **03/28/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22391** BUIDLING ID: **2440**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Holvay**  
SCHOOL NAME: **Budlong School** INSPECTION DATE: **3/8/2016**  
ADDRESS: **2701 W Foster Avenue** IDPH LICENSE NO: **100-07210**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **16**  
MATERIAL DESCRIPTION: **12"x12" Cream VFT**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **Janitor's closet by Principal's office - 1907**  
MATERIAL QUANTITY: **20** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature:

  
Michael Holvay  
Project Manager

Date: **03/08/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22391** BUIDLING ID: **2440**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Budlong School** REVIEW DATE: **3/28/2016**  
ADDRESS: **2701 W Foster Avenue** IDPH LICENSE NO: **100-07210**

---

HOMOGENEOUS AREA: **16**  
MATERIAL DESCRIPTION: **12"x12" Cream VFT**  
MATERIAL LOCATION: **Janitor's closet by Principal's office - 1907**  
MATERIAL QUANTITY: **20** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **03/28/2016**

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22391** BUIDLING ID: **2440**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Holvay**  
SCHOOL NAME: **Budlong School** INSPECTION DATE: **3/8/2016**  
ADDRESS: **2701 W Foster Avenue** IDPH LICENSE NO: **100-07210**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **16A**  
MATERIAL DESCRIPTION: **12"x12" Cream VFT Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Janitor's closet by Principal's office - 1907**  
MATERIAL QUANTITY: **20** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:

  
Michael Holvay  
Project Manager

Date: **03/08/2016**



# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22391** BUIDLING ID: **2440**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Budlong School** REVIEW DATE: **3/28/2016**  
ADDRESS: **2701 W Foster Avenue** IDPH LICENSE NO: **100-07210**

---

HOMOGENEOUS AREA: **16A**  
MATERIAL DESCRIPTION: **12"x12" Cream VFT Mastic**  
MATERIAL LOCATION: **Janitor's closet by Principal's office - 1907**  
MATERIAL QUANTITY: **20** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **03/28/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22391** BUIDLING ID: **2440**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Holvay**  
SCHOOL NAME: **Budlong School** INSPECTION DATE: **3/8/2016**  
ADDRESS: **2701 W Foster Avenue** IDPH LICENSE NO: **100-07210**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **17**  
MATERIAL DESCRIPTION: **12"x12" White VFT - Not observed**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 111 - 1955 - Not observed**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:

  
Michael Holvay  
Project Manager

Date: **03/08/2016**

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22391** BUIDLING ID: **2440**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Budlong School** REVIEW DATE: **3/28/2016**  
ADDRESS: **2701 W Foster Avenue** IDPH LICENSE NO: **100-07210**

---

HOMOGENEOUS AREA: **17**  
MATERIAL DESCRIPTION: **12"x12" White VFT - Not observed**  
MATERIAL LOCATION: **Room 111 - 1955 - Not observed**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **03/28/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22391** BUIDLING ID: **2440**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Holvay**  
SCHOOL NAME: **Budlong School** INSPECTION DATE: **3/8/2016**  
ADDRESS: **2701 W Foster Avenue** IDPH LICENSE NO: **100-07210**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **17A**  
MATERIAL DESCRIPTION: **12"x12" White VFT Mastic - Not observed**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 111 - 1955 - Not observed**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:

  
Michael Holvay  
Project Manager

Date: **03/08/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22391** BUIDLING ID: **2440**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Budlong School** REVIEW DATE: **3/28/2016**  
ADDRESS: **2701 W Foster Avenue** IDPH LICENSE NO: **100-07210**

---

HOMOGENEOUS AREA: **17A**  
MATERIAL DESCRIPTION: **12"x12" White VFT Mastic - Not observed**  
MATERIAL LOCATION: **Room 111 - 1955 - Not observed**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **03/28/2016**

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22391** BUIDLING ID: **2440**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Holvay**  
SCHOOL NAME: **Budlong School** INSPECTION DATE: **3/8/2016**  
ADDRESS: **2701 W Foster Avenue** IDPH LICENSE NO: **100-07210**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **18**  
MATERIAL DESCRIPTION: **9"x9" Peach VFT (ABATED)**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Abated** FRIABLE:

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1st Floor Middle Hallway - 1955 (ABATED)**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:

  
Michael Holvay  
Project Manager

Date: **03/08/2016**

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22391** BUIDLING ID: **2440**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Budlong School** REVIEW DATE: **3/28/2016**  
ADDRESS: **2701 W Foster Avenue** IDPH LICENSE NO: **100-07210**

---

HOMOGENEOUS AREA: **18**

MATERIAL DESCRIPTION: **9"x9" Peach VFT (ABATED)**

MATERIAL LOCATION: **1st Floor Middle Hallway - 1955 (ABATED)**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **03/28/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22391** BUIDLING ID: **2440**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Holvay**  
SCHOOL NAME: **Budlong School** INSPECTION DATE: **3/8/2016**  
ADDRESS: **2701 W Foster Avenue** IDPH LICENSE NO: **100-07210**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **18A**  
MATERIAL DESCRIPTION: **9"x9" Peach VFT Mastic - (ABATED)**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1st Floor Middle Hallway - 1955 (ABATED)**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:

  
Michael Holvay  
Project Manager

Date: **03/08/2016**



# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22391** BUIDLING ID: **2440**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Budlong School** REVIEW DATE: **3/28/2016**  
ADDRESS: **2701 W Foster Avenue** IDPH LICENSE NO: **100-07210**

---

HOMOGENEOUS AREA: **18A**  
MATERIAL DESCRIPTION: **9"x9" Peach VFT Mastic - (ABATED)**  
MATERIAL LOCATION: **1st Floor Middle Hallway - 1955 (ABATED)**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **03/28/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22391** BUIDLING ID: **2440**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Holvay**  
SCHOOL NAME: **Budlong School** INSPECTION DATE: **3/8/2016**  
ADDRESS: **2701 W Foster Avenue** IDPH LICENSE NO: **100-07210**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **19**  
MATERIAL DESCRIPTION: **9"x9" Tan VFT (ABATED)**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1st Floor NW Corridor Hallway - 1955**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:

  
Michael Holvay  
Project Manager

Date: **03/08/2016**

---

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22391** BUILDING ID: **2440**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Budlong School** REVIEW DATE: **3/28/2016**  
ADDRESS: **2701 W Foster Avenue** IDPH LICENSE NO: **100-07210**

---

HOMOGENEOUS AREA: **19**  
MATERIAL DESCRIPTION: **9"x9" Tan VFT (ABATED)**  
MATERIAL LOCATION: **1st Floor NW Corridor Hallway - 1955**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **03/28/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22391** BUIDLING ID: **2440**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Holvay**  
SCHOOL NAME: **Budlong School** INSPECTION DATE: **3/8/2016**  
ADDRESS: **2701 W Foster Avenue** IDPH LICENSE NO: **100-07210**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **19A**  
MATERIAL DESCRIPTION: **9"x9" Tan VFT Mastic (ABATED)**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1st Floor NW Corridor Hallway - 1955**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:

  
Michael Holvay  
Project Manager

Date: **03/08/2016**

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22391** BUILDING ID: **2440**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Budlong School** REVIEW DATE: **3/28/2016**  
ADDRESS: **2701 W Foster Avenue** IDPH LICENSE NO: **100-07210**

---

HOMOGENEOUS AREA: **19A**  
MATERIAL DESCRIPTION: **9"x9" Tan VFT Mastic (ABATED)**  
MATERIAL LOCATION: **1st Floor NW Corridor Hallway - 1955**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **03/28/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22391** BUIDLING ID: **2440**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Holvay**  
SCHOOL NAME: **Budlong School** INSPECTION DATE: **3/8/2016**  
ADDRESS: **2701 W Foster Avenue** IDPH LICENSE NO: **100-07210**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **20**  
MATERIAL DESCRIPTION: **9"x9" Tan Spotted VFT (ABATED)**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1st Floor NW Corridor Hallway - 1955**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:

  
Michael Holvay  
Project Manager

Date: **03/08/2016**

---

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22391** BUILDING ID: **2440**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Budlong School** REVIEW DATE: **3/28/2016**  
ADDRESS: **2701 W Foster Avenue** IDPH LICENSE NO: **100-07210**

---

HOMOGENEOUS AREA: **20**  
MATERIAL DESCRIPTION: **9"x9" Tan Spotted VFT (ABATED)**  
MATERIAL LOCATION: **1st Floor NW Corridor Hallway - 1955**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **03/28/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 22391 BUIDLING ID: 2440  
CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Michael Holvay  
SCHOOL NAME: Budlong School INSPECTION DATE: 3/8/2016  
ADDRESS: 2701 W Foster Avenue IDPH LICENSE NO: 100-07210

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 20A  
MATERIAL DESCRIPTION: 9"x9" Tan Spotted VFT Mastic (ABATED)  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: Abated FRIABLE:

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: 1st Floor NW Corridor Hallway - 1955

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:

  
Michael Holvay  
Project Manager

Date: 03/08/2016



# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22391** BUILDING ID: **2440**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Budlong School** REVIEW DATE: **3/28/2016**  
ADDRESS: **2701 W Foster Avenue** IDPH LICENSE NO: **100-07210**

---

HOMOGENEOUS AREA: **20A**  
MATERIAL DESCRIPTION: **9"x9" Tan Spotted VFT Mastic (ABATED)**  
MATERIAL LOCATION: **1st Floor NW Corridor Hallway - 1955**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **03/28/2016**

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22391** BUIDLING ID: **2440**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Holvay**  
SCHOOL NAME: **Budlong School** INSPECTION DATE: **3/8/2016**  
ADDRESS: **2701 W Foster Avenue** IDPH LICENSE NO: **100-07210**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **21**  
MATERIAL DESCRIPTION: **12"x12" Gray w/ Pink & White Streaks VFT**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **Room 112 - 1955**  
MATERIAL QUANTITY: **850** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:

  
Michael Holvay  
Project Manager

Date: **03/08/2016**

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22391** BUIDLING ID: **2440**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Budlong School** REVIEW DATE: **3/28/2016**  
ADDRESS: **2701 W Foster Avenue** IDPH LICENSE NO: **100-07210**

---

HOMOGENEOUS AREA: **21**  
MATERIAL DESCRIPTION: **12"x12" Gray w/ Pink & White Streaks VFT**  
MATERIAL LOCATION: **Room 112 - 1955**  
MATERIAL QUANTITY: **850** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **03/28/2016**

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22391** BUIDLING ID: **2440**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Holvay**  
SCHOOL NAME: **Budlong School** INSPECTION DATE: **3/8/2016**  
ADDRESS: **2701 W Foster Avenue** IDPH LICENSE NO: **100-07210**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **21A**  
MATERIAL DESCRIPTION: **12"x12" Gray w/ Pink & White Streaks VFT Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Room 112 - 1955**  
MATERIAL QUANTITY: **850** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_

  
Michael Holvay  
Project Manager

Date: 03/08/2016

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22391** BUILDING ID: **2440**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Budlong School** REVIEW DATE: **3/28/2016**  
ADDRESS: **2701 W Foster Avenue** IDPH LICENSE NO: **100-07210**

---

HOMOGENEOUS AREA: **21A**  
MATERIAL DESCRIPTION: **12"x12" Gray w/ Pink & White Streaks VFT Mastic**  
MATERIAL LOCATION: **Room 112 - 1955**  
MATERIAL QUANTITY: **850** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **03/28/2016**

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22391** BUIDLING ID: **2440**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Holvay**  
SCHOOL NAME: **Budlong School** INSPECTION DATE: **3/8/2016**  
ADDRESS: **2701 W Foster Avenue** IDPH LICENSE NO: **100-07210**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **22**  
MATERIAL DESCRIPTION: **12"x12" Beige w/ White Speckles VFT**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **Exit Door, Rooms 113, 114 (under carpet) - 1955**  
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature:

  
Michael Holvay  
Project Manager

Date: **03/08/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22391** BUIDLING ID: **2440**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Budlong School** REVIEW DATE: **3/28/2016**  
ADDRESS: **2701 W Foster Avenue** IDPH LICENSE NO: **100-07210**

---

HOMOGENEOUS AREA: **22**  
MATERIAL DESCRIPTION: **12"x12" Beige w/ White Speckles VFT**  
MATERIAL LOCATION: **Exit Door, Rooms 113, 114 (under carpet) - 1955**  
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **03/28/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22391** BUIDLING ID: **2440**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Holvay**  
SCHOOL NAME: **Budlong School** INSPECTION DATE: **3/8/2016**  
ADDRESS: **2701 W Foster Avenue** IDPH LICENSE NO: **100-07210**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **22A**  
MATERIAL DESCRIPTION: **12"x12" Beige w/ White Speckles VFT Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Exit Door, Rooms 113, 114 (under carpet) - 1955**  
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature:

  
Michael Holvay  
Project Manager

Date: **03/08/2016**



# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22391** BUILDING ID: **2440**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Budlong School** REVIEW DATE: **3/28/2016**  
ADDRESS: **2701 W Foster Avenue** IDPH LICENSE NO: **100-07210**

---

HOMOGENEOUS AREA: **22A**  
MATERIAL DESCRIPTION: **12"x12" Beige w/ White Speckles VFT Mastic**  
MATERIAL LOCATION: **Exit Door, Rooms 113, 114 (under carpet) - 1955**  
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **03/28/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22391** BUIDLING ID: **2440**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Holvay**  
SCHOOL NAME: **Budlong School** INSPECTION DATE: **3/8/2016**  
ADDRESS: **2701 W Foster Avenue** IDPH LICENSE NO: **100-07210**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **23**  
MATERIAL DESCRIPTION: **12"x12" Green w/ Black & White VFT (ABATED)**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 111 - 1955 (now HA34+35)**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Now HA#34+35**

Inspector's Signature:

  
Michael Holvay  
Project Manager

Date: **03/08/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22391** BUILDING ID: **2440**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Budlong School** REVIEW DATE: **3/28/2016**  
ADDRESS: **2701 W Foster Avenue** IDPH LICENSE NO: **100-07210**

---

HOMOGENEOUS AREA: **23**

MATERIAL DESCRIPTION: **12"x12" Green w/ Black & White VFT (ABATED)**

MATERIAL LOCATION: **Room 111 - 1955 (now HA34+35)**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **03/28/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22391** BUIDLING ID: **2440**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Holvay**  
SCHOOL NAME: **Budlong School** INSPECTION DATE: **3/8/2016**  
ADDRESS: **2701 W Foster Avenue** IDPH LICENSE NO: **100-07210**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **23A**  
MATERIAL DESCRIPTION: **12"x12" Green w/ White & Black VFT Mastic - (ABATED)**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 111 - 1955**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Now HA#34+35**

Inspector's Signature:

  
Michael Holvay  
Project Manager

Date: **03/08/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22391** BUILDING ID: **2440**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Budlong School** REVIEW DATE: **3/28/2016**  
ADDRESS: **2701 W Foster Avenue** IDPH LICENSE NO: **100-07210**

---

HOMOGENEOUS AREA: **23A**  
MATERIAL DESCRIPTION: **12"x12" Green w/ White & Black VFT Mastic - (ABATED)**  
MATERIAL LOCATION: **Room 111 - 1955**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **03/28/2016**

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22391** BUIDLING ID: **2440**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Holvay**  
SCHOOL NAME: **Budlong School** INSPECTION DATE: **3/8/2016**  
ADDRESS: **2701 W Foster Avenue** IDPH LICENSE NO: **100-07210**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **24**  
MATERIAL DESCRIPTION: **12"x12" Rust Brown w/ White & Brown Streaks VFT - (ABATED)**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 110 - 1955**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Now HA#34+35**

Inspector's Signature:

  
Michael Holvay  
Project Manager

Date: **03/08/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22391** BUIDLING ID: **2440**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Budlong School** REVIEW DATE: **3/28/2016**  
ADDRESS: **2701 W Foster Avenue** IDPH LICENSE NO: **100-07210**

---

HOMOGENEOUS AREA: **24**  
MATERIAL DESCRIPTION: **12"x12" Rust Brown w/ White & Brown Streaks VFT - (ABATED)**  
MATERIAL LOCATION: **Room 110 - 1955**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **03/28/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22391** BUIDLING ID: **2440**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Holvay**  
SCHOOL NAME: **Budlong School** INSPECTION DATE: **3/8/2016**  
ADDRESS: **2701 W Foster Avenue** IDPH LICENSE NO: **100-07210**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **24A**  
MATERIAL DESCRIPTION: **12"x12" Rust Brn w/ White & Brn Streaks VFT Mastic - (ABATED)**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 110 - 1955**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Now HA#34+35**

Inspector's Signature:

  
Michael Holvay  
Project Manager

Date: **03/08/2016**



# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22391** BUIDLING ID: **2440**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Budlong School** REVIEW DATE: **3/28/2016**  
ADDRESS: **2701 W Foster Avenue** IDPH LICENSE NO: **100-07210**

---

HOMOGENEOUS AREA: **24A**  
MATERIAL DESCRIPTION: **12"x12" Rust Brn w/ White & Brn Streaks VFT Mastic - (ABATED)**  
MATERIAL LOCATION: **Room 110 - 1955**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **03/28/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22391** BUIDLING ID: **2440**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Holvay**  
SCHOOL NAME: **Budlong School** INSPECTION DATE: **3/8/2016**  
ADDRESS: **2701 W Foster Avenue** IDPH LICENSE NO: **100-07210**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **25**  
MATERIAL DESCRIPTION: **12"x12" Grey VFT**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **All Rooms Except Boiler Rm, Electrical Rms, Gym and toilets - 1997 Annex**  
MATERIAL QUANTITY: **8800** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:

  
Michael Holvay  
Project Manager

Date: **03/08/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22391** BUIDLING ID: **2440**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Budlong School** REVIEW DATE: **3/28/2016**  
ADDRESS: **2701 W Foster Avenue** IDPH LICENSE NO: **100-07210**

---

HOMOGENEOUS AREA: **25**  
MATERIAL DESCRIPTION: **12"x12" Grey VFT**  
MATERIAL LOCATION: **All Rooms Except Boiler Rm, Electrical Rms, Gym and toilets - 1997 Annex**  
MATERIAL QUANTITY: **8800** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **03/28/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22391** BUIDLING ID: **2440**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Holvay**  
SCHOOL NAME: **Budlong School** INSPECTION DATE: **3/8/2016**  
ADDRESS: **2701 W Foster Avenue** IDPH LICENSE NO: **100-07210**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **25A**  
MATERIAL DESCRIPTION: **12"x12" Grey VFT Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **All Rooms Except Boiler Rm, Electrical Rms, Gym and Toilets - 1997 Annex**  
MATERIAL QUANTITY: **8800** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:

  
Michael Holvay  
Project Manager

Date: **03/08/2016**

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22391** BUILDING ID: **2440**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Budlong School** REVIEW DATE: **3/28/2016**  
ADDRESS: **2701 W Foster Avenue** IDPH LICENSE NO: **100-07210**

---

HOMOGENEOUS AREA: **25A**  
MATERIAL DESCRIPTION: **12"x12" Grey VFT Mastic**  
MATERIAL LOCATION: **All Rooms Except Boiler Rm, Electrical Rms, Gym and Toilets - 1997 Annex**  
MATERIAL QUANTITY: **8800** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **03/28/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 22391 BUIDLING ID: 2440  
CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Michael Holvay  
SCHOOL NAME: Budlong School INSPECTION DATE: 3/8/2016  
ADDRESS: 2701 W Foster Avenue IDPH LICENSE NO: 100-07210

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 26  
MATERIAL DESCRIPTION: Vinyl Baseboard  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: No ACBM FRIABLE:

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: All Rooms Except Boiler Rm, Electrical Rms & Gym - 1997 Annex

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:

  
Michael Holvay  
Project Manager

Date: 03/08/2016

---

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22391** BUIDLING ID: **2440**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Budlong School** REVIEW DATE: **3/28/2016**  
ADDRESS: **2701 W Foster Avenue** IDPH LICENSE NO: **100-07210**

---

HOMOGENEOUS AREA: **26**  
MATERIAL DESCRIPTION: **Vinyl Baseboard**  
MATERIAL LOCATION: **All Rooms Except Boiler Rm, Electrical Rms & Gym - 1997 Annex**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **03/28/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22391** BUIDLING ID: **2440**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Holvay**  
SCHOOL NAME: **Budlong School** INSPECTION DATE: **3/8/2016**  
ADDRESS: **2701 W Foster Avenue** IDPH LICENSE NO: **100-07210**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **26A**  
MATERIAL DESCRIPTION: **Vinyl Baseboard Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **All Rooms Except Boiler Rm, Electrical Rms & Gym - 1997 Annex**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:

  
Michael Holvay  
Project Manager

Date: **03/08/2016**



# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22391** BUIDLING ID: **2440**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Budlong School** REVIEW DATE: **3/28/2016**  
ADDRESS: **2701 W Foster Avenue** IDPH LICENSE NO: **100-07210**

---

HOMOGENEOUS AREA: **26A**  
MATERIAL DESCRIPTION: **Vinyl Baseboard Mastic**  
MATERIAL LOCATION: **All Rooms Except Boiler Rm, Electrical Rms & Gym - 1997 Annex**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **03/28/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22391** BUIDLING ID: **2440**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Holvay**  
SCHOOL NAME: **Budlong School** INSPECTION DATE: **3/8/2016**  
ADDRESS: **2701 W Foster Avenue** IDPH LICENSE NO: **100-07210**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **27**  
MATERIAL DESCRIPTION: **2'x4' Ceiling Tile**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **All Rooms Except Boiler Rm, Electrical Rms & Gym - 1997 Annex**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:

  
Michael Holvay  
Project Manager

Date: **03/08/2016**

---

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22391** BUIDLING ID: **2440**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Budlong School** REVIEW DATE: **3/28/2016**  
ADDRESS: **2701 W Foster Avenue** IDPH LICENSE NO: **100-07210**

---

HOMOGENEOUS AREA: **27**  
MATERIAL DESCRIPTION: **2'x4' Ceiling Tile**  
MATERIAL LOCATION: **All Rooms Except Boiler Rm, Electrical Rms & Gym - 1997 Annex**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **03/28/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22391** BUIDLING ID: **2440**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Holvay**  
SCHOOL NAME: **Budlong School** INSPECTION DATE: **3/8/2016**  
ADDRESS: **2701 W Foster Avenue** IDPH LICENSE NO: **100-07210**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **28**  
MATERIAL DESCRIPTION: **2'x4' Ceiling Tile**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **All Rooms Except Bathrooms & Mechanical Rooms - 1998 Fieldhouse**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:

  
Michael Holvay  
Project Manager

Date: **03/08/2016**

---

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22391** BUIDLING ID: **2440**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Budlong School** REVIEW DATE: **3/28/2016**  
ADDRESS: **2701 W Foster Avenue** IDPH LICENSE NO: **100-07210**

---

HOMOGENEOUS AREA: **28**  
MATERIAL DESCRIPTION: **2'x4' Ceiling Tile**  
MATERIAL LOCATION: **All Rooms Except Bathrooms & Mechanical Rooms - 1998 Fieldhouse**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **03/28/2016**

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22391** BUIDLING ID: **2440**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Holvay**  
SCHOOL NAME: **Budlong School** INSPECTION DATE: **3/8/2016**  
ADDRESS: **2701 W Foster Avenue** IDPH LICENSE NO: **100-07210**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **29**  
MATERIAL DESCRIPTION: **Vinyl Baseboard**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout 1998 Fieldhouse**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:

  
Michael Holvay  
Project Manager

Date: **03/08/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22391** BUIDLING ID: **2440**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Budlong School** REVIEW DATE: **3/28/2016**  
ADDRESS: **2701 W Foster Avenue** IDPH LICENSE NO: **100-07210**

---

HOMOGENEOUS AREA: **29**

MATERIAL DESCRIPTION: **Vinyl Baseboard**

MATERIAL LOCATION: **Throughout 1998 Fieldhouse**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **03/28/2016**

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22391** BUIDLING ID: **2440**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Holvay**  
SCHOOL NAME: **Budlong School** INSPECTION DATE: **3/8/2016**  
ADDRESS: **2701 W Foster Avenue** IDPH LICENSE NO: **100-07210**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **30**  
MATERIAL DESCRIPTION: **Vinyl Baseboard Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout 1998 Fieldhouse**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:

  
Michael Holvay  
Project Manager

Date: **03/08/2016**



# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22391** BUIDLING ID: **2440**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Budlong School** REVIEW DATE: **3/28/2016**  
ADDRESS: **2701 W Foster Avenue** IDPH LICENSE NO: **100-07210**

---

HOMOGENEOUS AREA: **30**

MATERIAL DESCRIPTION: **Vinyl Baseboard Mastic**

MATERIAL LOCATION: **Throughout 1998 Fieldhouse**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **03/28/2016**

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22391** BUIDLING ID: **2440**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Holvay**  
SCHOOL NAME: **Budlong School** INSPECTION DATE: **3/8/2016**  
ADDRESS: **2701 W Foster Avenue** IDPH LICENSE NO: **100-07210**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **31**  
MATERIAL DESCRIPTION: **Vinyl Baseboard**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout 2000 Mobile - Removed from school property**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **2000 Mobile Unit Not on Site**

Inspector's Signature:

  
Michael Holvay  
Project Manager

Date: **03/08/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22391** BUILDING ID: **2440**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Budlong School** REVIEW DATE: **3/28/2016**  
ADDRESS: **2701 W Foster Avenue** IDPH LICENSE NO: **100-07210**

---

HOMOGENEOUS AREA: **31**  
MATERIAL DESCRIPTION: **Vinyl Baseboard**  
MATERIAL LOCATION: **Throughout 2000 Mobile - Removed from school property**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **03/28/2016**

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22391** BUIDLING ID: **2440**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Holvay**  
SCHOOL NAME: **Budlong School** INSPECTION DATE: **3/8/2016**  
ADDRESS: **2701 W Foster Avenue** IDPH LICENSE NO: **100-07210**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **32**  
MATERIAL DESCRIPTION: **Vinyl Baseboard Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout 2000 Mobile - Removed from school property**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **2000 Mobile Unit not on site**

Inspector's Signature:

  
Michael Holvay  
Project Manager

Date: **03/08/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22391** BUIDLING ID: **2440**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Budlong School** REVIEW DATE: **3/28/2016**  
ADDRESS: **2701 W Foster Avenue** IDPH LICENSE NO: **100-07210**

---

HOMOGENEOUS AREA: **32**

MATERIAL DESCRIPTION: **Vinyl Baseboard Mastic**

MATERIAL LOCATION: **Throughout 2000 Mobile - Removed from school property**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **03/28/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22391** BUIDLING ID: **2440**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Holvay**  
SCHOOL NAME: **Budlong School** INSPECTION DATE: **3/8/2016**  
ADDRESS: **2701 W Foster Avenue** IDPH LICENSE NO: **100-07210**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **33**  
MATERIAL DESCRIPTION: **12"x12" cofee w/ cream streaks VFT**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **Room 117**  
MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:

  
Michael Holvay  
Project Manager

Date: **03/08/2016**

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22391** BUIDLING ID: **2440**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Budlong School** REVIEW DATE: **3/28/2016**  
ADDRESS: **2701 W Foster Avenue** IDPH LICENSE NO: **100-07210**

---

HOMOGENEOUS AREA: **33**  
MATERIAL DESCRIPTION: **12"x12" cofee w/ cream streaks VFT**  
MATERIAL LOCATION: **Room 117**  
MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **03/28/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22391** BUIDLING ID: **2440**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Holvay**  
SCHOOL NAME: **Budlong School** INSPECTION DATE: **3/8/2016**  
ADDRESS: **2701 W Foster Avenue** IDPH LICENSE NO: **100-07210**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **33A**  
MATERIAL DESCRIPTION: **12"x12" coffee w/ cream streaks VFT Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Room 117**  
MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:

  
Michael Holvay  
Project Manager

Date: **03/08/2016**



# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22391** BUIDLING ID: **2440**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Budlong School** REVIEW DATE: **3/28/2016**  
ADDRESS: **2701 W Foster Avenue** IDPH LICENSE NO: **100-07210**

---

HOMOGENEOUS AREA: **33A**  
MATERIAL DESCRIPTION: **12"x12" coffee w/ cream streaks VFT Mastic**  
MATERIAL LOCATION: **Room 117**  
MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **03/28/2016**

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22391** BUIDLING ID: **2440**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Holvay**  
SCHOOL NAME: **Budlong School** INSPECTION DATE: **3/8/2016**  
ADDRESS: **2701 W Foster Avenue** IDPH LICENSE NO: **100-07210**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **34**  
MATERIAL DESCRIPTION: **12"X 12" White w/Black Specks Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **Lunchroom, Kitchen Office and Corridor - 1955 Bldg**  
MATERIAL QUANTITY: **3200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature:

  
Michael Holvay  
Project Manager

Date: **03/08/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22391** BUIDLING ID: **2440**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Budlong School** REVIEW DATE: **3/28/2016**  
ADDRESS: **2701 W Foster Avenue** IDPH LICENSE NO: **100-07210**

---

HOMOGENEOUS AREA: **34**  
MATERIAL DESCRIPTION: **12"X 12" White w/Black Specks Floor Tile**  
MATERIAL LOCATION: **Lunchroom, Kitchen Office and Corridor - 1955 Bldg**  
MATERIAL QUANTITY: **3200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **03/28/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22391** BUIDLING ID: **2440**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Holvay**  
SCHOOL NAME: **Budlong School** INSPECTION DATE: **3/8/2016**  
ADDRESS: **2701 W Foster Avenue** IDPH LICENSE NO: **100-07210**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **35**  
MATERIAL DESCRIPTION: **12"X 12' White w/Black Specks Floor Tile MASTIC**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Lunchroom, Kitchen Office and Corridor - 1955 Bldg**  
MATERIAL QUANTITY: **3200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature:

  
Michael Holvay  
Project Manager

Date: **03/08/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22391** BUIDLING ID: **2440**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Budlong School** REVIEW DATE: **3/28/2016**  
ADDRESS: **2701 W Foster Avenue** IDPH LICENSE NO: **100-07210**

---

HOMOGENEOUS AREA: **35**  
MATERIAL DESCRIPTION: **12"X 12' White w/Black Specks Floor Tile MASTIC**  
MATERIAL LOCATION: **Lunchroom, Kitchen Office and Corridor - 1955 Bldg**  
MATERIAL QUANTITY: **3200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **03/28/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22391** BUIDLING ID: **2440**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Holvay**  
SCHOOL NAME: **Budlong School** INSPECTION DATE: **3/8/2016**  
ADDRESS: **2701 W Foster Avenue** IDPH LICENSE NO: **100-07210**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **36**  
MATERIAL DESCRIPTION: **Terrazzo -NOT OBSERVED**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **3rd Floor Boys and Mens Toilet and 2nd Floor Girls and Women's Toilet (1907 Bldg)**  
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS: **-NOT OBSERVED**

Inspector's Signature:

  
Michael Holvay  
Project Manager

Date: **03/08/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22391** BUIDLING ID: **2440**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Budlong School** REVIEW DATE: **3/28/2016**  
ADDRESS: **2701 W Foster Avenue** IDPH LICENSE NO: **100-07210**

---

HOMOGENEOUS AREA: **36**  
MATERIAL DESCRIPTION: **Terrazzo -NOT OBSERVED**  
MATERIAL LOCATION: **3rd Floor Boys and Mens Toilet and 2nd Floor Girls and Women's Toilet (1907 Bldg)**  
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **03/28/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22391** BUIDLING ID: **2440**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Holvay**  
SCHOOL NAME: **Budlong School** INSPECTION DATE: **3/8/2016**  
ADDRESS: **2701 W Foster Avenue** IDPH LICENSE NO: **100-07210**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **37**  
MATERIAL DESCRIPTION: **Mastic Under Rubber Stair Tread**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **Stairwell (1907 Bldg)**  
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:

  
Michael Holvay  
Project Manager

Date: **03/08/2016**



# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22391** BUIDLING ID: **2440**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Budlong School** REVIEW DATE: **3/28/2016**  
ADDRESS: **2701 W Foster Avenue** IDPH LICENSE NO: **100-07210**

---

HOMOGENEOUS AREA: **37**  
MATERIAL DESCRIPTION: **Mastic Under Rubber Stair Tread**  
MATERIAL LOCATION: **Stairwell (1907 Bldg)**  
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **03/28/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22391** BUIDLING ID: **2440**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Holvay**  
SCHOOL NAME: **Budlong School** INSPECTION DATE: **3/8/2016**  
ADDRESS: **2701 W Foster Avenue** IDPH LICENSE NO: **100-07210**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **38**  
MATERIAL DESCRIPTION: **Carpet Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Assembly Hall Balcony, Assistant Principal's Office, Room 101, 104, 106, 204, 102 ward, Main office, Principal's Office Basement Rm 116 (Old Library) - Bldg 1907**

MATERIAL QUANTITY: **3000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:

  
Michael Holvay  
Project Manager

Date: **03/08/2016**

# Chicago Public Schools

GSG Consultants, Inc.

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22391** BUIDLING ID: **2440**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Budlong School** REVIEW DATE: **3/28/2016**  
ADDRESS: **2701 W Foster Avenue** IDPH LICENSE NO: **100-07210**

---

HOMOGENEOUS AREA: **38**  
MATERIAL DESCRIPTION: **Carpet Mastic**  
MATERIAL LOCATION: **Assembly Hall Balcony, Assistant Principal's Office, Room 101, 104, 106, 204, 102 ward, Main office, Principal's Office Basement Rm 116 (Old Library) - Bldg 1907**  
MATERIAL QUANTITY: **3000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **03/28/2016**

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22391** BUIDLING ID: **2440**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Holvay**  
SCHOOL NAME: **Budlong School** INSPECTION DATE: **3/8/2016**  
ADDRESS: **2701 W Foster Avenue** IDPH LICENSE NO: **100-07210**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **39**  
MATERIAL DESCRIPTION: **12"X12" White w/ Gray Specks VFT**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **Basement Rm 115 - 1907**  
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature:

  
Michael Holvay  
Project Manager

Date: **03/08/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22391** BUILDING ID: **2440**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Budlong School** REVIEW DATE: **3/28/2016**  
ADDRESS: **2701 W Foster Avenue** IDPH LICENSE NO: **100-07210**

---

HOMOGENEOUS AREA: **39**  
MATERIAL DESCRIPTION: **12"X12" White w/ Gray Specks VFT**  
MATERIAL LOCATION: **Basement Rm 115 - 1907**  
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **03/28/2016**

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22391** BUIDLING ID: **2440**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Holvay**  
SCHOOL NAME: **Budlong School** INSPECTION DATE: **3/8/2016**  
ADDRESS: **2701 W Foster Avenue** IDPH LICENSE NO: **100-07210**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **39A**  
MATERIAL DESCRIPTION: **12"X12" White w/ Gray Specks VFT Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Basement Rm 115 - 1907**  
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature:

  
Michael Holvay  
Project Manager

Date: **03/08/2016**

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22391** BUILDING ID: **2440**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Budlong School** REVIEW DATE: **3/28/2016**  
ADDRESS: **2701 W Foster Avenue** IDPH LICENSE NO: **100-07210**

---

HOMOGENEOUS AREA: **39A**  
MATERIAL DESCRIPTION: **12"X12" White w/ Gray Specks VFT Mastic**  
MATERIAL LOCATION: **Basement Rm 115 - 1907**  
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **03/28/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22391** BUILDING ID: **2440**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Holvay**  
SCHOOL NAME: **Budlong School** INSPECTION DATE: **3/8/2016**  
ADDRESS: **2701 W Foster Avenue** IDPH LICENSE NO: **100-07210**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **40**  
MATERIAL DESCRIPTION: **2' x 4' Ceiling Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **3rd, 2nd and 1st Floor Corridors, Room 204, Main Office, Room 107, Basement Room 116, 117, 115, Basement Engineer Office, Room 119, 118B, 118C, Corridor by 118C & 118B - 1907 Building**

MATERIAL QUANTITY: **9500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:

  
Michael Holvay  
Project Manager

Date: **03/08/2016**

---



# Chicago Public Schools

GSG Consultants, Inc.

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22391** BUIDLING ID: **2440**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Budlong School** REVIEW DATE: **3/28/2016**  
ADDRESS: **2701 W Foster Avenue** IDPH LICENSE NO: **100-07210**

---

HOMOGENEOUS AREA: **40**  
MATERIAL DESCRIPTION: **2' x 4' Ceiling Tile**  
MATERIAL LOCATION: **3rd, 2nd and 1st Floor Corridors, Room 204, Main Office, Room 107, Basement Room 116, 117, 115, Basement Engineer Office, Room 119, 118B, 118C, Corridor by 118C & 118B - 1907 Building**  
MATERIAL QUANTITY: **9500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **03/28/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22391** BUIDLING ID: **2440**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Holvay**  
SCHOOL NAME: **Budlong School** INSPECTION DATE: **3/8/2016**  
ADDRESS: **2701 W Foster Avenue** IDPH LICENSE NO: **100-07210**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **41**  
MATERIAL DESCRIPTION: **12" x 12" White with Brown Streaks VFT**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **Basement Room 117 - Building 1907**  
MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature:

  
Michael Holvay  
Project Manager

Date: **03/08/2016**

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22391** BUIDLING ID: **2440**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Budlong School** REVIEW DATE: **3/28/2016**  
ADDRESS: **2701 W Foster Avenue** IDPH LICENSE NO: **100-07210**

---

HOMOGENEOUS AREA: **41**  
MATERIAL DESCRIPTION: **12" x 12" White with Brown Streaks VFT**  
MATERIAL LOCATION: **Basement Room 117 - Building 1907**  
MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **03/28/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22391** BUIDLING ID: **2440**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Holvay**  
SCHOOL NAME: **Budlong School** INSPECTION DATE: **3/8/2016**  
ADDRESS: **2701 W Foster Avenue** IDPH LICENSE NO: **100-07210**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **41A**  
MATERIAL DESCRIPTION: **12" x 12" White with Brown Streaks VFT Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Basement Room 117 - Building 1907**  
MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_

  
Michael Holvay  
Project Manager

Date: 03/08/2016

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22391** BUILDING ID: **2440**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Budlong School** REVIEW DATE: **3/28/2016**  
ADDRESS: **2701 W Foster Avenue** IDPH LICENSE NO: **100-07210**

---

HOMOGENEOUS AREA: **41A**  
MATERIAL DESCRIPTION: **12" x 12" White with Brown Streaks VFT Mastic**  
MATERIAL LOCATION: **Basement Room 117 - Building 1907**  
MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **03/28/2016**

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22391** BUIDLING ID: **2440**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Holvay**  
SCHOOL NAME: **Budlong School** INSPECTION DATE: **3/8/2016**  
ADDRESS: **2701 W Foster Avenue** IDPH LICENSE NO: **100-07210**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **42**  
MATERIAL DESCRIPTION: **12" x 12" Blue VFT -- NOT OBSERVED**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **Lunch Room - 1955 Building**  
MATERIAL QUANTITY: **41** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS: **-- NOT OBSERVED**

Inspector's Signature:

  
Michael Holvay  
Project Manager

Date: **03/08/2016**

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22391** BUILDING ID: **2440**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Budlong School** REVIEW DATE: **3/28/2016**  
ADDRESS: **2701 W Foster Avenue** IDPH LICENSE NO: **100-07210**

---

HOMOGENEOUS AREA: **42**  
MATERIAL DESCRIPTION: **12" x 12" Blue VFT -- NOT OBSERVED**  
MATERIAL LOCATION: **Lunch Room - 1955 Building**  
MATERIAL QUANTITY: **41** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **03/28/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22391** BUIDLING ID: **2440**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Holvay**  
SCHOOL NAME: **Budlong School** INSPECTION DATE: **3/8/2016**  
ADDRESS: **2701 W Foster Avenue** IDPH LICENSE NO: **100-07210**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **42A**  
MATERIAL DESCRIPTION: **12" x 12" Blue VFT Mastic-- NOT OBSERVED**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Lunch Room - 1955 Building**  
MATERIAL QUANTITY: **41** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS: **-- NOT OBSERVED**

Inspector's Signature:

  
Michael Holvay  
Project Manager

Date: **03/08/2016**



# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22391** BUIDLING ID: **2440**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Budlong School** REVIEW DATE: **3/28/2016**  
ADDRESS: **2701 W Foster Avenue** IDPH LICENSE NO: **100-07210**

---

HOMOGENEOUS AREA: **42A**  
MATERIAL DESCRIPTION: **12" x 12" Blue VFT Mastic-- NOT OBSERVED**  
MATERIAL LOCATION: **Lunch Room - 1955 Building**  
MATERIAL QUANTITY: **41** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **03/28/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22391** BUIDLING ID: **2440**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Holvay**  
SCHOOL NAME: **Budlong School** INSPECTION DATE: **3/8/2016**  
ADDRESS: **2701 W Foster Avenue** IDPH LICENSE NO: **100-07210**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **43**  
MATERIAL DESCRIPTION: **12" x 12" Red VFT-- NOT OBSERVED**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **Lunch Room - 1955 Building**  
MATERIAL QUANTITY: **41** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS: **-- NOT OBSERVED**

Inspector's Signature:

  
Michael Holvay  
Project Manager

Date: **03/08/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22391** BUILDING ID: **2440**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Budlong School** REVIEW DATE: **3/28/2016**  
ADDRESS: **2701 W Foster Avenue** IDPH LICENSE NO: **100-07210**

---

HOMOGENEOUS AREA: **43**  
MATERIAL DESCRIPTION: **12" x 12" Red VFT-- NOT OBSERVED**  
MATERIAL LOCATION: **Lunch Room - 1955 Building**  
MATERIAL QUANTITY: **41** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **03/28/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22391** BUIDLING ID: **2440**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Holvay**  
SCHOOL NAME: **Budlong School** INSPECTION DATE: **3/8/2016**  
ADDRESS: **2701 W Foster Avenue** IDPH LICENSE NO: **100-07210**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **43A**  
MATERIAL DESCRIPTION: **12" X 12" Red VFT Mastic-- NOT OBSERVED**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Lunch Room - 1955 Building**  
MATERIAL QUANTITY: **41** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS: **-- NOT OBSERVED**

Inspector's Signature:

  
Michael Holvay  
Project Manager

Date: **03/08/2016**

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22391** BUIDLING ID: **2440**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Budlong School** REVIEW DATE: **3/28/2016**  
ADDRESS: **2701 W Foster Avenue** IDPH LICENSE NO: **100-07210**

---

HOMOGENEOUS AREA: **43A**  
MATERIAL DESCRIPTION: **12" X 12" Red VFT Mastic-- NOT OBSERVED**  
MATERIAL LOCATION: **Lunch Room - 1955 Building**  
MATERIAL QUANTITY: **41** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **03/28/2016**

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22391** BUIDLING ID: **2440**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Holvay**  
SCHOOL NAME: **Budlong School** INSPECTION DATE: **3/8/2016**  
ADDRESS: **2701 W Foster Avenue** IDPH LICENSE NO: **100-07210**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **44**  
MATERIAL DESCRIPTION: **1' x 1' White Groove Ceiling Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Throughout 1955 Building**  
MATERIAL QUANTITY: **5000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:

  
Michael Holvay  
Project Manager

Date: **03/08/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22391** BUILDING ID: **2440**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Budlong School** REVIEW DATE: **3/28/2016**  
ADDRESS: **2701 W Foster Avenue** IDPH LICENSE NO: **100-07210**

---

HOMOGENEOUS AREA: **44**  
MATERIAL DESCRIPTION: **1' x 1' White Groove Ceiling Tile**  
MATERIAL LOCATION: **Throughout 1955 Building**  
MATERIAL QUANTITY: **5000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **03/28/2016**

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22391** BUIDLING ID: **2440**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Holvay**  
SCHOOL NAME: **Budlong School** INSPECTION DATE: **3/8/2016**  
ADDRESS: **2701 W Foster Avenue** IDPH LICENSE NO: **100-07210**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **45**  
MATERIAL DESCRIPTION: **12" x 12" Aqua Green VFT**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **Classrooms and Corridor - 1997 Annex**  
MATERIAL QUANTITY: **160** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature:

  
Michael Holvay  
Project Manager

Date: **03/08/2016**



# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22391** BUIDLING ID: **2440**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Budlong School** REVIEW DATE: **3/28/2016**  
ADDRESS: **2701 W Foster Avenue** IDPH LICENSE NO: **100-07210**

---

HOMOGENEOUS AREA: **45**  
MATERIAL DESCRIPTION: **12" x 12" Aqua Green VFT**  
MATERIAL LOCATION: **Classrooms and Corridor - 1997 Annex**  
MATERIAL QUANTITY: **160** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **03/28/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22391** BUIDLING ID: **2440**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Holvay**  
SCHOOL NAME: **Budlong School** INSPECTION DATE: **3/8/2016**  
ADDRESS: **2701 W Foster Avenue** IDPH LICENSE NO: **100-07210**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **45A**  
MATERIAL DESCRIPTION: **12" x 12" Aqua Green VFT Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Classrooms and Corridor - 1997 Annex**  
MATERIAL QUANTITY: **160** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:

  
Michael Holvay  
Project Manager

Date: **03/08/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22391** BUIDLING ID: **2440**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Budlong School** REVIEW DATE: **3/28/2016**  
ADDRESS: **2701 W Foster Avenue** IDPH LICENSE NO: **100-07210**

---

HOMOGENEOUS AREA: **45A**  
MATERIAL DESCRIPTION: **12" x 12" Aqua Green VFT Mastic**  
MATERIAL LOCATION: **Classrooms and Corridor - 1997 Annex**  
MATERIAL QUANTITY: **160** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **03/28/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22391** BUIDLING ID: **2440**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Holvay**  
SCHOOL NAME: **Budlong School** INSPECTION DATE: **3/8/2016**  
ADDRESS: **2701 W Foster Avenue** IDPH LICENSE NO: **100-07210**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **46**  
MATERIAL DESCRIPTION: **12" x 12" Beige VFT**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **Classrooms and Corridor - 1997 Annex**  
MATERIAL QUANTITY: **160** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature:

  
Michael Holvay  
Project Manager

Date: **03/08/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22391** BUIDLING ID: **2440**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Budlong School** REVIEW DATE: **3/28/2016**  
ADDRESS: **2701 W Foster Avenue** IDPH LICENSE NO: **100-07210**

---

HOMOGENEOUS AREA: **46**  
MATERIAL DESCRIPTION: **12" x 12" Beige VFT**  
MATERIAL LOCATION: **Classrooms and Corridor - 1997 Annex**  
MATERIAL QUANTITY: **160** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **03/28/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22391** BUIDLING ID: **2440**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Holvay**  
SCHOOL NAME: **Budlong School** INSPECTION DATE: **3/8/2016**  
ADDRESS: **2701 W Foster Avenue** IDPH LICENSE NO: **100-07210**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **46A**  
MATERIAL DESCRIPTION: **12" x 12" Beige VFT Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Classrooms and Corridor - 1997 Annex**  
MATERIAL QUANTITY: **160** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:

  
Michael Holvay  
Project Manager

Date: **03/08/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22391** BUIDLING ID: **2440**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Budlong School** REVIEW DATE: **3/28/2016**  
ADDRESS: **2701 W Foster Avenue** IDPH LICENSE NO: **100-07210**

---

HOMOGENEOUS AREA: **46A**  
MATERIAL DESCRIPTION: **12" x 12" Beige VFT Mastic**  
MATERIAL LOCATION: **Classrooms and Corridor - 1997 Annex**  
MATERIAL QUANTITY: **160** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **03/28/2016**

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22391** BUIDLING ID: **2440**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Holvay**  
SCHOOL NAME: **Budlong School** INSPECTION DATE: **3/8/2016**  
ADDRESS: **2701 W Foster Avenue** IDPH LICENSE NO: **100-07210**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **47**  
MATERIAL DESCRIPTION: **12" x 12" Blue VFT**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **Classroom and Corridor - 1997 Annex**  
MATERIAL QUANTITY: **160** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature:

  
Michael Holvay  
Project Manager

Date: **03/08/2016**



# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22391** BUILDING ID: **2440**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Budlong School** REVIEW DATE: **3/28/2016**  
ADDRESS: **2701 W Foster Avenue** IDPH LICENSE NO: **100-07210**

---

HOMOGENEOUS AREA: **47**  
MATERIAL DESCRIPTION: **12" x 12" Blue VFT**  
MATERIAL LOCATION: **Classroom and Corridor - 1997 Annex**  
MATERIAL QUANTITY: **160** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **03/28/2016**

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22391** BUIDLING ID: **2440**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Holvay**  
SCHOOL NAME: **Budlong School** INSPECTION DATE: **3/8/2016**  
ADDRESS: **2701 W Foster Avenue** IDPH LICENSE NO: **100-07210**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **47A**  
MATERIAL DESCRIPTION: **12" x 12" Blue VFT Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Classroom and Corridor - 1997 Annex**  
MATERIAL QUANTITY: **160** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:

  
Michael Holvay  
Project Manager

Date: **03/08/2016**

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22391** BUIDLING ID: **2440**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Budlong School** REVIEW DATE: **3/28/2016**  
ADDRESS: **2701 W Foster Avenue** IDPH LICENSE NO: **100-07210**

---

HOMOGENEOUS AREA: **47A**  
MATERIAL DESCRIPTION: **12" x 12" Blue VFT Mastic**  
MATERIAL LOCATION: **Classroom and Corridor - 1997 Annex**  
MATERIAL QUANTITY: **160** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **03/28/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22391** BUIDLING ID: **2440**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Holvay**  
SCHOOL NAME: **Budlong School** INSPECTION DATE: **3/8/2016**  
ADDRESS: **2701 W Foster Avenue** IDPH LICENSE NO: **100-07210**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **48**  
MATERIAL DESCRIPTION: **12" x 12" Off White VFT**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **Classrooms and Corridor - 1997 Annex**  
MATERIAL QUANTITY: **160** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature:

  
Michael Holvay  
Project Manager

Date: **03/08/2016**

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22391** BUIDLING ID: **2440**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Budlong School** REVIEW DATE: **3/28/2016**  
ADDRESS: **2701 W Foster Avenue** IDPH LICENSE NO: **100-07210**

---

HOMOGENEOUS AREA: **48**  
MATERIAL DESCRIPTION: **12" x 12" Off White VFT**  
MATERIAL LOCATION: **Classrooms and Corridor - 1997 Annex**  
MATERIAL QUANTITY: **160** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **03/28/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22391** BUIDLING ID: **2440**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Holvay**  
SCHOOL NAME: **Budlong School** INSPECTION DATE: **3/8/2016**  
ADDRESS: **2701 W Foster Avenue** IDPH LICENSE NO: **100-07210**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **48A**  
MATERIAL DESCRIPTION: **12" x 12" Off White VFT Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Classrooms and Corridor - 1997 Annex**  
MATERIAL QUANTITY: **160** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:

  
Michael Holvay  
Project Manager

Date: **03/08/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22391** BUILDING ID: **2440**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Budlong School** REVIEW DATE: **3/28/2016**  
ADDRESS: **2701 W Foster Avenue** IDPH LICENSE NO: **100-07210**

---

HOMOGENEOUS AREA: **48A**  
MATERIAL DESCRIPTION: **12" x 12" Off White VFT Mastic**  
MATERIAL LOCATION: **Classrooms and Corridor - 1997 Annex**  
MATERIAL QUANTITY: **160** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **03/28/2016**

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22391** BUIDLING ID: **2440**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Holvay**  
SCHOOL NAME: **Budlong School** INSPECTION DATE: **3/8/2016**  
ADDRESS: **2701 W Foster Avenue** IDPH LICENSE NO: **100-07210**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **A**  
MATERIAL DESCRIPTION: **MJP E/F/V on Fiberglass Pipe Insulation**  
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Boiler, Tank & Fan Rooms, Room Facing 119, Basement Boys & Girls Toilets - 1907**  
MATERIAL QUANTITY: **430** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature:

  
Michael Holvay  
Project Manager

Date: **03/08/2016**



# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22391** BUIDLING ID: **2440**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Budlong School** REVIEW DATE: **3/28/2016**  
ADDRESS: **2701 W Foster Avenue** IDPH LICENSE NO: **100-07210**

---

HOMOGENEOUS AREA: **A**  
MATERIAL DESCRIPTION: **MJP E/F/V on Fiberglass Pipe Insulation**  
MATERIAL LOCATION: **Boiler, Tank & Fan Rooms, Room Facing 119, Basement Boys & Girls Toilets - 1907**  
MATERIAL QUANTITY: **430** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **03/28/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22391** BUIDLING ID: **2440**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Holvay**  
SCHOOL NAME: **Budlong School** INSPECTION DATE: **3/8/2016**  
ADDRESS: **2701 W Foster Avenue** IDPH LICENSE NO: **100-07210**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **B**  
MATERIAL DESCRIPTION: **Cardboard Pipe Insulation**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Throughout - 1907 (See Hatching Maps)**  
MATERIAL QUANTITY: **1148** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: DAMAGE UNITS: **LF**  
COMMENTS:

Inspector's Signature:

  
Michael Holvay  
Project Manager

Date: **03/08/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22391** BUILDING ID: **2440**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Budlong School** REVIEW DATE: **3/28/2016**  
ADDRESS: **2701 W Foster Avenue** IDPH LICENSE NO: **100-07210**

---

HOMOGENEOUS AREA: **B**  
MATERIAL DESCRIPTION: **Cardboard Pipe Insulation**  
MATERIAL LOCATION: **Throughout - 1907 (See Hatching Maps)**  
MATERIAL QUANTITY: **1148** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **03/28/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22391** BUIDLING ID: **2440**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Holvay**  
SCHOOL NAME: **Budlong School** INSPECTION DATE: **3/8/2016**  
ADDRESS: **2701 W Foster Avenue** IDPH LICENSE NO: **100-07210**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **C**  
MATERIAL DESCRIPTION: **MJP E/F/V on Cardboard Pipe Insulation**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Throughout - 1907 (See Hatching Maps)**  
MATERIAL QUANTITY: **91** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: DAMAGE UNITS: **LF**  
COMMENTS:

Inspector's Signature:

  
Michael Holvay  
Project Manager

Date: **03/08/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22391** BUIDLING ID: **2440**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Budlong School** REVIEW DATE: **3/28/2016**  
ADDRESS: **2701 W Foster Avenue** IDPH LICENSE NO: **100-07210**

---

HOMOGENEOUS AREA: **C**  
MATERIAL DESCRIPTION: **MJP E/F/V on Cardboard Pipe Insulation**  
MATERIAL LOCATION: **Throughout - 1907 (See Hatching Maps)**  
MATERIAL QUANTITY: **91** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **03/28/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22391** BUIDLING ID: **2440**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Holvay**  
SCHOOL NAME: **Budlong School** INSPECTION DATE: **3/8/2016**  
ADDRESS: **2701 W Foster Avenue** IDPH LICENSE NO: **100-07210**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **D**  
MATERIAL DESCRIPTION: **Aircell Pipe Insulation**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Tank Room, Rm 115B, 117, Hall to 115, Teachers Lounge Rm, 118C, Bsmt Boys & Girls Toilet - 1907**

MATERIAL QUANTITY: **492** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature:

  
Michael Holvay  
Project Manager

Date: **03/08/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22391** BUIDLING ID: **2440**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Budlong School** REVIEW DATE: **3/28/2016**  
ADDRESS: **2701 W Foster Avenue** IDPH LICENSE NO: **100-07210**

---

HOMOGENEOUS AREA: **D**  
MATERIAL DESCRIPTION: **Aircell Pipe Insulation**  
MATERIAL LOCATION: **Tank Room, Rm 115B, 117, Hall to 115, Teachers Lounge Rm, 118C, Bsmt Boys & Girls Toilet - 1907**  
MATERIAL QUANTITY: **492** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **03/28/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22391** BUIDLING ID: **2440**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Holvay**  
SCHOOL NAME: **Budlong School** INSPECTION DATE: **3/8/2016**  
ADDRESS: **2701 W Foster Avenue** IDPH LICENSE NO: **100-07210**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **E**  
MATERIAL DESCRIPTION: **MJP E/F/V on Aircell Pipe Insulation**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with potential for significant damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Tank Room, Rm 115B, 117, Hall to 115, Teachers Lounge Rm, 118C, Bsmt Boys & Girls Toilet - 1907**

MATERIAL QUANTITY: **45** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature:

  
Michael Holvay  
Project Manager

Date: **03/08/2016**



# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22391** BUIDLING ID: **2440**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Budlong School** REVIEW DATE: **3/28/2016**  
ADDRESS: **2701 W Foster Avenue** IDPH LICENSE NO: **100-07210**

---

HOMOGENEOUS AREA: **E**  
MATERIAL DESCRIPTION: **MJP E/F/V on Aircell Pipe Insulation**  
MATERIAL LOCATION: **Tank Room, Rm 115B, 117, Hall to 115, Teachers Lounge Rm, 118C, Bsmt Boys & Girls Toilet - 1907**  
MATERIAL QUANTITY: **45** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **03/28/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22391** BUIDLING ID: **2440**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Holvay**  
SCHOOL NAME: **Budlong School** INSPECTION DATE: **3/8/2016**  
ADDRESS: **2701 W Foster Avenue** IDPH LICENSE NO: **100-07210**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **G**  
MATERIAL DESCRIPTION: **Cardboard Pipe Insulation**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Chase Behind Teachers Toilet, Behind Walls & Above Drop Ceilings - 1955**  
MATERIAL QUANTITY: **80** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: DAMAGE UNITS: **LF**  
COMMENTS:

Inspector's Signature:

  
Michael Holvay  
Project Manager

Date: **03/08/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22391** BUIDLING ID: **2440**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Budlong School** REVIEW DATE: **3/28/2016**  
ADDRESS: **2701 W Foster Avenue** IDPH LICENSE NO: **100-07210**

---

HOMOGENEOUS AREA: **G**  
MATERIAL DESCRIPTION: **Cardboard Pipe Insulation**  
MATERIAL LOCATION: **Chase Behind Teachers Toilet, Behind Walls & Above Drop Ceilings - 1955**  
MATERIAL QUANTITY: **80** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **03/28/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22391** BUIDLING ID: **2440**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Holvay**  
SCHOOL NAME: **Budlong School** INSPECTION DATE: **3/8/2016**  
ADDRESS: **2701 W Foster Avenue** IDPH LICENSE NO: **100-07210**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **H**  
MATERIAL DESCRIPTION: **MJP E/F/V on Cardboard Pipe Insulation**  
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Chase Behind Teachers Toilet, Behind Walls & Above Drop Ceilings - 1955**  
MATERIAL QUANTITY: **70** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature:

  
Michael Holvay  
Project Manager

Date: **03/08/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22391** BUIDLING ID: **2440**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Budlong School** REVIEW DATE: **3/28/2016**  
ADDRESS: **2701 W Foster Avenue** IDPH LICENSE NO: **100-07210**

---

HOMOGENEOUS AREA: **H**  
MATERIAL DESCRIPTION: **MJP E/F/V on Cardboard Pipe Insulation**  
MATERIAL LOCATION: **Chase Behind Teachers Toilet, Behind Walls & Above Drop Ceilings - 1955**  
MATERIAL QUANTITY: **70** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **03/28/2016**

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22391** BUIDLING ID: **2440**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Holvay**  
SCHOOL NAME: **Budlong School** INSPECTION DATE: **3/8/2016**  
ADDRESS: **2701 W Foster Avenue** IDPH LICENSE NO: **100-07210**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **I**  
MATERIAL DESCRIPTION: **Aircell Pipe Insulation**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Chase Behind Teachers Toilet, Behind Walls & Above Drop Ceilings - 1955**  
MATERIAL QUANTITY: **30** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature:

  
Michael Holvay  
Project Manager

Date: **03/08/2016**

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22391** BUIDLING ID: **2440**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Budlong School** REVIEW DATE: **3/28/2016**  
ADDRESS: **2701 W Foster Avenue** IDPH LICENSE NO: **100-07210**

---

HOMOGENEOUS AREA: **I**  
MATERIAL DESCRIPTION: **Aircell Pipe Insulation**  
MATERIAL LOCATION: **Chase Behind Teachers Toilet, Behind Walls & Above Drop Ceilings - 1955**  
MATERIAL QUANTITY: **30** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **03/28/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22391** BUIDLING ID: **2440**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Holvay**  
SCHOOL NAME: **Budlong School** INSPECTION DATE: **3/8/2016**  
ADDRESS: **2701 W Foster Avenue** IDPH LICENSE NO: **100-07210**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **J**  
MATERIAL DESCRIPTION: **MJP E/F/V on Aircell Pipe Insulation**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Chase Behind Teachers Toilet, Behind Walls & Above Drop Ceilings - 1955**  
MATERIAL QUANTITY: **80** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature:

  
Michael Holvay  
Project Manager

Date: **03/08/2016**



# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22391** BUIDLING ID: **2440**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Budlong School** REVIEW DATE: **3/28/2016**  
ADDRESS: **2701 W Foster Avenue** IDPH LICENSE NO: **100-07210**

---

HOMOGENEOUS AREA: **J**  
MATERIAL DESCRIPTION: **MJP E/F/V on Aircell Pipe Insulation**  
MATERIAL LOCATION: **Chase Behind Teachers Toilet, Behind Walls & Above Drop Ceilings - 1955**  
MATERIAL QUANTITY: **80** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **03/28/2016**

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22391** BUIDLING ID: **2440**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Holvay**  
SCHOOL NAME: **Budlong School** INSPECTION DATE: **3/8/2016**  
ADDRESS: **2701 W Foster Avenue** IDPH LICENSE NO: **100-07210**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **K**  
MATERIAL DESCRIPTION: **White Spray Applied Fireproofing**  
HISTORICAL AHERA DAMAGE CATEGORY **6**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Gym - 1997 Annex**  
MATERIAL QUANTITY: **5000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:

  
Michael Holvay  
Project Manager

Date: **03/08/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22391** BUILDING ID: **2440**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Budlong School** REVIEW DATE: **3/28/2016**  
ADDRESS: **2701 W Foster Avenue** IDPH LICENSE NO: **100-07210**

---

HOMOGENEOUS AREA: **K**  
MATERIAL DESCRIPTION: **White Spray Applied Fireproofing**  
MATERIAL LOCATION: **Gym - 1997 Annex**  
MATERIAL QUANTITY: **5000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **03/28/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22391** BUIDLING ID: **2440**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Holvay**  
SCHOOL NAME: **Budlong School** INSPECTION DATE: **3/8/2016**  
ADDRESS: **2701 W Foster Avenue** IDPH LICENSE NO: **100-07210**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **L**  
MATERIAL DESCRIPTION: **Drywall**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Corridors Above CT, Bathroom Ceilings, Boiler & Electrical Room Ceilings - 1997 Annex**

MATERIAL QUANTITY: **0** MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:

  
Michael Holvay  
Project Manager

Date: **03/08/2016**

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22391** BUIDLING ID: **2440**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Budlong School** REVIEW DATE: **3/28/2016**  
ADDRESS: **2701 W Foster Avenue** IDPH LICENSE NO: **100-07210**

---

HOMOGENEOUS AREA: **L**  
MATERIAL DESCRIPTION: **Drywall**  
MATERIAL LOCATION: **Corridors Above CT, Bathroom Ceilings, Boiler & Electrical Room Ceilings - 1997 Annex**  
MATERIAL QUANTITY: **0** MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **03/28/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22391** BUIDLING ID: **2440**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Holvay**  
SCHOOL NAME: **Budlong School** INSPECTION DATE: **3/8/2016**  
ADDRESS: **2701 W Foster Avenue** IDPH LICENSE NO: **100-07210**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **M**  
MATERIAL DESCRIPTION: **Drywall Tape**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Corridors Above CT, Bathroom Ceilings, Boiler & Electrical Room Ceilings - 1997 Annex**

MATERIAL QUANTITY: **0** MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:

  
Michael Holvay  
Project Manager

Date: **03/08/2016**

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22391** BUIDLING ID: **2440**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Budlong School** REVIEW DATE: **3/28/2016**  
ADDRESS: **2701 W Foster Avenue** IDPH LICENSE NO: **100-07210**

---

HOMOGENEOUS AREA: **M**  
MATERIAL DESCRIPTION: **Drywall Tape**  
MATERIAL LOCATION: **Corridors Above CT, Bathroom Ceilings, Boiler & Electrical Room Ceilings - 1997 Annex**  
MATERIAL QUANTITY: **0** MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **03/28/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22391** BUIDLING ID: **2440**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Holvay**  
SCHOOL NAME: **Budlong School** INSPECTION DATE: **3/8/2016**  
ADDRESS: **2701 W Foster Avenue** IDPH LICENSE NO: **100-07210**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **N**  
MATERIAL DESCRIPTION: **Drywall Joint Compound**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Corridors Above CT, Bathroom Ceilings, Boiler & Electrical Room Ceilings - 1997 Annex**

MATERIAL QUANTITY: **0** MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:

  
Michael Holvay  
Project Manager

Date: **03/08/2016**



# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22391** BUILDING ID: **2440**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Budlong School** REVIEW DATE: **3/28/2016**  
ADDRESS: **2701 W Foster Avenue** IDPH LICENSE NO: **100-07210**

---

HOMOGENEOUS AREA: **N**  
MATERIAL DESCRIPTION: **Drywall Joint Compound**  
MATERIAL LOCATION: **Corridors Above CT, Bathroom Ceilings, Boiler & Electrical Room Ceilings - 1997 Annex**  
MATERIAL QUANTITY: **0** MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **03/28/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22391** BUIDLING ID: **2440**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Holvay**  
SCHOOL NAME: **Budlong School** INSPECTION DATE: **3/8/2016**  
ADDRESS: **2701 W Foster Avenue** IDPH LICENSE NO: **100-07210**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **0**  
MATERIAL DESCRIPTION: **Drywall**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Men & Womens Bathrooms, Mechanical Room - 1998 Fieldhouse**

MATERIAL QUANTITY: **0** MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:

  
Michael Holvay  
Project Manager

Date: **03/08/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22391** BUILDING ID: **2440**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Budlong School** REVIEW DATE: **3/28/2016**  
ADDRESS: **2701 W Foster Avenue** IDPH LICENSE NO: **100-07210**

---

HOMOGENEOUS AREA: **0**  
MATERIAL DESCRIPTION: **Drywall**  
MATERIAL LOCATION: **Men & Womens Bathrooms, Mechanical Room - 1998 Fieldhouse**  
MATERIAL QUANTITY: **0** MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **03/28/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22391** BUIDLING ID: **2440**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Holvay**  
SCHOOL NAME: **Budlong School** INSPECTION DATE: **3/8/2016**  
ADDRESS: **2701 W Foster Avenue** IDPH LICENSE NO: **100-07210**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **P**  
MATERIAL DESCRIPTION: **Drywall Joint Compound**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Mens & Womens Bathrooms, Mechanical Room - 1998 Fieldhouse**

MATERIAL QUANTITY: **0** MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:

  
Michael Holvay  
Project Manager

Date: **03/08/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22391** BUIDLING ID: **2440**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Budlong School** REVIEW DATE: **3/28/2016**  
ADDRESS: **2701 W Foster Avenue** IDPH LICENSE NO: **100-07210**

---

HOMOGENEOUS AREA: **P**  
MATERIAL DESCRIPTION: **Drywall Joint Compound**  
MATERIAL LOCATION: **Mens & Womens Bathrooms, Mechanical Room - 1998 Fieldhouse**  
MATERIAL QUANTITY: **0** MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **03/28/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22391** BUIDLING ID: **2440**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Holvay**  
SCHOOL NAME: **Budlong School** INSPECTION DATE: **3/8/2016**  
ADDRESS: **2701 W Foster Avenue** IDPH LICENSE NO: **100-07210**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **Q**  
MATERIAL DESCRIPTION: **Vinyl Covered Drywall**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout 2000 Mobile - Removed from school property**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:

  
Michael Holvay  
Project Manager

Date: **03/08/2016**

---

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22391** BUIDLING ID: **2440**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Budlong School** REVIEW DATE: **3/28/2016**  
ADDRESS: **2701 W Foster Avenue** IDPH LICENSE NO: **100-07210**

---

HOMOGENEOUS AREA: **Q**  
MATERIAL DESCRIPTION: **Vinyl Covered Drywall**  
MATERIAL LOCATION: **Throughout 2000 Mobile - Removed from school property**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **03/28/2016**

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22391** BUIDLING ID: **2440**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Holvay**  
SCHOOL NAME: **Budlong School** INSPECTION DATE: **3/8/2016**  
ADDRESS: **2701 W Foster Avenue** IDPH LICENSE NO: **100-07210**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **R**  
MATERIAL DESCRIPTION: **Textured Covered Drywall**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout 2000 Mobile - Removed from school property**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:

  
Michael Holvay  
Project Manager

Date: **03/08/2016**



# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22391** BUILDING ID: **2440**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Budlong School** REVIEW DATE: **3/28/2016**  
ADDRESS: **2701 W Foster Avenue** IDPH LICENSE NO: **100-07210**

---

HOMOGENEOUS AREA: **R**

MATERIAL DESCRIPTION: **Textured Covered Drywall**

MATERIAL LOCATION: **Throughout 2000 Mobile - Removed from school property**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **03/28/2016**

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22391** BUILDING ID: **2440**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Holvay**  
SCHOOL NAME: **Budlong School** INSPECTION DATE: **3/8/2016**  
ADDRESS: **2701 W Foster Avenue** IDPH LICENSE NO: **100-07210**

---

### INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **49**  
MATERIAL DESCRIPTION: **Tank Insulation**  
MATERIAL LOCATION: **Tank Room (1907 Bldg)**  
MATERIAL QUANTITY: **20** MATERIAL UNITS: **SF**  
MATERIAL CATEGORY: **TSI** FRIABLE: **Yes**  
ASBESTOS TYPE: **Assumed**  
DISTURBANCE POTENTIAL: **LOW** CONDITION:  
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
ACCESSIBILITY: **Within Reach** DAMAGE REASON:  
DAMAGE QUANTITY: **0** DAMAGE REASON:  
DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature:

  
Michael Holvay  
Project Manager

Date: 03/08/2016

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22391** BUILDING ID: **2440**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Budlong School** REVIEW DATE: **3/28/2016**  
ADDRESS: **2701 W Foster Avenue** IDPH LICENSE NO: **100-07210**

HOMOGENEOUS AREA: **49**  
MATERIAL DESCRIPTION: **Tank Insulation**  
MATERIAL LOCATION: **Tank Room (1907 Bldg)**  
MATERIAL QUANTITY: **20** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_



Date: **03/28/2016**

# Chicago Public Schools

GSG Consultants, Inc.

## 2016 AHERA REINSPECTION

### Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **22391**    BUIDLING ID: **2440**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Michael Holvay**  
SCHOOL NAME: **Budlong School**    INSPECTION DATE: **3/8/2016**  
ADDRESS: **2701 W Foster Avenue**    IDPH LICENSE NO: **100-07210**

---

### INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **53**  
MATERIAL DESCRIPTION: **Drywall System**  
MATERIAL LOCATION: **All Restrooms (1907) Bldg**  
MATERIAL QUANTITY: **4000**    MATERIAL UNITS: **SF**  
MATERIAL CATEGORY: **MISC**    FRIABLE: **Yes**  
ASBESTOS TYPE: **Assumed**  
DISTURBANCE POTENTIAL: **MODERATE**    CONDITION:  
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
ACCESSIBILITY: **Within Reach**    DAMAGE REASON:  
DAMAGE QUANTITY: **0**    DAMAGE REASON:  
DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_

  
Michael Holvay  
Project Manager

Date: 03/08/2016

# Chicago Public Schools

GSG Consultants, Inc.  
2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22391** BUILDING ID: **2440**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Budlong School** REVIEW DATE: **3/28/2016**  
ADDRESS: **2701 W Foster Avenue** IDPH LICENSE NO: **100-07210**

HOMOGENEOUS AREA: **53**  
MATERIAL DESCRIPTION: **Drywall System**  
MATERIAL LOCATION: **All Restrooms (1907) Bldg**  
MATERIAL QUANTITY: **4000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_



Date: **03/28/2016**

# Chicago Public Schools

GSG Consultants, Inc.

## 2016 AHERA REINSPECTION

### Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22391** BUIDLING ID: **2440**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Holvay**  
SCHOOL NAME: **Budlong School** INSPECTION DATE: **3/8/2016**  
ADDRESS: **2701 W Foster Avenue** IDPH LICENSE NO: **100-07210**

---

### INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **51**  
MATERIAL DESCRIPTION: **Textured Paint on Drywall ceiling**  
MATERIAL LOCATION: **Basement- Girls and boys Toilet  
(1907) Bldg**  
MATERIAL QUANTITY: **700** MATERIAL UNITS: **SF**  
MATERIAL CATEGORY: **MISC** FRIABLE: **No**  
ASBESTOS TYPE: **Assumed**  
DISTURBANCE POTENTIAL: **LOW** CONDITION:  
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
ACCESSIBILITY: **Within Reach** DAMAGE REASON:  
DAMAGE QUANTITY: **0** DAMAGE REASON:  
DAMAGE REASON:  
DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature:

  
Michael Holvay  
Project Manager

Date: 03/08/2016

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22391** BUILDING ID: **2440**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Budlong School** REVIEW DATE: **3/28/2016**  
ADDRESS: **2701 W Foster Avenue** IDPH LICENSE NO: **100-07210**

HOMOGENEOUS AREA: **51**

MATERIAL DESCRIPTION: **Textured Paint on Drywall ceiling**

MATERIAL LOCATION: **Basement- Girls and boys Toilet  
(1907) Bldg**

MATERIAL QUANTITY: **700** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:  Date: **03/28/2016**

# Chicago Public Schools

GSG Consultants, Inc.

## 2016 AHERA REINSPECTION

### Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22391** BUILDING ID: **2440**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Holvay**  
SCHOOL NAME: **Budlong School** INSPECTION DATE: **3/8/2016**  
ADDRESS: **2701 W Foster Avenue** IDPH LICENSE NO: **100-07210**

---

### INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **50**  
MATERIAL DESCRIPTION: **2x4 White Smooth Ceiling Tile**  
MATERIAL LOCATION: **Old Girls Playroom (1907 Bldg)**  
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**  
MATERIAL CATEGORY: **MISC** FRIABLE: **Yes**  
ASBESTOS TYPE: **Assumed**  
DISTURBANCE POTENTIAL: **MODERATE** CONDITION:  
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
ACCESSIBILITY: **Within Reach** DAMAGE REASON:  
DAMAGE QUANTITY: **0** DAMAGE REASON:  
DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature:

  
Michael Holvay  
Project Manager

Date: **03/08/2016**



# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22391** BUILDING ID: **2440**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Budlong School** REVIEW DATE: **3/28/2016**  
ADDRESS: **2701 W Foster Avenue** IDPH LICENSE NO: **100-07210**

HOMOGENEOUS AREA: **50**  
MATERIAL DESCRIPTION: **2x4 White Smooth Ceiling Tile**  
MATERIAL LOCATION: **Old Girls Playroom (1907 Bldg)**  
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_



Date: **03/28/2016**

# Chicago Public Schools

GSG Consultants, Inc.

## 2016 AHERA REINSPECTION

### Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22391** BUILDING ID: **2440**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Holvay**  
SCHOOL NAME: **Budlong School** INSPECTION DATE: **3/8/2016**  
ADDRESS: **2701 W Foster Avenue** IDPH LICENSE NO: **100-07210**

---

### INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **52**  
MATERIAL DESCRIPTION: **Carpet Mastic**  
MATERIAL LOCATION: **Room 114 (1955 Bldg)**  
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**  
MATERIAL CATEGORY: **MISC** FRIABLE: **No**  
ASBESTOS TYPE: **Assumed**  
DISTURBANCE POTENTIAL: **LOW** CONDITION:  
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
ACCESSIBILITY: **Within Reach** DAMAGE REASON:  
DAMAGE QUANTITY: **0** DAMAGE REASON:  
DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature:

  
Michael Holvay  
Project Manager

Date: **03/08/2016**

# Chicago Public Schools

## GSG Consultants, Inc. 2016 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22391** BUILDING ID: **2440**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Budlong School** REVIEW DATE: **3/28/2016**  
ADDRESS: **2701 W Foster Avenue** IDPH LICENSE NO: **100-07210**

HOMOGENEOUS AREA: **52**  
MATERIAL DESCRIPTION: **Carpet Mastic**  
MATERIAL LOCATION: **Room 114 (1955 Bldg)**  
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_



Date: **03/28/2016**

# APPENDIX B

## Inspector and Management Planner Licenses

---



525-535 West Jefferson Street • Springfield, Illinois 62761-0001 • www.dph.illinois.gov

4/18/2016

**MICHAEL HOLVAY**  
855 WEST ADAMS ST., Suite 200  
CHICAGO, IL 60607

ASBESTOS PROFESSIONAL LICENSE ID NUMBER: 07210

Enclosed is your Asbestos Professional License. Please note the expiration date on the card and in the image depicted below.

**COPY OF THE ASBESTOS PROFESSIONAL LICENSE**

Front of License

Back of License

 <p><b>ASBESTOS PROFESSIONAL LICENSE</b></p>			<p><b>ENDORSEMENTS</b></p> <p>INSPECTOR</p> <p>PROJECT MANAGER</p> <p>AIR SAMPLING PROFESSIONAL</p>	<p><b>TC EXPIRES</b></p> <p>9/18/2016</p> <p>1/20/2017</p>
<p><b>ID NUMBER</b> 100 - 07210</p>	<p><b>ISSUED</b> 4/18/2016</p>	<p><b>EXPIRES</b> 05/13/2017</p>	<p><b>Alteration of this license shall result in legal action</b> This license issued under authority of the State of Illinois Department of Public Health This license is valid only when accompanied by a valid training course certificate.</p>	
<p><b>MICHAEL HOLVAY</b> 855 WEST ADAMS ST., Suite 20 CHICAGO, IL 60607</p> <p>Environmental Health</p>				

If you have any questions or need further assistance, contact the Asbestos Program at (217)782-3517 or fax (217)785-5897.

Our WEB address is: [dph.illinois.gov/topics-services/environmental-health-protection/asbestos](http://dph.illinois.gov/topics-services/environmental-health-protection/asbestos)  
EMAIL Address: [dph.asbestos@illinois.gov](mailto:dph.asbestos@illinois.gov)

**PROTECTING HEALTH, IMPROVING LIVES**  
*Nationally Accredited by PHAB*

2015



**OCCUPATIONAL TRAINING & SUPPLY, INC.**

7233 S. Adams Street ♦ Willowbrook, IL 60527 ♦ (630) 655-3900

# Asbestos Building Inspector Refresher

Occupational Training & Supply, Inc. certifies that

**Michael Holway**

has successfully completed the Asbestos Building Inspector Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency Response Act (AHERA) and TSCA Title II.

Course Date: 9/18/2015

Exam Date: 9/18/2015

Expiration Date: 9/18/2016

Certificate Number: BIR1509183493

  
\_\_\_\_\_  
Kathy DeSalvo, Director



525-535 West Jefferson Street • Springfield, Illinois 62761-0001 • www.idph.illinois.gov

4/18/2016

ARTURO SAENZ  
855 W ADAMS ST SUITE 200  
CHICAGO, IL 60607

ASBESTOS PROFESSIONAL LICENSE ID NUMBER: 04019

Enclosed is your Asbestos Professional License. Please note the expiration date on the card and in the image depicted below.

COPY OF THE ASBESTOS PROFESSIONAL LICENSE

Front of License

Back of License

 <p><b>ASBESTOS PROFESSIONAL LICENSE</b></p>			<p><b>ENDORSEMENTS</b></p> <p>INSPECTOR</p> <p>MANAGEMENT PLANNER</p> <p>AIR SAMPLING PROFESSIONAL</p> <p><b>Alteration of this license shall result in legal action</b> This license issued under authority of the State of Illinois Department of Public Health This license is valid only when accompanied by a valid training course certificate.</p>	<p><b>TC EXPIRES</b></p> <p>1/19/2017</p> <p>1/27/2017</p>
<p>ID NUMBER</p> <p>100 - 04019</p> <p><b>ARTURO SAENZ</b> 855 W ADAMS ST SUITE 200 CHICAGO, IL 60607 Environmental Health</p>	<p><b>ISSUED</b></p> <p>4/18/2016</p>	<p><b>EXPIRES</b></p> <p>05/13/2017</p> 		

If you have any questions or need further assistance, contact the Asbestos Program at (217)782-3517 or fax (217)785-5897.

Our WEB address is: [dph.illinois.gov/topics-services/environmental-health-protection/asbestos](http://dph.illinois.gov/topics-services/environmental-health-protection/asbestos)  
EMAIL Address: [dph.asbestos@illinois.gov](mailto:dph.asbestos@illinois.gov)

PROTECTING HEALTH, IMPROVING LIVES  
*Nationally Accredited by PHAB*

2016



**OCCUPATIONAL TRAINING & SUPPLY, INC.**

7233 S. Adams Street ♦ Willowbrook, IL 60527 ♦ (630) 655-3900

# Asbestos Management Planner Refresher

Occupational Training & Supply, Inc. certifies that

**Arturo Saenz**

has successfully completed the Asbestos Management Planner Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 1/27/2016

Exam Date: 1/27/2016

Expiration Date: 1/27/2017

Certificate Number: MPR1601270319

---

Kathy DeSalvo, Director



2016



**OCCUPATIONAL TRAINING & SUPPLY, INC.**

7233 S. Adams Street ♦ Willowbrook, IL 60527 ♦ (630) 655-3900

# Asbestos Management Planner Refresher

Occupational Training & Supply, Inc. certifies that

**Jigar Shah**

has successfully completed the Asbestos Management Planner Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 1/27/2016

Exam Date: 1/27/2016

Expiration Date: 1/27/2017

Certificate Number: MPR1601270320

---

Kathy DeSalvo, Director

# APPENDIX C

## Laboratory Accreditations

---

# APPENDIX D

## Laboratory Results

---

# APPENDIX E

## Chain of Custody Forms

---

## Three-Year Reinspection Key to Terms

	<b>CODE</b>	<b>KEY</b>
<b>MATERIAL</b>		
	ACBM	Asbestos Containing Building Materials
<b>MATERIAL CATEGORY</b>		
	MISC	Miscellaneous
	SURF	Surfacing
	TSI	Thermal System Insulation
<b>MATERIAL UNITS</b>		
	LF	Linear Feet
	SF	Square Feet
	CF	Cubic Feet
<b>DAMAGE TYPE</b>		
	Loc	Localized
	Dist	Distributed