

**ILLINOIS DEPARTMENT OF PUBLIC HEALTH
AHERA THREE YEAR REINSPECTION
ASBESTOS ABATEMENT PROGRAM
SCHOOL INFORMATION FORM**

SECTION I

NAME OF SCHOOL DISTRICT: CHICAGO SCHOOL DIST 299
SCHOOL ID NUMBER: 14-016-2990-2104
SCHOOL NAME: Burley School
ADDRESS OF SCHOOL: 1630 W. Barry Avenue
CITY: Chicago, IL, 60657

DATE LAST THREE YEAR REINSPECTION WAS COMPLETED **3/7/2013**

If the address on this form is different than the address of the building, submit a written explanation.

SECTION II *(Please type or print)*

PLEASE COMPLETE THE FOLLOWING FOR YOUR THREE YEAR REINSPECTION:

DATE REINSPECTION COMPLETED: 6/16/2016 ENROLLMENT 527
IDPH INSPECTOR LICENSE NUMBER: 100-05183
IDPH LICENSED INSPECTOR NAME (Please Print): Delores Fitzpatrick
IDPH MP LICENSE NUMBER: 100-01786
IDPH LICENSED MANAGEMENT PLANNER NAME (Please Print): Guillermo Garcia

DESIGNATED PERSON (Please Print): Robert Christlieb PHONE: (773) 553-3197



6/16/2016

Signature of Designated Person

Date

SECTION III

PLEASE COMPLETE THE FOLLOWING INFORMATION FOR ANY CHANGES WITHIN THE SCHOOL DISTRICT.

School building has been sold. Date of Sale: _____

School has been closed. Date closed: _____

School building has been demolished. Date: _____

School building is asbestos free since last reinspection: _____

Please explain in writing why the school building is now asbestos free and include the supporting documentation.

If a new school building has been added to the district, submit either an exclusionary statement or a management plan and inspection report. Include the complete name, address and city of school building.

Explain in writing if the address of the building is different than the address on this form:

THREE-YEAR REINSPECTION

CHICAGO SCHOOL DIST 299

Burley School

1630 W. Barry Avenue
Chicago, IL, 60657

Unit: 22421
Building ID: 2470

IDPH ID Number: 14-016-2990-2104

REPORT DATE:

Thursday, June 16, 2016

Prepared for:

Chicago Public Schools
125 S. Clark Street
Chicago, IL 60603

Prepared by:

GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone (312) 733-6262

Fax (312) 733-5612

**DO NOT REMOVE FROM SCHOOL
REQUIRED BY FEDERAL LAW**

March 10, 2016

Mr. R. Kent Cook
Asbestos Program
Illinois Department of Public Health
525 West Jefferson Street
Springfield, Illinois 62761

Re: Chicago Public Schools - 2016 Three-Year Reinspections

Dear Mr. Cook:

GSG Consultants, Inc., Managing Environmental Consultant (MEC), conducted the Three-Year Reinspections and performed management plan updates for the Chicago Public Schools (CPS) facilities in Region 1,2,6 Elementary Schools. Please update your records with the following information.

School District: 299 Unit: 22421 Region: 02 IDPH ID: 14-016-2990-2104

School: Burley School Building ID: 2470

Address: 1630 W. Barry Avenue

Chicago, IL, 60657

Building Contact: Redmond, Kevin

Contact Phone: 773-332-9639

Current Building Owners: Chicago Public Schools

Review Date: 05/18/2016

Inspector: Delores Fitzpatrick

Inspector IDPH License: 100-05183

Management Planner: Guillermo Garcia

Management Planner IDPH License: 100-01786

If you have any questions or comments, please contact us at (312) 733-6262

Sincerely,
GSG Consultants, Inc.



Guillermo Garcia
100-01786

Environmental Notification to Occupants

To: Faculty, Staff and Parents
From: Chicago Public Schools
Date: March 10, 2016

RE: Burley School, Unit 22421
1630 W. Barry Avenue
Chicago, IL, 60657

Dear Faculty, Staff and Parents,

This letter is to notify you that the 2016 asbestos three year re-inspection has been completed at Burley School , following the Federal Asbestos Hazard Emergency Response Act (AHERA), 40 CFR Part 763, Subpart E and is available for your review at the main office of the school.

Although asbestos-containing materials have been identified at Burley School, there is no reason to believe that any threat to the health of students or staff exists at this time. CPS will continue to carefully monitor the condition of asbestos-containing materials and if conditions warrant, all appropriate steps will be taken to maintain the health and safety of all building occupants.

If you have any questions regarding this matter or require additional information, please feel free to contact Robert Christlieb, the designated Local Education Authority's Designated Person at (773) 553-3197 .

Table of Contents

- I. School and Inspection Information
- II. Executive Summary
- III. Methodology
- IV. Abatement History
- V. Reassessments and Recommendations
- VI. Conclusions

Table I: Inspector's Reinspection Findings

Table II: Management Planner's Review

APPENDICES:

- Appendix A: Assessment Sheets, Drawings and Photos
- Appendix B: Inspector and Management Planner Licenses
- Appendix C: Laboratory Accreditations
- Appendix D: Laboratory Results
- Appendix E: Chain of Custody Forms

SCHOOL AND INSPECTION INFORMATION

1. School Information

School: Burley School
Address: 1630 W. Barry Avenue
IDPH ID: 14-016-2990-2104
Contact: Redmond, Kevin

Unit: 22421
Chicago, IL, 60657
Building ID: 2470
Phone: 773-332-9639

Region: 02

2. Description of Facility

Original Construction: 1896
Total Square Footage: 55812
Current Occupancy: 527

Additional Construction:
No of Floors: 2

3. LEA Designated Person

Contact: Robert Christlieb
Address: 125 South Clark Street, 17th Floor
Chicago, IL 60603

Phone: (773) 553-3197

4. Managing Environmental Consultant

MEC: GSG Consultants, Inc.
Contact: Arturo Saenz
Address 855 W. Adams St., Ste. 200
Phone: (312) 733-6262

Fax: (312) 733-5612

5. Inspector

Inspector Name: Delores Fitzpatrick

Inspector IDPH license # 100-05183

Signature:
Date: 3/10/2016



6. Management Planner

Management Planner Name: Guillermo Garcia

Management Planner IDPH license # 100-01786

Signature:
Date: 05/18/2016



7. Review Date: 05/18/2016

8. LEA Designated Person's Acknowledgement

The reinspection report and recommendations have been received by me and appropriate action will be taken by the School District.

Signature:



Date: 6/16/2016

Name: Robert Christlieb

II. EXECUTIVE SUMMARY

GSG Consultants, Inc. was retained by the Chicago Public Schools (CPS) to perform a three-year asbestos reinspection of the Burley School. This inspection was conducted in accordance with the United States Environmental Protection Agency (USEPA) Asbestos Hazard Emergency Response Act (AHERA) part 763.92 (b), and the ongoing Operations and Maintenance Program (O&M) originally designed in the School's Asbestos Management Plan. The purpose of this three-year reinspection is to record any condition changes in the asbestos-containing building material (ACBM) in the school since the previous three-year reinspection and the six-month periodic surveillance, to identify, assess, and include any Homogeneous Areas (HA) not identified in the Management Plan, and to recommend an appropriate response action to manage asbestos.

The inspector conducted a three-year reinspection of this facility under Illinois Department of Public Health (IDPH) school reinspection requirements and AHERA, sections 763.85 and 763.88. The main building and each addition to the main building, if constructed at different dates, were inspected separately. Laboratory accreditations are included in Appendix C, laboratory results are included in Appendix D, and chain of custody forms are included in Appendix E.

Note: During previous inspections, some of the HA(s) were identified together as 9" x 9" floor tile (FT), mastics assoc. with 9" x 9" FT, 12" x 12" FT, mastics assoc. with 12" x 12" FT, pipe insulation, etc. Some of these HA(s) have been re-identified by areas that are uniform in color, texture, construction date, application date, and general appearance.

The inspector has determined the following:

A. The following HAs have changed assessment categories for Building 2470:

- | | |
|---|---|
| B | Cardboard Pipe Insulation NOT OBSERVED in 2016 |
| C | MJP E/F/V on Cardboard Pipe Insulation NOT OBSERVED in 2016 |
| E | Aircell Pipe Insulation NOT OBSERVED in 2016 |
| F | Aircell Duct Insulation |

B. The following new homogenous areas have been identified for Building 2470:

| | |
|----|----------------------------------|
| 29 | 12 x 12 White VFT |
| 30 | 12 x 12 White VFT |
| 31 | 12 x 12 Gray w/ White Specks VFT |
| 32 | 12 x 12 Gray Specks VFT |

C. This reinspection covered only physically accessible and visible areas and materials that were identified in the LEA's management plan. The following materials were concealed and/or contained in areas that were inaccessible for sampling and have been classified as Assumed:

| | |
|----|---|
| 04 | Brown Linoleum |
| 08 | Brown Linoleum Mastic |
| 17 | 12"x12" White w/ Black & Gray Flecks Floor Tile |
| 18 | 12"x12" White w/ Black & Gray Flecks Floor Tile Mastic |
| 20 | MJP E/F/V on Fiberglass Pipe Insulation |
| 21 | 2'x4' Dot/Wave Ceiling Tile |
| 22 | 12"x12" White w/Gray Specks Floor Tile |
| 23 | 12"x12" White w/Gray Specks Floor Tile Mastic |
| 24 | Terrazzo |
| 25 | Salmon & White Linoleum |
| 26 | Salmon & White Linoleum Mastic |
| 27 | Transite Lab Tabletops |
| 28 | Fire Doors NOT OBSERVED |
| 29 | 12 x 12 White VFT |
| 30 | 12 x 12 White VFT |
| 31 | 12 x 12 Gray w/ White Specks VFT |
| 32 | 12 x 12 Gray Specks VFT |

The following areas were deemed to be inaccessible:

Materials were also listed as "assumed" if they were in good condition and sampling was not conducted to avoid damage.

This reinspection was conducted by Delores Fitzpatrick, IDPH License # 100-05183. The Management Plan was updated by Guillermo Garcia, IDPH License # 100-01786. Inspector and Management Planner Licenses are included in Appendix B.

III. METHODOLOGY

Tasks performed on-site included the following:

1. Review current management plan, identify HA(s) and extract appropriate information.
2. Examine and verify abatement records.
3. Touch and visually and physically reinspect and reassess the condition of all friable known or assumed ACBM.
4. Touch and visually and physically reinspect all non-friable known or assumed ACBM to determine whether these materials have become friable since the last inspection or periodic surveillance.
5. Identify any condition changes that may affect Hazard Ranking of known ACBM or Assumed ACBM, as well as any HA(s) that have become friable since the last reinspection.
6. Collect bulk samples from each newly discovered friable HA or previously assumed and submit for laboratory analysis.
7. Tabulate reinspection findings and submit for management planner review and recommendations with appropriate response actions based on the AHERA Damage Category of the ACBM.
8. Submit reinspection findings and management planner recommendations to the LEA within thirty (30) days for inclusion into the management plan.

IV. ABATEMENT HISTORY

The information collected from the existing management plan and inspection report(s) and from interviews with the school official revealed that the following asbestos abatement was conducted at the school since the previous Three year Reinspection.

Abatement Dates:

V. REASSESSMENTS AND RECOMMENDATIONS

The reassessments and recommendations are summarized in Tables I and II on the following pages. Detailed Hazard Assessment Sheets and Drawings and Photos (if applicable) are included in Appendix A.

VI. CONCLUSIONS

The Burley School Building 2470 Three-Year reinspection has been completed and response actions have been recommended for both friable and non-friable materials. A timely execution of the response actions recommended will enable the LEA and the Designated Person(s) to effectively manage the existing ACBM.

This three-year reinspection report should be inspected in the current Management plan at the CPS Central Office, and one (1) copy should be kept at the school for use when planning any renovation and/or demolition activities in areas where ACBM has been identified. Also, periodic surveillance documentation and any summary reports from any response actions that are executed at the school should be used to update the Management Plan.

Table I
Inspector's Reinspection Findings

Chicago Public Schools

School Burley School Unit 22421 Building ID 2470

Address 1630 W. Barry Avenue Region 02

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262 Fax: (312) 733-5612

Inspector's Comments are Summarized at the End of the Report

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category | Damage Category | Damage Reason | Disturbance Potential |
|-------|--|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|-------------------------------|------------------------------------|---------------|-----------------------|
| | | | | 103 (Under Carpet) - 1893 ABATED | | | | | | | | | | |
| 15 | 12"x12" Brown w/ White Flecks Floor Tile - NOT OBSERVED | | | Basement Teacher's Lounge - NOT OBSERVED (1893 Building) | | | | | | | | | | |
| 16 | 12"x12" Brown w/ White Flecks Floor Tile Mastic - NOT OBSERVED | | | Basement Teacher's Lounge - NOT OBSERVED - 1893 Building | | | | | | | | | | |
| 17 | 12"x12" White w/ Black & Gray Flecks Floor Tile | 120 | SF | Main Office - 1893 Building | ASSUMED | MISC | N | NONE | 0 | | | ACBM with the potential for damage | | MODERATE |
| 18 | 12"x12" White w/ Black & Gray Flecks Floor Tile Mastic | 120 | SF | Main Office - 1893 Building | ASSUMED | MISC | N | NONE | 0 | | | ACBM with the potential for damage | | LOW |
| 19 | Carpet Mastic ABATED | | | Main Office, Principal's Office, Principal's Office Conference Room and Room 101 - 1893 Building ABATED | ABATED | MISC | | | | | | | | |
| 20 | MJP E/F/V on Fiberglass Pipe Insulation | 50 | LF | Boiler Room, Tank Room and Old Engine Room - 1893 Building | ASSUMED | TSI | Y | NONE | 0 | | No | ACBM with the potential for damage | | LOW |
| 21 | 2'x4' Dot/Wave Ceiling Tile | 3,200 | SF | Rooms 104 and 304; NOT observed in Main Office, Engineer's Office and Conference Room next to Engineer's Office - 1893 Building | ASSUMED | MISC | Y | NONE | 0 | | No | ACBM with the potential for damage | | LOW |
| 22 | 12"x12" White w/Gray Specks Floor Tile | 800 | SF | Main Office | ASSUMED | MISC | N | NONE | 0 | | No | ACBM with the potential for damage | | MODERATE |
| 23 | 12"x12" White w/Gray Specks Floor Tile Mastic | 800 | SF | Main Office | ASSUMED | MISC | N | NONE | 0 | | No | ACBM with the potential for damage | | LOW |
| 24 | Terrazzo | 900 | SF | 2nd Floor Women's Teacher's Washroom, 2nd Floor Boy's Washroom - 1893 Building | ASSUMED | MISC | N | NONE | 0 | | No | ACBM with the potential for damage | | MODERATE |
| 25 | Salmon & White Linoleum | 100 | SF | Lab Counters in | ASSUMED | MISC | N | NONE | 0 | | No | ACBM with the | | MODERATE |

Chicago Public Schools

School Burley School Unit 22421 Building ID 2470

Address 1630 W. Barry Avenue Region 02

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262 Fax: (312) 733-5612

Inspector's Comments are Summarized at the End of the Report

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category | Damage Category | Damage Reason | Disturbance Potential |
|-------|---|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|-------------------------------|------------------------------------|---------------|-----------------------|
| | | | | Room 203 | | | | | | | | potential for damage | | |
| 26 | Salmon & White Linoleum Mastic | 100 | SF | Lab Counters in Room 203 | ASSUMED | MISC | N | NONE | 0 | | No | ACBM with the potential for damage | | LOW |
| 27 | Transite Lab Tabletops | 200 | SF | Room 203 | ASSUMED | MISC | N | NONE | 0 | | No | ACBM with the potential for damage | | MODERATE |
| 28 | Fire Doors NOT OBSERVED | 24 | EA | Basement, 1st, 2nd and 3rd Floors - 1893 Building NOT OBSERVED | ASSUMED | MISC | Y | NONE | 0 | | | ACBM with the potential for damage | | MODERATE |
| 29 | 12 x 12 White VFT | 7,000 | SF | Corridor 1st Floor | ASSUMED | MISC | N | NONE | 0 | | No | ACBM with the potential for damage | | MODERATE |
| 30 | 12 x 12 White VFT | 350 | SF | Lunch Room (Basement) | ASSUMED | MISC | N | NONE | 0 | | No | ACBM with the potential for damage | | MODERATE |
| 31 | 12 x 12 Gray w/ White Specks VFT | 300 | SF | Main Office (First Floor) | ASSUMED | MISC | N | NONE | 0 | | No | ACBM with the potential for damage | | MODERATE |
| 32 | 12 x 12 Gray Specks VFT | 175 | SF | Conference Room (First Floor) | ASSUMED | MISC | N | NONE | 0 | | No | ACBM with the potential for damage | | MODERATE |
| B | Cardboard Pipe Insulation NOT OBSERVED in 2016 | 717 | LF | Throughout (See Hatching Maps) - 1893 Building NOT OBSERVED in 2016 | CHR | TSI | Y | NONE | 0 | | Yes | ACBM with the potential for damage | | MODERATE |
| C | MJP E/F/V on Cardboard Pipe Insulation NOT OBSERVED in 2016 | 65 | LF | Throughout (See Hatching Maps) - 1893 Building NOT OBSERVED in 2016 | CHR | TSI | Y | NONE | 0 | | Yes | ACBM with the potential for damage | | MODERATE |
| D | Mag Block Tank Insulation - NOT OBSERVED in 2016 | | | Engine Room - (1893 Building) NOT OBSERVED in 2016 | | MISC | | None | | | | | | Moderate |
| E | Aircell Pipe Insulation NOT OBSERVED in 2016 | 25 | LF | Fresh Air Intake & Sprinkler Room - 1893 Building NOT OBSERVED in 2016 | CHR | TSI | Y | NONE | 0 | | Yes | ACBM with the potential for damage | | MODERATE |
| F | Aircell Duct Insulation | 730 | SF | East and West Basement Corridors, North Lunchroom, North Office, North Girl's Playroom and North Corridor - 1893 Building | CHR | TSI | Y | NONE | 0 | | Yes | ACBM with the potential for damage | | MODERATE |
| I | MJP E/F/V on Aircell Pipe Insulation NOT | 25 | LF | Fresh Air Intake & | CHR | TSI | Y | NONE | 0 | | No | ACBM with the | | MODERATE |

Chicago Public Schools

School Burley School Unit 22421 Building ID 2470

Address 1630 W. Barry Avenue Region 02

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262 Fax: (312) 733-5612

Inspector's Comments are Summarized at the End of the Report

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category | Damage Category | Damage Reason | Disturbance Potential |
|-------|---|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|-------------------------------|------------------------------------|---------------|-----------------------|
| | OBSERVED in 2016 | | | Sprinkler Room - 1893 Building NOT OBSERVED in 2016 | | | | | | | | potential for damage | | |
| J | Mag Block Pipe Insulation (SprinklerRm & Outside SprinklerRm (NOT OBSERVED,2016); Store Rm (ABATED) | 9 | LF | Sprinkler Rm & Outside Sprinkler Rm (NOT OBSERVED, 2016); Store Rm (ABATED) - 1893 Bldg | CHR | TSI | Y | NONE | 0 | | No | ACBM with the potential for damage | | MODERATE |
| K | MJP E/F/V on Mag Block Pipe Insulation | 2 | LF | Sprinkler Room and the Storeroom Outside Sprinkler Room - 1893 Building | CHR | TSI | Y | NONE | 0 | | No | ACBM with the potential for damage | | MODERATE |

Chicago Public Schools

School Burley School Unit 22421 Building ID 2470

Address 1630 W. Barry Avenue Region 02

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262 Fax: (312) 733-5612

Inspector's Comments are Summarized at the End of the Report

| |
|---|
| Reinspection Date 3/10/2016 |
| Inspector Name Delores Fitzpatrick |
| 100-05183 2/13/2017 |
| Inspector's IDPH License Number / Expiration Date |

Inspector's Comments

| HA Number: | Inspector Comments: |
|------------|-------------------------------|
| 02 | |
| 03 | |
| 04 | |
| 06 | |
| 07 | |
| 08 | |
| 09 | |
| 10 | |
| 11 | Observed Rubber Floor in 2016 |
| 12 | Observed Rubber Floor in 2016 |
| 13 | |
| 14 | |
| 15 | |
| 16 | |
| 17 | |
| 18 | |
| 19 | |
| 20 | |
| 21 | |
| 22 | |
| 23 | |
| 24 | |
| 25 | |
| 26 | |

Chicago Public Schools

School Burley School Unit 22421 Building ID 2470

Address 1630 W. Barry Avenue Region 02

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262 Fax: (312) 733-5612

Inspector's Comments are Summarized at the End of the Report

| HA Number: | Inspector Comments: |
|------------|----------------------|
| 27 | |
| 28 | NOT OBSERVED in 2016 |
| 29 | |
| 30 | |
| 31 | |
| 32 | |
| B | NOT OBSERVED in 2016 |
| C | NOT OBSERVED in 2016 |
| D | NOT OBSERVED in 2016 |
| E | NOT OBSERVED in 2016 |
| F | |
| I | NOT OBSERVED in 2016 |
| J | |
| K | |

Table II

Management Planner's Review

Chicago Public Schools

School Burley School
Address 1630 W. Barry Avenue

Unit 22421
 Chicago, IL, 60657

Building ID 2470
Region 02

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262

Fax: (312) 733-5612

Management Planner's Comments Summarized at the End of the Report

| HA Num | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Quantity | Damage Units | Damage Category | Response |
|--------|--|-------------------|----------------|--|---------------|-------------------|---------|-----------------|--------------|--------------------------------------|-----------------|
| 02 | 12"x12" White w/ Tan Streaks Floor Tile | 10,509 | SF | Rooms 105-108, 201, 202, 205-209 and Men's and Women's 1st Floor Washrooms - 1893 Building | Chrysotile | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 03 | 9"x9" Brown w/ White Streaks Floor Tile - ABATED | | | 1st Floor Corridor and South Lunchroom - 1893 Building - ABATED | Abated | MISC | | | | | |
| 04 | Brown Linoleum | 1,200 | SF | Gymnasium Stage and Stairs - 1893 Building | Assumed | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 06 | 12"x12" White w/Tan Streaks Floor Tile Mastic | 10,509 | SF | Rooms 105-108, 201, 202, 205-209 and Men's and Women's 1st Floor Washrooms - 1893 Building | Chrysotile | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 07 | 9"x9" Brown w/ White Streaks Floor Tile Mastic - ABATED | | | 1st Floor Corridor and South Lunchroom - 1893 Building - ABATED | Abated | MISC | | | | | |
| 08 | Brown Linoleum Mastic | 1,200 | SF | Gymnasium Stage and Stairs - 1893 Building | Assumed | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 09 | 12"x12" Brown w/ White Streaks Floor Tile | 300 | SF | Foyer and Mechanical Room-Fieldhouse | Chrysotile | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 10 | 12"x12" Brown w/ White Streaks Floor Tile Mastic | 300 | SF | Foyer and Mechanical Room-Fieldhouse | Chrysotile | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 11 | 12"x12" Beige w/ Black & White Flecks Floor Tile ABATED | | | Gymnasium - 1893 ABATED | Abated | MISC | | | | | |
| 12 | 12"x12" Beige w/ Black & White Flecks Floor Tile Mastic ABATED | | | Gymnasium - 1893 ABATED | Abated | MISC | | | | | |
| 13 | 9"x9" Gray w/ Black & White Streaks Floor Tile ABATED | | | Main Office, Main Office Copy Room Hallway and Room 103 (Under Carpet) - 1893 ABATED | Abated | MISC | | | | | |
| 14 | 9"x9" Gray w/ Black & White Streaks Floor Tile Mastic ABATED | | | Main Office, Main Office Copy Room Hallway and Room 103 (Under Carpet) - 1893 ABATED | Abated | MISC | | | | | |
| 15 | 12"x12" Brown w/ White Flecks Floor Tile - NOT OBSERVED | | | Basement Teacher's Lounge - NOT OBSERVED (1893 Building) | | | | | | | |
| 16 | 12"x12" Brown w/ White Flecks Floor Tile Mastic - NOT OBSERVED | | | Basement Teacher's Lounge - NOT OBSERVED - 1893 Building | | | | | | | |
| 17 | 12"x12" White w/ Black & Gray Flecks Floor Tile | 120 | SF | Main Office - 1893 Building | Assumed | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 18 | 12"x12" White w/ Black & Gray Flecks Floor Tile | 120 | SF | Main Office - 1893 Building | Assumed | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Follow O&M Plan |

Chicago Public Schools

School Burley School
Address 1630 W. Barry Avenue

Unit 22421
 Chicago, IL, 60657

Building ID 2470
Region 02

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262

Fax: (312) 733-5612

Management Planner's Comments Summarized at the End of the Report

| HA Num | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Quantity | Damage Units | Damage Category | Response |
|--------|---|-------------------|----------------|---|---------------|-------------------|---------|-----------------|--------------|--------------------------------------|-----------------|
| 19 | Mastic Carpet Mastic ABATED | | | Main Office, Principal's Office, Principal's Office Conference Room and Room 101 - 1893 Building ABATED | Abated | MISC | | | | | |
| 20 | MJP E/F/V on Fiberglass Pipe Insulation | 50 | LF | Boiler Room, Tank Room and Old Engine Room - 1893 Building | Assumed | TSI | Yes | 0 | LF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 21 | 2'x4' Dot/Wave Ceiling Tile | 3,200 | SF | Rooms 104 and 304; NOT observed in Main Office, Engineer's Office and Conference Room next to Engineer's Office - 1893 Building | Assumed | MISC | Yes | 0 | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 22 | 12"x12" White w/Gray Specks Floor Tile | 800 | SF | Main Office | Assumed | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 23 | 12"x12" White w/Gray Specks Floor Tile Mastic | 800 | SF | Main Office | Assumed | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 24 | Terrazzo | 900 | SF | 2nd Floor Women's Teacher's Washroom, 2nd Floor Boy's Washroom - 1893 Building | Assumed | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 25 | Salmon & White Linoleum | 100 | SF | Lab Counters in Room 203 | Assumed | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 26 | Salmon & White Linoleum Mastic | 100 | SF | Lab Counters in Room 203 | Assumed | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 27 | Transite Lab Tabletops | 200 | SF | Room 203 | Assumed | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 28 | Fire Doors NOT OBSERVED | 24 | EA | Basement, 1st, 2nd and 3rd Floors - 1893 Building NOT OBSERVED | Assumed | MISC | Yes | 0 | EA | 6 ACBM with the potential for damage | |
| 29 | 12 x 12 White VFT | 7,000 | SF | Corridor 1st Floor | Assumed | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 30 | 12 x 12 White VFT | 350 | SF | Lunch Room (Basement) | Assumed | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 31 | 12 x 12 Gray w/ White Specks VFT | 300 | SF | Main Office (First Floor) | Assumed | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 32 | 12 x 12 Gray Specks VFT | 175 | SF | Conference Room (First Floor) | Assumed | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| B | Cardboard Pipe Insulation NOT OBSERVED in 2016 | 717 | LF | Throughout (See Hatching Maps) - 1893 Building NOT OBSERVED in 2016 | Chrysotile | TSI | Yes | 0 | LF | 6 ACBM with the potential for damage | |
| C | MJP E/F/V on Cardboard Pipe Insulation NOT OBSERVED in 2016 | 65 | LF | Throughout (See Hatching Maps) - 1893 Building NOT OBSERVED in 2016 | Chrysotile | TSI | Yes | 0 | LF | 6 ACBM with the potential for damage | |
| D | Mag Block Tank Insulation - NOT OBSERVED in 2016 | | | Engine Room - (1893 Building) NOT OBSERVED in 2016 | | MISC | | | | | |
| E | Aircell Pipe Insulation NOT OBSERVED in 2016 | 25 | LF | Fresh Air Intake & Sprinkler Room - 1893 Building | Chrysotile | TSI | Yes | 0 | LF | 6 ACBM with the potential for damage | |

Chicago Public Schools

School Burley School
Address 1630 W. Barry Avenue

Unit 22421
 Chicago, IL, 60657

Building ID 2470
Region 02

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262

Fax: (312) 733-5612

Management Planner's Comments Summarized at the End of the Report

| HA Num | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Quantity | Damage Units | Damage Category | Response |
|--------|---|-------------------|----------------|---|---------------|-------------------|---------|-----------------|--------------|--------------------------------------|-----------------|
| | | | | NOT OBSERVED in 2016 | | | | | | | |
| F | Aircell Duct Insulation | 730 | SF | East and West Basement Corridors, North Lunchroom, North Office, North Girl's Playroom and North Corridor - 1893 Building | Chrysotile | TSI | Yes | 0 | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| I | MJP E/F/V on Aircell Pipe Insulation NOT OBSERVED in 2016 | 25 | LF | Fresh Air Intake & Sprinkler Room - 1893 Building NOT OBSERVED in 2016 | Chrysotile | TSI | Yes | 0 | LF | 6 ACBM with the potential for damage | |
| J | Mag Block Pipe Insulation (SprinklerRm & Outside SprinklerRm (NOT OBSERVED,2016); Store Rm (ABATED) | 9 | LF | Sprinkler Rm & Outside Sprinkler Rm (NOT OBSERVED, 2016); Store Rm (ABATED) - 1893 Bldg | Chrysotile | TSI | Yes | 0 | LF | 6 ACBM with the potential for damage | Follow O&M Plan |
| K | MJP E/F/V on Mag Block Pipe Insulation | 2 | LF | Sprinkler Room and the Storeroom Outside Sprinkler Room - 1893 Building | Chrysotile | TSI | Yes | 0 | LF | 6 ACBM with the potential for damage | Follow O&M Plan |

Chicago Public Schools

School Burley School
Address 1630 W. Barry Avenue

Unit 22421
 Chicago, IL, 60657

Building ID 2470
Region 02

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) GSG Consultants, Inc.
 855 W. Adams St., Ste. 200
 Phone: (312) 733-6262

Fax: (312) 733-5612

Management Planner's Comments Summarized at the End of the Report

| | |
|------------------------------------|------------------|
| Review Date | 5/18/2016 |
| Manager Planner Name | Guillermo Garcia |
| 100-01786 | 3/21/2017 |
| Manager IDPH License No/Expiration | |

| HA Number | Management Comments |
|-----------|---------------------|
| 02 | |
| 03 | |
| 04 | |
| 06 | |
| 07 | |
| 08 | |
| 09 | |
| 10 | |
| 11 | |
| 12 | |
| 13 | |
| 14 | |
| 15 | |
| 16 | |
| 17 | |
| 18 | |
| 19 | |
| 20 | |
| 21 | |
| 22 | |
| 23 | |
| 24 | |
| 25 | |
| 26 | |

Chicago Public Schools

School Burley School
Address 1630 W. Barry Avenue

Unit 22421
Chicago, IL, 60657

Building ID 2470
Region 02

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262

Fax: (312) 733-5612

Management Planner's Comments Summarized at the End of the Report

| HA Number | Management Comments |
|-----------|---------------------|
| 27 | |
| 28 | |
| 29 | |
| 30 | |
| 31 | |
| 32 | |
| B | |
| C | |
| D | |
| E | |
| F | |
| I | |
| J | |
| K | |

Chicago Public Schools

GSG Consultants, Inc.

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22421** BUILDING ID: **2470**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Delores Fitzpatrick**
SCHOOL NAME: **Burley School** INSPECTION DATE: **3/10/2016**
ADDRESS: **1630 W. Barry Avenue** IDPH LICENSE NO: **100-05183**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **02**
MATERIAL DESCRIPTION: **12"x12" White w/ Tan Streaks Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**

MATERIAL LOCATION: **Rooms 105-108, 201, 202, 205-209 and Men's and Women's 1st Floor Washrooms - 1893 Building**

MATERIAL QUANTITY: **10509** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 03/10/2016

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22421** BUILDING ID: **2470**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**
SCHOOL NAME: **Burley School** REVIEW DATE: **5/18/2016**
ADDRESS: **1630 W. Barry Avenue** IDPH LICENSE NO: **100-05183**

HOMOGENEOUS AREA: **02**
MATERIAL DESCRIPTION: **12"x12" White w/ Tan Streaks Floor Tile**
MATERIAL LOCATION: **Rooms 105-108, 201, 202, 205-209 and Men's and Women's 1st Floor Washrooms - 1893 Building**
MATERIAL QUANTITY: **10509** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **05/18/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22421** BUILDING ID: **2470**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Delores Fitzpatrick**
SCHOOL NAME: **Burley School** INSPECTION DATE: **3/10/2016**
ADDRESS: **1630 W. Barry Avenue** IDPH LICENSE NO: **100-05183**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **03**
MATERIAL DESCRIPTION: **9"x9" Brown w/ White Streaks Floor Tile - ABATED**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1st Floor Corridor and South Lunchroom - 1893 Building - ABATED**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **03/10/2016**

Chicago Public Schools

GSG Consultants, Inc.

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22421** BUIDLING ID: **2470**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**
SCHOOL NAME: **Burley School** REVIEW DATE: **5/18/2016**
ADDRESS: **1630 W. Barry Avenue** IDPH LICENSE NO: **100-05183**

HOMOGENEOUS AREA: **03**

MATERIAL DESCRIPTION: **9"x9" Brown w/ White Streaks Floor Tile - ABATED**

MATERIAL LOCATION: **1st Floor Corridor and South Lunchroom - 1893 Building - ABATED**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **05/18/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22421** BUIDLING ID: **2470**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Delores Fitzpatrick**
SCHOOL NAME: **Burley School** INSPECTION DATE: **3/10/2016**
ADDRESS: **1630 W. Barry Avenue** IDPH LICENSE NO: **100-05183**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **04**
MATERIAL DESCRIPTION: **Brown Linoleum**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Gymnasium Stage and Stairs - 1893 Building**
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 03/10/2016

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22421** BUILDING ID: **2470**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**
SCHOOL NAME: **Burley School** REVIEW DATE: **5/18/2016**
ADDRESS: **1630 W. Barry Avenue** IDPH LICENSE NO: **100-05183**

HOMOGENEOUS AREA: **04**
MATERIAL DESCRIPTION: **Brown Linoleum**
MATERIAL LOCATION: **Gymnasium Stage and Stairs - 1893 Building**
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **05/18/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22421** BUILDING ID: **2470**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Delores Fitzpatrick**
SCHOOL NAME: **Burley School** INSPECTION DATE: **3/10/2016**
ADDRESS: **1630 W. Barry Avenue** IDPH LICENSE NO: **100-05183**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **06**
MATERIAL DESCRIPTION: **12"x12" White w/Tan Streaks Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Rooms 105-108, 201, 202, 205-209 and Men's and Women's 1st Floor Washrooms - 1893 Building**

MATERIAL QUANTITY: **10509** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/10/2016**

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22421** BUIDLING ID: **2470**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**
SCHOOL NAME: **Burley School** REVIEW DATE: **5/18/2016**
ADDRESS: **1630 W. Barry Avenue** IDPH LICENSE NO: **100-05183**

HOMOGENEOUS AREA: **06**
MATERIAL DESCRIPTION: **12"x12" White w/Tan Streaks Floor Tile Mastic**
MATERIAL LOCATION: **Rooms 105-108, 201, 202, 205-209 and Men's and Women's 1st Floor Washrooms - 1893 Building**
MATERIAL QUANTITY: **10509** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **05/18/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22421** BUIDLING ID: **2470**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Delores Fitzpatrick**
SCHOOL NAME: **Burley School** INSPECTION DATE: **3/10/2016**
ADDRESS: **1630 W. Barry Avenue** IDPH LICENSE NO: **100-05183**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **07**
MATERIAL DESCRIPTION: **9"x9" Brown w/ White Streaks Floor Tile Mastic - ABATED**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1st Floor Corridor and South Lunchroom - 1893 Building - ABATED**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **03/10/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22421** BUIDLING ID: **2470**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**
SCHOOL NAME: **Burley School** REVIEW DATE: **5/18/2016**
ADDRESS: **1630 W. Barry Avenue** IDPH LICENSE NO: **100-05183**

HOMOGENEOUS AREA: **07**
MATERIAL DESCRIPTION: **9"x9" Brown w/ White Streaks Floor Tile Mastic - ABATED**
MATERIAL LOCATION: **1st Floor Corridor and South Lunchroom - 1893 Building - ABATED**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **05/18/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22421** BUIDLING ID: **2470**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Delores Fitzpatrick**
SCHOOL NAME: **Burley School** INSPECTION DATE: **3/10/2016**
ADDRESS: **1630 W. Barry Avenue** IDPH LICENSE NO: **100-05183**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **08**
MATERIAL DESCRIPTION: **Brown Linoleum Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Gymnasium Stage and Stairs - 1893 Building**
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 03/10/2016

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22421** BUILDING ID: **2470**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**
SCHOOL NAME: **Burley School** REVIEW DATE: **5/18/2016**
ADDRESS: **1630 W. Barry Avenue** IDPH LICENSE NO: **100-05183**

HOMOGENEOUS AREA: **08**
MATERIAL DESCRIPTION: **Brown Linoleum Mastic**
MATERIAL LOCATION: **Gymnasium Stage and Stairs - 1893 Building**
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **05/18/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22421** BUIDLING ID: **2470**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Delores Fitzpatrick**
SCHOOL NAME: **Burley School** INSPECTION DATE: **3/10/2016**
ADDRESS: **1630 W. Barry Avenue** IDPH LICENSE NO: **100-05183**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **09**
MATERIAL DESCRIPTION: **12"x12" Brown w/ White Streaks Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Foyer and Mechanical Room- Fieldhouse**
MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 03/10/2016

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22421** BUILDING ID: **2470**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**
SCHOOL NAME: **Burley School** REVIEW DATE: **5/18/2016**
ADDRESS: **1630 W. Barry Avenue** IDPH LICENSE NO: **100-05183**

HOMOGENEOUS AREA: **09**
MATERIAL DESCRIPTION: **12"x12" Brown w/ White Streaks Floor Tile**
MATERIAL LOCATION: **Foyer and Mechanical Room- Fieldhouse**
MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **05/18/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22421** BUIDLING ID: **2470**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Delores Fitzpatrick**
SCHOOL NAME: **Burley School** INSPECTION DATE: **3/10/2016**
ADDRESS: **1630 W. Barry Avenue** IDPH LICENSE NO: **100-05183**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **10**
MATERIAL DESCRIPTION: **12"x12" Brown w/ White Streaks Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Foyer and Mechanical Room- Fieldhouse**
MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 03/10/2016

Chicago Public Schools

GSG Consultants, Inc.

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22421** BUILDING ID: **2470**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**
SCHOOL NAME: **Burley School** REVIEW DATE: **5/18/2016**
ADDRESS: **1630 W. Barry Avenue** IDPH LICENSE NO: **100-05183**

HOMOGENEOUS AREA: **10**
MATERIAL DESCRIPTION: **12"x12" Brown w/ White Streaks Floor Tile Mastic**
MATERIAL LOCATION: **Foyer and Mechanical Room- Fieldhouse**
MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **05/18/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22421** BUIDLING ID: **2470**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Delores Fitzpatrick**
SCHOOL NAME: **Burley School** INSPECTION DATE: **3/10/2016**
ADDRESS: **1630 W. Barry Avenue** IDPH LICENSE NO: **100-05183**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **11**
MATERIAL DESCRIPTION: **12"x12" Beige w/ Black & White Flecks Floor Tile ABATED**
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Gymnasium - 1893 ABATED**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Observed Rubber Floor in 2016**

Inspector's Signature: _____



Date: 03/10/2016

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22421** BUILDING ID: **2470**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**
SCHOOL NAME: **Burley School** REVIEW DATE: **5/18/2016**
ADDRESS: **1630 W. Barry Avenue** IDPH LICENSE NO: **100-05183**

HOMOGENEOUS AREA: **11**
MATERIAL DESCRIPTION: **12"x12" Beige w/ Black & White Flecks Floor Tile ABATED**
MATERIAL LOCATION: **Gymnasium - 1893 ABATED**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **05/18/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22421** BUIDLING ID: **2470**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Delores Fitzpatrick**
SCHOOL NAME: **Burley School** INSPECTION DATE: **3/10/2016**
ADDRESS: **1630 W. Barry Avenue** IDPH LICENSE NO: **100-05183**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **12**
MATERIAL DESCRIPTION: **12"x12" Beige w/ Black & White Flecks Floor Tile Mastic ABATED**
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Gymnasium - 1893 ABATED**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Observed Rubber Floor in 2016**

Inspector's Signature:



Date: **03/10/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22421** BUIDLING ID: **2470**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**
SCHOOL NAME: **Burley School** REVIEW DATE: **5/18/2016**
ADDRESS: **1630 W. Barry Avenue** IDPH LICENSE NO: **100-05183**

HOMOGENEOUS AREA: **12**
MATERIAL DESCRIPTION: **12"x12" Beige w/ Black & White Flecks Floor Tile Mastic ABATED**
MATERIAL LOCATION: **Gymnasium - 1893 ABATED**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **05/18/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22421** BUIDLING ID: **2470**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Delores Fitzpatrick**
SCHOOL NAME: **Burley School** INSPECTION DATE: **3/10/2016**
ADDRESS: **1630 W. Barry Avenue** IDPH LICENSE NO: **100-05183**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **13**
MATERIAL DESCRIPTION: **9"x9" Gray w/ Black & White Streaks Floor Tile ABATED**
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Main Office, Main Office Copy Room Hallway and Room 103 (Under Carpet) - 1893
ABATED**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: 

Date: **03/10/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22421** BUIDLING ID: **2470**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**
SCHOOL NAME: **Burley School** REVIEW DATE: **5/18/2016**
ADDRESS: **1630 W. Barry Avenue** IDPH LICENSE NO: **100-05183**

HOMOGENEOUS AREA: **13**
MATERIAL DESCRIPTION: **9"x9" Gray w/ Black & White Streaks Floor Tile ABATED**
MATERIAL LOCATION: **Main Office, Main Office Copy Room Hallway and Room 103 (Under Carpet) - 1893 ABATED**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **05/18/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22421** BUIDLING ID: **2470**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Delores Fitzpatrick**
SCHOOL NAME: **Burley School** INSPECTION DATE: **3/10/2016**
ADDRESS: **1630 W. Barry Avenue** IDPH LICENSE NO: **100-05183**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **14**
MATERIAL DESCRIPTION: **9"x9" Gray w/ Black & White Streaks Floor Tile Mastic ABATED**
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Main Office, Main Office Copy Room Hallway and Room 103 (Under Carpet) - 1893
ABATED**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **03/10/2016**

Chicago Public Schools

GSG Consultants, Inc.

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22421** BUIDLING ID: **2470**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**
SCHOOL NAME: **Burley School** REVIEW DATE: **5/18/2016**
ADDRESS: **1630 W. Barry Avenue** IDPH LICENSE NO: **100-05183**

HOMOGENEOUS AREA: **14**
MATERIAL DESCRIPTION: **9"x9" Gray w/ Black & White Streaks Floor Tile Mastic ABATED**
MATERIAL LOCATION: **Main Office, Main Office Copy Room Hallway and Room 103 (Under Carpet) - 1893 ABATED**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **05/18/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22421** BUIDLING ID: **2470**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Delores Fitzpatrick**
SCHOOL NAME: **Burley School** INSPECTION DATE: **3/10/2016**
ADDRESS: **1630 W. Barry Avenue** IDPH LICENSE NO: **100-05183**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **15**
MATERIAL DESCRIPTION: **12"x12" Brown w/ White Flecks Floor Tile - NOT OBSERVED**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Basement Teacher's Lounge - NOT OBSERVED (1893 Building)**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **03/10/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22421** BUILDING ID: **2470**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**
SCHOOL NAME: **Burley School** REVIEW DATE: **5/18/2016**
ADDRESS: **1630 W. Barry Avenue** IDPH LICENSE NO: **100-05183**

HOMOGENEOUS AREA: **15**
MATERIAL DESCRIPTION: **12"x12" Brown w/ White Flecks Floor Tile - NOT OBSERVED**
MATERIAL LOCATION: **Basement Teacher's Lounge - NOT OBSERVED (1893 Building)**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **05/18/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22421** BUIDLING ID: **2470**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Delores Fitzpatrick**
SCHOOL NAME: **Burley School** INSPECTION DATE: **3/10/2016**
ADDRESS: **1630 W. Barry Avenue** IDPH LICENSE NO: **100-05183**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **16**
MATERIAL DESCRIPTION: **12"x12" Brown w/ White Flecks Floor Tile Mastic - NOT OBSERVED**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Basement Teacher's Lounge - NOT OBSERVED - 1893 Building**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **03/10/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22421** BUIDLING ID: **2470**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**
SCHOOL NAME: **Burley School** REVIEW DATE: **5/18/2016**
ADDRESS: **1630 W. Barry Avenue** IDPH LICENSE NO: **100-05183**

HOMOGENEOUS AREA: **16**
MATERIAL DESCRIPTION: **12"x12" Brown w/ White Flecks Floor Tile Mastic - NOT OBSERVED**
MATERIAL LOCATION: **Basement Teacher's Lounge - NOT OBSERVED - 1893 Building**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **05/18/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22421** BUILDING ID: **2470**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Delores Fitzpatrick**
SCHOOL NAME: **Burley School** INSPECTION DATE: **3/10/2016**
ADDRESS: **1630 W. Barry Avenue** IDPH LICENSE NO: **100-05183**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **17**
MATERIAL DESCRIPTION: **12"x12" White w/ Black & Gray Flecks Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Main Office - 1893 Building**
MATERIAL QUANTITY: **120** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 03/10/2016

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22421** BUILDING ID: **2470**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**
SCHOOL NAME: **Burley School** REVIEW DATE: **5/18/2016**
ADDRESS: **1630 W. Barry Avenue** IDPH LICENSE NO: **100-05183**

HOMOGENEOUS AREA: **17**
MATERIAL DESCRIPTION: **12"x12" White w/ Black & Gray Flecks Floor Tile**
MATERIAL LOCATION: **Main Office - 1893 Building**
MATERIAL QUANTITY: **120** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **05/18/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22421** BUILDING ID: **2470**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Delores Fitzpatrick**
SCHOOL NAME: **Burley School** INSPECTION DATE: **3/10/2016**
ADDRESS: **1630 W. Barry Avenue** IDPH LICENSE NO: **100-05183**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **18**
MATERIAL DESCRIPTION: **12"x12" White w/ Black & Gray Flecks Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Main Office - 1893 Building**

MATERIAL QUANTITY: **120**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 03/10/2016

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22421** BUIDLING ID: **2470**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**
SCHOOL NAME: **Burley School** REVIEW DATE: **5/18/2016**
ADDRESS: **1630 W. Barry Avenue** IDPH LICENSE NO: **100-05183**

HOMOGENEOUS AREA: **18**
MATERIAL DESCRIPTION: **12"x12" White w/ Black & Gray Flecks Floor Tile Mastic**
MATERIAL LOCATION: **Main Office - 1893 Building**
MATERIAL QUANTITY: **120** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **05/18/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22421** BUILDING ID: **2470**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Delores Fitzpatrick**
SCHOOL NAME: **Burley School** INSPECTION DATE: **3/10/2016**
ADDRESS: **1630 W. Barry Avenue** IDPH LICENSE NO: **100-05183**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **19**
MATERIAL DESCRIPTION: **Carpet Mastic ABATED**
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Main Office, Principal's Office, Principal's Office Conference Room and Room 101 - 1893 Building ABATED**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____



Date: **03/10/2016**

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22421** BUIDLING ID: **2470**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**
SCHOOL NAME: **Burley School** REVIEW DATE: **5/18/2016**
ADDRESS: **1630 W. Barry Avenue** IDPH LICENSE NO: **100-05183**

HOMOGENEOUS AREA: **19**
MATERIAL DESCRIPTION: **Carpet Mastic ABATED**
MATERIAL LOCATION: **Main Office, Principal's Office, Principal's Office Conference Room and Room 101 - 1893 Building ABATED**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **05/18/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22421** BUIDLING ID: **2470**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Delores Fitzpatrick**
SCHOOL NAME: **Burley School** INSPECTION DATE: **3/10/2016**
ADDRESS: **1630 W. Barry Avenue** IDPH LICENSE NO: **100-05183**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **20**
MATERIAL DESCRIPTION: **MJP E/F/V on Fiberglass Pipe Insulation**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Boiler Room, Tank Room and Old Engine Room - 1893 Building**
MATERIAL QUANTITY: **50** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: _____



Date: 03/10/2016

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22421** BUILDING ID: **2470**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**
SCHOOL NAME: **Burley School** REVIEW DATE: **5/18/2016**
ADDRESS: **1630 W. Barry Avenue** IDPH LICENSE NO: **100-05183**

HOMOGENEOUS AREA: **20**
MATERIAL DESCRIPTION: **MJP E/F/V on Fiberglass Pipe Insulation**
MATERIAL LOCATION: **Boiler Room, Tank Room and Old Engine Room - 1893 Building**
MATERIAL QUANTITY: **50** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **05/18/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22421** BUIDLING ID: **2470**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Delores Fitzpatrick**
SCHOOL NAME: **Burley School** INSPECTION DATE: **3/10/2016**
ADDRESS: **1630 W. Barry Avenue** IDPH LICENSE NO: **100-05183**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **21**
MATERIAL DESCRIPTION: **2'x4' Dot/Wave Ceiling Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Rooms 104 and 304; NOT observed in Main Office, Engineer's Office and Conference Room next to Engineer's Office - 1893 Building**

MATERIAL QUANTITY: **3200** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/10/2016**

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22421** BUIDLING ID: **2470**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**
SCHOOL NAME: **Burley School** REVIEW DATE: **5/18/2016**
ADDRESS: **1630 W. Barry Avenue** IDPH LICENSE NO: **100-05183**

HOMOGENEOUS AREA: **21**
MATERIAL DESCRIPTION: **2'x4' Dot/Wave Ceiling Tile**
MATERIAL LOCATION: **Rooms 104 and 304; NOT observed in Main Office, Engineer's Office and Conference Room next to Engineer's Office - 1893 Building**
MATERIAL QUANTITY: **3200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **05/18/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22421** BUIDLING ID: **2470**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Delores Fitzpatrick**
SCHOOL NAME: **Burley School** INSPECTION DATE: **3/10/2016**
ADDRESS: **1630 W. Barry Avenue** IDPH LICENSE NO: **100-05183**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **22**
MATERIAL DESCRIPTION: **12"x12" White w/Gray Specks Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Main Office**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 03/10/2016

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22421** BUIDLING ID: **2470**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**
SCHOOL NAME: **Burley School** REVIEW DATE: **5/18/2016**
ADDRESS: **1630 W. Barry Avenue** IDPH LICENSE NO: **100-05183**

HOMOGENEOUS AREA: **22**
MATERIAL DESCRIPTION: **12"x12" White w/Gray Specks Floor Tile**
MATERIAL LOCATION: **Main Office**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **05/18/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22421** BUIDLING ID: **2470**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Delores Fitzpatrick**
SCHOOL NAME: **Burley School** INSPECTION DATE: **3/10/2016**
ADDRESS: **1630 W. Barry Avenue** IDPH LICENSE NO: **100-05183**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **23**
MATERIAL DESCRIPTION: **12"x12" White w/Gray Specks Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Main Office**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 03/10/2016

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22421** BUIDLING ID: **2470**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**
SCHOOL NAME: **Burley School** REVIEW DATE: **5/18/2016**
ADDRESS: **1630 W. Barry Avenue** IDPH LICENSE NO: **100-05183**

HOMOGENEOUS AREA: **23**
MATERIAL DESCRIPTION: **12"x12" White w/Gray Specks Floor Tile Mastic**
MATERIAL LOCATION: **Main Office**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **05/18/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22421** BUIDLING ID: **2470**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Delores Fitzpatrick**
SCHOOL NAME: **Burley School** INSPECTION DATE: **3/10/2016**
ADDRESS: **1630 W. Barry Avenue** IDPH LICENSE NO: **100-05183**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **24**
MATERIAL DESCRIPTION: **Terrazzo**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **2nd Floor Women's Teacher's Washroom, 2nd Floor Boy's Washroom - 1893 Building**
MATERIAL QUANTITY: **900** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____



Date: 03/10/2016

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22421** BUILDING ID: **2470**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**
SCHOOL NAME: **Burley School** REVIEW DATE: **5/18/2016**
ADDRESS: **1630 W. Barry Avenue** IDPH LICENSE NO: **100-05183**

HOMOGENEOUS AREA: **24**
MATERIAL DESCRIPTION: **Terrazzo**
MATERIAL LOCATION: **2nd Floor Women's Teacher's Washroom, 2nd Floor Boy's Washroom - 1893 Building**
MATERIAL QUANTITY: **900** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **05/18/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22421** BUIDLING ID: **2470**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Delores Fitzpatrick**
SCHOOL NAME: **Burley School** INSPECTION DATE: **3/10/2016**
ADDRESS: **1630 W. Barry Avenue** IDPH LICENSE NO: **100-05183**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **25**
MATERIAL DESCRIPTION: **Salmon & White Linoleum**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Lab Counters in Room 203**
MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____



Date: 03/10/2016

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22421** BUIDLING ID: **2470**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**
SCHOOL NAME: **Burley School** REVIEW DATE: **5/18/2016**
ADDRESS: **1630 W. Barry Avenue** IDPH LICENSE NO: **100-05183**

HOMOGENEOUS AREA: **25**
MATERIAL DESCRIPTION: **Salmon & White Linoleum**
MATERIAL LOCATION: **Lab Counters in Room 203**
MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **05/18/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22421** BUIDLING ID: **2470**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Delores Fitzpatrick**
SCHOOL NAME: **Burley School** INSPECTION DATE: **3/10/2016**
ADDRESS: **1630 W. Barry Avenue** IDPH LICENSE NO: **100-05183**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **26**
MATERIAL DESCRIPTION: **Salmon & White Linoleum Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Lab Counters in Room 203**
MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 03/10/2016

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22421** BUIDLING ID: **2470**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**
SCHOOL NAME: **Burley School** REVIEW DATE: **5/18/2016**
ADDRESS: **1630 W. Barry Avenue** IDPH LICENSE NO: **100-05183**

HOMOGENEOUS AREA: **26**
MATERIAL DESCRIPTION: **Salmon & White Linoleum Mastic**
MATERIAL LOCATION: **Lab Counters in Room 203**
MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **05/18/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22421** BUIDLING ID: **2470**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Delores Fitzpatrick**
SCHOOL NAME: **Burley School** INSPECTION DATE: **3/10/2016**
ADDRESS: **1630 W. Barry Avenue** IDPH LICENSE NO: **100-05183**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **27**
MATERIAL DESCRIPTION: **Transite Lab Tabletops**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Room 203**
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 03/10/2016

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22421** BUIDLING ID: **2470**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**
SCHOOL NAME: **Burley School** REVIEW DATE: **5/18/2016**
ADDRESS: **1630 W. Barry Avenue** IDPH LICENSE NO: **100-05183**

HOMOGENEOUS AREA: **27**
MATERIAL DESCRIPTION: **Transite Lab Tabletops**
MATERIAL LOCATION: **Room 203**
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **05/18/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22421** BUIDLING ID: **2470**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Delores Fitzpatrick**
SCHOOL NAME: **Burley School** INSPECTION DATE: **3/10/2016**
ADDRESS: **1630 W. Barry Avenue** IDPH LICENSE NO: **100-05183**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **28**
MATERIAL DESCRIPTION: **Fire Doors NOT OBSERVED**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Basement, 1st, 2nd and 3rd Floors - 1893 Building
NOT OBSERVED**
MATERIAL QUANTITY: **24** MATERIAL UNITS: **EA**
DAMAGE QUANTITY: DAMAGE UNITS: **EA**
COMMENTS: **NOT OBSERVED in 2016**

Inspector's Signature: _____



Date: 03/10/2016

Chicago Public Schools

GSG Consultants, Inc.

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22421** BUIDLING ID: **2470**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**
SCHOOL NAME: **Burley School** REVIEW DATE: **5/18/2016**
ADDRESS: **1630 W. Barry Avenue** IDPH LICENSE NO: **100-05183**

HOMOGENEOUS AREA: **28**

MATERIAL DESCRIPTION: **Fire Doors NOT OBSERVED**

MATERIAL LOCATION: **Basement, 1st, 2nd and 3rd Floors - 1893 Building
NOT OBSERVED**

MATERIAL QUANTITY: **24**

MATERIAL UNITS: **EA**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **EA**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **05/18/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22421** BUIDLING ID: **2470**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Delores Fitzpatrick**
SCHOOL NAME: **Burley School** INSPECTION DATE: **3/10/2016**
ADDRESS: **1630 W. Barry Avenue** IDPH LICENSE NO: **100-05183**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **B**
MATERIAL DESCRIPTION: **Cardboard Pipe Insulation NOT OBSERVED in 2016**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with potential for significant damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**

MATERIAL LOCATION: **Throughout (See Hatching Maps) - 1893 Building
NOT OBSERVED in 2016**

MATERIAL QUANTITY: **717**

MATERIAL UNITS: **LF**

DAMAGE QUANTITY:

DAMAGE UNITS: **LF**

COMMENTS: **NOT OBSERVED in 2016**

Inspector's Signature:



Date: **03/10/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22421** BUILDING ID: **2470**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**
SCHOOL NAME: **Burley School** REVIEW DATE: **5/18/2016**
ADDRESS: **1630 W. Barry Avenue** IDPH LICENSE NO: **100-05183**

HOMOGENEOUS AREA: **B**
MATERIAL DESCRIPTION: **Cardboard Pipe Insulation NOT OBSERVED in 2016**
MATERIAL LOCATION: **Throughout (See Hatching Maps) - 1893 Building
NOT OBSERVED in 2016**
MATERIAL QUANTITY: **717** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **05/18/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22421** BUIDLING ID: **2470**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Delores Fitzpatrick**
SCHOOL NAME: **Burley School** INSPECTION DATE: **3/10/2016**
ADDRESS: **1630 W. Barry Avenue** IDPH LICENSE NO: **100-05183**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **C**
MATERIAL DESCRIPTION: **MJP E/F/V on Cardboard Pipe Insulation NOT OBSERVED in 2016**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with potential for significant damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**

MATERIAL LOCATION: **Throughout (See Hatching Maps) - 1893 Building
NOT OBSERVED in 2016**

MATERIAL QUANTITY: **65** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS: **NOT OBSERVED in 2016**

Inspector's Signature:



Date: **03/10/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22421** BUIDLING ID: **2470**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**
SCHOOL NAME: **Burley School** REVIEW DATE: **5/18/2016**
ADDRESS: **1630 W. Barry Avenue** IDPH LICENSE NO: **100-05183**

HOMOGENEOUS AREA: **C**
MATERIAL DESCRIPTION: **MJP E/F/V on Cardboard Pipe Insulation NOT OBSERVED in 2016**
MATERIAL LOCATION: **Throughout (See Hatching Maps) - 1893 Building
NOT OBSERVED in 2016**
MATERIAL QUANTITY: **65** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **05/18/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22421** BUIDLING ID: **2470**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Delores Fitzpatrick**
SCHOOL NAME: **Burley School** INSPECTION DATE: **3/10/2016**
ADDRESS: **1630 W. Barry Avenue** IDPH LICENSE NO: **100-05183**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **D**
MATERIAL DESCRIPTION: **Mag Block Tank Insulation - NOT OBSERVED in 2016**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **Moderate**

MATERIAL LOCATION: **Engine Room - (1893 Building)**
NOT OBSERVED in 2016

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **NOT OBSERVED in 2016**

Inspector's Signature:



Date: **03/10/2016**

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22421** BUIDLING ID: **2470**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**
SCHOOL NAME: **Burley School** REVIEW DATE: **5/18/2016**
ADDRESS: **1630 W. Barry Avenue** IDPH LICENSE NO: **100-05183**

HOMOGENEOUS AREA: **D**

MATERIAL DESCRIPTION: **Mag Block Tank Insulation - NOT OBSERVED in 2016**

MATERIAL LOCATION: **Engine Room - (1893 Building)**
NOT OBSERVED in 2016

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **05/18/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22421** BUIDLING ID: **2470**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Delores Fitzpatrick**
SCHOOL NAME: **Burley School** INSPECTION DATE: **3/10/2016**
ADDRESS: **1630 W. Barry Avenue** IDPH LICENSE NO: **100-05183**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **E**
MATERIAL DESCRIPTION: **Aircell Pipe Insulation NOT OBSERVED in 2016**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with potential for significant damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**

MATERIAL LOCATION: **Fresh Air Intake & Sprinkler Room - 1893 Building
NOT OBSERVED in 2016**

MATERIAL QUANTITY: **25** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS: **NOT OBSERVED in 2016**

Inspector's Signature: _____



Date: 03/10/2016

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22421** BUIDLING ID: **2470**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**
SCHOOL NAME: **Burley School** REVIEW DATE: **5/18/2016**
ADDRESS: **1630 W. Barry Avenue** IDPH LICENSE NO: **100-05183**

HOMOGENEOUS AREA: **E**
MATERIAL DESCRIPTION: **Aircell Pipe Insulation NOT OBSERVED in 2016**
MATERIAL LOCATION: **Fresh Air Intake & Sprinkler Room - 1893 Building
NOT OBSERVED in 2016**
MATERIAL QUANTITY: **25** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **05/18/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22421** BUIDLING ID: **2470**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Delores Fitzpatrick**
SCHOOL NAME: **Burley School** INSPECTION DATE: **3/10/2016**
ADDRESS: **1630 W. Barry Avenue** IDPH LICENSE NO: **100-05183**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **F**
MATERIAL DESCRIPTION: **Aircell Duct Insulation**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with potential for significant damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**

MATERIAL LOCATION: **East and West Basement Corridors, North Lunchroom, North Office, North Girl's Playroom and North Corridor - 1893 Building**

MATERIAL QUANTITY: **730** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/10/2016**

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22421** BUIDLING ID: **2470**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**
SCHOOL NAME: **Burley School** REVIEW DATE: **5/18/2016**
ADDRESS: **1630 W. Barry Avenue** IDPH LICENSE NO: **100-05183**

HOMOGENEOUS AREA: **F**
MATERIAL DESCRIPTION: **Aircell Duct Insulation**
MATERIAL LOCATION: **East and West Basement Corridors, North Lunchroom, North Office, North Girl's Playroom and North Corridor - 1893 Building**
MATERIAL QUANTITY: **730** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **05/18/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22421** BUIDLING ID: **2470**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Delores Fitzpatrick**
SCHOOL NAME: **Burley School** INSPECTION DATE: **3/10/2016**
ADDRESS: **1630 W. Barry Avenue** IDPH LICENSE NO: **100-05183**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **I**
MATERIAL DESCRIPTION: **MJP E/F/V on Aircell Pipe Insulation NOT OBSERVED in 2016**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**

MATERIAL LOCATION: **Fresh Air Intake & Sprinkler Room - 1893 Building
NOT OBSERVED in 2016**

MATERIAL QUANTITY: **25** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS: **NOT OBSERVED in 2016**

Inspector's Signature:



Date: **03/10/2016**

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22421** BUIDLING ID: **2470**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**
SCHOOL NAME: **Burley School** REVIEW DATE: **5/18/2016**
ADDRESS: **1630 W. Barry Avenue** IDPH LICENSE NO: **100-05183**

HOMOGENEOUS AREA: **I**
MATERIAL DESCRIPTION: **MJP E/F/V on Aircell Pipe Insulation NOT OBSERVED in 2016**
MATERIAL LOCATION: **Fresh Air Intake & Sprinkler Room - 1893 Building
NOT OBSERVED in 2016**
MATERIAL QUANTITY: **25** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **05/18/2016**

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22421** BUIDLING ID: **2470**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Delores Fitzpatrick**
SCHOOL NAME: **Burley School** INSPECTION DATE: **3/10/2016**
ADDRESS: **1630 W. Barry Avenue** IDPH LICENSE NO: **100-05183**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **J**
MATERIAL DESCRIPTION: **Mag Block Pipe Insulation (SprinklerRm & Outside SprinklerRm (NOT OBSERVED,2016); Store Rm (ABATED)**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**

MATERIAL LOCATION: **Sprinkler Rm & Outside Sprinkler Rm (NOT OBSERVED, 2016); Store Rm (ABATED) - 1893 Bldg**

MATERIAL QUANTITY: **9** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: _____



Date: 03/10/2016

Chicago Public Schools

GSG Consultants, Inc.

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22421** BUIDLING ID: **2470**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**
SCHOOL NAME: **Burley School** REVIEW DATE: **5/18/2016**
ADDRESS: **1630 W. Barry Avenue** IDPH LICENSE NO: **100-05183**

HOMOGENEOUS AREA: **J**
MATERIAL DESCRIPTION: **Mag Block Pipe Insulation (SprinklerRm & Outside SprinklerRm (NOT OBSERVED,2016); Store Rm (ABATED)**
MATERIAL LOCATION: **Sprinkler Rm & Outside Sprinkler Rm (NOT OBSERVED, 2016); Store Rm (ABATED) - 1893 Bldg**
MATERIAL QUANTITY: **9** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **05/18/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22421** BUIDLING ID: **2470**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Delores Fitzpatrick**
SCHOOL NAME: **Burley School** INSPECTION DATE: **3/10/2016**
ADDRESS: **1630 W. Barry Avenue** IDPH LICENSE NO: **100-05183**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **K**
MATERIAL DESCRIPTION: **MJP E/F/V on Mag Block Pipe Insulation**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Sprinkler Room and the Storeroom Outside Sprinkler Room - 1893 Building**
MATERIAL QUANTITY: **2** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: _____



Date: 03/10/2016

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22421** BUILDING ID: **2470**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**
SCHOOL NAME: **Burley School** REVIEW DATE: **5/18/2016**
ADDRESS: **1630 W. Barry Avenue** IDPH LICENSE NO: **100-05183**

HOMOGENEOUS AREA: **K**
MATERIAL DESCRIPTION: **MJP E/F/V on Mag Block Pipe Insulation**
MATERIAL LOCATION: **Sprinkler Room and the Storeroom Outside Sprinkler Room - 1893 Building**
MATERIAL QUANTITY: **2** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **05/18/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22421** BUILDING ID: **2470**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Delores Fitzpatrick**
SCHOOL NAME: **Burley School** INSPECTION DATE: **3/10/2016**
ADDRESS: **1630 W. Barry Avenue** IDPH LICENSE NO: **100-05183**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **31**
MATERIAL DESCRIPTION: **12 x 12 Gray w/ White Specks VFT**
MATERIAL LOCATION: **Main Office (First Floor)**
MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**
MATERIAL CATEGORY: **MISC** FRIABLE: **No**
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **MODERATE** CONDITION:
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
ACCESSIBILITY: DAMAGE REASON:
DAMAGE QUANTITY: **0** DAMAGE REASON:
DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____



Date: **03/10/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22421** BUILDING ID: **2470**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**
SCHOOL NAME: **Burley School** REVIEW DATE: **5/18/2016**
ADDRESS: **1630 W. Barry Avenue** IDPH LICENSE NO: **100-05183**

HOMOGENEOUS AREA: **31**
MATERIAL DESCRIPTION: **12 x 12 Gray w/ White Specks VFT**
MATERIAL LOCATION: **Main Office (First Floor)**
MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____



Date: 05/18/2016

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22421** BUILDING ID: **2470**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Delores Fitzpatrick**
SCHOOL NAME: **Burley School** INSPECTION DATE: **3/10/2016**
ADDRESS: **1630 W. Barry Avenue** IDPH LICENSE NO: **100-05183**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **32**
MATERIAL DESCRIPTION: **12 x 12 Gray Specks VFT**
MATERIAL LOCATION: **Conference Room (First Floor)**
MATERIAL QUANTITY: **175** MATERIAL UNITS: **SF**
MATERIAL CATEGORY: **MISC** FRIABLE: **No**
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **MODERATE** CONDITION:
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
ACCESSIBILITY: DAMAGE REASON:
DAMAGE QUANTITY: **0** DAMAGE REASON:
DAMAGE REASON:
DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature:



Date: **03/10/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22421** BUILDING ID: **2470**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**
SCHOOL NAME: **Burley School** REVIEW DATE: **5/18/2016**
ADDRESS: **1630 W. Barry Avenue** IDPH LICENSE NO: **100-05183**

HOMOGENEOUS AREA: **32**
MATERIAL DESCRIPTION: **12 x 12 Gray Specks VFT**
MATERIAL LOCATION: **Conference Room (First Floor)**
MATERIAL QUANTITY: **175** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____



Date: 05/18/2016

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22421** BUILDING ID: **2470**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Delores Fitzpatrick**
SCHOOL NAME: **Burley School** INSPECTION DATE: **3/10/2016**
ADDRESS: **1630 W. Barry Avenue** IDPH LICENSE NO: **100-05183**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **29**
MATERIAL DESCRIPTION: **12 x 12 White VFT**
MATERIAL LOCATION: **Corridor 1st Floor**
MATERIAL QUANTITY: **7000** MATERIAL UNITS: **SF**
MATERIAL CATEGORY: **MISC** FRIABLE: **No**
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **MODERATE** CONDITION:
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
ACCESSIBILITY: DAMAGE REASON:
DAMAGE QUANTITY: **0** DAMAGE REASON:
DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____



Date: 03/10/2016

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22421** BUILDING ID: **2470**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**
SCHOOL NAME: **Burley School** REVIEW DATE: **5/18/2016**
ADDRESS: **1630 W. Barry Avenue** IDPH LICENSE NO: **100-05183**

HOMOGENEOUS AREA: **29**
MATERIAL DESCRIPTION: **12 x 12 White VFT**
MATERIAL LOCATION: **Corridor 1st Floor**
MATERIAL QUANTITY: **7000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____



Date: 05/18/2016

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

| | | | | | |
|--------------|------------------------|------------------|---------------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 22421 | BUILDING ID: | 2470 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Delores Fitzpatrick | | |
| SCHOOL NAME: | Burley School | INSPECTION DATE: | 3/10/2016 | | |
| ADDRESS: | 1630 W. Barry Avenue | IDPH LICENSE NO: | 100-05183 | | |

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: 30

MATERIAL DESCRIPTION: 12 x 12 White VFT

MATERIAL LOCATION: Lunch Room (Basement)

MATERIAL QUANTITY: 350 MATERIAL UNITS: SF

MATERIAL CATEGORY: MISC FRIABLE: No

ASBESTOS TYPE: Assumed

DISTURBANCE POTENTIAL: MODERATE CONDITION:

AHERA DAMAGE CATEGORY: 6 ACBM with the potential for damage

ACCESSIBILITY: DAMAGE REASON:
DAMAGE REASON:
DAMAGE REASON:

DAMAGE QUANTITY: 0 DAMAGE UNITS: SF

COMMENTS:

Inspector's Signature: _____



Date: 03/10/2016 _____

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22421** BUILDING ID: **2470**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**
SCHOOL NAME: **Burley School** REVIEW DATE: **5/18/2016**
ADDRESS: **1630 W. Barry Avenue** IDPH LICENSE NO: **100-05183**

HOMOGENEOUS AREA: **30**
MATERIAL DESCRIPTION: **12 x 12 White VFT**
MATERIAL LOCATION: **Lunch Room (Basement)**
MATERIAL QUANTITY: **350** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____



Date: 05/18/2016

APPENDIX B

Inspector and Management Planner Licenses

CERTIFICATE OF ACHIEVEMENT ASBESTOS ABATEMENT

Accredited by the Illinois Department of Public Health

This is to certify that DELORES FITZPATRICK
has completed the ASBESTOS INSPECTOR'S REFRESHER course and successfully passed the
examination on 02/16/2013 with a minimum score of 70% or better. Training was in accordance
with U.S. E.P.A. 40 CFR 763 Subpart E, Appendix C, Asbestos Containing Materials in Schools:
Model Accreditation Plan, TSCA II, Authorized by both AHERA & ASHARA.



N. Kennedy

02/16/2013
Course Dates: _____
02/16/2014
Expires: _____
1302BIR20
Certificate Number: _____

Director of Training
Nicholas J. Penell
Doctor of Public Health
Phone Number: (312) 491-4081
FORM # A-010



525-535 West Jefferson Street • Springfield, Illinois 62761-0001 • www.dph.illinois.gov



4/20/2016

DELORES FITZPATRICK
855 WEST ADAMS, SUITE 200
CHICAGO, IL 60607

ASBESTOS PROFESSIONAL LICENSE ID NUMBER: 05183

Enclosed is your Asbestos Professional License. Please note the expiration date on the card and in the image depicted below.

COPY OF THE ASBESTOS PROFESSIONAL LICENSE

| Front of License | | | Back of License | |
|---|----------------------------|------------------------------|---|--|
|  | | | ASBESTOS PROFESSIONAL LICENSE | |
| ID NUMBER TC0 - 05183 | ISSUED 4/20/2016 | EXPIRES 05/15/2017 | ENDORSEMENTS INSPECTOR | TC EXPIRES 2/13/2017 |
| DELORES FITZPATRICK 855 WEST ADAMS, SUITE 200 CHICAGO, IL 60607 Environmental Health | | |  | PROJECT MANAGER 2/6/2017 AIR SAMPLING PROFESSIONAL |
| Alteration of this license shall result in legal action This license issued under authority of the State of Illinois Department of Public Health This license is valid only when accompanied by a valid training course certificate. | | | | |

If you have any questions or need further assistance, contact the Asbestos Program at (217)782-3517 or fax (217)785-5897.

Our WEB address is: dph.illinois.gov/topics-services/environmental-health-protection/asbestos
EMAIL Address: dph.asbestos@illinois.gov

PROTECTING HEALTH, IMPROVING LIVES
Nationally Accredited by NABE

CERTIFICATE OF ACHIEVEMENT ASBESTOS ABATEMENT

Accredited by the Illinois Department of Public Health

This is to certify that GUILLERMO GARCIA
has completed the Asbestos Management Planner Refresher course and passed the examination
on 03/21/2016 with a minimum score of 70% or better. Training was in accordance with U.S.
E.P.A. 40 CFR 763 Subpart E, Appendix C, Asbestos Containing Materials in Schools: Model
Accreditation Plan, TSCA II, Authorized by both AHERA & ASHARA.

03/21/2016

Course Dates:

03/21/2017

Expires:

1603MPR02

Certificate Number:



PUBLIC HEALTH & SAFETY inc.

Environmental and Occupational Services
105 S. Ashland Ave., Chicago, IL 60607

Nicholas J. Penoff

Director of Training

Nicholas J. Penoff

Doctor of Public Health

Phone: 312-491-0081

FORM # A-011



525-535 West Jefferson Street • Springfield, Illinois 62761-0001 • www.dph.illinois.gov

4/20/2016

GUILLERMO GARCIA
855 W ADAMS ST SUITE 100
CHICAGO, IL 60607

ASBESTOS PROFESSIONAL LICENSE ID NUMBER: 01786

Enclosed is your Asbestos Professional License. Please note the expiration date on the card and in the image depicted below.

COPY OF THE ASBESTOS PROFESSIONAL LICENSE

Front of License

Back of License

| | | | | |
|--|----------------------------|--|--|-----------------------|
|  ASBESTOS PROFESSIONAL LICENSE | | | ENDORSEMENTS | TC EXPIRES |
| ID NUMBER 100 - 01733 | ISSUED 4/20/2016 | EXPIRES 05/15/2017 | INSPECTOR | 3/21/2017 |
| GUILLERMO GARCIA 855 W ADAMS ST SUITE 100 CHICAGO, IL 60607 Environmental Health | |  | MANAGEMENT PLANNER PROJECT MANAGER AIR SAMPLING PROFESSIONAL | 3/21/2017 2/6/2017 |
| | | | Alteration of this license shall result in legal action This license issued under authority of the State of Illinois Department of Public Health This license is valid only when accompanied by a valid training course certificate. | |

If you have any questions or need further assistance, contact the Asbestos Program at (217)782-3517 or fax (217)785-5897.

Our WEB address is: dph.illinois.gov/topics-services/environmental-health-protection/asbestos
EMAIL Address: dph.asbestos@illinois.gov

PROTECTING HEALTH, IMPROVING LIVES
Nationally Accredited by PHAB

APPENDIX C

Laboratory Accreditations

APPENDIX D

Laboratory Results

APPENDIX E

Chain of Custody Forms

Three-Year Reinspection Key to Terms

| | CODE | KEY |
|--------------------------|-------------|--|
| MATERIAL | | |
| | ACBM | Asbestos Containing Building Materials |
| MATERIAL CATEGORY | | |
| | MISC | Miscellaneous |
| | SURF | Surfacing |
| | TSI | Thermal System Insulation |
| MATERIAL UNITS | | |
| | LF | Linear Feet |
| | SF | Square Feet |
| | CF | Cubic Feet |
| DAMAGE TYPE | | |
| | Loc | Localized |
| | Dist | Distributed |