

ILLINOIS DEPARTMENT OF PUBLIC HEALTH  
AHERA THREE YEAR REINSPECTION  
ASBESTOS ABATEMENT PROGRAM  
SCHOOL INFORMATION FORM

**SECTION I**

NAME OF SCHOOL DISTRICT: CHICAGO SCHOOL DIST 299  
SCHOOL ID NUMBER: 14-016-2990-2876  
SCHOOL NAME: Carson School, Rachel  
ADDRESS OF SCHOOL: 5516 S. Maplewood Ave.  
CITY: Chicago, IL, 60629

DATE LAST THREE YEAR REINSPECTION WAS COMPLETED **3/21/2013**

**If the address on this form is different than the address of the building, submit a written explanation.**

**SECTION II** (Please type or print)

PLEASE COMPLETE THE FOLLOWING FOR YOUR THREE YEAR REINSPECTION:

DATE REINSPECTION COMPLETED: 4/4/2016 ENROLLMENT 1078  
IDPH INSPECTOR LICENSE NUMBER: 100-02865  
IDPH LICENSED INSPECTOR NAME (Please Print): Steven Doran  
IDPH MP LICENSE NUMBER: 100-19466  
IDPH LICENSED MANAGEMENT PLANNER NAME (Please Print): Evan Christian

DESIGNATED PERSON (Please Print): Robert Christlieb PHONE: (773) 553-3197



4/4/2016

Signature of Designated Person

Date

**SECTION III**

PLEASE COMPLETE THE FOLLOWING INFORMATION FOR ANY CHANGES WITHIN THE SCHOOL DISTRICT.

School building has been sold. Date of Sale: \_\_\_\_\_

School has been closed. Date closed: \_\_\_\_\_

School building has been demolished. Date: \_\_\_\_\_

School building is asbestos free since last reinspection: \_\_\_\_\_

**Please explain in writing why the school building is now asbestos free and include the supporting documentation.**

If a new school building has been added to the district, submit either an exclusionary statement or a management plan and inspection report. Include the complete name, address and city of school building.

**Explain in writing if the address of the building is different than the address on this form:**

**THREE-YEAR REINSPECTION**

**CHICAGO SCHOOL DIST 299**

**Carson School, Rachel**

5516 S. Maplewood Ave.  
Chicago, IL, 60629

Unit: 22601  
Building ID: 2660

IDPH ID Number: 14-016-2990-2876

**REPORT DATE:**

Monday, April 04, 2016

**Prepared for:**

**Chicago Public Schools**  
**125 S. Clark Street**  
**Chicago, IL 60603**

**Prepared by:**

**Carnow, Conibear and Associates**

600 West Van Buren St., Ste 500

Phone (312) 762-2900

Fax (312) 782-5145

**DO NOT REMOVE FROM SCHOOL  
REQUIRED BY FEDERAL LAW**

March 10, 2016

Mr. R. Kent Cook  
Asbestos Program  
Illinois Department of Public Health  
525 West Jefferson Street  
Springfield, Illinois 62761

Re: Chicago Public Schools - 2016 Three-Year Reinspections

Dear Mr. Cook:

Carnow, Conibear and Associates, Managing Environmental Consultant (MEC), conducted the Three-Year Reinspections and performed management plan updates for the Chicago Public Schools (CPS) facilities in Region 3,4,5 Elementary Schools. Please update your records with the following information.

School District: 299                      Unit: 22601                      Region: 04                      IDPH ID: 14-016-2990-2876

School: Carson School, Rachel                      Building ID: 2660

Address: 5516 S. Maplewood Ave.

Chicago, IL, 60629

Building Contact: Cain, Kevin

Contact Phone: 773-844-7967

Current Building Owners: Chicago Public Schools

Review Date: 04/04/2016

Inspector: Steven Doran

Inspector IDPH License: 100-02865

Management Planner: Evan Christian

Management Planner IDPH License: 100-19466

If you have any questions or comments, please contact us at (312) 762-2900

Sincerely,  
Carnow, Conibear and Associates

Evan Christian  
100-19466

## **Environmental Notification to Occupants**

To: Faculty, Staff and Parents  
From: Chicago Public Schools  
Date: March 10, 2016

RE: Carson School, Rachel, Unit 22601  
5516 S. Maplewood Ave.  
Chicago, IL, 60629

Dear Faculty, Staff and Parents,

This letter is to notify you that the 2016 asbestos three year re-inspection has been completed at Carson School, Rachel , following the Federal Asbestos Hazard Emergency Response Act (AHERA), 40 CFR Part 763, Subpart E and is available for your review at the main office of the school.

Although asbestos-containing materials have been identified at Carson School, Rachel, there is no reason to believe that any threat to the health of students or staff exists at this time. CPS will continue to carefully monitor the condition of asbestos-containing materials and if conditions warrant, all appropriate steps will be taken to maintain the health and safety of all building occupants.

If you have any questions regarding this matter or require additional information, please feel free to contact Robert Christlieb, the designated Local Education Authority's Designated Person at (773) 553-3197 .

## **Table of Contents**

- I. School and Inspection Information
- II. Executive Summary
- III. Methodology
- IV. Abatement History
- V. Reassessments and Recommendations
- VI. Conclusions

Table I: Inspector's Reinspection Findings

Table II: Management Planner's Review

### **APPENDICES:**

- Appendix A: Assessment Sheets, Drawings and Photos
- Appendix B: Inspector and Management Planner Licenses
- Appendix C: Laboratory Accreditations
- Appendix D: Laboratory Results
- Appendix E: Chain of Custody Forms

## SCHOOL AND INSPECTION INFORMATION

### 1. School Information

School: Carson School, Rachel Unit: 22601 Region: 04  
Address: 5516 S. Maplewood Ave. Chicago, IL, 60629  
IDPH ID: 14-016-2990-2876 Building ID: 2660  
Contact: Cain, Kevin Phone: 773-844-7967

### 2. Description of Facility

Original Construction: 1917 Additional Construction:  
Total Square Footage: 62635 No of Floors: 3  
Current Occupancy: 1078

### 3. LEA Designated Person

Contact: Robert Christlieb Phone: (773) 553-3197  
Address: 125 South Clark Street, 17th Floor  
Chicago, IL 60603


### 4. Managing Environmental Consultant

MEC: Carnow, Conibear and Associates  
Contact: Dan Juneau  
Address 600 West Van Buren St., Ste 500  
Phone: (312) 762-2900 Fax: (312) 782-5145

### 5. Inspector

Inspector Name: Steven Doran

Inspector IDPH license # 100-02865

Signature:   
Date: 3/10/2016

### 6. Management Planner

Management Planner Name: Evan Christian

Management Planner IDPH license # 100-19466

Signature:  
Date: 04/04/2016

### 7. Review Date: 04/04/2016

### 8. LEA Designated Person's Acknowledgement

The reinspection report and recommendations have been received by me and appropriate action will be taken by the School District.

Signature: 

Date: 4/4/2016

Name: Robert Christlieb

## II. EXECUTIVE SUMMARY

Carnow, Conibear and Associates was retained by the Chicago Public Schools (CPS) to perform a three-year asbestos reinspection of the Carson School, Rachel. This inspection was conducted in accordance with the United States Environmental Protection Agency (USEPA) Asbestos Hazard Emergency Response Act (AHERA) part 763.92 (b), and the ongoing Operations and Maintenance Program (O&M) originally designed in the School's Asbestos Management Plan. The purpose of this three-year reinspection is to record any condition changes in the asbestos-containing building material (ACBM) in the school since the previous three-year reinspection and the six-month periodic surveillance, to identify, assess, and include any Homogeneous Areas (HA) not identified in the Management Plan, and to recommend an appropriate response action to manage asbestos.

The inspector conducted a three-year reinspection of this facility under Illinois Department of Public Health (IDPH) school reinspection requirements and AHERA, sections 763.85 and 763.88. The main building and each addition to the main building, if constructed at different dates, were inspected separately. Laboratory accreditations are included in Appendix C, laboratory results are included in Appendix D, and chain of custody forms are included in Appendix E.

Note: During previous inspections, some of the HA(s) were identified together as 9" x 9" floor tile (FT), mastics assoc. with 9" x 9" FT, 12" x 12" FT, mastics assoc. with 12" x 12" FT, pipe insulation, etc. Some of these HA(s) have been re-identified by areas that are uniform in color, texture, construction date, application date, and general appearance.

The inspector has determined the following:

A. The following HAs have changed assessment categories for Building 2660:

08	9x9 dark maroon w/white & red streaks floor tile
37	thermal aircell pipe insulation
39	thermal paperwrap pipe insulation
52	Plaster Walls
53	Plaster Ceilings
68	2x4 ceiling tile white w/Pinhole & worm
69	12x12 Off White w/Brown Floor Tile
71	12x12 Dark Brown w/Orange & White Floor Tile
73	12" x 12" White Floor Tile

74	Mastic Associated w/ 12" x 12" White Floor Tile
75	2' x 4' Smooth Ceiling Tile
76	4" x 4" Red Ceramic Tile w/ Grout
77	Mastic Associated w/ 4" x 4" Red Ceramic Tile w/ Grout
FT-1	12x12 white floor tile



B. The following new homogenous areas have been identified for Building 2660:

73	12" x 12" White Floor Tile
74	Mastic Associated w/ 12" x 12" White Floor Tile
75	2' x 4' Smooth Ceiling Tile
76	4" x 4" Red Ceramic Tile w/ Grout
77	Mastic Associated w/ 4" x 4" Red Ceramic Tile w/ Grout

C. This reinspection covered only physically accessible and visible areas and materials that were identified in the LEA's management plan. The following materials were concealed and/or contained in areas that were inaccessible for sampling and have been classified as Assumed:

37	thermal aircell pipe insulation
38	joint compound elbows on aircell pipe runs
39	thermal paperwrap pipe insulation
40	joint compound elbows on paperwrap pipe runs
44	12x12 Blue floor tile
45	12x12 Lt Blue w/White Floor Tile
46	12x12 Lt Blue w/White Floor Tile Mastic
47	12x12 Lt Grey w/ Dark Grey & White Floor Tile
48	12x12 Lt Grey w/ Dark Grey & White Floor Tile Mastic
49	12x12 Dk Grey w/lit grey floor tile
50	12x12 Dk grey w/ lt grey floor tile mastic
51	safe door insulation
52	Plaster Walls
53	Plaster Ceilings
54	12x12 Lt Brown w/Dark Brown & White Floor Tile
55	12x12 Lt Brown w/Dark Brown & White Floor Tile Mastic
56	12x12 White w/ Lt Brown & Dark Brown floor tile
57	12x12 White w/ Lt Brown & Dark Brown floor tile Mastic
58	Burlap Wall Covering
59	12x12 lt green w/Dk green & white floor tile
60	12x12 lt green w/Dk green & white floor tile mastic
61	Brown Carpet Adhesive
62	12x12 Brown w/Dark Brown & White Floor Tile
63	12x12 Brown w/Dark Brown & White Floor Tile mastic
64	12x12 dark brown w/White Pitted Floor Tile
65	12x12 dark brown w/White Pitted Floor Tile mastic
66	12x12 Purple w/ Dark Purple & White Floor Tile
67	12x12 Purple w/ Dark Purple & White Floor Tile Mastic
68	2x4 ceiling tile white w/Pinhole & worm
69	12x12 Off White w/Brown Floor Tile
70	12x12 Off White w/Brown Floor Tile Mastic
71	12x12 Dark Brown w/Orange & White Floor Tile
72	12x12 Dark Brown w/Orange & White Floor Tile Mastic
73	12" x 12" White Floor Tile
74	Mastic Associated w/ 12" x 12" White Floor Tile
75	2' x 4' Smooth Ceiling Tile

76	4" x 4" Red Ceramic Tile w/ Grout
77	Mastic Associated w/ 4" x 4" Red Ceramic Tile w/ Grout
BB-1	4" baseboard
BB-2	6" baseboard
BBM-1	4" baseboard mastic
FT-1	12x12 white floor tile
FTM-1	12x12 white floor tile mastic

The following areas were deemed to be inaccessible:

36	joint compound elbows on fiberglass pipe runs
37	thermal aircell pipe insulation
38	joint compound elbows on aircell pipe runs
39	thermal paperwrap pipe insulation
40	joint compound elbows on paperwrap pipe runs
41	boiler gasket
43	mastic
46	12x12 Lt Blue w/White Floor Tile Mastic
48	12x12 Lt Grey w/ Dark Grey & White Floor Tile Mastic
50	12x12 Dk grey w/ Lt grey floor tile mastic
55	12x12 Lt Brown w/Dark Brown & White Floor Tile Mastic
57	12x12 White w/ Lt Brown & Dark Brown floor tile Mastic
60	12x12 lt green w/Dk green & white floor tile mastic
63	12x12 Brown w/Dark Brown & White Floor Tile mastic
65	12x12 dark brown w/White Pitted Floor Tile mastic
67	12x12 Purple w/ Dark Purple & White Floor Tile Mastic
70	12x12 Off White w/Brown Floor Tile Mastic
72	12x12 Dark Brown w/Orange & White Floor Tile Mastic
74	Mastic Associated w/ 12" x 12" White Floor Tile
77	Mastic Associated w/ 4" x 4" Red Ceramic Tile w/ Grout
BBM-1	4" baseboard mastic
BBM-2	6" baseboard mastic
FTM-1	12x12 white floor tile mastic

Materials were also listed as "assumed" if they were in good condition and sampling was not conducted to avoid damage.

This reinspection was conducted by Steven Doran, IDPH License # 100-02865. The Management Plan was updated by Evan Christian, IDPH License # 100-19466. Inspector and Management Planner Licenses are included in Appendix B.

### **III. METHODOLOGY**

Tasks performed on-site included the following:

1. Review current management plan, identify HA(s) and extract appropriate information.
2. Examine and verify abatement records.
3. Touch and visually and physically reinspect and reassess the condition of all friable known or assumed ACBM.
4. Touch and visually and physically reinspect all non-friable known or assumed ACBM to determine whether these materials have become friable since the last inspection or periodic surveillance.
5. Identify any condition changes that may affect Hazard Ranking of known ACBM or Assumed ACBM, as well as any HA(s) that have become friable since the last reinspection.
6. Collect bulk samples from each newly discovered friable HA or previously assumed and submit for laboratory analysis.
7. Tabulate reinspection findings and submit for management planner review and recommendations with appropriate response actions based on the AHERA Damage Category of the ACBM.
8. Submit reinspection findings and management planner recommendations to the LEA within thirty (30) days for inclusion into the management plan.

### **IV. ABATEMENT HISTORY**

The information collected from the existing management plan and inspection report(s) and from interviews with the school official revealed that the following asbestos abatement was conducted at the school since the previous Three year Reinspection.

Abatement Dates:

### **V. REASSESSMENTS AND RECOMMENDATIONS**

The reassessments and recommendations are summarized in Tables I and II on the following pages. Detailed Hazard Assessment Sheets and Drawings and Photos (if applicable) are included in Appendix A.

### **VI. CONCLUSIONS**

The Carson School, Rachel Building 2660 Three-Year reinspection has been completed and response actions have been recommended for both friable and non-friable materials. A timely execution of the response actions recommended will enable the LEA and the Designated Person(s) to effectively manage the existing ACBM.

This three-year reinspection report should be inspected in the current Management plan at the CPS Central Office, and one (1) copy should be kept at the school for use when planning any renovation and/or demolition activities in areas where ACBM has been identified. Also, periodic surveillance documentation and any summary reports from any response actions that are executed at the school should be used to update the Management Plan.

**Table I**  
**Inspector's Reinspection Findings**

---

# Chicago Public Schools

School Carson School, Rachel Unit 22601 Building ID 2660

Address 5516 S. Maplewood Ave. Region 04

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
02	9x9 tan w/brown & white streaks floor tile	7,200	SF	2nd and 3rd corridors, 2nd Floor Storage	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
03	12x12 dark brown floor tile	1,590	SF	1st Floor Corridors	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
08	9x9 dark maroon w/white & red streaks floor tile	157	SF	engineers office,kitchen,entry to washrooms	CHR	MISC	N	LOC	10		Yes	ACBM with the potential for damage	3	LOW
09	9x9 tan w/white streaks floor tile			biology room 310 - ABATED	ABATED	MISC								
14	9x9 white w/black streaks floor tile, Covered by wood laminate			main office	CHR	MISC								
15	9x9 black w/white streaks floor tile			engineers office, main office	CHR	MISC								
16	8x24 black floor tile			main office	CHR	MISC								
18	9x9 green w/black & white streaks floor tile			study hall room 100	CHR	MISC								
19	9x9 dark green w/white streaks floor tile			north side study hall room 100	CHR	MISC								
23	9x9 light tan w/brown & white streaks floor tile			1st floor corridor - ABATED	ABATED	MISC								
24	15x24 reddish-brown floor tile			1st floor corridor - ABATED	ABATED	MISC								
25	9x9 brown w/gold & white streaks floor tile			1st floor corridor - ABATED	ABATED	MISC		None						
26	black transite countertops			science rooms 309	CHR	MISC								
36	joint compound elbows on fiberglass pipe runs	1,000	LF	throughout	CHR	TSI	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
37	thermal aircell pipe insulation	303	LF	1st floor	ASSUMED	TSI	Y	NONE	0		Yes	Any remaining friable ACBM or friable suspect ACBM		LOW
38	joint compound elbows on aircell pipe runs	60	LF	1st floor	ASSUMED	TSI	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
39	thermal paperwrap pipe insulation	152	LF	1st floor	ASSUMED	TSI	Y	NONE	0		Yes	Any remaining friable ACBM or friable suspect ACBM		LOW
40	joint compound elbows on paperwrap pipe runs	40	LF	1st floor	ASSUMED	TSI	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
41	boiler gasket	22	SF	boiler room	CHR	TSI	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
43	mastic	16,000	SF	1st, 2nd, and 3rd	CHR	MISC	N	NONE	0		No	ACBM with the		LOW

# Chicago Public Schools

School Carson School, Rachel Unit 22601 Building ID 2660

Address 5516 S. Maplewood Ave. Region 04

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				Floor Corridors and Rooms								potential for damage		
44	12x12 Blue floor tile			Study Hall Room 100	ASSUMED	MISC								
45	12x12 Lt Blue w/White Floor Tile	6,400	SF	Rooms 309, 303, 308, 304, 206, 101, 110	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
46	12x12 Lt Blue w/White Floor Tile Mastic	6,400	SF	Rooms 309, 303, 308, 304, 206, 101, 110	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
47	12x12 Lt Grey w/ Dark Grey & White Floor Tile	3,600	SF	Rooms 302, 307, 305, 205	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
48	12x12 Lt Grey w/ Dark Grey & White Floor Tile Mastic	3,600	SF	Rooms 302, 307, 305, 205	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
49	12x12 Dk Grey w/l grey floor tile	1,800	SF	rooms 306, 208	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
50	12x12 Dk grey w/ lt grey floor tile mastic	1,800	SF	rooms 306, 208	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
51	safe door insulation	40	SF	3rd Floor Adjacent to rm 301	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
52	Plaster Walls	20,000	SF	Throughout	ASSUMED	SURFACE	Y	NONE	0		Yes	ACBM with the potential for damage		LOW
53	Plaster Ceilings	8,000	SF	Throughout	ASSUMED	SURFACE	Y	NONE	0		Yes	Any remaining friable ACBM or friable suspect ACBM		LOW
54	12x12 Lt Brown w/Dark Brown & White Floor Tile	1,000	SF	Rm 201, 207	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
55	12x12 Lt Brown w/Dark Brown & White Floor Tile Mastic	1,000	SF	Rm 201, 207	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
56	12x12 White w/ Lt Brown & Dark Brown floor tile	1,100	SF	Rm 201, 207; Adj to office & copy room	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
57	12x12 White w/ Lt Brown & Dark Brown floor tile Mastic	1,300	SF	Rm 201, 207; Adj to office & copy room	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
58	Burlap Wall Covering	2,300	SF	rm 208	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
59	12x12 lt green w/Dk green & white floor tile	1,800	SF	Room 202, 210	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
60	12x12 lt green w/Dk green & white floor tile mastic	1,800	SF	rm 202, 210	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
61	Brown Carpet Adhesive			Principals Office	ASSUMED	MISC								
62	12x12 Brown w/Dark Brown & White Floor Tile	4,200	SF	1st Floor North Corridor, Rooms 101 and 110	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
63	12x12 Brown w/Dark Brown & White	4,200	SF	1st Floor North	ASSUMED	MISC	N	NONE	0		No	ACBM with the		LOW



# Chicago Public Schools

School Carson School, Rachel Unit 22601 Building ID 2660

Address 5516 S. Maplewood Ave. Region 04

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
	Floor Tile mastic			Corridor, Rooms 101 and 110								potential for damage		
64	12x12 dark brown w/White Pitted Floor Tile	720	SF	Ramps adj to gym	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
65	12x12 dark brown w/White Pitted Floor Tile mastic	720	SF	ramps adj to gym	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
66	12x12 Purple w/ Dark Purple & White Floor Tile	1,200	SF	auditorium	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
67	12x12 Purple w/ Dark Purple & White Floor Tile Mastic	1,200	SF	auditorium	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
68	2x4 ceiling tile white w/Pinhole & worm	3,000	SF	Auditorium	ASSUMED	MISC	Y	NONE	0		Yes	Any remaining friable ACBM or friable suspect ACBM		LOW
69	12x12 Off White w/Brown Floor Tile	950	SF	café & Kitchen	ASSUMED	MISC	N	DIST	55		Yes	ACBM with the potential for damage	3	LOW
70	12x12 Off White w/Brown Floor Tile Mastic	950	SF	Café & Kitchen	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
71	12x12 Dark Brown w/Orange & White Floor Tile	950	SF	Café & Kitchen	ASSUMED	MISC	N	DIST	10		Yes	ACBM with the potential for damage	3	LOW
72	12x12 Dark Brown w/Orange & White Floor Tile Mastic	950	SF	café & kitchen	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
73	12" x 12" White Floor Tile	960	SF	South Corridor near Elevators on 1st, 2nd, and 3rd Floor	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
74	Mastic Associated w/ 12" x 12" White Floor Tile	960	SF	South Corridor near Elevators on 1st, 2nd, and 3rd Floor	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
75	2' x 4' Smooth Ceiling Tile	2,700	SF	Rooms 203, 204, and 206	ASSUMED	MISC	Y	NONE	0		Yes	Any remaining friable ACBM or friable suspect ACBM		LOW
76	4" x 4" Red Ceramic Tile w/ Grout	250	SF	East Foyer Entrance near Assistant Principal's Office, Lunch Room	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
77	Mastic Associated w/ 4" x 4" Red Ceramic Tile w/ Grout	250	SF	East Foyer Entrance near Assistant Principal's Office, Lunch Room	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
BB-1	4" baseboard	2,500	LF	classrooms 3rd & 2nd, cafeteria	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
BB-2	6" baseboard	800	LF	room 303, 402	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
BBM-1	4" baseboard mastic	2,500	LF	classrooms 3rd & 2nd, cafeteria	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW

# Chicago Public Schools

School Carson School, Rachel Unit 22601 Building ID 2660

Address 5516 S. Maplewood Ave. Region 04

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
BBM-2	6" baseboard mastic	800	LF	room 303	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
FT-1	12x12 white floor tile	2,200	SF	room 200,203,209, copy rm. Kit. Storage, Teachers Lounge	ASSUMED	MISC	N	LOC	8		Yes	ACBM with the potential for damage	3	LOW
FTM-1	12x12 white floor tile mastic	2,200	SF	room 200, 203,209,copy room, kit. Storage, teachers lounge	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW

# Chicago Public Schools

School Carson School, Rachel Unit 22601 Building ID 2660

Address 5516 S. Maplewood Ave. Region 04

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

*Inspector's Comments are Summarized at the End of the Report*

Reinspection Date <b>3/10/2016</b>
Inspector Name <b>Steven Doran</b>
<b>100-02865</b> <b>5/15/2016</b>
Inspector's IDPH License Number / Expiration Date

### Inspector's Comments

HA Number:	Inspector Comments:
02	
03	
08	Damage is located in the Engineer's Office
09	
14	Not observed 2016
15	Not observed 2016 - Covered by wood laminate flooring
16	Not observed 2016 - Covered by wood laminate flooring
18	Not observed 2016
19	Not observed 2016
23	
24	
25	
26	Not observed 2016
36	
37	
38	
39	
40	
41	
43	
44	Not observed 2016
45	
46	
47	

# Chicago Public Schools

School Carson School, Rachel Unit 22601 Building ID 2660

Address 5516 S. Maplewood Ave. Region 04

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

*Inspector's Comments are Summarized at the End of the Report*

---

HA Number:	Inspector Comments:
48	
49	
50	
51	
52	
53	
54	Not observed 2016 - Room 402 is now wood flooring
55	Not observed 2016 - Room 402 is now wood flooring
56	Not observed 2016 - Room 402 is now wood flooring
57	Not observed 2016 - Room 402 is now wood flooring
58	
59	
60	
61	Not observed 2016 - Now wood floor
62	
63	
64	
65	
66	
67	
68	
69	Damage is located in the Cafe (10SF) and the Kitchen (45SF)
70	
71	Damage is located in the Cafe (5SF) and Kitchen (5SF)
72	
73	
74	
75	
76	

# Chicago Public Schools

**School** Carson School, Rachel **Unit** 22601 **Building ID** 2660

**Address** 5516 S. Maplewood Ave. **Region** 04

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

*Inspector's Comments are Summarized at the End of the Report*

---

HA Number:	Inspector Comments:
77	
BB-1	
BB-2	
BBM-1	
BBM-2	
FT-1	Damage is located in Room 200
FTM-1	

**Table II**

**Management Planner's Review**

---

# Chicago Public Schools

**School** Carson School, Rachel  
**Address** 5516 S. Maplewood Ave.

**Unit** 22601  
 Chicago, IL, 60629

**Building ID** 2660  
**Region** 04

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

### Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
02	9x9 tan w/brown & white streaks floor tile	7,200	SF	2nd and 3rd corridors, 2nd Floor Storage	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
03	12x12 dark brown floor tile	1,590	SF	1st Floor Corridors	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
08	9x9 dark maroon w/white & red streaks floor tile	157	SF	engineers office, kitchen, entry to washrooms	Chrysotile	MISC	No	10	SF	6 ACBM with the potential for damage	Repair
09	9x9 tan w/white streaks floor tile			biology room 310 - ABATED	Abated	MISC					
14	9x9 white w/black streaks floor tile, Covered by wood laminate			main office	Chrysotile	MISC					Follow O&M Plan
15	9x9 black w/white streaks floor tile			engineers office, main office	Chrysotile	MISC					Follow O&M Plan
16	8x24 black floor tile			main office	Chrysotile	MISC					Follow O&M Plan
18	9x9 green w/black & white streaks floor tile			study hall room 100	Chrysotile	MISC					Follow O&M Plan
19	9x9 dark green w/white streaks floor tile			north side study hall room 100	Chrysotile	MISC					Follow O&M Plan
23	9x9 light tan w/brown & white streaks floor tile			1st floor corridor - ABATED	Abated	MISC					
24	15x24 reddish-brown floor tile			1st floor corridor - ABATED	Abated	MISC					
25	9x9 brown w/gold & white streaks floor tile			1st floor corridor - ABATED	Abated	MISC					
26	black transite countertops			science rooms 309	Chrysotile	MISC					Follow O&M Plan
36	joint compound elbows on fiberglass pipe runs	1,000	LF	throughout	Chrysotile	TSI	Yes	0	LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
37	thermal aircell pipe insulation	303	LF	1st floor	Assumed	TSI	Yes	0	LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
38	joint compound elbows on aircell pipe runs	60	LF	1st floor	Assumed	TSI	Yes	0	LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
39	thermal paperwrap pipe insulation	152	LF	1st floor	Assumed	TSI	Yes	0	LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
40	joint compound elbows on paperwrap pipe runs	40	LF	1st floor	Assumed	TSI	Yes	0	LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
41	boiler gasket	22	SF	boiler room	Chrysotile	TSI	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
43	mastic	16,000	SF	1st, 2nd, and 3rd Floor Corridors and Rooms	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
44	12x12 Blue floor tile			Study Hall Room 100	Assumed	MISC					Follow O&M Plan
45	12x12 Lt Blue w/White Floor Tile	6,400	SF	Rooms 309, 303, 308, 304, 206, 101, 110	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
46	12x12 Lt Blue w/White Floor Tile Mastic	6,400	SF	Rooms 309, 303, 308, 304, 206, 101, 110	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
47	12x12 Lt Grey w/ Dark Grey & White Floor Tile	3,600	SF	Rooms 302, 307, 305, 205	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

# Chicago Public Schools

**School** Carson School, Rachel  
**Address** 5516 S. Maplewood Ave.

**Unit** 22601  
Chicago, IL, 60629

**Building ID** 2660  
**Region** 04

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

### Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
48	12x12 Lt Grey w/ Dark Grey & White Floor Tile Mastic	3,600	SF	Rooms 302, 307, 305, 205	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
49	12x12 Dk Grey w/l grey floor tile	1,800	SF	rooms 306, 208	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
50	12x12 Dk grey w/ lt grey floor tile mastic	1,800	SF	rooms 306, 208	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
51	safe door insulation	40	SF	3rd Floor Adjacent to rm 301	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
52	Plaster Walls	20,000	SF	Throughout	Assumed	SURFACE	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
53	Plaster Ceilings	8,000	SF	Throughout	Assumed	SURFACE	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
54	12x12 Lt Brown w/Dark Brown & White Floor Tile	1,000	SF	Rm 201, 207	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
55	12x12 Lt Brown w/Dark Brown & White Floor Tile Mastic	1,000	SF	Rm 201, 207	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
56	12x12 White w/ Lt Brown & Dark Brown floor tile	1,100	SF	Rm 201, 207; Adj to office & copy room	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
57	12x12 White w/ Lt Brown & Dark Brown floor tile Mastic	1,300	SF	Rm 201, 207; Adj to office & copy room	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
58	Burlap Wall Covering	2,300	SF	rm 208	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
59	12x12 lt green w/Dk green & white floor tile	1,800	SF	Room 202, 210	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
60	12x12 lt green w/Dk green & white floor tile mastic	1,800	SF	rm 202, 210	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
61	Brown Carpet Adhesive			Principals Office	Assumed	MISC					Follow O&M Plan
62	12x12 Brown w/Dark Brown & White Floor Tile	4,200	SF	1st Floor North Corridor, Rooms 101 and 110	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
63	12x12 Brown w/Dark Brown & White Floor Tile mastic	4,200	SF	1st Floor North Corridor, Rooms 101 and 110	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
64	12x12 dark brown w/White Pitted Floor Tile	720	SF	Ramps adj to gym	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
65	12x12 dark brown w/White Pitted Floor Tile mastic	720	SF	ramps adj to gym	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
66	12x12 Purple w/ Dark Purple & White Floor Tile	1,200	SF	auditorium	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
67	12x12 Purple w/ Dark Purple & White Floor Tile Mastic	1,200	SF	auditorium	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
68	2x4 ceiling tile white w/Pinhole & worm	3,000	SF	Auditorium	Assumed	MISC	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
69	12x12 Off White w/Brown Floor Tile	950	SF	café & Kitchen	Assumed	MISC	No	55	SF	6 ACBM with the potential for damage	Repair
70	12x12 Off White w/Brown Floor Tile Mastic	950	SF	Café & Kitchen	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
71	12x12 Dark Brown w/Orange & White Floor Tile	950	SF	Café & Kitchen	Assumed	MISC	No	10	SF	6 ACBM with the potential for damage	Repair
72	12x12 Dark Brown w/Orange & White Floor Tile Mastic	950	SF	café & kitchen	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
73	12" x 12" White Floor Tile	960	SF	South Corridor near Elevators on 1st,	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan



# Chicago Public Schools

**School** Carson School, Rachel  
**Address** 5516 S. Maplewood Ave.

**Unit** 22601  
 Chicago, IL, 60629

**Building ID** 2660  
**Region** 04

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

### *Management Planner's Comments Summarized at the End of the Report*

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
				2nd, and 3rd Floor							
74	Mastic Associated w/ 12" x 12" White Floor Tile	960	SF	South Corridor near Elevators on 1st, 2nd, and 3rd Floor	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
75	2' x 4' Smooth Ceiling Tile	2,700	SF	Rooms 203, 204, and 206	Assumed	MISC	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
76	4" x 4" Red Ceramic Tile w/ Grout	250	SF	East Foyer Entrance near Assistant Principal's Office, Lunch Room	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
77	Mastic Associated w/ 4" x 4" Red Ceramic Tile w/ Grout	250	SF	East Foyer Entrance near Assistant Principal's Office, Lunch Room	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
BB-1	4" baseboard	2,500	LF	classrooms 3rd & 2nd, cafeteria	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
BB-2	6" baseboard	800	LF	room 303, 402	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
BBM-1	4" baseboard mastic	2,500	LF	classrooms 3rd & 2nd, cafeteria	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
BBM-2	6" baseboard mastic	800	LF	room 303	Chrysotile	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
FT-1	12x12 white floor tile	2,200	SF	room 200,203,209, copy rm. Kit. Storage, Teachers Lounge	Assumed	MISC	No	8	SF	6 ACBM with the potential for damage	Repair
FTM-1	12x12 white floor tile mastic	2,200	SF	room 200, 203,209,copy room, kit. Storage, teachers lounge	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

# Chicago Public Schools

**School** Carson School, Rachel  
**Address** 5516 S. Maplewood Ave.

**Unit** 22601  
 Chicago, IL, 60629

**Building ID** 2660  
**Region** 04

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

*Management Planner's Comments Summarized at the End of the Report*

Review Date	4/4/2016
Manager Planner Name	Evan Christian
100-19466	5/15/2016
Manager IDPH License No/Expiration	

HA Number	Management Comments
02	
03	
08	Repair as needed then follow O&M plan.
09	If identified follow O&M procedure.
14	If identified follow O&M procedure.
15	If identified follow O&M procedure.
16	If identified follow O&M procedure.
18	If identified follow O&M procedure.
19	If identified follow O&M procedure.
23	If identified follow O&M procedure.
24	If identified follow O&M procedure.
25	If identified follow O&M procedure.
26	If identified follow O&M procedure.
36	
37	
38	
39	
40	
41	
43	

# Chicago Public Schools

**School** Carson School, Rachel  
**Address** 5516 S. Maplewood Ave.

**Unit** 22601  
 Chicago, IL, 60629

**Building ID** 2660  
**Region** 04

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

### *Management Planner's Comments Summarized at the End of the Report*

HA Number	Management Comments
44	If identified follow O&M procedure.
45	
46	
47	
48	
49	
50	
51	
52	
53	
54	If identified follow O&M procedure.
55	If identified follow O&M procedure.
56	If identified follow O&M procedure.
57	If identified follow O&M procedure.
58	
59	
60	
61	If identified follow O&M procedure.
62	
63	
64	
65	
66	
67	
68	
69	Repair as needed then follow O&M plan.
70	

# Chicago Public Schools

**School** Carson School, Rachel  
**Address** 5516 S. Maplewood Ave.

**Unit** 22601  
 Chicago, IL, 60629

**Building ID** 2660  
**Region** 04

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates  
 600 West Van Buren St., Ste 500  
 Phone: (312) 762-2900 Fax: (312) 782-5145

*Management Planner's Comments Summarized at the End of the Report*

HA Number	Management Comments
71	Repair as needed then follow O&M plan.
72	
73	
74	
75	
76	
77	
BB-1	
BB-2	
BBM-1	
BBM-2	
FT-1	Repair as needed then follow O&M plan.
FTM-1	

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22601** BUIDLING ID: **2660**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Steven Doran**  
SCHOOL NAME: **Carson School, Rachel** INSPECTION DATE: **3/10/2016**  
ADDRESS: **5516 S. Maplewood Ave.** IDPH LICENSE NO: **100-02865**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **02**  
MATERIAL DESCRIPTION: **9x9 tan w/brown & white streaks floor tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with potential for significant damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **2nd and 3rd corridors, 2nd Floor Storage**

MATERIAL QUANTITY: **7200**


MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/10/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22601** BUIDLING ID: **2660**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Carson School, Rachel** REVIEW DATE: **4/4/2016**  
ADDRESS: **5516 S. Maplewood Ave.** IDPH LICENSE NO: **100-02865**

---

HOMOGENEOUS AREA: **02**  
MATERIAL DESCRIPTION: **9x9 tan w/brown & white streaks floor tile**  
MATERIAL LOCATION: **2nd and 3rd corridors, 2nd Floor Storage**  
MATERIAL QUANTITY: **7200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **04/04/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22601** BUIDLING ID: **2660**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Steven Doran**  
SCHOOL NAME: **Carson School, Rachel** INSPECTION DATE: **3/10/2016**  
ADDRESS: **5516 S. Maplewood Ave.** IDPH LICENSE NO: **100-02865**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **03**  
MATERIAL DESCRIPTION: **12x12 dark brown floor tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1st Floor Corridors**  
MATERIAL QUANTITY: **1590** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/10/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22601** BUIDLING ID: **2660**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Carson School, Rachel** REVIEW DATE: **4/4/2016**  
ADDRESS: **5516 S. Maplewood Ave.** IDPH LICENSE NO: **100-02865**

---

HOMOGENEOUS AREA: **03**  
MATERIAL DESCRIPTION: **12x12 dark brown floor tile**  
MATERIAL LOCATION: **1st Floor Corridors**  
MATERIAL QUANTITY: **1590** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **04/04/2016**



# Chicago Public Schools

## Carnow, Conibear and Associates 2016 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22601** BUIDLING ID: **2660**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Steven Doran**  
SCHOOL NAME: **Carson School, Rachel** INSPECTION DATE: **3/10/2016**  
ADDRESS: **5516 S. Maplewood Ave.** IDPH LICENSE NO: **100-02865**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **08**  
MATERIAL DESCRIPTION: **9x9 dark maroon w/white & red streaks floor tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---


### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON: **Deterioration**  
DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **engineers office,kitchen,entry to washrooms**  
MATERIAL QUANTITY: **157** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS: **Damage is located in the Engineer's Office**

Inspector's Signature: \_\_\_\_\_



Date: 03/10/2016

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22601** BUIDLING ID: **2660**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Carson School, Rachel** REVIEW DATE: **4/4/2016**  
ADDRESS: **5516 S. Maplewood Ave.** IDPH LICENSE NO: **100-02865**

---

HOMOGENEOUS AREA: **08**  
MATERIAL DESCRIPTION: **9x9 dark maroon w/white & red streaks floor tile**  
MATERIAL LOCATION: **engineers office,kitchen,entry to washrooms**  
MATERIAL QUANTITY: **157** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **10** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Repair as needed then follow O&M plan.

Management Planner's Signature: \_\_\_\_\_ Date: **04/04/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22601** BUIDLING ID: **2660**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Steven Doran**  
SCHOOL NAME: **Carson School, Rachel** INSPECTION DATE: **3/10/2016**  
ADDRESS: **5516 S. Maplewood Ave.** IDPH LICENSE NO: **100-02865**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **09**  
MATERIAL DESCRIPTION: **9x9 tan w/white streaks floor tile**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **biology room 310 - ABATED**

MATERIAL QUANTITY:


MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **03/10/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22601** BUIDLING ID: **2660**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Carson School, Rachel** REVIEW DATE: **4/4/2016**  
ADDRESS: **5516 S. Maplewood Ave.** IDPH LICENSE NO: **100-02865**

---

HOMOGENEOUS AREA: **09**

MATERIAL DESCRIPTION: **9x9 tan w/white streaks floor tile**

MATERIAL LOCATION: **biology room 310 - ABATED**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

If identified follow O&M procedure.

Management Planner's Signature: \_\_\_\_\_ Date: **04/04/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22601** BUIDLING ID: **2660**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Steven Doran**  
SCHOOL NAME: **Carson School, Rachel** INSPECTION DATE: **3/10/2016**  
ADDRESS: **5516 S. Maplewood Ave.** IDPH LICENSE NO: **100-02865**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **14**  
MATERIAL DESCRIPTION: **9x9 white w/black streaks floor tile, Covered by wood laminate**  
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **main office**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed 2016**

Inspector's Signature:



Date: **03/10/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22601** BUIDLING ID: **2660**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Carson School, Rachel** REVIEW DATE: **4/4/2016**  
ADDRESS: **5516 S. Maplewood Ave.** IDPH LICENSE NO: **100-02865**

---

HOMOGENEOUS AREA: **14**

MATERIAL DESCRIPTION: **9x9 white w/black streaks floor tile, Covered by wood laminate**

MATERIAL LOCATION: **main office**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

If identified follow O&M procedure.

Management Planner's Signature: \_\_\_\_\_ Date: **04/04/2016**

# Chicago Public Schools

Carnow, Conibear and Associates  
2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22601** BUIDLING ID: **2660**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Steven Doran**  
SCHOOL NAME: **Carson School, Rachel** INSPECTION DATE: **3/10/2016**  
ADDRESS: **5516 S. Maplewood Ave.** IDPH LICENSE NO: **100-02865**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **15**  
MATERIAL DESCRIPTION: **9x9 black w/white streaks floor tile**  
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **engineers office, main office**

MATERIAL QUANTITY:


MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed 2016 - Covered by wood laminate flooring**

Inspector's Signature:



Date: **03/10/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22601** BUIDLING ID: **2660**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Carson School, Rachel** REVIEW DATE: **4/4/2016**  
ADDRESS: **5516 S. Maplewood Ave.** IDPH LICENSE NO: **100-02865**

---

HOMOGENEOUS AREA: **15**

MATERIAL DESCRIPTION: **9x9 black w/white streaks floor tile**

MATERIAL LOCATION: **engineers office, main office**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

If identified follow O&M procedure.

Management Planner's Signature: \_\_\_\_\_ Date: **04/04/2016**



# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22601** BUIDLING ID: **2660**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Steven Doran**  
SCHOOL NAME: **Carson School, Rachel** INSPECTION DATE: **3/10/2016**  
ADDRESS: **5516 S. Maplewood Ave.** IDPH LICENSE NO: **100-02865**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **16**  
MATERIAL DESCRIPTION: **8x24 black floor tile**  
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **main office**

MATERIAL QUANTITY:


MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed 2016 - Covered by wood laminate flooring**

Inspector's Signature:



Date: **03/10/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22601** BUIDLING ID: **2660**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Carson School, Rachel** REVIEW DATE: **4/4/2016**  
ADDRESS: **5516 S. Maplewood Ave.** IDPH LICENSE NO: **100-02865**

---

HOMOGENEOUS AREA: **16**

MATERIAL DESCRIPTION: **8x24 black floor tile**

MATERIAL LOCATION: **main office**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

If identified follow O&M procedure.

Management Planner's Signature: \_\_\_\_\_ Date: **04/04/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22601** BUIDLING ID: **2660**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Steven Doran**  
SCHOOL NAME: **Carson School, Rachel** INSPECTION DATE: **3/10/2016**  
ADDRESS: **5516 S. Maplewood Ave.** IDPH LICENSE NO: **100-02865**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **18**  
MATERIAL DESCRIPTION: **9x9 green w/black & white streaks floor tile**  
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **study hall room 100**

MATERIAL QUANTITY:


MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed 2016**

Inspector's Signature:



Date: **03/10/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22601** BUIDLING ID: **2660**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Carson School, Rachel** REVIEW DATE: **4/4/2016**  
ADDRESS: **5516 S. Maplewood Ave.** IDPH LICENSE NO: **100-02865**

---

HOMOGENEOUS AREA: **18**  
MATERIAL DESCRIPTION: **9x9 green w/black & white streaks floor tile**  
MATERIAL LOCATION: **study hall room 100**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

If identified follow O&M procedure.

Management Planner's Signature: \_\_\_\_\_ Date: **04/04/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22601** BUIDLING ID: **2660**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Steven Doran**  
SCHOOL NAME: **Carson School, Rachel** INSPECTION DATE: **3/10/2016**  
ADDRESS: **5516 S. Maplewood Ave.** IDPH LICENSE NO: **100-02865**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **19**  
MATERIAL DESCRIPTION: **9x9 dark green w/white streaks floor tile**  
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **north side study hall room 100**

MATERIAL QUANTITY:


MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed 2016**

Inspector's Signature:



Date: **03/10/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22601** BUIDLING ID: **2660**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Carson School, Rachel** REVIEW DATE: **4/4/2016**  
ADDRESS: **5516 S. Maplewood Ave.** IDPH LICENSE NO: **100-02865**

---

HOMOGENEOUS AREA: **19**

MATERIAL DESCRIPTION: **9x9 dark green w/white streaks floor tile**

MATERIAL LOCATION: **north side study hall room 100**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

If identified follow O&M procedure.

Management Planner's Signature: \_\_\_\_\_ Date: **04/04/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22601** BUIDLING ID: **2660**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Steven Doran**  
SCHOOL NAME: **Carson School, Rachel** INSPECTION DATE: **3/10/2016**  
ADDRESS: **5516 S. Maplewood Ave.** IDPH LICENSE NO: **100-02865**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **23**  
MATERIAL DESCRIPTION: **9x9 light tan w/brown & white streaks floor tile**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1st floor corridor - ABATED**

MATERIAL QUANTITY:


MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **03/10/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22601** BUIDLING ID: **2660**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Carson School, Rachel** REVIEW DATE: **4/4/2016**  
ADDRESS: **5516 S. Maplewood Ave.** IDPH LICENSE NO: **100-02865**

---

HOMOGENEOUS AREA: **23**

MATERIAL DESCRIPTION: **9x9 light tan w/brown & white streaks floor tile**

MATERIAL LOCATION: **1st floor corridor - ABATED**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

If identified follow O&M procedure.

Management Planner's Signature: \_\_\_\_\_ Date: **04/04/2016**



# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22601** BUIDLING ID: **2660**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Steven Doran**  
SCHOOL NAME: **Carson School, Rachel** INSPECTION DATE: **3/10/2016**  
ADDRESS: **5516 S. Maplewood Ave.** IDPH LICENSE NO: **100-02865**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **24**  
MATERIAL DESCRIPTION: **15x24 reddish-brown floor tile**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1st floor corridor - ABATED**

MATERIAL QUANTITY:


MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **03/10/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22601** BUIDLING ID: **2660**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Carson School, Rachel** REVIEW DATE: **4/4/2016**  
ADDRESS: **5516 S. Maplewood Ave.** IDPH LICENSE NO: **100-02865**

---

HOMOGENEOUS AREA: **24**

MATERIAL DESCRIPTION: **15x24 reddish-brown floor tile**

MATERIAL LOCATION: **1st floor corridor - ABATED**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

If identified follow O&M procedure.

Management Planner's Signature: \_\_\_\_\_ Date: **04/04/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22601** BUIDLING ID: **2660**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Steven Doran**  
SCHOOL NAME: **Carson School, Rachel** INSPECTION DATE: **3/10/2016**  
ADDRESS: **5516 S. Maplewood Ave.** IDPH LICENSE NO: **100-02865**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **25**  
MATERIAL DESCRIPTION: **9x9 brown w/gold & white streaks floor tile**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1st floor corridor - ABATED**

MATERIAL QUANTITY:


MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **03/10/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22601** BUIDLING ID: **2660**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Carson School, Rachel** REVIEW DATE: **4/4/2016**  
ADDRESS: **5516 S. Maplewood Ave.** IDPH LICENSE NO: **100-02865**

---

HOMOGENEOUS AREA: **25**

MATERIAL DESCRIPTION: **9x9 brown w/gold & white streaks floor tile**

MATERIAL LOCATION: **1st floor corridor - ABATED**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

If identified follow O&M procedure.

Management Planner's Signature: \_\_\_\_\_ Date: **04/04/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22601** BUIDLING ID: **2660**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Steven Doran**  
SCHOOL NAME: **Carson School, Rachel** INSPECTION DATE: **3/10/2016**  
ADDRESS: **5516 S. Maplewood Ave.** IDPH LICENSE NO: **100-02865**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **26**  
MATERIAL DESCRIPTION: **black transite countertops**  
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **science rooms 309**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed 2016**

Inspector's Signature:



Date: **03/10/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22601** BUIDLING ID: **2660**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Carson School, Rachel** REVIEW DATE: **4/4/2016**  
ADDRESS: **5516 S. Maplewood Ave.** IDPH LICENSE NO: **100-02865**

---

HOMOGENEOUS AREA: **26**

MATERIAL DESCRIPTION: **black transite countertops**

MATERIAL LOCATION: **science rooms 309**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

If identified follow O&M procedure.

Management Planner's Signature: \_\_\_\_\_ Date: **04/04/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22601** BUIDLING ID: **2660**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Steven Doran**  
SCHOOL NAME: **Carson School, Rachel** INSPECTION DATE: **3/10/2016**  
ADDRESS: **5516 S. Maplewood Ave.** IDPH LICENSE NO: **100-02865**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **36**  
MATERIAL DESCRIPTION: **joint compound elbows on fiberglass pipe runs**  
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **throughout**  
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature:



Date: **03/10/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22601** BUIDLING ID: **2660**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Carson School, Rachel** REVIEW DATE: **4/4/2016**  
ADDRESS: **5516 S. Maplewood Ave.** IDPH LICENSE NO: **100-02865**

---

HOMOGENEOUS AREA: **36**  
MATERIAL DESCRIPTION: **joint compound elbows on fiberglass pipe runs**  
MATERIAL LOCATION: **throughout**  
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **04/04/2016**



# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22601** BUIDLING ID: **2660**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Steven Doran**  
SCHOOL NAME: **Carson School, Rachel** INSPECTION DATE: **3/10/2016**  
ADDRESS: **5516 S. Maplewood Ave.** IDPH LICENSE NO: **100-02865**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **37**  
MATERIAL DESCRIPTION: **thermal aircell pipe insulation**  
HISTORICAL AHERA DAMAGE CATEGORY **7 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1st floor**  
MATERIAL QUANTITY: **303** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 03/10/2016

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22601** BUIDLING ID: **2660**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Carson School, Rachel** REVIEW DATE: **4/4/2016**  
ADDRESS: **5516 S. Maplewood Ave.** IDPH LICENSE NO: **100-02865**

---

HOMOGENEOUS AREA: **37**  
MATERIAL DESCRIPTION: **thermal aircell pipe insulation**  
MATERIAL LOCATION: **1st floor**  
MATERIAL QUANTITY: **303** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **04/04/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22601** BUIDLING ID: **2660**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Steven Doran**  
SCHOOL NAME: **Carson School, Rachel** INSPECTION DATE: **3/10/2016**  
ADDRESS: **5516 S. Maplewood Ave.** IDPH LICENSE NO: **100-02865**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **38**  
MATERIAL DESCRIPTION: **joint compound elbows on aircell pipe runs**  
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1st floor**  
MATERIAL QUANTITY: **60** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature:



Date: **03/10/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22601** BUIDLING ID: **2660**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Carson School, Rachel** REVIEW DATE: **4/4/2016**  
ADDRESS: **5516 S. Maplewood Ave.** IDPH LICENSE NO: **100-02865**

---

HOMOGENEOUS AREA: **38**  
MATERIAL DESCRIPTION: **joint compound elbows on aircell pipe runs**  
MATERIAL LOCATION: **1st floor**  
MATERIAL QUANTITY: **60** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **04/04/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22601** BUIDLING ID: **2660**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Steven Doran**  
SCHOOL NAME: **Carson School, Rachel** INSPECTION DATE: **3/10/2016**  
ADDRESS: **5516 S. Maplewood Ave.** IDPH LICENSE NO: **100-02865**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **39**  
MATERIAL DESCRIPTION: **thermal paperwrap pipe insulation**  
HISTORICAL AHERA DAMAGE CATEGORY **7 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1st floor**  
MATERIAL QUANTITY: **152** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature:



Date: **03/10/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22601** BUIDLING ID: **2660**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Carson School, Rachel** REVIEW DATE: **4/4/2016**  
ADDRESS: **5516 S. Maplewood Ave.** IDPH LICENSE NO: **100-02865**

---

HOMOGENEOUS AREA: **39**  
MATERIAL DESCRIPTION: **thermal paperwrap pipe insulation**  
MATERIAL LOCATION: **1st floor**  
MATERIAL QUANTITY: **152** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **04/04/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22601** BUIDLING ID: **2660**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Steven Doran**  
SCHOOL NAME: **Carson School, Rachel** INSPECTION DATE: **3/10/2016**  
ADDRESS: **5516 S. Maplewood Ave.** IDPH LICENSE NO: **100-02865**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **40**  
MATERIAL DESCRIPTION: **joint compound elbows on paperwrap pipe runs**  
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1st floor**  
MATERIAL QUANTITY: **40** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature:



Date: **03/10/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22601** BUIDLING ID: **2660**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Carson School, Rachel** REVIEW DATE: **4/4/2016**  
ADDRESS: **5516 S. Maplewood Ave.** IDPH LICENSE NO: **100-02865**

---

HOMOGENEOUS AREA: **40**  
MATERIAL DESCRIPTION: **joint compound elbows on paperwrap pipe runs**  
MATERIAL LOCATION: **1st floor**  
MATERIAL QUANTITY: **40** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **04/04/2016**



# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22601** BUIDLING ID: **2660**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Steven Doran**  
SCHOOL NAME: **Carson School, Rachel** INSPECTION DATE: **3/10/2016**  
ADDRESS: **5516 S. Maplewood Ave.** IDPH LICENSE NO: **100-02865**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **41**  
MATERIAL DESCRIPTION: **boiler gasket**  
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **boiler room**  
MATERIAL QUANTITY: **22** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/10/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22601** BUIDLING ID: **2660**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Carson School, Rachel** REVIEW DATE: **4/4/2016**  
ADDRESS: **5516 S. Maplewood Ave.** IDPH LICENSE NO: **100-02865**

---

HOMOGENEOUS AREA: **41**  
MATERIAL DESCRIPTION: **boiler gasket**  
MATERIAL LOCATION: **boiler room**  
MATERIAL QUANTITY: **22** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **04/04/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22601** BUIDLING ID: **2660**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Steven Doran**  
SCHOOL NAME: **Carson School, Rachel** INSPECTION DATE: **3/10/2016**  
ADDRESS: **5516 S. Maplewood Ave.** IDPH LICENSE NO: **100-02865**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **43**  
MATERIAL DESCRIPTION: **mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1st, 2nd, and 3rd Floor Corridors and Rooms**  
MATERIAL QUANTITY: **16000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/10/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22601** BUIDLING ID: **2660**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Carson School, Rachel** REVIEW DATE: **4/4/2016**  
ADDRESS: **5516 S. Maplewood Ave.** IDPH LICENSE NO: **100-02865**

---

HOMOGENEOUS AREA: **43**  
MATERIAL DESCRIPTION: **mastic**  
MATERIAL LOCATION: **1st, 2nd, and 3rd Floor Corridors and Rooms**  
MATERIAL QUANTITY: **16000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **04/04/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22601** BUIDLING ID: **2660**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Steven Doran**  
SCHOOL NAME: **Carson School, Rachel** INSPECTION DATE: **3/10/2016**  
ADDRESS: **5516 S. Maplewood Ave.** IDPH LICENSE NO: **100-02865**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **44**  
MATERIAL DESCRIPTION: **12x12 Blue floor tile**  
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Study Hall Room 100**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed 2016**

Inspector's Signature:



Date: **03/10/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22601** BUIDLING ID: **2660**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Carson School, Rachel** REVIEW DATE: **4/4/2016**  
ADDRESS: **5516 S. Maplewood Ave.** IDPH LICENSE NO: **100-02865**

---

HOMOGENEOUS AREA: **44**

MATERIAL DESCRIPTION: **12x12 Blue floor tile**

MATERIAL LOCATION: **Study Hall Room 100**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

If identified follow O&M procedure.

Management Planner's Signature: \_\_\_\_\_ Date: **04/04/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22601** BUIDLING ID: **2660**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Steven Doran**  
SCHOOL NAME: **Carson School, Rachel** INSPECTION DATE: **3/10/2016**  
ADDRESS: **5516 S. Maplewood Ave.** IDPH LICENSE NO: **100-02865**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **45**  
MATERIAL DESCRIPTION: **12x12 Lt Blue w/White Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Rooms 309, 303, 308, 304, 206, 101, 110**  
MATERIAL QUANTITY: **6400** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/10/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22601** BUIDLING ID: **2660**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Carson School, Rachel** REVIEW DATE: **4/4/2016**  
ADDRESS: **5516 S. Maplewood Ave.** IDPH LICENSE NO: **100-02865**

---

HOMOGENEOUS AREA: **45**  
MATERIAL DESCRIPTION: **12x12 Lt Blue w/White Floor Tile**  
MATERIAL LOCATION: **Rooms 309, 303, 308, 304, 206, 101, 110**  
MATERIAL QUANTITY: **6400** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **04/04/2016**



# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22601** BUIDLING ID: **2660**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Steven Doran**  
SCHOOL NAME: **Carson School, Rachel** INSPECTION DATE: **3/10/2016**  
ADDRESS: **5516 S. Maplewood Ave.** IDPH LICENSE NO: **100-02865**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **46**  
MATERIAL DESCRIPTION: **12x12 Lt Blue w/White Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Rooms 309, 303, 308, 304, 206, 101, 110**  
MATERIAL QUANTITY: **6400** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/10/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22601** BUIDLING ID: **2660**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Carson School, Rachel** REVIEW DATE: **4/4/2016**  
ADDRESS: **5516 S. Maplewood Ave.** IDPH LICENSE NO: **100-02865**

---

HOMOGENEOUS AREA: **46**  
MATERIAL DESCRIPTION: **12x12 Lt Blue w/White Floor Tile Mastic**  
MATERIAL LOCATION: **Rooms 309, 303, 308, 304, 206, 101, 110**  
MATERIAL QUANTITY: **6400** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **04/04/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22601** BUIDLING ID: **2660**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Steven Doran**  
SCHOOL NAME: **Carson School, Rachel** INSPECTION DATE: **3/10/2016**  
ADDRESS: **5516 S. Maplewood Ave.** IDPH LICENSE NO: **100-02865**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **47**  
MATERIAL DESCRIPTION: **12x12 Lt Grey w/ Dark Grey & White Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Rooms 302, 307, 305, 205**  
MATERIAL QUANTITY: **3600** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/10/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22601** BUIDLING ID: **2660**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Carson School, Rachel** REVIEW DATE: **4/4/2016**  
ADDRESS: **5516 S. Maplewood Ave.** IDPH LICENSE NO: **100-02865**

---

HOMOGENEOUS AREA: **47**  
MATERIAL DESCRIPTION: **12x12 Lt Grey w/ Dark Grey & White Floor Tile**  
MATERIAL LOCATION: **Rooms 302, 307, 305, 205**  
MATERIAL QUANTITY: **3600** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **04/04/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22601** BUIDLING ID: **2660**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Steven Doran**  
SCHOOL NAME: **Carson School, Rachel** INSPECTION DATE: **3/10/2016**  
ADDRESS: **5516 S. Maplewood Ave.** IDPH LICENSE NO: **100-02865**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **48**  
MATERIAL DESCRIPTION: **12x12 Lt Grey w/ Dark Grey & White Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Rooms 302, 307, 305, 205**  
MATERIAL QUANTITY: **3600** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/10/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22601** BUIDLING ID: **2660**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Carson School, Rachel** REVIEW DATE: **4/4/2016**  
ADDRESS: **5516 S. Maplewood Ave.** IDPH LICENSE NO: **100-02865**

---

HOMOGENEOUS AREA: **48**  
MATERIAL DESCRIPTION: **12x12 Lt Grey w/ Dark Grey & White Floor Tile Mastic**  
MATERIAL LOCATION: **Rooms 302, 307, 305, 205**  
MATERIAL QUANTITY: **3600** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **04/04/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22601** BUIDLING ID: **2660**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Steven Doran**  
SCHOOL NAME: **Carson School, Rachel** INSPECTION DATE: **3/10/2016**  
ADDRESS: **5516 S. Maplewood Ave.** IDPH LICENSE NO: **100-02865**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **49**  
MATERIAL DESCRIPTION: **12x12 Dk Grey w/lt grey floor tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **rooms 306, 208**  
MATERIAL QUANTITY: **1800** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/10/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22601** BUIDLING ID: **2660**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Carson School, Rachel** REVIEW DATE: **4/4/2016**  
ADDRESS: **5516 S. Maplewood Ave.** IDPH LICENSE NO: **100-02865**

---

HOMOGENEOUS AREA: **49**  
MATERIAL DESCRIPTION: **12x12 Dk Grey w/lt grey floor tile**  
MATERIAL LOCATION: **rooms 306, 208**  
MATERIAL QUANTITY: **1800** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **04/04/2016**



# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22601** BUIDLING ID: **2660**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Steven Doran**  
SCHOOL NAME: **Carson School, Rachel** INSPECTION DATE: **3/10/2016**  
ADDRESS: **5516 S. Maplewood Ave.** IDPH LICENSE NO: **100-02865**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **50**  
MATERIAL DESCRIPTION: **12x12 Dk grey w/ lt grey floor tile mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **rooms 306, 208**  
MATERIAL QUANTITY: **1800** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/10/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22601** BUIDLING ID: **2660**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Carson School, Rachel** REVIEW DATE: **4/4/2016**  
ADDRESS: **5516 S. Maplewood Ave.** IDPH LICENSE NO: **100-02865**

---

HOMOGENEOUS AREA: **50**  
MATERIAL DESCRIPTION: **12x12 Dk grey w/ lt grey floor tile mastic**  
MATERIAL LOCATION: **rooms 306, 208**  
MATERIAL QUANTITY: **1800** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **04/04/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22601** BUIDLING ID: **2660**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Steven Doran**  
SCHOOL NAME: **Carson School, Rachel** INSPECTION DATE: **3/10/2016**  
ADDRESS: **5516 S. Maplewood Ave.** IDPH LICENSE NO: **100-02865**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **51**  
MATERIAL DESCRIPTION: **safe door insulation**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **3rd Floor Adjacent to rm 301**  
MATERIAL QUANTITY: **40** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/10/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22601** BUIDLING ID: **2660**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Carson School, Rachel** REVIEW DATE: **4/4/2016**  
ADDRESS: **5516 S. Maplewood Ave.** IDPH LICENSE NO: **100-02865**

---

HOMOGENEOUS AREA: **51**  
MATERIAL DESCRIPTION: **safe door insulation**  
MATERIAL LOCATION: **3rd Floor Adjacent to rm 301**  
MATERIAL QUANTITY: **40** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **04/04/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22601** BUIDLING ID: **2660**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Steven Doran**  
SCHOOL NAME: **Carson School, Rachel** INSPECTION DATE: **3/10/2016**  
ADDRESS: **5516 S. Maplewood Ave.** IDPH LICENSE NO: **100-02865**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **52**  
MATERIAL DESCRIPTION: **Plaster Walls**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Throughout**  
MATERIAL QUANTITY: **20000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/10/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22601** BUIDLING ID: **2660**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Carson School, Rachel** REVIEW DATE: **4/4/2016**  
ADDRESS: **5516 S. Maplewood Ave.** IDPH LICENSE NO: **100-02865**

---

HOMOGENEOUS AREA: **52**  
MATERIAL DESCRIPTION: **Plaster Walls**  
MATERIAL LOCATION: **Throughout**  
MATERIAL QUANTITY: **20000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **04/04/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22601** BUIDLING ID: **2660**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Steven Doran**  
SCHOOL NAME: **Carson School, Rachel** INSPECTION DATE: **3/10/2016**  
ADDRESS: **5516 S. Maplewood Ave.** IDPH LICENSE NO: **100-02865**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **53**  
MATERIAL DESCRIPTION: **Plaster Ceilings**  
HISTORICAL AHERA DAMAGE CATEGORY **7 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Throughout**  
MATERIAL QUANTITY: **8000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 03/10/2016

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22601** BUIDLING ID: **2660**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Carson School, Rachel** REVIEW DATE: **4/4/2016**  
ADDRESS: **5516 S. Maplewood Ave.** IDPH LICENSE NO: **100-02865**

---

HOMOGENEOUS AREA: **53**  
MATERIAL DESCRIPTION: **Plaster Ceilings**  
MATERIAL LOCATION: **Throughout**  
MATERIAL QUANTITY: **8000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **04/04/2016**



# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22601** BUIDLING ID: **2660**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Steven Doran**  
SCHOOL NAME: **Carson School, Rachel** INSPECTION DATE: **3/10/2016**  
ADDRESS: **5516 S. Maplewood Ave.** IDPH LICENSE NO: **100-02865**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **54**  
MATERIAL DESCRIPTION: **12x12 Lt Brown w/Dark Brown & White Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Rm 201, 207**  
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS: **Not observed 2016 - Room 402 is now wood flooring**

Inspector's Signature: \_\_\_\_\_



Date: 03/10/2016

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22601** BUIDLING ID: **2660**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Carson School, Rachel** REVIEW DATE: **4/4/2016**  
ADDRESS: **5516 S. Maplewood Ave.** IDPH LICENSE NO: **100-02865**

---

HOMOGENEOUS AREA: **54**  
MATERIAL DESCRIPTION: **12x12 Lt Brown w/Dark Brown & White Floor Tile**  
MATERIAL LOCATION: **Rm 201, 207**  
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

If identified follow O&M procedure.

Management Planner's Signature: \_\_\_\_\_ Date: **04/04/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22601** BUIDLING ID: **2660**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Steven Doran**  
SCHOOL NAME: **Carson School, Rachel** INSPECTION DATE: **3/10/2016**  
ADDRESS: **5516 S. Maplewood Ave.** IDPH LICENSE NO: **100-02865**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **55**  
MATERIAL DESCRIPTION: **12x12 Lt Brown w/Dark Brown & White Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Rm 201, 207**  
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS: **Not observed 2016 - Room 402 is now wood flooring**

Inspector's Signature:



Date: **03/10/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22601** BUIDLING ID: **2660**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Carson School, Rachel** REVIEW DATE: **4/4/2016**  
ADDRESS: **5516 S. Maplewood Ave.** IDPH LICENSE NO: **100-02865**

---

HOMOGENEOUS AREA: **55**  
MATERIAL DESCRIPTION: **12x12 Lt Brown w/Dark Brown & White Floor Tile Mastic**  
MATERIAL LOCATION: **Rm 201, 207**  
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

If identified follow O&M procedure.

Management Planner's Signature: \_\_\_\_\_ Date: **04/04/2016**

# Chicago Public Schools

## Carnow, Conibear and Associates 2016 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22601** BUIDLING ID: **2660**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Steven Doran**  
SCHOOL NAME: **Carson School, Rachel** INSPECTION DATE: **3/10/2016**  
ADDRESS: **5516 S. Maplewood Ave.** IDPH LICENSE NO: **100-02865**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **56**  
MATERIAL DESCRIPTION: **12x12 White w/ Lt Brown & Dark Brown floor tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Rm 201, 207; Adj to office & copy room**  
MATERIAL QUANTITY: **1100** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS: **Not observed 2016 - Room 402 is now wood flooring**

Inspector's Signature: \_\_\_\_\_

*Steven Doran*

Date: 03/10/2016

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22601** BUIDLING ID: **2660**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Carson School, Rachel** REVIEW DATE: **4/4/2016**  
ADDRESS: **5516 S. Maplewood Ave.** IDPH LICENSE NO: **100-02865**

---

HOMOGENEOUS AREA: **56**  
MATERIAL DESCRIPTION: **12x12 White w/ Lt Brown & Dark Brown floor tile**  
MATERIAL LOCATION: **Rm 201, 207; Adj to office & copy room**  
MATERIAL QUANTITY: **1100** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

If identified follow O&M procedure.

Management Planner's Signature: \_\_\_\_\_ Date: **04/04/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22601** BUIDLING ID: **2660**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Steven Doran**  
SCHOOL NAME: **Carson School, Rachel** INSPECTION DATE: **3/10/2016**  
ADDRESS: **5516 S. Maplewood Ave.** IDPH LICENSE NO: **100-02865**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **57**  
MATERIAL DESCRIPTION: **12x12 White w/ Lt Brown & Dark Brown floor tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT


This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Rm 201, 207; Adj to office & copy room**  
MATERIAL QUANTITY: **1300** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS: **Not observed 2016 - Room 402 is now wood flooring**

Inspector's Signature: \_\_\_\_\_



Date: 03/10/2016

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22601** BUIDLING ID: **2660**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Carson School, Rachel** REVIEW DATE: **4/4/2016**  
ADDRESS: **5516 S. Maplewood Ave.** IDPH LICENSE NO: **100-02865**

---

HOMOGENEOUS AREA: **57**  
MATERIAL DESCRIPTION: **12x12 White w/ Lt Brown & Dark Brown floor tile Mastic**  
MATERIAL LOCATION: **Rm 201, 207; Adj to office & copy room**  
MATERIAL QUANTITY: **1300** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

If identified follow O&M procedure.

Management Planner's Signature: \_\_\_\_\_ Date: **04/04/2016**



# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22601** BUIDLING ID: **2660**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Steven Doran**  
SCHOOL NAME: **Carson School, Rachel** INSPECTION DATE: **3/10/2016**  
ADDRESS: **5516 S. Maplewood Ave.** IDPH LICENSE NO: **100-02865**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **58**  
MATERIAL DESCRIPTION: **Burlap Wall Covering**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **rm 208**  
MATERIAL QUANTITY: **2300** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/10/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22601** BUIDLING ID: **2660**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Carson School, Rachel** REVIEW DATE: **4/4/2016**  
ADDRESS: **5516 S. Maplewood Ave.** IDPH LICENSE NO: **100-02865**

---

HOMOGENEOUS AREA: **58**  
MATERIAL DESCRIPTION: **Burlap Wall Covering**  
MATERIAL LOCATION: **rm 208**  
MATERIAL QUANTITY: **2300** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **04/04/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22601** BUIDLING ID: **2660**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Steven Doran**  
SCHOOL NAME: **Carson School, Rachel** INSPECTION DATE: **3/10/2016**  
ADDRESS: **5516 S. Maplewood Ave.** IDPH LICENSE NO: **100-02865**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **59**  
MATERIAL DESCRIPTION: **12x12 lt green w/Dk green & white floor tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Room 202, 210**  
MATERIAL QUANTITY: **1800** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 03/10/2016

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22601** BUIDLING ID: **2660**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Carson School, Rachel** REVIEW DATE: **4/4/2016**  
ADDRESS: **5516 S. Maplewood Ave.** IDPH LICENSE NO: **100-02865**

---

HOMOGENEOUS AREA: **59**  
MATERIAL DESCRIPTION: **12x12 lt green w/Dk green & white floor tile**  
MATERIAL LOCATION: **Room 202, 210**  
MATERIAL QUANTITY: **1800** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **04/04/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22601** BUIDLING ID: **2660**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Steven Doran**  
SCHOOL NAME: **Carson School, Rachel** INSPECTION DATE: **3/10/2016**  
ADDRESS: **5516 S. Maplewood Ave.** IDPH LICENSE NO: **100-02865**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **60**  
MATERIAL DESCRIPTION: **12x12 lt green w/Dk green & white floor tile mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **rm 202, 210**  
MATERIAL QUANTITY: **1800** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/10/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22601** BUIDLING ID: **2660**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Carson School, Rachel** REVIEW DATE: **4/4/2016**  
ADDRESS: **5516 S. Maplewood Ave.** IDPH LICENSE NO: **100-02865**

---

HOMOGENEOUS AREA: **60**  
MATERIAL DESCRIPTION: **12x12 lt green w/Dk green & white floor tile mastic**  
MATERIAL LOCATION: **rm 202, 210**  
MATERIAL QUANTITY: **1800** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **04/04/2016**

# Chicago Public Schools

## Carnow, Conibear and Associates 2016 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22601** BUIDLING ID: **2660**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Steven Doran**  
SCHOOL NAME: **Carson School, Rachel** INSPECTION DATE: **3/10/2016**  
ADDRESS: **5516 S. Maplewood Ave.** IDPH LICENSE NO: **100-02865**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **61**  
MATERIAL DESCRIPTION: **Brown Carpet Adhesive**  
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE:

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Principals Office**

MATERIAL QUANTITY:


MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed 2016 - Now wood floor**

Inspector's Signature:



Date: **03/10/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22601** BUIDLING ID: **2660**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Carson School, Rachel** REVIEW DATE: **4/4/2016**  
ADDRESS: **5516 S. Maplewood Ave.** IDPH LICENSE NO: **100-02865**

---

HOMOGENEOUS AREA: **61**

MATERIAL DESCRIPTION: **Brown Carpet Adhesive**

MATERIAL LOCATION: **Principals Office**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

If identified follow O&M procedure.

Management Planner's Signature: \_\_\_\_\_ Date: **04/04/2016**



# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22601** BUIDLING ID: **2660**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Steven Doran**  
SCHOOL NAME: **Carson School, Rachel** INSPECTION DATE: **3/10/2016**  
ADDRESS: **5516 S. Maplewood Ave.** IDPH LICENSE NO: **100-02865**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **62**  
MATERIAL DESCRIPTION: **12x12 Brown w/Dark Brown & White Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1st Floor North Corridor, Rooms 101 and 110**  
MATERIAL QUANTITY: **4200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/10/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22601** BUIDLING ID: **2660**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Carson School, Rachel** REVIEW DATE: **4/4/2016**  
ADDRESS: **5516 S. Maplewood Ave.** IDPH LICENSE NO: **100-02865**

---

HOMOGENEOUS AREA: **62**  
MATERIAL DESCRIPTION: **12x12 Brown w/Dark Brown & White Floor Tile**  
MATERIAL LOCATION: **1st Floor North Corridor, Rooms 101 and 110**  
MATERIAL QUANTITY: **4200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **04/04/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22601** BUIDLING ID: **2660**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Steven Doran**  
SCHOOL NAME: **Carson School, Rachel** INSPECTION DATE: **3/10/2016**  
ADDRESS: **5516 S. Maplewood Ave.** IDPH LICENSE NO: **100-02865**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **63**  
MATERIAL DESCRIPTION: **12x12 Brown w/Dark Brown & White Floor Tile mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **1st Floor North Corridor, Rooms 101 and 110**

MATERIAL QUANTITY: **4200**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/10/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22601** BUIDLING ID: **2660**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Carson School, Rachel** REVIEW DATE: **4/4/2016**  
ADDRESS: **5516 S. Maplewood Ave.** IDPH LICENSE NO: **100-02865**

---

HOMOGENEOUS AREA: **63**  
MATERIAL DESCRIPTION: **12x12 Brown w/Dark Brown & White Floor Tile mastic**  
MATERIAL LOCATION: **1st Floor North Corridor, Rooms 101 and 110**  
MATERIAL QUANTITY: **4200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **04/04/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22601** BUIDLING ID: **2660**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Steven Doran**  
SCHOOL NAME: **Carson School, Rachel** INSPECTION DATE: **3/10/2016**  
ADDRESS: **5516 S. Maplewood Ave.** IDPH LICENSE NO: **100-02865**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **64**  
MATERIAL DESCRIPTION: **12x12 dark brown w/White Pitted Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Ramps adj to gym**  
MATERIAL QUANTITY: **720** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 03/10/2016

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22601** BUIDLING ID: **2660**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Carson School, Rachel** REVIEW DATE: **4/4/2016**  
ADDRESS: **5516 S. Maplewood Ave.** IDPH LICENSE NO: **100-02865**

---

HOMOGENEOUS AREA: **64**  
MATERIAL DESCRIPTION: **12x12 dark brown w/White Pitted Floor Tile**  
MATERIAL LOCATION: **Ramps adj to gym**  
MATERIAL QUANTITY: **720** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **04/04/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22601** BUIDLING ID: **2660**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Steven Doran**  
SCHOOL NAME: **Carson School, Rachel** INSPECTION DATE: **3/10/2016**  
ADDRESS: **5516 S. Maplewood Ave.** IDPH LICENSE NO: **100-02865**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **65**  
MATERIAL DESCRIPTION: **12x12 dark brown w/White Pitted Floor Tile mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **ramps adj to gym**

MATERIAL QUANTITY: **720**


MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/10/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22601** BUIDLING ID: **2660**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Carson School, Rachel** REVIEW DATE: **4/4/2016**  
ADDRESS: **5516 S. Maplewood Ave.** IDPH LICENSE NO: **100-02865**

---

HOMOGENEOUS AREA: **65**  
MATERIAL DESCRIPTION: **12x12 dark brown w/White Pitted Floor Tile mastic**  
MATERIAL LOCATION: **ramps adj to gym**  
MATERIAL QUANTITY: **720** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **04/04/2016**



# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22601** BUIDLING ID: **2660**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Steven Doran**  
SCHOOL NAME: **Carson School, Rachel** INSPECTION DATE: **3/10/2016**  
ADDRESS: **5516 S. Maplewood Ave.** IDPH LICENSE NO: **100-02865**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **66**  
MATERIAL DESCRIPTION: **12x12 Purple w/ Dark Purple & White Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **auditorium**  
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/10/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22601** BUIDLING ID: **2660**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Carson School, Rachel** REVIEW DATE: **4/4/2016**  
ADDRESS: **5516 S. Maplewood Ave.** IDPH LICENSE NO: **100-02865**

---

HOMOGENEOUS AREA: **66**  
MATERIAL DESCRIPTION: **12x12 Purple w/ Dark Purple & White Floor Tile**  
MATERIAL LOCATION: **auditorium**  
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **04/04/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22601** BUIDLING ID: **2660**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Steven Doran**  
SCHOOL NAME: **Carson School, Rachel** INSPECTION DATE: **3/10/2016**  
ADDRESS: **5516 S. Maplewood Ave.** IDPH LICENSE NO: **100-02865**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **67**  
MATERIAL DESCRIPTION: **12x12 Purple w/ Dark Purple & White Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **auditorium**  
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 03/10/2016

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22601** BUIDLING ID: **2660**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Carson School, Rachel** REVIEW DATE: **4/4/2016**  
ADDRESS: **5516 S. Maplewood Ave.** IDPH LICENSE NO: **100-02865**

---

HOMOGENEOUS AREA: **67**  
MATERIAL DESCRIPTION: **12x12 Purple w/ Dark Purple & White Floor Tile Mastic**  
MATERIAL LOCATION: **auditorium**  
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **04/04/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22601** BUIDLING ID: **2660**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Steven Doran**  
SCHOOL NAME: **Carson School, Rachel** INSPECTION DATE: **3/10/2016**  
ADDRESS: **5516 S. Maplewood Ave.** IDPH LICENSE NO: **100-02865**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **68**  
MATERIAL DESCRIPTION: **2x4 ceiling tile white w/Pinhole & worm**  
HISTORICAL AHERA DAMAGE CATEGORY **7 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Auditorium**  
MATERIAL QUANTITY: **3000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 03/10/2016

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22601** BUIDLING ID: **2660**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Carson School, Rachel** REVIEW DATE: **4/4/2016**  
ADDRESS: **5516 S. Maplewood Ave.** IDPH LICENSE NO: **100-02865**

---

HOMOGENEOUS AREA: **68**  
MATERIAL DESCRIPTION: **2x4 ceiling tile white w/Pinhole & worm**  
MATERIAL LOCATION: **Auditorium**  
MATERIAL QUANTITY: **3000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **04/04/2016**

# Chicago Public Schools

## Carnow, Conibear and Associates 2016 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22601** BUIDLING ID: **2660**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Steven Doran**  
SCHOOL NAME: **Carson School, Rachel** INSPECTION DATE: **3/10/2016**  
ADDRESS: **5516 S. Maplewood Ave.** IDPH LICENSE NO: **100-02865**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **69**  
MATERIAL DESCRIPTION: **12x12 Off White w/Brown Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---


### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON: **Deterioration**  
DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **café & Kitchen**  
MATERIAL QUANTITY: **950** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS: **Damage is located in the Cafe (10SF) and the Kitchen (45SF)**

Inspector's Signature: \_\_\_\_\_



Date: 03/10/2016

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22601** BUIDLING ID: **2660**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Carson School, Rachel** REVIEW DATE: **4/4/2016**  
ADDRESS: **5516 S. Maplewood Ave.** IDPH LICENSE NO: **100-02865**

---

HOMOGENEOUS AREA: **69**  
MATERIAL DESCRIPTION: **12x12 Off White w/Brown Floor Tile**  
MATERIAL LOCATION: **café & Kitchen**  
MATERIAL QUANTITY: **950** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **55** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Repair as needed then follow O&M plan.

Management Planner's Signature: \_\_\_\_\_ Date: **04/04/2016**



# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22601** BUIDLING ID: **2660**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Steven Doran**  
SCHOOL NAME: **Carson School, Rachel** INSPECTION DATE: **3/10/2016**  
ADDRESS: **5516 S. Maplewood Ave.** IDPH LICENSE NO: **100-02865**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **70**  
MATERIAL DESCRIPTION: **12x12 Off White w/Brown Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Café & Kitchen**  
MATERIAL QUANTITY: **950** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/10/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22601** BUIDLING ID: **2660**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Carson School, Rachel** REVIEW DATE: **4/4/2016**  
ADDRESS: **5516 S. Maplewood Ave.** IDPH LICENSE NO: **100-02865**

---

HOMOGENEOUS AREA: **70**  
MATERIAL DESCRIPTION: **12x12 Off White w/Brown Floor Tile Mastic**  
MATERIAL LOCATION: **Café & Kitchen**  
MATERIAL QUANTITY: **950** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **04/04/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22601** BUIDLING ID: **2660**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Steven Doran**  
SCHOOL NAME: **Carson School, Rachel** INSPECTION DATE: **3/10/2016**  
ADDRESS: **5516 S. Maplewood Ave.** IDPH LICENSE NO: **100-02865**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **71**  
MATERIAL DESCRIPTION: **12x12 Dark Brown w/Orange & White Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---


## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON: **Deterioration**  
DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Café & Kitchen**  
MATERIAL QUANTITY: **950** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS: **Damage is located in the Cafe (5SF) and Kitchen (5SF)**

Inspector's Signature: \_\_\_\_\_



Date: 03/10/2016

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22601** BUIDLING ID: **2660**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Carson School, Rachel** REVIEW DATE: **4/4/2016**  
ADDRESS: **5516 S. Maplewood Ave.** IDPH LICENSE NO: **100-02865**

---

HOMOGENEOUS AREA: **71**  
MATERIAL DESCRIPTION: **12x12 Dark Brown w/Orange & White Floor Tile**  
MATERIAL LOCATION: **Café & Kitchen**  
MATERIAL QUANTITY: **950** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **10** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Repair as needed then follow O&M plan.

Management Planner's Signature: \_\_\_\_\_ Date: **04/04/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22601** BUIDLING ID: **2660**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Steven Doran**  
SCHOOL NAME: **Carson School, Rachel** INSPECTION DATE: **3/10/2016**  
ADDRESS: **5516 S. Maplewood Ave.** IDPH LICENSE NO: **100-02865**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **72**  
MATERIAL DESCRIPTION: **12x12 Dark Brown w/Orange & White Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **café & kitchen**

MATERIAL QUANTITY: **950**


MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/10/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22601** BUIDLING ID: **2660**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Carson School, Rachel** REVIEW DATE: **4/4/2016**  
ADDRESS: **5516 S. Maplewood Ave.** IDPH LICENSE NO: **100-02865**

---

HOMOGENEOUS AREA: **72**  
MATERIAL DESCRIPTION: **12x12 Dark Brown w/Orange & White Floor Tile Mastic**  
MATERIAL LOCATION: **café & kitchen**  
MATERIAL QUANTITY: **950** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **04/04/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22601** BUIDLING ID: **2660**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Steven Doran**  
SCHOOL NAME: **Carson School, Rachel** INSPECTION DATE: **3/10/2016**  
ADDRESS: **5516 S. Maplewood Ave.** IDPH LICENSE NO: **100-02865**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **BB-1**  
MATERIAL DESCRIPTION: **4" baseboard**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **classrooms 3rd & 2nd, cafeteria**  
MATERIAL QUANTITY: **2500** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature:



Date: **03/10/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22601** BUIDLING ID: **2660**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Carson School, Rachel** REVIEW DATE: **4/4/2016**  
ADDRESS: **5516 S. Maplewood Ave.** IDPH LICENSE NO: **100-02865**

---

HOMOGENEOUS AREA: **BB-1**  
MATERIAL DESCRIPTION: **4" baseboard**  
MATERIAL LOCATION: **classrooms 3rd & 2nd, cafeteria**  
MATERIAL QUANTITY: **2500** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **04/04/2016**



# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22601** BUIDLING ID: **2660**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Steven Doran**  
SCHOOL NAME: **Carson School, Rachel** INSPECTION DATE: **3/10/2016**  
ADDRESS: **5516 S. Maplewood Ave.** IDPH LICENSE NO: **100-02865**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **BB-2**  
MATERIAL DESCRIPTION: **6" baseboard**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **room 303, 402**  
MATERIAL QUANTITY: **800** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature:



Date: **03/10/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22601** BUIDLING ID: **2660**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Carson School, Rachel** REVIEW DATE: **4/4/2016**  
ADDRESS: **5516 S. Maplewood Ave.** IDPH LICENSE NO: **100-02865**

---

HOMOGENEOUS AREA: **BB-2**  
MATERIAL DESCRIPTION: **6" baseboard**  
MATERIAL LOCATION: **room 303, 402**  
MATERIAL QUANTITY: **800** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **04/04/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22601** BUIDLING ID: **2660**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Steven Doran**  
SCHOOL NAME: **Carson School, Rachel** INSPECTION DATE: **3/10/2016**  
ADDRESS: **5516 S. Maplewood Ave.** IDPH LICENSE NO: **100-02865**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **BBM-1**  
MATERIAL DESCRIPTION: **4" baseboard mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **classrooms 3rd & 2nd, cafeteria**  
MATERIAL QUANTITY: **2500** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: DAMAGE UNITS: **LF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_

*Steven Doran*

Date: 03/10/2016

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22601** BUIDLING ID: **2660**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Carson School, Rachel** REVIEW DATE: **4/4/2016**  
ADDRESS: **5516 S. Maplewood Ave.** IDPH LICENSE NO: **100-02865**

---

HOMOGENEOUS AREA: **BBM-1**  
MATERIAL DESCRIPTION: **4" baseboard mastic**  
MATERIAL LOCATION: **classrooms 3rd & 2nd, cafeteria**  
MATERIAL QUANTITY: **2500** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **04/04/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22601** BUIDLING ID: **2660**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Steven Doran**  
SCHOOL NAME: **Carson School, Rachel** INSPECTION DATE: **3/10/2016**  
ADDRESS: **5516 S. Maplewood Ave.** IDPH LICENSE NO: **100-02865**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **BBM-2**  
MATERIAL DESCRIPTION: **6" baseboard mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **room 303**  
MATERIAL QUANTITY: **800** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature:



Date: **03/10/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22601** BUIDLING ID: **2660**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Carson School, Rachel** REVIEW DATE: **4/4/2016**  
ADDRESS: **5516 S. Maplewood Ave.** IDPH LICENSE NO: **100-02865**

---

HOMOGENEOUS AREA: **BBM-2**  
MATERIAL DESCRIPTION: **6" baseboard mastic**  
MATERIAL LOCATION: **room 303**  
MATERIAL QUANTITY: **800** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **04/04/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22601** BUIDLING ID: **2660**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Steven Doran**  
SCHOOL NAME: **Carson School, Rachel** INSPECTION DATE: **3/10/2016**  
ADDRESS: **5516 S. Maplewood Ave.** IDPH LICENSE NO: **100-02865**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **FT-1**  
MATERIAL DESCRIPTION: **12x12 white floor tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---


## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON: **Deterioration**  
DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **room 200,203,209, copy rm. Kit. Storage, Teachers Lounge**  
MATERIAL QUANTITY: **2200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS: **Damage is located in Room 200**

Inspector's Signature: \_\_\_\_\_



Date: 03/10/2016

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22601** BUIDLING ID: **2660**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Carson School, Rachel** REVIEW DATE: **4/4/2016**  
ADDRESS: **5516 S. Maplewood Ave.** IDPH LICENSE NO: **100-02865**

---

HOMOGENEOUS AREA: **FT-1**  
MATERIAL DESCRIPTION: **12x12 white floor tile**  
MATERIAL LOCATION: **room 200,203,209, copy rm. Kit. Storage, Teachers Lounge**  
MATERIAL QUANTITY: **2200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **8** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Repair as needed then follow O&M plan.

Management Planner's Signature: \_\_\_\_\_ Date: **04/04/2016**



# Chicago Public Schools

## Carnow, Conibear and Associates 2016 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22601** BUIDLING ID: **2660**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Steven Doran**  
SCHOOL NAME: **Carson School, Rachel** INSPECTION DATE: **3/10/2016**  
ADDRESS: **5516 S. Maplewood Ave.** IDPH LICENSE NO: **100-02865**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **FTM-1**  
MATERIAL DESCRIPTION: **12x12 white floor tile mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **room 200, 203,209,copy room, kit. Storage, teachers lounge**  
MATERIAL QUANTITY: **2200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/10/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22601** BUIDLING ID: **2660**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Carson School, Rachel** REVIEW DATE: **4/4/2016**  
ADDRESS: **5516 S. Maplewood Ave.** IDPH LICENSE NO: **100-02865**

---

HOMOGENEOUS AREA: **FTM-1**  
MATERIAL DESCRIPTION: **12x12 white floor tile mastic**  
MATERIAL LOCATION: **room 200, 203,209,copy room, kit. Storage, teachers lounge**  
MATERIAL QUANTITY: **2200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **04/04/2016**



# Chicago Public Schools

Carnow, Conibear and Associates

**2016 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **22601**      BUILDING ID: **2660**  
CITY/STATE: **Chicago, Illinois**      MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Carson School, Rachel**      REVIEW DATE: **4/4/2016**  
ADDRESS: **5516 S. Maplewood Ave.**      IDPH LICENSE NO: **100-02865**

HOMOGENEOUS AREA: **74**  
MATERIAL DESCRIPTION: **Mastic Associated w/ 12" x 12" White Floor Tile**  
MATERIAL LOCATION: **South Corridor near Elevators on 1st, 2nd, and 3rd Floor**  
MATERIAL QUANTITY: **960**      MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0**      DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_ Date: **04/04/2016**



# Chicago Public Schools

Carnow, Conibear and Associates

**2016 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **22601**      BUILDING ID: **2660**  
CITY/STATE: **Chicago, Illinois**      MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Carson School, Rachel**      REVIEW DATE: **4/4/2016**  
ADDRESS: **5516 S. Maplewood Ave.**      IDPH LICENSE NO: **100-02865**

HOMOGENEOUS AREA: **77**  
MATERIAL DESCRIPTION: **Mastic Associated w/ 4" x 4" Red Ceramic Tile w/ Grout**  
MATERIAL LOCATION: **East Foyer Entrance near Assistant Principal's Office, Lunch Room**  
MATERIAL QUANTITY: **250**      MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0**      DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_ Date: **04/04/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (New Homogeneous Area)


LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22601** BUILDING ID: **2660**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Steven Doran**  
SCHOOL NAME: **Carson School, Rachel** INSPECTION DATE: **3/10/2016**  
ADDRESS: **5516 S. Maplewood Ave.** IDPH LICENSE NO: **100-02865**

---

### INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **76**  
MATERIAL DESCRIPTION: **4" x 4" Red Ceramic Tile w/ Grout**  
MATERIAL LOCATION: **East Foyer Entrance near Assistant Principal's Office, Lunch Room**  
MATERIAL QUANTITY: **250** MATERIAL UNITS: **SF**  
MATERIAL CATEGORY: **MISC** FRIABLE: **No**  
ASBESTOS TYPE: **Assumed**  
DISTURBANCE POTENTIAL: **LOW** CONDITION:  
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
ACCESSIBILITY: **Within Reach** DAMAGE REASON:  
DAMAGE QUANTITY: **0** DAMAGE REASON:  
DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature:



Date: **03/10/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

**2016 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **22601**      BUILDING ID: **2660**  
CITY/STATE: **Chicago, Illinois**      MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Carson School, Rachel**      REVIEW DATE: **4/4/2016**  
ADDRESS: **5516 S. Maplewood Ave.**      IDPH LICENSE NO: **100-02865**

HOMOGENEOUS AREA: **76**  
MATERIAL DESCRIPTION: **4" x 4" Red Ceramic Tile w/ Grout**  
MATERIAL LOCATION: **East Foyer Entrance near Assistant Principal's Office, Lunch Room**  
MATERIAL QUANTITY: **250**      MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0**      DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_ Date: **04/04/2016**





# Chicago Public Schools

Carnow, Conibear and Associates

**2016 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **22601**      BUILDING ID: **2660**  
CITY/STATE: **Chicago, Illinois**      MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Carson School, Rachel**      REVIEW DATE: **4/4/2016**  
ADDRESS: **5516 S. Maplewood Ave.**      IDPH LICENSE NO: **100-02865**

HOMOGENEOUS AREA: **75**  
MATERIAL DESCRIPTION: **2' x 4' Smooth Ceiling Tile**  
MATERIAL LOCATION: **Rooms 203, 204, and 206**  
MATERIAL QUANTITY: **2700**      MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0**      DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_ Date: **04/04/2016**



# Chicago Public Schools

Carnow, Conibear and Associates

**2016 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **22601**      BUILDING ID: **2660**  
CITY/STATE: **Chicago, Illinois**      MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Carson School, Rachel**      REVIEW DATE: **4/4/2016**  
ADDRESS: **5516 S. Maplewood Ave.**      IDPH LICENSE NO: **100-02865**

HOMOGENEOUS AREA: **73**  
MATERIAL DESCRIPTION: **12" x 12" White Floor Tile**  
MATERIAL LOCATION: **South Corridor near Elevators on 1st, 2nd, and 3rd Floor**  
MATERIAL QUANTITY: **960**      MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0**      DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_ Date: **04/04/2016**

# APPENDIX B

## Inspector and Management Planner Licenses

---

2015



**OCCUPATIONAL TRAINING & SUPPLY, INC.**

7233 S. Adams Street ♦ Willowbrook, IL 60527 ♦ (630) 655-3900

# Asbestos Abatement Supervisor Refresher

Occupational Training & Supply, Inc. certifies that

**Steven Doran**

has successfully completed the Asbestos Abatement Supervisor Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 4/13/2015

Exam Date: 4/13/2015

Expiration Date: 4/13/2016

Certificate Number: ASR1504131973

Kathy DeSalvo, Director

**IDPH ASBESTOS PROFESSIONAL LICENSE**

ID NUMBER 100 - 02865 ISSUED 5/4/2015 EXPIRES 05/15/2016

STEVEN DORAN  
3340 MAPLE ST.  
EVERGREEN PARK, IL 60805



Environmental Health

**ENDORSEMENTS**

**TC EXPIRES**

INSPECTOR	2/14/2016
MANAGEMENT PLANNER	5/1/2015
PROJECT MANAGER	3/31/2015
AIR SAMPLING PROFESSIONAL	

Alteration of this license shall result in legal action.  
This license issued under authority of the State of Illinois  
Department of Public Health.  
This license is valid only when accompanied by a valid  
training course certificate.

# CERTIFICATE OF ACHIEVEMENT ASBESTOS ABATEMENT

Accredited by the Illinois Department of Public Health

This is to certify that STEVEN DORAN  
has completed the ASBESTOS INSPECTOR'S REFRESHER course and successfully passed the examination on 02/14/2015 with a minimum score of 70% or better. Training was in accordance with U.S. E.P.A. 40 CFR 763 Subpart E, Appendix C, Asbestos Containing Materials in Schools. Model Accreditation Plan, TSCA II, Authorized by both AHERA & ASHARA.



02/14/2015

Course Dates:

02/14/2016

Expires:

1502BIR12

Certificate Number:

A handwritten signature in black ink, appearing to read "N Penff".

Phone: 312-491-0081


Director of Training  
Nicholas J. Penff  
Doctor of Public Health

FORM # A-010B



# Evan Christian

Illinois Licensed Project Manager, and Air Sampling Professional



ENDORSEMENTS	TC EXPIRES
PROJECT MANAGER AIR SAMPLING PROFESSIONAL	12/12/2015
<b>Alteration of this license shall result in legal action</b> This license issued under authority of the State of Illinois Department of Public Health This license is valid only when accompanied by a valid training course certificate.	

**CARNOW  
CONIBEAR**

2015



# OCCUPATIONAL TRAINING & SUPPLY, INC.

7233 S. Adams Street ♦ Willowbrook, IL 60527 ♦ (630) 655-3900

## Asbestos Building Inspector Refresher

Occupational Training & Supply, Inc. certifies that

**Evan Christian**


has successfully completed the Asbestos Building Inspector Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 12/2/2015

Exam Date: 12/2/2015

Expiration Date: 12/2/2016

Certificate Number: BIR1512024159

  
Katy DeSalvo, Director

**Reliable**  
**Environmental**  
**Solutions, Inc.** **RES**

This is to certify that **Evan Christian**

*has on January 28 & 29, 2016, in Springfield, Illinois,  
completed the requirements for asbestos accreditation under Section 206 of TSCA Title II*

**Asbestos Management Planner Initial Training**

*as accredited by the State of Illinois and approved by the U.S.E.P.A. under 40 CFR 763 (AHERA)  
and passed the associated examination with a score of 70% or higher*

Course Date: January 28 & 29, 2016

Examination Date: January 29, 2016

Expiration Date: January 29, 2017

Certificate Number: MP/0103

*William S. Williams*

Training Program Manager, William S. Williams

4211 Westgate Drive, Springfield, Illinois ☐ 217.787.9800 ☐ 217.787.9801 FAX ☐ [www.ReliableEnv.com](http://www.ReliableEnv.com)

# APPENDIX C

## Laboratory Accreditations

---

# APPENDIX D

## Laboratory Results

---

# APPENDIX E

## Chain of Custody Forms

---

## Three-Year Reinspection Key to Terms

	<b>CODE</b>	<b>KEY</b>
<b>MATERIAL</b>		
	ACBM	Asbestos Containing Building Materials
<b>MATERIAL CATEGORY</b>		
	MISC	Miscellaneous
	SURF	Surfacing
	TSI	Thermal System Insulation
<b>MATERIAL UNITS</b>		
	LF	Linear Feet
	SF	Square Feet
	CF	Cubic Feet
<b>DAMAGE TYPE</b>		
	Loc	Localized
	Dist	Distributed