

ILLINOIS DEPARTMENT OF PUBLIC HEALTH  
AHERA THREE YEAR REINSPECTION  
ASBESTOS ABATEMENT PROGRAM  
SCHOOL INFORMATION FORM

**SECTION I**

NAME OF SCHOOL DISTRICT: CHICAGO SCHOOL DIST 299  
SCHOOL ID NUMBER: 14-016-2990-2864  
SCHOOL NAME: Perez School  
ADDRESS OF SCHOOL: 1241 W. 19th St.  
CITY: Chicago, IL, 60608

DATE LAST THREE YEAR REINSPECTION WAS COMPLETED **2/26/2013**

**If the address on this form is different than the address of the building, submit a written explanation.**

**SECTION II** (Please type or print)

PLEASE COMPLETE THE FOLLOWING FOR YOUR THREE YEAR REINSPECTION:

DATE REINSPECTION COMPLETED: 3/22/2016 ENROLLMENT 328  
IDPH INSPECTOR LICENSE NUMBER: 100-19466  
IDPH LICENSED INSPECTOR NAME (Please Print): Evan Christian  
IDPH MP LICENSE NUMBER: 100-09870  
IDPH LICENSED MANAGEMENT PLANNER NAME (Please Print): Todd Huffer

DESIGNATED PERSON (Please Print): Robert Christlieb PHONE: (773) 553-3197



3/22/2016

Signature of Designated Person

Date

**SECTION III**

PLEASE COMPLETE THE FOLLOWING INFORMATION FOR ANY CHANGES WITHIN THE SCHOOL DISTRICT.

School building has been sold. Date of Sale: \_\_\_\_\_

School has been closed. Date closed: \_\_\_\_\_

School building has been demolished. Date: \_\_\_\_\_

School building is asbestos free since last reinspection: \_\_\_\_\_

**Please explain in writing why the school building is now asbestos free and include the supporting documentation.**

If a new school building has been added to the district, submit either an exclusionary statement or a management plan and inspection report. Include the complete name, address and city of school building.

**Explain in writing if the address of the building is different than the address on this form:**

**THREE-YEAR REINSPECTION**

**CHICAGO SCHOOL DIST 299**

**Perez School**

1241 W. 19th St.  
Chicago, IL, 60608

Unit: 22861  
Building ID: 2930

IDPH ID Number: 14-016-2990-2864

**REPORT DATE:**

Tuesday, March 22, 2016

**Prepared for:**

**Chicago Public Schools**  
**125 S. Clark Street**  
**Chicago, IL 60603**

**Prepared by:**

**Carnow, Conibear and Associates**

600 West Van Buren St., Ste 500

Phone (312) 762-2900

Fax (312) 782-5145

**DO NOT REMOVE FROM SCHOOL  
REQUIRED BY FEDERAL LAW**

March 2, 2016

Mr. R. Kent Cook  
Asbestos Program  
Illinois Department of Public Health  
525 West Jefferson Street  
Springfield, Illinois 62761

Re: Chicago Public Schools - 2016 Three-Year Reinspections

Dear Mr. Cook:

Carnow, Conibear and Associates, Managing Environmental Consultant (MEC), conducted the Three-Year Reinspections and performed management plan updates for the Chicago Public Schools (CPS) facilities in Region 3,4,5 Elementary Schools. Please update your records with the following information.

School District: 299            Unit: 22861            Region: 03            IDPH ID: 14-016-2990-2864

School: Perez School            Building ID: 2930

Address: 1241 W. 19th St.

Chicago, IL, 60608

Building Contact: Sandoval, Michael

Contact Phone: 1111111111

Current Building Owners: Chicago Public Schools

Review Date: 03/22/2016

Inspector: Evan Christian

Inspector IDPH License: 100-19466

Management Planner: Todd Huffer

Management Planner IDPH License: 100-09870

If you have any questions or comments, please contact us at (312) 762-2900

Sincerely,  
Carnow, Conibear and Associates



Todd Huffer  
100-09870

## **Environmental Notification to Occupants**

To: Faculty, Staff and Parents  
From: Chicago Public Schools  
Date: March 02, 2016

RE: Perez School, Unit 22861  
1241 W. 19th St.  
Chicago, IL, 60608

Dear Faculty, Staff and Parents,

This letter is to notify you that the 2016 asbestos three year re-inspection has been completed at Perez School , following the Federal Asbestos Hazard Emergency Response Act (AHERA), 40 CFR Part 763, Subpart E and is available for your review at the main office of the school.

Although asbestos-containing materials have been identified at Perez School, there is no reason to believe that any threat to the health of students or staff exists at this time. CPS will continue to carefully monitor the condition of asbestos-containing materials and if conditions warrant, all appropriate steps will be taken to maintain the health and safety of all building occupants.

If you have any questions regarding this matter or require additional information, please feel free to contact Robert Christlieb, the designated Local Education Authority's Designated Person at (773) 553-3197 .

## **Table of Contents**

- I. School and Inspection Information
- II. Executive Summary
- III. Methodology
- IV. Abatement History
- V. Reassessments and Recommendations
- VI. Conclusions

Table I: Inspector's Reinspection Findings

Table II: Management Planner's Review

### **APPENDICES:**

- Appendix A: Assessment Sheets, Drawings and Photos
- Appendix B: Inspector and Management Planner Licenses
- Appendix C: Laboratory Accreditations
- Appendix D: Laboratory Results
- Appendix E: Chain of Custody Forms

## SCHOOL AND INSPECTION INFORMATION

### 1. School Information

School: Perez School Unit: 22861 Region: 03  
Address: 1241 W. 19th St. Chicago, IL, 60608  
IDPH ID: 14-016-2990-2864 Building ID: 2930  
Contact: Sandoval, Michael Phone: 1111111111

### 2. Description of Facility

Original Construction: Additional Construction:  
Total Square Footage: 38258 No of Floors: 3  
Current Occupancy: 328

### 3. LEA Designated Person

Contact: Robert Christlieb Phone: (773) 553-3197  
Address: 125 South Clark Street, 17th Floor  
Chicago, IL 60603

### 4. Managing Environmental Consultant

MEC: Carnow, Conibear and Associates  
Contact: Dan Juneau  
Address 600 West Van Buren St., Ste 500  
Phone: (312) 762-2900 Fax: (312) 782-5145

### 5. Inspector

Inspector Name: Evan Christian


Inspector IDPH license # 100-19466

Signature:  
Date: 3/2/2016

### 6. Management Planner

Management Planner Name: Todd Huffer

Management Planner IDPH license # 100-09870

Signature:   
Date: 03/22/2016

### 7. Review Date: 03/22/2016

### 8. LEA Designated Person's Acknowledgement

The reinspection report and recommendations have been received by me and appropriate action will be taken by the School District.

Signature: 

Date: 3/22/2016

Name: Robert Christlieb

## II. EXECUTIVE SUMMARY

Carnow, Conibear and Associates was retained by the Chicago Public Schools (CPS) to perform a three-year asbestos reinspection of the Perez School. This inspection was conducted in accordance with the United States Environmental Protection Agency (USEPA) Asbestos Hazard Emergency Response Act (AHERA) part 763.92 (b), and the ongoing Operations and Maintenance Program (O&M) originally designed in the School's Asbestos Management Plan. The purpose of this three-year reinspection is to record any condition changes in the asbestos-containing building material (ACBM) in the school since the previous three-year reinspection and the six-month periodic surveillance, to identify, assess, and include any Homogeneous Areas (HA) not identified in the Management Plan, and to recommend an appropriate response action to manage asbestos.

The inspector conducted a three-year reinspection of this facility under Illinois Department of Public Health (IDPH) school reinspection requirements and AHERA, sections 763.85 and 763.88. The main building and each addition to the main building, if constructed at different dates, were inspected separately. Laboratory accreditations are included in Appendix C, laboratory results are included in Appendix D, and chain of custody forms are included in Appendix E.

Note: During previous inspections, some of the HA(s) were identified together as 9" x 9" floor tile (FT), mastics assoc. with 9" x 9" FT, 12" x 12" FT, mastics assoc. with 12" x 12" FT, pipe insulation, etc. Some of these HA(s) have been re-identified by areas that are uniform in color, texture, construction date, application date, and general appearance.

The inspector has determined the following:

A. The following HAs have changed assessment categories for Building 2930:

B. The following new homogenous areas have been identified for Building 2930:



C. This reinspection covered only physically accessible and visible areas and materials that were identified in the LEA's management plan. The following materials were concealed and/or contained in areas that were inaccessible for sampling and have been classified as Assumed:

1	Stair Treads
10	12" x 12" Beige w/Gray Streaks Floor Tile Mastic
11	4" Black Vinyl Baseboard
13	4" Brown Vinyl Baseboard
14	4" Brown Vinyl Baseboard Adhesive
15	Brown Carpet Mastic
16	Beige Carpet Mastic
17	Blue Carpet Mastic
18	Cinder Block
19	Cinder Block Mortar
2	Stair Tread Adhesive
20	Lab Tops, Counters & Sinks
22	Elevator Brake Shoes
23	Ceiling Material
24	Sprayed-on coating on stainless steel sinks
25	12"x12" White w/ Blue Floor Tile
26	12"x12" White w/ Blue Floor Tile Mastic
27	Drywall
28	Drywall Joint Compound
29	Window Caulk
3	Spray on Fire Proofing
30	Door Caulk
31	Green Carpet Adhesive
4	Green Carpet Mastic
5	2' x 4' Fissured Lay-In Ceiling Panels
6	2' x 4' Random Dot Lay-In Ceiling Panels
7	12" x 12" White Floor Tile w/Gray Streaks
8	12" x 12" White w/Gray Streaks Floor Tile Mastic
9	12" x 12" Beige w/Gray Streaks Floor Tile

The following areas were deemed to be inaccessible:

10	12" x 12" Beige w/Gray Streaks Floor Tile Mastic
15	Brown Carpet Mastic
16	Beige Carpet Mastic
17	Blue Carpet Mastic
2	Stair Tread Adhesive
22	Elevator Brake Shoes
26	12"x12" White w/ Blue Floor Tile Mastic
4	Green Carpet Mastic

Materials were also listed as "assumed" if they were in good condition and sampling was not conducted to avoid damage.

This reinspection was conducted by Evan Christian, IDPH License # 100-19466. The Management Plan was updated by Todd Huffer, IDPH License # 100-09870. Inspector and Management Planner Licenses are included in Appendix B.

### **III. METHODOLOGY**

Tasks performed on-site included the following:

1. Review current management plan, identify HA(s) and extract appropriate information.
2. Examine and verify abatement records.
3. Touch and visually and physically reinspect and reassess the condition of all friable known or assumed ACBM.
4. Touch and visually and physically reinspect all non-friable known or assumed ACBM to determine whether these materials have become friable since the last inspection or periodic surveillance.
5. Identify any condition changes that may affect Hazard Ranking of known ACBM or Assumed ACBM, as well as any HA(s) that have become friable since the last reinspection.
6. Collect bulk samples from each newly discovered friable HA or previously assumed and submit for laboratory analysis.
7. Tabulate reinspection findings and submit for management planner review and recommendations with appropriate response actions based on the AHERA Damage Category of the ACBM.
8. Submit reinspection findings and management planner recommendations to the LEA within thirty (30) days for inclusion into the management plan.

### **IV. ABATEMENT HISTORY**

The information collected from the existing management plan and inspection report(s) and from interviews with the school official revealed that the following asbestos abatement was conducted at the school since the previous Three year Reinspection.

Abatement Dates:

### **V. REASSESSMENTS AND RECOMMENDATIONS**

The reassessments and recommendations are summarized in Tables I and II on the following pages. Detailed Hazard Assessment Sheets and Drawings and Photos (if applicable) are included in Appendix A.

### **VI. CONCLUSIONS**

The Perez School Building 2930 Three-Year reinspection has been completed and response actions have been recommended for both friable and non-friable materials. A timely execution of the response actions recommended will enable the LEA and the Designated Person(s) to effectively manage the existing ACBM.

This three-year reinspection report should be inspected in the current Management plan at the CPS Central Office, and one (1) copy should be kept at the school for use when planning any renovation and/or demolition activities in areas where ACBM has been identified. Also, periodic surveillance documentation and any summary reports from any response actions that are executed at the school should be used to update the Management Plan.

**Table I**  
**Inspector's Reinspection Findings**

---

# Chicago Public Schools

School Perez School Unit 22861 Building ID 2930

Address 1241 W. 19th St. Region 03

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
1	Stair Treads	450,000	SF	Stairways	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
10	12" x 12" Beige w/Gray Streaks Floor Tile Mastic	32,000	LF	Faculty Center, Main Office, 2nd Floor Stair Landing and room 203	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
11	4" Black Vinyl Baseboard	32,000	LF	Main Office and Library	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
12	4" Black Vinyl Baseboard Adhesive	3,000	LF	Main Office and Library	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
13	4" Brown Vinyl Baseboard	1,000	LF	Throughout Facility	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
14	4" Brown Vinyl Baseboard Adhesive	1,000	LF	Throughout Facility	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
15	Brown Carpet Mastic	2,400	SF	Rooms 205, 206, and Office	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
16	Beige Carpet Mastic	900	SF	Room 203	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
17	Blue Carpet Mastic	800	SF	Room 207	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
18	Cinder Block	1,000	SF	All Walls in Facility	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
19	Cinder Block Mortar	1,000	SF	All Walls in Facility	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
2	Stair Tread Adhesive	312	SF	Stairways	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
20	Lab Tops, Counters & Sinks	100	SF	Room 210	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
21	Fiberglass Insulation on Pipes, Joints, Boiler etc			Throughout Facility		MISC								
22	Elevator Brake Shoes	20	SF	Elevator Shaft	ASSUMED	MISC	N	NONE	0		No	ACBM with potential for significant damage		HIGH
23	Ceiling Material	2,000	SF	Lunchroom, Janitor's Closet, Washrooms and Stairways	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
24	Sprayed-on coating on stainless steel sinks	30	SF	Rooms 101, 102, 103, copy room, and nurse's office	ASSUMED	SURFACE	N	NONE	0		No	ACBM with the potential for damage		LOW
25	12"x12" White w/ Blue Floor Tile	120	SF	As Patching in Lunchroom	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
26	12"x12" White w/ Blue Floor Tile Mastic	120	SF	As Patching in Lunchroom	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
27	Drywall	5,000	SF	Cafe	ASSUMED	MISC	Y	NONE	0		No	Any remaining friable		LOW

# Chicago Public Schools

School Perez School Unit 22861 Building ID 2930

Address 1241 W. 19th St. Region 03

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
												ACBM or friable suspect ACBM		
28	Drywall Joint Compound	5,000	SF	Cafe	ASSUMED	MISC	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
29	Window Caulk	6,000	SF	Throughout	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
3	Spray on Fire Proofing	1,600	SF	Above Ceilings on Beams and Structural Supports	ASSUMED	SURFACE	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
30	Door Caulk	1,000	SF	Throughout	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
31	Green Carpet Adhesive	800	SF	Room 204	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
4	Green Carpet Mastic	600	SF	Library	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
5	2' x 4' Fissured Lay-In Ceiling Panels	15,000	SF	Throughout Facility	ASSUMED	MISC	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
6	2' x 4' Random Dot Lay-In Ceiling Panels	1,000	SF	Kitchen	ASSUMED	MISC	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
7	12" x 12" White Floor Tile w/Gray Streaks	12,000	SF	All Corridors, Gym, Lunch Area, Part of all 2nd Floor Classrooms, 210 & 211	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
8	12" x 12" White w/Gray Streaks Floor Tile Mastic	1,000	SF	All Corridors, Gym, Lunch Area, Part of all 2nd Floor Classrooms, 210 & 211	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
9	12" x 12" Beige w/Gray Streaks Floor Tile	1,000	SF	Faculty Center, Main Office, 2nd Floor Stair Landing	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW

# Chicago Public Schools

School Perez School Unit 22861 Building ID 2930

Address 1241 W. 19th St. Region 03

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

*Inspector's Comments are Summarized at the End of the Report*

Reinspection Date <b>3/2/2016</b>
Inspector Name <b><u>Evan Christian</u></b>
<b>100-19466</b> <b>5/15/2016</b>
Inspector's IDPH License Number / Expiration Date

### Inspector's Comments

HA Number:	Inspector Comments:
1	
10	
11	
12	
13	
14	
15	
16	
17	
18	
19	
2	
20	
21	Fiberglass not suspect material.
22	
23	
24	
25	
26	
27	
28	
29	
3	
30	

# Chicago Public Schools

**School** Perez School **Unit** 22861 **Building ID** 2930

**Address** 1241 W. 19th St. **Region** 03

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

*Inspector's Comments are Summarized at the End of the Report*

---

HA Number:	Inspector Comments:
31	
4	
5	
6	
7	
8	
9	



**Table II**

**Management Planner's Review**

---

# Chicago Public Schools

School Perez School  
Address 1241 W. 19th St.

Unit 22861  
Chicago, IL, 60608

Building ID 2930  
Region 03

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

### Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
1	Stair Treads	450,000	SF	Stairways	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
10	12" x 12" Beige w/Gray Streaks Floor Tile Mastic	32,000	LF	Faculty Center, Main Office, 2nd Floor Stair Landing and room 203	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
11	4" Black Vinyl Baseboard	32,000	LF	Main Office and Library	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
12	4" Black Vinyl Baseboard Adhesive	3,000	LF	Main Office and Library	Chrysotile	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
13	4" Brown Vinyl Baseboard	1,000	LF	Throughout Facility	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
14	4" Brown Vinyl Baseboard Adhesive	1,000	LF	Throughout Facility	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
15	Brown Carpet Mastic	2,400	SF	Rooms 205, 206, and Office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
16	Beige Carpet Mastic	900	SF	Room 203	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
17	Blue Carpet Mastic	800	SF	Room 207	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
18	Cinder Block	1,000	SF	All Walls in Facility	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
19	Cinder Block Mortar	1,000	SF	All Walls in Facility	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
2	Stair Tread Adhesive	312	SF	Stairways	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
20	Lab Tops, Counters & Sinks	100	SF	Room 210	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
21	Fiberglass Insulation on Pipes, Joints, Boiler etc			Throughout Facility		MISC					
22	Elevator Brake Shoes	20	SF	Elevator Shaft	Assumed	MISC	No	0	SF	5 ACBM with potential for significant damage	Follow O&M Plan
23	Ceiling Material	2,000	SF	Lunchroom, Janitor's Closet, Washrooms and Stairways	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
24	Sprayed-on coating on stainless steel sinks	30	SF	Rooms 101, 102, 103, copy room, and nurse's office	Assumed	SURFACE	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
25	12"x12" White w/ Blue Floor Tile	120	SF	As Patching in Lunchroom	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
26	12"x12" White w/ Blue Floor Tile Mastic	120	SF	As Patching in Lunchroom	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
27	Drywall	5,000	SF	Cafe	Assumed	MISC	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
28	Drywall Joint Compound	5,000	SF	Cafe	Assumed	MISC	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
29	Window Caulk	6,000	SF	Throughout	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
3	Spray on Fire Proofing	1,600	SF	Above Ceilings on Beams and Structural Supports	Assumed	SURFACE	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
30	Door Caulk	1,000	SF	Throughout	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
31	Green Carpet Adhesive	800	SF	Room 204	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
4	Green Carpet Mastic	600	SF	Library	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
5	2' x 4' Fissured Lay-In Ceiling Panels	15,000	SF	Throughout Facility	Assumed	MISC	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan

# Chicago Public Schools

**School** Perez School  
**Address** 1241 W. 19th St.

**Unit** 22861  
 Chicago, IL, 60608

**Building ID** 2930  
**Region** 03

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

### *Management Planner's Comments Summarized at the End of the Report*

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
6	2' x 4' Random Dot Lay-In Ceiling Panels	1,000	SF	Kitchen	Assumed	MISC	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
7	12" x 12" White Floor Tile w/Gray Streaks	12,000	SF	All Corridors, Gym, Lunch Area, Part of all 2nd Floor Classrooms, 210 & 211	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
8	12" x 12" White w/Gray Streaks Floor Tile Mastic	1,000	SF	All Corridors, Gym, Lunch Area, Part of all 2nd Floor Classrooms, 210 & 211	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
9	12" x 12" Beige w/Gray Streaks Floor Tile	1,000	SF	Faculty Center, Main Office, 2nd Floor Stair Landing	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

# Chicago Public Schools

**School** Perez School  
**Address** 1241 W. 19th St.

**Unit** 22861  
 Chicago, IL, 60608

**Building ID** 2930  
**Region** 03

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

### *Management Planner's Comments Summarized at the End of the Report*

Review Date	3/22/2016
Manager Planner Name	Todd Huffer
100-09870	5/15/2016
Manager IDPH License No/Expiration	

HA Number	Management Comments
1	
10	
11	
12	
13	
14	
15	
16	
17	
18	
19	
2	
20	
21	Fiberglass is not a suspect material
22	
23	
24	
25	
26	
27	
28	
29	
3	
30	
31	
4	

# Chicago Public Schools

**School** Perez School  
**Address** 1241 W. 19th St.

**Unit** 22861  
Chicago, IL, 60608

**Building ID** 2930  
**Region** 03

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates  
600 West Van Buren St., Ste 500  
Phone: (312) 762-2900 Fax: (312) 782-5145

### *Management Planner's Comments Summarized at the End of the Report*

HA Number	Management Comments
5	
6	
7	
8	
9	

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22861** BUIDLING ID: **2930**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Evan Christian**  
SCHOOL NAME: **Perez School** INSPECTION DATE: **3/2/2016**  
ADDRESS: **1241 W. 19th St.** IDPH LICENSE NO: **100-19466**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **1**  
MATERIAL DESCRIPTION: **Stair Treads**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Stairways**

MATERIAL QUANTITY: **450000**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **03/02/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22861** BUIDLING ID: **2930**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Perez School** REVIEW DATE: **3/22/2016**  
ADDRESS: **1241 W. 19th St.** IDPH LICENSE NO: **100-19466**

---

HOMOGENEOUS AREA: **1**  
MATERIAL DESCRIPTION: **Stair Treads**  
MATERIAL LOCATION: **Stairways**  
MATERIAL QUANTITY: **450000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **03/22/2016**

# Chicago Public Schools

## Carnow, Conibear and Associates 2016 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22861** BUIDLING ID: **2930**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Evan Christian**  
SCHOOL NAME: **Perez School** INSPECTION DATE: **3/2/2016**  
ADDRESS: **1241 W. 19th St.** IDPH LICENSE NO: **100-19466**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **10**  
MATERIAL DESCRIPTION: **12" x 12" Beige w/Gray Streaks Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Faculty Center, Main Office, 2nd Floor Stair Landing and room 203**  
MATERIAL QUANTITY: **32000** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 03/02/2016



# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22861** BUIDLING ID: **2930**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Perez School** REVIEW DATE: **3/22/2016**  
ADDRESS: **1241 W. 19th St.** IDPH LICENSE NO: **100-19466**

---

HOMOGENEOUS AREA: **10**  
MATERIAL DESCRIPTION: **12" x 12" Beige w/Gray Streaks Floor Tile Mastic**  
MATERIAL LOCATION: **Faculty Center, Main Office, 2nd Floor Stair Landing and room 203**  
MATERIAL QUANTITY: **32000** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **03/22/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22861** BUIDLING ID: **2930**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Evan Christian**  
SCHOOL NAME: **Perez School** INSPECTION DATE: **3/2/2016**  
ADDRESS: **1241 W. 19th St.** IDPH LICENSE NO: **100-19466**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **11**  
MATERIAL DESCRIPTION: **4" Black Vinyl Baseboard**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Main Office and Library**  
MATERIAL QUANTITY: **32000** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: DAMAGE UNITS: **LF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 03/02/2016

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22861** BUIDLING ID: **2930**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Perez School** REVIEW DATE: **3/22/2016**  
ADDRESS: **1241 W. 19th St.** IDPH LICENSE NO: **100-19466**

---

HOMOGENEOUS AREA: **11**  
MATERIAL DESCRIPTION: **4" Black Vinyl Baseboard**  
MATERIAL LOCATION: **Main Office and Library**  
MATERIAL QUANTITY: **32000** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **03/22/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22861** BUIDLING ID: **2930**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Evan Christian**  
SCHOOL NAME: **Perez School** INSPECTION DATE: **3/2/2016**  
ADDRESS: **1241 W. 19th St.** IDPH LICENSE NO: **100-19466**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **12**  
MATERIAL DESCRIPTION: **4" Black Vinyl Baseboard Adhesive**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Main Office and Library**

MATERIAL QUANTITY: **3000**

MATERIAL UNITS: **LF**

DAMAGE QUANTITY:

DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_

Date: 03/02/2016

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22861** BUIDLING ID: **2930**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Perez School** REVIEW DATE: **3/22/2016**  
ADDRESS: **1241 W. 19th St.** IDPH LICENSE NO: **100-19466**

---

HOMOGENEOUS AREA: **12**  
MATERIAL DESCRIPTION: **4" Black Vinyl Baseboard Adhesive**  
MATERIAL LOCATION: **Main Office and Library**  
MATERIAL QUANTITY: **3000** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **03/22/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22861** BUIDLING ID: **2930**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Evan Christian**  
SCHOOL NAME: **Perez School** INSPECTION DATE: **3/2/2016**  
ADDRESS: **1241 W. 19th St.** IDPH LICENSE NO: **100-19466**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **13**  
MATERIAL DESCRIPTION: **4" Brown Vinyl Baseboard**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Throughout Facility**

MATERIAL QUANTITY: **1000**

MATERIAL UNITS: **LF**

DAMAGE QUANTITY:

DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_

Date: 03/02/2016

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22861** BUIDLING ID: **2930**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Perez School** REVIEW DATE: **3/22/2016**  
ADDRESS: **1241 W. 19th St.** IDPH LICENSE NO: **100-19466**

---

HOMOGENEOUS AREA: **13**  
MATERIAL DESCRIPTION: **4" Brown Vinyl Baseboard**  
MATERIAL LOCATION: **Throughout Facility**  
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **03/22/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22861** BUIDLING ID: **2930**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Evan Christian**  
SCHOOL NAME: **Perez School** INSPECTION DATE: **3/2/2016**  
ADDRESS: **1241 W. 19th St.** IDPH LICENSE NO: **100-19466**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **14**  
MATERIAL DESCRIPTION: **4" Brown Vinyl Baseboard Adhesive**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Throughout Facility**

MATERIAL QUANTITY: **1000**

MATERIAL UNITS: **LF**

DAMAGE QUANTITY:

DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 03/02/2016



# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22861** BUIDLING ID: **2930**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Perez School** REVIEW DATE: **3/22/2016**  
ADDRESS: **1241 W. 19th St.** IDPH LICENSE NO: **100-19466**

---

HOMOGENEOUS AREA: **14**  
MATERIAL DESCRIPTION: **4" Brown Vinyl Baseboard Adhesive**  
MATERIAL LOCATION: **Throughout Facility**  
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **03/22/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22861** BUIDLING ID: **2930**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Evan Christian**  
SCHOOL NAME: **Perez School** INSPECTION DATE: **3/2/2016**  
ADDRESS: **1241 W. 19th St.** IDPH LICENSE NO: **100-19466**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **15**  
MATERIAL DESCRIPTION: **Brown Carpet Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Rooms 205, 206, and Office**  
MATERIAL QUANTITY: **2400** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 03/02/2016

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22861** BUIDLING ID: **2930**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Perez School** REVIEW DATE: **3/22/2016**  
ADDRESS: **1241 W. 19th St.** IDPH LICENSE NO: **100-19466**

---

HOMOGENEOUS AREA: **15**  
MATERIAL DESCRIPTION: **Brown Carpet Mastic**  
MATERIAL LOCATION: **Rooms 205, 206, and Office**  
MATERIAL QUANTITY: **2400** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **03/22/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22861** BUIDLING ID: **2930**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Evan Christian**  
SCHOOL NAME: **Perez School** INSPECTION DATE: **3/2/2016**  
ADDRESS: **1241 W. 19th St.** IDPH LICENSE NO: **100-19466**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **16**  
MATERIAL DESCRIPTION: **Beige Carpet Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Room 203**

MATERIAL QUANTITY: **900**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 03/02/2016

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22861** BUIDLING ID: **2930**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Perez School** REVIEW DATE: **3/22/2016**  
ADDRESS: **1241 W. 19th St.** IDPH LICENSE NO: **100-19466**

---

HOMOGENEOUS AREA: **16**

MATERIAL DESCRIPTION: **Beige Carpet Mastic**

MATERIAL LOCATION: **Room 203**

MATERIAL QUANTITY: **900**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **03/22/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22861** BUIDLING ID: **2930**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Evan Christian**  
SCHOOL NAME: **Perez School** INSPECTION DATE: **3/2/2016**  
ADDRESS: **1241 W. 19th St.** IDPH LICENSE NO: **100-19466**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **17**  
MATERIAL DESCRIPTION: **Blue Carpet Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Room 207**  
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 03/02/2016

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22861** BUIDLING ID: **2930**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Perez School** REVIEW DATE: **3/22/2016**  
ADDRESS: **1241 W. 19th St.** IDPH LICENSE NO: **100-19466**

---

HOMOGENEOUS AREA: **17**  
MATERIAL DESCRIPTION: **Blue Carpet Mastic**  
MATERIAL LOCATION: **Room 207**  
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **03/22/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22861** BUIDLING ID: **2930**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Evan Christian**  
SCHOOL NAME: **Perez School** INSPECTION DATE: **3/2/2016**  
ADDRESS: **1241 W. 19th St.** IDPH LICENSE NO: **100-19466**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **18**  
MATERIAL DESCRIPTION: **Cinder Block**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **All Walls in Facility**  
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 03/02/2016



# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22861** BUIDLING ID: **2930**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Perez School** REVIEW DATE: **3/22/2016**  
ADDRESS: **1241 W. 19th St.** IDPH LICENSE NO: **100-19466**

---

HOMOGENEOUS AREA: **18**  
MATERIAL DESCRIPTION: **Cinder Block**  
MATERIAL LOCATION: **All Walls in Facility**  
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **03/22/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22861** BUIDLING ID: **2930**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Evan Christian**  
SCHOOL NAME: **Perez School** INSPECTION DATE: **3/2/2016**  
ADDRESS: **1241 W. 19th St.** IDPH LICENSE NO: **100-19466**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **19**  
MATERIAL DESCRIPTION: **Cinder Block Mortar**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **All Walls in Facility**  
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 03/02/2016

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22861** BUIDLING ID: **2930**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Perez School** REVIEW DATE: **3/22/2016**  
ADDRESS: **1241 W. 19th St.** IDPH LICENSE NO: **100-19466**

---

HOMOGENEOUS AREA: **19**  
MATERIAL DESCRIPTION: **Cinder Block Mortar**  
MATERIAL LOCATION: **All Walls in Facility**  
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **03/22/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22861** BUIDLING ID: **2930**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Evan Christian**  
SCHOOL NAME: **Perez School** INSPECTION DATE: **3/2/2016**  
ADDRESS: **1241 W. 19th St.** IDPH LICENSE NO: **100-19466**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **2**  
MATERIAL DESCRIPTION: **Stair Tread Adhesive**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Stairways**

MATERIAL QUANTITY: **312**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_

Date: 03/02/2016

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22861** BUIDLING ID: **2930**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Perez School** REVIEW DATE: **3/22/2016**  
ADDRESS: **1241 W. 19th St.** IDPH LICENSE NO: **100-19466**

---

HOMOGENEOUS AREA: **2**  
MATERIAL DESCRIPTION: **Stair Tread Adhesive**  
MATERIAL LOCATION: **Stairways**  
MATERIAL QUANTITY: **312** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **03/22/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22861** BUIDLING ID: **2930**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Evan Christian**  
SCHOOL NAME: **Perez School** INSPECTION DATE: **3/2/2016**  
ADDRESS: **1241 W. 19th St.** IDPH LICENSE NO: **100-19466**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **20**  
MATERIAL DESCRIPTION: **Lab Tops, Counters & Sinks**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Room 210**  
MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 03/02/2016

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22861** BUIDLING ID: **2930**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Perez School** REVIEW DATE: **3/22/2016**  
ADDRESS: **1241 W. 19th St.** IDPH LICENSE NO: **100-19466**

---

HOMOGENEOUS AREA: **20**

MATERIAL DESCRIPTION: **Lab Tops, Counters & Sinks**

MATERIAL LOCATION: **Room 210**

MATERIAL QUANTITY: **100**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **03/22/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22861** BUIDLING ID: **2930**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Evan Christian**  
SCHOOL NAME: **Perez School** INSPECTION DATE: **3/2/2016**  
ADDRESS: **1241 W. 19th St.** IDPH LICENSE NO: **100-19466**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **21**  
MATERIAL DESCRIPTION: **Fiberglass Insulation on Pipes, Joints, Boiler etc**  
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout Facility**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Fiberglass not suspect material.**

Inspector's Signature: \_\_\_\_\_

Date: **03/02/2016**



# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22861** BUIDLING ID: **2930**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Perez School** REVIEW DATE: **3/22/2016**  
ADDRESS: **1241 W. 19th St.** IDPH LICENSE NO: **100-19466**

---

HOMOGENEOUS AREA: **21**

MATERIAL DESCRIPTION: **Fiberglass Insulation on Pipes, Joints, Boiler etc**

MATERIAL LOCATION: **Throughout Facility**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Fiberglass is not a suspect material

Management Planner's Signature: \_\_\_\_\_



Date: **03/22/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22861** BUIDLING ID: **2930**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Evan Christian**  
SCHOOL NAME: **Perez School** INSPECTION DATE: **3/2/2016**  
ADDRESS: **1241 W. 19th St.** IDPH LICENSE NO: **100-19466**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **22**  
MATERIAL DESCRIPTION: **Elevator Brake Shoes**  
HISTORICAL AHERA DAMAGE CATEGORY **5 ACBM with potential for significant damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **5. ACBM with potential for significant damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **HIGH**  
MATERIAL LOCATION: **Elevator Shaft**  
MATERIAL QUANTITY: **20** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 03/02/2016

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22861** BUIDLING ID: **2930**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Perez School** REVIEW DATE: **3/22/2016**  
ADDRESS: **1241 W. 19th St.** IDPH LICENSE NO: **100-19466**

---

HOMOGENEOUS AREA: **22**

MATERIAL DESCRIPTION: **Elevator Brake Shoes**

MATERIAL LOCATION: **Elevator Shaft**

MATERIAL QUANTITY: **20**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **03/22/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22861** BUIDLING ID: **2930**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Evan Christian**  
SCHOOL NAME: **Perez School** INSPECTION DATE: **3/2/2016**  
ADDRESS: **1241 W. 19th St.** IDPH LICENSE NO: **100-19466**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **23**  
MATERIAL DESCRIPTION: **Ceiling Material**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**

MATERIAL LOCATION: **Lunchroom, Janitor's Closet, Washrooms and Stairways**

MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 03/02/2016

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22861** BUIDLING ID: **2930**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Perez School** REVIEW DATE: **3/22/2016**  
ADDRESS: **1241 W. 19th St.** IDPH LICENSE NO: **100-19466**

---

HOMOGENEOUS AREA: **23**  
MATERIAL DESCRIPTION: **Ceiling Material**  
MATERIAL LOCATION: **Lunchroom, Janitor's Closet, Washrooms and Stairways**  
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **03/22/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22861** BUIDLING ID: **2930**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Evan Christian**  
SCHOOL NAME: **Perez School** INSPECTION DATE: **3/2/2016**  
ADDRESS: **1241 W. 19th St.** IDPH LICENSE NO: **100-19466**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **24**  
MATERIAL DESCRIPTION: **Sprayed-on coating on stainless steel sinks**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Rooms 101, 102, 103, copy room, and nurse's office**

MATERIAL QUANTITY: **30** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 03/02/2016

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22861** BUIDLING ID: **2930**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Perez School** REVIEW DATE: **3/22/2016**  
ADDRESS: **1241 W. 19th St.** IDPH LICENSE NO: **100-19466**

---

HOMOGENEOUS AREA: **24**

MATERIAL DESCRIPTION: **Sprayed-on coating on stainless steel sinks**

MATERIAL LOCATION: **Rooms 101, 102, 103, copy room, and nurse's office**

MATERIAL QUANTITY: **30**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **03/22/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22861** BUIDLING ID: **2930**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Evan Christian**  
SCHOOL NAME: **Perez School** INSPECTION DATE: **3/2/2016**  
ADDRESS: **1241 W. 19th St.** IDPH LICENSE NO: **100-19466**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **25**  
MATERIAL DESCRIPTION: **12"x12" White w/ Blue Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **As Patching in Lunchroom**

MATERIAL QUANTITY: **120**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 03/02/2016



# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22861** BUIDLING ID: **2930**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Perez School** REVIEW DATE: **3/22/2016**  
ADDRESS: **1241 W. 19th St.** IDPH LICENSE NO: **100-19466**

---

HOMOGENEOUS AREA: **25**  
MATERIAL DESCRIPTION: **12"x12" White w/ Blue Floor Tile**  
MATERIAL LOCATION: **As Patching in Lunchroom**  
MATERIAL QUANTITY: **120** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **03/22/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22861** BUIDLING ID: **2930**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Evan Christian**  
SCHOOL NAME: **Perez School** INSPECTION DATE: **3/2/2016**  
ADDRESS: **1241 W. 19th St.** IDPH LICENSE NO: **100-19466**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **26**  
MATERIAL DESCRIPTION: **12"x12" White w/ Blue Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **As Patching in Lunchroom**

MATERIAL QUANTITY: **120**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_

Date: 03/02/2016

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22861** BUIDLING ID: **2930**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Perez School** REVIEW DATE: **3/22/2016**  
ADDRESS: **1241 W. 19th St.** IDPH LICENSE NO: **100-19466**

---

HOMOGENEOUS AREA: **26**  
MATERIAL DESCRIPTION: **12"x12" White w/ Blue Floor Tile Mastic**  
MATERIAL LOCATION: **As Patching in Lunchroom**  
MATERIAL QUANTITY: **120** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **03/22/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22861** BUIDLING ID: **2930**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Evan Christian**  
SCHOOL NAME: **Perez School** INSPECTION DATE: **3/2/2016**  
ADDRESS: **1241 W. 19th St.** IDPH LICENSE NO: **100-19466**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **27**  
MATERIAL DESCRIPTION: **Drywall**  
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Cafe**  
MATERIAL QUANTITY: **5000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 03/02/2016

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22861** BUIDLING ID: **2930**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Perez School** REVIEW DATE: **3/22/2016**  
ADDRESS: **1241 W. 19th St.** IDPH LICENSE NO: **100-19466**

---

HOMOGENEOUS AREA: **27**  
MATERIAL DESCRIPTION: **Drywall**  
MATERIAL LOCATION: **Cafe**  
MATERIAL QUANTITY: **5000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **03/22/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22861** BUIDLING ID: **2930**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Evan Christian**  
SCHOOL NAME: **Perez School** INSPECTION DATE: **3/2/2016**  
ADDRESS: **1241 W. 19th St.** IDPH LICENSE NO: **100-19466**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **28**  
MATERIAL DESCRIPTION: **Drywall Joint Compound**  
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Cafe**  
MATERIAL QUANTITY: **5000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 03/02/2016

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22861** BUIDLING ID: **2930**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Perez School** REVIEW DATE: **3/22/2016**  
ADDRESS: **1241 W. 19th St.** IDPH LICENSE NO: **100-19466**

---

HOMOGENEOUS AREA: **28**  
MATERIAL DESCRIPTION: **Drywall Joint Compound**  
MATERIAL LOCATION: **Cafe**  
MATERIAL QUANTITY: **5000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **03/22/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **22861**    BUIDLING ID: **2930**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Evan Christian**  
SCHOOL NAME: **Perez School**    INSPECTION DATE: **3/2/2016**  
ADDRESS: **1241 W. 19th St.**    IDPH LICENSE NO: **100-19466**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **29**  
MATERIAL DESCRIPTION: **Window Caulk**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed**    FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Throughout**  
MATERIAL QUANTITY: **6000**    MATERIAL UNITS: **SF**  
DAMAGE QUANTITY:    DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 03/02/2016



# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22861** BUIDLING ID: **2930**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Perez School** REVIEW DATE: **3/22/2016**  
ADDRESS: **1241 W. 19th St.** IDPH LICENSE NO: **100-19466**

---

HOMOGENEOUS AREA: **29**  
MATERIAL DESCRIPTION: **Window Caulk**  
MATERIAL LOCATION: **Throughout**  
MATERIAL QUANTITY: **6000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **03/22/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **22861**    BUIDLING ID: **2930**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Evan Christian**  
SCHOOL NAME: **Perez School**    INSPECTION DATE: **3/2/2016**  
ADDRESS: **1241 W. 19th St.**    IDPH LICENSE NO: **100-19466**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **3**  
MATERIAL DESCRIPTION: **Spray on Fire Proofing**  
HISTORICAL AHERA DAMAGE CATEGORY **7 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed**    FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Above Ceilings on Beams and Structural Supports**  
MATERIAL QUANTITY: **1600**    MATERIAL UNITS: **SF**  
DAMAGE QUANTITY:    DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 03/02/2016

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22861** BUIDLING ID: **2930**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Perez School** REVIEW DATE: **3/22/2016**  
ADDRESS: **1241 W. 19th St.** IDPH LICENSE NO: **100-19466**

---

HOMOGENEOUS AREA: **3**  
MATERIAL DESCRIPTION: **Spray on Fire Proofing**  
MATERIAL LOCATION: **Above Ceilings on Beams and Structural Supports**  
MATERIAL QUANTITY: **1600** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **03/22/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22861** BUIDLING ID: **2930**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Evan Christian**  
SCHOOL NAME: **Perez School** INSPECTION DATE: **3/2/2016**  
ADDRESS: **1241 W. 19th St.** IDPH LICENSE NO: **100-19466**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **30**  
MATERIAL DESCRIPTION: **Door Caulk**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Throughout**  
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 03/02/2016

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22861** BUIDLING ID: **2930**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Perez School** REVIEW DATE: **3/22/2016**  
ADDRESS: **1241 W. 19th St.** IDPH LICENSE NO: **100-19466**

---

HOMOGENEOUS AREA: **30**  
MATERIAL DESCRIPTION: **Door Caulk**  
MATERIAL LOCATION: **Throughout**  
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **03/22/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22861** BUIDLING ID: **2930**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Evan Christian**  
SCHOOL NAME: **Perez School** INSPECTION DATE: **3/2/2016**  
ADDRESS: **1241 W. 19th St.** IDPH LICENSE NO: **100-19466**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **31**  
MATERIAL DESCRIPTION: **Green Carpet Adhesive**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Room 204**  
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 03/02/2016

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22861** BUIDLING ID: **2930**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Perez School** REVIEW DATE: **3/22/2016**  
ADDRESS: **1241 W. 19th St.** IDPH LICENSE NO: **100-19466**

---

HOMOGENEOUS AREA: **31**  
MATERIAL DESCRIPTION: **Green Carpet Adhesive**  
MATERIAL LOCATION: **Room 204**  
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **03/22/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22861** BUIDLING ID: **2930**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Evan Christian**  
SCHOOL NAME: **Perez School** INSPECTION DATE: **3/2/2016**  
ADDRESS: **1241 W. 19th St.** IDPH LICENSE NO: **100-19466**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **4**  
MATERIAL DESCRIPTION: **Green Carpet Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Library**

MATERIAL QUANTITY: **600**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_

Date: 03/02/2016



# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22861** BUIDLING ID: **2930**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Perez School** REVIEW DATE: **3/22/2016**  
ADDRESS: **1241 W. 19th St.** IDPH LICENSE NO: **100-19466**

---

HOMOGENEOUS AREA: **4**  
MATERIAL DESCRIPTION: **Green Carpet Mastic**  
MATERIAL LOCATION: **Library**  
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **03/22/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **22861**    BUIDLING ID: **2930**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Evan Christian**  
SCHOOL NAME: **Perez School**    INSPECTION DATE: **3/2/2016**  
ADDRESS: **1241 W. 19th St.**    IDPH LICENSE NO: **100-19466**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **5**  
MATERIAL DESCRIPTION: **2' x 4' Fissured Lay-In Ceiling Panels**  
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed**    FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Throughout Facility**  
MATERIAL QUANTITY: **15000**    MATERIAL UNITS: **SF**  
DAMAGE QUANTITY:    DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 03/02/2016

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22861** BUIDLING ID: **2930**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Perez School** REVIEW DATE: **3/22/2016**  
ADDRESS: **1241 W. 19th St.** IDPH LICENSE NO: **100-19466**

---

HOMOGENEOUS AREA: **5**  
MATERIAL DESCRIPTION: **2' x 4' Fissured Lay-In Ceiling Panels**  
MATERIAL LOCATION: **Throughout Facility**  
MATERIAL QUANTITY: **15000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **03/22/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22861** BUIDLING ID: **2930**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Evan Christian**  
SCHOOL NAME: **Perez School** INSPECTION DATE: **3/2/2016**  
ADDRESS: **1241 W. 19th St.** IDPH LICENSE NO: **100-19466**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **6**  
MATERIAL DESCRIPTION: **2' x 4' Random Dot Lay-In Ceiling Panels**  
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Kitchen**  
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 03/02/2016

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22861** BUIDLING ID: **2930**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Perez School** REVIEW DATE: **3/22/2016**  
ADDRESS: **1241 W. 19th St.** IDPH LICENSE NO: **100-19466**

---

HOMOGENEOUS AREA: **6**  
MATERIAL DESCRIPTION: **2' x 4' Random Dot Lay-In Ceiling Panels**  
MATERIAL LOCATION: **Kitchen**  
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **03/22/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22861** BUIDLING ID: **2930**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Evan Christian**  
SCHOOL NAME: **Perez School** INSPECTION DATE: **3/2/2016**  
ADDRESS: **1241 W. 19th St.** IDPH LICENSE NO: **100-19466**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **7**  
MATERIAL DESCRIPTION: **12" x 12" White Floor Tile w/Gray Streaks**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **All Corridors, Gym, Lunch Area, Part of all 2nd Floor Classrooms, 210 & 211**  
MATERIAL QUANTITY: **12000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 03/02/2016

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22861** BUIDLING ID: **2930**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Perez School** REVIEW DATE: **3/22/2016**  
ADDRESS: **1241 W. 19th St.** IDPH LICENSE NO: **100-19466**

---

HOMOGENEOUS AREA: **7**  
MATERIAL DESCRIPTION: **12" x 12" White Floor Tile w/Gray Streaks**  
MATERIAL LOCATION: **All Corridors, Gym, Lunch Area, Part of all 2nd Floor Classrooms, 210 & 211**  
MATERIAL QUANTITY: **12000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **03/22/2016**

# Chicago Public Schools

## Carnow, Conibear and Associates 2016 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22861** BUIDLING ID: **2930**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Evan Christian**  
SCHOOL NAME: **Perez School** INSPECTION DATE: **3/2/2016**  
ADDRESS: **1241 W. 19th St.** IDPH LICENSE NO: **100-19466**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **8**  
MATERIAL DESCRIPTION: **12" x 12" White w/Gray Streaks Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **All Corridors, Gym, Lunch Area, Part of all 2nd Floor Classrooms, 210 & 211**  
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 03/02/2016



# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22861** BUIDLING ID: **2930**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Perez School** REVIEW DATE: **3/22/2016**  
ADDRESS: **1241 W. 19th St.** IDPH LICENSE NO: **100-19466**

---

HOMOGENEOUS AREA: **8**  
MATERIAL DESCRIPTION: **12" x 12" White w/Gray Streaks Floor Tile Mastic**  
MATERIAL LOCATION: **All Corridors, Gym, Lunch Area, Part of all 2nd Floor Classrooms, 210 & 211**  
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **03/22/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22861** BUIDLING ID: **2930**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Evan Christian**  
SCHOOL NAME: **Perez School** INSPECTION DATE: **3/2/2016**  
ADDRESS: **1241 W. 19th St.** IDPH LICENSE NO: **100-19466**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **9**  
MATERIAL DESCRIPTION: **12" x 12" Beige w/Gray Streaks Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Faculty Center, Main Office, 2nd Floor Stair Landing**

MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 03/02/2016

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22861** BUIDLING ID: **2930**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Perez School** REVIEW DATE: **3/22/2016**  
ADDRESS: **1241 W. 19th St.** IDPH LICENSE NO: **100-19466**

---

HOMOGENEOUS AREA: **9**  
MATERIAL DESCRIPTION: **12" x 12" Beige w/Gray Streaks Floor Tile**  
MATERIAL LOCATION: **Faculty Center, Main Office, 2nd Floor Stair Landing**  
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **03/22/2016**

# **Chicago Public Schools**

**Carnow, Conibear and Associates**

***2016 AHERA REINSPECTION***


# APPENDIX B

## Inspector and Management Planner Licenses

---

# Evan Christian

Illinois Licensed Project Manager, and Air Sampling Professional



ENDORSEMENTS	TC EXPIRES
PROJECT MANAGER AIR SAMPLING PROFESSIONAL	12/12/2015
<b>Alteration of this license shall result in legal action</b> This license issued under authority of the State of Illinois Department of Public Health This license is valid only when accompanied by a valid training course certificate.	

**CARNOW  
CONIBEAR**

2015



**OCCUPATIONAL TRAINING & SUPPLY, INC.**  
7233 S. Adams Street ♦ Willowbrook, IL 60527 ♦ (630) 655-3900

# Asbestos Building Inspector Refresher

Occupational Training & Supply, Inc. certifies that  
**Evan Christian**


has successfully completed the Asbestos Building Inspector Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency Response Act (AHERA) and TSCA Title II.

Course Date: 12/2/2015

Exam Date: 12/2/2015

Expiration Date: 12/2/2016

Certificate Number: BIR1512024159

  
Katy DeSalvo, Director

**Reliable**  
**Environmental**  
**Solutions, Inc.** **RES**

This is to certify that **Evan Christian**

*has on January 28 & 29, 2016, in Springfield, Illinois,  
completed the requirements for asbestos accreditation under Section 206 of TSCA Title II*

**Asbestos Management Planner Initial Training**

*as accredited by the State of Illinois and approved by the U.S.E.P.A. under 40 CFR 763 (AHERA)  
and passed the associated examination with a score of 70% or higher*

Course Date: January 28 & 29, 2016

Examination Date: January 29, 2016

Expiration Date: January 29, 2017

Certificate Number: MP/0103

*William S. Williams*

Training Program Manager, William S. Williams

4211 Westgate Drive, Springfield, Illinois ☐ 217.787.9800 ☐ 217.787.9801 FAX ☐ [www.ReliableEnv.com](http://www.ReliableEnv.com)



2015



# OCCUPATIONAL TRAINING & SUPPLY, INC.

7233 S. Adams Street ♦ Willowbrook, IL 60527 ♦ (630) 655-3900

## Asbestos Building Inspector Refresher

Occupational Training & Supply, Inc. certifies that

**Todd Huffer**


has successfully completed the Asbestos Building Inspector Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 12/2/2015

Exam Date: 12/2/2015

Expiration Date: 12/2/2016

Certificate Number: BIR1512024161

  
\_\_\_\_\_  
Kathy DeSalvo, Director

# Todd Huffer

Illinois Licensed Asbestos Inspector, Management Planner,  
Project Manager, and Air Sampling Professional



## ASBESTOS PROFESSIONAL LICENSE

ID NUMBER	ISSUED	EXPIRES
100 - 09870	3/16/2015	05/15/2016

TODD T HUFFER  
315 HATLEN COURT  
MT. PROSPECT, IL 60056

Environmental Health



### ENDORSEMENTS

### TC EXPIRES

INSPECTOR	12/2/2015
MANAGEMENT PLANNER	2/20/2016
PROJECT MANAGER	12/11/2015
AIR SAMPLING PROFESSIONAL	

**Alteration of this license shall result in legal action**  
This license issued under authority of the State of Illinois  
Department of Public Health  
This license is valid only when accompanied by a valid  
training course certificate.

**CARNOW  
CONIBEAR**

2016



# OCCUPATIONAL TRAINING & SUPPLY, INC.

7233 S. Adams Street ♦ Willowbrook, IL 60527 ♦ (630) 655-3900

## Asbestos Management Planner Refresher

Occupational Training & Supply, Inc. certifies that

**Todd Huffer**

has successfully completed the Asbestos Management Planner Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 1/27/2016

Exam Date: 1/27/2016

Expiration Date: 1/27/2017

Certificate Number: MPR1601270318

Kathy DeSalvo, Director

# APPENDIX C

## Laboratory Accreditations

---

# APPENDIX D

## Laboratory Results

---

# APPENDIX E

## Chain of Custody Forms

---

## Three-Year Reinspection Key to Terms

	<b>CODE</b>	<b>KEY</b>
<b>MATERIAL</b>		
	ACBM	Asbestos Containing Building Materials
<b>MATERIAL CATEGORY</b>		
	MISC	Miscellaneous
	SURF	Surfacing
	TSI	Thermal System Insulation
<b>MATERIAL UNITS</b>		
	LF	Linear Feet
	SF	Square Feet
	CF	Cubic Feet
<b>DAMAGE TYPE</b>		
	Loc	Localized
	Dist	Distributed