

**ILLINOIS DEPARTMENT OF PUBLIC HEALTH  
AHERA THREE YEAR REINSPECTION  
ASBESTOS ABATEMENT PROGRAM  
SCHOOL INFORMATION FORM**

**SECTION I**

NAME OF SCHOOL DISTRICT: CHICAGO SCHOOL DIST 299  
SCHOOL ID NUMBER: 14-016-2990-2153  
SCHOOL NAME: Deneen School  
ADDRESS OF SCHOOL: 7240 S. Wabash  
CITY: Chicago, IL, 60619

DATE LAST THREE YEAR REINSPECTION WAS COMPLETED **4/30/2013**

**If the address on this form is different than the address of the building, submit a written explanation.**

**SECTION II** *(Please type or print)*

**PLEASE COMPLETE THE FOLLOWING FOR YOUR THREE YEAR REINSPECTION:**

DATE REINSPECTION COMPLETED: 3/16/2016 ENROLLMENT 553  
IDPH INSPECTOR LICENSE NUMBER: 100-08864  
IDPH LICENSED INSPECTOR NAME (Please Print): Robert DeBord  
IDPH MP LICENSE NUMBER: 100-09870  
IDPH LICENSED MANAGEMENT PLANNER NAME (Please Print): Todd Huffer

DESIGNATED PERSON (Please Print): Robert Christlieb PHONE: (773) 553-3197



3/16/2016

*Signature of Designated Person*

*Date*

**SECTION III**

PLEASE COMPLETE THE FOLLOWING INFORMATION FOR ANY CHANGES WITHIN THE SCHOOL DISTRICT.

School building has been sold. Date of Sale: \_\_\_\_\_

School has been closed. Date closed: \_\_\_\_\_

School building has been demolished. Date: \_\_\_\_\_

School building is asbestos free since last reinspection: \_\_\_\_\_

**Please explain in writing why the school building is now asbestos free and include the supporting documentation.**

If a new school building has been added to the district, submit either an exclusionary statement or a management plan and inspection report. Include the complete name, address and city of school building.

**Explain in writing if the address of the building is different than the address on this form:**

**THREE-YEAR REINSPECTION**

**CHICAGO SCHOOL DIST 299**

**Deneen School**

7240 S. Wabash  
Chicago, IL, 60619

Unit: 22931  
Building ID: 3010

IDPH ID Number: 14-016-2990-2153

**REPORT DATE:**

Wednesday, March 16, 2016

**Prepared for:**

**Chicago Public Schools**  
**125 S. Clark Street**  
**Chicago, IL 60603**

**Prepared by:**

**Carnow, Conibear and Associates**

600 West Van Buren St., Ste 500

Phone (312) 762-2900

Fax (312) 782-5145

**DO NOT REMOVE FROM SCHOOL  
REQUIRED BY FEDERAL LAW**

February 29, 2016

Mr. R. Kent Cook  
Asbestos Program  
Illinois Department of Public Health  
525 West Jefferson Street  
Springfield, Illinois 62761

Re: Chicago Public Schools - 2016 Three-Year Reinspections

Dear Mr. Cook:

Carnow, Conibear and Associates, Managing Environmental Consultant (MEC), conducted the Three-Year Reinspections and performed management plan updates for the Chicago Public Schools (CPS) facilities in Region 3,4,5 Elementary Schools. Please update your records with the following information.

School District: 299                      Unit: 22931                      Region: 05                      IDPH ID: 14-016-2990-2153

School: Deneen School                      Building ID: 3010

Address: 7240 S. Wabash  
Chicago, IL, 60619

Building Contact: Crespo, Edgar                      Contact Phone: 773-710-5317

Current Building Owners: Chicago Public Schools

Review Date: 03/14/2016

Inspector: Robert DeBord                      Inspector IDPH License: 100-08864  
Management Planner: Todd Huffer                      Management Planner IDPH License: 100-09870

If you have any questions or comments, please contact us at (312) 762-2900

Sincerely,  
Carnow, Conibear and Associates



Todd Huffer  
100-09870

## **Environmental Notification to Occupants**

To: Faculty, Staff and Parents  
From: Chicago Public Schools  
Date: February 29, 2016

RE: Deneen School, Unit 22931  
7240 S. Wabash  
Chicago, IL, 60619

Dear Faculty, Staff and Parents,

This letter is to notify you that the 2016 asbestos three year re-inspection has been completed at Deneen School , following the Federal Asbestos Hazard Emergency Response Act (AHERA), 40 CFR Part 763, Subpart E and is available for your review at the main office of the school.

Although asbestos-containing materials have been identified at Deneen School, there is no reason to believe that any threat to the health of students or staff exists at this time. CPS will continue to carefully monitor the condition of asbestos-containing materials and if conditions warrant, all appropriate steps will be taken to maintain the health and safety of all building occupants.

If you have any questions regarding this matter or require additional information, please feel free to contact Robert Christlieb, the designated Local Education Authority's Designated Person at (773) 553-3197 .

## **Table of Contents**

- I. School and Inspection Information
- II. Executive Summary
- III. Methodology
- IV. Abatement History
- V. Reassessments and Recommendations
- VI. Conclusions

Table I: Inspector's Reinspection Findings

Table II: Management Planner's Review

### **APPENDICES:**

- Appendix A: Assessment Sheets, Drawings and Photos
- Appendix B: Inspector and Management Planner Licenses
- Appendix C: Laboratory Accreditations
- Appendix D: Laboratory Results
- Appendix E: Chain of Custody Forms

## SCHOOL AND INSPECTION INFORMATION

### 1. School Information

School: Deneen School Unit: 22931 Region: 05  
Address: 7240 S. Wabash Chicago, IL, 60619  
IDPH ID: 14-016-2990-2153 Building ID: 3010  
Contact: Crespo, Edgar Phone: 773-710-5317

### 2. Description of Facility

Original Construction: 1955 Additional Construction: 2005, 1958, 1962  
Total Square Footage: 33076 No of Floors: 2  
Current Occupancy: 553

### 3. LEA Designated Person

Contact: Robert Christlieb Phone: (773) 553-3197  
Address: 125 South Clark Street, 17th Floor  
Chicago, IL 60603

### 4. Managing Environmental Consultant

MEC: Carnow, Conibear and Associates  
Contact: Dan Juneau  
Address 600 West Van Buren St., Ste 500  
Phone: (312) 762-2900 Fax: (312) 782-5145

### 5. Inspector

Inspector Name: Robert DeBord


Inspector IDPH license # 100-08864

Signature:  
Date: 2/29/2016

### 6. Management Planner

Management Planner Name: Todd Huffer

Management Planner IDPH license # 100-09870

Signature:   
Date: 03/14/2016

### 7. Review Date: 03/14/2016

### 8. LEA Designated Person's Acknowledgement

The reinspection report and recommendations have been received by me and appropriate action will be taken by the School District.

Signature: 

Date: 3/16/2016

Name: Robert Christlieb

## II. EXECUTIVE SUMMARY

Carnow, Conibear and Associates was retained by the Chicago Public Schools (CPS) to perform a three-year asbestos reinspection of the Deneen School. This inspection was conducted in accordance with the United States Environmental Protection Agency (USEPA) Asbestos Hazard Emergency Response Act (AHERA) part 763.92 (b), and the ongoing Operations and Maintenance Program (O&M) originally designed in the School's Asbestos Management Plan. The purpose of this three-year reinspection is to record any condition changes in the asbestos-containing building material (ACBM) in the school since the previous three-year reinspection and the six-month periodic surveillance, to identify, assess, and include any Homogeneous Areas (HA) not identified in the Management Plan, and to recommend an appropriate response action to manage asbestos.

The inspector conducted a three-year reinspection of this facility under Illinois Department of Public Health (IDPH) school reinspection requirements and AHERA, sections 763.85 and 763.88. The main building and each addition to the main building, if constructed at different dates, were inspected separately. Laboratory accreditations are included in Appendix C, laboratory results are included in Appendix D, and chain of custody forms are included in Appendix E.

Note: During previous inspections, some of the HA(s) were identified together as 9" x 9" floor tile (FT), mastics assoc. with 9" x 9" FT, 12" x 12" FT, mastics assoc. with 12" x 12" FT, pipe insulation, etc. Some of these HA(s) have been re-identified by areas that are uniform in color, texture, construction date, application date, and general appearance.

The inspector has determined the following:

A. The following HAs have changed assessment categories for Building 3010:

B. The following new homogenous areas have been identified for Building 3010:



C. This reinspection covered only physically accessible and visible areas and materials that were identified in the LEA's management plan. The following materials were concealed and/or contained in areas that were inaccessible for sampling and have been classified as Assumed:

05	1 x 1 Acoustical Ceiling tiles
06A	12 x 12 Blue Floor tile
06B	12 x 12 White Floor tile
14A	12x12 blue flr tile
14B	12x12 white flr tile
15A	12x12 blue flr tile mastic
15B	12x12 white flr tile mastic
18A	12x12 white flr tile
18B	12x12 blue flr tile
19B	12x12 blue flr tile mastic
23	wrap around duct fiberglass
24	wrap around breeching fiberglass
36	Brown coat plaster
37	Acoustic ceiling plaster
38A	12 x 12 Blue Floortile mastic
38B	12 x 12 White Floortile mastic
39	Brown coat plaster
40	1 x 1 Acoustical Ceiling tile mastic
41	2'x4' Acoustical ceiling tiles
42A	12x12 blue floor tile
42B	12x12 blue floor tile mastic
43A	12x12 blue floor tile
43B	12x12 blue floor tile mastic
44	Blue/Gray Carpet Mastic
45	Brown Carpet Mastic
46	12" x 12" Light Green VFT
47	12" x 12" Light Green VFT Mastic
48	Tan Baseboard
49	Tan Baseboard Mastic
50	12" x 12" Yellow VFT
51	12" x 12" Light Beige VFT
52	Mastic Associated with HA 50 and HA 51
53	Green Baseboard
54	Green Baseboard Mastic
FT-1	12x12 green speckled floor tile
FT-2	12x12 beige floor tile
FTM-1	12x12 green mastic
FTM-2	12x12 mastic

The following areas were deemed to be inaccessible:

44	Blue/Gray Carpet Mastic
45	Brown Carpet Mastic
47	12" x 12" Light Green VFT Mastic
49	Tan Baseboard Mastic
52	Mastic Associated with HA 50 and HA 51
54	Green Baseboard Mastic
FTM-1	12x12 green mastic
FTM-2	12x12 mastic

Materials were also listed as "assumed" if they were in good condition and sampling was not conducted to avoid damage.

This reinspection was conducted by Robert DeBord, IDPH License # 100-08864. The Management Plan was updated by Todd Huffer, IDPH License # 100-09870. Inspector and Management Planner Licenses are included in Appendix B.

### **III. METHODOLOGY**

Tasks performed on-site included the following:

1. Review current management plan, identify HA(s) and extract appropriate information.
2. Examine and verify abatement records.
3. Touch and visually and physically reinspect and reassess the condition of all friable known or assumed ACBM.
4. Touch and visually and physically reinspect all non-friable known or assumed ACBM to determine whether these materials have become friable since the last inspection or periodic surveillance.
5. Identify any condition changes that may affect Hazard Ranking of known ACBM or Assumed ACBM, as well as any HA(s) that have become friable since the last reinspection.
6. Collect bulk samples from each newly discovered friable HA or previously assumed and submit for laboratory analysis.
7. Tabulate reinspection findings and submit for management planner review and recommendations with appropriate response actions based on the AHERA Damage Category of the ACBM.
8. Submit reinspection findings and management planner recommendations to the LEA within thirty (30) days for inclusion into the management plan.

### **IV. ABATEMENT HISTORY**

The information collected from the existing management plan and inspection report(s) and from interviews with the school official revealed that the following asbestos abatement was conducted at the school since the previous Three year Reinspection.

Abatement Dates:

### **V. REASSESSMENTS AND RECOMMENDATIONS**

The reassessments and recommendations are summarized in Tables I and II on the following pages. Detailed Hazard Assessment Sheets and Drawings and Photos (if applicable) are included in Appendix A.

### **VI. CONCLUSIONS**

The Deneen School Building 3010 Three-Year reinspection has been completed and response actions have been recommended for both friable and non-friable materials. A timely execution of the response actions recommended will enable the LEA and the Designated Person(s) to effectively manage the existing ACBM.

This three-year reinspection report should be inspected in the current Management plan at the CPS Central Office, and one (1) copy should be kept at the school for use when planning any renovation and/or demolition activities in areas where ACBM has been identified. Also, periodic surveillance documentation and any summary reports from any response actions that are executed at the school should be used to update the Management Plan.

**Table I**  
**Inspector's Reinspection Findings**

---

# Chicago Public Schools

School Deneen School Unit 22931 Building ID 3010

Address 7240 S. Wabash Region 05

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
03	2 x 2 Drop ceiling tile			1953 Bldg, Lobby and gym	NO_ACBM									
04	1 x 1 Acoustical ceiling tiles			1953 Bldg, Lunch Rm, Kitchen	NO_ACBM									
05	1 x 1 Acoustical Ceiling tiles	600	SF	1953 Bldg, Lobby	ASSUMED	MISC	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
06A	12 x 12 Blue Floor tile	4,675	SF	1962 Add, Rms 116,117,118,119,120,Teachers lounge (115)	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
06B	12 x 12 White Floor tile	2,640	SF	1962 Add, 1st,2nd Fl Corridor	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
09	Vinyl Mop Board			1953 Bldg, Classrooms, Lunchroom	NO_ACBM									
10	Vinyl Mop Board mastic			1953 Bldg, Classrooms, lunchroom	NO_ACBM									
12	9x9 Tan Floor Tile			1953 bldg Room 200	CHR	MISC								
13	9x9 tan flr tile mastic			1953 building, room 200	CHR	MISC		None						Low
14A	12x12 blue flr tile	11,200	SF	1953 bldg- school offices, rms 104,103,105,109,202,203,204,205,206,207,208,209	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
14B	12x12 white flr tile	5,400	SF	1953 bldg 1st, 2nd flr corridors, Rm. 200	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
15A	12x12 blue flr tile mastic	11,200	SF	1953 bldg- school offices, rms 104,103,105,109,202,203,204,205,206,207,208,209	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
15B	12x12 white flr tile mastic	8,825	SF	1953 bldg 1st, 2nd flr corridors and rms 106, 107, 108	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
18A	12x12 white flr tile	3,850	SF	1958- 1st & 2nd fl corridors	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
18B	12x12 blue flr tile	4,660	SF	1958- Rooms 112, 114, 210, 212, 214	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
19A	12x12 white flr tile mastic	3,850	SF	1958- 1st & 2nd fl	CHR	MISC	N	NONE	0		No	ACBM with the		LOW



# Chicago Public Schools

School Deneen School Unit 22931 Building ID 3010

Address 7240 S. Wabash Region 05

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
41	2'x4' Acoustical ceiling tiles	2,400	SF	1953 bldg- lunchroom	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
42A	12x12 blue floor tile	4,413	SF	1953 bldg - rooms 104, 106, 108	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
42B	12x12 blue floor tile mastic	4,413	SF	1953 bldg - rooms 104, 106, 108	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
43A	12x12 blue floor tile	1,471	SF	1958 bldg - room 110	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
43B	12x12 blue floor tile mastic	1,471	SF	1958 bldg - room 110	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
44	Blue/Gray Carpet Mastic	384	SF	Rm. 102 Old Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
45	Brown Carpet Mastic	2,000	SF	Main Office, 2007 Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
46	12" x 12" Light Green VFT	7,892	SF	Cafeteria, Rms. 160, 201, 263, 252, 256 2007 Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
47	12" x 12" Light Green VFT Mastic	7,892	SF	Cafeteria, Rms. 160, 201, 263, 252, 256 2007 Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
48	Tan Baseboard	312	LF	Cafeteria, Rms. 160, 201, 263, 252, 256 2007 Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
49	Tan Baseboard Mastic	312	LF	Cafeteria, Rms. 160, 201, 263, 252, 256 2007 Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
50	12" x 12" Yellow VFT	225	SF	Cafeteria, Rms. 160, 261, 263, 252, 2007 Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
51	12" x 12" Light Beige VFT	225	SF	Cafeteria, Rms. 160, 261, 263, 252, 2007 Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
52	Mastic Associated with HA 50 and HA 51	450	SF	Cafeteria, Rms. 160, 261, 263, 252, 2007 Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
53	Green Baseboard	224	LF	Rm. 256 (Library) 2007 Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
54	Green Baseboard Mastic	224	LF	Rm. 256 (Library) 2007 Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
A	Aircell Pipe Insulation			1953 Bldg, Airtunnel, Crawlspace, Abated	ABATED	TSI								
B	MJP fittings			1953 Bldg, Air tunnels, Crawlspace,	ABATED	TSI		None						





# Chicago Public Schools

School Deneen School Unit 22931 Building ID 3010

Address 7240 S. Wabash Region 05

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

*Inspector's Comments are Summarized at the End of the Report*

Reinspection Date <b>2/29/2016</b>
Inspector Name <b>Robert DeBord</b>
<b>100-08864</b> <b>5/15/2016</b>
Inspector's IDPH License Number / Expiration Date

### Inspector's Comments

HA Number:	Inspector Comments:
03	
04	
05	
06A	
06B	
09	
10	
12	Not observed 2016
13	Not observed 2016
14A	
14B	
15A	
15B	
18A	
18B	
19A	
19B	
22	
23	
24	
25	
26	
27	
28	

# Chicago Public Schools

School Deneen School Unit 22931 Building ID 3010

Address 7240 S. Wabash Region 05

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

*Inspector's Comments are Summarized at the End of the Report*

---

HA Number:	Inspector Comments:
29	
32	
33	
34	
36	
37	
38A	
38B	
39	Not observed 2016
40	Not observed 2016
41	
42A	
42B	
43A	
43B	
44	
45	
46	
47	
48	
49	
50	
51	
52	
53	
54	
A	
B	
C	

# Chicago Public Schools

School Deneen School Unit 22931 Building ID 3010

Address 7240 S. Wabash Region 05

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

*Inspector's Comments are Summarized at the End of the Report*

---

HA Number:	Inspector Comments:
E	
F	
FT-1	
FT-2	
FTM-1	
FTM-2	
G	
H	
I	
J	
K	
L	

**Table II**

**Management Planner's Review**

---

# Chicago Public Schools

School Deneen School  
Address 7240 S. Wabash

Unit 22931  
Chicago, IL, 60619

Building ID 3010  
Region 05

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

### Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
03	2 x 2 Drop ceiling tile			1953 Bldg, Lobby and gym	No ACBM						
04	1 x 1 Acoustical ceiling tiles			1953 Bldg, Lunch Rm, Kitchen	No ACBM						
05	1 x 1 Acoustical Ceiling tiles	600	SF	1953 Bldg, Lobby	Assumed	MISC	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
06A	12 x 12 Blue Floor tile	4,675	SF	1962 Add, Rms 116,117,118,119,120,Teachers lounge (115)	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
06B	12 x 12 White Floor tile	2,640	SF	1962 Add, 1st,2nd Fl Corridor	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
09	Vinyl Mop Board			1953 Bldg, Classrooms, Lunchroom	No ACBM						
10	Vinyl Mop Board mastic			1953 Bldg, Classrooms, lunchroom	No ACBM						
12	9x9 Tan Floor Tile			1953 bldg Room 200	Chrysotile	MISC					Follow O&M Plan
13	9x9 tan flr tile mastic			1953 building, room 200	Chrysotile	MISC					Follow O&M Plan
14A	12x12 blue flr tile	11,200	SF	1953 bldg- school offices, rms 104,103,105,109,202,203,204,205,206, 207,208,209	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
14B	12x12 white flr tile	5,400	SF	1953 bldg 1st, 2nd flr corridors, Rm. 200	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
15A	12x12 blue flr tile mastic	11,200	SF	1953 bldg- school offices, rms 104,103,105,109,202,203,204,205,206, 207,208,209	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
15B	12x12 white flr tile mastic	8,825	SF	1953 bldg 1st, 2nd flr corridors and rms 106, 107, 108	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
18A	12x12 white flr tile	3,850	SF	1958- 1st & 2nd fl corridors	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
18B	12x12 blue flr tile	4,660	SF	1958- Rooms 112, 114, 210, 212, 214	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
19A	12x12 white flr tile mastic	3,850	SF	1958- 1st & 2nd fl corridors	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
19B	12x12 blue flr tile mastic	4,660	SF	1958- Rooms 112, 114, 210, 212, 214	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
22	Vibration gasket			1953 bldg fan room	No ACBM						
23	wrap around duct fiberglass	275	LF	boiler room	Assumed	TSI	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
24	wrap around breaching fiberglass	150	LF	boiler room	Assumed	TSI	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
25	Boiler Gasket - abated			Boiler room	Abated	MISC					
26	Baseboard			1958- Rms 210A, 210B, 212, 214, 110, 112, 114	No ACBM						
27	Baseboard mastic			1958- Rms 210A, 210B, 212, 214, 110, 112, 114	No ACBM						
28	Baseboard			1962 bldg- 116, 117, 118, 119, 120, 216, 218, 219, 220	No ACBM						

# Chicago Public Schools

School Deneen School

Unit 22931

Building ID 3010

Address 7240 S. Wabash

Chicago, IL, 60619

Region 05

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

### Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
29	Baseboard Mastic			1962 bldg- 116, 117, 118, 119, 120, 216, 218, 219, 220	No ACBM						
32	Acoustic ceiling			1958 bldg- corridors	No ACBM	SURFACE					
33	Acoustic plaster			1962- rooms 116, 117, 118, 119, 120, teachers lounge, 218, 220	No ACBM	SURFACE					
34	Acoustic plaster	1,390	SF	1958- room 110	Chrysotile	SURFACE	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
36	Brown coat plaster	7,900	SF	1958 bldg- corridors/ceiling	Assumed	SURFACE	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
37	Acoustic ceiling plaster	1,260	SF	1962- 1st and 2nd flr corridor	Assumed	SURFACE	No	0	SF	5 ACBM with potential for significant damage	Follow O&M Plan
38A	12 x 12 Blue Floortile mastic	4,755	SF	1962 Add, Rms 116,117,118,119,120,teachers lounge (115), Engineer's Office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
38B	12 x 12 White Floortile mastic	2,640	SF	1062 Add,1st,2nd Fl Corridor	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
39	Brown coat plaster			1962- 1st and 2nd flr corridor	Assumed	SURFACE					Follow O&M Plan
40	1 x 1 Acoustical Ceiling tile mastic			1953 Bldg, Kitchen, Lunch Rm	Assumed	MISC					Follow O&M Plan
41	2'x4' Acoustical ceiling tiles	2,400	SF	1953 bldg- lunchroom	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
42A	12x12 blue floor tile	4,413	SF	1953 bldg - rooms 104, 106, 108	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
42B	12x12 blue floor tile mastic	4,413	SF	1953 bldg - rooms 104, 106, 108	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
43A	12x12 blue floor tile	1,471	SF	1958 bldg - room 110	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
43B	12x12 blue floor tile mastic	1,471	SF	1958 bldg - room 110	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
44	Blue/Gray Carpet Mastic	384	SF	Rm. 102 Old Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
45	Brown Carpet Mastic	2,000	SF	Main Office, 2007 Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
46	12" x 12" Light Green VFT	7,892	SF	Cafeteria, Rms. 160, 201, 263, 252, 256 2007 Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
47	12" x 12" Light Green VFT Mastic	7,892	SF	Cafeteria, Rms. 160, 201, 263, 252, 256 2007 Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
48	Tan Baseboard	312	LF	Cafeteria, Rms. 160, 201, 263, 252, 256 2007 Building	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
49	Tan Baseboard Mastic	312	LF	Cafeteria, Rms. 160, 201, 263, 252, 256 2007 Building	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
50	12" x 12" Yellow VFT	225	SF	Cafeteria, Rms. 160, 261, 263, 252, 2007 Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
51	12" x 12" Light Beige VFT	225	SF	Cafeteria, Rms. 160, 261, 263, 252, 2007 Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
52	Mastic Associated with HA 50 and HA 51	450	SF	Cafeteria, Rms. 160, 261, 263, 252,	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

# Chicago Public Schools

**School** Deneen School  
**Address** 7240 S. Wabash

**Unit** 22931  
 Chicago, IL, 60619

**Building ID** 3010  
**Region** 05

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

### Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
				2007 Building							
53	Green Baseboard	224	LF	Rm. 256 (Library) 2007 Building	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
54	Green Baseboard Mastic	224	LF	Rm. 256 (Library) 2007 Building	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
A	Aircell Pipe Insulation			1953 Bldg, Airtunnel, Crawlspace, Abated	Abated	TSI					
B	MJP fittings			1953 Bldg, Air tunnels, Crawlspace, Abated	Abated	TSI					
C	Fittings on fiberglass runs		Fittings	1962 Bldg, Pipe Chases, Crawlspace, Abated	Abated	TSI			Fittings		
E	Aircell pipe insulation			1958 Add, Crawlspace, Abated	Abated	TSI					
F	Cardboard pipe insulation			1958 Add, Crawlspace, Abated	Abated	TSI					
FT-1	12x12 green speckled floor tile	250	SF	Room 200 and 100	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
FT-2	12x12 beige floor tile	85	SF	Room 217	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
FTM-1	12x12 green mastic	250	SF	Room 200 & 100	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
FTM-2	12x12 mastic	85	SF	room 217	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
G	Fittings on fiberglass runs			1958 Add, Abated	Abated	TSI					
H	Fittings on fiberglass runs		Fittings	1962 Bldg, Crawlspace, Abated	Abated	TSI			Fittings		
I	Aircell pipe fittings		Fittings	1953 Bldg, Air tunnel, Crawlspace, corridor, Abated	Abated	TSI			Fittings		
J	Cardboard pipe fittings		Fittings	1953 Bldg, Air tunnels, Abated	Abated	TSI			Fittings		
K	Aircell pipe joint		Fittings	1958 Bldg, Crawlspace, Abated	Abated	TSI			Fittings		
L	Cardboard Joint Fittings		Fittings	1958 Add, Crawlspace, Abated	Abated	TSI			Fittings		

# Chicago Public Schools

**School** Deneen School  
**Address** 7240 S. Wabash

**Unit** 22931  
 Chicago, IL, 60619

**Building ID** 3010  
**Region** 05

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

*Management Planner's Comments Summarized at the End of the Report*

Review Date	3/14/2016
Manager Planner Name	Todd Huffer
100-09870	5/15/2016
Manager IDPH License No/Expiration	

HA Number	Management Comments
03	
04	
05	
06A	
06B	
09	
10	
12	Material Not Observed in 2016, may be present under new floor
13	not observed in 2016, mat be present under new flooring
14A	
14B	
15A	
15B	
18A	
18B	
19A	



# Chicago Public Schools

**School** Deneen School  
**Address** 7240 S. Wabash

**Unit** 22931  
 Chicago, IL, 60619

**Building ID** 3010  
**Region** 05

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

### *Management Planner's Comments Summarized at the End of the Report*

HA Number	Management Comments
19B	
22	
23	
24	
25	
26	
27	
28	
29	
32	
33	
34	
36	
37	
38A	
38B	
39	Not observed in 2016. Maintain O&M if identified
40	Not observed in 2016. Maintain O&M if observed
41	
42A	
42B	
43A	
43B	
44	
45	
46	
47	

# Chicago Public Schools

**School** Deneen School  
**Address** 7240 S. Wabash

**Unit** 22931  
 Chicago, IL, 60619

**Building ID** 3010  
**Region** 05

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

### *Management Planner's Comments Summarized at the End of the Report*

HA Number	Management Comments
48	
49	
50	
51	
52	
53	
54	
A	Material Abated
B	Material Abated
C	Material Abated
E	Material Abated
F	material abated
FT-1	
FT-2	
FTM-1	
FTM-2	
G	material abated
H	material abated
I	material abated
J	material abated
K	material abated
L	material abated

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22931** BUIDLING ID: **3010**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Robert DeBord**  
SCHOOL NAME: **Deneen School** INSPECTION DATE: **2/29/2016**  
ADDRESS: **7240 S. Wabash** IDPH LICENSE NO: **100-08864**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **03**  
MATERIAL DESCRIPTION: **2 x 2 Drop ceiling tile**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1953 Bldg, Lobby and gym**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **02/29/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22931** BUIDLING ID: **3010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Deneen School** REVIEW DATE: **3/14/2016**  
ADDRESS: **7240 S. Wabash** IDPH LICENSE NO: **100-08864**

---

HOMOGENEOUS AREA: **03**

MATERIAL DESCRIPTION: **2 x 2 Drop ceiling tile**

MATERIAL LOCATION: **1953 Bldg, Lobby and gym**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **03/14/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22931** BUIDLING ID: **3010**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Robert DeBord**  
SCHOOL NAME: **Deneen School** INSPECTION DATE: **2/29/2016**  
ADDRESS: **7240 S. Wabash** IDPH LICENSE NO: **100-08864**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **04**  
MATERIAL DESCRIPTION: **1 x 1 Acoustical ceiling tiles**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1953 Bldg, Lunch Rm, Kitchen**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **02/29/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22931** BUIDLING ID: **3010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Deneen School** REVIEW DATE: **3/14/2016**  
ADDRESS: **7240 S. Wabash** IDPH LICENSE NO: **100-08864**

---

HOMOGENEOUS AREA: **04**

MATERIAL DESCRIPTION: **1 x 1 Acoustical ceiling tiles**

MATERIAL LOCATION: **1953 Bldg, Lunch Rm, Kitchen**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **03/14/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22931** BUIDLING ID: **3010**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Robert DeBord**  
SCHOOL NAME: **Deneen School** INSPECTION DATE: **2/29/2016**  
ADDRESS: **7240 S. Wabash** IDPH LICENSE NO: **100-08864**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **05**  
MATERIAL DESCRIPTION: **1 x 1 Acoustical Ceiling tiles**  
HISTORICAL AHERA DAMAGE CATEGORY **7**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7**. **Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1953 Bldg, Lobby**  
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 02/29/2016

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22931** BUIDLING ID: **3010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Deneen School** REVIEW DATE: **3/14/2016**  
ADDRESS: **7240 S. Wabash** IDPH LICENSE NO: **100-08864**

---

HOMOGENEOUS AREA: **05**

MATERIAL DESCRIPTION: **1 x 1 Acoustical Ceiling tiles**

MATERIAL LOCATION: **1953 Bldg, Lobby**

MATERIAL QUANTITY: **600**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **03/14/2016**



# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22931** BUIDLING ID: **3010**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Robert DeBord**  
SCHOOL NAME: **Deneen School** INSPECTION DATE: **2/29/2016**  
ADDRESS: **7240 S. Wabash** IDPH LICENSE NO: **100-08864**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **06A**  
MATERIAL DESCRIPTION: **12 x 12 Blue Floor tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **1962 Add, Rms 116,117,118,119,120,Teachers lounge (115)**

MATERIAL QUANTITY: **4675** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 02/29/2016

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22931** BUIDLING ID: **3010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Deneen School** REVIEW DATE: **3/14/2016**  
ADDRESS: **7240 S. Wabash** IDPH LICENSE NO: **100-08864**

---

HOMOGENEOUS AREA: **06A**  
MATERIAL DESCRIPTION: **12 x 12 Blue Floor tile**  
MATERIAL LOCATION: **1962 Add, Rms 116,117,118,119,120,Teachers lounge (115)**  
MATERIAL QUANTITY: **4675** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **03/14/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22931** BUIDLING ID: **3010**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Robert DeBord**  
SCHOOL NAME: **Deneen School** INSPECTION DATE: **2/29/2016**  
ADDRESS: **7240 S. Wabash** IDPH LICENSE NO: **100-08864**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **06B**  
MATERIAL DESCRIPTION: **12 x 12 White Floor tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1962 Add, 1st,2nd FI Corridor**  
MATERIAL QUANTITY: **2640** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 02/29/2016

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22931** BUIDLING ID: **3010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Deneen School** REVIEW DATE: **3/14/2016**  
ADDRESS: **7240 S. Wabash** IDPH LICENSE NO: **100-08864**

---

HOMOGENEOUS AREA: **06B**  
MATERIAL DESCRIPTION: **12 x 12 White Floor tile**  
MATERIAL LOCATION: **1962 Add, 1st,2nd Fl Corridor**  
MATERIAL QUANTITY: **2640** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **03/14/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **22931**    BUILDING ID: **3010**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Robert DeBord**  
SCHOOL NAME: **Deneen School**    INSPECTION DATE: **2/29/2016**  
ADDRESS: **7240 S. Wabash**    IDPH LICENSE NO: **100-08864**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **09**  
MATERIAL DESCRIPTION: **Vinyl Mop Board**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM**    FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1953 Bldg, Classrooms, Lunchroom**

MATERIAL QUANTITY:    MATERIAL UNITS:

DAMAGE QUANTITY:    DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **02/29/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22931** BUIDLING ID: **3010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Deneen School** REVIEW DATE: **3/14/2016**  
ADDRESS: **7240 S. Wabash** IDPH LICENSE NO: **100-08864**

---

HOMOGENEOUS AREA: **09**

MATERIAL DESCRIPTION: **Vinyl Mop Board**

MATERIAL LOCATION: **1953 Bldg, Classrooms, Lunchroom**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **03/14/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22931** BUIDLING ID: **3010**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Robert DeBord**  
SCHOOL NAME: **Deneen School** INSPECTION DATE: **2/29/2016**  
ADDRESS: **7240 S. Wabash** IDPH LICENSE NO: **100-08864**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **10**  
MATERIAL DESCRIPTION: **Vinyl Mop Board mastic**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1953 Bldg, Classrooms, lunchroom**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_

Date: **02/29/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22931** BUIDLING ID: **3010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Deneen School** REVIEW DATE: **3/14/2016**  
ADDRESS: **7240 S. Wabash** IDPH LICENSE NO: **100-08864**

---

HOMOGENEOUS AREA: **10**

MATERIAL DESCRIPTION: **Vinyl Mop Board mastic**

MATERIAL LOCATION: **1953 Bldg, Classrooms, lunchroom**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **03/14/2016**



# Chicago Public Schools

## Carnow, Conibear and Associates 2016 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22931** BUIDLING ID: **3010**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Robert DeBord**  
SCHOOL NAME: **Deneen School** INSPECTION DATE: **2/29/2016**  
ADDRESS: **7240 S. Wabash** IDPH LICENSE NO: **100-08864**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **12**  
MATERIAL DESCRIPTION: **9x9 Tan Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE:

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1953 bldg Room 200**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Not observed 2016**

Inspector's Signature: \_\_\_\_\_ Date: 02/29/2016

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22931** BUIDLING ID: **3010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Deneen School** REVIEW DATE: **3/14/2016**  
ADDRESS: **7240 S. Wabash** IDPH LICENSE NO: **100-08864**

---

HOMOGENEOUS AREA: **12**

MATERIAL DESCRIPTION: **9x9 Tan Floor Tile**

MATERIAL LOCATION: **1953 bldg Room 200**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Material Not Observed in 2016, may be present under new floor

Management Planner's Signature: \_\_\_\_\_



Date: **03/14/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22931** BUIDLING ID: **3010**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Robert DeBord**  
SCHOOL NAME: **Deneen School** INSPECTION DATE: **2/29/2016**  
ADDRESS: **7240 S. Wabash** IDPH LICENSE NO: **100-08864**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **13**  
MATERIAL DESCRIPTION: **9x9 tan flr tile mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **Low**

MATERIAL LOCATION: **1953 building, room 200**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Not observed 2016**

Inspector's Signature: \_\_\_\_\_ Date: 02/29/2016

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22931** BUIDLING ID: **3010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Deneen School** REVIEW DATE: **3/14/2016**  
ADDRESS: **7240 S. Wabash** IDPH LICENSE NO: **100-08864**

---

HOMOGENEOUS AREA: **13**

MATERIAL DESCRIPTION: **9x9 tan flr tile mastic**

MATERIAL LOCATION: **1953 building, room 200**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

not observed in 2016, mat be present under new flooring

Management Planner's Signature: \_\_\_\_\_



Date: **03/14/2016**

# Chicago Public Schools

## Carnow, Conibear and Associates 2016 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22931** BUIDLING ID: **3010**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Robert DeBord**  
SCHOOL NAME: **Deneen School** INSPECTION DATE: **2/29/2016**  
ADDRESS: **7240 S. Wabash** IDPH LICENSE NO: **100-08864**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **14A**  
MATERIAL DESCRIPTION: **12x12 blue flr tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1953 bldg- school offices, rms 104,103,105,109,202,203,204,205,206,207,208,209**  
MATERIAL QUANTITY: **11200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 02/29/2016

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22931** BUIDLING ID: **3010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Deneen School** REVIEW DATE: **3/14/2016**  
ADDRESS: **7240 S. Wabash** IDPH LICENSE NO: **100-08864**

---

HOMOGENEOUS AREA: **14A**  
MATERIAL DESCRIPTION: **12x12 blue flr tile**  
MATERIAL LOCATION: **1953 bldg- school offices, rms 104,103,105,109,202,203,204,205,206,207,208,209**  
MATERIAL QUANTITY: **11200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **03/14/2016**

# Chicago Public Schools

## Carnow, Conibear and Associates 2016 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22931** BUIDLING ID: **3010**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Robert DeBord**  
SCHOOL NAME: **Deneen School** INSPECTION DATE: **2/29/2016**  
ADDRESS: **7240 S. Wabash** IDPH LICENSE NO: **100-08864**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **14B**  
MATERIAL DESCRIPTION: **12x12 white flr tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1953 bldg 1st, 2nd flr corridors, Rm. 200**  
MATERIAL QUANTITY: **5400** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 02/29/2016

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22931** BUIDLING ID: **3010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Deneen School** REVIEW DATE: **3/14/2016**  
ADDRESS: **7240 S. Wabash** IDPH LICENSE NO: **100-08864**

---

HOMOGENEOUS AREA: **14B**  
MATERIAL DESCRIPTION: **12x12 white flr tile**  
MATERIAL LOCATION: **1953 bldg 1st, 2nd flr corridors, Rm. 200**  
MATERIAL QUANTITY: **5400** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **03/14/2016**



# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22931** BUIDLING ID: **3010**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Robert DeBord**  
SCHOOL NAME: **Deneen School** INSPECTION DATE: **2/29/2016**  
ADDRESS: **7240 S. Wabash** IDPH LICENSE NO: **100-08864**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **15A**  
MATERIAL DESCRIPTION: **12x12 blue flr tile mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1953 bldg- school offices, rms 104,103,105,109,202,203,204,205,206,207,208,209**  
MATERIAL QUANTITY: **11200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 02/29/2016

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22931** BUIDLING ID: **3010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Deneen School** REVIEW DATE: **3/14/2016**  
ADDRESS: **7240 S. Wabash** IDPH LICENSE NO: **100-08864**

---

HOMOGENEOUS AREA: **15A**  
MATERIAL DESCRIPTION: **12x12 blue flr tile mastic**  
MATERIAL LOCATION: **1953 bldg- school offices, rms 104,103,105,109,202,203,204,205,206,207,208,209**  
MATERIAL QUANTITY: **11200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **03/14/2016**

# Chicago Public Schools

## Carnow, Conibear and Associates 2016 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22931** BUIDLING ID: **3010**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Robert DeBord**  
SCHOOL NAME: **Deneen School** INSPECTION DATE: **2/29/2016**  
ADDRESS: **7240 S. Wabash** IDPH LICENSE NO: **100-08864**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **15B**  
MATERIAL DESCRIPTION: **12x12 white flr tile mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1953 bldg 1st, 2nd flr corridors and rms 106, 107, 108**  
MATERIAL QUANTITY: **8825** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 02/29/2016

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22931** BUIDLING ID: **3010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Deneen School** REVIEW DATE: **3/14/2016**  
ADDRESS: **7240 S. Wabash** IDPH LICENSE NO: **100-08864**

---

HOMOGENEOUS AREA: **15B**  
MATERIAL DESCRIPTION: **12x12 white flr tile mastic**  
MATERIAL LOCATION: **1953 bldg 1st, 2nd flr corridors and rms 106, 107, 108**  
MATERIAL QUANTITY: **8825** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **03/14/2016**

# Chicago Public Schools

## Carnow, Conibear and Associates 2016 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **22931**    BUILDING ID: **3010**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Robert DeBord**  
SCHOOL NAME: **Deneen School**    INSPECTION DATE: **2/29/2016**  
ADDRESS: **7240 S. Wabash**    IDPH LICENSE NO: **100-08864**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **18A**  
MATERIAL DESCRIPTION: **12x12 white flr tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed**    FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1958- 1st & 2nd fl corridors**  
MATERIAL QUANTITY: **3850**    MATERIAL UNITS: **SF**  
DAMAGE QUANTITY:    DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 02/29/2016

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22931** BUIDLING ID: **3010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Deneen School** REVIEW DATE: **3/14/2016**  
ADDRESS: **7240 S. Wabash** IDPH LICENSE NO: **100-08864**

---

HOMOGENEOUS AREA: **18A**  
MATERIAL DESCRIPTION: **12x12 white flr tile**  
MATERIAL LOCATION: **1958- 1st & 2nd fl corridors**  
MATERIAL QUANTITY: **3850** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **03/14/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **22931**    BUIDLING ID: **3010**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Robert DeBord**  
SCHOOL NAME: **Deneen School**    INSPECTION DATE: **2/29/2016**  
ADDRESS: **7240 S. Wabash**    IDPH LICENSE NO: **100-08864**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **18B**  
MATERIAL DESCRIPTION: **12x12 blue flr tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed**    FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1958- Rooms 112, 114, 210, 212, 214**  
MATERIAL QUANTITY: **4660**    MATERIAL UNITS: **SF**  
DAMAGE QUANTITY:    DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 02/29/2016

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22931** BUIDLING ID: **3010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Deneen School** REVIEW DATE: **3/14/2016**  
ADDRESS: **7240 S. Wabash** IDPH LICENSE NO: **100-08864**

---

HOMOGENEOUS AREA: **18B**  
MATERIAL DESCRIPTION: **12x12 blue flr tile**  
MATERIAL LOCATION: **1958- Rooms 112, 114, 210, 212, 214**  
MATERIAL QUANTITY: **4660** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **03/14/2016**



# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22931** BUIDLING ID: **3010**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Robert DeBord**  
SCHOOL NAME: **Deneen School** INSPECTION DATE: **2/29/2016**  
ADDRESS: **7240 S. Wabash** IDPH LICENSE NO: **100-08864**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **19A**  
MATERIAL DESCRIPTION: **12x12 white flr tile mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1958- 1st & 2nd fl corridors**  
MATERIAL QUANTITY: **3850** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 02/29/2016

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22931** BUIDLING ID: **3010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Deneen School** REVIEW DATE: **3/14/2016**  
ADDRESS: **7240 S. Wabash** IDPH LICENSE NO: **100-08864**

---

HOMOGENEOUS AREA: **19A**  
MATERIAL DESCRIPTION: **12x12 white flr tile mastic**  
MATERIAL LOCATION: **1958- 1st & 2nd fl corridors**  
MATERIAL QUANTITY: **3850** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **03/14/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22931** BUIDLING ID: **3010**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Robert DeBord**  
SCHOOL NAME: **Deneen School** INSPECTION DATE: **2/29/2016**  
ADDRESS: **7240 S. Wabash** IDPH LICENSE NO: **100-08864**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **19B**  
MATERIAL DESCRIPTION: **12x12 blue flr tile mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **1958- Rooms 112, 114, 210, 212, 214**

MATERIAL QUANTITY: **4660**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_

Date: 02/29/2016

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22931** BUIDLING ID: **3010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Deneen School** REVIEW DATE: **3/14/2016**  
ADDRESS: **7240 S. Wabash** IDPH LICENSE NO: **100-08864**

---

HOMOGENEOUS AREA: **19B**  
MATERIAL DESCRIPTION: **12x12 blue flr tile mastic**  
MATERIAL LOCATION: **1958- Rooms 112, 114, 210, 212, 214**  
MATERIAL QUANTITY: **4660** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **03/14/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22931** BUIDLING ID: **3010**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Robert DeBord**  
SCHOOL NAME: **Deneen School** INSPECTION DATE: **2/29/2016**  
ADDRESS: **7240 S. Wabash** IDPH LICENSE NO: **100-08864**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **22**  
MATERIAL DESCRIPTION: **Vibration gasket**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1953 bldg fan room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_

Date: **02/29/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22931** BUIDLING ID: **3010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Deneen School** REVIEW DATE: **3/14/2016**  
ADDRESS: **7240 S. Wabash** IDPH LICENSE NO: **100-08864**

---

HOMOGENEOUS AREA: **22**

MATERIAL DESCRIPTION: **Vibration gasket**

MATERIAL LOCATION: **1953 bldg fan room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **03/14/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **22931**    BUIDLING ID: **3010**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Robert DeBord**  
SCHOOL NAME: **Deneen School**    INSPECTION DATE: **2/29/2016**  
ADDRESS: **7240 S. Wabash**    IDPH LICENSE NO: **100-08864**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **23**  
MATERIAL DESCRIPTION: **wrap around duct fiberglass**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed**    FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **boiler room**  
MATERIAL QUANTITY: **275**    MATERIAL UNITS: **LF**  
DAMAGE QUANTITY:    DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 02/29/2016

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22931** BUIDLING ID: **3010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Deneen School** REVIEW DATE: **3/14/2016**  
ADDRESS: **7240 S. Wabash** IDPH LICENSE NO: **100-08864**

---

HOMOGENEOUS AREA: **23**

MATERIAL DESCRIPTION: **wrap around duct fiberglass**

MATERIAL LOCATION: **boiler room**

MATERIAL QUANTITY: **275**

MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **03/14/2016**



# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22931** BUIDLING ID: **3010**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Robert DeBord**  
SCHOOL NAME: **Deneen School** INSPECTION DATE: **2/29/2016**  
ADDRESS: **7240 S. Wabash** IDPH LICENSE NO: **100-08864**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **24**  
MATERIAL DESCRIPTION: **wrap around breaching fiberglass**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **boiler room**

MATERIAL QUANTITY: **150**

MATERIAL UNITS: **LF**

DAMAGE QUANTITY:

DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 02/29/2016

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22931** BUIDLING ID: **3010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Deneen School** REVIEW DATE: **3/14/2016**  
ADDRESS: **7240 S. Wabash** IDPH LICENSE NO: **100-08864**

---

HOMOGENEOUS AREA: **24**

MATERIAL DESCRIPTION: **wrap around breaching fiberglass**

MATERIAL LOCATION: **boiler room**

MATERIAL QUANTITY: **150**

MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **03/14/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22931** BUIDLING ID: **3010**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Robert DeBord**  
SCHOOL NAME: **Deneen School** INSPECTION DATE: **2/29/2016**  
ADDRESS: **7240 S. Wabash** IDPH LICENSE NO: **100-08864**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **25**  
MATERIAL DESCRIPTION: **Boiler Gasket - abated**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Boiler room**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **02/29/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22931** BUIDLING ID: **3010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Deneen School** REVIEW DATE: **3/14/2016**  
ADDRESS: **7240 S. Wabash** IDPH LICENSE NO: **100-08864**

---

HOMOGENEOUS AREA: **25**

MATERIAL DESCRIPTION: **Boiler Gasket - abated**

MATERIAL LOCATION: **Boiler room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **03/14/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22931** BUIDLING ID: **3010**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Robert DeBord**  
SCHOOL NAME: **Deneen School** INSPECTION DATE: **2/29/2016**  
ADDRESS: **7240 S. Wabash** IDPH LICENSE NO: **100-08864**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **26**  
MATERIAL DESCRIPTION: **Baseboard**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1958- Rms 210A, 210B, 212, 214, 110, 112, 114**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **02/29/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22931** BUIDLING ID: **3010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Deneen School** REVIEW DATE: **3/14/2016**  
ADDRESS: **7240 S. Wabash** IDPH LICENSE NO: **100-08864**

---

HOMOGENEOUS AREA: **26**

MATERIAL DESCRIPTION: **Baseboard**

MATERIAL LOCATION: **1958- Rms 210A, 210B, 212, 214, 110, 112, 114**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **03/14/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22931** BUIDLING ID: **3010**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Robert DeBord**  
SCHOOL NAME: **Deneen School** INSPECTION DATE: **2/29/2016**  
ADDRESS: **7240 S. Wabash** IDPH LICENSE NO: **100-08864**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **27**  
MATERIAL DESCRIPTION: **Baseboard mastic**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1958- Rms 210A, 210B, 212, 214, 110, 112, 114**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **02/29/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22931** BUIDLING ID: **3010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Deneen School** REVIEW DATE: **3/14/2016**  
ADDRESS: **7240 S. Wabash** IDPH LICENSE NO: **100-08864**

---

HOMOGENEOUS AREA: **27**

MATERIAL DESCRIPTION: **Baseboard mastic**

MATERIAL LOCATION: **1958- Rms 210A, 210B, 212, 214, 110, 112, 114**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **03/14/2016** \_\_\_\_\_



# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22931** BUIDLING ID: **3010**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Robert DeBord**  
SCHOOL NAME: **Deneen School** INSPECTION DATE: **2/29/2016**  
ADDRESS: **7240 S. Wabash** IDPH LICENSE NO: **100-08864**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **28**  
MATERIAL DESCRIPTION: **Baseboard**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1962 bldg- 116, 117, 118, 119, 120, 216, 218, 219, 220**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **02/29/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22931** BUIDLING ID: **3010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Deneen School** REVIEW DATE: **3/14/2016**  
ADDRESS: **7240 S. Wabash** IDPH LICENSE NO: **100-08864**

---

HOMOGENEOUS AREA: **28**

MATERIAL DESCRIPTION: **Baseboard**

MATERIAL LOCATION: **1962 bldg- 116, 117, 118, 119, 120, 216, 218, 219, 220**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **03/14/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22931** BUIDLING ID: **3010**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Robert DeBord**  
SCHOOL NAME: **Deneen School** INSPECTION DATE: **2/29/2016**  
ADDRESS: **7240 S. Wabash** IDPH LICENSE NO: **100-08864**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **29**  
MATERIAL DESCRIPTION: **Baseboard Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1962 bldg- 116, 117, 118, 119, 120, 216, 218, 219, 220**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **02/29/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22931** BUIDLING ID: **3010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Deneen School** REVIEW DATE: **3/14/2016**  
ADDRESS: **7240 S. Wabash** IDPH LICENSE NO: **100-08864**

---

HOMOGENEOUS AREA: **29**

MATERIAL DESCRIPTION: **Baseboard Mastic**

MATERIAL LOCATION: **1962 bldg- 116, 117, 118, 119, 120, 216, 218, 219, 220**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **03/14/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22931** BUIDLING ID: **3010**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Robert DeBord**  
SCHOOL NAME: **Deneen School** INSPECTION DATE: **2/29/2016**  
ADDRESS: **7240 S. Wabash** IDPH LICENSE NO: **100-08864**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **32**  
MATERIAL DESCRIPTION: **Acoustic ceiling**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1958 bldg- corridors**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_

Date: **02/29/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22931** BUIDLING ID: **3010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Deneen School** REVIEW DATE: **3/14/2016**  
ADDRESS: **7240 S. Wabash** IDPH LICENSE NO: **100-08864**

---

HOMOGENEOUS AREA: **32**

MATERIAL DESCRIPTION: **Acoustic ceiling**

MATERIAL LOCATION: **1958 bldg- corridors**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **03/14/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **22931**    BUILDING ID: **3010**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Robert DeBord**  
SCHOOL NAME: **Deneen School**    INSPECTION DATE: **2/29/2016**  
ADDRESS: **7240 S. Wabash**    IDPH LICENSE NO: **100-08864**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **33**  
MATERIAL DESCRIPTION: **Acoustic plaster**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM**    FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1962- rooms 116, 117, 118, 119, 120, teachers lounge, 218, 220**

MATERIAL QUANTITY:    MATERIAL UNITS:

DAMAGE QUANTITY:    DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **02/29/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22931** BUIDLING ID: **3010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Deneen School** REVIEW DATE: **3/14/2016**  
ADDRESS: **7240 S. Wabash** IDPH LICENSE NO: **100-08864**

---

HOMOGENEOUS AREA: **33**

MATERIAL DESCRIPTION: **Acoustic plaster**

MATERIAL LOCATION: **1962- rooms 116, 117, 118, 119, 120, teachers lounge, 218, 220**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **03/14/2016**



# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22931** BUIDLING ID: **3010**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Robert DeBord**  
SCHOOL NAME: **Deneen School** INSPECTION DATE: **2/29/2016**  
ADDRESS: **7240 S. Wabash** IDPH LICENSE NO: **100-08864**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **34**  
MATERIAL DESCRIPTION: **Acoustic plaster**  
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1958- room 110**  
MATERIAL QUANTITY: **1390** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 02/29/2016

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22931** BUIDLING ID: **3010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Deneen School** REVIEW DATE: **3/14/2016**  
ADDRESS: **7240 S. Wabash** IDPH LICENSE NO: **100-08864**

---

HOMOGENEOUS AREA: **34**  
MATERIAL DESCRIPTION: **Acoustic plaster**  
MATERIAL LOCATION: **1958- room 110**  
MATERIAL QUANTITY: **1390** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **03/14/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22931** BUIDLING ID: **3010**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Robert DeBord**  
SCHOOL NAME: **Deneen School** INSPECTION DATE: **2/29/2016**  
ADDRESS: **7240 S. Wabash** IDPH LICENSE NO: **100-08864**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **36**  
MATERIAL DESCRIPTION: **Brown coat plaster**  
HISTORICAL AHERA DAMAGE CATEGORY **6**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1958 bldg- corridors/ceiling**  
MATERIAL QUANTITY: **7900** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 02/29/2016

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22931** BUIDLING ID: **3010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Deneen School** REVIEW DATE: **3/14/2016**  
ADDRESS: **7240 S. Wabash** IDPH LICENSE NO: **100-08864**

---

HOMOGENEOUS AREA: **36**  
MATERIAL DESCRIPTION: **Brown coat plaster**  
MATERIAL LOCATION: **1958 bldg- corridors/ceiling**  
MATERIAL QUANTITY: **7900** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **03/14/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22931** BUIDLING ID: **3010**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Robert DeBord**  
SCHOOL NAME: **Deneen School** INSPECTION DATE: **2/29/2016**  
ADDRESS: **7240 S. Wabash** IDPH LICENSE NO: **100-08864**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **37**  
MATERIAL DESCRIPTION: **Acoustic ceiling plaster**  
HISTORICAL AHERA DAMAGE CATEGORY **5 ACBM with potential for significant damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **5. ACBM with potential for significant damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1962- 1st and 2nd flr corridor**  
MATERIAL QUANTITY: **1260** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 02/29/2016

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22931** BUIDLING ID: **3010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Deneen School** REVIEW DATE: **3/14/2016**  
ADDRESS: **7240 S. Wabash** IDPH LICENSE NO: **100-08864**

---

HOMOGENEOUS AREA: **37**  
MATERIAL DESCRIPTION: **Acoustic ceiling plaster**  
MATERIAL LOCATION: **1962- 1st and 2nd flr corridor**  
MATERIAL QUANTITY: **1260** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **03/14/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22931** BUIDLING ID: **3010**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Robert DeBord**  
SCHOOL NAME: **Deneen School** INSPECTION DATE: **2/29/2016**  
ADDRESS: **7240 S. Wabash** IDPH LICENSE NO: **100-08864**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **38A**  
MATERIAL DESCRIPTION: **12 x 12 Blue Floortile mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1962 Add, Rms 116,117,118,119,120,teachers lounge (115), Engineer's Office**  
MATERIAL QUANTITY: **4755** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 02/29/2016

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22931** BUIDLING ID: **3010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Deneen School** REVIEW DATE: **3/14/2016**  
ADDRESS: **7240 S. Wabash** IDPH LICENSE NO: **100-08864**

---

HOMOGENEOUS AREA: **38A**  
MATERIAL DESCRIPTION: **12 x 12 Blue Floortile mastic**  
MATERIAL LOCATION: **1962 Add, Rms 116,117,118,119,120,teachers lounge (115), Engineer's Office**  
MATERIAL QUANTITY: **4755** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **03/14/2016**



# Chicago Public Schools

## Carnow, Conibear and Associates 2016 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22931** BUIDLING ID: **3010**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Robert DeBord**  
SCHOOL NAME: **Deneen School** INSPECTION DATE: **2/29/2016**  
ADDRESS: **7240 S. Wabash** IDPH LICENSE NO: **100-08864**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **38B**  
MATERIAL DESCRIPTION: **12 x 12 White Floortile mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1062 Add,1st,2nd FI Corridor**  
MATERIAL QUANTITY: **2640** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 02/29/2016

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22931** BUIDLING ID: **3010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Deneen School** REVIEW DATE: **3/14/2016**  
ADDRESS: **7240 S. Wabash** IDPH LICENSE NO: **100-08864**

---

HOMOGENEOUS AREA: **38B**  
MATERIAL DESCRIPTION: **12 x 12 White Floortile mastic**  
MATERIAL LOCATION: **1062 Add,1st,2nd FI Corridor**  
MATERIAL QUANTITY: **2640** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **03/14/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22931** BUIDLING ID: **3010**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Robert DeBord**  
SCHOOL NAME: **Deneen School** INSPECTION DATE: **2/29/2016**  
ADDRESS: **7240 S. Wabash** IDPH LICENSE NO: **100-08864**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **39**  
MATERIAL DESCRIPTION: **Brown coat plaster**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Assumed** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1962- 1st and 2nd flr corridor**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed 2016**

Inspector's Signature: \_\_\_\_\_

Date: 02/29/2016

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22931** BUIDLING ID: **3010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Deneen School** REVIEW DATE: **3/14/2016**  
ADDRESS: **7240 S. Wabash** IDPH LICENSE NO: **100-08864**

---

HOMOGENEOUS AREA: **39**

MATERIAL DESCRIPTION: **Brown coat plaster**

MATERIAL LOCATION: **1962- 1st and 2nd flr corridor**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Not observed in 2016. Maintain O&M if identified

Management Planner's Signature: \_\_\_\_\_



Date: **03/14/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22931** BUIDLING ID: **3010**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Robert DeBord**  
SCHOOL NAME: **Deneen School** INSPECTION DATE: **2/29/2016**  
ADDRESS: **7240 S. Wabash** IDPH LICENSE NO: **100-08864**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **40**  
MATERIAL DESCRIPTION: **1 x 1 Acoustical Ceiling tile mastic**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Assumed** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1953 Bldg, Kitchen, Lunch Rm**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Not observed 2016**

Inspector's Signature: \_\_\_\_\_ Date: **02/29/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22931** BUIDLING ID: **3010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Deneen School** REVIEW DATE: **3/14/2016**  
ADDRESS: **7240 S. Wabash** IDPH LICENSE NO: **100-08864**

---

HOMOGENEOUS AREA: **40**

MATERIAL DESCRIPTION: **1 x 1 Acoustical Ceiling tile mastic**

MATERIAL LOCATION: **1953 Bldg, Kitchen, Lunch Rm**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Not observed in 2016. Maintain O&M if observed

Management Planner's Signature: \_\_\_\_\_



Date: **03/14/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22931** BUIDLING ID: **3010**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Robert DeBord**  
SCHOOL NAME: **Deneen School** INSPECTION DATE: **2/29/2016**  
ADDRESS: **7240 S. Wabash** IDPH LICENSE NO: **100-08864**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **41**  
MATERIAL DESCRIPTION: **2'x4' Acoustical ceiling tiles**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1953 bldg- lunchroom**  
MATERIAL QUANTITY: **2400** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 02/29/2016

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22931** BUIDLING ID: **3010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Deneen School** REVIEW DATE: **3/14/2016**  
ADDRESS: **7240 S. Wabash** IDPH LICENSE NO: **100-08864**

---

HOMOGENEOUS AREA: **41**  
MATERIAL DESCRIPTION: **2'x4' Acoustical ceiling tiles**  
MATERIAL LOCATION: **1953 bldg- lunchroom**  
MATERIAL QUANTITY: **2400** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **03/14/2016**



# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22931** BUIDLING ID: **3010**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Robert DeBord**  
SCHOOL NAME: **Deneen School** INSPECTION DATE: **2/29/2016**  
ADDRESS: **7240 S. Wabash** IDPH LICENSE NO: **100-08864**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **42A**  
MATERIAL DESCRIPTION: **12x12 blue floor tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1953 bldg - rooms 104, 106, 108**  
MATERIAL QUANTITY: **4413** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 02/29/2016

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22931** BUIDLING ID: **3010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Deneen School** REVIEW DATE: **3/14/2016**  
ADDRESS: **7240 S. Wabash** IDPH LICENSE NO: **100-08864**

---

HOMOGENEOUS AREA: **42A**  
MATERIAL DESCRIPTION: **12x12 blue floor tile**  
MATERIAL LOCATION: **1953 bldg - rooms 104, 106, 108**  
MATERIAL QUANTITY: **4413** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **03/14/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22931** BUIDLING ID: **3010**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Robert DeBord**  
SCHOOL NAME: **Deneen School** INSPECTION DATE: **2/29/2016**  
ADDRESS: **7240 S. Wabash** IDPH LICENSE NO: **100-08864**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **42B**  
MATERIAL DESCRIPTION: **12x12 blue floor tile mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1953 bldg - rooms 104, 106, 108**  
MATERIAL QUANTITY: **4413** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 02/29/2016

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22931** BUIDLING ID: **3010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Deneen School** REVIEW DATE: **3/14/2016**  
ADDRESS: **7240 S. Wabash** IDPH LICENSE NO: **100-08864**

---

HOMOGENEOUS AREA: **42B**  
MATERIAL DESCRIPTION: **12x12 blue floor tile mastic**  
MATERIAL LOCATION: **1953 bldg - rooms 104, 106, 108**  
MATERIAL QUANTITY: **4413** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **03/14/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22931** BUIDLING ID: **3010**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Robert DeBord**  
SCHOOL NAME: **Deneen School** INSPECTION DATE: **2/29/2016**  
ADDRESS: **7240 S. Wabash** IDPH LICENSE NO: **100-08864**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **43A**  
MATERIAL DESCRIPTION: **12x12 blue floor tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1958 bldg - room 110**  
MATERIAL QUANTITY: **1471** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 02/29/2016

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22931** BUIDLING ID: **3010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Deneen School** REVIEW DATE: **3/14/2016**  
ADDRESS: **7240 S. Wabash** IDPH LICENSE NO: **100-08864**

---

HOMOGENEOUS AREA: **43A**  
MATERIAL DESCRIPTION: **12x12 blue floor tile**  
MATERIAL LOCATION: **1958 bldg - room 110**  
MATERIAL QUANTITY: **1471** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **03/14/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22931** BUIDLING ID: **3010**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Robert DeBord**  
SCHOOL NAME: **Deneen School** INSPECTION DATE: **2/29/2016**  
ADDRESS: **7240 S. Wabash** IDPH LICENSE NO: **100-08864**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **43B**  
MATERIAL DESCRIPTION: **12x12 blue floor tile mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1958 bldg - room 110**  
MATERIAL QUANTITY: **1471** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 02/29/2016

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22931** BUIDLING ID: **3010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Deneen School** REVIEW DATE: **3/14/2016**  
ADDRESS: **7240 S. Wabash** IDPH LICENSE NO: **100-08864**

---

HOMOGENEOUS AREA: **43B**  
MATERIAL DESCRIPTION: **12x12 blue floor tile mastic**  
MATERIAL LOCATION: **1958 bldg - room 110**  
MATERIAL QUANTITY: **1471** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **03/14/2016**



# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22931** BUIDLING ID: **3010**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Robert DeBord**  
SCHOOL NAME: **Deneen School** INSPECTION DATE: **2/29/2016**  
ADDRESS: **7240 S. Wabash** IDPH LICENSE NO: **100-08864**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **44**  
MATERIAL DESCRIPTION: **Blue/Gray Carpet Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Rm. 102 Old Building**  
MATERIAL QUANTITY: **384** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 02/29/2016

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22931** BUIDLING ID: **3010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Deneen School** REVIEW DATE: **3/14/2016**  
ADDRESS: **7240 S. Wabash** IDPH LICENSE NO: **100-08864**

---

HOMOGENEOUS AREA: **44**  
MATERIAL DESCRIPTION: **Blue/Gray Carpet Mastic**  
MATERIAL LOCATION: **Rm. 102 Old Building**  
MATERIAL QUANTITY: **384** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **03/14/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22931** BUIDLING ID: **3010**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Robert DeBord**  
SCHOOL NAME: **Deneen School** INSPECTION DATE: **2/29/2016**  
ADDRESS: **7240 S. Wabash** IDPH LICENSE NO: **100-08864**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **45**  
MATERIAL DESCRIPTION: **Brown Carpet Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Main Office, 2007 Building**  
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 02/29/2016

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22931** BUIDLING ID: **3010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Deneen School** REVIEW DATE: **3/14/2016**  
ADDRESS: **7240 S. Wabash** IDPH LICENSE NO: **100-08864**

---

HOMOGENEOUS AREA: **45**  
MATERIAL DESCRIPTION: **Brown Carpet Mastic**  
MATERIAL LOCATION: **Main Office, 2007 Building**  
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **03/14/2016**

# Chicago Public Schools

## Carnow, Conibear and Associates 2016 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **22931**    BUILDING ID: **3010**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Robert DeBord**  
SCHOOL NAME: **Deneen School**    INSPECTION DATE: **2/29/2016**  
ADDRESS: **7240 S. Wabash**    IDPH LICENSE NO: **100-08864**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **46**  
MATERIAL DESCRIPTION: **12" x 12" Light Green VFT**  
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed**    FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Cafeteria, Rms. 160, 201, 263, 252, 256 2007 Building**  
MATERIAL QUANTITY: **7892**    MATERIAL UNITS: **SF**  
DAMAGE QUANTITY:    DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 02/29/2016

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22931** BUIDLING ID: **3010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Deneen School** REVIEW DATE: **3/14/2016**  
ADDRESS: **7240 S. Wabash** IDPH LICENSE NO: **100-08864**

---

HOMOGENEOUS AREA: **46**  
MATERIAL DESCRIPTION: **12" x 12" Light Green VFT**  
MATERIAL LOCATION: **Cafeteria, Rms. 160, 201, 263, 252, 256 2007 Building**  
MATERIAL QUANTITY: **7892** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **03/14/2016**

# Chicago Public Schools

## Carnow, Conibear and Associates 2016 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **22931**    BUILDING ID: **3010**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Robert DeBord**  
SCHOOL NAME: **Deneen School**    INSPECTION DATE: **2/29/2016**  
ADDRESS: **7240 S. Wabash**    IDPH LICENSE NO: **100-08864**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **47**  
MATERIAL DESCRIPTION: **12" x 12" Light Green VFT Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed**    FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Cafeteria, Rms. 160, 201, 263, 252, 256 2007 Building**  
MATERIAL QUANTITY: **7892**    MATERIAL UNITS: **SF**  
DAMAGE QUANTITY:    DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 02/29/2016

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22931** BUIDLING ID: **3010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Deneen School** REVIEW DATE: **3/14/2016**  
ADDRESS: **7240 S. Wabash** IDPH LICENSE NO: **100-08864**

---

HOMOGENEOUS AREA: **47**  
MATERIAL DESCRIPTION: **12" x 12" Light Green VFT Mastic**  
MATERIAL LOCATION: **Cafeteria, Rms. 160, 201, 263, 252, 256 2007 Building**  
MATERIAL QUANTITY: **7892** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **03/14/2016**



# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22931** BUIDLING ID: **3010**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Robert DeBord**  
SCHOOL NAME: **Deneen School** INSPECTION DATE: **2/29/2016**  
ADDRESS: **7240 S. Wabash** IDPH LICENSE NO: **100-08864**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **48**  
MATERIAL DESCRIPTION: **Tan Baseboard**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Cafeteria, Rms. 160, 201, 263, 252, 256 2007 Building**  
MATERIAL QUANTITY: **312** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 02/29/2016

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22931** BUIDLING ID: **3010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Deneen School** REVIEW DATE: **3/14/2016**  
ADDRESS: **7240 S. Wabash** IDPH LICENSE NO: **100-08864**

---

HOMOGENEOUS AREA: **48**  
MATERIAL DESCRIPTION: **Tan Baseboard**  
MATERIAL LOCATION: **Cafeteria, Rms. 160, 201, 263, 252, 256 2007 Building**  
MATERIAL QUANTITY: **312** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **03/14/2016**

# Chicago Public Schools

## Carnow, Conibear and Associates 2016 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22931** BUIDLING ID: **3010**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Robert DeBord**  
SCHOOL NAME: **Deneen School** INSPECTION DATE: **2/29/2016**  
ADDRESS: **7240 S. Wabash** IDPH LICENSE NO: **100-08864**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **49**  
MATERIAL DESCRIPTION: **Tan Baseboard Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Cafeteria, Rms. 160, 201, 263, 252, 256 2007 Building**  
MATERIAL QUANTITY: **312** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 02/29/2016

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22931** BUILDING ID: **3010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Deneen School** REVIEW DATE: **3/14/2016**  
ADDRESS: **7240 S. Wabash** IDPH LICENSE NO: **100-08864**

---

HOMOGENEOUS AREA: **49**  
MATERIAL DESCRIPTION: **Tan Baseboard Mastic**  
MATERIAL LOCATION: **Cafeteria, Rms. 160, 201, 263, 252, 256 2007 Building**  
MATERIAL QUANTITY: **312** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **03/14/2016**

# Chicago Public Schools

## Carnow, Conibear and Associates 2016 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22931** BUIDLING ID: **3010**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Robert DeBord**  
SCHOOL NAME: **Deneen School** INSPECTION DATE: **2/29/2016**  
ADDRESS: **7240 S. Wabash** IDPH LICENSE NO: **100-08864**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **50**  
MATERIAL DESCRIPTION: **12" x 12" Yellow VFT**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **Cafeteria, Rms. 160, 261, 263, 252, 2007 Building**  
MATERIAL QUANTITY: **225** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 02/29/2016

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22931** BUIDLING ID: **3010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Deneen School** REVIEW DATE: **3/14/2016**  
ADDRESS: **7240 S. Wabash** IDPH LICENSE NO: **100-08864**

---

HOMOGENEOUS AREA: **50**  
MATERIAL DESCRIPTION: **12" x 12" Yellow VFT**  
MATERIAL LOCATION: **Cafeteria, Rms. 160, 261, 263, 252, 2007 Building**  
MATERIAL QUANTITY: **225** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **03/14/2016**

# Chicago Public Schools

## Carnow, Conibear and Associates 2016 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22931** BUIDLING ID: **3010**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Robert DeBord**  
SCHOOL NAME: **Deneen School** INSPECTION DATE: **2/29/2016**  
ADDRESS: **7240 S. Wabash** IDPH LICENSE NO: **100-08864**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **51**  
MATERIAL DESCRIPTION: **12" x 12" Light Beige VFT**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**

MATERIAL LOCATION: **Cafeteria, Rms. 160, 261, 263, 252, 2007 Building**

MATERIAL QUANTITY: **225** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 02/29/2016

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22931** BUIDLING ID: **3010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Deneen School** REVIEW DATE: **3/14/2016**  
ADDRESS: **7240 S. Wabash** IDPH LICENSE NO: **100-08864**

---

HOMOGENEOUS AREA: **51**  
MATERIAL DESCRIPTION: **12" x 12" Light Beige VFT**  
MATERIAL LOCATION: **Cafeteria, Rms. 160, 261, 263, 252, 2007 Building**  
MATERIAL QUANTITY: **225** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **03/14/2016**



# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22931** BUIDLING ID: **3010**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Robert DeBord**  
SCHOOL NAME: **Deneen School** INSPECTION DATE: **2/29/2016**  
ADDRESS: **7240 S. Wabash** IDPH LICENSE NO: **100-08864**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **52**  
MATERIAL DESCRIPTION: **Mastic Associated with HA 50 and HA 51**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Cafeteria, Rms. 160, 261, 263, 252, 2007 Building**

MATERIAL QUANTITY: **450** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 02/29/2016

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22931** BUIDLING ID: **3010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Deneen School** REVIEW DATE: **3/14/2016**  
ADDRESS: **7240 S. Wabash** IDPH LICENSE NO: **100-08864**

---

HOMOGENEOUS AREA: **52**  
MATERIAL DESCRIPTION: **Mastic Associated with HA 50 and HA 51**  
MATERIAL LOCATION: **Cafeteria, Rms. 160, 261, 263, 252, 2007 Building**  
MATERIAL QUANTITY: **450** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **03/14/2016**

# Chicago Public Schools

## Carnow, Conibear and Associates 2016 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22931** BUIDLING ID: **3010**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Robert DeBord**  
SCHOOL NAME: **Deneen School** INSPECTION DATE: **2/29/2016**  
ADDRESS: **7240 S. Wabash** IDPH LICENSE NO: **100-08864**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **53**  
MATERIAL DESCRIPTION: **Green Baseboard**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Rm. 256 (Library) 2007 Building**  
MATERIAL QUANTITY: **224** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 02/29/2016

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22931** BUIDLING ID: **3010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Deneen School** REVIEW DATE: **3/14/2016**  
ADDRESS: **7240 S. Wabash** IDPH LICENSE NO: **100-08864**

---

HOMOGENEOUS AREA: **53**  
MATERIAL DESCRIPTION: **Green Baseboard**  
MATERIAL LOCATION: **Rm. 256 (Library) 2007 Building**  
MATERIAL QUANTITY: **224** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **03/14/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **22931**    BUILDING ID: **3010**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Robert DeBord**  
SCHOOL NAME: **Deneen School**    INSPECTION DATE: **2/29/2016**  
ADDRESS: **7240 S. Wabash**    IDPH LICENSE NO: **100-08864**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **54**  
MATERIAL DESCRIPTION: **Green Baseboard Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed**    FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Rm. 256 (Library) 2007 Building**  
MATERIAL QUANTITY: **224**    MATERIAL UNITS: **LF**  
DAMAGE QUANTITY:    DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 02/29/2016

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22931** BUIDLING ID: **3010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Deneen School** REVIEW DATE: **3/14/2016**  
ADDRESS: **7240 S. Wabash** IDPH LICENSE NO: **100-08864**

---

HOMOGENEOUS AREA: **54**  
MATERIAL DESCRIPTION: **Green Baseboard Mastic**  
MATERIAL LOCATION: **Rm. 256 (Library) 2007 Building**  
MATERIAL QUANTITY: **224** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **03/14/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22931** BUIDLING ID: **3010**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Robert DeBord**  
SCHOOL NAME: **Deneen School** INSPECTION DATE: **2/29/2016**  
ADDRESS: **7240 S. Wabash** IDPH LICENSE NO: **100-08864**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **A**  
MATERIAL DESCRIPTION: **Aircell Pipe Insulation**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1953 Bldg, Airtunnel, Crawlspace, Abated**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **02/29/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22931** BUIDLING ID: **3010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Deneen School** REVIEW DATE: **3/14/2016**  
ADDRESS: **7240 S. Wabash** IDPH LICENSE NO: **100-08864**

---

HOMOGENEOUS AREA: **A**

MATERIAL DESCRIPTION: **Aircell Pipe Insulation**

MATERIAL LOCATION: **1953 Bldg, Airtunnel, Crawlspace, Abated**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Material Abated

Management Planner's Signature: \_\_\_\_\_



Date: **03/14/2016**



# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22931** BUIDLING ID: **3010**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Robert DeBord**  
SCHOOL NAME: **Deneen School** INSPECTION DATE: **2/29/2016**  
ADDRESS: **7240 S. Wabash** IDPH LICENSE NO: **100-08864**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **B**  
MATERIAL DESCRIPTION: **MJP fittings**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1953 Bldg, Air tunnels, Crawlspace, Abated**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **02/29/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22931** BUIDLING ID: **3010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Deneen School** REVIEW DATE: **3/14/2016**  
ADDRESS: **7240 S. Wabash** IDPH LICENSE NO: **100-08864**

---

HOMOGENEOUS AREA: **B**

MATERIAL DESCRIPTION: **MJP fittings**

MATERIAL LOCATION: **1953 Bldg, Air tunnels, Crawlspace, Abated**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Material Abated

Management Planner's Signature: \_\_\_\_\_



Date: **03/14/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22931** BUIDLING ID: **3010**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Robert DeBord**  
SCHOOL NAME: **Deneen School** INSPECTION DATE: **2/29/2016**  
ADDRESS: **7240 S. Wabash** IDPH LICENSE NO: **100-08864**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **C**  
MATERIAL DESCRIPTION: **Fittings on fiberglass runs**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1962 Bldg, Pipe Chases, Crawlspace, Abated**

MATERIAL QUANTITY: MATERIAL UNITS: **Fittings**

DAMAGE QUANTITY: DAMAGE UNITS: **Fittings**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 02/29/2016

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22931** BUIDLING ID: **3010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Deneen School** REVIEW DATE: **3/14/2016**  
ADDRESS: **7240 S. Wabash** IDPH LICENSE NO: **100-08864**

---

HOMOGENEOUS AREA: **C**

MATERIAL DESCRIPTION: **Fittings on fiberglass runs**

MATERIAL LOCATION: **1962 Bldg, Pipe Chases, Crawlspace, Abated**

MATERIAL QUANTITY: MATERIAL UNITS: **Fittings**

DAMAGE QUANTITY: DAMAGE UNITS: **Fittings**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Material Abated

Management Planner's Signature: \_\_\_\_\_



Date: **03/14/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22931** BUIDLING ID: **3010**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Robert DeBord**  
SCHOOL NAME: **Deneen School** INSPECTION DATE: **2/29/2016**  
ADDRESS: **7240 S. Wabash** IDPH LICENSE NO: **100-08864**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **E**  
MATERIAL DESCRIPTION: **Aircell pipe insulation**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1958 Add, Crawlspace, Abated**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **02/29/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22931** BUIDLING ID: **3010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Deneen School** REVIEW DATE: **3/14/2016**  
ADDRESS: **7240 S. Wabash** IDPH LICENSE NO: **100-08864**

---

HOMOGENEOUS AREA: **E**

MATERIAL DESCRIPTION: **Aircell pipe insulation**

MATERIAL LOCATION: **1958 Add, Crawlspace, Abated**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Material Abated

Management Planner's Signature: \_\_\_\_\_



Date: **03/14/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22931** BUIDLING ID: **3010**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Robert DeBord**  
SCHOOL NAME: **Deneen School** INSPECTION DATE: **2/29/2016**  
ADDRESS: **7240 S. Wabash** IDPH LICENSE NO: **100-08864**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **F**  
MATERIAL DESCRIPTION: **Cardboard pipe insulation**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1958 Add, Crawlspace, Abated**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **02/29/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22931** BUIDLING ID: **3010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Deneen School** REVIEW DATE: **3/14/2016**  
ADDRESS: **7240 S. Wabash** IDPH LICENSE NO: **100-08864**

---

HOMOGENEOUS AREA: **F**

MATERIAL DESCRIPTION: **Cardboard pipe insulation**

MATERIAL LOCATION: **1958 Add, Crawlspace, Abated**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

material abated

Management Planner's Signature: \_\_\_\_\_



Date: **03/14/2016**



# Chicago Public Schools

## Carnow, Conibear and Associates 2016 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22931** BUIDLING ID: **3010**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Robert DeBord**  
SCHOOL NAME: **Deneen School** INSPECTION DATE: **2/29/2016**  
ADDRESS: **7240 S. Wabash** IDPH LICENSE NO: **100-08864**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **FT-1**  
MATERIAL DESCRIPTION: **12x12 green speckled floor tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Room 200 and 100**  
MATERIAL QUANTITY: **250** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 02/29/2016

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22931** BUIDLING ID: **3010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Deneen School** REVIEW DATE: **3/14/2016**  
ADDRESS: **7240 S. Wabash** IDPH LICENSE NO: **100-08864**

---

HOMOGENEOUS AREA: **FT-1**  
MATERIAL DESCRIPTION: **12x12 green speckled floor tile**  
MATERIAL LOCATION: **Room 200 and 100**  
MATERIAL QUANTITY: **250** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **03/14/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22931** BUIDLING ID: **3010**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Robert DeBord**  
SCHOOL NAME: **Deneen School** INSPECTION DATE: **2/29/2016**  
ADDRESS: **7240 S. Wabash** IDPH LICENSE NO: **100-08864**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **FT-2**  
MATERIAL DESCRIPTION: **12x12 beige floor tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Room 217**  
MATERIAL QUANTITY: **85** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 02/29/2016

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22931** BUIDLING ID: **3010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Deneen School** REVIEW DATE: **3/14/2016**  
ADDRESS: **7240 S. Wabash** IDPH LICENSE NO: **100-08864**

---

HOMOGENEOUS AREA: **FT-2**  
MATERIAL DESCRIPTION: **12x12 beige floor tile**  
MATERIAL LOCATION: **Room 217**  
MATERIAL QUANTITY: **85** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **03/14/2016**

# Chicago Public Schools

## Carnow, Conibear and Associates 2016 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22931** BUIDLING ID: **3010**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Robert DeBord**  
SCHOOL NAME: **Deneen School** INSPECTION DATE: **2/29/2016**  
ADDRESS: **7240 S. Wabash** IDPH LICENSE NO: **100-08864**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **FTM-1**  
MATERIAL DESCRIPTION: **12x12 green mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Room 200 & 100**  
MATERIAL QUANTITY: **250** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 02/29/2016

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22931** BUIDLING ID: **3010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Deneen School** REVIEW DATE: **3/14/2016**  
ADDRESS: **7240 S. Wabash** IDPH LICENSE NO: **100-08864**

---

HOMOGENEOUS AREA: **FTM-1**  
MATERIAL DESCRIPTION: **12x12 green mastic**  
MATERIAL LOCATION: **Room 200 & 100**  
MATERIAL QUANTITY: **250** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **03/14/2016**

# Chicago Public Schools

## Carnow, Conibear and Associates 2016 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **22931**    BUIDLING ID: **3010**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Robert DeBord**  
SCHOOL NAME: **Deneen School**    INSPECTION DATE: **2/29/2016**  
ADDRESS: **7240 S. Wabash**    IDPH LICENSE NO: **100-08864**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **FTM-2**  
MATERIAL DESCRIPTION: **12x12 mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed**    FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **room 217**  
MATERIAL QUANTITY: **85**    MATERIAL UNITS: **SF**  
DAMAGE QUANTITY:    DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 02/29/2016

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22931** BUIDLING ID: **3010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Deneen School** REVIEW DATE: **3/14/2016**  
ADDRESS: **7240 S. Wabash** IDPH LICENSE NO: **100-08864**

---

HOMOGENEOUS AREA: **FTM-2**  
MATERIAL DESCRIPTION: **12x12 mastic**  
MATERIAL LOCATION: **room 217**  
MATERIAL QUANTITY: **85** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **03/14/2016**



# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **22931**    BUIDLING ID: **3010**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Robert DeBord**  
SCHOOL NAME: **Deneen School**    INSPECTION DATE: **2/29/2016**  
ADDRESS: **7240 S. Wabash**    IDPH LICENSE NO: **100-08864**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **G**  
MATERIAL DESCRIPTION: **Fttings on fiberglass runs**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated**    FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1958 Add, Abated**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **02/29/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22931** BUIDLING ID: **3010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Deneen School** REVIEW DATE: **3/14/2016**  
ADDRESS: **7240 S. Wabash** IDPH LICENSE NO: **100-08864**

---

HOMOGENEOUS AREA: **G**

MATERIAL DESCRIPTION: **Fttings on fiberglass runs**

MATERIAL LOCATION: **1958 Add, Abated**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

material abated

Management Planner's Signature: \_\_\_\_\_



Date: **03/14/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22931** BUIDLING ID: **3010**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Robert DeBord**  
SCHOOL NAME: **Deneen School** INSPECTION DATE: **2/29/2016**  
ADDRESS: **7240 S. Wabash** IDPH LICENSE NO: **100-08864**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **H**  
MATERIAL DESCRIPTION: **Fittings on fiberglass runs**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1962 Bldg, Crawlspace, Abated**

MATERIAL QUANTITY: MATERIAL UNITS: **Fittings**

DAMAGE QUANTITY: DAMAGE UNITS: **Fittings**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 02/29/2016

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22931** BUIDLING ID: **3010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Deneen School** REVIEW DATE: **3/14/2016**  
ADDRESS: **7240 S. Wabash** IDPH LICENSE NO: **100-08864**

---

HOMOGENEOUS AREA: **H**

MATERIAL DESCRIPTION: **Fittings on fiberglass runs**

MATERIAL LOCATION: **1962 Bldg, Crawlspace, Abated**

MATERIAL QUANTITY: MATERIAL UNITS: **Fittings**

DAMAGE QUANTITY: DAMAGE UNITS: **Fittings**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:  
material abated

Management Planner's Signature: \_\_\_\_\_



Date: **03/14/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **22931**    BUIDLING ID: **3010**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Robert DeBord**  
SCHOOL NAME: **Deneen School**    INSPECTION DATE: **2/29/2016**  
ADDRESS: **7240 S. Wabash**    IDPH LICENSE NO: **100-08864**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **I**  
MATERIAL DESCRIPTION: **Aircell pipe fittings**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated**    FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1953 Bldg, Air tunnel, Crawlspace, corridor, Abated**

MATERIAL QUANTITY:    MATERIAL UNITS: **Fittings**

DAMAGE QUANTITY:    DAMAGE UNITS: **Fittings**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 02/29/2016

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22931** BUIDLING ID: **3010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Deneen School** REVIEW DATE: **3/14/2016**  
ADDRESS: **7240 S. Wabash** IDPH LICENSE NO: **100-08864**

---

HOMOGENEOUS AREA: **I**

MATERIAL DESCRIPTION: **Aircell pipe fittings**

MATERIAL LOCATION: **1953 Bldg, Air tunnel, Crawlspace, corridor, Abated**

MATERIAL QUANTITY: MATERIAL UNITS: **Fittings**

DAMAGE QUANTITY: DAMAGE UNITS: **Fittings**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:  
material abated

Management Planner's Signature: \_\_\_\_\_



Date: **03/14/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22931** BUIDLING ID: **3010**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Robert DeBord**  
SCHOOL NAME: **Deneen School** INSPECTION DATE: **2/29/2016**  
ADDRESS: **7240 S. Wabash** IDPH LICENSE NO: **100-08864**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **J**  
MATERIAL DESCRIPTION: **Cardboard pipe fittings**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1953 Bldg, Air tunnels, Abated**

MATERIAL QUANTITY: MATERIAL UNITS: **Fittings**

DAMAGE QUANTITY: DAMAGE UNITS: **Fittings**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 02/29/2016

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22931** BUIDLING ID: **3010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Deneen School** REVIEW DATE: **3/14/2016**  
ADDRESS: **7240 S. Wabash** IDPH LICENSE NO: **100-08864**

---

HOMOGENEOUS AREA: **J**

MATERIAL DESCRIPTION: **Cardboard pipe fittings**

MATERIAL LOCATION: **1953 Bldg, Air tunnels, Abated**

MATERIAL QUANTITY: MATERIAL UNITS: **Fittings**

DAMAGE QUANTITY: DAMAGE UNITS: **Fittings**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:  
material abated

Management Planner's Signature: \_\_\_\_\_



Date: **03/14/2016**



# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22931** BUIDLING ID: **3010**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Robert DeBord**  
SCHOOL NAME: **Deneen School** INSPECTION DATE: **2/29/2016**  
ADDRESS: **7240 S. Wabash** IDPH LICENSE NO: **100-08864**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **K**  
MATERIAL DESCRIPTION: **Aircell pipe joint**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1958 Bldg, Crawlspace, Abated**

MATERIAL QUANTITY: MATERIAL UNITS: **Fittings**

DAMAGE QUANTITY: DAMAGE UNITS: **Fittings**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 02/29/2016

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22931** BUIDLING ID: **3010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Deneen School** REVIEW DATE: **3/14/2016**  
ADDRESS: **7240 S. Wabash** IDPH LICENSE NO: **100-08864**

---

HOMOGENEOUS AREA: **K**  
MATERIAL DESCRIPTION: **Aircell pipe joint**  
MATERIAL LOCATION: **1958 Bldg, Crawlspace, Abated**  
MATERIAL QUANTITY: MATERIAL UNITS: **Fittings**  
DAMAGE QUANTITY: DAMAGE UNITS: **Fittings**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:  
material abated

Management Planner's Signature: \_\_\_\_\_



Date: **03/14/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22931** BUIDLING ID: **3010**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Robert DeBord**  
SCHOOL NAME: **Deneen School** INSPECTION DATE: **2/29/2016**  
ADDRESS: **7240 S. Wabash** IDPH LICENSE NO: **100-08864**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **L**  
MATERIAL DESCRIPTION: **Cardboard Joint Fittings**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1958 Add, Crawlspace, Abated**

MATERIAL QUANTITY: MATERIAL UNITS: **Fittings**

DAMAGE QUANTITY: DAMAGE UNITS: **Fittings**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 02/29/2016

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22931** BUIDLING ID: **3010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Deneen School** REVIEW DATE: **3/14/2016**  
ADDRESS: **7240 S. Wabash** IDPH LICENSE NO: **100-08864**

---

HOMOGENEOUS AREA: **L**

MATERIAL DESCRIPTION: **Cardboard Joint Fittings**

MATERIAL LOCATION: **1958 Add, Crawlspace, Abated**

MATERIAL QUANTITY: MATERIAL UNITS: **Fittings**

DAMAGE QUANTITY: DAMAGE UNITS: **Fittings**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:  
material abated

Management Planner's Signature: \_\_\_\_\_



Date: **03/14/2016**

# **Chicago Public Schools**

**Carnow, Conibear and Associates**

***2016 AHERA REINSPECTION***

# APPENDIX B

## **Inspector and Management Planner Licenses**

---

2015



**OCCUPATIONAL TRAINING & SUPPLY, INC.**

7233 S. Adams Street ♦ Willowbrook, IL 60527 ♦ (630) 655-3900

# Asbestos Building Inspector Refresher

Occupational Training & Supply, Inc. certifies that

**Robert DeBord**


has successfully completed the Asbestos Building Inspector Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 12/2/2015


Exam Date: 12/2/2015

Expiration Date: 12/2/2016

Certificate Number: BIR1512024160


  
Kathy DeSalvo, Director


**Robert De Bord**  
Illinois Licensed Asbestos Inspector, Project Manager, and  
Air Sampling Professional

 **ASBESTOS  
PROFESSIONAL  
LICENSE**

ID NUMBER: **100 - 08864**      ISSUED: **5/27/2015**      EXPIRES: **05/15/2016**

**ROBERT W DE BORD**  
301 MIAMI ST  
PARK FOREST, IL 60466



  
Environmental Health

ENDORSEMENTS	TC EXPIRES
INSPECTOR	2/13/2016
PROJECT MANAGER AIR SAMPLING PROFESSIONAL	2/12/2016

**Alteration of this license shall result in legal action**  
This license issued under authority of the State of Illinois  
Department of Public Health  
This license is valid only when accompanied by a valid  
training course certificate.

**CARNOW  
CONIBEAR**



2015



# OCCUPATIONAL TRAINING & SUPPLY, INC.

7233 S. Adams Street ♦ Willowbrook, IL 60527 ♦ (630) 655-3900

## Asbestos Building Inspector Refresher

Occupational Training & Supply, Inc. certifies that

**Todd Huffer**


has successfully completed the Asbestos Building Inspector Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 12/2/2015

Exam Date: 12/2/2015

Expiration Date: 12/2/2016

Certificate Number: BIR1512024161

  
\_\_\_\_\_  
Kathy DeSalvo, Director

# Todd Huffer

Illinois Licensed Asbestos Inspector, Management Planner,  
Project Manager, and Air Sampling Professional



## ASBESTOS PROFESSIONAL LICENSE

ID NUMBER	ISSUED	EXPIRES
100 - 09870	3/16/2015	05/15/2016

TODD T HUFFER  
315 HATLEN COURT  
MT. PROSPECT, IL 60056

Environmental Health



### ENDORSEMENTS

### TC EXPIRES

INSPECTOR

12/2/2015

MANAGEMENT PLANNER

2/20/2016

PROJECT MANAGER

12/11/2015

AIR SAMPLING PROFESSIONAL

**Alteration of this license shall result in legal action**  
This license issued under authority of the State of Illinois  
Department of Public Health

This license is valid only when accompanied by a valid  
training course certificate.

**CARNOW  
CONIBEAR**

2016



# OCCUPATIONAL TRAINING & SUPPLY, INC.

7233 S. Adams Street ♦ Willowbrook, IL 60527 ♦ (630) 655-3900

## Asbestos Management Planner Refresher

Occupational Training & Supply, Inc. certifies that

**Todd Huffer**

has successfully completed the Asbestos Management Planner Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 1/27/2016

Exam Date: 1/27/2016

Expiration Date: 1/27/2017

Certificate Number: MPR1601270318

Kathy DeSalvo, Director

# APPENDIX C

## Laboratory Accreditations

---

# APPENDIX D

## Laboratory Results

---

# APPENDIX E

## Chain of Custody Forms

---

## Three-Year Reinspection Key to Terms

	<b>CODE</b>	<b>KEY</b>
<b>MATERIAL</b>		
	ACBM	Asbestos Containing Building Materials
<b>MATERIAL CATEGORY</b>		
	MISC	Miscellaneous
	SURF	Surfacing
	TSI	Thermal System Insulation
<b>MATERIAL UNITS</b>		
	LF	Linear Feet
	SF	Square Feet
	CF	Cubic Feet
<b>DAMAGE TYPE</b>		
	Loc	Localized
	Dist	Distributed