

ILLINOIS DEPARTMENT OF PUBLIC HEALTH
AHERA THREE YEAR REINSPECTION
ASBESTOS ABATEMENT PROGRAM
SCHOOL INFORMATION FORM

SECTION I

NAME OF SCHOOL DISTRICT: CHICAGO SCHOOL DIST 299
SCHOOL ID NUMBER: 14-016-2990-2166
SCHOOL NAME: Doolittle East
ADDRESS OF SCHOOL: 535 E. 35th Street
CITY: Chicago, IL, 60616

DATE LAST THREE YEAR REINSPECTION WAS COMPLETED 2/25/2013

If the address on this form is different than the address of the building, submit a written explanation.

SECTION II (Please type or print)

PLEASE COMPLETE THE FOLLOWING FOR YOUR THREE YEAR REINSPECTION:

DATE REINSPECTION COMPLETED: 6/1/2016 ENROLLMENT 278
IDPH INSPECTOR LICENSE NUMBER: 100-10882
IDPH LICENSED INSPECTOR NAME (Please Print): Beinville Brooks
IDPH MP LICENSE NUMBER: 100-03613
IDPH LICENSED MANAGEMENT PLANNER NAME (Please Print): Daniel Juneau

DESIGNATED PERSON (Please Print): Robert Christlieb PHONE: (773) 553-3197



6/1/2016

Signature of Designated Person

Date

SECTION III

PLEASE COMPLETE THE FOLLOWING INFORMATION FOR ANY CHANGES WITHIN THE SCHOOL DISTRICT.

School building has been sold. Date of Sale: _____

School has been closed. Date closed: _____

School building has been demolished. Date: _____

School building is asbestos free since last reinspection: _____

Please explain in writing why the school building is now asbestos free and include the supporting documentation.

If a new school building has been added to the district, submit either an exclusionary statement or a management plan and inspection report. Include the complete name, address and city of school building.

Explain in writing if the address of the building is different than the address on this form:

THREE-YEAR REINSPECTION

CHICAGO SCHOOL DIST 299

Doolittle East

535 E. 35th Street
Chicago, IL, 60616

Unit: 22991
Building ID: 3070

IDPH ID Number: 14-016-2990-2166

REPORT DATE:

Wednesday, June 01, 2016

Prepared for:

Chicago Public Schools
125 S. Clark Street
Chicago, IL 60603

Prepared by:

Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone (312) 762-2900

Fax (312) 782-5145

**DO NOT REMOVE FROM SCHOOL
REQUIRED BY FEDERAL LAW**

April 5, 2016

Mr. R. Kent Cook
Asbestos Program
Illinois Department of Public Health
525 West Jefferson Street
Springfield, Illinois 62761

Re: Chicago Public Schools - 2016 Three-Year Reinspections

Dear Mr. Cook:

Carnow, Conibear and Associates, Managing Environmental Consultant (MEC), conducted the Three-Year Reinspections and performed management plan updates for the Chicago Public Schools (CPS) facilities in Region 3,4,5 Elementary Schools. Please update your records with the following information.

School District: 299 Unit: 66442 Region: 04 IDPH ID: 14-016-2990-2166

School: Doolittle East Building ID: 3070

Address: 535 E. 35th Street
Chicago, IL, 60616

Building Contact: Kennedy, Robert Contact Phone: 708-259-3137


Current Building Owners: Chicago Public Schools

Review Date: 06/01/2016

Inspector: Beinville Brooks Inspector IDPH License: 100-10882
Management Planner: Daniel Juneau Management Planner IDPH License: 100-03613

If you have any questions or comments, please contact us at (312) 762-2900

Sincerely,
Carnow, Conibear and Associates



Daniel Juneau
100-03613

Environmental Notification to Occupants

To: Faculty, Staff and Parents
From: Chicago Public Schools
Date: April 05, 2016

RE: Doolittle East, Unit 22991
535 E. 35th Street
Chicago, IL, 60616

Dear Faculty, Staff and Parents,

This letter is to notify you that the 2016 asbestos three year re-inspection has been completed at Doolittle East , following the Federal Asbestos Hazard Emergency Response Act (AHERA), 40 CFR Part 763, Subpart E and is available for your review at the main office of the school.

Although asbestos-containing materials have been identified at Doolittle East, there is no reason to believe that any threat to the health of students or staff exists at this time. CPS will continue to carefully monitor the condition of asbestos-containing materials and if conditions warrant, all appropriate steps will be taken to maintain the health and safety of all building occupants.

If you have any questions regarding this matter or require additional information, please feel free to contact Robert Christlieb, the designated Local Education Authority's Designated Person at (773) 553-3197 .

Table of Contents

- I. School and Inspection Information
- II. Executive Summary
- III. Methodology
- IV. Abatement History
- V. Reassessments and Recommendations
- VI. Conclusions

Table I: Inspector's Reinspection Findings

Table II: Management Planner's Review

APPENDICES:

- Appendix A: Assessment Sheets, Drawings and Photos
- Appendix B: Inspector and Management Planner Licenses
- Appendix C: Laboratory Accreditations
- Appendix D: Laboratory Results
- Appendix E: Chain of Custody Forms

II. EXECUTIVE SUMMARY

Carnow, Conibear and Associates was retained by the Chicago Public Schools (CPS) to perform a three-year asbestos reinspection of the Doolittle East. This inspection was conducted in accordance with the United States Environmental Protection Agency (USEPA) Asbestos Hazard Emergency Response Act (AHERA) part 763.92 (b), and the ongoing Operations and Maintenance Program (O&M) originally designed in the School's Asbestos Management Plan. The purpose of this three-year reinspection is to record any condition changes in the asbestos-containing building material (ACBM) in the school since the previous three-year reinspection and the six-month periodic surveillance, to identify, assess, and include any Homogeneous Areas (HA) not identified in the Management Plan, and to recommend an appropriate response action to manage asbestos.

The inspector conducted a three-year reinspection of this facility under Illinois Department of Public Health (IDPH) school reinspection requirements and AHERA, sections 763.85 and 763.88. The main building and each addition to the main building, if constructed at different dates, were inspected separately. Laboratory accreditations are included in Appendix C, laboratory results are included in Appendix D, and chain of custody forms are included in Appendix E.

Note: During previous inspections, some of the HA(s) were identified together as 9" x 9" floor tile (FT), mastics assoc. with 9" x 9" FT, 12" x 12" FT, mastics assoc. with 12" x 12" FT, pipe insulation, etc. Some of these HA(s) have been re-identified by areas that are uniform in color, texture, construction date, application date, and general appearance.

The inspector has determined the following:

A. The following HAs have changed assessment categories for Building 3070:

1	Plaster
26	Blue Patterned Carpet Mastic
43	12" x 12" Black w/ White Specks Floor Tile
44	Mastic Associated w/ 12" x 12" Black w/ White Specks Floor Tile
45	12" x 12" Tan w/ White Specks Floor Tile
46	Mastic Associated w/ 12" x 12" Tan w/ White Specks Floor Tile
47	12" x 12" Cream w/ White Specks Floor Tile
48	Mastic Associated w/ 12" x 12" Cream w/ White Specks Floor Tile

M

Gray Mud Packing

B. The following new homogenous areas have been identified for Building 3070:

- 43 12" x 12" Black w/ White Specks Floor Tile
- 44 Mastic Associated w/ 12" x 12" Black w/ White Specks Floor Tile
- 45 12" x 12" Tan w/ White Specks Floor Tile
- 46 Mastic Associated w/ 12" x 12" Tan w/ White Specks Floor Tile
- 47 12" x 12" Cream w/ White Specks Floor Tile
- 48 Mastic Associated w/ 12" x 12" Cream w/ White Specks Floor Tile

C. This reinspection covered only physically accessible and visible areas and materials that were identified in the LEA's management plan. The following materials were concealed and/or contained in areas that were inaccessible for sampling and have been classified as Assumed:

1	Plaster
20	Brown Carpet Mastic
21	Gray Carpet Mastic
23	Brown Mix Carpet
25	Orange Carpet Mastic
26	Blue Patterned Carpet Mastic
27	Vault Door Liner
34	90 de. Black Baseboard Metal Baseboard - Not Observed
35	90 de. Black Baseboard Adhesive ?metal baseboard - Not Observed
36	Free Standing Lab Tables - Not AHERA
37	12" x 12" Gray w/White & Black Specs Floor Tile
38	12" x 12" Gray w/White & Black Specs FT Mastic
39	Red Carpet Mastic
40	Blue/Gray/Wht Multi Color Ceramic Floor Tile Grout
41	12" x 12" Tan Mottle floor tile over existing HA 13/14
42	Mastic for 12" x 12" tan floor tile
43	12" x 12" Black w/ White Specks Floor Tile
44	Mastic Associated w/ 12" x 12" Black w/ White Specks Floor Tile
45	12" x 12" Tan w/ White Specks Floor Tile
46	Mastic Associated w/ 12" x 12" Tan w/ White Specks Floor Tile
47	12" x 12" Cream w/ White Specks Floor Tile
48	Mastic Associated w/ 12" x 12" Cream w/ White Specks Floor Tile
AA	12"x12" Floor tile tan w/ green specs
AA-1	12"x12" Floor tile tan w/ green specs mastic
AB	Baseboard
AB-1	Baseboard mastic
AC	Carpet Mastic
AD	Terrazo Flooring
AE	12'x12" Floor tile tan/green
AE-1	12"x12" Floor Tile Tan/Green Mastic
AF	Gerth Flooring Mastic
AG	Drywall
AH	Fire Doors
AI	Window Caulk

The following areas were deemed to be inaccessible:

11	12" x 12" Dark Brown Floor Tile Mastic
13	9" x 9" Wine Colored Floor Tile
20	Brown Carpet Mastic
26	Blue Patterned Carpet Mastic
27	Vault Door Liner
35	90 de. Black Baseboard Adhesive ?metal baseboard - Not Observed
38	12" x 12" Gray w/White & Black Specs FT Mastic
39	Red Carpet Mastic
42	Mastic for 12" x 12" tan floor tile
44	Mastic Associated w/ 12" x 12" Black w/ White Specks Floor Tile
46	Mastic Associated w/ 12" x 12" Tan w/ White Specks Floor Tile
48	Mastic Associated w/ 12" x 12" Cream w/ White Specks Floor Tile
9	12"x12" Gray Floor Tile w/Multi-Color Strks Mastic
AA-1	12"x12" Floor tile tan w/ green specs mastic
AB-1	Baseboard mastic
AC	Carpet Mastic
AE-1	12"x12" Floor Tile Tan/Green Mastic
AF	Gerth Flooring Mastic
AI	Window Caulk

Materials were also listed as "assumed" if they were in good condition and sampling was not conducted to avoid damage.

This reinspection was conducted by Beinville Brooks, IDPH License # 100-10882. The Management Plan was updated by Daniel Juneau, IDPH License # 100-03613. Inspector and Management Planner Licenses are included in Appendix B.

III. METHODOLOGY

Tasks performed on-site included the following:

1. Review current management plan, identify HA(s) and extract appropriate information.
2. Examine and verify abatement records.
3. Touch and visually and physically reinspect and reassess the condition of all friable known or assumed ACBM.
4. Touch and visually and physically reinspect all non-friable known or assumed ACBM to determine whether these materials have become friable since the last inspection or periodic surveillance.
5. Identify any condition changes that may affect Hazard Ranking of known ACBM or Assumed ACBM, as well as any HA(s) that have become friable since the last reinspection.
6. Collect bulk samples from each newly discovered friable HA or previously assumed and submit for laboratory analysis.
7. Tabulate reinspection findings and submit for management planner review and recommendations with appropriate response actions based on the AHERA Damage Category of the ACBM.
8. Submit reinspection findings and management planner recommendations to the LEA within thirty (30) days for inclusion into the management plan.

IV. ABATEMENT HISTORY

The information collected from the existing management plan and inspection report(s) and from interviews with the school official revealed that the following asbestos abatement was conducted at the school since the previous Three year Reinspection.

Abatement Dates:

V. REASSESSMENTS AND RECOMMENDATIONS

The reassessments and recommendations are summarized in Tables I and II on the following pages. Detailed Hazard Assessment Sheets and Drawings and Photos (if applicable) are included in Appendix A.

VI. CONCLUSIONS

The Doolittle East Building 3070 Three-Year reinspection has been completed and response actions have been recommended for both friable and non-friable materials. A timely execution of the response actions recommended will enable the LEA and the Designated Person(s) to effectively manage the existing ACBM.

This three-year reinspection report should be inspected in the current Management plan at the CPS Central Office, and one (1) copy should be kept at the school for use when planning any renovation and/or demolition activities in areas where ACBM has been identified. Also, periodic surveillance documentation and any summary reports from any response actions that are executed at the school should be used to update the Management Plan.

Table I
Inspector's Reinspection Findings

Chicago Public Schools

School Doolittle East Unit 66442 Building ID 3070

Address 535 E. 35th Street Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
31	4" Black Vinyl Baseboard Adhesive - Abated			Lunchroom	ABATED	MISC								
32	12" x 12" White Floor Tile w/ Gray Specks			Rooms 112, 310, 316, 110 - ABATED	ABATED	MISC								
33	12" x 12" White Floor Tile w/Gray Specks Mastic			Rooms 112, 310, 316, 110 - ABATED	ABATED	MISC								
34	90 de. Black Baseboard Metal Baseboard - Not Observed	100	LF	Large Gym	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
35	90 de. Black Baseboard Adhesive ?metal baseboard - Not Observed	100	LF	Large Gym	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
36	Free Standing Lab Tables - Not AHERA			Room 317 - Removed	ASSUMED	MISC								
37	12" x 12" Gray w/White & Black Specs Floor Tile	750	SF	Rooms 309	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
38	12" x 12" Gray w/White & Black Specs FT Mastic	750	SF	Room 309	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
39	Red Carpet Mastic	2,250	SF	Main Office and Principal's Office and Room 106	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
4	9" x 9" Multi-Colored Floor Tile			Room 110 - ABATED	ABATED	MISC								
40	Blue/Gray/Wht Multi Color Ceramic Floor Tile Grout	4,050	SF	Boys' and Girls' Washrooms on 1st,2nd,3rd Floors and Basement	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
41	12" x 12" Tan Mottle floor tile over existing HA 13/14	500	SF	Engineers office	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
42	Mastic for 12" x 12" tan floor tile	500	SF	Engineers office	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
43	12" x 12" Black w/ White Specks Floor Tile	860	SF	Room 306	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
44	Mastic Associated w/ 12" x 12" Black w/ White Specks Floor Tile	860	SF	Room 306	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
45	12" x 12" Tan w/ White Specks Floor Tile	3,422	SF	Rooms 200 and 310, Pre-K Cafeteria	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
46	Mastic Associated w/ 12" x 12" Tan w/ White Specks Floor Tile	3,422	SF	Rooms 200 and 310, Pre-K Cafeteria	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
47	12" x 12" Cream w/ White Specks Floor Tile	1,140	SF	Dance Hall/Small Gym	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
48	Mastic Associated w/ 12" x 12" Cream w/ White Specks Floor Tile	1,140	SF	Dance Hall/Small Gym	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
7	12" x 12" Dark Brown Floor Tile	2,250	SF	First, Second & Third Floor Corridors	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW

Chicago Public Schools

School Doolittle East Unit 66442 Building ID 3070

Address 535 E. 35th Street Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
8	9" x 9" Tan Floor Tile - ABATED 1999			Lunchroom & Small Gym	ABATED									
9	12"x12" Gray Floor Tile w/Multi-Color Strks Mastic	29,000	SF	See HA 3 - Abated	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
A	Insulation Jacketing & Wrap on Water Tank			Boiler Room	NO_ACBM	MISC								
AA	12"x12" Floor tile tan w/ green specs	16,936	SF	Lunchroom, Rm 112,116,118,210,212,216,218,301, 310, 312,317-319	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
AA-1	12"x12" Floor tile tan w/ green specs mastic	16,936	SF	Lunchroom, Rm 112,116,118,210,212,216,218,301, 310, 312,317-319	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
AB	Baseboard	300	LF	Lunchroom	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
AB-1	Baseboard mastic	300	LF	Lunchroom	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
AC	Carpet Mastic	3,200	SF	Library, Auditorium	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
AD	Terrazo Flooring	600	SF	Elevator, Ground Floor	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
AE	12"x12" Floor tile tan/green	1,300	SF	Elevator Area, 1st - 3rd Floor	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
AE-1	12"x12" Floor Tile Tan/Green Mastic	1,300	SF	Elevator, 1st-3rd Floor	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
AF	Gerth Flooring Mastic	6,500	SF	Rooms 205, 302, 303, 305, 310, 316	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
AG	Drywall	2,100	SF	Elevator Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
AH	Fire Doors	8	EA	Elevator Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
AI	Window Caulk	15,000	LF	Elevator Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
B	Insulation Jacketing & Wrap on Water Tank			Boiler Room	NO_ACBM	MISC								
F	Cementitious Insulation on Small Joints	100	LF	Wet Walls in Boy's Washrooms, Boiler Room, Janitor's Closets, Classroom 209	CHR	TSI	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
G	Air Cell Pipe Insulation	350	LF	Washrooms, Boiler Room, Auditorium, Room 209	CHR	TSI	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW

Chicago Public Schools

School Doolittle East Unit 66442 Building ID 3070

Address 535 E. 35th Street Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

Reinspection Date 4/5/2016
Inspector Name Beinvile Brooks
100-10882 5/15/2017
Inspector's IDPH License Number / Expiration Date

Inspector's Comments

HA Number:	Inspector Comments:
1	
10	
11	
12	
13	
14	
15	
16	
17	
18	
2	
20	
21	Not observed 2016
22	
23	Not a suspect material
24	
25	Not observed 2016
26	
27	
28	
29	
3	
30	
31	

Chicago Public Schools

School Doolittle East Unit 66442 Building ID 3070

Address 535 E. 35th Street Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
32	
33	
34	
35	
36	
37	
38	
39	
4	
40	
41	
42	
43	
44	
45	
46	
47	
48	
7	
8	
9	
A	
AA	
AA-1	
AB	
AB-1	
AC	
AD	
AE	

Chicago Public Schools

School Doolittle East Unit 66442 Building ID 3070

Address 535 E. 35th Street Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
AE-1	
AF	
AG	
AH	
AI	
B	
F	
G	
L	
M	
N	

Table II

Management Planner's Review

Chicago Public Schools

School Doolittle East
Address 535 E. 35th Street

Unit 66442
Chicago, IL, 60616

Building ID 3070
Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
1	Plaster	60,000	SF	Throughout Facility	Assumed	SURFACE	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
10	9" x 9" Multi-Colored Floor Tile Mastic			Room 110 - ABATED	Abated	MISC					
11	12" x 12" Dark Brown Floor Tile Mastic	2,250	SF	First, Second & Third Floor Corridors	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
12	9" x 9" Tan Floor Tile Mastic - ABATED 1999			Lunchroom & Small Gym	Abated						
13	9" x 9" Wine Colored Floor Tile	500	SF	Engineer's Office	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
14	9" x 9" Wine Colored Floor Tile Mastic			Engineer's Office	No ACBM						
15	Red Floor Tile - ABATED 1999			Lunchroom	Abated						
16	Red Floor Tile Mastic - ABATED 1999			Lunchroom	Abated						
17	Brick Mortar - not AHERA			Exterior of Building	No ACBM	MISC					
18	Window Sash Caulking	22	LF	1928 and 1944 Additions	Chrysotile	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
2	2' x 4' (Off) White Ceiling Panels			Office	No ACBM	MISC					
20	Brown Carpet Mastic	450	SF	Rooms 104	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
21	Gray Carpet Mastic			Room 106 Not Observed replaced with red carpet	Assumed	MISC					
22	Green Patterned Carpet Mastic - ABATED			Library	Abated	MISC					
23	Brown Mix Carpet			Office Replaced with red carpet	Assumed	MISC					
24	Purple Carpet Mastic - ABATED			Auditorium	Abated	MISC					
25	Orange Carpet Mastic			Rooms B-1 & B-2	Assumed	MISC					
26	Blue Patterned Carpet Mastic	750	SF	Principal's Office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
27	Vault Door Liner	32	SF	Office	Assumed	TSI	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
28	12" x 12" White Floor Tile w/Blue Specks			Lunchroom & Small Gym - ABATED	Abated	MISC					
29	12" x 12" White Floor Tile w/Blue Specks Mastic			Lunchroom & Small Gym - ABATED	Abated	MISC					
3	12" x 12" Gray Floor Tile w/Multi-Color Streaks	29,000	SF	Corridors, rooms B19,100-103,105,107,109,116,200-207,209,300-307,309	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
30	4" Black Vinyl Baseboard - Abated 2006			Lunchroom Not observed Paint	Abated	MISC					
31	4" Black Vinyl Baseboard Adhesive - Abated			Lunchroom	Abated	MISC					
32	12" x 12" White Floor Tile w/ Gray Specks			Rooms 112, 310, 316, 110 - ABATED	Abated	MISC					
33	12" x 12" White Floor Tile w/Gray Specks Mastic			Rooms 112, 310, 316, 110 - ABATED	Abated	MISC					
34	90 de. Black Baseboard Metal Baseboard - Not Observed	100	LF	Large Gym	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
35	90 de. Black Baseboard Adhesive ?metal baseboard - Not Observed	100	LF	Large Gym	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
36	Free Standing Lab Tables - Not AHERA			Room 317 - Removed	Assumed	MISC					

Chicago Public Schools

School Doolittle East
Address 535 E. 35th Street

Unit 66442
Chicago, IL, 60616

Building ID 3070
Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
37	12" x 12" Gray w/White & Black Specs Floor Tile	750	SF	Rooms 309	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
38	12" x 12" Gray w/White & Black Specs FT Mastic	750	SF	Room 309	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
39	Red Carpet Mastic	2,250	SF	Main Office and Principal's Office and Room 106	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
4	9" x 9" Multi-Colored Floor Tile			Room 110 - ABATED	Abated	MISC					
40	Blue/Gray/Wht Multi Color Ceramic Floor Tile Grout	4,050	SF	Boys' and Girls' Washrooms on 1st,2nd,3rd Floors and Basement	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
41	12" x 12" Tan Mottle floor tile over existing HA 13/14	500	SF	Engineers office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
42	Mastic for 12" x 12" tan floor tile	500	SF	Engineers office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
43	12" x 12" Black w/ White Specks Floor Tile	860	SF	Room 306	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
44	Mastic Associated w/ 12" x 12" Black w/ White Specks Floor Tile	860	SF	Room 306	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
45	12" x 12" Tan w/ White Specks Floor Tile	3,422	SF	Rooms 200 and 310, Pre-K Cafeteria	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
46	Mastic Associated w/ 12" x 12" Tan w/ White Specks Floor Tile	3,422	SF	Rooms 200 and 310, Pre-K Cafeteria	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
47	12" x 12" Cream w/ White Specks Floor Tile	1,140	SF	Dance Hall/Small Gym	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
48	Mastic Associated w/ 12" x 12" Cream w/ White Specks Floor Tile	1,140	SF	Dance Hall/Small Gym	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
7	12" x 12" Dark Brown Floor Tile	2,250	SF	First, Second & Third Floor Corridors	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
8	9" x 9" Tan Floor Tile - ABATED 1999			Lunchroom & Small Gym	Abated						
9	12"x12" Gray Floor Tile w/Multi-Color Strks Mastic	29,000	SF	See HA 3 - Abated	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
A	Insulation Jacketing & Wrap on Water Tank			Boiler Room	No ACBM	MISC					
AA	12"x12" Floor tile tan w/ green specs	16,936	SF	Lunchroom, Rm 112,116,118,210,212,216,218,301,310,312,317-319	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
AA-1	12"x12" Floor tile tan w/ green specs mastic	16,936	SF	Lunchroom, Rm 112,116,118,210,212,216,218,301,310,312,317-319	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
AB	Baseboard	300	LF	Lunchroom	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
AB-1	Baseboard mastic	300	LF	Lunchroom	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
AC	Carpet Mastic	3,200	SF	Library, Auditorium	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
AD	Terrazo Flooring	600	SF	Elevator, Ground Floor	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
AE	12"x12" Floor tile tan/green	1,300	SF	Elevator Area, 1st - 3rd Floor	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
AE-1	12"x12" Floor Tile Tan/Green Mastic	1,300	SF	Elevator, 1st-3rd Floor	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

Chicago Public Schools

School Doolittle East
Address 535 E. 35th Street

Unit 66442
 Chicago, IL, 60616

Building ID 3070
Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
AF	Gerth Flooring Mastic	6,500	SF	Rooms 205, 302, 303, 305, 310, 316	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
AG	Drywall	2,100	SF	Elevator Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
AH	Fire Doors	8	EA	Elevator Building	Assumed	MISC	No	0	EA	6 ACBM with the potential for damage	Follow O&M Plan
AI	Window Caulk	15,000	LF	Elevator Building	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
B	Insulation Jacketing & Wrap on Water Tank			Boiler Room	No ACBM	MISC					
F	Cementitious Insulation on Small Joints	100	LF	Wet Walls in Boy's Washrooms, Boiler Room, Janitor's Closets, Classroom 209	Chrysotile	TSI	Yes	0	LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
G	Air Cell Pipe Insulation	350	LF	Washrooms, Boiler Room, Auditorium, Room 209	Chrysotile	TSI	Yes	0	LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
L	Cementitious Joint Insulation- Large Gray Fittings	48	LF	Boiler Room, Janitor Closet, Basement	Chrysotile	TSI	Yes	20	LF	1 Damaged or significantly damaged friable thermal system insulating ACBM	Repair
M	Gray Mud Packing	10	SF	Engineer's Washroom- Surrounding Duct	Chrysotile	TSI	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
N	Cementitious Valve Insulation- Large Gray Fittings			Boiler Room - ABATED 1999	Abated						

Chicago Public Schools

School Doolittle East
Address 535 E. 35th Street

Unit 66442
 Chicago, IL, 60616

Building ID 3070
Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

Review Date	6/1/2016
Manager Planner Name	Daniel Juneau
100-03613	5/15/2016
Manager IDPH License No/Expiration	

HA Number	Management Comments
1	
10	
11	
12	
13	
14	
15	
16	
17	
18	
2	
20	
21	If identified, implement O&M
22	
23	
24	
25	If identified, implement O&M
26	
27	
28	
29	
3	

Chicago Public Schools

School Doolittle East
Address 535 E. 35th Street

Unit 66442
 Chicago, IL, 60616

Building ID 3070
Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates
 600 West Van Buren St., Ste 500
 Phone: (312) 762-2900 Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
30	
31	
32	
33	
34	
35	
36	
37	
38	
39	
4	
40	
41	
42	
43	
44	
45	
46	
47	
48	
7	
8	
9	
A	
AA	
AA-1	
AB	

Chicago Public Schools

School Doolittle East
Address 535 E. 35th Street

Unit 66442
 Chicago, IL, 60616

Building ID 3070
Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates
 600 West Van Buren St., Ste 500
 Phone: (312) 762-2900 Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
AB-1	
AC	
AD	
AE	
AE-1	
AF	
AG	
AH	
AI	
B	
F	
G	
L	Repair Localized Damage and Continue O&M
M	
N	

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66442** BUIDLING ID: **3070**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Beinville Brooks**
SCHOOL NAME: **Doolittle East** INSPECTION DATE: **4/5/2016**
ADDRESS: **535 E. 35th Street** IDPH LICENSE NO: **100-10882**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **1**
MATERIAL DESCRIPTION: **Plaster**
HISTORICAL AHERA DAMAGE CATEGORY **7**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT


This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Throughout Facility**
MATERIAL QUANTITY: **60000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____



Date: 04/05/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66442** BUIDLING ID: **3070**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Doolittle East** REVIEW DATE: **6/1/2016**
ADDRESS: **535 E. 35th Street** IDPH LICENSE NO: **100-10882**

HOMOGENEOUS AREA: **1**
MATERIAL DESCRIPTION: **Plaster**
MATERIAL LOCATION: **Throughout Facility**
MATERIAL QUANTITY: **60000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **06/01/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66442** BUIDLING ID: **3070**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Beinville Brooks**
SCHOOL NAME: **Doolittle East** INSPECTION DATE: **4/5/2016**
ADDRESS: **535 E. 35th Street** IDPH LICENSE NO: **100-10882**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **10**
MATERIAL DESCRIPTION: **9" x 9" Multi-Colored Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 110 - ABATED**

MATERIAL QUANTITY:


MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____



Date: **04/05/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66442** BUIDLING ID: **3070**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Doolittle East** REVIEW DATE: **6/1/2016**
ADDRESS: **535 E. 35th Street** IDPH LICENSE NO: **100-10882**

HOMOGENEOUS AREA: **10**

MATERIAL DESCRIPTION: **9" x 9" Multi-Colored Floor Tile Mastic**

MATERIAL LOCATION: **Room 110 - ABATED**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:


DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **06/01/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66442** BUIDLING ID: **3070**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Beinville Brooks**
SCHOOL NAME: **Doolittle East** INSPECTION DATE: **4/5/2016**
ADDRESS: **535 E. 35th Street** IDPH LICENSE NO: **100-10882**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **11**
MATERIAL DESCRIPTION: **12" x 12" Dark Brown Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **First, Second & Third Floor Corridors**

MATERIAL QUANTITY: **2250**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 04/05/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66442** BUIDLING ID: **3070**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Doolittle East** REVIEW DATE: **6/1/2016**
ADDRESS: **535 E. 35th Street** IDPH LICENSE NO: **100-10882**

HOMOGENEOUS AREA: **11**
MATERIAL DESCRIPTION: **12" x 12" Dark Brown Floor Tile Mastic**
MATERIAL LOCATION: **First, Second & Third Floor Corridors**
MATERIAL QUANTITY: **2250** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **06/01/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66442** BUIDLING ID: **3070**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Beinville Brooks**
SCHOOL NAME: **Doolittle East** INSPECTION DATE: **4/5/2016**
ADDRESS: **535 E. 35th Street** IDPH LICENSE NO: **100-10882**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **12**
MATERIAL DESCRIPTION: **9" x 9" Tan Floor Tile Mastic - ABATED 1999**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Lunchroom & Small Gym**

MATERIAL QUANTITY:


MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____



Date: 04/05/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66442** BUIDLING ID: **3070**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Doolittle East** REVIEW DATE: **6/1/2016**
ADDRESS: **535 E. 35th Street** IDPH LICENSE NO: **100-10882**

HOMOGENEOUS AREA: **12**
MATERIAL DESCRIPTION: **9" x 9" Tan Floor Tile Mastic - ABATED 1999**
MATERIAL LOCATION: **Lunchroom & Small Gym**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **06/01/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66442** BUIDLING ID: **3070**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Beinville Brooks**
SCHOOL NAME: **Doolittle East** INSPECTION DATE: **4/5/2016**
ADDRESS: **535 E. 35th Street** IDPH LICENSE NO: **100-10882**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **13**
MATERIAL DESCRIPTION: **9" x 9" Wine Colored Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.


The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Engineer's Office**
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 04/05/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66442** BUIDLING ID: **3070**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Doolittle East** REVIEW DATE: **6/1/2016**
ADDRESS: **535 E. 35th Street** IDPH LICENSE NO: **100-10882**

HOMOGENEOUS AREA: **13**
MATERIAL DESCRIPTION: **9" x 9" Wine Colored Floor Tile**
MATERIAL LOCATION: **Engineer's Office**
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **06/01/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66442** BUIDLING ID: **3070**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Beinville Brooks**
SCHOOL NAME: **Doolittle East** INSPECTION DATE: **4/5/2016**
ADDRESS: **535 E. 35th Street** IDPH LICENSE NO: **100-10882**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **14**
MATERIAL DESCRIPTION: **9" x 9" Wine Colored Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Engineer's Office**

MATERIAL QUANTITY:


MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **04/05/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66442** BUIDLING ID: **3070**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Doolittle East** REVIEW DATE: **6/1/2016**
ADDRESS: **535 E. 35th Street** IDPH LICENSE NO: **100-10882**

HOMOGENEOUS AREA: **14**

MATERIAL DESCRIPTION: **9" x 9" Wine Colored Floor Tile Mastic**

MATERIAL LOCATION: **Engineer's Office**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:


DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **06/01/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66442** BUIDLING ID: **3070**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Beinville Brooks**
SCHOOL NAME: **Doolittle East** INSPECTION DATE: **4/5/2016**
ADDRESS: **535 E. 35th Street** IDPH LICENSE NO: **100-10882**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **15**
MATERIAL DESCRIPTION: **Red Floor Tile - ABATED 1999**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Lunchroom**

MATERIAL QUANTITY:


MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **04/05/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66442** BUIDLING ID: **3070**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Doolittle East** REVIEW DATE: **6/1/2016**
ADDRESS: **535 E. 35th Street** IDPH LICENSE NO: **100-10882**

HOMOGENEOUS AREA: **15**

MATERIAL DESCRIPTION: **Red Floor Tile - ABATED 1999**

MATERIAL LOCATION: **Lunchroom**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:


DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **06/01/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66442** BUIDLING ID: **3070**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Beinville Brooks**
SCHOOL NAME: **Doolittle East** INSPECTION DATE: **4/5/2016**
ADDRESS: **535 E. 35th Street** IDPH LICENSE NO: **100-10882**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **16**
MATERIAL DESCRIPTION: **Red Floor Tile Mastic - ABATED 1999**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Lunchroom**

MATERIAL QUANTITY:


MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____



Date: **04/05/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66442** BUIDLING ID: **3070**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Doolittle East** REVIEW DATE: **6/1/2016**
ADDRESS: **535 E. 35th Street** IDPH LICENSE NO: **100-10882**

HOMOGENEOUS AREA: **16**

MATERIAL DESCRIPTION: **Red Floor Tile Mastic - ABATED 1999**

MATERIAL LOCATION: **Lunchroom**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **06/01/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66442** BUIDLING ID: **3070**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Beinville Brooks**
SCHOOL NAME: **Doolittle East** INSPECTION DATE: **4/5/2016**
ADDRESS: **535 E. 35th Street** IDPH LICENSE NO: **100-10882**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **17**
MATERIAL DESCRIPTION: **Brick Mortar - not AHERA**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Exterior of Building**

MATERIAL QUANTITY:


MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **04/05/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66442** BUIDLING ID: **3070**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Doolittle East** REVIEW DATE: **6/1/2016**
ADDRESS: **535 E. 35th Street** IDPH LICENSE NO: **100-10882**

HOMOGENEOUS AREA: **17**

MATERIAL DESCRIPTION: **Brick Mortar - not AHERA**

MATERIAL LOCATION: **Exterior of Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **06/01/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66442** BUIDLING ID: **3070**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Beinville Brooks**
SCHOOL NAME: **Doolittle East** INSPECTION DATE: **4/5/2016**
ADDRESS: **535 E. 35th Street** IDPH LICENSE NO: **100-10882**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **18**
MATERIAL DESCRIPTION: **Window Sash Caulking**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1928 and 1944 Additions**
MATERIAL QUANTITY: **22** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: DAMAGE UNITS: **LF**
COMMENTS:

Inspector's Signature: _____



Date: 04/05/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66442** BUIDLING ID: **3070**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Doolittle East** REVIEW DATE: **6/1/2016**
ADDRESS: **535 E. 35th Street** IDPH LICENSE NO: **100-10882**

HOMOGENEOUS AREA: **18**
MATERIAL DESCRIPTION: **Window Sash Caulking**
MATERIAL LOCATION: **1928 and 1944 Additions**
MATERIAL QUANTITY: **22** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **06/01/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66442** BUIDLING ID: **3070**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Beinville Brooks**
SCHOOL NAME: **Doolittle East** INSPECTION DATE: **4/5/2016**
ADDRESS: **535 E. 35th Street** IDPH LICENSE NO: **100-10882**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **2**
MATERIAL DESCRIPTION: **2' x 4' (Off) White Ceiling Panels**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Office**

MATERIAL QUANTITY:


MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **04/05/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66442** BUIDLING ID: **3070**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Doolittle East** REVIEW DATE: **6/1/2016**
ADDRESS: **535 E. 35th Street** IDPH LICENSE NO: **100-10882**

HOMOGENEOUS AREA: **2**

MATERIAL DESCRIPTION: **2' x 4' (Off) White Ceiling Panels**

MATERIAL LOCATION: **Office**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:


DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **06/01/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66442** BUIDLING ID: **3070**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Beinville Brooks**
SCHOOL NAME: **Doolittle East** INSPECTION DATE: **4/5/2016**
ADDRESS: **535 E. 35th Street** IDPH LICENSE NO: **100-10882**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **20**
MATERIAL DESCRIPTION: **Brown Carpet Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms 104**
MATERIAL QUANTITY: **450** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 04/05/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66442** BUIDLING ID: **3070**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Doolittle East** REVIEW DATE: **6/1/2016**
ADDRESS: **535 E. 35th Street** IDPH LICENSE NO: **100-10882**

HOMOGENEOUS AREA: **20**
MATERIAL DESCRIPTION: **Brown Carpet Mastic**
MATERIAL LOCATION: **Rooms 104**
MATERIAL QUANTITY: **450** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **06/01/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66442** BUIDLING ID: **3070**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Beinville Brooks**
SCHOOL NAME: **Doolittle East** INSPECTION DATE: **4/5/2016**
ADDRESS: **535 E. 35th Street** IDPH LICENSE NO: **100-10882**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **21**
MATERIAL DESCRIPTION: **Gray Carpet Mastic**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:


MATERIAL LOCATION: **Room 106 Not Observed replaced with red carpet**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Not observed 2016**

Inspector's Signature:



Date: **04/05/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66442** BUILDING ID: **3070**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Doolittle East** REVIEW DATE: **6/1/2016**
ADDRESS: **535 E. 35th Street** IDPH LICENSE NO: **100-10882**

HOMOGENEOUS AREA: **21**

MATERIAL DESCRIPTION: **Gray Carpet Mastic**

MATERIAL LOCATION: **Room 106 Not Observed replaced with red carpet**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

If identified, implement O&M

Management Planner's Signature: _____



Date: **06/01/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66442** BUIDLING ID: **3070**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Beinville Brooks**
SCHOOL NAME: **Doolittle East** INSPECTION DATE: **4/5/2016**
ADDRESS: **535 E. 35th Street** IDPH LICENSE NO: **100-10882**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **22**
MATERIAL DESCRIPTION: **Green Patterned Carpet Mastic - ABATED**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Library**

MATERIAL QUANTITY:


MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **04/05/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66442** BUIDLING ID: **3070**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Doolittle East** REVIEW DATE: **6/1/2016**
ADDRESS: **535 E. 35th Street** IDPH LICENSE NO: **100-10882**

HOMOGENEOUS AREA: **22**

MATERIAL DESCRIPTION: **Green Patterned Carpet Mastic - ABATED**

MATERIAL LOCATION: **Library**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:


DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **06/01/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66442** BUIDLING ID: **3070**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Beinville Brooks**
SCHOOL NAME: **Doolittle East** INSPECTION DATE: **4/5/2016**
ADDRESS: **535 E. 35th Street** IDPH LICENSE NO: **100-10882**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **23**
MATERIAL DESCRIPTION: **Brown Mix Carpet**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Office Replaced with red carpet**

MATERIAL QUANTITY:


MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not a suspect material**

Inspector's Signature:



Date: **04/05/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66442** BUIDLING ID: **3070**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Doolittle East** REVIEW DATE: **6/1/2016**
ADDRESS: **535 E. 35th Street** IDPH LICENSE NO: **100-10882**

HOMOGENEOUS AREA: **23**

MATERIAL DESCRIPTION: **Brown Mix Carpet**

MATERIAL LOCATION: **Office Replaced with red carpet**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:


DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **06/01/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66442** BUIDLING ID: **3070**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Beinville Brooks**
SCHOOL NAME: **Doolittle East** INSPECTION DATE: **4/5/2016**
ADDRESS: **535 E. 35th Street** IDPH LICENSE NO: **100-10882**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **24**
MATERIAL DESCRIPTION: **Purple Carpet Mastic - ABATED**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Auditorium**

MATERIAL QUANTITY:


MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____



Date: **04/05/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66442** BUIDLING ID: **3070**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Doolittle East** REVIEW DATE: **6/1/2016**
ADDRESS: **535 E. 35th Street** IDPH LICENSE NO: **100-10882**

HOMOGENEOUS AREA: **24**

MATERIAL DESCRIPTION: **Purple Carpet Mastic - ABATED**

MATERIAL LOCATION: **Auditorium**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **06/01/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66442** BUIDLING ID: **3070**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Beinville Brooks**
SCHOOL NAME: **Doolittle East** INSPECTION DATE: **4/5/2016**
ADDRESS: **535 E. 35th Street** IDPH LICENSE NO: **100-10882**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **25**
MATERIAL DESCRIPTION: **Orange Carpet Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Rooms B-1 & B-2**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed 2016**

Inspector's Signature: _____



Date: 04/05/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66442** BUIDLING ID: **3070**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Doolittle East** REVIEW DATE: **6/1/2016**
ADDRESS: **535 E. 35th Street** IDPH LICENSE NO: **100-10882**

HOMOGENEOUS AREA: **25**

MATERIAL DESCRIPTION: **Orange Carpet Mastic**

MATERIAL LOCATION: **Rooms B-1 & B-2**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

If identified, implement O&M

Management Planner's Signature: _____



Date: **06/01/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66442** BUIDLING ID: **3070**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Beinville Brooks**
SCHOOL NAME: **Doolittle East** INSPECTION DATE: **4/5/2016**
ADDRESS: **535 E. 35th Street** IDPH LICENSE NO: **100-10882**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **26**
MATERIAL DESCRIPTION: **Blue Patterned Carpet Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Principal's Office**
MATERIAL QUANTITY: **750** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 04/05/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66442** BUIDLING ID: **3070**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Doolittle East** REVIEW DATE: **6/1/2016**
ADDRESS: **535 E. 35th Street** IDPH LICENSE NO: **100-10882**

HOMOGENEOUS AREA: **26**

MATERIAL DESCRIPTION: **Blue Patterned Carpet Mastic**

MATERIAL LOCATION: **Principal's Office**

MATERIAL QUANTITY: **750**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **06/01/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66442** BUIDLING ID: **3070**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Beinville Brooks**
SCHOOL NAME: **Doolittle East** INSPECTION DATE: **4/5/2016**
ADDRESS: **535 E. 35th Street** IDPH LICENSE NO: **100-10882**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **27**
MATERIAL DESCRIPTION: **Vault Door Liner**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Office**
MATERIAL QUANTITY: **32** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 04/05/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66442** BUIDLING ID: **3070**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Doolittle East** REVIEW DATE: **6/1/2016**
ADDRESS: **535 E. 35th Street** IDPH LICENSE NO: **100-10882**

HOMOGENEOUS AREA: **27**

MATERIAL DESCRIPTION: **Vault Door Liner**

MATERIAL LOCATION: **Office**

MATERIAL QUANTITY: **32**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **06/01/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66442** BUIDLING ID: **3070**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Beinville Brooks**
SCHOOL NAME: **Doolittle East** INSPECTION DATE: **4/5/2016**
ADDRESS: **535 E. 35th Street** IDPH LICENSE NO: **100-10882**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **28**
MATERIAL DESCRIPTION: **12" x 12" White Floor Tile w/Blue Specks**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Lunchroom & Small Gym - ABATED**

MATERIAL QUANTITY:


MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **04/05/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66442** BUIDLING ID: **3070**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Doolittle East** REVIEW DATE: **6/1/2016**
ADDRESS: **535 E. 35th Street** IDPH LICENSE NO: **100-10882**

HOMOGENEOUS AREA: **28**

MATERIAL DESCRIPTION: **12" x 12" White Floor Tile w/Blue Specks**

MATERIAL LOCATION: **Lunchroom & Small Gym - ABATED**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **06/01/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66442** BUIDLING ID: **3070**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Beinville Brooks**
SCHOOL NAME: **Doolittle East** INSPECTION DATE: **4/5/2016**
ADDRESS: **535 E. 35th Street** IDPH LICENSE NO: **100-10882**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **29**
MATERIAL DESCRIPTION: **12" x 12" White Floor Tile w/Blue Specks Mastic**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:


MATERIAL LOCATION: **Lunchroom & Small Gym - ABATED**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **04/05/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66442** BUIDLING ID: **3070**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Doolittle East** REVIEW DATE: **6/1/2016**
ADDRESS: **535 E. 35th Street** IDPH LICENSE NO: **100-10882**

HOMOGENEOUS AREA: **29**

MATERIAL DESCRIPTION: **12" x 12" White Floor Tile w/Blue Specks Mastic**

MATERIAL LOCATION: **Lunchroom & Small Gym - ABATED**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **06/01/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66442** BUIDLING ID: **3070**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Beinville Brooks**
SCHOOL NAME: **Doolittle East** INSPECTION DATE: **4/5/2016**
ADDRESS: **535 E. 35th Street** IDPH LICENSE NO: **100-10882**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **3**
MATERIAL DESCRIPTION: **12" x 12" Gray Floor Tile w/Multi-Color Streaks**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Corridors, rooms B19,100-103,105,107,109,116,200-207,209,300-307,309**
MATERIAL QUANTITY: **29000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 04/05/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66442** BUIDLING ID: **3070**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Doolittle East** REVIEW DATE: **6/1/2016**
ADDRESS: **535 E. 35th Street** IDPH LICENSE NO: **100-10882**

HOMOGENEOUS AREA: **3**
MATERIAL DESCRIPTION: **12" x 12" Gray Floor Tile w/Multi-Color Streaks**
MATERIAL LOCATION: **Corridors, rooms B19,100-103,105,107,109,116,200-207,209,300-307,309**
MATERIAL QUANTITY: **29000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **06/01/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66442** BUIDLING ID: **3070**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Beinville Brooks**
SCHOOL NAME: **Doolittle East** INSPECTION DATE: **4/5/2016**
ADDRESS: **535 E. 35th Street** IDPH LICENSE NO: **100-10882**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **30**
MATERIAL DESCRIPTION: **4" Black Vinyl Baseboard - Abated 2006**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Lunchroom Not observed Paint**

MATERIAL QUANTITY:


MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **04/05/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66442** BUIDLING ID: **3070**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Doolittle East** REVIEW DATE: **6/1/2016**
ADDRESS: **535 E. 35th Street** IDPH LICENSE NO: **100-10882**

HOMOGENEOUS AREA: **30**

MATERIAL DESCRIPTION: **4" Black Vinyl Baseboard - Abated 2006**

MATERIAL LOCATION: **Lunchroom Not observed Paint**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:


DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **06/01/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66442** BUIDLING ID: **3070**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Beinville Brooks**
SCHOOL NAME: **Doolittle East** INSPECTION DATE: **4/5/2016**
ADDRESS: **535 E. 35th Street** IDPH LICENSE NO: **100-10882**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **31**
MATERIAL DESCRIPTION: **4" Black Vinyl Baseboard Adhesive - Abated**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Lunchroom**

MATERIAL QUANTITY:


MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____



Date: **04/05/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66442** BUIDLING ID: **3070**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Doolittle East** REVIEW DATE: **6/1/2016**
ADDRESS: **535 E. 35th Street** IDPH LICENSE NO: **100-10882**

HOMOGENEOUS AREA: **31**

MATERIAL DESCRIPTION: **4" Black Vinyl Baseboard Adhesive - Abated**

MATERIAL LOCATION: **Lunchroom**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **06/01/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66442** BUIDLING ID: **3070**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Beinville Brooks**
SCHOOL NAME: **Doolittle East** INSPECTION DATE: **4/5/2016**
ADDRESS: **535 E. 35th Street** IDPH LICENSE NO: **100-10882**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **32**
MATERIAL DESCRIPTION: **12" x 12" White Floor Tile w/ Gray Specks**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Rooms 112, 310, 316, 110 - ABATED**

MATERIAL QUANTITY:


MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____



Date: **04/05/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66442** BUIDLING ID: **3070**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Doolittle East** REVIEW DATE: **6/1/2016**
ADDRESS: **535 E. 35th Street** IDPH LICENSE NO: **100-10882**

HOMOGENEOUS AREA: **32**

MATERIAL DESCRIPTION: **12" x 12" White Floor Tile w/ Gray Specks**

MATERIAL LOCATION: **Rooms 112, 310, 316, 110 - ABATED**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **06/01/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66442** BUIDLING ID: **3070**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Beinville Brooks**
SCHOOL NAME: **Doolittle East** INSPECTION DATE: **4/5/2016**
ADDRESS: **535 E. 35th Street** IDPH LICENSE NO: **100-10882**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **33**
MATERIAL DESCRIPTION: **12" x 12" White Floor Tile w/Gray Specks Mastic**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Rooms 112, 310, 316, 110 - ABATED**

MATERIAL QUANTITY:


MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **04/05/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66442** BUIDLING ID: **3070**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Doolittle East** REVIEW DATE: **6/1/2016**
ADDRESS: **535 E. 35th Street** IDPH LICENSE NO: **100-10882**

HOMOGENEOUS AREA: **33**

MATERIAL DESCRIPTION: **12" x 12" White Floor Tile w/Gray Specks Mastic**

MATERIAL LOCATION: **Rooms 112, 310, 316, 110 - ABATED**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:


DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **06/01/2016**

Chicago Public Schools

Carnow, Conibear and Associates 2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66442** BUIDLING ID: **3070**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Beinville Brooks**
SCHOOL NAME: **Doolittle East** INSPECTION DATE: **4/5/2016**
ADDRESS: **535 E. 35th Street** IDPH LICENSE NO: **100-10882**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **34**
MATERIAL DESCRIPTION: **90 de. Black Baseboard Metal Baseboard - Not Observed**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Large Gym**

MATERIAL QUANTITY: **100**

MATERIAL UNITS: **LF**

DAMAGE QUANTITY:

DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: _____



Date: 04/05/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66442** BUIDLING ID: **3070**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Doolittle East** REVIEW DATE: **6/1/2016**
ADDRESS: **535 E. 35th Street** IDPH LICENSE NO: **100-10882**

HOMOGENEOUS AREA: **34**
MATERIAL DESCRIPTION: **90 de. Black Baseboard Metal Baseboard - Not Observed**
MATERIAL LOCATION: **Large Gym**
MATERIAL QUANTITY: **100** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **06/01/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66442** BUIDLING ID: **3070**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Beinville Brooks**
SCHOOL NAME: **Doolittle East** INSPECTION DATE: **4/5/2016**
ADDRESS: **535 E. 35th Street** IDPH LICENSE NO: **100-10882**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **35**
MATERIAL DESCRIPTION: **90 de. Black Baseboard Adhesive ?metal baseboard - Not Observed**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Large Gym**

MATERIAL QUANTITY: **100**

MATERIAL UNITS: **LF**

DAMAGE QUANTITY:

DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: _____



Date: 04/05/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66442** BUIDLING ID: **3070**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Doolittle East** REVIEW DATE: **6/1/2016**
ADDRESS: **535 E. 35th Street** IDPH LICENSE NO: **100-10882**

HOMOGENEOUS AREA: **35**
MATERIAL DESCRIPTION: **90 de. Black Baseboard Adhesive ?metal baseboard - Not Observed**
MATERIAL LOCATION: **Large Gym**
MATERIAL QUANTITY: **100** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **06/01/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66442** BUIDLING ID: **3070**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Beinvile Brooks**
SCHOOL NAME: **Doolittle East** INSPECTION DATE: **4/5/2016**
ADDRESS: **535 E. 35th Street** IDPH LICENSE NO: **100-10882**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **36**
MATERIAL DESCRIPTION: **Free Standing Lab Tables - Not AHERA**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 317 - Removed**

MATERIAL QUANTITY:


MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **04/05/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66442** BUIDLING ID: **3070**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Doolittle East** REVIEW DATE: **6/1/2016**
ADDRESS: **535 E. 35th Street** IDPH LICENSE NO: **100-10882**

HOMOGENEOUS AREA: **36**

MATERIAL DESCRIPTION: **Free Standing Lab Tables - Not AHERA**

MATERIAL LOCATION: **Room 317 - Removed**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **06/01/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66442** BUIDLING ID: **3070**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Beinville Brooks**
SCHOOL NAME: **Doolittle East** INSPECTION DATE: **4/5/2016**
ADDRESS: **535 E. 35th Street** IDPH LICENSE NO: **100-10882**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **37**
MATERIAL DESCRIPTION: **12" x 12" Gray w/White & Black Specs Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms 309**
MATERIAL QUANTITY: **750** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 04/05/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66442** BUIDLING ID: **3070**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Doolittle East** REVIEW DATE: **6/1/2016**
ADDRESS: **535 E. 35th Street** IDPH LICENSE NO: **100-10882**

HOMOGENEOUS AREA: **37**
MATERIAL DESCRIPTION: **12" x 12" Gray w/White & Black Specs Floor Tile**
MATERIAL LOCATION: **Rooms 309**
MATERIAL QUANTITY: **750** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **06/01/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66442** BUIDLING ID: **3070**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Beinville Brooks**
SCHOOL NAME: **Doolittle East** INSPECTION DATE: **4/5/2016**
ADDRESS: **535 E. 35th Street** IDPH LICENSE NO: **100-10882**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **38**
MATERIAL DESCRIPTION: **12" x 12" Gray w/White & Black Specs FT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 309**
MATERIAL QUANTITY: **750** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 04/05/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66442** BUIDLING ID: **3070**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Doolittle East** REVIEW DATE: **6/1/2016**
ADDRESS: **535 E. 35th Street** IDPH LICENSE NO: **100-10882**

HOMOGENEOUS AREA: **38**
MATERIAL DESCRIPTION: **12" x 12" Gray w/White & Black Specs FT Mastic**
MATERIAL LOCATION: **Room 309**
MATERIAL QUANTITY: **750** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **06/01/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66442** BUIDLING ID: **3070**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Beinville Brooks**
SCHOOL NAME: **Doolittle East** INSPECTION DATE: **4/5/2016**
ADDRESS: **535 E. 35th Street** IDPH LICENSE NO: **100-10882**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **39**
MATERIAL DESCRIPTION: **Red Carpet Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Main Office and Principal's Office and Room 106**
MATERIAL QUANTITY: **2250** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 04/05/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66442** BUIDLING ID: **3070**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Doolittle East** REVIEW DATE: **6/1/2016**
ADDRESS: **535 E. 35th Street** IDPH LICENSE NO: **100-10882**

HOMOGENEOUS AREA: **39**
MATERIAL DESCRIPTION: **Red Carpet Mastic**
MATERIAL LOCATION: **Main Office and Principal's Office and Room 106**
MATERIAL QUANTITY: **2250** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **06/01/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66442** BUIDLING ID: **3070**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Beinville Brooks**
SCHOOL NAME: **Doolittle East** INSPECTION DATE: **4/5/2016**
ADDRESS: **535 E. 35th Street** IDPH LICENSE NO: **100-10882**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **4**
MATERIAL DESCRIPTION: **9" x 9" Multi-Colored Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 110 - ABATED**

MATERIAL QUANTITY:


MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **04/05/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66442** BUIDLING ID: **3070**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Doolittle East** REVIEW DATE: **6/1/2016**
ADDRESS: **535 E. 35th Street** IDPH LICENSE NO: **100-10882**

HOMOGENEOUS AREA: **4**

MATERIAL DESCRIPTION: **9" x 9" Multi-Colored Floor Tile**

MATERIAL LOCATION: **Room 110 - ABATED**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **06/01/2016**

Chicago Public Schools

Carnow, Conibear and Associates 2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66442** BUIDLING ID: **3070**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Beinville Brooks**
SCHOOL NAME: **Doolittle East** INSPECTION DATE: **4/5/2016**
ADDRESS: **535 E. 35th Street** IDPH LICENSE NO: **100-10882**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **40**
MATERIAL DESCRIPTION: **Blue/Gray/Wht Multi Color Ceramic Floor Tile Grout**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Boys' and Girls' Washrooms on 1st,2nd,3rd Floors and Basement**
MATERIAL QUANTITY: **4050** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 04/05/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66442** BUIDLING ID: **3070**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Doolittle East** REVIEW DATE: **6/1/2016**
ADDRESS: **535 E. 35th Street** IDPH LICENSE NO: **100-10882**

HOMOGENEOUS AREA: **40**
MATERIAL DESCRIPTION: **Blue/Gray/Wht Multi Color Ceramic Floor Tile Grout**
MATERIAL LOCATION: **Boys' and Girls' Washrooms on 1st,2nd,3rd Floors and Basement**
MATERIAL QUANTITY: **4050** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **06/01/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66442** BUIDLING ID: **3070**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Beinville Brooks**
SCHOOL NAME: **Doolittle East** INSPECTION DATE: **4/5/2016**
ADDRESS: **535 E. 35th Street** IDPH LICENSE NO: **100-10882**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **41**
MATERIAL DESCRIPTION: **12" x 12" Tan Mottle floor tile over existing HA 13/14**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Engineers office**
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 04/05/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66442** BUIDLING ID: **3070**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Doolittle East** REVIEW DATE: **6/1/2016**
ADDRESS: **535 E. 35th Street** IDPH LICENSE NO: **100-10882**

HOMOGENEOUS AREA: **41**

MATERIAL DESCRIPTION: **12" x 12" Tan Mottle floor tile over existing HA 13/14**

MATERIAL LOCATION: **Engineers office**

MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **06/01/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66442** BUIDLING ID: **3070**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Beinville Brooks**
SCHOOL NAME: **Doolittle East** INSPECTION DATE: **4/5/2016**
ADDRESS: **535 E. 35th Street** IDPH LICENSE NO: **100-10882**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **42**
MATERIAL DESCRIPTION: **Mastic for 12" x 12" tan floor tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Engineers office**
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 04/05/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66442** BUIDLING ID: **3070**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Doolittle East** REVIEW DATE: **6/1/2016**
ADDRESS: **535 E. 35th Street** IDPH LICENSE NO: **100-10882**

HOMOGENEOUS AREA: **42**
MATERIAL DESCRIPTION: **Mastic for 12" x 12" tan floor tile**
MATERIAL LOCATION: **Engineers office**
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **06/01/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66442** BUIDLING ID: **3070**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Beinville Brooks**
SCHOOL NAME: **Doolittle East** INSPECTION DATE: **4/5/2016**
ADDRESS: **535 E. 35th Street** IDPH LICENSE NO: **100-10882**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **7**
MATERIAL DESCRIPTION: **12" x 12" Dark Brown Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **First, Second & Third Floor Corridors**

MATERIAL QUANTITY: **2250**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 04/05/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66442** BUIDLING ID: **3070**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Doolittle East** REVIEW DATE: **6/1/2016**
ADDRESS: **535 E. 35th Street** IDPH LICENSE NO: **100-10882**

HOMOGENEOUS AREA: **7**
MATERIAL DESCRIPTION: **12" x 12" Dark Brown Floor Tile**
MATERIAL LOCATION: **First, Second & Third Floor Corridors**
MATERIAL QUANTITY: **2250** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **06/01/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66442** BUIDLING ID: **3070**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Beinville Brooks**
SCHOOL NAME: **Doolittle East** INSPECTION DATE: **4/5/2016**
ADDRESS: **535 E. 35th Street** IDPH LICENSE NO: **100-10882**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **8**
MATERIAL DESCRIPTION: **9" x 9" Tan Floor Tile - ABATED 1999**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Lunchroom & Small Gym**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **04/05/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66442** BUIDLING ID: **3070**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Doolittle East** REVIEW DATE: **6/1/2016**
ADDRESS: **535 E. 35th Street** IDPH LICENSE NO: **100-10882**

HOMOGENEOUS AREA: **8**

MATERIAL DESCRIPTION: **9" x 9" Tan Floor Tile - ABATED 1999**

MATERIAL LOCATION: **Lunchroom & Small Gym**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:


DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **06/01/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66442** BUIDLING ID: **3070**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Beinville Brooks**
SCHOOL NAME: **Doolittle East** INSPECTION DATE: **4/5/2016**
ADDRESS: **535 E. 35th Street** IDPH LICENSE NO: **100-10882**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **9**
MATERIAL DESCRIPTION: **12"x12" Gray Floor Tile w/Multi-Color Strks Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **See HA 3 - Abated**
MATERIAL QUANTITY: **29000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 04/05/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66442** BUIDLING ID: **3070**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Doolittle East** REVIEW DATE: **6/1/2016**
ADDRESS: **535 E. 35th Street** IDPH LICENSE NO: **100-10882**

HOMOGENEOUS AREA: **9**
MATERIAL DESCRIPTION: **12"x12" Gray Floor Tile w/Multi-Color Strks Mastic**
MATERIAL LOCATION: **See HA 3 - Abated**
MATERIAL QUANTITY: **29000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **06/01/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66442** BUIDLING ID: **3070**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Beinville Brooks**
SCHOOL NAME: **Doolittle East** INSPECTION DATE: **4/5/2016**
ADDRESS: **535 E. 35th Street** IDPH LICENSE NO: **100-10882**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **A**
MATERIAL DESCRIPTION: **Insulation Jacketing & Wrap on Water Tank**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____



Date: **04/05/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66442** BUIDLING ID: **3070**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Doolittle East** REVIEW DATE: **6/1/2016**
ADDRESS: **535 E. 35th Street** IDPH LICENSE NO: **100-10882**

HOMOGENEOUS AREA: **A**

MATERIAL DESCRIPTION: **Insulation Jacketing & Wrap on Water Tank**

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **06/01/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66442** BUIDLING ID: **3070**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Beinville Brooks**
SCHOOL NAME: **Doolittle East** INSPECTION DATE: **4/5/2016**
ADDRESS: **535 E. 35th Street** IDPH LICENSE NO: **100-10882**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **AA**
MATERIAL DESCRIPTION: **12"x12" Floor tile tan w/ green specs**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Lunchroom, Rm 112,116,118,210,212,216,218,301, 310, 312,317-319**
MATERIAL QUANTITY: **16936** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 04/05/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66442** BUIDLING ID: **3070**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Doolittle East** REVIEW DATE: **6/1/2016**
ADDRESS: **535 E. 35th Street** IDPH LICENSE NO: **100-10882**

HOMOGENEOUS AREA: **AA**
MATERIAL DESCRIPTION: **12"x12" Floor tile tan w/ green specs**
MATERIAL LOCATION: **Lunchroom, Rm 112,116,118,210,212,216,218,301, 310, 312,317-319**
MATERIAL QUANTITY: **16936** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **06/01/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66442** BUIDLING ID: **3070**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Beinville Brooks**
SCHOOL NAME: **Doolittle East** INSPECTION DATE: **4/5/2016**
ADDRESS: **535 E. 35th Street** IDPH LICENSE NO: **100-10882**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **AA-1**
MATERIAL DESCRIPTION: **12"x12" Floor tile tan w/ green specs mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Lunchroom, Rm 112,116,118,210,212,216,218,301, 310, 312,317-319**
MATERIAL QUANTITY: **16936** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 04/05/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66442** BUIDLING ID: **3070**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Doolittle East** REVIEW DATE: **6/1/2016**
ADDRESS: **535 E. 35th Street** IDPH LICENSE NO: **100-10882**

HOMOGENEOUS AREA: **AA-1**
MATERIAL DESCRIPTION: **12"x12" Floor tile tan w/ green specs mastic**
MATERIAL LOCATION: **Lunchroom, Rm 112,116,118,210,212,216,218,301, 310, 312,317-319**
MATERIAL QUANTITY: **16936** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **06/01/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66442** BUIDLING ID: **3070**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Beinville Brooks**
SCHOOL NAME: **Doolittle East** INSPECTION DATE: **4/5/2016**
ADDRESS: **535 E. 35th Street** IDPH LICENSE NO: **100-10882**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **AB**
MATERIAL DESCRIPTION: **Baseboard**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Lunchroom**
MATERIAL QUANTITY: **300** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: _____



Date: 04/05/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66442** BUIDLING ID: **3070**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Doolittle East** REVIEW DATE: **6/1/2016**
ADDRESS: **535 E. 35th Street** IDPH LICENSE NO: **100-10882**

HOMOGENEOUS AREA: **AB**
MATERIAL DESCRIPTION: **Baseboard**
MATERIAL LOCATION: **Lunchroom**
MATERIAL QUANTITY: **300** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **06/01/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66442** BUIDLING ID: **3070**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Beinville Brooks**
SCHOOL NAME: **Doolittle East** INSPECTION DATE: **4/5/2016**
ADDRESS: **535 E. 35th Street** IDPH LICENSE NO: **100-10882**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **AB-1**
MATERIAL DESCRIPTION: **Baseboard mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Lunchroom**

MATERIAL QUANTITY: **300**

MATERIAL UNITS: **LF**

DAMAGE QUANTITY:

DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: _____



Date: 04/05/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66442** BUIDLING ID: **3070**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Doolittle East** REVIEW DATE: **6/1/2016**
ADDRESS: **535 E. 35th Street** IDPH LICENSE NO: **100-10882**

HOMOGENEOUS AREA: **AB-1**
MATERIAL DESCRIPTION: **Baseboard mastic**
MATERIAL LOCATION: **Lunchroom**
MATERIAL QUANTITY: **300** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **06/01/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66442** BUIDLING ID: **3070**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Beinville Brooks**
SCHOOL NAME: **Doolittle East** INSPECTION DATE: **4/5/2016**
ADDRESS: **535 E. 35th Street** IDPH LICENSE NO: **100-10882**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **AC**
MATERIAL DESCRIPTION: **Carpet Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Library, Auditorium**
MATERIAL QUANTITY: **3200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 04/05/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66442** BUIDLING ID: **3070**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Doolittle East** REVIEW DATE: **6/1/2016**
ADDRESS: **535 E. 35th Street** IDPH LICENSE NO: **100-10882**

HOMOGENEOUS AREA: **AC**
MATERIAL DESCRIPTION: **Carpet Mastic**
MATERIAL LOCATION: **Library, Auditorium**
MATERIAL QUANTITY: **3200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **06/01/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66442** BUIDLING ID: **3070**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Beinville Brooks**
SCHOOL NAME: **Doolittle East** INSPECTION DATE: **4/5/2016**
ADDRESS: **535 E. 35th Street** IDPH LICENSE NO: **100-10882**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **AD**
MATERIAL DESCRIPTION: **Terrazo Flooring**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Elevator, Ground Floor**
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 04/05/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66442** BUILDING ID: **3070**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Doolittle East** REVIEW DATE: **6/1/2016**
ADDRESS: **535 E. 35th Street** IDPH LICENSE NO: **100-10882**

HOMOGENEOUS AREA: **AD**
MATERIAL DESCRIPTION: **Terrazo Flooring**
MATERIAL LOCATION: **Elevator, Ground Floor**
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **06/01/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66442** BUIDLING ID: **3070**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Beinville Brooks**
SCHOOL NAME: **Doolittle East** INSPECTION DATE: **4/5/2016**
ADDRESS: **535 E. 35th Street** IDPH LICENSE NO: **100-10882**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **AE**
MATERIAL DESCRIPTION: **12'x12" Floor tile tan/green**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Elevator Area, 1st - 3rd Floor**
MATERIAL QUANTITY: **1300** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 04/05/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66442** BUIDLING ID: **3070**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Doolittle East** REVIEW DATE: **6/1/2016**
ADDRESS: **535 E. 35th Street** IDPH LICENSE NO: **100-10882**

HOMOGENEOUS AREA: **AE**
MATERIAL DESCRIPTION: **12'x12" Floor tile tan/green**
MATERIAL LOCATION: **Elevator Area, 1st - 3rd Floor**
MATERIAL QUANTITY: **1300** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **06/01/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66442** BUIDLING ID: **3070**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Beinville Brooks**
SCHOOL NAME: **Doolittle East** INSPECTION DATE: **4/5/2016**
ADDRESS: **535 E. 35th Street** IDPH LICENSE NO: **100-10882**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **AE-1**
MATERIAL DESCRIPTION: **12"x12" Floor Tile Tan/Green Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Elevator, 1st-3rd Floor**
MATERIAL QUANTITY: **1300** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 04/05/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66442** BUIDLING ID: **3070**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Doolittle East** REVIEW DATE: **6/1/2016**
ADDRESS: **535 E. 35th Street** IDPH LICENSE NO: **100-10882**

HOMOGENEOUS AREA: **AE-1**
MATERIAL DESCRIPTION: **12"x12" Floor Tile Tan/Green Mastic**
MATERIAL LOCATION: **Elevator, 1st-3rd Floor**
MATERIAL QUANTITY: **1300** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **06/01/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66442** BUIDLING ID: **3070**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Beinville Brooks**
SCHOOL NAME: **Doolittle East** INSPECTION DATE: **4/5/2016**
ADDRESS: **535 E. 35th Street** IDPH LICENSE NO: **100-10882**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **AF**
MATERIAL DESCRIPTION: **Gerth Flooring Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Rooms 205, 302, 303, 305, 310, 316**

MATERIAL QUANTITY: **6500**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 04/05/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66442** BUIDLING ID: **3070**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Doolittle East** REVIEW DATE: **6/1/2016**
ADDRESS: **535 E. 35th Street** IDPH LICENSE NO: **100-10882**

HOMOGENEOUS AREA: **AF**
MATERIAL DESCRIPTION: **Gerth Flooring Mastic**
MATERIAL LOCATION: **Rooms 205, 302, 303, 305, 310, 316**
MATERIAL QUANTITY: **6500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **06/01/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66442** BUIDLING ID: **3070**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Beinville Brooks**
SCHOOL NAME: **Doolittle East** INSPECTION DATE: **4/5/2016**
ADDRESS: **535 E. 35th Street** IDPH LICENSE NO: **100-10882**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **AG**
MATERIAL DESCRIPTION: **Drywall**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Elevator Building**
MATERIAL QUANTITY: **2100** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 04/05/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66442** BUIDLING ID: **3070**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Doolittle East** REVIEW DATE: **6/1/2016**
ADDRESS: **535 E. 35th Street** IDPH LICENSE NO: **100-10882**

HOMOGENEOUS AREA: **AG**
MATERIAL DESCRIPTION: **Drywall**
MATERIAL LOCATION: **Elevator Building**
MATERIAL QUANTITY: **2100** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **06/01/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66442** BUIDLING ID: **3070**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Beinville Brooks**
SCHOOL NAME: **Doolittle East** INSPECTION DATE: **4/5/2016**
ADDRESS: **535 E. 35th Street** IDPH LICENSE NO: **100-10882**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **AH**
MATERIAL DESCRIPTION: **Fire Doors**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Elevator Building**
MATERIAL QUANTITY: **8** MATERIAL UNITS: **EA**
DAMAGE QUANTITY: DAMAGE UNITS: **EA**

COMMENTS:

Inspector's Signature: _____



Date: 04/05/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66442** BUIDLING ID: **3070**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Doolittle East** REVIEW DATE: **6/1/2016**
ADDRESS: **535 E. 35th Street** IDPH LICENSE NO: **100-10882**

HOMOGENEOUS AREA: **AH**
MATERIAL DESCRIPTION: **Fire Doors**
MATERIAL LOCATION: **Elevator Building**
MATERIAL QUANTITY: **8** MATERIAL UNITS: **EA**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **EA**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **06/01/2016**

Chicago Public Schools

Carnow, Conibear and Associates 2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66442** BUIDLING ID: **3070**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Beinville Brooks**
SCHOOL NAME: **Doolittle East** INSPECTION DATE: **4/5/2016**
ADDRESS: **535 E. 35th Street** IDPH LICENSE NO: **100-10882**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **AI**
MATERIAL DESCRIPTION: **Window Caulk**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Elevator Building**
MATERIAL QUANTITY: **15000** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: _____



Date: 04/05/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66442** BUIDLING ID: **3070**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Doolittle East** REVIEW DATE: **6/1/2016**
ADDRESS: **535 E. 35th Street** IDPH LICENSE NO: **100-10882**

HOMOGENEOUS AREA: **AI**
MATERIAL DESCRIPTION: **Window Caulk**
MATERIAL LOCATION: **Elevator Building**
MATERIAL QUANTITY: **15000** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **06/01/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66442** BUIDLING ID: **3070**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Beinville Brooks**
SCHOOL NAME: **Doolittle East** INSPECTION DATE: **4/5/2016**
ADDRESS: **535 E. 35th Street** IDPH LICENSE NO: **100-10882**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **B**
MATERIAL DESCRIPTION: **Insulation Jacketing & Wrap on Water Tank**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY:


MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **04/05/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66442** BUIDLING ID: **3070**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Doolittle East** REVIEW DATE: **6/1/2016**
ADDRESS: **535 E. 35th Street** IDPH LICENSE NO: **100-10882**

HOMOGENEOUS AREA: **B**

MATERIAL DESCRIPTION: **Insulation Jacketing & Wrap on Water Tank**

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **06/01/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66442** BUIDLING ID: **3070**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Beinville Brooks**
SCHOOL NAME: **Doolittle East** INSPECTION DATE: **4/5/2016**
ADDRESS: **535 E. 35th Street** IDPH LICENSE NO: **100-10882**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **F**
MATERIAL DESCRIPTION: **Cementitious Insulation on Small Joints**
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Wet Walls in Boy's Washrooms, Boiler Room, Janitor's Closets, Classroom 209**
MATERIAL QUANTITY: **100** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: _____



Date: 04/05/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66442** BUIDLING ID: **3070**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Doolittle East** REVIEW DATE: **6/1/2016**
ADDRESS: **535 E. 35th Street** IDPH LICENSE NO: **100-10882**

HOMOGENEOUS AREA: **F**
MATERIAL DESCRIPTION: **Cementitious Insulation on Small Joints**
MATERIAL LOCATION: **Wet Walls in Boy's Washrooms, Boiler Room, Janitor's Closets, Classroom 209**
MATERIAL QUANTITY: **100** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **06/01/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66442** BUIDLING ID: **3070**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Beinville Brooks**
SCHOOL NAME: **Doolittle East** INSPECTION DATE: **4/5/2016**
ADDRESS: **535 E. 35th Street** IDPH LICENSE NO: **100-10882**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **G**
MATERIAL DESCRIPTION: **Air Cell Pipe Insulation**
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Washrooms, Boiler Room, Auditorium, Room 209**
MATERIAL QUANTITY: **350** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: _____



Date: 04/05/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66442** BUIDLING ID: **3070**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Doolittle East** REVIEW DATE: **6/1/2016**
ADDRESS: **535 E. 35th Street** IDPH LICENSE NO: **100-10882**

HOMOGENEOUS AREA: **G**
MATERIAL DESCRIPTION: **Air Cell Pipe Insulation**
MATERIAL LOCATION: **Washrooms, Boiler Room, Auditorium, Room 209**
MATERIAL QUANTITY: **350** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **06/01/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66442** BUIDLING ID: **3070**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Beinville Brooks**
SCHOOL NAME: **Doolittle East** INSPECTION DATE: **4/5/2016**
ADDRESS: **535 E. 35th Street** IDPH LICENSE NO: **100-10882**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **L**
MATERIAL DESCRIPTION: **Cementitious Joint Insulation- Large Gray Fittings**
HISTORICAL AHERA DAMAGE CATEGORY **1 Damaged or significantly damaged friable thermal system insulating ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Repair**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **1. Damaged or significantly damaged friable thermal system insulating ACBM**

DAMAGE REASON: **Deterioration**
DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Boiler Room, Janitor Closet, Basement**
MATERIAL QUANTITY: **48** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: DAMAGE UNITS: **LF**
COMMENTS:

Inspector's Signature: _____



Date: 04/05/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66442** BUILDING ID: **3070**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Doolittle East** REVIEW DATE: **6/1/2016**
ADDRESS: **535 E. 35th Street** IDPH LICENSE NO: **100-10882**

HOMOGENEOUS AREA: **L**
MATERIAL DESCRIPTION: **Cementitious Joint Insulation- Large Gray Fittings**
MATERIAL LOCATION: **Boiler Room, Janitor Closet, Basement**
MATERIAL QUANTITY: **48** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **20** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.


The RESPONSE ACTION recommendation is:

Repair

Comments:

Repair Localized Damage and Continue O&M

Management Planner's Signature: _____



Date: **06/01/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66442** BUIDLING ID: **3070**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Beinville Brooks**
SCHOOL NAME: **Doolittle East** INSPECTION DATE: **4/5/2016**
ADDRESS: **535 E. 35th Street** IDPH LICENSE NO: **100-10882**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **M**
MATERIAL DESCRIPTION: **Gray Mud Packing**
HISTORICAL AHERA DAMAGE CATEGORY **7**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7**. **Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Engineer's Washroom- Surrounding Duct**
MATERIAL QUANTITY: **10** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 04/05/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66442** BUIDLING ID: **3070**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Doolittle East** REVIEW DATE: **6/1/2016**
ADDRESS: **535 E. 35th Street** IDPH LICENSE NO: **100-10882**


HOMOGENEOUS AREA: **M**
MATERIAL DESCRIPTION: **Gray Mud Packing**
MATERIAL LOCATION: **Engineer's Washroom- Surrounding Duct**
MATERIAL QUANTITY: **10** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **06/01/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66442** BUIDLING ID: **3070**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Beinville Brooks**
SCHOOL NAME: **Doolittle East** INSPECTION DATE: **4/5/2016**
ADDRESS: **535 E. 35th Street** IDPH LICENSE NO: **100-10882**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **N**
MATERIAL DESCRIPTION: **Cementitious Valve Insulation- Large Gray Fittings**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Boiler Room - ABATED 1999**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____



Date: **04/05/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66442** BUIDLING ID: **3070**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Doolittle East** REVIEW DATE: **6/1/2016**
ADDRESS: **535 E. 35th Street** IDPH LICENSE NO: **100-10882**

HOMOGENEOUS AREA: **N**

MATERIAL DESCRIPTION: **Cementitious Valve Insulation- Large Gray Fittings**

MATERIAL LOCATION: **Boiler Room - ABATED 1999**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:


DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **06/01/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66442** BUILDING ID: **3070**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Doolittle East** REVIEW DATE: **6/1/2016**
ADDRESS: **535 E. 35th Street** IDPH LICENSE NO: **100-10882**

HOMOGENEOUS AREA: **48**

MATERIAL DESCRIPTION: **Mastic Associated w/ 12" x 12" Cream w/ White Specks Floor Tile**

MATERIAL LOCATION: **Dance Hall/Small Gym**

MATERIAL QUANTITY: **1140** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____



Date: **06/01/2016**

Chicago Public Schools

Carnow, Conibear and Associates 2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66442** BUILDING ID: **3070**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Doolittle East** REVIEW DATE: **6/1/2016**
ADDRESS: **535 E. 35th Street** IDPH LICENSE NO: **100-10882**

HOMOGENEOUS AREA: **44**
MATERIAL DESCRIPTION: **Mastic Associated w/ 12" x 12" Black w/ White Specks Floor Tile**
MATERIAL LOCATION: **Room 306**
MATERIAL QUANTITY: **860** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:  Date: **06/01/2016**

Chicago Public Schools

Carnow, Conibear and Associates 2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66442** BUILDING ID: **3070**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Doolittle East** REVIEW DATE: **6/1/2016**
ADDRESS: **535 E. 35th Street** IDPH LICENSE NO: **100-10882**


HOMOGENEOUS AREA: **47**
MATERIAL DESCRIPTION: **12" x 12" Cream w/ White Specks Floor Tile**
MATERIAL LOCATION: **Dance Hall/Small Gym**
MATERIAL QUANTITY: **1140** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____



Date: **06/01/2016**

Chicago Public Schools

Carnow, Conibear and Associates 2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66442** BUILDING ID: **3070**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Doolittle East** REVIEW DATE: **6/1/2016**
ADDRESS: **535 E. 35th Street** IDPH LICENSE NO: **100-10882**


HOMOGENEOUS AREA: **43**
MATERIAL DESCRIPTION: **12" x 12" Black w/ White Specks Floor Tile**
MATERIAL LOCATION: **Room 306**
MATERIAL QUANTITY: **860** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____



Date: **06/01/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION


Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66442** BUILDING ID: **3070**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Beinville Brooks**
SCHOOL NAME: **Doolittle East** INSPECTION DATE: **4/5/2016**
ADDRESS: **535 E. 35th Street** IDPH LICENSE NO: **100-10882**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **45**
MATERIAL DESCRIPTION: **12" x 12" Tan w/ White Specks Floor Tile**
MATERIAL LOCATION: **Rooms 200 and 310, Pre-K Cafeteria**
MATERIAL QUANTITY: **3422** MATERIAL UNITS: **SF**
MATERIAL CATEGORY: **MISC** FRIABLE: **No**
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **LOW** CONDITION:
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
ACCESSIBILITY: **Within Reach** DAMAGE REASON:
DAMAGE QUANTITY: **0** DAMAGE REASON:
DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____



Date: 04/05/2016

Chicago Public Schools

Carnow, Conibear and Associates 2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66442** BUILDING ID: **3070**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Doolittle East** REVIEW DATE: **6/1/2016**
ADDRESS: **535 E. 35th Street** IDPH LICENSE NO: **100-10882**


HOMOGENEOUS AREA: **45**
MATERIAL DESCRIPTION: **12" x 12" Tan w/ White Specks Floor Tile**
MATERIAL LOCATION: **Rooms 200 and 310, Pre-K Cafeteria**
MATERIAL QUANTITY: **3422** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____



Date: **06/01/2016**

Chicago Public Schools

Carnow, Conibear and Associates 2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66442** BUILDING ID: **3070**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Doolittle East** REVIEW DATE: **6/1/2016**
ADDRESS: **535 E. 35th Street** IDPH LICENSE NO: **100-10882**


HOMOGENEOUS AREA: **46**
MATERIAL DESCRIPTION: **Mastic Associated w/ 12" x 12" Tan w/ White Specks Floor Tile**
MATERIAL LOCATION: **Rooms 200 and 310, Pre-K Cafeteria**
MATERIAL QUANTITY: **3422** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____



Date: **06/01/2016**

APPENDIX B

Inspector and Management Planner Licenses



**ASBESTOS
PROFESSIONAL
LICENSE**

ID NUMBER
100 - 10882

ISSUED
3/11/2015

EXPIRES
05/15/2016

BEINVILLE S BROOKS
PO BOX 1373
CALUMET, IL 60409

Environmental Health



ENDORSEMENTS

SUPERVISOR/WORKER
INSPECTOR

TC EXPIRES

1/30/2016
2/14/2016

PROJECT MANAGER
AIR SAMPLING PROFESSIONAL

1/30/2016

Alteration of this license shall result in legal action
This license issued under authority of the State of Illinois
Department of Public Health

This license is valid only when accompanied by a valid
training course certificate.

CERTIFICATE OF ACHIEVEMENT ASBESTOS ABATEMENT

Accredited by the Illinois Department of Public Health

This is to certify that BENVILLE BROOKS
has completed the ASBESTOS INSPECTOR'S REFRESHER course and successfully passed the
examination on 01/06/2016 with a minimum score of 70% or better. Training was in accordance
with U.S. E.P.A. 40 CFR 763 Subpart E, Appendix C, Asbestos Containing Materials in Schools:
Model Accreditation Plan, TSCA II, Authorized by both AHERA & ASHARA.

01/06/2016

Course Dates:

01/06/2017

Expires:

1601BIR01

Certificate Number:



M. Deery

Phone: 312-491-0081

Director of Training
Nicholas J. Penell
Doctor of Public Health

FORM # A-010B

2016



OCCUPATIONAL TRAINING & SUPPLY, INC.

7233 S. Adams Street ♦ Willowbrook, IL 60527 ♦ (630) 655-3900

Asbestos Management Planner Refresher

Occupational Training & Supply, Inc. certifies that

Daniel Juneau


has successfully completed the Asbestos Management Planner Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 1/6/2016

Exam Date: 1/6/2016

Expiration Date: 1/6/2017

Certificate Number: MPR1601060038



Kathy DeSalvo, Director

Daniel Juneau

Illinois Licensed Asbestos Inspector, Management Planner,
Project Manager, and Air Sampling Professional



ASBESTOS PROFESSIONAL LICENSE

ID NUMBER ISSUED EXPIRES
100 - 03613 **3/16/2015** **05/15/2016**

DANIEL J JUNEAU
1408 OAKWOOD AVENUE
DES PLAINES, IL 60016

Environmental Health



ENDORSEMENTS

TC EXPIRES

INSPECTOR	12/2/2015
MANAGEMENT PLANNER	1/20/2016
PROJECT MANAGER	12/11/2015
AIR SAMPLING PROFESSIONAL	

Alteration of this license shall result in legal action
This license issued under authority of the State of Illinois
Department of Public Health
This license is valid only when accompanied by a valid
training course certificate.

**CARNOW
CONIBEAR**

2015



OCCUPATIONAL TRAINING & SUPPLY, INC.

7233 S. Adams Street ♦ Willowbrook, IL 60527 ♦ (630) 655-3900

Asbestos Building Inspector Refresher

Occupational Training & Supply, Inc. certifies that

Daniel Juneau


has successfully completed the Asbestos Building Inspector Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 12/2/2015

Exam Date: 12/2/2015

Expiration Date: 12/2/2016

Certificate Number: BIR1512024163



Kathy DeSalvo, Director

APPENDIX C

Laboratory Accreditations

APPENDIX D

Laboratory Results

APPENDIX E

Chain of Custody Forms

Three-Year Reinspection Key to Terms

	CODE	KEY
MATERIAL		
	ACBM	Asbestos Containing Building Materials
MATERIAL CATEGORY		
	MISC	Miscellaneous
	SURF	Surfacing
	TSI	Thermal System Insulation
MATERIAL UNITS		
	LF	Linear Feet
	SF	Square Feet
	CF	Cubic Feet
DAMAGE TYPE		
	Loc	Localized
	Dist	Distributed