

ILLINOIS DEPARTMENT OF PUBLIC HEALTH
AHERA THREE YEAR REINSPECTION
ASBESTOS ABATEMENT PROGRAM
SCHOOL INFORMATION FORM

SECTION I

NAME OF SCHOOL DISTRICT: CHICAGO SCHOOL DIST 299
SCHOOL ID NUMBER: 14-016-2990-2838
SCHOOL NAME: Telpochcalli School
ADDRESS OF SCHOOL: 2832 W. 24th Blvd.
CITY: Chicago, IL, 60623

DATE LAST THREE YEAR REINSPECTION WAS COMPLETED **3/22/2013**

If the address on this form is different than the address of the building, submit a written explanation.

SECTION II (Please type or print)

PLEASE COMPLETE THE FOLLOWING FOR YOUR THREE YEAR REINSPECTION:

DATE REINSPECTION COMPLETED: 3/15/2016 ENROLLMENT 295
IDPH INSPECTOR LICENSE NUMBER: 100-08864
IDPH LICENSED INSPECTOR NAME (Please Print): Robert DeBord
IDPH MP LICENSE NUMBER: 100-19466
IDPH LICENSED MANAGEMENT PLANNER NAME (Please Print): Evan Christian

DESIGNATED PERSON (Please Print): Robert Christlieb PHONE: (773) 553-3197



3/15/2016

Signature of Designated Person

Date

SECTION III

PLEASE COMPLETE THE FOLLOWING INFORMATION FOR ANY CHANGES WITHIN THE SCHOOL DISTRICT.

School building has been sold. Date of Sale: _____

School has been closed. Date closed: _____

School building has been demolished. Date: _____

School building is asbestos free since last reinspection: _____

Please explain in writing why the school building is now asbestos free and include the supporting documentation.

If a new school building has been added to the district, submit either an exclusionary statement or a management plan and inspection report. Include the complete name, address and city of school building.

Explain in writing if the address of the building is different than the address on this form:

THREE-YEAR REINSPECTION

CHICAGO SCHOOL DIST 299

Telpochcalli School

2832 W. 24th Blvd.
Chicago, IL, 60623

Unit: 23231
Building ID: 3380

IDPH ID Number: 14-016-2990-2838

REPORT DATE:

Tuesday, March 15, 2016

Prepared for:

Chicago Public Schools
125 S. Clark Street
Chicago, IL 60603

Prepared by:

Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone (312) 762-2900

Fax (312) 782-5145

**DO NOT REMOVE FROM SCHOOL
REQUIRED BY FEDERAL LAW**

Environmental Notification to Occupants

To: Faculty, Staff and Parents
From: Chicago Public Schools
Date: February 25, 2016

RE: Telpochcalli School, Unit 23231
2832 W. 24th Blvd.
Chicago, IL, 60623

Dear Faculty, Staff and Parents,

This letter is to notify you that the 2016 asbestos three year re-inspection has been completed at Telpochcalli School , following the Federal Asbestos Hazard Emergency Response Act (AHERA), 40 CFR Part 763, Subpart E and is available for your review at the main office of the school.

Although asbestos-containing materials have been identified at Telpochcalli School, there is no reason to believe that any threat to the health of students or staff exists at this time. CPS will continue to carefully monitor the condition of asbestos-containing materials and if conditions warrant, all appropriate steps will be taken to maintain the health and safety of all building occupants.

If you have any questions regarding this matter or require additional information, please feel free to contact Robert Christlieb, the designated Local Education Authority's Designated Person at (773) 553-3197 .

Table of Contents

- I. School and Inspection Information
- II. Executive Summary
- III. Methodology
- IV. Abatement History
- V. Reassessments and Recommendations
- VI. Conclusions

Table I: Inspector's Reinspection Findings

Table II: Management Planner's Review

APPENDICES:

- Appendix A: Assessment Sheets, Drawings and Photos
- Appendix B: Inspector and Management Planner Licenses
- Appendix C: Laboratory Accreditations
- Appendix D: Laboratory Results
- Appendix E: Chain of Custody Forms

SCHOOL AND INSPECTION INFORMATION

1. School Information

School: Telpochcalli School Unit: 23231 Region: 03
Address: 2832 W. 24th Blvd. Chicago, IL, 60623
IDPH ID: 14-016-2990-2838 Building ID: 3380
Contact: Moore, Kevin Phone: 773-534-1770

2. Description of Facility

Original Construction: Additional Construction:
Total Square Footage: 41400 No of Floors:
Current Occupancy: 295

3. LEA Designated Person

Contact: Robert Christlieb Phone: (773) 553-3197
Address: 125 South Clark Street, 17th Floor
Chicago, IL 60603

4. Managing Environmental Consultant

MEC: Carnow, Conibear and Associates
Contact: Dan Juneau
Address 600 West Van Buren St., Ste 500
Phone: (312) 762-2900 Fax: (312) 782-5145

5. Inspector

Inspector Name: Robert DeBord

Inspector IDPH license # 100-08864

Signature:
Date: 2/25/2016

6. Management Planner

Management Planner Name: Evan Christian

Management Planner IDPH license # 100-19466

Signature:
Date: 03/15/2016

7. Review Date: 03/15/2016

8. LEA Designated Person's Acknowledgement

The reinspection report and recommendations have been received by me and appropriate action will be taken by the School District.

Signature: 

Date: 3/15/2016

Name: Robert Christlieb

II. EXECUTIVE SUMMARY

Carnow, Conibear and Associates was retained by the Chicago Public Schools (CPS) to perform a three-year asbestos reinspection of the Telpochcalli School. This inspection was conducted in accordance with the United States Environmental Protection Agency (USEPA) Asbestos Hazard Emergency Response Act (AHERA) part 763.92 (b), and the ongoing Operations and Maintenance Program (O&M) originally designed in the School's Asbestos Management Plan. The purpose of this three-year reinspection is to record any condition changes in the asbestos-containing building material (ACBM) in the school since the previous three-year reinspection and the six-month periodic surveillance, to identify, assess, and include any Homogeneous Areas (HA) not identified in the Management Plan, and to recommend an appropriate response action to manage asbestos.

The inspector conducted a three-year reinspection of this facility under Illinois Department of Public Health (IDPH) school reinspection requirements and AHERA, sections 763.85 and 763.88. The main building and each addition to the main building, if constructed at different dates, were inspected separately. Laboratory accreditations are included in Appendix C, laboratory results are included in Appendix D, and chain of custody forms are included in Appendix E.

Note: During previous inspections, some of the HA(s) were identified together as 9" x 9" floor tile (FT), mastics assoc. with 9" x 9" FT, 12" x 12" FT, mastics assoc. with 12" x 12" FT, pipe insulation, etc. Some of these HA(s) have been re-identified by areas that are uniform in color, texture, construction date, application date, and general appearance.

The inspector has determined the following:

A. The following HAs have changed assessment categories for Building 3380:

100	12" x 12" Blue Vinyl Floor Tile
101	12" x 12" Gray Vinyl Floor Tile
102	12" x 12" White Vinyl Floor Tile
103	12" x 12" Blue, White, and Gray Vinyl Floor Tile
104	Mastic Associated w/ Blue, Gray, and White Vinyl Floor Tiles
105	12" x 12" Light Gray w/ Dk. Gray Specks Vinyl Floor Tile
106	White Board over Black Boards
72	Aircell Duct Insulation

- 74 Magblock Pipe Insulation
- 75 Hard Fittings on Aircell Pipe Insulation

B. The following new homogenous areas have been identified for Building 3380:

100	12" x 12" Blue Vinyl Floor Tile
101	12" x 12" Gray Vinyl Floor Tile
102	12" x 12" White Vinyl Floor Tile
103	12" x 12" Blue, White, and Gray Vinyl Floor Tile
104	Mastic Associated w/ Blue, Gray, and White Vinyl Floor Tiles
105	12" x 12" Light Gray w/ Dk. Gray Specks Vinyl Floor Tile
106	White Board over Black Boards

C. This reinspection covered only physically accessible and visible areas and materials that were identified in the LEA's management plan. The following materials were concealed and/or contained in areas that were inaccessible for sampling and have been classified as Assumed:

100	12" x 12" Blue Vinyl Floor Tile
101	12" x 12" Gray Vinyl Floor Tile
102	12" x 12" White Vinyl Floor Tile
103	12" x 12" Blue, White, and Gray Vinyl Floor Tile
104	Mastic Associated w/ Blue, Gray, and White Vinyl Floor Tiles
105	12" x 12" Light Gray w/ Dk. Gray Specks Vinyl Floor Tile
106	White Board over Black Boards
22A	12" x 12" Red w/Specks Floor Tile
22C	12" x 12" Off-white w/Beige Specks Floor Tile
22E	12" x 12" Tan w/Red & Brown Streaks Floor Tile
24A	12" x 12" Red w/Specks Floor Tile Mastic
24B	12" x 12" Pink Floor Tile w/Specks Mastic
24F	12" x 12" Floor Tile Mastic
51	Stage Lighting Electrical Insulation
52	Incinerator Interior Insulation
57	Exterior Brick - Non AHERA
62	Chimney Brick
63	Chimney Brick Mortar
64	Chimney Refracting Brick
72	Aircell Duct Insulation
73	Aircell Pipe Insulation
74	Magblock Pipe Insulation
75	Hard Fittings on Aircell Pipe Insulation
76	1' x 1' White w/ Holes Panels
78	4" Black vinyl baseboard
79	4" black baseboard adhesive
80	4" grey vinyl baseboard
81	4" grey vinyl baseboard adhesive
82	6" brown vinyl baseboard
83	6" brown vinyl baseboard adhesive
84	1x1 deep fissured ceiling tile
85	1x1 deep fissured ceiling tile adhesive
86	12x12 lt beige/white floor tile
87	12x12 lt beige/white floor tile mastic
88	sink undercoating
89	maroon carpet mastic
90	12x12 maroon floor tile - REMOVED
91	12x12 beige with maroon floor tile - REMOVED
92	mastic associated with marron tile and beige - REMOVED

93	Black Lab Table
94	2x4 fissured ceiling tile
95	chalkboard
96	chalkboard adhesive
99	Brown Carpet Adhesive - REMOVED

The following areas were deemed to be inaccessible:

104	Mastic Associated w/ Blue, Gray, and White Vinyl Floor Tiles
24A	12" x 12" Red w/Specks Floor Tile Mastic
24B	12" x 12" Pink Floor Tile w/Specks Mastic
24C	12"x12" Off-white w/Beige Specks Floor Tile Mastic
24E	12"x12"Tan w/Red & Brown Streaks Floor Tile Mastic
24F	12" x 12" Floor Tile Mastic
25A	9" x 9" Brown w/White & Dark Brn Streaks FT Mastic
25B	9" x 9" Tan w/White & Dark Brown Streaks FT Mastic
25C	9"x9" Dark Brown w/White & Red Streaks FT Mastic
81	4" grey vinyl baseboard adhesive
85	1x1 deep fissured ceiling tile adhesive
87	12x12 lt beige/white floor tile mastic
89	maroon carpet mastic
96	chalkboard adhesive

Materials were also listed as "assumed" if they were in good condition and sampling was not conducted to avoid damage.

This reinspection was conducted by Robert DeBord, IDPH License # 100-08864. The Management Plan was updated by Evan Christian, IDPH License # 100-19466. Inspector and Management Planner Licenses are included in Appendix B.

III. METHODOLOGY

Tasks performed on-site included the following:

1. Review current management plan, identify HA(s) and extract appropriate information.
2. Examine and verify abatement records.
3. Touch and visually and physically reinspect and reassess the condition of all friable known or assumed ACBM.
4. Touch and visually and physically reinspect all non-friable known or assumed ACBM to determine whether these materials have become friable since the last inspection or periodic surveillance.
5. Identify any condition changes that may affect Hazard Ranking of known ACBM or Assumed ACBM, as well as any HA(s) that have become friable since the last reinspection.
6. Collect bulk samples from each newly discovered friable HA or previously assumed and submit for laboratory analysis.
7. Tabulate reinspection findings and submit for management planner review and recommendations with appropriate response actions based on the AHERA Damage Category of the ACBM.
8. Submit reinspection findings and management planner recommendations to the LEA within thirty (30) days for inclusion into the management plan.

IV. ABATEMENT HISTORY

The information collected from the existing management plan and inspection report(s) and from interviews with the school official revealed that the following asbestos abatement was conducted at the school since the previous Three year Reinspection.

Abatement Dates:

V. REASSESSMENTS AND RECOMMENDATIONS

The reassessments and recommendations are summarized in Tables I and II on the following pages. Detailed Hazard Assessment Sheets and Drawings and Photos (if applicable) are included in Appendix A.

VI. CONCLUSIONS

The Telpochcalli School Building 3380 Three-Year reinspection has been completed and response actions have been recommended for both friable and non-friable materials. A timely execution of the response actions recommended will enable the LEA and the Designated Person(s) to effectively manage the existing ACBM.

This three-year reinspection report should be inspected in the current Management plan at the CPS Central Office, and one (1) copy should be kept at the school for use when planning any renovation and/or demolition activities in areas where ACBM has been identified. Also, periodic surveillance documentation and any summary reports from any response actions that are executed at the school should be used to update the Management Plan.

Table I
Inspector's Reinspection Findings

Chicago Public Schools

School Telpochcalli School Unit 23231 Building ID 3380

Address 2832 W. 24th Blvd. Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
100	12" x 12" Blue Vinyl Floor Tile	1,100	SF	1st and 2nd Floor Corridor	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
101	12" x 12" Gray Vinyl Floor Tile	1,100	SF	1st and 2nd Floor Corridor	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
102	12" x 12" White Vinyl Floor Tile	1,100	SF	1st and 2nd Floor Corridor	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
103	12" x 12" Blue, White, and Gray Vinyl Floor Tile	200	SF	Entrances	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
104	Mastic Associated w/ Blue, Gray, and White Vinyl Floor Tiles	3,500	SF	1st and 2nd Floor Corridors and Entrances	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
105	12" x 12" Light Gray w/ Dk. Gray Specks Vinyl Floor Tile	200	SF	Room 164 (Computer room)	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
106	White Board over Black Boards	10,000	SF	All Black Boards	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
22A	12" x 12" Red w/Specks Floor Tile	9,000	SF	Main Office, Rooms 155 and 156, and 2nd Floor Hall, 167, copy room, 164, 165, 166, 155, 154, 262	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
22C	12" x 12" Off-white w/Beige Specks Floor Tile	1,900	SF	Rooms 151 and 251	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
22D	12" x 12" Peach w/Black & White Streaks Floor Tile			1st Floor Corridors -	ABATED	MISC								
22E	12" x 12" Tan w/Red & Brown Streaks Floor Tile	1,100	SF	1st Floor Corridors	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
23A	9"x9" Brown w/White & Dark Brown Streaks Floor Tile	475	SF	Engineer's Office, 2nd floor band room and offices	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
23B	9"x9" Tan w/White & Dark Brown Streaks Floor Tile	600	SF	Engineer's Office 2nd floor band room and offices, Rm. 168	CHR	MISC	N	LOC	20		No	ACBM with potential for significant damage		LOW
23C	9" x 9" Dark Brown w/White & Red Streaks Floor Tile	1,000	SF	Engineer's Office, by receiving engineer's lounge	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
24A	12" x 12" Red w/Specks Floor Tile Mastic	9,000	SF	Main Office, Rooms 155 and 156, 2nd Floor Hall, 167, copy rm. 155, 154, 156, 262	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
24B	12" x 12" Pink Floor Tile w/Specks Mastic	2,000	SF	Main Office, Rooms 155 and 156, 2nd Floor Hall	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
24C	12"x12" Off-white w/Beige Specks Floor	1,900	SF	Rooms 151 and 251	CHR	MISC	N	NONE	0		No	ACBM with the		LOW

Chicago Public Schools

School Telpochcalli School Unit 23231 Building ID 3380

Address 2832 W. 24th Blvd. Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
	AHERA													
68	Lower Roof Parapet Wall Brick Mortar - Not AHERA			Auditorium Roof	NO_ACBM	MISC								
69	Kitchen Exhaust Vent Caulk - Not AHERA			Roof	NO_ACBM	MISC								
70	Window Glaze - Not AHERA			Exterior Skylight of Main Building	NO_ACBM	MISC								
71	Window Caulk - Not AHERA			Exterior Skylight of Main Building	NO_ACBM	MISC								
72	Aircell Duct Insulation	1,200	SF	1st Floor Hallway Ductwork	ASSUMED	TSI	Y	NONE	0		Yes	Any remaining friable ACBM or friable suspect ACBM		LOW
73	Aircell Pipe Insulation	160	LF	Engine Rms and Rm 151	ASSUMED	TSI	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		MODERATE
74	Magblock Pipe Insulation	1,200	LF	Engine Rooms and Tunnel	ASSUMED	TSI	Y	NONE	0		Yes	Any remaining friable ACBM or friable suspect ACBM		LOW
75	Hard Fittings on Aircell Pipe Insulation	250	LF	Engine Rm and Room 151	ASSUMED	TSI	Y	NONE	0		Yes	Any remaining friable ACBM or friable suspect ACBM		LOW
76	1' x 1' White w/ Holes Panels			band room offices	ASSUMED	MISC								
77	Plaster			Throughout Building/ walls abd ceilings	NO_ACBM	SURFACE								
78	4" Black vinyl baseboard			engineers lounge, receiving office, 168, band room/office, store room, entrance	ASSUMED	MISC		None						Low
79	4" black baseboard adhesive			engineers lounge, receiving office, 168, band room/office, store room, entrance	ASSUMED	MISC		None						Low
80	4" grey vinyl baseboard	30	LF	168, band room office 2/3	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
81	4" grey vinyl baseboard adhesive	30	LF	168, band room office 2/3	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
82	6" brown vinyl baseboard			167, 166, main office, 154-156, 152, stairlanding, 262	ASSUMED	MISC		None						Low
83	6" brown vinyl baseboard adhesive			167, 166, main office, 154-156, 152, stairlanding, 262	ASSUMED	MISC		None						Low

Chicago Public Schools

School Telpochcalli School Unit 23231 Building ID 3380

Address 2832 W. 24th Blvd. Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

Reinspection Date 2/25/2016
Inspector Name Robert DeBord
100-08864 5/15/2016
Inspector's IDPH License Number / Expiration Date

Inspector's Comments

HA Number:	Inspector Comments:
100	
101	
102	
103	
104	
105	
106	
22A	
22C	
22D	
22E	
23A	
23B	
23C	
24A	
24B	
24C	
24D	
24E	
24F	
25A	
25B	
25C	
50	

Chicago Public Schools

School Telpochcalli School Unit 23231 Building ID 3380

Address 2832 W. 24th Blvd. Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
51	
52	
54	
55	
56	
57	
58	
59	
60	
61	
62	Not observed 2016
63	Not observed 2016
64	Not observed 2016
66	
67	
68	
69	
70	
71	
72	
73	
74	
75	
76	Not observed 2016
77	
78	Not observed 2016
79	Not observed 2016
80	
81	

Chicago Public Schools

School Telpochcalli School Unit 23231 Building ID 3380

Address 2832 W. 24th Blvd. Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
82	Not observed 2016
83	Not observed 2016
84	
85	
86	
87	
88	
89	
90	
91	
92	
93	
94	
95	Not observed - skimmed over with white board.
96	
97	
98	
99	
F	
I	

Table II

Management Planner's Review

Chicago Public Schools

School Telpochcalli School
Address 2832 W. 24th Blvd.

Unit 23231
Chicago, IL, 60623

Building ID 3380
Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
100	12" x 12" Blue Vinyl Floor Tile	1,100	SF	1st and 2nd Floor Corridor	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
101	12" x 12" Gray Vinyl Floor Tile	1,100	SF	1st and 2nd Floor Corridor	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
102	12" x 12" White Vinyl Floor Tile	1,100	SF	1st and 2nd Floor Corridor	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
103	12" x 12" Blue, White, and Gray Vinyl Floor Tile	200	SF	Entrances	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
104	Mastic Associated w/ Blue, Gray, and White Vinyl Floor Tiles	3,500	SF	1st and 2nd Floor Corridors and Entrances	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
105	12" x 12" Light Gray w/ Dk. Gray Specks Vinyl Floor Tile	200	SF	Room 164 (Computer room)	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
106	White Board over Black Boards	10,000	SF	All Black Boards	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
22A	12" x 12" Red w/Specks Floor Tile	9,000	SF	Main Office, Rooms 155 and 156, and 2nd Floor Hall, 167, copy room, 164, 165, 166, 155, 154, 262	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
22C	12" x 12" Off-white w/Beige Specks Floor Tile	1,900	SF	Rooms 151 and 251	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
22D	12" x 12" Peach w/Black & White Streaks Floor Tile			1st Floor Corridors -	Abated	MISC					
22E	12" x 12" Tan w/Red & Brown Streaks Floor Tile	1,100	SF	1st Floor Corridors	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
23A	9"x9"Brown w/White & Dark Brown Streaks Floor Tile	475	SF	Engineer's Office, 2nd floor band room and offices	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
23B	9"x9" Tan w/White & Dark Brown Streaks Floor Tile	600	SF	Engineer's Office 2nd floor band room and offices, Rm. 168	Chrysotile	MISC	No	20	SF	5 ACBM with potential for significant damage	Repair
23C	9" x 9"Dark Brown w/White & Red Streaks Floor Tile	1,000	SF	Engineer's Office, by receiving engineer's lounge	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
24A	12" x 12" Red w/Specks Floor Tile Mastic	9,000	SF	Main Office, Rooms 155 and 156, 2nd Floor Hall, 167,copy rm,155,154,156,262	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
24B	12" x 12" Pink Floor Tile w/Specks Mastic	2,000	SF	Main Office, Rooms 155 and 156, 2nd Floor Hall	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
24C	12"x12" Off-white w/Beige Specks Floor Tile Mastic	1,900	SF	Rooms 151 and 251	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
24D	12" x 12" Peach w/Black & White Streaks FT Mastic			1st Floor Corridors and stair landings	Abated	MISC					
24E	12"x12"Tan w/Red & Brown Streaks Floor Tile Mastic	900	SF	1st Floor Corridor	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
24F	12" x 12" Floor Tile Mastic	1,800	SF	2nd Floor Corridor	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
25A	9" x 9" Brown w/White & Dark Brn Streaks FT Mastic	475	SF	Engineer's Office 2nd floor, band room and band offices	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
25B	9" x 9" Tan w/White & Dark Brown Streaks FT Mastic	250	SF	Engineer's Office 2nd floor, band room and band offices	Chrysotile	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

Chicago Public Schools

School Telpochcalli School
Address 2832 W. 24th Blvd.

Unit 23231
 Chicago, IL, 60623

Building ID 3380
Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
25C	9"x9" Dark Brown w/White & Red Streaks FT Mastic	250	SF	Engineers office by receiving and eng. Lounge	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
50	Window Caulk	14,000	LF	Throughout Building, Main Office, Assistants Office, Engineers Office	Chrysotile	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
51	Stage Lighting Electrical Insulation	100	SF	Auditorium	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
52	Incinerator Interior Insulation	250	SF	Boiler Room	Assumed	TSI	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
54	Window Glaze			Interior, Rooms 107,118, Boiler Room	No ACBM	MISC					
55	Window Caulk - Not AHERA			Building Exterior	Chrysotile	MISC					
56	Window Glaze - Not AHERA			Building Exterior	Chrysotile	MISC					
57	Exterior Brick - Non AHERA			Building Exterior	Assumed	MISC					
58	Brick Mortar - Not AHERA			Building Exterior	No ACBM	MISC					
59	Base Stone Block - Not AHERA			Building Exterior	No ACBM	MISC					
60	Base Stone Block Mortar - Not AHERA			Building Exterior	No ACBM	MISC					
61	Exterior Door Caulk - Not AHERA			Building Exterior	Chrysotile	MISC					
62	Chimney Brick			Interior	Assumed	MISC					Follow O&M Plan
63	Chimney Brick Mortar			Interior	Assumed	MISC					Follow O&M Plan
64	Chimney Refracting Brick			Interior	Assumed	MISC					Follow O&M Plan
66	Roof Flashing - Not AHERA			Auditorium Roof	Chrysotile	MISC					
67	Lower Roof Parapet Wall Brick - Not AHERA			Auditorium Roof	No ACBM	MISC					
68	Lower Roof Parapet Wall Brick Mortar - Not AHERA			Auditorium Roof	No ACBM	MISC					
69	Kitchen Exhaust Vent Caulk - Not AHERA			Roof	No ACBM	MISC					
70	Window Glaze - Not AHERA			Exterior Skylight of Main Building	No ACBM	MISC					
71	Window Caulk - Not AHERA			Exterior Skylight of Main Building	No ACBM	MISC					
72	Aircell Duct Insulation	1,200	SF	1st Floor Hallway Ductwork	Assumed	TSI	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
73	Aircell Pipe Insulation	160	LF	Engine Rms and Rm 151	Assumed	TSI	Yes	0	LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
74	Magblock Pipe Insulation	1,200	LF	Engine Rooms and Tunnel	Assumed	TSI	Yes	0	LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
75	Hard Fittings on Aircell Pipe Insulation	250	LF	Engine Rm and Room 151	Assumed	TSI	Yes	0	LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
76	1' x 1' White w/ Holes Panels			band room offices	Assumed	MISC					Follow O&M Plan
77	Plaster			Throughout Building/ walls abd ceilings	No ACBM	SURFACE					

Chicago Public Schools

School Telpochcalli School
Address 2832 W. 24th Blvd.

Unit 23231
 Chicago, IL, 60623

Building ID 3380
Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
78	4" Black vinyl baseboard			engineers lounge, receiving office, 168, band room/office, store room, entrance	Assumed	MISC					Follow O&M Plan
79	4" black baseboard adhesive			engineers lounge, receiving office, 168, band room/office, store room, entrance	Assumed	MISC					Follow O&M Plan
80	4" grey vinyl baseboard	30	LF	168, band room office 2/3	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
81	4" grey vinyl baseboard adhesive	30	LF	168, band room office 2/3	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
82	6" brown vinyl baseboard			167, 166, main office, 154-156, 152, stairlanding, 262	Assumed	MISC					Follow O&M Plan
83	6" brown vinyl baseboard adhesive			167, 166, main office, 154-156, 152, stairlanding, 262	Assumed	MISC					Follow O&M Plan
84	1x1 deep fissured ceiling tile	1,600	SF	168, band room and offices 1-4, storage 167 166 main office	Assumed	MISC	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
85	1x1 deep fissured ceiling tile adhesive	1,600	SF	168, band room and offices 1-4, storage 167 166 main office	Assumed	MISC	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
86	12x12 lt beige/white floor tile	1,000	SF	251	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
87	12x12 lt beige/white floor tile mastic	1,000	SF	251	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
88	sink undercoating	4	SF	156a	Assumed	SURFACE	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
89	maroon carpet mastic	2,040	SF	257-258	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
90	12x12 maroon floor tile - REMOVED			2nd floor cooridor checkboard	Assumed	MISC					
91	12x12 beige with maroon floor tile - REMOVED			2nd floor cooridor checkboard	Assumed	MISC					
92	mastic associated with marron tile and beige - REMOVED			2nd floor cooridor checkerboard	Assumed	MISC					
93	Black Lab Table	120	SF	Rooms 152 and 262	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
94	2x4 fissured ceiling tile	2,800	SF	257,258 eng. Lounge and main office	Assumed	MISC	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
95	chalkboard			all classrooms 215,221,225	Assumed	MISC					Follow O&M Plan
96	chalkboard adhesive	10,000	SF	all classrooms	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
97	Patch Floor Tile - white, pink, brown			1st floor Hallway	Abated	MISC					
98	Mastic w/ Patch Floor Tile - white, pink, brown			1st floor Hallway	Abated	MISC					
99	Brown Carpet Adhesive - REMOVED			Entrances	Assumed	MISC					
F	Fiberglass Tank Insulation			Boiler Room	Not Tested						
I	Fiberglass Pipe Insulation			Boiler Room	Not Tested						

Chicago Public Schools

School Telpochcalli School
Address 2832 W. 24th Blvd.

Unit 23231
 Chicago, IL, 60623

Building ID 3380
Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

Review Date	3/15/2016
Manager Planner Name	Evan Christian
100-19466	5/15/2016
Manager IDPH License No/Expiration	

HA Number	Management Comments
100	
101	
102	
103	
104	
105	
106	
22A	
22C	

Chicago Public Schools

School Telpochcalli School

Unit 23231

Building ID 3380

Address 2832 W. 24th Blvd.

Chicago, IL, 60623

Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
22D	If identified follow O&M procedure.
22E	
23A	
23B	Repair as needed then follow O&M plan.
23C	
24A	
24B	
24C	
24D	If identified follow O&M procedure.
24E	
24F	
25A	
25B	
25C	
50	
51	
52	
54	
55	
56	
57	
58	
59	
60	
61	
62	If identified follow O&M procedure.
63	If identified follow O&M procedure.

Chicago Public Schools

School Telpochcalli School
Address 2832 W. 24th Blvd.

Unit 23231
 Chicago, IL, 60623

Building ID 3380
Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
64	If identified follow O&M procedure.
66	
67	
68	
69	
70	
71	
72	
73	
74	
75	
76	If identified follow O&M procedure.
77	
78	If identified follow O&M procedure.
79	If identified follow O&M procedure.
80	
81	
82	If identified follow O&M procedure.
83	If identified follow O&M procedure.
84	
85	
86	
87	
88	
89	
90	If identified follow O&M procedure.
91	If identified follow O&M procedure.

Chicago Public Schools

School Telpochcalli School
Address 2832 W. 24th Blvd.

Unit 23231
Chicago, IL, 60623

Building ID 3380
Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
92	If identified follow O&M procedure.
93	
94	
95	If identified follow O&M procedure.
96	
97	If identified follow O&M procedure.
98	If identified follow O&M procedure.
99	If identified follow O&M procedure.
F	
I	

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23231** BUIDLING ID: **3380**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Robert DeBord**
SCHOOL NAME: **Telpochcalli School** INSPECTION DATE: **2/25/2016**
ADDRESS: **2832 W. 24th Blvd.** IDPH LICENSE NO: **100-08864**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **22A**
MATERIAL DESCRIPTION: **12" x 12" Red w/Specks Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Main Office, Rooms 155 and 156, and 2nd Floor Hall, 167, copy room, 164, 165, 166, 155, 154, 262**

MATERIAL QUANTITY: **9000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 02/25/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23231** BUIDLING ID: **3380**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Telpochcalli School** REVIEW DATE: **3/15/2016**
ADDRESS: **2832 W. 24th Blvd.** IDPH LICENSE NO: **100-08864**

HOMOGENEOUS AREA: **22A**

MATERIAL DESCRIPTION: **12" x 12" Red w/Specks Floor Tile**

MATERIAL LOCATION: **Main Office, Rooms 155 and 156, and 2nd Floor Hall, 167, copy room, 164, 165, 166, 155, 154, 262**

MATERIAL QUANTITY: **9000**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **03/15/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23231** BUIDLING ID: **3380**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Robert DeBord**
SCHOOL NAME: **Telpochcalli School** INSPECTION DATE: **2/25/2016**
ADDRESS: **2832 W. 24th Blvd.** IDPH LICENSE NO: **100-08864**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **22C**
MATERIAL DESCRIPTION: **12" x 12" Off-white w/Beige Specks Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms 151 and 251**
MATERIAL QUANTITY: **1900** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 02/25/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23231** BUIDLING ID: **3380**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Telpochcalli School** REVIEW DATE: **3/15/2016**
ADDRESS: **2832 W. 24th Blvd.** IDPH LICENSE NO: **100-08864**

HOMOGENEOUS AREA: **22C**

MATERIAL DESCRIPTION: **12" x 12" Off-white w/Beige Specks Floor Tile**

MATERIAL LOCATION: **Rooms 151 and 251**

MATERIAL QUANTITY: **1900**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **03/15/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23231** BUIDLING ID: **3380**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Robert DeBord**
SCHOOL NAME: **Telpochcalli School** INSPECTION DATE: **2/25/2016**
ADDRESS: **2832 W. 24th Blvd.** IDPH LICENSE NO: **100-08864**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **22D**
MATERIAL DESCRIPTION: **12" x 12" Peach w/Black & White Streaks Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1st Floor Corridors -**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____

Date: 02/25/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23231** BUIDLING ID: **3380**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Telpochcalli School** REVIEW DATE: **3/15/2016**
ADDRESS: **2832 W. 24th Blvd.** IDPH LICENSE NO: **100-08864**

HOMOGENEOUS AREA: **22D**

MATERIAL DESCRIPTION: **12" x 12" Peach w/Black & White Streaks Floor Tile**

MATERIAL LOCATION: **1st Floor Corridors -**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

If identified follow O&M procedure.

Management Planner's Signature: _____ Date: **03/15/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23231** BUIDLING ID: **3380**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Robert DeBord**
SCHOOL NAME: **Telpochcalli School** INSPECTION DATE: **2/25/2016**
ADDRESS: **2832 W. 24th Blvd.** IDPH LICENSE NO: **100-08864**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **22E**
MATERIAL DESCRIPTION: **12" x 12" Tan w/Red & Brown Streaks Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1st Floor Corridors**
MATERIAL QUANTITY: **1100** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 02/25/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23231** BUIDLING ID: **3380**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Telpochcalli School** REVIEW DATE: **3/15/2016**
ADDRESS: **2832 W. 24th Blvd.** IDPH LICENSE NO: **100-08864**

HOMOGENEOUS AREA: **22E**
MATERIAL DESCRIPTION: **12" x 12" Tan w/Red & Brown Streaks Floor Tile**
MATERIAL LOCATION: **1st Floor Corridors**
MATERIAL QUANTITY: **1100** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **03/15/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23231** BUIDLING ID: **3380**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Robert DeBord**
SCHOOL NAME: **Telpochcalli School** INSPECTION DATE: **2/25/2016**
ADDRESS: **2832 W. 24th Blvd.** IDPH LICENSE NO: **100-08864**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **23A**
MATERIAL DESCRIPTION: **9"x9"Brown w/White & Dark Brown Streaks Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Engineer's Office, 2nd floor band room and offices**

MATERIAL QUANTITY: **475** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 02/25/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23231** BUIDLING ID: **3380**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Telpochcalli School** REVIEW DATE: **3/15/2016**
ADDRESS: **2832 W. 24th Blvd.** IDPH LICENSE NO: **100-08864**

HOMOGENEOUS AREA: **23A**
MATERIAL DESCRIPTION: **9"x9"Brown w/White & Dark Brown Streaks Floor Tile**
MATERIAL LOCATION: **Engineer's Office, 2nd floor band room and offices**
MATERIAL QUANTITY: **475** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **03/15/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23231** BUIDLING ID: **3380**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Robert DeBord**
SCHOOL NAME: **Telpochcalli School** INSPECTION DATE: **2/25/2016**
ADDRESS: **2832 W. 24th Blvd.** IDPH LICENSE NO: **100-08864**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **23B**
MATERIAL DESCRIPTION: **9"x9" Tan w/White & Dark Brown Streaks Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **5 ACBM with potential for significant damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **5. ACBM with potential for significant damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Engineer's Office 2nd floor band room and offices, Rm. 168**

MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 02/25/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23231** BUIDLING ID: **3380**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Telpochcalli School** REVIEW DATE: **3/15/2016**
ADDRESS: **2832 W. 24th Blvd.** IDPH LICENSE NO: **100-08864**

HOMOGENEOUS AREA: **23B**
MATERIAL DESCRIPTION: **9"x9" Tan w/White & Dark Brown Streaks Floor Tile**
MATERIAL LOCATION: **Engineer's Office 2nd floor band room and offices, Rm. 168**
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **20** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Repair as needed then follow O&M plan.

Management Planner's Signature: _____ Date: **03/15/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23231** BUIDLING ID: **3380**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Robert DeBord**
SCHOOL NAME: **Telpochcalli School** INSPECTION DATE: **2/25/2016**
ADDRESS: **2832 W. 24th Blvd.** IDPH LICENSE NO: **100-08864**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **23C**
MATERIAL DESCRIPTION: **9" x 9" Dark Brown w/White & Red Streaks Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Engineer's Office, by receiving engineer's lounge**

MATERIAL QUANTITY: **1000**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____

Date: 02/25/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23231** BUIDLING ID: **3380**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Telpochcalli School** REVIEW DATE: **3/15/2016**
ADDRESS: **2832 W. 24th Blvd.** IDPH LICENSE NO: **100-08864**

HOMOGENEOUS AREA: **23C**
MATERIAL DESCRIPTION: **9" x 9"Dark Brown w/White & Red Streaks Floor Tile**
MATERIAL LOCATION: **Engineer's Office, by receiving engineer's lounge**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **03/15/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23231** BUIDLING ID: **3380**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Robert DeBord**
SCHOOL NAME: **Telpochcalli School** INSPECTION DATE: **2/25/2016**
ADDRESS: **2832 W. 24th Blvd.** IDPH LICENSE NO: **100-08864**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **24A**
MATERIAL DESCRIPTION: **12" x 12" Red w/Specks Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Main Office, Rooms 155 and 156, 2nd Floor Hall, 167,copy rm,155,154,156,262**
MATERIAL QUANTITY: **9000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 02/25/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23231** BUIDLING ID: **3380**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Telpochcalli School** REVIEW DATE: **3/15/2016**
ADDRESS: **2832 W. 24th Blvd.** IDPH LICENSE NO: **100-08864**

HOMOGENEOUS AREA: **24A**
MATERIAL DESCRIPTION: **12" x 12" Red w/Specks Floor Tile Mastic**
MATERIAL LOCATION: **Main Office, Rooms 155 and 156, 2nd Floor Hall, 167,copy rm,155,154,156,262**
MATERIAL QUANTITY: **9000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **03/15/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23231** BUIDLING ID: **3380**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Robert DeBord**
SCHOOL NAME: **Telpochcalli School** INSPECTION DATE: **2/25/2016**
ADDRESS: **2832 W. 24th Blvd.** IDPH LICENSE NO: **100-08864**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **24B**
MATERIAL DESCRIPTION: **12" x 12" Pink Floor Tile w/Specks Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Main Office, Rooms 155 and 156, 2nd Floor Hall**

MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 02/25/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23231** BUIDLING ID: **3380**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Telpochcalli School** REVIEW DATE: **3/15/2016**
ADDRESS: **2832 W. 24th Blvd.** IDPH LICENSE NO: **100-08864**

HOMOGENEOUS AREA: **24B**
MATERIAL DESCRIPTION: **12" x 12" Pink Floor Tile w/Specks Mastic**
MATERIAL LOCATION: **Main Office, Rooms 155 and 156, 2nd Floor Hall**
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **03/15/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23231** BUIDLING ID: **3380**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Robert DeBord**
SCHOOL NAME: **Telpochcalli School** INSPECTION DATE: **2/25/2016**
ADDRESS: **2832 W. 24th Blvd.** IDPH LICENSE NO: **100-08864**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **24C**
MATERIAL DESCRIPTION: **12"x12" Off-white w/Beige Specks Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms 151 and 251**
MATERIAL QUANTITY: **1900** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 02/25/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23231** BUIDLING ID: **3380**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Telpochcalli School** REVIEW DATE: **3/15/2016**
ADDRESS: **2832 W. 24th Blvd.** IDPH LICENSE NO: **100-08864**

HOMOGENEOUS AREA: **24C**
MATERIAL DESCRIPTION: **12"x12" Off-white w/Beige Specks Floor Tile Mastic**
MATERIAL LOCATION: **Rooms 151 and 251**
MATERIAL QUANTITY: **1900** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **03/15/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23231** BUIDLING ID: **3380**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Robert DeBord**
SCHOOL NAME: **Telpochcalli School** INSPECTION DATE: **2/25/2016**
ADDRESS: **2832 W. 24th Blvd.** IDPH LICENSE NO: **100-08864**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **24D**
MATERIAL DESCRIPTION: **12" x 12" Peach w/Black & White Streaks FT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1st Floor Corridors and stair landings**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____

Date: 02/25/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23231** BUIDLING ID: **3380**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Telpochcalli School** REVIEW DATE: **3/15/2016**
ADDRESS: **2832 W. 24th Blvd.** IDPH LICENSE NO: **100-08864**

HOMOGENEOUS AREA: **24D**

MATERIAL DESCRIPTION: **12" x 12" Peach w/Black & White Streaks FT Mastic**

MATERIAL LOCATION: **1st Floor Corridors and stair landings**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

If identified follow O&M procedure.

Management Planner's Signature: _____ Date: **03/15/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23231** BUIDLING ID: **3380**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Robert DeBord**
SCHOOL NAME: **Telpochcalli School** INSPECTION DATE: **2/25/2016**
ADDRESS: **2832 W. 24th Blvd.** IDPH LICENSE NO: **100-08864**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **24E**
MATERIAL DESCRIPTION: **12"x12"Tan w/Red & Brown Streaks Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1st Floor Corridor**
MATERIAL QUANTITY: **900** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 02/25/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23231** BUIDLING ID: **3380**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Telpochcalli School** REVIEW DATE: **3/15/2016**
ADDRESS: **2832 W. 24th Blvd.** IDPH LICENSE NO: **100-08864**

HOMOGENEOUS AREA: **24E**
MATERIAL DESCRIPTION: **12"x12"Tan w/Red & Brown Streaks Floor Tile Mastic**
MATERIAL LOCATION: **1st Floor Corridor**
MATERIAL QUANTITY: **900** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **03/15/2016**

Chicago Public Schools

Carnow, Conibear and Associates 2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23231** BUILDING ID: **3380**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Robert DeBord**
SCHOOL NAME: **Telpochcalli School** INSPECTION DATE: **2/25/2016**
ADDRESS: **2832 W. 24th Blvd.** IDPH LICENSE NO: **100-08864**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **24F**
MATERIAL DESCRIPTION: **12" x 12" Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **2nd Floor Corridor**
MATERIAL QUANTITY: **1800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 02/25/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23231** BUIDLING ID: **3380**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Telpochcalli School** REVIEW DATE: **3/15/2016**
ADDRESS: **2832 W. 24th Blvd.** IDPH LICENSE NO: **100-08864**

HOMOGENEOUS AREA: **24F**
MATERIAL DESCRIPTION: **12" x 12" Floor Tile Mastic**
MATERIAL LOCATION: **2nd Floor Corridor**
MATERIAL QUANTITY: **1800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **03/15/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23231** BUIDLING ID: **3380**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Robert DeBord**
SCHOOL NAME: **Telpochcalli School** INSPECTION DATE: **2/25/2016**
ADDRESS: **2832 W. 24th Blvd.** IDPH LICENSE NO: **100-08864**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **25A**
MATERIAL DESCRIPTION: **9" x 9" Brown w/White & Dark Brn Streaks FT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Engineer's Office 2nd floor, band room and band offices**

MATERIAL QUANTITY: **475** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 02/25/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23231** BUIDLING ID: **3380**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Telpochcalli School** REVIEW DATE: **3/15/2016**
ADDRESS: **2832 W. 24th Blvd.** IDPH LICENSE NO: **100-08864**

HOMOGENEOUS AREA: **25A**
MATERIAL DESCRIPTION: **9" x 9" Brown w/White & Dark Brn Streaks FT Mastic**
MATERIAL LOCATION: **Engineer's Office 2nd floor, band room and band offices**
MATERIAL QUANTITY: **475** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **03/15/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23231** BUIDLING ID: **3380**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Robert DeBord**
SCHOOL NAME: **Telpochcalli School** INSPECTION DATE: **2/25/2016**
ADDRESS: **2832 W. 24th Blvd.** IDPH LICENSE NO: **100-08864**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **25B**
MATERIAL DESCRIPTION: **9" x 9" Tan w/White & Dark Brown Streaks FT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Engineer's Office 2nd floor, band room and band offices**

MATERIAL QUANTITY: **250** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 02/25/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23231** BUIDLING ID: **3380**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Telpochcalli School** REVIEW DATE: **3/15/2016**
ADDRESS: **2832 W. 24th Blvd.** IDPH LICENSE NO: **100-08864**

HOMOGENEOUS AREA: **25B**
MATERIAL DESCRIPTION: **9" x 9" Tan w/White & Dark Brown Streaks FT Mastic**
MATERIAL LOCATION: **Engineer's Office 2nd floor, band room and band offices**
MATERIAL QUANTITY: **250** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **03/15/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23231** BUIDLING ID: **3380**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Robert DeBord**
SCHOOL NAME: **Telpochcalli School** INSPECTION DATE: **2/25/2016**
ADDRESS: **2832 W. 24th Blvd.** IDPH LICENSE NO: **100-08864**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **25C**
MATERIAL DESCRIPTION: **9"x9" Dark Brown w/White & Red Streaks FT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Engineers office by receiving and eng. Lounge**

MATERIAL QUANTITY: **250** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 02/25/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23231** BUIDLING ID: **3380**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Telpochcalli School** REVIEW DATE: **3/15/2016**
ADDRESS: **2832 W. 24th Blvd.** IDPH LICENSE NO: **100-08864**

HOMOGENEOUS AREA: **25C**
MATERIAL DESCRIPTION: **9"x9" Dark Brown w/White & Red Streaks FT Mastic**
MATERIAL LOCATION: **Engineers office by receiving and eng. Lounge**
MATERIAL QUANTITY: **250** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **03/15/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23231** BUIDLING ID: **3380**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Robert DeBord**
SCHOOL NAME: **Telpochcalli School** INSPECTION DATE: **2/25/2016**
ADDRESS: **2832 W. 24th Blvd.** IDPH LICENSE NO: **100-08864**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **50**
MATERIAL DESCRIPTION: **Window Caulk**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Throughout Building, Main Office, Assistants Office, Engineers Office**
MATERIAL QUANTITY: **14000** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: _____ Date: 02/25/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23231** BUIDLING ID: **3380**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Telpochcalli School** REVIEW DATE: **3/15/2016**
ADDRESS: **2832 W. 24th Blvd.** IDPH LICENSE NO: **100-08864**

HOMOGENEOUS AREA: **50**
MATERIAL DESCRIPTION: **Window Caulk**
MATERIAL LOCATION: **Throughout Building, Main Office, Assistants Office, Engineers Office**
MATERIAL QUANTITY: **14000** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **03/15/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23231** BUIDLING ID: **3380**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Robert DeBord**
SCHOOL NAME: **Telpochcalli School** INSPECTION DATE: **2/25/2016**
ADDRESS: **2832 W. 24th Blvd.** IDPH LICENSE NO: **100-08864**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **51**
MATERIAL DESCRIPTION: **Stage Lighting Electrical Insulation**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Auditorium**

MATERIAL QUANTITY: **100**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____

Date: 02/25/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23231** BUIDLING ID: **3380**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Telpochcalli School** REVIEW DATE: **3/15/2016**
ADDRESS: **2832 W. 24th Blvd.** IDPH LICENSE NO: **100-08864**

HOMOGENEOUS AREA: **51**

MATERIAL DESCRIPTION: **Stage Lighting Electrical Insulation**

MATERIAL LOCATION: **Auditorium**

MATERIAL QUANTITY: **100**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **03/15/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23231** BUIDLING ID: **3380**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Robert DeBord**
SCHOOL NAME: **Telpochcalli School** INSPECTION DATE: **2/25/2016**
ADDRESS: **2832 W. 24th Blvd.** IDPH LICENSE NO: **100-08864**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **52**
MATERIAL DESCRIPTION: **Incinerator Interior Insulation**
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Boiler Room**
MATERIAL QUANTITY: **250** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 02/25/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23231** BUIDLING ID: **3380**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Telpochcalli School** REVIEW DATE: **3/15/2016**
ADDRESS: **2832 W. 24th Blvd.** IDPH LICENSE NO: **100-08864**

HOMOGENEOUS AREA: **52**

MATERIAL DESCRIPTION: **Incinerator Interior Insulation**

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY: **250**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **03/15/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23231** BUIDLING ID: **3380**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Robert DeBord**
SCHOOL NAME: **Telpochcalli School** INSPECTION DATE: **2/25/2016**
ADDRESS: **2832 W. 24th Blvd.** IDPH LICENSE NO: **100-08864**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **54**
MATERIAL DESCRIPTION: **Window Glaze**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Interior, Rooms 107,118, Boiler Room**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **02/25/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23231** BUIDLING ID: **3380**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Telpochcalli School** REVIEW DATE: **3/15/2016**
ADDRESS: **2832 W. 24th Blvd.** IDPH LICENSE NO: **100-08864**

HOMOGENEOUS AREA: **54**

MATERIAL DESCRIPTION: **Window Glaze**

MATERIAL LOCATION: **Interior, Rooms 107,118, Boiler Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **03/15/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23231** BUILDING ID: **3380**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Robert DeBord**
SCHOOL NAME: **Telpochcalli School** INSPECTION DATE: **2/25/2016**
ADDRESS: **2832 W. 24th Blvd.** IDPH LICENSE NO: **100-08864**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **55**
MATERIAL DESCRIPTION: **Window Caulk - Not AHERA**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Chrysotile** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **Low**

MATERIAL LOCATION: **Building Exterior**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **02/25/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23231** BUIDLING ID: **3380**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Telpochcalli School** REVIEW DATE: **3/15/2016**
ADDRESS: **2832 W. 24th Blvd.** IDPH LICENSE NO: **100-08864**

HOMOGENEOUS AREA: **55**

MATERIAL DESCRIPTION: **Window Caulk - Not AHERA**

MATERIAL LOCATION: **Building Exterior**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **03/15/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23231** BUILDING ID: **3380**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Robert DeBord**
SCHOOL NAME: **Telpochcalli School** INSPECTION DATE: **2/25/2016**
ADDRESS: **2832 W. 24th Blvd.** IDPH LICENSE NO: **100-08864**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **56**
MATERIAL DESCRIPTION: **Window Glaze - Not AHERA**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Chrysotile** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Building Exterior**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **02/25/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23231** BUIDLING ID: **3380**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Telpochcalli School** REVIEW DATE: **3/15/2016**
ADDRESS: **2832 W. 24th Blvd.** IDPH LICENSE NO: **100-08864**

HOMOGENEOUS AREA: **56**

MATERIAL DESCRIPTION: **Window Glaze - Not AHERA**

MATERIAL LOCATION: **Building Exterior**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **03/15/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23231** BUILDING ID: **3380**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Robert DeBord**
SCHOOL NAME: **Telpochcalli School** INSPECTION DATE: **2/25/2016**
ADDRESS: **2832 W. 24th Blvd.** IDPH LICENSE NO: **100-08864**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **57**
MATERIAL DESCRIPTION: **Exterior Brick - Non AHERA**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Building Exterior**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **02/25/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23231** BUIDLING ID: **3380**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Telpochcalli School** REVIEW DATE: **3/15/2016**
ADDRESS: **2832 W. 24th Blvd.** IDPH LICENSE NO: **100-08864**

HOMOGENEOUS AREA: **57**

MATERIAL DESCRIPTION: **Exterior Brick - Non AHERA**

MATERIAL LOCATION: **Building Exterior**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **03/15/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23231** BUILDING ID: **3380**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Robert DeBord**
SCHOOL NAME: **Telpochcalli School** INSPECTION DATE: **2/25/2016**
ADDRESS: **2832 W. 24th Blvd.** IDPH LICENSE NO: **100-08864**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **58**
MATERIAL DESCRIPTION: **Brick Mortar - Not AHERA**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Building Exterior**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **02/25/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23231** BUIDLING ID: **3380**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Telpochcalli School** REVIEW DATE: **3/15/2016**
ADDRESS: **2832 W. 24th Blvd.** IDPH LICENSE NO: **100-08864**

HOMOGENEOUS AREA: **58**

MATERIAL DESCRIPTION: **Brick Mortar - Not AHERA**

MATERIAL LOCATION: **Building Exterior**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **03/15/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23231** BUILDING ID: **3380**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Robert DeBord**
SCHOOL NAME: **Telpochcalli School** INSPECTION DATE: **2/25/2016**
ADDRESS: **2832 W. 24th Blvd.** IDPH LICENSE NO: **100-08864**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **59**
MATERIAL DESCRIPTION: **Base Stone Block - Not AHERA**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Building Exterior**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **02/25/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23231** BUIDLING ID: **3380**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Telpochcalli School** REVIEW DATE: **3/15/2016**
ADDRESS: **2832 W. 24th Blvd.** IDPH LICENSE NO: **100-08864**

HOMOGENEOUS AREA: **59**

MATERIAL DESCRIPTION: **Base Stone Block - Not AHERA**

MATERIAL LOCATION: **Building Exterior**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **03/15/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23231** BUIDLING ID: **3380**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Robert DeBord**
SCHOOL NAME: **Telpochcalli School** INSPECTION DATE: **2/25/2016**
ADDRESS: **2832 W. 24th Blvd.** IDPH LICENSE NO: **100-08864**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **60**
MATERIAL DESCRIPTION: **Base Stone Block Mortar - Not AHERA**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Building Exterior**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 02/25/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23231** BUIDLING ID: **3380**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Telpochcalli School** REVIEW DATE: **3/15/2016**
ADDRESS: **2832 W. 24th Blvd.** IDPH LICENSE NO: **100-08864**

HOMOGENEOUS AREA: **60**

MATERIAL DESCRIPTION: **Base Stone Block Mortar - Not AHERA**

MATERIAL LOCATION: **Building Exterior**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **03/15/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23231** BUIDLING ID: **3380**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Robert DeBord**
SCHOOL NAME: **Telpochcalli School** INSPECTION DATE: **2/25/2016**
ADDRESS: **2832 W. 24th Blvd.** IDPH LICENSE NO: **100-08864**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **61**
MATERIAL DESCRIPTION: **Exterior Door Caulk - Not AHERA**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Chrysotile** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Building Exterior**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **02/25/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23231** BUIDLING ID: **3380**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Telpochcalli School** REVIEW DATE: **3/15/2016**
ADDRESS: **2832 W. 24th Blvd.** IDPH LICENSE NO: **100-08864**

HOMOGENEOUS AREA: **61**

MATERIAL DESCRIPTION: **Exterior Door Caulk - Not AHERA**

MATERIAL LOCATION: **Building Exterior**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **03/15/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23231** BUIDLING ID: **3380**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Robert DeBord**
SCHOOL NAME: **Telpochcalli School** INSPECTION DATE: **2/25/2016**
ADDRESS: **2832 W. 24th Blvd.** IDPH LICENSE NO: **100-08864**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **62**
MATERIAL DESCRIPTION: **Chimney Brick**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Interior**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed 2016**

Inspector's Signature: _____ Date: **02/25/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23231** BUIDLING ID: **3380**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Telpochcalli School** REVIEW DATE: **3/15/2016**
ADDRESS: **2832 W. 24th Blvd.** IDPH LICENSE NO: **100-08864**

HOMOGENEOUS AREA: **62**

MATERIAL DESCRIPTION: **Chimney Brick**

MATERIAL LOCATION: **Interior**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

If identified follow O&M procedure.

Management Planner's Signature: _____ Date: **03/15/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23231** BUIDLING ID: **3380**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Robert DeBord**
SCHOOL NAME: **Telpochcalli School** INSPECTION DATE: **2/25/2016**
ADDRESS: **2832 W. 24th Blvd.** IDPH LICENSE NO: **100-08864**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **63**
MATERIAL DESCRIPTION: **Chimney Brick Mortar**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Interior**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed 2016**

Inspector's Signature: _____

Date: 02/25/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23231** BUIDLING ID: **3380**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Telpochcalli School** REVIEW DATE: **3/15/2016**
ADDRESS: **2832 W. 24th Blvd.** IDPH LICENSE NO: **100-08864**

HOMOGENEOUS AREA: **63**

MATERIAL DESCRIPTION: **Chimney Brick Mortar**

MATERIAL LOCATION: **Interior**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

If identified follow O&M procedure.

Management Planner's Signature: _____ Date: **03/15/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23231** BUIDLING ID: **3380**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Robert DeBord**
SCHOOL NAME: **Telpochcalli School** INSPECTION DATE: **2/25/2016**
ADDRESS: **2832 W. 24th Blvd.** IDPH LICENSE NO: **100-08864**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **64**
MATERIAL DESCRIPTION: **Chimney Refracting Brick**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Interior**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed 2016**

Inspector's Signature: _____ Date: **02/25/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23231** BUIDLING ID: **3380**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Telpochcalli School** REVIEW DATE: **3/15/2016**
ADDRESS: **2832 W. 24th Blvd.** IDPH LICENSE NO: **100-08864**

HOMOGENEOUS AREA: **64**

MATERIAL DESCRIPTION: **Chimney Refracting Brick**

MATERIAL LOCATION: **Interior**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

If identified follow O&M procedure.

Management Planner's Signature: _____ Date: **03/15/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23231** BUIDLING ID: **3380**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Robert DeBord**
SCHOOL NAME: **Telpochcalli School** INSPECTION DATE: **2/25/2016**
ADDRESS: **2832 W. 24th Blvd.** IDPH LICENSE NO: **100-08864**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **66**
MATERIAL DESCRIPTION: **Roof Flashing - Not AHERA**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Chrysotile** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Auditorium Roof**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **02/25/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23231** BUIDLING ID: **3380**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Telpochcalli School** REVIEW DATE: **3/15/2016**
ADDRESS: **2832 W. 24th Blvd.** IDPH LICENSE NO: **100-08864**

HOMOGENEOUS AREA: **66**

MATERIAL DESCRIPTION: **Roof Flashing - Not AHERA**

MATERIAL LOCATION: **Auditorium Roof**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **03/15/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23231** BUIDLING ID: **3380**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Robert DeBord**
SCHOOL NAME: **Telpochcalli School** INSPECTION DATE: **2/25/2016**
ADDRESS: **2832 W. 24th Blvd.** IDPH LICENSE NO: **100-08864**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **67**
MATERIAL DESCRIPTION: **Lower Roof Parapet Wall Brick - Not AHERA**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Auditorium Roof**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **02/25/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23231** BUIDLING ID: **3380**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Telpochcalli School** REVIEW DATE: **3/15/2016**
ADDRESS: **2832 W. 24th Blvd.** IDPH LICENSE NO: **100-08864**

HOMOGENEOUS AREA: **67**

MATERIAL DESCRIPTION: **Lower Roof Parapet Wall Brick - Not AHERA**

MATERIAL LOCATION: **Auditorium Roof**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **03/15/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23231** BUIDLING ID: **3380**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Robert DeBord**
SCHOOL NAME: **Telpochcalli School** INSPECTION DATE: **2/25/2016**
ADDRESS: **2832 W. 24th Blvd.** IDPH LICENSE NO: **100-08864**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **68**
MATERIAL DESCRIPTION: **Lower Roof Parapet Wall Brick Mortar - Not AHERA**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Auditorium Roof**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **02/25/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23231** BUIDLING ID: **3380**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Telpochcalli School** REVIEW DATE: **3/15/2016**
ADDRESS: **2832 W. 24th Blvd.** IDPH LICENSE NO: **100-08864**

HOMOGENEOUS AREA: **68**

MATERIAL DESCRIPTION: **Lower Roof Parapet Wall Brick Mortar - Not AHERA**

MATERIAL LOCATION: **Auditorium Roof**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **03/15/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23231** BUILDING ID: **3380**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Robert DeBord**
SCHOOL NAME: **Telpochcalli School** INSPECTION DATE: **2/25/2016**
ADDRESS: **2832 W. 24th Blvd.** IDPH LICENSE NO: **100-08864**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **69**
MATERIAL DESCRIPTION: **Kitchen Exhaust Vent Caulk - Not AHERA**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Roof**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **02/25/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23231** BUIDLING ID: **3380**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Telpochcalli School** REVIEW DATE: **3/15/2016**
ADDRESS: **2832 W. 24th Blvd.** IDPH LICENSE NO: **100-08864**

HOMOGENEOUS AREA: **69**

MATERIAL DESCRIPTION: **Kitchen Exhaust Vent Caulk - Not AHERA**

MATERIAL LOCATION: **Roof**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **03/15/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23231** BUILDING ID: **3380**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Robert DeBord**
SCHOOL NAME: **Telpochcalli School** INSPECTION DATE: **2/25/2016**
ADDRESS: **2832 W. 24th Blvd.** IDPH LICENSE NO: **100-08864**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **70**
MATERIAL DESCRIPTION: **Window Glaze - Not AHERA**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Exterior Skylight of Main Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____

Date: 02/25/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23231** BUIDLING ID: **3380**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Telpochcalli School** REVIEW DATE: **3/15/2016**
ADDRESS: **2832 W. 24th Blvd.** IDPH LICENSE NO: **100-08864**

HOMOGENEOUS AREA: **70**

MATERIAL DESCRIPTION: **Window Glaze - Not AHERA**

MATERIAL LOCATION: **Exterior Skylight of Main Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **03/15/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23231** BUILDING ID: **3380**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Robert DeBord**
SCHOOL NAME: **Telpochcalli School** INSPECTION DATE: **2/25/2016**
ADDRESS: **2832 W. 24th Blvd.** IDPH LICENSE NO: **100-08864**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **71**
MATERIAL DESCRIPTION: **Window Caulk - Not AHERA**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Exterior Skylight of Main Building**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **02/25/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23231** BUIDLING ID: **3380**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Telpochcalli School** REVIEW DATE: **3/15/2016**
ADDRESS: **2832 W. 24th Blvd.** IDPH LICENSE NO: **100-08864**

HOMOGENEOUS AREA: **71**

MATERIAL DESCRIPTION: **Window Caulk - Not AHERA**

MATERIAL LOCATION: **Exterior Skylight of Main Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **03/15/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23231** BUIDLING ID: **3380**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Robert DeBord**
SCHOOL NAME: **Telpochcalli School** INSPECTION DATE: **2/25/2016**
ADDRESS: **2832 W. 24th Blvd.** IDPH LICENSE NO: **100-08864**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **72**
MATERIAL DESCRIPTION: **Aircell Duct Insulation**
HISTORICAL AHERA DAMAGE CATEGORY **7 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1st Floor Hallway Ductwork**
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 02/25/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23231** BUIDLING ID: **3380**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Telpochcalli School** REVIEW DATE: **3/15/2016**
ADDRESS: **2832 W. 24th Blvd.** IDPH LICENSE NO: **100-08864**

HOMOGENEOUS AREA: **72**
MATERIAL DESCRIPTION: **Aircell Duct Insulation**
MATERIAL LOCATION: **1st Floor Hallway Ductwork**
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **03/15/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23231** BUIDLING ID: **3380**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Robert DeBord**
SCHOOL NAME: **Telpochcalli School** INSPECTION DATE: **2/25/2016**
ADDRESS: **2832 W. 24th Blvd.** IDPH LICENSE NO: **100-08864**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **73**
MATERIAL DESCRIPTION: **Aircell Pipe Insulation**
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Engine Rms and Rm 151**
MATERIAL QUANTITY: **160** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: _____ Date: 02/25/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23231** BUIDLING ID: **3380**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Telpochcalli School** REVIEW DATE: **3/15/2016**
ADDRESS: **2832 W. 24th Blvd.** IDPH LICENSE NO: **100-08864**

HOMOGENEOUS AREA: **73**

MATERIAL DESCRIPTION: **Aircell Pipe Insulation**

MATERIAL LOCATION: **Engine Rms and Rm 151**

MATERIAL QUANTITY: **160**

MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **03/15/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23231** BUIDLING ID: **3380**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Robert DeBord**
SCHOOL NAME: **Telpochcalli School** INSPECTION DATE: **2/25/2016**
ADDRESS: **2832 W. 24th Blvd.** IDPH LICENSE NO: **100-08864**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **74**
MATERIAL DESCRIPTION: **Magblock Pipe Insulation**
HISTORICAL AHERA DAMAGE CATEGORY **7 Damaged or significantly damaged friable thermal system insulating ACBM**
HISTORICAL DAMAGE REASON: **Deterioration
Physical Damage
Water**
HISTORICAL RESPONSE ACTION: **Remove**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Engine Rooms and Tunnel**

MATERIAL QUANTITY: **1200**

MATERIAL UNITS: **LF**

DAMAGE QUANTITY:

DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: _____

Date: **02/25/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23231** BUIDLING ID: **3380**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Telpochcalli School** REVIEW DATE: **3/15/2016**
ADDRESS: **2832 W. 24th Blvd.** IDPH LICENSE NO: **100-08864**

HOMOGENEOUS AREA: **74**

MATERIAL DESCRIPTION: **Magblock Pipe Insulation**

MATERIAL LOCATION: **Engine Rooms and Tunnel**

MATERIAL QUANTITY: **1200**

MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Remove

Comments:

Management Planner's Signature: _____ Date: **03/15/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23231** BUIDLING ID: **3380**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Robert DeBord**
SCHOOL NAME: **Telpochcalli School** INSPECTION DATE: **2/25/2016**
ADDRESS: **2832 W. 24th Blvd.** IDPH LICENSE NO: **100-08864**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **75**
MATERIAL DESCRIPTION: **Hard Fittings on Aircell Pipe Insulation**
HISTORICAL AHERA DAMAGE CATEGORY **7 Damaged or significantly damaged friable thermal system insulating ACBM**
HISTORICAL DAMAGE REASON: **Deterioration
Physical Damage
Water**
HISTORICAL RESPONSE ACTION: **Remove**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Engine Rm and Room 151**

MATERIAL QUANTITY: **250** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: _____

Date: **02/25/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23231** BUIDLING ID: **3380**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Telpochcalli School** REVIEW DATE: **3/15/2016**
ADDRESS: **2832 W. 24th Blvd.** IDPH LICENSE NO: **100-08864**

HOMOGENEOUS AREA: **75**

MATERIAL DESCRIPTION: **Hard Fittings on Aircell Pipe Insulation**

MATERIAL LOCATION: **Engine Rm and Room 151**

MATERIAL QUANTITY: **250** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Remove

Comments:

Management Planner's Signature: _____ Date: **03/15/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23231** BUIDLING ID: **3380**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Robert DeBord**
SCHOOL NAME: **Telpochcalli School** INSPECTION DATE: **2/25/2016**
ADDRESS: **2832 W. 24th Blvd.** IDPH LICENSE NO: **100-08864**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **76**
MATERIAL DESCRIPTION: **1' x 1' White w/ Holes Panels**
HISTORICAL AHERA DAMAGE CATEGORY **Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **band room offices**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed 2016**

Inspector's Signature: _____

Date: 02/25/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23231** BUIDLING ID: **3380**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Telpochcalli School** REVIEW DATE: **3/15/2016**
ADDRESS: **2832 W. 24th Blvd.** IDPH LICENSE NO: **100-08864**

HOMOGENEOUS AREA: **76**

MATERIAL DESCRIPTION: **1' x 1' White w/ Holes Panels**

MATERIAL LOCATION: **band room offices**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

If identified follow O&M procedure.

Management Planner's Signature: _____ Date: **03/15/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23231** BUIDLING ID: **3380**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Robert DeBord**
SCHOOL NAME: **Telpochcalli School** INSPECTION DATE: **2/25/2016**
ADDRESS: **2832 W. 24th Blvd.** IDPH LICENSE NO: **100-08864**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **77**
MATERIAL DESCRIPTION: **Plaster**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout Building/ walls abd ceilings**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **02/25/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23231** BUIDLING ID: **3380**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Telpochcalli School** REVIEW DATE: **3/15/2016**
ADDRESS: **2832 W. 24th Blvd.** IDPH LICENSE NO: **100-08864**

HOMOGENEOUS AREA: **77**

MATERIAL DESCRIPTION: **Plaster**

MATERIAL LOCATION: **Throughout Building/ walls abd ceilings**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **03/15/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23231** BUIDLING ID: **3380**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Robert DeBord**
SCHOOL NAME: **Telpochcalli School** INSPECTION DATE: **2/25/2016**
ADDRESS: **2832 W. 24th Blvd.** IDPH LICENSE NO: **100-08864**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **78**
MATERIAL DESCRIPTION: **4" Black vinyl baseboard**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **Low**

MATERIAL LOCATION: **engineers lounge, receiving office, 168, band room/office, store room, entrance**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Not observed 2016**

Inspector's Signature: _____ Date: **02/25/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23231** BUIDLING ID: **3380**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Telpochcalli School** REVIEW DATE: **3/15/2016**
ADDRESS: **2832 W. 24th Blvd.** IDPH LICENSE NO: **100-08864**

HOMOGENEOUS AREA: **78**
MATERIAL DESCRIPTION: **4" Black vinyl baseboard**
MATERIAL LOCATION: **engineers lounge, receiving office, 168, band room/office, store room, entrance**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

If identified follow O&M procedure.

Management Planner's Signature: _____ Date: **03/15/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23231** BUIDLING ID: **3380**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Robert DeBord**
SCHOOL NAME: **Telpochcalli School** INSPECTION DATE: **2/25/2016**
ADDRESS: **2832 W. 24th Blvd.** IDPH LICENSE NO: **100-08864**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **79**
MATERIAL DESCRIPTION: **4" black baseboard adhesive**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **Low**

MATERIAL LOCATION: **engineers lounge, receiving office, 168, band room/office, store room, entrance**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Not observed 2016**

Inspector's Signature: _____ Date: **02/25/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23231** BUIDLING ID: **3380**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Telpochcalli School** REVIEW DATE: **3/15/2016**
ADDRESS: **2832 W. 24th Blvd.** IDPH LICENSE NO: **100-08864**

HOMOGENEOUS AREA: **79**

MATERIAL DESCRIPTION: **4" black baseboard adhesive**

MATERIAL LOCATION: **engineers lounge, receiving office, 168, band room/office, store room, entrance**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

If identified follow O&M procedure.

Management Planner's Signature: _____ Date: **03/15/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23231** BUIDLING ID: **3380**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Robert DeBord**
SCHOOL NAME: **Telpochcalli School** INSPECTION DATE: **2/25/2016**
ADDRESS: **2832 W. 24th Blvd.** IDPH LICENSE NO: **100-08864**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **80**
MATERIAL DESCRIPTION: **4" grey vinyl baseboard**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **168, band room office 2/3**
MATERIAL QUANTITY: **30** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: DAMAGE UNITS: **LF**
COMMENTS:

Inspector's Signature: _____ Date: 02/25/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23231** BUIDLING ID: **3380**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Telpochcalli School** REVIEW DATE: **3/15/2016**
ADDRESS: **2832 W. 24th Blvd.** IDPH LICENSE NO: **100-08864**

HOMOGENEOUS AREA: **80**

MATERIAL DESCRIPTION: **4" grey vinyl baseboard**

MATERIAL LOCATION: **168, band room office 2/3**

MATERIAL QUANTITY: **30**

MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **03/15/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23231** BUIDLING ID: **3380**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Robert DeBord**
SCHOOL NAME: **Telpochcalli School** INSPECTION DATE: **2/25/2016**
ADDRESS: **2832 W. 24th Blvd.** IDPH LICENSE NO: **100-08864**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **81**
MATERIAL DESCRIPTION: **4" grey vinyl baseboard adhesive**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **168, band room office2/3**
MATERIAL QUANTITY: **30** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: DAMAGE UNITS: **LF**
COMMENTS:

Inspector's Signature: _____ Date: 02/25/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23231** BUIDLING ID: **3380**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Telpochcalli School** REVIEW DATE: **3/15/2016**
ADDRESS: **2832 W. 24th Blvd.** IDPH LICENSE NO: **100-08864**

HOMOGENEOUS AREA: **81**

MATERIAL DESCRIPTION: **4" grey vinyl baseboard adhesive**

MATERIAL LOCATION: **168, band room office2/3**

MATERIAL QUANTITY: **30**

MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **03/15/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23231** BUIDLING ID: **3380**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Robert DeBord**
SCHOOL NAME: **Telpochcalli School** INSPECTION DATE: **2/25/2016**
ADDRESS: **2832 W. 24th Blvd.** IDPH LICENSE NO: **100-08864**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **82**
MATERIAL DESCRIPTION: **6" brown vinyl baseboard**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **Low**

MATERIAL LOCATION: **167, 166, main office, 154-156, 152, stairlanding, 262**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Not observed 2016**

Inspector's Signature: _____ Date: **02/25/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23231** BUIDLING ID: **3380**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Telpochcalli School** REVIEW DATE: **3/15/2016**
ADDRESS: **2832 W. 24th Blvd.** IDPH LICENSE NO: **100-08864**

HOMOGENEOUS AREA: **82**

MATERIAL DESCRIPTION: **6" brown vinyl baseboard**

MATERIAL LOCATION: **167, 166, main office, 154-156, 152, stairlanding, 262**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

If identified follow O&M procedure.

Management Planner's Signature: _____ Date: **03/15/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23231** BUIDLING ID: **3380**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Robert DeBord**
SCHOOL NAME: **Telpochcalli School** INSPECTION DATE: **2/25/2016**
ADDRESS: **2832 W. 24th Blvd.** IDPH LICENSE NO: **100-08864**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **83**
MATERIAL DESCRIPTION: **6" brown vinyl baseboard adhesive**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **Low**

MATERIAL LOCATION: **167, 166, main office, 154-156, 152, stairlanding, 262**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Not observed 2016**

Inspector's Signature: _____ Date: 02/25/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23231** BUIDLING ID: **3380**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Telpochcalli School** REVIEW DATE: **3/15/2016**
ADDRESS: **2832 W. 24th Blvd.** IDPH LICENSE NO: **100-08864**

HOMOGENEOUS AREA: **83**

MATERIAL DESCRIPTION: **6" brown vinyl baseboard adhesive**

MATERIAL LOCATION: **167, 166, main office, 154-156, 152, stairlanding, 262**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

If identified follow O&M procedure.

Management Planner's Signature: _____ Date: **03/15/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23231** BUIDLING ID: **3380**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Robert DeBord**
SCHOOL NAME: **Telpochcalli School** INSPECTION DATE: **2/25/2016**
ADDRESS: **2832 W. 24th Blvd.** IDPH LICENSE NO: **100-08864**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **84**
MATERIAL DESCRIPTION: **1x1 deep fissured ceiling tile**
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **168, band room and offices 1-4, storage 167 166 main office**
MATERIAL QUANTITY: **1600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 02/25/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23231** BUIDLING ID: **3380**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Telpochcalli School** REVIEW DATE: **3/15/2016**
ADDRESS: **2832 W. 24th Blvd.** IDPH LICENSE NO: **100-08864**

HOMOGENEOUS AREA: **84**

MATERIAL DESCRIPTION: **1x1 deep fissured ceiling tile**

MATERIAL LOCATION: **168, band room and offices 1-4, storage 167 166 main office**

MATERIAL QUANTITY: **1600**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **03/15/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23231** BUIDLING ID: **3380**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Robert DeBord**
SCHOOL NAME: **Telpochcalli School** INSPECTION DATE: **2/25/2016**
ADDRESS: **2832 W. 24th Blvd.** IDPH LICENSE NO: **100-08864**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **85**
MATERIAL DESCRIPTION: **1x1 deep fissured ceiling tile adhesive**
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **168, band room and offices 1-4, storage 167 166 main office**
MATERIAL QUANTITY: **1600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 02/25/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23231** BUIDLING ID: **3380**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Telpochcalli School** REVIEW DATE: **3/15/2016**
ADDRESS: **2832 W. 24th Blvd.** IDPH LICENSE NO: **100-08864**

HOMOGENEOUS AREA: **85**
MATERIAL DESCRIPTION: **1x1 deep fissured ceiling tile adhesive**
MATERIAL LOCATION: **168, band room and offices 1-4, storage 167 166 main office**
MATERIAL QUANTITY: **1600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **03/15/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23231** BUIDLING ID: **3380**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Robert DeBord**
SCHOOL NAME: **Telpochcalli School** INSPECTION DATE: **2/25/2016**
ADDRESS: **2832 W. 24th Blvd.** IDPH LICENSE NO: **100-08864**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **86**
MATERIAL DESCRIPTION: **12x12 lt beige/white floor tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **251**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 02/25/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23231** BUIDLING ID: **3380**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Telpochcalli School** REVIEW DATE: **3/15/2016**
ADDRESS: **2832 W. 24th Blvd.** IDPH LICENSE NO: **100-08864**

HOMOGENEOUS AREA: **86**

MATERIAL DESCRIPTION: **12x12 lt beige/white floor tile**

MATERIAL LOCATION: **251**

MATERIAL QUANTITY: **1000**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **03/15/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23231** BUIDLING ID: **3380**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Robert DeBord**
SCHOOL NAME: **Telpochcalli School** INSPECTION DATE: **2/25/2016**
ADDRESS: **2832 W. 24th Blvd.** IDPH LICENSE NO: **100-08864**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **87**
MATERIAL DESCRIPTION: **12x12 lt beige/white floor tile mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **251**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 02/25/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23231** BUIDLING ID: **3380**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Telpochcalli School** REVIEW DATE: **3/15/2016**
ADDRESS: **2832 W. 24th Blvd.** IDPH LICENSE NO: **100-08864**

HOMOGENEOUS AREA: **87**
MATERIAL DESCRIPTION: **12x12 lt beige/white floor tile mastic**
MATERIAL LOCATION: **251**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **03/15/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23231** BUIDLING ID: **3380**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Robert DeBord**
SCHOOL NAME: **Telpochcalli School** INSPECTION DATE: **2/25/2016**
ADDRESS: **2832 W. 24th Blvd.** IDPH LICENSE NO: **100-08864**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **88**
MATERIAL DESCRIPTION: **sink undercoating**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **156a**
MATERIAL QUANTITY: **4** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 02/25/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23231** BUIDLING ID: **3380**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Telpochcalli School** REVIEW DATE: **3/15/2016**
ADDRESS: **2832 W. 24th Blvd.** IDPH LICENSE NO: **100-08864**

HOMOGENEOUS AREA: **88**

MATERIAL DESCRIPTION: **sink undercoating**

MATERIAL LOCATION: **156a**

MATERIAL QUANTITY: **4**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **03/15/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23231** BUIDLING ID: **3380**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Robert DeBord**
SCHOOL NAME: **Telpochcalli School** INSPECTION DATE: **2/25/2016**
ADDRESS: **2832 W. 24th Blvd.** IDPH LICENSE NO: **100-08864**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **89**
MATERIAL DESCRIPTION: **maroon carpet mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **257-258**
MATERIAL QUANTITY: **2040** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 02/25/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23231** BUIDLING ID: **3380**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Telpochcalli School** REVIEW DATE: **3/15/2016**
ADDRESS: **2832 W. 24th Blvd.** IDPH LICENSE NO: **100-08864**

HOMOGENEOUS AREA: **89**
MATERIAL DESCRIPTION: **maroon carpet mastic**
MATERIAL LOCATION: **257-258**
MATERIAL QUANTITY: **2040** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **03/15/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23231** BUIDLING ID: **3380**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Robert DeBord**
SCHOOL NAME: **Telpochcalli School** INSPECTION DATE: **2/25/2016**
ADDRESS: **2832 W. 24th Blvd.** IDPH LICENSE NO: **100-08864**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **90**
MATERIAL DESCRIPTION: **12x12 maroon floor tile - REMOVED**
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **2nd floor cooridor checkeboard**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____

Date: 02/25/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23231** BUIDLING ID: **3380**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Telpochcalli School** REVIEW DATE: **3/15/2016**
ADDRESS: **2832 W. 24th Blvd.** IDPH LICENSE NO: **100-08864**

HOMOGENEOUS AREA: **90**

MATERIAL DESCRIPTION: **12x12 maroon floor tile - REMOVED**

MATERIAL LOCATION: **2nd floor cooridor checkeboard**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

If identified follow O&M procedure.

Management Planner's Signature: _____ Date: **03/15/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23231** BUIDLING ID: **3380**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Robert DeBord**
SCHOOL NAME: **Telpochcalli School** INSPECTION DATE: **2/25/2016**
ADDRESS: **2832 W. 24th Blvd.** IDPH LICENSE NO: **100-08864**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **91**
MATERIAL DESCRIPTION: **12x12 beige with maroon floor tile - REMOVED**
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **2nd floor cooridor checkboard**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____

Date: 02/25/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23231** BUIDLING ID: **3380**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Telpochcalli School** REVIEW DATE: **3/15/2016**
ADDRESS: **2832 W. 24th Blvd.** IDPH LICENSE NO: **100-08864**

HOMOGENEOUS AREA: **91**

MATERIAL DESCRIPTION: **12x12 beige with maroon floor tile - REMOVED**

MATERIAL LOCATION: **2nd floor cooridor checkboard**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

If identified follow O&M procedure.

Management Planner's Signature: _____ Date: **03/15/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23231** BUIDLING ID: **3380**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Robert DeBord**
SCHOOL NAME: **Telpochcalli School** INSPECTION DATE: **2/25/2016**
ADDRESS: **2832 W. 24th Blvd.** IDPH LICENSE NO: **100-08864**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **92**
MATERIAL DESCRIPTION: **mastic associated with marron tile and beige - REMOVED**
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **2nd floor cooridor checkerboard**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____

Date: 02/25/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23231** BUIDLING ID: **3380**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Telpochcalli School** REVIEW DATE: **3/15/2016**
ADDRESS: **2832 W. 24th Blvd.** IDPH LICENSE NO: **100-08864**

HOMOGENEOUS AREA: **92**

MATERIAL DESCRIPTION: **mastic associated with marron tile and beige - REMOVED**

MATERIAL LOCATION: **2nd floor cooridor checkerboard**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

If identified follow O&M procedure.

Management Planner's Signature: _____ Date: **03/15/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23231** BUIDLING ID: **3380**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Robert DeBord**
SCHOOL NAME: **Telpochcalli School** INSPECTION DATE: **2/25/2016**
ADDRESS: **2832 W. 24th Blvd.** IDPH LICENSE NO: **100-08864**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **93**
MATERIAL DESCRIPTION: **Black Lab Table**
HISTORICAL AHERA DAMAGE CATEGORY **6**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms 152 and 262**
MATERIAL QUANTITY: **120** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 02/25/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23231** BUIDLING ID: **3380**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Telpochcalli School** REVIEW DATE: **3/15/2016**
ADDRESS: **2832 W. 24th Blvd.** IDPH LICENSE NO: **100-08864**

HOMOGENEOUS AREA: **93**
MATERIAL DESCRIPTION: **Black Lab Table**
MATERIAL LOCATION: **Rooms 152 and 262**
MATERIAL QUANTITY: **120** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **03/15/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23231** BUIDLING ID: **3380**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Robert DeBord**
SCHOOL NAME: **Telpochcalli School** INSPECTION DATE: **2/25/2016**
ADDRESS: **2832 W. 24th Blvd.** IDPH LICENSE NO: **100-08864**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **94**
MATERIAL DESCRIPTION: **2x4 fissured ceiling tile**
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **257,258 eng. Lounge and main office**
MATERIAL QUANTITY: **2800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 02/25/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23231** BUIDLING ID: **3380**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Telpochcalli School** REVIEW DATE: **3/15/2016**
ADDRESS: **2832 W. 24th Blvd.** IDPH LICENSE NO: **100-08864**

HOMOGENEOUS AREA: **94**
MATERIAL DESCRIPTION: **2x4 fissured ceiling tile**
MATERIAL LOCATION: **257,258 eng. Lounge and main office**
MATERIAL QUANTITY: **2800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **03/15/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23231** BUIDLING ID: **3380**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Robert DeBord**
SCHOOL NAME: **Telpochcalli School** INSPECTION DATE: **2/25/2016**
ADDRESS: **2832 W. 24th Blvd.** IDPH LICENSE NO: **100-08864**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **95**
MATERIAL DESCRIPTION: **chalkboard**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **Low**

MATERIAL LOCATION: **all classrooms 215,221,225**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed - skimmed over with white board.**

Inspector's Signature: _____

Date: 02/25/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23231** BUIDLING ID: **3380**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Telpochcalli School** REVIEW DATE: **3/15/2016**
ADDRESS: **2832 W. 24th Blvd.** IDPH LICENSE NO: **100-08864**

HOMOGENEOUS AREA: **95**

MATERIAL DESCRIPTION: **chalkboard**

MATERIAL LOCATION: **all classrooms 215,221,225**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

If identified follow O&M procedure.

Management Planner's Signature: _____ Date: **03/15/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23231** BUIDLING ID: **3380**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Robert DeBord**
SCHOOL NAME: **Telpochcalli School** INSPECTION DATE: **2/25/2016**
ADDRESS: **2832 W. 24th Blvd.** IDPH LICENSE NO: **100-08864**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **96**
MATERIAL DESCRIPTION: **chalkboard adhesive**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **all classrooms**
MATERIAL QUANTITY: **10000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 02/25/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23231** BUIDLING ID: **3380**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Telpochcalli School** REVIEW DATE: **3/15/2016**
ADDRESS: **2832 W. 24th Blvd.** IDPH LICENSE NO: **100-08864**

HOMOGENEOUS AREA: **96**

MATERIAL DESCRIPTION: **chalkboard adhesive**

MATERIAL LOCATION: **all classrooms**

MATERIAL QUANTITY: **10000**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **03/15/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23231** BUIDLING ID: **3380**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Robert DeBord**
SCHOOL NAME: **Telpochcalli School** INSPECTION DATE: **2/25/2016**
ADDRESS: **2832 W. 24th Blvd.** IDPH LICENSE NO: **100-08864**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **97**
MATERIAL DESCRIPTION: **Patch Floor Tile - white, pink, brown**
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1st floor Hallway**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____

Date: 02/25/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23231** BUIDLING ID: **3380**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Telpochcalli School** REVIEW DATE: **3/15/2016**
ADDRESS: **2832 W. 24th Blvd.** IDPH LICENSE NO: **100-08864**

HOMOGENEOUS AREA: **97**

MATERIAL DESCRIPTION: **Patch Floor Tile - white, pink, brown**

MATERIAL LOCATION: **1st floor Hallway**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

If identified follow O&M procedure.

Management Planner's Signature: _____ Date: **03/15/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23231** BUIDLING ID: **3380**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Robert DeBord**
SCHOOL NAME: **Telpochcalli School** INSPECTION DATE: **2/25/2016**
ADDRESS: **2832 W. 24th Blvd.** IDPH LICENSE NO: **100-08864**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **98**
MATERIAL DESCRIPTION: **Mastic w/ Patch Floor Tile - white, pink, brown**
HISTORICAL AHERA DAMAGE CATEGORY: **ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1st floor Hallway**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____

Date: 02/25/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23231** BUIDLING ID: **3380**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Telpochcalli School** REVIEW DATE: **3/15/2016**
ADDRESS: **2832 W. 24th Blvd.** IDPH LICENSE NO: **100-08864**

HOMOGENEOUS AREA: **98**

MATERIAL DESCRIPTION: **Mastic w/ Patch Floor Tile - white, pink, brown**

MATERIAL LOCATION: **1st floor Hallway**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

If identified follow O&M procedure.

Management Planner's Signature: _____ Date: **03/15/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23231** BUIDLING ID: **3380**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Robert DeBord**
SCHOOL NAME: **Telpochcalli School** INSPECTION DATE: **2/25/2016**
ADDRESS: **2832 W. 24th Blvd.** IDPH LICENSE NO: **100-08864**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **99**
MATERIAL DESCRIPTION: **Brown Carpet Adhesive - REMOVED**
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Entrances**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____

Date: 02/25/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23231** BUIDLING ID: **3380**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Telpochcalli School** REVIEW DATE: **3/15/2016**
ADDRESS: **2832 W. 24th Blvd.** IDPH LICENSE NO: **100-08864**

HOMOGENEOUS AREA: **99**

MATERIAL DESCRIPTION: **Brown Carpet Adhesive - REMOVED**

MATERIAL LOCATION: **Entrances**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

If identified follow O&M procedure.

Management Planner's Signature: _____ Date: **03/15/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23231** BUIDLING ID: **3380**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Robert DeBord**
SCHOOL NAME: **Telpochcalli School** INSPECTION DATE: **2/25/2016**
ADDRESS: **2832 W. 24th Blvd.** IDPH LICENSE NO: **100-08864**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **F**
MATERIAL DESCRIPTION: **Fiberglass Tank Insulation**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Not Tested** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **02/25/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23231** BUIDLING ID: **3380**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Telpochcalli School** REVIEW DATE: **3/15/2016**
ADDRESS: **2832 W. 24th Blvd.** IDPH LICENSE NO: **100-08864**

HOMOGENEOUS AREA: **F**

MATERIAL DESCRIPTION: **Fiberglass Tank Insulation**

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **03/15/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23231** BUILDING ID: **3380**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Robert DeBord**
SCHOOL NAME: **Telpochcalli School** INSPECTION DATE: **2/25/2016**
ADDRESS: **2832 W. 24th Blvd.** IDPH LICENSE NO: **100-08864**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **I**
MATERIAL DESCRIPTION: **Fiberglass Pipe Insulation**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Not Tested** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **02/25/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23231** BUIDLING ID: **3380**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Telpochcalli School** REVIEW DATE: **3/15/2016**
ADDRESS: **2832 W. 24th Blvd.** IDPH LICENSE NO: **100-08864**

HOMOGENEOUS AREA: **I**

MATERIAL DESCRIPTION: **Fiberglass Pipe Insulation**

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **03/15/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23231** BUILDING ID: **3380**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Telpochcalli School** REVIEW DATE: **3/15/2016**
ADDRESS: **2832 W. 24th Blvd.** IDPH LICENSE NO: **100-08864**

HOMOGENEOUS AREA: **103**

MATERIAL DESCRIPTION: **12" x 12" Blue, White, and Gray Vinyl Floor Tile**

MATERIAL LOCATION: **Entrances**

MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____ Date: **03/15/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23231** BUILDING ID: **3380**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Telpochcalli School** REVIEW DATE: **3/15/2016**
ADDRESS: **2832 W. 24th Blvd.** IDPH LICENSE NO: **100-08864**

HOMOGENEOUS AREA: **106**

MATERIAL DESCRIPTION: **White Board over Black Boards**

MATERIAL LOCATION: **All Black Boards**

MATERIAL QUANTITY: **10000**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____ Date: **03/15/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23231** BUILDING ID: **3380**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Telpochcalli School** REVIEW DATE: **3/15/2016**
ADDRESS: **2832 W. 24th Blvd.** IDPH LICENSE NO: **100-08864**

HOMOGENEOUS AREA: **104**

MATERIAL DESCRIPTION: **Mastic Associated w/ Blue, Gray, and White Vinyl Floor Tiles**

MATERIAL LOCATION: **1st and 2nd Floor Corridors and Entrances**

MATERIAL QUANTITY: **3500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____ Date: **03/15/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23231** BUILDING ID: **3380**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Telpochcalli School** REVIEW DATE: **3/15/2016**
ADDRESS: **2832 W. 24th Blvd.** IDPH LICENSE NO: **100-08864**

HOMOGENEOUS AREA: **100**
MATERIAL DESCRIPTION: **12" x 12" Blue Vinyl Floor Tile**
MATERIAL LOCATION: **1st and 2nd Floor Corridor**
MATERIAL QUANTITY: **1100** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____ Date: **03/15/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23231** BUILDING ID: **3380**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Telpochcalli School** REVIEW DATE: **3/15/2016**
ADDRESS: **2832 W. 24th Blvd.** IDPH LICENSE NO: **100-08864**

HOMOGENEOUS AREA: **101**
MATERIAL DESCRIPTION: **12" x 12" Gray Vinyl Floor Tile**
MATERIAL LOCATION: **1st and 2nd Floor Corridor**
MATERIAL QUANTITY: **1100** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____ Date: **03/15/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23231** BUIDLING ID: **3380**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Robert DeBord**
SCHOOL NAME: **Telpochcalli School** INSPECTION DATE: **2/25/2016**
ADDRESS: **2832 W. 24th Blvd.** IDPH LICENSE NO: **100-08864**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **102**
MATERIAL DESCRIPTION: **12" x 12" White Vinyl Floor Tile**
MATERIAL LOCATION: **1st and 2nd Floor Corridor**
MATERIAL QUANTITY: **1100** MATERIAL UNITS: **SF**
MATERIAL CATEGORY: **MISC** FRIABLE: **No**
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **LOW** CONDITION:
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
ACCESSIBILITY: **Within Reach** DAMAGE REASON:
DAMAGE QUANTITY: **0** DAMAGE REASON:
DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: 02/25/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23231** BUILDING ID: **3380**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Telpochcalli School** REVIEW DATE: **3/15/2016**
ADDRESS: **2832 W. 24th Blvd.** IDPH LICENSE NO: **100-08864**

HOMOGENEOUS AREA: **102**
MATERIAL DESCRIPTION: **12" x 12" White Vinyl Floor Tile**
MATERIAL LOCATION: **1st and 2nd Floor Corridor**
MATERIAL QUANTITY: **1100** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____ Date: **03/15/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23231** BUILDING ID: **3380**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Telpochcalli School** REVIEW DATE: **3/15/2016**
ADDRESS: **2832 W. 24th Blvd.** IDPH LICENSE NO: **100-08864**

HOMOGENEOUS AREA: **105**

MATERIAL DESCRIPTION: **12" x 12" Light Gray w/ Dk. Gray Specks Vinyl Floor Tile**

MATERIAL LOCATION: **Room 164 (Computer room)**

MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____ Date: **03/15/2016**

APPENDIX B

Inspector and Management Planner Licenses

2015



OCCUPATIONAL TRAINING & SUPPLY, INC.

7233 S. Adams Street ♦ Willowbrook, IL 60527 ♦ (630) 655-3900

Asbestos Building Inspector Refresher

Occupational Training & Supply, Inc. certifies that

Robert DeBord


has successfully completed the Asbestos Building Inspector Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 12/2/2015

Exam Date: 12/2/2015

Expiration Date: 12/2/2016

Certificate Number: BIR1512024160


Kathy DeSalvo, Director

Robert De Bord
Illinois Licensed Asbestos Inspector, Project Manager, and
Air Sampling Professional



**ASBESTOS
PROFESSIONAL
LICENSE**

ID NUMBER ISSUED EXPIRES
100 - 08864 **5/27/2015** **05/15/2016**

ROBERT W DE BORD
301 MIAMI ST
PARK FOREST, IL 60466
Environmental Health




ENDORSEMENTS	TC EXPIRES
INSPECTOR	2/13/2016
PROJECT MANAGER AIR SAMPLING PROFESSIONAL	2/12/2016

Alteration of this license shall result in legal action
This license issued under authority of the State of Illinois
Department of Public Health
This license is valid only when accompanied by a valid
training course certificate.

**CARNOW
CONIBEAR**

Evan Christian

Illinois Licensed Project Manager, and Air Sampling Professional



ENDORSEMENTS	TC EXPIRES
PROJECT MANAGER AIR SAMPLING PROFESSIONAL	12/12/2015
Alteration of this license shall result in legal action This license issued under authority of the State of Illinois Department of Public Health This license is valid only when accompanied by a valid training course certificate.	

**CARNOW
CONIBEAR**

2015



OCCUPATIONAL TRAINING & SUPPLY, INC.

7233 S. Adams Street ♦ Willowbrook, IL 60527 ♦ (630) 655-3900

Asbestos Building Inspector Refresher

Occupational Training & Supply, Inc. certifies that

Evan Christian


has successfully completed the Asbestos Building Inspector Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 12/2/2015

Exam Date: 12/2/2015

Expiration Date: 12/2/2016

Certificate Number: BIR1512024159


Katy DeSalvo, Director

Reliable
Environmental
Solutions, Inc. **RES**

This is to certify that **Evan Christian**

*has on January 28 & 29, 2016, in Springfield, Illinois,
completed the requirements for asbestos accreditation under Section 206 of TSCA Title II*

Asbestos Management Planner Initial Training

*as accredited by the State of Illinois and approved by the U.S.E.P.A. under 40 CFR 763 (AHERA)
and passed the associated examination with a score of 70% or higher*

Course Date: January 28 & 29, 2016

Examination Date: January 29, 2016

Expiration Date: January 29, 2017

Certificate Number: MP/0103

William S. Williams

Training Program Manager, William S. Williams

4211 Westgate Drive, Springfield, Illinois ☐ 217.787.9800 ☐ 217.787.9801 FAX ☐ www.ReliableEnv.com

APPENDIX C

Laboratory Accreditations

APPENDIX D

Laboratory Results

APPENDIX E

Chain of Custody Forms

Three-Year Reinspection Key to Terms

	CODE	KEY
MATERIAL		
	ACBM	Asbestos Containing Building Materials
MATERIAL CATEGORY		
	MISC	Miscellaneous
	SURF	Surfacing
	TSI	Thermal System Insulation
MATERIAL UNITS		
	LF	Linear Feet
	SF	Square Feet
	CF	Cubic Feet
DAMAGE TYPE		
	Loc	Localized
	Dist	Distributed