

**ILLINOIS DEPARTMENT OF PUBLIC HEALTH
AHERA THREE YEAR REINSPECTION
ASBESTOS ABATEMENT PROGRAM
SCHOOL INFORMATION FORM**

SECTION I

NAME OF SCHOOL DISTRICT: CHICAGO SCHOOL DIST 299
SCHOOL ID NUMBER: 14-016-2990-2084
SCHOOL NAME: Bethune School
ADDRESS OF SCHOOL: 3030 W. Arthington
CITY: Chicago, IL, 60612

DATE LAST THREE YEAR REINSPECTION WAS COMPLETED **3/12/2013**

If the address on this form is different than the address of the building, submit a written explanation.

SECTION II *(Please type or print)*

PLEASE COMPLETE THE FOLLOWING FOR YOUR THREE YEAR REINSPECTION:

DATE REINSPECTION COMPLETED: 3/25/2016 ENROLLMENT 342
IDPH INSPECTOR LICENSE NUMBER: 100-00249
IDPH LICENSED INSPECTOR NAME (Please Print): John Feely
IDPH MP LICENSE NUMBER: 100-03613
IDPH LICENSED MANAGEMENT PLANNER NAME (Please Print): Daniel Juneau

DESIGNATED PERSON (Please Print): Robert Christlieb PHONE: (773) 553-3197



3/25/2016

Signature of Designated Person

Date

SECTION III

PLEASE COMPLETE THE FOLLOWING INFORMATION FOR ANY CHANGES WITHIN THE SCHOOL DISTRICT.

School building has been sold. Date of Sale: _____

School has been closed. Date closed: _____

School building has been demolished. Date: _____

School building is asbestos free since last reinspection: _____

Please explain in writing why the school building is now asbestos free and include the supporting documentation.

If a new school building has been added to the district, submit either an exclusionary statement or a management plan and inspection report. Include the complete name, address and city of school building.

Explain in writing if the address of the building is different than the address on this form:

THREE-YEAR REINSPECTION

CHICAGO SCHOOL DIST 299

Bethune School

3030 W. Arthington
Chicago, IL, 60612

Unit: 23251
Building ID: 8020

IDPH ID Number: 14-016-2990-2084

REPORT DATE:

Friday, March 25, 2016

Prepared for:

Chicago Public Schools
125 S. Clark Street
Chicago, IL 60603

Prepared by:

Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone (312) 762-2900

Fax (312) 782-5145

**DO NOT REMOVE FROM SCHOOL
REQUIRED BY FEDERAL LAW**

February 19, 2016

Mr. R. Kent Cook
Asbestos Program
Illinois Department of Public Health
525 West Jefferson Street
Springfield, Illinois 62761

Re: Chicago Public Schools - 2016 Three-Year Reinspections

Dear Mr. Cook:

Carnow, Conibear and Associates, Managing Environmental Consultant (MEC), conducted the Three-Year Reinspections and performed management plan updates for the Chicago Public Schools (CPS) facilities in Region 3,4,5 Elementary Schools. Please update your records with the following information.

School District: 299 Unit: 26611 Region: 03 IDPH ID: 14-016-2990-2084

School: Bethune School Building ID: 8020

Address: 3030 W. Arthington
Chicago, IL, 60612

Building Contact: Desrosiers, Timothy Contact Phone: 773-344-7241


Current Building Owners: Chicago Public Schools

Review Date: 03/25/2016

Inspector: John Feely Inspector IDPH License: 100-00249
Management Planner: Daniel Juneau Management Planner IDPH License: 100-03613

If you have any questions or comments, please contact us at (312) 762-2900

Sincerely,
Carnow, Conibear and Associates



Daniel Juneau
100-03613

Environmental Notification to Occupants

To: Faculty, Staff and Parents
From: Chicago Public Schools
Date: February 19, 2016

RE: Bethune School, Unit 23251
3030 W. Arthington
Chicago, IL, 60612

Dear Faculty, Staff and Parents,

This letter is to notify you that the 2016 asbestos three year re-inspection has been completed at Bethune School , following the Federal Asbestos Hazard Emergency Response Act (AHERA), 40 CFR Part 763, Subpart E and is available for your review at the main office of the school.

Although asbestos-containing materials have been identified at Bethune School, there is no reason to believe that any threat to the health of students or staff exists at this time. CPS will continue to carefully monitor the condition of asbestos-containing materials and if conditions warrant, all appropriate steps will be taken to maintain the health and safety of all building occupants.

If you have any questions regarding this matter or require additional information, please feel free to contact Robert Christlieb, the designated Local Education Authority's Designated Person at (773) 553-3197 .

Table of Contents

- I. School and Inspection Information
- II. Executive Summary
- III. Methodology
- IV. Abatement History
- V. Reassessments and Recommendations
- VI. Conclusions

Table I: Inspector's Reinspection Findings

Table II: Management Planner's Review

APPENDICES:

- Appendix A: Assessment Sheets, Drawings and Photos
- Appendix B: Inspector and Management Planner Licenses
- Appendix C: Laboratory Accreditations
- Appendix D: Laboratory Results
- Appendix E: Chain of Custody Forms

SCHOOL AND INSPECTION INFORMATION

1. School Information

School: Bethune School Unit: 26611 Region: 03
Address: 3030 W. Arthington Chicago, IL, 60612
IDPH ID: 14-016-2990-2084 Building ID: 8020
Contact: Desrosiers, Timothy Phone: 773-344-7241

2. Description of Facility

Original Construction: 1969 Additional Construction:
Total Square Footage: 75510 No of Floors: 3
Current Occupancy: 342

3. LEA Designated Person

Contact: Robert Christlieb Phone: (773) 553-3197
Address: 125 South Clark Street, 17th Floor
Chicago, IL 60603

4. Managing Environmental Consultant

MEC: Carnow, Conibear and Associates
Contact: Dan Juneau
Address 600 West Van Buren St., Ste 500
Phone: (312) 762-2900 Fax: (312) 782-5145

5. Inspector

Inspector Name: John Feely


Inspector IDPH license # 100-00249

Signature:
Date: 2/19/2016

6. Management Planner

Management Planner Name: Daniel Juneau

Management Planner IDPH license # 100-03613

Signature: 
Date: 03/25/2016

7. Review Date: 03/25/2016

8. LEA Designated Person's Acknowledgement

The reinspection report and recommendations have been received by me and appropriate action will be taken by the School District.

Signature: 

Date: 3/25/2016

Name: Robert Christlieb

II. EXECUTIVE SUMMARY

Carnow, Conibear and Associates was retained by the Chicago Public Schools (CPS) to perform a three-year asbestos reinspection of the Bethune School. This inspection was conducted in accordance with the United States Environmental Protection Agency (USEPA) Asbestos Hazard Emergency Response Act (AHERA) part 763.92 (b), and the ongoing Operations and Maintenance Program (O&M) originally designed in the School's Asbestos Management Plan. The purpose of this three-year reinspection is to record any condition changes in the asbestos-containing building material (ACBM) in the school since the previous three-year reinspection and the six-month periodic surveillance, to identify, assess, and include any Homogeneous Areas (HA) not identified in the Management Plan, and to recommend an appropriate response action to manage asbestos.

The inspector conducted a three-year reinspection of this facility under Illinois Department of Public Health (IDPH) school reinspection requirements and AHERA, sections 763.85 and 763.88. The main building and each addition to the main building, if constructed at different dates, were inspected separately. Laboratory accreditations are included in Appendix C, laboratory results are included in Appendix D, and chain of custody forms are included in Appendix E.

Note: During previous inspections, some of the HA(s) were identified together as 9" x 9" floor tile (FT), mastics assoc. with 9" x 9" FT, 12" x 12" FT, mastics assoc. with 12" x 12" FT, pipe insulation, etc. Some of these HA(s) have been re-identified by areas that are uniform in color, texture, construction date, application date, and general appearance.

The inspector has determined the following:

A. The following HAs have changed assessment categories for Building 8020:

001	Hard Plaster
002	Acoustical Plaster
032	Vault Door
033	Interior Boiler Insulation
73	9 X 9 Gray W/Dark Gray Floor Tile
74	12" X 12" Tan W/Brown Floor Tile
74M	12" X 12" Tan W/Brown Floor Tile Mastic
76	12" X 12" Blue W/Dark Blue Floor Tile
76M	12" X 12" Blue W/Dark Blue Floor Tile Mastic

77	12" X 12" Tan /Brown Floor Tile
78	12" x 12" White Floor Tile
79	Mastic Associated w/ 12" x 12" White Floor Tile
80	12" x 12" Blue Floor Tile
81	Mastic Associated w/ 12" x 12" Blue Floor Tile
A	Hard Joint Compound on Fiberglass Pipe Insulation
C	Cementitious Material

B. The following new homogenous areas have been identified for Building 8020:

78	12" x 12" White Floor Tile
79	Mastic Associated w/ 12" x 12" White Floor Tile
80	12" x 12" Blue Floor Tile
81	Mastic Associated w/ 12" x 12" Blue Floor Tile

C. This reinspection covered only physically accessible and visible areas and materials that were identified in the LEA's management plan. The following materials were concealed and/or contained in areas that were inaccessible for sampling and have been classified as Assumed:

001	Hard Plaster
002	Acoustical Plaster
010	4" Black Baseboard Mastic
011	Drywall & Compound
016 A	12"x12" Tan Floor Tile
016 B	12" x 12" Brown Mix Floor Tile
017 B	12" x 12" Brown Mix Floor Tile Mastic
018	12"x12" Pink Floor Tile
019	12"x12" Pink Floor Tile Mastic
020 A	12"x12" White Floor Tile
020 B	12" x 12" Blue Floor Tile
021 A	12"x12" White Floor Tile Mastic
021 B	12" x 12" Blue Floor Tile Mastic
022	12"x12" White Floor Tile
023	12"x12" White Floor Tile Mastic
024 A	12"x12" Yellow Floor Tile
024 B	12" x 12" Light Yellow Floor Tile
025 A	12"x12" Yellow Floor Tile Mastic
025 B	12" x 12" Light Yellow Floor Tile Mastic
026	12"x12" Green Floor Tile
027	12"x12" Green Floor Tile Mastic
028 A	12"x12" Black w/White Floor Tile
028 B	12" x 12" White w/Black Floor Tile
029 A	12"x12" Black w/White Floor Tile Mastic
029 B	12" x 12" White w/ Black Floor Tile Mastic
030	Carpet Mastic
031	Boiler Room Fire Doors
032	Vault Door
033	Interior Boiler Insulation
034	Transite Table Tops
035	Interior Portion of Heating Units
036	4" Black Baseboard
037	Material Beneath Floor Tile
039	12" x 12" White Floor Tile
043	12" x 12" Multi-Brown Floor Tile
045	Linoleum
046	Linoleum Adhesive
47	Sink Undercoat
48	Lab Counter/Sink
49	Material Inside Divider Wall
50	9" x 9" Brown w/Brown Specks Floor Tile
51	9" x 9" Brown w/Brown Specks Floor Tile Mastic

52	12" x 12" White w/Black Floor Tile
53	12" x 12" White w/Black Floor Tile Mastic
54	12" x 12" Brown Mix Floor Tile
55	12" x 12" Brown Mix Floor Tile Mastic
56	12" x 12" Beige Mix Floor Tile
57	12" x 12" Beige Mix Floor Tile Mastic
58	9" x 9" Lt. Brown Floor Tile
59	9" x 9" Lt. Brown Floor Tile Mastic
60	Chalk Board/Poster Board Adhesive
61	12"x12" Beige w/brown floor tile
62	12" x12" Beige w/brown floor tile adhesive
63	4" Beige baseboard
64	4" Beige baseboard adhesive
65	4" black baseboard
66	4" blue baseboard adhesive
70	Ceramic Grout and Adhesive Brown, Tan & White
71	12 x 12 FT Brown with White Streaks
72	Mastic under 12 x 12 FT Brown with White Streaks
73	9 X 9 Gray W/Dark Gray Floor Tile
73M	9 X 9 Gray W/Dark Gray Floor Tile Mastic
74	12" X 12" Tan W/Brown Floor Tile
74M	12" X 12" Tan W/Brown Floor Tile Mastic
75	12" X 12" Tan W/Brown Floor Tile
75M	12" X 12" Tan W/Brown Floor Tile Mastic
76	12" X 12" Blue W/Dark Blue Floor Tile
76M	12" X 12" Blue W/Dark Blue Floor Tile Mastic
77	12" X 12" Tan /Brown Floor Tile
77M	12" X 12" Tan W/Brown Floor Tile Mastic
78	12" x 12" White Floor Tile
79	Mastic Associated w/ 12" x 12" White Floor Tile
80	12" x 12" Blue Floor Tile
81	Mastic Associated w/ 12" x 12" Blue Floor Tile
C	Cementitious Material

The following areas were deemed to be inaccessible:

005	9"x9" Tan Floor Tile Mastic
007	9"x9" Green Floor Tile Mastic
009	9"x9" Dark Brown Floor Tile Mastic w/ white specks
010	4" Black Baseboard Mastic
017 A	12"x12" Tan Floor Tile Mastic
017 B	12" x 12" Brown Mix Floor Tile Mastic
021 A	12"x12" White Floor Tile Mastic
021 B	12" x 12" Blue Floor Tile Mastic
023	12"x12" White Floor Tile Mastic

025 B	12" x 12" Light Yellow Floor Tile Mastic
027	12"x12" Green Floor Tile Mastic
029 A	12"x12" Black w/White Floor Tile Mastic
029 B	12" x 12" White w/ Black Floor Tile Mastic
032	Vault Door
033	Interior Boiler Insulation
040	12" x 12" White Floor Tile Mastic
042	9" x 9" Light Brown Floor Tile Mastic
044	12" x 12" Multi-Brown Floor Tile Mastic
046	Linoleum Adhesive
57	12" x 12" Beige Mix Floor Tile Mastic
60	Chalk Board/Poster Board Adhesive
62	12" x12" Beige w/brown floor tile adhesive
66	4" blue baseboard adhesive
72	Mastic under 12 x 12 FT Brown with White Streaks
73M	9 X 9 Gray W/Dark Gray Floor Tile Mastic
74M	12" X 12" Tan W/Brown Floor Tile Mastic
75M	12" X 12" Tan W/Brown Floor Tile Mastic
76M	12" X 12" Blue W/Dark Blue Floor Tile Mastic
77M	12" X 12" Tan W/Brown Floor Tile Mastic
79	Mastic Associated w/ 12" x 12" White Floor Tile
81	Mastic Associated w/ 12" x 12" Blue Floor Tile

Materials were also listed as "assumed" if they were in good condition and sampling was not conducted to avoid damage.

This reinspection was conducted by John Feely, IDPH License # 100-00249. The Management Plan was updated by Daniel Juneau, IDPH License # 100-03613. Inspector and Management Planner Licenses are included in Appendix B.

III. METHODOLOGY

Tasks performed on-site included the following:

1. Review current management plan, identify HA(s) and extract appropriate information.
2. Examine and verify abatement records.
3. Touch and visually and physically reinspect and reassess the condition of all friable known or assumed ACBM.
4. Touch and visually and physically reinspect all non-friable known or assumed ACBM to determine whether these materials have become friable since the last inspection or periodic surveillance.
5. Identify any condition changes that may affect Hazard Ranking of known ACBM or Assumed ACBM, as well as any HA(s) that have become friable since the last reinspection.
6. Collect bulk samples from each newly discovered friable HA or previously assumed and submit for laboratory analysis.
7. Tabulate reinspection findings and submit for management planner review and recommendations with appropriate response actions based on the AHERA Damage Category of the ACBM.
8. Submit reinspection findings and management planner recommendations to the LEA within thirty (30) days for inclusion into the management plan.

IV. ABATEMENT HISTORY

The information collected from the existing management plan and inspection report(s) and from interviews with the school official revealed that the following asbestos abatement was conducted at the school since the previous Three year Reinspection.

Abatement Dates:

V. REASSESSMENTS AND RECOMMENDATIONS

The reassessments and recommendations are summarized in Tables I and II on the following pages. Detailed Hazard Assessment Sheets and Drawings and Photos (if applicable) are included in Appendix A.

VI. CONCLUSIONS

The Bethune School Building 8020 Three-Year reinspection has been completed and response actions have been recommended for both friable and non-friable materials. A timely execution of the response actions recommended will enable the LEA and the Designated Person(s) to effectively manage the existing ACBM.

This three-year reinspection report should be inspected in the current Management plan at the CPS Central Office, and one (1) copy should be kept at the school for use when planning any renovation and/or demolition activities in areas where ACBM has been identified. Also, periodic surveillance documentation and any summary reports from any response actions that are executed at the school should be used to update the Management Plan.

Table I
Inspector's Reinspection Findings

Chicago Public Schools

School Bethune School Unit 26611 Building ID 8020

Address 3030 W. Arthington Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				Corridors										
013	Window Glazing			Throughout School	CHR	MISC								
014	Exterior Brick			Exterior	NO_ACBM	MISC								
015	Exterior Brick Mortar			Exterior	NO_ACBM	MISC								
016 A	12"x12" Tan Floor Tile	7,900	SF	Corridors, room 209 (as patch)	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
016 B	12" x 12" Brown Mix Floor Tile	7,900	SF	Corridors, 107 & Office	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
017 A	12"x12" Tan Floor Tile Mastic	7,900	SF	Corridors, room 209 (as patch)	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
017 B	12" x 12" Brown Mix Floor Tile Mastic	7,900	SF	Corridors, 107 & Office	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
018	12"x12" Pink Floor Tile			Assistant Principal's Office	ASSUMED	MISC								
019	12"x12" Pink Floor Tile Mastic			Assistant Principal's Office	ASSUMED	MISC								
020 A	12"x12" White Floor Tile	1,595	SF	Lunch Room, 112	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
020 B	12" x 12" Blue Floor Tile	1,595	SF	Lunch Room	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
021 A	12"x12" White Floor Tile Mastic	2,138	SF	Lunch Room, 112	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
021 B	12" x 12" Blue Floor Tile Mastic	2,138	SF	Lunch Room, 112	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
022	12"x12" White Floor Tile	950	SF	Lunch Room Storage Area, Main Office, Vault	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
023	12"x12" White Floor Tile Mastic	950	SF	Lunch Room Storage Area, Main Office, Vault	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
024 A	12"x12" Yellow Floor Tile	500	SF	Room 106	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
024 B	12" x 12" Light Yellow Floor Tile	500	SF	Room 106	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
025 A	12"x12" Yellow Floor Tile Mastic	500	SF	Room 106	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
025 B	12" x 12" Light Yellow Floor Tile Mastic	500	SF	Room 106	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
026	12"x12" Green Floor Tile	562	SF	Room 112	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
027	12"x12" Green Floor Tile Mastic	562	SF	Room 112	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
028 A	12"x12" Black w/White Floor Tile	480	SF	Room 108, as patches in various	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW

Chicago Public Schools

School Bethune School Unit 26611 Building ID 8020

Address 3030 W. Arthington Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				classrooms & boiler rm, wash rm										
028 B	12" x 12" White w/Black Floor Tile	480	SF	Room 108	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
029 A	12"x12" Black w/White Floor Tile Mastic	480	SF	Room 108, as patches in various classrooms & boiler rm, wash rm	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
029 B	12" x 12" White w/ Black Floor Tile Mastic	480	SF	Room 108	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
030	Carpet Mastic			Rooms 306, 308, 309, 310, 311, 312, 313, 314, 315	ASSUMED	MISC								
031	Boiler Room Fire Doors	4	SF	Boiler Room	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
032	Vault Door	56	SF	Main Office, 1st floor hall	ASSUMED	TSI	Y	NONE	0		Yes	Any remaining friable ACBM or friable suspect ACBM		LOW
033	Interior Boiler Insulation	200	SF	Boiler Room	ASSUMED	TSI	Y	NONE	0		Yes	Any remaining friable ACBM or friable suspect ACBM		LOW
034	Transite Table Tops	150	SF	Science Room 217	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
035	Interior Portion of Heating Units			Classrooms	ASSUMED	MISC								
036	4" Black Baseboard	100	LF	Rooms 306	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
037	Material Beneath Floor Tile			Lunch Room	ASSUMED	MISC								
038	Mastic for Material Beneath Floor Tile			Lunch Room	CHR	MISC								
039	12" x 12" White Floor Tile	400	SF	Room 112	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
040	12" x 12" White Floor Tile Mastic	400	SF	Room 112	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
041	9" x 9" Light Brown Floor Tile	2,800	SF	Library, 311	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
042	9" x 9" Light Brown Floor Tile Mastic	2,800	SF	Library, 311	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
043	12" x 12" Multi-Brown Floor Tile	1,000	SF	Room 107	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
044	12" x 12" Multi-Brown Floor Tile Mastic	1,000	SF	Room 107	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
045	Linoleum	400	SF	Classrooms Shelves	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
046	Linoleum Adhesive	400	SF	Classroom Shelves on Second and Third	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW

Chicago Public Schools

School Bethune School Unit 26611 Building ID 8020

Address 3030 W. Arthington Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				Floors										
47	Sink Undercoat	20	SF	Room 205	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
48	Lab Counter/Sink	150	SF	Room 217	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
49	Material Inside Divider Wall			Room 104 and 216	ASSUMED	MISC								
50	9" x 9" Brown w/Brown Specks Floor Tile			Storage by Room 107	ASSUMED	MISC								
51	9" x 9" Brown w/Brown Specks Floor Tile Mastic	30	SF	Storage by Room 107	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
52	12" x 12" White w/Black Floor Tile	1,038	SF	Room 308 and Kitchen Storage	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
53	12" x 12" White w/Black Floor Tile Mastic	1,038	SF	Room 308 and Kitchen Storage	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
54	12" x 12" Brown Mix Floor Tile	750	SF	Room 207	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
55	12" x 12" Brown Mix Floor Tile Mastic	750	SF	Room 207	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
56	12" x 12" Beige Mix Floor Tile	750	SF	Room 207	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
57	12" x 12" Beige Mix Floor Tile Mastic	750	SF	Room 207	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
58	9" x 9" Lt. Brown Floor Tile	1,600	SF	Gym Entries, 211, 213	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
59	9" x 9" Lt. Brown Floor Tile Mastic	1,600	SF	Gym Entries, 211,213	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
60	Chalk Board/Poster Board Adhesive	6,240	SF	All classrooms	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
61	12"x12" Beige w/brown floor tile	720	SF	115	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
62	12" x12" Beige w/brown floor tile adhesive	720	SF	115	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
63	4" Beige baseboard			113, 115	ASSUMED	MISC								
64	4" Beige baseboard adhesive			113, 115	ASSUMED	MISC								
65	4" black baseboard	100	LF	306	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
66	4" blue baseboard adhesive	100	LF	306	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
70	Ceramic Grout and Adhesive Brown, Tan & White	1,800	SF	1st, 2nd, 3rd Floor Girls & Boys bathrooms	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
71	12 x 12 FT Brown with White Streaks	5,000	SF	Rooms 306, 312, 314, 315, 313, 310, 306, 309	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW

Chicago Public Schools

School Bethune School Unit 26611 Building ID 8020

Address 3030 W. Arthington Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
72	Mastic under 12 x 12 FT Brown with White Streaks	5,000	SF	Rooms 306, 312, 314, 315, 313, 310, 306, 309	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
73	9 X 9 Gray W/Dark Gray Floor Tile	150	SF	Room 314-A, MDF Room	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
73M	9 X 9 Gray W/Dark Gray Floor Tile Mastic	150	SF	Room 314-A MDF	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
74	12" X 12" Tan W/Brown Floor Tile	360	SF	Room 109	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
74M	12" X 12" Tan W/Brown Floor Tile Mastic	360	SF	Room 109	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
75	12" X 12" Tan W/Brown Floor Tile	625	SF	Assistant Principals Office	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
75M	12" X 12" Tan W/Brown Floor Tile Mastic	625	SF	Assistant Principal Office	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
76	12" X 12" Blue W/Dark Blue Floor Tile	1,150	SF	1, 2, 3 Floors Store Rooms and Elevators	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
76M	12" X 12" Blue W/Dark Blue Floor Tile Mastic	1,150	SF	1, 2, 3 Floors Store Rooms, and Elevators	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
77	12" X 12" Tan /Brown Floor Tile	2,268	SF	Rooms 102,104,106,108,11 2,115,111,107,105,2 00,202,204,206,208, 210,212,201,203,20 5,207,209,211,213,2 15,216,217,300,302, 304,306,308,305,30 7,309,311,313,315.	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
77M	12" X 12" Tan W/Brown Floor Tile Mastic	2,268	SF	Rooms 102,104,106,108,11 2,115,111,107,105,2 00,202,204,206,208, 210,212,201,203,20 5,207,209,211,213,2 15,216,217,300,302, 304,306,308,305,30 7,309,311,313,315.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
78	12" x 12" White Floor Tile	9,000	SF	Rms. 203, 207, 209, 306, 308-314	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
79	Mastic Associated w/ 12" x 12" White Floor Tile	9,000	SF	Rms. 203, 207, 209, 306, 308-314	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
80	12" x 12" Blue Floor Tile	300	SF	100A, 200A, 300A	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the		LOW

Chicago Public Schools

School Bethune School Unit 26611 Building ID 8020

Address 3030 W. Arthington Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				Elevator								potential for damage		
81	Mastic Associated w/ 12" x 12" Blue Floor Tile	300	SF	100A, 200A, 300A Elevator	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
A	Hard Joint Compound on Fiberglass Pipe Insulation	300	LF	Throughout Facility, including fan room, crawlspace, boiler room	CHR	TSI	Y	DIST	6		Yes	Damaged or significantly damaged friable thermal system insulating ACBM	2	LOW
B	Mag Block Insulation - ABATED			Boiler Room - Boiler Tank	ABATED	TSI								
C	Cementitious Material	10	SF	Boiler Room	ASSUMED	TSI	Y	NONE	0		Yes	Any remaining friable ACBM or friable suspect ACBM		LOW

Chicago Public Schools

School Bethune School Unit 26611 Building ID 8020

Address 3030 W. Arthington Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

Reinspection Date 2/19/2016
Inspector Name John Feely
100-00249 5/15/2016
Inspector's IDPH License Number / Expiration Date

Inspector's Comments

HA Number:	Inspector Comments:
001	
002	
003	
004	Not observed 2016
005	
006	
007	
008	
009	
010	
011	
012	
013	Not observed 2016
014	
015	
016 A	
016 B	
017 A	
017 B	
018	Not observed 2016
019	Not observed 2016
020 A	
020 B	
021 A	

Chicago Public Schools

School Bethune School Unit 26611 Building ID 8020

Address 3030 W. Arthington Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
021 B	
022	
023	
024 A	
024 B	
025 A	
025 B	
026	
027	
028 A	
028 B	
029 A	
029 B	
030	Not observed 2016
031	
032	
033	
034	
035	Not observed 2016
036	
037	Not observed 2016
038	Not observed 2016
039	
040	
041	
042	
043	
044	
045	

Chicago Public Schools

School Bethune School Unit 26611 Building ID 8020

Address 3030 W. Arthington Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
046	
47	
48	
49	Not observed 2016
50	Not observed 2016
51	
52	
53	
54	
55	
56	
57	
58	
59	
60	
61	
62	
63	Not observed 2016
64	Not observed 2016
65	
66	
70	
71	
72	
73	
73M	
74	
74M	
75	

Chicago Public Schools

School Bethune School Unit 26611 Building ID 8020

Address 3030 W. Arthington Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
75M	
76	
76M	
77	
77M	
78	
79	
80	
81	
A	
B	
C	

Table II

Management Planner's Review

Chicago Public Schools

School Bethune School
Address 3030 W. Arthington

Unit 26611
 Chicago, IL, 60612

Building ID 8020
Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
001	Hard Plaster	30,000	SF	Throughout Facility	Assumed	SURFACE	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
002	Acoustical Plaster	30,000	SF	1st, 2nd, 3rd, floor. Assumed to be beneath new popcorn ceiling.	Assumed	SURFACE	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
003	9"x9" Tan Floor Tile	16,200	SF	101,102,104,105,113,200,201,202,204,205,208,210,214A,216,217,214,2nd fl storage,300,302,304,305,307,308,311,313	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
004	Spray-on Insulation			All I-Beams Throughout Facility	Chrysotile	SURFACE					
005	9"x9" Tan Floor Tile Mastic	16,200	SF	101,102,104,105,113,200,201,202,204,205,208,210,214A,216,217,214,2nd fl storage,300,302,304,305,307,308,311,313	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
006	9"x9" Green Floor Tile	8,550	SF	209,203,212,215,303,306,101, Kitch Office&storage, Teacher Lounges, 215,308 storage, 2nd fl janitor clo	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
007	9"x9" Green Floor Tile Mastic	8,550	SF	209,203,212,215,303,306,101,Kitch Office&storage,Teacher Lounge,215,308 storage,2nd fl janitor closet	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
008	9" x 9" Dark Brown Floor Tile with white specks	750	SF	Room 206, 3rd floor janitor's closet	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
009	9"x9" Dark Brown Floor Tile Mastic w/ white specks	750	SF	Room 206, 3rd floor janitor's closet	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
010	4" Black Baseboard Mastic	100	LF	Room 306	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
011	Drywall & Compound	400	LF	Rooms 113, 306, 315, 115	Assumed	SURFACE	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
012	Acoustical Popcorn Ceiling			106, 108, 112 and Corridors	No ACBM	MISC					
013	Window Glazing			Throughout School	Chrysotile	MISC					
014	Exterior Brick			Exterior	No ACBM	MISC					
015	Exterior Brick Mortar			Exterior	No ACBM	MISC					
016 A	12"x12" Tan Floor Tile	7,900	SF	Corridors, room 209 (as patch)	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
016 B	12" x 12" Brown Mix Floor Tile	7,900	SF	Corridors, 107 & Office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
017 A	12"x12" Tan Floor Tile Mastic	7,900	SF	Corridors, room 209 (as patch)	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
017 B	12" x 12" Brown Mix Floor Tile Mastic	7,900	SF	Corridors, 107 & Office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
018	12"x12" Pink Floor Tile			Assistant Principal's Office	Assumed	MISC					
019	12"x12" Pink Floor Tile Mastic			Assistant Principal's Office	Assumed	MISC					
020 A	12"x12" White Floor Tile	1,595	SF	Lunch Room, 112	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
020 B	12" x 12" Blue Floor Tile	1,595	SF	Lunch Room	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

Chicago Public Schools

School Bethune School
Address 3030 W. Arthington

Unit 26611
Chicago, IL, 60612

Building ID 8020
Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
021 A	12"x12" White Floor Tile Mastic	2,138	SF	Lunch Room, 112	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
021 B	12" x 12" Blue Floor Tile Mastic	2,138	SF	Lunch Room, 112	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
022	12"x12" White Floor Tile	950	SF	Lunch Room Storage Area, Main Office, Vault	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
023	12"x12" White Floor Tile Mastic	950	SF	Lunch Room Storage Area, Main Office, Vault	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
024 A	12"x12" Yellow Floor Tile	500	SF	Room 106	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
024 B	12" x 12" Light Yellow Floor Tile	500	SF	Room 106	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
025 A	12"x12" Yellow Floor Tile Mastic	500	SF	Room 106	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
025 B	12" x 12" Light Yellow Floor Tile Mastic	500	SF	Room 106	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
026	12"x12" Green Floor Tile	562	SF	Room 112	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
027	12"x12" Green Floor Tile Mastic	562	SF	Room 112	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
028 A	12"x12" Black w/White Floor Tile	480	SF	Room 108, as patches in various classrooms & boiler rm, wash rm	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
028 B	12" x 12" White w/Black Floor Tile	480	SF	Room 108	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
029 A	12"x12" Black w/White Floor Tile Mastic	480	SF	Room 108, as patches in various classrooms & boiler rm, wash rm	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
029 B	12" x 12" White w/ Black Floor Tile Mastic	480	SF	Room 108	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
030	Carpet Mastic			Rooms 306, 308, 309, 310, 311, 312, 313, 314, 315	Assumed	MISC					
031	Boiler Room Fire Doors	4	SF	Boiler Room	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
032	Vault Door	56	SF	Main Office, 1st floor hall	Assumed	TSI	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
033	Interior Boiler Insulation	200	SF	Boiler Room	Assumed	TSI	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
034	Transite Table Tops	150	SF	Science Room 217	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
035	Interior Portion of Heating Units			Classrooms	Assumed	MISC					
036	4" Black Baseboard	100	LF	Rooms 306	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
037	Material Beneath Floor Tile			Lunch Room	Assumed	MISC					
038	Mastic for Material Beneath Floor Tile			Lunch Room	Chrysotile	MISC					
039	12" x 12" White Floor Tile	400	SF	Room 112	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
040	12" x 12" White Floor Tile Mastic	400	SF	Room 112	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
041	9" x 9" Light Brown Floor Tile	2,800	SF	Library, 311	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
042	9" x 9" Light Brown Floor Tile Mastic	2,800	SF	Library, 311	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
043	12" x 12" Multi-Brown Floor Tile	1,000	SF	Room 107	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

Chicago Public Schools

School Bethune School
Address 3030 W. Arthington

Unit 26611
Chicago, IL, 60612

Building ID 8020
Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
044	12" x 12" Multi-Brown Floor Tile Mastic	1,000	SF	Room 107	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
045	Linoleum	400	SF	Classrooms Shelves	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
046	Linoleum Adhesive	400	SF	Classroom Shelves on Second and Third Floors	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
47	Sink Undercoat	20	SF	Room 205	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
48	Lab Counter/Sink	150	SF	Room 217	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
49	Material Inside Divider Wall			Room 104 and 216	Assumed	MISC					
50	9" x 9" Brown w/Brown Specks Floor Tile			Storage by Room 107	Assumed	MISC					
51	9" x 9" Brown w/Brown Specks Floor Tile Mastic	30	SF	Storage by Room 107	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
52	12" x 12" White w/Black Floor Tile	1,038	SF	Room 308 and Kitchen Storage	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
53	12" x 12" White w/Black Floor Tile Mastic	1,038	SF	Room 308 and Kitchen Storage	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
54	12" x 12" Brown Mix Floor Tile	750	SF	Room 207	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
55	12" x 12" Brown Mix Floor Tile Mastic	750	SF	Room 207	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
56	12" x 12" Beige Mix Floor Tile	750	SF	Room 207	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
57	12" x 12" Beige Mix Floor Tile Mastic	750	SF	Room 207	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
58	9" x 9" Lt. Brown Floor Tile	1,600	SF	Gym Entries, 211, 213	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
59	9" x 9" Lt. Brown Floor Tile Mastic	1,600	SF	Gym Entries, 211,213	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
60	Chalk Board/Poster Board Adhesive	6,240	SF	All classrooms	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
61	12"x12" Beige w/brown floor tile	720	SF	115	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
62	12" x12" Beige w/brown floor tile adhesive	720	SF	115	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
63	4" Beige baseboard			113, 115	Assumed	MISC					
64	4" Beige baseboard adhesive			113, 115	Assumed	MISC					
65	4" black baseboard	100	LF	306	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
66	4" blue baseboard adhesive	100	LF	306	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
70	Ceramic Grout and Adhesive Brown, Tan & White	1,800	SF	1st, 2nd, 3rd Floor Girls & Boys bathrooms	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
71	12 x 12 FT Brown with White Streaks	5,000	SF	Rooms 306, 312, 314, 315, 313, 310, 306, 309	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
72	Mastic under 12 x 12 FT Brown with White Streaks	5,000	SF	Rooms 306, 312, 314, 315, 313, 310, 306, 309	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
73	9 X 9 Gray W/Dark Gray Floor Tile	150	SF	Room 314-A, MDF Room	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
73M	9 X 9 Gray W/Dark Gray Floor Tile Mastic	150	SF	Room 314-A MDF	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
74	12" X 12" Tan W/Brown Floor Tile	360	SF	Room 109	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
74M	12" X 12" Tan W/Brown Floor Tile Mastic	360	SF	Room 109	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
75	12" X 12" Tan W/Brown Floor Tile	625	SF	Assistant Principals Office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

Chicago Public Schools

School Bethune School
Address 3030 W. Arthington

Unit 26611
 Chicago, IL, 60612

Building ID 8020
Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
75M	12" X 12" Tan W/Brown Floor Tile Mastic	625	SF	Assistant Principal Office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
76	12" X 12" Blue W/Dark Blue Floor Tile	1,150	SF	1, 2, 3 Floors Store Rooms and Elevators	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
76M	12" X 12" Blue W/Dark Blue Floor Tile Mastic	1,150	SF	1, 2, 3 Floors Store Rooms, and Elevators	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
77	12" X 12" Tan /Brown Floor Tile	2,268	SF	Rooms 102,104,106,108,112,115,111,107,105,200,202,204,206,208,210,212,201,203,205,207,209,211,213,215,216,217,300,302,304,306,308,305,307,309,311,313,315.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
77M	12" X 12" Tan W/Brown Floor Tile Mastic	2,268	SF	Rooms 102,104,106,108,112,115,111,107,105,200,202,204,206,208,210,212,201,203,205,207,209,211,213,215,216,217,300,302,304,306,308,305,307,309,311,313,315.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
78	12" x 12" White Floor Tile	9,000	SF	Rms. 203, 207, 209, 306, 308-314	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
79	Mastic Associated w/ 12" x 12" White Floor Tile	9,000	SF	Rms. 203, 207, 209, 306, 308-314	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
80	12" x 12" Blue Floor Tile	300	SF	100A, 200A, 300A Elevator	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
81	Mastic Associated w/ 12" x 12" Blue Floor Tile	300	SF	100A, 200A, 300A Elevator	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
A	Hard Joint Compound on Fiberglass Pipe Insulation	300	LF	Throughout Facility, including fan room, crawlspace, boiler room	Chrysotile	TSI	Yes	6	LF	1 Damaged or significantly damaged friable thermal system insulating ACBM	Repair
B	Mag Block Insulation - ABATED			Boiler Room - Boiler Tank	Abated	TSI					
C	Cementitious Material	10	SF	Boiler Room	Assumed	TSI	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan

Chicago Public Schools

School Bethune School
Address 3030 W. Arthington

Unit 26611
 Chicago, IL, 60612

Building ID 8020
Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

Review Date	3/25/2016
Manager Planner Name	Daniel Juneau
100-03613	5/15/2016
Manager IDPH License No/Expiration	

HA Number	Management Comments
001	
002	
003	
004	If identified, implement O&M
005	
006	
007	
008	
009	
010	
011	
012	
013	If identified, implement O&M

Chicago Public Schools

School Bethune School
Address 3030 W. Arthington

Unit 26611
 Chicago, IL, 60612

Building ID 8020
Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
014	
015	
016 A	
016 B	
017 A	
017 B	
018	If identified, implement O&M
019	If identified, implement O&M
020 A	
020 B	
021 A	
021 B	
022	
023	
024 A	
024 B	
025 A	
025 B	
026	
027	
028 A	
028 B	
029 A	
029 B	
030	If identified, implement O&M
031	
032	

Chicago Public Schools

School Bethune School
Address 3030 W. Arthington

Unit 26611
 Chicago, IL, 60612

Building ID 8020
Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates
 600 West Van Buren St., Ste 500
 Phone: (312) 762-2900 Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
033	
034	
035	If identified, implement O&M
036	
037	If identified, implement O&M
038	If identified, implement O&M
039	
040	
041	
042	
043	
044	
045	
046	
47	
48	
49	If identified, implement O&M
50	If identified, implement O&M
51	
52	
53	
54	
55	
56	
57	
58	
59	

Chicago Public Schools

School Bethune School
Address 3030 W. Arthington

Unit 26611
 Chicago, IL, 60612

Building ID 8020
Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
60	
61	
62	
63	If identified, implement O&M
64	If identified, implement O&M
65	
66	
70	
71	
72	
73	
73M	
74	
74M	
75	
75M	
76	
76M	
77	
77M	
78	
79	
80	
81	
A	Patch and repair as needed then follow O&M plan.
B	
C	

Chicago Public Schools

School Bethune School

Unit 26611

Building ID 8020

Address 3030 W. Arthington

Chicago, IL, 60612

Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26611** BUIDLING ID: **8020**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Feely**
SCHOOL NAME: **Bethune School** INSPECTION DATE: **2/19/2016**
ADDRESS: **3030 W. Arthington** IDPH LICENSE NO: **100-00249**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **001**
MATERIAL DESCRIPTION: **Hard Plaster**
HISTORICAL AHERA DAMAGE CATEGORY **7 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Throughout Facility**
MATERIAL QUANTITY: **30000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: 02/19/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26611** BUIDLING ID: **8020**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Bethune School** REVIEW DATE: **3/25/2016**
ADDRESS: **3030 W. Arthington** IDPH LICENSE NO: **100-00249**

HOMOGENEOUS AREA: **001**
MATERIAL DESCRIPTION: **Hard Plaster**
MATERIAL LOCATION: **Throughout Facility**
MATERIAL QUANTITY: **30000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **03/25/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26611** BUIDLING ID: **8020**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Feely**
SCHOOL NAME: **Bethune School** INSPECTION DATE: **2/19/2016**
ADDRESS: **3030 W. Arthington** IDPH LICENSE NO: **100-00249**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **002**
MATERIAL DESCRIPTION: **Acoustical Plaster**
HISTORICAL AHERA DAMAGE CATEGORY **7 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1st, 2nd, 3rd, floor. Assumed to be beneath new popcorn ceiling.**
MATERIAL QUANTITY: **30000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 02/19/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26611** BUIDLING ID: **8020**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Bethune School** REVIEW DATE: **3/25/2016**
ADDRESS: **3030 W. Arthington** IDPH LICENSE NO: **100-00249**

HOMOGENEOUS AREA: **002**
MATERIAL DESCRIPTION: **Acoustical Plaster**
MATERIAL LOCATION: **1st, 2nd, 3rd, floor. Assumed to be beneath new popcorn ceiling.**
MATERIAL QUANTITY: **30000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **03/25/2016**

Chicago Public Schools

Carnow, Conibear and Associates 2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26611** BUIDLING ID: **8020**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Feely**
SCHOOL NAME: **Bethune School** INSPECTION DATE: **2/19/2016**
ADDRESS: **3030 W. Arthington** IDPH LICENSE NO: **100-00249**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **003**
MATERIAL DESCRIPTION: **9"x9" Tan Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **101,102,104,105,113,200,201,202,204,205,208,210,214A,216,217,214,2nd fl storage,300,302,304,305,307,308,311,313**

MATERIAL QUANTITY: **16200** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 02/19/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26611** BUIDLING ID: **8020**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Bethune School** REVIEW DATE: **3/25/2016**
ADDRESS: **3030 W. Arthington** IDPH LICENSE NO: **100-00249**

HOMOGENEOUS AREA: **003**
MATERIAL DESCRIPTION: **9"x9" Tan Floor Tile**
MATERIAL LOCATION: **101,102,104,105,113,200,201,202,204,205,208,210,214A,216,217,214,2nd fl storage,300,302,304,305,307,308,311,313**
MATERIAL QUANTITY: **16200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **03/25/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26611** BUIDLING ID: **8020**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Feely**
SCHOOL NAME: **Bethune School** INSPECTION DATE: **2/19/2016**
ADDRESS: **3030 W. Arthington** IDPH LICENSE NO: **100-00249**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **004**
MATERIAL DESCRIPTION: **Spray-on Insulation**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **All I-Beams Throughout Facility**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Not observed 2016**

Inspector's Signature: _____ Date: **02/19/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26611** BUIDLING ID: **8020**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Bethune School** REVIEW DATE: **3/25/2016**
ADDRESS: **3030 W. Arthington** IDPH LICENSE NO: **100-00249**

HOMOGENEOUS AREA: **004**
MATERIAL DESCRIPTION: **Spray-on Insulation**
MATERIAL LOCATION: **All I-Beams Throughout Facility**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

If identified, implement O&M

Management Planner's Signature: _____



Date: **03/25/2016**

Chicago Public Schools

Carnow, Conibear and Associates 2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26611** BUIDLING ID: **8020**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Feely**
SCHOOL NAME: **Bethune School** INSPECTION DATE: **2/19/2016**
ADDRESS: **3030 W. Arthington** IDPH LICENSE NO: **100-00249**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **005**
MATERIAL DESCRIPTION: **9"x9" Tan Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **101,102,104,105,113,200,201,202,204,205,208,210,214A,216,217,214,2nd fl storage,300,302,304,305,307,308,311,313**

MATERIAL QUANTITY: **16200** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 02/19/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26611** BUIDLING ID: **8020**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Bethune School** REVIEW DATE: **3/25/2016**
ADDRESS: **3030 W. Arthington** IDPH LICENSE NO: **100-00249**

HOMOGENEOUS AREA: **005**
MATERIAL DESCRIPTION: **9"x9" Tan Floor Tile Mastic**
MATERIAL LOCATION: **101,102,104,105,113,200,201,202,204,205,208,210,214A,216,217,214,2nd fl storage,300,302,304,305,307,308,311,313**
MATERIAL QUANTITY: **16200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **03/25/2016**

Chicago Public Schools

Carnow, Conibear and Associates 2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26611** BUIDLING ID: **8020**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Feely**
SCHOOL NAME: **Bethune School** INSPECTION DATE: **2/19/2016**
ADDRESS: **3030 W. Arthington** IDPH LICENSE NO: **100-00249**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **006**
MATERIAL DESCRIPTION: **9"x9" Green Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **209,203,212,215,303,306,101, Kitch Office&storage, Teacher Lounges, 215,308 storage, 2nd fl janitor clo**

MATERIAL QUANTITY: **8550**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____

Date: 02/19/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26611** BUIDLING ID: **8020**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Bethune School** REVIEW DATE: **3/25/2016**
ADDRESS: **3030 W. Arthington** IDPH LICENSE NO: **100-00249**

HOMOGENEOUS AREA: **006**
MATERIAL DESCRIPTION: **9"x9" Green Floor Tile**
MATERIAL LOCATION: **209,203,212,215,303,306,101, Kitch Office&storage, Teacher Lounges, 215,308 storage, 2nd fl janitor clo**
MATERIAL QUANTITY: **8550** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **03/25/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26611** BUIDLING ID: **8020**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Feely**
SCHOOL NAME: **Bethune School** INSPECTION DATE: **2/19/2016**
ADDRESS: **3030 W. Arthington** IDPH LICENSE NO: **100-00249**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **007**
MATERIAL DESCRIPTION: **9"x9" Green Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **209,203,212,215,303,306,101,Kitch Office&storage,Teacher Lounge,215,308 storage,2nd fl janitor closet**

MATERIAL QUANTITY: **8550** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 02/19/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26611** BUIDLING ID: **8020**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Bethune School** REVIEW DATE: **3/25/2016**
ADDRESS: **3030 W. Arthington** IDPH LICENSE NO: **100-00249**

HOMOGENEOUS AREA: **007**
MATERIAL DESCRIPTION: **9"x9" Green Floor Tile Mastic**
MATERIAL LOCATION: **209,203,212,215,303,306,101,Kitch Office&storage,Teacher Lounge,215,308 storage,2nd fl janitor closet**
MATERIAL QUANTITY: **8550** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **03/25/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26611** BUIDLING ID: **8020**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Feely**
SCHOOL NAME: **Bethune School** INSPECTION DATE: **2/19/2016**
ADDRESS: **3030 W. Arthington** IDPH LICENSE NO: **100-00249**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **008**
MATERIAL DESCRIPTION: **9" x 9" Dark Brown Floor Tile with white specks**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Room 206, 3rd floor janitor's closet**

MATERIAL QUANTITY: **750**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____

Date: 02/19/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26611** BUIDLING ID: **8020**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Bethune School** REVIEW DATE: **3/25/2016**
ADDRESS: **3030 W. Arthington** IDPH LICENSE NO: **100-00249**

HOMOGENEOUS AREA: **008**
MATERIAL DESCRIPTION: **9" x 9" Dark Brown Floor Tile with white specks**
MATERIAL LOCATION: **Room 206, 3rd floor janitor's closet**
MATERIAL QUANTITY: **750** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **03/25/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26611** BUIDLING ID: **8020**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Feely**
SCHOOL NAME: **Bethune School** INSPECTION DATE: **2/19/2016**
ADDRESS: **3030 W. Arthington** IDPH LICENSE NO: **100-00249**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **009**
MATERIAL DESCRIPTION: **9"x9" Dark Brown Floor Tile Mastic w/ white specks**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Room 206, 3rd floor janitor's closet**

MATERIAL QUANTITY: **750**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____

Date: 02/19/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26611** BUIDLING ID: **8020**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Bethune School** REVIEW DATE: **3/25/2016**
ADDRESS: **3030 W. Arthington** IDPH LICENSE NO: **100-00249**

HOMOGENEOUS AREA: **009**
MATERIAL DESCRIPTION: **9"x9" Dark Brown Floor Tile Mastic w/ white specks**
MATERIAL LOCATION: **Room 206, 3rd floor janitor's closet**
MATERIAL QUANTITY: **750** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **03/25/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26611** BUIDLING ID: **8020**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Feely**
SCHOOL NAME: **Bethune School** INSPECTION DATE: **2/19/2016**
ADDRESS: **3030 W. Arthington** IDPH LICENSE NO: **100-00249**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **010**
MATERIAL DESCRIPTION: **4" Black Baseboard Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 306**
MATERIAL QUANTITY: **100** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: _____ Date: 02/19/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26611** BUIDLING ID: **8020**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Bethune School** REVIEW DATE: **3/25/2016**
ADDRESS: **3030 W. Arthington** IDPH LICENSE NO: **100-00249**

HOMOGENEOUS AREA: **010**
MATERIAL DESCRIPTION: **4" Black Baseboard Mastic**
MATERIAL LOCATION: **Room 306**
MATERIAL QUANTITY: **100** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **03/25/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26611** BUIDLING ID: **8020**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Feely**
SCHOOL NAME: **Bethune School** INSPECTION DATE: **2/19/2016**
ADDRESS: **3030 W. Arthington** IDPH LICENSE NO: **100-00249**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **011**
MATERIAL DESCRIPTION: **Drywall & Compound**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms 113, 306, 315, 115**
MATERIAL QUANTITY: **400** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: _____ Date: 02/19/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26611** BUIDLING ID: **8020**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Bethune School** REVIEW DATE: **3/25/2016**
ADDRESS: **3030 W. Arthington** IDPH LICENSE NO: **100-00249**

HOMOGENEOUS AREA: **011**
MATERIAL DESCRIPTION: **Drywall & Compound**
MATERIAL LOCATION: **Rooms 113, 306, 315, 115**
MATERIAL QUANTITY: **400** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **03/25/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26611** BUIDLING ID: **8020**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Feely**
SCHOOL NAME: **Bethune School** INSPECTION DATE: **2/19/2016**
ADDRESS: **3030 W. Arthington** IDPH LICENSE NO: **100-00249**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **012**
MATERIAL DESCRIPTION: **Acoustical Popcorn Ceiling**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **106, 108, 112 and Corridors**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 02/19/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26611** BUIDLING ID: **8020**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Bethune School** REVIEW DATE: **3/25/2016**
ADDRESS: **3030 W. Arthington** IDPH LICENSE NO: **100-00249**

HOMOGENEOUS AREA: **012**
MATERIAL DESCRIPTION: **Acoustical Popcorn Ceiling**
MATERIAL LOCATION: **106, 108, 112 and Corridors**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **03/25/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26611** BUIDLING ID: **8020**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Feely**
SCHOOL NAME: **Bethune School** INSPECTION DATE: **2/19/2016**
ADDRESS: **3030 W. Arthington** IDPH LICENSE NO: **100-00249**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **013**
MATERIAL DESCRIPTION: **Window Glazing**
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout School**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Not observed 2016**

Inspector's Signature: _____ Date: 02/19/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26611** BUIDLING ID: **8020**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Bethune School** REVIEW DATE: **3/25/2016**
ADDRESS: **3030 W. Arthington** IDPH LICENSE NO: **100-00249**

HOMOGENEOUS AREA: **013**
MATERIAL DESCRIPTION: **Window Glazing**
MATERIAL LOCATION: **Throughout School**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.


The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

If identified, implement O&M

Management Planner's Signature: _____



Date: **03/25/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26611** BUIDLING ID: **8020**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Feely**
SCHOOL NAME: **Bethune School** INSPECTION DATE: **2/19/2016**
ADDRESS: **3030 W. Arthington** IDPH LICENSE NO: **100-00249**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **014**
MATERIAL DESCRIPTION: **Exterior Brick**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Exterior**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **02/19/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26611** BUIDLING ID: **8020**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Bethune School** REVIEW DATE: **3/25/2016**
ADDRESS: **3030 W. Arthington** IDPH LICENSE NO: **100-00249**

HOMOGENEOUS AREA: **014**

MATERIAL DESCRIPTION: **Exterior Brick**

MATERIAL LOCATION: **Exterior**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **03/25/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26611** BUIDLING ID: **8020**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Feely**
SCHOOL NAME: **Bethune School** INSPECTION DATE: **2/19/2016**
ADDRESS: **3030 W. Arthington** IDPH LICENSE NO: **100-00249**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **015**
MATERIAL DESCRIPTION: **Exterior Brick Mortar**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Exterior**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 02/19/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26611** BUIDLING ID: **8020**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Bethune School** REVIEW DATE: **3/25/2016**
ADDRESS: **3030 W. Arthington** IDPH LICENSE NO: **100-00249**

HOMOGENEOUS AREA: **015**
MATERIAL DESCRIPTION: **Exterior Brick Mortar**
MATERIAL LOCATION: **Exterior**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **03/25/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26611** BUIDLING ID: **8020**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Feely**
SCHOOL NAME: **Bethune School** INSPECTION DATE: **2/19/2016**
ADDRESS: **3030 W. Arthington** IDPH LICENSE NO: **100-00249**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **016 A**
MATERIAL DESCRIPTION: **12"x12" Tan Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Corridors, room 209 (as patch)**

MATERIAL QUANTITY: **7900**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____

Date: 02/19/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26611** BUIDLING ID: **8020**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Bethune School** REVIEW DATE: **3/25/2016**
ADDRESS: **3030 W. Arthington** IDPH LICENSE NO: **100-00249**

HOMOGENEOUS AREA: **016 A**
MATERIAL DESCRIPTION: **12"x12" Tan Floor Tile**
MATERIAL LOCATION: **Corridors, room 209 (as patch)**
MATERIAL QUANTITY: **7900** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **03/25/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26611** BUIDLING ID: **8020**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Feely**
SCHOOL NAME: **Bethune School** INSPECTION DATE: **2/19/2016**
ADDRESS: **3030 W. Arthington** IDPH LICENSE NO: **100-00249**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **016 B**
MATERIAL DESCRIPTION: **12" x 12" Brown Mix Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Corridors, 107 & Office**

MATERIAL QUANTITY: **7900**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____

Date: 02/19/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26611** BUIDLING ID: **8020**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Bethune School** REVIEW DATE: **3/25/2016**
ADDRESS: **3030 W. Arthington** IDPH LICENSE NO: **100-00249**

HOMOGENEOUS AREA: **016 B**
MATERIAL DESCRIPTION: **12" x 12" Brown Mix Floor Tile**
MATERIAL LOCATION: **Corridors, 107 & Office**
MATERIAL QUANTITY: **7900** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **03/25/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26611** BUIDLING ID: **8020**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Feely**
SCHOOL NAME: **Bethune School** INSPECTION DATE: **2/19/2016**
ADDRESS: **3030 W. Arthington** IDPH LICENSE NO: **100-00249**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **017 A**
MATERIAL DESCRIPTION: **12"x12" Tan Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Corridors, room 209 (as patch)**

MATERIAL QUANTITY: **7900**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____

Date: 02/19/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26611** BUIDLING ID: **8020**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Bethune School** REVIEW DATE: **3/25/2016**
ADDRESS: **3030 W. Arthington** IDPH LICENSE NO: **100-00249**

HOMOGENEOUS AREA: **017 A**
MATERIAL DESCRIPTION: **12"x12" Tan Floor Tile Mastic**
MATERIAL LOCATION: **Corridors, room 209 (as patch)**
MATERIAL QUANTITY: **7900** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **03/25/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26611** BUIDLING ID: **8020**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Feely**
SCHOOL NAME: **Bethune School** INSPECTION DATE: **2/19/2016**
ADDRESS: **3030 W. Arthington** IDPH LICENSE NO: **100-00249**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **017 B**
MATERIAL DESCRIPTION: **12" x 12" Brown Mix Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Corridors, 107 & Office**

MATERIAL QUANTITY: **7900**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____

Date: 02/19/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26611** BUIDLING ID: **8020**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Bethune School** REVIEW DATE: **3/25/2016**
ADDRESS: **3030 W. Arthington** IDPH LICENSE NO: **100-00249**

HOMOGENEOUS AREA: **017 B**
MATERIAL DESCRIPTION: **12" x 12" Brown Mix Floor Tile Mastic**
MATERIAL LOCATION: **Corridors, 107 & Office**
MATERIAL QUANTITY: **7900** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **03/25/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26611** BUIDLING ID: **8020**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Feely**
SCHOOL NAME: **Bethune School** INSPECTION DATE: **2/19/2016**
ADDRESS: **3030 W. Arthington** IDPH LICENSE NO: **100-00249**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **018**
MATERIAL DESCRIPTION: **12"x12" Pink Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Assistant Principal's Office**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed 2016**

Inspector's Signature: _____

Date: 02/19/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26611** BUIDLING ID: **8020**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Bethune School** REVIEW DATE: **3/25/2016**
ADDRESS: **3030 W. Arthington** IDPH LICENSE NO: **100-00249**

HOMOGENEOUS AREA: **018**
MATERIAL DESCRIPTION: **12"x12" Pink Floor Tile**
MATERIAL LOCATION: **Assistant Principal's Office**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

If identified, implement O&M

Management Planner's Signature: _____



Date: **03/25/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26611** BUIDLING ID: **8020**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Feely**
SCHOOL NAME: **Bethune School** INSPECTION DATE: **2/19/2016**
ADDRESS: **3030 W. Arthington** IDPH LICENSE NO: **100-00249**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **019**
MATERIAL DESCRIPTION: **12"x12" Pink Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Assistant Principal's Office**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed 2016**

Inspector's Signature: _____

Date: 02/19/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26611** BUIDLING ID: **8020**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Bethune School** REVIEW DATE: **3/25/2016**
ADDRESS: **3030 W. Arthington** IDPH LICENSE NO: **100-00249**

HOMOGENEOUS AREA: **019**
MATERIAL DESCRIPTION: **12"x12" Pink Floor Tile Mastic**
MATERIAL LOCATION: **Assistant Principal's Office**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

If identified, implement O&M

Management Planner's Signature: _____



Date: **03/25/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26611** BUIDLING ID: **8020**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Feely**
SCHOOL NAME: **Bethune School** INSPECTION DATE: **2/19/2016**
ADDRESS: **3030 W. Arthington** IDPH LICENSE NO: **100-00249**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **020 A**
MATERIAL DESCRIPTION: **12"x12" White Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Lunch Room, 112**

MATERIAL QUANTITY: **1595**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____

Date: 02/19/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26611** BUIDLING ID: **8020**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Bethune School** REVIEW DATE: **3/25/2016**
ADDRESS: **3030 W. Arthington** IDPH LICENSE NO: **100-00249**

HOMOGENEOUS AREA: **020 A**
MATERIAL DESCRIPTION: **12"x12" White Floor Tile**
MATERIAL LOCATION: **Lunch Room, 112**
MATERIAL QUANTITY: **1595** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **03/25/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26611** BUIDLING ID: **8020**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Feely**
SCHOOL NAME: **Bethune School** INSPECTION DATE: **2/19/2016**
ADDRESS: **3030 W. Arthington** IDPH LICENSE NO: **100-00249**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **020 B**
MATERIAL DESCRIPTION: **12" x 12" Blue Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Lunch Room**
MATERIAL QUANTITY: **1595** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 02/19/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26611** BUIDLING ID: **8020**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Bethune School** REVIEW DATE: **3/25/2016**
ADDRESS: **3030 W. Arthington** IDPH LICENSE NO: **100-00249**

HOMOGENEOUS AREA: **020 B**
MATERIAL DESCRIPTION: **12" x 12" Blue Floor Tile**
MATERIAL LOCATION: **Lunch Room**
MATERIAL QUANTITY: **1595** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **03/25/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26611** BUIDLING ID: **8020**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Feely**
SCHOOL NAME: **Bethune School** INSPECTION DATE: **2/19/2016**
ADDRESS: **3030 W. Arthington** IDPH LICENSE NO: **100-00249**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **021 A**
MATERIAL DESCRIPTION: **12"x12" White Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Lunch Room, 112**

MATERIAL QUANTITY: **2138**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____

Date: 02/19/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26611** BUIDLING ID: **8020**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Bethune School** REVIEW DATE: **3/25/2016**
ADDRESS: **3030 W. Arthington** IDPH LICENSE NO: **100-00249**

HOMOGENEOUS AREA: **021 A**
MATERIAL DESCRIPTION: **12"x12" White Floor Tile Mastic**
MATERIAL LOCATION: **Lunch Room, 112**
MATERIAL QUANTITY: **2138** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **03/25/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26611** BUIDLING ID: **8020**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Feely**
SCHOOL NAME: **Bethune School** INSPECTION DATE: **2/19/2016**
ADDRESS: **3030 W. Arthington** IDPH LICENSE NO: **100-00249**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **021 B**
MATERIAL DESCRIPTION: **12" x 12" Blue Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Lunch Room, 112**

MATERIAL QUANTITY: **2138**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____

Date: 02/19/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26611** BUIDLING ID: **8020**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Bethune School** REVIEW DATE: **3/25/2016**
ADDRESS: **3030 W. Arthington** IDPH LICENSE NO: **100-00249**

HOMOGENEOUS AREA: **021 B**
MATERIAL DESCRIPTION: **12" x 12" Blue Floor Tile Mastic**
MATERIAL LOCATION: **Lunch Room, 112**
MATERIAL QUANTITY: **2138** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **03/25/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26611** BUIDLING ID: **8020**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Feely**
SCHOOL NAME: **Bethune School** INSPECTION DATE: **2/19/2016**
ADDRESS: **3030 W. Arthington** IDPH LICENSE NO: **100-00249**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **022**
MATERIAL DESCRIPTION: **12"x12" White Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Lunch Room Storage Area, Main Office, Vault**

MATERIAL QUANTITY: **950** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 02/19/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26611** BUIDLING ID: **8020**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Bethune School** REVIEW DATE: **3/25/2016**
ADDRESS: **3030 W. Arthington** IDPH LICENSE NO: **100-00249**

HOMOGENEOUS AREA: **022**
MATERIAL DESCRIPTION: **12"x12" White Floor Tile**
MATERIAL LOCATION: **Lunch Room Storage Area, Main Office, Vault**
MATERIAL QUANTITY: **950** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **03/25/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26611** BUIDLING ID: **8020**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Feely**
SCHOOL NAME: **Bethune School** INSPECTION DATE: **2/19/2016**
ADDRESS: **3030 W. Arthington** IDPH LICENSE NO: **100-00249**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **023**
MATERIAL DESCRIPTION: **12"x12" White Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Lunch Room Storage Area, Main Office, Vault**

MATERIAL QUANTITY: **950** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 02/19/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26611** BUIDLING ID: **8020**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Bethune School** REVIEW DATE: **3/25/2016**
ADDRESS: **3030 W. Arthington** IDPH LICENSE NO: **100-00249**

HOMOGENEOUS AREA: **023**
MATERIAL DESCRIPTION: **12"x12" White Floor Tile Mastic**
MATERIAL LOCATION: **Lunch Room Storage Area, Main Office, Vault**
MATERIAL QUANTITY: **950** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **03/25/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26611** BUIDLING ID: **8020**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Feely**
SCHOOL NAME: **Bethune School** INSPECTION DATE: **2/19/2016**
ADDRESS: **3030 W. Arthington** IDPH LICENSE NO: **100-00249**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **024 A**
MATERIAL DESCRIPTION: **12"x12" Yellow Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 106**
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 02/19/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26611** BUIDLING ID: **8020**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Bethune School** REVIEW DATE: **3/25/2016**
ADDRESS: **3030 W. Arthington** IDPH LICENSE NO: **100-00249**

HOMOGENEOUS AREA: **024 A**
MATERIAL DESCRIPTION: **12"x12" Yellow Floor Tile**
MATERIAL LOCATION: **Room 106**
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **03/25/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26611** BUIDLING ID: **8020**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Feely**
SCHOOL NAME: **Bethune School** INSPECTION DATE: **2/19/2016**
ADDRESS: **3030 W. Arthington** IDPH LICENSE NO: **100-00249**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **024 B**
MATERIAL DESCRIPTION: **12" x 12" Light Yellow Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 106**
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 02/19/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26611** BUIDLING ID: **8020**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Bethune School** REVIEW DATE: **3/25/2016**
ADDRESS: **3030 W. Arthington** IDPH LICENSE NO: **100-00249**

HOMOGENEOUS AREA: **024 B**
MATERIAL DESCRIPTION: **12" x 12" Light Yellow Floor Tile**
MATERIAL LOCATION: **Room 106**
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **03/25/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26611** BUIDLING ID: **8020**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Feely**
SCHOOL NAME: **Bethune School** INSPECTION DATE: **2/19/2016**
ADDRESS: **3030 W. Arthington** IDPH LICENSE NO: **100-00249**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **025 A**
MATERIAL DESCRIPTION: **12"x12" Yellow Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 106**
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 02/19/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26611** BUIDLING ID: **8020**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Bethune School** REVIEW DATE: **3/25/2016**
ADDRESS: **3030 W. Arthington** IDPH LICENSE NO: **100-00249**

HOMOGENEOUS AREA: **025 A**
MATERIAL DESCRIPTION: **12"x12" Yellow Floor Tile Mastic**
MATERIAL LOCATION: **Room 106**
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **03/25/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26611** BUIDLING ID: **8020**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Feely**
SCHOOL NAME: **Bethune School** INSPECTION DATE: **2/19/2016**
ADDRESS: **3030 W. Arthington** IDPH LICENSE NO: **100-00249**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **025 B**
MATERIAL DESCRIPTION: **12" x 12" Light Yellow Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 106**
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 02/19/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26611** BUIDLING ID: **8020**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Bethune School** REVIEW DATE: **3/25/2016**
ADDRESS: **3030 W. Arthington** IDPH LICENSE NO: **100-00249**

HOMOGENEOUS AREA: **025 B**
MATERIAL DESCRIPTION: **12" x 12" Light Yellow Floor Tile Mastic**
MATERIAL LOCATION: **Room 106**
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **03/25/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26611** BUIDLING ID: **8020**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Feely**
SCHOOL NAME: **Bethune School** INSPECTION DATE: **2/19/2016**
ADDRESS: **3030 W. Arthington** IDPH LICENSE NO: **100-00249**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **026**
MATERIAL DESCRIPTION: **12"x12" Green Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 112**
MATERIAL QUANTITY: **562** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 02/19/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26611** BUIDLING ID: **8020**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Bethune School** REVIEW DATE: **3/25/2016**
ADDRESS: **3030 W. Arthington** IDPH LICENSE NO: **100-00249**

HOMOGENEOUS AREA: **026**
MATERIAL DESCRIPTION: **12"x12" Green Floor Tile**
MATERIAL LOCATION: **Room 112**
MATERIAL QUANTITY: **562** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **03/25/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26611** BUIDLING ID: **8020**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Feely**
SCHOOL NAME: **Bethune School** INSPECTION DATE: **2/19/2016**
ADDRESS: **3030 W. Arthington** IDPH LICENSE NO: **100-00249**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **027**
MATERIAL DESCRIPTION: **12"x12" Green Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 112**
MATERIAL QUANTITY: **562** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 02/19/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26611** BUIDLING ID: **8020**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Bethune School** REVIEW DATE: **3/25/2016**
ADDRESS: **3030 W. Arthington** IDPH LICENSE NO: **100-00249**

HOMOGENEOUS AREA: **027**
MATERIAL DESCRIPTION: **12"x12" Green Floor Tile Mastic**
MATERIAL LOCATION: **Room 112**
MATERIAL QUANTITY: **562** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **03/25/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26611** BUIDLING ID: **8020**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Feely**
SCHOOL NAME: **Bethune School** INSPECTION DATE: **2/19/2016**
ADDRESS: **3030 W. Arthington** IDPH LICENSE NO: **100-00249**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **028 A**
MATERIAL DESCRIPTION: **12"x12" Black w/White Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 108, as patches in various classrooms & boiler rm, wash rm**
MATERIAL QUANTITY: **480** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 02/19/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26611** BUIDLING ID: **8020**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Bethune School** REVIEW DATE: **3/25/2016**
ADDRESS: **3030 W. Arthington** IDPH LICENSE NO: **100-00249**

HOMOGENEOUS AREA: **028 A**
MATERIAL DESCRIPTION: **12"x12" Black w/White Floor Tile**
MATERIAL LOCATION: **Room 108, as patches in various classrooms & boiler rm, wash rm**
MATERIAL QUANTITY: **480** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **03/25/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26611** BUIDLING ID: **8020**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Feely**
SCHOOL NAME: **Bethune School** INSPECTION DATE: **2/19/2016**
ADDRESS: **3030 W. Arthington** IDPH LICENSE NO: **100-00249**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **028 B**
MATERIAL DESCRIPTION: **12" x 12" White w/Black Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 108**
MATERIAL QUANTITY: **480** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 02/19/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26611** BUIDLING ID: **8020**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Bethune School** REVIEW DATE: **3/25/2016**
ADDRESS: **3030 W. Arthington** IDPH LICENSE NO: **100-00249**

HOMOGENEOUS AREA: **028 B**

MATERIAL DESCRIPTION: **12" x 12" White w/Black Floor Tile**

MATERIAL LOCATION: **Room 108**

MATERIAL QUANTITY: **480**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **03/25/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26611** BUIDLING ID: **8020**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Feely**
SCHOOL NAME: **Bethune School** INSPECTION DATE: **2/19/2016**
ADDRESS: **3030 W. Arthington** IDPH LICENSE NO: **100-00249**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **029 A**
MATERIAL DESCRIPTION: **12"x12" Black w/White Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 108, as patches in various classrooms & boiler rm, wash rm**
MATERIAL QUANTITY: **480** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 02/19/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26611** BUIDLING ID: **8020**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Bethune School** REVIEW DATE: **3/25/2016**
ADDRESS: **3030 W. Arthington** IDPH LICENSE NO: **100-00249**

HOMOGENEOUS AREA: **029 A**
MATERIAL DESCRIPTION: **12"x12" Black w/White Floor Tile Mastic**
MATERIAL LOCATION: **Room 108, as patches in various classrooms & boiler rm, wash rm**
MATERIAL QUANTITY: **480** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **03/25/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26611** BUIDLING ID: **8020**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Feely**
SCHOOL NAME: **Bethune School** INSPECTION DATE: **2/19/2016**
ADDRESS: **3030 W. Arthington** IDPH LICENSE NO: **100-00249**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **029 B**
MATERIAL DESCRIPTION: **12" x 12" White w/ Black Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with potential for significant damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Room 108**

MATERIAL QUANTITY: **480**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____

Date: 02/19/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26611** BUIDLING ID: **8020**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Bethune School** REVIEW DATE: **3/25/2016**
ADDRESS: **3030 W. Arthington** IDPH LICENSE NO: **100-00249**

HOMOGENEOUS AREA: **029 B**
MATERIAL DESCRIPTION: **12" x 12" White w/ Black Floor Tile Mastic**
MATERIAL LOCATION: **Room 108**
MATERIAL QUANTITY: **480** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **03/25/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26611** BUIDLING ID: **8020**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Feely**
SCHOOL NAME: **Bethune School** INSPECTION DATE: **2/19/2016**
ADDRESS: **3030 W. Arthington** IDPH LICENSE NO: **100-00249**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **030**
MATERIAL DESCRIPTION: **Carpet Mastic**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Rooms 306, 308, 309, 310, 311, 312, 313, 314, 315**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Not observed 2016**

Inspector's Signature: _____ Date: **02/19/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26611** BUIDLING ID: **8020**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Bethune School** REVIEW DATE: **3/25/2016**
ADDRESS: **3030 W. Arthington** IDPH LICENSE NO: **100-00249**

HOMOGENEOUS AREA: **030**
MATERIAL DESCRIPTION: **Carpet Mastic**
MATERIAL LOCATION: **Rooms 306, 308, 309, 310, 311, 312, 313, 314, 315**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

If identified, implement O&M

Management Planner's Signature: _____



Date: **03/25/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26611** BUIDLING ID: **8020**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Feely**
SCHOOL NAME: **Bethune School** INSPECTION DATE: **2/19/2016**
ADDRESS: **3030 W. Arthington** IDPH LICENSE NO: **100-00249**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **031**
MATERIAL DESCRIPTION: **Boiler Room Fire Doors**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY: **4**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____

Date: 02/19/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26611** BUIDLING ID: **8020**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Bethune School** REVIEW DATE: **3/25/2016**
ADDRESS: **3030 W. Arthington** IDPH LICENSE NO: **100-00249**

HOMOGENEOUS AREA: **031**
MATERIAL DESCRIPTION: **Boiler Room Fire Doors**
MATERIAL LOCATION: **Boiler Room**
MATERIAL QUANTITY: **4** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **03/25/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26611** BUIDLING ID: **8020**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Feely**
SCHOOL NAME: **Bethune School** INSPECTION DATE: **2/19/2016**
ADDRESS: **3030 W. Arthington** IDPH LICENSE NO: **100-00249**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **032**
MATERIAL DESCRIPTION: **Vault Door**
HISTORICAL AHERA DAMAGE CATEGORY **7 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Main Office, 1st floor hall**
MATERIAL QUANTITY: **56** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 02/19/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26611** BUIDLING ID: **8020**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Bethune School** REVIEW DATE: **3/25/2016**
ADDRESS: **3030 W. Arthington** IDPH LICENSE NO: **100-00249**

HOMOGENEOUS AREA: **032**
MATERIAL DESCRIPTION: **Vault Door**
MATERIAL LOCATION: **Main Office, 1st floor hall**
MATERIAL QUANTITY: **56** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **03/25/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26611** BUIDLING ID: **8020**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Feely**
SCHOOL NAME: **Bethune School** INSPECTION DATE: **2/19/2016**
ADDRESS: **3030 W. Arthington** IDPH LICENSE NO: **100-00249**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **033**
MATERIAL DESCRIPTION: **Interior Boiler Insulation**
HISTORICAL AHERA DAMAGE CATEGORY **7 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Boiler Room**
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 02/19/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26611** BUIDLING ID: **8020**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Bethune School** REVIEW DATE: **3/25/2016**
ADDRESS: **3030 W. Arthington** IDPH LICENSE NO: **100-00249**

HOMOGENEOUS AREA: **033**
MATERIAL DESCRIPTION: **Interior Boiler Insulation**
MATERIAL LOCATION: **Boiler Room**
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **03/25/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26611** BUIDLING ID: **8020**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Feely**
SCHOOL NAME: **Bethune School** INSPECTION DATE: **2/19/2016**
ADDRESS: **3030 W. Arthington** IDPH LICENSE NO: **100-00249**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **034**
MATERIAL DESCRIPTION: **Transite Table Tops**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Science Room 217**
MATERIAL QUANTITY: **150** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 02/19/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26611** BUIDLING ID: **8020**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Bethune School** REVIEW DATE: **3/25/2016**
ADDRESS: **3030 W. Arthington** IDPH LICENSE NO: **100-00249**

HOMOGENEOUS AREA: **034**
MATERIAL DESCRIPTION: **Transite Table Tops**
MATERIAL LOCATION: **Science Room 217**
MATERIAL QUANTITY: **150** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **03/25/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26611** BUIDLING ID: **8020**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Feely**
SCHOOL NAME: **Bethune School** INSPECTION DATE: **2/19/2016**
ADDRESS: **3030 W. Arthington** IDPH LICENSE NO: **100-00249**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **035**
MATERIAL DESCRIPTION: **Interior Portion of Heating Units**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Classrooms**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed 2016**

Inspector's Signature: _____ Date: **02/19/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26611** BUIDLING ID: **8020**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Bethune School** REVIEW DATE: **3/25/2016**
ADDRESS: **3030 W. Arthington** IDPH LICENSE NO: **100-00249**

HOMOGENEOUS AREA: **035**
MATERIAL DESCRIPTION: **Interior Portion of Heating Units**
MATERIAL LOCATION: **Classrooms**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

If identified, implement O&M

Management Planner's Signature: _____



Date: **03/25/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26611** BUIDLING ID: **8020**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Feely**
SCHOOL NAME: **Bethune School** INSPECTION DATE: **2/19/2016**
ADDRESS: **3030 W. Arthington** IDPH LICENSE NO: **100-00249**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **036**
MATERIAL DESCRIPTION: **4" Black Baseboard**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms 306**
MATERIAL QUANTITY: **100** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: _____ Date: 02/19/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26611** BUIDLING ID: **8020**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Bethune School** REVIEW DATE: **3/25/2016**
ADDRESS: **3030 W. Arthington** IDPH LICENSE NO: **100-00249**

HOMOGENEOUS AREA: **036**
MATERIAL DESCRIPTION: **4" Black Baseboard**
MATERIAL LOCATION: **Rooms 306**
MATERIAL QUANTITY: **100** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **03/25/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26611** BUIDLING ID: **8020**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Feely**
SCHOOL NAME: **Bethune School** INSPECTION DATE: **2/19/2016**
ADDRESS: **3030 W. Arthington** IDPH LICENSE NO: **100-00249**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **037**
MATERIAL DESCRIPTION: **Material Beneath Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Lunch Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed 2016**

Inspector's Signature: _____ Date: **02/19/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26611** BUIDLING ID: **8020**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Bethune School** REVIEW DATE: **3/25/2016**
ADDRESS: **3030 W. Arthington** IDPH LICENSE NO: **100-00249**

HOMOGENEOUS AREA: **037**
MATERIAL DESCRIPTION: **Material Beneath Floor Tile**
MATERIAL LOCATION: **Lunch Room**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.


The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

If identified, implement O&M

Management Planner's Signature: _____



Date: **03/25/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26611** BUIDLING ID: **8020**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Feely**
SCHOOL NAME: **Bethune School** INSPECTION DATE: **2/19/2016**
ADDRESS: **3030 W. Arthington** IDPH LICENSE NO: **100-00249**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **038**
MATERIAL DESCRIPTION: **Mastic for Material Beneath Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY: **ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Lunch Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed 2016**

Inspector's Signature: _____

Date: 02/19/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26611** BUIDLING ID: **8020**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Bethune School** REVIEW DATE: **3/25/2016**
ADDRESS: **3030 W. Arthington** IDPH LICENSE NO: **100-00249**

HOMOGENEOUS AREA: **038**

MATERIAL DESCRIPTION: **Mastic for Material Beneath Floor Tile**

MATERIAL LOCATION: **Lunch Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

If identified, implement O&M

Management Planner's Signature: _____



Date: **03/25/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26611** BUIDLING ID: **8020**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Feely**
SCHOOL NAME: **Bethune School** INSPECTION DATE: **2/19/2016**
ADDRESS: **3030 W. Arthington** IDPH LICENSE NO: **100-00249**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **039**
MATERIAL DESCRIPTION: **12" x 12" White Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 112**
MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 02/19/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26611** BUIDLING ID: **8020**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Bethune School** REVIEW DATE: **3/25/2016**
ADDRESS: **3030 W. Arthington** IDPH LICENSE NO: **100-00249**

HOMOGENEOUS AREA: **039**
MATERIAL DESCRIPTION: **12" x 12" White Floor Tile**
MATERIAL LOCATION: **Room 112**
MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **03/25/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26611** BUIDLING ID: **8020**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Feely**
SCHOOL NAME: **Bethune School** INSPECTION DATE: **2/19/2016**
ADDRESS: **3030 W. Arthington** IDPH LICENSE NO: **100-00249**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **040**
MATERIAL DESCRIPTION: **12" x 12" White Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Room 112**

MATERIAL QUANTITY: **400**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____

Date: 02/19/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26611** BUIDLING ID: **8020**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Bethune School** REVIEW DATE: **3/25/2016**
ADDRESS: **3030 W. Arthington** IDPH LICENSE NO: **100-00249**

HOMOGENEOUS AREA: **040**
MATERIAL DESCRIPTION: **12" x 12" White Floor Tile Mastic**
MATERIAL LOCATION: **Room 112**
MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **03/25/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26611** BUIDLING ID: **8020**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Feely**
SCHOOL NAME: **Bethune School** INSPECTION DATE: **2/19/2016**
ADDRESS: **3030 W. Arthington** IDPH LICENSE NO: **100-00249**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **041**
MATERIAL DESCRIPTION: **9" x 9" Light Brown Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Library, 311**

MATERIAL QUANTITY: **2800**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____

Date: 02/19/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26611** BUIDLING ID: **8020**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Bethune School** REVIEW DATE: **3/25/2016**
ADDRESS: **3030 W. Arthington** IDPH LICENSE NO: **100-00249**

HOMOGENEOUS AREA: **041**
MATERIAL DESCRIPTION: **9" x 9" Light Brown Floor Tile**
MATERIAL LOCATION: **Library, 311**
MATERIAL QUANTITY: **2800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **03/25/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26611** BUIDLING ID: **8020**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Feely**
SCHOOL NAME: **Bethune School** INSPECTION DATE: **2/19/2016**
ADDRESS: **3030 W. Arthington** IDPH LICENSE NO: **100-00249**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **042**
MATERIAL DESCRIPTION: **9" x 9" Light Brown Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Library, 311**

MATERIAL QUANTITY: **2800**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____

Date: 02/19/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26611** BUIDLING ID: **8020**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Bethune School** REVIEW DATE: **3/25/2016**
ADDRESS: **3030 W. Arthington** IDPH LICENSE NO: **100-00249**

HOMOGENEOUS AREA: **042**
MATERIAL DESCRIPTION: **9" x 9" Light Brown Floor Tile Mastic**
MATERIAL LOCATION: **Library, 311**
MATERIAL QUANTITY: **2800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **03/25/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26611** BUIDLING ID: **8020**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Feely**
SCHOOL NAME: **Bethune School** INSPECTION DATE: **2/19/2016**
ADDRESS: **3030 W. Arthington** IDPH LICENSE NO: **100-00249**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **043**
MATERIAL DESCRIPTION: **12" x 12" Multi-Brown Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 107**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 02/19/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26611** BUIDLING ID: **8020**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Bethune School** REVIEW DATE: **3/25/2016**
ADDRESS: **3030 W. Arthington** IDPH LICENSE NO: **100-00249**

HOMOGENEOUS AREA: **043**
MATERIAL DESCRIPTION: **12" x 12" Multi-Brown Floor Tile**
MATERIAL LOCATION: **Room 107**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **03/25/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26611** BUIDLING ID: **8020**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Feely**
SCHOOL NAME: **Bethune School** INSPECTION DATE: **2/19/2016**
ADDRESS: **3030 W. Arthington** IDPH LICENSE NO: **100-00249**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **044**
MATERIAL DESCRIPTION: **12" x 12" Multi-Brown Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Room 107**

MATERIAL QUANTITY: **1000**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____

Date: 02/19/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26611** BUIDLING ID: **8020**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Bethune School** REVIEW DATE: **3/25/2016**
ADDRESS: **3030 W. Arthington** IDPH LICENSE NO: **100-00249**

HOMOGENEOUS AREA: **044**
MATERIAL DESCRIPTION: **12" x 12" Multi-Brown Floor Tile Mastic**
MATERIAL LOCATION: **Room 107**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **03/25/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26611** BUIDLING ID: **8020**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Feely**
SCHOOL NAME: **Bethune School** INSPECTION DATE: **2/19/2016**
ADDRESS: **3030 W. Arthington** IDPH LICENSE NO: **100-00249**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **045**
MATERIAL DESCRIPTION: **Linoleum**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Classrooms Shelves**
MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 02/19/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26611** BUILDING ID: **8020**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Bethune School** REVIEW DATE: **3/25/2016**
ADDRESS: **3030 W. Arthington** IDPH LICENSE NO: **100-00249**

HOMOGENEOUS AREA: **045**
MATERIAL DESCRIPTION: **Linoleum**
MATERIAL LOCATION: **Classrooms Shelves**
MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **03/25/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26611** BUIDLING ID: **8020**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Feely**
SCHOOL NAME: **Bethune School** INSPECTION DATE: **2/19/2016**
ADDRESS: **3030 W. Arthington** IDPH LICENSE NO: **100-00249**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **046**
MATERIAL DESCRIPTION: **Linoleum Adhesive**
HISTORICAL AHERA DAMAGE CATEGORY **6**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Classroom Shelves on Second and Third Floors**

MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 02/19/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26611** BUIDLING ID: **8020**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Bethune School** REVIEW DATE: **3/25/2016**
ADDRESS: **3030 W. Arthington** IDPH LICENSE NO: **100-00249**

HOMOGENEOUS AREA: **046**
MATERIAL DESCRIPTION: **Linoleum Adhesive**
MATERIAL LOCATION: **Classroom Shelves on Second and Third Floors**
MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **03/25/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26611** BUIDLING ID: **8020**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Feely**
SCHOOL NAME: **Bethune School** INSPECTION DATE: **2/19/2016**
ADDRESS: **3030 W. Arthington** IDPH LICENSE NO: **100-00249**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **47**
MATERIAL DESCRIPTION: **Sink Undercoat**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 205**
MATERIAL QUANTITY: **20** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 02/19/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26611** BUIDLING ID: **8020**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Bethune School** REVIEW DATE: **3/25/2016**
ADDRESS: **3030 W. Arthington** IDPH LICENSE NO: **100-00249**

HOMOGENEOUS AREA: **47**

MATERIAL DESCRIPTION: **Sink Undercoat**

MATERIAL LOCATION: **Room 205**

MATERIAL QUANTITY: **20**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **03/25/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26611** BUIDLING ID: **8020**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Feely**
SCHOOL NAME: **Bethune School** INSPECTION DATE: **2/19/2016**
ADDRESS: **3030 W. Arthington** IDPH LICENSE NO: **100-00249**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **48**
MATERIAL DESCRIPTION: **Lab Counter/Sink**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 217**
MATERIAL QUANTITY: **150** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 02/19/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26611** BUIDLING ID: **8020**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Bethune School** REVIEW DATE: **3/25/2016**
ADDRESS: **3030 W. Arthington** IDPH LICENSE NO: **100-00249**

HOMOGENEOUS AREA: **48**
MATERIAL DESCRIPTION: **Lab Counter/Sink**
MATERIAL LOCATION: **Room 217**
MATERIAL QUANTITY: **150** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **03/25/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26611** BUIDLING ID: **8020**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Feely**
SCHOOL NAME: **Bethune School** INSPECTION DATE: **2/19/2016**
ADDRESS: **3030 W. Arthington** IDPH LICENSE NO: **100-00249**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **49**
MATERIAL DESCRIPTION: **Material Inside Divider Wall**
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 104 and 216**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed 2016**

Inspector's Signature: _____

Date: 02/19/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26611** BUILDING ID: **8020**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Bethune School** REVIEW DATE: **3/25/2016**
ADDRESS: **3030 W. Arthington** IDPH LICENSE NO: **100-00249**

HOMOGENEOUS AREA: **49**

MATERIAL DESCRIPTION: **Material Inside Divider Wall**

MATERIAL LOCATION: **Room 104 and 216**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.


The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

If identified, implement O&M

Management Planner's Signature: _____



Date: **03/25/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26611** BUIDLING ID: **8020**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Feely**
SCHOOL NAME: **Bethune School** INSPECTION DATE: **2/19/2016**
ADDRESS: **3030 W. Arthington** IDPH LICENSE NO: **100-00249**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **50**
MATERIAL DESCRIPTION: **9" x 9" Brown w/Brown Specks Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Storage by Room 107**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Not observed 2016**

Inspector's Signature: _____ Date: **02/19/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26611** BUIDLING ID: **8020**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Bethune School** REVIEW DATE: **3/25/2016**
ADDRESS: **3030 W. Arthington** IDPH LICENSE NO: **100-00249**

HOMOGENEOUS AREA: **50**

MATERIAL DESCRIPTION: **9" x 9" Brown w/Brown Specks Floor Tile**

MATERIAL LOCATION: **Storage by Room 107**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

If identified, implement O&M

Management Planner's Signature: _____



Date: **03/25/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26611** BUIDLING ID: **8020**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Feely**
SCHOOL NAME: **Bethune School** INSPECTION DATE: **2/19/2016**
ADDRESS: **3030 W. Arthington** IDPH LICENSE NO: **100-00249**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **51**
MATERIAL DESCRIPTION: **9" x 9" Brown w/Brown Specks Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Storage by Room 107**

MATERIAL QUANTITY: **30**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____

Date: 02/19/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26611** BUIDLING ID: **8020**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Bethune School** REVIEW DATE: **3/25/2016**
ADDRESS: **3030 W. Arthington** IDPH LICENSE NO: **100-00249**

HOMOGENEOUS AREA: **51**
MATERIAL DESCRIPTION: **9" x 9" Brown w/Brown Specks Floor Tile Mastic**
MATERIAL LOCATION: **Storage by Room 107**
MATERIAL QUANTITY: **30** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **03/25/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26611** BUIDLING ID: **8020**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Feely**
SCHOOL NAME: **Bethune School** INSPECTION DATE: **2/19/2016**
ADDRESS: **3030 W. Arthington** IDPH LICENSE NO: **100-00249**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **52**
MATERIAL DESCRIPTION: **12" x 12" White w/Black Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 308 and Kitchen Storage**
MATERIAL QUANTITY: **1038** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 02/19/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26611** BUIDLING ID: **8020**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Bethune School** REVIEW DATE: **3/25/2016**
ADDRESS: **3030 W. Arthington** IDPH LICENSE NO: **100-00249**

HOMOGENEOUS AREA: **52**
MATERIAL DESCRIPTION: **12" x 12" White w/Black Floor Tile**
MATERIAL LOCATION: **Room 308 and Kitchen Storage**
MATERIAL QUANTITY: **1038** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **03/25/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26611** BUIDLING ID: **8020**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Feely**
SCHOOL NAME: **Bethune School** INSPECTION DATE: **2/19/2016**
ADDRESS: **3030 W. Arthington** IDPH LICENSE NO: **100-00249**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **53**
MATERIAL DESCRIPTION: **12" x 12" White w/Black Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Room 308 and Kitchen Storage**

MATERIAL QUANTITY: **1038**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____

Date: 02/19/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26611** BUIDLING ID: **8020**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Bethune School** REVIEW DATE: **3/25/2016**
ADDRESS: **3030 W. Arthington** IDPH LICENSE NO: **100-00249**

HOMOGENEOUS AREA: **53**
MATERIAL DESCRIPTION: **12" x 12" White w/Black Floor Tile Mastic**
MATERIAL LOCATION: **Room 308 and Kitchen Storage**
MATERIAL QUANTITY: **1038** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **03/25/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26611** BUIDLING ID: **8020**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Feely**
SCHOOL NAME: **Bethune School** INSPECTION DATE: **2/19/2016**
ADDRESS: **3030 W. Arthington** IDPH LICENSE NO: **100-00249**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **54**
MATERIAL DESCRIPTION: **12" x 12" Brown Mix Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Room 207**

MATERIAL QUANTITY: **750**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____

Date: 02/19/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26611** BUIDLING ID: **8020**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Bethune School** REVIEW DATE: **3/25/2016**
ADDRESS: **3030 W. Arthington** IDPH LICENSE NO: **100-00249**

HOMOGENEOUS AREA: **54**
MATERIAL DESCRIPTION: **12" x 12" Brown Mix Floor Tile**
MATERIAL LOCATION: **Room 207**
MATERIAL QUANTITY: **750** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **03/25/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26611** BUIDLING ID: **8020**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Feely**
SCHOOL NAME: **Bethune School** INSPECTION DATE: **2/19/2016**
ADDRESS: **3030 W. Arthington** IDPH LICENSE NO: **100-00249**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **55**
MATERIAL DESCRIPTION: **12" x 12" Brown Mix Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Room 207**

MATERIAL QUANTITY: **750**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____

Date: 02/19/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26611** BUIDLING ID: **8020**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Bethune School** REVIEW DATE: **3/25/2016**
ADDRESS: **3030 W. Arthington** IDPH LICENSE NO: **100-00249**

HOMOGENEOUS AREA: **55**
MATERIAL DESCRIPTION: **12" x 12" Brown Mix Floor Tile Mastic**
MATERIAL LOCATION: **Room 207**
MATERIAL QUANTITY: **750** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **03/25/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26611** BUIDLING ID: **8020**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Feely**
SCHOOL NAME: **Bethune School** INSPECTION DATE: **2/19/2016**
ADDRESS: **3030 W. Arthington** IDPH LICENSE NO: **100-00249**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **56**
MATERIAL DESCRIPTION: **12" x 12" Beige Mix Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Room 207**

MATERIAL QUANTITY: **750**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____

Date: 02/19/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26611** BUIDLING ID: **8020**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Bethune School** REVIEW DATE: **3/25/2016**
ADDRESS: **3030 W. Arthington** IDPH LICENSE NO: **100-00249**

HOMOGENEOUS AREA: **56**
MATERIAL DESCRIPTION: **12" x 12" Beige Mix Floor Tile**
MATERIAL LOCATION: **Room 207**
MATERIAL QUANTITY: **750** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **03/25/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26611** BUIDLING ID: **8020**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Feely**
SCHOOL NAME: **Bethune School** INSPECTION DATE: **2/19/2016**
ADDRESS: **3030 W. Arthington** IDPH LICENSE NO: **100-00249**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **57**
MATERIAL DESCRIPTION: **12" x 12" Beige Mix Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Room 207**

MATERIAL QUANTITY: **750**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____

Date: 02/19/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26611** BUIDLING ID: **8020**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Bethune School** REVIEW DATE: **3/25/2016**
ADDRESS: **3030 W. Arthington** IDPH LICENSE NO: **100-00249**

HOMOGENEOUS AREA: **57**
MATERIAL DESCRIPTION: **12" x 12" Beige Mix Floor Tile Mastic**
MATERIAL LOCATION: **Room 207**
MATERIAL QUANTITY: **750** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **03/25/2016**

Chicago Public Schools

Carnow, Conibear and Associates 2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26611** BUIDLING ID: **8020**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Feely**
SCHOOL NAME: **Bethune School** INSPECTION DATE: **2/19/2016**
ADDRESS: **3030 W. Arthington** IDPH LICENSE NO: **100-00249**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **58**
MATERIAL DESCRIPTION: **9" x 9" Lt. Brown Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Gym Entries, 211, 213**
MATERIAL QUANTITY: **1600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: 02/19/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26611** BUIDLING ID: **8020**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Bethune School** REVIEW DATE: **3/25/2016**
ADDRESS: **3030 W. Arthington** IDPH LICENSE NO: **100-00249**

HOMOGENEOUS AREA: **58**
MATERIAL DESCRIPTION: **9" x 9" Lt. Brown Floor Tile**
MATERIAL LOCATION: **Gym Entries, 211, 213**
MATERIAL QUANTITY: **1600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **03/25/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26611** BUIDLING ID: **8020**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Feely**
SCHOOL NAME: **Bethune School** INSPECTION DATE: **2/19/2016**
ADDRESS: **3030 W. Arthington** IDPH LICENSE NO: **100-00249**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **59**
MATERIAL DESCRIPTION: **9" x 9" Lt. Brown Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Gym Entries, 211,213**
MATERIAL QUANTITY: **1600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 02/19/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26611** BUIDLING ID: **8020**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Bethune School** REVIEW DATE: **3/25/2016**
ADDRESS: **3030 W. Arthington** IDPH LICENSE NO: **100-00249**

HOMOGENEOUS AREA: **59**
MATERIAL DESCRIPTION: **9" x 9" Lt. Brown Floor Tile Mastic**
MATERIAL LOCATION: **Gym Entries, 211,213**
MATERIAL QUANTITY: **1600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **03/25/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26611** BUIDLING ID: **8020**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Feely**
SCHOOL NAME: **Bethune School** INSPECTION DATE: **2/19/2016**
ADDRESS: **3030 W. Arthington** IDPH LICENSE NO: **100-00249**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **60**
MATERIAL DESCRIPTION: **Chalk Board/Poster Board Adhesive**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **All classrooms**

MATERIAL QUANTITY: **6240**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____

Date: 02/19/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26611** BUIDLING ID: **8020**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Bethune School** REVIEW DATE: **3/25/2016**
ADDRESS: **3030 W. Arthington** IDPH LICENSE NO: **100-00249**

HOMOGENEOUS AREA: **60**
MATERIAL DESCRIPTION: **Chalk Board/Poster Board Adhesive**
MATERIAL LOCATION: **All classrooms**
MATERIAL QUANTITY: **6240** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **03/25/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26611** BUIDLING ID: **8020**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Feely**
SCHOOL NAME: **Bethune School** INSPECTION DATE: **2/19/2016**
ADDRESS: **3030 W. Arthington** IDPH LICENSE NO: **100-00249**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **61**
MATERIAL DESCRIPTION: **12"x12" Beige w/brown floor tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **115**
MATERIAL QUANTITY: **720** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 02/19/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26611** BUIDLING ID: **8020**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Bethune School** REVIEW DATE: **3/25/2016**
ADDRESS: **3030 W. Arthington** IDPH LICENSE NO: **100-00249**

HOMOGENEOUS AREA: **61**
MATERIAL DESCRIPTION: **12"x12" Beige w/brown floor tile**
MATERIAL LOCATION: **115**
MATERIAL QUANTITY: **720** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **03/25/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26611** BUIDLING ID: **8020**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Feely**
SCHOOL NAME: **Bethune School** INSPECTION DATE: **2/19/2016**
ADDRESS: **3030 W. Arthington** IDPH LICENSE NO: **100-00249**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **62**
MATERIAL DESCRIPTION: **12" x12" Beige w/brown floor tile adhesive**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **115**
MATERIAL QUANTITY: **720** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 02/19/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26611** BUIDLING ID: **8020**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Bethune School** REVIEW DATE: **3/25/2016**
ADDRESS: **3030 W. Arthington** IDPH LICENSE NO: **100-00249**

HOMOGENEOUS AREA: **62**
MATERIAL DESCRIPTION: **12" x12" Beige w/brown floor tile adhesive**
MATERIAL LOCATION: **115**
MATERIAL QUANTITY: **720** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **03/25/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26611** BUIDLING ID: **8020**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Feely**
SCHOOL NAME: **Bethune School** INSPECTION DATE: **2/19/2016**
ADDRESS: **3030 W. Arthington** IDPH LICENSE NO: **100-00249**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **63**
MATERIAL DESCRIPTION: **4" Beige baseboard**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **113, 115**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed 2016**

Inspector's Signature: _____ Date: **02/19/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26611** BUIDLING ID: **8020**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Bethune School** REVIEW DATE: **3/25/2016**
ADDRESS: **3030 W. Arthington** IDPH LICENSE NO: **100-00249**

HOMOGENEOUS AREA: **63**

MATERIAL DESCRIPTION: **4" Beige baseboard**

MATERIAL LOCATION: **113, 115**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

If identified, implement O&M

Management Planner's Signature: _____



Date: **03/25/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26611** BUIDLING ID: **8020**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Feely**
SCHOOL NAME: **Bethune School** INSPECTION DATE: **2/19/2016**
ADDRESS: **3030 W. Arthington** IDPH LICENSE NO: **100-00249**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **64**
MATERIAL DESCRIPTION: **4" Beige baseboard adhesive**
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **113, 115**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed 2016**

Inspector's Signature: _____

Date: 02/19/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26611** BUIDLING ID: **8020**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Bethune School** REVIEW DATE: **3/25/2016**
ADDRESS: **3030 W. Arthington** IDPH LICENSE NO: **100-00249**

HOMOGENEOUS AREA: **64**

MATERIAL DESCRIPTION: **4" Beige baseboard adhesive**

MATERIAL LOCATION: **113, 115**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

If identified, implement O&M

Management Planner's Signature: _____



Date: **03/25/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26611** BUIDLING ID: **8020**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Feely**
SCHOOL NAME: **Bethune School** INSPECTION DATE: **2/19/2016**
ADDRESS: **3030 W. Arthington** IDPH LICENSE NO: **100-00249**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **65**
MATERIAL DESCRIPTION: **4" black baseboard**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **306**
MATERIAL QUANTITY: **100** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: _____ Date: 02/19/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26611** BUIDLING ID: **8020**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Bethune School** REVIEW DATE: **3/25/2016**
ADDRESS: **3030 W. Arthington** IDPH LICENSE NO: **100-00249**

HOMOGENEOUS AREA: **65**
MATERIAL DESCRIPTION: **4" black baseboard**
MATERIAL LOCATION: **306**
MATERIAL QUANTITY: **100** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **03/25/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26611** BUIDLING ID: **8020**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Feely**
SCHOOL NAME: **Bethune School** INSPECTION DATE: **2/19/2016**
ADDRESS: **3030 W. Arthington** IDPH LICENSE NO: **100-00249**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **66**
MATERIAL DESCRIPTION: **4" blue baseboard adhesive**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **306**
MATERIAL QUANTITY: **100** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: _____ Date: 02/19/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26611** BUIDLING ID: **8020**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Bethune School** REVIEW DATE: **3/25/2016**
ADDRESS: **3030 W. Arthington** IDPH LICENSE NO: **100-00249**

HOMOGENEOUS AREA: **66**
MATERIAL DESCRIPTION: **4" blue baseboard adhesive**
MATERIAL LOCATION: **306**
MATERIAL QUANTITY: **100** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **03/25/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26611** BUIDLING ID: **8020**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Feely**
SCHOOL NAME: **Bethune School** INSPECTION DATE: **2/19/2016**
ADDRESS: **3030 W. Arthington** IDPH LICENSE NO: **100-00249**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **70**
MATERIAL DESCRIPTION: **Ceramic Grout and Adhesive Brown, Tan & White**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1st, 2nd, 3rd Floor Girls & Boys bathrooms**
MATERIAL QUANTITY: **1800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 02/19/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26611** BUIDLING ID: **8020**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Bethune School** REVIEW DATE: **3/25/2016**
ADDRESS: **3030 W. Arthington** IDPH LICENSE NO: **100-00249**

HOMOGENEOUS AREA: **70**
MATERIAL DESCRIPTION: **Ceramic Grout and Adhesive Brown, Tan & White**
MATERIAL LOCATION: **1st, 2nd, 3rd Floor Girls & Boys bathrooms**
MATERIAL QUANTITY: **1800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **03/25/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26611** BUIDLING ID: **8020**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Feely**
SCHOOL NAME: **Bethune School** INSPECTION DATE: **2/19/2016**
ADDRESS: **3030 W. Arthington** IDPH LICENSE NO: **100-00249**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **71**
MATERIAL DESCRIPTION: **12 x 12 FT Brown with White Streaks**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms 306, 312, 314, 315, 313, 310, 306, 309**
MATERIAL QUANTITY: **5000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 02/19/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26611** BUIDLING ID: **8020**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Bethune School** REVIEW DATE: **3/25/2016**
ADDRESS: **3030 W. Arthington** IDPH LICENSE NO: **100-00249**

HOMOGENEOUS AREA: **71**
MATERIAL DESCRIPTION: **12 x 12 FT Brown with White Streaks**
MATERIAL LOCATION: **Rooms 306, 312, 314, 315, 313, 310, 306, 309**
MATERIAL QUANTITY: **5000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **03/25/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26611** BUIDLING ID: **8020**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Feely**
SCHOOL NAME: **Bethune School** INSPECTION DATE: **2/19/2016**
ADDRESS: **3030 W. Arthington** IDPH LICENSE NO: **100-00249**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **72**
MATERIAL DESCRIPTION: **Mastic under 12 x 12 FT Brown with White Streaks**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Rooms 306, 312, 314, 315, 313, 310, 306, 309**

MATERIAL QUANTITY: **5000**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____

Date: 02/19/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26611** BUIDLING ID: **8020**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Bethune School** REVIEW DATE: **3/25/2016**
ADDRESS: **3030 W. Arthington** IDPH LICENSE NO: **100-00249**

HOMOGENEOUS AREA: **72**
MATERIAL DESCRIPTION: **Mastic under 12 x 12 FT Brown with White Streaks**
MATERIAL LOCATION: **Rooms 306, 312, 314, 315, 313, 310, 306, 309**
MATERIAL QUANTITY: **5000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **03/25/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26611** BUIDLING ID: **8020**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Feely**
SCHOOL NAME: **Bethune School** INSPECTION DATE: **2/19/2016**
ADDRESS: **3030 W. Arthington** IDPH LICENSE NO: **100-00249**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **73**
MATERIAL DESCRIPTION: **9 X 9 Gray W/Dark Gray Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 314-A, MDF Room**
MATERIAL QUANTITY: **150** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: 02/19/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26611** BUILDING ID: **8020**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Bethune School** REVIEW DATE: **3/25/2016**
ADDRESS: **3030 W. Arthington** IDPH LICENSE NO: **100-00249**

HOMOGENEOUS AREA: **73**
MATERIAL DESCRIPTION: **9 X 9 Gray W/Dark Gray Floor Tile**
MATERIAL LOCATION: **Room 314-A, MDF Room**
MATERIAL QUANTITY: **150** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **03/25/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26611** BUIDLING ID: **8020**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Feely**
SCHOOL NAME: **Bethune School** INSPECTION DATE: **2/19/2016**
ADDRESS: **3030 W. Arthington** IDPH LICENSE NO: **100-00249**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **73M**
MATERIAL DESCRIPTION: **9 X 9 Gray W/Dark Gray Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Room 314-A MDF**

MATERIAL QUANTITY: **150**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____

Date: 02/19/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26611** BUILDING ID: **8020**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Bethune School** REVIEW DATE: **3/25/2016**
ADDRESS: **3030 W. Arthington** IDPH LICENSE NO: **100-00249**

HOMOGENEOUS AREA: **73M**
MATERIAL DESCRIPTION: **9 X 9 Gray W/Dark Gray Floor Tile Mastic**
MATERIAL LOCATION: **Room 314-A MDF**
MATERIAL QUANTITY: **150** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **03/25/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26611** BUIDLING ID: **8020**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Feely**
SCHOOL NAME: **Bethune School** INSPECTION DATE: **2/19/2016**
ADDRESS: **3030 W. Arthington** IDPH LICENSE NO: **100-00249**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **74**
MATERIAL DESCRIPTION: **12" X 12" Tan W/Brown Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 109**
MATERIAL QUANTITY: **360** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 02/19/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26611** BUIDLING ID: **8020**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Bethune School** REVIEW DATE: **3/25/2016**
ADDRESS: **3030 W. Arthington** IDPH LICENSE NO: **100-00249**

HOMOGENEOUS AREA: **74**
MATERIAL DESCRIPTION: **12" X 12" Tan W/Brown Floor Tile**
MATERIAL LOCATION: **Room 109**
MATERIAL QUANTITY: **360** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **03/25/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26611** BUIDLING ID: **8020**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Feely**
SCHOOL NAME: **Bethune School** INSPECTION DATE: **2/19/2016**
ADDRESS: **3030 W. Arthington** IDPH LICENSE NO: **100-00249**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **74M**
MATERIAL DESCRIPTION: **12" X 12" Tan W/Brown Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Room 109**

MATERIAL QUANTITY: **360**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____

Date: 02/19/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26611** BUIDLING ID: **8020**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Bethune School** REVIEW DATE: **3/25/2016**
ADDRESS: **3030 W. Arthington** IDPH LICENSE NO: **100-00249**

HOMOGENEOUS AREA: **74M**
MATERIAL DESCRIPTION: **12" X 12" Tan W/Brown Floor Tile Mastic**
MATERIAL LOCATION: **Room 109**
MATERIAL QUANTITY: **360** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **03/25/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26611** BUIDLING ID: **8020**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Feely**
SCHOOL NAME: **Bethune School** INSPECTION DATE: **2/19/2016**
ADDRESS: **3030 W. Arthington** IDPH LICENSE NO: **100-00249**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **75**
MATERIAL DESCRIPTION: **12" X 12" Tan W/Brown Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Assistant Principals Office**

MATERIAL QUANTITY: **625**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____

Date: 02/19/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26611** BUIDLING ID: **8020**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Bethune School** REVIEW DATE: **3/25/2016**
ADDRESS: **3030 W. Arthington** IDPH LICENSE NO: **100-00249**

HOMOGENEOUS AREA: **75**
MATERIAL DESCRIPTION: **12" X 12" Tan W/Brown Floor Tile**
MATERIAL LOCATION: **Assistant Principals Office**
MATERIAL QUANTITY: **625** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **03/25/2016**

Chicago Public Schools

Carnow, Conibear and Associates 2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26611** BUILDING ID: **8020**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Feely**
SCHOOL NAME: **Bethune School** INSPECTION DATE: **2/19/2016**
ADDRESS: **3030 W. Arthington** IDPH LICENSE NO: **100-00249**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **75M**
MATERIAL DESCRIPTION: **12" X 12" Tan W/Brown Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Assistant Principal Office**
MATERIAL QUANTITY: **625** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 02/19/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26611** BUIDLING ID: **8020**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Bethune School** REVIEW DATE: **3/25/2016**
ADDRESS: **3030 W. Arthington** IDPH LICENSE NO: **100-00249**

HOMOGENEOUS AREA: **75M**
MATERIAL DESCRIPTION: **12" X 12" Tan W/Brown Floor Tile Mastic**
MATERIAL LOCATION: **Assistant Principal Office**
MATERIAL QUANTITY: **625** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **03/25/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26611** BUIDLING ID: **8020**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Feely**
SCHOOL NAME: **Bethune School** INSPECTION DATE: **2/19/2016**
ADDRESS: **3030 W. Arthington** IDPH LICENSE NO: **100-00249**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **76**
MATERIAL DESCRIPTION: **12" X 12" Blue W/Dark Blue Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1, 2, 3 Floors Store Rooms and Elevators**
MATERIAL QUANTITY: **1150** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 02/19/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26611** BUIDLING ID: **8020**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Bethune School** REVIEW DATE: **3/25/2016**
ADDRESS: **3030 W. Arthington** IDPH LICENSE NO: **100-00249**

HOMOGENEOUS AREA: **76**
MATERIAL DESCRIPTION: **12" X 12" Blue W/Dark Blue Floor Tile**
MATERIAL LOCATION: **1, 2, 3 Floors Store Rooms and Elevators**
MATERIAL QUANTITY: **1150** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **03/25/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26611** BUIDLING ID: **8020**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Feely**
SCHOOL NAME: **Bethune School** INSPECTION DATE: **2/19/2016**
ADDRESS: **3030 W. Arthington** IDPH LICENSE NO: **100-00249**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **76M**
MATERIAL DESCRIPTION: **12" X 12" Blue W/Dark Blue Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **1, 2 , 3 Floors Store Rooms, and Elevators**

MATERIAL QUANTITY: **1150**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____

Date: 02/19/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26611** BUIDLING ID: **8020**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Bethune School** REVIEW DATE: **3/25/2016**
ADDRESS: **3030 W. Arthington** IDPH LICENSE NO: **100-00249**

HOMOGENEOUS AREA: **76M**
MATERIAL DESCRIPTION: **12" X 12" Blue W/Dark Blue Floor Tile Mastic**
MATERIAL LOCATION: **1, 2, 3 Floors Store Rooms, and Elevators**
MATERIAL QUANTITY: **1150** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **03/25/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26611** BUIDLING ID: **8020**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Feely**
SCHOOL NAME: **Bethune School** INSPECTION DATE: **2/19/2016**
ADDRESS: **3030 W. Arthington** IDPH LICENSE NO: **100-00249**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **77**
MATERIAL DESCRIPTION: **12" X 12" Tan /Brown Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Rooms
102,104,106,108,112,115,111,107,105,200,202,204,206,208,210,212,201,203,205,207,209,
211,213,215,216,217,300,302,304,306,308,305,307,309,311,313,315.**

MATERIAL QUANTITY: **2268** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 02/19/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26611** BUILDING ID: **8020**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Bethune School** REVIEW DATE: **3/25/2016**
ADDRESS: **3030 W. Arthington** IDPH LICENSE NO: **100-00249**

HOMOGENEOUS AREA: **77**
MATERIAL DESCRIPTION: **12" X 12" Tan /Brown Floor Tile**
MATERIAL LOCATION: **Rooms**
102,104,106,108,112,115,111,107,105,200,202,204,206,208,210,212,201,203,205,207,209,211,213,215
,216,217,300,302,304,306,308,305,307,309,311,313,315.
MATERIAL QUANTITY: **2268** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **03/25/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26611** BUIDLING ID: **8020**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Feely**
SCHOOL NAME: **Bethune School** INSPECTION DATE: **2/19/2016**
ADDRESS: **3030 W. Arthington** IDPH LICENSE NO: **100-00249**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **77M**
MATERIAL DESCRIPTION: **12" X 12" Tan W/Brown Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Rooms
102,104,106,108,112,115,111,107,105,200,202,204,206,208,210,212,201,203,205,207,209,
211,213,215,216,217,300,302,304,306,308,305,307,309,311,313,315.**

MATERIAL QUANTITY: **2268** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 02/19/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26611** BUIDLING ID: **8020**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Bethune School** REVIEW DATE: **3/25/2016**
ADDRESS: **3030 W. Arthington** IDPH LICENSE NO: **100-00249**

HOMOGENEOUS AREA: **77M**
MATERIAL DESCRIPTION: **12" X 12" Tan W/Brown Floor Tile Mastic**
MATERIAL LOCATION: **Rooms**
102,104,106,108,112,115,111,107,105,200,202,204,206,208,210,212,201,203,205,207,209,211,213,215
,216,217,300,302,304,306,308,305,307,309,311,313,315.
MATERIAL QUANTITY: **2268** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **03/25/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26611** BUIDLING ID: **8020**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Feely**
SCHOOL NAME: **Bethune School** INSPECTION DATE: **2/19/2016**
ADDRESS: **3030 W. Arthington** IDPH LICENSE NO: **100-00249**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **A**
MATERIAL DESCRIPTION: **Hard Joint Compound on Fiberglass Pipe Insulation**
HISTORICAL AHERA DAMAGE CATEGORY **1 Damaged or significantly damaged friable thermal system insulating ACBM**
HISTORICAL DAMAGE REASON: **Delamination**
HISTORICAL RESPONSE ACTION: **Repair**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **1. Damaged or significantly damaged friable thermal system insulating ACBM**

DAMAGE REASON: **Delamination**
DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Throughout Facility, including fan room, crawlspace, boiler room**
MATERIAL QUANTITY: **300** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **300** DAMAGE UNITS: **LF**
COMMENTS:

Inspector's Signature: _____ Date: 02/19/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26611** BUIDLING ID: **8020**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Bethune School** REVIEW DATE: **3/25/2016**
ADDRESS: **3030 W. Arthington** IDPH LICENSE NO: **100-00249**

HOMOGENEOUS AREA: **A**
MATERIAL DESCRIPTION: **Hard Joint Compound on Fiberglass Pipe Insulation**
MATERIAL LOCATION: **Throughout Facility, including fan room, crawlspace, boiler room**
MATERIAL QUANTITY: **300** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **6** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.


The RESPONSE ACTION recommendation is:

Repair

Comments:

Patch and repair as needed then follow O&M plan.

Management Planner's Signature: _____



Date: **03/25/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26611** BUIDLING ID: **8020**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Feely**
SCHOOL NAME: **Bethune School** INSPECTION DATE: **2/19/2016**
ADDRESS: **3030 W. Arthington** IDPH LICENSE NO: **100-00249**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **B**
MATERIAL DESCRIPTION: **Mag Block Insulation - ABATED**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Boiler Room - Boiler Tank**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 02/19/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26611** BUIDLING ID: **8020**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Bethune School** REVIEW DATE: **3/25/2016**
ADDRESS: **3030 W. Arthington** IDPH LICENSE NO: **100-00249**

HOMOGENEOUS AREA: **B**

MATERIAL DESCRIPTION: **Mag Block Insulation - ABATED**

MATERIAL LOCATION: **Boiler Room - Boiler Tank**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:


DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **03/25/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26611** BUIDLING ID: **8020**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Feely**
SCHOOL NAME: **Bethune School** INSPECTION DATE: **2/19/2016**
ADDRESS: **3030 W. Arthington** IDPH LICENSE NO: **100-00249**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **C**
MATERIAL DESCRIPTION: **Cementitious Material**
HISTORICAL AHERA DAMAGE CATEGORY **7 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Boiler Room**
MATERIAL QUANTITY: **10** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 02/19/2016

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26611** BUIDLING ID: **8020**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Bethune School** REVIEW DATE: **3/25/2016**
ADDRESS: **3030 W. Arthington** IDPH LICENSE NO: **100-00249**

HOMOGENEOUS AREA: **C**
MATERIAL DESCRIPTION: **Cementitious Material**
MATERIAL LOCATION: **Boiler Room**
MATERIAL QUANTITY: **10** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **03/25/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26611** BUILDING ID: **8020**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Feely**
SCHOOL NAME: **Bethune School** INSPECTION DATE: **2/19/2016**
ADDRESS: **3030 W. Arthington** IDPH LICENSE NO: **100-00249**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **80**
MATERIAL DESCRIPTION: **12" x 12" Blue Floor Tile**
MATERIAL LOCATION: **100A, 200A, 300A Elevator**
MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**
MATERIAL CATEGORY: **MISC** FRIABLE: **No**
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **LOW** CONDITION:
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
ACCESSIBILITY: **Within Reach** DAMAGE REASON:
DAMAGE QUANTITY: **0** DAMAGE REASON:
DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: 02/19/2016

Chicago Public Schools

Carnow, Conibear and Associates 2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26611** BUILDING ID: **8020**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Bethune School** REVIEW DATE: **3/25/2016**
ADDRESS: **3030 W. Arthington** IDPH LICENSE NO: **100-00249**


HOMOGENEOUS AREA: **80**
MATERIAL DESCRIPTION: **12" x 12" Blue Floor Tile**
MATERIAL LOCATION: **100A, 200A, 300A Elevator**
MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____



Date: 03/25/2016

Chicago Public Schools

Carnow, Conibear and Associates 2016 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26611** BUILDING ID: **8020**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Feely**
SCHOOL NAME: **Bethune School** INSPECTION DATE: **2/19/2016**
ADDRESS: **3030 W. Arthington** IDPH LICENSE NO: **100-00249**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **81**

MATERIAL DESCRIPTION: **Mastic Associated w/ 12" x 12" Blue Floor Tile**

MATERIAL LOCATION: **100A, 200A, 300A Elevator**

MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**

MATERIAL CATEGORY: **MISC** FRIABLE: **No**

ASBESTOS TYPE: **Assumed**

DISTURBANCE POTENTIAL: **LOW** CONDITION:

AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**

ACCESSIBILITY: **Not Reachable** DAMAGE REASON:

DAMAGE QUANTITY: **0** DAMAGE REASON:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: **02/19/2016**

Chicago Public Schools

Carnow, Conibear and Associates 2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26611** BUILDING ID: **8020**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Bethune School** REVIEW DATE: **3/25/2016**
ADDRESS: **3030 W. Arthington** IDPH LICENSE NO: **100-00249**


HOMOGENEOUS AREA: **81**
MATERIAL DESCRIPTION: **Mastic Associated w/ 12" x 12" Blue Floor Tile**
MATERIAL LOCATION: **100A, 200A, 300A Elevator**
MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____



Date: **03/25/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26611** BUILDING ID: **8020**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Feely**
SCHOOL NAME: **Bethune School** INSPECTION DATE: **2/19/2016**
ADDRESS: **3030 W. Arthington** IDPH LICENSE NO: **100-00249**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **78**
MATERIAL DESCRIPTION: **12" x 12" White Floor Tile**
MATERIAL LOCATION: **Rms. 203, 207, 209, 306, 308-314**
MATERIAL QUANTITY: **9000** MATERIAL UNITS: **SF**
MATERIAL CATEGORY: **MISC** FRIABLE: **No**
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **LOW** CONDITION:
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
ACCESSIBILITY: **Within Reach** DAMAGE REASON:
DAMAGE QUANTITY: **0** DAMAGE REASON:
DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: **02/19/2016**

Chicago Public Schools

Carnow, Conibear and Associates 2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26611** BUILDING ID: **8020**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Bethune School** REVIEW DATE: **3/25/2016**
ADDRESS: **3030 W. Arthington** IDPH LICENSE NO: **100-00249**


HOMOGENEOUS AREA: **78**
MATERIAL DESCRIPTION: **12" x 12" White Floor Tile**
MATERIAL LOCATION: **Rms. 203, 207, 209, 306, 308-314**
MATERIAL QUANTITY: **9000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____



Date: **03/25/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26611** BUILDING ID: **8020**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **John Feely**
SCHOOL NAME: **Bethune School** INSPECTION DATE: **2/19/2016**
ADDRESS: **3030 W. Arthington** IDPH LICENSE NO: **100-00249**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **79**

MATERIAL DESCRIPTION: **Mastic Associated w/ 12" x 12" White Floor Tile**

MATERIAL LOCATION: **Rms. 203, 207, 209, 306, 308-314**

MATERIAL QUANTITY: **9000** MATERIAL UNITS: **SF**

MATERIAL CATEGORY: **MISC** FRIABLE: **No**

ASBESTOS TYPE: **Assumed**

DISTURBANCE POTENTIAL: **LOW** CONDITION:

AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**

ACCESSIBILITY: **Not Reachable** DAMAGE REASON:
DAMAGE REASON:
DAMAGE REASON:

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: **02/19/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26611** BUILDING ID: **8020**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Bethune School** REVIEW DATE: **3/25/2016**
ADDRESS: **3030 W. Arthington** IDPH LICENSE NO: **100-00249**

HOMOGENEOUS AREA: **79**

MATERIAL DESCRIPTION: **Mastic Associated w/ 12" x 12" White Floor Tile**

MATERIAL LOCATION: **Rms. 203, 207, 209, 306, 308-314**

MATERIAL QUANTITY: **9000** MATERIAL UNITS: **SF**


DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____



Date: **03/25/2016**

APPENDIX B

Inspector and Management Planner Licenses

ASBESTOS INSPECTOR
 Issued by
STATE OF WISCONSIN
 Dept. of Health Services
 John Charles Feely
 9513 Lawton Ave
 Oak Lawn, IL 60453-2999

ALI-369	Exp: 07/11/2016	250 lbs	5' 11"
		01/13/1963	Male

Training due by: 07/11/2016

LEAD DIVISION OF PUBLIC HEALTH
IDPH
 ASBESTOS PROFESSIONAL LICENSE

ID NUMBER 100 - 00249
 ISSUED 3/2/2015
 EXPIRES 05/15/2016

JOHN C FEELY
 9513 SOUTH LAWTON AVENUE
 OAK LAWN, IL 60453
 Environmental Health

2016



OCCUPATIONAL TRAINING & SUPPLY, INC.

7233 S. Adams Street ♦ Willowbrook, IL 60527 ♦ (630) 655-3900

Asbestos Building Inspector Refresher

Occupational Training & Supply, Inc. certifies that

John Feely


has successfully completed the Asbestos Building Inspector Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency Response Act (AHERA) and TSCA Title II.

Course Date: 1/6/2016

Exam Date: 1/6/2016

Expiration Date: 1/6/2017

Certificate Number: BIR1601060019


Kathy DeSalvo, Director

2016



OCCUPATIONAL TRAINING & SUPPLY, INC.

7233 S. Adams Street ♦ Willowbrook, IL 60527 ♦ (630) 655-3900

Asbestos Management Planner Refresher

Occupational Training & Supply, Inc. certifies that

Daniel Juneau

has successfully completed the Asbestos Management Planner Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 1/6/2016

Exam Date: 1/6/2016

Expiration Date: 1/6/2017

Certificate Number: MPR1601060038



Kathy DeSalvo, Director

Daniel Juneau

Illinois Licensed Asbestos Inspector, Management Planner,
Project Manager, and Air Sampling Professional



ASBESTOS PROFESSIONAL LICENSE

ID NUMBER
100 - 03613

ISSUED
3/16/2015

EXPIRES
05/15/2016

DANIEL J JUNEAU
1408 OAKWOOD AVENUE
DES PLAINES, IL 60016

Environmental Health



ENDORSEMENTS

TC EXPIRES

INSPECTOR

12/2/2015

MANAGEMENT PLANNER

1/20/2016

PROJECT MANAGER

12/11/2015

AIR SAMPLING PROFESSIONAL

Alteration of this license shall result in legal action

This license issued under authority of the State of Illinois
Department of Public Health

This license is valid only when accompanied by a valid
training course certificate.

**CARNOW
CONIBEAR**

2015



OCCUPATIONAL TRAINING & SUPPLY, INC.

7233 S. Adams Street ♦ Willowbrook, IL 60527 ♦ (630) 655-3900

Asbestos Building Inspector Refresher

Occupational Training & Supply, Inc. certifies that

Daniel Juneau


has successfully completed the Asbestos Building Inspector Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 12/2/2015

Exam Date: 12/2/2015

Expiration Date: 12/2/2016

Certificate Number: BIR1512024163


Kathy DeSalvo, Director

APPENDIX C

Laboratory Accreditations

APPENDIX D

Laboratory Results

APPENDIX E

Chain of Custody Forms

Three-Year Reinspection Key to Terms

	CODE	KEY
MATERIAL		
	ACBM	Asbestos Containing Building Materials
MATERIAL CATEGORY		
	MISC	Miscellaneous
	SURF	Surfacing
	TSI	Thermal System Insulation
MATERIAL UNITS		
	LF	Linear Feet
	SF	Square Feet
	CF	Cubic Feet
DAMAGE TYPE		
	Loc	Localized
	Dist	Distributed