

**ILLINOIS DEPARTMENT OF PUBLIC HEALTH  
AHERA THREE YEAR REINSPECTION  
ASBESTOS ABATEMENT PROGRAM  
SCHOOL INFORMATION FORM**

**SECTION I**

NAME OF SCHOOL DISTRICT: CHICAGO SCHOOL DIST 299  
SCHOOL ID NUMBER: 14-016-2990-2224  
SCHOOL NAME: Graham School  
ADDRESS OF SCHOOL: 4436 S. Union  
CITY: Chicago, IL, 60609

DATE LAST THREE YEAR REINSPECTION WAS COMPLETED **3/28/2013**

**If the address on this form is different than the address of the building, submit a written explanation.**

---

**SECTION II** *(Please type or print)*

**PLEASE COMPLETE THE FOLLOWING FOR YOUR THREE YEAR REINSPECTION:**

DATE REINSPECTION COMPLETED: 4/14/2016 ENROLLMENT 457  
IDPH INSPECTOR LICENSE NUMBER: 100-19466  
IDPH LICENSED INSPECTOR NAME (Please Print): Evan Christian  
IDPH MP LICENSE NUMBER: 100-09870  
IDPH LICENSED MANAGEMENT PLANNER NAME (Please Print): Todd Huffer

DESIGNATED PERSON (Please Print): Robert Christlieb PHONE: (773) 553-3197



4/14/2016

*Signature of Designated Person*

*Date*

**SECTION III**

PLEASE COMPLETE THE FOLLOWING INFORMATION FOR ANY CHANGES WITHIN THE SCHOOL DISTRICT.

School building has been sold. Date of Sale: \_\_\_\_\_

School has been closed. Date closed: \_\_\_\_\_

School building has been demolished. Date: \_\_\_\_\_

School building is asbestos free since last reinspection: \_\_\_\_\_

**Please explain in writing why the school building is now asbestos free and include the supporting documentation.**

If a new school building has been added to the district, submit either an exclusionary statement or a management plan and inspection report. Include the complete name, address and city of school building.

**Explain in writing if the address of the building is different than the address on this form:**

---

---

---

**THREE-YEAR REINSPECTION**

**CHICAGO SCHOOL DIST 299**

**Graham School**

4436 S. Union  
Chicago, IL, 60609

Unit: 23391  
Building ID: 3600

IDPH ID Number: 14-016-2990-2224

**REPORT DATE:**

Thursday, April 14, 2016

**Prepared for:**

**Chicago Public Schools**  
**125 S. Clark Street**  
**Chicago, IL 60603**

**Prepared by:**

**Carnow, Conibear and Associates**

600 West Van Buren St., Ste 500

Phone (312) 762-2900

Fax (312) 782-5145

**DO NOT REMOVE FROM SCHOOL  
REQUIRED BY FEDERAL LAW**



## **Environmental Notification to Occupants**

To: Faculty, Staff and Parents  
From: Chicago Public Schools  
Date: March 10, 2016

RE: Graham School, Unit 23391  
4436 S. Union  
Chicago, IL, 60609

Dear Faculty, Staff and Parents,

This letter is to notify you that the 2016 asbestos three year re-inspection has been completed at Graham School, following the Federal Asbestos Hazard Emergency Response Act (AHERA), 40 CFR Part 763, Subpart E and is available for your review at the main office of the school.

Although asbestos-containing materials have been identified at Graham School, there is no reason to believe that any threat to the health of students or staff exists at this time. CPS will continue to carefully monitor the condition of asbestos-containing materials and if conditions warrant, all appropriate steps will be taken to maintain the health and safety of all building occupants.

If you have any questions regarding this matter or require additional information, please feel free to contact Robert Christlieb, the designated Local Education Authority's Designated Person at (773) 553-3197 .

## **Table of Contents**

- I. School and Inspection Information
- II. Executive Summary
- III. Methodology
- IV. Abatement History
- V. Reassessments and Recommendations
- VI. Conclusions

Table I: Inspector's Reinspection Findings

Table II: Management Planner's Review

### **APPENDICES:**

- Appendix A: Assessment Sheets, Drawings and Photos
- Appendix B: Inspector and Management Planner Licenses
- Appendix C: Laboratory Accreditations
- Appendix D: Laboratory Results
- Appendix E: Chain of Custody Forms

## SCHOOL AND INSPECTION INFORMATION

### 1. School Information

School: Graham School Unit: 23391 Region: 04  
Address: 4436 S. Union Chicago, IL, 60609  
IDPH ID: 14-016-2990-2224 Building ID: 3600  
Contact: Fuller, Dean Phone: 773-268-3414

### 2. Description of Facility

Original Construction: 1974 Additional Construction:  
Total Square Footage: 43000 No of Floors: 3  
Current Occupancy: 457

### 3. LEA Designated Person

Contact: Robert Christlieb Phone: (773) 553-3197  
Address: 125 South Clark Street, 17th Floor  
Chicago, IL 60603

### 4. Managing Environmental Consultant

MEC: Carnow, Conibear and Associates  
Contact: Dan Juneau  
Address 600 West Van Buren St., Ste 500  
Phone: (312) 762-2900 Fax: (312) 782-5145

### 5. Inspector

Inspector Name: Evan Christian


Inspector IDPH license # 100-19466

Signature:  
Date: 3/10/2016

### 6. Management Planner

Management Planner Name: Todd Huffer

Management Planner IDPH license # 100-09870

Signature:   
Date: 04/14/2016

### 7. Review Date: 04/14/2016

### 8. LEA Designated Person's Acknowledgement

The reinspection report and recommendations have been received by me and appropriate action will be taken by the School District.

Signature: 

Date: 4/14/2016

Name: Robert Christlieb

## II. EXECUTIVE SUMMARY

Carnow, Conibear and Associates was retained by the Chicago Public Schools (CPS) to perform a three-year asbestos reinspection of the Graham School. This inspection was conducted in accordance with the United States Environmental Protection Agency (USEPA) Asbestos Hazard Emergency Response Act (AHERA) part 763.92 (b), and the ongoing Operations and Maintenance Program (O&M) originally designed in the School's Asbestos Management Plan. The purpose of this three-year reinspection is to record any condition changes in the asbestos-containing building material (ACBM) in the school since the previous three-year reinspection and the six-month periodic surveillance, to identify, assess, and include any Homogeneous Areas (HA) not identified in the Management Plan, and to recommend an appropriate response action to manage asbestos.

The inspector conducted a three-year reinspection of this facility under Illinois Department of Public Health (IDPH) school reinspection requirements and AHERA, sections 763.85 and 763.88. The main building and each addition to the main building, if constructed at different dates, were inspected separately. Laboratory accreditations are included in Appendix C, laboratory results are included in Appendix D, and chain of custody forms are included in Appendix E.

Note: During previous inspections, some of the HA(s) were identified together as 9" x 9" floor tile (FT), mastics assoc. with 9" x 9" FT, 12" x 12" FT, mastics assoc. with 12" x 12" FT, pipe insulation, etc. Some of these HA(s) have been re-identified by areas that are uniform in color, texture, construction date, application date, and general appearance.

The inspector has determined the following:

A. The following HAs have changed assessment categories for Building 3600:

D1	Paperwrap Pipe Insulation Fittings
G	Cardboard Pipe Wrap

B. The following new homogenous areas have been identified for Building 3600:



C. This reinspection covered only physically accessible and visible areas and materials that were identified in the LEA's management plan. The following materials were concealed and/or contained in areas that were inaccessible for sampling and have been classified as Assumed:

10.1	12x12 Brown w/White & Brown Speckles Floor Tile
10.3	12x12 Off-White w/Brown Speckles Floor Tile
10.4	12x12 Floor Tile (under carpet)
11	1x1 Ceiling Tile Mastic
14.4	Mastic Under Floor Tile (Under Carpet)
2	1x1 Acoustical Ceiling Tile
24	Blue/Green Carpet Mastic
25	12" x 12" White w/Lt. Blue Specks FT
26	12" x 12" White w/Lt. Blue Specks FT Mastic
27	12" x 12" Beige w/Gray & Brown Streaks FT
28	12" x 12" Beige w/Gray & Brown Streaks FT Mastic
29	Incinerator Lining
30	Chalkboards
31	12x12 Beige Speckled Floor Tile
32	Mastic associated with 12x12 Beige Speckled FT
36	9x9 Lt Gray floor tile w/red& gray specks
37	9x9 Lt Gray floor tile w/red& gray specks Mastic
38	12" x 12" Brown VFT
39	12" x 12" Brown VFT Mastic

The following areas were deemed to be inaccessible:

11	1x1 Ceiling Tile Mastic
13.1	Mastic for 9x9 Brown VFT w/White and Brown Speckle
13.2	Mastic for 9x9 VFT Brown/Pink/Gray Grains
13.3	Mastic for 9x9 Off-white w/Brown and Gray Streaks
13.4	Mastic for 9x9 Red Floor Tile
14.1	Mastic for 12x12 brown VFT w/White and Brown Speck
14.2	Mastic for 12x12 Off White VFTw/Gray and Brown Str
14.3	Mastic for 12x12 Off White VFT w/Brown Speckles
14.4	Mastic Under Floor Tile (Under Carpet)
26	12" x 12" White w/Lt. Blue Specks FT Mastic
32	Mastic associated with 12x12 Beige Speckled FT
34	Mastic on 9x9 Dark Brown with white/red streaks FT

35  
39

9x9 Light Brown w/white & Brown FT  
12" x 12" Brown VFT Mastic

Materials were also listed as "assumed" if they were in good condition and sampling was not conducted to avoid damage.

This reinspection was conducted by Evan Christian, IDPH License # 100-19466. The Management Plan was updated by Todd Huffer, IDPH License # 100-09870. Inspector and Management Planner Licenses are included in Appendix B.

### **III. METHODOLOGY**

Tasks performed on-site included the following:

1. Review current management plan, identify HA(s) and extract appropriate information.
2. Examine and verify abatement records.
3. Touch and visually and physically reinspect and reassess the condition of all friable known or assumed ACBM.
4. Touch and visually and physically reinspect all non-friable known or assumed ACBM to determine whether these materials have become friable since the last inspection or periodic surveillance.
5. Identify any condition changes that may affect Hazard Ranking of known ACBM or Assumed ACBM, as well as any HA(s) that have become friable since the last reinspection.
6. Collect bulk samples from each newly discovered friable HA or previously assumed and submit for laboratory analysis.
7. Tabulate reinspection findings and submit for management planner review and recommendations with appropriate response actions based on the AHERA Damage Category of the ACBM.
8. Submit reinspection findings and management planner recommendations to the LEA within thirty (30) days for inclusion into the management plan.

### **IV. ABATEMENT HISTORY**

The information collected from the existing management plan and inspection report(s) and from interviews with the school official revealed that the following asbestos abatement was conducted at the school since the previous Three year Reinspection.

Abatement Dates:

### **V. REASSESSMENTS AND RECOMMENDATIONS**

The reassessments and recommendations are summarized in Tables I and II on the following pages. Detailed Hazard Assessment Sheets and Drawings and Photos (if applicable) are included in Appendix A.

### **VI. CONCLUSIONS**

The Graham School Building 3600 Three-Year reinspection has been completed and response actions have been recommended for both friable and non-friable materials. A timely execution of the response actions recommended will enable the LEA and the Designated Person(s) to effectively manage the existing ACBM.

This three-year reinspection report should be inspected in the current Management plan at the CPS Central Office, and one (1) copy should be kept at the school for use when planning any renovation and/or demolition activities in areas where ACBM has been identified. Also, periodic surveillance documentation and any summary reports from any response actions that are executed at the school should be used to update the Management Plan.

**Table I**  
**Inspector's Reinspection Findings**

---

# Chicago Public Schools

School Graham School Unit 23391 Building ID 3600

Address 4436 S. Union Region 04

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
1	Plaster			Throughout	NO_ACBM									
10.1	12x12 Brown w/White & Brown Speckles Floor Tile	3,092	SF	Room 098, 101, 103, 104 and 109	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
10.2	12x12 Off-White w/Gray & Brown Streaks Floor Tile	1,400	SF	Room 99, 2nd Floor Teachers Restroom	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
10.3	12x12 Off-White w/Brown Speckles Floor Tile	5,928	SF	Lunchroom	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
10.4	12x12 Floor Tile (under carpet)			Room 205	ASSUMED	MISC								
11	1x1 Ceiling Tile Mastic	200	SF	Gym	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
13.1	Mastic for 9x9 Brown VFT w/White and Brown Speckle	7,200	SF	Rm 104, 202, 203,204, 209, and 301	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
13.2	Mastic for 9x9 VFT Brown/Pink/Gray Grains	10	SF	3rd Fl Teachers Toilet	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
13.3	Mastic for 9x9 Off-white w/Brown and Gray Streaks	800	SF	Basement Teachers Lunch Room	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
13.4	Mastic for 9x9 Red Floor Tile	250	SF	Basement Store Room North of the Teachers Lunch Room	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
14.1	Mastic for 12x12 brown VFT w/White and Brown Speck	3,400	SF	Rooms 098, 101, 103, 109, 3rd Floor Teachers Restroom	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
14.2	Mastic for 12x12 Off White VFTw/Gray and Brown Str	1,400	SF	Room 099 & 2nd Floor Womens Restroom	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
14.3	Mastic for 12x12 Off White VFT w/Brown Speckles	1,950	SF	Lunchroom	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
14.4	Mastic Under Floor Tile (Under Carpet)	1,000	SF	Room 205	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
15	Drywall			2nd Floor Boy's and Girl's Washrooms, Basement Eng. Office	NO_ACBM									
16	Canvas			Classrooms	NO_ACBM									
17	Window Glaze			Interior	NO_ACBM									
18	Glazed Brick			Entrances to Building, Girl's and Boy's Washrooms	NO_ACBM									
19	Glazed Brick Mortar			Entrances to Building, Girl's and Boy's Washrooms	NO_ACBM									
2	1x1 Acoustical Ceiling Tile	200	SF	Gym	ASSUMED	MISC	Y	NONE	0		No	Any remaining friable		LOW



# Chicago Public Schools

School Graham School Unit 23391 Building ID 3600

Address 4436 S. Union Region 04

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				205, Various Others										
9.1	9x9 VFT, Brown w/White and Brown Streaks	7,200	SF	Rm104, 202, 203,204, 209, and 301	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
9.2	9x9 VFT, White w/Brown, Pink, and Gray Grains	10	SF	3rd Floor Teacher's Washrooms	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
9.3	9x9 VFT, Off-White w/Brown and Gray Streaks	800	SF	Basement Teacher's Lunchroom	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
9.4	9x9 Red Floor Tile	250	SF	Basement Storage Room	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
A	Boilers Insulation (2)	650	SF	Boiler Room	CHR	TSI	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
B	Fittings on Fiberglass Insulation	240	LF	Throughout Basement, Room 106, 208, 209,306, 308, 2nd floor Boys+Girls Restrooms	CHR	TSI	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
D1	Paperwrap Pipe Insulation Fittings	120	LF	Throughout Basement	CHR	TSI	Y	LOC	2		Yes	Damaged or significantly damaged friable thermal system insulating ACBM	3	MODERATE
D2	Aircell Pipe Insulation Fittings	200	LF	Throughout Basement	CHR	TSI	Y		0		No	Any remaining friable ACBM or friable suspect ACBM		
E	Preformed Pipe Wrap			Basement North Corridor	CHR	TSI								
F	Aircell Pipe Wrap	800	LF	Basement	CHR	TSI	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
G	Cardboard Pipe Wrap	725	LF	Throughout Basement	CHR	TSI	Y	LOC	3		Yes	Damaged or significantly damaged friable thermal system insulating ACBM	2	MODERATE

# Chicago Public Schools

School Graham School Unit 23391 Building ID 3600

Address 4436 S. Union Region 04

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

*Inspector's Comments are Summarized at the End of the Report*

Reinspection Date <b>3/10/2016</b>
Inspector Name <b>Evan Christian</b>
<b>100-19466</b> <b>5/15/2016</b>
Inspector's IDPH License Number / Expiration Date

### Inspector's Comments

HA Number:	Inspector Comments:
1	
10.1	
10.2	
10.3	
10.4	Not observed 2016
11	
13.1	
13.2	
13.3	
13.4	
14.1	
14.2	
14.3	
14.4	Also found in Library
15	
16	
17	
18	
19	
2	
20	
21	
22	Not observed 2016
23	



# Chicago Public Schools

School Graham School Unit 23391 Building ID 3600

Address 4436 S. Union Region 04

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

*Inspector's Comments are Summarized at the End of the Report*

---

HA Number:	Inspector Comments:
24	Not observed 2016
25	
26	
27	
28	Not observed 2016
29	Not observed 2016
30	
31	
32	
33	
34	
35	
36	
37	
38	
39	
4.1	
4.2	
9.1	
9.2	
9.3	
9.4	
A	
B	
D1	
D2	
E	not observed 2016
F	
G	

# Chicago Public Schools

**School** Graham School **Unit** 23391 **Building ID** 3600

**Address** 4436 S. Union **Region** 04

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

*Inspector's Comments are Summarized at the End of the Report*

---

**Table II**

**Management Planner's Review**

---

# Chicago Public Schools

School Graham School

Unit 23391

Building ID 3600

Address 4436 S. Union

Chicago, IL, 60609

Region 04

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

### Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
1	Plaster			Throughout	No ACBM						
10.1	12x12 Brown w/White & Brown Speckles Floor Tile	3,092	SF	Room 098, 101, 103, 104 and 109	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
10.2	12x12 Off-White w/Gray & Brown Streaks Floor Tile	1,400	SF	Room 99, 2nd Floor Teachers Restroom	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
10.3	12x12 Off-White w/Brown Speckles Floor Tile	5,928	SF	Lunchroom	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
10.4	12x12 Floor Tile (under carpet)			Room 205	Assumed	MISC					
11	1x1 Ceiling Tile Mastic	200	SF	Gym	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
13.1	Mastic for 9x9 Brown VFT w/White and Brown Speckle	7,200	SF	Rm 104, 202, 203,204, 209, and 301	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
13.2	Mastic for 9x9 VFT Brown/Pink/Gray Grains	10	SF	3rd Fl Teachers Toilet	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
13.3	Mastic for 9x9 Off-white w/Brown and Gray Streaks	800	SF	Basement Teachers Lunch Room	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
13.4	Mastic for 9x9 Red Floor Tile	250	SF	Basement Store Room North of the Teachers Lunch Room	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
14.1	Mastic for 12x12 brown VFT w/White and Brown Speck	3,400	SF	Rooms 098, 101, 103, 109, 3rd Floor Teachers Restroom	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
14.2	Mastic for 12x12 Off White VFTw/Gray and Brown Str	1,400	SF	Room 099 & 2nd Floor Womens Restroom	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
14.3	Mastic for 12x12 Off White VFT w/Brown Speckles	1,950	SF	Lunchroom	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
14.4	Mastic Under Floor Tile (Under Carpet)	1,000	SF	Room 205	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
15	Drywall			2nd Floor Boy's and Girl's Washrooms, Basement Eng. Office	No ACBM						
16	Canvas			Classrooms	No ACBM						
17	Window Glaze			Interior	No ACBM						
18	Glazed Brick			Entrances to Building, Girl's and Boy's Washrooms	No ACBM						
19	Glazed Brick Mortar			Entrances to Building, Girl's and Boy's Washrooms	No ACBM						
2	1x1 Acoustical Ceiling Tile	200	SF	Gym	Assumed	MISC	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
20	Yellow Brick			Exterior	No ACBM						
21	Brick Mortar			Exterior	No ACBM						
22	Green Layer Under 9x9 VFT			2nd Floor Teacher's Washroom	Chrysotile	MISC					
23	Drywall Tape Compound			Basement Storage Room, Boy's and Girl's Washrooms	No ACBM						
24	Blue/Green Carpet Mastic			Main Office	Assumed	MISC					

# Chicago Public Schools

School Graham School  
Address 4436 S. Union

Unit 23391  
Chicago, IL, 60609

Building ID 3600  
Region 04

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

### Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
25	12" x 12" White w/Lt. Blue Specks FT	150	SF	Main Office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
26	12" x 12" White w/Lt. Blue Specks FT Mastic	150	SF	Main Office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
27	12" x 12" Beige w/Gray & Brown Streaks FT			Trailer Pod - torn down	Assumed	MISC					
28	12" x 12" Beige w/Gray & Brown Streaks FT Mastic			Trailer Pod - torn down	Assumed	MISC					
29	Incinerator Lining			Coal Room	Assumed	MISC					
30	Chalkboards	2,700	SF	Room 101-104, 106-108, 201-209, 301-309	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
31	12x12 Beige Speckled Floor Tile	550	SF	Room 109 Coatroom & 209 Coatroom	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
32	Mastic associated with 12x12 Beige Speckled FT	550	SF	Room 109 Coatroom & 209 Coatroom	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
33	9x9 Dark Brown with white/red streaks FT	2,200	SF	1st Floor Corridor	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
34	Mastic on 9x9 Dark Brown with white/red streaks FT	2,200	SF	1st Floor Corridor	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
35	9x9 Light Brown w/white & Brown FT	400	SF	Rm104, 202, 203,204, 209, and 301, 1st Floor Corridor	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
36	9x9 Lt Gray floor tile w/red& gray specks	430	SF	Principals office & platform	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
37	9x9 Lt Gray floor tile w/red& gray specks Mastic	430	SF	Principals Office & platform	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
38	12" x 12" Brown VFT	24	SF	1st Floor Corridor	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
39	12" x 12" Brown VFT Mastic	24	SF	1st Floor Corridor	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
4.1	2x4 White Ceiling Tile, Type 1			Room 106 & 301	No ACBM						
4.2	2x4 White Ceiling Tile, Type 2			Rooms 101, 107, 205, Various Others	No ACBM						
9.1	9x9 VFT, Brown w/White and Brown Streaks	7,200	SF	Rm104, 202, 203,204, 209, and 301	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
9.2	9x9 VFT, White w/Brown, Pink, and Gray Grains	10	SF	3rd Floor Teacher's Washrooms	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
9.3	9x9 VFT, Off-White w/Brown and Gray Streaks	800	SF	Basement Teacher's Lunchroom	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
9.4	9x9 Red Floor Tile	250	SF	Basement Storage Room	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
A	Boilers Insulation (2)	650	SF	Boiler Room	Chrysotile	TSI	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
B	Fittings on Fiberglass Insulation	240	LF	Throughout Basement, Room 106, 208, 209,306, 308, 2nd floor Boys+Girls Restrooms	Chrysotile	TSI	Yes	0	LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
D1	Paperwrap Pipe Insulation Fittings	120	LF	Throughout Basement	Chrysotile	TSI	Yes	2	LF	1 Damaged or significantly damaged friable thermal system insulating ACBM	Remove
D2	Aircell Pipe Insulation Fittings	200	LF	Throughout Basement	Chrysotile	TSI	Yes	0	LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
E	Preformed Pipe Wrap			Basement North Corridor	Chrysotile	TSI					
F	Aircell Pipe Wrap	800	LF	Basement	Chrysotile	TSI	Yes	0	LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan

# Chicago Public Schools

**School** Graham School  
**Address** 4436 S. Union

**Unit** 23391  
 Chicago, IL, 60609

**Building ID** 3600  
**Region** 04

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

### *Management Planner's Comments Summarized at the End of the Report*

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
G	Cardboard Pipe Wrap	725	LF	Throughout Basement	Chrysotile	TSI	Yes	3	LF	suspect ACBM 1 Damaged or significantly damaged friable thermal system insulating ACBM	Remove

Review Date	4/14/2016
Manager Planner Name	Todd Huffer

HA Number	Management Comments
1	

# Chicago Public Schools

**School** Graham School  
**Address** 4436 S. Union

**Unit** 23391  
 Chicago, IL, 60609

**Building ID** 3600  
**Region** 04

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

### *Management Planner's Comments Summarized at the End of the Report*

100-09870	5/15/2016
Manager IDPH License No/Expiration	

HA Number	Management Comments
10.1	
10.2	
10.3	
10.4	material not observed in 2016
11	
13.1	
13.2	
13.3	
13.4	
14.1	
14.2	
14.3	
14.4	Material is also Library
15	
16	
17	
18	
19	
2	
20	
21	
22	material not observed in 2016
23	
24	material not observed in 2016
25	
26	
27	

# Chicago Public Schools

**School** Graham School  
**Address** 4436 S. Union

**Unit** 23391  
 Chicago, IL, 60609

**Building ID** 3600  
**Region** 04

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

### *Management Planner's Comments Summarized at the End of the Report*

HA Number	Management Comments
28	material not observed in 2016
29	material not observed in 2016
30	
31	
32	
33	
34	
35	
36	
37	
38	
39	
4.1	
4.2	
9.1	
9.2	
9.3	
9.4	
A	
B	
D1	Remove/Repair Material. Follow O&M procedures after response action
D2	
E	material not observed in 2016
F	
G	Remove/Repair Material. Follow O&M procedures after response action.



# Chicago Public Schools

**School** Graham School

**Unit** 23391

**Building ID** 3600

**Address** 4436 S. Union

Chicago, IL, 60609

**Region** 04

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

*Management Planner's Comments Summarized at the End of the Report*

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23391** BUIDLING ID: **3600**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Evan Christian**  
SCHOOL NAME: **Graham School** INSPECTION DATE: **3/10/2016**  
ADDRESS: **4436 S. Union** IDPH LICENSE NO: **100-19466**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **1**  
MATERIAL DESCRIPTION: **Plaster**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **03/10/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23391** BUIDLING ID: **3600**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Graham School** REVIEW DATE: **4/14/2016**  
ADDRESS: **4436 S. Union** IDPH LICENSE NO: **100-19466**

---

HOMOGENEOUS AREA: **1**

MATERIAL DESCRIPTION: **Plaster**

MATERIAL LOCATION: **Throughout**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **04/14/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23391** BUIDLING ID: **3600**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Evan Christian**  
SCHOOL NAME: **Graham School** INSPECTION DATE: **3/10/2016**  
ADDRESS: **4436 S. Union** IDPH LICENSE NO: **100-19466**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **10.1**  
MATERIAL DESCRIPTION: **12x12 Brown w/White & Brown Speckles Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Room 098, 101, 103, 104 and 109**  
MATERIAL QUANTITY: **3092** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 03/10/2016

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23391** BUIDLING ID: **3600**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Graham School** REVIEW DATE: **4/14/2016**  
ADDRESS: **4436 S. Union** IDPH LICENSE NO: **100-19466**

---

HOMOGENEOUS AREA: **10.1**  
MATERIAL DESCRIPTION: **12x12 Brown w/White & Brown Speckles Floor Tile**  
MATERIAL LOCATION: **Room 098, 101, 103, 104 and 109**  
MATERIAL QUANTITY: **3092** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **04/14/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23391** BUIDLING ID: **3600**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Evan Christian**  
SCHOOL NAME: **Graham School** INSPECTION DATE: **3/10/2016**  
ADDRESS: **4436 S. Union** IDPH LICENSE NO: **100-19466**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **10.2**  
MATERIAL DESCRIPTION: **12x12 Off-White w/Gray & Brown Streaks Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Room 99, 2nd Floor Teachers Restroom**

MATERIAL QUANTITY: **1400**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_

Date: 03/10/2016

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23391** BUIDLING ID: **3600**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Graham School** REVIEW DATE: **4/14/2016**  
ADDRESS: **4436 S. Union** IDPH LICENSE NO: **100-19466**

---

HOMOGENEOUS AREA: **10.2**  
MATERIAL DESCRIPTION: **12x12 Off-White w/Gray & Brown Streaks Floor Tile**  
MATERIAL LOCATION: **Room 99, 2nd Floor Teachers Restroom**  
MATERIAL QUANTITY: **1400** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **04/14/2016**

# Chicago Public Schools

## Carnow, Conibear and Associates 2016 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **23391**    BUIDLING ID: **3600**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Evan Christian**  
SCHOOL NAME: **Graham School**    INSPECTION DATE: **3/10/2016**  
ADDRESS: **4436 S. Union**    IDPH LICENSE NO: **100-19466**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **10.3**  
MATERIAL DESCRIPTION: **12x12 Off-White w/Brown Speckles Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed**    FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Lunchroom**  
MATERIAL QUANTITY: **5928**    MATERIAL UNITS: **SF**  
DAMAGE QUANTITY:    DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 03/10/2016



# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23391** BUIDLING ID: **3600**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Graham School** REVIEW DATE: **4/14/2016**  
ADDRESS: **4436 S. Union** IDPH LICENSE NO: **100-19466**

---

HOMOGENEOUS AREA: **10.3**  
MATERIAL DESCRIPTION: **12x12 Off-White w/Brown Speckles Floor Tile**  
MATERIAL LOCATION: **Lunchroom**  
MATERIAL QUANTITY: **5928** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **04/14/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23391** BUIDLING ID: **3600**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Evan Christian**  
SCHOOL NAME: **Graham School** INSPECTION DATE: **3/10/2016**  
ADDRESS: **4436 S. Union** IDPH LICENSE NO: **100-19466**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **10.4**  
MATERIAL DESCRIPTION: **12x12 Floor Tile (under carpet)**  
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 205**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed 2016**

Inspector's Signature: \_\_\_\_\_

Date: 03/10/2016

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23391** BUIDLING ID: **3600**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Graham School** REVIEW DATE: **4/14/2016**  
ADDRESS: **4436 S. Union** IDPH LICENSE NO: **100-19466**

---

HOMOGENEOUS AREA: **10.4**

MATERIAL DESCRIPTION: **12x12 Floor Tile (under carpet)**

MATERIAL LOCATION: **Room 205**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

material not observed in 2016

Management Planner's Signature: \_\_\_\_\_



Date: **04/14/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23391** BUIDLING ID: **3600**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Evan Christian**  
SCHOOL NAME: **Graham School** INSPECTION DATE: **3/10/2016**  
ADDRESS: **4436 S. Union** IDPH LICENSE NO: **100-19466**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **11**  
MATERIAL DESCRIPTION: **1x1 Ceiling Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 Any remaining friable ACBM or friable suspect ACBM**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Gym**

MATERIAL QUANTITY: **200**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_

Date: 03/10/2016

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23391** BUIDLING ID: **3600**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Graham School** REVIEW DATE: **4/14/2016**  
ADDRESS: **4436 S. Union** IDPH LICENSE NO: **100-19466**

---

HOMOGENEOUS AREA: **11**  
MATERIAL DESCRIPTION: **1x1 Ceiling Tile Mastic**  
MATERIAL LOCATION: **Gym**  
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **04/14/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23391** BUIDLING ID: **3600**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Evan Christian**  
SCHOOL NAME: **Graham School** INSPECTION DATE: **3/10/2016**  
ADDRESS: **4436 S. Union** IDPH LICENSE NO: **100-19466**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **13.1**  
MATERIAL DESCRIPTION: **Mastic for 9x9 Brown VFT w/White and Brown Speckle**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Rm 104, 202, 203,204, 209, and 301**

MATERIAL QUANTITY: **7200**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_

Date: 03/10/2016

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23391** BUIDLING ID: **3600**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Graham School** REVIEW DATE: **4/14/2016**  
ADDRESS: **4436 S. Union** IDPH LICENSE NO: **100-19466**

---

HOMOGENEOUS AREA: **13.1**  
MATERIAL DESCRIPTION: **Mastic for 9x9 Brown VFT w/White and Brown Speckle**  
MATERIAL LOCATION: **Rm 104, 202, 203,204, 209, and 301**  
MATERIAL QUANTITY: **7200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **04/14/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23391** BUIDLING ID: **3600**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Evan Christian**  
SCHOOL NAME: **Graham School** INSPECTION DATE: **3/10/2016**  
ADDRESS: **4436 S. Union** IDPH LICENSE NO: **100-19466**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **13.2**  
MATERIAL DESCRIPTION: **Mastic for 9x9 VFT Brown/Pink/Gray Grains**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **3rd FI Teachers Toilet**  
MATERIAL QUANTITY: **10** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 03/10/2016



# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23391** BUIDLING ID: **3600**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Graham School** REVIEW DATE: **4/14/2016**  
ADDRESS: **4436 S. Union** IDPH LICENSE NO: **100-19466**

---

HOMOGENEOUS AREA: **13.2**

MATERIAL DESCRIPTION: **Mastic for 9x9 VFT Brown/Pink/Gray Grains**

MATERIAL LOCATION: **3rd FI Teachers Toilet**

MATERIAL QUANTITY: **10**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **04/14/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23391** BUIDLING ID: **3600**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Evan Christian**  
SCHOOL NAME: **Graham School** INSPECTION DATE: **3/10/2016**  
ADDRESS: **4436 S. Union** IDPH LICENSE NO: **100-19466**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **13.3**  
MATERIAL DESCRIPTION: **Mastic for 9x9 Off-white w/Brown and Gray Streaks**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Basement Teachers Lunch Room**

MATERIAL QUANTITY: **800**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_

Date: 03/10/2016

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23391** BUIDLING ID: **3600**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Graham School** REVIEW DATE: **4/14/2016**  
ADDRESS: **4436 S. Union** IDPH LICENSE NO: **100-19466**

---

HOMOGENEOUS AREA: **13.3**

MATERIAL DESCRIPTION: **Mastic for 9x9 Off-white w/Brown and Gray Streaks**

MATERIAL LOCATION: **Basement Teachers Lunch Room**

MATERIAL QUANTITY: **800**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **04/14/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23391** BUIDLING ID: **3600**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Evan Christian**  
SCHOOL NAME: **Graham School** INSPECTION DATE: **3/10/2016**  
ADDRESS: **4436 S. Union** IDPH LICENSE NO: **100-19466**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **13.4**  
MATERIAL DESCRIPTION: **Mastic for 9x9 Red Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Basement Store Room North of the Teachers Lunch Room**  
MATERIAL QUANTITY: **250** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 03/10/2016

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23391** BUIDLING ID: **3600**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Graham School** REVIEW DATE: **4/14/2016**  
ADDRESS: **4436 S. Union** IDPH LICENSE NO: **100-19466**

---

HOMOGENEOUS AREA: **13.4**  
MATERIAL DESCRIPTION: **Mastic for 9x9 Red Floor Tile**  
MATERIAL LOCATION: **Basement Store Room North of the Teachers Lunch Room**  
MATERIAL QUANTITY: **250** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **04/14/2016**

# Chicago Public Schools

## Carnow, Conibear and Associates 2016 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **23391**    BUILDING ID: **3600**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Evan Christian**  
SCHOOL NAME: **Graham School**    INSPECTION DATE: **3/10/2016**  
ADDRESS: **4436 S. Union**    IDPH LICENSE NO: **100-19466**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **14.1**  
MATERIAL DESCRIPTION: **Mastic for 12x12 brown VFT w/White and Brown Speck**  
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile**    FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Rooms 098, 101, 103, 109, 3rd Floor Teachers Restroom**  
MATERIAL QUANTITY: **3400**    MATERIAL UNITS: **SF**  
DAMAGE QUANTITY:    DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 03/10/2016

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23391** BUIDLING ID: **3600**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Graham School** REVIEW DATE: **4/14/2016**  
ADDRESS: **4436 S. Union** IDPH LICENSE NO: **100-19466**

---

HOMOGENEOUS AREA: **14.1**  
MATERIAL DESCRIPTION: **Mastic for 12x12 brown VFT w/White and Brown Speck**  
MATERIAL LOCATION: **Rooms 098, 101, 103, 109, 3rd Floor Teachers Restroom**  
MATERIAL QUANTITY: **3400** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **04/14/2016**

# Chicago Public Schools

## Carnow, Conibear and Associates 2016 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23391** BUIDLING ID: **3600**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Evan Christian**  
SCHOOL NAME: **Graham School** INSPECTION DATE: **3/10/2016**  
ADDRESS: **4436 S. Union** IDPH LICENSE NO: **100-19466**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **14.2**  
MATERIAL DESCRIPTION: **Mastic for 12x12 Off White VFTw/Gray and Brown Str**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Room 099 & 2nd Floor Womens Restroom**  
MATERIAL QUANTITY: **1400** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 03/10/2016



# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23391** BUIDLING ID: **3600**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Graham School** REVIEW DATE: **4/14/2016**  
ADDRESS: **4436 S. Union** IDPH LICENSE NO: **100-19466**

---

HOMOGENEOUS AREA: **14.2**  
MATERIAL DESCRIPTION: **Mastic for 12x12 Off White VFTw/Gray and Brown Str**  
MATERIAL LOCATION: **Room 099 & 2nd Floor Womens Restroom**  
MATERIAL QUANTITY: **1400** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **04/14/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23391** BUIDLING ID: **3600**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Evan Christian**  
SCHOOL NAME: **Graham School** INSPECTION DATE: **3/10/2016**  
ADDRESS: **4436 S. Union** IDPH LICENSE NO: **100-19466**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **14.3**  
MATERIAL DESCRIPTION: **Mastic for 12x12 Off White VFT w/Brown Speckles**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Lunchroom**

MATERIAL QUANTITY: **1950**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_

Date: 03/10/2016

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23391** BUIDLING ID: **3600**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Graham School** REVIEW DATE: **4/14/2016**  
ADDRESS: **4436 S. Union** IDPH LICENSE NO: **100-19466**

---

HOMOGENEOUS AREA: **14.3**  
MATERIAL DESCRIPTION: **Mastic for 12x12 Off White VFT w/Brown Speckles**  
MATERIAL LOCATION: **Lunchroom**  
MATERIAL QUANTITY: **1950** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **04/14/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23391** BUIDLING ID: **3600**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Evan Christian**  
SCHOOL NAME: **Graham School** INSPECTION DATE: **3/10/2016**  
ADDRESS: **4436 S. Union** IDPH LICENSE NO: **100-19466**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **14.4**  
MATERIAL DESCRIPTION: **Mastic Under Floor Tile (Under Carpet)**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Room 205**

MATERIAL QUANTITY: **1000**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS: **Also found in Library**

Inspector's Signature: \_\_\_\_\_

Date: 03/10/2016

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23391** BUIDLING ID: **3600**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Graham School** REVIEW DATE: **4/14/2016**  
ADDRESS: **4436 S. Union** IDPH LICENSE NO: **100-19466**

---

HOMOGENEOUS AREA: **14.4**  
MATERIAL DESCRIPTION: **Mastic Under Floor Tile (Under Carpet)**  
MATERIAL LOCATION: **Room 205**  
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Material is also Library

Management Planner's Signature: \_\_\_\_\_



Date: **04/14/2016**

# Chicago Public Schools

## Carnow, Conibear and Associates 2016 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23391** BUIDLING ID: **3600**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Evan Christian**  
SCHOOL NAME: **Graham School** INSPECTION DATE: **3/10/2016**  
ADDRESS: **4436 S. Union** IDPH LICENSE NO: **100-19466**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **15**  
MATERIAL DESCRIPTION: **Drywall**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **2nd Floor Boy's and Girl's Washrooms, Basement Eng. Office**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **03/10/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23391** BUIDLING ID: **3600**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Graham School** REVIEW DATE: **4/14/2016**  
ADDRESS: **4436 S. Union** IDPH LICENSE NO: **100-19466**

---

HOMOGENEOUS AREA: **15**

MATERIAL DESCRIPTION: **Drywall**

MATERIAL LOCATION: **2nd Floor Boy's and Girl's Washrooms, Basement Eng. Office**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **04/14/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23391** BUIDLING ID: **3600**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Evan Christian**  
SCHOOL NAME: **Graham School** INSPECTION DATE: **3/10/2016**  
ADDRESS: **4436 S. Union** IDPH LICENSE NO: **100-19466**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **16**  
MATERIAL DESCRIPTION: **Canvas**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Classrooms**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **03/10/2016**



# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23391** BUIDLING ID: **3600**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Graham School** REVIEW DATE: **4/14/2016**  
ADDRESS: **4436 S. Union** IDPH LICENSE NO: **100-19466**

---

HOMOGENEOUS AREA: **16**

MATERIAL DESCRIPTION: **Canvas**

MATERIAL LOCATION: **Classrooms**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **04/14/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **23391**    BUIDLING ID: **3600**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Evan Christian**  
SCHOOL NAME: **Graham School**    INSPECTION DATE: **3/10/2016**  
ADDRESS: **4436 S. Union**    IDPH LICENSE NO: **100-19466**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **17**  
MATERIAL DESCRIPTION: **Window Glaze**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM**    FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Interior**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **03/10/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23391** BUIDLING ID: **3600**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Graham School** REVIEW DATE: **4/14/2016**  
ADDRESS: **4436 S. Union** IDPH LICENSE NO: **100-19466**

---

HOMOGENEOUS AREA: **17**

MATERIAL DESCRIPTION: **Window Glaze**

MATERIAL LOCATION: **Interior**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **04/14/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23391** BUIDLING ID: **3600**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Evan Christian**  
SCHOOL NAME: **Graham School** INSPECTION DATE: **3/10/2016**  
ADDRESS: **4436 S. Union** IDPH LICENSE NO: **100-19466**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **18**  
MATERIAL DESCRIPTION: **Glazed Brick**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Entrances to Building, Girl's and Boy's Washrooms**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 03/10/2016

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23391** BUIDLING ID: **3600**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Graham School** REVIEW DATE: **4/14/2016**  
ADDRESS: **4436 S. Union** IDPH LICENSE NO: **100-19466**

---

HOMOGENEOUS AREA: **18**

MATERIAL DESCRIPTION: **Glazed Brick**

MATERIAL LOCATION: **Entrances to Building, Girl's and Boy's Washrooms**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **04/14/2016** \_\_\_\_\_

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23391** BUIDLING ID: **3600**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Evan Christian**  
SCHOOL NAME: **Graham School** INSPECTION DATE: **3/10/2016**  
ADDRESS: **4436 S. Union** IDPH LICENSE NO: **100-19466**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **19**  
MATERIAL DESCRIPTION: **Glazed Brick Mortar**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Entrances to Building, Girl's and Boy's Washrooms**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 03/10/2016

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23391** BUIDLING ID: **3600**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Graham School** REVIEW DATE: **4/14/2016**  
ADDRESS: **4436 S. Union** IDPH LICENSE NO: **100-19466**

---

HOMOGENEOUS AREA: **19**

MATERIAL DESCRIPTION: **Glazed Brick Mortar**

MATERIAL LOCATION: **Entrances to Building, Girl's and Boy's Washrooms**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **04/14/2016** \_\_\_\_\_

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23391** BUIDLING ID: **3600**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Evan Christian**  
SCHOOL NAME: **Graham School** INSPECTION DATE: **3/10/2016**  
ADDRESS: **4436 S. Union** IDPH LICENSE NO: **100-19466**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **2**  
MATERIAL DESCRIPTION: **1x1 Acoustical Ceiling Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Gym**

MATERIAL QUANTITY: **200**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_

Date: 03/10/2016



# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23391** BUIDLING ID: **3600**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Graham School** REVIEW DATE: **4/14/2016**  
ADDRESS: **4436 S. Union** IDPH LICENSE NO: **100-19466**

---

HOMOGENEOUS AREA: **2**  
MATERIAL DESCRIPTION: **1x1 Acoustical Ceiling Tile**  
MATERIAL LOCATION: **Gym**  
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **04/14/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23391** BUIDLING ID: **3600**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Evan Christian**  
SCHOOL NAME: **Graham School** INSPECTION DATE: **3/10/2016**  
ADDRESS: **4436 S. Union** IDPH LICENSE NO: **100-19466**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **20**  
MATERIAL DESCRIPTION: **Yellow Brick**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Exterior**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **03/10/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23391** BUIDLING ID: **3600**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Graham School** REVIEW DATE: **4/14/2016**  
ADDRESS: **4436 S. Union** IDPH LICENSE NO: **100-19466**

---

HOMOGENEOUS AREA: **20**

MATERIAL DESCRIPTION: **Yellow Brick**

MATERIAL LOCATION: **Exterior**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **04/14/2016** \_\_\_\_\_

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **23391**    BUILDING ID: **3600**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Evan Christian**  
SCHOOL NAME: **Graham School**    INSPECTION DATE: **3/10/2016**  
ADDRESS: **4436 S. Union**    IDPH LICENSE NO: **100-19466**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **21**  
MATERIAL DESCRIPTION: **Brick Mortar**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM**    FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Exterior**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **03/10/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23391** BUIDLING ID: **3600**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Graham School** REVIEW DATE: **4/14/2016**  
ADDRESS: **4436 S. Union** IDPH LICENSE NO: **100-19466**

---

HOMOGENEOUS AREA: **21**

MATERIAL DESCRIPTION: **Brick Mortar**

MATERIAL LOCATION: **Exterior**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **04/14/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23391** BUIDLING ID: **3600**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Evan Christian**  
SCHOOL NAME: **Graham School** INSPECTION DATE: **3/10/2016**  
ADDRESS: **4436 S. Union** IDPH LICENSE NO: **100-19466**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **22**  
MATERIAL DESCRIPTION: **Green Layer Under 9x9 VFT**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Chrysotile** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **2nd Floor Teacher's Washroom**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed 2016**

Inspector's Signature: \_\_\_\_\_ Date: **03/10/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23391** BUIDLING ID: **3600**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Graham School** REVIEW DATE: **4/14/2016**  
ADDRESS: **4436 S. Union** IDPH LICENSE NO: **100-19466**

---

HOMOGENEOUS AREA: **22**

MATERIAL DESCRIPTION: **Green Layer Under 9x9 VFT**

MATERIAL LOCATION: **2nd Floor Teacher's Washroom**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

material not observed in 2016

Management Planner's Signature: \_\_\_\_\_



Date: **04/14/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23391** BUIDLING ID: **3600**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Evan Christian**  
SCHOOL NAME: **Graham School** INSPECTION DATE: **3/10/2016**  
ADDRESS: **4436 S. Union** IDPH LICENSE NO: **100-19466**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **23**  
MATERIAL DESCRIPTION: **Drywall Tape Compound**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Basement Storage Room, Boy's and Girl's Washrooms**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 03/10/2016



# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23391** BUIDLING ID: **3600**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Graham School** REVIEW DATE: **4/14/2016**  
ADDRESS: **4436 S. Union** IDPH LICENSE NO: **100-19466**

---

HOMOGENEOUS AREA: **23**

MATERIAL DESCRIPTION: **Drywall Tape Compound**

MATERIAL LOCATION: **Basement Storage Room, Boy's and Girl's Washrooms**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **04/14/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23391** BUIDLING ID: **3600**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Evan Christian**  
SCHOOL NAME: **Graham School** INSPECTION DATE: **3/10/2016**  
ADDRESS: **4436 S. Union** IDPH LICENSE NO: **100-19466**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **24**  
MATERIAL DESCRIPTION: **Blue/Green Carpet Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Main Office**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed 2016**

Inspector's Signature: \_\_\_\_\_

Date: 03/10/2016

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23391** BUIDLING ID: **3600**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Graham School** REVIEW DATE: **4/14/2016**  
ADDRESS: **4436 S. Union** IDPH LICENSE NO: **100-19466**

---

HOMOGENEOUS AREA: **24**

MATERIAL DESCRIPTION: **Blue/Green Carpet Mastic**

MATERIAL LOCATION: **Main Office**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

material not observed in 2016

Management Planner's Signature: \_\_\_\_\_



Date: **04/14/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23391** BUIDLING ID: **3600**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Evan Christian**  
SCHOOL NAME: **Graham School** INSPECTION DATE: **3/10/2016**  
ADDRESS: **4436 S. Union** IDPH LICENSE NO: **100-19466**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **25**  
MATERIAL DESCRIPTION: **12" x 12" White w/Lt. Blue Specks FT**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Main Office**

MATERIAL QUANTITY: **150**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_

Date: 03/10/2016

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23391** BUIDLING ID: **3600**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Graham School** REVIEW DATE: **4/14/2016**  
ADDRESS: **4436 S. Union** IDPH LICENSE NO: **100-19466**

---

HOMOGENEOUS AREA: **25**

MATERIAL DESCRIPTION: **12" x 12" White w/Lt. Blue Specks FT**

MATERIAL LOCATION: **Main Office**

MATERIAL QUANTITY: **150**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **04/14/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23391** BUIDLING ID: **3600**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Evan Christian**  
SCHOOL NAME: **Graham School** INSPECTION DATE: **3/10/2016**  
ADDRESS: **4436 S. Union** IDPH LICENSE NO: **100-19466**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **26**  
MATERIAL DESCRIPTION: **12" x 12" White w/Lt. Blue Specks FT Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Main Office**

MATERIAL QUANTITY: **150**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_

Date: 03/10/2016

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23391** BUIDLING ID: **3600**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Graham School** REVIEW DATE: **4/14/2016**  
ADDRESS: **4436 S. Union** IDPH LICENSE NO: **100-19466**

---

HOMOGENEOUS AREA: **26**  
MATERIAL DESCRIPTION: **12" x 12" White w/Lt. Blue Specks FT Mastic**  
MATERIAL LOCATION: **Main Office**  
MATERIAL QUANTITY: **150** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **04/14/2016**

# Chicago Public Schools

## Carnow, Conibear and Associates 2016 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **23391**    BUIDLING ID: **3600**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Evan Christian**  
SCHOOL NAME: **Graham School**    INSPECTION DATE: **3/10/2016**  
ADDRESS: **4436 S. Union**    IDPH LICENSE NO: **100-19466**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **27**  
MATERIAL DESCRIPTION: **12" x 12" Beige w/Gray & Brown Streaks FT**  
HISTORICAL AHERA DAMAGE CATEGORY: **ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed**    FRIABLE:

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Trailer Pod - torn down**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_

Date: 03/10/2016



# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23391** BUIDLING ID: **3600**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Graham School** REVIEW DATE: **4/14/2016**  
ADDRESS: **4436 S. Union** IDPH LICENSE NO: **100-19466**

---

HOMOGENEOUS AREA: **27**

MATERIAL DESCRIPTION: **12" x 12" Beige w/Gray & Brown Streaks FT**

MATERIAL LOCATION: **Trailer Pod - torn down**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **04/14/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23391** BUIDLING ID: **3600**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Evan Christian**  
SCHOOL NAME: **Graham School** INSPECTION DATE: **3/10/2016**  
ADDRESS: **4436 S. Union** IDPH LICENSE NO: **100-19466**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **28**  
MATERIAL DESCRIPTION: **12" x 12" Beige w/Gray & Brown Streaks FT Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Trailer Pod - torn down**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed 2016**

Inspector's Signature: \_\_\_\_\_

Date: 03/10/2016

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23391** BUIDLING ID: **3600**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Graham School** REVIEW DATE: **4/14/2016**  
ADDRESS: **4436 S. Union** IDPH LICENSE NO: **100-19466**

---

HOMOGENEOUS AREA: **28**

MATERIAL DESCRIPTION: **12" x 12" Beige w/Gray & Brown Streaks FT Mastic**

MATERIAL LOCATION: **Trailer Pod - torn down**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

material not observed in 2016

Management Planner's Signature: \_\_\_\_\_



Date: **04/14/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23391** BUIDLING ID: **3600**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Evan Christian**  
SCHOOL NAME: **Graham School** INSPECTION DATE: **3/10/2016**  
ADDRESS: **4436 S. Union** IDPH LICENSE NO: **100-19466**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **29**  
MATERIAL DESCRIPTION: **Incinerator Lining**  
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Coal Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed 2016**

Inspector's Signature: \_\_\_\_\_

Date: 03/10/2016

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23391** BUIDLING ID: **3600**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Graham School** REVIEW DATE: **4/14/2016**  
ADDRESS: **4436 S. Union** IDPH LICENSE NO: **100-19466**

---

HOMOGENEOUS AREA: **29**

MATERIAL DESCRIPTION: **Incinerator Lining**

MATERIAL LOCATION: **Coal Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

material not observed in 2016

Management Planner's Signature: \_\_\_\_\_



Date: **04/14/2016**

# Chicago Public Schools

## Carnow, Conibear and Associates 2016 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **23391**    BUIDLING ID: **3600**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Evan Christian**  
SCHOOL NAME: **Graham School**    INSPECTION DATE: **3/10/2016**  
ADDRESS: **4436 S. Union**    IDPH LICENSE NO: **100-19466**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **30**  
MATERIAL DESCRIPTION: **Chalkboards**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed**    FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Room 101-104, 106-108, 201-209, 301-309**  
MATERIAL QUANTITY: **2700**    MATERIAL UNITS: **SF**  
DAMAGE QUANTITY:    DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 03/10/2016

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23391** BUIDLING ID: **3600**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Graham School** REVIEW DATE: **4/14/2016**  
ADDRESS: **4436 S. Union** IDPH LICENSE NO: **100-19466**

---

HOMOGENEOUS AREA: **30**  
MATERIAL DESCRIPTION: **Chalkboards**  
MATERIAL LOCATION: **Room 101-104, 106-108, 201-209, 301-309**  
MATERIAL QUANTITY: **2700** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **04/14/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23391** BUIDLING ID: **3600**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Evan Christian**  
SCHOOL NAME: **Graham School** INSPECTION DATE: **3/10/2016**  
ADDRESS: **4436 S. Union** IDPH LICENSE NO: **100-19466**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **31**  
MATERIAL DESCRIPTION: **12x12 Beige Speckled Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Room 109 Coatroom & 209 Coatroom**

MATERIAL QUANTITY: **550**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_

Date: 03/10/2016



# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23391** BUIDLING ID: **3600**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Graham School** REVIEW DATE: **4/14/2016**  
ADDRESS: **4436 S. Union** IDPH LICENSE NO: **100-19466**

---

HOMOGENEOUS AREA: **31**  
MATERIAL DESCRIPTION: **12x12 Beige Speckled Floor Tile**  
MATERIAL LOCATION: **Room 109 Coatroom & 209 Coatroom**  
MATERIAL QUANTITY: **550** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **04/14/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23391** BUIDLING ID: **3600**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Evan Christian**  
SCHOOL NAME: **Graham School** INSPECTION DATE: **3/10/2016**  
ADDRESS: **4436 S. Union** IDPH LICENSE NO: **100-19466**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **32**  
MATERIAL DESCRIPTION: **Mastic associated with 12x12 Beige Speckled FT**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Room 109 Coatroom & 209 Coatroom**

MATERIAL QUANTITY: **550**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_

Date: 03/10/2016

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23391** BUIDLING ID: **3600**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Graham School** REVIEW DATE: **4/14/2016**  
ADDRESS: **4436 S. Union** IDPH LICENSE NO: **100-19466**

---

HOMOGENEOUS AREA: **32**  
MATERIAL DESCRIPTION: **Mastic associated with 12x12 Beige Speckled FT**  
MATERIAL LOCATION: **Room 109 Coatroom & 209 Coatroom**  
MATERIAL QUANTITY: **550** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **04/14/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23391** BUIDLING ID: **3600**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Evan Christian**  
SCHOOL NAME: **Graham School** INSPECTION DATE: **3/10/2016**  
ADDRESS: **4436 S. Union** IDPH LICENSE NO: **100-19466**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **33**  
MATERIAL DESCRIPTION: **9x9 Dark Brown with white/red streaks FT**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1st Floor Corridor**  
MATERIAL QUANTITY: **2200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 03/10/2016

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23391** BUIDLING ID: **3600**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Graham School** REVIEW DATE: **4/14/2016**  
ADDRESS: **4436 S. Union** IDPH LICENSE NO: **100-19466**

---

HOMOGENEOUS AREA: **33**  
MATERIAL DESCRIPTION: **9x9 Dark Brown with white/red streaks FT**  
MATERIAL LOCATION: **1st Floor Corridor**  
MATERIAL QUANTITY: **2200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **04/14/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23391** BUIDLING ID: **3600**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Evan Christian**  
SCHOOL NAME: **Graham School** INSPECTION DATE: **3/10/2016**  
ADDRESS: **4436 S. Union** IDPH LICENSE NO: **100-19466**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **34**  
MATERIAL DESCRIPTION: **Mastic on 9x9 Dark Brown with white/red streaks FT**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1st Floor Corridor**  
MATERIAL QUANTITY: **2200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 03/10/2016

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23391** BUIDLING ID: **3600**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Graham School** REVIEW DATE: **4/14/2016**  
ADDRESS: **4436 S. Union** IDPH LICENSE NO: **100-19466**

---

HOMOGENEOUS AREA: **34**

MATERIAL DESCRIPTION: **Mastic on 9x9 Dark Brown with white/red streaks FT**

MATERIAL LOCATION: **1st Floor Corridor**

MATERIAL QUANTITY: **2200**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **04/14/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23391** BUIDLING ID: **3600**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Evan Christian**  
SCHOOL NAME: **Graham School** INSPECTION DATE: **3/10/2016**  
ADDRESS: **4436 S. Union** IDPH LICENSE NO: **100-19466**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **35**  
MATERIAL DESCRIPTION: **9x9 Light Brown w/white & Brown FT**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Rm104, 202, 203,204, 209, and 301, 1st Floor Corridor**  
MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 03/10/2016



# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23391** BUIDLING ID: **3600**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Graham School** REVIEW DATE: **4/14/2016**  
ADDRESS: **4436 S. Union** IDPH LICENSE NO: **100-19466**

---

HOMOGENEOUS AREA: **35**  
MATERIAL DESCRIPTION: **9x9 Light Brown w/white & Brown FT**  
MATERIAL LOCATION: **Rm104, 202, 203,204, 209, and 301, 1st Floor Corridor**  
MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **04/14/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23391** BUIDLING ID: **3600**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Evan Christian**  
SCHOOL NAME: **Graham School** INSPECTION DATE: **3/10/2016**  
ADDRESS: **4436 S. Union** IDPH LICENSE NO: **100-19466**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **36**  
MATERIAL DESCRIPTION: **9x9 Lt Gray floor tile w/red& gray specks**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Principals office & platform**

MATERIAL QUANTITY: **430**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 03/10/2016

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23391** BUIDLING ID: **3600**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Graham School** REVIEW DATE: **4/14/2016**  
ADDRESS: **4436 S. Union** IDPH LICENSE NO: **100-19466**

---

HOMOGENEOUS AREA: **36**

MATERIAL DESCRIPTION: **9x9 Lt Gray floor tile w/red& gray specks**

MATERIAL LOCATION: **Principals office & platform**

MATERIAL QUANTITY: **430**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **04/14/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23391** BUIDLING ID: **3600**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Evan Christian**  
SCHOOL NAME: **Graham School** INSPECTION DATE: **3/10/2016**  
ADDRESS: **4436 S. Union** IDPH LICENSE NO: **100-19466**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **37**  
MATERIAL DESCRIPTION: **9x9 Lt Gray floor tile w/red& gray specks Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Principals Office & platform**

MATERIAL QUANTITY: **430**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_

Date: 03/10/2016

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23391** BUIDLING ID: **3600**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Graham School** REVIEW DATE: **4/14/2016**  
ADDRESS: **4436 S. Union** IDPH LICENSE NO: **100-19466**

---

HOMOGENEOUS AREA: **37**  
MATERIAL DESCRIPTION: **9x9 Lt Gray floor tile w/red& gray specks Mastic**  
MATERIAL LOCATION: **Principals Office & platform**  
MATERIAL QUANTITY: **430** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **04/14/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23391** BUIDLING ID: **3600**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Evan Christian**  
SCHOOL NAME: **Graham School** INSPECTION DATE: **3/10/2016**  
ADDRESS: **4436 S. Union** IDPH LICENSE NO: **100-19466**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **38**  
MATERIAL DESCRIPTION: **12" x 12" Brown VFT**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1st Floor Corridor**  
MATERIAL QUANTITY: **24** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 03/10/2016

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23391** BUIDLING ID: **3600**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Graham School** REVIEW DATE: **4/14/2016**  
ADDRESS: **4436 S. Union** IDPH LICENSE NO: **100-19466**

---

HOMOGENEOUS AREA: **38**  
MATERIAL DESCRIPTION: **12" x 12" Brown VFT**  
MATERIAL LOCATION: **1st Floor Corridor**  
MATERIAL QUANTITY: **24** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **04/14/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23391** BUIDLING ID: **3600**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Evan Christian**  
SCHOOL NAME: **Graham School** INSPECTION DATE: **3/10/2016**  
ADDRESS: **4436 S. Union** IDPH LICENSE NO: **100-19466**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **39**  
MATERIAL DESCRIPTION: **12" x 12" Brown VFT Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **1st Floor Corridor**

MATERIAL QUANTITY: **24**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 03/10/2016



# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23391** BUIDLING ID: **3600**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Graham School** REVIEW DATE: **4/14/2016**  
ADDRESS: **4436 S. Union** IDPH LICENSE NO: **100-19466**

---

HOMOGENEOUS AREA: **39**  
MATERIAL DESCRIPTION: **12" x 12" Brown VFT Mastic**  
MATERIAL LOCATION: **1st Floor Corridor**  
MATERIAL QUANTITY: **24** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **04/14/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23391** BUIDLING ID: **3600**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Evan Christian**  
SCHOOL NAME: **Graham School** INSPECTION DATE: **3/10/2016**  
ADDRESS: **4436 S. Union** IDPH LICENSE NO: **100-19466**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **4.1**  
MATERIAL DESCRIPTION: **2x4 White Ceiling Tile, Type 1**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 106 & 301**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **03/10/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23391** BUIDLING ID: **3600**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Graham School** REVIEW DATE: **4/14/2016**  
ADDRESS: **4436 S. Union** IDPH LICENSE NO: **100-19466**

---

HOMOGENEOUS AREA: **4.1**

MATERIAL DESCRIPTION: **2x4 White Ceiling Tile, Type 1**

MATERIAL LOCATION: **Room 106 & 301**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **04/14/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23391** BUIDLING ID: **3600**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Evan Christian**  
SCHOOL NAME: **Graham School** INSPECTION DATE: **3/10/2016**  
ADDRESS: **4436 S. Union** IDPH LICENSE NO: **100-19466**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **4.2**  
MATERIAL DESCRIPTION: **2x4 White Ceiling Tile, Type 2**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Rooms 101, 107, 205, Various Others**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **03/10/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23391** BUIDLING ID: **3600**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Graham School** REVIEW DATE: **4/14/2016**  
ADDRESS: **4436 S. Union** IDPH LICENSE NO: **100-19466**

---

HOMOGENEOUS AREA: **4.2**

MATERIAL DESCRIPTION: **2x4 White Ceiling Tile, Type 2**

MATERIAL LOCATION: **Rooms 101, 107, 205, Various Others**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **04/14/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23391** BUIDLING ID: **3600**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Evan Christian**  
SCHOOL NAME: **Graham School** INSPECTION DATE: **3/10/2016**  
ADDRESS: **4436 S. Union** IDPH LICENSE NO: **100-19466**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **9.1**  
MATERIAL DESCRIPTION: **9x9 VFT, Brown w/White and Brown Streaks**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Rm104, 202, 203,204, 209, and 301**

MATERIAL QUANTITY: **7200**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_

Date: 03/10/2016

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23391** BUIDLING ID: **3600**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Graham School** REVIEW DATE: **4/14/2016**  
ADDRESS: **4436 S. Union** IDPH LICENSE NO: **100-19466**

---

HOMOGENEOUS AREA: **9.1**  
MATERIAL DESCRIPTION: **9x9 VFT, Brown w/White and Brown Streaks**  
MATERIAL LOCATION: **Rm104, 202, 203,204, 209, and 301**  
MATERIAL QUANTITY: **7200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **04/14/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23391** BUIDLING ID: **3600**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Evan Christian**  
SCHOOL NAME: **Graham School** INSPECTION DATE: **3/10/2016**  
ADDRESS: **4436 S. Union** IDPH LICENSE NO: **100-19466**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **9.2**  
MATERIAL DESCRIPTION: **9x9 VFT, White w/Brown, Pink, and Gray Grains**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **3rd Floor Teacher's Washrooms**  
MATERIAL QUANTITY: **10** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 03/10/2016



# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23391** BUIDLING ID: **3600**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Graham School** REVIEW DATE: **4/14/2016**  
ADDRESS: **4436 S. Union** IDPH LICENSE NO: **100-19466**

---

HOMOGENEOUS AREA: **9.2**  
MATERIAL DESCRIPTION: **9x9 VFT, White w/Brown, Pink, and Gray Grains**  
MATERIAL LOCATION: **3rd Floor Teacher's Washrooms**  
MATERIAL QUANTITY: **10** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **04/14/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23391** BUIDLING ID: **3600**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Evan Christian**  
SCHOOL NAME: **Graham School** INSPECTION DATE: **3/10/2016**  
ADDRESS: **4436 S. Union** IDPH LICENSE NO: **100-19466**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **9.3**  
MATERIAL DESCRIPTION: **9x9 VFT, Off-White w/Brown and Gray Streaks**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Basement Teacher's Lunchroom**

MATERIAL QUANTITY: **800**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_

Date: 03/10/2016

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23391** BUIDLING ID: **3600**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Graham School** REVIEW DATE: **4/14/2016**  
ADDRESS: **4436 S. Union** IDPH LICENSE NO: **100-19466**

---

HOMOGENEOUS AREA: **9.3**  
MATERIAL DESCRIPTION: **9x9 VFT, Off-White w/Brown and Gray Streaks**  
MATERIAL LOCATION: **Basement Teacher's Lunchroom**  
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **04/14/2016**

# Chicago Public Schools

## Carnow, Conibear and Associates 2016 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23391** BUIDLING ID: **3600**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Evan Christian**  
SCHOOL NAME: **Graham School** INSPECTION DATE: **3/10/2016**  
ADDRESS: **4436 S. Union** IDPH LICENSE NO: **100-19466**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **9.4**  
MATERIAL DESCRIPTION: **9x9 Red Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Basement Storage Room**  
MATERIAL QUANTITY: **250** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 03/10/2016

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23391** BUIDLING ID: **3600**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Graham School** REVIEW DATE: **4/14/2016**  
ADDRESS: **4436 S. Union** IDPH LICENSE NO: **100-19466**

---

HOMOGENEOUS AREA: **9.4**  
MATERIAL DESCRIPTION: **9x9 Red Floor Tile**  
MATERIAL LOCATION: **Basement Storage Room**  
MATERIAL QUANTITY: **250** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **04/14/2016**

# Chicago Public Schools

## Carnow, Conibear and Associates 2016 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23391** BUIDLING ID: **3600**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Evan Christian**  
SCHOOL NAME: **Graham School** INSPECTION DATE: **3/10/2016**  
ADDRESS: **4436 S. Union** IDPH LICENSE NO: **100-19466**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **A**  
MATERIAL DESCRIPTION: **Boilers Insulation (2)**  
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY: **650**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_

Date: 03/10/2016

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23391** BUIDLING ID: **3600**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Graham School** REVIEW DATE: **4/14/2016**  
ADDRESS: **4436 S. Union** IDPH LICENSE NO: **100-19466**

---

HOMOGENEOUS AREA: **A**  
MATERIAL DESCRIPTION: **Boilers Insulation (2)**  
MATERIAL LOCATION: **Boiler Room**  
MATERIAL QUANTITY: **650** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **04/14/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23391** BUIDLING ID: **3600**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Evan Christian**  
SCHOOL NAME: **Graham School** INSPECTION DATE: **3/10/2016**  
ADDRESS: **4436 S. Union** IDPH LICENSE NO: **100-19466**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **B**  
MATERIAL DESCRIPTION: **Fittings on Fiberglass Insulation**  
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Throughout Basement, Room 106, 208, 209,306, 308, 2nd floor Boys+Girls Restrooms**  
MATERIAL QUANTITY: **240** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 03/10/2016



# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23391** BUIDLING ID: **3600**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Graham School** REVIEW DATE: **4/14/2016**  
ADDRESS: **4436 S. Union** IDPH LICENSE NO: **100-19466**

---

HOMOGENEOUS AREA: **B**  
MATERIAL DESCRIPTION: **Fittings on Fiberglass Insulation**  
MATERIAL LOCATION: **Throughout Basement, Room 106, 208, 209,306, 308, 2nd floor Boys+Girls Restrooms**  
MATERIAL QUANTITY: **240** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **04/14/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23391** BUIDLING ID: **3600**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Evan Christian**  
SCHOOL NAME: **Graham School** INSPECTION DATE: **3/10/2016**  
ADDRESS: **4436 S. Union** IDPH LICENSE NO: **100-19466**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **D1**  
MATERIAL DESCRIPTION: **Paperwrap Pipe Insulation Fittings**  
HISTORICAL AHERA DAMAGE CATEGORY **1 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **1. Damaged or significantly damaged friable thermal system insulating ACBM**

DAMAGE REASON: **Deterioration**  
DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **Throughout Basement**  
MATERIAL QUANTITY: **120** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: DAMAGE UNITS: **LF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 03/10/2016

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23391** BUIDLING ID: **3600**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Graham School** REVIEW DATE: **4/14/2016**  
ADDRESS: **4436 S. Union** IDPH LICENSE NO: **100-19466**

---

HOMOGENEOUS AREA: **D1**  
MATERIAL DESCRIPTION: **Paperwrap Pipe Insulation Fittings**  
MATERIAL LOCATION: **Throughout Basement**  
MATERIAL QUANTITY: **120** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **2** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Remove/Repair Material. Follow O&M procedures after response action

Management Planner's Signature: \_\_\_\_\_



Date: **04/14/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23391** BUIDLING ID: **3600**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Evan Christian**  
SCHOOL NAME: **Graham School** INSPECTION DATE: **3/10/2016**  
ADDRESS: **4436 S. Union** IDPH LICENSE NO: **100-19466**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **D2**  
MATERIAL DESCRIPTION: **Aircell Pipe Insulation Fittings**  
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout Basement**

MATERIAL QUANTITY: **200** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 03/10/2016

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23391** BUIDLING ID: **3600**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Graham School** REVIEW DATE: **4/14/2016**  
ADDRESS: **4436 S. Union** IDPH LICENSE NO: **100-19466**

---

HOMOGENEOUS AREA: **D2**  
MATERIAL DESCRIPTION: **Aircell Pipe Insulation Fittings**  
MATERIAL LOCATION: **Throughout Basement**  
MATERIAL QUANTITY: **200** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **04/14/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23391** BUIDLING ID: **3600**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Evan Christian**  
SCHOOL NAME: **Graham School** INSPECTION DATE: **3/10/2016**  
ADDRESS: **4436 S. Union** IDPH LICENSE NO: **100-19466**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **E**  
MATERIAL DESCRIPTION: **Preformed Pipe Wrap**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Chrysotile** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Basement North Corridor**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **not observed 2016**

Inspector's Signature: \_\_\_\_\_ Date: **03/10/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23391** BUIDLING ID: **3600**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Graham School** REVIEW DATE: **4/14/2016**  
ADDRESS: **4436 S. Union** IDPH LICENSE NO: **100-19466**

---

HOMOGENEOUS AREA: **E**

MATERIAL DESCRIPTION: **Preformed Pipe Wrap**

MATERIAL LOCATION: **Basement North Corridor**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

material not observed in 2016

Management Planner's Signature: \_\_\_\_\_



Date: **04/14/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23391** BUIDLING ID: **3600**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Evan Christian**  
SCHOOL NAME: **Graham School** INSPECTION DATE: **3/10/2016**  
ADDRESS: **4436 S. Union** IDPH LICENSE NO: **100-19466**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **F**  
MATERIAL DESCRIPTION: **Aircell Pipe Wrap**  
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Basement**

MATERIAL QUANTITY: **800**

MATERIAL UNITS: **LF**

DAMAGE QUANTITY:

DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_

Date: 03/10/2016



# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23391** BUIDLING ID: **3600**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Graham School** REVIEW DATE: **4/14/2016**  
ADDRESS: **4436 S. Union** IDPH LICENSE NO: **100-19466**

---

HOMOGENEOUS AREA: **F**  
MATERIAL DESCRIPTION: **Aircell Pipe Wrap**  
MATERIAL LOCATION: **Basement**  
MATERIAL QUANTITY: **800** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **04/14/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23391** BUIDLING ID: **3600**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Evan Christian**  
SCHOOL NAME: **Graham School** INSPECTION DATE: **3/10/2016**  
ADDRESS: **4436 S. Union** IDPH LICENSE NO: **100-19466**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **G**  
MATERIAL DESCRIPTION: **Cardboard Pipe Wrap**  
HISTORICAL AHERA DAMAGE CATEGORY **1 Any remaining friable ACBM or friable suspect ACBM**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **1. Damaged or significantly damaged friable thermal system insulating ACBM**

DAMAGE REASON: **Delamination**  
DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **Throughout Basement**  
MATERIAL QUANTITY: **725** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: DAMAGE UNITS: **LF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 03/10/2016

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23391** BUIDLING ID: **3600**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Graham School** REVIEW DATE: **4/14/2016**  
ADDRESS: **4436 S. Union** IDPH LICENSE NO: **100-19466**

---

HOMOGENEOUS AREA: **G**  
MATERIAL DESCRIPTION: **Cardboard Pipe Wrap**  
MATERIAL LOCATION: **Throughout Basement**  
MATERIAL QUANTITY: **725** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **3** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Remove/Repair Material. Follow O&M procedures after response action.

Management Planner's Signature: \_\_\_\_\_



Date: 04/14/2016

# **Chicago Public Schools**

**Carnow, Conibear and Associates**

***2016 AHERA REINSPECTION***


# APPENDIX B

## Inspector and Management Planner Licenses

---

# Evan Christian

Illinois Licensed Project Manager, and Air Sampling Professional



ENDORSEMENTS	TC EXPIRES
PROJECT MANAGER AIR SAMPLING PROFESSIONAL	12/12/2015

**Alteration of this license shall result in legal action**  
This license issued under authority of the State of Illinois  
Department of Public Health  
This license is valid only when accompanied by a valid  
training course certificate.

**CARNOW  
CONIBEAR**

2015



# OCCUPATIONAL TRAINING & SUPPLY, INC.

7233 S. Adams Street ♦ Willowbrook, IL 60527 ♦ (630) 655-3900

## Asbestos Building Inspector Refresher

Occupational Training & Supply, Inc. certifies that

**Evan Christian**


has successfully completed the Asbestos Building Inspector Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency Response Act (AHERA) and TSCA Title II.

Course Date: 12/2/2015

Exam Date: 12/2/2015

Expiration Date: 12/2/2016

Certificate Number: BIR1512024159

  
Katy DeSalvo, Director

**Reliable**  
**Environmental**  
**Solutions, Inc.** **RES**

This is to certify that **Evan Christian**

*has on January 28 & 29, 2016, in Springfield, Illinois,  
completed the requirements for asbestos accreditation under Section 206 of TSCA Title II*

**Asbestos Management Planner Initial Training**

*as accredited by the State of Illinois and approved by the U.S.E.P.A. under 40 CFR 763 (AHERA)  
and passed the associated examination with a score of 70% or higher*

Course Date: January 28 & 29, 2016

Examination Date: January 29, 2016

Expiration Date: January 29, 2017

Certificate Number: MP/0103

*William S. Williams*

Training Program Manager, William S. Williams

4211 Westgate Drive, Springfield, Illinois ☐ 217.787.9800 ☐ 217.787.9801 FAX ☐ [www.ReliableEnv.com](http://www.ReliableEnv.com)



2015



# OCCUPATIONAL TRAINING & SUPPLY, INC.

7233 S. Adams Street ♦ Willowbrook, IL 60527 ♦ (630) 655-3900

## Asbestos Building Inspector Refresher

Occupational Training & Supply, Inc. certifies that

**Todd Huffer**


has successfully completed the Asbestos Building Inspector Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 12/2/2015

Exam Date: 12/2/2015


Expiration Date: 12/2/2016

Certificate Number: BIR1512024161

  
\_\_\_\_\_  
Kathy DeSalvo, Director


# Todd Huffer

Illinois Licensed Asbestos Inspector, Management Planner,  
Project Manager, and Air Sampling Professional

 **ASBESTOS  
PROFESSIONAL  
LICENSE**

ID NUMBER	ISSUED	EXPIRES
<b>100 - 09870</b>	<b>3/16/2015</b>	<b>05/15/2016</b>

**TODD T HUFFER**  
315 HATLEN COURT  
MT. PROSPECT, IL 60056



Environmental Health

ENDORSEMENTS	TC EXPIRES
INSPECTOR	12/2/2015
MANAGEMENT PLANNER	2/20/2016
PROJECT MANAGER	12/11/2015
AIR SAMPLING PROFESSIONAL	

**Alteration of this license shall result in legal action**  
This license issued under authority of the State of Illinois  
Department of Public Health  
This license is valid only when accompanied by a valid  
training course certificate.

**CARNOW  
CONIBEAR**

2016



# OCCUPATIONAL TRAINING & SUPPLY, INC.

7233 S. Adams Street ♦ Willowbrook, IL 60527 ♦ (630) 655-3900

## Asbestos Management Planner Refresher

Occupational Training & Supply, Inc. certifies that

**Todd Huffer**

has successfully completed the Asbestos Management Planner Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 1/27/2016

Exam Date: 1/27/2016

Expiration Date: 1/27/2017

Certificate Number: MPR1601270318

Kathy DeSalvo, Director

# APPENDIX C

## Laboratory Accreditations

---

# APPENDIX D

## Laboratory Results

---

# APPENDIX E

## Chain of Custody Forms

---

## Three-Year Reinspection Key to Terms

	<b>CODE</b>	<b>KEY</b>
<b>MATERIAL</b>		
	ACBM	Asbestos Containing Building Materials
<b>MATERIAL CATEGORY</b>		
	MISC	Miscellaneous
	SURF	Surfacing
	TSI	Thermal System Insulation
<b>MATERIAL UNITS</b>		
	LF	Linear Feet
	SF	Square Feet
	CF	Cubic Feet
<b>DAMAGE TYPE</b>		
	Loc	Localized
	Dist	Distributed