

**ILLINOIS DEPARTMENT OF PUBLIC HEALTH  
AHERA THREE YEAR REINSPECTION  
ASBESTOS ABATEMENT PROGRAM  
SCHOOL INFORMATION FORM**

**SECTION I**

NAME OF SCHOOL DISTRICT: CHICAGO SCHOOL DIST 299  
SCHOOL ID NUMBER: 14-016-2990-3520  
SCHOOL NAME: South Loop School Branch  
ADDRESS OF SCHOOL: 1915 South Federal Street  
CITY: Chicago, IL, 60616

DATE LAST THREE YEAR REINSPECTION WAS COMPLETED **3/13/2013**

**If the address on this form is different than the address of the building, submit a written explanation.**

---

**SECTION II** *(Please type or print)*

**PLEASE COMPLETE THE FOLLOWING FOR YOUR THREE YEAR REINSPECTION:**

DATE REINSPECTION COMPLETED: 5/20/2016 ENROLLMENT 774  
IDPH INSPECTOR LICENSE NUMBER: 100-09969  
IDPH LICENSED INSPECTOR NAME (Please Print): Dionne Carey  
IDPH MP LICENSE NUMBER: 100-09870  
IDPH LICENSED MANAGEMENT PLANNER NAME (Please Print): Todd Huffer

DESIGNATED PERSON (Please Print): Robert Christlieb PHONE: (773) 553-3197



5/20/2016

*Signature of Designated Person*

*Date*

**SECTION III**

PLEASE COMPLETE THE FOLLOWING INFORMATION FOR ANY CHANGES WITHIN THE SCHOOL DISTRICT.

School building has been sold. Date of Sale: \_\_\_\_\_

School has been closed. Date closed: \_\_\_\_\_

School building has been demolished. Date: \_\_\_\_\_

School building is asbestos free since last reinspection: \_\_\_\_\_

**Please explain in writing why the school building is now asbestos free and include the supporting documentation.**

If a new school building has been added to the district, submit either an exclusionary statement or a management plan and inspection report. Include the complete name, address and city of school building.

**Explain in writing if the address of the building is different than the address on this form:**

---

---

---

**THREE-YEAR REINSPECTION**

**CHICAGO SCHOOL DIST 299**

**South Loop School Branch**

1915 South Federal Street  
Chicago, IL, 60616

Unit: 23751  
Building ID: 3961

IDPH ID Number: 14-016-2990-3520

**REPORT DATE:**

Friday, May 20, 2016

**Prepared for:**

**Chicago Public Schools**  
**125 S. Clark Street**  
**Chicago, IL 60603**

**Prepared by:**

**Carnow, Conibear and Associates**

600 West Van Buren St., Ste 500

Phone (312) 762-2900

Fax (312) 782-5145

**DO NOT REMOVE FROM SCHOOL  
REQUIRED BY FEDERAL LAW**



## **Environmental Notification to Occupants**

To: Faculty, Staff and Parents  
From: Chicago Public Schools  
Date: March 18, 2016

RE: South Loop School Branch, Unit 23751  
1915 South Federal Street  
Chicago, IL, 60616

Dear Faculty, Staff and Parents,

This letter is to notify you that the 2016 asbestos three year re-inspection has been completed at South Loop School Branch , following the Federal Asbestos Hazard Emergency Response Act (AHERA), 40 CFR Part 763, Subpart E and is available for your review at the main office of the school.

Although asbestos-containing materials have been identified at South Loop School Branch, there is no reason to believe that any threat to the health of students or staff exists at this time. CPS will continue to carefully monitor the condition of asbestos-containing materials and if conditions warrant, all appropriate steps will be taken to maintain the health and safety of all building occupants.

If you have any questions regarding this matter or require additional information, please feel free to contact Robert Christlieb, the designated Local Education Authority's Designated Person at (773) 553-3197 .

## **Table of Contents**

- I. School and Inspection Information
- II. Executive Summary
- III. Methodology
- IV. Abatement History
- V. Reassessments and Recommendations
- VI. Conclusions

Table I: Inspector's Reinspection Findings

Table II: Management Planner's Review

### **APPENDICES:**

- Appendix A: Assessment Sheets, Drawings and Photos
- Appendix B: Inspector and Management Planner Licenses
- Appendix C: Laboratory Accreditations
- Appendix D: Laboratory Results
- Appendix E: Chain of Custody Forms

## SCHOOL AND INSPECTION INFORMATION

### 1. School Information

School: South Loop School Branch Unit: 23751 Region: 03  
Address: 1915 South Federal Street Chicago, IL, 60616  
IDPH ID: 14-016-2990-3520 Building ID: 3961  
Contact: Bulvan, William Phone: 312-217-0613

### 2. Description of Facility

Original Construction: 1986 Additional Construction:  
Total Square Footage: 13260 No of Floors: 1  
Current Occupancy: 774

### 3. LEA Designated Person

Contact: Robert Christlieb Phone: (773) 553-3197  
Address: 125 South Clark Street, 17th Floor  
Chicago, IL 60603


### 4. Managing Environmental Consultant

MEC: Carnow, Conibear and Associates  
Contact: Dan Juneau  
Address 600 West Van Buren St., Ste 500  
Phone: (312) 762-2900 Fax: (312) 782-5145

### 5. Inspector

Inspector Name: Dionne Carey


Inspector IDPH license # 100-09969

Signature:   
Date: 3/18/2016

### 6. Management Planner

Management Planner Name: Todd Huffer

Management Planner IDPH license # 100-09870

Signature:   
Date: 05/20/2016

### 7. Review Date: 05/20/2016

### 8. LEA Designated Person's Acknowledgement

The reinspection report and recommendations have been received by me and appropriate action will be taken by the School District.

Signature: 

Date: 5/20/2016

Name: Robert Christlieb

## II. EXECUTIVE SUMMARY

Carnow, Conibear and Associates was retained by the Chicago Public Schools (CPS) to perform a three-year asbestos reinspection of the South Loop School Branch. This inspection was conducted in accordance with the United States Environmental Protection Agency (USEPA) Asbestos Hazard Emergency Response Act (AHERA) part 763.92 (b), and the ongoing Operations and Maintenance Program (O&M) originally designed in the School's Asbestos Management Plan. The purpose of this three-year reinspection is to record any condition changes in the asbestos-containing building material (ACBM) in the school since the previous three-year reinspection and the six-month periodic surveillance, to identify, assess, and include any Homogeneous Areas (HA) not identified in the Management Plan, and to recommend an appropriate response action to manage asbestos.

The inspector conducted a three-year reinspection of this facility under Illinois Department of Public Health (IDPH) school reinspection requirements and AHERA, sections 763.85 and 763.88. The main building and each addition to the main building, if constructed at different dates, were inspected separately. Laboratory accreditations are included in Appendix C, laboratory results are included in Appendix D, and chain of custody forms are included in Appendix E.

Note: During previous inspections, some of the HA(s) were identified together as 9" x 9" floor tile (FT), mastics assoc. with 9" x 9" FT, 12" x 12" FT, mastics assoc. with 12" x 12" FT, pipe insulation, etc. Some of these HA(s) have been re-identified by areas that are uniform in color, texture, construction date, application date, and general appearance.

The inspector has determined the following:

A. The following HAs have changed assessment categories for Building 3961:

B. The following new homogenous areas have been identified for Building 3961:



C. This reinspection covered only physically accessible and visible areas and materials that were identified in the LEA's management plan. The following materials were concealed and/or contained in areas that were inaccessible for sampling and have been classified as Assumed:

17	Gray Linoleum
18	Gray Linoleum Adhesive
19	Drywall
20	Drywall Joint Compound
21	1'X1' Ceiling Tiles
22	12"X12" Gray w/White/Gray Floor Tile
23	12"X12" Gray w/White/Gray Floor Tile Mastic
24	Ceramic Tile Grout
25	Ceramic Tile Adhesive
26	Whiteboard ( Markerboard ) Adhesive
27	4" Gray Vinyl Baseboard
28	4" Gray Vinyl Baseboard Adhesive
29	Posterboard Adhesive

The following areas were deemed to be inaccessible:

18	Gray Linoleum Adhesive
23	12"X12" Gray w/White/Gray Floor Tile Mastic
25	Ceramic Tile Adhesive
26	Whiteboard ( Markerboard ) Adhesive
28	4" Gray Vinyl Baseboard Adhesive
29	Posterboard Adhesive

Materials were also listed as "assumed" if they were in good condition and sampling was not conducted to avoid damage.

This reinspection was conducted by Dionne Carey, IDPH License # 100-09969. The Management Plan was updated by Todd Huffer, IDPH License # 100-09870. Inspector and Management Planner Licenses are included in Appendix B.

### **III. METHODOLOGY**

Tasks performed on-site included the following:

1. Review current management plan, identify HA(s) and extract appropriate information.
2. Examine and verify abatement records.
3. Touch and visually and physically reinspect and reassess the condition of all friable known or assumed ACBM.
4. Touch and visually and physically reinspect all non-friable known or assumed ACBM to determine whether these materials have become friable since the last inspection or periodic surveillance.
5. Identify any condition changes that may affect Hazard Ranking of known ACBM or Assumed ACBM, as well as any HA(s) that have become friable since the last reinspection.
6. Collect bulk samples from each newly discovered friable HA or previously assumed and submit for laboratory analysis.
7. Tabulate reinspection findings and submit for management planner review and recommendations with appropriate response actions based on the AHERA Damage Category of the ACBM.
8. Submit reinspection findings and management planner recommendations to the LEA within thirty (30) days for inclusion into the management plan.

### **IV. ABATEMENT HISTORY**

The information collected from the existing management plan and inspection report(s) and from interviews with the school official revealed that the following asbestos abatement was conducted at the school since the previous Three year Reinspection.

Abatement Dates:

### **V. REASSESSMENTS AND RECOMMENDATIONS**

The reassessments and recommendations are summarized in Tables I and II on the following pages. Detailed Hazard Assessment Sheets and Drawings and Photos (if applicable) are included in Appendix A.

### **VI. CONCLUSIONS**

The South Loop School Branch Building 3961 Three-Year reinspection has been completed and response actions have been recommended for both friable and non-friable materials. A timely execution of the response actions recommended will enable the LEA and the Designated Person(s) to effectively manage the existing ACBM.

This three-year reinspection report should be inspected in the current Management plan at the CPS Central Office, and one (1) copy should be kept at the school for use when planning any renovation and/or demolition activities in areas where ACBM has been identified. Also, periodic surveillance documentation and any summary reports from any response actions that are executed at the school should be used to update the Management Plan.

**Table I**  
**Inspector's Reinspection Findings**

---

# Chicago Public Schools

School South Loop School Branch Unit 23751 Building ID 3961

Address 1915 South Federal Street Region 03

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
001	1'x1' White Ceiling Tile - Abated During Rehab			Throughout Building except Lunchroom, All Purpose Room and Rm 119	ABATED	MISC								
002	12x12 Beige Floor Tile - Abated During Rehab			Corridors & Lunchroom	ABATED	MISC								
003	12"x12" Beige FT Mastic - Abated During Rehab			Throughout Bldg. Lunchroom & Corridor	ABATED	MISC								
004	1'x1' Acoustical Ceiling Adhesive			Throughout Bldg. - Abated During Rehab	ABATED	MISC								
005	Drywall - Removed during rehab			Throughout Bldg.	ABATED	MISC								
006	Drywall Joint Compound - Removed during rehab			Throughout Bldg.	ABATED	MISC								
007	Vinyl Baseboard - Removed during rehab			Throughout Bldg.	ABATED	MISC								
008	Vinyl Baseboard Mastic - removed during rehab			Throughout Bldg.	ABATED	MISC								
009	Carpet Adhesive - Removed during rehab			Throughout Building	ABATED	MISC								
010	12"x12" Tan Floor Tile - Abated during rehab			Room 102 Washroom & Room 116 small area HWH	ABATED	MISC								
011	12"x12"Tan Floor Tile Mastic - Abated during rehab			Room 102 Washroom & Room 116 small area HWH	ABATED	MISC								
012	Ceramic Grout - Removed during rehab			Boys & Girls Washrooms Throughout Bldg.	ABATED	SURFACE								
013	Vinyl Base w/Carpet - Removed during rehab			Throughout various classrooms 101, 102, 103, 104, 105, 106 etc.	ABATED	MISC								
014	Vinyl Base Mastic w/Carpet - removed during rehab			Throughout various classrooms 101, 102, 103, 104, 105, 106 etc.	ABATED	MISC								
015	Roof Deck Panel - Non AHERA			Exterior - Non AHERA	ABATED	MISC								
016	Vault Door Liner - Abated during rehab			Office	ABATED	MISC								
17	Gray Linoleum	2,340	SF	APR (106) and 109	ASSUMED	MISC	N	NONE	0		No	ACBM with the		LOW

# Chicago Public Schools

School South Loop School Branch Unit 23751 Building ID 3961  
 Address 1915 South Federal Street Region 03

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
												potential for damage		
18	Gray Linoleum Adhesive	2,340	SF	APR (106) and 109	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
19	Drywall	19,115	SF	All Rooms Ceilings	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
20	Drywall Joint Compound	13,115	SF	All Rooms Ceilings	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
21	1'X1' Ceiling Tiles	8,750	SF	Corridors, Classrooms and Offices	ASSUMED	MISC	Y	NONE	0		No	ACBM with the potential for damage		LOW
22	12"X12" Gray w/White/Gray Floor Tile	10,700	SF	101 - 105, 107, Corridors, Staff Rooms, Offices, Kitchen	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
23	12"X12" Gray w/White/Gray Floor Tile Mastic	10,700	SF	101 - 105, 107, Corridors, Staff Rooms, Offices, Kitchen	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
24	Ceramic Tile Grout	350	SF	All Washrooms	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
25	Ceramic Tile Adhesive	350	SF	All Washrooms	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
26	Whiteboard ( Markerboard ) Adhesive	400	SF	101, 102, 103, 104 and 105	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
27	4" Gray Vinyl Baseboard	1,100	LF	All Rooms except Washrooms	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
28	4" Gray Vinyl Baseboard Adhesive	1,100	LF	All Rooms except Washrooms	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
29	Posterboard Adhesive	420	SF	101, 102, 103, 104, 105 and All Purpose Room	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW

# Chicago Public Schools

School South Loop School Branch Unit 23751 Building ID 3961  
Address 1915 South Federal Street Region 03

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

*Inspector's Comments are Summarized at the End of the Report*

Reinspection Date <b>3/18/2016</b>
Inspector Name <b>Dionne Carey</b>
<b>100-09969</b> <b>5/15/2017</b>
Inspector's IDPH License Number / Expiration Date

### Inspector's Comments

HA Number:	Inspector Comments:
001	
002	
003	
004	
005	
006	
007	
008	
009	
010	
011	
012	
013	
014	
015	
016	
17	
18	
19	
20	
21	
22	
23	
24	

# Chicago Public Schools

**School** South Loop School Branch **Unit** 23751 **Building ID** 3961

**Address** 1915 South Federal Street **Region** 03

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

*Inspector's Comments are Summarized at the End of the Report*

---

HA Number:	Inspector Comments:
25	
26	
27	
28	
29	

**Table II**

**Management Planner's Review**

---



# Chicago Public Schools

**School** South Loop School Branch  
**Address** 1915 South Federal Street

**Unit** 23751  
 Chicago, IL, 60616

**Building ID** 3961  
**Region** 03

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

### Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
001	1'x1' White Ceiling Tile - Abated During Rehab			Throughout Building except Lunchroom, All Purpose Room and Rm 119	Abated	MISC					
002	12x12 Beige Floor Tile - Abated During Rehab			Corridors & Lunchroom	Abated	MISC					
003	12"x12" Beige FT Mastic - Abated During Rehab			Throughout Bldg. Lunchroom & Corridor	Abated	MISC					
004	1'x1' Acoustical Ceiling Adhesive			Throughout Bldg. - Abated During Rehab	Abated	MISC					
005	Drywall - Removed during rehab			Throughout Bldg.	Abated	MISC					
006	Drywall Joint Compound - Removed during rehab			Throughout Bldg.	Abated	MISC					
007	Vinyl Baseboard - Removed during rehab			Throughout Bldg.	Abated	MISC					
008	Vinyl Baseboard Mastic - removed during rehab			Throughout Bldg.	Abated	MISC					
009	Carpet Adhesive - Removed during rehab			Throughout Building	Abated	MISC					
010	12"x12" Tan Floor Tile - Abated during rehab			Room 102 Washroom & Room 116 small area HWH	Abated	MISC					
011	12"x12"Tan Floor Tile Mastic - Abated during rehab			Room 102 Washroom & Room 116 small area HWH	Abated	MISC					
012	Ceramic Grout - Removed during rehab			Boys & Girls Washrooms Throughout Bldg.	Abated	SURFACE					
013	Vinyl Base w/Carpet - Removed during rehab			Throughout various classrooms 101, 102, 103, 104, 105, 106 etc.	Abated	MISC					
014	Vinyl Base Mastic w/Carpet - removed during rehab			Throughout various classrooms 101, 102, 103, 104, 105, 106 etc.	Abated	MISC					
015	Roof Deck Panel - Non AHERA			Exterior - Non AHERA	Abated	MISC					
016	Vault Door Liner - Abated during rehab			Office	Abated	MISC					
17	Gray Linoleum	2,340	SF	APR (106) and 109	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
18	Gray Linoleum Adhesive	2,340	SF	APR (106) and 109	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
19	Drywall	19,115	SF	All Rooms Ceilings	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
20	Drywall Joint Compound	13,115	SF	All Rooms Ceilings	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
21	1'X1' Ceiling Tiles	8,750	SF	Corridors, Classrooms and Offices	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
22	12"X12" Gray w/White/Gray Floor Tile	10,700	SF	101 - 105, 107, Corridors, Staff Rooms, Offices, Kitchen	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
23	12"X12" Gray w/White/Gray Floor Tile Mastic	10,700	SF	101 - 105, 107, Corridors, Staff Rooms, Offices, Kitchen	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
24	Ceramic Tile Grout	350	SF	All Washrooms	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
25	Ceramic Tile Adhesive	350	SF	All Washrooms	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

# Chicago Public Schools

**School** South Loop School Branch  
**Address** 1915 South Federal Street

**Unit** 23751  
 Chicago, IL, 60616

**Building ID** 3961  
**Region** 03

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

### *Management Planner's Comments Summarized at the End of the Report*

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
26	Whiteboard ( Markerboard ) Adhesive	400	SF	101, 102, 103, 104 and 105	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
27	4" Gray Vinyl Baseboard	1,100	LF	All Rooms except Washrooms	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
28	4" Gray Vinyl Baseboard Adhesive	1,100	LF	All Rooms except Washrooms	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
29	Posterboard Adhesive	420	SF	101, 102, 103, 104, 105 and All Purpose Room	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

HA Number	Management Comments
-----------	---------------------

# Chicago Public Schools

**School** South Loop School Branch  
**Address** 1915 South Federal Street

**Unit** 23751  
 Chicago, IL, 60616

**Building ID** 3961  
**Region** 03

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

### *Management Planner's Comments Summarized at the End of the Report*

Review Date	5/20/2016
Manager Planner Name	Todd Huffer
100-09870	5/15/2016
Manager IDPH License No/Expiration	

HA Number	Management Comments
001	abated
002	abated
003	Abated
004	abated
005	abated
006	abated
007	abated
008	abated
009	abated
010	abated
011	abated
012	abated
013	abated
014	abated
015	abated
016	abated
17	
18	
19	
20	
21	
22	
23	
24	
25	
26	
27	

# Chicago Public Schools

**School** South Loop School Branch

**Unit** 23751

**Building ID** 3961

**Address** 1915 South Federal Street

Chicago, IL, 60616

**Region** 03

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

### *Management Planner's Comments Summarized at the End of the Report*

HA Number	Management Comments
28	
29	

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23751** BUIDLING ID: **3961**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **South Loop School Branch** INSPECTION DATE: **3/18/2016**  
ADDRESS: **1915 South Federal Street** IDPH LICENSE NO: **100-09969**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **001**  
MATERIAL DESCRIPTION: **1'x1' White Ceiling Tile - Abated During Rehab**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout Building except Lunchroom, All Purpose Room and Rm 119**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **03/18/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23751** BUIDLING ID: **3961**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **South Loop School Branch** REVIEW DATE: **5/20/2016**  
ADDRESS: **1915 South Federal Street** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **001**  
MATERIAL DESCRIPTION: **1'x1' White Ceiling Tile - Abated During Rehab**  
MATERIAL LOCATION: **Throughout Building except Lunchroom, All Purpose Room and Rm 119**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:  
abated

Management Planner's Signature: \_\_\_\_\_



Date: 05/20/2016

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23751** BUIDLING ID: **3961**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **South Loop School Branch** INSPECTION DATE: **3/18/2016**  
ADDRESS: **1915 South Federal Street** IDPH LICENSE NO: **100-09969**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **002**  
MATERIAL DESCRIPTION: **12x12 Beige Floor Tile - Abated During Rehab**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Corridors & Lunchroom**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **03/18/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23751** BUIDLING ID: **3961**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **South Loop School Branch** REVIEW DATE: **5/20/2016**  
ADDRESS: **1915 South Federal Street** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **002**  
MATERIAL DESCRIPTION: **12x12 Beige Floor Tile - Abated During Rehab**  
MATERIAL LOCATION: **Corridors & Lunchroom**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:  
abated

Management Planner's Signature: \_\_\_\_\_



Date: 05/20/2016



# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23751** BUIDLING ID: **3961**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **South Loop School Branch** INSPECTION DATE: **3/18/2016**  
ADDRESS: **1915 South Federal Street** IDPH LICENSE NO: **100-09969**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **003**  
MATERIAL DESCRIPTION: **12"x12" Beige FT Mastic - Abated During Rehab**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout Bldg. Lunchroom & Corridor**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **03/18/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23751** BUIDLING ID: **3961**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **South Loop School Branch** REVIEW DATE: **5/20/2016**  
ADDRESS: **1915 South Federal Street** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **003**  
MATERIAL DESCRIPTION: **12"x12" Beige FT Mastic - Abated During Rehab**  
MATERIAL LOCATION: **Throughout Bldg. Lunchroom & Corridor**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:  
Abated

Management Planner's Signature: \_\_\_\_\_



Date: 05/20/2016

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23751** BUIDLING ID: **3961**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **South Loop School Branch** INSPECTION DATE: **3/18/2016**  
ADDRESS: **1915 South Federal Street** IDPH LICENSE NO: **100-09969**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **004**  
MATERIAL DESCRIPTION: **1'x1' Acoustical Ceiling Adhesive**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout Bldg. - Abated During Rehab**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **03/18/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23751** BUIDLING ID: **3961**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **South Loop School Branch** REVIEW DATE: **5/20/2016**  
ADDRESS: **1915 South Federal Street** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **004**  
MATERIAL DESCRIPTION: **1'x1' Acoustical Ceiling Adhesive**  
MATERIAL LOCATION: **Throughout Bldg. - Abated During Rehab**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:  
abated

Management Planner's Signature: \_\_\_\_\_



Date: 05/20/2016

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23751** BUIDLING ID: **3961**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **South Loop School Branch** INSPECTION DATE: **3/18/2016**  
ADDRESS: **1915 South Federal Street** IDPH LICENSE NO: **100-09969**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **005**  
MATERIAL DESCRIPTION: **Drywall - Removed during rehab**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout Bldg.**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **03/18/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23751** BUIDLING ID: **3961**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **South Loop School Branch** REVIEW DATE: **5/20/2016**  
ADDRESS: **1915 South Federal Street** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **005**  
MATERIAL DESCRIPTION: **Drywall - Removed during rehab**  
MATERIAL LOCATION: **Throughout Bldg.**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:  
abated

Management Planner's Signature: \_\_\_\_\_



Date: 05/20/2016

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23751** BUIDLING ID: **3961**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **South Loop School Branch** INSPECTION DATE: **3/18/2016**  
ADDRESS: **1915 South Federal Street** IDPH LICENSE NO: **100-09969**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **006**  
MATERIAL DESCRIPTION: **Drywall Joint Compound - Removed during rehab**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout Bldg.**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **03/18/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23751** BUIDLING ID: **3961**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **South Loop School Branch** REVIEW DATE: **5/20/2016**  
ADDRESS: **1915 South Federal Street** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **006**  
MATERIAL DESCRIPTION: **Drywall Joint Compound - Removed during rehab**  
MATERIAL LOCATION: **Throughout Bldg.**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:  
abated

Management Planner's Signature: \_\_\_\_\_



Date: 05/20/2016



# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23751** BUIDLING ID: **3961**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **South Loop School Branch** INSPECTION DATE: **3/18/2016**  
ADDRESS: **1915 South Federal Street** IDPH LICENSE NO: **100-09969**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **007**  
MATERIAL DESCRIPTION: **Vinyl Baseboard - Removed during rehab**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout Bldg.**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **03/18/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23751** BUIDLING ID: **3961**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **South Loop School Branch** REVIEW DATE: **5/20/2016**  
ADDRESS: **1915 South Federal Street** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **007**  
MATERIAL DESCRIPTION: **Vinyl Baseboard - Removed during rehab**  
MATERIAL LOCATION: **Throughout Bldg.**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:  
abated

Management Planner's Signature: \_\_\_\_\_



Date: 05/20/2016

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23751** BUIDLING ID: **3961**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **South Loop School Branch** INSPECTION DATE: **3/18/2016**  
ADDRESS: **1915 South Federal Street** IDPH LICENSE NO: **100-09969**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **008**  
MATERIAL DESCRIPTION: **Vinyl Baseboard Mastic - removed during rehab**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout Bldg.**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **03/18/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23751** BUIDLING ID: **3961**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **South Loop School Branch** REVIEW DATE: **5/20/2016**  
ADDRESS: **1915 South Federal Street** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **008**  
MATERIAL DESCRIPTION: **Vinyl Baseboard Mastic - removed during rehab**  
MATERIAL LOCATION: **Throughout Bldg.**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:  
abated

Management Planner's Signature: \_\_\_\_\_



Date: 05/20/2016

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23751** BUIDLING ID: **3961**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **South Loop School Branch** INSPECTION DATE: **3/18/2016**  
ADDRESS: **1915 South Federal Street** IDPH LICENSE NO: **100-09969**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **009**  
MATERIAL DESCRIPTION: **Carpet Adhesive - Removed during rehab**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout Building**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **03/18/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23751** BUILDING ID: **3961**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **South Loop School Branch** REVIEW DATE: **5/20/2016**  
ADDRESS: **1915 South Federal Street** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **009**  
MATERIAL DESCRIPTION: **Carpet Adhesive - Removed during rehab**  
MATERIAL LOCATION: **Throughout Building**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:  
abated

Management Planner's Signature: \_\_\_\_\_



Date: 05/20/2016

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23751** BUIDLING ID: **3961**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **South Loop School Branch** INSPECTION DATE: **3/18/2016**  
ADDRESS: **1915 South Federal Street** IDPH LICENSE NO: **100-09969**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **010**  
MATERIAL DESCRIPTION: **12"x12" Tan Floor Tile - Abated during rehab**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 102 Washroom & Room 116 small area HWH**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **03/18/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23751** BUIDLING ID: **3961**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **South Loop School Branch** REVIEW DATE: **5/20/2016**  
ADDRESS: **1915 South Federal Street** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **010**  
MATERIAL DESCRIPTION: **12"x12" Tan Floor Tile - Abated during rehab**  
MATERIAL LOCATION: **Room 102 Washroom & Room 116 small area HWH**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:  
abated

Management Planner's Signature: \_\_\_\_\_



Date: 05/20/2016



# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23751** BUIDLING ID: **3961**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **South Loop School Branch** INSPECTION DATE: **3/18/2016**  
ADDRESS: **1915 South Federal Street** IDPH LICENSE NO: **100-09969**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **011**  
MATERIAL DESCRIPTION: **12"x12"Tan Floor Tile Mastic - Abated during rehab**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 102 Washroom & Room 116 small area HWH**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **03/18/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23751** BUIDLING ID: **3961**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **South Loop School Branch** REVIEW DATE: **5/20/2016**  
ADDRESS: **1915 South Federal Street** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **011**  
MATERIAL DESCRIPTION: **12"x12"Tan Floor Tile Mastic - Abated during rehab**  
MATERIAL LOCATION: **Room 102 Washroom & Room 116 small area HWH**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:  
abated

Management Planner's Signature: \_\_\_\_\_



Date: 05/20/2016

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23751** BUIDLING ID: **3961**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **South Loop School Branch** INSPECTION DATE: **3/18/2016**  
ADDRESS: **1915 South Federal Street** IDPH LICENSE NO: **100-09969**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **012**  
MATERIAL DESCRIPTION: **Ceramic Grout - Removed during rehab**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Boys & Girls Washrooms Throughout Bldg.**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **03/18/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23751** BUILDING ID: **3961**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **South Loop School Branch** REVIEW DATE: **5/20/2016**  
ADDRESS: **1915 South Federal Street** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **012**  
MATERIAL DESCRIPTION: **Ceramic Grout - Removed during rehab**  
MATERIAL LOCATION: **Boys & Girls Washrooms Throughout Bldg.**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:  
abated

Management Planner's Signature: \_\_\_\_\_



Date: 05/20/2016

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23751** BUIDLING ID: **3961**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **South Loop School Branch** INSPECTION DATE: **3/18/2016**  
ADDRESS: **1915 South Federal Street** IDPH LICENSE NO: **100-09969**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **013**  
MATERIAL DESCRIPTION: **Vinyl Base w/Carpet - Removed during rehab**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout various classrooms 101, 102, 103, 104, 105, 106 etc.**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **03/18/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23751** BUIDLING ID: **3961**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **South Loop School Branch** REVIEW DATE: **5/20/2016**  
ADDRESS: **1915 South Federal Street** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **013**  
MATERIAL DESCRIPTION: **Vinyl Base w/Carpet - Removed during rehab**  
MATERIAL LOCATION: **Throughout various classrooms 101, 102, 103, 104, 105, 106 etc.**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:  
abated

Management Planner's Signature: \_\_\_\_\_



Date: 05/20/2016

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23751** BUIDLING ID: **3961**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **South Loop School Branch** INSPECTION DATE: **3/18/2016**  
ADDRESS: **1915 South Federal Street** IDPH LICENSE NO: **100-09969**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **014**  
MATERIAL DESCRIPTION: **Vinyl Base Mastic w/Carpet - removed during rehab**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout various classrooms 101, 102, 103, 104, 105, 106 etc.**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **03/18/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23751** BUIDLING ID: **3961**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **South Loop School Branch** REVIEW DATE: **5/20/2016**  
ADDRESS: **1915 South Federal Street** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **014**  
MATERIAL DESCRIPTION: **Vinyl Base Mastic w/Carpet - removed during rehab**  
MATERIAL LOCATION: **Throughout various classrooms 101, 102, 103, 104, 105, 106 etc.**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:  
abated

Management Planner's Signature: \_\_\_\_\_



Date: 05/20/2016



# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23751** BUIDLING ID: **3961**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **South Loop School Branch** INSPECTION DATE: **3/18/2016**  
ADDRESS: **1915 South Federal Street** IDPH LICENSE NO: **100-09969**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **015**  
MATERIAL DESCRIPTION: **Roof Deck Panel - Non AHERA**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Exterior - Non AHERA**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **03/18/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23751** BUIDLING ID: **3961**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **South Loop School Branch** REVIEW DATE: **5/20/2016**  
ADDRESS: **1915 South Federal Street** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **015**  
MATERIAL DESCRIPTION: **Roof Deck Panel - Non AHERA**  
MATERIAL LOCATION: **Exterior - Non AHERA**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:  
abated

Management Planner's Signature: \_\_\_\_\_



Date: 05/20/2016

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23751** BUIDLING ID: **3961**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **South Loop School Branch** INSPECTION DATE: **3/18/2016**  
ADDRESS: **1915 South Federal Street** IDPH LICENSE NO: **100-09969**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **016**  
MATERIAL DESCRIPTION: **Vault Door Liner - Abated during rehab**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Office**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **03/18/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23751** BUIDLING ID: **3961**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **South Loop School Branch** REVIEW DATE: **5/20/2016**  
ADDRESS: **1915 South Federal Street** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **016**  
MATERIAL DESCRIPTION: **Vault Door Liner - Abated during rehab**  
MATERIAL LOCATION: **Office**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:  
abated

Management Planner's Signature: \_\_\_\_\_



Date: 05/20/2016

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23751** BUIDLING ID: **3961**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **South Loop School Branch** INSPECTION DATE: **3/18/2016**  
ADDRESS: **1915 South Federal Street** IDPH LICENSE NO: **100-09969**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **17**  
MATERIAL DESCRIPTION: **Gray Linoleum**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **APR (106) and 109**  
MATERIAL QUANTITY: **2340** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/18/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23751** BUIDLING ID: **3961**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **South Loop School Branch** REVIEW DATE: **5/20/2016**  
ADDRESS: **1915 South Federal Street** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **17**  
MATERIAL DESCRIPTION: **Gray Linoleum**  
MATERIAL LOCATION: **APR (106) and 109**  
MATERIAL QUANTITY: **2340** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/20/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23751** BUIDLING ID: **3961**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **South Loop School Branch** INSPECTION DATE: **3/18/2016**  
ADDRESS: **1915 South Federal Street** IDPH LICENSE NO: **100-09969**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **18**  
MATERIAL DESCRIPTION: **Gray Linoleum Adhesive**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **APR (106) and 109**  
MATERIAL QUANTITY: **2340** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/18/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23751** BUIDLING ID: **3961**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **South Loop School Branch** REVIEW DATE: **5/20/2016**  
ADDRESS: **1915 South Federal Street** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **18**  
MATERIAL DESCRIPTION: **Gray Linoleum Adhesive**  
MATERIAL LOCATION: **APR (106) and 109**  
MATERIAL QUANTITY: **2340** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/20/2016**



# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23751** BUIDLING ID: **3961**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **South Loop School Branch** INSPECTION DATE: **3/18/2016**  
ADDRESS: **1915 South Federal Street** IDPH LICENSE NO: **100-09969**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **19**  
MATERIAL DESCRIPTION: **Drywall**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **All Rooms Ceilings**  
MATERIAL QUANTITY: **19115** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/18/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23751** BUILDING ID: **3961**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **South Loop School Branch** REVIEW DATE: **5/20/2016**  
ADDRESS: **1915 South Federal Street** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **19**  
MATERIAL DESCRIPTION: **Drywall**  
MATERIAL LOCATION: **All Rooms Ceilings**  
MATERIAL QUANTITY: **19115** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/20/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23751** BUIDLING ID: **3961**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **South Loop School Branch** INSPECTION DATE: **3/18/2016**  
ADDRESS: **1915 South Federal Street** IDPH LICENSE NO: **100-09969**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **20**  
MATERIAL DESCRIPTION: **Drywall Joint Compound**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **All Rooms Ceilings**  
MATERIAL QUANTITY: **13115** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/18/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23751** BUIDLING ID: **3961**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **South Loop School Branch** REVIEW DATE: **5/20/2016**  
ADDRESS: **1915 South Federal Street** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **20**  
MATERIAL DESCRIPTION: **Drywall Joint Compound**  
MATERIAL LOCATION: **All Rooms Ceilings**  
MATERIAL QUANTITY: **13115** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/20/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23751** BUIDLING ID: **3961**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **South Loop School Branch** INSPECTION DATE: **3/18/2016**  
ADDRESS: **1915 South Federal Street** IDPH LICENSE NO: **100-09969**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **21**  
MATERIAL DESCRIPTION: **1'X1' Ceiling Tiles**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Corridors, Classrooms and Offices**  
MATERIAL QUANTITY: **8750** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature:



Date: **03/18/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23751** BUIDLING ID: **3961**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **South Loop School Branch** REVIEW DATE: **5/20/2016**  
ADDRESS: **1915 South Federal Street** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **21**  
MATERIAL DESCRIPTION: **1'X1' Ceiling Tiles**  
MATERIAL LOCATION: **Corridors, Classrooms and Offices**  
MATERIAL QUANTITY: **8750** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/20/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23751** BUIDLING ID: **3961**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **South Loop School Branch** INSPECTION DATE: **3/18/2016**  
ADDRESS: **1915 South Federal Street** IDPH LICENSE NO: **100-09969**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **22**  
MATERIAL DESCRIPTION: **12"X12" Gray w/White/Gray Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **101 - 105, 107, Corridors, Staff Rooms, Offices, Kitchen**  
MATERIAL QUANTITY: **10700** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/18/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23751** BUIDLING ID: **3961**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **South Loop School Branch** REVIEW DATE: **5/20/2016**  
ADDRESS: **1915 South Federal Street** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **22**  
MATERIAL DESCRIPTION: **12"X12" Gray w/White/Gray Floor Tile**  
MATERIAL LOCATION: **101 - 105, 107, Corridors, Staff Rooms, Offices, Kitchen**  
MATERIAL QUANTITY: **10700** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/20/2016**



# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23751** BUIDLING ID: **3961**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **South Loop School Branch** INSPECTION DATE: **3/18/2016**  
ADDRESS: **1915 South Federal Street** IDPH LICENSE NO: **100-09969**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **23**  
MATERIAL DESCRIPTION: **12"X12" Gray w/White/Gray Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **101 - 105, 107, Corridors, Staff Rooms, Offices, Kitchen**  
MATERIAL QUANTITY: **10700** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/18/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23751** BUIDLING ID: **3961**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **South Loop School Branch** REVIEW DATE: **5/20/2016**  
ADDRESS: **1915 South Federal Street** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **23**  
MATERIAL DESCRIPTION: **12"X12" Gray w/White/Gray Floor Tile Mastic**  
MATERIAL LOCATION: **101 - 105, 107, Corridors, Staff Rooms, Offices, Kitchen**  
MATERIAL QUANTITY: **10700** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/20/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23751** BUIDLING ID: **3961**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **South Loop School Branch** INSPECTION DATE: **3/18/2016**  
ADDRESS: **1915 South Federal Street** IDPH LICENSE NO: **100-09969**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **24**  
MATERIAL DESCRIPTION: **Ceramic Tile Grout**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **All Washrooms**  
MATERIAL QUANTITY: **350** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/18/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23751** BUIDLING ID: **3961**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **South Loop School Branch** REVIEW DATE: **5/20/2016**  
ADDRESS: **1915 South Federal Street** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **24**  
MATERIAL DESCRIPTION: **Ceramic Tile Grout**  
MATERIAL LOCATION: **All Washrooms**  
MATERIAL QUANTITY: **350** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/20/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23751** BUIDLING ID: **3961**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **South Loop School Branch** INSPECTION DATE: **3/18/2016**  
ADDRESS: **1915 South Federal Street** IDPH LICENSE NO: **100-09969**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **25**  
MATERIAL DESCRIPTION: **Ceramic Tile Adhesive**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **All Washrooms**  
MATERIAL QUANTITY: **350** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/18/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23751** BUIDLING ID: **3961**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **South Loop School Branch** REVIEW DATE: **5/20/2016**  
ADDRESS: **1915 South Federal Street** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **25**  
MATERIAL DESCRIPTION: **Ceramic Tile Adhesive**  
MATERIAL LOCATION: **All Washrooms**  
MATERIAL QUANTITY: **350** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/20/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23751** BUIDLING ID: **3961**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **South Loop School Branch** INSPECTION DATE: **3/18/2016**  
ADDRESS: **1915 South Federal Street** IDPH LICENSE NO: **100-09969**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **26**  
MATERIAL DESCRIPTION: **Whiteboard ( Markerboard ) Adhesive**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **101, 102, 103, 104 and 105**  
MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature:



Date: **03/18/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23751** BUIDLING ID: **3961**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **South Loop School Branch** REVIEW DATE: **5/20/2016**  
ADDRESS: **1915 South Federal Street** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **26**  
MATERIAL DESCRIPTION: **Whiteboard ( Markerboard ) Adhesive**  
MATERIAL LOCATION: **101, 102, 103, 104 and 105**  
MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/20/2016**



# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23751** BUIDLING ID: **3961**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **South Loop School Branch** INSPECTION DATE: **3/18/2016**  
ADDRESS: **1915 South Federal Street** IDPH LICENSE NO: **100-09969**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **27**  
MATERIAL DESCRIPTION: **4" Gray Vinyl Baseboard**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **All Rooms except Washrooms**  
MATERIAL QUANTITY: **1100** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: DAMAGE UNITS: **LF**  
COMMENTS:

Inspector's Signature:



Date: **03/18/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23751** BUIDLING ID: **3961**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **South Loop School Branch** REVIEW DATE: **5/20/2016**  
ADDRESS: **1915 South Federal Street** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **27**  
MATERIAL DESCRIPTION: **4" Gray Vinyl Baseboard**  
MATERIAL LOCATION: **All Rooms except Washrooms**  
MATERIAL QUANTITY: **1100** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/20/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23751** BUIDLING ID: **3961**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **South Loop School Branch** INSPECTION DATE: **3/18/2016**  
ADDRESS: **1915 South Federal Street** IDPH LICENSE NO: **100-09969**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **28**  
MATERIAL DESCRIPTION: **4" Gray Vinyl Baseboard Adhesive**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **All Rooms except Washrooms**  
MATERIAL QUANTITY: **1100** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature:



Date: **03/18/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23751** BUILDING ID: **3961**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **South Loop School Branch** REVIEW DATE: **5/20/2016**  
ADDRESS: **1915 South Federal Street** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **28**  
MATERIAL DESCRIPTION: **4" Gray Vinyl Baseboard Adhesive**  
MATERIAL LOCATION: **All Rooms except Washrooms**  
MATERIAL QUANTITY: **1100** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/20/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23751** BUIDLING ID: **3961**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Dionne Carey**  
SCHOOL NAME: **South Loop School Branch** INSPECTION DATE: **3/18/2016**  
ADDRESS: **1915 South Federal Street** IDPH LICENSE NO: **100-09969**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **29**  
MATERIAL DESCRIPTION: **Posterboard Adhesive**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **101, 102, 103, 104, 105 and All Purpose Room**  
MATERIAL QUANTITY: **420** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/18/2016**

# Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23751** BUIDLING ID: **3961**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **South Loop School Branch** REVIEW DATE: **5/20/2016**  
ADDRESS: **1915 South Federal Street** IDPH LICENSE NO: **100-09969**

---

HOMOGENEOUS AREA: **29**  
MATERIAL DESCRIPTION: **Posterboard Adhesive**  
MATERIAL LOCATION: **101, 102, 103, 104, 105 and All Purpose Room**  
MATERIAL QUANTITY: **420** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **05/20/2016**

# **Chicago Public Schools**

**Carnow, Conibear and Associates**

***2016 AHERA REINSPECTION***

# APPENDIX B

## Inspector and Management Planner Licenses

---



# JAINA ASSOCIATES

THIS IS TO CERTIFY

THAT

**DIONNE L. CAREY**

HAS SUCCESSFULLY COMPLETED THE SAMPLING AND EVALUATING ASBESTOS AIRBORNE DUST - NIOSH 582 EQUIVALENT TRAINING COURSE, AND PASSED THE EXAMINATION WITH A SCORE OF 70% OR ABOVE FOR THE PURPOSE OF CERTIFICATION.

COURSE DATE: May 14 to 17, 2005

EXAM DATE: May 17, 2005

LOCATION: GSG Environmental, Inc.  
855 West Adams Street, Suite 200  
Chicago, Illinois 60607

DIRECTOR  
OF TRAINING:  
  
SANJIV JAIN

CERTIFICATE No.: 05JA-051405  
IDPH COURSE PROVIDER No.: 038



525-535 West Jefferson Street • Springfield, Illinois 62761-0001 • [www.dph.illinois.gov](http://www.dph.illinois.gov)

4/18/2016

**DIONNE L CAREY WALKER**  
211 Somerset Drive  
Streamwood, IL 60107


ASBESTOS PROFESSIONAL LICENSE ID NUMBER: 09969

Enclosed is your Asbestos Professional License. Please note the expiration date on the card and in the image depicted below.

COPY OF THE ASBESTOS PROFESSIONAL LICENSE

Front of License

Back of License

ASBESTOS PROFESSIONAL LICENSE			ENDORSEMENTS	TC EXPIRES
			INSPECTOR	3/11/2017
ID NUMBER	ISSUED	EXPIRES	PROJECT MANAGER	3/12/2017
100 - 09969	4/18/2016	05/15/2017	AIR SAMPLING PROFESSIONAL	
<b>DIONNE L CAREY WALKER</b>			<b>Alteration of this license shall result in legal action</b>	
211 Somerset Drive			This license issued under authority of the State of Illinois	
Streamwood, IL 60107			Department of Public Health	
Environmental Health			This license is valid only when accompanied by a valid training course certificate.	

If you have any questions or need further assistance, contact the Asbestos Program at (217)782-3517 or fax (217)785-5897.

Our WEB address is: [dph.illinois.gov/topics-services/environmental-health-protection/asbestos](http://dph.illinois.gov/topics-services/environmental-health-protection/asbestos)  
EMAIL Address: [dph.asbestos@illinois.gov](mailto:dph.asbestos@illinois.gov)

PROTECTING HEALTH, IMPROVING LIVES  
*Nationally Accredited by PHAB*

2015



**OCCUPATIONAL TRAINING & SUPPLY, INC.**  
7233 S. Adams Street ♦ Willowbrook, IL 60527 ♦ (630) 655-3900

# Asbestos Building Inspector Refresher

Occupational Training & Supply, Inc. certifies that

**Todd Huffer**


has successfully completed the Asbestos Building Inspector Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 12/2/2015

Exam Date: 12/2/2015

Expiration Date: 12/2/2016

Certificate Number: BIR1512024161

  
\_\_\_\_\_  
Kathy DeSalvo, Director

# Todd Huffer

Illinois Licensed Asbestos Inspector, Management Planner,  
Project Manager, and Air Sampling Professional



## ASBESTOS PROFESSIONAL LICENSE

ID NUMBER ISSUED EXPIRES  
**100 - 09870** **3/16/2015** **05/15/2016**

TODD T HUFFER  
315 HATLEN COURT  
MT. PROSPECT, IL 60056

Environmental Health



### ENDORSEMENTS

### TC EXPIRES

INSPECTOR	12/2/2015
MANAGEMENT PLANNER	2/20/2016
PROJECT MANAGER	12/11/2015
AIR SAMPLING PROFESSIONAL	

**Alteration of this license shall result in legal action**  
This license issued under authority of the State of Illinois  
Department of Public Health  
This license is valid only when accompanied by a valid  
training course certificate.

**CARNOW  
CONIBEAR**

2016



# OCCUPATIONAL TRAINING & SUPPLY, INC.

7233 S. Adams Street ♦ Willowbrook, IL 60527 ♦ (630) 655-3900

## Asbestos Management Planner Refresher

Occupational Training & Supply, Inc. certifies that

**Todd Huffer**

has successfully completed the Asbestos Management Planner Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 1/27/2016

Exam Date: 1/27/2016

Expiration Date: 1/27/2017

Certificate Number: MPR1601270318

Kathy DeSalvo, Director

# APPENDIX C

## Laboratory Accreditations

---

# APPENDIX D

## Laboratory Results

---

# APPENDIX E

## Chain of Custody Forms

---



## Three-Year Reinspection Key to Terms

	<b>CODE</b>	<b>KEY</b>
<b>MATERIAL</b>		
	ACBM	Asbestos Containing Building Materials
<b>MATERIAL CATEGORY</b>		
	MISC	Miscellaneous
	SURF	Surfacing
	TSI	Thermal System Insulation
<b>MATERIAL UNITS</b>		
	LF	Linear Feet
	SF	Square Feet
	CF	Cubic Feet
<b>DAMAGE TYPE</b>		
	Loc	Localized
	Dist	Distributed