

ILLINOIS DEPARTMENT OF PUBLIC HEALTH
AHERA THREE YEAR REINSPECTION
ASBESTOS ABATEMENT PROGRAM
SCHOOL INFORMATION FORM

SECTION I

NAME OF SCHOOL DISTRICT: CHICAGO SCHOOL DIST 299
SCHOOL ID NUMBER: 14-016-2990-2316
SCHOOL NAME: Lloyd School
ADDRESS OF SCHOOL: 2103 N. Lamon Avenue
CITY: Chicago, IL, 60639

DATE LAST THREE YEAR REINSPECTION WAS COMPLETED 2/27/2013

If the address on this form is different than the address of the building, submit a written explanation.

SECTION II (Please type or print)

PLEASE COMPLETE THE FOLLOWING FOR YOUR THREE YEAR REINSPECTION:

DATE REINSPECTION COMPLETED: 8/11/2016 ENROLLMENT 1161
IDPH INSPECTOR LICENSE NUMBER: 100-19039
IDPH LICENSED INSPECTOR NAME (Please Print): Wayne Gardner
IDPH MP LICENSE NUMBER: 100-07342
IDPH LICENSED MANAGEMENT PLANNER NAME (Please Print): Jigar Shah

DESIGNATED PERSON (Please Print): Robert Christlieb PHONE: (773) 553-3197



8/11/2016

Signature of Designated Person

Date

SECTION III

PLEASE COMPLETE THE FOLLOWING INFORMATION FOR ANY CHANGES WITHIN THE SCHOOL DISTRICT.

School building has been sold. Date of Sale: _____

School has been closed. Date closed: _____

School building has been demolished. Date: _____

School building is asbestos free since last reinspection: _____

Please explain in writing why the school building is now asbestos free and include the supporting documentation.

If a new school building has been added to the district, submit either an exclusionary statement or a management plan and inspection report. Include the complete name, address and city of school building.

Explain in writing if the address of the building is different than the address on this form:

THREE-YEAR REINSPECTION

CHICAGO SCHOOL DIST 299

Lloyd School

2103 N. Lamon Avenue
Chicago, IL, 60639

Unit: 24221
Building ID: 4500

IDPH ID Number: 14-016-2990-2316

REPORT DATE:

Thursday, August 11, 2016

Prepared for:

**Chicago Public Schools
125 S. Clark Street
Chicago, IL 60603**

Prepared by:

GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone (312) 733-6262

Fax (312) 733-5612

**DO NOT REMOVE FROM SCHOOL
REQUIRED BY FEDERAL LAW**

February 18, 2016

Mr. R. Kent Cook
Asbestos Program
Illinois Department of Public Health
525 West Jefferson Street
Springfield, Illinois 62761

Re: Chicago Public Schools - 2016 Three-Year Reinspections

Dear Mr. Cook:

GSG Consultants, Inc., Managing Environmental Consultant (MEC), conducted the Three-Year Reinspections and performed management plan updates for the Chicago Public Schools (CPS) facilities in Region 1,2,6 Elementary Schools. Please update your records with the following information.

School District: 299 Unit: 24221 Region: 02 IDPH ID: 14-016-2990-2316

School: Lloyd School Building ID: 4500

Address: 2103 N. Lamon Avenue
Chicago, IL, 60639

Building Contact: Barrera, Felix Contact Phone: 773-842-9123

Current Building Owners: Chicago Public Schools

Review Date: 08/08/2016

Inspector: Wayne Gardner Inspector IDPH License: 100-19039
Management Planner: Jigar Shah Management Planner IDPH License: 100-07342

If you have any questions or comments, please contact us at (312) 733-6262

Sincerely,
GSG Consultants, Inc.



Jigar Shah
100-07342

Environmental Notification to Occupants

To: Faculty, Staff and Parents
From: Chicago Public Schools
Date: February 18, 2016

RE: Lloyd School, Unit 24221
2103 N. Lamon Avenue
Chicago, IL, 60639

Dear Faculty, Staff and Parents,

This letter is to notify you that the 2016 asbestos three year re-inspection has been completed at Lloyd School , following the Federal Asbestos Hazard Emergency Response Act (AHERA), 40 CFR Part 763, Subpart E and is available for your review at the main office of the school.

Although asbestos-containing materials have been identified at Lloyd School, there is no reason to believe that any threat to the health of students or staff exists at this time. CPS will continue to carefully monitor the condition of asbestos-containing materials and if conditions warrant, all appropriate steps will be taken to maintain the health and safety of all building occupants.

If you have any questions regarding this matter or require additional information, please feel free to contact Robert Christlieb, the designated Local Education Authority's Designated Person at (773) 553-3197 .

Table of Contents

- I. School and Inspection Information
- II. Executive Summary
- III. Methodology
- IV. Abatement History
- V. Reassessments and Recommendations
- VI. Conclusions

Table I: Inspector's Reinspection Findings

Table II: Management Planner's Review

APPENDICES:

- Appendix A: Assessment Sheets, Drawings and Photos
- Appendix B: Inspector and Management Planner Licenses
- Appendix C: Laboratory Accreditations
- Appendix D: Laboratory Results
- Appendix E: Chain of Custody Forms

SCHOOL AND INSPECTION INFORMATION

1. School Information

School: Lloyd School Unit: 24221 Region: 02
Address: 2103 N. Lamon Avenue Chicago, IL, 60639
IDPH ID: 14-016-2990-2316 Building ID: 4500
Contact: Barrera, Felix Phone: 773-842-9123

2. Description of Facility

Original Construction: 2000 Additional Construction: 1907,1913
Total Square Footage: 77200 No of Floors: 4
Current Occupancy: 1161

3. LEA Designated Person

Contact: Robert Christlieb Phone: (773) 553-3197
Address: 125 South Clark Street, 17th Floor
Chicago, IL 60603


4. Managing Environmental Consultant

MEC: GSG Consultants, Inc.
Contact: Arturo Saenz
Address 855 W. Adams St., Ste. 200
Phone: (312) 733-6262 Fax: (312) 733-5612

5. Inspector

Inspector Name: Wayne Gardner


Inspector IDPH license # 100-19039

Signature: 
Date: 2/18/2016

6. Management Planner

Management Planner Name: Jigar Shah


Management Planner IDPH license # 100-07342

Signature: 
Date: 08/08/2016

7. Review Date: 08/08/2016

8. LEA Designated Person's Acknowledgement

The reinspection report and recommendations have been received by me and appropriate action will be taken by the School District.

Signature: 

Date: 8/11/2016

Name: Robert Christlieb

II. EXECUTIVE SUMMARY

GSG Consultants, Inc. was retained by the Chicago Public Schools (CPS) to perform a three-year asbestos reinspection of the Lloyd School. This inspection was conducted in accordance with the United States Environmental Protection Agency (USEPA) Asbestos Hazard Emergency Response Act (AHERA) part 763.92 (b), and the ongoing Operations and Maintenance Program (O&M) originally designed in the School's Asbestos Management Plan. The purpose of this three-year reinspection is to record any condition changes in the asbestos-containing building material (ACBM) in the school since the previous three-year reinspection and the six-month periodic surveillance, to identify, assess, and include any Homogeneous Areas (HA) not identified in the Management Plan, and to recommend an appropriate response action to manage asbestos.

The inspector conducted a three-year reinspection of this facility under Illinois Department of Public Health (IDPH) school reinspection requirements and AHERA, sections 763.85 and 763.88. The main building and each addition to the main building, if constructed at different dates, were inspected separately. Laboratory accreditations are included in Appendix C, laboratory results are included in Appendix D, and chain of custody forms are included in Appendix E.

Note: During previous inspections, some of the HA(s) were identified together as 9" x 9" floor tile (FT), mastics assoc. with 9" x 9" FT, 12" x 12" FT, mastics assoc. with 12" x 12" FT, pipe insulation, etc. Some of these HA(s) have been re-identified by areas that are uniform in color, texture, construction date, application date, and general appearance.

The inspector has determined the following:

A. The following HAs have changed assessment categories for Building 4500:

F	Aircell Pipe Insulation
---	-------------------------

B. The following new homogenous areas have been identified for Building 4500:

46

Sheet Vinyl Flooring and Glue

C. This reinspection covered only physically accessible and visible areas and materials that were identified in the LEA's management plan. The following materials were concealed and/or contained in areas that were inaccessible for sampling and have been classified as Assumed:

05	Green Swirl Linoleum
08	Green Swirl Linoleum Mastic
10	12"x12" Tan w/ White Speckles VFT
12	Hard Coat Plaster
13	Hard Coat Plaster
14	12"x12" White w/ Brown Speckles VFT
15	12"x12" White w/ Brown Speckles VFT Mastic
16	12"x12" Gray w/ White Speckled VFT
17	12"x12" Gray w/ White Speckled VFT Mastic
26	2'x4' Groove Pattern Ceiling Tile
27	2'x4' Dot/Groove Pattern Ceiling Tile
28	2'x4' Horizontal Groove Pattern Ceiling Tile
29	2'x4' White Textured Speckled Ceiling Tile
30	2' x 4' Dot/Groove Pattern Ceiling Tile
31	12" x 12" Black with Light Grey Streaks VFT
31 A	12" x 12" Black with Light Grey Streaks VFT Mastic
32	12" x 12" Orange with White Streaks VFT
32 A	12" x 12" Orange with White Streaks VFT Mastic
33	12" x 12" Gray with Dark Gray Streaks VFT
33 A	12" x 12" Gray with Dark Gray Streaks VFT Mastic
34	Drywall
35	Drywall Joint Compound
36	Baseboard Mastic
36 A	Baseboard
37	Carpet Mastic
38	12 x 12 Maroon VFT
38A	12 x 12 Maroon VFT Mastic
39	2' x 4' Ceiling Tile with 2' x 2' Patern
40	Carpet Mastic (Red Carpet)
41	12" x 12" White with Gray Specks
42	12" x 12" White with Gray Specks Matic
43	Terrazo White with Brown Specks
44	Terrazo Gray with Black Specks
46	Sheet Vinyl Flooring and Glue
G	Fireproofing
H	Boiler Gasket

The following areas were deemed to be inaccessible:

27	2'x4' Dot/Groove Pattern Ceiling Tile
28	2'x4' Horizontal Groove Pattern Ceiling Tile
29	2'x4' White Textured Speckled Ceiling Tile
31 A	12" x 12" Black with Light Grey Streaks VFT Mastic
32 A	12" x 12" Orange with White Streaks VFT Mastic
33 A	12" x 12" Gray with Dark Gray Streaks VFT Mastic
36	Baseboard Mastic
37	Carpet Mastic
G	Fireproofing

Materials were also listed as "assumed" if they were in good condition and sampling was not conducted to avoid damage.

This reinspection was conducted by Wayne Gardner , IDPH License # 100-19039. The Management Plan was updated by Jigar Shah, IDPH License # 100-07342. Inspector and Management Planner Licenses are included in Appendix B.

III. METHODOLOGY

Tasks performed on-site included the following:

1. Review current management plan, identify HA(s) and extract appropriate information.
2. Examine and verify abatement records.
3. Touch and visually and physically reinspect and reassess the condition of all friable known or assumed ACBM.
4. Touch and visually and physically reinspect all non-friable known or assumed ACBM to determine whether these materials have become friable since the last inspection or periodic surveillance.
5. Identify any condition changes that may affect Hazard Ranking of known ACBM or Assumed ACBM, as well as any HA(s) that have become friable since the last reinspection.
6. Collect bulk samples from each newly discovered friable HA or previously assumed and submit for laboratory analysis.
7. Tabulate reinspection findings and submit for management planner review and recommendations with appropriate response actions based on the AHERA Damage Category of the ACBM.
8. Submit reinspection findings and management planner recommendations to the LEA within thirty (30) days for inclusion into the management plan.

IV. ABATEMENT HISTORY

The information collected from the existing management plan and inspection report(s) and from interviews with the school official revealed that the following asbestos abatement was conducted at the school since the previous Three year Reinspection.

Abatement Dates:

V. REASSESSMENTS AND RECOMMENDATIONS

The reassessments and recommendations are summarized in Tables I and II on the following pages. Detailed Hazard Assessment Sheets and Drawings and Photos (if applicable) are included in Appendix A.

VI. CONCLUSIONS

The Lloyd School Building 4500 Three-Year reinspection has been completed and response actions have been recommended for both friable and non-friable materials. A timely execution of the response actions recommended will enable the LEA and the Designated Person(s) to effectively manage the existing ACBM.

This three-year reinspection report should be inspected in the current Management plan at the CPS Central Office, and one (1) copy should be kept at the school for use when planning any renovation and/or demolition activities in areas where ACBM has been identified. Also, periodic surveillance documentation and any summary reports from any response actions that are executed at the school should be used to update the Management Plan.

Table I
Inspector's Reinspection Findings

Chicago Public Schools

School Lloyd School Unit 24221 Building ID 4500

Address 2103 N. Lamon Avenue Region 02

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262 Fax: (312) 733-5612

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
21	9"x9" Orange w/ White Streaks VFT Mastic (ABATED)			Room 106, 1907 (ABATED)	ABATED									
22	9"x9" Gray w/ White Streaks VFT	500	SF	Lunch Room Office, Room 310 & Wardrobe, 1913	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
23	9"x9" Gray w/ White Streaks VFT Mastic	1,250	SF	Lunch Room Office, Room 310 & Wardrobe, 1913	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
24	12"x12" Gray w/ White Speckled VFT (NOT OBSERVED)			Kitchen, Lunchroom 1913 (NOT OBSERVED)										
25	12"x12" Gray w/ White Speckled VFT Mastic - NOT OBSERVED			Kitchen, Lunchroom 1913 (NOT OBSERVED)										
26	2'x4' Groove Pattern Ceiling Tile	300	SF	2nd Floor: Boy's Toilet, Lounge, & Teacher's Toilet 1907	ASSUMED	MISC	Y	NONE	0		No	ACBM with the potential for damage		LOW
27	2'x4' Dot/Groove Pattern Ceiling Tile	50	SF	2nd Floor: Boy's Toilet, & Teacher's Lounge, Teacher's Toilet 1907	ASSUMED	MISC	Y	NONE	0		No	ACBM with the potential for damage		LOW
28	2'x4' Horizontal Groove Pattern Ceiling Tile	20	SF	2nd Floor Boy's Toilet 1907	ASSUMED	MISC	Y	NONE	0		No	ACBM with the potential for damage		LOW
29	2'x4' White Textured Speckled Ceiling Tile	80	SF	Room 004 - 1907	ASSUMED	MISC	Y	NONE	0		No	ACBM with the potential for damage		LOW
30	2' x 4' Dot/Groove Pattern Ceiling Tile	32,000	SF	Throughout, 1999 Annex	ASSUMED	MISC	Y	NONE	0		No	ACBM with the potential for damage		MODERATE
31	12" x 12" Black with Light Grey Streaks VFT	9,000	SF	Throughout, 1999 Annex	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
31 A	12" x 12" Black with Light Grey Streaks VFT Mastic	9,000	SF	Throughout, 1999 Annex	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
32	12" x 12" Orange with White Streaks VFT	2,000	SF	Throughout, 1999 Annex	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
32 A	12" x 12" Orange with White Streaks VFT Mastic	2,000	SF	Throughout, 1999 Annex	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
33	12" x 12" Gray with Dark Gray Streaks VFT	10,000	SF	Throughout, 1999 Annex	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
33 A	12" x 12" Gray with Dark Gray Streaks VFT Mastic	10,000	SF	Throughout, 1999 Annex	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
34	Drywall	1,400	SF	Room 313, 314, 315, 213, 214, 215, 2nd and 3rd Floor Boy's/Girl's/Teacher'	ASSUMED	MISC	Y	NONE	0		No	ACBM with the potential for damage		MODERATE

Chicago Public Schools

School Lloyd School Unit 24221 Building ID 4500

Address 2103 N. Lamon Avenue Region 02

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262 Fax: (312) 733-5612

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				s Toilets, 1999 Annex										
35	Drywall Joint Compound	100	LF	Room 313, 314, 315, 213, 214, 215, 2nd and 3rd Floor Boy's/Girl's/Teacher's Toilets, 1999 Annex	ASSUMED	MISC	Y	NONE	0		No	ACBM with the potential for damage		MODERATE
36	Baseboard Mastic	5,000	LF	Throughout, 1999 Annex	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
36 A	Baseboard	5,000	LF	Throughout, 1999 Annex	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
37	Carpet Mastic	3,200	SF	Room 226, 125, 125 A, 125 B, 126 A, 1999 Annex	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
38	12 x 12 Maroon VFT	750	SF	Room 106, 1907	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
38A	12 x 12 Maroon VFT Mastic	750	SF	Room 106	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
39	2' x 4' Ceiling Tile with 2' x 2' Patern	400	SF	2nd and 3rd Floor Corridors to Annex Building 1907	ASSUMED	MISC	Y	NONE	0			ACBM with the potential for damage		LOW
40	Carpet Mastic (Red Carpet)	500	SF	Auditorium - 1907	ASSUMED	MISC	Y	NONE	0			ACBM with the potential for damage		MODERATE
41	12" x 12" White with Gray Specks	1,200	SF	Room 102 & Corridor to Room 012 - 1907	ASSUMED	MISC	N	NONE	0			ACBM with the potential for damage		LOW
42	12" x 12" White with Gray Specks Matic	1,200	SF	Room 102 & Corridor to Room 102 - 1907	ASSUMED	MISC	N	NONE	0			ACBM with the potential for damage		LOW
43	Terrazo White with Brown Specks		SF	Throughout - Annex 1999	ASSUMED	MISC	N	NONE	0			ACBM with the potential for damage		LOW
44	Terrazo Gray with Black Specks		SF	Throughout - Annex 1999	ASSUMED	MISC	N	NONE	0			ACBM with the potential for damage		LOW
45	Terrazo Red with Gray Specks					MISC								
46	Sheet Vinyl Flooring and Glue	1,000	SF	Gymnasium Third Floor (1907 Bldg)	ASSUMED	MISC	N	NONE	0			ACBM with the potential for damage		LOW
F	Aircell Pipe Insulation	15	LF	Boiler Room-Toilet & Storage Room, 1907	CHR	TSI	Y	LOC	3		Yes	Damaged or significantly damaged friable thermal system insulating ACBM	3	LOW
G	Fireproofing	10,000	SF	Above Ceiling on I-Beams, 1999 Annex	ASSUMED	SURFACE	N	NONE	0		No	ACBM with the potential for damage		LOW
H	Boiler Gasket	30	LF	Boiler Room	ASSUMED	MISC	Y	NONE	0			ACBM with the		LOW

Chicago Public Schools

School Lloyd School Unit 24221 Building ID 4500

Address 2103 N. Lamon Avenue Region 02

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262 Fax: (312) 733-5612

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
												potential for damage		

Chicago Public Schools

School Lloyd School Unit 24221 Building ID 4500

Address 2103 N. Lamon Avenue Region 02

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262 Fax: (312) 733-5612

Inspector's Comments are Summarized at the End of the Report

Reinspection Date <u>2/18/2016</u>
Inspector Name <u>Wayne Gardner</u>
<u>100-19039</u> <u>2/13/2017</u>
Inspector's IDPH License Number / Expiration Date

Inspector's Comments

HA Number:	Inspector Comments:
03	
04	
05	
06	
07	
08	
09	
10	
12	
13	
14	
15	
16	
17	
18	
19	
20	
21	
22	
23	
24	
25	
26	
27	

Chicago Public Schools

School Lloyd School Unit 24221 Building ID 4500

Address 2103 N. Lamon Avenue Region 02

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262 Fax: (312) 733-5612

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
28	
29	
30	
31	
31 A	
32	
32 A	
33	
33 A	
34	
35	
36	
36 A	
37	
38	
38A	
39	
40	
41	
42	
43	
44	
45	
46	
F	Damage in Boiler Rm (Toilet & Storage)
G	
H	

Chicago Public Schools

School Lloyd School **Unit** 24221 **Building ID** 4500

Address 2103 N. Lamon Avenue **Region** 02

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262 Fax: (312) 733-5612

Inspector's Comments are Summarized at the End of the Report

Table II

Management Planner's Review

Chicago Public Schools

School Lloyd School
Address 2103 N. Lamon Avenue

Unit 24221
Chicago, IL, 60639

Building ID 4500
Region 02

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262

Fax: (312) 733-5612

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
03	9"x9" Brown VFT (NOT OBSERVED)	1,000	SF	B-8(012) + Hall South of B-8 (012), 1907	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
04	12"x12" Tan w/ White Speckles VFT	2,200	SF	Rooms: 004, 208A, 307A, Gym 2nd Flr Boys & Girls Toilet and 2nd Flr Teachers Lounge & Toilet 1907	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
05	Green Swirl Linoleum	1,000	SF	Room 010, 1913	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
06	9"x 9" Brown VFT Mastic (NOT OBSERVED)	4,500	SF	B-8(012) + Hall South of B-8 (012), 1907	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
07	12"x12" Tan w/ White Speckles VFT Mastic	550	SF	Room 102, 1913	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
08	Green Swirl Linoleum Mastic	1,000	SF	Room 010, 1913	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
09	12"x12" Tan w/ White Speckles VFT Mastic	2,200	SF	Rooms: 004, 208A, 307A, Gym, 2nd Flr Boys & Girls Toilet and 2nd Flr Teachers Lounge & Toilet 1907	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
10	12"x12" Tan w/ White Speckles VFT	550	SF	Room 102, 1913	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
12	Hard Coat Plaster	100,000	SF	Throughout, 1907	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
13	Hard Coat Plaster	20,000	SF	Throughout, 1913	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
14	12"x12" White w/ Brown Speckles VFT	800	SF	Room 308, 1907	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
15	12"x12" White w/ Brown Speckles VFT Mastic	800	SF	Room 308, 1907	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
16	12"x12" Gray w/ White Speckled VFT	600	SF	Room 004 (Parents Room), 1907	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
17	12"x12" Gray w/ White Speckled VFT Mastic	600	SF	Room 004 (Parents Room), 1907	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
18	9"x9" Green w/ White Streaks VFT (ABATED)			Room 106, 1907 (ABATED)	Abated						
19	9"x9" Green w/ White Streaks VFT Mastic (ABATED)			Room 106, 1907 (ABATED)	Abated						
20	9"x9" Orange w/ White Streaks VFT (ABATED)			Room 106, 1907 (ABATED)	Abated						
21	9"x9" Orange w/ White Streaks VFT Mastic (ABATED)			Room 106, 1907 (ABATED)	Abated						
22	9"x9" Gray w/ White Streaks VFT	500	SF	Lunch Room Office, Room 310 & Wardrobe, 1913	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
23	9"x9" Gray w/ White Streaks VFT Mastic	1,250	SF	Lunch Room Office, Room 310 & Wardrobe, 1913	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
24	12"x12" Gray w/ White Speckled VFT (NOT OBSERVED)			Kitchen, Lunchroom 1913 (NOT OBSERVED)							
25	12"x12" Gray w/ White Speckled VFT Mastic - NOT OBSERVED			Kitchen, Lunchroom 1913 (NOT OBSERVED)							
26	2'x4' Groove Pattern Ceiling Tile	300	SF	2nd Floor: Boy's Toilet, Lounge, & Teacher's Toilet 1907	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

Chicago Public Schools

School Lloyd School
Address 2103 N. Lamon Avenue

Unit 24221
Chicago, IL, 60639

Building ID 4500
Region 02

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262

Fax: (312) 733-5612

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
27	2'x4' Dot/Groove Pattern Ceiling Tile	50	SF	2nd Floor: Boy's Toliet, & Teacher's Lounge, Teacher's Toliet 1907	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
28	2'x4' Horizontal Groove Pattern Ceiling Tile	20	SF	2nd Floor Boy's Toliet 1907	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
29	2'x4' White Textured Speckled Ceiling Tile	80	SF	Room 004 - 1907	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
30	2' x 4' Dot/Groove Pattern Ceiling Tile	32,000	SF	Throughout, 1999 Annex	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
31	12" x 12" Black with Light Grey Streaks VFT	9,000	SF	Throughout, 1999 Annex	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
31 A	12" x 12" Black with Light Grey Streaks VFT Mastic	9,000	SF	Throughout, 1999 Annex	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
32	12" x 12" Orange with White Streaks VFT	2,000	SF	Throughout, 1999 Annex	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
32 A	12" x 12" Orange with White Streaks VFT Mastic	2,000	SF	Throughout, 1999 Annex	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
33	12" x 12" Gray with Dark Gray Streaks VFT	10,000	SF	Throughout, 1999 Annex	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
33 A	12" x 12" Gray with Dark Gray Streaks VFT Mastic	10,000	SF	Throughout, 1999 Annex	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
34	Drywall	1,400	SF	Room 313, 314, 315, 213, 214, 215, 2nd and 3rd Floor Boy's/Girl's/Teacher's Toilets, 1999 Annex	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
35	Drywall Joint Compound	100	LF	Room 313, 314, 315, 213, 214, 215, 2nd and 3rd Floor Boy's/Girl's/Teacher's Toilets, 1999 Annex	Assumed	MISC	Yes	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
36	Baseboard Mastic	5,000	LF	Throughout, 1999 Annex	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
36 A	Baseboard	5,000	LF	Throughout, 1999 Annex	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
37	Carpet Mastic	3,200	SF	Room 226, 125, 125 A, 125 B, 126 A, 1999 Annex	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
38	12 x 12 Maroon VFT	750	SF	Room 106, 1907	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
38A	12 x 12 Maroon VFT Mastic	750	SF	Room 106	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
39	2' x 4' Ceiling Tile with 2' x 2' Patern	400	SF	2nd and 3rd Floor Corridors to Annex Building 1907	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
40	Carpet Mastic (Red Carpet)	500	SF	Auditorium - 1907	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
41	12" x 12" White with Gray Specks	1,200	SF	Room 102 & Corridor to Room 012 - 1907	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
42	12" x 12" White with Gray Specks Matic	1,200	SF	Room 102 & Corridor to Room 102 - 1907	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
43	Terrazo White with Brown Specks		SF	Throughout - Annex 1999	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
44	Terrazo Gray with Black Specks		SF	Throughout - Annex 1999	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
45	Terrazo Red with Gray Specks					MISC					
46	Sheet Vinyl Flooring and Glue	1,000	SF	Gymnasium Third Floor (1907 Bldg)	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

Chicago Public Schools

School Lloyd School
Address 2103 N. Lamon Avenue

Unit 24221
 Chicago, IL, 60639

Building ID 4500
Region 02

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262

Fax: (312) 733-5612

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
F	Aircell Pipe Insulation	15	LF	Boiler Room-Toilet & Storage Room, 1907	Chrysotile	TSI	Yes	3	LF	1 Damaged or significantly damaged friable thermal system insulating ACM	Repair
G	Fireproofing	10,000	SF	Above Ceiling on I-Beams, 1999 Annex	Assumed	SURFACE	No	0	SF	6 ACM with the potential for damage	Follow O&M Plan
H	Boiler Gasket	30	LF	Boiler Room	Assumed	MISC	Yes	0	LF	6 ACM with the potential for damage	Follow O&M Plan

Review Date 8/8/2016

HA Number	Management Comments
-----------	---------------------

Chicago Public Schools

School Lloyd School
Address 2103 N. Lamon Avenue

Unit 24221
 Chicago, IL, 60639

Building ID 4500
Region 02

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) GSG Consultants, Inc.
 855 W. Adams St., Ste. 200
 Phone: (312) 733-6262

Fax: (312) 733-5612

Management Planner's Comments Summarized at the End of the Report

Manager Planner Name	Jigar Shah
100-07342	1/19/2017
Manager IDPH License No/Expiration	

HA Number	Management Comments
03	
04	
05	
06	
07	
08	
09	
10	
12	
13	
14	
15	
16	
17	
18	
19	
20	
21	
22	
23	
24	
25	
26	
27	
28	
29	
30	

Chicago Public Schools

School Lloyd School
Address 2103 N. Lamon Avenue

Unit 24221
 Chicago, IL, 60639

Building ID 4500
Region 02

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262 Fax: (312) 733-5612

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
31	
31 A	
32	
32 A	
33	
33 A	
34	
35	
36	
36 A	
37	
38	
38A	
39	
40	
41	
42	
43	
44	
45	
46	
F	Repair Damaged ACM ASAP
G	
H	

Chicago Public Schools

School Lloyd School
Address 2103 N. Lamon Avenue

Unit 24221
Chicago, IL, 60639

Building ID 4500
Region 02

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) GSG Consultants, Inc.
855 W. Adams St., Ste. 200
Phone: (312) 733-6262

Fax: (312) 733-5612

Management Planner's Comments Summarized at the End of the Report

Chicago Public Schools

GSG Consultants, Inc.

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24221** BUIDLING ID: **4500**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Wayne Gardner**
SCHOOL NAME: **Lloyd School** INSPECTION DATE: **2/18/2016**
ADDRESS: **2103 N. Lamon Avenue** IDPH LICENSE NO: **100-19039**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **03**
MATERIAL DESCRIPTION: **9"x9" Brown VFT (NOT OBSERVED)**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **B-8(012) + Hall South of B-8 (012), 1907**

MATERIAL QUANTITY: **1000**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **02/18/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24221** BUIDLING ID: **4500**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Lloyd School** REVIEW DATE: **8/8/2016**
ADDRESS: **2103 N. Lamon Avenue** IDPH LICENSE NO: **100-19039**

HOMOGENEOUS AREA: **03**
MATERIAL DESCRIPTION: **9"x9" Brown VFT (NOT OBSERVED)**
MATERIAL LOCATION: **B-8(012) + Hall South of B-8 (012), 1907**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **08/08/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24221** BUILDING ID: **4500**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Wayne Gardner**
SCHOOL NAME: **Lloyd School** INSPECTION DATE: **2/18/2016**
ADDRESS: **2103 N. Lamon Avenue** IDPH LICENSE NO: **100-19039**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **04**
MATERIAL DESCRIPTION: **12"x12" Tan w/ White Speckles VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**

MATERIAL LOCATION: **Rooms: 004, 208A, 307A, Gym 2nd Flr Boys & Girls Toilet and 2nd Flr Teachers Lounge & Toilet 1907**

MATERIAL QUANTITY: **2200** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **02/18/2016**

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24221** BUILDING ID: **4500**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Lloyd School** REVIEW DATE: **8/8/2016**
ADDRESS: **2103 N. Lamon Avenue** IDPH LICENSE NO: **100-19039**

HOMOGENEOUS AREA: **04**
MATERIAL DESCRIPTION: **12"x12" Tan w/ White Speckles VFT**
MATERIAL LOCATION: **Rooms: 004, 208A, 307A, Gym 2nd Flr Boys & Girls Toilet and 2nd Flr Teachers Lounge & Toilet 1907**
MATERIAL QUANTITY: **2200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **08/08/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24221** BUIDLING ID: **4500**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Wayne Gardner**
SCHOOL NAME: **Lloyd School** INSPECTION DATE: **2/18/2016**
ADDRESS: **2103 N. Lamon Avenue** IDPH LICENSE NO: **100-19039**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **05**
MATERIAL DESCRIPTION: **Green Swirl Linoleum**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Room 010, 1913**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **02/18/2016**

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24221** BUIDLING ID: **4500**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Lloyd School** REVIEW DATE: **8/8/2016**
ADDRESS: **2103 N. Lamon Avenue** IDPH LICENSE NO: **100-19039**

HOMOGENEOUS AREA: **05**
MATERIAL DESCRIPTION: **Green Swirl Linoleum**
MATERIAL LOCATION: **Room 010, 1913**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____

Jigar Shah

Date: **08/08/2016**

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24221** BUIDLING ID: **4500**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Wayne Gardner**
SCHOOL NAME: **Lloyd School** INSPECTION DATE: **2/18/2016**
ADDRESS: **2103 N. Lamon Avenue** IDPH LICENSE NO: **100-19039**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **06**
MATERIAL DESCRIPTION: **9"x 9" Brown VFT Mastic (NOT OBSERVED)**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **B-8(012) + Hall South of B-8 (012), 1907**
MATERIAL QUANTITY: **4500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____



Date: 02/18/2016

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24221** BUILDING ID: **4500**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Lloyd School** REVIEW DATE: **8/8/2016**
ADDRESS: **2103 N. Lamon Avenue** IDPH LICENSE NO: **100-19039**

HOMOGENEOUS AREA: **06**
MATERIAL DESCRIPTION: **9"x 9" Brown VFT Mastic (NOT OBSERVED)**
MATERIAL LOCATION: **B-8(012) + Hall South of B-8 (012), 1907**
MATERIAL QUANTITY: **4500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____

Jigar Shah

Date: **08/08/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24221** BUIDLING ID: **4500**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Wayne Gardner**
SCHOOL NAME: **Lloyd School** INSPECTION DATE: **2/18/2016**
ADDRESS: **2103 N. Lamon Avenue** IDPH LICENSE NO: **100-19039**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **07**
MATERIAL DESCRIPTION: **12"x12" Tan w/ White Speckles VFT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 102, 1913**
MATERIAL QUANTITY: **550** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **02/18/2016**

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24221** BUIDLING ID: **4500**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Lloyd School** REVIEW DATE: **8/8/2016**
ADDRESS: **2103 N. Lamon Avenue** IDPH LICENSE NO: **100-19039**

HOMOGENEOUS AREA: **07**
MATERIAL DESCRIPTION: **12"x12" Tan w/ White Speckles VFT Mastic**
MATERIAL LOCATION: **Room 102, 1913**
MATERIAL QUANTITY: **550** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **08/08/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24221** BUIDLING ID: **4500**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Wayne Gardner**
SCHOOL NAME: **Lloyd School** INSPECTION DATE: **2/18/2016**
ADDRESS: **2103 N. Lamon Avenue** IDPH LICENSE NO: **100-19039**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **08**
MATERIAL DESCRIPTION: **Green Swirl Linoleum Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 010, 1913**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **02/18/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24221** BUIDLING ID: **4500**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Lloyd School** REVIEW DATE: **8/8/2016**
ADDRESS: **2103 N. Lamon Avenue** IDPH LICENSE NO: **100-19039**

HOMOGENEOUS AREA: **08**
MATERIAL DESCRIPTION: **Green Swirl Linoleum Mastic**
MATERIAL LOCATION: **Room 010, 1913**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **08/08/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24221** BUIDLING ID: **4500**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Wayne Gardner**
SCHOOL NAME: **Lloyd School** INSPECTION DATE: **2/18/2016**
ADDRESS: **2103 N. Lamon Avenue** IDPH LICENSE NO: **100-19039**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **09**
MATERIAL DESCRIPTION: **12"x12" Tan w/ White Speckles VFT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Rooms: 004, 208A, 307A, Gym, 2nd Flr Boys & Girls Toilet and 2nd Flr Teachers Lounge & Toilet 1907**

MATERIAL QUANTITY: **2200**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **02/18/2016**

Chicago Public Schools

GSG Consultants, Inc.

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24221** BUILDING ID: **4500**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Lloyd School** REVIEW DATE: **8/8/2016**
ADDRESS: **2103 N. Lamon Avenue** IDPH LICENSE NO: **100-19039**

HOMOGENEOUS AREA: **09**
MATERIAL DESCRIPTION: **12"x12" Tan w/ White Speckles VFT Mastic**
MATERIAL LOCATION: **Rooms: 004, 208A, 307A, Gym, 2nd Flr Boys & Girls Toilet and 2nd Flr Teachers Lounge & Toilet 1907**
MATERIAL QUANTITY: **2200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **08/08/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24221** BUIDLING ID: **4500**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Wayne Gardner**
SCHOOL NAME: **Lloyd School** INSPECTION DATE: **2/18/2016**
ADDRESS: **2103 N. Lamon Avenue** IDPH LICENSE NO: **100-19039**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **10**
MATERIAL DESCRIPTION: **12"x12" Tan w/ White Speckles VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Room 102, 1913**
MATERIAL QUANTITY: **550** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____



Date: 02/18/2016

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24221** BUIDLING ID: **4500**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Lloyd School** REVIEW DATE: **8/8/2016**
ADDRESS: **2103 N. Lamon Avenue** IDPH LICENSE NO: **100-19039**

HOMOGENEOUS AREA: **10**
MATERIAL DESCRIPTION: **12"x12" Tan w/ White Speckles VFT**
MATERIAL LOCATION: **Room 102, 1913**
MATERIAL QUANTITY: **550** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **08/08/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24221** BUIDLING ID: **4500**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Wayne Gardner**
SCHOOL NAME: **Lloyd School** INSPECTION DATE: **2/18/2016**
ADDRESS: **2103 N. Lamon Avenue** IDPH LICENSE NO: **100-19039**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **12**
MATERIAL DESCRIPTION: **Hard Coat Plaster**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Throughout, 1907**
MATERIAL QUANTITY: **100000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **02/18/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24221** BUILDING ID: **4500**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Lloyd School** REVIEW DATE: **8/8/2016**
ADDRESS: **2103 N. Lamon Avenue** IDPH LICENSE NO: **100-19039**

HOMOGENEOUS AREA: **12**
MATERIAL DESCRIPTION: **Hard Coat Plaster**
MATERIAL LOCATION: **Throughout, 1907**
MATERIAL QUANTITY: **100000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **08/08/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24221** BUIDLING ID: **4500**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Wayne Gardner**
SCHOOL NAME: **Lloyd School** INSPECTION DATE: **2/18/2016**
ADDRESS: **2103 N. Lamon Avenue** IDPH LICENSE NO: **100-19039**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **13**
MATERIAL DESCRIPTION: **Hard Coat Plaster**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Throughout, 1913**
MATERIAL QUANTITY: **20000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **02/18/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24221** BUILDING ID: **4500**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Lloyd School** REVIEW DATE: **8/8/2016**
ADDRESS: **2103 N. Lamon Avenue** IDPH LICENSE NO: **100-19039**

HOMOGENEOUS AREA: **13**
MATERIAL DESCRIPTION: **Hard Coat Plaster**
MATERIAL LOCATION: **Throughout, 1913**
MATERIAL QUANTITY: **20000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **08/08/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24221** BUIDLING ID: **4500**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Wayne Gardner**
SCHOOL NAME: **Lloyd School** INSPECTION DATE: **2/18/2016**
ADDRESS: **2103 N. Lamon Avenue** IDPH LICENSE NO: **100-19039**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **14**
MATERIAL DESCRIPTION: **12"x12" White w/ Brown Speckles VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Room 308, 1907**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **02/18/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24221** BUILDING ID: **4500**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Lloyd School** REVIEW DATE: **8/8/2016**
ADDRESS: **2103 N. Lamon Avenue** IDPH LICENSE NO: **100-19039**

HOMOGENEOUS AREA: **14**
MATERIAL DESCRIPTION: **12"x12" White w/ Brown Speckles VFT**
MATERIAL LOCATION: **Room 308, 1907**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **08/08/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24221** BUIDLING ID: **4500**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Wayne Gardner**
SCHOOL NAME: **Lloyd School** INSPECTION DATE: **2/18/2016**
ADDRESS: **2103 N. Lamon Avenue** IDPH LICENSE NO: **100-19039**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **15**
MATERIAL DESCRIPTION: **12"x12" White w/ Brown Speckles VFT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 308, 1907**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **02/18/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24221** BUILDING ID: **4500**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Lloyd School** REVIEW DATE: **8/8/2016**
ADDRESS: **2103 N. Lamon Avenue** IDPH LICENSE NO: **100-19039**

HOMOGENEOUS AREA: **15**
MATERIAL DESCRIPTION: **12"x12" White w/ Brown Speckles VFT Mastic**
MATERIAL LOCATION: **Room 308, 1907**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:  Date: **08/08/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24221** BUIDLING ID: **4500**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Wayne Gardner**
SCHOOL NAME: **Lloyd School** INSPECTION DATE: **2/18/2016**
ADDRESS: **2103 N. Lamon Avenue** IDPH LICENSE NO: **100-19039**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **16**
MATERIAL DESCRIPTION: **12"x12" Gray w/ White Speckled VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Room 004 (Parents Room), 1907**
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____



Date: 02/18/2016

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24221** BUILDING ID: **4500**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Lloyd School** REVIEW DATE: **8/8/2016**
ADDRESS: **2103 N. Lamon Avenue** IDPH LICENSE NO: **100-19039**

HOMOGENEOUS AREA: **16**
MATERIAL DESCRIPTION: **12"x12" Gray w/ White Speckled VFT**
MATERIAL LOCATION: **Room 004 (Parents Room), 1907**
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **08/08/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24221** BUIDLING ID: **4500**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Wayne Gardner**
SCHOOL NAME: **Lloyd School** INSPECTION DATE: **2/18/2016**
ADDRESS: **2103 N. Lamon Avenue** IDPH LICENSE NO: **100-19039**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **17**
MATERIAL DESCRIPTION: **12"x12" Gray w/ White Speckled VFT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 004 (Parents Room), 1907**
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **02/18/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24221** BUIDLING ID: **4500**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Lloyd School** REVIEW DATE: **8/8/2016**
ADDRESS: **2103 N. Lamon Avenue** IDPH LICENSE NO: **100-19039**

HOMOGENEOUS AREA: **17**
MATERIAL DESCRIPTION: **12"x12" Gray w/ White Speckled VFT Mastic**
MATERIAL LOCATION: **Room 004 (Parents Room), 1907**
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:  Date: **08/08/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24221** BUIDLING ID: **4500**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Wayne Gardner**
SCHOOL NAME: **Lloyd School** INSPECTION DATE: **2/18/2016**
ADDRESS: **2103 N. Lamon Avenue** IDPH LICENSE NO: **100-19039**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **18**
MATERIAL DESCRIPTION: **9"x9" Green w/ White Streaks VFT(ABATED)**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 106, 1907 (ABATED)**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **02/18/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24221** BUIDLING ID: **4500**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Lloyd School** REVIEW DATE: **8/8/2016**
ADDRESS: **2103 N. Lamon Avenue** IDPH LICENSE NO: **100-19039**

HOMOGENEOUS AREA: **18**
MATERIAL DESCRIPTION: **9"x9" Green w/ White Streaks VFT(ABATED)**
MATERIAL LOCATION: **Room 106, 1907 (ABATED)**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:  Date: **08/08/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24221** BUILDING ID: **4500**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Wayne Gardner**
SCHOOL NAME: **Lloyd School** INSPECTION DATE: **2/18/2016**
ADDRESS: **2103 N. Lamon Avenue** IDPH LICENSE NO: **100-19039**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **19**
MATERIAL DESCRIPTION: **9"x9" Green w/ White Streaks VFT Mastic (ABATED)**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 106, 1907 (ABATED)**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **02/18/2016**

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24221** BUILDING ID: **4500**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Lloyd School** REVIEW DATE: **8/8/2016**
ADDRESS: **2103 N. Lamon Avenue** IDPH LICENSE NO: **100-19039**

HOMOGENEOUS AREA: **19**

MATERIAL DESCRIPTION: **9"x9" Green w/ White Streaks VFT Mastic (ABATED)**

MATERIAL LOCATION: **Room 106, 1907 (ABATED)**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:


DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **08/08/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 24221 BUILDING ID: 4500
CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Wayne Gardner
SCHOOL NAME: Lloyd School INSPECTION DATE: 2/18/2016
ADDRESS: 2103 N. Lamon Avenue IDPH LICENSE NO: 100-19039

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 20
MATERIAL DESCRIPTION: 9"x9" Orange w/ White Streaks VFT (ABATED)
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: Abated FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:
DISTURBANCE POTENTIAL:
MATERIAL LOCATION: Room 106, 1907 (ABATED)
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:
COMMENTS:

Inspector's Signature:



Date: 02/18/2016

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24221** BUILDING ID: **4500**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Lloyd School** REVIEW DATE: **8/8/2016**
ADDRESS: **2103 N. Lamon Avenue** IDPH LICENSE NO: **100-19039**

HOMOGENEOUS AREA: **20**

MATERIAL DESCRIPTION: **9"x9" Orange w/ White Streaks VFT (ABATED)**

MATERIAL LOCATION: **Room 106, 1907 (ABATED)**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:


DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **08/08/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24221** BUILDING ID: **4500**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Wayne Gardner**
SCHOOL NAME: **Lloyd School** INSPECTION DATE: **2/18/2016**
ADDRESS: **2103 N. Lamon Avenue** IDPH LICENSE NO: **100-19039**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **21**
MATERIAL DESCRIPTION: **9"x9" Orange w/ White Streaks VFT Mastic (ABATED)**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 106, 1907 (ABATED)**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **02/18/2016**

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24221** BUIDLING ID: **4500**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Lloyd School** REVIEW DATE: **8/8/2016**
ADDRESS: **2103 N. Lamon Avenue** IDPH LICENSE NO: **100-19039**


HOMOGENEOUS AREA: **21**
MATERIAL DESCRIPTION: **9"x9" Orange w/ White Streaks VFT Mastic (ABATED)**
MATERIAL LOCATION: **Room 106, 1907 (ABATED)**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **08/08/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24221** BUIDLING ID: **4500**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Wayne Gardner**
SCHOOL NAME: **Lloyd School** INSPECTION DATE: **2/18/2016**
ADDRESS: **2103 N. Lamon Avenue** IDPH LICENSE NO: **100-19039**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **22**
MATERIAL DESCRIPTION: **9"x9" Gray w/ White Streaks VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Lunch Room Office, Room 310 & Wardrobe, 1913**
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **02/18/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24221** BUILDING ID: **4500**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Lloyd School** REVIEW DATE: **8/8/2016**
ADDRESS: **2103 N. Lamon Avenue** IDPH LICENSE NO: **100-19039**

HOMOGENEOUS AREA: **22**
MATERIAL DESCRIPTION: **9"x9" Gray w/ White Streaks VFT**
MATERIAL LOCATION: **Lunch Room Office, Room 310 & Wardrobe, 1913**
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____

Jigar Shah

Date: **08/08/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24221** BUIDLING ID: **4500**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Wayne Gardner**
SCHOOL NAME: **Lloyd School** INSPECTION DATE: **2/18/2016**
ADDRESS: **2103 N. Lamon Avenue** IDPH LICENSE NO: **100-19039**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **23**
MATERIAL DESCRIPTION: **9"x9" Gray w/ White Streaks VFT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Lunch Room Office, Room 310 & Wardrobe, 1913**
MATERIAL QUANTITY: **1250** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **02/18/2016**

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24221** BUILDING ID: **4500**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Lloyd School** REVIEW DATE: **8/8/2016**
ADDRESS: **2103 N. Lamon Avenue** IDPH LICENSE NO: **100-19039**

HOMOGENEOUS AREA: **23**
MATERIAL DESCRIPTION: **9"x9" Gray w/ White Streaks VFT Mastic**
MATERIAL LOCATION: **Lunch Room Office, Room 310 & Wardrobe, 1913**
MATERIAL QUANTITY: **1250** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____

Jigar Shah

Date: **08/08/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 24221 BUILDING ID: 4500
CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Wayne Gardner
SCHOOL NAME: Lloyd School INSPECTION DATE: 2/18/2016
ADDRESS: 2103 N. Lamon Avenue IDPH LICENSE NO: 100-19039

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 24
MATERIAL DESCRIPTION: 12"x12" Gray w/ White Speckled VFT (NOT OBSERVED)
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: Follow O&M Plan
ASBESTOS TYPE: FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Kitchen, Lunchroom 1913 (NOT OBSERVED)

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 02/18/2016

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24221** BUILDING ID: **4500**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Lloyd School** REVIEW DATE: **8/8/2016**
ADDRESS: **2103 N. Lamon Avenue** IDPH LICENSE NO: **100-19039**

HOMOGENEOUS AREA: **24**
MATERIAL DESCRIPTION: **12"x12" Gray w/ White Speckled VFT (NOT OBSERVED)**
MATERIAL LOCATION: **Kitchen, Lunchroom 1913 (NOT OBSERVED)**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **08/08/2016**

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24221** BUIDLING ID: **4500**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Wayne Gardner**
SCHOOL NAME: **Lloyd School** INSPECTION DATE: **2/18/2016**
ADDRESS: **2103 N. Lamon Avenue** IDPH LICENSE NO: **100-19039**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **25**
MATERIAL DESCRIPTION: **12"x12" Gray w/ White Speckled VFT Mastic - NOT OBSERVED**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Kitchen, Lunchroom 1913 (NOT OBSERVED)**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **02/18/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24221** BUILDING ID: **4500**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Lloyd School** REVIEW DATE: **8/8/2016**
ADDRESS: **2103 N. Lamon Avenue** IDPH LICENSE NO: **100-19039**

HOMOGENEOUS AREA: **25**
MATERIAL DESCRIPTION: **12"x12" Gray w/ White Speckled VFT Mastic - NOT OBSERVED**
MATERIAL LOCATION: **Kitchen, Lunchroom 1913 (NOT OBSERVED)**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **08/08/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24221** BUIDLING ID: **4500**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Wayne Gardner**
SCHOOL NAME: **Lloyd School** INSPECTION DATE: **2/18/2016**
ADDRESS: **2103 N. Lamon Avenue** IDPH LICENSE NO: **100-19039**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **26**
MATERIAL DESCRIPTION: **2'x4' Groove Pattern Ceiling Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **2nd Floor: Boy's Toliet, Lounge, & Teacher's Toliet 1907**
MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 02/18/2016

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24221** BUILDING ID: **4500**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Lloyd School** REVIEW DATE: **8/8/2016**
ADDRESS: **2103 N. Lamon Avenue** IDPH LICENSE NO: **100-19039**

HOMOGENEOUS AREA: **26**
MATERIAL DESCRIPTION: **2'x4' Groove Pattern Ceiling Tile**
MATERIAL LOCATION: **2nd Floor: Boy's Toilet, Lounge, & Teacher's Toilet 1907**
MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:  Date: **08/08/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24221** BUIDLING ID: **4500**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Wayne Gardner**
SCHOOL NAME: **Lloyd School** INSPECTION DATE: **2/18/2016**
ADDRESS: **2103 N. Lamon Avenue** IDPH LICENSE NO: **100-19039**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **27**
MATERIAL DESCRIPTION: **2'x4' Dot/Groove Pattern Ceiling Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **2nd Floor: Boy's Toliet, & Teacher's Lounge, Teacher's Toliet 1907**
MATERIAL QUANTITY: **50** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 02/18/2016

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24221** BUILDING ID: **4500**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Lloyd School** REVIEW DATE: **8/8/2016**
ADDRESS: **2103 N. Lamon Avenue** IDPH LICENSE NO: **100-19039**

HOMOGENEOUS AREA: **27**
MATERIAL DESCRIPTION: **2'x4' Dot/Groove Pattern Ceiling Tile**
MATERIAL LOCATION: **2nd Floor: Boy's Toliet, & Teacher's Lounge, Teacher's Toliet 1907**
MATERIAL QUANTITY: **50** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____

Jigar Shah

Date: **08/08/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24221** BUIDLING ID: **4500**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Wayne Gardner**
SCHOOL NAME: **Lloyd School** INSPECTION DATE: **2/18/2016**
ADDRESS: **2103 N. Lamon Avenue** IDPH LICENSE NO: **100-19039**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **28**
MATERIAL DESCRIPTION: **2'x4' Horizontal Groove Pattern Ceiling Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **2nd Floor Boy's Toliet 1907**
MATERIAL QUANTITY: **20** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **02/18/2016**

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24221** BUIDLING ID: **4500**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Lloyd School** REVIEW DATE: **8/8/2016**
ADDRESS: **2103 N. Lamon Avenue** IDPH LICENSE NO: **100-19039**

HOMOGENEOUS AREA: **28**
MATERIAL DESCRIPTION: **2'x4' Horizontal Groove Pattern Ceiling Tile**
MATERIAL LOCATION: **2nd Floor Boy's Toliet 1907**
MATERIAL QUANTITY: **20** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **08/08/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24221** BUIDLING ID: **4500**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Wayne Gardner**
SCHOOL NAME: **Lloyd School** INSPECTION DATE: **2/18/2016**
ADDRESS: **2103 N. Lamon Avenue** IDPH LICENSE NO: **100-19039**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **29**
MATERIAL DESCRIPTION: **2'x4' White Textured Speckled Ceiling Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 004 - 1907**
MATERIAL QUANTITY: **80** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **02/18/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24221** BUIDLING ID: **4500**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Lloyd School** REVIEW DATE: **8/8/2016**
ADDRESS: **2103 N. Lamon Avenue** IDPH LICENSE NO: **100-19039**

HOMOGENEOUS AREA: **29**
MATERIAL DESCRIPTION: **2'x4' White Textured Speckled Ceiling Tile**
MATERIAL LOCATION: **Room 004 - 1907**
MATERIAL QUANTITY: **80** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____

Jigar Shah

Date: **08/08/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24221** BUIDLING ID: **4500**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Wayne Gardner**
SCHOOL NAME: **Lloyd School** INSPECTION DATE: **2/18/2016**
ADDRESS: **2103 N. Lamon Avenue** IDPH LICENSE NO: **100-19039**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **30**
MATERIAL DESCRIPTION: **2' x 4' Dot/Groove Pattern Ceiling Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with potential for significant damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Throughout, 1999 Annex**
MATERIAL QUANTITY: **32000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **02/18/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24221** BUIDLING ID: **4500**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Lloyd School** REVIEW DATE: **8/8/2016**
ADDRESS: **2103 N. Lamon Avenue** IDPH LICENSE NO: **100-19039**

HOMOGENEOUS AREA: **30**
MATERIAL DESCRIPTION: **2' x 4' Dot/Groove Pattern Ceiling Tile**
MATERIAL LOCATION: **Throughout, 1999 Annex**
MATERIAL QUANTITY: **32000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **08/08/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24221** BUIDLING ID: **4500**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Wayne Gardner**
SCHOOL NAME: **Lloyd School** INSPECTION DATE: **2/18/2016**
ADDRESS: **2103 N. Lamon Avenue** IDPH LICENSE NO: **100-19039**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **31**
MATERIAL DESCRIPTION: **12" x 12" Black with Light Grey Streaks VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**

MATERIAL LOCATION: **Throughout, 1999 Annex**

MATERIAL QUANTITY: **9000**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **02/18/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24221** BUIDLING ID: **4500**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Lloyd School** REVIEW DATE: **8/8/2016**
ADDRESS: **2103 N. Lamon Avenue** IDPH LICENSE NO: **100-19039**

HOMOGENEOUS AREA: **31**
MATERIAL DESCRIPTION: **12" x 12" Black with Light Grey Streaks VFT**
MATERIAL LOCATION: **Throughout, 1999 Annex**
MATERIAL QUANTITY: **9000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____

Jigar Shah

Date: **08/08/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24221** BUIDLING ID: **4500**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Wayne Gardner**
SCHOOL NAME: **Lloyd School** INSPECTION DATE: **2/18/2016**
ADDRESS: **2103 N. Lamon Avenue** IDPH LICENSE NO: **100-19039**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **31 A**
MATERIAL DESCRIPTION: **12" x 12" Black with Light Grey Streaks VFT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Throughout, 1999 Annex**
MATERIAL QUANTITY: **9000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **02/18/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24221** BUILDING ID: **4500**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Lloyd School** REVIEW DATE: **8/8/2016**
ADDRESS: **2103 N. Lamon Avenue** IDPH LICENSE NO: **100-19039**

HOMOGENEOUS AREA: **31 A**
MATERIAL DESCRIPTION: **12" x 12" Black with Light Grey Streaks VFT Mastic**
MATERIAL LOCATION: **Throughout, 1999 Annex**
MATERIAL QUANTITY: **9000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:  Date: **08/08/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24221** BUIDLING ID: **4500**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Wayne Gardner**
SCHOOL NAME: **Lloyd School** INSPECTION DATE: **2/18/2016**
ADDRESS: **2103 N. Lamon Avenue** IDPH LICENSE NO: **100-19039**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **32**
MATERIAL DESCRIPTION: **12" x 12" Orange with White Streaks VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**

MATERIAL LOCATION: **Throughout, 1999 Annex**

MATERIAL QUANTITY: **2000**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **02/18/2016**

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24221** BUIDLING ID: **4500**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Lloyd School** REVIEW DATE: **8/8/2016**
ADDRESS: **2103 N. Lamon Avenue** IDPH LICENSE NO: **100-19039**

HOMOGENEOUS AREA: **32**
MATERIAL DESCRIPTION: **12" x 12" Orange with White Streaks VFT**
MATERIAL LOCATION: **Throughout, 1999 Annex**
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **08/08/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24221** BUILDING ID: **4500**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Wayne Gardner**
SCHOOL NAME: **Lloyd School** INSPECTION DATE: **2/18/2016**
ADDRESS: **2103 N. Lamon Avenue** IDPH LICENSE NO: **100-19039**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **32 A**
MATERIAL DESCRIPTION: **12" x 12" Orange with White Streaks VFT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Throughout, 1999 Annex**
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature:



Date: **02/18/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24221** BUILDING ID: **4500**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Lloyd School** REVIEW DATE: **8/8/2016**
ADDRESS: **2103 N. Lamon Avenue** IDPH LICENSE NO: **100-19039**

HOMOGENEOUS AREA: **32 A**
MATERIAL DESCRIPTION: **12" x 12" Orange with White Streaks VFT Mastic**
MATERIAL LOCATION: **Throughout, 1999 Annex**
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____

Jigar Shah

Date: **08/08/2016**

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24221** BUIDLING ID: **4500**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Wayne Gardner**
SCHOOL NAME: **Lloyd School** INSPECTION DATE: **2/18/2016**
ADDRESS: **2103 N. Lamon Avenue** IDPH LICENSE NO: **100-19039**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **33**
MATERIAL DESCRIPTION: **12" x 12" Gray with Dark Gray Streaks VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Throughout, 1999 Annex**
MATERIAL QUANTITY: **10000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **02/18/2016**

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24221** BUIDLING ID: **4500**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Lloyd School** REVIEW DATE: **8/8/2016**
ADDRESS: **2103 N. Lamon Avenue** IDPH LICENSE NO: **100-19039**

HOMOGENEOUS AREA: **33**
MATERIAL DESCRIPTION: **12" x 12" Gray with Dark Gray Streaks VFT**
MATERIAL LOCATION: **Throughout, 1999 Annex**
MATERIAL QUANTITY: **10000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____

Jigar Shah

Date: **08/08/2016**

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24221** BUIDLING ID: **4500**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Wayne Gardner**
SCHOOL NAME: **Lloyd School** INSPECTION DATE: **2/18/2016**
ADDRESS: **2103 N. Lamon Avenue** IDPH LICENSE NO: **100-19039**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **33 A**
MATERIAL DESCRIPTION: **12" x 12" Gray with Dark Gray Streaks VFT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Throughout, 1999 Annex**
MATERIAL QUANTITY: **10000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **02/18/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24221** BUILDING ID: **4500**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Lloyd School** REVIEW DATE: **8/8/2016**
ADDRESS: **2103 N. Lamon Avenue** IDPH LICENSE NO: **100-19039**

HOMOGENEOUS AREA: **33 A**
MATERIAL DESCRIPTION: **12" x 12" Gray with Dark Gray Streaks VFT Mastic**
MATERIAL LOCATION: **Throughout, 1999 Annex**
MATERIAL QUANTITY: **10000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:  Date: **08/08/2016**

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24221** BUILDING ID: **4500**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Wayne Gardner**
SCHOOL NAME: **Lloyd School** INSPECTION DATE: **2/18/2016**
ADDRESS: **2103 N. Lamon Avenue** IDPH LICENSE NO: **100-19039**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **34**
MATERIAL DESCRIPTION: **Drywall**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with potential for significant damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**

MATERIAL LOCATION: **Room 313, 314, 315, 213, 214, 215, 2nd and 3rd Floor Boy's/Girl's/Teacher's Toilets, 1999 Annex**

MATERIAL QUANTITY: **1400**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **02/18/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24221** BUILDING ID: **4500**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Lloyd School** REVIEW DATE: **8/8/2016**
ADDRESS: **2103 N. Lamon Avenue** IDPH LICENSE NO: **100-19039**

HOMOGENEOUS AREA: **34**
MATERIAL DESCRIPTION: **Drywall**
MATERIAL LOCATION: **Room 313, 314, 315, 213, 214, 215, 2nd and 3rd Floor Boy's/Girl's/Teacher's Toilets, 1999 Annex**
MATERIAL QUANTITY: **1400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____

Jigar Shah

Date: **08/08/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 24221 BUIDLING ID: 4500
CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Wayne Gardner
SCHOOL NAME: Lloyd School INSPECTION DATE: 2/18/2016
ADDRESS: 2103 N. Lamon Avenue IDPH LICENSE NO: 100-19039

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 35
MATERIAL DESCRIPTION: Drywall Joint Compound
HISTORICAL AHERA DAMAGE CATEGORY 6 ACBM with potential for significant damage
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: Follow O&M Plan
ASBESTOS TYPE: Assumed FRIABLE: Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: MODERATE
MATERIAL LOCATION: Room 313, 314, 315, 213, 214, 215, 2nd and 3rd Floor Boy's/Girl's/Teacher's Toilets, 1999 Annex
MATERIAL QUANTITY: 100 MATERIAL UNITS: LF
DAMAGE QUANTITY: DAMAGE UNITS: LF
COMMENTS:

Inspector's Signature:



Date: 02/18/2016

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24221** BUILDING ID: **4500**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Lloyd School** REVIEW DATE: **8/8/2016**
ADDRESS: **2103 N. Lamon Avenue** IDPH LICENSE NO: **100-19039**

HOMOGENEOUS AREA: **35**
MATERIAL DESCRIPTION: **Drywall Joint Compound**
MATERIAL LOCATION: **Room 313, 314, 315, 213, 214, 215, 2nd and 3rd Floor Boy's/Girl's/Teacher's Toilets, 1999 Annex**
MATERIAL QUANTITY: **100** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **08/08/2016**

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24221** BUIDLING ID: **4500**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Wayne Gardner**
SCHOOL NAME: **Lloyd School** INSPECTION DATE: **2/18/2016**
ADDRESS: **2103 N. Lamon Avenue** IDPH LICENSE NO: **100-19039**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **36**
MATERIAL DESCRIPTION: **Baseboard Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Throughout, 1999 Annex**
MATERIAL QUANTITY: **5000** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: DAMAGE UNITS: **LF**
COMMENTS:

Inspector's Signature: _____



Date: 02/18/2016

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24221** BUILDING ID: **4500**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Lloyd School** REVIEW DATE: **8/8/2016**
ADDRESS: **2103 N. Lamon Avenue** IDPH LICENSE NO: **100-19039**

HOMOGENEOUS AREA: **36**
MATERIAL DESCRIPTION: **Baseboard Mastic**
MATERIAL LOCATION: **Throughout, 1999 Annex**
MATERIAL QUANTITY: **5000** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **08/08/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24221** BUIDLING ID: **4500**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Wayne Gardner**
SCHOOL NAME: **Lloyd School** INSPECTION DATE: **2/18/2016**
ADDRESS: **2103 N. Lamon Avenue** IDPH LICENSE NO: **100-19039**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **36 A**
MATERIAL DESCRIPTION: **Baseboard**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Throughout, 1999 Annex**
MATERIAL QUANTITY: **5000** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature:



Date: **02/18/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24221** BUIDLING ID: **4500**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Lloyd School** REVIEW DATE: **8/8/2016**
ADDRESS: **2103 N. Lamon Avenue** IDPH LICENSE NO: **100-19039**

HOMOGENEOUS AREA: **36 A**
MATERIAL DESCRIPTION: **Baseboard**
MATERIAL LOCATION: **Throughout, 1999 Annex**
MATERIAL QUANTITY: **5000** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:  Date: **08/08/2016**

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24221** BUIDLING ID: **4500**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Wayne Gardner**
SCHOOL NAME: **Lloyd School** INSPECTION DATE: **2/18/2016**
ADDRESS: **2103 N. Lamon Avenue** IDPH LICENSE NO: **100-19039**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **37**
MATERIAL DESCRIPTION: **Carpet Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 226, 125, 125 A, 125 B, 126 A, 1999 Annex**
MATERIAL QUANTITY: **3200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **02/18/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24221** BUIDLING ID: **4500**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Lloyd School** REVIEW DATE: **8/8/2016**
ADDRESS: **2103 N. Lamon Avenue** IDPH LICENSE NO: **100-19039**

HOMOGENEOUS AREA: **37**
MATERIAL DESCRIPTION: **Carpet Mastic**
MATERIAL LOCATION: **Room 226, 125, 125 A, 125 B, 126 A, 1999 Annex**
MATERIAL QUANTITY: **3200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:  Date: **08/08/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24221** BUIDLING ID: **4500**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Wayne Gardner**
SCHOOL NAME: **Lloyd School** INSPECTION DATE: **2/18/2016**
ADDRESS: **2103 N. Lamon Avenue** IDPH LICENSE NO: **100-19039**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **38**
MATERIAL DESCRIPTION: **12 x 12 Maroon VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Room 106, 1907**
MATERIAL QUANTITY: **750** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **02/18/2016**

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24221** BUIDLING ID: **4500**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Lloyd School** REVIEW DATE: **8/8/2016**
ADDRESS: **2103 N. Lamon Avenue** IDPH LICENSE NO: **100-19039**

HOMOGENEOUS AREA: **38**
MATERIAL DESCRIPTION: **12 x 12 Maroon VFT**
MATERIAL LOCATION: **Room 106, 1907**
MATERIAL QUANTITY: **750** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____

Jigar Shah

Date: **08/08/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24221** BUIDLING ID: **4500**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Wayne Gardner**
SCHOOL NAME: **Lloyd School** INSPECTION DATE: **2/18/2016**
ADDRESS: **2103 N. Lamon Avenue** IDPH LICENSE NO: **100-19039**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **38A**
MATERIAL DESCRIPTION: **12 x 12 Maroon VFT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 106**
MATERIAL QUANTITY: **750** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **02/18/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24221** BUILDING ID: **4500**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Lloyd School** REVIEW DATE: **8/8/2016**
ADDRESS: **2103 N. Lamon Avenue** IDPH LICENSE NO: **100-19039**

HOMOGENEOUS AREA: **38A**
MATERIAL DESCRIPTION: **12 x 12 Maroon VFT Mastic**
MATERIAL LOCATION: **Room 106**
MATERIAL QUANTITY: **750** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:  Date: **08/08/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 24221 BUILDING ID: 4500
CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Wayne Gardner
SCHOOL NAME: Lloyd School INSPECTION DATE: 2/18/2016
ADDRESS: 2103 N. Lamon Avenue IDPH LICENSE NO: 100-19039

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 39
MATERIAL DESCRIPTION: 2' x 4' Ceiling Tile with 2' x 2' Patern
HISTORICAL AHERA DAMAGE CATEGORY 6 ACBM with the potential for damage
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: Follow O&M Plan
ASBESTOS TYPE: Assumed FRIABLE: Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW
MATERIAL LOCATION: 2nd and 3rd Floor Corridors to Annex Building 1907
MATERIAL QUANTITY: 400 MATERIAL UNITS: SF
DAMAGE QUANTITY: DAMAGE UNITS: SF

COMMENTS:

Inspector's Signature:



Date: 02/18/2016

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24221** BUILDING ID: **4500**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Lloyd School** REVIEW DATE: **8/8/2016**
ADDRESS: **2103 N. Lamon Avenue** IDPH LICENSE NO: **100-19039**

HOMOGENEOUS AREA: **39**
MATERIAL DESCRIPTION: **2' x 4' Ceiling Tile with 2' x 2' Pattern**
MATERIAL LOCATION: **2nd and 3rd Floor Corridors to Annex Building 1907**
MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____

Jigar Shah

Date: **08/08/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24221** BUIDLING ID: **4500**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Wayne Gardner**
SCHOOL NAME: **Lloyd School** INSPECTION DATE: **2/18/2016**
ADDRESS: **2103 N. Lamon Avenue** IDPH LICENSE NO: **100-19039**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **40**
MATERIAL DESCRIPTION: **Carpet Mastic (Red Carpet)**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Auditorium - 1907**
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____



Date: 02/18/2016

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24221** BUILDING ID: **4500**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Lloyd School** REVIEW DATE: **8/8/2016**
ADDRESS: **2103 N. Lamon Avenue** IDPH LICENSE NO: **100-19039**

HOMOGENEOUS AREA: **40**
MATERIAL DESCRIPTION: **Carpet Mastic (Red Carpet)**
MATERIAL LOCATION: **Auditorium - 1907**
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____

Jigar Shah

Date: **08/08/2016**

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24221** BUIDLING ID: **4500**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Wayne Gardner**
SCHOOL NAME: **Lloyd School** INSPECTION DATE: **2/18/2016**
ADDRESS: **2103 N. Lamon Avenue** IDPH LICENSE NO: **100-19039**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **41**
MATERIAL DESCRIPTION: **12" x 12" White with Gray Specks**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 102 & Corridor to Room 012 - 1907**
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **02/18/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24221** BUIDLING ID: **4500**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Lloyd School** REVIEW DATE: **8/8/2016**
ADDRESS: **2103 N. Lamon Avenue** IDPH LICENSE NO: **100-19039**

HOMOGENEOUS AREA: **41**
MATERIAL DESCRIPTION: **12" x 12" White with Gray Specks**
MATERIAL LOCATION: **Room 102 & Corridor to Room 012 - 1907**
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **08/08/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24221** BUIDLING ID: **4500**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Wayne Gardner**
SCHOOL NAME: **Lloyd School** INSPECTION DATE: **2/18/2016**
ADDRESS: **2103 N. Lamon Avenue** IDPH LICENSE NO: **100-19039**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **42**
MATERIAL DESCRIPTION: **12" x 12" White with Gray Specks Matic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 102 & Corridor to Room 102 - 1907**
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **02/18/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24221** BUIDLING ID: **4500**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Lloyd School** REVIEW DATE: **8/8/2016**
ADDRESS: **2103 N. Lamon Avenue** IDPH LICENSE NO: **100-19039**

HOMOGENEOUS AREA: **42**
MATERIAL DESCRIPTION: **12" x 12" White with Gray Specks Matic**
MATERIAL LOCATION: **Room 102 & Corridor to Room 102 - 1907**
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:  Date: **08/08/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24221** BUIDLING ID: **4500**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Wayne Gardner**
SCHOOL NAME: **Lloyd School** INSPECTION DATE: **2/18/2016**
ADDRESS: **2103 N. Lamon Avenue** IDPH LICENSE NO: **100-19039**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **43**
MATERIAL DESCRIPTION: **Terrazo White with Brown Specks**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Throughout - Annex 1999**

MATERIAL QUANTITY: MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **02/18/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24221** BUILDING ID: **4500**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Lloyd School** REVIEW DATE: **8/8/2016**
ADDRESS: **2103 N. Lamon Avenue** IDPH LICENSE NO: **100-19039**

HOMOGENEOUS AREA: **43**
MATERIAL DESCRIPTION: **Terrazo White with Brown Specks**
MATERIAL LOCATION: **Throughout - Annex 1999**
MATERIAL QUANTITY: MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **08/08/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24221** BUIDLING ID: **4500**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Wayne Gardner**
SCHOOL NAME: **Lloyd School** INSPECTION DATE: **2/18/2016**
ADDRESS: **2103 N. Lamon Avenue** IDPH LICENSE NO: **100-19039**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **44**
MATERIAL DESCRIPTION: **Terrazo Gray with Black Specks**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Throughout - Annex 1999**

MATERIAL QUANTITY: MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 02/18/2016

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24221** BUIDLING ID: **4500**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Lloyd School** REVIEW DATE: **8/8/2016**
ADDRESS: **2103 N. Lamon Avenue** IDPH LICENSE NO: **100-19039**

HOMOGENEOUS AREA: **44**
MATERIAL DESCRIPTION: **Terrazo Gray with Black Specks**
MATERIAL LOCATION: **Throughout - Annex 1999**
MATERIAL QUANTITY: MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **08/08/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24221** BUIDLING ID: **4500**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Wayne Gardner**
SCHOOL NAME: **Lloyd School** INSPECTION DATE: **2/18/2016**
ADDRESS: **2103 N. Lamon Avenue** IDPH LICENSE NO: **100-19039**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **45**
MATERIAL DESCRIPTION: **Terrazo Red with Gray Specks**
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION:

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **02/18/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24221** BUILDING ID: **4500**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Lloyd School** REVIEW DATE: **8/8/2016**
ADDRESS: **2103 N. Lamon Avenue** IDPH LICENSE NO: **100-19039**

HOMOGENEOUS AREA: **45**

MATERIAL DESCRIPTION: **Terrazo Red with Gray Specks**

MATERIAL LOCATION:

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **08/08/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 24221 BUILDING ID: 4500
CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Wayne Gardner
SCHOOL NAME: Lloyd School INSPECTION DATE: 2/18/2016
ADDRESS: 2103 N. Lamon Avenue IDPH LICENSE NO: 100-19039

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: F
MATERIAL DESCRIPTION: Aircell Pipe Insulation
HISTORICAL AHERA DAMAGE CATEGORY 1 Damaged or significantly damaged friable thermal system insulating ACBM
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: Repair
ASBESTOS TYPE: Chrysotile FRIABLE: Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be 1. **Damaged or significantly damaged friable thermal system insulating ACBM**

DAMAGE REASON: Deterioration
DISTURBANCE POTENTIAL: LOW
MATERIAL LOCATION: Boiler Room-Toilet & Storage Room, 1907
MATERIAL QUANTITY: 15 MATERIAL UNITS: LF
DAMAGE QUANTITY: DAMAGE UNITS: LF
COMMENTS: Damage in Boiler Rm (Toilet & Storage)

Inspector's Signature:



Date: 02/18/2016

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24221** BUIDLING ID: **4500**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Lloyd School** REVIEW DATE: **8/8/2016**
ADDRESS: **2103 N. Lamon Avenue** IDPH LICENSE NO: **100-19039**

HOMOGENEOUS AREA: **F**
MATERIAL DESCRIPTION: **Aircell Pipe Insulation**
MATERIAL LOCATION: **Boiler Room-Toilet & Storage Room, 1907**
MATERIAL QUANTITY: **15** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **3** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Repair

Comments:

Repair Damaged ACM ASAP

Management Planner's Signature:  Date: **08/08/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 24221 BUIDLING ID: 4500
CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Wayne Gardner
SCHOOL NAME: Lloyd School INSPECTION DATE: 2/18/2016
ADDRESS: 2103 N. Lamon Avenue IDPH LICENSE NO: 100-19039

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: G
MATERIAL DESCRIPTION: Fireproofing
HISTORICAL AHERA DAMAGE CATEGORY 6 ACBM with the potential for damage
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: Follow O&M Plan
ASBESTOS TYPE: Assumed FRIABLE: No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW
MATERIAL LOCATION: Above Ceiling on I-Beams, 1999 Annex
MATERIAL QUANTITY: 10000 MATERIAL UNITS: SF
DAMAGE QUANTITY: DAMAGE UNITS: SF
COMMENTS:

Inspector's Signature:



Date: 02/18/2016

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24221** BUILDING ID: **4500**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Lloyd School** REVIEW DATE: **8/8/2016**
ADDRESS: **2103 N. Lamon Avenue** IDPH LICENSE NO: **100-19039**

HOMOGENEOUS AREA: **G**
MATERIAL DESCRIPTION: **Fireproofing**
MATERIAL LOCATION: **Above Ceiling on I-Beams, 1999 Annex**
MATERIAL QUANTITY: **10000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **08/08/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24221** BUIDLING ID: **4500**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Wayne Gardner**
SCHOOL NAME: **Lloyd School** INSPECTION DATE: **2/18/2016**
ADDRESS: **2103 N. Lamon Avenue** IDPH LICENSE NO: **100-19039**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **H**
MATERIAL DESCRIPTION: **Boiler Gasket**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Boiler Room**
MATERIAL QUANTITY: **30** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature:



Date: **02/18/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24221** BUIDLING ID: **4500**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Lloyd School** REVIEW DATE: **8/8/2016**
ADDRESS: **2103 N. Lamon Avenue** IDPH LICENSE NO: **100-19039**

HOMOGENEOUS AREA: **H**
MATERIAL DESCRIPTION: **Boiler Gasket**
MATERIAL LOCATION: **Boiler Room**
MATERIAL QUANTITY: **30** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **08/08/2016**

Chicago Public Schools

GSG Consultants, Inc.
2016 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24221** BUILDING ID: **4500**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Wayne Gardner**
SCHOOL NAME: **Lloyd School** INSPECTION DATE: **2/18/2016**
ADDRESS: **2103 N. Lamon Avenue** IDPH LICENSE NO: **100-19039**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **46**
MATERIAL DESCRIPTION: **Sheet Vinyl Flooring and Glue**
MATERIAL LOCATION: **Gymnasium Third Floor (1907 Bldg)**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**
MATERIAL CATEGORY: **MISC** FRIABLE: **No**
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **LOW** CONDITION:
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
ACCESSIBILITY: **Within Reach** DAMAGE REASON:
DAMAGE QUANTITY: **0** DAMAGE REASON:
DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____



Date: 02/18/2016

Chicago Public Schools

GSG Consultants, Inc. 2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24221** BUILDING ID: **4500**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Lloyd School** REVIEW DATE: **8/8/2016**
ADDRESS: **2103 N. Lamon Avenue** IDPH LICENSE NO: **100-19039**

HOMOGENEOUS AREA: **46**
MATERIAL DESCRIPTION: **Sheet Vinyl Flooring and Glue**
MATERIAL LOCATION: **Gymnasium Third Floor (1907 Bldg)**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____



Date: **08/08/2016**

APPENDIX B

Inspector and Management Planner Licenses



525-535 West Jefferson Street • Springfield, Illinois 62761-0001 • www.dph.illinois.gov

4/20/2016

DELORES FITZPATRICK
855 WEST ADAMS, SUITE 200
CHICAGO, IL 60607

ASBESTOS PROFESSIONAL LICENSE ID NUMBER: 05183

Enclosed is your Asbestos Professional License. Please note the expiration date on the card and in the image depicted below.

COPY OF THE ASBESTOS PROFESSIONAL LICENSE

Front of License

Back of License

		ASBESTOS PROFESSIONAL LICENSE		ENDORSEMENTS INSPECTOR PROJECT MANAGER AIR SAMPLING PROFESSIONAL	TC EXPIRES 2/13/2017 2/6/2017
ID NUMBER 00 - 05183	ISSUED 4/20/2016	EXPIRES 05/15/2017		Alteration of this license shall result in legal action This license issued under authority of the State of Illinois Department of Public Health This license is valid only when accompanied by a valid training course certificate.	
DELORES FITZPATRICK 855 WEST ADAMS, SUITE 200 CHICAGO, IL 60607 Environmental Health					

If you have any questions or need further assistance, contact the Asbestos Program at (217)782-3517 or fax (217)785-5897.

Our WEB address is: dph.illinois.gov/topics-services/environmental-health-protection/asbestos
EMAIL Address: dph.asbestos@illinois.gov

PROTECTING HEALTH, IMPROVING LIVES
Nationally Accredited by PHA/E

CERTIFICATE OF ACHIEVEMENT ASBESTOS ABATEMENT

Accredited by the Illinois Department of Public Health

This is to certify that WAYNE GARDNER
has completed the ASBESTOS INSPECTOR'S REFRESHER course and successfully passed the
examination on 02/13/2016 with a minimum score of 70% or better. Training was in accordance
with U.S. E.P.A. 40 CFR 763 Subpart E, Appendix C, Asbestos Containing Materials in Schools:
Model Accreditation Plan, TSCA II, Authorized by both AHERA & ASHARA.

02/13/2016

Course Dates:

02/13/2017

Expires:

1602BIR14

Certificate Number:




A handwritten signature in black ink, appearing to read "N. Peneff".

Director of Training
Nicholas J. Peneff
Doctor of Public Health

Phone: 312-491-0081

FORM # A-010B

2016



OCCUPATIONAL TRAINING & SUPPLY, INC.

7233 S. Adams Street ♦ Willowbrook, IL 60527 ♦ (630) 655-3900

Asbestos Management Planner Refresher

Occupational Training & Supply, Inc. certifies that

Jigar Shah

has successfully completed the Asbestos Management Planner Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 1/27/2016

Exam Date: 1/27/2016

Expiration Date: 1/27/2017

Certificate Number: MPR1601270320


Kathy DeSalvo, Director



525-535 West Jefferson Street • Springfield, Illinois 62761-0001 • www.dph.illinois.gov

4/20/2016

JIGAR M SHAH
 855 W ADAMS ST, SUITE 200
 CHICAGO, IL 60607

ASBESTOS PROFESSIONAL LICENSE ID NUMBER: 07342

Enclosed is your Asbestos Professional License. Please note the expiration date on the card and in the image depicted below.

COPY OF THE ASBESTOS PROFESSIONAL LICENSE

Front of License

Back of License

		ASBESTOS PROFESSIONAL LICENSE		ENDORSEMENTS	TC EXPIRES
ID NUMBER 109 - 07342	ISSUED 4/20/2016	EXPIRES 05/15/2017		INSPECTOR PROJECT DESIGNER MANAGEMENT PLANNER PROJECT MANAGER AIR SAMPLING PROFESSIONAL	1/19/2017 2/2/2017 1/27/2017 2/26/2017
JIGAR M SHAH 855 W ADAMS ST, SUITE 200 CHICAGO, IL 60607 Environmental Health		Alteration of this license shall result in legal action This license issued under authority of the State of Illinois Department of Public Health This license is valid only when accompanied by a valid training course certificate.			

If you have any questions or need further assistance, contact the Asbestos Program at (217)782-3517 or fax (217)785-5897.

Our WEB address is: dph.illinois.gov/topics-services/environmental-health-protection/asbestos
 EMAIL Address: dph.asbestos@illinois.gov

PROTECTING HEALTH, IMPROVING LIVES
Nationally Accredited by PHAB

APPENDIX C

Laboratory Accreditations

APPENDIX D

Laboratory Results

APPENDIX E

Chain of Custody Forms

Three-Year Reinspection Key to Terms

	CODE	KEY
MATERIAL		
	ACBM	Asbestos Containing Building Materials
MATERIAL CATEGORY		
	MISC	Miscellaneous
	SURF	Surfacing
	TSI	Thermal System Insulation
MATERIAL UNITS		
	LF	Linear Feet
	SF	Square Feet
	CF	Cubic Feet
DAMAGE TYPE		
	Loc	Localized
	Dist	Distributed